PHASE I ENVIRONMENTAL SITE ASSESSMENT

for

East Adams Redevelopment Phase VIII Area – Burt Street Syracuse, New York

Prepared for:

McCormack Baron Salazar, Inc. (MBSDI)
100 North Broadway, Suite 100
St. Louis, Missouri 63102

Prepared by:

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
360 West 31st Street, 8th Floor
New York, NY 10001

Daniel Dean, P.G.
Senior Project Manager

Brian Gochenaur, QEP
Associate Principal

Report Date: **30 October 2025**
180-Day Viability Date: **22 December 2025**
170859701

LANGAN

TABLE OF CONTENTS

EXECUTIVE SUMMARY **i**

1. Introduction **1**

PURPOSE 1

SCOPE OF SERVICES 1

USER RESPONSIBILITIES 3

1.1 LIMITING CONDITIONS/DEVIATIONS 4

1.2 DATA GAPS 4

2. 1.3 **Subject Property Description and Current Use** **5**

1.4

1.5 LOCATION, LEGAL DESCRIPTION, AND OWNERSHIP 5

PHYSICAL SETTING 5

2.1 SUBJECT PROPERTY DESCRIPTION 6

2.2

2.3 CURRENT SUBJECT PROPERTY USE 6

2.4 HAZARDOUS SUBSTANCES AND PETROLEUM PRODUCTS 6

2.5 AIR EMISSIONS 7

2.6

2.7 WASTE MANAGEMENT 7

2.8 WASTEWATER 7

2.9 STORM WATER 7

2.10 NON-ASTM SCOPE CONSIDERATIONS 7

3. 3.1 **Subject Property History and Records Review** **9**

3.2 HISTORICAL SUMMARY 9

3.3

REGULATORY DATABASE REVIEW 9

4.1 PRIOR REPORT REVIEW 11

4. 4.2 **Adjoining Properties and Surrounding Area** **12**

4.3

CURRENT USE OF ADJOINING PROPERTIES AND SURROUNDING AREA 12

ADJOINING PROPERTIES AND SURROUNDING AREA HISTORY 12

REGULATORY DATABASE REVIEW 13

5. 8.1 **Conclusions, Findings and Opinions** **16**

6. 8.2 **Environmental Professional Statement** **18**

7. References **19**

8. Limitations and Definitions **20**

ASTM DEFINITIONS 20

STANDARD ENVIRONMENTAL RECORD SOURCES 23

TABLES

Table ES-1 Conclusions, Findings and Opinions

Table 2-1 Utility Providers

Table 3-1 Subject Property History

Table 4-1 Current Use of Adjoining Properties and Surrounding Area

Table 4-2 Historical Use of Adjoining Properties

Table 5-1 Conclusions, Findings and Opinions

Table 7-1 Dates of Assessment Components

APPENDICES

Appendix A Figures

- Figure 1 Subject Property Location Map
- Figure 2 Subject Property Layout
- Figure 3 Nearby Properties Map

Appendix B Agency Records and Other Reports

Appendix C Site Reconnaissance Checklist and Photographs

Appendix D User Provided Information

Appendix E Historical Resources

Appendix F Environmental Database Report

Appendix G Resumes of Environmental Professionals

EXECUTIVE SUMMARY

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) completed a Phase I Environmental Site Assessment (ESA) of the East Adams Redevelopment Phase 8 Area located at Burt Street in Syracuse, New York (the "subject property") under the written authorization of McCormack Baron Salazar, Inc. (MBSDI) (the "Client" and the "user").

The Phase I ESA was completed following the guidelines of ASTM International Standard Practice E1527-21 (ASTM E1527-21), the United States Environmental Protection Agency's (US EPA) All Appropriate Inquiries (AAI) Rule, and industry standard practice. The user requested this ESA as part of their environmental due diligence related to a potential transaction involving the subject property.

Subject Property Layout

The about 1.7-acre subject property is the identified as Onondaga County Tax Parcel ID Section 094, Block 09, Lots 4.0, 5.0, 6.0, and the southern portion of 3.0. The subject property is bound by train tracks to the north, South McBride Street to the east, Burt Street to the south, and Oakwood Avenue to the west. The subject property is partially-vegetated and without structures. The main entrance into the subject property is located on Burt Street from the south.

Subject Property Current Use

The eastern portion of the subject property is used by Syracuse Housing Authority tenants for parking and the western portion of the subject property is occupied by a construction company. Nine shipping containers are present on the western portion of the subject property.

Subject Property History

The subject property has historically been used for residential, commercial, and industrial purposes including the "John Crabtree Stoneyard" (1910) and a scrap metal yard and metal welding company (1951-1990). The present-day parking lot and storage area were developed at the subject property by 2003.

Adjoining Properties and Surrounding Area

The adjoining and surrounding area was developed with mostly residential and mixed residential and commercial buildings by the late 1800s. Between the 1900s and 1970s, the area became increasingly developed with multi-story residential, institutional, and commercial buildings. The Syracuse University (SU) Steam Station appears in the adjoining and surrounding area to the northeast by 1953. The adjoining and surrounding area appears in its present-day configuration by 2019.

Conclusions

Langan completed a Phase I ESA of the subject property using the scope guidelines and inherent limitations of ASTM E1527-21. Table ES-1 presents the conclusions of the Phase I ESA.

Table ES-1 Conclusions, Findings and Opinions

ASTM E1527-21 Scope Items
Recognized Environmental Conditions (RECs)
Open Spill No. 23-08014: Petroleum impacts were identified in a monitoring well at the subject property during a routine sampling event in December 2023. A spill was reported to the New York State Department of Environmental Conservation (NYSDEC) and Spill No. 23-08014 was assigned to the subject property. The spill is currently open. The open petroleum release at the subject property is a REC.
Soil, Groundwater, and Soil Vapor Contamination at the Subject Property: Reported contamination on the eastern side of the subject property includes metals, polychlorinated biphenyls (PCBs), volatile organic compounds (VOCs), and polycyclic aromatic hydrocarbons (PAHs) in soil; VOCs in groundwater; and VOCs in soil vapor. Contamination is associated with historical use of the subject property as a scrap metal yard. Excavation and off-site disposal of contaminated soils was conducted in certain areas of the subject property and a one-foot soil cover was placed across the site as interim remedial measures (IRM). While the eastern part of the site is managed under a Site Management Plan (SMP) and Environmental Easement (EE) approved by the NYSDEC, contaminants of concern that exceed commercial use soil cleanup objectives (SCO) remain in place site-wide. And areas of light non-aqueous phase liquid (LNAPL) are expected to remain at the site. Additionally, soil vapor was not addressed as part of the IRM; therefore, potential for vapor intrusion exists in the event of redevelopment. The known presence of contamination in soil, groundwater and soil vapor at the subject property is considered a REC.
Historic Infilling of the Subject Property: According to the U.S. Department of Agriculture's (USDA) data for Onondaga County, the subject property is likely underlain by a layer of non-native fill. Additionally, historic Sanborn maps indicate the presence of historical structures which were likely demolished and comingled with non-native fill. Non-native fill found in urban environments typically contains ash, demolition debris, and/or municipal waste products and may contain contaminants (e.g., semivolatile organic compounds [SVOCs] or metals) at concentrations above applicable regulatory standards.
Controlled Recognized Environmental Conditions (CRECs)
Langan did not identify CRECs.
Historical Recognized Environmental Conditions (HRECs)
Closed Spill No. 0402274: NYSDEC Spill No. 0402274 was reported May 2004 regarding a spill of an unknown amount of unknown liquid. On 4 June 2004, the spill case was closed after the spill location was visited by the NYSDEC and was considered to be sufficiently remediated. Due to its regulatory status, this spill listing is considered an HREC.
De Minimis Conditions
Langan did not identify de minimis conditions.
Significant Data Gaps
Langan did not identify significant data gaps.
Non-ASTM E1527-21 Scope Items
Asbestos Containing Material (ACM), Lead Based Paint (LBP) and Polychlorinated Biphenyls (PCB)
ACM and LBP- and PCB-containing building materials were not present at the subject property.
Mold

ASTM E1527-21 Scope Items
Suspect mold was not identified at the subject property.
Radon
According to the USEPA Radon Zone Map, the subject property is located in Zone 1, which indicates a predicted average indoor radon screening level greater than 4 pico Curies per liter (pCi/L). According to the New York State Department of Health (NYSDOH) database of local and county radon testing results, 476 homes were tested in Onondaga County with average concentrations of 3.0 pCi/L and 1.76 pCi/L in basements and living areas, respectively. Based on this information, there is potential for elevated levels of radon gas in on-site buildings at the subject property. Mitigation measures (e.g., radon mitigation system) should be considered as part of redevelopment beneath future structures.
Business Environmental Risks (BER)
Monitoring Wells: Four groundwater monitoring wells are present at the subject property. Redevelopment of the subject property may require abandonment and/or replacement of the monitoring wells. Langan considers the potential costs associated with abandonment and/or replacement of the monitoring wells a BER.
Unknown Contents of 55-Gallon Drum: An unlabeled 55-gallon drum was observed at the southeastern side of the subject property. An unlabeled drum does not trigger a regulatory reporting requirement but is often associated with cost premiums for handling, management, transport, and disposal; therefore the unlabeled 55-gallon drum at the subject property is a BER.

1. INTRODUCTION

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) completed a Phase I Environmental Site Assessment (ESA) of the East Adams Redevelopment Phase 8 Area located at Burt Street in Syracuse, New York (the "subject property") under the written authorization of McCormack Baron Salazar, Inc. (MBSDI) (the "Client" and the "user"). A Subject Property Location Map is provided in Appendix A (Figure 1).

The Phase I ESA was completed following the guidelines of ASTM International Standard Practice E1527-21 (ASTM E1527-21), the United States Environmental Protection Agency's (US EPA) All Appropriate Inquiries (AAI) Rule, and industry standard practice. The user requested this ESA as part of their environmental due diligence associated with a potential transaction involving the subject property.

Purpose

1.1 The purpose of this Phase I ESA is to identify recognized environmental conditions (REC) associated with the subject property. This purpose also includes identifying controlled recognized environmental conditions (CREC), historical recognized environmental conditions (HREC), de minimis conditions, and significant data gaps. The definitions of REC, CREC, HREC, de minimis condition, and other select ASTM terms used in this report are in Section 8.

Scope of Services

1.2 Langan's scope of services consisted of the completion of a Phase I ESA following the guidelines of ASTM E1527-21. Langan's scope of services as it pertains to the elements of a Phase I ESA as specified in ASTM E1527-21 is described below.

On 8 July 2024, the US EPA final rule designating two per- and polyfluoroalkyl substances (PFAS) – perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) including their salts and structural isomers – as hazardous substances under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) became effective. Because of the complex and varied historical use of PFAS in various industries; limited prior disclosures of PFAS content on product specification sheets, Material Safety Data Sheets (MSDS), and Safety Data Sheets (SDS); the complex chemistry and chemical transformations associated with some PFAS; and the ever-growing and varied list of state regulations, it is not feasible to evaluate PFOA and PFOS without also considering other PFAS. As such, absent analytical data, Langan incorporated a review of PFAS as a general class into this Phase I ESA.

PFAS and other CERCLA hazardous substances and petroleum products have been detected in background environmental samples across the globe, including in areas removed from specific recognized sources. This Phase I ESA was not intended to evaluate background concentrations of CERCLA hazardous substances or petroleum products, regardless of whether the source is naturally occurring or anthropogenic. The objective of Langan's scope of services was to identify the presence, likely presence, and/or material threat of a release of CERCLA hazardous substances and petroleum products related to specific property uses that are generally recognized as known or potential sources of such substances and products.

1.2.1 Records Review and Local Government Interviews

Langan contracted a third-party provider to search environmental regulatory databases and provide historical records. The database search included select federal, state, local and tribal standard source environmental databases within the approximate search radii specified by ASTM E1527-21.

Langan submitted Freedom of Information Act (FOIA) requests to supplement environmental database listing information. The FOIA requests were submitted to the New York State Department of Environmental Conservation (NYSDEC), New York State Department of Health (NYSDOH) and the City of Syracuse. Langan also reviewed online records including the Onondaga County Building Department database, United States Geological Survey (USGS) mapping, and US EPA databases. Agency FOIA-requested information, where received, is discussed in relevant sections of this report, and referenced in Section 7. Pertinent documents are provided in Appendix B.

Langan supplemented the third-party-provided historical records with review of online historical record sources including Google Earth Pro and NETR Online.

1.2.2 Site Reconnaissance and Owner/Operator/Occupant Interviews

Langan completed the site reconnaissance on 24 June 2025. Anikka Hayward (maintenance worker with the Syracuse Housing Authority [SHA]; the "key site manager") accompanied Olivia Miller of Langan during the site reconnaissance. Ms. Hayward has been associated with the subject property since 2023.

Langan walked the periphery of the subject property, observed the subject property from adjoining public thoroughfares, and walked the accessible interiors of structures at the subject property. Langan observed the adjoining properties and the surrounding area from the periphery of the subject property and from public thoroughfares adjoining to or traveled on to access the subject property. The weather at the time of the site reconnaissance was about 89°F and sunny. Photographs from the site reconnaissance are provided in Appendix C.

A telephone interview was completed with Lindy Madill (Development Director of SHA), the owner of the subject property, on 15 July 2025. The key site manager was not aware of any environmental documents pertaining to the subject property, other than the documents provided in Section 3.3 of this report. The key site manager stated that, to her knowledge, there were no pending, threatened, or past litigation or administrative proceedings relevant to hazardous substances or petroleum products in, on, at, or from the subject property, and that she was not aware of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances of petroleum products. Other relevant information from the interview is included in this report.

1.2.3 Evaluation, Report and Parts Used in Concert

Langan evaluated the information obtained from the records reviews, site reconnaissance and interviews described above, and from the user as described in Section 1.3 in concert with each other. Langan's findings, opinions, and conclusions are discussed throughout this report. Significant assumptions, or deletions, deviations or exceptions to ASTM E1527-21 are noted in Section 1.4.

1.2.4 Non-ASTM Scope Services

Langan evaluated the following Non-ASTM Scope Services as part of this Phase I ESA in accordance with the United States Department of Housing and Urban Development (HUD) guidance: asbestos-containing material (ACM), lead-based paint (LBP), polychlorinated biphenyls (PCBs), mold, and radon. Findings are further described in Section 2.10

1.2.5 Vapor Encroachment Screening

Langan completed a limited vapor encroachment screening for potential vapor encroachment conditions (VEC), in general conformance with ASTM E2600-15 Standard Guide for Vapor Encroachment Screening, which may affect the subject property. The VEC screening focused on the current and historical use of the subject property and utilized the regulatory agency database report provided by Environmental Data Resources, Inc. (EDR) to evaluate identified chemicals of concern (ChOC). To identify the area of concern (AOC) for contaminated sites with non-petroleum hydrocarbon ChOCs, Langan utilized the approximate minimum search distance defined by ASTM E2600-15 of 1,760 feet (1/3 mile) from the subject property boundary for ChOC-contaminated sites. For sites contaminated with petroleum hydrocarbon ChOCs, Langan utilized the AOC approximate minimum search distance of 528 feet (1/10 mile). The AOC was adjusted accordingly based on review of physical setting characteristics, known release information, subject property land features, groundwater flow direction and soil type, et al.

ASTM's Vapor Encroachment guidance indicates that when groundwater flow direction can be estimated or determined, the cross-gradient or down-gradient radius distances can be significantly reduced. The reduced AOC distances were calculated when considering groundwater flow direction by utilizing the following default distances, which were determined using the Buonicore Methodology: (non-petroleum hydrocarbon ChOCs) 1,760 feet in the upgradient direction; 365 feet in the cross-gradient direction; and 100 feet in the downgradient direction and (petroleum hydrocarbon ChOCs) 528 feet in the upgradient direction; 165 feet in the cross-gradient direction if Light Non-Aqueous Phase Liquid (LNAPL, i.e., floating product) is suspected; 95 feet in the cross-gradient direction if no LNAPL is suspected; 100 feet in the downgradient direction (LNAPL suspected); and 30 feet in the downgradient direction (LNAPL not suspected).

VECs identified for the subject property are further discussed in Section 4.0.

1.3 User Responsibilities

Langan requested that the user provide the results of tasks the user is responsible for completing to satisfy the requirements of AAI. The tasks include: searching for known environmental liens and activity and use limitations (AULs) filed or recorded against the subject property, and provision of information related to specialized knowledge or experience of the user or the degree of obviousness relative to conditions indicative of releases or threatened releases; actual knowledge of the user regarding environmental liens or AULs related to the subject property; specialized knowledge or experience of the user; reasons for significantly lower purchase prices, and commonly known or reasonably ascertainable information within the local community about the subject property. Langan also requested that the user state the reason the Phase I ESA was requested. A summary of the user's responses is provided in Appendix D and relevant information provided by the user is discussed in applicable sections of this report.

Unless specifically included in the scope of services, Langan did not complete a title search or a

search for environmental liens or AULs, as that is the responsibility of the user. If the user requested that Langan complete such searches on the user's behalf, the information was supplied to Langan by a vendor, and to the vendor by government sources; therefore, neither Langan nor the vendor can verify the completeness or accuracy of the title search, or AUL searches.

Limiting Conditions/Deviations

Langan was unable to observe the contents of the nine shipping containers stored on the subject property due to access issues. No staining, odors, or other evidence of a release was observed in the vicinity of the shipping containers. Therefore, this limiting condition did not impact Langan's
1.4 conclusions.

Langan did not delete or deviate from the ASTM E1527-21 guidelines during this Phase I ESA.

Data Gaps

Data gaps, if encountered, are discussed throughout the report. Significant data gaps, if any, are
1.5 summarized in Section 5.0.

2. SUBJECT PROPERTY DESCRIPTION AND CURRENT USE

The following sections describe the subject property location, ownership, physical setting, and current layout and operations.

Location, Legal Description, and Ownership

The about 1.7-acre subject property is bound by train tracks on the north, South McBride Street on the east, Burt Street on the south, and Oakwood Avenue on the west. The subject property is described Onondaga County as Tax Parcel ID Section 094, Block 09, Lots 4.0, 5.0, 6.0, and the
2.1 southern portion of Lot 3.0. A legal description of the subject property is provided on the property record card in Appendix E. The subject property is owned by the Syracuse Housing Authority.

Physical Setting

The physical setting that includes the geologic, hydrogeologic, hydrologic, and topographic
2.2 characteristics of the subject property and surrounding area is discussed below.

2.2.1 Topography

The 2019 United States Geological Survey (USGS) 7.5-minute quadrangle topographic map for Syracuse East depicts the subject property at an elevation of approximately 400 feet above mean sea level (amsl) and is generally flat. The regional topography slopes downward toward the west and Onondaga Creek, which is located approximately 2,600 feet west of the subject property.

2.2.2 Geology

According to the U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) Soil Survey Geographic (SSURGO) data for the subject property, soils at the subject property are comprised primarily of urban land. Urban land is described as excavated, filled, and made land. Typically, these soils have been mixed with other materials, such as brick, concrete, and demolition debris of unknown origin (non-native fill). Non-native fill found in urban environments typically contains ash, demolition debris, and/or municipal waste products and may contain contaminants (e.g., semivolatile organic compounds [SVOCs] or metals) at concentrations above applicable regulatory standards. Inadvertent releases of petroleum products, chemicals, or other hazardous substances resulting from historical infilling operations may have affected soil, groundwater, and/or soil vapor at the subject property.

Based on review of the USGS "Geologic Map of New York, Finger Lakes Sheet (Fisher, Isachsen, Rickard, March 1970)", the subject property is underlain by bedrock of the Syracuse Foundation, consisting of dolostone, shale, gypsum, and salt.

2.2.3 Hydrogeology

Surface water bodies are not present within the subject property. The nearest surface water body is Onondaga Creek. Information regarding subject property-specific groundwater flow direction is unavailable. Groundwater flow can be influenced by several factors such as surface water bodies, wetlands, hydrogeologic and anthropogenic variables. However, based on topographic gradient and proximity to Onondaga Creek, it is expected that groundwater generally flows to the west.

A review of the Geocheck section of the LightBox Environmental Data Resources (EDR) Regulatory Database Report (Appendix F) did not identify groundwater wells on the subject property. Langan observed four monitoring wells at the subject property during the site reconnaissance. Based on information from the Institutional and Engineering Controls (IC/EC) database, the monitoring wells installed at the subject property indicated that groundwater depth levels varied seasonally, ranging from 2.4 feet to 9.6 feet below ground surface (bgs).

Subject Property Description

The subject property is partially-vegetated with no structures. Nine shipping containers are present on the western portion of the property. The main entrance into the subject property is located on Burt Street from the south.

2.3

According to the Rezone Syracuse ordinance and City of Syracuse Zoning Map, the subject property is zoned MX-2: Neighborhood Center District. The MX-2: Neighborhood Center zoning district is generally characterized as intended for mixed-use development, primarily for medium- to higher-density residential uses and nonresidential uses that provide goods and services to the surrounding area. The surrounding properties are zoned for LI: Light Industry and Employment Districts, MX-4: Urban Core Districts, R5: High Density Residential Districts, PID: Planned Institutional Districts, and OS: Open Space Districts. A copy of the zoning map is included in Appendix B.

A Subject Property Layout Map is provided in Figure 2 of Appendix A. Photographs of the subject property and a checklist documenting Langan's observations relative to the features, activities, uses, and conditions outlined in Section 9.4 of ASTM E1527-21 are in Appendix C.

2.4 **Current Subject Property Use**

The eastern portion of the subject property is used by Syracuse Housing Authority tenants for parking and the western portion of the subject property is occupied by a construction company.

The following table summarizes subject property utility providers.

Table 2-1 Utility Providers

Utility	Providers
Electricity (used for cooling)	National Grid
Natural gas (used for heating)	National Grid
Water	City of Syracuse
Sewer	Onondaga County

2.5

Hazardous Substances and Petroleum Products

Langan did not observe hazardous substances at the subject property. Langan did not observe evidence of leaks, spills, pools of liquid or releases such as staining, or sheens, other than as described below.

2.5.1 Underground Storage Tanks (USTs)

The EDR database report did not identify USTs at the subject property, and Langan did not observe evidence of USTs.

2.5.2 Aboveground Storage Tanks (ASTs)

The EDR database report did not identify ASTs at the subject property, and Langan did not observe evidence of ASTs.

2.5.3 Drums, Totes, and Intermediate Bulk Containers

Langan observed one unlabeled 55-gallon drum during the site reconnaissance. An unlabeled drum does not trigger a regulatory reporting requirement but is often associated with cost premiums for handling, management, transportation, and disposal; therefore the unlabeled 55-gallon drum at the subject property is a BER.

2.5.4 Other Chemical Storage, Containers, or Equipment

Langan observed nine shipping containers on the western portion of the subject property during the site reconnaissance. No staining, odors, or other evidence of a release was observed in the vicinity of the shipping containers. Accordingly, Langan does not consider the shipping containers an environmental concern for the subject property.

Air Emissions

2.6 Langan did not observe potential air emissions sources at the subject property.

Waste Management

2.7 The following sections describe current hazardous and non-hazardous waste streams, and observations of fill areas or other solid waste throughout the subject property.

2.7.1 Hazardous Waste

Langan did not observe any indication of hazardous waste generation at the subject property.

2.7.2 Non-Hazardous Waste

Langan did not observe any indication of non-hazardous waste generation at the subject property.

2.7.3 Fill Areas or Solid Waste

2.8 Langan did not observe areas that were apparently filled or graded by non-natural causes (or filled with material of unknown origin) that suggest the presence of garbage, construction debris, demolition debris, or other solid waste disposal, or mounds or depressions suggesting solid waste disposal.

2.9 Wastewater

Langan did not observe wastewater processes at the subject property. Additionally, Langan did not observe or identify evidence of septic systems or cesspools at the subject property.

Storm Water

Storm water at the subject property percolates through pervious areas or sheet flows to the adjoining roadways into the municipal storm sewer system.

Non-ASTM Considerations

2.10.1 ACM, LBP, and PCBs

ACM, LBP and PCB-containing materials were not present at the subject property.

2.10 *2.10.2 Mold*

Mold was not identified at the subject property.

2.10.3 Radon

Radon is a colorless, odorless radioactive gas that results from the natural breakdown of uranium minerals in soil, rock, and water, which subsequently enters the atmosphere. It can concentrate in buildings, entering through cracks and other penetrations of a building foundation. Some areas are more likely to have elevated concentrations of radon than others, reflecting subsurface lithological conditions.

The USEPA has established a recommended radon action level of 4.0 pico Curies per liter (pCi/L). According to the USEPA Radon Zone Map, the subject property is located in Zone 1, which indicates a predicted average indoor radon screening level greater than 4 pCi/L. The NYSDOH maintains a database of radon test results on a local and county level. According to the database, 476 homes were tested in Onondaga County with average concentrations of 3.0 pCi/L and 1.76 pCi/L in basements and living areas, respectively. A total of 62% of basements and 76% of living areas had concentrations below 4 pCi/L. Based on this information, there is potential for elevated levels of radon gas in on-site buildings at the subject property. Mitigation measures (e.g., radon mitigation system) should be considered as part of redevelopment beneath future structures.

3. SUBJECT PROPERTY HISTORY AND RECORDS REVIEW

The following sections provide summaries of the historical uses of the subject property, and available information regarding documented environmental conditions associated with the historical uses.

Historical Summary

Langan compiled the following summary of the subject property history based on a review of readily available and reasonably ascertainable sources and interviews. Historical resources are provided in Appendix E.

3.1 **Table 3-1 Subject Property History**

Time Period	Historical Discussion
1892 – 1947	The subject property is depicted with multi-family residential dwellings in the western portion on Sanborn Maps in the early 1890s. By 1910, additional multi-family dwellings and the John Crabtree Stoneyard appear in the eastern portion of the subject property.
1951 – 1990s	By 1951 through at least 1990, the subject property appears as a scrap metal yard with multiple sheds and a welding building in the western portion on Sanborn Maps.
2000s – Present	According to aerial photographs and imagery from the early 2000s through present day, the subject property was redeveloped into a parking lot and storage area. From 2003 through 2023, the western portion of the subject property appeared as grassy land with no permanent structures. At present day, construction equipment appears on the western portion of the subject property, while the eastern portion is used for nearby tenant parking. There is scattered vegetation throughout the property. The subject property is currently owned by Syracuse Housing Authority.

Environmental concerns related to historical operations as a scrap metal yard and welding company are discussed further in Section 3.2. Additionally, demolition of historic structures for redevelopment of the subject property in its current configuration may have required infilling with non-native fill. As discussed in Section 2.2.2, non-native fill found in urban environments typically contains ash, demolition debris, and/or municipal waste products and may contain contaminants (e.g., SVOCs or metals) at concentrations above applicable regulatory standards. Inadvertent
3.2 releases of petroleum products, chemicals, or other hazardous substances resulting from historical operations and/or infilling operations may have affected soil, groundwater, and/or soil vapor at the subject property.

Regulatory Database Review

The subject property is identified on the NY SPILLS, Institutional and Engineering Controls (IC/EC), Environmental Resource Permit (ERP), Resource Conservation and Recovery Act (RCRA), New York Manifest, Facility Index System (FINDS), and Enforcement and Compliance History Online (ECHO) databases. The listings are related to contamination from historical use as a scrap metal yard and a metal welding company. The environmental database report is attached as Appendix F.

The IC/EC database listing indicates the presence of contamination from metals, oils, petroleum, and dielectric fluids from historical uses of the subject property. The primary contaminants of concern (COCs) were metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); petroleum; and SVOCs, specifically polycyclic aromatic hydrocarbons (PAHs), a subset of SVOCs. Volatile organic compounds (VOCs) were also found at the subject property, but to a lesser degree than the other COCs. No subject property-related contamination was identified off-site.

Soil contamination at the subject property was reported at the concentrations listed below:

- Arsenic concentrations up to 218 parts per million (ppm), exceeding the commercial use soil cleanup objective (SCO) for New York of 16 ppm.
- Barium concentrations up to 6,390 ppm, exceeding the commercial use SCO of 400 ppm.
- Benzo(a)pyrene concentrations up to 7.2 ppm, exceeding the commercial use SCO of 1.0 ppm.
- Cadmium concentrations up to 139 ppm, exceeding the commercial use SCO of 9.3 ppm.
- Copper concentrations up to 51,100 ppm, exceeding the commercial use SCO of 270 ppm.
- Lead concentrations up to 19,200 ppm, exceeding the commercial use SCO of 1,000 ppm.
- Mercury concentrations up to 438 ppm, exceeding the commercial use SCO of 2.8 ppm.
- PCB concentrations up to 29.0 ppm, exceeding the commercial use SCO of 1.0 ppm.
- Trichloroethene concentrations up to 6.84 ppm, exceeding the SCO for the protection of groundwater SCO of 0.47 ppm.

Soil vapor contamination at the subject property was reported at the concentrations listed below that were below applicable screening levels:

- 1,1,1-trichloroethane was detected at 5.66 micrograms per cubic meter ($\mu g/m^3$).
- Cis-1,2-dichloroethene was detected at 0.443 $\mu g/m^3$.
- Tetrachloroethene was detected at 4.96 $\mu g/m^3$.
- Trichloroethene (TCE) was detected at 1.37 $\mu g/m^3$.

Groundwater contamination reported at the subject property includes petroleum and TCE. TCE concentrations in groundwater were reported to exceed 5 micrograms per liter (µg/L) with subsequent natural attenuation. An area of petroleum light non-aqueous phase liquid (LNAPL) several feet thick was reported in the north-central portion of the subject property.

Certain areas of soil contamination at the subject property exceeding SCOs were excavated and disposed of off-site as interim remedial measures (IRM). One IRM included excavation of the area with reported LNAPL. A one-foot clean soil cover has been installed across the eastern portion of the subject property. The eastern portion of the subject property, including the soil cover, is being managed under a Site Management Plan (SMP) and Environmental Easement (EE) approved by NYSDEC. The EE restricts use of the site to commercial or industrial uses, only. Contaminated soil is reported to be primarily found in the first two feet below the soil cover (1 to

3 feet bgs). Soil vapor contamination was not addressed by the SMP due to the absence of permanent structures at the subject property; therefore, the potential for vapor intrusion exists if the subject property is redeveloped. Institutional controls restricting the use of groundwater were reportedly not implemented due to the nearby areas being served by a public water supply that is not impacted by subject property-related contamination. The known presence of contamination in soil, groundwater and soil vapor at the subject property is considered a REC.

The RCRA-Large Quantity Generator (LQG) database listing is due to the shipment of approximately 2.2 tons of contaminated material off-site from the subject property in 2009 as part of an IRM excavation event. This listing is not related to historical operations at the subject property. Due to the listing being related to remedial activities, this RCRA--LQG listing is not considered to be an environmental concern for the subject property.

The ERP database listing is for NYSDEC Spill No. 2308014, which was reported to NYSDEC in December 2023 when 8 feet of petroleum LNAPL was reported in a monitoring well at the subject property during a routine sampling event. The well number was not reported. CNS Environmental reportedly removed 6 quarts of petroleum LNAPL from the well in January 2024 and conducted follow-up monitoring. The spill incident is currently open. Due to its regulatory status as an active case, this spill listing is a REC.

NYSDEC Spill No. 0402274 was reported May 2004 as a spill of an unknown amount of unknown liquid. On 4 June 2004, the spill case was closed after the spill location was visited by the NYSDEC and was considered to be sufficiently remediated. Due to its regulatory status, this spill listing is considered a historical REC (HREC).

The NY SPILLS database listing is for NYSDEC Spill No. 0712291. The spill was reported at the subject property in February 2008 when an unknown amount of petroleum LNAPL was found while gauging a monitoring well (#MW3) at the subject property. Dvirka & Bartilucci reportedly conducted additional investigation and remediation, but no further details were provided in the database listing. The spill case was closed by NYSDEC on 10 February 2009. Due to its regulatory status, this spill listing is not considered to be an environmental concern for the subject property.

3.3 Prior Report Review

Prior reports reviewed as part of this Phase I ESA include the following:

- Site Investigation and Remedial Alternatives Report and Work Plan, McKinney Brut Street Site ERP Code E734806, dated June 2007
- Site Investigation and Remedial Alternatives Report and Work Plan, McKinney Brut Street Site ERP Code E734806, dated November 2011
- Construction Completion Report, McKinney Property Site ERP Site No. E734806, dated August 2015
- McKinney Property ERP Record of Decision, Site No. E734806, dated December 2015
- Final Engineering Report, NYSDEC ERP Site No. E734086, dated May 2016
- Site Management Plan, NYSDEC ERP Site No. E734086, dated May 2016
- Environmental Easement, NYSDEC ERP Site No. E734086, dated September 2016

Relevant findings from the above reports were summarized in Section 3.2 and are provided in Appendix B.

4. ADJOINING PROPERTIES AND SURROUNDING AREA

The following sections describe current and historical uses of and database listings for adjoining properties and the surrounding area.

Current Use of Adjoining Properties and Surrounding Area

The current use of adjoining and surrounding properties is summarized in Table 4-1.

Table 4-1 Current Use of Adjoining Properties and Surrounding Area

4.1

Direction	Adjoining Properties	Surrounding Area
North	Rail line followed by Syracuse University's vacant Steam Station water reservoir (1202-1204 South McBride Street) and vacant land (1212 South McBride Street and 420 East Taylor Street)	Multi-family residential and parks
East	South McBride Street followed by a rail line and vacant land (501 and 507 East Taylor Street)	US Interstate 81, multi-family residential, and a university
South	Burt Street followed by a multi-family residential building (450 Burt Street)	Multi-family residential and churches
West	Oakwood Avenue followed by Hub Liquor Store (116 Oakwood Avenue), Eddie's Eagle Market (140 Oakwood Avenue), and a gravel parking lot (1105 through 1117 South State Street)	Retail businesses, a radio station, and a church

Langan did not observe obvious conditions likely to represent environmental concerns for the subject property from current uses of adjoining or surrounding properties.

4.2

Adjoining Properties and Surrounding Area History

Langan compiled the following summaries of the adjoining properties and surrounding area history based on a review of historical resources and interviews. Historical resources are provided in Appendix E.

Table 4-2 Historical Use of Adjoining Properties

Direction	Adjoining Properties
North	The northern adjoining property is depicted with multi-family residential buildings and a coal and wood storage yard by 1892 through at least 1910. The rail line appears as constructed on the 1892 Sanborn Map. From 1951 through present day, the northern adjoining property appears as part of the vacant Syracuse University Steam Station surrounded by vacant land with a rail line running through it in the southeast-northwest direction. This property is discussed further in Section 4.3.1.
East	The eastern adjoining properties appear as undeveloped land by 1892 through at least 1910. The rail line appears as constructed on the 1892 Sanborn Map. By 1978 through present day, the eastern adjoining properties appear as paved land followed by the rail line and a treed area. Langan does not consider the historical use of the eastern adjoining properties an environmental concern for the subject property.

Direction	Adjoining Properties
South	The southern adjoining property is depicted with multi-family residential buildings by 1892. Burt Street appears as constructed on the 1892 Sanborn Map. By 1910, two hen houses, a garage, a shed, and a workshop are depicted on the property. By 1951, the hen houses were redeveloped into automobile garages. The property appears in a similar configuration from 1951 through at least 1971. By 1990, the residential units that appeared in the northeastern corner of the property were razed. According to aerial photographs the remaining residential buildings appear razed by 2008. By 2008 through at least 2017, the northeastern corner of the property appears as a parking lot and the central portion appears as a treed area. The southern adjoining property appears in its current configuration as a T-shaped multi-family residential building by 2019. Langan does not consider the historical use of the southern adjoining property an environmental concern for the subject property.
West	The western adjoining properties are depicted with multi-family residential buildings, an autobody shop, two carpenter shops, and a stone yard by 1892. Grape Street (present-day Oakwood Avenue) appears as constructed on the 1892 Sanborn Map. By 1910, a bridge shop appears in the northeast corner of the property. By 1951, the western adjoining properties primarily consist of scrap metal storage and residential housing. From 1961 through at least 1990, the western adjoining properties appear with a Salvation Army warehouse (until 2003) and a scrap metal yard. By 1969 through at least 1977, Anthony Di Pino's gas station and Harry B. Halliday's automotive repair shop appeared on the property. The former buildings were demolished in the early 2000s and the property was configured into its current state. This property is discussed further in Section 4.3.1.

The surrounding area was depicted as primarily residential by the early 1890s through 1959. Surrounding roadways were apparent by the early 1950s. The Syracuse University (SU) Steam Station appears to the northeast by 1953. Commercial development and parking lots were apparent to the north, northeast, east, west, and northwest of the subject property by the mid-1960s. The surrounding area appears in similar configuration from 2008 to present.

4.3 Database listings associated with the surrounding area are discussed in Section 4.3.

Regulatory Database Review

Langan reviewed the environmental database report to evaluate if adjoining or surrounding area properties identified in the database report are suspected to represent an environmental concern for the subject property (see Section 8.2). Langan did not consider request and review of the associated regulatory agency files necessary to evaluate potential RECs for the subject property unless discussed in Section 4.3.1 or 4.3.2 below.

4.3.1 Adjoining Properties

Database listings for adjoining properties are summarized as follows.

Spill No. 9908800 – Syracuse University (SU) Steam Plant (northern-adjoining, upgradient)

NYSDEC Spill No. 9908800 was reported in October 1999 as a release of approximately 10 gallons of No. 2 fuel oil from a tank that was closed in 1989. On 23 November 1999, the spill case was closed after the spill location was visited by the NYSDEC and was considered to be

sufficiently remediated. Due to its regulatory status, this spill listing is not considered to be an environmental concern for the subject property.

Roth Bros Metal Company – 1107 South State Street (western-adjoining, downgradient)

This facility is listed in the Lead Smelters and Superfund Enterprise Management System (SEMS)-Archive databases for historic scrapping and recycling operations conducted at the site. According to the listings, site activities included the recycling of batteries and scrap metals, precious metal recovery, and smelting. Based on the inferred cross-gradient location and absence of violations and spills for the above listings, this listing does not present an environmental concern for the subject property.

Former Salvation Army/1105-1117 South State Street /East Adams Redevelopment Phase 2 Area/ 1105-1117 South State Street/Anthony DiPino (western-adjoining, downgradient)

This facility was identified in the NY Brownfields database under the name 'East Adams Redevelopment – Phase II Area' and BCP Site No. C734163. The site was developed as early as the 1890s and was historically occupied by a carriage manufacturing and painting facility, a bridge manufacturing facility with two gasoline tanks, a clothing factory, a scrap metal yard, a gasoline station with gasoline storage tanks, a paper baling facility, and automobile repair facility. The site is also listed in the UST, UST Finder, UST Finder Release, LTANKS, and NY Spills databases. This facility was identified on the EDR Historical Automotive Repair database as a gasoline service station (Anthony Di Pino's) and autobody repair shop (Harry B. Halliday's) from 1969 to 1977. Environmental investigations conducted between 1996 and 2023 identified contaminants of concern including VOCs, SVOCs and metals in soil; VOCs, SVOCs, and total metals in groundwater; and petroleum-related VOCs in soil vapor. There is one open NY Spill associated with this site, Spill No. 2208975, reported 6 February 2023 during a Phase II for petroleum-impacted material encountered between 5 and 15 feet bgs.

The site will be remediated in accordance with a NYSDEC-approved RAWP. Evidence of contamination related to this facility was not encountered during the January 2023 Phase II ESA at the subject property; therefore, this listing does not present an environmental concern for the subject property.

4.3.2 Surrounding Area

Langan evaluated each of the database listings for surrounding area properties (see Section 8.2). Those warranting further discussion in the context of potential to represent an environmental concern for the subject property are discussed below.

SU Steam Station/ Chilled Water Plant – 500 East Taylor Street/Intersection of East Taylor Street and South McBride Street (approximately 70 feet northeast, inferred up-gradient)

This facility was identified on the RCRA, Manifest, UST Finder, UST, AST, Chemical Bulk Storage (CBS) AST, Aeromatic Information Retrieval System (AIRS), LTANKS, and NY Spills databases.

The facility was listed on the RCRA database as a SQG in 1987, a large quantity generator (LQG) in 1992, and a very small quantity generator (VSQG) in 2006, 2007, and 2018. The facility was listed as not a generator in 2019. Hazardous waste generated at the facility includes ignitable waste (D001), corrosive waste (D002), spent halogenated solvents used in degreasing (F001), and spent halogenated solvents (F002). The NAICS code associated with the facility is colleges, universities, and professional schools (61131). No violations were reported. The facility is also

listed in the Manifest database with EPA ID NYD982271918 and is associated with the RCRA listing for the transport of hazardous waste generated at the site.

The facility is on the UST and UST Finder databases, and, according to the listing, the facility has four, 30,000-gallon No. 2 fuel oil USTs that are currently in service. In addition, three, 30,000-gallon No. 2 fuel oil USTs historically operated at the facility and are currently closed.

According to the AST database, the facility has one, 275-gallon No. 2 fuel oil AST and one, 300-gallon No. 1 fuel oil AST. According to the CBS AST database, the facility has one, 1,000-gallon methane AST, one, 1,500-gallon sulfuric acid AST, and two, 1,000-gallon ethylenediamine tetra-acetic acid (EDTA) ASTs that are currently in service.

According to the AIRS database, a permit was issued to the facility on 3 February 2012 and expired on 2 February 2012.

The following NY Spill Numbers are associated with the facility: 9908800, 0600689, 8801654, 9204042, 9107234, 1502394, 1810736, and 8605131. Product releases include No. 2 fuel oil, hydraulic oil, polychlorinated biphenyl (PCB) oil, and phosphoric acid. The releases were caused by tank failures, tank test failures, equipment failure, human error, and the collapse of a building. Spill Numbers 8910992 and 8801654 note impacts to groundwater. Each spill incident has been granted closed status by the NYSDEC, indicating that NYSDEC is satisfied with spill remediation. Due to the distance and cross-gradient location with respect to the subject property, this facility is not considered a REC.

5. CONCLUSIONS, FINDINGS AND OPINIONS

Langan completed a Phase I ESA consistent with the scope and limitations of ASTM E1527-21 for the subject property at East Adams Redevelopment Phase 8 Area located at Burt Street in Syracuse, New York. Exceptions to, or deletions from, ASTM E1527-21 are described in Section 8 of this report.

This assessment has revealed the following RECs in connection with the subject property as presented in Table 5-1.

Table 5-1 Conclusions, Findings and Opinions

ASTM E1527-21 Scope Items
Recognized Environmental Conditions (RECs)
Open Spill No. 23-08014: Petroleum impacts were identified in a monitoring well at the subject property during a routine sampling event in December 2023. A spill was reported to the New York State Department of Environmental Conservation (NYSDEC) and Spill No. 23-08014 was assigned to the subject property. The spill is currently open. The open petroleum release at the subject property is a REC.
Soil, Groundwater, and Soil Vapor Contamination at the Subject Property: Reported contamination at the eastern side of the subject property includes metals, PCBs, VOCs, and PAHs in soil; VOCs in groundwater; and VOCs in soil vapor. Contamination is associated with historical use of the subject property as a scrap metal yard. Excavation and off-site disposal of contaminated soils was conducted in certain areas of the subject property and a one-foot soil cover was placed across the site as IRM. While the eastern part of the site is managed under a SMP and EE approved by the NYSDEC, contaminants of concern that exceed commercial use SCOs remain in place site-wide. And areas of LNAPL are expected to remain at the site. Additionally, soil vapor was not addressed as part of the IRM; therefore, potential for vapor intrusion exists in the event of redevelopment. The known presence of contamination in soil, groundwater and soil vapor at the subject property is considered a REC.
Historic Infilling of the Subject Property: According to the USDA data for Onondaga County, the subject property is likely underlain by a layer of non-native fill. Additionally, historic Sanborn maps indicate the presence of historical structures which were likely demolished and comingled with non-native fill. Non-native fill found in urban environments typically contains ash, demolition debris, and/or municipal waste products and may contain contaminants (e.g., SVOCs or metals) at concentrations above applicable regulatory standards.
Controlled Recognized Environmental Conditions (CRECs)
Langan did not identify CRECs.
Historical Recognized Environmental Conditions (HRECs)
Closed Spill No. 0402274: NYSDEC Spill No. 0402274 was reported May 2004 regarding a spill of an unknown amount of unknown liquid. On 4 June 2004, the spill case was closed after the spill location was visited by the NYSDEC and was considered to be sufficiently remediated. Due to its regulatory status, this spill listing is considered an HREC.
De Minimis Conditions
Langan did not identify de minimis conditions.
Significant Data Gaps
Langan did not identify significant data gaps.
Non-ASTM E1527-21 Scope Items

ASTM E1527-21 Scope Items
ACM, LBP and PCBs
ACM and LBP- and PCB-containing building materials were not present at the subject property.
Mold
Suspect mold was not identified at the subject property.
Radon
According to the USEPA Radon Zone Map, the subject property is located in Zone 1, which indicates a predicted average indoor radon screening level greater than 4 pico Curies per liter (pCi/L). According to the New York State Department of Health (NYSDOH) database of local and county radon testing results, 476 homes were tested in Onondaga County with average concentrations of 3.0 pCi/L and 1.76 pCi/L in basements and living areas, respectively. Based on this information, there is potential for elevated levels of radon gas in on-site buildings at the subject property. Mitigation measures (e.g., radon mitigation system) should be considered as part of redevelopment beneath future structures.
Business Environmental Risks (BERs)
Monitoring Wells: Four groundwater monitoring wells are present at the subject property. Redevelopment of the subject property may require abandonment and/or replacement of the monitoring wells. Langan considers the potential costs associated with abandonment and/or replacement of the monitoring wells a BER.
Unknown Contents of 55-Gallon Drum: An unlabeled 55-gallon drum was observed at the southeastern side of the subject property. An unlabeled drum does not trigger a regulatory reporting requirement but is often associated with cost premiums for handling, management, transport, and disposal; therefore the unlabeled 55-gallon drum at the subject property is a BER.

6. ENVIRONMENTAL PROFESSIONAL STATEMENT

I declare that to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR Part 312 and I have the specific qualifications based on my education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Brian Gochenaur, QEP
Associate Principal (Environmental Professional)

Resumes outlining the qualifications of the project team and the Environmental Professional are included in Appendix G.

7. REFERENCES

Langan used the following sources to complete this Phase I ESA.

- ASTM E1527-21, Standard Practice for Environmental Property Assessments: Phase I Environmental Property Assessment Process, published 16 November 2021
- City of Syracuse Zoning Map, https://www.syr.gov/Departments/Zoning-Administration/2023-Zoning-Map, searched 19 June 2025
- EDR, Inc., Radius Map Report with GeoCheck, 23 June 2025
- EDR, Inc., City Directory Image Report, 25 June 2025
- EDR, Inc., Aerial Photographs, 25 June 2025
- EDR, Inc., Historical Topographic Map Report, 25 June 2025
- EDR, Inc., Sanborn Map Report, 25 June 2025
- Interstate Technology and Regulatory Council, Per and Polyfluoroalkyl Substances Technical and Regulatory Guidance, July 2023
- Onondaga County Department of Finance, https://ocfintax.ongov.net/lmate/propdetail.aspx?swis=311500&printkey=095000000600100000000, searched 27 June 2025
- Onondaga County GIS Parcel Viewer, https://spatial.vhb.com/onondaga/, searched 27 June 2025
- PFAS Exchange GIS Webviewer, https://experience.arcgis.com/experience/12412ab41b3141598e0bb48523a7c940/
- United States Census Bureau, North American Industry Classification System, https://www.census.gov/naics/
- US EPA 40 CFR Part 302 (EPA-HQ-OLEM-2019-0341; FRL-7204-03-OLEM), RIN 2050-AH09, Designation of Perfluorooctanoic Acid (PFOA) and Perfluorooctanesulfonic Acid (PFOS) as CERCLA Hazardous Substances, Final Rule, 8 May 2024
- US EPA ECHO database: http://echo.epa.gov/facilities searched 27 June 2025
- US EPA ECHO: PFAS Analytic Tools - https://echo.epa.gov/trends/pfas-tools
- US EPA ENVIROFACTS database: https://www3.epa.gov/enviro/ searched 27 June 2025
- US EPA MyProperty database: https://www3.epa.gov/enviro/facts/myproperty/ searched 27 July 2025

Table 7-1 Dates of Assessment Components

COMPONENT	DATE
Interviews	24 June 2025
Review of government records	27 June 2025
Site reconnaissance	24 June 2025
Declaration by Environmental Professional	30 October 2025

8. LIMITATIONS AND DEFINITIONS

This Phase I ESA report was prepared for Client and is intended to be used in its entirety. Excerpts taken from this report are not necessarily representative of the assessment findings. The Client is the sole intended beneficiary of the report. The user requested no special terms or conditions regarding this Phase I ESA.

Langan's scope of services, which is described in Section 1.2 and in the contract executed between Langan and the Client, was limited to that agreed to with the Client/user and no other services beyond those explicitly stated are implied. To the extent possible, the services performed and agreed upon for this Phase I ESA are consistent with the guidelines of ASTM E1527-21.

This report is not intended to be an exhaustive assessment of the subject property. The purpose of the Phase I ESA is to reduce uncertainty about unknown conditions at the subject property. No environmental site assessment can wholly eliminate uncertainty regarding the potential for RECs in connection with a subject property. Therefore, Langan cannot "verify," "insure," "certify", or "guarantee" that the subject property is free of environmental concerns.

No expressed or implied representation or warranty is included or intended in this report, except that our services were completed using the care and skill ordinarily followed by professionals providing similar services under similar circumstances in similar locations at the same point in time.

The conclusions provided in this report are based solely on information obtained through completing the standard activities required by ASTM E1527-21 and are intended exclusively for the purpose stated herein, at the specified subject property, as it existed at the point in time the assessment was completed. The conclusions provided in this report do not apply to conditions and features of which Langan was not made aware of through good faith efforts to complete the activities required by ASTM E1527-21 and did not have the opportunity to evaluate.

8.1 ASTM Definitions

The following definitions are provided in ASTM E1527-21 and presented below for reference. This section is not a comprehensive list of definitions provided in ASTM E1527-21 and is intended to summarize those pertinent to this Phase I ESA report.

Activity and use limitations (AULs): legal or physical restrictions or limitations on the use of, or access to, a site or facility: (1) to reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil, soil vapor, groundwater, and/or surface water on the property, or (2) to prevent activities that could interfere with the effective-ness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or engineering controls, are intended to prevent adverse impacts to individuals or populations that may be exposed to hazardous substances and petroleum products in the soil, soil vapor, groundwater, and/or surface water on a property.

Adjoining properties: any real property or properties the border of which is contiguous or partially contiguous with that of the subject property, or that would be contiguous or partially contiguous with that of the subject property but for a street, road, or other public thoroughfare separating them.

All Appropriate Inquiries: that inquiry constituting all appropriate inquiries into the previous ownership and uses of the subject property consistent with good commercial and customary practice as defined in CERCLA, 42 U.S.C.§ 9601(35)(B) and 40 C.F.R. Part 312, that will qualify a party to a commercial real estate transaction for one of the threshold criteria for satisfying the LLPs to CERCLA liability (42U.S.C. §§ 9601(35)(A) & (B), § 9607(b)(3), § 9607(q), and§ 9607(r)), assuming compliance with other elements of the defense.

Approximate minimum search distance: the area for which records must be obtained and reviewed pursuant to ASTM E1527-21 Section 8 subject to the limitations provided in that section. This may include areas outside the subject property and shall be measured from the nearest subject property boundary. This term is used in lieu of radius to include irregularly shaped properties.

Business environmental risk (BER): a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of commercial real estate, not necessarily related to those environmental issues required to be investigated in this practice. Consideration of BER issues may involve addressing one or more non-scope considerations.

Controlled recognized environmental condition (CREC): recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations).

Data gap: a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. Data gaps may result from incompleteness in any of the activities required by this practice, including, but not limited to, site reconnaissance (for example, an inability to conduct the site visit), and interviews (for example, an inability to interview the key site manager, regulatory officials, etc.).

De minimis condition: a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a de minimis condition is not a recognized environmental condition nor a controlled recognized environmental condition.

Engineering controls: physical modifications to a site or facility (for example, capping, slurry walls, or point of use water treatment) to reduce or eliminate the potential for exposure to hazardous substances or petroleum products in the soil or groundwater on a property. Engineering controls are a type of activity and use limitation (AUL).

Environment: environment shall have the same meaning as the definition of environment in CERCLA 42 U.S.C. § 9601(8).

Historical recognized environmental condition (HREC): previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations). A historical recognized environmental condition is not a recognized environmental condition.

Institutional controls (IC): a legal or administrative mechanism (for example, "deed restrictions," restrictive covenants, easements, or zoning) on the use of, or access to, a site or facility to (1) reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil or groundwater on the property, or (2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. An institutional control is a type of activity and use limitation (AUL).

Key site manager: the person identified by the owner or operator of a subject property as having good knowledge of the uses and physical characteristics of the subject property.

Material threat: obvious threat which is likely to lead to a release and that, in the opinion of the environmental professional, would likely result in impact to public health or the environment.

Obvious: that which is plain or evident; a condition or fact that could not be ignored or overlooked by a reasonable observer.

Property use limitation: limitation or restriction on current or future use of a property in connection with a response to a release, in accordance with the applicable regulatory authority or authorities that allows hazardous sub-stances or petroleum products to remain in place at concentrations exceeding unrestricted use criteria.

Reasonably ascertainable: information that is (1) publicly available, (2) obtainable from its source within reasonable time and cost constraints, and (3) practically reviewable.

Recognized environmental conditions: (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment. For the purposes of this definition, "likely" is that which is neither certain nor proved, but can be expected or believed by a reasonable observer based on the logic and/or experience of the environmental professional, and/or available evidence, as stated in the report to support the opinions given therein.

Release: a release of any hazardous substance or petroleum product shall have the same meaning as the definition of "release" in CERCLA 42 U.S.C. § 9601(22). There are a number of statutory exclusions from the definition of release that may impact the environmental professional's opinions and conclusions, such as the normal application of fertilizer.

Significant data gap: a data gap that affects the ability of the environmental professional to identify a recognized environmental condition.

Site reconnaissance: that part that is contained in Section 9 of ASTM E1527-21 and addresses what should be done in connection with the site visit. The site reconnaissance includes, but is not limited to, the site visit done in connection with such a Phase I Environmental Site Assessment.

Site visit: the visit of the subject property during which observations are made constituting the site reconnaissance section of this practice.

Subject property: the property that is the subject of the environmental site assessment described in this practice.

User: the party seeking to use ASTM E1527-21 to complete an environmental site assessment of the subject property.

Standard Environmental Record Sources

8.2 Langan reviewed an environmental database search report prepared by an environmental database search provider for the subject property and surrounding area. The database search report includes a listing of properties identified on select federal, state, local and tribal standard source environmental databases within the approximate minimum search radii outlined in ASTM E1527-21. This information was supplied to Langan by the environmental database search provider, and to the environmental database search provider by government sources; therefore, neither Langan nor the environmental database search provider can verify the completeness and accuracy of the database information. Appendix F contains a copy of the report, with specific source and property descriptions, and the dates of the last update for each database searched. Langan reviewed the database search report on a record-by-record basis to evaluate if certain properties identified in the database report are likely to represent an environmental concern for the subject property. The evaluation criteria included factors such as distance, groundwater gradient, nature of the listing, and regulatory status. Unless specifically discussed in the body of this report, the facilities listed on the database do not appear to represent an environmental concern to the subject property.

Appendix A Figures



LANGAN
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
T: 212.479.5400 F: 212.479.5444
www.langan.com

Project	EAST ADAMS REDEVELOPMENT - PHASE VIII AREA SYRACUSE ONONDAGA COUNTY NEW YORK
Figure Title	SUBJECT PROPERTY LOCATION MAP
Project No.	170859701
Date	11/25/2025
Scale	1" = 2,000'
Drawn By	GS
Figure	1

© 2025 Langan



Legend

- Subject Property
- Parcel Boundary
- Rail Lines
- Inferred Groundwater Flow Direction
- Monitoring Wells

Notes:
1. Aerial imagery provided through Langan's subscription to Near Map, dated 04/30/2025.
2. Parcel data provided by Onondaga County.
3. All locations of site reconnaissance observations are approximate.
4. Groundwater flow direction inferred from review of topographic maps.

WARNING: It is a violation of the NYS Education Law Article 145 for any person, unless he is acting under the direction of a licensed professional engineer, to alter this item in any way.

70 0 70
SCALE IN FEET

LANGAN
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
T: 212.479.5400 F: 212.479.5444 www.langan.com

Project
EAST ADAMS REDEVELOPMENT - PHASE VIII AREA
SYRACUSE
ONONDAGA COUNTY NEW YORK

Figure Title
SUBJECT PROPERTY LAYOUT

Project No.	170859701
Date	11/25/2025
Scale	1"=70'
Drawn By	GS

Figure 2

© 2025 Langan

Path: \\langan.com\data\NYC\data7\170859701\Project Data\ArcGIS\APRX\170859701 Phase 4-12\170859701 Phase 4-12.aprx Date: 11/25/2025 User: Gsajbel Time: 4:15 PM



Legend

- Subject Property
- Parcel Boundary
- Inferred Groundwater Flow Direction

Notes:
1. Aerial imagery provided through Langan's subscription to Near Map, dated 04/30/2025.
2. Parcel data provided by Onondaga County.
3. Groundwater flow direction inferred from review of topographic maps.

WARNING: It is a violation of the NYS Education Law Article 145 for any person, unless he is acting under the direction of a licensed professional engineer, to alter this item in any way.

200 0 200
SCALE IN FEET

LANGAN
Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C.
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
T: 212.479.5400 F: 212.479.5444 www.langan.com

Project
EAST ADAMS REDEVELOPMENT - PHASE VIII AREA
SYRACUSE
ONONDAGA COUNTY NEW YORK

Figure Title
NEARBY PROPERTIES MAP

Project No. 170859701
Date 7/3/2025
Scale 1"=200'
Drawn By GS

Figure 3

© 2025 Langan

Path: \\langan.com\data\NYC\data7\170859701\Project Data\ArcGIS\APRX\170859701 Phase 4-12\170859701 Phase 4-12.aprx Date: 7/3/2025 User: Gsajbel Time: 12:54 PM

Appendix B Agency Records and Other Reports

REZONE SYRACUSE
A Citywide Zoning Update

REZONE SYRACUSE ZONING MAP

Syracuse New York



LEGEND

Zoning Designations

Residential Districts

- R1 Single Unit Residential
- R2 Low Density Residential
- R3 Small Lot Residential
- R4 Medium Density Residential
- R5 High Density Residential

Mixed-Use Business

- MX-1 Urban Neighborhood
- MX-2 Neighborhood Center
- MX-3 Mixed-Use Transition
- MX-4 Urban Core
- MX-5 Central Business District

Non-Residential Districts

- CM Commercial
- LI Light Industry and Employment

Special Purpose Districts

- OS Open Space

Planned Development Districts

- PID Planned Institutional
- PDD Planned Development

0 1,000 2,000 3,000 4,000 5,000 Feet

0 0.25 0.5 0.75 1 Miles

N

March 27, 2023

An official website of New York State.
Here's how you know

NYS Department of Environmental Conservation
DER Environmental Remediation Databases

Details from Spill Incidents Database Search

Spill Record

Administrative Information

DEC Region: 7
Spill Number: 2308014

Spill Date/Time

Spill Date: 12/28/2023
Spill Time: 12:00:00 PM
Call Received Date: 01/04/2024
Call Received Time: 12:20:00 PM

Location

Spill Name: ERP SITE
Address: 1226 MCBRIDE ST
City: SYRACUSE
County: Onondaga

Spill Description

Material Spilled	Amount Spilled	Resource Affected
unknown petroleum	Unknown	Groundwater

Cause: Unknown
Source: Commercial/Industrial
Waterbody:

Record Close

Date Spill Closed: Not Closed

If you have questions about this reported incident, please contact the Regional Office where the incident occurred.

Refine This Search

- Русский
- יידיש
- বাংলা
- 한국어
- Kreyòl Ayisyen
- Italiano
- العربية
- Polski
- Français
- اردو

Detailed Facility Report

Facility Summary

SYRACUSE HOUSING AUTHORITY

409 BURT STREET, SYRACUSE, NY 13202

FRS (Facility Registry Service) ID: 110004313706

EPA Region: 02

Latitude: 43.03835

Longitude: -76.14528

Locational Data Source: FRS

Industries: Administration of Housing Programs, Urban Planning, and Community Development

Indian Country: N

Enforcement and Compliance Summary

Statute	RCRA
Compliance Monitoring Activities (5 years)	--
Date of Last Compliance Monitoring Activity	--
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	--
Formal Enforcement Actions (5 years)	--
Penalties from Formal Enforcement Actions (5 years)	--
EPA Cases (5 years)	--
Penalties from EPA Cases (5 years)	--

Regulatory Information

Clean Air Act (CAA): No Information

Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Active LQG, (NY0000201889)

Safe Drinking Water Act (SDWA): No Information

Other Regulatory Reports

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Go To Enforcement/Compliance Details

Known Data Problems <https://epa.gov/resources/echo-data/known-data-problems>

Facility/System Characteristics

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110004313706					N	43.03835	-76.14528
RCRAInfo	RCRA	NY0000201889	LQG	Active (H)			N	43.038331	-76.145417

Facility Address

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110004313706	SYRACUSE HOUSING AUTHORITY	409 BURT STREET, SYRACUSE, NY 13202	Onondaga County
RCRAInfo	RCRA	NY0000201889	SYRACUSE HOUSING AUTHORITY	409 BURT ST, SYRACUSE, NY 13202	Onondaga County

Facility SIC (Standard Industrial Classification) Codes

System	Identifier	SIC Code	SIC Description

No data records returned

Facility NAICS (North American Industry Classification System) Codes

System	Identifier	NAICS Code	NAICS Description
RCRAInfo	NY0000201889	92511	Administration of Housing Programs

Facility Tribe Information

Reservation Name	Tribe Name	EPA Tribal ID	Distance to Tribe (miles)
Oneida Indian Nation Reservation	Oneida Indian Nation	100000182	10
Onondaga Nation Reservation	Onondaga Nation	100000184	5

Enforcement and Compliance

Compliance Monitoring History

Last 5 Years

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <https://www.epa.gov/compliance/compliance-monitoring-programs> *activities or because they are not counted as inspections within EPA's Annual Results* <https://www.epa.gov/enforcement/enforcement-data-and-results>.

Compliance Summary Data

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
RCRA	NY0000201889	No	06/21/2025	0	06/20/2025

Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type		QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11
RCRA (Source ID: NY0000201889)			07/01-09/30/22	10/01-12/31/22	01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25
	Facility-Level Status		No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified
	Violation	Agency											

Informal Enforcement Actions

Last 5 Years

Statute	System	Source ID	Type of Action	Lead Agency	Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

Formal Enforcement Actions

Last 5 Years

Statute	System	Law/ Section	Source ID	Type of Action	Case No.	Lead Agency	Case Name	Issued/ Filed Date	Settlements/ Actions	Settlement/ Action Date	Federal Penalty Assessed	State/ Local Penalty Assessed	Penalty Amount Collected	SEP Value	Comp Action Cost

No data records returned

Environmental Conditions

Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?

No data records returned

Assessed Waters From Latest State Submission (ATTAINS)

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use

No data records returned

Air Quality Nonattainment Areas

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)
Ozone	No	--	No	--
Lead	No	--	No	--
Particulate Matter	No	--	No	--
Carbon Monoxide	No	--	Yes	Carbon Monoxide (1971)
Sulfur Dioxide	No	--	No	--

Pollutants

Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID	Year	Air Emissions	Surface Water Discharges	Off-Site Transfers to POTWs (Publicly Owned Treatment Works)	Underground Injections	Disposal to Land	Total On-Site Releases	Total Off-Site Transfers

No data records returned

Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

Community

Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2022 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <https://epa.gov/help/reports/dfr-data-dictionary#demographic>.

General Statistics (ACS (American Community Survey))	
Total Persons	25,455
Population Density	8,155/sq.mi.
Housing Units in Area	10,108
Percent People of Color	62%
Households in Area	8,009
Households on Public Assistance	652
Persons With Low Income	12,379
Percent With Low Income	72%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	43.03835
Center Longitude	-76.14528
Total Area	3.121 sq.mi.
Land Area	100%
Water Area	0%

Income Breakdown (ACS (American Community Survey)) - Households (%)	
Less than $15,000	2,630 (32.84%)
$15,000 - $25,000	1,298 (16.21%)
$25,000 - $50,000	1,829 (22.84%)
$50,000 - $75,000	916 (11.44%)
Greater than $75,000	1,335 (16.67%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)	
Children 5 years and younger	1,038 (4%)
Minors 17 years and younger	4,134 (16%)
Adults 18 years and older	21,319 (84%)
Seniors 65 years and older	1,581 (6%)

Race Breakdown (ACS (American Community Survey)) - Persons (%)	
White	10,488 (41%)
African-American	9,408 (37%)
Hispanic-Origin	3,177 (12%)
Asian	2,455 (10%)
Hawaiian/Pacific Islander	1 (0%)
American Indian	170 (1%)
Other/Multiracial	2,159 (8%)

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)	
Less than 9th Grade	763 (6.76%)
9th through 12th Grade	1,531 (13.56%)
High School Diploma	3,235 (28.64%)
Some College/2-year	1,982 (17.55%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	3,017 (26.71%)

Related Topics: Envirofacts

FRS

FRS Facility Detail Report

SYRACUSE HOUSING AUTHORITY

EPA Registry Id: 110004313706
409 BURT STREET
SYRACUSE, NY 13202



Legend

- Selected Facility
- EPA Facility of Interest
- State/Tribe Facility of Interest

The facility locations displayed come from the FRS Spatial Coordinates tables. They are the best representative locations for the displayed facilities based on the accuracy of the collection method and quality assurance checks performed against each location. The North American Datum of 1983 is used to display all coordinates.

Facility Registry Service Links:

- Facility Registry Service (FRS) Overview
- FRS Facility Query
- FRS Organization Query
- EZ Query
- FRS Physical Data Model
- FRS Geospatial Model

Environmental Interests

Information System	System Facility Name	Information System Id/Report Link	Environmental Interest Type	Data Source	Last Updated Date	Supplemental Environmental Interests:
RESOURCE CONSERVATION AND RECOVERY ACT INFORMATION SYSTEM	SYRACUSE HOUSING AUTHORITY	NY0000201889	LQG (Y)	RCRAINFO		
BIENNIAL REPORTERS	SYRACUSE HOUSING AUTHORITY	NY0000201889	HAZARDOUS WASTE BIENNIAL REPORTER	RCRAINFO	12/31/2009	

Additional EPA Reports: MyEnvironment Enforcement and Compliance Facility Coordinates Viewer Watershed Report

Standard Industrial Classification Codes (SIC)

No SIC Codes returned.

Facility Codes and Flags

EPA Region:	02
Duns Number:	
Congressional District Number:	24
Legislative District Number:	NY
HUC Code/Watershed:	04140201 / SENECA
US Mexico Border Indicator:	
Federal Facility:	NO
Tribal Land:	NO

Alternative Names

No Alternative Names returned.

Organizations

Affiliation Type	Name	DUNS Number	Information System	Mailing Address
OPERATOR	SYRACUSE HOUSING AUTHORITY		RCRAINFO	View
OPERATOR	SYRACUSE HOUSING AUTHORITY		RCRAINFO	
OWNER	SYRACUSE HOUSING AUTHORITY		RCRAINFO	View
OWNER	SYRACUSE HOUSING AUTHORITY		RCRAINFO	

National Industry Classification System Codes (NAICS)

Data Source	NAICS Code	Description	Primary
RCRAINFO	92511	ADMINISTRATION OF HOUSING PROGRAMS	

Facility Mailing Addresses

Affiliation Type	Delivery Point	City Name	State	Postal Code	Information System
OPERATOR	409 BURT ST	SYRACUSE	NY	13202	RCRAINFO
OWNER	409 BURT ST	SYRACUSE	NY	13202	RCRAINFO
FACILITY MAILING ADDRESS	516 BURT ST	SYRACUSE	NY	13202	RCRAINFO

Contacts

Affiliation Type	Full Name	Office Phone	Information System	Mailing Addres
REGULATORY CONTACT	WILLIAM W GEHRKE	3154756181 4318	RCRAINFO	
REGULATORY CONTACT	WILLIAM W GEHRKE	1478611	RCRAINFO	
REGULATORY CONTACT	WILLIAM W GEHRKE	315-475-6181 X4318	RCRAINFO	

Query executed on: JUN-27-2025

Last updated on September 24, 2015

EPA

BR Facility Summary Report

SYRACUSE HOUSING AUTHORITY
409 BURT STREET
SYRACUSE, NY 13202
**You can navigate within the map with your mouse.*

ACRES

No ACRES report found.

BR

Handler ID: NY0000201889 —

Facility Information

HANDLER NAME: <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/handler_name>	SYRACUSE HOUSING AUTHORITY	**HANDLER ID:** <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/handler_id>	NY0000201889
STREET 1: <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/location_street1>	BURT ST	**REPORTING YEAR:** <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/report_cycle>	2009
STREET 2: <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/location_street2>			
CITY: <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/location_city>	SYRACUSE	**GENERATOR STATUS:** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/fed_waste_generator>	Federal = LQG
STATE: <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/location_state>	NY	**ZIP CODE:** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/location_zip>	13202
COUNTY: <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/county_name>	ONONDAGA	**PENALTY:** <https://epa.gov/envirofacts/metadata/column/rcra/rcr_cmecomp3/final_amount>	

Mailing Information

HANDLER NAME: <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/handler_name>	SYRACUSE HOUSING AUTHORITY
STREET 1: <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/mail_street1>	BURT ST
STREET 2: <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/mail_street2>	
CITY: <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/mail_city>	SYRACUSE
STATE: <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/mail_state>	NY
ZIP CODE: <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/mail_zip>	13202

Basic Waste Information

WASTE TYPE	NATIONAL REPORT (Tons)
Generation <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/generation_tons>	2.203
Management <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/managed_tons>	
Waste Received <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/received_tons>	
Waste Shipped <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/shipped_tons>	2.203
Incineration <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/generation_tons>	

WASTE TYPE	NATIONAL REPORT (Tons)
Disposal <https://epa.gov/envirofacts/metadata/column/rcra/br_reporting/generation_tons>	

Additional information can be obtained from Biennial Reporting (BR) Search.

SEMS

No SEMS report found.

GHG

No GHG report found.

ICIS-AIR

No ICIS-AIR report found.

ICIS-NPDES

No ICIS-NPDES report found.

RCRAInfo

Handler ID: NY0000201889 —

Handler ID: <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_handler/handler_id> NY0000201889

List of Naics Codes and Descriptions

Naics Code <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_naics/naics_code>	Naics Description <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_lu_naics/naics_desc>
92511	ADMINISTRATION OF HOUSING PROGRAMS

Handler / Facility Classification

Unspecified Universe for the facility listed above.

Handler Type <https://epa.gov/envirofacts/metadata/column/rcra/rcr_hd_reporting/in_a_universe>
Large Quantity Generator

Additional information can be obtained from Resource Conservation and Recovery Information (RCRAInfo) Search.

TRI

No TRI report found.

Contact Us <https://www.epa.gov/enviro/forms/contact-us-about-envirofacts> to ask a question, provide feedback, or report a problem.

Last updated on June 25, 2025

Facility Information from Bulk Storage Database

Site Number: 7-000152
Status: Unregulated/Closed

An official website of New York State.
Here's how you know

NYS Department of Environmental Conservation
DER Environmental Remediation Databases

Zipcode: 13202
County: Onondaga

Facility (Property) Owner(s) Information

Facility Owner: SYRACUSE UNIVERSITY
Mail Contact: SYRACUSE UNIVERSITY, SKYTOP ROAD, SYRACUSE, NY, 13244

Facility Operator

Facility Operator: THOMAS REDDINGER

Tank Information

Tank No.	Tank Location	Status	Capacity (Gal.)
001	Aboveground on saddles, legs, stilts, rack or cradle	Closed - Removed	1500
002	Aboveground on saddles, legs, stilts, rack or cradle	Closed - Removed	200
002-A	Aboveground on saddles, legs, stilts, rack or cradle	Tank Converted to Non-Regulated use	1000
003	Aboveground on saddles, legs, stilts, rack or cradle	Closed - Removed	200

Tank No.	Tank Location	Status	Capacity (Gal.)
003-A	Aboveground on saddles, legs, stilts, rack or cradle	Tank Converted to Non-Regulated use	1000
004	Aboveground on saddles, legs, stilts, rack or cradle	Tank Converted to Non-Regulated use	1000

Refine This Search

DER Environmental Remediation Databases Privacy Policy Terms of Service

- AgenciesApp DirectoryCountiesEventsProgramsServices

Translate
Translation Services
This page is available in other languages

- English
- Español
- 中文
- 繁體中文
- Русский
- יידיש
- বাংলা
- 한국어
- Kreyòl Ayisyen
- Italiano
- العربية
- Polski
- Français
- اردو

An official website of New York State.
Here's how you know

NYS Department of Environmental Conservation
DER Environmental Remediation Databases

Facility Information from Bulk Storage Database

Facility Information

Site Number: 7-180602
Status: Active
Expiration Date: 06/18/2027
Site Type: PBS
Facility Type: School
Site Name: SYRACUSE UNIVERSITY STEAM STATION
Address: 500 EAST TAYLOR ST
Locality: Syracuse
State: NY
Zipcode: 13202
County: Onondaga

Facility (Property) Owner(s) Information

Facility Owner: SYRACUSE UNIVERSITY
Mail Contact: SYRACUSE UNIVERSITY, ENVIRONMENTAL HEALTH & SAFETY SERVICES, SYRACUSE, NY, 13244-1270

Facility Operator

Facility Operator: NATHAN PRIOR - CENTRIO ENERGY

Tank Information

Tank No.	Tank Location	Status	Capacity (Gal.)
001	Underground including vaulted with no access for inspection	Closed Prior to 03/1991	30000
002	Underground including vaulted with no access for inspection	Closed Prior to 03/1991	30000
003	Underground including vaulted with no access for inspection	Closed Prior to 03/1991	15000
005	Underground including vaulted with no access for inspection	In Service	30000
006	Underground including vaulted with no access for inspection	In Service	30000
007	Underground including vaulted with no access for inspection	In Service	30000
008	Underground including vaulted with no access for inspection	In Service	30000
009	Aboveground on saddles, legs, stilts, rack or cradle	Closed - Removed	275
010	Aboveground on saddles, legs, stilts, rack or cradle	Closed - Removed	300

Refine This Search

Appendix C Site Reconnaissance Checklist and Photographs

LANGAN

Site Reconnaissance Photographs

Client Name:	Subject Property Location:	Project No.
MBSDI	East Adams Redevelopment – Phase VIII (Burt Street)	170859701

Date	Photo No.
6-24-25	1

Direction Photo Taken:

East

Description:

General view of the western side of the subject property at 8 Burt Street.

Date	Photo No.
6-24-25	2

Direction Photo Taken:

North

Description:

Storage containers at the subject property.

LANGAN	Site Reconnaissance Photographs	
Client Name: MBSDI	**Subject Property Location:** East Adams Redevelopment – Phase VIII (Burt Street)	**Project No.** 170859701

Date	**Photo No.**
6-24-25	3

Direction Photo Taken:

North

Description:

Additional storage containers at the subject property

Date	**Photo No.**
6-24-25	4

Direction Photo Taken:

Northwest

Description:

Partial view of the wooded area at the subject property

Client Name:	Subject Property Location:	Project No.
MBSDI	East Adams Redevelopment – Phase VIII (Burt Street)	170859701

Date	Photo No.
6-24-25	5

Direction Photo Taken:

Northeast

Description:

A metal structure along the southern side of the subject property

Date	Photo No.
6-24-25	6

Direction Photo Taken:

West

Description:

General view of the eastern side of the subject property

LANGAN	Site Reconnaissance Photographs	
Client Name: MBSDI	**Subject Property Location:** East Adams Redevelopment – Phase VIII (Burt Street)	**Project No.** 170859701

Date	**Photo No.**
6-24-25	7

Direction Photo Taken:

South

Description:

A monitoring well near the central and northern side of the subject property

Date	**Photo No.**
6-24-25	8

Direction Photo Taken:

East

Description:

A monitoring well on the southeastern corner of the subject property

LANGAN

Site Reconnaissance Photographs

Client Name:	Subject Property Location:	Project No.
MBSDI	East Adams Redevelopment – Phase VIII (Burt Street)	170859701

Date	Photo No.
6-24-25	9

Direction Photo Taken:

Northwest

Description:

An apparent overturned monitoring well cover on the southern side of the subject property

Date	Photo No.
6-24-25	10

Direction Photo Taken:

Northwest

Description:

An unlabeled 55-gallon steel drum staged on the southeastern side of the subject property

LANGAN

Site Reconnaissance Photographs

Client Name:	Subject Property Location:	Project No.
MBSDI	East Adams Redevelopment – Phase VIII (Burt Street)	170859701

Date	Photo No.
6-24-25	11

Direction Photo Taken:

North

Description:

View of the adjoining parking lot area to the north of the subject property

Date	Photo No.
6-24-25	12

Direction Photo Taken:

North

Description:

View of the adjoining elevated railroad tracks to the north and the neighboring steam station to the north

LANGAN

Site Reconnaissance Photographs

Client Name:	Subject Property Location:	Project No.
MBSDI	East Adams Redevelopment – Phase VIII (Burt Street)	170859701

Date	Photo No.
6-24-25	13

Direction Photo Taken:

East

Description:

View of the parking lot and elevated railroad to the east of the subject property, across South McBride Street

Date	Photo No.
6-24-25	14

Direction Photo Taken:

Southeast

Description:

View of the adjoining residential building to the south, across Burt Street

Client Name:	Subject Property Location:	Project No.
MBSDI	East Adams Redevelopment – Phase VIII (Burt Street)	170859701

Date	Photo No.
6-24-25	15

Direction Photo Taken:

Southwest

Description:

View of the adjoining commercial property and wooded area to the west, across Oakwood Avenue

Date	Photo No.
6-24-25	16

Direction Photo Taken:

Northwest

Description:

View of an additional adjoining commercial property to the west, across Oakwood Avenue

Client Name:	Subject Property Location:	Project No.
MBSDI	East Adams Redevelopment – Phase VIII (Burt Street)	170859701

LANGAN

PHASE I ESA SITE RECONNAISSANCE CHECKLIST

GENERAL INFORMATION
Langan personnel: Olivia Miller
Date of site reconnaissance: 24 June 2025
Business name / subject property occupant: East Adams Redevelopment – Phase VIII (Burt Street)
Full subject property address: 1226 South McBride Street and 407-409 Burt Street Syracuse, New York 13202
Weather conditions: 85ºF, Sunny

Features, Activities, Uses, and Conditions	**Identified/Observed?**		**Report Section(s)**
General Subject Property Setting	**Yes**	**No**	
Current use(s) of the subject property	☒	☐	2.0
Past use(s) of the subject property	☒	☐	3.1
Current use(s) of adjoining properties	☒	☐	4.1
Past use(s) of adjoining properties	☒	☐	4.2
Current or past uses in the surrounding area	☒	☐	4.1 and 4.2
Geologic, hydrogeologic, hydrologic, and topographic conditions	☒	☐	2.2
Structures and other improvements at the subject property	☒	☐	2.3
Roads	☒	☐	2.3
Potable water supply/source for the subject property	☐	☒	2.4
Sewage disposal system for the subject property	☐	☒	2.4

Interior/Exterior Features	**At Interior?**		**At Exterior?**		**Report Section(s) (if yes)**
	Yes	**No**	**Yes**	**No**	
Hazardous substances and petroleum products in connection with identified uses	☐	☒	☐	☒	2.5
Storage tanks	☐	☒	☐	☒	2.5.1 and 2.5.2
Strong, pungent, or noxious odors and their sources	☐	☒	☐	☒	2.6
Standing surface water and pools or sumps containing liquids likely to be hazardous substances or petroleum products	☐	☒	☐	☒	2.5
Drums, totes, and intermediate bulk containers	☐	☒	☒	☐	2.5.3
Hazardous substance and petroleum product containers not in connection with identified uses	☐	☒	☐	☒	2.5.4
Unidentified substance containers	☐	☒	☒	☐	2.5.4
PCB-containing items	☐	☒	☐	☒	2.5.4
Heating/cooling	☐	☒	☐	☒	2.4
Stains or corrosion on floors, walls, or ceilings	☐	☒	☐	☒	2.5 and 2.7
Drains and sumps	☐	☒	☐	☒	2.8
Pits, ponds, or lagoons	☐	☒	☐	☒	2.2.3
Stained soil or pavement	☐	☒	☐	☒	2.5 and 2.7
Stressed vegetation	☐	☒	☐	☒	2.9
Solid waste	☐	☒	☐	☒	2.7
Water/wastewater	☐	☒	☐	☒	2.8 and 2.9
Wells	☐	☒	☒	☐	2.2.3
Septic systems or cesspools	☐	☒	☐	☒	2.8

Appendix D User Provided Information

User Questionnaire
Introduction/Limitations
November 2021

The information in this User Questionnaire is prepared and provided by the *user** to the environmental professional pursuant to 40 CFR 313.22 in order to qualify for one of the *Landowner Liability Protections* (LLPs) offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the *"Brownfields Amendments"*). The user must conduct the following inquiries required by 40 C.F.R. §§ 312.25, 312.28, 312.29, 312.30, and 312.31. These inquiries must also be conducted by EPA Brownfield Assessment and Characterization grantees. The user should provide the following information to the environmental professional. Failure to conduct these inquiries could result in a determination that "all appropriate inquiries" is not complete.

*Pursuant to ASTM E 1527-21, the "user" is the party seeking to complete the environmental site assessment of the property. It is also the person seeking to establish one or more of the Landowner Liability Protections (LLPs) under CERCLA. A user may include, without limitation, a potential purchaser or potential leasee or tenant of the property, an owner of the property, a lender or a property manager.

DATE PREPARED: 7.16.25

SUBJECT PROPERTY (address): East Adams VIII, NE Corner of Burt St. & Oakwood Ave., Syracuse, NY

USER(S): East Adams Phase VIII, L.P.

NAME OF PERSON COMPLETING QUESTIONNAIRE: Michael Saunders

(1) Environmental liens that are filed or recorded against the subject property (40 C.F.R. § 312.25).

Did a search of land title records (or judicial records where appropriate, see Note 1 below) identify any environmental liens filed or recorded against the subject property under federal, tribal, state, or local law?

NOTE 1—In certain jurisdictions, federal, tribal, state, or local statutes, or regulations specify that *environmental liens* and *AULs* be filed in judicial records rather than in *land title records*. In such cases judicial records shall be searched for *environmental liens* and *AULs*.

Answer: The Environmental Professional is hereby requested to conduct the search for environmental cleanup liens and the results will be included in the Phase I Report. Except as provided in the Phase I Report, the user has not identified any environmental cleanup liens.

(2) Activity and use limitations that are in place on the subject property or that have been filed or recorded against the subject property.

Did a search of land title records (or judicial records where appropriate, see Note 1 above) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the subject property and/or have been filed or recorded against the subject property under federal, tribal, state or local law?

Answer: The Environmental Professional is hereby requested to perform the search for AULs and the results will be included in the Phase I Report. Except as provided in the Phase I Report, the user has not identified any AULs for the subject property.

(3) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 C.F.R. § 312.28).

Do you have any specialized knowledge or experience related to the subject property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the subject property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

Answer: The user is a developer of multifamily and mixed-use properties and has provided to the Environmental Professional all specialized knowledge, if any, that is has in connection with the subject property or nearby properties relevant to environmental matters.

(4) Relationship of the purchase price to the fair market value of the subject property if it were not contaminated (40 C.F.R. § 312.29).

Does the purchase price being paid for this subject property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the subject property?

Answer: In the opinion of the user, the lease price reasonably reflects the fair market value of the subject property, given the non-environmental use restrictions imposed as part of the lease. The user believes the lease price reflects several factors, including the overall physical and economic conditions at and near the subject property and the seller's desire to encourage and incentivize redevelopment of the subject property for a public good. To the knowledge of the user, the lease price has not been adjusted to reflect any real or potential contamination that might be found at the subject property.

(5) Commonly known or reasonably ascertainable information about the subject property (40 C.F.R. § 312.30).

Are you aware of commonly known or reasonably ascertainable information about the subject property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example,

(a) Do you know the past uses of the subject property?

The user has provided the Environmental Professional with all relevant information/documents, if any, in its possession concerning former uses of the subject property.

(b) Do you know of specific chemicals that are present or once were present at the subject property?

The user has provided to the Environmental Professional all information/documents, if any, in its possession concerning specific chemicals that are present or once were present at the subject property.

(c) Do you know of spills or other chemical releases that have taken place at the subject property?

The user has provided the Environmental Professional with all information/documents, if any, in its possession concerning spills or other chemical releases at the subject property.

(d) Do you know of any environmental cleanups that have taken place at the subject property?

The user has provided to the Environmental Professional all information/documents, if any, in its possession concerning environmental cleanups that have taken place at the subject property.

(6) The degree of obviousness of the presence or likely presence of contamination at the subject property, and the ability to detect the contamination by appropriate investigation (40 C.F.R. § 312.31).

Based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of releases at the subject property?

Answer: To the user's knowledge, the subject property has been used for various commercial and industrial purposes, but the user has not observed obvious indication of contamination at the subject property, other than information/documents that have been provided to the Environmental Professional.

Additional Questions:

(I) Helpful Documents

Do you know whether any of the environmental documents listed in Section 10.8.1 of ASTM E1527-21 exist? If so, can copies be provided to the environmental professional?

Answer: The user has provided to the Environmental Professional all information/documents, if any, in its possession relevant to environmental evaluations conducted at or for the subject property.

(II) Proceedings Involving the Subject Property Questions

Do you know of:

(1) Any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, at, or from the subject property?

Answer: The user has provided to the Environmental Professional all information/documents, if any, in its possession concerning pending, threatened, or past litigation relevant to hazardous substances and/or petroleum products in, on, at or from the subject property.

(2) Any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, at, or from the subject property?

Answer: The user has provided to the Environmental Professional all information/documents, if any, in its possession concerning pending, threatened, or past administrative proceedings relevant to hazardous substances and/or petroleum products in, on, at or from the subject property.

(3) Any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?

Answer: The user has provided to the Environmental Professional all information/documents, if any, in its possession concerning any possible violation of environmental laws or possible liability related to hazardous substances and/or petroleum products with respect to the subject property.

Appendix E Historical Resources

East Adams Redevelopment - Phase 8 Area
409 Burt Street
Syracuse, NY 13202

Inquiry Number: 8026569.5
June 25, 2025

The EDR-City Directory Image Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available business directory data at approximately five year intervals.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2020	☑	☑	EDR Digital Archive
2017	☑	☑	Cole Information
2014	☑	☑	Cole Information
2010	☑	☑	Cole Information
2005	☑	☑	Cole Information
2000	☑	☑	Cole Information
1995	☑	☑	Cole Information
1992	☑	☑	Cole Information
1988	☑	☑	Polk's City Directory
1983	☑	☑	Polk's City Directory
1977	☑	☑	Polk's City Directory
1972	☑	☑	Polk's City Directory
1968	☑	☑	Polk's City Directory
1964	☑	☑	Polk's City Directory
1959	☑	☑	Polk's City Directory
1955	☑	☑	Polk's City Directory
1949	☑	☑	Polk's City Directory
1944	☑	☑	Polk's City Directory
1939	☑	☑	Polk's City Directory

FINDINGS

TARGET PROPERTY STREET

409 Burt Street
Syracuse, NY 13202

Year	*CD Image*	*Source*
BURT ST		
2020	pg A2	EDR Digital Archive
2017	pg A6	Cole Information
2014	pg A11	Cole Information
2010	pg A17	Cole Information
2005	pg A23	Cole Information
2000	pg A29	Cole Information
1995	pg A34	Cole Information
1992	pg A38	Cole Information
1988	pg A43	Polk's City Directory
1983	pg A45	Polk's City Directory
1983	pg A46	Polk's City Directory
1977	pg A48	Polk's City Directory
1972	pg A50	Polk's City Directory
1968	pg A52	Polk's City Directory
1964	pg A55	Polk's City Directory
1959	pg A58	Polk's City Directory
1955	pg A60	Polk's City Directory
1949	pg A63	Polk's City Directory
1944	pg A65	Polk's City Directory
1939	pg A67	Polk's City Directory

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*
S MCBRIDE ST		
2020	pg. A5	EDR Digital Archive
2017	pg. A9	Cole Information
2014	pg. A14	Cole Information
2010	pg. A20	Cole Information
2005	pg. A26	Cole Information
2000	pg. A31	Cole Information
1995	pg. A36	Cole Information
1992	pg. A41	Cole Information
1988	pg. A44	Polk's City Directory
1983	pg. A47	Polk's City Directory
1977	pg. A49	Polk's City Directory
1972	pg. A51	Polk's City Directory
1968	pg. A53	Polk's City Directory
1968	pg. A54	Polk's City Directory
1964	pg. A56	Polk's City Directory
1964	pg. A57	Polk's City Directory
1959	pg. A59	Polk's City Directory
1955	pg. A61	Polk's City Directory
1955	pg. A62	Polk's City Directory
1949	pg. A64	Polk's City Directory
1944	pg. A66	Polk's City Directory
1939	pg. A68	Polk's City Directory

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BURT ST 2020

300	ADLONIA EVANS
	AMBER PEEL
	ANDREA KILLINS
	ANGELA HALSELL
	ANNIE ANDERSON
	ANNIE EPPS
	APRIL THOMPSON
	ARTIE TYSON
	AVAS BADGER
	AVAS HATCHER
	AYANA PORTER
	BETTY GREENE
	BOBBY FORT
	BRENDA OLSON
	BRENDA ROACHE
	BRENDA SOLIVAN
	BRIAN EVANS
	CARL KNIGHT
	CARL WHITTY
	CARMEN GARCIA
	CHARLES BRANCH
	CHARLES BUCKNAM
	CHARLES DECUIR
	CHERYL JOHNSON-FORD
	CLARA HILL
	CRYSTAL DYKES
	CURTIS WILLIAMS
	CYNTHIA HATCHER
	DANA SMITH
	DAVID KELLY
	DERAY MCGEE
	DIANE KNIGHT
	DOLLICA EVERETT
	DREAMA BRAXTON
	DUANE AIKEN
	ELIZABETH STEWART
	ELOISE WILSON
	EMERY JACKSON
	EMMA HUDSON
	ERNEST JONES
	ETRENDIA COLLINS
	EVA COOPER
	EVE HENDERSON
	EVELYN BENNETT
	EVELYN FLORES
	FREADDIE BAXTRON
	FRED CARLISLE
	FREDERICA SWANSON
	GABRIELLE VANDUSER
	GARNELL MASON

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BURT ST 2020 (Cont'd)

300	GEORGE LESLIE
	GLADESHA LOCKWOOD
	GLEN LYLES
	HAROLD SALGADO
	HARRY RUSH
	HERMAN WRIGHT
	IVETTE MARQUEZ
	JAMES BERRY
	JAMILA DOW
	JAMIMALESON ALEXANDER
	JAZMIN BELL
	JENELLE SYSLO
	JENNIFER CUTTER
	JEROME SHARIF
	JESSICA MKONO
	JESSICA PHILLIPS
	JOHN GLOVER
	JOHN SULLIVAN
	JOHNNIE BAXTER
	JOHNNY RUFUS
	JOHNNY STROUD
	JONATHAN WHITEHURST
	JOSIE MIRANDA
	JUDITH KNOX
	KATRINA FREDERICK
	KHADIJA MAKARAN
	KIMELA GONZALEZ
	LACEY WHITE
	LATASHA JOHNSON
	LILLIE DECUIR
	LINDA MCDONALD
	LISA BALLARD
	LOI HUA
	LOUIS WALKER
	MADINA MUGANGA
	MANDY BRIGGS
	MARCUS PHOENIX
	MARGO TUCKER
	MARK HILL
	MARTHA ALLEN
	MARY MASSARD
	MEALS ON WHEELS
	MELODY SPENCER
	MELVIN HAYWARD
	MICHAEL MILNER
	MILDRED VINN
	MOISES CRUZ
	MONICA PACE
	MORGAN ROBINSON
	MORRIS ROBERSON

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BURT ST 2020 (Cont'd)

300	MYRA DEXTER
	NEHEMIAH JONES
	NORBERT BAKER
	OCTAVIA MCCARTHY
	OSMAN ABDALLA
	PATRICIA BROOKS
	PATRICIA HOEFLER
	PATRICIA IACOBELLO
	PAULETTE TWIGGS
	PEARL GERMAN
	PEGGY JONES
	QUAVAUN ALDAMUY
	RAYBON DOZIER
	RAYVON DOZIER
	REGINALD SWANSON
	RHONDA GOODWIN
	RICHARD BANKS
	ROBERT JACKSON
	ROBERT MOBLEY
	RONALD MCNEAL
	RONNIE GLOVER
	RONNIE GREGORY
	ROSA CHEEVES
	ROSETTA HUDDLESTON
	SANDIE SAMEDY
	SHAKWAN ROSA
	SHANNON BAXTER
	SHAWN ALDAMUY
	SHIRLEY BURROUGHS
	SHIRLEY PULLINS
	SHIRLEY RANDALL
	SIDNEY SCOTT
	SUZAN ANDERSON
	SYRACUSE BEHAVIORAL HEALTHCARE
	TANISHA WIGGINS
	TONY BARNUM
	TRAFINA COLEMAN
	TREVOR TAYLOR
	VALENTINO CLAUDIOORTEGA
	VALERIE SMITH
	VIRGINIA COOK
	WALLACE MCKINNON
	WANDA REEVES
	WESLEY BENT
	YURIEL AGOSTO
	YVETTE REESE
	YWCA
302	REFUGEE-IMMIGRANT SELF
450	FREEDOM COMMONS LLC

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

S MCBRIDE ST 2020

1038	KEYA KING
	TALISHA MONTANEZ
1039	SHAQUAN SPENCER
	YENNY PEREZ
1040	KIEWANNA HUDDLESTON
1042	ROMAN CANNANDY
1043	TARA HARRIS
	TYREMA JOHNSON
1044	DARIES PERRY
	ROSE WILLIAMS
1045	ALEXANDER JENNINGS
1046	GREG MYERS
1100	IDA HALL
1102	GABRIEL BRELAND
	LEO JERNINGAN
1104	YOLANDA HOSEA
1108	CALVIN BROWN
	CHIRSMA ROBERTS
1112	KHADIJA MUSA
	LATICIA GRADY
1114	VERA JACKSON
1116	FELICIANO DEJESUS
1117	BECKY COCKRELL
1120	HARMONY WALKER
	RAYSHAWN WILBORN
1122	BRIANNE KIRKLAND
1124	JONNIESHA HOLLOMAN
1126	ALEAH TRAPPS
	CHRISTOPHER TRAPPS
	JUAN PIZARRO
1128	SALEEMA SANSAURUS
	SHAKEEM SANSAURUS
1130	MILTON PYE
1406	BRENDA CIRILO
	ELEANESSE PINTO
	FELA ORTIZ
	JOSHUA HANCE

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2017

300	ACOSTA, MERCEDES
	ALDAMUY, STACEY A
	ANDERSON, SUZAN
	BANKS, RICHARD L
	BARNUM, TONY
	BAXTER, JOHNNIE L
	BLUE, CARL A
	BRANCH, CHARLES A
	BRASWELL, ANTHONY
	BRIGGS, MANDY
	BROOKS, PATRICIA A
	BROWNLEE, ROBIN
	COLEMAN, TRAFINA R
	COOK, VIRGINIA
	CORREA, LUZ
	CUEVAS, LETICIA
	DECUIR, CHARLES
	DIAZ, ELVIRA
	DOW, JAMILA M
	DOZIER, RAYBON
	EPPS, ANNIEMAE M
	EVANS, BRIAN K
	EVERETT, DOLLICA S
	FREDERICK, KATRINA M
	FREEMAN, SHERREL A
	GANDOL, CITO J
	GARCIA, CARMEN
	GERMAN, PEARL A
	GLOVER, RONNIE A
	GRAY, EUGENE
	HAMLET, MARY E
	HATCHER, AVAS
	HAYWARD, MELVIN
	HILL, LYNETTE
	HILL, SHERRI
	HOEFLER, PATRICIA Z
	HOWARD, JOHN E
	HUA, CAI
	HUDSON, MYRON D
	IACOBELLO, PATRICIA A
	JACKSON, CURTIS
	JACKSON, EMERY
	JACOBS, CLIFFORD
	JONES, L B
	JORDAN, WYLENE
	JUNIOUS, SABRINA
	KELLY, DAVID
	KILGORE, SANDRA
	KNIGHTON, JOYCE A
	KOEK, JEAN A

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2017 (Cont'd)

300 LAWSON, JANET
LESLIE, GEORGE W
LOCKWOOD, GLADESHA
LOPEZ, CARLOS
MARQUEZ, IVETTE M
MCCARTHY, OCTAVIA N
MCDONALD, LINDA A
MCKENZIE, THELMA
MEALS ON WHEELS
MELENDEZ, EFIGENIO
MORSE, FAYETTE
MOTTO, LUIS
NAPPER, ORESA J
NELLONS, CARRIE E
NIEVES, AILED
OLSON, BRENDA L
PHOENIX, MARCUS
PIZARRO, JUAN A
PULLINS, SHIRLEY D
QUINONES, MARCELINA
RANDALL, SHIRLEY A
REED, SINYORA
REEVES, WANDA E
RIVERA, VALERIE
ROBINSON, JAMES
ROSS, CHERYL E
RUCKER, BENNIE
RUIZ, MELQUIADES
RUSH, HARRY
RYAN, CARMEN
SAMORA, JOEY
SEALS, DAVID G
SHEPARD, CLARK J
SINGLETON, DOROTHY D
SMITH, VALERIE A
SOLIVAN, BRENDA R
SWANSON, REGINALD N
TAYLOR, LARRY
THORNTON, CAROL
THOUSAND, BARBARA D
TUCKER, MAGGIE L
TWIGGS, PAULETTE M
WALKER, LOUIS C
WALLACE, SARAH E
WALTON, ANTHONY A
WHITEHURST, JOHNATHAN R
WHITMAN, FRANCINE
WILLIAMS, CARRIE L
WILLIAMS, HANNA
WILLIAMS, MARILYNN

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2017 (Cont'd)

300	WRIGHT, HERMAN
302	SOMALIBANTU COMMUNITY ASSOCIATION
516	HOUSING AUTHORITY

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2017

900	BRITT, ANIYA
901	CLARK, MAY F
902	DAIGLE, ALICE C
903	COYLE, EILEEN M
905	BANNER, KIARIA
906	CARTER, RENATA M
907	VALENTIN, LUZ
908	WILLIAMS, KATRINA
909	SENIOR, ANDRA
910	COOPER, JOMEL
913	HAMMONDS, RIBEYA M
914	MYERS, LAPETRA
915	SOUSSI, CHOKRI
916	MARTINEZ, DANIEL
917	HOWARD, LEE G
918	MAKARAM, KHADIJA
919	SYLLIVAN, SANDUL
921	GIBSON, QURAN
922	LEE, RUBY N
923	TRENT, SHANNON
925	HASSAN, MOHAMMED
926	CRUZ, MAYSIEL
927	HARRISON, THOMAS S
929	BABCOCK, CATHY A
931	SHREDFASTDOCUMENT
	WILLIAMS, DARON
932	MCGREW, ELLA L
933	GENOVESE, PENELOPE A
934	WIGGINS, LAUREN Y
935	STRONG, LARRY
936	VALENTIN, JOSE
937	ANDERSON, DENISE A
938	PATTERSON, CAMILLE M
939	NEVES, CHELSEA
1000	ADEN, NOOR
1002	MILLS, SHOKEYMA
1004	MATOS, JINNY
1005	JENKINS, LEVY
1010	THORNTON, YOREL
1011	STRINGFIELD, GERALDINE
1013	HAWKINS, QIANA Y
1016	ROBINSON, RODERICK
1017	MARTIN, TIMOTHY B
1018	MARTIN, MONIQUE L
1020	WRIGHT, PATRICA A
1021	KING, ALEXUS
1022	CANADA, ROSA V
1023	MCBRIDE, JOHN
1024	HARDNETT, STACEY N
1027	ROBINSON, SHAKIAH

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2017 (Cont'd)

1031	NEAL, ERICA
1034	SINGLETARY, JOYCE A
1036	NOOR, JEYLAN
1043	JOHNSON, TYREMA
1044	PERRY, PAMELLA
1045	JENNINGS, ALEXANDER
1046	CORNELES, KAREN L
1047	WOODS, NAZHANDA Z
1102	BRELAND, GABRIELLA M
1104	HOSEA, YOLANDA R
1106	HALL, VERA
1110	BUSH, ALVA
1114	GRISWOLD, ERIKA
1116	BRUNSON, BRITTANY A
1118	LEWIS, ARLENE E
1120	WILBORN, RAYSHAWN
1423	BALLARD, PEBBLES
1425	REESE, FORD D
1427	DAVIS, MARIO D
1430	DENSON, LARRY E
1432	WIGGINS, CHARLIE M

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2014

205 GARY, WILL

300 ADELMA, VELAZQUEZ
ALDAMUY, STACEY A
ASH, JOHNNIEMAE
BARNES, NADINE
BASS, WYLENE
BAXTER, JOHNNIE L
BENNETT, ANNA M
BENNETT, EVELYN M
BENT, WESLEY A
BENY, WESLEY
BIGNESS, TELA
BLUE, CARL A
BROOKS, PATRICIA A
CARLISLE, FRED
CARMON, ROY
COLEMAN, TRAFINA R
COOK, VIRGINIA
CORREA, LUZ
CRUZ, MOISES M
CUEVAS, LETICIA
DAVIS, MARY M
DEAN, JENER B
DECUIR, CHARLES
DORSEY, MARY R
EPPS, ANNIEMAE M
EVANS, ADLONIA J
FOREST, KAREN
FREDERICA, SWANSON
FREDERICK, KATRINA M
FREEMAN, SHERREL A
GANDOL, TITO
GARY, MARCUS D
GERMAN, PEARL A
GOWANS, HARRY
GREEN, DOROTHY L
GREENE, BETTY J
HAMLET, MARY E
HATCHER, AVAS
HAYWARD, MELVIN
HENDERSON, EVA J
HENNIGAN, KS S
HILL, LYNETTE
HOEFLER, PAT Z
HOWARD, JOHN E
HOWINGTON, THERESA
HUA, CAI
HUDSON, MYRON D
HUNTER, EUGENE E
IACOBELLO, PATRICIA

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2014 (Cont'd)

300	ISIDORE, MICHELE R
	JACKSON, EMERY
	JACKSON, STEPHEN L
	JOHNSON, FORD
	JONES, L B
	KELLY, DAVID
	KNIGHT, DIANE
	KNIGHTON, JOYCE A
	KNOX, JUDITH A
	LAYME, ANGELA
	LESLIE, GEORGE W
	LEWIS, CHANELLE L
	MARQUEZ, IVETTE
	MASON, GARNELL
	MASSARD, DANNY B
	MCDONALD, LINDA A
	MEALS ON WHEELS
	MELCHOIR, JOANN C
	MICTCHELL, CHRISTINE
	MKONO, JESSICA L
	MOYER, CHRISTINE T
	MYERS, NANCY L
	NAPPER, ORESA L
	NELLONS, CARRIE E
	NELSON, TERRI L
	NIEVES, AILED
	NIEVES, VELIA A
	OLSON, BRENDA
	PINO, MIQUELA J
	PLACENCIA, MERCEDES
	POLI, HEATHER L
	PULLINS, SHIRLEY D
	RANDALL, SHIRLEY A
	REEVES, WANDA E
	RILEY, DELANE
	ROACHE, BRENDA A
	ROBINSONLANT, LINDA
	ROSS, SHEILA A
	RUIZ, MELQUIADES
	RUIZ-DIAZ, MELQUIADEZ
	SEALS, DAVID G
	SHEPARD, CLARK J
	SIMMS, ELAINE
	SINGLETON, DOROTHY D
	SINGLETON, VEONCE D
	SMITH, DANA M
	SOLIVAN, BRENDA R
	STOTT, CINDI R
	SWANSON, REGINALD N
	TAPLIN, TIMOTHY

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2014 (Cont'd)

300	THORNTON, CAROL
	THOUSAND, BARBARA D
	TILLIE, JOY
	TROTMAN, AUDREY
	TUCKER, MAGGIE
	VINN, MILDRED
	WALKER, LOUIS C
	WALLACE, SARAH E
	WARD, DONNA M
	WATTS, NADINE
	WELSH, DANELLA L
	WHITE, EDITH E
	WHITTY, CARL
	WILLIAMS, SANDRA
	WILSON, ELOISE
	WRIGHT, HERMAN
302	SOMALI BANCU COMMUNITY ORGANIZATION
	SOMALIBANTU COMMUNITY ASSOCIATION
414	SOMERS, PHILLIP C

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2014

900	OCCUPANT UNKNOWN,
901	CLARK, MAY F
902	DAIGLE, ALICE C
903	MCBRIDE, LETITIA R
904	CAUTHEN, QUADASIA T
905	JOHNSON, FRANITA M
906	CARTER, RENATA M
907	FINCH, TESHIA M
908	REESE, ELLIOTT J
909	SENIOR, ANDRA
910	PRICE, LATOYA J
911	TAYLOR, TAMARA
912	RODRIGUEZ, ILEANA
	WILLIAMS, TASHICO P
913	HAMMONDS, RIBEYA M
915	GERMAN, KENYA
916	MARTINEZ, DANIEL
917	LEE, TINA
918	ABDIKADIR, ABDI H
919	DEWBERRY, SONYA A
921	BROWN, QUANESHA
922	LEE, RUBY N
923	DRUMMOND, QUANISHA A
925	HASSAN, MOHAMMED
926	LUGO, LUIS D
	REYES, EDNITA O
927	CLARK, NAYESHIA
931	SHREDFASTDOCUMENT
	WATTS, GERTRUDE
932	MCGREW, ELLA L
933	DAVIS, KENNY J
935	STRONG, LARRY
936	VALENTIN, JOSE
937	RUIZ, CHALINA
938	PATTERSON, CAMILLE M
939	HAWKINS, FRANKIE M
1002	MADDOX, ORLANDO
	MILLS, SHOKEYMA
1004	FRIESON, KIMBERLY
1005	RAUFER, ROBERT J
1006	WHITSETT, EDWARD
1008	OCCUPANT UNKNOWN,
1010	REDELL, TWAN
	SMITH, PAULINE C
1011	OCCUPANT UNKNOWN,
1013	HAWKINS, QIANA Y
1014	OCCUPANT UNKNOWN,
1015	MCDANIEL, ALTHEA L
1016	DORTCH, JUANDERA R
	GADDIS, STELLA

1016 NELLONS, M
1017 FERGUSON, MAURICE
1018 OCCUPANT UNKNOWN,
1020 WRIGHT, PATRICA A
1021 GUNN, CASSANDRA
1022 HATHAWAY, D
1023 MCBRIDE, JOHN
1024 OCCUPANT UNKNOWN,
1025 SIGLER, ZAKIYYAH
1026 OCCUPANT UNKNOWN,
1027 ROBINSON, S
1028 RAMSEY, DEBRA D
1029 JOHNSON, MONICA
1030 STROMAN, HAZEL
1031 RICHARDSON, SHAWN D
1032 DAVIS, CRYSTAL R
1033 OCCUPANT UNKNOWN,
1034 STEPP, REGINALD J
1035 OCCUPANT UNKNOWN,
1036 BOYD, LARISHA
1037 REDDISH, KINDELL S
1038 OCCUPANT UNKNOWN,
1039 OCCUPANT UNKNOWN,
1040 OCCUPANT UNKNOWN,
1041 ROBINSON, ZANAYA
1042 OCCUPANT UNKNOWN,
1043 HARRIS, TARA T
1044 PERRY, PAMELLA
1045 JENNINGS, ALEXANDER
1046 CORNELES, KAREN L
1047 PEREZ, ISAMIN
1100 OCCUPANT UNKNOWN,
1102 BRELAND, GABRIELLA M
1104 OCCUPANT UNKNOWN,
1106 HALL, VERA
1108 BAKER, TONY
1110 OCCUPANT UNKNOWN,
1112 OCCUPANT UNKNOWN,
1114 GRISWOLD, ERIKA
1116 BRUNSON, BRITTANY A
1118 OCCUPANT UNKNOWN,
1120 WALKER, HARMONY
1122 OCCUPANT UNKNOWN,
1124 WHITEHURST, JOHNATHAN R
1126 MYERS, KAREN L
1128 HILL, MERVIN L
1130 INNOCENT, HAKIZIMANA
1406 CIRILO, PABLO
ORTIZ, FELA
1412 BARNETT, JESSICA

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2014 (Cont'd)

1425	MYERS, EVAYVONE Y
1427	DAVIS, MARIO D
1430	DENSON, LARRY E
1432	WIGGINS, MAE

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2010

205 GARY, WILL
300 AIKEN, ALFRED K
ALFORD, ANNIE P
ALLEN, CARRIE
ALLEN, MARTHA
ALOI, KIMBERLY
ANDERSON, L
ASH, JOHNNIEMAE
AVANT, DEBRA
BALLARD, LISA J
BANKS, RICHARD
BASS, WYLENE
BAXTER, SHANNON
BENT, WESLEY A
BENY, WESLEY
BETHEA, CHERITA
BLUE, CARL
BOSTIC, DOROTHY D
BRANCH, CHARLES D
BRAXTON, F
BUCKNAM, CHARLES F
CAGE, SUPREENA
CAMBLE, JOE
CLARK, AMBER
CONNER, LEON M
COOK, VIRGINIA
CORONA, ANSELMO I
CORREA, LUZ
CRUZ, MOISES
CUEVAS, LETICIA
CYRUS, DEBBIE
DAVIS, HOWARD M
DYKES, CRYSTAL D
EPPS, ANNIEMAE M
ERNST, CARRIE
EVANS, M
EVERSON, LONNIE C
FOREST, KAREN
FRANKLIN, HESKETH C
FREDERICK, KATRINA
FREEMAN, LOUISE
GARY, MARCUS D
GERMAN, PEARL A
GLOVER, JOHN W
GOODE, DELORES M
GOWANS, HARRY
GREENE, BETTY J
GREGORY, RONNIE L
GREGORY, RUTH S
HARSHAW, CHARLES

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2010 (Cont'd)

300	HATCHER, CINTHIA
	HENNIGAN, KATHRYN
	HILL, LYNETTE
	HOEFLER, PAT A
	HOWARD, JOHN E
	HUA, LOI B
	HUDDLESTON, ROSETTE
	HUDSON, EMMA P
	IACOBELLO, P
	JACKSON, DARLENE M
	JOHNNY, HAWKINS
	JOHNSON, LONNIE L
	JOHNSON-FORD, CHERYL J
	JOIE, JOEY
	JONES, ERNEST
	JONES, L B
	JORDAN, LESLIE J
	JUDGE, ANTHONY R
	KELLY, DAVID
	KNIGHTON, JOYCE A
	LAYNE, ANGELA
	LEE, PATRICIA
	LESLIE, GEORGE W
	LINDSAY, ANNETTE
	MARQUEZ, IVETTE
	MCDONALD, LINDA A
	MCKENZIE, THELMA
	MEALS ON WHEELS
	MELCHOIR, JOANN C
	MILLER, LEWIS
	MILNER, MICHAEL
	MITCHELL, CLIFFORD
	NAPPER, ORESA L
	NELLONS, CARRIE E
	NIEVES, AILED
	OQUENDO, MELISSA
	PERRYMMAN, MONICA
	PINO, MIQUELA J
	PULLINS, SHIRLEY D
	RANDALL, SHIRLEY
	REEVES, WANDA E
	RILEY, DELANE
	ROSARIO, VANESSA
	ROSS, S
	SHIELDS, BRYAN E
	SHINE, ELIZABETH
	SINGLETON, KIMBERELY
	SPEARS, JOHN
	STONE, DAVID
	STOTT, CINDI R

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2010 (Cont'd)

300	THORNTON, JENNIFER
	TILLIE, BETTY
	TUCKER, MARGO L
	TURNER, K C
	VAUGHN, JOANNE U
	VINN, MILDRED
	WALLACE, SARAH E
	WATTS, NADINE
	WHITE, ULYSSES
	WILLIAMS, ANTHONY A
	WILLIAMS, HANNA
	WILLIAMS, ROXANNE E
	WILSON, MABLE
	WRIGHT, ARTHUR
	WRIGHT, HERMAN
	YWCA RESIDENCE PROGRAM
407	OGLETREE, JOHNNIE L
414	SOMERS, PHILLIP C
516	SYRACUSE HOUSING AUTHORITY

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2010

900	LAMBERT, SABRINA A
901	CLARK, MAY F
902	DAIGLE, ALICE C
903	OCCUPANT UNKNOWN,
905	JOHNSON, FRANITA
906	CARTER, RENATA
907	FINCH, SEYQUANA
909	SENIOR, JAMES A
910	OCCUPANT UNKNOWN,
911	JONES, EDWARD L
	THOMAS, BOBBY R
912	GARCIA, BARBARA
	WILLIAMS, TASHICO
913	WILLIAMS, CARSHENA
914	ALLEN, TITUS B
915	MCGANN, SUKHREET M
916	MARTINEZ, ANDREA
917	OCCUPANT UNKNOWN,
918	ABDIKADIR, ABDI H
919	RUSSELL, ELISIA M
921	KELLAM, TRACY
922	GILES, SHIKELA L
923	BROWN, ALZINA
925	HASSAN, MOHAMMED
926	OCCUPANT UNKNOWN,
928	OCCUPANT UNKNOWN,
929	OCCUPANT UNKNOWN,
931	WATTS, JACQUELINE M
932	MCGREW, ELLA L
934	WIGGINS, LAUREN Y
935	RICHARDSON, MAURICE
936	OCCUPANT UNKNOWN,
937	ANDERSON, DENISE
938	FONTAINE, KARLA
939	OCCUPANT UNKNOWN,
1000	DARLING, ANITA
1001	PIONEER HOMES COMMUNITY CTR
1002	CALDWELL, SHAQUAN Q
1004	FRIESON, KIMBERLY
1005	OCCUPANT UNKNOWN,
1006	MIDDLEBROOKS, LYNNICE
1010	BARFIELD, BOBBIE
	BISNETT-HARTLEY, CARL
	HILL, RAYNEISHA
	HINKLE, AONNA
	HUBBARD, F G
	REDELL, TWAN
	THOMAS, MIKA
	THOMPSON, TIFFANY
1011	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2010 (Cont'd)

1012	CAVALE, M
	WALKER, LAURA A
	WYNN, LATOYA N
1013	MIKE, JEFF S
1015	THOMPSON, ANN R
1016	CONWAY, JOHN
	GADDIS, STELLA
	REYNOLDS, SHARON
1017	KING, KEYA B
1018	TOWNSEND, NANIKA
1019	RICHARDSON, SOPHIA
1020	WRIGHT, PATRICA A
1021	JONES, LISA
1022	OCCUPANT UNKNOWN,
1023	MCBRIDE, JOHN
1024	OCCUPANT UNKNOWN,
1025	MARTINEZ, ANDREA
1026	STROTHERS, SHENIQUE L
1027	OCCUPANT UNKNOWN,
1028	RAMSEY, DEBRA D
1029	ROBINSON, SCHWONDA T
1030	HUNTER, CHE
1031	OCCUPANT UNKNOWN,
1032	DAVIS, N
1033	HENRY, TIFFANY T
1034	AHMED, HALIMA
1035	DAVIS, BARBARA R
1036	HENDERSON, JEFFREY
1037	REDDISH, KINDELL S
1038	GADDIS, STELLA
1039	OCCUPANT UNKNOWN,
1040	JONES, ELVIS S
1041	OCCUPANT UNKNOWN,
1042	OCCUPANT UNKNOWN,
1043	HARRIS, TARA T
1044	PERRY, PAMELLA
1045	HOOD, LAURA
1046	OCCUPANT UNKNOWN,
1047	PEREZ, ISAMIN
1100	OCCUPANT UNKNOWN,
1102	BRELAND, GABRIELLA M
1104	OCCUPANT UNKNOWN,
1105	ROSS, MARY J
1106	HALL, VERA
1108	MURRAY, BETSEY
1110	OCCUPANT UNKNOWN,
1112	OCCUPANT UNKNOWN,
1114	HARDY, GARY
1116	CHESTER, MONIQUE
1117	SYRACUSE CITY OFC

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2010 (Cont'd)

1118	LEWIS, JOSEPH J
1120	OCCUPANT UNKNOWN,
1122	GREEN, NAGA
1124	WHITEHURST, JOHNATHAN
1126	OCCUPANT UNKNOWN,
1128	MCKETHAN, ANNIE
1130	TAPE, NORMA A
1406	POWELL, BEATRICE
1409	HEBREW BAPTIST CHURCH MAE
1423	LITTLE, LOUISE E
1425	HOME CARE & REPAIR SVC
	MYERS, EVAYVONE Y
1427	DAVIS, MARIO D
1430	DENSON, LARRY E
1432	BUSSEY, MARCINE

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2005

205	A HAMILTON CONSTRUCTION BACK H
234	HOUSE OF HAIR
236	OCCUPANT UNKNOWN,
300	ALFONSO, TONY
	ALFORD, ANNIE P
	ALMUS OLVER TOWER
	ALVARADO, DOLORES
	ANDERSON, L
	ASH, JOHNNIE M
	AVANT, DEBRA
	BARD, CONSTANCE
	BATISTA, PATRICIA
	BELL, NADINE
	BRANCH, JENNIFER
	BRYANT, M
	BUCKNAM, CHARLES F
	CARMON, R
	CASEY, KATRINA L
	CATHCART, FAITH
	CINARD, ALICE
	CLARK, WALTER A
	COLLINS, E
	COOPER, SHERYL
	CUNNINGHAM, PATT
	CURTIS, JACQULINE R
	DEXTER, LEE
	DOW, LAQUITTA M
	EURE, LEONARD
	EVERSON, LONNIE C
	FAMILY SERVICE CENTER
	FARMER, V
	FORD, CHERYL J
	FOREST, KAREN
	FRANK, ANDREW J
	FRANKLIN, EDWARD T
	FREEMAN, ELIZABETH A
	GAINES, JONATHAN T
	GIBSON, LACEY
	GONYOU, EDWARD E
	GORDON, KATHLEEN M
	GREGORY, RONNIE
	GREGORY, RUTH S
	GRIFFIN, JAMES
	HALL, L
	HARRIS, MARY J
	HARSHAW, CHARLES
	HEARD, SUSAN
	HENDERSON, EVA
	HIGHTOWER, ANGELA
	HOEFLER, PATRICIA Z

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2005 (Cont'd)

300	HOLMES, BRENDA G
	HORDGE, THOMAS
	HOWARD, JOHN E
	HUDSON, MYRON
	HYDLEBERG, STEFANI
	JACKSON, DOROTHY M
	JACKSON, EMERY
	JACOBS, CLIFFORD
	JOHNSON, DONNA
	JOHNSON, PAUL M
	JONES, ERNEST
	KELLY, DAVID
	KINARD, ALICE
	KOEK, JEAN
	KOLAS, LENA
	LYLES, GLEN
	LYNN, PATRICIA E
	MACMASTER, K
	MAHMOUD, ABDOIRAHMAN
	MCDONALD, LINDA A
	MCGUIRE, PATRICK P
	MCKENZIE, THELMA
	MEALS ON WHEELS OF SYRACS N
	MERCADO, EDUARDO
	MITCHELL, CLIFFORD
	MOBLEY, ROBERT L
	NICKERSON, M
	NICKOLOGIANIS, ANNETTE
	OLIVER, ALGIN
	PEREZ, ADA
	POTTS, CHARLES T
	PRINTOP, ROBBIN L
	PRUNER, KAREN
	REDMON, EDDIE
	REEVES, WANDA E
	ROBINSON, MORGAN C
	SAPP, MATTIE
	SARGENT, ATHEA
	SERWAH, ELIZABETH A
	SHIELDS, CHERYL
	SHINE, ELIZABETH
	SHIRLEY, AMY
	SMYTH, KARI
	STICKLER, NORMAN
	STOTT, C
	SULLIVAN, JOHN L
	SULLIVAN, MAYBELLE C
	TAYLOR, CAROL
	TUCKER, TERRY L
	WATTS, MARILYN

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2005 (Cont'd)

300	WHARRY, DARLA
	WHITE, EDITH
	WILEY, N
	WILLIAMS, ALESIA
	WILLIAMS, JASON
	YWCA OF SYRAC
	YWCA RESIDENCE PROGRAM
302	HUNTINGTON FAMILY CENTERS
407	OGLETREE, JOHNNIE L
414	SOMERS, PHILLIP C
425	OCCUPANT UNKNOWN,
516	SYRACUSE HOUSING AUTHORITY

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2005

901	CLARK, MAY F
902	DAIGLE, ALICE C
903	PEDROSO, REGLA
904	OCCUPANT UNKNOWN,
905	ROSS, VANESSA V
906	OCCUPANT UNKNOWN,
907	DYNASTY NAIL SPOT
908	OCCUPANT UNKNOWN,
909	SENIOR, JAMES
910	GILES, SHIKELA L
911	THOMAS, BOBBY R
912	HARRIS, TERRENCE
913	YOUNG, JEFFREY
914	ALLEN, TITUS B
915	OCCUPANT UNKNOWN,
916	OCCUPANT UNKNOWN,
919	BRANTLEY, SHLANA
920	BONAPARTE, S
921	OCCUPANT UNKNOWN,
922	SINGLETARY, DEREK
923	OCCUPANT UNKNOWN,
924	OCCUPANT UNKNOWN,
925	OCCUPANT UNKNOWN,
926	OCCUPANT UNKNOWN,
927	SMITH, KIMANI L
928	OCCUPANT UNKNOWN,
929	CONNERS, NAOMI L
930	MAYNOR, LEE
932	MCGREW, ELLA L
933	GENOVESE, PENELOPE
934	HEMPHILL, MICHELLE C
935	GABLES, DARRELL J
936	GOMEZ, SHARON
937	RAY, HATTIE M
938	HARRIS, DOROTHY J
939	HAWKINS, AHTIA
1000	HAMMONDS, BRIDGET
1001	PIONEER HOMES COMMUNITY CENTER
1002	OCCUPANT UNKNOWN,
1004	APONTE, JESSICA
1005	OCCUPANT UNKNOWN,
1006	FIELDER, DONNELL M
1008	JONES, WILLIE L
1010	OCCUPANT UNKNOWN,
1012	WYNN, LATOYA
1013	MIKE, JEFFEL L
1014	RICE, CORINE T
1015	MCDANIEL, ALTHEA
1016	PRICE, A
1017	FERGUSON, MAURICE

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2005 (Cont'd)

1018 TOWNSEND, NANIKA
1019 OCCUPANT UNKNOWN,
1020 HARRISON, ARKISHA K
1021 ORTIZ, CECILIA
1022 HATHAWAY, DAVID J
1023 MCBRIDE, JOHN
1024 NEWTON, NATASHA
1025 BRITT, LORRAINE
1026 FRAZIER, R
1027 BARNES, SHARENA
1028 RAMSEY, DEBORAH D
1029 RUSSO, MICHELLE
1030 CROSS, TRINITY
1031 SHEPHERD, KALEAS
1032 REED, MARSHA
1033 HARRIS, VERONNA
1034 SCOTT, TAMIKA L
1036 SEALS, GERALDINE
1037 COBB, JEFFREY
1038 OCCUPANT UNKNOWN,
1039 WHATLEY, DARIEL J
1040 JACKSON, TROY
1041 STROMAN, GEORGE
1042 CANNADY, ROMAN
1043 OCCUPANT UNKNOWN,
1044 BAKER, SHARIKA
1045 OCCUPANT UNKNOWN,
1046 BONNER, MAELEAN
1047 ROBINSON, BARAKA
1100 HALL, DWIGHT L
1102 BRELAND, GABRIELLA M
1104 JAMISON, SHERITA N
1106 HALL, VERA
1108 MURRAY, BETSEY
1110 SMITH, RICARDO
1112 MILLS, LUSHURNDA
1114 BROWN, LORIE
1116 HUNTLEY, LINDEL Y
1118 LEWIS, JOSEPH J
1120 MILLER, ZION
1122 PETERSON, LIZ
1124 NELSONS CUT & GO
NELSONS CUT AND GO
WHITEHURST, JOHNATHAN
1126 OCCUPANT UNKNOWN,
1128 GILES, VERNETTA
POWERFUL RECORDZ
1130 TAPE, NORMA A
1406 POWELL, BEATRICE
1423 LITTLE, LOUISE E

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2005 (Cont'd)

1425	MYERS, EVAYVONE Y
1427	DAVIS, MARIO D
1429	WILLIAMS, NANCY J
1430	DENSON, LARRY E
1432	BUSSEY, MARCINE

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2000

222	GRIFFINS, HENDERS
234	JUST GRILLIN
	MONTGOMERY, KEVIN D
236	OCCUPANT UNKNOWN,
300	ALFONSO, RODELL
	ALFORD, A P
	ALSONSO, TONY
	ASH, JOHNNIE M
	BRYANT, TONYA M
	BURKE, F L
	CAMPBELL, TOMMY
	EDICK, BOB
	EXLEY, E
	GIBSON, LACEY
	GONYOU, EDWARD E
	GRANT, WILLIE J
	GREEN, R
	HAWKINS, LARENA
	HENDERSON, TONIA
	HOEFLER, P
	HOLMES, BRENDA G
	JACKSON, EMERY
	JACKSON, K M
	JACKSON, S
	JEFFERSON, L
	JOHNSON, ROBERT
	JOHNSON-FORD, CHERYL
	JONES, ERNEST
	JONES, ROSE B
	LUCAS, Z
	MAY, DEBORAH
	MCCLENAHAN, H
	MCKENZIE, THELMA
	MCMULLEN, BRIAN
	MEALS ON WHEELS
	MILES, MYRTICE R
	MILLS, HATTIE
	MITCHELL, C
	PATTERSON, H
	PATTERSON, VELMA
	PETROCCI, FELICIA
	RATCLIFF, VIVIAN
	SCOT, KELLY C
	SHINE, E
	SMITH, LAURA
	SNOW, JOSEPH
	STEAD, SHARON
	STICKLER, NORMAN
	TUCKER, MARGO
	WILLIAMS, HORACE

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 2000 (Cont'd)

300	Y W C A RESIDENCE PROGRAM
302	HUNTINGTON FAMILY CENTERS
407	OGLETREE, JOHNNIE L
414	SOMERS, PHILLIP
418	DAVIS, RUTH K
	HARRIS, ANNIE
512	ANDREWS JOHN
516	HOUSING AUTHORITY SYRACUSE

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2000

901	CLARK, MAY
902	DAIGLE, ALICE
903	OCCUPANT UNKNOWN,
905	ROSS, VANESSA
906	BURNS, PAULINE
907	PHOENIX, TONI J
908	OCCUPANT UNKNOWN,
909	SENIOR, ANDRA
910	LEE, RUBY N
911	OCCUPANT UNKNOWN,
912	OCCUPANT UNKNOWN,
915	HINKLE, LISA M
916	SMITH, PAULINE M
917	MCGRIFF, ESSIE
918	GLASS, RACHEAL L
919	OCCUPANT UNKNOWN,
920	FORD, DOROTHY
921	OCCUPANT UNKNOWN,
923	ROWSER, SAMUEL D
924	RODRIGUEZ, LYDIA C
925	LEMON, TANYA O
927	WILLIS, NOLITA
928	ESPEY, S
929	STENSON, KANLIA N
930	OCCUPANT UNKNOWN,
931	OCCUPANT UNKNOWN,
932	MCGREW, ELLA L
933	OCCUPANT UNKNOWN,
934	OCCUPANT UNKNOWN,
935	LIVELY, LAKISHA
936	STEVENS, MAYBELL
937	OCCUPANT UNKNOWN,
938	HARRIS, DOROTHY
939	OCCUPANT UNKNOWN,
1000	OCCUPANT UNKNOWN,
1001	SYRACUSE HOUSING AUIHORIIY PNR HOMES COMMUNITY CENTER
1002	OCCUPANT UNKNOWN,
1003	FRANKLIN, EDWARD T
1004	MCCORMICK, ADELE
1006	FIELDER, ANN
1010	BRUMFIELD, L B
1011	OCCUPANT UNKNOWN,
1012	OCCUPANT UNKNOWN,
1013	JONE, DORA M
1014	RICE, C
1015	OCCUPANT UNKNOWN,
1016	OCCUPANT UNKNOWN,
1017	MCRAE, LATONYA
1018	OCCUPANT UNKNOWN,
1019	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2000 (Cont'd)

1020	HARRISON, A
1021	PULLEY, TIRONA N
1022	HATHAWAY, D J
1023	BLAKELEY, E J
1024	DURHAM, TOM
1025	WILLIAMS, K
1026	CHAVIS, STEVEN D
1027	CORLEY, MARILYN L
1028	PLEASANTS, FREEMAN
1029	TOWNSEND, K
1030	JONES, L
1031	OCCUPANT UNKNOWN,
1032	OCCUPANT UNKNOWN,
1033	OCCUPANT UNKNOWN,
1034	OCCUPANT UNKNOWN,
1035	OCCUPANT UNKNOWN,
1036	SEALS, G
1037	OCCUPANT UNKNOWN,
1038	DAWSON, ESSENCE
1039	OCCUPANT UNKNOWN,
1040	OCCUPANT UNKNOWN,
1041	STROMAN, GEORGE
1042	OCCUPANT UNKNOWN,
1043	OCCUPANT UNKNOWN,
1044	OCCUPANT UNKNOWN,
1045	OCCUPANT UNKNOWN,
1046	CUNDIFF, GREGORY L
1047	OCCUPANT UNKNOWN,
1100	OCCUPANT UNKNOWN,
1102	BRELAND, G
1104	OCCUPANT UNKNOWN,
1106	TAPE, GLORIA
1108	MATHIS, NANCY
1110	ADJEI, ZINA
1114	BAKER, GLADYS
1116	HUNTLEY, LINDEL
1118	LEWIS, JOSEPH
1120	OCCUPANT UNKNOWN,
1122	OCCUPANT UNKNOWN,
1124	CATHCART, D
1126	OCCUPANT UNKNOWN,
1128	OVERTON, LAVINIA
1130	TAPE, NORMA
1307	ROYAL, TERRA
1415	BROWN, CHARLES
1423	LITTLE, LOUISE
1425	MYERS, E
1427	DAVIS, MARIO
1429	WILLIAMS, NANCY J
1430	DENSON, EVELYN

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 2000 (Cont'd)

1432 BUSSEY, MARCINE

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 1995

220	SANDERS, JACQUELINE
300	ALFONSO, RODELL
	ALFORD, A P
	ASH, JOHNNIE M
	BANKS, R
	BEAMON, W
	BOGAN, EDWARD
	BRISTOW, PRINCE
	BULLITT, HATTIE
	BURKE, F L
	CATHCART, DELILLIAN
	CHATMAN, FRANCIS
	CHRISTIAN, ROSA L
	COLLIER, WILLIS
	CROSBY, JESSIE
	CURTIS, J
	DAVIS, EVERETT
	EDICK, BOB
	EDWARDS, LILLIE MAE
	EURE, VERNA
	EXLEY, E
	FINNEY, JANE
	FLOYD, CONNIE
	GONYOU, EDWARD E
	GRANT, WILLIE J
	GREEN, WILLIAM, JR
	HARSHAW, CHARLES
	HICKLIN, PATSY R
	HOEFLER, P
	HOLMES, BRENDA G
	JACKSON, EMERY, JR
	JACKSON, S
	JOHNSON, ADDIE M
	JOHNSON, ROBERT, SR
	JONES, ERNEST
	JONES, MATTIE
	JONES, ROSE BUD
	KALISIEWICZ, EDWARD
	LOKEY, CURTIS
	LUKAS, M D
	MATTHEWS, JAMES A
	MC KENZIE, THELMA
	MEALS ON WHEELS
	MILES, MYRTICE R
	MILLS, HATTIE
	MITCHELL, CLIFFORD
	OLIVO, EDUARDO
	PALMER, JACK
	PATTERSON, H
	PATTERSON, VELMA

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 1995 (Cont'd)

300	RATCLIFF, VIVIAN
	REEDER, W
	SHEPPARD, JOHNIE
	SHINE, E
	SIMS, MAMIE
	SNOW, JOSEPH
	STEVENS, ROBERT A
	STICKLER, N
	SULLIVAN, DUCHESS
	SYRACUSE CITY SCHOOL DISTRICT-PRE-KINDERGARTEN PROGRAMS-BURT
	SYRACUSE HOUSING AUTHORITY-HAPP - SECTION 88
	SYRACUSE HOUSING AUTHORITY-NIGHT EMERGENCY AIDESS
	THORTON, M
	TUCKER, MARGO
	WALLACE, JAMES
	WARD, CHARLES
	WASHINGTON, RICKY
	WILLIAMS, DOROTHY
	WILLIAMS, HORACE
407	OGLETREE, JOHNNIE L
414	SOMERS, PHILLIP
418	DAVIS, RUTH KITCHING
512	ALCO MACHINERY
	ANDREWS JOHN
516	HOUSING AUTHORITY SYRACUSE
	SYRACUSE CITY OF HOUSING AUTHORITYY
	SYRACUSE HOUSING AUTHORITY-MAIN OFCSS

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 1995

901	CLARK, MAY
902	DAIGLE, A
905	ROSS, VANESSA
906	BURNS, PAULINE
911	TATE, T
912	MILLER, K
914	SHEPHERD, DALTON
917	MC GRIFF, ESSIE
918	GLASS, RACHEAL LEE
920	FORD, WILLIE J, SR
921	JOHNSON, R M
926	KIRBY, DAVID L
928	ESPEY, I
930	TOOKES, OTIS
932	MCGREW, ELLA L
936	STEVENS, MAYBELL
938	HARRIS, DOROTHY
1000	HART, ESSIE MAE
1001	SYRACUSE HOUSING AUTHORITY-PIONEER HOMES COMMUNITY CENTERR
1003	FRANKLIN, EDWARD T
1004	DOUTHIT, C
1006	FIELDER, ANN
1008	BLACKSHEAR, L B
1014	HARRISON, MARY
1015	DALLAS, ROXIE A
1016	KENDRICK, ANNIE
1018	GILLIAM, BESSIE
1022	HATHAWAY, D J
1023	BLAKELEY, E J
1025	WILLIAMS, K
1026	MCGILL, JODIE
1028	GREGORY, ARCELLA M
1030	KHABIR, MAE
1031	WRIGHT, SHANNON
1032	GIST, MARILYN
1036	SEALS, GERALDINE
1039	RUTLEDGE, A
1040	BRELAND, INELL
1042	JOHNSON, R J
1043	JACKSON, DARLENE
1046	SMITH, PAULINE
1047	SENIOR, G
1106	TAPE, GLORIA
1108	MATHIS, NANCY
1114	BAKER, GLADYS
1116	HUNTLEY, LINDEL
1118	LEWIS, JOSEPH
1120	DAVIS, JANIQUA
1122	VINCENT, C
1128	OVERTON, LAVINIA

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 1995 (Cont'd)

1130 TAPE, NORMA
1411 ROWSER, SAMUEL D
1413 TURNER, D
WESTBROOK, JOHNNY
1415 MURRY, E
1423 LITTLE, L
1427 DAVIS, MARIO
1430 DENSON, EVELYN
1432 BUSSEY, MARCINE

Target Street	Cross Street	Source
✓	-	Cole Information

BURT ST 1992

218	WALLACE, JOHN H
234	SPARKLE CLEANERS
236	CUTTING CREW THE
	MOSS, E
300	ALFONSO, RODELL
	ALFORD, A P
	ALLEN, ARTHUR
	ALLEN, C
	ASH, DOROTHY
	ASH, JOHNNIE M
	BANKS, R
	BOGAN, EDWARD
	BRANDON, WILLARD, JR
	BRISTOW, PRINCE
	BROOME, LENA
	BROWN, GEORGE
	BULLITT, HATTIE
	BURKE, F L
	CARMAN, OLLIE
	CATHCART, DELILLIAN
	CHATMAN, FRANCIS
	CHRISTIAN, ROSA L
	CLEAVELAND, D
	CLEMONS, MINNIE
	COLLIER, WILLIS
	COLUNIO, SAM & HELENA
	COMAN, VASTIE
	COWAN, JOAN
	CROLICK, IRVING H
	CROSBY, JESSIE
	CURTIS, J
	DAVIS, EVERETT
	DEERING, J M
	DEMOTT, BERTHA
	DENNIS, ESTELLA
	EDICK, BOB
	EDWARDS, LILLIE MAE
	ERIE ENRICHED HOUSING PROGRAM
	EXLEY, E
	FAMILY SVCE CENTER
	FINNEY, JANE
	FLOYD, CONNIE
	FRANKLIN, STANLEY
	GAIGE, RICHARD T
	GAINES, KATIE B
	GAINSBACK, JAMES
	GRANT, WILLIE J
	GREEN, WILLIAM, JR
	GURIDY, FRANK A
	HARRIS, A

300 HARSHAW, CHARLES
HOLMES, BRENDA G
HOLMES, M E
JACKSON, EMERY, JR
JACKSON, ROBERT L
JENNINGS, T
JOHNSON, ADDIE M
JOHNSON, ROBERT, SR
JONES, ERNEST
JONES, MATTIE
JONES, ROSE BUD
JONES, WILLIE
KALISIEWICZ, EDWARD
KIM, KYI SOH
KNOX, B
LEE, CHOON-HA
LEE, GLADYS
LEPPO, JULIA
LOKEY, CURTIS
LUKAS, M D
MC DONALD, THELMA
MC KENZIE, THELMA
MEALS ON WHEELS
MICHAELS, M
MICHAELS, ROBERT
MILES, MYRTICE R
MILLS, HATTIE
MITCHELL, CLIFFORD
MORTON, L
NAZARIAN, ELIS
NOBLES, DANIEL
NORRINGTON, ROBERT L
OLIVO, EDUARDO
PAIGE, ELEANOR
PASSINEAU, MARY B
PATTERSON, H
PATTERSON, VELMA
PAYOLI, GEORGE
RATCLIFF, VIVIAN
REEDER, W
ROGERS, L
SAPP, KENNETH C
SHAY, STANLEY
SHEPPARD, JOHNIE
SHINE, E
SIMS, MAMIE
SIZMORE, LAURA
SNOW, JOSEPH
STEVENS, ROBERT A
STEWART, EARNESTINE

300	STICKLER, N
	STROMAN, WILLIE
	SULLIVAN, DUCHESS
	SVOBODA, R
	SYRACUSE CITY SCHOOL DISTRICT-PRE-KINDERGARTEN PROGRAMS-BURT
	SYRACUSE HOUSING AUTHORITY-NIGHT EMERGENCY AIDES
	TALLMAN, JAMES
	TAYLOR, ANN
	THORTON, M
	TILLMAN, C
	TORRANCE, WILLIE
	WALL, M Z
	WARD, CHARLES
	WASHINGTON, BEATRICE
	WASHINGTON, RICKY
	WILLIAMS, HORACE
	YOUNG, HATTIE
302	FAMILY SVCE CENTER NURSERY SCHOOL
407	OGLETREE, JOHNNIE L
410	GUTSHALL, C H
414	SOMERS, PHILLIP
418	DAVIS, RUTH KITCHING
420	MC LEAN, NEAL
512	ALCO MACHINERY
	ANDREWS JOHN
516	HOUSING AUTHORITY SYRACUSE
	SYRACUSE HOUSING AUTHORITY-MAIN OFCS

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 1992

900	MANN, MARY
902	DAIGLE, A
906	BURNS, PAULINE
907	TEJADA, CARMEN
908	CARSON, C
909	WILLIAMS, A
912	MILLER, K
913	TATE, T
914	STARLING, LOWANDA
915	HINKLE, L
916	SMITH, PAULINE
918	HILLS, B
920	PITTS, RIHEEM
923	FAISON, FRAN
924	JACKSON, V
925	FRAZIER, M
928	ESPEY, I
930	SMITH, ROBIN A
931	FLEMING, JAMES
932	MCGREW, ELLA L
935	HARRISON, A
936	RICHARDSON, Q T
937	TOOKES, OTIS
938	JOHNSON, M
939	NOEL, NETTIE
1000	HART, ESSIE MAE
1001	SYRACUSE HOUSING AUTHORITY-PIONEER HOMES COMMUNITY CENTER
1003	FRANKLIN, EDWARD T
1004	TISDELL, L L
1005	STEVENS, MAYBELL
1006	FIELDER, ANN
1008	BLACKSHEAR, L B
1011	KEARSE, BELEADER
1012	OVERTON, LAVINIA
1014	RICHARDSON, SHELTON
1019	WILSON, OTIS DEMONE
1022	HATHAWAY, D J
1023	BLAKELEY, E J
1024	THOMAS, P
1025	TRAPPS, VITA
1026	RENDER, SANTINA
1027	GLASS, RACHEAL LEE
1030	KHABIR, MAE
1031	WILLIAMS, K
1035	RICHARDSON, SOPHIA
1036	SEALS, GERALDINE
1038	MARTIN, GLORIA
1040	FORD, T
1045	SMITH, VELMA J
1047	SENIOR, G

Target Street	Cross Street	Source
-	✓	Cole Information

S MCBRIDE ST 1992 (Cont'd)

1104	MCMILLAN, LENESHA
1106	TAPE, GLORIA
1110	MELENDEZ, W
1114	BAKER, GLADYS
1116	SMITH, SHERRY
1118	LEWIS, JOS
1122	MATHIS, NANCY
1124	BROWN, G
1126	WILLIAMS, B
1130	TAPE, NORMA
1226	FEGLEY SERVICES INC
	J A F ASSOCIATES INC
1408	EPPS, LILLIE B
1411	ROWSER, SAMUEL D
1423	LITTLE, FRED
1430	DENSON, EVELYN
1432	WIGGINS, MAY

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1988

313 Vacant

OAKWOOD AV INTERSECTS

407 Ogletree John L © 478-2086

409 Vacant

410★Coleman Doretha 426-0167

412 Vacant

414 Somers Phillip C 476-0663

418 Davis Ruth 471-3799

Harris Anna Mae

420★Valenson Robt A 478-0656

SOUTH MC BRIDE INTERSECTS

512 Vacant

CONRAIL INTERSECTS

516 Syracuse Housing Authority 475-6181

INTERSTATE 81 EXPRESSWAY INTERSECTS

ALMOND ST ENDS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1988

1124 Stanley Julius 479-5640
1126 Lamb Helen
1128 Hathaway Valerie
1130 Bell T B 471-5699
E TAYLOR ST INTERSECTS
1200 Syr University Steam Station 423-3328
CONRAIL INTERSECTS
1226 Cooper A Metal Co Inc junk dlrs
475-3144
BURT ST INTERSECTS
1307 Shaw Jack Rev 472-2179
1311 Harris Clifford
1312 Niagara Mohawk Mc Bride St Sub Sta
1313 Carol Ben L
VAN BUREN INTERSECTS
1402 Vacant
1406 Brown Charles ◎ 476-7836
Central Eugene
1408 Epps Lillie B Mrs 424-0035
1409 Hebrew Baptist Church 422-3948
1411 Grace Jos ◎ 475-4703
★Howell Jacqueline
1413 Murry
1415 Stewart Louise Mrs 472-9436
Vacant
1417 Vacant
ROSE AV ENDS
SIZER BEGINS
1423 Little Fred ◎ 475-9684
1429 Washington Louise B 476-3780
1435 Johnson Gwendolyn 476-4921
E RAYNOR INTERSECTS

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1983

307 Maurer Francis C ◎ 474-3279
309 Salvation Army (Whse)
313 Vacant
Vacant

OAKWOOD AV INTERSECTS
407 Ogletree John L ◎ 478-2086
410 Vacant
414 Belonge Ruby Mrs ◎
416 Vacant
418 Davis Ruth Mrs ◎ 471-3799
Harris Anna Mae
420 Wadleigh Barbara ◎
SOUTH MC BRIDE INTERSECTS
506 Shales Florence
Cummings Ruby

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1983



Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1983

1130★Rivers Gloria
E TAYLOR ST INTERSECTS
1200 Syr University Steam Station 476-3093
CONRAIL INTERSECTS
1226 Cooper A Metal Co Inc junk dlrs
475-3144
Ace Sanitary Haulers 478-5531
BURT ST INTERSECTS
1309 Vacant
1311★Williams Emma 471-1452
1312 Niagara Mohawk Mc Bride St Sub Sta
1313★Banks Rufus L 479-9412
VAN BUREN INTERSECTS
1401 Vacant
1402 No Return
1403 Apartments
1 Vacant
2 Miller Shirley Mrs
3★Brown Charles
4 Vacant
1405 Vacant
1406★Mathis Loretha O 478-1257
1408★Epps Charles 424-0035
1409 Hebrew Baptist Church 422-3948
1410 Vacant
1411 Grace Joseph 475-4703
1413 Vacant
1415 Vacant
1417 Vacant
ROSE AV ENDS
SIZER BEGINS
1423 Little Fred 475-9684
1428 Vacant
Vacant
1429 Washington Louise
1430 Vacant

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1977

302 Central Village Day Care Center 475-3731
307 Maurer Francis C ◎ 474-3279
309 Salvation Army (Whse)
313 Pitcher Elmer
Vacant

78

OAKWOOD AV INTERSECTS
407 Ogletree John L ◎ 478-2086
410 Cross Bosco 424-0029
Vacant
412 Vacant
414 Belonge Ruby Mrs ◎ 476-2857
416 Mankoff Saml ◎
418★Davis Ruth Mrs ◎ 471-3799
Harris Anna Mae
420 Edwards James ◎ 422-6537
SOUTH MC BRIDE INTERSECTS
506 Merrick James
★Murrell Edna M Mrs
512 Andrews Lumber Co 476-5933
D L & W R R INTERSECTS
516 Syracuse Housing Authority genl ofc
475-6181
ROUTE 81 EXPRESSWAY INTERSECTS
ALMOND ENDS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1977

1120 Greer Eletha Mrs 472-7491
1122 Frett Lavern Mrs 472-1238
1124 Stanley Julius 476-2593
1126 Stanley Jeanett 478-6247
1128 Graham Mary Mrs
1130 Vacant
E TAYLOR INTERSECTS
1200 Syr University Steam Station 476-3093
D L & W R R INTERSECTS
1226 Cooper A Metal Co Inc junk 475-3144
Ace Sanitary Haulers 478-5531
BURT INTERSECTS
1304 Vacant
1309★Frazier Clara M Mrs
1311★Thomas Julia Mrs
1312 Niagara Mohawk Mc Bride St Sub Sta
1313 Smith Willie
VAN BUREN INTERSECTS
1401 Vacant
1402★Epps Annie Mae Mrs 478-3633
1403 Apartments
1★Shepheard John J 474-5471
2★Miller Shirley Mrs
3★Haw Bernice Mrs
4★Grant Danl T
1405★Gaffney Phyllis
1406★Ware Edna L Mrs
★Whitfield Carl 471-0450
1408★Long Nellie M Mrs
★Mc Fadden Earlene Mrs
1409 Hebrew Baptist Church 422-3948
1410★Smith Pamela
1411 Grace Joseph 475-4703
Vacant
1413 Gray Alberta Mrs 475-8805
Tookes Otis B 475-4776
Young Violet Mrs
1415★Mc Fadden Lula M Mrs
★Knight Mae Mrs
1417 Dowdell Lucinda J Mrs
Vacant
1421 Vacant
ROSE AV ENDS

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1972

C1207 Paninski Frank 479-7497
C1208 Diehl Irene D 476-6192
C1209 Peregoy Margt Mrs 476-6323
C1210 Kaplan Zelig
302 Central Village Day Care Center 475-3731
307 Fadden Margt Mrs
309 Salvation Army (Whse)
313 Hunt Jack
Pritchard Howard
Simmons Charles

78

OAKWOOD AV INTERSECTS
407 Ogletree John L ◎ 478-2086
410 Simmons Peggy Mrs 475-1302
Jackson Augusta Mrs 476-0835
412 Harrison Norma Mrs
414 Belonge Ruby Mrs 476-8022
416 Mankoff Saml
418 Davis Ruth Mrs ◎
Taylor Azalia Mrs
420 La Plant Geo ◎ 478-0203
422 Brown Mary E Mrs
SOUTH MC BRIDE INTERSECTS
500 Jones Shirley Mrs
502 No Return
506 Bohanon Alf E
Brown Leona Mrs 475-7898
512 Andrews Lumber Co 476-5933
D L & W R R INTERSECTS
516 Syracuse Housing Authority genl ofc 475-6181
ROUTE 81 EXPRESSWAY INTERSECTS
ALMOND ENDS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1972

1104 Van Ness Estelle W Mrs
1105 Wilson Community Center
1106 Wynn Martha Mrs 476-2379
1108 Mc Clain Geo
1110 Williams Tescora Mrs
1112 Vacant
1114 Baker Gladys Mrs
1116 Gibson Julia Mrs 479-8048
1118 Lewis Joseph 478-1828
1120 Greer Eletha Mrs 472-7491
1122 Maeweather Tempi Mrs 475-8574
1124 Breland Cefus
1126 Rushing Alice S Mrs
1128 Graham Mary Mrs
1130 Tilley Mary M Mrs 475-1928
E TAYLOR INTERSECTS
1200 Syr University Steam Station 476-3093
D L & W R R INTERSECTS
1226 Cooper A Metal Co Inc junk 475-3144
Ace Sanitary Haulers 478-5531
BURT INTERSECTS
1300 Wright Pearlie Mrs 478-5303
1302 Vacant
1304 Busby Myrtle M © 476-9577
1305 Vacant
1307 Hoffman Harry © GR8-4773
1309 Spinks Viola Mrs
Mc Alpine Eddie
1311 Jenkins Martha Mrs 475-7169
1312 Niagara Mohawk Mc Bride St Sub Sta
1313 King Willie Lee
Austin Roosevelt
VAN BUREN INTERSECTS
1401 Vacant
1403 Apartments
1 Lucas Eddie
2 Jones Johnny
3 Pierce Barbara Mrs
4 Hall Barbara Mrs
1404 Vacant
1405 Pratt Mary J Mrs
1406 Nugent Andrew 476-1919
1408 Wilson Odell Mrs 475-5936
Green Michelle
1409 Hebrew Baptist Church
1410 Scott Josephine Mrs
1411 Grace Joseph 475-4703
Fredge Johnnie M Mrs 475-9663
1413 Gray Alberta Mrs 475-8805
Tookes Otis B 475-4776
1415 Hall Henry
Brock Homer
1417 Seamans Ruth Mrs
King Laura Mrs
1421 Abrams Waste Materials Co junk dlrs
476-3402
ROSE AV ENDS

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1968

302 CENTRAL VILLAGE DAY CARE CENTER
475-3731
307 MAURER FRANCIS ● GR5-5380
313 REED IRENE M MRS
GRAY OOROTHY MRS
317 HALL RICHD
RAMON JOSE

78

---OAKWOOO AV INTERSECTS
407 OGLETREE JOHN L ● GR8-20B6
410 SIMMONS PEGGY MRS GR5-1302
412 HARRISON ERNEST
414 BELONGE SEELEY W GR6-B022
416 MANKOFF SAML
41B DAVIS RUTH MRS GR6-1579
VACANT
420 LA PLANT GEO ● GRB-0203
422 VACANT
---SOUTH MC BRIOE INTERSECTS
500 OYKES JOHN O GR6-2370
502 DYKES JOHN JR GR6-1554
506 BOHANON ALF E
BROWN LEONA MRS 475-7B9B
512 ANDREWS LUMBER CO GR6-5933
---D L & W R R CROSSES
516 CITY HOUSING AUTHORITY PIONEER
HOMES AOMN BLDG GR5-61B1
KENNEOY WM G LWYR HA2-61B5

79

---ROUTE 81 EXPWY INTERSECTS
---ALMONO ENOS

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1968

1118 LEWIS JOSEPH GRB-182B
1120 TITUS RAYMONO 475-1746
1122 KIPP EOMUND A
1124 BRELAND CEFUS
1126 OOEN CLAUDIA MRS
1128 GRAHAM MARY MRS
1130 TILLEY MARY M MRS GR5-1928
1200 SYR UNIVERSITY STEAM STATION
GR6-3093
---O L & W R R INTERSCTS
1226 COOPER A METAL CO INC JUNK
GR5-3144
ACE SANITARY HAULERS GRB-5531
1300 WRIGHT PEARLIE MRS 478-5303
1302 LOWE FRANK • 475-B734
1304 BUS8Y MYRTLE M • GR6-9577
1305 VACANT
1307 HOFFMAN HARRY GR8-4773
1309 MC GRIFF OELORIS C MRS
FULWOOO LANNIE M
1311 GAINEY M C 475-5561
1312 NIAGARA MOHAWK MC 8RIOE ST SUB
STA
1313 BROOKS FLORIOA MRS
8ROOKS BOBBY L
---VAN 8UREN INTERSECTS
1401 BETTER HOMES CONTRACTORS &
DISTRI8UTORS INC GR5-1693
1403 APARTMENTS
1 SIMPSON MORRIS
2 NO RETURN
3 LUCAS FREOK
4 SPAIN JO ANNE
STREET CONTINUEO
1404 VACANT
1405 JDNES PHILLMORE

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1968

1406 NUGENT ANDREW GR6-1919
1408 NO RETURN
HEBERT GLADYS MRS • GR5-4934
1409 VACANT
1410 VACANT
1411 GRACE JOSEPH GR5-4703
JONES ULYSSES GR5-9663
1413 GRAY ALBERTA MRS 475-8805
TOOKES OTIS 475-4776
1415 HALL HENRY
SINGLETARY LONNIE
1417 JONES ALONZO
VACANT
1421 ABRAMS WASTE MATERIALS CO JUNK
OLRS GR6-3402
---ROSE AV ENDS
---SIZER BEGINS
1423 LITTLE FREO 475-4684
1424 WATSON WILLIE
VACANT
WHITE MAE MRS 478-4440
ENKER ANNA MRS GR6-2411
1425 TURNER MADIE MRS 476-0714
WILLIAMS WM 478-5602
1427 LESSEN SOL • 475-4654
1428 HALLOCK MILOREO MRS 475-9469
LYNCH JANE 476-1302
1429 KOLOIN IOA MRS • GR8-0554
1430 VACANT
SILVERBUSCH GUSTA MRS GR8-0285
MC CLELLAN TESSIE MRS
1431 SIMON RAE MRS • GR5-8117
1432 REYNOLOS ELIZ MRS GR5-6439
1433 MADDOX WALTER 475-4610
1434 HORACE CARROLL
1435 BRUNSON ESSIE MRS • 476-1361

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1964

C1205 WISE LOUISE R MRS
478-1779
C1206 SCHEUER JULIA 478-5268
C1207 WHITSON CLARA MRS
478-3588
C1208 WE8BER JOSEPH P
C1209 STEWART SETH 476-6664
C1210 KAPLAN ZELIG
302 CENTRAL VILLAGE NURSERY SCH
478-6733
307 MAURER MARGT M MRS • GR5-5380
313 VACANT
STACKHOUSE CLARENCE
STROMEN WILLIE 475-1948
317 PAUL MOSES GR5-2209
VACANT

78

---OAKWOOD AV INTERSECTS
407 OGLETREE JOHN L • GR8-2086
410 IDE CHAUNCEY M JR • GR5-5041
412 OAYS LEWIS D JR GR6-4631
414 8ELONGE SEELEY W GR6-8022
416 MANKOFF SAML
418 DAVIS RUTH MRS GR6-1579
RHODES RUTH MRS
420 LA PLANT GEO • GR8-0203
422 VACANT
---SOUTH MC 8RIDE & 8URT INTERSECTS
500 DYKES JOHN D GR6-2370
502 OYKES JOHN JR GR6-1554
506 BOHANON ALF E
EUOELL WILLIE GR6-7220
512 ANDREWS LUMBER CO • GR6-5933
---D L & W R R CROSSES
516 CITY HOUSING AUTHORITY PIONEER
HOMES AOMN 8LDG GR5-6181

79

---ALMOND ENOS
601 VACANT
VACANT
603 8ASS WILLIE LEE 475-6311
VACANT
8ELL JOHN A
605 LEVY GOLDIE • GR8-7960
RENERT PHILIP • GR8-7960

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1964

1044 TUCKER SAML 476-4358
1045 PRETTYMAN WILLIEREE MRS
1046 GEARY PAUL M 476-0909
1047 PHILLIPS STARLING
---JACKSON INTERSECTS
1100 BROWN ARLETHIA 476-6676
1101 WILSON PLAYGROUND GR5-6912
1102 BELL ROBT L
1104 VACANT
1105 WILSON COMMUNITY CENTER
1106 WYNN JOHN W G: 2279
1108 MITCHELL GEO
1110 WILLIAMS WM
1112 CRAWFORD ALBERT GR5-5285
1114 FRANK LENORA MRS GR8-8027
1116 PINKARO GEORGIANNA
1118 LEWIS JOSEPH GR8-1828
1120 BROOKS ERNSET
1122 COLLIER SILAS 478-4211
1124 BRELAND CEFUS
1126 DIXON BERNICE R MRS GR8-1655
1128 LOVE BARNEY
1130 TILLEY MARY M GR5-1928
1200 SYR UNIVERSITY STEAM STATION
GR6-3093
1207 VACANT
---D L & W R R INTERSCTS
---BURT INTERSECTS
1226 COOPER A METAL CO INC JUNK
GR5-3144
1300 WRIGHT PEARLIE 478-5303
1302 LOWE FRANK GR8-0155
1304 BUSBY MYRTLE L MRS • GR6-9577
1305 VACANT
1307 HOFFMAN HARRY GR8-4773
1309 VACANT
1311 BROTHERTON GOLDER W • GR6-5926

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1964



1313 RYALS MASIE
---VAN BUREN INTERSECTS
1401 BETTER HDMES CONTRACTORS &
DISTRIBUTORS INC GR5-1693
1402 N A A C P 476-9601
1403 APARTMENTS
1 TARVER BEN
2 HENRY LEE
3 BOSTON MADELINE MRS 478-8339
4 MITCHELL ROSE 475-9729
STREET CONTINUED
1404 CLEMONT MARY MRS
1406 NUGENT ANDREW GR6-1919
1408 CRANDALL FRANCIS I
HEBERT EUG J • GR5-4934
1409 JACKSON ANNIE GR8-5349
1410 KING ANNA 476-2993
---ROSE AV ENDS
1411 GRACE JOSEPH GR5-4703
NO RETURN
1413 GRAY ALBERTA MRS 475-8805
1415 SINGLETARY S LEWIS GR8-7774
SINGLETARY LONNIE GR5-9582
1417 LEE LAMAR
REAR HALL IDA M
1420 KASNITZ SAML GRO • GR8-0643
JONES ALONZO 476-3431
1421 ABRAMS WASTE MATERIALS CO JUNK
DLRS GR6-3402
1423 LITTLE FRED 475-4684
---SIZER BEGINS
1424 LORINAND GLORIA M 476-3898
LAVEY GERALD
SCHILLINGER FRANK A GR5-5979
WHITE MAE 478-4440
ENKER ANNA MRS GR6-2411
1425 TURNER CHARLIE 476-2601
WILLIAMS WM 478-5602
1427 LESSEN SOL
1428 HALLOCK MILDRED MRS GR5-9170
LYNCH KATHRYN T MRS GR6-1302
1429 KOLDIN IDA MRS • GR8-0554
1430 CASKE FRANK GR8-6478
SILVERBUSCH GUSTA MRS GR8-0285
MARTIN PAULINE MRS
1431 SIMON RAE MRS • GR5-8117
1432 REYNOLDS ROYAL O GR5-6439
1433 MADDOX WALTER 475-4610
1434 VACANT
1435 GLAZIER IDA MRS • GR6-2762

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1959

230 Robinson Cecil E 2 ΔGR8-2394
232 Roberts Homer A 1 ◎ ΔGR8-8832
234 Brunner Beulah M Mrs 1
ΔGR5-5023
236 Bassett Donald 2 ΔGR8-8510

S State st crosses

306 Buettner Peter O 1 ΔGR5-2479
Lormand Arth E 2
307 Maurer Margt M Mrs ◎ ΔGR5-5380
308 Wells Florence L Mrs 1
Buettner Theodore J 2
313 Hughley Wilma 1 ΔGR8-2257
Alexander Elias 2
313½ Masters Mitchell
314 McLeod Sara Mrs 1 ΔGR6-7035
Clair Geraldine A Mrs 2 ΔGR5-0566
Burke Jonas H 2 ◎ ΔGR8-1061
315 Welch Nellie Mrs 1 ΔGR8-5888
316 Bell Willie 1 ΔGR8-5733
317 Brown Louise C Mrs 1
Prahl David 2
318 Blasco Eliz Mrs 1 ◎ ΔGR6-8069
Spencer Prudence I Mrs 2
321 Kravec Wanda ΔGR6-5145

Oakwood av crosses

407 Ogletree John L ◎ ΔGR8-2086
410 Ide Chauncey M jr ◎ ΔGR5-5041
412 Chiasson Andrew I
414 Beloing Seeley ΔGR6-8022
416 Mankoff Saml
418 Davis Ruth Mrs 1 ΔGR6-1579
James Elgirtha Mrs 2
420 LaPlant Geo ◎ ΔGR8-0203
422 Stroman Wm

S McBride st crosses

500 Dykes John D 1 ΔGR6-2370
502 Dykes John jr 2
506 Rochelson Rose Mrs 1 ◎ ΔGR8-2202
Eudell Willie 2 ΔGR6-7220

DL&WRR crosses

516 Vacant

S Almond st ends

601 Jamison Sammie 1 ◎ ΔGR8-2426
Bowman John 1 ΔGR5-1255
Irons Simon 2 ΔGR7-6911
603 Myles Chas 1
Phelps Curtis 2 ΔGR6-5493
Horton Jesse J 3 ΔGR6-0910
605 Levy Goldie 1 ◎
Renert Philip 2 ΔGR8-7960

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1959

Jackson crosses

—— Wilson Playground
1100 Orcutt Harry A 1 ΔGR6-3028
1102 Breland Milfred 2
1104 Wilkerson Eula Mrs 2 ΔGR6-4359
1105 Wilson Community Center
1106 Wynn John W 1 ΔGR5-0193
1108 Russell Andrew 1 ΔGR6-4370
1110 Williams Wm 2
1112 Nealy Theo 2 ΔGR5-9781
1114 Johnson Roderick S 1 ΔGR6-2941
1116 Smoke Louis 1
1118 Hernandez Raymond 2
1120 Breland Emanuel E 2 ΔGR5-5678
1122 Rosenberger Emil F 1 ΔGR6-6276
1124 Mattice Robt S 1
1126 Swart Walter J 2 ΔGR6-4733
1128 Breland Lenward 2 ΔGR5-3731
1130 Nushiewat Jamil S 1

E Taylor crosses

1200 Syracuse Univ Steam Sta
1207 Vacant

DL&WRR crosses

1226 Cooper A Metal Co Inc junk ΔGR5-3144

Burt st crosses

1300 Stroman Geo
1302 Lowe Frank ΔGR8-1946
1304 Busby Myrtle L Mrs © ΔGR6-9577
1305 Welch Patk © ΔGR6-0469
1306 Howington Lucy Mrs ΔGR8-4479
1307 Hoffman Harry ΔGR8-4773
1309 Watson Jas ΔGR6-2486
1311 Edwards Mary J Mrs drsmkr ΔGR6-5926
Brotherton Golder W © ΔGR6-5926
1313 Apostolic Church of Jesus Christ
Jones Robt W Rev 2 © ΔGR5-8585

VanBuren st crosses

1401 Lifetime Home Modernization Corp ΔGR5-1693
1402 Lebowitz Florence Mrs 1 © ΔGR5-1805
1403 Bennett Ruth L 1
Irons Martin 2
Lamps Montroe 3
Weaver Hertha jr 4
1404 Dolan Delos M 2 ΔGR5-7831
1405 Lifetime Air Conditioning Corp ΔGR5-1693
1406 Robinson Oliver © ΔGR6-9630
1408 Hebert Eug J © ΔGR5-4934
1409 Tripp Wilbert 1 ΔGR8-8020
Smith Jas E 2
1410 Williams Carrie

Rose av ends

1411 Grace Jos 1 ΔGR5-4703
Dowdell John 2 ΔGR6-0489
1413 Moore L C 1 ΔGR8-7581
Tooks Otis 2
1415 Singletary Lonnie 2 ΔGR5-9582
Singletary S Lewis 1
1417 Lee Lamar
rear Miller Isiah
1420 Kasnitz Saml gro ΔGR8-0643
Jones Alanzo 2
1421 Abrams Waste Materials Co junk dlrs ΔGR6-3402

Sizer st begins

1423 Schreyer Jas ΔGR6-6522
1424 Enker Anna Mrs 1 ΔGR6-2411
Pinkus Bessie Mrs 1
Delong Gurnard 2 ΔGR6-4674
Alderman Ida M 2 ΔGR6-3909
1425 Kurtz Eliz A Mrs 1 © ΔGR6-6989
Lowe Raymond J jr 2 ΔGR6-6989

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1955

220	FISHER EDW	42882
223	KING GEORGE H	46709
227	RICHARDS WINFIELD	44470
230	ROBINSON CECIL	42394
232	ROBERTS HOMER A	48832
234	PHILLIPS FRED W	753912
306	BUETTNER PETER O	752479
236	FERGUSON DOROTHY	48973
307	MACKEY ALEX	755380
313	HUGHLEY WILMA MRS	42257
313	JOHNSON SAML L	42893
313½	BANKS MARY L	760459
314	BURKE LUCILLE	41061
314	MCLEOD SARAH E MRS	767035
314	TAYLOR WILLIAM	42786
314	WOODS MARY A	765664
315	WELCH WM S MRS	45888
316	TUNSTALL ELLA MAE	45733
317	PAUL MOSES	752209
318	BLASCO ILONA A	768069
321	SMITH LEANDER E	48188
407	OGLETREE JOHNNIE L	42086
410	IDE C M JR	755041
418	DAVIS KITCHING RUTH	761579
418	HUDSON LILLIAN D	43217
420	LAPLANT GEO	40203
422	SWAYZE CAROL	760464
500	DYKES JOHN	762370
502	DANIEL JUDGE B	752856
506	ROCHELSON FRANCIS	42202
516	*BEYNON JNO W	753195
516	*GREENE ORVILLE H	753195
516	*GREENE WM H	753195
516	*WILSON&G LUMBR CO	753195
601	BOWMAN DAISY MAE	751255
601	HALL JOHN	41575
601	MCDUFFIE HOSLEY	751712
603	ASHKIN JOS	766383
603	MESMER MOE	768043
603	SEBELOWITZ LEONARD	48813
605	LEVY IRVING J	40186
605	RENERT PHILIP	47960

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1955

1101	*WILSON CLINIC	764544
1102	SMITH MILDRED L	765000
1116	GOLD MABEL C MRS	45912
1128	FORKEY MARTHA E MRS	767344
1226	*COOPER A METAL CO	753144
1226	*RUBENSTEIN JACK	753144
1300	BURT ANNA	41446
1302	LOWE FRANK	41946
1305	WELCH PATK JAS	760615
1307	HOFFMAN S	44773
1309	BANKS PALMERLEE	766522
1311	BROTHERTON GOLDER W	765926
1313	JONES ROBT W REV	758585
1401	ENGEL ANNE E RN	40830
1401	*LIFE TIME HOME	756800
1402	LEROWITZ FLORENCE	751805
1406	ROBERSON OLIVER	769630
1408	HERBERT EUGENE J	754934
1409	FIELDS HOLLOWAY	755646
1409	HARPER MERLIN H	45467
1411	GRACE JOE	754703
1415	TORRENCE ROGER W	757295
1417	DAVIS JOS MRS	47211
1417	HOFFMAN DEFORREST R	47211
1417	HOPPER ALBERTA J	760026
1420	*KASNITZ GROCRY ST	40643
1421	*ABRAMS WASTE MTRAS	763402
1423	HALECZKO JOHN	45073
1424	ROSENBLATT IDA	763957
1425	KURTZ ELIZ	766989

• 31 136

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1955



1428	GRAY FRANK	48493
1428	LYNCH JANE C	761302
1429	KOLDIN SAM	40554
1430	CASKE FRANK	46478
1430	GREENE BARBARA MISS	762689
1430	NEWER MORRIS	760626
1430	SMEADER CLARENCE D	768711
1431	SIMON SEYMOUR B	758117
1432	BROWN DONALD S	767025
1433	STEIN ANNA E MRS	47577
1434	DEDRICK FRED L	759869
1435	GLAZIER DANIEL	756116

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1949



232 No Return
234 Caselle Theo barber
Hodge John A—1 ◎
236 Hodge Ludwig—2
S State st crosses
306 Melchior Jos E—1
Lormand Arth E—2
307 Mackey Alex mason h ◎
308 Wells Florence L Mrs—1
Buettner Peter O—2 ◎
313 Heath Cynthia Mrs—1
Snyder Adelbert—1
Adamsick Mary Mrs—2
Dunn Thos L
313½ Parlin Elmer E
314 Wells Raymond G—1
Burke Jonas H—2 ◎
315 Pidge Claude E—1
Tarbell Eliz Mrs—2
rear Vacant
316 Henderson Burt—1
317 Brown Louise C Mrs—1
McManus Inez Mrs—2
318 Blasco Wm—1 ◎
Spencer Clarence—2
319 Vacant
321 Vacant
Oakwood av crosses
401 Storage
Vacant—2
405 Moofie Nina Mrs
407 Vacant
410 Gove Lillian Mrs ◎
412 Taylor Hoyt H
414 Burdick Sarah Mrs
416 Mankoff Mary Mrs ◎
418 French Jas F—1 ◎
Beard Wm L—2
420 Swayze Theo W ◎
422 Swayze Carol ◎
S McBride st crosses
500 Fults Curtis W—1 ◎
502 Burgette Inez—2 ◎
504 Bowers Frank C—1 ◎
Schubert Jos—2
506 Rochelson Rose Mrs—1 ◎
Stoltzenau Otto—2
DL&W RR crosses
511 Clark Harriet J Mrs ◎
513 Brewer Fred ◎
515 Campbell Fredk H
516 Wilson & Greene Lumber Co Inc
517 Malay Thos jr
517½ Kelly E Patricia
Almond ct ends
601 Schaknowski Ida Mrs—1
Rubenstein Louis
Keilin Isadore—2
Maxfield Arth
603 Jaffe Aaron—1
Vacant—2
Berger Maurice E—3
605 Levy Rae Mrs—1 ◎
Vacant—2

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1949

1112 Voumard Henry A—2
1114 Vacant—1
1116 Radell Chester E—1
1118 Roupas James G—2
1120 Sherpa Leo R—2
1122 Haynes Howard W—1
1124 Tucci Tessie Mrs—1
1126 Mack Jos J—2
1128 Miller Jas M—2
1130 Dederick Earl F—1
1200 Syracuse University Steam Station
1203 Vacant
1207 Vacant

D L & W R R crosses

1226 Cooper A Metal Co Inc junk

Burt st crosses

1300 Burt Anna Mrs
1302 Cook Howard
1303 Gates Clifford A
1304 Coleman Saml ◎
1305 Rudd Lester
1306 Clark Walter I ◎
1307 Hoffman Harry
1309 Koff Philip ◎
1311 Slosson Frank ◎
1313 Kinne Howard E ◎

VanBuren st crosses

1401 Joh Leopold L & Sons mill supplies ◎
1402 Lebowitz Saml—1 ◎
1403 Henty Elbert J—2
1404 Dolan Delos M—2
1405 Forney Herbert A
1406 Ranieri Frank V
1408 Hebert Eug J
1409 Harper Merlin—1
Edmonds Lindsay—2
1410 Smith John

Rose av ends

1411 Patchett Fredk L—1
Chiasson Adler—2
1413 Salvation Army Outpost The
Sellers Frances—2
1415 Schreyer May Mrs—1
Torrance Roger—2 ◎
1417 Davis Joe—2

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1944

236 Timmons Harry B—2

S State st crosses

306 Melchior Jos E—1
Lormand Arth—2
307 Mackey Alex mason h ◎
308 Wells Florence L Mrs—1
Cooper Wm M—2
311 Wilson Oliver B—1
Sayers May E Mrs—2
313 Heath Cynthia Mrs—1
Adamsick Mary Mrs—2
313½ Parlin Elmer E
314 Babcock T Wm—1
Dunn Thos L—2
Closs Eliz Mrs—2
315 Pidge Claude E—1
Vacant—2
rear Vacant
316 Vacant
317 Brown Louise C Mrs—1
McManus Harry F—2
318 Rahrle Albert L—1
Spencer Clarence—2
319 Derosia Arthur G
321 Hudson Jas C

Oakwood av crosses

401 Vacant store
Cowles Eliz Mrs—2
405 Vacant
407 Morrissey Mary V ◎
410 Gorman Lillian E Mrs birds and dogs h ◎
412 Taylor Bernice Mrs
414 Burdick Isadore ◎
416 Mankoff Mary Mrs
418 Vacant—1
Griffin Steve—2
420 Swayze Theo W
422 Brownell Everett S

S McBride st crosses

500 Witaszek Jos—1
Kimball Arthur F—2
502 Vacant
504 Trickler Dorothy M Mrs—1
Vacant—2
506 Rochelson Rose Mrs—1 ◎
Stoltzenau Otto—2

DL&W RR crosses

511 Clark Harriet J Mrs ◎
513 Whitney Arvilla C Mrs
515 Campbell Fredk

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1944

1100 Davis Chas L—1
1102 Siegel Riech M—2
1104 Uzunoff Grigor—2
1106 Knox Robt V—1
1108 Vacant
1110 Craig Thomas F—2
Wilson playground
East Taylor st crosses
1112 Hardter Herbert—2
1114 Shuman David—1
1116 Radell Chester E—1
1118 Macri Thos—2
1120 Balstra Peter—2
1122 Johnson Leo A—1
1124 Tucci Leonard—1
1126 Coon Donald—2
1128 Marrapese Adrian—2
1130 Dederick Earl F—1
E Taylor st crosses
1200 Syracuse University Steam Station
1203 Rawson John A
1205 Vacant
1207 Wilson & Greene Lumber Co bldg supplies
D L & W R R crosses
1226 Cooper A Metal Co Inc junk
Burt st crosses
1300 Burt Anna Mrs
1302 Cook Geo H
1303 Peck Alf B—1
Jock Albert—2
1304 Meltzer Hyman ◎
1305 Rudd Lester M
1306 Clark Walter I ◎
1307 Hoffman Jennie
1309 Koff Philip ◎
1311 Smith Wm B
1313 DeNero Michl
VanBuren st crosses
1401 Vacant
1402 Hurwitz Simon ◎
1403 Vacant
1404 Dolan Delos M—2
1405 Forney Herbert A
1406 Ranieri Frank
1408 Brown Leo W—1
Hebert Eug J—2
1409 Lessen Dora Mrs—1
Broga Arthur—2
1410 Chiasson Maurice
Rose av ends
1411 Patchett Fredk L—1
Gridley Wm P—2
1413 Davis Jos R—1
Vacant—2
1415 Hopseker Carl J—1
Perks Chas H pntr h—2
1417 Hoffman Francis W
1420 Kasnitz Saml gro h
1421 Abrams Waste Materials Co junk
Sizer st begins
1423 Lewis Margt Mrs
1424 Pinkus Bessie Mrs—1
Goldstein Sam
Rosenblatt Reuben—2
Moser Florence Mrs—2
1425 Lowe Mary A Mrs—1 ◎
Murphy Patk J—2
1427 Katzowitz Jacob
rear Oney Clarence
1428 Steinberg Louis—1
Lynch Kathryn T Mrs—2
1429 Koldin Hyman
1430 Glazier Danl—1
Bissette Alfred—1
Smeader Clarence D—2
Beagle Geo

Target Street	Cross Street	Source
✓	-	Polk's City Directory

BURT ST 1939

306 Trass Henry—1
Muirhead Henrietta B Mrs—2
307 Mackey Alex mason h ◎
308 Wells Florence L Mrs—1
Cooper Wm M—2
309 Nelson Edwd J
311 Bloss John A—1
Sayers Jas D—2
313 Lamphere Jos W pntr h—1
Clarke Harold G—2
Dennis Geo W
313½ Garfield Francis E
314 Babcock T Wm—1
Garfield Clarence C—2
Burke Michl J
315 Pidge Claude E—1
Kirkby Levi—2
rear Vacant
316 Buettner Peter O—1 ◎
317 Thurner Rudolph—1
LaFlam Frances A Mrs—2
318 Rahrle Albert L—1
Spencer Clarence—2
319 Derosia Arthur G
321 Smith Burt W

Oakwood av crosses

401 Vacant store
Bowman Lloyd C—2
405 Weaver Clinton M
407 Morrissey Mary V ◎
410 Gorman Lillian E Mrs birds and dogs h ◎
412 Corlew Albert
414 Burdick Isadore ◎
416 Mankoff Mary Mrs
418 Swayze Theo W—1
Smith Anna C Mrs—2
420 Blaich Geo ◎
422 Burt Geo A oil burners and stoves h

S McBride st crosses

500 Witaszek Jos—1
501 Scornick Service Station gas sta
502 Rudd Geo E—2
504 Osborne Louis pntr h 1
Angell Harold E—2
506 Rochelson Rose Mrs—1 ◎
Lobdell Wm L—2
Lobdell Arthur pntr h—2
508 LaRonde Lawrence J—1
Dolan Roy W—2
508½ Curtis Lena M Mrs

DL&W RR crosses

511 Clark Harriet J Mrs ◎
513 Howe Jos D
515 Radell Chester E
515½ Frink Marshall
516 Wilson & Greene Lumber Co ◎
517 Howser Geo B
517½ Kelly Ella P Mrs

Almond st ends

601 Hoffman Isadore—1
Stern Harry
Friedman David—2 ◎
Keilin Isadore
603 Scornick Eli—1
Lesson David truckmn h—1
Besdin Benj—2
Elkin Abr—3
605 Levy Barnet—1
Vacant—2

Target Street	Cross Street	Source
-	✓	Polk's City Directory

S MCBRIDE ST 1939

1100 to 1110 Syracuse Housing Project
Star av ends
1112 to 1118 Syracuse Housing Project
Wilson playground
E Taylor st crosses
1200 Syracuse University Steam Station
1203 Rawson John A
1205 Haven John H ◎
1207 Wilson & Greene Lumber Co bldg supplies
D L & W R R crosses
1226 Cooper A Metal Co Inc
Burt st crosses
1300 Burt Anna Mrs
1302 Cook Geo ◎
1303 Kimball Arthur F
1304 Meltzer Hyman ◎
1305 Ryder Geo
1306 Singer Chas ◎
1307 Markowitz Albert ◎
1309 Vacant
1311 Parish Francis L
1313 Hoffman Goldie Mrs
VanBuren st crosses
1401 Sher Asher meats
1402 Hurwitz Simon ◎
1403 Forney Herbert A
1404 Sheley Arthur A
1405 Levine Louis
1406 Ranieri Frank
1408 Clemons Richd J—1
Hebert Eug J—2
1409 Lessen Julius—1
Sheley Frank N—2
1410 Phinney Lyle
Rose av ends
1411 Rousseau Peter—1 ◎
Fox Robt J
Stegmen Fred W
1413 Davis Jos R—1
Lewis Margt Mrs—2
1415 Demperio Thos—1
Perks Chas H pntr h—2
1417 Corp Richd T
1419 Vacant
1420 Stolusky Jos gro h
1421 Abrams Waste Materials Co Inc junk
Sizer st begins
1423 Fox Jane Mrs
1424 Pinkus Bessie Mrs—1
Barney Leon C
Williams Claude A—2
Rosenblatt Reuben

East Adams Redevelopment - Phase 8 Area

409 Burt Street

Syracuse, NY 13202

Inquiry Number: 8026569.3

June 23, 2025

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

06/23/25

Site Name:

East Adams Redevelopment - I
409 Burt Street
Syracuse, NY 13202
EDR Inquiry # 8026569.3

Client Name:

Langan
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
Contact: Lexi Haley

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Langan were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # BDD1-4828-968C

PO # 170859701

Project EA Redevelopment - Phase 8

Maps Provided:

1990
1971
1968
1961
1953
1951
1910
1892

Sanborn® Library search results

Certification #: BDD1-4828-968C

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Langan (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1990 Source Sheets


Volume 1A, Sheet 10a
1990

Volume 1A, Sheet 12a
1990


Volume 1A, Sheet 26a
1990


Volume 1A, Sheet 8a
1990

Volume 1A, Sheet 25a
1990

Volume 1, Sheet 26
1990

1971 Source Sheets

Volume 1, Sheet 26
1971

Volume 1A, Sheet 25a
1971


Volume 1A, Sheet 8a
1971

Volume 1A, Sheet 26a
1971

Volume 1A, Sheet 12a
1971


Volume 1A, Sheet 10a
1971

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1968 Source Sheets


Volume 1A, Sheet 10a
1968

Volume 1A, Sheet 12a
1968

Volume 1A, Sheet 26a
1968


Volume 1A, Sheet 8a
1968

Volume 1, Sheet 26
1968

Volume 1A, Sheet 25a
1968

1961 Source Sheets

Volume 1A, Sheet 25a
1961

Volume 1A, Sheet 26a
1961

Volume 1A, Sheet 12a
1961

Volume 1A, Sheet 10a
1961

1953 Source Sheets

Volume 1A, Sheet 10a
1953

Volume 1A, Sheet 12a
1953

Volume 1A, Sheet 26a
1953

Volume 1A, Sheet 25a
1953

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1953 Source Sheets

Volume 1, Sheet 26
1953

1951 Source Sheets

Volume 1, Sheet 26
1951

Volume 1, Sheet 89
1951

Volume 1, Sheet 25
1951

Volume 1, Sheet 12
1951

Volume 1, Sheet 10
1951

1910 Source Sheets

Volume 1, Sheet 10
1910

Volume 1, Sheet 12
1910

Volume 1, Sheet 25
1910

Volume 1, Sheet 26
1910

1892 Source Sheets

Volume 1, Sheet 64
1892

Volume 1, Sheet 57
1892

Volume 1, Sheet 63
1892

Volume 1, Sheet 58
1892



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #:	BDD1-4828-968C
Copyright	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 26
Volume 1A, Sheet 25a
Volume 1A, Sheet 8a
Volume 1A, Sheet 26a
Volume 1A, Sheet 12a
Volume 1A, Sheet 10a

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #	BDD1-4828-968C
Copyright	1971

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1A, Sheet 10a
Volume 1A, Sheet 12a
Volume 1A, Sheet 26a
Volume 1A, Sheet 8a
Volume 1A, Sheet 25a
Volume 1, Sheet 26

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #BDD1-4828-968C

Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #:	BDD1-4828-968C
Copyright	1968

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1A, Sheet 25a
Volume 1, Sheet 26
Volume 1A, Sheet 8a
Volume 1A, Sheet 26a
Volume 1A, Sheet 12a
Volume 1A, Sheet 10a

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #BDD1-4828-968C

Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #:	BDD1-4828-968C
Copyright	1961

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1A, Sheet 10a
Volume 1A, Sheet 12a
Volume 1A, Sheet 26a
Volume 1A, Sheet 25a

0 Feet 150 300 600

N

Certified Sanborn® Map

1953



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #:	BDD1-4828-968C
Copyright	1953

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 26
Volume 1A, Sheet 25a
Volume 1A, Sheet 26a
Volume 1A, Sheet 12a
Volume 1A, Sheet 10a

0 Feet 150 300 600

N



Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #	BDD1-4828-968C
Copyright	1951

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 10
Volume 1, Sheet 12
Volume 1, Sheet 25
Volume 1, Sheet 89
Volume 1, Sheet 26

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #BDD1-4828-968C

Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #:	BDD1-4828-968C
Copyright	1910

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 26
Volume 1, Sheet 25
Volume 1, Sheet 12
Volume 1, Sheet 10

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #BDD1-4828-968C

Site Name:	East Adams Redevelopment - Phase 8 Area
Address:	409 Burt Street
City, ST, ZIP:	Syracuse, NY 13202
Client:	Langan
EDR Inquiry:	8026569.3
Order Date:	06/23/2025
Certification #	BDD1-4828-968C
Copyright	1892

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 58
Volume 1, Sheet 63
Volume 1, Sheet 57
Volume 1, Sheet 64

0 Feet 150 300 600

N

East Adams Redevelopment - Phase 8 Area

409 Burt Street

Syracuse, NY 13202

Inquiry Number: 8026569.11

June 23, 2025

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

06/23/25

Site Name:

East Adams Redevelopment - I
409 Burt Street
Syracuse, NY 13202
EDR Inquiry # 8026569.11

Client Name:

Langan
368 Ninth Avenue, 8th Floor
New York, NY 10001-2727
Contact: Lexi Haley

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2022	1"=500'	Flight Year: 2022	USDA/NAIP
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2008	1"=500'	Flight Year: 2008	USDA/NAIP
1995	1"=500'	Acquisition Date: March 27, 1995	USGS/DOQQ
1988	1"=500'	Flight Date: October 31, 1988	NYDOT
1986	1"=500'	Flight Date: April 14, 1986	USDA
1978	1"=500'	Flight Date: September 13, 1978	USDA
1966	1"=500'	Flight Date: July 01, 1966	USDA
1959	1"=500'	Flight Date: June 15, 1959	USDA
1951	1"=500'	Flight Date: October 15, 1951	USDA
1938	1"=500'	Flight Date: September 05, 1938	USDA

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

INQUIRY #: 8026569.11

YEAR: 2022

= 500'

N

EDR

INQUIRY #: 8026569.11
YEAR: 2019
= 500'
N
EDR

INQUIRY #: 8026569.11
YEAR: 2015
= 500'
N
EDR

INQUIRY #: 8026569.11
YEAR: 2011
= 500'
N
EDR


INQUIRY #: 8026569.11
YEAR: 2008
= 500'
N
EDR

INQUIRY #: 8026569.11
YEAR: 1995
= 500'
N
EDR


INQUIRY #: 8026569.11
YEAR: 1988
= 500'
N
EDR

INQUIRY #: 8026569.11
YEAR: 1986
= 500'
N
EDR


INQUIRY #: 8026569.11
YEAR: 1978
= 500'
N
EDR


INQUIRY #: 8026569.11
YEAR: 1966
= 500'
N
EDR


INQUIRY #: 8026569.11
YEAR: 1959
= 500'
N
EDR



INQUIRY #: 8026569.11

YEAR: 1951

= 500'

N

EDR



INQUIRY #: 8026569.11

YEAR: 1938

= 500'

N

EDR

East Adams Redevelopment - Phase 8 Area

409 Burt Street

Syracuse, NY 13202

Inquiry Number: 8026569.4

June 23, 2025

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

06/23/25

Site Name:	Client Name:
East Adams Redevelopment - I	Langan
409 Burt Street	368 Ninth Avenue, 8th Floor
Syracuse, NY 13202	New York, NY 10001-2727
EDR Inquiry # 8026569.4	Contact: Lexi Haley

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Langan were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:		*Coordinates:*	
P.O.#	170859701	**Latitude:**	43.038714 43° 2' 19" North
Project:	EA Redevelopment - Phase 8	**Longitude:**	-76.145026 -76° 8' 42" West
		UTM Zone:	Zone 18 North
		UTM X Meters:	406729.00
		UTM Y Meters:	4765750.05
		Elevation:	403.78' above sea level

Maps Provided:

2019	1938, 1939
2016	1898
2013	1895
1978	
1973, 1977	
1957, 1958	
1947	
1939, 1943	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets

Syracuse West
2019
7.5-minute, 24000

Syracuse East
2019
7.5-minute, 24000

2016 Source Sheets

Syracuse West
2016
7.5-minute, 24000

Syracuse East
2016
7.5-minute, 24000

2013 Source Sheets

Syracuse West
2013
7.5-minute, 24000

Syracuse East
2013
7.5-minute, 24000

1978 Source Sheets

Syracuse East
1978
7.5-minute, 24000
Aerial Photo Revised 1976

Syracuse West
1978
7.5-minute, 24000
Aerial Photo Revised 1976

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1973, 1977 Source Sheets

Syracuse West
1973
7.5-minute, 24000
Aerial Photo Revised 1972

Syracuse East
1977
7.5-minute, 24000
Aerial Photo Revised 1972

1957, 1958 Source Sheets

Syracuse East
1957
7.5-minute, 24000
Aerial Photo Revised 1956

Syracuse West
1958
7.5-minute, 24000
Aerial Photo Revised 1956

1947 Source Sheets

Syracuse West
1947
7.5-minute, 31680

1939, 1943 Source Sheets

Syracuse West
1939
7.5-minute, 31680

Syracuse East
1943
7.5-minute, 31680

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1938, 1939 Source Sheets



Syracuse East
1938
7.5-minute, 24000

1898 Source Sheets

Syracuse
1898
15-minute, 62500

1895 Source Sheets

Syracuse
1895
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse West, 2019, 7.5-minute
E, Syracuse East, 2019, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 A
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N

Historical Topo Map

2016



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse West, 2016, 7.5-minute
E, Syracuse East, 2016, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 Al
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N

Historical Topo Map

2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse West, 2013, 7.5-minute
E, Syracuse East, 2013, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 Al
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Syracuse West, 1978, 7.5-minute
E, Syracuse East, 1978, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 A
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N



This report includes information from the following map sheet(s).



TP, Syracuse West, 1973, 7.5-minute
E, Syracuse East, 1977, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 A
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Syracuse West, 1958, 7.5-minute
E, Syracuse East, 1957, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 Al
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse West, 1947, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 Al
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse West, 1939, 7.5-minute
E, Syracuse East, 1943, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 Al
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse West, 1939, 7.5-minute
E, Syracuse East, 1938, 7.5-minute

SITE NAME: East Adams Redevelopment - Phase 8 A
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse, 1898, 15-minute

SITE NAME: East Adams Redevelopment - Phase 8 A
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Syracuse, 1895, 15-minute

SITE NAME: East Adams Redevelopment - Phase 8 A
ADDRESS: 409 Burt Street
Syracuse, NY 13202
CLIENT: Langan

N

East Adams Redevelopment - Phase 8 Area
409 Burt Street
Syracuse, NY 13202

Inquiry Number: 8026569.6
June 23, 2025

The EDR Property Tax Map Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Property Tax Map Report

Environmental Data Resources, Inc.'s EDR Property Tax Map Report is designed to assist environmental professionals in evaluating potential environmental conditions on a target property by understanding property boundaries and other characteristics. The report includes a search of available property tax maps, which include information on boundaries for the target property and neighboring properties, addresses, parcel identification numbers, as well as other data typically used in property location and identification.

NO COVERAGE

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

East Adams Redevelopment - Phase 8 Area
409 Burt Street
Syracuse, NY 13202

Inquiry Number: 8026569.7
June 23, 2025

EDR Building Permit Report

Target Property and Adjoining Properties

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

About This Report

Executive Summary

Findings

Glossary

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILD FAX PROPERTY HISTORY

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

A search of building department records was conducted by Environmental Data Resources, Inc (EDR) on behalf of Langan on Jun 23, 2025.

TARGET PROPERTY

409 Burt Street
Syracuse, NY 13202

SEARCH METHODS

EDR searches available lists for both the Target Property and Surrounding Properties.

RESEARCH SUMMARY

Building permits identified: **YES**

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Syracuse

Year	*Source*	*TP*	*Adjoining*
2025	City of Syracuse, Division of Code Enforcement		X
2024	City of Syracuse, Division of Code Enforcement		X
2023	City of Syracuse, Division of Code Enforcement		X
2022	City of Syracuse, Division of Code Enforcement		X
2021	City of Syracuse, Division of Code Enforcement		X
2020	City of Syracuse, Division of Code Enforcement		X
2019	City of Syracuse, Division of Code Enforcement		X
	City of Syracuse, Division of Code Enforcement	X	
2018	City of Syracuse, Division of Code Enforcement		X
	City of Syracuse, Division of Code Enforcement	X	
2017	City of Syracuse, Division of Code Enforcement		X
2016	City of Syracuse, Division of Code Enforcement		X
2015	City of Syracuse, Division of Code Enforcement		X
2014	City of Syracuse, Division of Code Enforcement		X
2013	City of Syracuse, Division of Code Enforcement		X
2012	City of Syracuse, Division of Code Enforcement		X
2011	City of Syracuse, Division of Code Enforcement		X
2010	City of Syracuse, Division of Code Enforcement		X
2009	City of Syracuse, Division of Code Enforcement		X
2008	City of Syracuse, Division of Code Enforcement		X
2007	City of Syracuse, Division of Code Enforcement		X
2006	City of Syracuse, Division of Code Enforcement		X
2005	City of Syracuse, Division of Code Enforcement		X
2004	City of Syracuse, Division of Code Enforcement		X
2003	City of Syracuse, Division of Code Enforcement		X
	City of Syracuse, Division of Code Enforcement	X	
2002	City of Syracuse, Division of Code Enforcement		X
2001	City of Syracuse, Division of Code Enforcement		X

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

Year	Source	TP	Adjoining
2000	City of Syracuse, Division of Code Enforcement		X
1999	City of Syracuse, Division of Code Enforcement		X
1998	City of Syracuse, Division of Code Enforcement		
1997	City of Syracuse, Division of Code Enforcement		
1996	City of Syracuse, Division of Code Enforcement		
1995	City of Syracuse, Division of Code Enforcement		
1994	City of Syracuse, Division of Code Enforcement		
1993	City of Syracuse, Division of Code Enforcement		
1992	City of Syracuse, Division of Code Enforcement		
1991	City of Syracuse, Division of Code Enforcement		
1990	City of Syracuse, Division of Code Enforcement		
1989	City of Syracuse, Division of Code Enforcement		
1988	City of Syracuse, Division of Code Enforcement		
1987	City of Syracuse, Division of Code Enforcement		
1986	City of Syracuse, Division of Code Enforcement		
1985	City of Syracuse, Division of Code Enforcement		
1984	City of Syracuse, Division of Code Enforcement		
1983	City of Syracuse, Division of Code Enforcement		
1982	City of Syracuse, Division of Code Enforcement		
1981	City of Syracuse, Division of Code Enforcement		
1980	City of Syracuse, Division of Code Enforcement		
1979	City of Syracuse, Division of Code Enforcement		
1978	City of Syracuse, Division of Code Enforcement		
1977	City of Syracuse, Division of Code Enforcement		
1976	City of Syracuse, Division of Code Enforcement		
1975	City of Syracuse, Division of Code Enforcement		
1974	City of Syracuse, Division of Code Enforcement		
1973	City of Syracuse, Division of Code Enforcement		
1972	City of Syracuse, Division of Code Enforcement		
1971	City of Syracuse, Division of Code Enforcement		
1970	City of Syracuse, Division of Code Enforcement		
1969	City of Syracuse, Division of Code Enforcement		
1968	City of Syracuse, Division of Code Enforcement		
1967	City of Syracuse, Division of Code Enforcement		
1966	City of Syracuse, Division of Code Enforcement		
1965	City of Syracuse, Division of Code Enforcement		
1964	City of Syracuse, Division of Code Enforcement		
1963	City of Syracuse, Division of Code Enforcement		
1962	City of Syracuse, Division of Code Enforcement		
1961	City of Syracuse, Division of Code Enforcement		
1960	City of Syracuse, Division of Code Enforcement		

Name: JurisdictionName
Years: Years
Source: Source
Phone: Phone

BUILDING DEPARTMENT RECORDS SEARCHED

Name: Syracuse
Years: 1960-2025
Source: City of Syracuse, Division of Code Enforcement, SYRACUSE, NY
Phone: (315) 448-8600

Name: Ithaca town
Years: 1955-2019
Source: Town of Ithaca, Building and Code Enforcement Department, BINGHAMTON, NY
Phone: (607) 273-1783

Name: De Witt town
Years: 1974-2015
Source: , SYRACUSE, NY
Phone: (315) 446-3910

TARGET PROPERTY FINDINGS

TARGET PROPERTY DETAIL

409 Burt Street
Syracuse, NY 13202

409 BURT ST

Date:	**2/26/2019**
Permit Type:	
Description:	**Demolish a storage building**
Permit Description:	**Demolition**
Work Class:	
Proposed Use:	
Permit Number:	36926
Status:	
Valuation:	$1,800.00
Contractor Company:	
Contractor Name:	Diversified Construction Services

Date:	**10/9/2018**
Permit Type:	
Description:	**Electric for new pole service.**
Permit Description:	**Electric**
Work Class:	
Proposed Use:	
Permit Number:	35571
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Syr Housing Authority

TARGET PROPERTY FINDINGS

Date:	**3/28/2003**
Permit Type:	**COMMERCIAL**
Description:	
Permit Description:	**INTRUSION ALARM SYSTEM**
Work Class:	
Proposed Use:	
Permit Number:	61246
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

BURT ST

407 BURT ST

Date:	**12/30/2010**
Permit Type:	**RESIDENTIAL**
Description:	**DEMO ONE STORY WOOD FRAME SINGLE FAMILY PER THE ATTACHED APPROVALS.**
Permit Description:	**DEMOLTION**
Work Class:	
Proposed Use:	
Permit Number:	99995
Status:	
Valuation:	$6,000.00
Contractor Company:	
Contractor Name:	

Date:	**1/28/2009**
Permit Type:	**RESIDENTIAL**
Description:	
Permit Description:	**HEATING**
Work Class:	
Proposed Use:	
Permit Number:	91333
Status:	
Valuation:	$1,800.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

410 BURT ST

Date:	**12/9/1999**
Permit Type:	**RESIDENTIAL**
Description:	**DEMOLISH 1 FAMILY STRUCTURE**
Permit Description:	**DEMOLTION**
Work Class:	
Proposed Use:	
Permit Number:	43031
Status:	
Valuation:	$5,000.00
Contractor Company:	
Contractor Name:	

412 BURT ST

Date:	**12/9/1999**
Permit Type:	**RESIDENTIAL**
Description:	**DEMOLISH 1 FAMILY STRUCTURE**
Permit Description:	**DEMOLTION**
Work Class:	
Proposed Use:	
Permit Number:	43030
Status:	
Valuation:	$500.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

414 BURT ST

Date:	**10/15/2007**
Permit Type:	**RESIDENTIAL**
Description:	**DEMO ONE FAMILY PER THE ATTACHED APPROVALS.**
Permit Description:	**DEMOLTION**
Work Class:	
Proposed Use:	
Permit Number:	85179
Status:	
Valuation:	$6,000.00
Contractor Company:	
Contractor Name:	

418 BURT ST

Date:	**7/19/2002**
Permit Type:	**RESIDENTIAL**
Description:	**DEMO 2 FAM WOOD STRUCTURE**
Permit Description:	**DEMOLTION**
Work Class:	
Proposed Use:	
Permit Number:	57755
Status:	
Valuation:	$3,000.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

450 BURT ST

Date: **6/27/2019**
Permit Type:
Description: **Kitchen Hood - Freedom Commons**

Permit Description: **HVAC/Mechanical**
Work Class:
Proposed Use:
Permit Number: 38331
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Freedom Commons Housing

Date: **5/9/2018**
Permit Type:
Description: **Fire alarms for Freedom Commons**

Permit Description: **Fire Alarm**
Work Class:
Proposed Use:
Permit Number: 30897
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **5/7/2018**
Permit Type:
Description: **Sprinkler**

Permit Description: **Sprinkler**
Work Class:
Proposed Use:
Permit Number: 33235
Status:
Valuation: $1,500.00
Contractor Company:
Contractor Name: Freedom Commons Housing

ADJOINING PROPERTY FINDINGS

Date: **3/26/2018**
Permit Type:
Description: **Install new elevator**

Permit Description: **Elevator**
Work Class:
Proposed Use:
Permit Number: 31130
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Freedom Commons Housing

Date: **1/18/2018**
Permit Type:
Description: **Electric**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 31196
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Hoefler Communications Inc

Date: **1/11/2018**
Permit Type:
Description: **HVAC for Freedom Commons**

Permit Description: **HVAC/Mechanical**
Work Class:
Proposed Use:
Permit Number: 31131
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Freedom Commons Housing

ADJOINING PROPERTY FINDINGS

Date: **10/25/2017**
Permit Type:
Description: **HVAC for Freedom Commons**

Permit Description: **Sprinkler**
Work Class:
Proposed Use:
Permit Number: 30484
Status:
Valuation: $35,000.00
Contractor Company:
Contractor Name: Freedom Commons Housing

Date: **5/24/2017**
Permit Type:
Description: **Site Work**

Permit Description: **Site Work**
Work Class:
Proposed Use:
Permit Number: 27575
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse Housing Authority

Date: **5/24/2017**
Permit Type:
Description: **Erect New Building.****TCO typed, awaiting signatures 7/8/2019****C of O typed, awaiting signatures 7/19/2019***C of O issued 7/22/2019**

Permit Description: **Com. New Building**
Work Class:
Proposed Use:
Permit Number: 27576
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Norstar Building Corp

ADJOINING PROPERTY FINDINGS

Date: **5/24/2017**
Permit Type:
Description: **Electric**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 28445
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Freedom Commons Housing c/o Syracuse Housing Authority

E TAYLOR ST

301 E TAYLOR ST

Date: **9/10/2002**
Permit Type: **RESIDENTIAL**
Description: **MC KINNEY MANOR- 119 ANGELOU TERR.**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 58625
Status:
Valuation: $1,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

500 E TAYLOR ST

Date:	**1/15/2025**
Permit Type:	
Description:	**Construct building for vehicle and equipement storage**
Permit Description:	**Com. New Building**
Work Class:	
Proposed Use:	
Permit Number:	51146
Status:	
Valuation:	$900.00
Contractor Company:	
Contractor Name:	Parsons and McKenna

Date:	**9/3/2024**
Permit Type:	
Description:	**Replace VFD and motor for ID Fan #3**
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	ELECTRIC-2024-847
Status:	Approved
Valuation:	$80,000.00
Contractor Company:	
Contractor Name:	

Date:	**6/12/2024**
Permit Type:	
Description:	**Install Lighting, Devices and Data in New Office Spaces**
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	ELECTRIC-2024-523
Status:	Finaled
Valuation:	$90,220.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date:	**6/11/2024**
Permit Type:	
Description:	**Renovate 325 sq ft office space ****CO TYPED-AWAITING SIGNATURES 10/7/2024CO ISSUED 11/25/2024**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	50009
Status:	
Valuation:	$2,500.00
Contractor Company:	
Contractor Name:	Syracuse University

Date:	**4/12/2024**
Permit Type:	
Description:	**New Building**
Permit Description:	**Com. New Building**
Work Class:	
Proposed Use:	
Permit Number:	503744
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Bond Building Construction Inc.

Date:	**4/5/2024**
Permit Type:	
Description:	**New Building**
Permit Description:	**Com. New Building**
Work Class:	
Proposed Use:	
Permit Number:	50374
Status:	
Valuation:	$12,100.00
Contractor Company:	
Contractor Name:	Bond Building Construction Inc.

ADJOINING PROPERTY FINDINGS

Date: **3/21/2024**
Permit Type:
Description: **Replace emergency lights, demo abandoned conduit**

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: ELECTRIC-2024-239
Status: Approved
Valuation: $2,000.00
Contractor Company:
Contractor Name:

Date: **1/2/2024**
Permit Type:
Description: **Footing and Foundation - SU STEAM**

Permit Description: **Footing / Foundation**
Work Class:
Proposed Use:
Permit Number: 50002
Status:
Valuation: $18,000.00
Contractor Company:
Contractor Name: Bond Building Construction Inc.

Date: **12/19/2023**
Permit Type:
Description: **electrical service, power, lights, data, fire alarm, security, communications etc....**

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: ELECTRIC-2023-1189
Status: Approved
Valuation: $10.50
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**12/5/2023**
Permit Type:	
Description:	**Site Work - Steam Plant**
Permit Description:	**Site Work**
Work Class:	
Proposed Use:	
Permit Number:	49806
Status:	
Valuation:	$50.00
Contractor Company:	
Contractor Name:	Bond Building Construction Inc.

Date:	**10/23/2023**
Permit Type:	
Description:	**Select electrical demo & temporary power**
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	ELECTRIC-2023-1012
Status:	Approved
Valuation:	$50,000.00
Contractor Company:	
Contractor Name:	

Date:	**6/1/2022**
Permit Type:	
Description:	**Upgrade to life safety event reporting system panel.**
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	ELECTRIC-2022-521
Status:	Approved
Valuation:	$10,000.00
Contractor Company:	
Contractor Name:	David Maher

ADJOINING PROPERTY FINDINGS

Date:	**3/8/2022**
Permit Type:	
Description:	**SEC Riley Plant Deaerator Upgrade**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	45671
Status:	
Valuation:	$400.00
Contractor Company:	
Contractor Name:	Industrial Contracting Inc.

Date:	**2/3/2022**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	ELECTRIC-2022-28
Status:	Approved
Valuation:	$120,000.00
Contractor Company:	
Contractor Name:	Kaitlynne Knapp

Date:	**4/22/2021**
Permit Type:	
Description:	
Permit Description:	**Electrical**
Work Class:	
Proposed Use:	
Permit Number:	SUBMISSION-2021-521
Status:	Approved
Valuation:	$43,000.00
Contractor Company:	
Contractor Name:	Kaitlynne Knapp

ADJOINING PROPERTY FINDINGS

Date: **3/17/2021**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: SUBMISSION-2021-334
Status: Approved
Valuation: $7,850.00
Contractor Company:
Contractor Name: Joseph Cardinal

Date: **12/3/2019**
Permit Type:
Description: **Electric: Steam and Chilled Water**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 40266
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **11/6/2019**
Permit Type:
Description: **Modifications to the steam plant's neutralization system & upgrades of equipment**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 39616
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: MRL Constructors of New York Inc

ADJOINING PROPERTY FINDINGS

Date:	**11/4/2019**
Permit Type:	
Description:	**Modifications to the steam plant's neutralization system & upgrades of equipment including the removal of the mezzanine.**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	39617
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Industrial Contracting Inc.

Date:	**9/16/2019**
Permit Type:	
Description:	**Electric: units 201 and 202, Steam and Chilled Water**
Permit Description:	**Electric**
Work Class:	
Proposed Use:	
Permit Number:	39386
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Syracuse University

Date:	**9/4/2019**
Permit Type:	
Description:	**HVAC: Steam and Chilled Water**
Permit Description:	**HVAC/Mechanical**
Work Class:	
Proposed Use:	
Permit Number:	39246
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Syracuse University

ADJOINING PROPERTY FINDINGS

Date: **5/16/2019**
Permit Type:
Description: **Electric: Steam and Chilled Water**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 37980
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **4/15/2019**
Permit Type:
Description: **Electric**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 37606
Status:
Valuation: $8,000.00
Contractor Company:
Contractor Name:

Date: **2/22/2019**
Permit Type:
Description: **Tank Removal: Remove (1) 275 US Gallon above ground fuel oil tank.Department of Environmental Conservation - Spill Number: 1810736**

Permit Description: **FPB Tank - Removal**
Work Class:
Proposed Use:
Permit Number: 36849
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **5/15/2018**
Permit Type:
Description: **electric - 2nd flr steam station**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 33305
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **11/20/2017**
Permit Type:
Description: **Low voltage for 2nd floor**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 30761
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **10/25/2017**
Permit Type:
Description: **Electric - Low Voltage for Steam and Chilled Water**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 30526
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

ADJOINING PROPERTY FINDINGS

Date: **5/17/2017**
Permit Type:
Description: **Fire alarms for Alco & Riley building**

Permit Description: **Fire Alarm**
Work Class:
Proposed Use:
Permit Number: 28074
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **5/1/2017**
Permit Type:
Description: **electric**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 28328
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: O'Connell Electric

Date: **4/6/2017**
Permit Type:
Description: **Replace flat roof and structural modifications**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 27789
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

ADJOINING PROPERTY FINDINGS

Date: **6/6/2016**
Permit Type:
Description: **Generator Docking Station & Additional Lighting Upgrades.**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 24214
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **12/2/2015**
Permit Type:
Description: **Electrical**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 22108
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **11/30/2015**
Permit Type:
Description: **Low Voltage**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 21914
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

ADJOINING PROPERTY FINDINGS

Date: **8/27/2015**
Permit Type:
Description: **Electrical**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 20680
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **3/25/2015**
Permit Type:
Description: **elec**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 18648
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **8/5/2014**
Permit Type:
Description: **Electrical for Steam Station**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 16104
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

ADJOINING PROPERTY FINDINGS

Date:	**6/2/2014**
Permit Type:	
Description:	**HVAC-Steam station second floor offices**
Permit Description:	**HVAC/Mechanical**
Work Class:	
Proposed Use:	
Permit Number:	14398
Status:	
Valuation:	$199,655.00
Contractor Company:	
Contractor Name:	Syracuse University

Date:	**6/2/2014**
Permit Type:	
Description:	**Instrumentation Upgrade for Riley Steam Station Pressure Reduction.EMERALD ELECTRIC CONTRACTORS (14123)**
Permit Description:	**Electric**
Work Class:	
Proposed Use:	
Permit Number:	15421
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Emerald Electrical Contractors

Date:	**5/30/2014**
Permit Type:	
Description:	**Install a panelized office system with mezzanine above on 2nd floor of Steam Station**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	14975
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Syracuse University

ADJOINING PROPERTY FINDINGS

Date: **5/30/2014**
Permit Type:
Description: **Exterior alterations related to the installation of a high-pressure gas line.**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 15029
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syracuse University

Date: **11/8/2013**
Permit Type:
Description: **RILEY BUILDING @ SU STEAM STATION: - FOUR EYE WASH AND SHOWER STATIONS WITH ASSOCIATED DETECTION AND ALARM ANNUNCIATIONALLIED ELECTRIC**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 13327
Status:
Valuation: $20,320.00
Contractor Company:
Contractor Name: Syracuse University

Date: **7/16/2013**
Permit Type:
Description: **Sprinkler work for S. U. Steamed Station**

Permit Description: **Sprinkler**
Work Class:
Proposed Use:
Permit Number: 11896
Status:
Valuation: $725.00
Contractor Company:
Contractor Name: Syracuse University

ADJOINING PROPERTY FINDINGS

Date:	**9/26/2012**
Permit Type:	
Description:	**Erect a 14' X 14' addition to the north west corner of the building type VB construction for type U occupancy as per attached plans dated 4-20-12 for water tank enclosure. Separate permits are required for Electrical & plaumbing.A FINAL REPORT MUST BE SUBMITTED INDICATING THAT ALL SPECIAL INSPECTIONS HAVE BEEN MADE, AND ALL DISCREPANCIES HAVE BEEN RESOLVED PRIOR TO ISSUANCE OF A C/C**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	08551
Status:	
Valuation:	$23,000.00
Contractor Company:	
Contractor Name:	Syracuse University

Date:	**9/21/2012**
Permit Type:	
Description:	**Electrical work for outside diesel tanks and inside storage shed.AHR Mechanical**
Permit Description:	**Electric**
Work Class:	
Proposed Use:	
Permit Number:	08467
Status:	
Valuation:	$2,720.00
Contractor Company:	
Contractor Name:	Syracuse University

ADJOINING PROPERTY FINDINGS

Date:	**8/7/2012**
Permit Type:	
Description:	**Low voltage work for Control Room at Steam PlantSU Technicians**
Permit Description:	**Electric**
Work Class:	
Proposed Use:	
Permit Number:	07865
Status:	
Valuation:	$10,879.00
Contractor Company:	
Contractor Name:	Syracuse University

Date:	**8/1/2012**
Permit Type:	
Description:	**Erect a 14' X 14' addition to the north west corner of the building, type VB construction, for type U occupancy as per attached plans dated 4/20/12 for water tank enclosure. Separate permits are required for plumbing, and electrical.A final report must be submitted stating that all special inspections have been made and all discrepencies resolved prior to the issuance of a C of C.**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	07389
Status:	
Valuation:	$23,000.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **4/6/2012**
Permit Type:
Description: **CHILLED WATER PLANT**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 05848
Status:
Valuation: $15,000.00
Contractor Company:
Contractor Name: Syracuse University

Date: **1/25/2011**
Permit Type: **COMMERCIAL**
Description: **DEMOLITION OF STEEL/MASONARY COMMERCIAL BUILDINGS PER THE ATTACHED PLAN AND REVIEW ON FILE. THE FOLLOWING TO BE**

Permit Description: **DEMOLTION**
Work Class:
Proposed Use:
Permit Number: 210
Status:
Valuation: $400,000.00
Contractor Company:
Contractor Name:

Date: **9/16/2010**
Permit Type: **COMMERCIAL**
Description: **STEAM STATION-RILEY PLANT GRD FLR**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 98741
Status:
Valuation: $11,850.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**12/9/2008**
Permit Type:	**COMMERCIAL**
Description:	**CHILLED WATER PLANT**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	90817
Status:	
Valuation:	$145,000.00
Contractor Company:	
Contractor Name:	

Date:	**12/5/2008**
Permit Type:	**COMMERCIAL**
Description:	**INSTALL 2 COOLING TOWERS #5 AND #6, RIGGING, RAILING, WALKWAYS, AND RAMPS PER THE ATTACHED PLANS DATED 8/5/08. A**
Permit Description:	**MISCELLANEOUS**
Work Class:	
Proposed Use:	
Permit Number:	90045
Status:	
Valuation:	$259,000.00
Contractor Company:	
Contractor Name:	

Date:	**10/24/2008**
Permit Type:	**COMMERCIAL**
Description:	**CHILLED WATER PLANT TOWERS 5 & 6**
Permit Description:	**HEATING**
Work Class:	
Proposed Use:	
Permit Number:	90291
Status:	
Valuation:	$240,000.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **7/31/2007**
Permit Type: **COMMERCIAL**
Description: **RILEY BUILDING**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 84101
Status:
Valuation: $1,300.00
Contractor Company:
Contractor Name:

Date: **7/31/2007**
Permit Type: **COMMERCIAL**
Description: **SU STEAM STATION**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 84102
Status:
Valuation: $1,950.00
Contractor Company:
Contractor Name:

Date: **12/12/2006**
Permit Type: **COMMERCIAL**
Description: **SU STEAM STATION**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 81065
Status:
Valuation: $835.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **12/12/2006**
Permit Type: **COMMERCIAL**
Description: **SU STEAM STATION-RILEY BUILDING**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 81066
Status:
Valuation: $1,680.00
Contractor Company:
Contractor Name:

Date: **11/28/2006**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 80970
Status:
Valuation: $24,600.00
Contractor Company:
Contractor Name:

Date: **9/27/2006**
Permit Type: **COMMERCIAL**
Description: **CHILLED WATER BUILDING**

Permit Description: **HEATING**
Work Class:
Proposed Use:
Permit Number: 80259
Status:
Valuation: $120,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**6/7/2005**
Permit Type:	**COMMERCIAL**
Description:	**SU STEAM STATION**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	72153
Status:	
Valuation:	$7,000.00
Contractor Company:	
Contractor Name:	

Date:	**5/31/2005**
Permit Type:	**COMMERCIAL**
Description:	**INITIAL ENTRY: CONSTRUCT EXTERIOR STAIRWAY PER THE ATTACHED PLAN. (PLAN REVISION #3) SU CHILLED WATER PLANT**
Permit Description:	**REMODELING**
Work Class:	
Proposed Use:	
Permit Number:	71488
Status:	
Valuation:	$124,000.00
Contractor Company:	
Contractor Name:	

Date:	**3/23/2005**
Permit Type:	**COMMERCIAL**
Description:	**CHILLED WATER PLANT**
Permit Description:	**HEATING**
Work Class:	
Proposed Use:	
Permit Number:	70983
Status:	
Valuation:	$4,640.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **3/15/2005**
Permit Type: **COMMERCIAL**
Description: **FOR CHILLED WATER PLANT**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 70905
Status:
Valuation: $58,548.00
Contractor Company:
Contractor Name:

Date: **4/30/2004**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 66882
Status:
Valuation: $9,280.00
Contractor Company:
Contractor Name:

Date: **3/16/2004**
Permit Type: **COMMERCIAL**
Description: **OTHER - VARIABLE FREQ DR.**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 66317
Status:
Valuation: $10,500.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **10/24/2002**
Permit Type: **COMMERCIAL**
Description: **STEAM STATION**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 59419
Status:
Valuation: $5,000.00
Contractor Company:
Contractor Name:

Date: **9/23/2002**
Permit Type: **COMMERCIAL**
Description: **CHILLED WATER PLANT**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 58856
Status:
Valuation: $142,500.00
Contractor Company:
Contractor Name:

Date: **9/23/2002**
Permit Type: **COMMERCIAL**
Description: **CHILLED WATER PLANT**

Permit Description: **SMOKE DETECTION SYSTEM**
Work Class:
Proposed Use:
Permit Number: 58857
Status:
Valuation: $21,500.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **9/18/2002**
Permit Type: **COMMERCIAL**
Description: **CONSTRUCT NEW CHILLER PLANT ADDITION, ONE STORY 26'X 62' WITH BASEMENT LEVEL FOR FUTURE COOLING TOWERS. ALSO CONST.**

Permit Description: **REMODELING**
Work Class:
Proposed Use:
Permit Number: 57718
Status:
Valuation: $831,000.00
Contractor Company:
Contractor Name:

Date: **9/18/2002**
Permit Type: **COMMERCIAL**
Description: **SYRACUSE UNIVERSITY CHILLED WATER PLANT.**

Permit Description: **HEATING**
Work Class:
Proposed Use:
Permit Number: 57842
Status:
Valuation: $655,000.00
Contractor Company:
Contractor Name:

Date: **9/6/2002**
Permit Type: **COMMERCIAL**
Description: **SU STEAM PLANT**

Permit Description: **HEATING**
Work Class:
Proposed Use:
Permit Number: 58604
Status:
Valuation: $47,299.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **3/29/2001**
Permit Type: **COMMERCIAL**
Description: **OTHER ITEMS: CONNECTION FOR GENERATOR SWITCHES** **225A TRANSFER**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 50326
Status:
Valuation: $15,000.00
Contractor Company:
Contractor Name:

Date: **4/28/2000**
Permit Type: **COMMERCIAL**
Description: **SU UNDERGROUND STEAM DISTRIBUTION**

Permit Description: **HEATING**
Work Class:
Proposed Use:
Permit Number: 45333
Status:
Valuation: $334,000.00
Contractor Company:
Contractor Name:

Date: **4/26/2000**
Permit Type: **COMMERCIAL**
Description: **PROJECT ORANGE CO GEN PLANT TRANSFORMER #5**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 44416
Status:
Valuation: $765.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **2/9/2000**
Permit Type: **COMMERCIAL**
Description: **CO GEN PLANT**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 43766
Status:
Valuation: $275.00
Contractor Company:
Contractor Name:

Date: **1/27/2000**
Permit Type: **COMMERCIAL**
Description: **SU CO GEN PLANT**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 43752
Status:
Valuation: $150.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

OAKWOOD AVE

116 OAKWOOD AVE

Date:	**9/4/2008**
Permit Type:	**COMMERCIAL**
Description:	**SECURITY TRANSFER FOR HUB LIQUORS**
Permit Description:	**INTRUSION ALARM SYSTEM**
Work Class:	
Proposed Use:	
Permit Number:	89518
Status:	
Valuation:	$49.00
Contractor Company:	
Contractor Name:	

Date:	**5/31/2006**
Permit Type:	**COMMERCIAL**
Description:	
Permit Description:	**INTRUSION ALARM SYSTEM**
Work Class:	
Proposed Use:	
Permit Number:	76551
Status:	
Valuation:	$275.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

140 OAKWOOD AVE

Date: **3/3/2014**
Permit Type:
Description: **Electrical**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 14281
Status:
Valuation: $500.00
Contractor Company:
Contractor Name:

Date: **2/19/2013**
Permit Type:
Description:

Permit Description: **Security Alarm**
Work Class:
Proposed Use:
Permit Number: 10220
Status:
Valuation: $186.00
Contractor Company:
Contractor Name:

Date: **8/24/2012**
Permit Type:
Description: **SMARTWATT LIGHTING PROGRAM.**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 08191
Status:
Valuation: $434.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **3/4/2008**
Permit Type: **COMMERCIAL**
Description: **RECONSTRUCT/REPAIR DOOR AND BUILDING FACADE DUE TO DAMAGE FROM AUTOMOBILE ACCIDENT PER THE ATTACHED DRAWING.**

Permit Description: **REMODELING**
Work Class:
Proposed Use:
Permit Number: 86630
Status:
Valuation: $2,000.00
Contractor Company:
Contractor Name:

Date: **7/28/2004**
Permit Type: **COMMERCIAL**
Description: **M&M MARKET**

Permit Description: **SPRINKLER**
Work Class:
Proposed Use:
Permit Number: 63708
Status:
Valuation: $1,395.00
Contractor Company:
Contractor Name:

Date: **3/7/2002**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **INTRUSION ALARM SYSTEM**
Work Class:
Proposed Use:
Permit Number: 55328
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

221 OAKWOOD AVE

Date:	**11/10/2014**
Permit Type:	
Description:	**meter set 2nd flr**
Permit Description:	**Electric (Meter Set)**
Work Class:	
Proposed Use:	
Permit Number:	17491
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

Date:	**10/2/2006**
Permit Type:	**RESIDENTIAL**
Description:	**ESO 1345265**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	80323
Status:	
Valuation:	$100.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

233 OAKWOOD AVE

Date: **12/20/2021**
Permit Type:
Description:

Permit Description: **Electrical**
Work Class:
Proposed Use:
Permit Number: SUBMISSION-2021-2249
Status: Approved
Valuation: $1,400.00
Contractor Company:
Contractor Name: Stephen Cook

Date: **11/20/2013**
Permit Type:
Description: **PERMIT TO REMOVE AND REPAIR ELECTRICAL VIOLATIONS**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 13351
Status:
Valuation: $3,500.00
Contractor Company:
Contractor Name:

Date: **7/7/2004**
Permit Type: **MIXED**
Description: **1ST FL REAR #41901-83123 / 2ND FL REAR # 32811-30008**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 67889
Status:
Valuation: $150.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **4/30/2003**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **INTRUSION ALARM SYSTEM**
Work Class:
Proposed Use:
Permit Number: 61763
Status:
Valuation: $150.00
Contractor Company:
Contractor Name:

Date: **4/29/2002**
Permit Type: **MIXED**
Description: **1ST FLR REAR - 41901-83114** **2ND FLR REAR - 05701-82115**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 56227
Status:
Valuation: $100.00
Contractor Company:
Contractor Name:

Date: **1/15/2002**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **INTRUSION ALARM SYSTEM**
Work Class:
Proposed Use:
Permit Number: 54926
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **4/19/2000**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **INTRUSION ALARM SYSTEM**
Work Class:
Proposed Use:
Permit Number: 44988
Status:
Valuation: $50.00
Contractor Company:
Contractor Name:

301 OAKWOOD AVE

Date: **5/26/2020**
Permit Type:
Description: **HVAC**

Permit Description: **HVAC/Mechanical**
Work Class:
Proposed Use:
Permit Number: 41548
Status:
Valuation: $300.00
Contractor Company:
Contractor Name: Syracuse Housing Authority

Date: **7/15/2016**
Permit Type:
Description: **Roof repairs for 212 Van Buren St, Bldg 28**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 29755
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syr Housing Authority

ADJOINING PROPERTY FINDINGS

311 OAKWOOD AVE

Date:	**1/9/2007**
Permit Type:	**COMMERCIAL**
Description:	**ESO# 1859560**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	81415
Status:	
Valuation:	$2,500.00
Contractor Company:	
Contractor Name:	

Date:	**1/4/2007**
Permit Type:	**COMMERCIAL**
Description:	**RECONSTRUCTION OF ROOF BY REPAIRING TAIL CONNECTIONS. COMPLETE NEW ROOF BY ATTACHING 2X4 PURLINS OVER EXISTING**
Permit Description:	**REMODELING**
Work Class:	
Proposed Use:	
Permit Number:	81262
Status:	
Valuation:	$12,000.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **12/10/2003**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **INTRUSION ALARM SYSTEM**
Work Class:
Proposed Use:
Permit Number: 65212
Status:
Valuation: $574.00
Contractor Company:
Contractor Name:

S MCBRIDE ST

1101 S MCBRIDE ST

Date: **1/23/2006**
Permit Type: **COMMERCIAL**
Description: **INSTALL 1 GENERAL PURPOSE HYDRAULIC PASSENGER ELEVATOR RATED AT 2500 LBS PER ATTACHED PLAN & REVIEW ON FILE.**

Permit Description: **ELEVATOR**
Work Class:
Proposed Use:
Permit Number: 74958
Status:
Valuation: $43,100.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **11/7/2005**
Permit Type: **COMMERCIAL**
Description: **WILSON REC CENTER**

Permit Description: **ELECTRICAL**
Work Class:
Proposed Use:
Permit Number: 74231
Status:
Valuation: $57,000.00
Contractor Company:
Contractor Name:

Date: **10/6/2005**
Permit Type: **COMMERCIAL**
Description: **INITIAL ENTRY: CONSTRUCT BUILDING EXPANSION PER THE PLANS AND APPROVALS. WILSON PARK COMMUNITY CENTER** **ATTACHED**

Permit Description: **REMODELING**
Work Class:
Proposed Use:
Permit Number: 73319
Status:
Valuation: $302,200.00
Contractor Company:
Contractor Name:

Date: **10/5/2005**
Permit Type: **COMMERCIAL**
Description: **WILSON REC CENTER**

Permit Description: **HEATING**
Work Class:
Proposed Use:
Permit Number: 71752
Status:
Valuation: $100,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

1202 S MCBRIDE ST

Date:	**11/15/2010**
Permit Type:	**COMMERCIAL**
Description:	**FOR ALCO BOILER HOUSE**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	99583
Status:	
Valuation:	$51,000.00
Contractor Company:	
Contractor Name:	

Date:	**7/31/2007**
Permit Type:	**COMMERCIAL**
Description:	**ALCO BUILDING**
Permit Description:	**SPRINKLER**
Work Class:	
Proposed Use:	
Permit Number:	84103
Status:	
Valuation:	$1,950.00
Contractor Company:	
Contractor Name:	

Date:	**12/12/2006**
Permit Type:	**COMMERCIAL**
Description:	**ALCO BUILDING**
Permit Description:	**SPRINKLER**
Work Class:	
Proposed Use:	
Permit Number:	81067
Status:	
Valuation:	$1,300.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

1226 S MCBRIDE ST

Date:	**10/8/2009**
Permit Type:	**COMMERCIAL**
Description:	**DEMO OF A 1 STORY MASONARY STRUCTURE AND A 1 STORY WOOD FRAME STRUCTURE PER THE ATTACHED APPROVALS.**
Permit Description:	**DEMOLTION**
Work Class:	
Proposed Use:	
Permit Number:	94293
Status:	
Valuation:	$29,750.00
Contractor Company:	
Contractor Name:	

Date:	**5/25/2001**
Permit Type:	**COMMERCIAL**
Description:	**800A 1M SERVICE ESO# 413-334**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	51499
Status:	
Valuation:	$800.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

1307 S MCBRIDE ST

Date:	**7/19/2002**
Permit Type:	**RESIDENTIAL**
Description:	**DEMO 1 FAM WOOD STRUCTURE**
Permit Description:	**DEMOLTION**
Work Class:	
Proposed Use:	
Permit Number:	57753
Status:	
Valuation:	$3,000.00
Contractor Company:	
Contractor Name:	

1406 S MCBRIDE ST

Date:	**4/23/2012**
Permit Type:	
Description:	
Permit Description:	**HVAC/Mechanical**
Work Class:	
Proposed Use:	
Permit Number:	05860
Status:	
Valuation:	$8,000.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **4/4/2012**
Permit Type:
Description: **ESR# 1183 6562**

Permit Description: **Electric**
Work Class:
Proposed Use:
Permit Number: 05803
Status:
Valuation: $8,500.00
Contractor Company:
Contractor Name: Homes of Syr Housing Devel

Date: **9/30/2005**
Permit Type: **RESIDENTIAL**
Description: **DEMO ONE FAMILY PER THE ATTACHED.**

Permit Description: **DEMOLTION**
Work Class:
Proposed Use:
Permit Number: 73606
Status:
Valuation: $5,000.00
Contractor Company:
Contractor Name:

1408 S MCBRIDE ST

Date: **7/19/2002**
Permit Type: **RESIDENTIAL**
Description: **DEMO 2 FAM WOOD FRAME STRUCTURE**

Permit Description: **DEMOLTION**
Work Class:
Proposed Use:
Permit Number: 57754
Status:
Valuation: $5,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

1412 S MCBRIDE ST

Date:	**12/12/2023**
Permit Type:	
Description:	**sheetrock and insulate**
Permit Description:	**Misc.(deck, fence,ramp)**
Work Class:	
Proposed Use:	
Permit Number:	50359
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Homes of Syr Housing Development c/o Syr Housing Authority

Date:	**4/23/2012**
Permit Type:	
Description:	
Permit Description:	**HVAC/Mechanical**
Work Class:	
Proposed Use:	
Permit Number:	05861
Status:	
Valuation:	$8,000.00
Contractor Company:	
Contractor Name:	

Date:	**4/4/2012**
Permit Type:	
Description:	**ESR# 1183 6589**
Permit Description:	**Electric**
Work Class:	
Proposed Use:	
Permit Number:	05804
Status:	
Valuation:	$8,500.00
Contractor Company:	
Contractor Name:	Homes of Syr Housing Devel

ADJOINING PROPERTY FINDINGS

S STATE ST

1105 S STATE ST

Date:	**2/15/2011**
Permit Type:	**COMMERCIAL**
Description:	**METER SET FOR ? GUARD SHACK ?**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	502
Status:	
Valuation:	$200.00
Contractor Company:	
Contractor Name:	

Date:	**5/16/2007**
Permit Type:	**COMMERCIAL**
Description:	**ESO# 250 3312**
Permit Description:	**ELECTRICAL**
Work Class:	
Proposed Use:	
Permit Number:	82967
Status:	
Valuation:	$150.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **8/6/2004**
Permit Type: **COMMERCIAL**
Description:

Permit Description: **MISCELLANEOUS**
Work Class:
Proposed Use:
Permit Number: 68407
Status:
Valuation: $800.00
Contractor Company:
Contractor Name:

Date: **5/6/2004**
Permit Type: **COMMERCIAL**
Description: **DEMO COMMERCIAL STRUCTURE PER THE ATTACHED.**

Permit Description: **DEMOLTION**
Work Class:
Proposed Use:
Permit Number: 67008
Status:
Valuation: $58,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

S TOWNSEND ST

1101 S TOWNSEND ST

Date:	**6/23/2015**
Permit Type:	
Description:	**1100-14 South McBride Street (Building #5) Roof**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	19617
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Syr Housing Authority

Date:	**6/23/2015**
Permit Type:	
Description:	**101-15 Radisson Court (Building #6) Roof**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	19618
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Syr Housing Authority

ADJOINING PROPERTY FINDINGS

Date: **6/23/2015**
Permit Type:
Description: **1100-14 Radisson Court (Building #7) Roof**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 19619
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syr Housing Authority

Date: **6/23/2015**
Permit Type:
Description: **1101-15 South Townsend Street (Building #8) Roof**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 19620
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syr Housing Authority

Date: **6/17/2015**
Permit Type:
Description: **AKA 1117-31 South Townsend Street (Building #1)-roof repair**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 19613
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syr Housing Authority

ADJOINING PROPERTY FINDINGS

Date: **6/17/2015**
Permit Type:
Description: **116-18 Radisson Court (Building #2) Roof**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 19614
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syr Housing Authority

Date: **6/17/2015**
Permit Type:
Description: **117-19 Radisson Court (Building #3) Roof**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 19615
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syr Housing Authority

Date: **6/17/2015**
Permit Type:
Description: **1116-30 South McBride Street (Building #4) Roof**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 19616
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Syr Housing Authority

ADJOINING PROPERTY FINDINGS

1109 S TOWNSEND ST

Date: **4/20/2020**
Permit Type:
Description: **Fire Alarm - Isabella Lofts*Per Kevin, not mailing a copy out due to age. JB**

Permit Description: **Fire Alarm**
Work Class:
Proposed Use:
Permit Number: 39721
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Franciscan Properties Inc

Date: **9/11/2015**
Permit Type:
Description: **Sprinkler**

Permit Description: **Sprinkler**
Work Class:
Proposed Use:
Permit Number: 20900
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Franciscan Properties Inc

Date: **7/21/2015**
Permit Type:
Description: **Landing & steps repairs**

Permit Description: **Com. Reno/Rem/Chg Occ**
Work Class:
Proposed Use:
Permit Number: 20018
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**8/1/2014**
Permit Type:	
Description:	**sprinkler**
Permit Description:	**Sprinkler**
Work Class:	
Proposed Use:	
Permit Number:	16228
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Franciscan Properties Inc

Date:	**7/6/2012**
Permit Type:	
Description:	**Interior buildout of -1- bathroom on 1st floor and repair of 3 sets of exterior stone/concrete/masonry stairs, as per the attached architectural plans dated 4-11-2012;Separate permits required for any electric, hvac, plumb, etc; Must comply with the Building Code of NYS for safeguards during construction.**
Permit Description:	**Com. Reno/Rem/Chg Occ**
Work Class:	
Proposed Use:	
Permit Number:	07216
Status:	
Valuation:	$34,850.00
Contractor Company:	
Contractor Name:	Franciscan Properties Inc

GLOSSARY

General Building Department concepts

- **ICC:** The International Code Council. The governing body for the building/development codes used by all jurisdictions who've adopted the ICC guidelines. MOST of the US has done this. Canada, Mexico, and other countries use ICC codes books and guides as well. There are a few states who have added guidelines to the ICC codes to better fit their needs. For example, California has added seismic retrofit requirements for most commercial structures.
- **Building Department (Permitting Authority, Building Codes, Inspections Department, Building and Inspections):** This is the department in a jurisdiction where an owner or contractor goes to obtain permits and inspections for building, tearing down, remodeling, adding to, re-roofing, moving or otherwise making changes to any structure, Residential or Commercial.
- **Jurisdiction:** This is the geographic area representing the properties over which a Permitting Authority has responsibility.
- **GC:** General Contractor. Usually the primary contractor hired for any Residential or Commercial construction work.
- **Sub:** Subordinate contracting companies or subcontractors. Usually a "trades" contractor working for the GC. These contractors generally have an area of expertise in which they are licensed like Plumbing, Electrical, Heating and Air systems, Gas Systems, Pools etc. (called "trades").
- **Journeymen:** Sub contractors who have their own personal licenses in one or more trades and work for different contracting companies, wherever they are needed or there is work.
- **HVAC (Mechanical, Heating & Air companies):** HVAC = Heating, Ventilation, and Air Conditioning.
- **ELEC (Electrical, TempPole, TPole, TPower, Temporary Power, Panel, AMP Change, Power Release):** Electrical permits can be pulled for many reasons. The most common reason is to increase the AMPs of power in an electrical power panel. This requires a permit in almost every jurisdiction. Other commons reason for Electrical permits is to insert a temporary power pole at a new construction site. Construction requires electricity, and in a new development, power has yet to be run to the lot. The temporary power pole is usually the very first permit pulled for new development. The power is released to the home owner when construction is complete and this sometimes takes the form of a Power Release permit or inspection.
- **"Pull" a permit:** To obtain and pay for a building permit.
- **CBO:** Chief Building Official
- **Planning Department:** The department in the development process where the building /structural plans are reviewed for their completeness and compliance with building codes
- **Zoning Department:** The department in the development process where the site plans are reviewed for their compliance with the regulations associated with the zoning district in which they are situated.
- **Zoning District:** A pre-determined geographic boundary within a jurisdiction where certain types of structures are permitted / prohibited. Examples are Residential structure, Commercial/Retail structures, Industrial/Manufacturing structures etc. Each zoning district has regulations associated with it like the sizes of the lots, the density of the structures on the lots, the number of parking spaces required for certain types of structures on the lots etc.
- **PIN (TMS, GIS ID, Parcel#):** Property Identification Number and Tax Map System number.
- **State Card (Business license):** A license card issued to a contractor to conduct business.
- **Building Inspector (Inspector):** The inspector is a building department employee that inspects building construction for compliance to codes.
- **C.O.:** Certificate of Occupancy. This is the end of the construction process and designates that the owners now have permission to occupy a structure after its building is complete. Sometimes also referred to as a Certificate of Compliance.

GLOSSARY

Permit Content Definitions

- Permit Number: The alphanumerical designation assigned to a permit for tracking within the building department system. Sometimes the permit number gives clues to its role, e.g. a "PL" prefix may designate a plumbing permit.
- Description: A field on the permit form that allows the building department to give a brief description of the work being done. More often than not, this is the most important field for EP's to find clues to the prior use (s) of the property.
- Permit Type: Generally a brief designation of the type of job being done. For example BLDG-RES, BLDG-COM, ELEC, MECH etc.

Sample Building Permit Data

Date: Nov 09, 2000
Permit Type: Bldg -
New Permit Number: 101000000405
Status: Valuation: $1,000,000.00
Contractor Company: OWNER-BUILDER
Contractor Name:

Description: New one store retail (SAV-ON) with drive-thru pharmacy. Certificate of Occupancy.

East Adams Redevelopment - Phase 8 Area
409 Burt Street
Syracuse, NY 13202

Inquiry Number: 8026569.8S
June 25, 2025

EDR Environmental Lien and AUL Search 1980

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search 1980

The EDR Environmental Lien and AUL Search 1980 report provides results from a search of available land title records for environmental cleanup liens and other activity and use limitations (AULs), such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address and/or parcel information to:

- search for parcel number and/or legal description
- search for ownership information filed between 1980 and the most current publicly available date
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.
- search for publicly available environmental encumbering instrument(s) filed between 1980 and present
- provide a copy of any environmental encumbrance(s)
- provide a copy of the current deed when available

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Property Archives, LLC researched and compiled the land title information contained in this EDR Environmental Lien and AUL Search 1980 report on behalf of EDR.

Property Archives

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC and Property Archives, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search 1980

TARGET PROPERTY INFORMATION

ADDRESS

East Adams Redevelopment - Phase 8 Area
409 Burt Street
Syracuse, NY, 13202

PROPERTY DESCRIPTION

Parcel ID: **311500 094.-09-03.0**

Current Owner: The New York Susquehanna and Western Railway Corporation

Legal Description: See attached Deed Exhibit.

Parcel ID: **311500 094.-09-04.0**

Current Owner: Syracuse Housing Authority, Inc.

Legal Description: See attached Deed Exhibit.

Parcel ID: **311500 094.-09-05.0**

Current Owner: Syracuse Housing Authority

Legal Description: See attached Deed Exhibit.

Parcel ID: **311500 094.-09-06.0**

Current Owner: Syracuse Housing Authority

Legal Description: See attached Deed Exhibit.

FINDINGS SUMMARY

The following is a summary of information contained in the report. Additional details may be found in the Findings Detail section.

Parcel: **311500 094.-09-03.0**

Environmental Lien: Found ☐ Not Found ☒

Other Activity and Use Limitations (AULs): Found ☐ Not Found ☒

HISTORICAL CHAIN of TITLE FROM 1980			
RECORDED	**INSTRUMENT**	**GRANTEE**	**GRANTOR**
March 13, 2024	2024-7609	The New York Susquehanna and Western Railway Corporation	Onondaga County Industrial Development Agency
May 07, 1993	3842/257	Onondaga County Industrial Corporation	Consolidated Rail Corporation
November 10, 1978	2678/109	Consolidated Rail Corporation	Penn Central Transportation

EDR Environmental Lien and AUL Search 1980

Parcel: **311500 094.-09-04.0**

Environmental Lien: Found ☐ Not Found ☒

Other Activity and Use Limitations (AULs): Found ☐ Not Found ☒

HISTORICAL CHAIN of TITLE FROM 1980			
RECORDED	**INSTRUMENT**	**GRANTEE**	**GRANTOR**
July 13, 2005	4893/471	Syracuse Housing Authority, Inc.	City of Syracuse
July 13, 2005	4893/464	City of Syracuse	Brian Roulin, Commissioner of Finance of the City of Syracuse
June 23, 1998	4246/225	George McKinney	Charles W. Peterson, District Director of Internal Revenue
January 11, 1991	3672/175	John A. Fegley	PPRC Realty Corp.
December 19, 1988	3498/28	PPRC Realty Corp.	Barbara A. Frent, Myrna Rubenstein and Emanuel Rubenstein
December 15, 1988	3497/180	Barbara A. Frent, Myrna Rubenstein and Emanuel Rubenstein	A. Cooper Metal Co., Inc.
July 21, 1975	2558/780	A. Cooper Metal Co., Inc.	City of Syracuse

Parcel: **311500 094.-09-05.0**

Environmental Lien: Found ☐ Not Found ☒

Other Activity and Use Limitations (AULs): Found ☐ Not Found ☒

HISTORICAL CHAIN of TITLE FROM 1980			
RECORDED	**INSTRUMENT**	**GRANTEE**	**GRANTOR**
February 11, 2003	4766/156	Syracuse Housing Authority	El-Roh Realty Corp.
December 06, 1940	952/45	El-Roh Realty Corp.	Syracuse Savings Bank

Parcel: **311500 094.-09-06.0**

Environmental Lien: Found ☐ Not Found ☒

Other Activity and Use Limitations (AULs): Found ☐ Not Found ☒

HISTORICAL CHAIN of TITLE FROM 1980			
RECORDED	**INSTRUMENT**	**GRANTEE**	**GRANTOR**
August 17, 2010	5136/58	Syracuse Housing Authority	John W. Ogletree and Ruth Ogletree
September 12, 1951	1525/639	John W. Ogletree and Ruth Ogletree	Robert Lieber

EDR Environmental Lien and AUL Search 1980

RESEARCH SOURCE(S)

The following research sources were reviewed from January 01, 1980, to June 18, 2025. Based on available information evaluated by the title search professional, the jurisdiction does not require a search of judicial records to identify environmental liens.

Source 1: Syracuse Township Assessor
Onondaga County, NY

Source 2: Onondaga County Clerk
Onondaga County, NY

FINDINGS DETAIL

Parcel: **311500 094.-09-03.0**

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

Other AULs: Found ☐ Not Found ☒

MISCELLANEOUS DOCUMENTS

None

Parcel: **311500 094.-09-04.0**

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

Other AULs: Found ☐ Not Found ☒

MISCELLANEOUS DOCUMENTS

None

EDR Environmental Lien and AUL Search 1980

Parcel: **311500 094.-09-05.0**

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

Other AULs: Found ☐ Not Found ☒

MISCELLANEOUS DOCUMENTS

None

Parcel: **311500 094.-09-06.0**

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

Other AULs: Found ☐ Not Found ☒

MISCELLANEOUS DOCUMENTS

None

HISTORICAL CHAIN OF TITLE FROM 1980

Parcel ID: 311500 094.-09-03.0

DEED TYPE:	Deed
GRANTEE:	The New York Susquehanna and Western Railway Corporation
GRANTOR:	Onondaga County Industrial Development Agency
DATE EXECUTED:	December 14, 2023
DATE RECORDED:	March 13, 2024
INSTRUMENT#:	2024-7609

See attached Deed Exhibit A.

EDR Environmental Lien and AUL Search 1980

DEED TYPE:	Deed
GRANTEE:	Onondaga County Industrial Corporation
GRANTOR:	Consolidated Rail Corporation
DATE EXECUTED:	May 07, 1993
DATE RECORDED:	May 07, 1993
BOOK / PAGE:	3842/257

DEED TYPE:	Deed
GRANTEE:	Consolidated Rail Corporation
GRANTOR:	Penn Central Transportation
DATE EXECUTED:	November 10, 1978
DATE RECORDED:	November 10, 1978
BOOK / PAGE:	2678/109

Parcel ID: 311500 094.-09-04.0

DEED TYPE:	Deed
GRANTEE:	Syracuse Housing Authority, Inc.
GRANTOR:	City of Syracuse
DATE EXECUTED:	July 12, 2005
DATE RECORDED:	July 13, 2005
BOOK / PAGE:	4893/471

See attached Deed Exhibit B.

DEED TYPE:	Tax Sale Deed
GRANTEE:	City of Syracuse
GRANTOR:	Brian Roulin, Commissioner of Finance of the City of Syracuse
DATE EXECUTED:	July 13, 2005
DATE RECORDED:	July 13, 2005
BOOK / PAGE:	4893/464

DEED TYPE:	District Directors Deed
GRANTEE:	George McKinney
GRANTOR:	Charles W. Peterson, District Director of Internal Revenue
DATE EXECUTED:	June 23, 1998
DATE RECORDED:	June 23, 1998
BOOK / PAGE:	4246/225

EDR Environmental Lien and AUL Search 1980

DEED TYPE:	Deed
GRANTEE:	John A. Fegley
GRANTOR:	PPRC Realty Corp.
DATE EXECUTED:	January 11, 1991
DATE RECORDED:	January 11, 1991
BOOK / PAGE:	3672/175

DEED TYPE:	Deed
GRANTEE:	PPRC Realty Corp.
GRANTOR:	Barbara A. Frent, Myrna Rubenstein and Emanuel Rubenstein
DATE EXECUTED:	December 19, 1988
DATE RECORDED:	December 19, 1988
BOOK / PAGE:	3498/28

DEED TYPE:	Deed
GRANTEE:	Barbara A. Frent, Myrna Rubenstein and Emanuel Rubenstein
GRANTOR:	A. Cooper Metal Co., Inc.
DATE EXECUTED:	December 15, 1988
DATE RECORDED:	December 15, 1988
BOOK / PAGE:	3497/180

DEED TYPE:	Deed
GRANTEE:	A. Cooper Metal Co., Inc.
GRANTOR:	City of Syracuse
DATE EXECUTED:	July 01, 1975
DATE RECORDED:	July 21, 1975
BOOK / PAGE:	2558/780

Parcel ID: 311500 094.-09-05.0

DEED TYPE:	Deed
GRANTEE:	Syracuse Housing Authority
GRANTOR:	El-Roh Realty Corp.
DATE EXECUTED:	October 02, 2002
DATE RECORDED:	February 11, 2003
BOOK / PAGE:	4766/156

See attached Deed Exhibit C.

EDR Environmental Lien and AUL Search 1980

DEED TYPE:	Deed
GRANTEE:	El-Roh Realty Corp.
GRANTOR:	Syracuse Savings Bank
DATE EXECUTED:	December 03, 1940
DATE RECORDED:	December 06, 1940
BOOK / PAGE:	952/45

Parcel ID: 311500 094.-09-06.0

DEED TYPE:	Deed
GRANTEE:	Syracuse Housing Authority
GRANTOR:	John W. Ogletree and Ruth Ogletree
DATE EXECUTED:	August 17, 2010
DATE RECORDED:	August 17, 2010
BOOK / PAGE:	5136/58

See attached Deed Exhibit D.

DEED TYPE:	Deed
GRANTEE:	John W. Ogletree and Ruth Ogletree
GRANTOR:	Robert Lieber
DATE EXECUTED:	September 12, 1951
DATE RECORDED:	September 12, 1951
BOOK / PAGE:	1525/639

EDR Environmental Lien and AUL Search 1980

CURRENT DEED EXHIBIT A

Emily Essi Bersani, County Clerk
401 Montgomery Street
Room 200
Syracuse, NY 13202
(315) 435-2229

Onondaga County Clerk Recording Cover Sheet

Received From :
BARCLAY DAMON LLP
125 E JEFFERSON ST
SYRACUSE, NY 13202

Return To :
BARCLAY DAMON LLP
125 E JEFFERSON ST
SYRACUSE, NY 13202

First PARTY 1
ONONDAGA COUNTY INDUSTRIAL DEVELOPMENT AGENCY

First PARTY 2
NEW YORK SUSQUEHANNA AND WESTERN RAILWAY CORPORATION

Index Type : Land Records
Instr Number : 2024-00007609
Book : **Page :**

Type of Instrument : Deed
Type of Transaction : Deed Comm Or Vacant
Recording Fee: $385.50
Recording Pages : 18

The Property affected by this instrument is situated in Syracuse, in the County of Onondaga, New York

Real Estate Transfer Tax

RETT # :	7350
Deed Amount :	$0.00
RETT Amount :	$0.00
Total Fees :	$385.50

Doc ID - 054803280018

State of New York
County of Onondaga

I hereby certify that the within and foregoing was recorded in the Clerk's office for Onondaga County, New York

On (Recorded Date) : 03/13/2024
At (Recorded Time) : 1:07:18 PM

Emily Essi Bersani, County Clerk

This sheet constitutes the Clerks endorsement required by Section 319 of Real Property Law of the State of New York

17

Quitclaim Deed

Record and Return:

Barclay Damon LLP
80 State Street
Albany, NY 12207
Attn: Oksana M. Ludd, Esq

THIS INDENTURE

This Indenture is made the 14th day of December 2023

BY AND BETWEEN **ONONDAGA COUNTY INDUSTRIAL DEVELOPMENT AGENCY**, (previously erroneously identified as Onondaga County Industrial Development Authority), a public benefit Corporation duly organized and existing under the laws of the State of New York, with an address at 335 Montgomery Street, 2nd Floor, Syracuse, New York 13202 the "Grantor", and

THE NEW YORK SUSQUEHANNA AND WESTERN RAILWAY CORPORATION, a corporation organized under the laws of the State of New Jersey, with an office located at 1 Railroad Avenue, Cooperstown, NY 13326, the "Grantee."

WITNESSETH, that the Grantor, in consideration of the sum of ONE AND MORE DOLLARS ($1.00 and more), lawful money of the United States, paid by the Grantee, the receipt whereof is hereby acknowledged, does hereby remise, release and quitclaim unto the Grantee, the heirs or successors and assigns of the Grantee forever, all right, title and interest of the Grantor of, in and to the following described Premises:

> ALL THAT CERTAIN property of Grantor, together with all of the improvements thereon, being the lines of railroad known as the Jamesville Industrial Track, Lake Industrial Track (including the Salt Land Spur) and a portion of Track No. 7 of the Chicago Line, situate in the County of Onondaga and State of New York, described in Exhibit "A" and beginning and end points generally indicated in Exhibit "B", sheets 1 through 13, to a Indenture dated April 12, 1993 and filed with the Onondaga County Clerk's Office on May 7, 1993 at Liber 3842 Page 257, hereinafter further referred to as "Premises".

BEING the Premises conveyed by Consolidated Rail Corporation to Onondaga County Industrial Corporation by Indenture dated April 12, 1993 and filed with the Onondaga County Clerk's Office on May 7, 1993 at Liber 3842 Page 257.

UNDER and SUBJECT, however, to (1) whatever rights the public may have to the use of any road alleys, bridges or streets crossing the Premises, (2) any streams, rivers, creeks and water ways passing under, across or through the Premises, and (3) any easements or agreements of record or otherwise affecting the land hereby conveyed, and to the state of facts which a personal inspection or accurate survey would disclose, and to any pipes, wires, poles, cables, culverts,

drainage courses or systems and their appurtenances now existing and remaining in, on, under, over, across and through the Premises, together with the right to maintain, repair, renew, replace, use and remove same.

Grantee by the acceptance of this Instrument, does hereby accept all existing and prospective responsibility for removal and/or restoration cost for any and all railroad bridges and grade crossings and their appurtenances that may be located on the Premises conveyed to the said Grantee; and any obligations and/or responsibility as may have been or may hereafter be imposed on Grantor by any Public Utility commission or any other governmental agency having jurisdiction for any and all bridges structures and grade crossings and their appurtenances , including but not limited to the removal, repairing or restoration of same in accordance with the requirements of said Commission or other governmental agency.

IN WITNESS WHEREOF, the Grantor has caused this instrument to be signed as of the day and year first above written.

Onondaga County Industrial
Development Agency

By: _____
Name: Robert Petrovich

STATE OF NEW YORK)
) ss.:
COUNTY OF ONONDAGA)

On this 14th day of December, in the year 2023, before me, the undersigned, personally appeared Robert M. Petrovich, personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that he/she executed the same in his/her capacity, and that by his/her signature on the instrument, the individual or the person upon behalf of which the individual acted, executed the instrument.

AMANDA M. FITZGERALD
Notary Public, State of New York
Qual. in Rensselaer Co., No. 02FI0002061
My Commission Expires February 28, 2027

_____
Notary Public

EXHIBIT "A"

LEGAL DESCRIPTION

Jamesville Industrial Track and Lake Industrial Tract
(including the Salt Land Spur), Line Code 6251

ALL THAT CERTAIN property of the Grantor, being portions of Grantor's lines of railroad known as the Jamesville Industrial Track and the Lake Industrial Tract, including the Salt Lake Spur (a.k.a. Syracuse Branch) and identified as Line Code 6251 in the Recorder's Office of Onondaga County, New York in Deed Book 2678 at page 91, situate in the County of Onondaga and State of New York; being further described as follows:

BEGINNING at approximately Mile Post 264.3, being at a property line with The New York, Susquehanna and Western Railway Company on the south and Consolidated Rail Corporation on the north, in Jamesville in the Town of Dewitt, as indicated on sheet 1 of 13 in attached Exhibit "B" ; thence extending in a general northwesterly direction passing through the Town of Onondaga to approximately Mile Post 273.55, being at the connection to Track 7 of Consolidated Rail Corporation's Chicago Line, hereinafter described, in the City of Syracuse, the place of Ending, as indicated on sheet 12 of 13
in the attached Exhibit "B".

BEING a part or portion of the same premises which Thomas F. Patton and Ralph S. Tyler, Jr., as Trustees of the Property of Erie Lackawanna Railroad Company, Debtor, by Conveyance Document No. EL-CRC-RP-27, dated March 31, 1976 and recorded on November 10, 1978, in the Recorder's Office of Onondaga County, New York, in Record Book 2678 at page 91&c., granted and conveyed unto Consolidated Rail Corporation.

Track No. 7 of the Chicago Line, Line Code 4700

ALL THAT CERTAIN strip of land of the Grantor, being and easterly portion of Grantor's line of railroad known as the Chicago Line (a.k.a. the Penn Central Albany-Rensselaer to Bay View Main Line) and identified as Line Code 4700 in the Recorder's Office of Onondaga County, New York in Book 2070 at page 116, situated in the City of Syracuse, County of Onondaga and State of New York; being further described as follows:

BEGINNING at approximately Mile Post 292.72, being at the connection to the aforedescribed Salt Land Spur, as indicated on sheet 12 of 13 in the attached Exhibit "B"; thence extending in a general northeasterly direction to Railroad Station 34+194 at Mile Post 291.89, the place of ENDING, as indicated on sheet 13 of 13 in the attached Exhibit "B".

BEING a part or portion of the same premises which Richard W. Blanchette, Richard C. Bond and John H. McArthur, as Trustees of the Property of Penn Central Transportation Company, Debtor, by Conveyance Document No. PC-CRC-PR-124, dated March 30, 1976 and recorded on

November 10, 1978, in the Recorder's Office of Onondaga County, New York, in Record Book 2678 at page 109&c., granted and conveyed unto Consolidated Rail Corporation.

Isolated Portion of the Chicago Line, Line Code 4700

ALL THAT CERTAIN strip of land of the Grantor, being a portion of Grantor's line of railroad adjacent to the line of railroad known as the Chicago Line (a.k.a. the Penn Central Albany-Rensselaer to Bay View Main Line) and identified as Line Code 4700 in the Recorder's Office of Onondaga County, New York in Book 2070 at page 116, situated in the City of Syracuse, County of Onondaga and State of New York; being further described as follows:

BEGINNING at a point adjacent to the aforedescribed Jamesville Industrial Tract and Lake Industrial Track at approximately Mile Post 271.5 of Line Code 6251, as indicated on Sheet 9 of 13 in the attached Exhibit "B"; thence continuing adjacent to said Jamesville/Lake Industrial Track in a general westerly-northwesterly direction to a point adjacent to said Jamesville/Lake Industrial Track at approximately Mile Post 273.3, the place of ENDING, as indicated on Sheet 11 of 13 in the attached Exhibit "B".

TOGETHER with the Tracy Street Lead, being a line of railroad which extends in a general northerly, then easterly direction from its connection, in the vicinity of Geddes Street, to the above described railroad.

BEING a part or portion of the same premises which Richard W. Blanchette, Richard C. Bond and John H. McArthur, as Trustees of the Property of Penn Central Transportation Company, Debtor, by Conveyance Document No. PC-CRC-PR-124, dated March 30, 1976 and recorded on November 10, 1978, in the Recorder's Office of Onondaga County, New York, in Record Book 2678 at page 109&c., granted and conveyed unto Consolidated Rail Corporation.

EXHIBIT B

MAP ADDENDUM


DEED BOOK 3842 PAGE 264
PROPERTY TO BE CONVEYED
BY
CONSOLIDATED RAIL CORPORATION
TO
ONONDAGA COUNTY
INDUSTRIAL DEVELOPMENT AUTHORITY
CASE NO. 70320
SHEET 1 OF 12
BEGIN L.C. 6251
M.P. 264.31
Ray 4/11/92
6/5/92


LIBER 3842 PAGE 265
CASE NO. 70320
SHEET 2 of 3


DEED BOOK 3842 PAGE 266
CASE NO. 70320
SHEET 3 OF 13


3842 267
CASE NO. 70320
SHEET 4 OF 13


3842 268
CASE NO. 7952D
SHEET 5 of 13


3842 PAGE 269
CASE NO. 70390
SHEET 6 OF 12


CASE NO. 70320


LIBER 3842 PAGE 272
CASE NO. 70320
SHEET 4 OF 19
NEW YORK CENTRAL RAILROAD


REC'D
PAGE 3842 273
CASE NO. 70920
SHEET 10 OF 15


842 274
END L.C.1760-
AT M.P. 273.32
OF L.C. 6251
L.C. 6251
CASE NO. 70320
SHEET 11 OF 13


DEED BOOK 3842 PAGE 275
NOTE:
GRANTEE TO RELOCATE
TRACK NO.7 ONTO
GRANTEE'S PROPERTY
CASE NO. 70920


PAGE 276
NOTE: DETAILS NOT TO SCALE
DETAIL
STA. 36+065
STA. 35+829
STA. 35+294
STA. 35+179
14°
END L.C. 4700
M.P. 291.89
STA. 34+194
CASE NO. 70920
SHEET 8 OF 13

EDR Environmental Lien and AUL Search 1980

CURRENT DEED EXHIBIT B

ONONDAGA COUNTY CLERK'S OFFICE BOOK 4893 PAGE 471
M. ANN CIARPELLI - COUNTY CLERK
401 Montgomery St - Room 200 Phone: 315-435-2226
Syracuse NY 13202 Fax: 315-435-3455

Submitted by: SALT CITY
Document type: DEED
Grantor: CITY OF SYRACUSE
Grantee: SYRACUSE HOUSING AUTHORITY
Legal desc: SYR L98&99 B258 S E
Prop addr: 1226 S MCBRIDE ST

Receipt: 445642 SR
Instrument: 0850005
Book/Page: 04893/0471
Date filed: 07/13/2005 at 12:28PM
Updated: 07/15/2005 MS
Record and return to:
SYRACUSE HOUSING AUTHORITY
516 BURT ST
SYRACUSE NY 13202

RECORDING FEES

Addl pages:	2 x 3.00	$	6.00
Addl names:	x	$	
Addl refs:	x	$	
Misc:		$	
Basic:		$	8.50
Total:		$	14.50

MISCELLANEOUS FEES

RMI:	$	20.00
TP 584:	$	5.00
RP5217:	$	165.00
Affts:	$	
Total:	$	190.00

MORTGAGE TAX

Mortgage:	$	
Basic:	$	
Insurance fund:	$	
Net add:	$	
Misc:	$	
Total:	$	

DEED TRANSFER TAX

Consideration:	$	10,500.00
Transfer tax:	$	42.00

SWIS: 3115
Map #: 094-09-04.0

TOTAL PAID: $246.50
Control no: 15863

WARNING - This sheet constitutes the Clerk's endorsement, required by Section 319 of the Real Property Law of the State of New York. Do not detach.
Taxes imposed on this instrument at time of recording were paid.
Certain information contained in this document is not verified by this office.

M. ANN CIARPELLI
Onondaga County Clerk

D 0 4 8 9 3 0 4 7 1

THIS INDENTURE, made this 12th day of July, 2005 by and between the City of Syracuse, a municipal corporation, in the County of Onondaga, State of New York, herein sometimes referred to as "City" party of the first part; and SYRACUSE HOUSING AUTHORITY, INC., 516 Burt Street, Syracuse, New York, party of the second part;

13202

WHEREAS, the City of Syracuse has heretofore acquired the hereinafter described premises by tax sale proceedings and is owner thereof; and

WHEREAS, the said premises hereinafter described are not required for municipal purposes and the sale of the City's right, title, and interest in and to the said premises to Syracuse Housing Authority, Inc. has been authorized and directed for the sum of TEN THOUSAND FOUR HUNDRED DOLLARS ($10,400.00) by an ordinance of the Common Council unanimously adopted on April 11, 2005; and approved by the Mayor on April 14, 2005, which ordinance is still in full force and effect; and

NOW THEREFORE, THIS INDENTURE WITNESSETH: That the City of Syracuse, party of the first part, for and in consideration of the sum of TEN THOUSAND FOUR HUNDRED DOLLARS ($10,400.00) lawful money of the United States, paid by the party of the second part, receipt whereof is hereby acknowledged, does hereby remise, release, and quit claim unto the party of the second part and their heirs and assigns forever

ALL OF THE RIGHT, TITLE AND INTEREST OF THE CITY OF SYRACUSE IN AND TO:

ALL THAT TRACT OR PARCEL OF LAND, located in the City of Syracuse, County of Onondaga, and State of New York being more particularly described as being in Lot P 98 & 99, Block 258, designated as Section 094, Block -09 Lot –04 Sublot .0 (094.-09.-04.0), Property #1858000105, 103' x 173.80' Ang. Brick Building.

Subject to easements, covenants, and restrictions of record

This property is commonly known as 1226 S. McBride Street.

TO HAVE AND TO HOLD the above granted and described premises unto said party of the second part Syracuse Housing Authority, Inc.

Together, with all of the appurtenances and all the estate and rights, of the party of the first part in and to said premises.

APPROVED AS TO FORM AND LEGALITY

12:28 07/13/05 0850005 SR DB-04893P-471

IN WITNESS WHEREOF, the City of Syracuse, party of the first part, has caused its corporate seal to be hereunto affixed by its City Clerk this Indenture to be subscribed by its Mayor on the date and year first above written.

ATTEST:

John P. Copanas,
City Clerk

CITY OF SYRACUSE

Matthew J. Driscoll
Mayor

State of New York)
County of Onondaga) ss.:

On this 23rd day of June, 2005, before me, the undersigned, personally appeared Mayor Matthew J. Driscoll, personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that he executed the same in his capacity, and that by his signature on the instrument, the individual, or the person upon behalf of which the individual acted, executed the instrument.

Dian Sherwood
Notary Public

DIAN FIFIELD Sherwood
Notary Public in the State of New York
Qualified in Onondaga County, No 5072669
My Commission Expires February 3, 2007

State of New York)
) ss:
County of Onondaga)

On the 23rd day of June, in the year 2005, before me, the undersigned, a Notary Public in and for said State, personally appeared John P. Copanas, the subscribing witness to the foregoing instrument, with whom I am personally acquainted, who, being by me duly sworn, did depose and say that he resides in Syracuse, New York: that he knows Matthew J. Driscoll to be individual described in and who executed the foregoing instrument: that said subscribing witness was present and saw said Matthew J. Driscoll execute the same; and that said witness at the same subscribing his name as a witness thereto.

Dian Sherwood
Notary Public

DIAN FIFIELD Sherwood
Notary Public in the State of New York
Qualified in Onondaga County, No. 5072669
My Commission Expires February 3, 2007

EDR Environmental Lien and AUL Search 1980

CURRENT DEED EXHIBIT C

ONONDAGA COUNTY CLERK'S OFFICE
M. ANN CIARPELLI - COUNTY CLERK
401 Montgomery St - Room 200
Syracuse NY 13202

Phone: 315-435-2226
Fax: 315-435-3455

BOOK 4766 PAGE 156

Submitted by: SALINA
Document type: DEED
Grantor: EL ROH REALTY CORP
Grantee: SYRACUSE HOUSING AUTHORITY
Legal desc: SYR L97 B258 S E
Prop addr:

Receipt: 217173 MF
Instrument: 0157403
Book/Page: 04766/0156
Date filed: 02/11/2003 at 01:55PM
Updated: 02/18/2003 MS
Record and return to:
TED LIMPERT
500 S SALINA ST STE 1040
SYRACUSE NY 13202

RECORDING FEES

Addl pages:	3 x 3.00	$	9.00
Addl names:	x	$	
Addl refs:	x	$	
Misc:		$	
Basic:		$	8.50
Total:		$	17.50

MISCELLANEOUS FEES

RMI:	$	20.00
TP 584:	$	5.00
RP5217:	$	25.00
Affts:	$	
Total:	$	50.00

MORTGAGE TAX

Mortgage:	$	
Basic:	$	
Insurance fund:	$	
Net add:	$	
Misc:	$	
Total:	$	

DEED TRANSFER TAX

Consideration:	$	25,000.00
Transfer tax:	$	100.00

SWIS: 3115
Map #: 094.-09-05.0

TOTAL PAID: $167.50
Control no: 8928

WARNING - This sheet constitutes the Clerk's endorsement, required by Section 319 of the Real Property Law of the State of New York. Do not detach.
Taxes imposed on this instrument at time of recording were paid.
Certain information contained in this document is not verified by this office.

M. ANN CIARPELLI
Onondaga County Clerk

D 0 4 7 6 6 0 1 5 6

Quitclaim Deed with Lien Covenant

THIS IS A LEGAL INSTRUMENT AND SHOULD BE EXECUTED UNDER SUPERVISION OF AN ATTORNEY.

THIS INDENTURE, made this 2 day of ~~September~~ October, 2002.

BETWEEN

EL-ROH REALTY CORP., a New York corporation with a principal place of business located at 800 West Hiawatha Boulevard, Syracuse, New York 13201

grantor

SYRACUSE HOUSING AUTHORITY
516 Burt Street
Syracuse, New York 13202

grantee

WITNESSETH, that the grantor, in consideration of One and No/100 ($1.00) Dollars, paid by the grantee, hereby grants and releases unto the grantee, the heirs or successors and assigns of the grantee forever,

ALL THAT TRACT OR PARCEL OF LAND, situate in the City of Syracuse, County of Onondaga and State of New York, and known and distinguished on a map of said city made by Trowbridge, as being part of Block Number Two Hundred Fifty-Eight (258) in said City and bounded and described as follows, viz:

BEGINNING on the easterly line of Grape Street at a point three (3) rods northerly from the north line of Burt Street and running thence easterly parallel with Burt Street seven (7) rods; thence northerly parallel with Grape Street three (3) rods; thence westerly parallel with Burt Street seven (7) rods to Grape Street; thence southerly along the easterly line of Grape Street three (3) rods to the place of beginning.

TOGETHER WITH ALL the right, title and interest, if any, now or hereafter owned by the party of the first part in and to strips and gores of land adjacent to or adjoining said premises and in and to any land lying in the bed of any street, road, avenue, lane, or right of way as they now exist or formerly existed, or may hereafter exist, included in, in front of, or adjoining the above described premises; together with the easement rights and appurtenances and all the estate and rights of the party of the first part in and to said premises.

SUBJECT to easements, covenants and restrictions of record.

BEING the same premises conveyed to Grantor herein by Covenant against Grantor Deed from Syracuse Savings Bank dated December 3, 1940 and recorded in the Onondaga County Clerk's Office on December 6, 1940 in Book 952 of Deeds at Page 45.

ALSO ALL THAT TRACT OR PARCEL OF LAND, situate in the City of Syracuse, Onondaga County, New York, and known and distinguished on a map of said City made by Trowbridge, as being part of Block No. 258 in said City, and bounded and described as follows, viz:

COMMENCING at a point on the easterly line of Grape Street (now Oakwood Avenue) six (6) rods northerly from the north line of Burt Street; running thence easterly parallel with Burt Street seven (7) rods; thence northerly parallel with Grape Street (now Oakwood Avenue) three (3) rods; thence westerly parallel with Burt Street seven (7) rods to Grape Street (now Oakwood Avenue); thence southerly along the east line of Grape Street (now Oakwood Avenue) three (3) rods to the place of beginning.

SUBJECT to easements, covenants and restrictions of record.

BEING the same premises conveyed to Grantor herein by Warranty Deed from Syracuse Savings Bank dated August 20, 1937 and recorded in the Onondaga County Clerk's Office on August 23, 1937 in Book 843 of Deeds at Page 263.

ALSO ALL THAT TRACT OR PARCEL OF LAND, situate in the City of Syracuse, County of Onondaga and State of New York, being part of Block Number Two Hundred and Fifty-Eight (258) and bounded as follows:

BEGINNING at a point on the east line of Grape Street, nine (9) rods northerly from the north line of Burt Street and running thence easterly on a line parallel with Burt Street, ten (10) rods; thence northerly on a line parallel with Grape Street, three (3) rods; thence

13:55 02/11/03 0157403 MF DB-04766 -156

Street, ten (10) rods; thence northerly on a line parallel with Grape Street, three (3) rods; thence westerly on a line parallel with Burt Street ten (10) rods; thence southerly along the east line of Grape Street three (3) rods to the place of beginning.

ALSO ALL THAT TRACT OR PARCEL OF LAND, situate in the City of Syracuse, County of Onondaga and State of New York, and known and distinguished as being part of Block 258 in said City and bounded and described as follows, viz:

BEGINNING at a point on the northerly line of Burt Street seven (7) rods easterly from the east line of Grape Street; running thence northerly on a line parallel with Grape Street nine (9) rods; thence easterly parallel with Burt Street (3) rods; thence southerly parallel with Grape Street nine (9) rods to Burt Street; thence westerly along the northerly line of Burt Street three (3) rods to the place of beginning.

ALSO ALL THAT TRACT OR PARCEL OF LAND, situate in the City of Syracuse, County of Onondaga and State of New York, known as distinguished as Lot Number ninety-seven (97) in Block Number Two Hundred and Fifty-Eight (258), bounded and described as follows:

BEGINNING at the southeast corner of said Lot Ninety-Seven (97) on the north line of Burt Street; thence north twelve (12) rods; thence west four (4) rods; thence south twelve (12) rods; thence east four (4) rods to the place of beginning.

SUBJECT to easements, covenants and restrictions of record.

BEING the same premises conveyed to Grantor herein by Warranty Deed from Philip Roth and Leona Roth dated May 5, 1933 and recorded in the Onondaga County Clerk's Office on September 13, 1933 in Book 731 of Deeds at Page 279.

ALSO ALL THAT TRACT, PIECE OR PARCEL OF LAND, situate in the City of Syracuse, County of Onondaga and State of New York, known and distinguished as being part of Block Number 258, according to Trowbridge's map of the City of Syracuse, bounded and described as follows:

BEGINNING at a point on the easterly line of South Townsend Street (formerly Grape Street), at the intersection thereof with the northerly line of Burt Street; running thence easterly along the northerly line of Burt Street, seventy-seven (77) feet; thence northerly parallel with the east line of South Townsend Street, forty-nine and one-half (49 ½) feet; thence running westerly parallel to Burt Street seventy-seven (77) feet to the east line of South Townsend Street; thence southerly along the easterly line of South Townsend Street; forty-nine and one-half (49 ½) feet to the place of beginning.

SUBJECT to easements, covenants and restrictions of record.

BEING the same premises conveyed to Grantor herein by Quitclaim Deed from Mary V. Morrissey, John Lanctot, a/k/a John Lancto, Mary M. Morrissey, Alice M. McIntyre f/k/a Alice May Morrissey and Mary Lanctot DeLima dated August 27, 1946 and recorded in the Onondaga County Clerk's Office on October 24, 1946 in Book 1240 of Deeds at Page 364.

EXCEPTING AND RESERVING ALL THAT TRACT OR PARCEL OF LAND, herein designated as Parcel Number 130, situate in the City of Syracuse, County of Onondaga and State of New York, for relocation of railroad, elimination of grade crossings of the Delaware, Lackawanna and Western Railroad Company, Public Service Commission Case No. 9329, as shown on the accompanying map an described as follows:

PARCEL No. 130

BEGINNING at a point in the division line between property belonging to the Syracuse and Binghamton Railroad Company (Delaware, Lackawanna & Western Railroad Company) (reputed owner) on the north and east and El-Roh Realty Corporation (reputed owner) on the south and west; said point beginning being at an angle point in said division

Hundred Thirty-One (231) feet, measured along a line parallel with Burt Street, from the easterly line of Oakwood Avenue; thence running southerly along aforesaid division line twenty and ninety-two hundredths (20.92) feet to a point; thence running in a northwesterly direction fifty-five and eight hundredths (55.08) feet, more or less, to a point in the first mentioned division line distant westerly fifty and fifty-seven hundredths (50.57) feet, measured along said division line, from the point of beginning; thence running easterly along said division line fity and fifty-seven hundredths (50.57) feet to the place of beginning; containing five hundred twenty-nine (529) square feet of land, more or less.

TOGETHER with the appurtenances thereto and all right, title and interest of, in or to the land in City streets in front of or adjacent to the above described premises.

All as shown on a certain map made by and filed in the office of Syracuse Grade Crossing Commission and entitled "Public Service Case No. 9329, Elimination of Grade Crossings of Delaware, Lackawanna and Western Railroad Company, in Syracuse, New York, El-Roh Realty Corp., (reputed owner), Map No. 130, Parcel No. 130 Total, 529 square feet, more or less, " and a blue print copy of said map will be filed in the Onondaga County Clerk's Office at the time of recording this deed.

Grantee is aware of the history and prior use of the property and the property conveyed herein is transferred to grantee in its current condition, AS IS in all respects.

***TOGETHER** with the appurtenances and all the estate and rights of the grantor in and to said premises.*
***TO HAVE AND TO HOLD** the premises herein granted unto the grantee, the heirs or successors and assigns of the grantee forever. **AND** the grantor covenants as follows:*
***FIRST** - The grantee shall quietly enjoy the said premises;*
This deed is subject to the trust provisions of Section 13 of the Lien Law. The words "grantor" and "grantee" shall be construed to read in the plural whenever the sense of this deed so requires.
***IN WITNESS WHEREOF**, the grantor has executed this deed the day and year first above written.*

EL-ROH REALTY CORP.

By: Seymour Roth V.P.

STATE OF NEW YORK, COUNTY OF ONONDAGA)ss.:

On the 2nd day of ~~September~~ OcT in the year 2002 before me, the undersigned, a Notary Public in and for said State, personally appeared Seymour Roth, personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that he executed the same in his capacity, and that by his signature on the instrument, the individual, or the person upon behalf of which the individual acted, executed the instrument.

Sidney Manes
Notary Public

SLB:230565.2

SIDNEY L. MANES
Notary Public in the State of New York
Qualified in Onondaga County No. 2504200
My Commission Expires 4/30/03

EDR Environmental Lien and AUL Search 1980

CURRENT DEED EXHIBIT D

ONONDAGA COUNTY CLERK'S OFFICE
M. ANN CIARPELLI - COUNTY CLERK
401 Montgomery St - Room 200
Syracuse, NY 13202
Phone: 315-435-2226
Fax: 315-435-3455

Doc Type: DEED
Grantor: OGLETREE RUTH
OGLETREE JOHN W
Grantee: SYRACUSE HOUSING AUTHORITY

Legal Desc: SYR B258 S E

Prop Address: 407 BURT STREET

Receipt: 866647 BH
Book/Page: 05136/0058 Inst: 27332
Date Filed: 08/17/2010 at 3:41PM
Updated: 08/18/2010 MS
Record and Return To:

THERESA MARZULLO
SYRACUSE HOUSING AUTHORITY
516 BURT STREET
SYRACUSE NY 13202

Submitted by: ROSE SALINA

Recording Fees			Miscellaneous Fees	
Addl pages:	1 x 5.00 =	$ 5.00	RMI:	$ 20.00
Addl Names:	0 x 0.50 =	$ 0.00	TP 584:	$ 5.00
Addl Refs:	0 x 0.50 =	$ 0.00	RP5217:	$ 125.00
Misc:		0.00	AFFTS:	$ 0.00
Basic		$25.50		
		==========		==========
TOTAL:		$30.50	TOTAL:	$ 150.00

MORTGAGE TAX		DEED TRANSFER TAX	
Mortgage:		Consideration	$24000.00
Basic:	$0.00	Transfer Tax:	$0.00
Ins Fund:	$0.00	SWIS:	3115
Net Add:	$0.00	Map #:	094-09-06.0
Misc:	$0.00		==========
	==========	Total Paid	$ 180.50
TOTAL	$0.00	Control no	524

WARNING - This sheet constitutes the Clerk's endorsement, required by Section 319 of the Real Property Law of the State of New York. Do not detach. Taxes imposed on this instrument at time of recording were paid. Certain information contained in this document is not verified by this office.

M. ANN CIARPELLI
Onondaga County Clerk

Book/Page 05136 / 0058 Instrument no.: 27332

D051360058

P 1688 Warranty Deed Full Covenants. Corp. or Ind.
Stat Form AA with Lien Covenant. 1 Side Recording 11 98
BlumbergExcelsior, Inc.
PUBLISHER NYC 10013

THIS IS A LEGAL INSTRUMENT AND SHOULD BE EXECUTED UNDER SUPERVISION OF AN ATTORNEY.

THIS INDENTURE, made the 17th day of August 2010

BETWEEN JOHN W. OGLETREE AND
RUTH OGLETREE his wife of
407 Burt St., Syracuse, NY 13202

grantor

and

SYRACUSE HOUSING AUTHORITY of
516 Burt St., Syracuse, NY 13202

grantee

WITNESSETH, that the grantor, in consideration of ($1.00)

Dollars, paid by the grantee hereby grants and releases unto the grantee, the heirs or successor and assigns of the grantee forever,

ALL THAT TRACT OR PARCEL OF LAND bound and described as follows:

situate in the City of Syracuse, County of Onondaga and State of New York known and distinguished as being part of Block 258, according to Trowbridge's map of said City of Syracuse, bounded and described as follows: Beginning at a point in the northly line of Burt Street 77 feet easterly from the east line of Oakwood Avenue(formerly Grape Street); thence running easterly along the northerly line of Burt Street 38 1/2 feet to a point; thence running northerly parallel to Oakwood Avenue 49 1/2 feet to a point; thence running westerly parallel to Burt Street 38 1/2 feet to a point; thence running southerly parallel to the easterly line of Oakwood Avenue 49 1/2 feet to the point or place of beginning.

That this same property was conveyed to the grantor herein by a warranty deed from Robert Lieber recorded in the Onondaga County Clerk's Office on September 12, 1951 in Book ~~4525~~ 1525 at Page ~~659~~. 639&C

R&R: Theresa Marzullo/Syracuse Housing Authority 516 Burt Street, Syracuse, NY 13202

TOGETHER with the appurtenances and all the estate and rights of the grantor in and to said premises.
TO HAVE AND TO HOLD the premises here granted unto the grantee, the heirs or successors and assigns forever.
AND the said grantor covenants as follows:
FIRST.—That the grantor is seized of the said premises in fee simple, and has good right to convey the same;
SECOND.—That the grantee shall quietly enjoy the said premises;
THIRD.—That the said premises are free from incumbrances;
FOURTH.—That the grantor will execute or procure any further necessary assurance of the title to said premises;
FIFTH.—That the grantor will forever warrant the title to said premises;
This deed is subject to the trust provisions of Section 13 of the Lien Law.
The words "grantor" and "grantee" shall be construed to read in the plural whenever the sense of this deed so requires.
IN WITNESS WHEREOF, the grantor has executed this deed the day and year first above written.

In presence of:

x John W. Ogletree L. S.
x Ruth Ogletree L. S.

ACKNOWLEDGMENT IN NEW YORK STATE (RPL 309-a)

State of New York
County of } ss.:

On before me, the undersigned,
personally appeared

personally known to me or proved to me on the basis of satisfactory evidence to be the individual(s) whose name(s) is (are) subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their capacity(ies), and that by his/her/their signature(s) on the instrument, the individual(s), or the person upon behalf of which the individual(s) acted, executed the instrument.

LESLIE H COHEN
NOTARY PUBLIC STATE OF NEW YORK
ONONDAGA COUNTY
LIC #02CO6102346
Comm. Exp. 12/3/2011

(signature and office of individual taking acknowledgment)

ACKNOWLEDGMENT OUTSIDE NEW YORK STATE (RPL 309-b)

State of New York
County of Onondaga } ss.:

On August 17, 2010 before me, the undersigned,
personally appeared John W. Ogletree and Ruth Ogletree

personally known to me or proved to me on the basis of satisfactory evidence to be the individual(s) whose name(s) is(are) subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their capacity(ies), and that by his/her/their signature(s) on the instrument, the individual(s), or the person upon behalf of which the individual(s) acted, executed the instrument, and that such individual made such appearance before the undersigned in

(insert city or political subdivision and state or county or other place acknowledgment taken)

(signature and office of individual taking acknowledgment)

Onondaga County
GIS On The Web

PARCEL VIEWER
Powered by SAM IS
v2.6.16

Home | Search | Tools | Results | Help

ONONDAGA COUNTY DEPARTMENT OF PLANNING

Welcome to the Onondaga County GIS On The Web application. With this viewer you can:

- Search for parcels by owner name, address, etc.
- Search for features by geometry
- Measure distances and areas
- Find addresses
- Export a map to PDF for printing
- and much more...

Note that some GIS layers will not turn on until you are zoomed in to a certain level. If a layer is turned on but not visible, try zooming in or out.

Links

Contact Information

Metadata

Disclaimer

© 2025 VHB | All rights reserved. | Designed by VHB.



Onondaga County
GIS On The Web

Parcel Viewer
Powered by SAM IS
v2.6.16

Home | Search | Tools | Results | Help

ONONDAGA COUNTY DEPARTMENT OF PLANNING

Welcome to the Onondaga County GIS On The Web application. With this viewer you can:

- Search for parcels by owner name, address, etc.
- Search for features by geometry
- Measure distances and areas
- Find addresses
- Export a map to PDF for printing
- and much more...

Note that some GIS layers will not turn on until you are zoomed in to a certain level. If a layer is turned on but not visible, try zooming in or out.

Links

Contact Information

Metadata

Disclaimer

© 2025 VHB | All rights reserved. | Designed by VHB.



Onondaga County
GIS On The Web

PARCEL VIEWER
Powered by SAM IS
v2.6.16

Home | Search | Tools | Results | Help

ONONDAGA COUNTY
DEPARTMENT OF PLANNING

Welcome to the Onondaga County GIS On The Web application. With this viewer you can:

- Search for parcels by owner name, address, etc.
- Search for features by geometry
- Measure distances and areas
- Find addresses
- Export a map to PDF for printing
- and much more...

Note that some GIS layers will not turn on until you are zoomed in to a certain level. If a layer is turned on but not visible, try zooming in or out.

Links

Contact Information

Metadata

Disclaimer

© 2025 VHB | All rights reserved. | Designed by VHB.



Onondaga County
GIS On The Web

PARCEL VIEWER
Powered by SAM IS
v2.6.16

Home | Search | Tools | Results | Help

ONONDAGA COUNTY DEPARTMENT OF PLANNING

Welcome to the Onondaga County GIS On The Web application. With this viewer you can:

- Search for parcels by owner name, address, etc.
- Search for features by geometry
- Measure distances and areas
- Find addresses
- Export a map to PDF for printing
- and much more...

Note that some GIS layers will not turn on until you are zoomed in to a certain level. If a layer is turned on but not visible, try zooming in or out.

Links

Contact Information

Metadata

Disclaimer

© 2025 VHB | All rights reserved. | Designed by VHB.



Appendix F Environmental Database Report

East Adams Redevelopment - Phase 8 Area
409 Burt Street
Syracuse, NY 13202

Inquiry Number: 8026569.2s
June 23, 2025

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	860
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-10
Physical Setting Source Map Findings	A-12
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

409 BURT STREET
SYRACUSE, NY 13202

COORDINATES

Latitude (North):	43.0387140 - 43° 2' 19.37''
Longitude (West):	76.1450260 - 76° 8' 42.09''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	406726.4
UTM Y (Meters):	4765535.0
Elevation:	404 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115660 SYRACUSE WEST, NY
Version Date:	2019
East Map:	14115658 SYRACUSE EAST, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20221014, 20221103
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
409 BURT STREET
SYRACUSE, NY 13202

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	SYRACUSE HOUSING AUT	409 BURT ST	RCRA-LQG, FINDS, ECHO, NY MANIFEST		TP
A2	MCKINNEY PROPERTY	1226 SOUTH MCBRIDE S	NY ENG CONTROLS, NY INST CONTROL, NY ERP, NY...	Higher	1 ft.
A3	ERP SITE	1226 MCBRIDE ST	NY Spills	Higher	1 ft.
B4	SYRACUSE HOUSING AUT	BURT & MCBRIDE ST	PA MANIFEST	Higher	43, 0.008, ESE
B5	MC BRIDE SUB	S MCBRIDE	RCRA NonGen / NLR, NY MANIFEST	Higher	44, 0.008, East
C6	STEAM PLANT	MCBRIDE ST	NY LTANKS	Higher	183, 0.035, NE
C7	SYRACUSE UNIVERSITY	500 E. TAYLOR STREET	NY CBS AST	Higher	210, 0.040, NE
C8	STEAM STATION	500 EAST TAYLOR ST	NY Spills	Higher	210, 0.040, NE
C9	SU CHILLED WATER PLA	500 E. TAYLOR STREET	NY AST, NY CBS AST	Higher	210, 0.040, NE
C10	SYRACUSE UNIV STEAM	500 EAST TAYLOR ST	NY Spills	Higher	210, 0.040, NE
C11	SYRACUSE UNIVERSITY	500 EAST TAYLOR ST	NY UST, NY AST	Higher	210, 0.040, NE
C12	SYRACUSE UNIVERSITY	500 E TAYLOR ST	NY LTANKS, NY Spills, NY AIRS	Higher	210, 0.040, NE
C13	SU CHILLED WATER PLA	500 E. TAYLOR STREET	NY CBS, NY AST, NY Spills, NY MANIFEST	Higher	210, 0.040, NE
C14	SYRACUSE UNIVERSITY	500 E TAYLOR ST	RCRA NonGen / NLR, E MANIFEST, NJ MANIFEST	Higher	210, 0.040, NE
C15	SYRACUSE UNIVERSITY	500 EAST TAYLOR ST	UST FINDER	Higher	210, 0.040, NE
C16	TAYLOR & MCBRIDE ST.	TAYLOR AND MCBRIDE S	NY Spills	Higher	222, 0.042, NE
C17	E. TAYLOR AND MCBRID	EAST TAYLOR AND MCBR	NY Spills	Higher	222, 0.042, NE
C18	STEAM HEAT SYR. UNIV	TALOR & MCBRIDE ST	NY Spills	Higher	223, 0.042, NE
C19	INTERSECTION OF	EAST TAYLOR/SOUTH MC	NY Spills	Higher	223, 0.042, NE
C20	PROJECT ORANGE	OLD S.U. STEAM PLANT	NY Spills	Higher	252, 0.048, ENE
21	NIAGARA MOHAWK POWER	235 OAKWOOD AVE. EXT	NY LTANKS, NY Spills, NY MANIFEST	Lower	310, 0.059, SSW
D22	CITY OWNED APARTMENT	301-311 EAST TAYLOR	NY Spills	Lower	316, 0.060, WNW
E23	CENTRAL VILLAGE HOUS	302 BURT ST	UST FINDER	Lower	335, 0.063, WSW
E24	CENTRAL VILLAGE HOUS	302 BURT ST	NY UST	Lower	335, 0.063, WSW
E25	EAST ADAMS REDEVELOP	300 BURT STREET	NY BROWNFIELDS	Lower	341, 0.065, WSW
F26	SYRACUSE HOUSING AUT	516 BURT ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	371, 0.070, ESE
G27	SYRACUSE HOUSING AUT	116-118 RADISSON COU	RCRA-SQG, NY MANIFEST	Lower	418, 0.079, North
G28	PARKING LOT- 111 RAD	111 RADISON CT	NY Spills	Lower	437, 0.083, North
H29	DI PINO ANTHONY	1117 SOUTH STATE ST	EDR Hist Auto	Lower	503, 0.095, West
H30	FORMER SALVATION ARM	1117 SOUTH STATE ST	NY UST	Lower	503, 0.095, West
D31	ROTH BROS METAL CO.	1107 S. STATE STREET	SEMS-ARCHIVE, LEAD SMELTERS	Lower	505, 0.096, WNW
D32	THE SALVATION ARMY	1105 S. STATE ST	NY UST	Lower	506, 0.096, WNW
D33	SPILL NUMBER 8601904	1105 SOUTH STATE ST	NY Spills	Lower	506, 0.096, WNW
D34	EAST ADAMS REDEVELOP	1105-1117 SOUTH STAT	NY BROWNFIELDS, NY PFAS	Lower	506, 0.096, WNW
D35	FORMER SALVATION ARM	1105 SOUTH STATE ST	UST FINDER RELEASE	Lower	506, 0.096, WNW
D36	SALVATION ARMY	1105 SOUTH STATE ST	UST FINDER RELEASE	Lower	506, 0.096, WNW
D37	FORMER SALVATION ARM	1105 SOUTH STATE ST	NY LTANKS, NY Spills	Lower	506, 0.096, WNW
D38	THE SALVATION ARMY	1105 S. STATE ST	UST FINDER	Lower	506, 0.096, WNW
E39	COMMERCIAL - SOUTH S	CORNER OF SOUTH STAT	NY Spills	Lower	519, 0.098, WSW

MAPPED SITES SUMMARY

Target Property Address:
409 BURT STREET
SYRACUSE, NY 13202

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
F40	STEWART COURT	BURT ST	NY Spills	Higher	524, 0.099, East
I41	PROJECT ORANGE	520 E TAYLOR ST	NY CBS, NY AST, NY CBS AST, NY Spills, RCRA NonGen...	Higher	531, 0.101, ENE
I42	SYRACUSE HOUSING AUT	1207 ALMOND STREET	PA MANIFEST	Higher	548, 0.104, East
I43	SYRACUSE HOUSING AUT	1207 ALMOND ST	RCRA-SQG, E MANIFEST, NY MANIFEST	Higher	548, 0.104, East
F44	IN THE STREET	ALMOND AND VAN BUREN	NY Spills	Higher	556, 0.105, ESE
E45	SPARKLE CLEANERS INC	234 BURT ST	EDR Hist Cleaner	Lower	578, 0.109, WSW
I46	SU STEAM STATION	550 E TAYLOR ST	NY Spills	Higher	592, 0.112, ENE
J47	GREATER SYRACUSE LAN	1210-1214 SOUTH STAT	NY Spills	Lower	613, 0.116, WSW
J48	1210 S STATE ST	1210 S STATE ST	US BROWNFIELDS, FINDS	Lower	613, 0.116, WSW
J49	1212 S STATE ST	1212 S STATE ST	US BROWNFIELDS, FINDS	Lower	623, 0.118, WSW
J50	1214 S STATE ST	1214 S STATE ST	US BROWNFIELDS, FINDS	Lower	635, 0.120, WSW
K51	S STATE STREET	S STATE ST/NEW STREE	NY LTANKS	Lower	649, 0.123, WNW
I52	NYSDOT BIN 1031569	I-81/EAST ADAMS STRE	RCRA NonGen / NLR, NY MANIFEST	Higher	656, 0.124, ENE
53	SYRACUSE HOUSING AUT	101-102 DYER COURT	RCRA-VSQG	Higher	773, 0.146, NE
54	NY1-1 PIONEER HOMES	ADAMS/RENWICK/TAYLOR	NY UST	Lower	776, 0.147, NNW
L55	917 MONTGOMERY STREE	917 MONTGOMERY STREE	US BROWNFIELDS, FINDS	Lower	810, 0.153, West
M56	NYSDOT BIN 7706370 -	522 RENWICK AVE	NY MANIFEST	Higher	811, 0.154, ESE
M57	NYSDOT BIN 7706370 -	522 RENWICK AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	811, 0.154, ESE
K58	SYRACUSE HOUSING AUT	218 NEW ST	RCRA-SQG, NY MANIFEST	Lower	878, 0.166, NW
K59	SYRACUSE HOUSING AUT	218 NEW STREET	PA MANIFEST	Lower	878, 0.166, NW
60	TRIPP KATIE	1429 S MCBRIDE ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	906, 0.172, SSE
61	NYS TEAMSTERS	NEW STREET	NY LTANKS	Lower	910, 0.172, NW
L62	WAREHOUSE	908 MONTGOMERY ST	NY UST	Lower	943, 0.179, West
63	SYRACUSE UNIVERSITY	401 VAN BUREN ST	RCRA NonGen / NLR, FINDS, ECHO, E MANIFEST, NY...	Higher	962, 0.182, ESE
N64	SOUTH SALINA SIDA	1016-1018 MONTGOMERY	NY SHWS	Lower	987, 0.187, WSW
O65	DR. KING ELEMENTARY	416 416 E RAYMOR AVE	RCRA-VSQG, E MANIFEST	Lower	1103, 0.209, SSE
O66	KING ELEMENTARY SCHO	416 E RAYNOR AVE	NY MANIFEST, NY COOLING TOWERS	Lower	1103, 0.209, SSE
N67	1045-1047 SOUTH SALI	1045 SOUTH SALINA ST	US BROWNFIELDS, FINDS	Lower	1151, 0.218, WSW
P68	EAST ADAMS REDEVELOP	100 ANGELOU TERRACE	NY BROWNFIELDS	Lower	1165, 0.221, NNW
Q69	FAMILY DOLLAR #5071	945 S SALINA ST	NY MANIFEST	Lower	1174, 0.222, West
Q70	FAMILY DOLLAR #5071	945 S SALINA ST	RCRA-VSQG, ECHO	Lower	1174, 0.222, West
N71	1049-1071 SOUTH SALI	1049-1071 SOUTH SALI	US BROWNFIELDS, FINDS	Lower	1182, 0.224, WSW
P72	SYRACUSE POLICE DEPT	916 S STATE ST	UST FINDER	Lower	1199, 0.227, NNW
P73	SYRACUSE POLICE DEPT	916 S STATE ST	NY UST	Lower	1199, 0.227, NNW
R74	1073-1079 SOUTH SALI	1073-1079 SOUTH SALI	US BROWNFIELDS, FINDS	Lower	1219, 0.231, WSW
R75	1101-1111 SOUTH SALI	1101-1111 SOUTH SALI	US BROWNFIELDS, FINDS	Lower	1224, 0.232, SW
R76	1081-1085 SOUTH SALI	1081-1085 SOUTH SALI	US BROWNFIELDS, FINDS	Lower	1234, 0.234, WSW
R77	SOUTH SALINA STREET	1081 SOUTH SALINA ST	NY BROWNFIELDS, NY Spills	Lower	1234, 0.234, WSW
P78	FIRE STATION #1	900 SOUTH STATE ST	NY UST	Lower	1282, 0.243, NNW

MAPPED SITES SUMMARY

Target Property Address:
409 BURT STREET
SYRACUSE, NY 13202

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P79	NIAGARA MOHAWK A NAT	900 SOUTH STATE STRE	NY MANIFEST	Lower	1282, 0.243, NNW
P80	FIRE STATION #1	900 SOUTH STATE ST	NY AST	Lower	1282, 0.243, NNW
P81	FIRE STATION #1	900 SOUTH STATE ST	UST FINDER	Lower	1282, 0.243, NNW
P82	NIAGARA MOHAWK - A N	900 SOUTH STATE ST	RCRA NonGen / NLR, E MANIFEST	Lower	1282, 0.243, NNW
Q83	SYRACUSE COMMUNITY H	930 S SALINA ST	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Lower	1290, 0.244, West
S84	SYRACUSE CITY OF HOU	1306 S STATE ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1295, 0.245, SSW
S85	NIAGARA MOHAWK POWER	1309 S STATE ST MH13	RCRA NonGen / NLR, E MANIFEST	Lower	1319, 0.250, SSW
T86	MONDO'S AGWAY	1127 SO. SALINA ST	UST FINDER RELEASE	Lower	1416, 0.268, SW
T87	1127 SOUTH SALINA SY	1127 SOUTH SALINA ST	NY LTANKS, NY UST, NY Spills	Lower	1416, 0.268, SW
U88	FORMER COYNE TEXTILE	140 CORTLAND AVENUE	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Lower	1431, 0.271, WSW
U89	RENALLI TAYLOR ST LL	140 CORTLAND AVE	NY LTANKS, NY CBS, NY CBS AST, NY BROWNFIELDS, NY...	Lower	1431, 0.271, WSW
T90	MONDO'S SERVICE STAT	1133 SOUTH SALINA	UST FINDER RELEASE	Lower	1433, 0.271, SW
T91	MONDO'S SERVICE STAT	1133 SOUTH SALINA	NY LTANKS	Lower	1433, 0.271, SW
V92	ADAMS & STATE ST. GA	ADAMS & STATE STREET	NY LTANKS	Lower	1445, 0.274, NNW
V93	ADAMS & STATE ST. GA	ADAMS & STATE STREET	UST FINDER RELEASE	Lower	1445, 0.274, NNW
W94	V.A. MEDICAL CENTER	800 IRIVING AVENUE	NY LTANKS	Higher	1463, 0.277, East
W95	V.A. MEDICAL CENTER	800 IRIVING AVENUE	UST FINDER RELEASE	Higher	1463, 0.277, East
X96	CASTLE REST NURSE HO	401 E CASTLE ST	UST FINDER RELEASE	Higher	1523, 0.288, South
X97	CASTLE REST NURSE HO	401 E CASTLE ST	NY LTANKS	Higher	1523, 0.288, South
98	SYRACUSE UNIV	900 IRVING AVE	NY LTANKS, NY Spills	Higher	1547, 0.293, ESE
Y99	680 SOUTH SALINA ST	680 SOUTH SALINA ST	NY LTANKS, NY Spills	Lower	1623, 0.307, WNW
Y100	DESIMONES SERVICE ST	680 S. SALINA ST	UST FINDER RELEASE	Lower	1623, 0.307, WNW
T101	1202-04 SOUTH SALINA	1202-04 SOUTH SALINA	US BROWNFIELDS, FINDS	Lower	1628, 0.308, SW
T102	1146 S SALINA STREET	1146 S SALINA STREET	US BROWNFIELDS, FINDS	Lower	1661, 0.315, SW
103	CENTRO PARKING INC.	SUNY HEALTH SRV. CEN	NY LTANKS	Lower	1674, 0.317, North
104	1208-18 SOUTH SALINA	1208-18 SOUTH SALINA	US BROWNFIELDS, FINDS	Lower	1693, 0.321, SW
105	SYRACUSE UNIVERISTY	OFF SKYTOP RD	NY LTANKS	Higher	1786, 0.338, East
106	HARRISON PL & E ADAM	HARRISON PL & E ADAM	NY LTANKS	Lower	1835, 0.348, NW
Z107	743 IRVING AVE.	743 IRVING AVE	NY LTANKS	Higher	1848, 0.350, ENE
Z108	743 IRVING AVE.	743 IRVING AVE	UST FINDER RELEASE	Higher	1848, 0.350, ENE
AA109	SUNY UPSTATE	750 EAST ADAMS ST	NY LTANKS, NY CBS, NY AST, NY CBS AST, NY Spills,...	Higher	1886, 0.357, NE
AB110	1357 SALINA STREET S	1357 SALINA STREET S	US BROWNFIELDS, FINDS	Lower	1965, 0.372, SSW
111	JMA CAMPUS PLAN	623 ONEIDA STREET	NY BROWNFIELDS	Lower	1977, 0.374, WSW
AC112	SPILL NUMBER 9900884	116 EAST CASTLE ST	UST FINDER RELEASE	Lower	1979, 0.375, SSW
AC113	CASTLE REST NURSING	116 EAST CASTLE ST	NY LTANKS, NY Spills	Lower	1979, 0.375, SSW
114	S&F AUTOMOTIVE	420 ONEIDA ST	NY LTANKS	Lower	2023, 0.383, West
AD115	CENTRAL BUS CNYRTA M	200 CORTLAND AVE	NY LTANKS, NY Spills, NY COOLING TOWERS	Lower	2025, 0.384, SW
AD116	CNY CENTRO INC	200 CORTLAND AVE	NY LTANKS, NY CBS, NY Spills, NY AIRS	Lower	2025, 0.384, SW
AA117	CLARK HALL; CROUSE I	ELIZABETH BLACKWELL	NY LTANKS	Higher	2026, 0.384, NE

MAPPED SITES SUMMARY

Target Property Address:
409 BURT STREET
SYRACUSE, NY 13202

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AE118	MARATHON WATER SUPPL	MARATHON SCHOOL BUS	NY LTANKS	Lower	2054, 0.389, NNW
AF119	BYRNE DAIRY	KING ST	NY LTANKS	Lower	2057, 0.390, West
AF120	BYRNE DAIRY	235 KING STREET	NY LTANKS	Lower	2082, 0.394, West
121	HARRISON CONVENTION	HARRISON & MONTGOMER	UST FINDER RELEASE	Lower	2098, 0.397, NNW
AB122	1400-20 SALINA STREE	1400-20 SALINA STREE	US BROWNFIELDS, FINDS	Lower	2175, 0.412, SSW
AE123	SPILL NUMBER 8601815	600 S. STATE ST @ CI	NY LTANKS	Lower	2257, 0.427, North
124	BYRNE DAIRY INC.	240 ONEIDA STREET	NY LTANKS, NY UST, NY CBS, NY AST, NY Spills, NY...	Lower	2304, 0.436, WNW
AG125	ATLAS SERVICES	TAYLOR ST; KING ST	NY LTANKS	Lower	2319, 0.439, West
126	SYRACUSE UNIVERSITY	M17 SKYTOP RD	NY LTANKS	Higher	2348, 0.445, East
AH127	HARRISON PARKING GAR	WARREN & HARRISON ST	UST FINDER RELEASE	Lower	2387, 0.452, NW
AH128	HARRISON PARKING GAR	WARREN & HARRISON ST	NY LTANKS	Lower	2387, 0.452, NW
AG129	ATLAS LINEN	320 WEST TAYLOR ST	UST FINDER RELEASE	Lower	2417, 0.458, West
130	HUTCHING PSYCH CTR T	620 MADISON ST	NY LTANKS, NY Spills	Lower	2445, 0.463, NNE
131	MONTGOMERY STREET	MONGOMERY ST AND MAD	NY LTANKS	Lower	2499, 0.473, NNW
AI132	CHIMES BUILDING	500-550 SOUTH SALINA	NY BROWNFIELDS	Lower	2513, 0.476, NW
AI133	500 SOUTH SALINA STR	500 SOUTH SALINA STR	UST FINDER RELEASE	Lower	2513, 0.476, NW
AI134	THE CHIMES BUILDING	500-550 SOUTH SALINA	US BROWNFIELDS	Lower	2513, 0.476, NW
135	MIDSTATE AUTO	PO BOX 11298	NY SWF/LF	Higher	2543, 0.482, SSW
AJ136	H.S.M.PACKAGING CORP	123 LARNED ST	UST FINDER RELEASE	Lower	2570, 0.487, WNW
AJ137	H.S.M.PACKAGING CORP	123 LARNED ST	NY LTANKS	Lower	2570, 0.487, WNW
AK138	DISTRICT HEATING & C	601 S STATE ST	NY LTANKS, NY Spills, NY AIRS, NY MANIFEST	Lower	2576, 0.488, NNW
AK139	STEAM STATION-S.STAT	601 S. STATE ST	UST FINDER RELEASE	Lower	2576, 0.488, NNW
140	MANLEY FIELD GROUNDS	MANLEY FIELD HOUSE	NY LTANKS	Higher	2627, 0.498, ESE
141	BROWN MANUFACTURING	101 CHESTER ST	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY ERP	Lower	3796, 0.719, WSW
142	NIMO - SYRACUSE - ER	300 ERIC BLVD WEST	EDR MGP	Lower	5120, 0.970, NNW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
SYRACUSE HOUSING AUT 409 BURT ST SYRACUSE, NY 13202	RCRA-LQG EPA ID:: NY0000201889 FINDS Registry ID:: 110004313706 ECHO Registry ID: 110004313706 NY MANIFEST EPA ID: NY0000201889	NY0000201889

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---------- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System

US ENG CONTROLS ..... Engineering Controls Sites List
US INST CONTROLS ..... Institutional Controls Sites List

Federal ERNS list

ERNS ..... Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ..... Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ..... Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ..... Underground Storage Tank Listing
NY CBS UST ..... Chemical Bulk Storage Database
NY MOSF UST ..... Major Oil Storage Facilities Database
NY MOSF ..... Major Oil Storage Facility Site Listing
NY MOSF AST ..... Major Oil Storage Facilities Database
INDIAN UST ..... Underground Storage Tanks on Indian Land
NY TANKS ..... Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ..... Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

NY VCP ..... Voluntary Cleanup Agreements
INDIAN VCP ..... Voluntary Cleanup Priority Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ..... Registered Waste Tire Storage & Facility List
NY SWRCY ..... Registered Recycling Facility List
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands
ODI ..... Open Dump Inventory
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ..... Delisted National Clandestine Laboratory Register
NY DEL SHWS ..... Delisted Registry Sites
US CDL ..... National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ..... Historical Petroleum Bulk Storage Database
NY HIST AST ..... Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ..... Spill Liens Information

LIENS 2 ---------- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System
NY Hist Spills ---------- SPILLS Database
NY SPILLS 90 ---------- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---------- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---------- Formerly Used Defense Sites
DOD ---------- Department of Defense Sites
SCRD DRYCLEANERS ---------- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---------- Financial Assurance Information
EPA WATCH LIST ---------- EPA WATCH LIST
2020 COR ACTION ---------- 2020 Corrective Action Program List
TSCA ---------- Toxic Substances Control Act
TRIS ---------- Toxic Chemical Release Inventory System
SSTS ---------- Section 7 Tracking Systems
ROD ---------- Records Of Decision
RMP ---------- Risk Management Plans
RAATS ---------- RCRA Administrative Action Tracking System
PRP ---------- Potentially Responsible Parties
PADS ---------- PCB Activity Database System
FTTS ---------- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---------- Material Licensing Tracking System
COAL ASH DOE ---------- Steam-Electric Plant Operation Data
COAL ASH EPA ---------- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---------- PCB Transformer Registration Database
RADINFO ---------- Radiation Information Database
HIST FTTS ---------- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---------- Incident and Accident Data
CONSENT ---------- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---------- Indian Reservations
FUSRAP ---------- Formerly Utilized Sites Remedial Action Program
UMTRA ---------- Uranium Mill Tailings Sites
US MINES ---------- Mines Master Index File
MINES MRDS ---------- Mineral Resources Data System
ABANDONED MINES ---------- Abandoned Mines
UXO ---------- Unexploded Ordnance Sites
DOCKET HWC ---------- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---------- EPA Fuels Program Registered Listing
PFAS NPL ---------- Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES ---------- Federal Sites PFAS Information
PFAS TSCA ---------- PFAS Manufacture and Imports Information
PFAS TRIS ---------- List of PFAS Added to the TRI
PFAS RCRA MANIFEST ---------- PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR ---------- PFAS Contamination Site Location Listing
PFAS WQP ---------- Ambient Environmental Sampling for PFAS
PFAS PROJECT ---------- NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS NPDES ---------- Clean Water Act Discharge Monitoring Information
PFAS ECHO FIRE TRAIN ---------- Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT ---------- All Certified Part 139 Airports PFAS Information Listing

AQUEOUS FOAM NRC Aqueous Foam Related Incidents Listing
BIOSOLIDS ICIS-NPDES Biosolids Facility Data
NY COAL ASH Coal Ash Disposal Site Listing
NY E DESIGNATION E DESIGNATION SITE LISTING
NY Financial Assurance Financial Assurance Information Listing
NY HSWDS Hazardous Substance Waste Disposal Site Inventory
NY LEAD Lead-based Paint Testing Results
NY VAPOR REOPENED Vapor Intrusion Legacy Site List
NY UIC Underground Injection Control Wells
NY NYC LAND USE New York City Land Use Information
NY NYC OER OER Cleanup Sites Listing
NY ILI New York State Inactive Landfill Initiative
NY MGP Manufactured Gas Plants Listing

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 03/27/2025 has revealed that there

is 1 SEMS-ARCHIVE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ROTH BROS METAL CO.	***1107 S. STATE STREET***	***WNW 0 - 1/8 (0.096 mi.)***	***D31***	***275***

Lists of Federal RCRA generators

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 4 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE HOUSING AUT EPA ID:: NYR000154468	***1207 ALMOND ST***	***E 0 - 1/8 (0.104 mi.)***	***I43***	***346***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE HOUSING AUT EPA ID:: NYR000154476	***116-118 RADISSON COU***	***N 0 - 1/8 (0.079 mi.)***	***G27***	***264***
SYRACUSE HOUSING AUT EPA ID:: NYR000171124	***218 NEW ST***	***NW 1/8 - 1/4 (0.166 mi.)***	***K58***	***433***
SYRACUSE COMMUNITY H EPA ID:: NYR000199190	***930 S SALINA ST***	***W 1/8 - 1/4 (0.244 mi.)***	***Q83***	***509***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 3 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE HOUSING AUT EPA ID:: NYR000164129	101-102 DYER COURT	NE 1/8 - 1/4 (0.146 mi.)	53	405

Lower Elevation	Address	Direction / Distance	Map ID	Page
DR. KING ELEMENTARY EPA ID:: NYR000240960	***416 416 E RAYMOR AVE***	***SSE 1/8 - 1/4 (0.209 mi.)***	***O65***	***459***
FAMILY DOLLAR #5071 EPA ID:: NYR000211730	***945 S SALINA ST***	***W 1/8 - 1/4 (0.222 mi.)***	***Q70***	***474***

EXECUTIVE SUMMARY

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 02/03/2025 has revealed that there are 2 NY SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTH SALINA SIDA Site Code: 422215	1016-1018 MONTGOMERY	WSW 1/8 - 1/4 (0.187 mi.)	N64	458
BROWN MANUFACTURING Site Code: 465076	***101 CHESTER ST***	***WSW 1/2 - 1 (0.719 mi.)***	***141***	***823***

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 02/20/2025 has revealed that there is 1 NY SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MIDSTATE AUTO	PO BOX 11298	SSW 1/4 - 1/2 (0.482 mi.)	135	805

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/02/2025 has revealed that there are 37 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STEAM PLANT Site ID: 259520 Spill Date: 1999-10-20 Spill Number/Closed Date: 9908800 / 1999-11-23	MCBRIDE ST	NE 0 - 1/8 (0.035 mi.)	C6	73
SYRACUSE UNIVERSITY Site ID: 229011 Site ID: 229012 Spill Date: 1986-11-11 Spill Number/Closed Date: 8605131 / 1988-01-15	***500 E TAYLOR ST***	***NE 0 - 1/8 (0.040 mi.)***	***C12***	***91***

Spill Number/Closed Date: 8605148 / 1988-01-15

V.A. MEDICAL CENTER Site ID: 242917 Site ID: 242920 Spill Date: 2004-05-27 Spill Date: 1998-09-28 Spill Number/Closed Date: 0402165 / 2004-09-29 Spill Number/Closed Date: 9807877 / 2002-08-06	800 IRIVING AVENUE	E 1/4 - 1/2 (0.277 mi.)	W94	652
CASTLE REST NURSE HO Site ID: 149961 Spill Date: 1991-01-18 Spill Number/Closed Date: 9011086 / 1991-01-31	401 E CASTLE ST	S 1/4 - 1/2 (0.288 mi.)	X97	656
SYRACUSE UNIV Site ID: 96874 Spill Date: 2003-01-10 Spill Number/Closed Date: 0210237 / 2003-10-31	***900 IRVING AVE***	***ESE 1/4 - 1/2 (0.293 mi.)***	***98***	***657***
SYRACUSE UNIVERISTY Site ID: 207927 Spill Date: 2004-01-14 Spill Number/Closed Date: 0311616 / 2004-05-04	OFF SKYTOP RD	E 1/4 - 1/2 (0.338 mi.)	105	699
743 IRVING AVE. Site ID: 180766 Spill Date: 1991-05-08 Spill Number/Closed Date: 9101558 / 1991-05-08	743 IRVING AVE	ENE 1/4 - 1/2 (0.350 mi.)	Z107	701
SUNY UPSTATE Site ID: 500005 Spill Date: 2014-09-19 Spill Number/Closed Date: 1406531 / 2015-07-22	***750 EAST ADAMS ST***	***NE 1/4 - 1/2 (0.357 mi.)***	***AA109***	***703***
CLARK HALL; CROUSE I Site ID: 114725 Spill Date: 1988-02-18 Spill Number/Closed Date: 8709940 / 1988-04-12	ELIZABETH BLACKWELL	NE 1/4 - 1/2 (0.384 mi.)	AA117	755
SYRACUSE UNIVERSITY Site ID: 156486 Spill Date: 1998-08-03 Spill Number/Closed Date: 9805513 / 1998-09-21	M17 SKYTOP RD	E 1/4 - 1/2 (0.445 mi.)	126	780
MANLEY FIELD GROUNDS Site ID: 293002 Spill Date: 1992-06-10 Spill Number/Closed Date: 9202927 / 1992-06-11	MANLEY FIELD HOUSE	ESE 1/4 - 1/2 (0.498 mi.)	140	822

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA MOHAWK POWER Site ID: 327666 Spill Date: 1994-10-24 Spill Number/Closed Date: 9409889 / 1995-04-18	***235 OAKWOOD AVE. EXT***	***SSW 0 - 1/8 (0.059 mi.)***	***21***	***224***
FORMER SALVATION ARM Site ID: 61010 Spill Date: 2004-08-04 Spill Number/Closed Date: 0404882 / 2005-03-04	***1105 SOUTH STATE ST***	***WNW 0 - 1/8 (0.096 mi.)***	***D37***	***289***
S STATE STREET	S STATE ST/NEW STREE	WNW 0 - 1/8 (0.123 mi.)	K51	397

Site ID: 229077 Spill Date: 1992-10-19 Spill Number/Closed Date: 9208359 / 1993-01-26				
NYS TEAMSTERS Site ID: 100774 Spill Date: 1990-05-11 Spill Number/Closed Date: 9001641 / 1990-09-13	NEW STREET	NW 1/8 - 1/4 (0.172 mi.)	61	442
1127 SOUTH SALINA SY Site ID: 302125 Spill Date: 1985-03-25 Spill Number/Closed Date: 8403634 / 1991-06-17	***1127 SOUTH SALINA ST***	***SW 1/4 - 1/2 (0.268 mi.)***	***T87***	***527***
RENALLI TAYLOR ST LL Site ID: 156885 Spill Date: 1996-07-01 Spill Number/Closed Date: 9604373 / 1996-07-02	***140 CORTLAND AVE***	***WSW 1/4 - 1/2 (0.271 mi.)***	***U89***	***597***
MONDO'S SERVICE STAT Site ID: 382878 Spill Date: 2007-06-13 Spill Number/Closed Date: 0703031 / 2007-10-04	1133 SOUTH SALINA	SW 1/4 - 1/2 (0.271 mi.)	T91	649
ADAMS & STATE ST. GA Site ID: 210798 Spill Date: 1991-11-06 Spill Number/Closed Date: 9108385 / 1991-11-07	ADAMS & STATE STREET	NNW 1/4 - 1/2 (0.274 mi.)	V92	650
680 SOUTH SALINA ST Site ID: 525912 Site ID: 265820 Spill Date: 2016-04-18 Spill Date: 1987-09-28 Spill Number/Closed Date: 1600634 / 2019-12-10 Spill Number/Closed Date: 8705408 / 1987-10-28	***680 SOUTH SALINA ST***	***WNW 1/4 - 1/2 (0.307 mi.)***	***Y99***	***660***
CENTRO PARKING INC. Site ID: 323404 Spill Date: 1993-12-23 Spill Number/Closed Date: 9311487 / 2001-02-12	SUNY HEALTH SRV. CEN	N 1/4 - 1/2 (0.317 mi.)	103	680
HARRISON PL & E ADAM Site ID: 97685 Spill Date: 1999-02-25 Spill Number/Closed Date: 9814193 / 1999-04-26	HARRISON PL & E ADAM	NW 1/4 - 1/2 (0.348 mi.)	106	700
CASTLE REST NURSING Site ID: 166430 Spill Date: 1999-04-23 Spill Number/Closed Date: 9900884 / 2000-03-20	***116 EAST CASTLE ST***	***SSW 1/4 - 1/2 (0.375 mi.)***	***AC113***	***733***
S&F AUTOMOTIVE Site ID: 194355 Spill Date: 1992-09-24 Spill Number/Closed Date: 9207347 / 1992-10-05	420 ONEIDA ST	W 1/4 - 1/2 (0.383 mi.)	114	735
CENTRAL BUS CNYRTA M Site ID: 275090 Spill Date: 1993-03-09 Spill Number/Closed Date: 9213577 / 1995-12-28	***200 CORTLAND AVE***	***SW 1/4 - 1/2 (0.384 mi.)***	***AD115***	***736***
CNY CENTRO INC	***200 CORTLAND AVE***	***SW 1/4 - 1/2 (0.384 mi.)***	***AD116***	***741***

Site ID: 230780
Site ID: 230781
Spill Date: 1995-01-18
Spill Date: 1995-10-11
Spill Number/Closed Date: 9413883 / 2002-08-06
Spill Number/Closed Date: 9508450 / 1995-10-11

MARATHON WATER SUPPL	MARATHON SCHOOL BUS	NNW 1/4 - 1/2 (0.389 mi.)	AE118	756
Site ID: 64963 Spill Date: 1991-07-09 Spill Number/Closed Date: 9104876 / 1996-04-22				
BYRNE DAIRY	KING ST	W 1/4 - 1/2 (0.390 mi.)	AF119	757
Site ID: 109545 Spill Date: 2003-02-22 Spill Number/Closed Date: 0211606 / 2003-07-30				
BYRNE DAIRY	235 KING STREET	W 1/4 - 1/2 (0.394 mi.)	AF120	758
Site ID: 198191 Spill Date: 1986-09-16 Spill Number/Closed Date: 8603904 / 1988-01-15				
SPILL NUMBER 8601815	600 S. STATE ST @ CI	N 1/4 - 1/2 (0.427 mi.)	AE123	765
Site ID: 137258 Spill Date: 1986-06-16 Spill Number/Closed Date: 8601815 / 1988-01-15				
BYRNE DAIRY INC.	***240 ONEIDA STREET***	***WNW 1/4 - 1/2 (0.436 mi.)***	***124***	***766***
Site ID: 64142 Site ID: 109079 Site ID: 168673 Spill Date: 1998-07-09 Spill Date: 1997-06-11 Spill Date: 1987-12-28 Spill Number/Closed Date: 9804457 / 2000-11-08 Spill Number/Closed Date: 9703387 / 1997-06-30 Spill Number/Closed Date: 8708332 / 1988-02-04				
ATLAS SERVICES	TAYLOR ST; KING ST	W 1/4 - 1/2 (0.439 mi.)	AG125	779
Site ID: 243223 Spill Date: 1987-11-25 Spill Number/Closed Date: 8707432 / 1988-01-05				
HARRISON PARKING GAR	WARREN & HARRISON ST	NW 1/4 - 1/2 (0.452 mi.)	AH128	781
Site ID: 121632 Spill Date: 1991-01-05 Spill Number/Closed Date: 9010749 / 1999-11-26				
HUTCHING PSYCH CTR T	***620 MADISON ST***	***NNE 1/4 - 1/2 (0.463 mi.)***	***130***	***783***
Site ID: 187125 Spill Date: 2003-02-24 Spill Number/Closed Date: 0211660 / 2004-11-26				
MONTGOMERY STREET	MONGOMERY ST AND MAD	NNW 1/4 - 1/2 (0.473 mi.)	131	793
Site ID: 316015 Spill Date: 2003-12-10 Spill Number/Closed Date: 0310457 / 2003-12-15				
H.S.M.PACKAGING CORP	123 LARNED ST	WNW 1/4 - 1/2 (0.487 mi.)	AJ137	807
Site ID: 228231 Spill Date: 1996-07-24				

Spill Number/Closed Date: 9605294 / 1996-09-30

DISTRICT HEATING & C ***601 S STATE ST*** ***NNW 1/4 - 1/2 (0.488 mi.)*** ***AK138*** ***808***
Site ID: 93875
Spill Date: 1986-07-18
Spill Number/Closed Date: 8602554 / 1988-12-12

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 8 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE UNIVERSITY	***500 EAST TAYLOR ST***	***NE 0 - 1/8 (0.040 mi.)***	***C11***	***83***
Database: UST, Date of Government Version: 03/17/2025				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CENTRAL VILLAGE HOUS	302 BURT ST	WSW 0 - 1/8 (0.063 mi.)	E24	249
Database: UST, Date of Government Version: 03/17/2025				
FORMER SALVATION ARM	1117 SOUTH STATE ST	W 0 - 1/8 (0.095 mi.)	H30	271
Database: UST, Date of Government Version: 03/17/2025				
THE SALVATION ARMY	1105 S. STATE ST	WNW 0 - 1/8 (0.096 mi.)	D32	277
Database: UST, Date of Government Version: 03/17/2025				
NY1-1 PIONEER HOMES	ADAMS/RENWICK/TAYLOR	NNW 1/8 - 1/4 (0.147 mi.)	54	408
Database: UST, Date of Government Version: 03/17/2025				
WAREHOUSE	908 MONTGOMERY ST	W 1/8 - 1/4 (0.179 mi.)	L62	443
Database: UST, Date of Government Version: 03/17/2025				
SYRACUSE POLICE DEPT	916 S STATE ST	NNW 1/8 - 1/4 (0.227 mi.)	P73	481
Database: UST, Date of Government Version: 03/17/2025				
FIRE STATION #1	900 SOUTH STATE ST	NNW 1/8 - 1/4 (0.243 mi.)	P78	498
Database: UST, Date of Government Version: 03/17/2025				

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 03/17/2025 has revealed that there are 2 NY CBS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SU CHILLED WATER PLA	***500 E. TAYLOR STREET***	***NE 0 - 1/8 (0.040 mi.)***	***C13***	***185***
Facility Status: Unregulated/Closed				
CBS Number: 7-000152				
CBS Number: 7-000281				
PROJECT ORANGE	***520 E TAYLOR ST***	***ENE 0 - 1/8 (0.101 mi.)***	***I41***	***294***

Facility Status: Unregulated/Closed
CBS Number: 7-000230

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 5 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SU CHILLED WATER PLA	***500 E. TAYLOR STREET***	***NE 0 - 1/8 (0.040 mi.)***	***C9***	***78***
Database: AST, Date of Government Version: 03/17/2025 Facility Id: 7-000281				
SYRACUSE UNIVERSITY	***500 EAST TAYLOR ST***	***NE 0 - 1/8 (0.040 mi.)***	***C11***	***83***
Database: AST, Date of Government Version: 03/17/2025 Facility Id: 7-180602				
SU CHILLED WATER PLA	***500 E. TAYLOR STREET***	***NE 0 - 1/8 (0.040 mi.)***	***C13***	***185***
Database: AST, Date of Government Version: 03/17/2025 Facility Id: 7-000152				
PROJECT ORANGE	***520 E TAYLOR ST***	***ENE 0 - 1/8 (0.101 mi.)***	***I41***	***294***
Database: AST, Date of Government Version: 03/17/2025 Facility Id: 7-000230				

Lower Elevation	Address	Direction / Distance	Map ID	Page
FIRE STATION #1	900 SOUTH STATE ST	NNW 1/8 - 1/4 (0.243 mi.)	P80	502
Database: AST, Date of Government Version: 03/17/2025 Facility Id: 7-181935				

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 3 NY CBS AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE UNIVERSITY Facility Status: 1 Facility Status: 1 CBS Number: 7-000152	500 E. TAYLOR STREET	NE 0 - 1/8 (0.040 mi.)	C7	74
SU CHILLED WATER PLA Facility Status: 2 Facility Status: 1 CBS Number: 7-000281	***500 E. TAYLOR STREET***	***NE 0 - 1/8 (0.040 mi.)***	***C9***	***78***
PROJECT ORANGE Facility Status: 1	***520 E TAYLOR ST***	***ENE 0 - 1/8 (0.101 mi.)***	***I41***	***294***

Facility Status: 1
CBS Number: 7-000230

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 02/03/2025 has revealed that there are 2 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCKINNEY PROPERTY Site Code: 57334	***1226 SOUTH MCBRIDE S***	***0 - 1/8 (0.000 mi.)***	***A2***	***21***

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER COYNE TEXTILE Site Code: 507968	***140 CORTLAND AVENUE***	***WSW 1/4 - 1/2 (0.271 mi.)***	***U88***	***536***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 02/03/2025 has revealed that there are 2 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCKINNEY PROPERTY Site Code: 57334	***1226 SOUTH MCBRIDE S***	***0 - 1/8 (0.000 mi.)***	***A2***	***21***

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER COYNE TEXTILE Site Code: 507968	***140 CORTLAND AVENUE***	***WSW 1/4 - 1/2 (0.271 mi.)***	***U88***	***536***

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 02/03/2025 has revealed that there are 8 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAST ADAMS REDEVELOP Site Code: 657340	300 BURT STREET	WSW 0 - 1/8 (0.065 mi.)	E25	251
EAST ADAMS REDEVELOP Site Code: 659420	***1105-1117 SOUTH STAT***	***WNW 0 - 1/8 (0.096 mi.)***	***D34***	***280***
EAST ADAMS REDEVELOP	100 ANGELOU TERRACE	NNW 1/8 - 1/4 (0.221 mi.)	P68	469

Site Code: 658151				
SOUTH SALINA STREET Site Code: 570636	***1081 SOUTH SALINA ST***	***WSW 1/8 - 1/4 (0.234 mi.)***	***R77***	***491***
FORMER COYNE TEXTILE Site Code: 507968	***140 CORTLAND AVENUE***	***WSW 1/4 - 1/2 (0.271 mi.)***	***U88***	***536***
RENALLI TAYLOR ST LL Site Code: 580830	***140 CORTLAND AVE***	***WSW 1/4 - 1/2 (0.271 mi.)***	***U89***	***597***
JMA CAMPUS PLAN Site Code: 667687	623 ONEIDA STREET	WSW 1/4 - 1/2 (0.374 mi.)	111	730
CHIMES BUILDING Site Code: 662655	500-550 SOUTH SALINA	NW 1/4 - 1/2 (0.476 mi.)	AI132	794

NY ERP: In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

A review of the NY ERP list, as provided by EDR, and dated 02/03/2025 has revealed that there is 1 NY ERP site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCKINNEY PROPERTY Site Code: 57334	***1226 SOUTH MCBRIDE S***	***0 - 1/8 (0.000 mi.)***	***A2***	***21***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 09/09/2024 has revealed that there are 15 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
1210 S STATE ST	***1210 S STATE ST***	***WSW 0 - 1/8 (0.116 mi.)***	***J48***	***357***
1212 S STATE ST	***1212 S STATE ST***	***WSW 0 - 1/8 (0.118 mi.)***	***J49***	***370***
1214 S STATE ST	***1214 S STATE ST***	***WSW 0 - 1/8 (0.120 mi.)***	***J50***	***384***
917 MONTGOMERY STREE	***917 MONTGOMERY STREE***	***W 1/8 - 1/4 (0.153 mi.)***	***L55***	***410***
1045-1047 SOUTH SALI	***1045 SOUTH SALINA ST***	***WSW 1/8 - 1/4 (0.218 mi.)***	***N67***	***466***
1049-1071 SOUTH SALI	***1049-1071 SOUTH SALI***	***WSW 1/8 - 1/4 (0.224 mi.)***	***N71***	***477***
1073-1079 SOUTH SALI	***1073-1079 SOUTH SALI***	***WSW 1/8 - 1/4 (0.231 mi.)***	***R74***	***484***
1101-1111 SOUTH SALI	***1101-1111 SOUTH SALI***	***SW 1/8 - 1/4 (0.232 mi.)***	***R75***	***486***
1081-1085 SOUTH SALI	***1081-1085 SOUTH SALI***	***WSW 1/8 - 1/4 (0.234 mi.)***	***R76***	***489***
1202-04 SOUTH SALINA	***1202-04 SOUTH SALINA***	***SW 1/4 - 1/2 (0.308 mi.)***	***T101***	***666***

Lower Elevation	Address	Direction / Distance	Map ID	Page
1146 S SALINA STREET	***1146 S SALINA STREET***	***SW 1/4 - 1/2 (0.315 mi.)***	***T102***	***673***
1208-18 SOUTH SALINA	***1208-18 SOUTH SALINA***	***SW 1/4 - 1/2 (0.321 mi.)***	***104***	***681***
1357 SALINA STREET S	***1357 SALINA STREET S***	***SSW 1/4 - 1/2 (0.372 mi.)***	***AB110***	***723***
1400-20 SALINA STREE	***1400-20 SALINA STREE***	***SSW 1/4 - 1/2 (0.412 mi.)***	***AB122***	***760***
THE CHIMES BUILDING	500-550 SOUTH SALINA	NW 1/4 - 1/2 (0.476 mi.)	AI134	798

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/02/2025 has revealed that there are 22 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCKINNEY PROPERTY	***1226 SOUTH MCBRIDE S***	***0 - 1/8 (0.000 mi.)***	***A2***	***21***
Spill Number/Closed Date: 0402274 / 2004-06-04				
Spill Number/Closed Date: 0712291 / 2009-02-10				
Site ID: 202067				
Site ID: 393888				
Spill Date: 2004-05-31				
Spill Date: 2008-02-21				
ERP SITE	1226 MCBRIDE ST	0 - 1/8 (0.000 mi.)	A3	65
Spill Number/Closed Date: 2308014 / Not Reported				
Site ID: 661110				
Spill Date: 2023-12-28				
STEAM STATION	500 EAST TAYLOR ST	NE 0 - 1/8 (0.040 mi.)	C8	77
Spill Number/Closed Date: 1810736 / 2019-03-26				
Site ID: 581643				
Spill Date: 2019-01-23				
SYRACUSE UNIV STEAM	500 EAST TAYLOR ST	NE 0 - 1/8 (0.040 mi.)	C10	81
Spill Number/Closed Date: 1502394 / 2016-04-08				
Site ID: 508657				
Spill Date: 2015-06-03				
SYRACUSE UNIVERSITY	***500 E TAYLOR ST***	***NE 0 - 1/8 (0.040 mi.)***	***C12***	***91***
Spill Number/Closed Date: 0407665 / 2004-10-13				
Spill Number/Closed Date: 8910992 / 1990-07-09				
Spill Number/Closed Date: 1206833 / 2012-12-04				
Site ID: 332190				
Site ID: 161895				
Site ID: 469851				
Spill Date: 2004-10-11				
Spill Date: 1990-02-17				
Spill Date: 2012-10-11				
SU CHILLED WATER PLA	***500 E. TAYLOR STREET***	***NE 0 - 1/8 (0.040 mi.)***	***C13***	***185***
Spill Number/Closed Date: 1902943 / 2020-03-27				
Spill Number/Closed Date: 9008107 / 1990-10-24				
Site ID: 590889				

Site ID: 161896
Spill Date: 2019-06-21
Spill Date: 1990-10-24

TAYLOR & MCBRIDE ST. Spill Number/Closed Date: 9107234 / 1991-11-12 Site ID: 284835 Spill Date: 1991-10-05	TAYLOR AND MCBRIDE S	NE 0 - 1/8 (0.042 mi.)	C16	218
E. TAYLOR AND MCBRID Spill Number/Closed Date: 9204042 / 1992-07-08 Site ID: 238382 Spill Date: 1992-07-08	EAST TAYLOR AND MCBR	NE 0 - 1/8 (0.042 mi.)	C17	219
STEAM HEAT SYR. UNIV Spill Number/Closed Date: 8801654 / 1995-02-09 Site ID: 257809 Spill Date: 1988-05-23	TALOR & MCBRIDE ST	NE 0 - 1/8 (0.042 mi.)	C18	220
INTERSECTION OF Spill Number/Closed Date: 0600689 / 2006-04-19 Site ID: 362754 Spill Date: 2006-04-18	EAST TAYLOR/SOUTH MC	NE 0 - 1/8 (0.042 mi.)	C19	221
PROJECT ORANGE Spill Number/Closed Date: 9207607 / 1992-09-30 Site ID: 262415 Spill Date: 1992-09-29	OLD S.U. STEAM PLANT	ENE 0 - 1/8 (0.048 mi.)	C20	222
STEWART COURT Spill Number/Closed Date: 9612359 / 1997-01-29 Site ID: 152474 Spill Date: 1996-12-26	BURT ST	E 0 - 1/8 (0.099 mi.)	F40	293
PROJECT ORANGE Spill Number/Closed Date: 0001904 / 2002-06-03 Spill Number/Closed Date: 1213761 / 2013-01-09 Spill Number/Closed Date: 9211857 / 1993-03-02 Site ID: 223336 Site ID: 476969 Site ID: 212315 Spill Date: 2000-05-15 Spill Date: 2012-12-20 Spill Date: 1993-01-16	***520 E TAYLOR ST***	***ENE 0 - 1/8 (0.101 mi.)***	***I41***	***294***
IN THE STREET Spill Number/Closed Date: 1011911 / 2011-04-26 Site ID: 445807 Spill Date: 2011-03-01	ALMOND AND VAN BUREN	ESE 0 - 1/8 (0.105 mi.)	F44	353
SU STEAM STATION Spill Number/Closed Date: 8912216 / 1990-04-04 Site ID: 133848 Spill Date: 1990-03-23	550 E TAYLOR ST	ENE 0 - 1/8 (0.112 mi.)	I46	355

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA MOHAWK POWER Spill Number/Closed Date: 0405104 / 2004-08-30 Spill Number/Closed Date: 0405144 / 2004-08-30 Spill Number/Closed Date: 0405710 / 2004-11-16	***235 OAKWOOD AVE. EXT***	***SSW 0 - 1/8 (0.059 mi.)***	***21***	***224***

Spill Number/Closed Date: 8708047 / 1988-07-05
Spill Number/Closed Date: 9206473 / 1992-12-07
**Additional key fields are available in the Map Findings section*
Site ID: 327661
Site ID: 327662
Site ID: 327663
Site ID: 327664
Site ID: 327665
**Additional key fields are available in the Map Findings section*
Spill Date: 2004-08-10
Spill Date: 2004-08-25
Spill Date: 1987-12-17
Spill Date: 1992-09-03
Spill Date: 1995-12-06
**Additional key fields are available in the Map Findings section*

CITY OWNED APARTMENT	301-311 EAST TAYLOR	WNW 0 - 1/8 (0.060 mi.)	D22	247
Spill Number/Closed Date: 2400040 / Not Reported Site ID: 664372 Spill Date: 2024-04-02				
PARKING LOT- 111 RAD	111 RADISON CT	N 0 - 1/8 (0.083 mi.)	G28	268
Spill Number/Closed Date: 2005041 / 2022-05-13 Site ID: 610813 Spill Date: 2020-09-01				
SPILL NUMBER 8601904	1105 SOUTH STATE ST	WNW 0 - 1/8 (0.096 mi.)	D33	279
Spill Number/Closed Date: 8601904 / 1987-08-11 Site ID: 142087 Spill Date: 1986-06-19				
FORMER SALVATION ARM	***1105 SOUTH STATE ST***	***WNW 0 - 1/8 (0.096 mi.)***	***D37***	***289***
Spill Number/Closed Date: 9711143 / 2002-08-06 Site ID: 61011 Spill Date: 1998-01-05				
COMMERCIAL - SOUTH S	CORNER OF SOUTH STAT	WSW 0 - 1/8 (0.098 mi.)	E39	292
Spill Number/Closed Date: 2208975 / 2024-12-03 Site ID: 648324 Spill Date: 2023-02-06				
GREATER SYRACUSE LAN	1210-1214 SOUTH STAT	WSW 0 - 1/8 (0.116 mi.)	J47	356
Spill Number/Closed Date: 2200433 / 2022-04-20 Site ID: 635449 Spill Date: 2022-04-06				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/02/2025 has revealed that there are 11 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MC BRIDE SUB EPA ID:: NYD980782775	***S MCBRIDE***	***E 0 - 1/8 (0.008 mi.)***	***B5***	***67***
SYRACUSE UNIVERSITY EPA ID:: NYD982271918	***500 E TAYLOR ST***	***NE 0 - 1/8 (0.040 mi.)***	***C14***	***199***
SYRACUSE HOUSING AUT EPA ID:: NYD981873599	***516 BURT ST***	***ESE 0 - 1/8 (0.070 mi.)***	***F26***	***254***
PROJECT ORANGE EPA ID:: NYD987016136	***520 E TAYLOR ST***	***ENE 0 - 1/8 (0.101 mi.)***	***I41***	***294***
NYSDOT BIN 1031569 EPA ID:: NY0000202481	***I-81/EAST ADAMS STRE***	***ENE 0 - 1/8 (0.124 mi.)***	***I52***	***398***
NYSDOT BIN 7706370 - EPA ID:: NYR000229765	***522 RENWICK AVE***	***ESE 1/8 - 1/4 (0.154 mi.)***	***M57***	***429***
SYRACUSE UNIVERSITY EPA ID:: NYD986947505	***401 VAN BUREN ST***	***ESE 1/8 - 1/4 (0.182 mi.)***	***63***	***446***

Lower Elevation	Address	Direction / Distance	Map ID	Page
TRIPP KATIE EPA ID:: NYR000056853	***1429 S MCBRIDE ST***	***SSE 1/8 - 1/4 (0.172 mi.)***	***60***	***437***
NIAGARA MOHAWK - A N EPA ID:: NYP000976662	***900 SOUTH STATE ST***	***NNW 1/8 - 1/4 (0.243 mi.)***	***P82***	***505***
SYRACUSE CITY OF HOU EPA ID:: NY0000969188	***1306 S STATE ST***	***SSW 1/8 - 1/4 (0.245 mi.)***	***S84***	***516***
NIAGARA MOHAWK POWER EPA ID:: NYP000263590	***1309 S STATE ST MH13***	***SSW 1/8 - 1/4 (0.250 mi.)***	***S85***	***520***

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 16 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
V.A. MEDICAL CENTER	800 IRIVING AVENUE	E 1/4 - 1/2 (0.277 mi.)	W95	654
CASTLE REST NURSE HO	401 E CASTLE ST	S 1/4 - 1/2 (0.288 mi.)	X96	655
743 IRVING AVE.	743 IRVING AVE	ENE 1/4 - 1/2 (0.350 mi.)	Z108	702

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER SALVATION ARM	1105 SOUTH STATE ST	WNW 0 - 1/8 (0.096 mi.)	D35	288
SALVATION ARMY	1105 SOUTH STATE ST	WNW 0 - 1/8 (0.096 mi.)	D36	288
MONDO'S AGWAY	1127 SO. SALINA ST	SW 1/4 - 1/2 (0.268 mi.)	T86	526
MONDO'S SERVICE STAT	1133 SOUTH SALINA	SW 1/4 - 1/2 (0.271 mi.)	T90	649
ADAMS & STATE ST. GA	ADAMS & STATE STREET	NNW 1/4 - 1/2 (0.274 mi.)	V93	652
DESIMONES SERVICE ST	680 S. SALINA ST	WNW 1/4 - 1/2 (0.307 mi.)	Y100	665
SPILL NUMBER 9900884	116 EAST CASTLE ST	SSW 1/4 - 1/2 (0.375 mi.)	AC112	732
HARRISON CONVENTION	HARRISON & MONTGOMER	NNW 1/4 - 1/2 (0.397 mi.)	121	760

EXECUTIVE SUMMARY

Lower Elevation	Address	Direction / Distance	Map ID	Page
HARRISON PARKING GAR	WARREN & HARRISON ST	NW 1/4 - 1/2 (0.452 mi.)	AH127	781
ATLAS LINEN	320 WEST TAYLOR ST	W 1/4 - 1/2 (0.458 mi.)	AG129	783
500 SOUTH SALINA STR	500 SOUTH SALINA STR	NW 1/4 - 1/2 (0.476 mi.)	AI133	798
H.S.M.PACKAGING CORP	123 LARNED ST	WNW 1/4 - 1/2 (0.487 mi.)	AJ136	806
STEAM STATION-S.STAT	601 S. STATE ST	NNW 1/4 - 1/2 (0.488 mi.)	AK139	821

UST FINDER: EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

A review of the UST FINDER list, as provided by EDR, and dated 06/08/2023 has revealed that there are 5 UST FINDER sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE UNIVERSITY	500 EAST TAYLOR ST	NE 0 - 1/8 (0.040 mi.)	C15	216

Lower Elevation	Address	Direction / Distance	Map ID	Page
CENTRAL VILLAGE HOUS	302 BURT ST	WSW 0 - 1/8 (0.063 mi.)	E23	248
THE SALVATION ARMY	1105 S. STATE ST	WNW 0 - 1/8 (0.096 mi.)	D38	291
SYRACUSE POLICE DEPT	916 S STATE ST	NNW 1/8 - 1/4 (0.227 mi.)	P72	480
FIRE STATION #1	900 SOUTH STATE ST	NNW 1/8 - 1/4 (0.243 mi.)	P81	504

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 02/17/2025 has revealed that there are 6 E MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE UNIVERSITY	***500 E TAYLOR ST***	***NE 0 - 1/8 (0.040 mi.)***	***C14***	***199***
SYRACUSE HOUSING AUT	***1207 ALMOND ST***	***E 0 - 1/8 (0.104 mi.)***	***I43***	***346***
SYRACUSE UNIVERSITY	***401 VAN BUREN ST***	***ESE 1/8 - 1/4 (0.182 mi.)***	***63***	***446***

Lower Elevation	Address	Direction / Distance	Map ID	Page
DR. KING ELEMENTARY	***416 416 E RAYMOR AVE***	***SSE 1/8 - 1/4 (0.209 mi.)***	***O65***	***459***
NIAGARA MOHAWK - A N	***900 SOUTH STATE ST***	***NNW 1/8 - 1/4 (0.243 mi.)***	***P82***	***505***
NIAGARA MOHAWK POWER	***1309 S STATE ST MH13***	***SSW 1/8 - 1/4 (0.250 mi.)***	***S85***	***520***

EXECUTIVE SUMMARY

NY PFAS: DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

A review of the NY PFAS list, as provided by EDR, has revealed that there is 1 NY PFAS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EAST ADAMS REDEVELOP	***1105-1117 SOUTH STAT***	***WNW 0 - 1/8 (0.096 mi.)***	***D34***	***280***
Database: PFAS 3, Date of Government Version: 02/03/2025				

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there are 16 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MC BRIDE SUB	***S MCBRIDE***	***E 0 - 1/8 (0.008 mi.)***	***B5***	***67***
EPA ID: NYD980782775				
SU CHILLED WATER PLA	***500 E. TAYLOR STREET***	***NE 0 - 1/8 (0.040 mi.)***	***C13***	***185***
EPA ID: NYD982271918				
SYRACUSE HOUSING AUT	***516 BURT ST***	***ESE 0 - 1/8 (0.070 mi.)***	***F26***	***254***
EPA ID: NYD981873599				
PROJECT ORANGE	***520 E TAYLOR ST***	***ENE 0 - 1/8 (0.101 mi.)***	***I41***	***294***
EPA ID: NYD987016136				
SYRACUSE HOUSING AUT	***1207 ALMOND ST***	***E 0 - 1/8 (0.104 mi.)***	***I43***	***346***
EPA ID: NYR000154468				
NYSDOT BIN 1031569	***I-81/EAST ADAMS STRE***	***ENE 0 - 1/8 (0.124 mi.)***	***I52***	***398***
EPA ID: NY0000202481				
NYSDOT BIN 7706370 -	522 RENWICK AVE	ESE 1/8 - 1/4 (0.154 mi.)	M56	428
EPA ID: NYR000229765				
SYRACUSE UNIVERSITY	***401 VAN BUREN ST***	***ESE 1/8 - 1/4 (0.182 mi.)***	***63***	***446***
EPA ID: NYD986947505				

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA MOHAWK POWER	***235 OAKWOOD AVE. EXT***	***SSW 0 - 1/8 (0.059 mi.)***	***21***	***224***
EPA ID: NYD980788442				
SYRACUSE HOUSING AUT	***116-118 RADISSON COU***	***N 0 - 1/8 (0.079 mi.)***	***G27***	***264***
EPA ID: NYR000154476				
SYRACUSE HOUSING AUT	***218 NEW ST***	***NW 1/8 - 1/4 (0.166 mi.)***	***K58***	***433***
EPA ID: NYR000171124				
TRIPP KATIE	***1429 S MCBRIDE ST***	***SSE 1/8 - 1/4 (0.172 mi.)***	***60***	***437***
EPA ID: NYR000056853				
KING ELEMENTARY SCHO	***416 E RAYNOR AVE***	***SSE 1/8 - 1/4 (0.209 mi.)***	***O66***	***465***
EPA ID: NYR000240960				
FAMILY DOLLAR #5071	945 S SALINA ST	W 1/8 - 1/4 (0.222 mi.)	Q69	471

EPA ID: NYR000211730				
NIAGARA MOHAWK A NAT EPA ID: NYP000976662	900 SOUTH STATE STRE	NNW 1/8 - 1/4 (0.243 mi.)	P79	501
SYRACUSE COMMUNITY H EPA ID: NYR000199190	***930 S SALINA ST***	***W 1/8 - 1/4 (0.244 mi.)***	***Q83***	***509***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there is 1 NJ MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE UNIVERSITY EPA Id: NYD982271918	***500 E TAYLOR ST***	***NE 0 - 1/8 (0.040 mi.)***	***C14***	***199***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 3 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE HOUSING AUT Generator EPA Id: NY0000201889	BURT & MCBRIDE ST	ESE 0 - 1/8 (0.008 mi.)	B4	66
SYRACUSE HOUSING AUT Generator EPA Id: NYR000154468	1207 ALMOND STREET	E 0 - 1/8 (0.104 mi.)	I42	346

Lower Elevation	Address	Direction / Distance	Map ID	Page
SYRACUSE HOUSING AUT Generator EPA Id: NYR000171124	218 NEW STREET	NW 1/8 - 1/4 (0.166 mi.)	K59	437

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within

approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIMO - SYRACUSE - ER	300 ERIC BLVD WEST	NNW 1/2 - 1 (0.970 mi.)	142	859

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there is 1 EDR Hist Auto site within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DI PINO ANTHONY	1117 SOUTH STATE ST	W 0 - 1/8 (0.095 mi.)	H29	270

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SPARKLE CLEANERS INC	234 BURT ST	WSW 0 - 1/8 (0.109 mi.)	E45	354

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 3 records.

Site Name	Database(s)
ROTONDO WAREHOUSE	NY SHWS, NY HSWDS
SIDA PROPERTIES	NY SHWS
OLD TIP-TOP BAKERY	NY SHWS

OVERVIEW MAP - 8026569.2S



0 1/4 1/2 1 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	East Adams Redevelopment - Phase 8 Area	CLIENT:	Langan
ADDRESS:	409 Burt Street Syracuse NY 13202	CONTACT:	Lexi Haley
LAT/LONG:	43.038714 / 76.145026	INQUIRY #:	8026569.2s
		DATE:	June 23, 2025 11:34 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 8026569.2S

0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	East Adams Redevelopment - Phase 8 Area	CLIENT:	Langan
ADDRESS:	409 Burt Street Syracuse NY 13202	CONTACT:	Lexi Haley
LAT/LONG:	43.038714 / 76.145026	INQUIRY #:	8026569.2s
		DATE:	June 23, 2025 11:37 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		1	0	0	NR	NR	1
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250	1	0	0	NR	NR	NR	1
RCRA-SQG	0.250		2	2	NR	NR	NR	4
RCRA-VSQG	0.250		0	3	NR	NR	NR	3
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		0	1	0	1	NR	2
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	0	1	NR	NR	1
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		5	1	31	NR	NR	37
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		4	4	NR	NR	NR	8
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		2	0	NR	NR	NR	2
NY AST	0.250		4	1	NR	NR	NR	5
NY CBS AST	0.250		3	0	NR	NR	NR	3
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		1	0	1	NR	NR	2
NY INST CONTROL	0.500		1	0	1	NR	NR	2
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		2	2	4	NR	NR	8
NY ERP	0.500		1	0	0	NR	NR	1
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		3	6	6	NR	NR	15
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125		22	NR	NR	NR	NR	22
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		5	6	NR	NR	NR	11
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001	1	0	NR	NR	NR	NR	1
UXO	1.000		0	0	0	0	NR	0
ECHO	0.001	1	0	NR	NR	NR	NR	1
DOCKET HWC	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	0	NR	NR	NR	0
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	0.001		0	NR	NR	NR	NR	0
UST FINDER RELEASE	0.500		2	0	14	NR	NR	16
UST FINDER	0.250		3	2	NR	NR	NR	5
E MANIFEST	0.250		2	4	NR	NR	NR	6
NY PFAS	0.250		1	0	NR	NR	NR	1
NY AIRS	0.001		0	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0
NY Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY LEAD	0.001		0	NR	NR	NR	NR	0
NY MANIFEST	0.250	1	8	8	NR	NR	NR	17
RI MANIFEST	0.250		0	0	NR	NR	NR	0
NJ MANIFEST	0.250		1	0	NR	NR	NR	1
PA MANIFEST	0.250		2	1	NR	NR	NR	3
NY SPDES	0.001		0	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	0.001		0	NR	NR	NR	NR	0
NY COOLING TOWERS	0.001		0	NR	NR	NR	NR	0
NY NYC LAND USE	0.001		0	NR	NR	NR	NR	0
NY NYC OER	1.000		0	0	0	0	NR	0
NY ILI	0.500		0	0	0	NR	NR	0
NY MGP	1.000		0	0	0	0	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	1	NR	1
EDR Hist Auto	0.125		1	NR	NR	NR	NR	1
EDR Hist Cleaner	0.125		1	NR	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		4	77	41	58	2	0	182

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target
Property

SYRACUSE HOUSING AUTHORITY
409 BURT ST
SYRACUSE, NY 13202

RCRA-LQG **1000889954**
FINDS **NY0000201889**
ECHO
NY MANIFEST

Site 1 of 3 in cluster A

Actual:
404 ft.

RCRA Listings:

Date Form Received by Agency:	20100309
Handler Name:	Syracuse Housing Authority
Handler Address:	Burt St
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NY0000201889
Contact Name:	WILLIAM W GEHRKE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	315-475-6181 x4318
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Federal
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2009
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R7
Mailing Address:	BURT ST
Mailing City,State,Zip:	SYRACUSE, NY 13202
Owner Name: Syracuse Housing Authority	
Owner Type:	Federal
Operator Name: Syracuse Housing Authority	
Operator Type:	Federal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	The land is federally-owned, The site is federally-owned, The site is federally-operated
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210917
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: U213
Waste Description: Furan, Tetrahydro-(I) (Or) Tetrahydrofuran (I)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SEYMOUR ROTH EL-ROH	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Owner/Operator Indicator: Owner
Owner/Operator Name: SEYMOUR ROTH EL-ROH
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY
Legal Status: Other
Date Became Current: 19400115
Date Ended Current: Not reported
Owner/Operator Address: 516 BURT ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SEYMOUR ROTH EL-ROH
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY
Legal Status: Other
Date Became Current: 19400115
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY
Legal Status: Federal
Date Became Current: 19400204
Date Ended Current: Not reported
Owner/Operator Address: 409 BURT ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY
Legal Status: Federal
Date Became Current: 19400204
Date Ended Current: Not reported
Owner/Operator Address: 409 BURT ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100309
Handler Name: SYRACUSE HOUSING AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19990708
Handler Name: SYRACUSE HOUSING AUTH
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SYRACUSE HOUSING AUTH
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SYRACUSE HOUSING AUTH

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940406
Handler Name: SYRACUSE HOUSING AUTH
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20090618
Handler Name: SYRACUSE HOUSING AUTH
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92511
NAICS Description: Administration Of Housing Programs

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004313706

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000889954
Registry ID:	110004313706
DFR URL:	
Name:	SYRACUSE HOUSING AUTHORITY
Address:	409 BURT STREET
City,State,Zip:	SYRACUSE, NY 13202

NY MANIFEST:

EPA ID:	NY0000201889
Country:	USA
Name:	Syracuse Housing Authority
Address:	409 BURT STREET
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	409 BURT STREET
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Syracuse Housing Authority
Mailing Contact:	David Lessun
Mailing Address 1:	409 BURT ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3154756181

Manifest Data:

Document ID:	NJA1848024
Manifest Status:	Not reported
Trans1 State ID:	NYLW1771
Year:	1994
Trans2 State ID:	08690
Generator Ship Date:	09/28/1994

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Trans1 Recv Date:	09/28/1994
Trans2 Recv Date:	09/29/1994
TSD Site Recv Date:	09/30/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ILD984908202
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00556
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986980253
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2009
Trans1 Recv Date:	12/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	000634453JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Mercury
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	300
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986980253
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2009
Trans1 Recv Date:	12/23/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	000634453JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Mercury
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	200
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2009
Trans1 Recv Date:	07/10/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	002474219FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Furan, Tetrahydro-(I) (Or) Tetrahydrofuran (I)
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1100
Units:	Pounds
Number of Containers:	1
Container Type:	Wooden boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2009
Trans1 Recv Date:	07/10/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	002474219FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1000
Units:	Pounds
Number of Containers:	1

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Container Type:	Wooden boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2009
Trans1 Recv Date:	07/10/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	002474219FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1100
Units:	Pounds
Number of Containers:	1
Container Type:	Wooden boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2009

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Trans1 Recv Date:	07/10/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	002474219FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1200
Units:	Pounds
Number of Containers:	1
Container Type:	Wooden boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	NJ0000027193
Generator Ship Date:	07/10/2009
Trans1 Recv Date:	07/10/2009
Trans2 Recv Date:	07/17/2009
TSD Site Recv Date:	07/20/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000201889
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1000889954**

Manifest Tracking Number:	002474221FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	B003
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3
Units:	Kilograms
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

A2 **MCKINNEY PROPERTY** **NY ENG CONTROLS** **S108984459**
1226 SOUTH MCBRIDE STREET **NY INST CONTROL** **N/A**
< 1/8 **SYRACUSE, NY 13202** **NY ERP**
1 ft. **NY Spills**

Site 2 of 3 in cluster A

Relative: ENG CONTROLS:
Higher

Name:	MCKINNEY PROPERTY
Address:	1226 SOUTH MCBRIDE STREET
City,State,Zip:	SYRACUSE, NY 13202-
Site Code:	57334
HW Code:	E734086
Control Code:	15
Control Type:	ENG
Date Record Added:	12/04/2015
Date Rec Updated:	10/27/2022
Updated By:	GWPRISCO
Site Description:	"Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land

Actual:
408 ft.

MCKINNEY PROPERTY (Continued) **S108984459**

Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and,

MCKINNEY PROPERTY (Continued) **S108984459**

to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site

MCKINNEY PROPERTY (Continued) **S108984459**

contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2004-01-22 11:57:00
Record Upd:	2012-10-04 14:39:00
Updated By:	ldennist
Own Op:	1
Sub Type:	C01
Owner Name:	William Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	6
Sub Type:	C01
Owner Name:	Melissa Liquori
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
HW Code:	E734086
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	Petroleum Products
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Code:	Not reported
HW Code:	E734086
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	ACENAPHTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

MCKINNEY PROPERTY (Continued) **S108984459**

HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00
Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00
Updated By: JPCOOK

INST CONTROL:
Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Control Name: Ground Water Use Restriction
HW Code: E734086
Control Code: 08
Control Type: INST
Dt record added: 12/04/2015
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57334
Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from

MCKINNEY PROPERTY (Continued) **S108984459**

the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present

MCKINNEY PROPERTY (Continued) **S108984459**

at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

MCKINNEY PROPERTY (Continued) **S108984459**

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-01-22 11:57:00
Record Upd: 2012-10-04 14:39:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: William Simmons
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Melissa Liquori
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
HW Code: E734086
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00
Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00
Updated By: JPCOOK

Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Control Name: IC/EC Plan
HW Code: E734086
Control Code: 34
Control Type: INST
Dt record added: 12/04/2015
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57334
Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the

MCKINNEY PROPERTY (Continued) **S108984459**

west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their

MCKINNEY PROPERTY (Continued) **S108984459**

respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported

MCKINNEY PROPERTY (Continued) **S108984459**

Lat/Long: Not reported
Dell: False
Record Add: 2004-01-22 11:57:00
Record Upd: 2012-10-04 14:39:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: William Simmons
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Melissa Liquori
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
HW Code: E734086
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported

MCKINNEY PROPERTY (Continued) **S108984459**

HW Code: E734086
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00
Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00
Updated By: JPCOOK

Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Control Name: Landuse Restriction
HW Code: E734086
Control Code: 25
Control Type: INST
Dt record added: 12/04/2015
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57334
Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also

MCKINNEY PROPERTY (Continued) **S108984459**

contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1

MCKINNEY PROPERTY (Continued) **S108984459**

ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-01-22 11:57:00
Record Upd: 2012-10-04 14:39:00
Updated By: ldennist
Own Op: 1
Sub Type: C01

MCKINNEY PROPERTY (Continued) **S108984459**

Owner Name: William Simmons
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Melissa Liquori
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
HW Code: E734086
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Code: Not reported
HW Code: E734086
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00

MCKINNEY PROPERTY (Continued) **S108984459**

Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00
Updated By: JPCOOK

Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Control Name: Soil Management Plan
HW Code: E734086
Control Code: 14
Control Type: INST
Dt record added: 12/04/2015
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57334
Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was

MCKINNEY PROPERTY (Continued) **S108984459**

generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its

MCKINNEY PROPERTY (Continued) **S108984459**

SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-01-22 11:57:00
Record Upd: 2012-10-04 14:39:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: William Simmons
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6

MCKINNEY PROPERTY (Continued) **S108984459**

Sub Type: C01
Owner Name: Melissa Liquori
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
HW Code: E734086
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: indeno(1,2,3-cd)pyrene

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00
Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00

MCKINNEY PROPERTY (Continued) **S108984459**

Updated By: JPCOOK

Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Control Name: Monitoring Plan
HW Code: E734086
Control Code: 31
Control Type: INST
Dt record added: 12/04/2015
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57334
Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings

MCKINNEY PROPERTY (Continued) **S108984459**

were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its

MCKINNEY PROPERTY (Continued) **S108984459**

groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-01-22 11:57:00
Record Upd: 2012-10-04 14:39:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: William Simmons
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Melissa Liquori
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America

MCKINNEY PROPERTY (Continued) **S108984459**

HW Code: E734086
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00
Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00
Updated By: JPCOOK

Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Control Name: Site Management Plan

MCKINNEY PROPERTY (Continued) **S108984459**

HW Code: E734086
Control Code: 32
Control Type: INST
Dt record added: 12/04/2015
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57334
Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."
Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil

MCKINNEY PROPERTY (Continued) **S108984459**

cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil

MCKINNEY PROPERTY (Continued) **S108984459**

	Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."
Health Problem:	"People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	False
Record Add:	2004-01-22 11:57:00
Record Upd:	2012-10-04 14:39:00
Updated By:	ldennist
Own Op:	1
Sub Type:	C01
Owner Name:	William Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	6
Sub Type:	C01
Owner Name:	Melissa Liquori
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
HW Code:	E734086
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	E734086
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported

MCKINNEY PROPERTY (Continued) **S108984459**

HW Code: E734086
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: MERCURY
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00
Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00
Updated By: JPCOOK

Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Control Name: Environmental Easement
HW Code: E734086
Control Code: J
Control Type: INST
Dt record added: 12/04/2015
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57334

MCKINNEY PROPERTY (Continued) **S108984459**

Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically

MCKINNEY PROPERTY (Continued) **S108984459**

polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related

MCKINNEY PROPERTY (Continued) **S108984459**

contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: False
Record Add: 2004-01-22 11:57:00
Record Upd: 2012-10-04 14:39:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: William Simmons
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Melissa Liquori
Owner Company: Syracuse Housing Authority
Owner Address: 516 Burt Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
HW Code: E734086
Waste Type: BENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Petroleum Products

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ACENAPHTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ZINC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: MERCURY
Waste Quantity: UNKNOWN

MCKINNEY PROPERTY (Continued) **S108984459**

Waste Code: Not reported
HW Code: E734086
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: E734086
Waste Type: 1,2-dichlorobenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C302977
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-12-21 13:49:00
Record Updated: 2015-12-21 13:49:00
Updated By: JPCOOK
Crossref ID: L/P 05344 / 0902
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-11-02 10:43:00
Record Updated: 2015-11-02 10:43:00
Updated By: JPCOOK

ERP:
Name: MCKINNEY PROPERTY
Address: 1226 SOUTH MCBRIDE STREET
City,State,Zip: SYRACUSE, NY 13202-
Site Code: 57334
Program: ERP
HW Code: E734086
Site Class: C
Class N: C
SWIS: 3415
Region: 7
Town: Syracuse (c)
Acres: 0.600
Record Added: 01/22/2004
Record Updated: 02/13/2024
Updated By: GWPRISCO
Site Description: "Location: The McKinney Property site is an approximately 0.60-acre site located at 1226 McBride Street, on the northwest corner of South McBride Street and Burt Street, in an urban area of the City of

MCKINNEY PROPERTY (Continued) **S108984459**

Syracuse. Site Features: The site is developed as a gravel parking lot with a vegetated strip extending along the northern, eastern and southern site perimeter. There are no buildings on the site. It is generally flat, with a gentle slope from northwest to southeast. There is a concrete retaining wall along the north boundary of the site, which supports an elevated rail line. Current Zoning and Land Use: The majority of the site is a parking lot. It is zoned for commercial use. The surrounding parcels are used for a mix of commercial, industrial, and residential purposes. Several nearby properties are owned by the Syracuse Housing Authority (SHA), including a large residential apartment building. There are also several townhouses located south of the site, across Burt Street from the site. The site is bordered to the north by an elevated railroad line. A portion of the Syracuse University steam plant facility lies beyond the rail line to the north. The site is bordered to the south by Burt Street, with residential buildings beyond. An electrical substation is located further south. To the east, the site is bordered by South McBride Street, with the elevated rail line and the rest of the Syracuse University steam plant lying beyond. To the west, the site is bordered by a commercial property owned by SHA, with vacant lots and Oakwood Avenue beyond. Beyond Oakwood Avenue are vacant lots and two small commercial properties. Past Use of the Site: The site was previously occupied by a metal working company and a scrap metal storage/processing business. The metal working/processing operations have led to contamination of the site by metals and oils. Equipment associated with these operations also contributed to contamination, including underground storage tanks, capacitors containing dielectric fluids, an oil/water separator and hydraulic machinery. Site Geology and Hydrogeology: Unconsolidated deposits in the area have been mapped as lacustrine silt and clay. Soil encountered during the investigation consisted of several feet of fill material, underlain by the lacustrine unit, which consisted of silt and clay with lesser amounts of fine sand. The fill was generally approximately 2 feet thick, but ranged up to 9 feet thick. The fill unit consisted of fill or reworked native deposits, mixed with gravel, concrete, metal, wood and other anthropogenic materials. The lacustrine unit showed interlaminations of silt, clay and sand, showing the annual cycle of deposition (varves). It is expected the lacustrine unit is underlain by till; however, neither the till nor bedrock were encountered in any boring advanced at the site. Borings were installed to a maximum depth of 22 feet below grade. Depth to groundwater varied seasonally and ranged from 2.4 feet below grade to 9.6 feet below grade. The predominant direction of groundwater flow at the Site was determined to be south/southwest toward Onondaga Creek."

Env Problem: "Certain areas of contamination were excavated and disposed of off-site as interim remedial measures (IRMs). A one-foot clean soil cover system has been installed across the entire site. Contamination at concentrations greater than commercial use soil cleanup objectives (SCOs) remains below the cover system and is being managed under a Site Management Plan. Nature and Extent of Contamination: The primary contaminants of concern at the site are metals, including arsenic, barium, cadmium, copper, lead, and mercury; polychlorinated biphenyls (PCBs); and semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), which are a subset of SVOCs. Petroleum was also encountered in certain locations at the site, though the areas with the heaviest known petroleum contamination were

MCKINNEY PROPERTY (Continued) **S108984459**

excavated and disposed of off-site by the IRMs. Several volatile organic compounds (VOCs) were detected in soil vapor and were also detected above applicable standards, criteria or guidance values (SCGs) in soil and groundwater; however, to a lesser extent than the other contaminants of concern. No site-related contamination was identified off-site. Soil Contaminants, including metals, PAHs and, to a lesser extent, PCBs remain in soil below the cover system. These contaminants are primarily present in soil immediately below the cover system, at depths ranging from one foot to approximately three feet below grade. Mercury is present across the site at elevated concentrations, primarily in the two feet of soil immediately below the cover system (one foot to three feet below grade). It is present at concentrations up to 438 parts per million (ppm) compared to its soil cleanup objective (SCO) for the protection of public health for commercial use of 2.8 ppm. Similarly, other metals are present at elevated concentrations across the site, primarily in the two feet of soil immediately below the cover system. Arsenic; barium; cadmium; copper; and lead were detected at concentrations up to 218; 6,390; 139; 51,100; and 19,200 ppm, respectively, compared to their respective commercial use SCOs of 16; 400; 9.3; 270; and 1,000 ppm. PAHs are present across the site in the two feet of soil immediately below the cover system, generally at concentrations only slightly exceeding commercial use SCOs, though a couple locations had somewhat higher concentrations. Benzo(a)pyrene, a PAH, exceeded its commercial use SCO more frequently than the other PAHs, and is present at concentrations up to 7.2 ppm, compared to its commercial use SCO of 1 ppm. Concentrations of total PAHs in soils below the cover system range from not detected to 400.8 ppm. PCBs are present across the site in the two feet of soil immediately below the cover system at concentrations exceeding its commercial use SCO. PCBs are present in soils at concentrations up to 29 ppm, compared to its commercial use SCO of 1 ppm. Trichloroethene (TCE) is present in subsurface soil in one area of the site at concentrations up to 6.84 ppm, exceeding its SCO for the protection of groundwater of 0.47 ppm. Groundwater - Groundwater impacts by petroleum were previously noted in a well located at the upgradient edge (northwest corner) of the site. A layer of separate phase petroleum several feet thick was identified in this well. The petroleum contamination in the vicinity of this well was excavated as part of an IRM conducted in 2014. TCE was previously detected in groundwater at concentrations exceeding its groundwater standard of 5 ug/L. The most heavily contaminated soil in this vicinity was excavated and disposed of off-site as part of an IRM conducted in 2014. Groundwater monitoring shows TCE concentrations in groundwater have been reduced. Groundwater results for the rest of the site indicated relatively minor impacts to groundwater quality. The impacts noted were generally only slightly above groundwater standards and/or were not extending off-site. Soil Vapor - Several VOCs were detected in soil vapor including 1,1,1-trichloroethane (which was detected at 5.66 micrograms per cubic meter [ug/m3]); cis-1,2-dichloroethene (which was detected at 0.443 ug/m3); tetrachloroethene (which was detected at 4.96 ug/m3); and trichloroethene (which was detected at 1.37 ug/m3)."

Health Problem: "People are not drinking contaminated groundwater because the area is served by a public water supply that is not affected by site-related contamination. Contact with contaminated soil remaining at the site is unlikely unless people dig below the soil cover system and demarcation layer that exists across the entire site. Volatile

MCKINNEY PROPERTY (Continued) **S108984459**

organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because there are no on-site buildings, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition. However, the potential exists for the inhalation of site contaminants due to soil vapor intrusion for any future on-site building development and occupancy. Furthermore, environmental data available for an off-site property indicates that soil vapor intrusion is not a concern. "

SPILLS:

Name:	PRIVATE RESIDENCE
Address:	1226 SOUTH MCBRIDE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0402274 / 2004-06-04
Facility ID:	0402274
Facility Type:	ER
DER Facility ID:	168092
Site ID:	202067
DEC Region:	7
Spill Cause:	Other
Spill Class:	E6
SWIS:	3415
Spill Date:	2004-05-31
Investigator:	CXROSSI
Referred To:	Not reported
Reported to Dept:	2004-06-01
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-01
Spill Record Last Update:	2004-06-04
Spiller Name:	JOE GALLAWAY
Spiller Company:	PRIVATE RESIDENCE
Spiller Address:	1226 SOUTH MCBRIDE
Spiller Company:	001
Contact Name:	JOE GALLAWAY
Latitude:	43.0387069
Longitude:	-76.1438841
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CTR
Remarks:	A FIRE AT THIS RESIDENCE YESTERDAY, NEED DEC TO RESPOND, TO TALK ABOUT CONTAMINATION AND DEBRIS: ON SCENE RIGHT NOW: FD Called Hotline to get response on if there was a record of contamination.

Name:	FORMER SCRAP METAL FACILI
Address:	1226 SOUTH MCBRIDE
City,State,Zip:	SYRACUSE, NY

MCKINNEY PROPERTY (Continued) **S108984459**

Spill Number/Closed Date:	0712291 / 2009-02-10
Facility ID:	0712291
Facility Type:	ER
DER Facility ID:	168092
Site ID:	393888
DEC Region:	7
Spill Cause:	Other
Spill Class:	C3
SWIS:	3415
Spill Date:	2008-02-21
Investigator:	menash
Referred To:	Not reported
Reported to Dept:	2008-02-21
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-21
Spill Record Last Update:	2009-02-10
Spiller Name:	SYRACUSE HOUSING AUTHORIT
Spiller Company:	FORMER SCRAP METAL FACILI
Spiller Address:	1226 SOUTH MCBRIDE
Spiller Company:	001
Contact Name:	SYRACUSE HOUSING AUTHORIT
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Spill turned over to Enviromental Remediation(Haz Waste) ERP Site E734086. Claudia Boutot Project Manager.
Remarks:	Gauging existing monitoring wells at the site found free product in one of the wells... #MW3 northwest corner of the site. Dvirka & Bartilucci are doing the investigations and the remediation.

All Materials:

Site ID:	393888
Operable Unit ID:	1150838
Operable Unit:	01
Material ID:	2141481
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A3 **ERP SITE** **NY Spills** **S131511286**
1226 MCBRIDE ST **N/A**
< 1/8 **SYRACUSE, NY**
1 ft.

Site 3 of 3 in cluster A

Relative: Higher

Actual: 408 ft.

SPILLS:

Name:	ERP SITE
Address:	1226 MCBRIDE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2308014 / Not Reported
Facility ID:	2308014
Facility Type:	ER
DER Facility ID:	606442
Site ID:	661110
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3415
Spill Date:	2023-12-28
Investigator:	ACLOFARO
Referred To:	Not reported
Reported to Dept:	2024-01-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2024-01-04
Spill Record Last Update:	2024-01-18
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WAYNE RANDLE
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	01/04/23: Oil accumulating in a groundwater monitoring well. CNS to monitor weekly to see if this is a trend or if oil was intentionally dumped in well. 8ft of product in well when sampled on 12/28 during 15-month sampling and 2ft when sampled yesterday. Well is 2 PVC. (CBK)
Remarks:	DEC REP Andrew Loforow lead. Sampling groundwater and found free product in well. Approx 6 courts of oil removed.

All Materials:

Site ID:	661110
Operable Unit ID:	1407916
Operable Unit:	01
Material ID:	2425374
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum

ERP SITE (Continued) **S131511286**

Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Groundwater
Oxygenate:	Not reported

B4 **SYRACUSE HOUSING AUTHORITY** **PA MANIFEST** **S111771520**
ESE **BURT & MCBRIDE ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.008 mi.
43 ft. **Site 1 of 2 in cluster B**

Relative:
Higher

Actual:
408 ft.

PA MANIFEST:

Name:	SYRACUSE HOUSING AUTHORITY
Address:	BURT & MCBRIDE ST
City,State,Zip:	SYRACUSE, NY 13202
Year:	2009
Manifest Number:	000634453JJK
Manifest Type:	T
Generator EPA ID:	NY0000201889
Generator Date:	12/23/2009
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	DM
Waste Quantity:	300
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported

Year:	2009
Manifest Number:	000634453JJK
Manifest Type:	T
Generator EPA ID:	NY0000201889
Generator Date:	12/23/2009
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **S111771520**

Page Number:	1
Line Number:	2
Waste Number:	D009
Container Number:	1
Container Type:	DM
Waste Quantity:	200
Unit:	P
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported

B5 **MC BRIDE SUB** **RCRA NonGen / NLR** **1000164721**
East **S MCBRIDE** **NY MANIFEST** **NYD980782775**
< 1/8 **SYRACUSE, NY 13202**
0.008 mi.
44 ft. **Site 2 of 2 in cluster B**

Relative: **Higher**
Actual: **409 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Mc Bride Sub
Handler Address:		S Mcbride
Handler City,State,Zip:		SYRACUSE, NY 13202
EPA ID:		NYD980782775
Contact Name:		Not reported
Contact Address:		ERIE BLVD W
Contact City,State,Zip:		SYRACUSE, NY 13202
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		ERIE BLVD W
Mailing City,State,Zip:		SYRACUSE, NY 13202
Owner Name:	Ownername	
Owner Type:		Private
Operator Name:	Ownername	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No

MC BRIDE SUB (Continued) **1000164721**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	X002
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

MC BRIDE SUB (Continued) **1000164721**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MC BRIDE SUB
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MC BRIDE SUB
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MC BRIDE SUB
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

MC BRIDE SUB (Continued) **1000164721**

Receive Date: 19841120
Handler Name: MC BRIDE SUB
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYD980782775
Country: USA
Name: Niagara Mohawk Power Corporation
Address: S MCBRIDE
Address 2: Not reported
City,State,Zip: SYRACUSE, NY 13202
Zip 4: Not reported
Location Address 1: MC BRIDE SUBSTATION
Location Address 2: Not reported
Location City,State,Zip: SYRACUSE, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Niagara Mohawk Power Corporation
Mailing Contact: Niagara Mohawk Power Corporation
Mailing Address 1: 300 ERIE BLVD WEST
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13202
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154282351

Manifest Data:
Document ID: NYA3713005
Manifest Status: C - Completed copy
Trans1 State ID: 35218GN
Year: 1986
Trans2 State ID: 7A-010

MC BRIDE SUB (Continued) **1000164721**

Generator Ship Date:	860617
Trans1 Recv Date:	860617
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860617
Part A Recv Date:	860625
Part B Recv Date:	860625
Generator EPA ID:	NYD980782775
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980647952
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B003
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02400
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NYB1741680
Manifest Status:	Not reported
Trans1 State ID:	CR6700(NY
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	08/28/1990
Trans1 Recv Date:	08/28/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/28/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980782775
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980647952
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

MC BRIDE SUB (Continued) **1000164721**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00538
Units:	Kilograms
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	00.89

Document ID:	NYB1741770
Manifest Status:	Not reported
Trans1 State ID:	980C50OH
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	12/04/1990
Trans1 Recv Date:	12/04/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/05/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980782775
Trans1 EPA ID:	OHD981954571
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD981100969
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	05381
Units:	Kilograms
Number of Containers:	001

MC BRIDE SUB (Continued) **1000164721**

Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	00.89

C6 **STEAM PLANT** **NY LTANKS** **S104278476**
NE **MCBRIDE ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.035 mi.
183 ft. **Site 1 of 15 in cluster C**

Relative: **Higher**

Actual: **407 ft.**

LTANKS:

Name:	STEAM PLANT
Address:	MCBRIDE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9908800 / 1999-11-23
Facility ID:	9908800
Site ID:	259520
Spill Date:	1999-10-20
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1999-10-20
CID:	257
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-20
Spill Record Last Update:	1999-11-23
Spiller Name:	JIM MCCUMBER
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	285 AINSLEY DR
Spiller County:	001
Spiller Contact:	PAT STOCK
Spiller Phone:	(315) 443-4132
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	212253
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	old contamination from a old tank that was closed 10yrs ago

All Materials:

Site ID:	259520
Operable Unit ID:	1087484
Operable Unit:	01
Material ID:	297899
Material Code:	0001A
Material Name:	#2 fuel oil

STEAM PLANT (Continued) **S104278476**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

C7 **SYRACUSE UNIVERSITY STEAM STATION** **NY CBS AST** **U003077914**
NE **500 E. TAYLOR STREET** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.040 mi.
210 ft. **Site 2 of 15 in cluster C**

Relative: **Higher**

Actual: **406 ft.**

CBS AST:

CBS Number:	7-000152
ICS Number:	7-700483
PBS Number:	7-180602
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	G
Telephone:	(315) 474-8230
Facility Town:	SYRACUSE (C)
Region:	STATE
Expiration Date:	07/18/2003
Total Capacity of All Active Tanks(gal):	1500
Operator:	JOSEPH BURROUGHS
Emergency Contact:	JOSEPH BURROUGHS
Emergency Phone:	(315) 474-8230
Owner Name:	SYRACUSE UNIVERSITY
Owner Address:	SKYTOP ROAD
Owner City,St,Zip:	SYRACUSE, NY 13244-6400
Owner Telephone:	(315) 443-4188
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	PROJECT ORANGE ASSOCIATES, L.P.
Mail Contact Addr:	507 PLUM ST
Mail Contact Addr2:	NIAGARA MOHAWK ENERGY MARKETING
Mail Contact Contact:	JAMES CIFARATTA
Mail Contact City,St,Zip:	SYRACUSE, NY 13204
Mail Phone:	(315) 460-3379

Tank Id:	004
CAS Number:	75718
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/70
Tank Closed:	00/00
Capacity (Gal):	1000
Chemical:	Methane, dichlorodifluoro-
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	00
Tank Error Status:	No Missing Data

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U003077914**

Date Entered:	03/16/1992
Certified Date:	06/18/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Unknown
Pipe Internal:	None
Pipe External:	01
Pipe Flag:	01
Leak Detection:	01
Overfill Protection:	04
Haz Percent:	99
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/18/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/30/2001

Tank Id:	001
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	06/72
Tank Closed:	Not reported
Capacity (Gal):	1500
Chemical:	Sulfuric acid
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	01
Tank Error Status:	No Missing Data
Date Entered:	07/18/1989
Certified Date:	06/18/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	01
Pipe Flag:	01
Leak Detection:	00
Overfill Protection:	04
Haz Percent:	93
Last Test:	Not reported

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U003077914**

Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/18/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/30/2001

Tank Id:	003
CAS Number:	60004
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	02/91
Tank Closed:	00/00
Capacity (Gal):	1000
Chemical:	Ethylenediamine tetraacetic acid (EDTA)
Tank Location:	Indoors, Belowground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	01
Tank Error Status:	No Missing Data
Date Entered:	04/03/1991
Certified Date:	06/18/2001
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	00
Overfill Protection:	04
Haz Percent:	30
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/18/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/30/2001

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U003077914**

Tank Id:	002
CAS Number:	60004
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	02/91
Tank Closed:	00/00
Capacity (Gal):	1000
Chemical:	Ethylenediamine tetraacetic acid (EDTA)
Tank Location:	Indoors, Belowground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	1
Tank Secret:	False
Tank Secondary Containment:	01
Tank Error Status:	No Missing Data
Date Entered:	04/03/1991
Certified Date:	06/18/2001
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	00
Overfill Protection:	04
Haz Percent:	30
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/18/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/30/2001

C8 **STEAM STATION** **NY Spills** **S123660417**
NE **500 EAST TAYLOR ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.040 mi.
210 ft. **Site 3 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

SPILLS:

Name:	STEAM STATION
Address:	500 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1810736 / 2019-03-26
Facility ID:	1810736
Facility Type:	ER
DER Facility ID:	424153
Site ID:	581643
DEC Region:	7

STEAM STATION (Continued) **S123660417**

Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3415
Spill Date:	2019-01-23
Investigator:	DJLASALL
Referred To:	Not reported
Reported to Dept:	2019-01-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-01-23
Spill Record Last Update:	2019-03-26
Spiller Name:	Not reported
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHAD AMES
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	cleanup completed by RP.
Remarks:	some sprayed outside storage area, most contained. Spill onto crushed stone and snow. clean up in progress.

All Materials:

Site ID:	581643
Operable Unit ID:	1329333
Operable Unit:	01
Material ID:	2338393
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

C9 **SU CHILLED WATER PLANT** **NY AST** **S100346926**
NE **500 E. TAYLOR STREET** **NY CBS AST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.040 mi.
210 ft. **Site 4 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

AST:

Name:	SU CHILLED WATER PLANT
Address:	500 E. TAYLOR STREET
City,State,Zip:	SYRACUSE, NY 13202
Region:	STATE
DEC Region:	7

SU CHILLED WATER PLANT (Continued) **S100346926**

Site Status: Unregulated/Closed
Facility Id: 7-000281
Program Type: CBS
UTM X: 406826.97609
UTM Y: 4765824.13209
Expiration Date: N/A
Site Type: School

Tank Info:

Tank Number: 002
Tank Id: 192050
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Stainless Steel Alloy
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1996
Capacity Gallons: 1100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 11/01/1999
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: 003
Tank Id: 192051
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Plastic
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1996
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 11/01/1999
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

CBS AST:

CBS Number: 7-000281
ICS Number: Not reported
PBS Number: 7-180602
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: G
Telephone: (315) 443-4188
Facility Town: SYRACUSE (C)

SU CHILLED WATER PLANT (Continued) **S100346926**

Region:	STATE
Expiration Date:	10/09/2000
Total Capacity of All Active Tanks(gal):	0
Operator:	SYRACUSE UNIVERSITY
Emergency Contact:	TOM REDDINGER
Emergency Phone:	(315) 443-4188
Owner Name:	SYRACUSE UNIVERSITY
Owner Address:	SKYTOP ROAD
Owner City,St,Zip:	SYRACUSE, NY 13244
Owner Telephone:	(315) 443-8230
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	SYRACUSE UNIVERSITY
Mail Contact Addr:	EHO O29 LYMAN HALL
Mail Contact Addr2:	100 COLLEGE PLACE
Mail Contact Contact:	JAMES MCCUMBER
Mail Contact City,St,Zip:	SYRACUSE, NY 13244
Mail Phone:	(315) 443-4132

Tank Id:	003
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	0
Install Date:	10/96
Tank Closed:	11/99
Capacity (Gal):	500
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	01
Tank Error Status:	No Missing Data
Date Entered:	10/09/1996
Certified Date:	08/31/1998
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	01
Overfill Protection:	04
Haz Percent:	12
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False

SU CHILLED WATER PLANT (Continued) **S100346926**

Fiscal Amt for Registration Fee Correct: True
Renewal Has Been Printed for Facility: True
Pre-Printed Renewal App Last Printed: 07/05/2000

Tank Id:	002
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	0
Install Date:	10/96
Tank Closed:	11/99
Capacity (Gal):	1100
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Stainless steel alloy
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	01
Tank Error Status:	No Missing Data
Date Entered:	10/09/1996
Certified Date:	08/31/1998
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	None,None
Pipe Location:	None
Pipe Type:	Steel/Iron
Pipe Internal:	Other
Pipe External:	00
Pipe Flag:	00
Leak Detection:	01
Overfill Protection:	02
Haz Percent:	93
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	07/05/2000

C10 **SYRACUSE UNIV STEAM STATION** **NY Spills** **S117974012**
NE **500 EAST TAYLOR ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.040 mi.
210 ft. **Site 5 of 15 in cluster C**

Relative: SPILLS:
Higher

Name:	SYRACUSE UNIV STEAM STATION
Address:	500 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	1502394 / 2016-04-08

Actual:
406 ft.

SYRACUSE UNIV STEAM STATION (Continued) **S117974012**

Facility ID:	1502394
Facility Type:	ER
DER Facility ID:	463342
Site ID:	508657
DEC Region:	7
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	3415
Spill Date:	2015-06-03
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2015-06-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	2016-04-08
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-06-03
Spill Record Last Update:	2016-04-08
Spiller Name:	BECKY PONZA
Spiller Company:	SYRACUSE UNIV STEAM STATION
Spiller Address:	500 EAST TAYLOR ST
Spiller Company:	999
Contact Name:	BECKY PONZA
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	NO ACTIVE CBS REGISTRATION AT THIS FACILITY AND MATERIAL SPILLED IS NOT STORED IN BULK AT THIS FACILITY. THEREFORE HAZ SPILL MUNI REPORTING NOT NECESSARY. SOIL AND ASPHALT PARKING LOT CLEANED BY SU PERSONNEL. SMALL AMOUNT OF MATERIAL SPILLED TO GRAVEL ON LOT NEXT DOOR THAT SU EXCAVATED AND DISPOSED OF ALSO. 7/22/2015 - Disposal documentation requested. KCKemp 4/8/2016 - No disposal documentation received. Spill closed as not meeting standards due to lack of disposal documentation. KCKemp
Remarks:	mixture was being pumped out of drum, loss to soil. C/u pending

All Materials:

Site ID:	508657
Operable Unit ID:	1257965
Operable Unit:	01
Material ID:	2261031
Material Code:	0039A
Material Name:	sulfuric acid
Case No.:	07664939
Material FA:	Hazardous Material
Quantity:	15.00
Units:	G
Recovered:	15.00
Resource Affected:	Soil, Impervious Surface
Oxygenate:	Not reported

SYRACUSE UNIV STEAM STATION (Continued) **S117974012**

Site ID:	508657
Operable Unit ID:	1257965
Operable Unit:	01
Material ID:	2261032
Material Code:	0110A
Material Name:	phosphoric acid
Case No.:	07664382
Material FA:	Hazardous Material
Quantity:	15.00
Units:	G
Recovered:	15.00
Resource Affected:	Soil, Impervious Surface
Oxygenate:	Not reported

C11 **SYRACUSE UNIVERSITY STEAM STATION** **NY UST U004148320**
NE **500 EAST TAYLOR ST** **NY AST N/A**
< 1/8 **SYRACUSE, NY 13202**
0.040 mi.
210 ft. **Site 6 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

UST:

Name:	SYRACUSE UNIVERSITY STEAM STATION
Address:	500 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-180602 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	06/18/2027
UTM X:	406857.02521
UTM Y:	4765814.73916
Site Type:	School

Affiliation Records:

Site Id:	44931
Affiliation Type:	Facility Owner
Company Name:	SYRACUSE UNIVERSITY
Contact Type:	DIRECTOR EHSS
Contact Name:	REBECCA J PONZA
Address1:	CROUSE-HINDS HALL - 900 SOUTH CROUSE AVE
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13244-2130
Country Code:	001
Phone:	(315) 443-4132
EMail:	ehss@syr.edu
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2018-12-21

Site Id:	44931
Affiliation Type:	Facility Operator
Company Name:	SYRACUSE UNIVERSITY STEAM STATION
Contact Type:	Not reported
Contact Name:	NATHAN PRIOR - CENTRIO ENERGY
Address1:	Not reported

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 443-5105
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2022-03-15

Site Id:	44931
Affiliation Type:	Mail Contact
Company Name:	SYRACUSE UNIVERSITY
Contact Type:	Not reported
Contact Name:	REBECCA J PONZA
Address1:	ENVIRONMENTAL HEALTH & SAFETY SERVICES
Address2:	029 LYMAN HALL, 100 COLLEGE PL
City:	SYRACUSE
State:	NY
Zip Code:	13244-1270
Country Code:	001
Phone:	(315) 443-9133
EMail:	EHSS@SYR.EDU
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2020-10-02

Site Id:	44931
Affiliation Type:	Emergency Contact
Company Name:	SYRACUSE UNIVERSITY
Contact Type:	Not reported
Contact Name:	SU PUBLIC SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 443-2224
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2013-07-12

Tank Info:

Tank Number:	001
Tank ID:	129267
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	30000
Install Date:	01/01/1963
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 01
Date Test: 08/01/1985
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 002
Tank ID: 129268
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 30000
Install Date: 01/01/1963
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 01
Date Test: 08/01/1985
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
I04 - Overfill - Product Level Gauge (A/G)

Tank Number: 003
Tank ID: 129269
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

Capacity Gallons: 15000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 005
Tank ID: 129270
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 30000
Install Date: 08/01/1989
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
B09 - Tank External Protection - Urethane
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
B02 - Tank External Protection - Original Sacrificial Anode
F05 - Pipe External Protection - Jacketed

Tank Number:	006
Tank ID:	129271
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	30000
Install Date:	08/01/1989
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
J02 - Dispenser - Suction Dispenser
B09 - Tank External Protection - Urethane
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A00 - Tank Internal Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
F05 - Pipe External Protection - Jacketed

Tank Number:	007
Tank ID:	129272
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	30000
Install Date:	08/01/1989
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
B09 - Tank External Protection - Urethane
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
B02 - Tank External Protection - Original Sacrificial Anode
F05 - Pipe External Protection - Jacketed

Tank Number: 008
Tank ID: 129273
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 30000
Install Date: 08/01/1989
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
B09 - Tank External Protection - Urethane
C03 - Pipe Location - Aboveground/Underground Combination
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
A00 - Tank Internal Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
B02 - Tank External Protection - Original Sacrificial Anode
F05 - Pipe External Protection - Jacketed

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

AST:

Name:	SYRACUSE UNIVERSITY STEAM STATION
Address:	500 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY 13202
Region:	STATE
DEC Region:	7
Site Status:	Active
Facility Id:	7-180602
Program Type:	PBS
UTM X:	406857.02521
UTM Y:	4765814.73916
Expiration Date:	06/18/2027
Site Type:	School

Affiliation Records:

Site Id:	44931
Affiliation Type:	Facility Owner
Company Name:	SYRACUSE UNIVERSITY
Contact Type:	DIRECTOR EHSS
Contact Name:	REBECCA J PONZA
Address1:	CROUSE-HINDS HALL - 900 SOUTH CROUSE AVE
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13244-2130
Country Code:	001
Phone:	(315) 443-4132
EMail:	ehss@syr.edu
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2018-12-21

Site Id:	44931
Affiliation Type:	Facility Operator
Company Name:	SYRACUSE UNIVERSITY STEAM STATION
Contact Type:	Not reported
Contact Name:	NATHAN PRIOR - CENTRIO ENERGY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 443-5105
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2022-03-15

Site Id:	44931
Affiliation Type:	Mail Contact
Company Name:	SYRACUSE UNIVERSITY
Contact Type:	Not reported
Contact Name:	REBECCA J PONZA
Address1:	ENVIRONMENTAL HEALTH & SAFETY SERVICES
Address2:	029 LYMAN HALL, 100 COLLEGE PL
City:	SYRACUSE

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

State:	NY
Zip Code:	13244-1270
Country Code:	001
Phone:	(315) 443-9133
EMail:	EHSS@SYR.EDU
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2020-10-02

Site Id:	44931
Affiliation Type:	Emergency Contact
Company Name:	SYRACUSE UNIVERSITY
Contact Type:	Not reported
Contact Name:	SU PUBLIC SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 443-2224
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2013-07-12

Tank Info:

Tank Number:	009
Tank Id:	129274
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
G01 - Tank Secondary Containment - Diking (Aboveground)
K00 - Spill Prevention - None
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I05 - Overfill - Vent Whistle
E99 - Piping Secondary Containment - Other
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1990
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported

SYRACUSE UNIVERSITY STEAM STATION (Continued) **U004148320**

Next Test Date:	Not reported
Date Tank Closed:	02/25/2019
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	010
Tank Id:	214870
Material Code:	0012
Common Name of Substance:	Kerosene [#1 Fuel Oil] (On-Site Consumption)

Equipment Records:

J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I01 - Overfill - Float Vent Valve
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	12/08/2006
Capacity Gallons:	300
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/22/2009
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	kerosene [#1 fuel oil] (on-site consumption)

C12 **SYRACUSE UNIVERSITY - STEAM STATION** **NY LTANKS** **S111258241**
NE **500 E TAYLOR ST** **NY Spills** **N/A**
< 1/8 **SYRACUSE, NY 13244** **NY AIRS**
0.040 mi.
210 ft. **Site 7 of 15 in cluster C**

Relative: **Higher**
Actual: **406 ft.**

LTANKS:

Name:	SYR. U. STEAM STATION
Address:	500 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8605131 / 1988-01-15
Facility ID:	8605131
Site ID:	229011
Spill Date:	1986-11-11
Spill Cause:	Tank Test Failure

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1988-01-15
SWIS:	3415
Investigator:	WATKINS
Referred To:	Not reported
Reported to Dept:	1986-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1986-11-25
Spill Record Last Update:	1988-02-10
Spiller Name:	Not reported
Spiller Company:	SYRACUSE U. STEAM STATION
Spiller Address:	500 E. TAYLER ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	267351
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was AW / / : LEAK ON TOP OF TANK. WILL ABANDON TANK BY END OF YR.WILL SEND LETTER WHEN THE WORK BEGINS.
Remarks:	ATLANTIC TESTING DID TANK TEST. LOSING 2 IN MINUTES. ALSO SEE SPILL #86-5148. DUPLICATION.

All Materials:

Site ID:	229011
Operable Unit ID:	902093
Operable Unit:	01
Material ID:	474334
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	SYRACUSE U. STEAM STATION
Address:	500 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8605148 / 1988-01-15
Facility ID:	8605148
Site ID:	229012
Spill Date:	1986-11-11
Spill Cause:	Tank Test Failure

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1988-01-15
SWIS:	3415
Investigator:	WATKINS
Referred To:	Not reported
Reported to Dept:	1986-11-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1986-11-25
Spill Record Last Update:	1988-02-10
Spiller Name:	Not reported
Spiller Company:	SYRACUSE UNIV. STEAM STA.
Spiller Address:	500 E. TAYLER ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	267351
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was AW
Remarks:	1000 GAL. TANK. FAILURE RATE .8 GALS. PER HOUR. TANK 55 YEARS OLD. SEE ALSO SPILL #86-5131. DUPLICATION.

All Materials:

Site ID:	229012
Operable Unit ID:	902111
Operable Unit:	01
Material ID:	474349
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	SYRACUSE UNIVERSITY CHILLED WATER PLANT
Address:	500 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0407665 / 2004-10-13
Facility ID:	0407665
Facility Type:	ER
DER Facility ID:	267351
Site ID:	332190

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	2004-10-11
Investigator:	BFMATTHE
Referred To:	Not reported
Reported to Dept:	2004-10-11
CID:	72
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-12
Spill Record Last Update:	2004-11-22
Spiller Name:	JIM MCCUMBER
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JIM MCCUMBER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	SPOKE TO JIM MCCUMBER THEY WOULD LIKE TO NEUTRALIZE AND CLEAN UP. SOME OF SPILL WENT ONTO STATE PROPERTY AND WANTED TO VERIFY IT WAS OK TO ENTER PROPERTY. SPOKE TO DICK BRAZELL AND HE AUTHORIZED. CLEANUP COMPLETE.
Remarks:	Punctured polydrum caused about 20 gallons of sodium hypoclorite (12%) to spill onto asphalt and stone driving area. Spill contained, also went onto adjacent p

All Materials:

Site ID:	332190
Operable Unit ID:	1094447
Operable Unit:	01
Material ID:	574553
Material Code:	0124A
Material Name:	sodium hypochlorite
Case No.:	07681529
Material FA:	Hazardous Material
Quantity:	20.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SYRACUSE U STEAM STATION
Address:	500 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8910992 / 1990-07-09
Facility ID:	8910992
Facility Type:	ER

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

DER Facility ID:	267351
Site ID:	161895
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3415
Spill Date:	1990-02-17
Investigator:	HDWARNER
Referred To:	Not reported
Reported to Dept:	1990-02-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1990-02-19
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-03-07
Spill Record Last Update:	1995-03-06
Spiller Name:	Not reported
Spiller Company:	SYRACUSE UNIV
Spiller Address:	500 E TAYLOR
Spiller Company:	001
Contact Name:	Not reported
Latitude:	43.0394104
Longitude:	-76.1437744
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was HW 07/09/90: VENT LINE LEAKED ON NEWLY INSTALLED UNDERGROUND TANKS. INTERFACE CLEANED UP SMALL AMOUNT OF CONTAMINATED SOIL AND DISPOSED.
Remarks:	VENT LINE RUPTURED.STEAM PALNT PERSONNEL CLEAN UP.

All Materials:

Site ID:	161895
Operable Unit ID:	937992
Operable Unit:	01
Material ID:	440539
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SYRACUSE UNVI/ STEAM STATION
Address:	500 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1206833 / 2012-12-04
Facility ID:	1206833
Facility Type:	ER

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

DER Facility ID:	424153
Site ID:	469851
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3415
Spill Date:	2012-10-11
Investigator:	MJROMOCK
Referred To:	Not reported
Reported to Dept:	2012-10-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-10-11
Spill Record Last Update:	2012-12-04
Spiller Name:	BECKY PONZA
Spiller Company:	SYRACUSE UNVI
Spiller Address:	500 EAST TAYLOR ST
Spiller Company:	999
Contact Name:	BECKY PONZA
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	10/11/2012 - Repairs being done to underground storage tanks. Groundwater being removed from excavtion to effect repairs. 10/25/2012 - Spoke w/ B. Ponza at SU. Contaminated water is being stored on site in frac tank. Water being sampled prior to discharge to sanitary sewer. 11/19/2012 - Rec'd e-mail documenting recent activities regarding GW discharge to Onondaga County sewer. 12/4/2012 - Called B.Ponza at SU. Repairs to tank monitoring system completed.
Remarks:	sheen observed during excavation,tanks present, unk cause, c/u and investigation ongoing

All Materials:

Site ID:	469851
Operable Unit ID:	1219737
Operable Unit:	01
Material ID:	2218270
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Groundwater
Oxygenate:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

AIRS:

Name:	SYRACUSE UNIVERSITY - STEAM STATION
Address:	500 E TAYLOR ST
City,State,Zip:	SYRACUSE, NY 13244
DECID:	7311500204
Process ID:	Not reported
Latitude:	43.039272869
Longitude:	76.143121261
FIPS Code:	Not reported
Auth Type Code:	ATV
Permit Status:	Expired
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	02/03/2012
Expired Date:	02/02/2017
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Issued
Auth Status Code:	Not reported
Emissions:	Not reported
Issue date:	06/22/2021
Expired Date:	06/21/2026
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

AIRS Detail:

DECID:	7311500204
Facility Name:	SYRACUSE UNIVERSITY - STEAM STATION
Auth Type:	ATV
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported
Contaminant:	VOC
Amount(Lbs/Yr):	Not reported
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	Not reported
CAS #:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: Not reported
CAS #: Not reported
Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: Not reported
Contaminant: UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: VOC
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PARTICULATES
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: PM-10
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: TOTAL HAP
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: Not reported
CAS #: Not reported
Contaminant: LEAD
Amount(Lbs/Yr): Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 0.00450768

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 0.00676152

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 6.1168799999999999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 7.1363600000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 25538

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 7.3912300000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 3.4141200000000001E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.220108

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.031444

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.1081138

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 0.17185529999999999

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 8.5353000000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 512.11800000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 458.76600000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.53454800000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.95788200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 654.37300000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 455.21600000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 3.3807599999999998E-4

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2016
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 4.8366700000000004E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 3.3807599999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 4.55938

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 94.331999999999994

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 170.70599999999999

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year:	2016
CAS #:	007446095
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	152.922
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440484
Contaminant:	COBALT
Amount(Lbs/Yr):	0.01320648
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	13206.48
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000205992
Contaminant:	BENZO[B]FLUORANTHENE
Amount(Lbs/Yr):	2.8299599999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000207089
Contaminant:	BENZO[K]FLUORANTHENE
Amount(Lbs/Yr):	2.8299599999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000207089
Contaminant:	BENZO[K]FLUORANTHENE
Amount(Lbs/Yr):	5.1211799999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	739.726
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	507.11399999999998
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 18866400

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 535.22699999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 450.76799999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.33016200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 361.60599999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 1.8866400000000001E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 2162.2759999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 19725

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 139.40989999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.30990299999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.13363700000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.24183350000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.33016200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 1.251844

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 1.1214280000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	0.00188664
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	0.14225499999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	5.9743600000000001E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	7.3972599999999999E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	6.6266199999999997E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	3.7732800000000002E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	0.15547069999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	662.66200000000003
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000129000
Contaminant:	PYRENE
Amount(Lbs/Yr):	0.00140865

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.59163299999999996

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 21.129750000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 6.8282400000000002E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 3.0584399999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 2.6727399999999998E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 4.3327900000000004E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 0.000440216

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 345.88400000000001

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2016
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 138.04769999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 8.1701700000000006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.31296099999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.35681800000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.02366532

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 4.0877200000000002E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.28035700000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.69176800000000005

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year:	2016
CAS #:	007440393
Contaminant:	BARIUM
Amount(Lbs/Yr):	1.2396119999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	0.14086499999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	0.1070574
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	23665.32
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	6.1168799999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	9.5904199999999995E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000205992
Contaminant:	BENZO[B]FLUORANTHENE
Amount(Lbs/Yr):	5.1211799999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	408.77199999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 1.4225500000000001E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 647.97900000000004

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 586.20100000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 487.38200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 881.98099999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 19.11525

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 0.00478941

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 0.00377328

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.305844

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 1.8866400000000001E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 7.8884400000000003E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 24957

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 6.1168799999999999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.2394705

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440508
Contaminant: COPPER

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	0.21663950000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440020
Contaminant:	NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr):	0.59163299999999996
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	7.8609999999999999E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	9.6850599999999995E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	7.3249800000000004E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439987
Contaminant:	MOLYBDENUM
Amount(Lbs/Yr):	0.31296099999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	23898.84
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	21409.080000000002
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000206440
Contaminant:	FLUORANTHENE
Amount(Lbs/Yr):	0.00084519

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 6.8282399999999995E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 732.49800000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 790.09699999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 2162.2759999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 19725

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 139.40989999999999

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2016
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.30990299999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.13363700000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.24183350000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.33016200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 1.251844

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 1.1214280000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 0.00188664

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.14225499999999999

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year:	2016
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	5.9743600000000001E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	7.3972599999999999E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	6.6266199999999997E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	3.7732800000000002E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	0.15547069999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	662.66200000000003
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000129000
Contaminant:	PYRENE
Amount(Lbs/Yr):	0.00140865
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	0.59163299999999996
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 21.129750000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 6.8282400000000002E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 3.0584399999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 2.6727399999999998E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 4.3327900000000004E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 0.000440216

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 345.88400000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 138.04769999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440666

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: ZINC
Amount(Lbs/Yr): 8.1701700000000006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.31296099999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.35681800000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.02366532

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 4.0877200000000002E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.28035700000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.69176800000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 1.2396119999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439921
Contaminant: LEAD

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	0.14086499999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	0.1070574
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	23665.32
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	6.1168799999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	9.5904199999999995E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000205992
Contaminant:	BENZO[B]FLUORANTHENE
Amount(Lbs/Yr):	5.1211799999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	408.77199999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000129000
Contaminant:	PYRENE
Amount(Lbs/Yr):	1.4225500000000001E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000074828
Contaminant:	METHANE
Amount(Lbs/Yr):	647.97900000000004

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 586.20100000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 487.38200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 881.98099999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 19.11525

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 0.00478941

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 0.00377328

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.305844

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date:	Not reported
Year:	2016
CAS #:	000191242
Contaminant:	BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr):	1.8866400000000001E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000056495
Contaminant:	3-METHYLCHOLANTHRENE
Amount(Lbs/Yr):	5.0711400000000002E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000086737
Contaminant:	FLUORENE
Amount(Lbs/Yr):	7.8884400000000003E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	0NY210000
Contaminant:	OXIDES OF NITROGEN
Amount(Lbs/Yr):	24957
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	6.1168799999999999E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	0.2394705
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	0.21663950000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440020
Contaminant:	NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr):	0.59163299999999996
Issue Date:	Not reported
Expiration Date:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: 2016
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 7.8609999999999999E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 9.6850599999999995E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 7.3249800000000004E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.31296099999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 23898.84

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 21409.080000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 6.8282399999999995E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 732.49800000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	790.09699999999998
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000083329
Contaminant:	ACENAPHTHENE
Amount(Lbs/Yr):	5.1211799999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000206440
Contaminant:	FLUORANTHENE
Amount(Lbs/Yr):	0.00084519
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000050000
Contaminant:	FORMALDEHYDE
Amount(Lbs/Yr):	11.791499999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000050000
Contaminant:	FORMALDEHYDE
Amount(Lbs/Yr):	21.338249999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	619.80600000000004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	77.037800000000004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	124.88630000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007782492

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: SELENIUM
Amount(Lbs/Yr): 0.00377328

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 0.00676152

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.17294200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.28035700000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.398314

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.39442199999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.36160599999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.30990299999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	0.59747099999999997
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440382
Contaminant:	ARSENIC
Amount(Lbs/Yr):	5.0973999999999998E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000218019
Contaminant:	CHRYSENE
Amount(Lbs/Yr):	5.0711400000000002E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000205992
Contaminant:	BENZO[B]FLUORANTHENE
Amount(Lbs/Yr):	4.5876599999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000206440
Contaminant:	FLUORANTHENE
Amount(Lbs/Yr):	4.7165999999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000207089
Contaminant:	BENZO[K]FLUORANTHENE
Amount(Lbs/Yr):	5.0711400000000002E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000108883
Contaminant:	TOLUENE
Amount(Lbs/Yr):	0.86655800000000005
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000124389
Contaminant:	CARBON DIOXIDE
Amount(Lbs/Yr):	33807600
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000129000
Contaminant:	PYRENE
Amount(Lbs/Yr):	7.8609999999999997E-4

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	330.16199999999998
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	597.471
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	591.63300000000004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000050328
Contaminant:	BENZO(A)PYRENE
Amount(Lbs/Yr):	3.0584399999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000053703
Contaminant:	DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr):	3.0584399999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	0.59747099999999997
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	0.53522700000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	0NY075025
Contaminant:	PM 2.5
Amount(Lbs/Yr):	2141.1480000000001
Issue Date:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date:	Not reported
Year:	2016
CAS #:	0NY075025
Contaminant:	PM 2.5
Amount(Lbs/Yr):	1937.0119999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	6.8282400000000002E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	625.92200000000003
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	560.71400000000006
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440484
Contaminant:	COBALT
Amount(Lbs/Yr):	0.02140908
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440666
Contaminant:	ZINC
Amount(Lbs/Yr):	8.2507900000000003
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000207089
Contaminant:	BENZO[K]FLUORANTHENE
Amount(Lbs/Yr):	4.5876599999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000218019
Contaminant:	CHRYSENE
Amount(Lbs/Yr):	5.1211799999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: 2016
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 282.99599999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 0.17355110000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 30584400

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 251.55199999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 1.8866400000000001E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 3.4141199999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 4.0779199999999996E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.188664

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.34141199999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 7.9662799999999996E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1194.8720000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 27012

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440622

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: VANADIUM
Amount(Lbs/Yr): 0.65437299999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.64797899999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.58620099999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 169.03800000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 0.00338076

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 3.0584399999999999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 2.3898840000000001E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.17294200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	0.53522700000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440382
Contaminant:	ARSENIC
Amount(Lbs/Yr):	5.6902000000000001E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440382
Contaminant:	ARSENIC
Amount(Lbs/Yr):	0.056346
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	0.12743499999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000205992
Contaminant:	BENZO[B]FLUORANTHENE
Amount(Lbs/Yr):	5.0711400000000002E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000206440
Contaminant:	FLUORANTHENE
Amount(Lbs/Yr):	7.6460999999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000218019
Contaminant:	CHRYSENE
Amount(Lbs/Yr):	2.8299599999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	6.7615199999999996E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000108883
Contaminant:	TOLUENE
Amount(Lbs/Yr):	0.96733400000000003

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 0.00127435

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 34141200

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 873.36300000000006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 407.79199999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 3.3807599999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 3.4141199999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 3.4141199999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 2.5155199999999998E-3

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2016
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.33807599999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 4.5521600000000004E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 0.00450768

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 0.00676152

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 6.1168799999999999E-3

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 7.1363600000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 25538

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 7.3912300000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 3.4141200000000001E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.220108

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.031444

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.1081138

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 0.17185529999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 8.5353000000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 512.11800000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 458.76600000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.53454800000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.95788200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074828

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: METHANE
Amount(Lbs/Yr): 654.37300000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 455.21600000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 3.3807599999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 4.8366700000000004E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 3.3807599999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440666
Contaminant: ZINC

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr): 4.55938

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 94.331999999999994

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 170.70599999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 152.922

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.01320648

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 13206.48

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 5.1211799999999999E-4

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 739.726

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 507.11399999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 18866400

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 535.22699999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 450.76799999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.33016200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 361.60599999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 1.8866400000000001E-4

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date:	Not reported
Year:	2016
CAS #:	000050000
Contaminant:	FORMALDEHYDE
Amount(Lbs/Yr):	11.791499999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000050000
Contaminant:	FORMALDEHYDE
Amount(Lbs/Yr):	21.338249999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	619.80600000000004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	77.037800000000004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	124.88630000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	0.00377328
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	0.00676152
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	007440439
Contaminant:	CADMIUM
Amount(Lbs/Yr):	0.17294200000000001
Issue Date:	Not reported
Expiration Date:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: 2016
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.28035700000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.398314

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.39442199999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.36160599999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.30990299999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.59747099999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 5.0973999999999998E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 4.7165999999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 407.79199999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 3.3807599999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 3.4141199999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 3.4141199999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 2.5155199999999998E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 025321226

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.33807599999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 4.5521600000000004E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.86655800000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 33807600

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 7.8609999999999997E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000106978
Contaminant: BUTANE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	330.16199999999998
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	597.471
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	591.63300000000004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000050328
Contaminant:	BENZO(A)PYRENE
Amount(Lbs/Yr):	3.0584399999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000053703
Contaminant:	DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr):	3.0584399999999999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	0.59747099999999997
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	0.53522700000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	0NY075025
Contaminant:	PM 2.5
Amount(Lbs/Yr):	2141.1480000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	0NY075025
Contaminant:	PM 2.5
Amount(Lbs/Yr):	1937.0119999999999

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 6.8282400000000002E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 625.92200000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 560.71400000000006

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.02140908

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 8.2507900000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 5.1211799999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 4.5876599999999999E-4

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2016
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 282.99599999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 0.17355110000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 30584400

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 251.55199999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 1.8866400000000001E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 3.4141199999999998E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: 2016
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 4.0779199999999996E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.188664

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.34141199999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 7.9662799999999996E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1194.8720000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 27012

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.65437299999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.64797899999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.58620099999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 169.03800000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 0.00338076

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 3.0584399999999999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 2.3898840000000001E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.17294200000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.53522700000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440382

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: ARSENIC
Amount(Lbs/Yr): 5.6902000000000001E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.056346

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.12743499999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 5.0711400000000002E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 7.6460999999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 2.8299599999999999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 6.7615199999999996E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.96733400000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2016
CAS #: 000129000
Contaminant: PYRENE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	0.00127435
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000124389
Contaminant:	CARBON DIOXIDE
Amount(Lbs/Yr):	34141200
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2016
CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	873.36300000000006
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000057976
Contaminant:	7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr):	0.015103890336
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	1.3939565605
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074828
Contaminant:	METHANE
Amount(Lbs/Yr):	2187.9118
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	2943.233
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074986
Contaminant:	PROPANE
Amount(Lbs/Yr):	1021.1002366
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000083329
Contaminant:	ACENAPHTHENE
Amount(Lbs/Yr):	0.0016991876628

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000085018
Contaminant:	PHENANTHRENE
Amount(Lbs/Yr):	0.010849190014

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000086737
Contaminant:	FLUORENE
Amount(Lbs/Yr):	0.0026431808088

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	0.38929446519

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000091576
Contaminant:	2-METHYL NAPHTHALENE
Amount(Lbs/Yr):	0.022655835504

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	1340.1940605

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000108883
Contaminant:	TOLUENE
Amount(Lbs/Yr):	2.1698380027

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	1659.2878844

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	1148.7377661

Issue Date:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2012
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 0.0022655835504

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 113931600

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 0.00471996573

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 0.0011327917752

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 0.0016991876628

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 0.0016991876628

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 0.002893561938

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 0.0011487377661

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: 2012
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 0.0011487377661

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 79849.87

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.496453623

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.35899109548

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 0.24549686796

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 1.0383924606

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 1.9827375066

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.1888807392

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 4.1535698424

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 0.011376792752

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 1.0386075106

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 1.3314436044

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.079295424264

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 1.1297103948

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 1.4550808297

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 48.802473589

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050328

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 0.00076582517743

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 0.00076582517743

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 0.0016991876628

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 0.0011487377661

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.8025114741

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 2.1711842358

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 27.375879434

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 1124.878

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007446119
Contaminant: SULFUR TRIOXIDE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	22.287
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	480.8607
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	0.022949085504
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	2093.829
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	025321226
Contaminant:	DICHLOROBENZENE
Amount(Lbs/Yr):	0.76582517743
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	0NY075025
Contaminant:	PM 2.5
Amount(Lbs/Yr):	7190.5744096
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	0NY075105
Contaminant:	UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr):	30.266609133
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	0NY210000
Contaminant:	OXIDES OF NITROGEN
Amount(Lbs/Yr):	172417.925
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	0NY998100
Contaminant:	UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr):	5.6548375

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440484
Contaminant:	COBALT
Amount(Lbs/Yr):	0.086239192181
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	0.87286993231
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440622
Contaminant:	VANADIUM
Amount(Lbs/Yr):	2.3613112145
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007440666
Contaminant:	ZINC
Amount(Lbs/Yr):	29.773195403
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007446095
Contaminant:	SULFUR DIOXIDE
Amount(Lbs/Yr):	627.04812
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007446119
Contaminant:	SULFUR TRIOXIDE
Amount(Lbs/Yr):	0.301302
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007664417
Contaminant:	AMMONIA
Amount(Lbs/Yr):	534.1513
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	007782492
Contaminant:	SELENIUM
Amount(Lbs/Yr):	0.025168369195
Issue Date:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2012
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 2280.8164

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.83288720965

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 7831.8427783

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 54.557304646

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 188915.38

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 10.19317

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 53.746970603

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 0.00083288720965

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year:	2012
CAS #:	000053703
Contaminant:	DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr):	0.00083288720965
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000056495
Contaminant:	3-METHYLCHOLANTHRENE
Amount(Lbs/Yr):	0.0018479826896
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000056553
Contaminant:	BENZO(A)ANTHRACENE
Amount(Lbs/Yr):	0.0012493308145
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000057976
Contaminant:	7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr):	0.016426512796
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000071432
Contaminant:	BENZENE
Amount(Lbs/Yr):	1.5544626169
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074828
Contaminant:	METHANE
Amount(Lbs/Yr):	2382.52284
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	3200.967
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012
CAS #:	000074986
Contaminant:	PROPANE
Amount(Lbs/Yr):	1110.5162795
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2012

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 0.0018479826896

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 0.01179923547

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 0.0028746397394

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 0.42338433157

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 0.024639769195

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 1457.5526169

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 2.359847094

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 1804.5889542

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000110543

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: HEXANE
Amount(Lbs/Yr): 1249.3308145

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 0.0024639769195

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 123908400

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 0.0051332852489

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 0.0012319884597

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 0.0018479826896

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 0.0018479826896

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 0.0031909771493

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr): 0.0012493308145

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 0.0012493308145

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 86912.08

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.55741376489

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.39062303891

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 0.26703655294

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 1.1293227548

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 2.1566141245

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.20547941795

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 4.517291019

Issue Date: Not reported
Expiration Date: Not reported
Year: 2012
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 0.012407984597

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 9.6044999999999995E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.122680431738698

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 0.49072172695479299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.12510231973869801

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.16168889130379799

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 9.3683238782278702E-3

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2011
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 9.4798515434448699E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.25651362999909599

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 3.2343022912929502

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 54.963299999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 5.5787649903999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 81.900133838282699

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 2.3192316622719198

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 2583.991

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year:	2011
CAS #:	000091203
Contaminant:	NAPHTHALENE
Amount(Lbs/Yr):	0.68393840356470004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000108883
Contaminant:	TOLUENE
Amount(Lbs/Yr):	3.7077329098688199
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	1956.7171305187901
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000124389
Contaminant:	CARBON DIOXIDE
Amount(Lbs/Yr):	134518897.91999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	96502.540548000004
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	0.55959942886778602
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	0.82080841875767696
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	0.29947866859083
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 2.4031236877058202

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.237759257654787

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 1.3489231851164201E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 812.24250840000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 4.8275508127604803E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 2472.7739999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 1.3004780870125201

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 8687.3071200824907

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY210000

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 209559.53279999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 16339.298932142199

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 9.1111687012523601E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 9.2442787012523599E-5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000056495
Contaminant: 3-METHYLCHOLANTHRENE
Amount(Lbs/Yr): 2.00749797390597E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 1.4137873051878601E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000057976
Contaminant: 7,12-DIMETHYLBENZ[A]ANTHRACENE
Amount(Lbs/Yr): 0.00178444264347197

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 347.72699999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000074986
Contaminant: PROPANE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr):	120.637449350032
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000075070
Contaminant:	ACETALDEHYDE
Amount(Lbs/Yr):	0.00258479
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000083329
Contaminant:	ACENAPHTHENE
Amount(Lbs/Yr):	2.0553519222513299E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000085018
Contaminant:	PHENANTHRENE
Amount(Lbs/Yr):	0.00138085089934408
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000086737
Contaminant:	FLUORENE
Amount(Lbs/Yr):	4.1068135638818999E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000091576
Contaminant:	2-METHYL NAPHTHALENE
Amount(Lbs/Yr):	2.6766639652079601E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000106978
Contaminant:	BUTANE
Amount(Lbs/Yr):	158.33665227191599
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000106990
Contaminant:	1,3-BUTADIENE
Amount(Lbs/Yr):	8.2047270000000002E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2011
CAS #:	000107028
Contaminant:	ACROLEIN
Amount(Lbs/Yr):	0.000311725

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 196.03585519380101

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000115071
Contaminant: PROPYLENE
Amount(Lbs/Yr): 8.6946000000000002E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 2.7396828971838901E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 5.7374690869702104E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 1.3548109648161901E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000193395
Contaminant: INDENO[1,2,3-CD]PYRENE
Amount(Lbs/Yr): 2.0201349602653199E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 2.0108379703006999E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 3.6022866796847202E-4

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2011
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 1.3623943051878601E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2011
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 1.3690673051878601E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 7.9926399999999995E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 610.86479999999995

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 2.4824200000000001E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075005
Contaminant: PM-10
Amount(Lbs/Yr): 7593.9326000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 279752.04800000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 5495.2455200000004

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year:	2009
CAS #:	0NY075100
Contaminant:	UNSPECIATED PARTICULATES (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr):	7594.3346000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	0NY075025
Contaminant:	PM 2.5
Amount(Lbs/Yr):	7593.6310999999996
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	010024972
Contaminant:	NITROUS OXIDE
Amount(Lbs/Yr):	507.38920000000002
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000120127
Contaminant:	ANTHRACENE
Amount(Lbs/Yr):	5.4945606817175701E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	278.59458891855701
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000129000
Contaminant:	PYRENE
Amount(Lbs/Yr):	1.1447001420244901E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000191242
Contaminant:	BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr):	2.7472803408587802E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000205992
Contaminant:	BENZO[B]FLUORANTHENE
Amount(Lbs/Yr):	4.1209205112881703E-4
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 6.9677408521469602E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 2.78594588918557E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 2.78594588918557E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 19357.472000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.118451614202449

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 8.7041450793861497E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 5.9533887385273598E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.251834031245388

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440020

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.480830939650287

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 4.5801277680979698E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 1.00733612498155

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 2.7551803408587799E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.25186879124538802

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.32210867976685797

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 1.9230962386011501E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.19461798414416401

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440622
Contaminant: VANADIUM

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Amount(Lbs/Yr): 0.52656206533126704

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 6.6392734637420601

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 227.89879999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007446119
Contaminant: SULFUR TRIOXIDE
Amount(Lbs/Yr): 3.6023999999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 115.35442

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 5.5419606817175698E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.185729725945704

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 1742.56701587723

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 4.8921702739999997

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 64548.080000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 0.91403000000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 11.7597878716065

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 1.85729725945704E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 1.85729725945704E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 2.78594588918557E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 0.33371702040498302

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 530.27596000000005

Issue Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Expiration Date: Not reported
Year: 2009
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 713.7998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 247.63963459427299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 4.1209205112881703E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 2.6311711175641501E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 6.4103207953371602E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 9.4412610689066395E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 5.4945606817175703E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 325.02702040498298

Issue Date: Not reported
Expiration Date: Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Year: 2009
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 0.526234223512829

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 402.41440621569302

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 27630960

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 74.955522000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 1.2199999999999999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 0.60943879999999995

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106467
Contaminant: BENZENE, 1,4-DICHLORO-
Amount(Lbs/Yr): 1.198896

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 3.3968720000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

CAS #:	000110543
Contaminant:	HEXANE
Amount(Lbs/Yr):	1798.3440000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	83924.729999999996
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007439921
Contaminant:	LEAD
Amount(Lbs/Yr):	0.50004652000000005
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007439965
Contaminant:	MANGANESE
Amount(Lbs/Yr):	0.37998808000000001
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007439976
Contaminant:	MERCURY
Amount(Lbs/Yr):	0.25992964000000002
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440020
Contaminant:	NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr):	2.0982368400000002
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440382
Contaminant:	ARSENIC
Amount(Lbs/Yr):	0.20004111999999999
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440417
Contaminant:	BERYLLIUM
Amount(Lbs/Yr):	1.2158840000000001E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2009
CAS #:	007440439

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

Contaminant: CADMIUM
Amount(Lbs/Yr): 1.09915684

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 1.3988808399999999

AIRS Emissions:
County: ONONDAGA
Municipality: SYRACUSE
Facility ID: 7311500204
Facility Name: SYRACUSE UNIVERSITY - STEAM STATION
SIC Code: 8221

Year: 2023
VOC(tons): 10.95
NOx(tons): 49.02
Co(tons): 41.61
Co2(tons): 53707.19
Particulates: 3.54
PM10(tons): 0
PM2.5(tons): 3.52
HAPS: 0.83
So2: 0.4

Year: 2022
VOC(tons): 5.32
NOx(tons): 50.23
Co(tons): 41.44
Co2(tons): 59194.8
Particulates: 3.75
PM10(tons): 0
PM2.5(tons): 3.73
HAPS: 0.89
So2: 0.3

Year: 2021
VOC(tons): 4.27
NOx(tons): 48.32
Co(tons): 40.47
Co2(tons): 57812.4
Particulates: 3.66
PM10(tons): 0.01
PM2.5(tons): 3.64
HAPS: 0.91
So2: 0.29

Year: 2020
VOC(tons): 9.6
NOx(tons): 53.52
Co(tons): 44.38
Co2(tons): 61167.89
Particulates: 3.98
PM10(tons): 0

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

PM2.5(tons):	3.96
HAPS:	0
So2:	0.42
Year:	2019
VOC(tons):	2.27
NOx(tons):	54.04
Co(tons):	45.11
Co2(tons):	64440.6
Particulates:	0.02
PM10(tons):	0
PM2.5(tons):	4.06
HAPS:	0
So2:	0.32
Year:	2018
VOC(tons):	2.18
NOx(tons):	51.79
Co(tons):	43.33
Co2(tons):	61899
Particulates:	3.92
PM10(tons):	0
PM2.5(tons):	3.9
HAPS:	0
So2:	0.31
Year:	2017
VOC(tons):	9.05
NOx(tons):	58.04
Co(tons):	44.71
Co2(tons):	62430.76
Particulates:	4.24
PM10(tons):	0
PM2.5(tons):	4.22
HAPS:	0
So2:	0.59
Year:	2016
VOC(tons):	3.08
NOx(tons):	48.62
Co(tons):	41.09
Co2(tons):	58699.8
Particulates:	3.74
PM10(tons):	0
PM2.5(tons):	3.72
HAPS:	0
So2:	0.29
Year:	2015
VOC(tons):	2.14
NOx(tons):	50.59
Co(tons):	42.44
Co2(tons):	60684.56
Particulates:	3.86
PM10(tons):	0.02
PM2.5(tons):	3.82
HAPS:	0

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **S111258241**

So2:	0.31
Year:	2014
VOC(tons):	10.13
NOx(tons):	107.69
Co(tons):	48.17
Co2(tons):	79011.04
Particulates:	4.04
PM10(tons):	0
PM2.5(tons):	4.02
HAPS:	0
So2:	0.32
Year:	2013
VOC(tons):	2.85
NOx(tons):	94.46
Co(tons):	43.46
Co2(tons):	61954.2
Particulates:	3.95
PM10(tons):	3.95
PM2.5(tons):	3.92
HAPS:	0
So2:	0.31
Year:	2012
VOC(tons):	2.61
NOx(tons):	86.21
Co(tons):	39.92
Co2(tons):	56965.8
Particulates:	3.63
PM10(tons):	3.61
PM2.5(tons):	3.6
HAPS:	0
So2:	0.56
Year:	2011
VOC(tons):	9.43
NOx(tons):	104.78
Co(tons):	48.25
Co2(tons):	67259.45
Particulates:	4.35
PM10(tons):	4.35
PM2.5(tons):	4.34
HAPS:	0
So2:	0.41
Year:	2010
VOC(tons):	3.69
NOx(tons):	139.88
Co(tons):	41.96
Co2(tons):	66358.57
Particulates:	11.39
PM10(tons):	7.6
PM2.5(tons):	3.8
HAPS:	0
So2:	0.31

C13 **SU CHILLED WATER PLANT** **NY CBS** **S102166574**
NE **500 E. TAYLOR STREET** **NY AST** **N/A**
< 1/8 **SYRACUSE, NY 13202** **NY Spills**
0.040 mi. **NY MANIFEST**
210 ft. **Site 8 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

CBS:

Name:	SYRACUSE UNIVERSITY STEAM STATION
Address:	500 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY 13202
CBS Number:	7-000152
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	7
UTMX:	406899.41504
UTMY:	4765790.33863

Name:	SU CHILLED WATER PLANT
Address:	500 E. TAYLOR STREET
City,State,Zip:	SYRACUSE, NY 13202
CBS Number:	7-000281
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	7
UTMX:	406826.97609
UTMY:	4765824.13209

AST:

Name:	SYRACUSE UNIVERSITY STEAM STATION
Address:	500 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY 13202
Region:	STATE
DEC Region:	7
Site Status:	Unregulated/Closed
Facility Id:	7-000152
Program Type:	CBS
UTM X:	406899.41504
UTM Y:	4765790.33863
Expiration Date:	N/A
Site Type:	School

Tank Info:

Tank Number:	001
Tank Id:	187570
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1972
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/16/2011
Register:	True

SU CHILLED WATER PLANT (Continued) **S102166574**

Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	002
Tank Id:	195960
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/01/2003
Capacity Gallons:	200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/30/2009
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	002-A
Tank Id:	195961
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Fiberglass Reinforced Plastic
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	02/01/1991
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	003
Tank Id:	195962
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	02/01/2004
Capacity Gallons:	200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/30/2009
Register:	True

SU CHILLED WATER PLANT (Continued) **S102166574**

Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: 003-A
Tank Id: 195963
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Fiberglass Reinforced Plastic
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 02/01/1991
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: 004
Tank Id: 190059
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Tank Converted to Non-Regulated Use
Pipe Model: Not reported
Install Date: 12/01/1970
Capacity Gallons: 1000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

SPILLS:
Name: SYRACUSE UNIVERSITY
Address: 500 E TAYLOR ST
City,State,Zip: SYRACUSE, NY
Spill Number/Closed Date: 1902943 / 2020-03-27
Facility ID: 1902943
Facility Type: ER
DER Facility ID: 541078
Site ID: 590889
DEC Region: 7
Spill Cause: Equipment Failure
Spill Class: B4
SWIS: 3415
Spill Date: 2019-06-21
Investigator: CFNORRIS

SU CHILLED WATER PLANT (Continued) **S102166574**

Referred To:	Not reported
Reported to Dept:	2019-06-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-06-21
Spill Record Last Update:	2020-03-27
Spiller Name:	Not reported
Spiller Company:	MCGINNIS NELSON CONTRACTOR
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHAD AMES
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Spill to stone below sidewalk during replacement of sidewalk pavers. Incident report to be sent over soon. 1/21/2019 I spoke to Chad Ames, SU Health and Safety. He will be sending the incident report and disposal information, hopefully today. REPORT RECEIVED
Remarks:	loss to crushed stone, c/u in progress

All Materials:

Site ID:	590889
Operable Unit ID:	1338515
Operable Unit:	01
Material ID:	2348010
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SU STEAM STATION
Address:	500 E TAYLOR ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9008107 / 1990-10-24
Facility ID:	9008107
Facility Type:	ER
DER Facility ID:	280417
Site ID:	161896
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	3400
Spill Date:	1990-10-24
Investigator:	DJLASALL

SU CHILLED WATER PLANT (Continued) **S102166574**

Referred To:	Not reported
Reported to Dept:	1990-10-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1990-10-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SU STEAM STATION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
Latitude:	43.0389813
Longitude:	-76.1429976
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was DL
Remarks:	PLANT PERSONNEL USED PADS TO CLEAN UP AND DISPOSED OF SAME.

All Materials:

Site ID:	161896
Operable Unit ID:	945310
Operable Unit:	01
Material ID:	559262
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYD982271918
Country:	USA
Name:	Syracuse University Steam Station
Address:	500 E TAYLOR ST
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13244
Zip 4:	Not reported
Location Address 1:	500 EAST TAYLOR STREET
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13244
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Syracuse University Steam Station

SU CHILLED WATER PLANT (Continued) **S102166574**

Mailing Contact: Brian Fitzpatrick
Mailing Address 1: 108 COLLEGE PLACE
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13244
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154233328

Manifest Data:
Document ID: ILA7829484
Manifest Status: Not reported
Trans1 State ID: UPW018074
Year: 1999
Trans2 State ID: UPW012400
Generator Ship Date: 07/28/1999
Trans1 Recv Date: 07/28/1999
Trans2 Recv Date: 07/30/1999
TSD Site Recv Date: 08/04/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982271918
Trans1 EPA ID: MAD039322250
Trans2 EPA ID: OHD009865825
TSDF ID 1: ILD000608471
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00440
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn

SU CHILLED WATER PLANT (Continued) **S102166574**

Specific Gravity: 01.00

Document ID: NYC3311436
Manifest Status: Not reported
Trans1 State ID: NYAM6504
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 10/25/1994
Trans1 Recv Date: 10/25/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/26/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982271918
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NYD982743312
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00021
Units: Gallons (liquids only)
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYC2998721
Manifest Status: Not reported
Trans1 State ID: NYLJ5601
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 02/14/1994
Trans1 Recv Date: 02/14/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/15/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD982271918
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported

SU CHILLED WATER PLANT (Continued) **S102166574**

TSDF ID 1:	NYD982743312
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00017
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC4837792
Manifest Status:	Not reported
Trans1 State ID:	NYMU2534
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/1997
Trans1 Recv Date:	10/07/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/08/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD982743312
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported

SU CHILLED WATER PLANT (Continued) **S102166574**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00015
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC4445504
Manifest Status:	Not reported
Trans1 State ID:	NYNF6576
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/22/1997
Trans1 Recv Date:	01/22/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/23/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD982743312
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00015
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC1872843
Manifest Status:	Not reported
Trans1 State ID:	NYDN5385
Year:	1992
Trans2 State ID:	Not reported

SU CHILLED WATER PLANT (Continued) **S102166574**

Generator Ship Date:	10/09/1992
Trans1 Recv Date:	10/09/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/09/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000824581
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00086
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD054126164
Generator Ship Date:	10/06/2011
Trans1 Recv Date:	10/06/2011
Trans2 Recv Date:	10/11/2011
TSD Site Recv Date:	10/12/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000570816VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

SU CHILLED WATER PLANT (Continued) **S102166574**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Mercury
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	17
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD054126164
Generator Ship Date:	10/06/2011
Trans1 Recv Date:	10/06/2011
Trans2 Recv Date:	10/11/2011
TSD Site Recv Date:	10/12/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000570816VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported

SU CHILLED WATER PLANT (Continued) **S102166574**

Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	124
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	NYA5856579
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	AM8365
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890105
Trans1 Recv Date:	900105
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	900105
Part A Recv Date:	900111
Part B Recv Date:	900119
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

SU CHILLED WATER PLANT (Continued) **S102166574**

Quantity:	00605
Units:	Gallons (liquids only)
Number of Containers:	011
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	ILA8497054
Manifest Status:	Not reported
Trans1 State ID:	UPW018074
Year:	2000
Trans2 State ID:	UPW012400
Generator Ship Date:	01/20/2000
Trans1 Recv Date:	01/20/2000
Trans2 Recv Date:	01/24/2000
TSD Site Recv Date:	02/01/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	OHD009865825
TSDF ID 1:	ILD000608471
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00040
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

SU CHILLED WATER PLANT (Continued) **S102166574**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NYD980769947
Generator Ship Date:	10/03/2013
Trans1 Recv Date:	10/03/2013
Trans2 Recv Date:	10/08/2013
TSD Site Recv Date:	10/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD982271918
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000609559VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	28
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
85 additional NY MANIFEST: record(s) in the EDR Site Report.

C14 **SYRACUSE UNIVERSITY - STEAM STATION** **RCRA NonGen / NLR** **1000145092**
NE **500 E TAYLOR ST** **E MANIFEST** **NYD982271918**
< 1/8 **SYRACUSE, NY 13244** **NJ MANIFEST**
0.040 mi.
210 ft. **Site 9 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

RCRA Listings:

Date Form Received by Agency:	20190503
Handler Name:	Syracuse University - Steam Station
Handler Address:	E Taylor St
Handler City,State,Zip:	SYRACUSE, NY 13244
EPA ID:	NYD982271918
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R7
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20190503
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYRACUSE UNIV BD OF TRUSTEES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	TOLLEY ADMINISTRATION BLDG
Owner/Operator City,State,Zip:	SYRACUSE, NY 13244
Owner/Operator Telephone:	315-443-4132
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE UNIV BD OF TRUSTEES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: TOLLEY ADMINISTRATION BLDG
Owner/Operator City,State,Zip: SYRACUSE, NY 13244
Owner/Operator Telephone: 315-443-4132
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE UNIV BD OF TRUSTEES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: TOLLEY ADMINISTRATION BLDG
Owner/Operator City,State,Zip: SYRACUSE, NY 13244
Owner/Operator Telephone: 315-443-4132
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE UNIVERSITY
Legal Status: Private
Date Became Current: 19270101
Date Ended Current: Not reported
Owner/Operator Address: 900 S CROUSE AVE
Owner/Operator City,State,Zip: SYRACUSE, NY 13244
Owner/Operator Telephone: 315-443-4132
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 315-443-3081
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE UNIVERSITY
Legal Status: Private
Date Became Current: 19270101
Date Ended Current: Not reported
Owner/Operator Address: 900 S CROUSE AVE
Owner/Operator City,State,Zip: SYRACUSE, NY 13244
Owner/Operator Telephone: 315-443-4132
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: 315-443-3081
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SYRACUSE UNIV - STEAM STATION
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SYRACUSE UNIV - STEAM STATION
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20190503
Handler Name: SYRACUSE UNIVERSITY - STEAM STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19870807
Handler Name: SYRACUSE UNIV - STEAM STATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920228
Handler Name: SYRACUSE UNIVERSITY STEAM STATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180502
Handler Name: SYRACUSE UNIVERSITY - STEAM STATION
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 61131
NAICS Description: Colleges, Universities, And Professional Schools

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 001563043VES
Last Updated Date: 20190515
Shipped Date: 20190424
Received Date: 20190501
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYD982271918
Generator Name: Syracuse University-Steam Sta
Generator Location Street Number: Not reported
Generator Location Street 1: 500 EAST TAYLOR ST
Generator Location Street 2: STEAM STATION
Generator Location City: SYRACUSE
Generator Location State: NY
Generator Location Zip: 13244-0000
Generator Mail Street Number: Not reported
Generator Mail Street 1: C/O EHSS
Generator Mail Street 2: 100 College Place
Generator Mail City: SYRACUSE
Generator Mail Zip: 13244-0000
Generator Mail State: NY
Generator Contact Company Name: Not reported
Designated Facility EPA ID: NJD980536593
Designated Facility Name: Not reported
Designated Facility Mail Street Number: 1

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1 EDEN LANE
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	1 EDEN LANE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions Llc
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	001563044VES
Last Updated Date:	20190605
Shipped Date:	20190424
Received Date:	20190501
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13244-0000
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13244-0000
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD093945293
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	PO BOX 453
Designated Facility Mail Street 2:	4301 INFIRMARY RD
Designated Facility Mail City:	WEST CARROLLTON
Designated Facility Mail Zip:	45449
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4301 INFIRMARY RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	WEST CARROLLTON
Designated Facility Location Zip:	45449-1278
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Veolia Es Technical Solutions Llc
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	001563623VES
Last Updated Date:	20220512

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Shipped Date:	20220428
Received Date:	20220504
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13244
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	1 EDEN LANE
Designated Facility Mail Street 2:	L.L.C.
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	L.L.C.
Designated Facility Location Street 2:	1 EDEN LANE
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	001563639VES
Last Updated Date:	20220708
Shipped Date:	20220601
Received Date:	20220615
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Generator Mail Zip:	13244
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	1 EDEN LANE
Designated Facility Mail Street 2:	L.L.C.
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	L.L.C.
Designated Facility Location Street 2:	1 EDEN LANE
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	001563659VES
Last Updated Date:	20220926
Shipped Date:	20220824
Received Date:	20220831
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13244
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	1 EDEN LANE
Designated Facility Mail Street 2:	L.L.C.
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	L.L.C.
Designated Facility Location Street 2:	1 EDEN LANE
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Designated Facility Contact Company Name:	Veolia Es Technical Solutions
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	001556606VES
Last Updated Date:	20191226
Shipped Date:	20191206
Received Date:	20191218
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13244
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD002454544
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	125 FACTORY LN
Designated Facility Mail City:	MIDDLESEX
Designated Facility Mail Zip:	08846
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	125 FACTORY LN
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	MIDDLESEX
Designated Facility Location Zip:	08846
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions Llc
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	001560223VES
Last Updated Date:	20230417
Shipped Date:	20230315
Received Date:	20230324
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Generator Location State:	NY
Generator Location Zip:	13244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13244
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	1 EDEN LANE
Designated Facility Mail Street 2:	L.L.C.
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	L.L.C.
Designated Facility Location Street 2:	1 EDEN LANE
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	001558051VES
Last Updated Date:	20200304
Shipped Date:	20200220
Received Date:	20200228
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13244
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13244
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD093945293
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4301 INFIRMARY RD PO BOX 453
Designated Facility Mail City:	WEST CARROLLTON
Designated Facility Mail Zip:	45342
Designated Facility Mail State:	OH

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4301 INFIRMARY RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	WEST CARROLLTON
Designated Facility Location Zip:	45449
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Veolia Es Technical Solutions Llc
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	001556943VES
Last Updated Date:	20201211
Shipped Date:	20201120
Received Date:	20201201
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD982271918
Generator Name:	Syracuse University-Steam Sta
Generator Location Street Number:	Not reported
Generator Location Street 1:	500 EAST TAYLOR ST
Generator Location Street 2:	STEAM STATION
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13244-0000
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS
Generator Mail Street 2:	100 College Place
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13244-0000
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	1 EDEN LANE
Designated Facility Mail Street 2:	L.L.C.
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	L.L.C.
Designated Facility Location Street 2:	1 EDEN LANE
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	001556943VES
Transporter Line Number:	1
Transporter EPA ID:	NJD080631369
Transporter Name:	Veolia Es Technical Solutions
Manifest Tracking Number:	001556943VES

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Transporter Line Number: 2
Transporter EPA ID: NJD054126164
Transporter Name: Freehold Cartage Inc

Waste Line:
Manifest Tracking Number: 001556943VES
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3432
U.S. DOT Description: Un3432, Waste Polychlorinated Biphenyls, Solid, (Lead Pipe Pieces & Oily Debris W/>50-Ppm Pcb'S), 9, Ii, Rq (1-Lb/Pcb'S/B007; 10-Lbs/D008) **(Steam# 15498)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 36
Quantity Unit of Measure Code: K
Quantity Unit of Measure Description: Kilograms
Waste Quantity, in Tons: 0.039689977
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.039689977
Waste Quantity, in Kilograms: 36
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 36
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D008
Quantity Haz Kg: 36
Quantity Haz Tons: 0.039689977
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: NY-B, NY-B007

Manifest Tracking Number: 001556943VES
Waste Line Number: 2
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3432
U.S. DOT Description: Un3432, Polychlorinated Biphenyls, Solid, (Debris >50ppm Pcb'S: Dirt, Ppe, Poly, Rags), 9, Iii, Rq (1-Lb/Pcb'S/B007) **(Steam#15499)
Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	7
Quantity Unit of Measure Code:	K
Quantity Unit of Measure Description:	Kilograms
Waste Quantity, in Tons:	0.0077174953
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0077174953
Waste Quantity, in Kilograms:	7
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	7
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	7
Quantity Non Haz Tons:	0.0077174953
State Waste Codes:	NJ-ID27, NY-B, NY-B007

NJ MANIFEST:

EPA ID:	NYD982271918
Name:	SYRACUSE UNIVERSITY STEAM ST
Address:	500 E TAYLOR ST.
City,State,Zip:	SYRACUSE, NY 13244
County:	Not reported
Mailing Address:	500 E TAYLOR ST.
Mailing City,State,Zip:	SYRACUSE 13244
Telephone:	3154434188
Emergency Telephone:	3154434188
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	000000

Manifest Data:

EPA ID:	NYD982271918

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Manifest Number:	NJA3092111
Date Shipped:	07/16/2004
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD054126164
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/16/2004
Date Trans2 Transported Waste:	07/22/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/23/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09030422
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD982271918
Manifest Number:	000380452VES
Date Shipped:	02/05/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD054126164
Transporter 3 EPA ID:	NJD000692061
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/05/2010
Date Trans2 Transported Waste:	02/11/2010
Date Trans3 Transported Waste:	02/16/2010

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/16/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D009
Hand Code:	H141
Quantity:	1
Unit:	P

EPA ID:	NYD982271918
Manifest Number:	NJA3091700
Date Shipped:	07/08/2005
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD054126164
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/08/2005
Date Trans2 Transported Waste:	07/14/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/15/2005
TSDF EPA Facility Name:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	08230521
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

EPA ID:	NYD982271918
Manifest Number:	000570816VES
Date Shipped:	10/6/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD054126164
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported

SYRACUSE UNIVERSITY - STEAM STATION (Continued) **1000145092**

Waste Code:	D009
Hand Code:	H141
Quantity:	17.00
Unit:	Pounds
Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	124.00
Unit:	Pounds
EPA ID:	NYD982271918
Manifest Number:	NJA3092105
Date Shipped:	03/11/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD054126164
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/11/2004
Date Trans2 Transported Waste:	03/16/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/17/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	04020421
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

C15
NE
< 1/8
0.040 mi.
210 ft.

SYRACUSE UNIVERSITY STEAM STATION
500 EAST TAYLOR ST
SYRACUSE, NY

Site 10 of 15 in cluster C

UST FINDER | **1028588722** | **N/A**

Relative:
Higher

Actual:
406 ft.

UST FINDER:

Object ID:	318218
Facility ID:	NY44931
Name:	SYRACUSE UNIVERSITY STEAM STATION
Address:	500 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY
Address Match Type:	Not reported
Open USTs:	4
Closed USTs:	3
TOS USTs:	0
Population 1500ft:	3032
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-76.143772
Y Coord:	43.039411
Latitude:	43.039411
Longitude:	-76.143772

UST FINDER:

Object ID:	1277884
Facility ID:	NY44931
Tank ID:	NY70351
Tank Status:	Closed
Installation Date:	1963/01/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	30000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1277885
Facility ID:	NY44931
Tank ID:	NY70352
Tank Status:	Open
Installation Date:	1989/08/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	30000
Substances:	Not reported
Tank Wall Type:	Not reported

SYRACUSE UNIVERSITY STEAM STATION (Continued) **1028588722**

Object ID:	1277886
Facility ID:	NY44931
Tank ID:	NY70956
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	15000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1277887
Facility ID:	NY44931
Tank ID:	NY71906
Tank Status:	Closed
Installation Date:	1963/01/01 16:00:01+00
Removal Date:	Not reported
Tank Capacity:	30000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1277888
Facility ID:	NY44931
Tank ID:	NY71907
Tank Status:	Open
Installation Date:	1989/08/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	30000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1277889
Facility ID:	NY44931
Tank ID:	NY73477
Tank Status:	Open
Installation Date:	1989/08/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	30000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1277890
Facility ID:	NY44931
Tank ID:	NY75588
Tank Status:	Open
Installation Date:	1989/08/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	30000
Substances:	Not reported
Tank Wall Type:	Not reported

C16 **TAYLOR & MCBRIDE ST.- PCB** **NY Spills** **S103567303**
NE **TAYLOR AND MCBRIDE ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.042 mi.
222 ft. **Site 11 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

SPILLS:

Name:	TAYLOR & MCBRIDE ST.- PCB
Address:	TAYLOR AND MCBRIDE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9107234 / 1991-11-12
Facility ID:	9107234
Facility Type:	ER
DER Facility ID:	230968
Site ID:	284835
DEC Region:	7
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	3415
Spill Date:	1991-10-05
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1991-10-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	1991-10-07
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-10-07
Spill Record Last Update:	1991-11-12
Spiller Name:	Not reported
Spiller Company:	NIAGRA MOHAWK POWER CO.
Spiller Address:	300 ERIE BLVD.
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR
	10/07/91: NIMO PERSONEL
	PERFORMING CLEANUP. TO SEND CLOSURE REPORT W/SAMPLING RESULT FROM
	SPILL SITE. 11/12/91: REC'D
	DOCUMENTATION REPORT REGARDING CLEANUP FROM NIAGRA-MOHAWK.
Remarks:	BLDG. CONSTRUCTION PROJECT COLLASPED BRINGING DOWN THREE UTILITY
	POLES. ONE TRANSFORMER LEAKED WHEN IT HIT THE GROUND.

All Materials:

Site ID:	284835
Operable Unit ID:	957577
Operable Unit:	01
Material ID:	419452
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00

TAYLOR & MCBRIDE ST.- PCB (Continued) **S103567303**

Units:	G
Recovered:	19.00
Resource Affected:	Soil
Oxygenate:	Not reported

C17 **E. TAYLOR AND MCBRIDE ST.** **NY Spills** **S102165193**
NE **EAST TAYLOR AND MCBRIDE** **N/A**
< 1/8 **SYRACUSE, NY**
0.042 mi.
222 ft. **Site 12 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

SPILLS:

Name:	E. TAYLOR AND MCBRIDE ST.
Address:	EAST TAYLOR AND MCBRIDE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9204042 / 1992-07-08
Facility ID:	9204042
Facility Type:	ER
DER Facility ID:	196313
Site ID:	238382
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	E6
SWIS:	3415
Spill Date:	1992-07-08
Investigator:	RJBRAZEL
Referred To:	Not reported
Reported to Dept:	1992-07-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1992-07-08
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-07-20
Spill Record Last Update:	1993-04-06
Spiller Name:	Not reported
Spiller Company:	NO NAME CONSTRUCTION CO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RB 09/28/95: This is additional information about material spilled from the translation of the old spill file: HEAVY YELLOW SMOKE.
Remarks:	CALLER AND SEVERAL OTHER BUSINESS PEOPLE IN THE VICINITY ARE CONCERNEDBECAUSE SMALL CHILDREN ARE PLAYING IN THE AREA

All Materials:

Site ID:	238382
Operable Unit ID:	971435

E. TAYLOR AND MCBRIDE ST. (Continued) **S102165193**

Operable Unit:	01
Material ID:	411798
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Air
Oxygenate:	Not reported

C18 **STEAM HEAT SYR. UNIVERS.** **NY Spills** **S102164496**
NE **TALOR & MCBRIDE ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.042 mi.
223 ft. **Site 13 of 15 in cluster C**

Relative: **Higher**

Actual: **406 ft.**

SPILLS:

Name:	STEAM HEAT SYR. UNIVERS.
Address:	TALOR & MCBRIDE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8801654 / 1995-02-09
Facility ID:	8801654
Facility Type:	ER
DER Facility ID:	211093
Site ID:	257809
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3415
Spill Date:	1988-05-23
Investigator:	HDWARNER
Referred To:	Not reported
Reported to Dept:	1988-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	1995-02-09
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-06-07
Spill Record Last Update:	1995-02-09
Spiller Name:	Not reported
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was HW 01/19/89: DEC MONITORING THE CLEANUP EFFORTS. 04/12/91: NEW FUEL STORAGE TANKS WERE INSTALLED BY SU

STEAM HEAT SYR. UNIVERS. (Continued) **S102164496**

DURING SUMMER OF 90. LARGE
QUANTITY OF CONTAMINATED SOIL REMOVED. STAN TALLET OF STEAM STATION CURRENTLY MONITORING. 06/19/91:
MET STAN TALLET AT SITE CHECKED WELL ADJACENT TO RECOVERY SYSTEM FORPRODUCT. LAYER OF FUEL STILL
PRESENT IN WELL. SU TO EXCAVATE AROUND WELL SOMTIME IN JULY. 02/07/92: MEETING AT STEAM STATION SU
WILL DO SOIL BORINGS BEFORE EXCAVATING SOIL. WORK SCHEDULED FOR 02/06/92. CRAIG BUTLER OF ES
HANDLING PROJECT. 06/27/92: SOIL EXCAVATED AREA OF APPROX 15' BY 20' REMOVED GARY DYER HAULED
CONTAMINATED SOIL. ES ON SITE TO OVER SEE EXCAVATION, WILL SEND CLOSURE REPORT.

Remarks: BARRY KOUGOT 422-0121. DRILLING AND HIT OIL. 6 TO 18 OF FUEL OILON GROUND WATER. FOUND ABANDONED 15K TANK ;FULL OF WATER AND FUEL OIL.

All Materials:

Site ID:	257809
Operable Unit ID:	917147
Operable Unit:	01
Material ID:	460784
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

C19 **INTERSECTION OF** **NY Spills** **S107787451**
NE **EAST TAYLOR/SOUTH MCBRIDE** **N/A**
< 1/8 **SYRACUSE, NY**
0.042 mi.
223 ft. **Site 14 of 15 in cluster C**

Relative: Higher
Actual: 406 ft.

SPILLS:

Name:	INTERSECTION OF
Address:	EAST TAYLOR/SOUTH MCBRIDE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0600689 / 2006-04-19
Facility ID:	0600689
Facility Type:	ER
DER Facility ID:	312985
Site ID:	362754
DEC Region:	7
Spill Cause:	Other
Spill Class:	D3
SWIS:	3415
Spill Date:	2006-04-18
Investigator:	KCKemp
Referred To:	Not reported
Reported to Dept:	2006-04-18
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other

INTERSECTION OF (Continued) **S107787451**

Spill Notifier:	Responsible Party
Cleanup Ceased:	2006-04-19
Cleanup Meets Std:	True
Last Inspection:	2006-04-18
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-18
Spill Record Last Update:	2006-04-19
Spiller Name:	GLENN WILLIAMS
Spiller Company:	NATIONAL GRID
Spiller Address:	300 ERIE BLVD WEST
Spiller Company:	001
Contact Name:	GLENN WILLIAMS
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	cleaned up by optech. no stains noted.
Remarks:	THEY WERE REELING HOSE AND OI LEAKED OUT AND OPTECH IS ENROUTE TO CLEAN UP

All Materials:

Site ID:	362754
Operable Unit ID:	1120827
Operable Unit:	01
Material ID:	2110318
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

C20 **PROJECT ORANGE** **NY Spills** **S102165331**
ENE **OLD S.U. STEAM PLANT** **N/A**
< 1/8 **SYRACUSE, NY**
0.048 mi.
252 ft. **Site 15 of 15 in cluster C**

Relative:
Higher

Actual:
406 ft.

SPILLS:

Name:	PROJECT ORANGE
Address:	OLD S.U. STEAM PLANT
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9207607 / 1992-09-30
Facility ID:	9207607
Facility Type:	ER
DER Facility ID:	214230
Site ID:	262415
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	E6
SWIS:	3415
Spill Date:	1992-09-29
Investigator:	CFMANNES
Referred To:	Not reported

PROJECT ORANGE (Continued) **S102165331**

Reported to Dept:	1992-09-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-09-30
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	PROJECT ORANGE
Spiller Address:	1100 TOWNCOUNTRY RD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM 09/30/92: NO RESPONSE WARRENTED , UPSTATE ASBESTOS IS CLEAN UP CONTRACTOR.
Remarks:	TRACY JONES 315474 8230 CALLED STEAM PIPE WATER MAIN RUPTURE BROKE PIPE INSTALLTION MATERIAL DISSOLVED INTO WATER , WATER PUMPED INTO SEWERS

All Materials:

Site ID:	262415
Operable Unit ID:	974429
Operable Unit:	01
Material ID:	408237
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	262415
Operable Unit ID:	974429
Operable Unit:	01
Material ID:	408236
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

21 SSW < 1/8 0.059 mi. 310 ft. — **NIAGARA MOHAWK POWER CORP**, **235 OAKWOOD AVE. EXT.**, **TROY, NY 13202** — **NY LTANKS**, **NY Spills**, **NY MANIFEST** — **S108294880**, **N/A**

Relative: Lower

Actual: 398 ft.

LTANKS:

Name:	NIMO OAKWOOD AVE RT 40
Address:	235 OAKWOOD AVE RT 40
City,State,Zip:	TROY, NY
Spill Number/Closed Date:	9409889 / 1995-04-18
Facility ID:	9409889
Site ID:	327666
Spill Date:	1994-10-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1995-02-28
SWIS:	4217
Investigator:	WXOBRIEN
Referred To:	Not reported
Reported to Dept:	1994-10-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-11-03
Spill Record Last Update:	2012-07-18
Spiller Name:	Not reported
Spiller Company:	NIAGARA MOHAWK NIMO
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	4
DER Facility ID:	263775
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'BRIEN Tank pit contaminated from leakage. not leaving area. Will have to remediate when tanks are replaced. PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374. 4/28/06 GW results from 1995 show low levels ~ 1.5 ppm
Remarks:	SEE RPT, DOB TELECON W/M&E, 4K UGT FAILED PETROTITE @ GROSS RATE. TANK FIXED & PASSED RETEST.

All TTF:

Facility ID:	9409889
Spill Number:	9409889
Spill Tank Test:	1543277
Site ID:	327666
Tank Number:	Not reported
Tank Size:	0
Material:	0008

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 327666
Operable Unit ID: 1003862
Operable Unit: 01
Material ID: 375762
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

SPILLS:
Name: NIMO TRANSFORMER OAKWOOD RT 40
Address: 235 OAKWOOD AVE RT 40
City,State,Zip: TROY, NY
Spill Number/Closed Date: 0405104 / 2004-08-30
Facility ID: 0405104
Facility Type: ER
DER Facility ID: 263775
Site ID: 327661
DEC Region: 4
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 4217
Spill Date: 2004-08-10
Investigator: WEBLAIN
Referred To: Not reported
Reported to Dept: 2004-08-10
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-08-10
Spill Record Last Update: 2012-07-18

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Spiller Name:	BARBARA SCHEURER
Spiller Company:	TRANSFORMER PAD [NIMO]
Spiller Address:	235 OAKWOOD AVE
Spiller Company:	001
Contact Name:	BARBARA SCHEURER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BLAIN 8/30/04 Blain contacted Barb Schuerer, NIMO. Non-PCB oil. cleaned up. PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374.
Remarks:	TRANSFORMER DETERIORATED AND STARTED TO LEAK: CREW ON SCENE AND HAZMAT ON WAY: SPEEDI DRI AND PADS PLACED: 2 QUARTS SPILLED OUT:

All Materials:

Site ID:	327661
Operable Unit ID:	887978
Operable Unit:	01
Material ID:	489122
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	327661
Operable Unit ID:	887978
Operable Unit:	01
Material ID:	489123
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NIMO TRANSFORMER OAKWOOD RT 40
Address:	235 OAKWOOD AVE RT 40
City,State,Zip:	TROY, NY
Spill Number/Closed Date:	0405144 / 2004-08-30
Facility ID:	0405144
Facility Type:	ER
DER Facility ID:	263775
Site ID:	327662
DEC Region:	4
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4217
Spill Date:	2004-08-10

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	2004-08-10
CID:	407
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-10
Spill Record Last Update:	2012-07-18
Spiller Name:	TOM SULLIVAN
Spiller Company:	NIMO
Spiller Address:	235 OAKWOOD AVE
Spiller Company:	001
Contact Name:	TOM SULLIVAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BLAIN 8/30/2004 Blain contacted NIMO. Non-PCB oil, cleaned up. PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374.
Remarks:	Spill is contained.

All Materials:

Site ID:	327662
Operable Unit ID:	887998
Operable Unit:	01
Material ID:	489188
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NIMO BLDG OAKWOOD AVE RT 40
Address:	235 OAKWOOD AVE RT 40
City,State,Zip:	TROY, NY
Spill Number/Closed Date:	0405710 / 2004-11-16
Facility ID:	0405710
Facility Type:	ER
DER Facility ID:	263775
Site ID:	327663
DEC Region:	4
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4217
Spill Date:	2004-08-25

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	2004-08-25
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-08-25
Spill Record Last Update:	2012-07-18
Spiller Name:	TOM SULLIVAN
Spiller Company:	NIAGRA[SP]MOHAWK BLD NIMO
Spiller Address:	235 OAKWOOD AVE.
Spiller Company:	001
Contact Name:	TOM SULLIVAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Factory labeled non-PCB, remediation complete. PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374.
Remarks:	CONTAINED AT THE SITE AND HAZMAT CREW IS ON ITS WAY TO CLEAN IT UP.

All Materials:

Site ID:	327663
Operable Unit ID:	888460
Operable Unit:	01
Material ID:	486517
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NIMO OAKWOOD AVE O/W SEP RT 40
Address:	235 OAKWOOD AVE RT 40
City,State,Zip:	TROY, NY
Spill Number/Closed Date:	8708047 / 1988-07-05
Facility ID:	8708047
Facility Type:	ER
DER Facility ID:	263775
Site ID:	327664
DEC Region:	4
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4217
Spill Date:	1987-12-17
Investigator:	MCDONALD
Referred To:	Not reported

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Reported to Dept:	1987-12-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1988-07-05
Cleanup Meets Std:	True
Last Inspection:	1987-12-22
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-12-23
Spill Record Last Update:	2012-07-18
Spiller Name:	Not reported
Spiller Company:	NIAGARA MOHAWK NIMO
Spiller Address:	1125 BROADWAY
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374.
Remarks:	OIL/WATER SEPARATOR OVERFILLED, SOME TO STORM DRAIN. NIMO TO CLEANUP

All Materials:

Site ID:	327664
Operable Unit ID:	912370
Operable Unit:	01
Material ID:	463443
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Site ID:	327664
Operable Unit ID:	912370
Operable Unit:	01
Material ID:	463444
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	500.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	NIMO MAINT CTR OAKWOOD RT 40
Address:	235 OAKWOOD AVE RT 40
City,State,Zip:	TROY, NY

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Spill Number/Closed Date:	9206473 / 1992-12-07
Facility ID:	9206473
Facility Type:	ER
DER Facility ID:	263775
Site ID:	327665
DEC Region:	4
Spill Cause:	Other
Spill Class:	C3
SWIS:	4217
Spill Date:	1992-09-03
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	1992-09-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1992-09-03
Cleanup Meets Std:	True
Last Inspection:	1992-09-03
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-08
Spill Record Last Update:	2012-07-18
Spiller Name:	Not reported
Spiller Company:	NIAGARA MOHAWK NIMO MAIN
Spiller Address:	OAKWOOD AVE RT 40
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BLAIN PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374.
Remarks:	FOUND CONT. SOIL FROM LEAKING LIFT CYLINDER, 4-5YDS STOCKPILED. BLAIN @ SITE-MINOR PROBLEM.

All Materials:

Site ID:	327665
Operable Unit ID:	970170
Operable Unit:	01
Material ID:	410634
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NIMO OAKWOOD AVE RT 40
Address:	235 OAKWOOD AVE RT 40
City,State,Zip:	TROY, NY

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Spill Number/Closed Date:	9511298 / 1996-07-12
Facility ID:	9511298
Facility Type:	ER
DER Facility ID:	263775
Site ID:	327667
DEC Region:	4
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	4217
Spill Date:	1995-12-06
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	1995-12-07
CID:	216
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-07
Spill Record Last Update:	2012-07-18
Spiller Name:	MARTIN CONDON
Spiller Company:	NIAGARA MOHAWK NIMO
Spiller Address:	235 OAKWOOD AVENUE
Spiller Company:	001
Contact Name:	MARTIN CONDON
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BLAIN NO RESPONSE. HOTLINE HAD SPILLER AS NOMO . PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374.
Remarks:	EMPLOYEES WERE PUMPING OIL TO AN OUTSIDE DRUM ALARM ON OUTSIDE DRUM NEVER ACTIVATED CAUSEING A OVERFLOW

All Materials:

Site ID:	327667
Operable Unit ID:	1025523
Operable Unit:	01
Material ID:	358646
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NIMO GARAGE TRANSFORMER OAKWOOD RT 40
Address:	235 OAKWOOD AVE RT 40

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

City,State,Zip:	TROY, NY
Spill Number/Closed Date:	9800231 / 1998-04-06
Facility ID:	9800231
Facility Type:	ER
DER Facility ID:	263775
Site ID:	327668
DEC Region:	4
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	4217
Spill Date:	1998-04-06
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	1998-04-06
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-06
Spill Record Last Update:	2012-07-18
Spiller Name:	BILL LYSOGORSKI
Spiller Company:	NIAGARA MOHAWK NIMO
Spiller Address:	5215 WESTER TRNPK [SP]
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BLAIN PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374.
Remarks:	TRANSFORMER FELL FROM PALLET WHILE BE MOVED SPILL TO PAVEMENT AND GRAVEL AREA CLEAN UP BY CALLERS CREW

All Materials:

Site ID:	327668
Operable Unit ID:	1060738
Operable Unit:	01
Material ID:	325774
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NATIONAL GRID OAKWOOD AVE (NIMO) RT 40
Address:	235 OAKWOOD AVE RT 40

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

City,State,Zip:	TROY, NY
Spill Number/Closed Date:	0800093 / 2008-04-03
Facility ID:	0800093
Facility Type:	ER
DER Facility ID:	263775
Site ID:	395793
DEC Region:	4
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4217
Spill Date:	2008-04-02
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	2008-04-02
CID:	404
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-02
Spill Record Last Update:	2012-07-18
Spiller Name:	BARBARA SCHERER [SP] BARBARA SCHEURER
Spiller Company:	NATIONAL GRID (NIMO)
Spiller Address:	235 OAKWOOD AVE
Spiller Company:	999
Contact Name:	BARBARA SCHUERER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	minor. non-pcb closed
Remarks:	leaky transformer in storage area; Hazmat crew in route; it is non pcb; on gravel and concrete

All Materials:

Site ID:	395793
Operable Unit ID:	1152734
Operable Unit:	01
Material ID:	2143513
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	395793
Operable Unit ID:	1152734
Operable Unit:	01
Material ID:	2143528
Material Code:	0020A
Material Name:	transformer oil

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NATIONAL GRID
Address:	235 OAKWOOD AVE
City,State,Zip:	TROY, NY
Spill Number/Closed Date:	2203438 / 2022-09-06
Facility ID:	2203438
Facility Type:	ER
DER Facility ID:	529286
Site ID:	639545
DEC Region:	4
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4217
Spill Date:	2022-07-20
Investigator:	AXODONNE
Referred To:	Not reported
Reported to Dept:	2022-07-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-07-20
Spill Record Last Update:	2022-09-06
Spiller Name:	MATT ROUTE
Spiller Company:	NATIONAL GRID
Spiller Address:	235 OAKWOOD AVE
Spiller Company:	999
Contact Name:	JOHN WENSLEY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	07.20.22 - email sent to Matt Root for cleanup detail. aod 07.20.22 - 5 gallon spill at Troy service center. Equipment failure on gravel and stone. 09.06.22 - Hydraulic line break resulted in hydraulic oil spill on roadway and adjacent shoulder. Crew hand dug comamintated soil. Spread speedy dry and shovel up. Load all waste into drum for disposal. closed. aod
Remarks:	CLEANUP PENDING

All Materials:

Site ID:	639545
Operable Unit ID:	1386600
Operable Unit:	01

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Material ID:	2401392
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	NIMO SERV CTR OAKWOOD AVE RT 40
Address:	235 OAKWOOD AVE RT 40
City,State,Zip:	TROY, NY
Spill Number/Closed Date:	0212237 / 2003-11-13
Facility ID:	0212237
Facility Type:	ER
DER Facility ID:	263775
Site ID:	327660
DEC Region:	4
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	4217
Spill Date:	2003-03-13
Investigator:	WEBLAIN
Referred To:	Not reported
Reported to Dept:	2003-03-13
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-13
Spill Record Last Update:	2012-07-18
Spiller Name:	CALLER
Spiller Company:	NIAGARA MOHAWK NIMO
Spiller Address:	OAKWOOD AV
Spiller Company:	001
Contact Name:	TOM SULLIVAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BLAIN PBS 4-429503; see 8708047, 9206473, 9409889, 9511298, 9800231, 0212237, 0405104, 0405144, 0405710, 0509374. 11/13/2003 NIMO reports factory labeled non-PCB. Cleanup complete.
Remarks:	forklift driver hit a pad mounted transformer w/ the forklift causing spill to concrete - clean up in progress

All Materials:

Site ID:	327660
Operable Unit ID:	865689

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Operable Unit:	01
Material ID:	511973
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	25.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	NATIONAL GRID TR#4780 NIMO OAKWOOD RT 40
Address:	235 OAKWOOD AVE EXT RT 40
City,State,Zip:	TROY, NY
Spill Number/Closed Date:	0704961 / 2007-08-16
Facility ID:	0704961
Facility Type:	ER
DER Facility ID:	334597
Site ID:	385210
DEC Region:	4
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4217
Spill Date:	2007-08-01
Investigator:	weblain
Referred To:	Not reported
Reported to Dept:	2007-08-01
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-08-01
Spill Record Last Update:	2012-07-18
Spiller Name:	BARABRA SCHEURERE [SP] BARBARA SCHEURER
Spiller Company:	NATIONAL GRID TR#4780 (NIMO)
Spiller Address:	235 OAKWOOD AVE EXT
Spiller Company:	999
Contact Name:	BARABRA SCHEURERE [SP] BARBARA SCHEURER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	hydraulic oil. minor.
Remarks:	HOSE FAILED AND IS ALL CONTAINED AND IN PROCESS OF CLEANING UP

All Materials:

Site ID:	385210
Operable Unit ID:	1142485
Operable Unit:	01
Material ID:	2132722
Material Code:	0010
Material Name:	hydraulic oil

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7.00
Units:	G
Recovered:	7.00
Resource Affected:	Soil
Oxygenate:	Not reported

Click this hyperlink while viewing on your computer to access
17 additional NY SPILL: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYD980788442
Country:	USA
Name:	Niagara Mohawk Power Corp
Address:	235 OAKWOOD AVE. EXT.
Address 2:	Not reported
City,State,Zip:	TROY, NY 13202-4298
Zip 4:	Not reported
Location Address 1:	235 OAKWOOD AVE
Location Address 2:	Not reported
Location City,State,Zip:	TROY, NY 12182
Location Zip 4:	1600
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Niagara Mohawk Power Corp
Mailing Contact:	Niagara Mohawk Power Corp
Mailing Address 1:	1125 BROADWAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	ALBANY, NY 12204
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5184713502

Manifest Data:

Document ID:	NYC3140436
Manifest Status:	Not reported
Trans1 State ID:	NYRH6932
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/1994
Trans1 Recv Date:	07/22/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD986872869
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00008
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYG2923641
Manifest Status:	Not reported
Trans1 State ID:	TPZ409NJ
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	10/15/2001
Trans1 Recv Date:	10/15/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/22/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	NJD071629976
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD981113749
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B004
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01142
Units:	Kilograms
Number of Containers:	006
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYG2907558
Manifest Status:	Not reported
Trans1 State ID:	0726992ME
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	04/27/2001
Trans1 Recv Date:	04/27/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/04/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	NYD986899912
Trans2 EPA ID:	Not reported
TSDF ID 1:	ALD983167891
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B006
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00136
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Specific Gravity:	01.00
Document ID:	NYC1837293
Manifest Status:	Not reported
Trans1 State ID:	NYEC2076
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	08/14/1992
Trans1 Recv Date:	08/14/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/14/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD986872869
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYC2254454
Manifest Status:	Not reported
Trans1 State ID:	NYIM5676

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	05/04/1993
Trans1 Recv Date:	05/04/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/04/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD986872869
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00008
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYB4020552
Manifest Status:	Not reported
Trans1 State ID:	PB9830NY
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	06/05/1997
Trans1 Recv Date:	06/05/1997
Trans2 Recv Date:	Not reported

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

TSD Site Recv Date:	06/05/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000730408
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Mercury
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00499
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00091
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC2313933
Manifest Status:	Not reported
Trans1 State ID:	NYIM5676
Year:	1993

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Trans2 State ID:	Not reported
Generator Ship Date:	05/27/1993
Trans1 Recv Date:	05/27/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/27/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD986872869
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00008
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC3364345
Manifest Status:	Not reported
Trans1 State ID:	NYGS7503
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	12/06/1994
Trans1 Recv Date:	12/06/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/06/1994

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD986872869
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00008
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC1888367
Manifest Status:	Not reported
Trans1 State ID:	NYGS7503
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/1992
Trans1 Recv Date:	10/12/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/12/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

TSDF ID 1:	NYD986872869
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYG2442537
Manifest Status:	Not reported
Trans1 State ID:	AA709F
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	11/07/2000
Trans1 Recv Date:	11/07/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/08/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	NJD071629976
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD981113749
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B004
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00345
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYG2442555
Manifest Status:	Not reported
Trans1 State ID:	AA709F
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/2000
Trans1 Recv Date:	09/26/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980788442
Trans1 EPA ID:	NJD071629978
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD981113749
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B004
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00937

NIAGARA MOHAWK POWER CORP (Continued) **S108294880**

Units:	Kilograms
Number of Containers:	004
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	B004
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00205
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
105 additional NY MANIFEST: record(s) in the EDR Site Report.

D22 **CITY OWNED APARTMENT COMPLEX** **NY Spills** **S131919859**
WNW **301-311 EAST TAYLOR ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.060 mi.
316 ft. **Site 1 of 9 in cluster D**

Relative:
Lower

Actual:
399 ft.

SPILLS:

Name:	CITY OWNED APARTMENT COMPLEX
Address:	301-311 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2400040 / Not Reported
Facility ID:	2400040
Facility Type:	ER
DER Facility ID:	609512
Site ID:	664372
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	3415
Spill Date:	2024-04-02
Investigator:	CBKERLIN
Referred To:	Not reported
Reported to Dept:	2024-04-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2024-04-02
Spill Record Last Update:	2024-04-02
Spiller Name:	MATT WALKER
Spiller Company:	UNK

CITY OWNED APARTMENT COMPLEX (Continued) **S131919859**

Spiller Address:	301-311 EAST TAYLOR ST
Spiller Company:	999
Contact Name:	MATT WALKER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	4/2/24: Phase II test results came back with BTEX hits in soil and water, site used to be a gas station. Part of I-81 redevelopment project. (CBK)
Remarks:	phase 2 results from 3/5/24 soil and ground water affected. clean up pending. location is an old gas stations from the 1950s

All Materials:

Site ID:	664372
Operable Unit ID:	1411191
Operable Unit:	01
Material ID:	2428949
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

E23 **CENTRAL VILLAGE HOUSING PROJECT** **UST FINDER** **1028590168**
WSW **302 BURT ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.063 mi.
335 ft. **Site 1 of 5 in cluster E**

Relative: **Lower**
Actual: **396 ft.**

UST FINDER:

Object ID:	318193
Facility ID:	NY46337
Name:	CENTRAL VILLAGE HOUSING PROJECT
Address:	302 BURT ST
City,State,Zip:	SYRACUSE, NY 13202
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	0
TOS USTs:	1
Population 1500ft:	2207
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)

CENTRAL VILLAGE HOUSING PROJECT (Continued) **1028590168**

Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-76.147216
Y Coord:	43.03821
Latitude:	43.03821
Longitude:	-76.147216

UST FINDER:

Object ID:	1282797
Facility ID:	NY46337
Tank ID:	NY74450
Tank Status:	Temporarily out of Service
Installation Date:	1984/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Not reported
Tank Wall Type:	Not reported

E24 **CENTRAL VILLAGE HOUSING PROJECT** **NY UST** **U000388734**
WSW **302 BURT ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.063 mi.
335 ft. **Site 2 of 5 in cluster E**

Relative:
Lower

Actual:
396 ft.

UST:

Name:	CENTRAL VILLAGE HOUSING PROJECT
Address:	302 BURT ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-498955 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	02/10/2030
UTM X:	406652.97099
UTM Y:	4765681.72010
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	46337
Affiliation Type:	Facility Operator
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	SYRACUSE HOUSING AUTHORITY
Address1:	516 Burt Street
Address2:	Not reported
City:	Syracuse
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 475-6181
EMail:	mliquori@syrhousing.org
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-12-13

Site Id:	46337

CENTRAL VILLAGE HOUSING PROJECT (Continued) **U000388734**

Affiliation Type:	Mail Contact
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	Director of Asset Management and Modernization
Contact Name:	Melissa Liquori
Address1:	516 BURT ST
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 470-4354
EMail:	mliquori@SYRHOUSING.ORG
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-12-13

Site Id:	46337
Affiliation Type:	Emergency Contact
Company Name:	Melissa Liquori
Contact Type:	Not reported
Contact Name:	Melissa Liquori
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NY
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 956-2644
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2024-12-13

Site Id:	46337
Affiliation Type:	Facility Owner
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	FACILITIES MANAGER
Contact Name:	MARTIN BRUNET
Address1:	516 BURT ST
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 470-4354
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2019-12-10

Tank Info:

Tank Number:	001
Tank ID:	133571
Tank Status:	Temporarily Out of Service
Material Name:	Temporarily Out of Service
Capacity Gallons:	10000

CENTRAL VILLAGE HOUSING PROJECT (Continued) **U000388734**

Install Date:	12/01/1984
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	07/26/2019
Next Test Date:	07/26/2020
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
K00 - Spill Prevention - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None

E25 **EAST ADAMS REDEVELOPMENT - ALMUS OLVER TOWER** **NY BROWNFIELDS** **S131541419**
WSW **300 BURT STREET** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.065 mi.
341 ft. **Site 3 of 5 in cluster E**

Relative: **Lower**
Actual: **396 ft.**

BROWNFIELDS:

Name:	EAST ADAMS REDEVELOPMENT - ALMUS OLVER TOWER
Address:	300 BURT STREET
City,State,Zip:	SYRACUSE, NY 13202
Program:	BCP
Site Code:	657340
Acres:	2.306
HW Code:	C734161
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	09/22/2023
Record Updated Date:	02/14/2024
Update By:	GWPRISCO
Site Description:	"02/13/2024 Site was denied from the Brownfield Cleanup Program (BCP). Based upon review of the BCP application, the proposed site is not a brownfield site as defined in Article 27, Title 14 of the Environmental Conservation Law. Location: The site is located at 300 Burt Street within an urban, mixed-use area in the City of Syracuse, New York. The site is located in the northwestern portion of an about 8.82-acre tax parcel, identified as Onondaga County Tax Parcel 094.-17-01.0. The site is bound by a residential building at 302 Burt Street and Burt Street followed by vacant land at 516 Burt Street to the north, Oakwood Avenue followed by residential and commercial

EAST ADAMS REDEVELOPMENT - ALMUS OLVER TOWER (Continued) **S131541419**

properties at 221-223 Oakwood Avenue and 233-235 Oakwood Avenue, respectively, and vacant land at 229 Oakwood Avenue to the east, residential buildings at 313 Raynor Avenue East and Oakwood Avenue to the south, and vacant land at 234-238 Burt Street and State Street South and 1208, 1210, 1212, 1214, 1216, 1218-1220, and 1224 State Street South to the west. The site is improved with a 12-story apartment building in the central part of the site and asphalt-paved parking lots surrounding the building to the northeast, south, and west. The remainder of the site is comprised of landscaped areas and concrete-paved walkways. The area surrounding the site consists of residential, commercial, and industrial properties. Site Features: According to the May 2023 Phase I Environmental Site Assessment (ESA) and the July 2023 Phase II ESA prepared by EA engineering, P.C. and its affiliate EA Science and Technology (EA), the elevation of the site ranges from about elevation (el) 388 to 398 feet. The topography of the site is generally flat with the surrounding area gently sloping towards the southwest. Current Zoning and Land Use: According to the Rezone Syracuse ordinance and City of Syracuse Zoning Map, the site is located within an MX-4: Urban Core District. The MX-4: Urban Core zoning district is generally characterized as pedestrian-friendly, transit-supportive areas of higher density residential development and a well-integrated mix of non-residential uses. The surrounding properties are zoned for MX-2: Neighborhood Center Districts, R2: Low Density Residential Districts, R4: Medium Density Residential Districts, and R5: High Density Residential Districts. Land use within a half-mile radius is urban and includes residential, commercial, institutional/public services, industrial, vacant land, and public parks. The nearest ecological receptor is the Onondaga Creek, located approximately 0.4 miles west of the site. At present, the site is occupied by a residential building, asphalt-paved parking lots, landscaped areas and concrete-paved walkways. Past Use of the Site: Historical Sanborn Fire Insurance Maps indicate that the site has been located in a residential and commercial area since as early as 1892. By 1892, the site was developed with several one- to two-story dwellings, stables, sheds, and store fronts. By 1910, some of the structures were demolished. From 1951 to 1961, the site was developed with an automobile repair facility in the northwestern part of the site and a printing, paper ruling and book binding facility and a beer warehouse in the southern part of the site. The remainder of the site was developed with residential and commercial buildings, with automobile garages identified in the eastern part of the site. By 1963, the site was occupied by the Syracuse Housing Authority and developed in its present-day configuration. Site Geology and Hydrogeology: According to the U.S. Department of Agriculture s (USDA) Natural Resources Conservation Service (NRCS) Soil Survey Geographic (SSURGO) data for the site, soils at the site are comprised primarily of urban land. Urban land is described as excavated, filled, and made land. According to the Phase II ESA conducted by EA, soil at the site consists of brown silty sand with varying amounts of medium-grained sand, gravel, and clay to about 6 feet below ground surface (bgs). This layer is underlain by brown to gray clay with varying amounts of silt, fine- to medium-grained sand, gravel, and organic matter to the termination depth of the borings (about 15 feet bgs). Bedrock was not encountered during the investigation. Based on review of the Geologic Map of New York, Finger Lakes Sheet (Fisher, Isachsen, Rickard, dated March 1970) , the site is underlain by bedrock of the Syracuse

EAST ADAMS REDEVELOPMENT - ALMUS OLVER TOWER (Continued) **S131541419**

	Foundation, consisting of dolostone, shale, gypsum and salt. Based on measurements collected during the Phase II ESA conducted by EA, groundwater at the site flows to the southwest, following the local topography, towards Onondaga Creek. Groundwater was observed at about 6.4 to 9.0 feet bgs (corresponding to el. 382.47 to 383.94). "
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	4
Sub Type:	NNN
Owner Name:	William J Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Rene Battelle
Owner Company:	Onondaga County Public Libraries-Central Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13205
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Allyson Carpenter
Owner Company:	Almus Olver Tower, L.P.
Owner Address:	28 Liberty Street
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10005
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	William J Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported

EAST ADAMS REDEVELOPMENT - ALMUS OLVER TOWER (Continued) **S131541419**

Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

F26 **SYRACUSE HOUSING AUTHORITY** **RCRA NonGen / NLR** **1004570531**
ESE **516 BURT ST** **FINDS** **NYD981873599**
< 1/8 **SYRACUSE, NY 13202** **ECHO**
0.070 mi. **NY MANIFEST**
371 ft. **Site 1 of 3 in cluster F**

Relative: **Higher**

Actual: **410 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Syracuse Housing Authority
Handler Address:		Burt St
Handler City,State,Zip:		SYRACUSE, NY 13202
EPA ID:		NYD981873599
Contact Name:		EILEEN D GILLIGAN
Contact Address:		BURT ST
Contact City,State,Zip:		SYRACUSE, NY 13202
Contact Telephone:		315-475-6181
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		BURT ST
Mailing City,State,Zip:		SYRACUSE, NY 13202
Owner Name:	Syracuse Housing Authority	
Owner Type:		Municipal
Operator Name:	Syracuse Housing Authority	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	Lead
Waste Code:	NONE
Waste Description:	Not Defined
Waste Code:	X002
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYRACUSE HOUSING AUTHORITY
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	516 BURT ST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202
Owner/Operator Telephone:	315-475-6181
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 516 BURT ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-475-6181
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 516 BURT ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-475-6181
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950519
Handler Name: SYRACUSE HOUSING AUTHORITY
Federal Waste Generator Description: Not reported
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SYRACUSE HOUSING AUTHORITY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SYRACUSE HOUSING AUTHORITY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19961125
Handler Name: SYRACUSE HOUSING AUTHORITY
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980227
Handler Name: SYRACUSE HOUSING AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020618
Handler Name: SYRACUSE HOUSING AUTHORITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 53111
NAICS Description: Lessors Of Residential Buildings And Dwellings

NAICS Code: 92511
NAICS Description: Administration Of Housing Programs

Facility Has Received Notices of Violations:
Violations: No Violations Found

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110000809457

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004570531
Registry ID: 110000809457

DFR URL:
Name: SYRACUSE HOUSING AUTHORITY
Address: 516 BURT ST
City,State,Zip: SYRACUSE, NY 13202

NY MANIFEST:
EPA ID: NYD981873599
Country: USA
Name: Syracuse Housing Authority
Address: 516 BURT ST
Address 2: Not reported
City,State,Zip: SYRACUSE, NY 13202

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Zip 4:	Not reported
Location Address 1:	300 BURT STREET
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Syracuse Housing Authority
Mailing Contact:	Cary Barber
Mailing Address 1:	516 BURT STREET
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3156474221

Manifest Data:

Document ID:	NHG0004600
Manifest Status:	Not reported
Trans1 State ID:	PR5398NY
Year:	2002
Trans2 State ID:	Not reported
Generator Ship Date:	01/10/2002
Trans1 Recv Date:	01/10/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/14/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981873599
Trans1 EPA ID:	NYD980761191
Trans2 EPA ID:	Not reported
TSDF ID 1:	NHD018902874
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B001
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00003
Units:	Kilograms
Number of Containers:	002

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	NYB7405668
Manifest Status:	Not reported
Trans1 State ID:	NY2281OH
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	12/05/1995
Trans1 Recv Date:	12/05/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/06/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981873599
Trans1 EPA ID:	NYD982792814
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00150
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Lead
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00375
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00
Document ID:	MAG0910650

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Manifest Status:	Not reported
Trans1 State ID:	TNY34284
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/1996
Trans1 Recv Date:	12/20/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/30/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981873599
Trans1 EPA ID:	MAD019371079
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD019371079
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB8711514
Manifest Status:	Not reported
Trans1 State ID:	67285KNY
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/23/1997
Trans1 Recv Date:	01/23/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981873599
Trans1 EPA ID:	NYD000688671
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	14941
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB8711523
Manifest Status:	Not reported
Trans1 State ID:	8375577NY
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/1997
Trans1 Recv Date:	01/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/28/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981873599
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B001
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Waste Code 6:	Not reported
Quantity:	04800
Units:	Kilograms
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	B006
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00800
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG1960578
Manifest Status:	Not reported
Trans1 State ID:	NPF236KS
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/2001
Trans1 Recv Date:	07/09/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981873599
Trans1 EPA ID:	SCR000074591
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD981113749
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B002
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02455
Units:	Kilograms
Number of Containers:	002
Container Type:	Metal boxes, cartons, cases (including roll-offs)

SYRACUSE HOUSING AUTHORITY (Continued) **1004570531**

Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	B003
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	01245
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Recycle
Specific Gravity:	01.00

G27 **SYRACUSE HOUSING AUTH - PIONEER HOMES** **RCRA-SQG** **1010566800**
North **116-118 RADISSON COURT** **NY MANIFEST** **NYR000154476**
< 1/8 **SYRACUSE, NY 13202**
0.079 mi.
418 ft. **Site 1 of 2 in cluster G**

Relative: **Lower**
Actual: **401 ft.**

RCRA Listings:

Date Form Received by Agency:	20080205
Handler Name:	Syracuse Housing Auth - Pioneer Homes
Handler Address:	Radisson Court
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NYR000154476
Contact Name:	WILLIAM W GEHRKE
Contact Address:	BURT ST
Contact City,State,Zip:	SYRACUSE, NY 13202
Contact Telephone:	315-470-4315
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Other
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R7
Mailing Address:	RADISSON COURT
Mailing City,State,Zip:	SYRACUSE, NY 13202
Owner Name: Not reported	
Owner Type:	Not reported
Operator Name: Not reported	
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

SYRACUSE HOUSING AUTH - PIONEER HOMES (Continued) **1010566800**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: SYRACUSE HOUSING AUTH	
Legal Status:	Other
Date Became Current:	19400101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: SYRACUSE HOUSING AUTH	
Legal Status:	Other
Date Became Current:	19400101
Date Ended Current:	Not reported
Owner/Operator Address:	516 BURT ST

SYRACUSE HOUSING AUTH - PIONEER HOMES (Continued) **1010566800**

Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20080205
Handler Name: SYRACUSE HOUSING AUTH - PIONEER HOMES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080206
Handler Name: SYRACUSE HOUSING AUTH - PIONEER HOMES
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92511
NAICS Description: Administration Of Housing Programs

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYR000154476
Country: USA
Name: Syracuse Housing Auth - Pioneer Homes
Address: 116-118 RADISSON COURT
Address 2: Not reported
City,State,Zip: SYRACUSE, NY 13202
Zip 4: Not reported
Location Address 1: 116-118 RADISSON COURT
Location Address 2: Not reported
Location City,State,Zip: SYRACUSE, NY 13202

SYRACUSE HOUSING AUTH - PIONEER HOMES (Continued) **1010566800**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Syracuse Housing Auth - Pioneer Homes
Mailing Contact: William Gekrke
Mailing Address 1: 516 BURT ST
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13202
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154704315

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYR000115733
Year: 2018
Trans2 State ID: NYD980761191
Generator Ship Date: 03/12/2008
Trans1 Recv Date: 03/12/2008
Trans2 Recv Date: 03/21/2008
TSD Site Recv Date: 03/25/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000154476
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: PAD067098822
TSDF ID 2: Not reported
Manifest Tracking Number: 000885784FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Corrosive Waste
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 30

SYRACUSE HOUSING AUTH - PIONEER HOMES (Continued) **1010566800**

Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

G28 **PARKING LOT- 111 RADISON COURT** **NY Spills** **S126996788**
North **111 RADISON CT** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.083 mi.
437 ft. **Site 2 of 2 in cluster G**

Relative: **Lower**

Actual: **402 ft.**

SPILLS:

Name:	PARKING LOT- 111 RADISON COURT
Address:	111 RADISON CT
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	2005041 / 2022-05-13
Facility ID:	2005041
Facility Type:	ER
DER Facility ID:	559030
Site ID:	610813
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	B1
SWIS:	3415
Spill Date:	2020-09-01
Investigator:	CFNORRIS
Referred To:	Not reported
Reported to Dept:	2020-09-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2020-09-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-09-01
Spill Record Last Update:	2022-06-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ASHLEY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	RP HIT DEBRIS ON HIGHWAY. HER GAS TANK AND TIRE WERE PUNCTURED. TANK PLUG FAILED, AND GAS LEAKED ONTO PARKING LOT OUTSIDE RP'S SISTER'S APARTMENT ON RADISSON COURT. SYRACUSE FD NOTIFIED AFTER PROGRESSIVE RECOMMENDATION. FD PUT DOWN SPEEDY-DRI AND NOTIFIED HOTLINE. I TOOK 15 MINUTES TO REACH SPILL SITE. FD WAS ALREADY OFF-SITE. PROGRESSIVE HIRED TOW COMPANY, BUT THEY WERE NOT PREPARED TO REMOVE SPEEDY-DRI OR CONTINUE LOCATION DECOMMTAMINATION. I HIRED NRC

PARKING LOT- 111 RADISON COURT (Continued) **S126996788**

TO CLEAR PARKING LOT OF
GASOLINE SPILL. A MAN CAME OVER TO TALK TO FEMALE DRIVER. I DO NOT KNOW IF THAT WAS THE REGISTERED
VEHICLE OWNER. VEHICLE PLATE IS JRP-7723. FEMALE DRIVER NAME IS UNKNOWN. 11/2021 I CALLED SYRACUSE
FIRE. THEY WERE UNABLE TO SUPPLY REPORTS WITHOUT A FEE. 06/06/2022 I DECIDED TO CONTACT THE SHERIFF
RECORDS, IN CASE THEY HAD A CONTACT WITH CITY FIRE. THE SHERIFF RECORDS CONTACT STATED THAT THE
SHERIFF HAS ACCESS TO CITY FIRE REPORTS, BUT, THIS SPILL HAS NO REPORT. IT WAS LISTED AS A HAZARD
CALL (E10), AND WITHDRAWN. THE DR NUMBER IS DR 20-41725.

Remarks: c/u pending

All Materials:

Site ID:	610813
Operable Unit ID:	1357959
Operable Unit:	01
Material ID:	2369387
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	PARKING LOT- 111 RADISON COURT
Address:	111 RADISON CT
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	2005041 / 2022-05-13
Facility ID:	2005041
Facility Type:	ER
DER Facility ID:	559030
Site ID:	610813
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	B1
SWIS:	3415
Spill Date:	2020-09-01
Investigator:	CFNORRIS
Referred To:	Not reported
Reported to Dept:	2020-09-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2020-09-01
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-09-01
Spill Record Last Update:	2022-06-06

PARKING LOT- 111 RADISON COURT (Continued) **S126996788**

Spiller Name:	tyrone j english jr
Spiller Company:	registered car owner
Spiller Address:	614 oakwood ave
Spiller Company:	999
Contact Name:	ASHLEY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	RP HIT DEBRIS ON HIGHWAY. HER GAS TANK AND TIRE WERE PUNCTURED. TANK PLUG FAILED, AND GAS LEAKED ONTO PARKING LOT OUTSIDE RP'S SISTER'S APARTMENT ON RADISSON COURT. SYRACUSE FD NOTIFIED AFTER PROGRESSIVE RECOMMENDATION. FD PUT DOWN SPEEDY-DRI AND NOTIFIED HOTLINE. I TOOK 15 MINUTES TO REACH SPILL SITE. FD WAS ALREADY OFF-SITE. PROGRESSIVE HIRED TOW COMPANY, BUT THEY WERE NOT PREPARED TO REMOVE SPEEDY-DRI OR CONTINUE LOCATION DECOMMTAMINATION. I HIRED NRC TO CLEAR PARKING LOT OF GASOLINE SPILL. A MAN CAME OVER TO TALK TO FEMALE DRIVER. I DO NOT KNOW IF THAT WAS THE REGISTERED VEHICLE OWNER. VEHICLE PLATE IS JRP-7723. FEMALE DRIVER NAME IS UNKNOWN. 11/2021 I CALLED SYRACUSE FIRE. THEY WERE UNABLE TO SUPPLY REPORTS WITHOUT A FEE. 06/06/2022 I DECIDED TO CONTACT THE SHERIFF RECORDS, IN CASE THEY HAD A CONTACT WITH CITY FIRE. THE SHERIFF RECORDS CONTACT STATED THAT THE SHERIFF HAS ACCESS TO CITY FIRE REPORTS, BUT, THIS SPILL HAS NO REPORT. IT WAS LISTED AS A HAZARD CALL (E10), AND WITHDRAWN. THE DR NUMBER IS DR 20-41725.
Remarks:	c/u pending

All Materials:

Site ID:	610813
Operable Unit ID:	1357959
Operable Unit:	01
Material ID:	2369387
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

H29 **DI PINO ANTHONY** **EDR Hist Auto** **1021064592**
West **1117 SOUTH STATE ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.095 mi.
503 ft. **Site 1 of 2 in cluster H**

Relative: EDR Hist Auto
Lower

Actual:
399 ft.

Year:	Name:	Type:
1969	DI PINO ANTHONY	Gasoline Service Stations
1969	HALLIDAY HARRY B	General Automotive Repair Shops
1970	HALLIDAY HARRY B	General Automotive Repair Shops

DI PINO ANTHONY (Continued) **1021064592**

1970	DI PINO ANTHONY	Gasoline Service Stations
1971	HALLIDAY HARRY B	General Automotive Repair Shops
1971	DI PINO ANTHONY	Gasoline Service Stations
1972	DI PINO ANTHONY	Gasoline Service Stations
1972	HALLIDAY HARRY B	General Automotive Repair Shops
1973	HALLIDAY HARRY B	General Automotive Repair Shops
1973	DI PINO ANTHONY	Gasoline Service Stations
1974	HALLIDAY HARRY B	General Automotive Repair Shops
1974	DI PINO ANTHONY	Gasoline Service Stations
1975	HALLIDAY HARRY B	General Automotive Repair Shops
1975	DI PINO ANTHONY	Gasoline Service Stations
1976	HALLIDAY HARRY B	General Automotive Repair Shops
1976	DI PINO ANTHONY	Gasoline Service Stations
1977	HALLIDAY HARRY B	General Automotive Repair Shops
1977	DI PINO ANTHONY	Gasoline Service Stations

H30 **FORMER SALVATION ARMY PROPERTY** **NY UST** **U004046802**
West **1117 SOUTH STATE ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.095 mi.
503 ft. **Site 2 of 2 in cluster H**

Relative: **Lower**

Actual: **399 ft.**

UST:

Name:	FORMER SALVATION ARMY PROPERTY
Address:	1117 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-601001 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	N/A
UTM X:	406603.83375
UTM Y:	4765746.98664
Site Type:	Other

Affiliation Records:

Site Id:	333717
Affiliation Type:	Mail Contact
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	DAVID FICKENSHER
Address1:	516 BURT ST.
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 475-6181
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2004-11-17

Site Id:	333717
Affiliation Type:	Facility Operator
Company Name:	FORMER SALVATION ARMY PROPERTY
Contact Type:	Not reported
Contact Name:	N\\A

FORMER SALVATION ARMY PROPERTY (Continued) **U004046802**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 475-6181
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2004-11-17

Site Id:	333717
Affiliation Type:	Emergency Contact
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	N\\A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 475-6181
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2004-11-17

Site Id:	333717
Affiliation Type:	Facility Owner
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	516 BURT ST.
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 475-6181
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2004-11-17

Tank Info:

Tank Number:	001
Tank ID:	180870
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

FORMER SALVATION ARMY PROPERTY (Continued) **U004046802**

Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
I00 - Overfill - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J00 - Dispenser - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 002
Tank ID: 180871
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
J00 - Dispenser - None
B00 - Tank External Protection - None

FORMER SALVATION ARMY PROPERTY (Continued) **U004046802**

F00 - Pipe External Protection - None

Tank Number:	003
Tank ID:	180872
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	180873
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

FORMER SALVATION ARMY PROPERTY (Continued) **U004046802**

Equipment Records:

L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
K00 - Spill Prevention - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

D31 **ROTH BROS METAL CO.** **SEMS-ARCHIVE** **1015754900**
WNW **1107 S. STATE STREET** **LEAD SMELTERS** **NYN000206645**
< 1/8 **SYRACUSE, NY 01320**
0.096 mi.
505 ft. **Site 2 of 9 in cluster D**

Relative: **Lower**
Actual: **399 ft.**

SEMS Archive:

Site ID:	0206645
EPA ID:	NYN000206645
Name:	ROTH BROS METAL CO.
Address:	1107 S. STATE STREET
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Cong District:	Not reported
FIPS Code:	36067
FF:	N
NPL:	Not on the NPL
Non NPL Status:	Referred to Removal - NFRAP

SEMS Archive Detail:

Region:	02
Site ID:	0206645
EPA ID:	NYN000206645
Site Name:	ROTH BROS METAL CO.
NPL:	N
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	2015-08-05 05:00:00
Finish Date:	2015-08-05 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206645
EPA ID:	NYN000206645
Site Name:	ROTH BROS METAL CO.
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA

ROTH BROS METAL CO. (Continued) **1015754900**

SEQ: 1
Start Date: 2013-05-10 05:00:00
Finish Date: 2013-06-26 05:00:00
Qual: N
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206645
EPA ID: NYN000206645
Site Name: ROTH BROS METAL CO.
NPL: N
FF: N
OU: 00
Action Code: HX
Action Name: PRE-CERC
SEQ: 1
Start Date: Not reported
Finish Date: 2012-11-28 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0206645
EPA ID: NYN000206645
Site Name: ROTH BROS METAL CO.
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 2012-11-28 05:00:00
Finish Date: 2012-11-28 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Lead Smelter Sites:
Site ID: 0206645
Facility Region Id: 02
Latitude: Not reported
Longitude: Not reported
CoC Ind: Not reported
Contaminant Name: Not reported
FF Ind: N
NAI: N
Non-Primary Site-Sub Type: Not reported
NPL: Not on the NPL
Primary Site-Sub Type: Batteries/scrap metals/secondary smelting/precious metal recovery (Recycling);
Special Initiative: Not reported

D32 **THE SALVATION ARMY** **NY UST** **U000415424**
WNW **1105 S. STATE ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.096 mi.
506 ft. **Site 3 of 9 in cluster D**

Relative:
Lower

Actual:
399 ft.

UST:

Name:	THE SALVATION ARMY
Address:	1105 S. STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-128058 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	N/A
UTM X:	406539.18601
UTM Y:	4765799.29374
Site Type:	Other

Affiliation Records:

Site Id:	44653
Affiliation Type:	Facility Operator
Company Name:	THE SALVATION ARMY
Contact Type:	Not reported
Contact Name:	THE SALVATION ARMY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 583-3500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	44653
Affiliation Type:	Facility Owner
Company Name:	THE SALVATION ARMY INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	440 W. NYACK RD.
Address2:	Not reported
City:	WEST NYACK
State:	NY
Zip Code:	10994
Country Code:	001
Phone:	(212) 337-4779
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	44653
Affiliation Type:	Mail Contact
Company Name:	THE SALVATION ARMY INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	440 W. NYACK RD.

THE SALVATION ARMY (Continued) **U000415424**

Address2:	P.O. BOX C-635
City:	W. NYACK
State:	NY
Zip Code:	10994-0635
Country Code:	001
Phone:	(914) 620-4779
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	44653
Affiliation Type:	Emergency Contact
Company Name:	THE SALVATION ARMY INC.
Contact Type:	Not reported
Contact Name:	S. TIMOTHY LANTS, CAPTAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 475-9983
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	128169
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	12/01/1986
Date Tank Closed:	01/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B02 - Tank External Protection - Original Sacrificial Anode
C00 - Pipe Location - No Piping

THE SALVATION ARMY (Continued) **U000415424**

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

D33 **SPILL NUMBER 8601904** **NY Spills** **S104643869**
WNW **1105 SOUTH STATE ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.096 mi.
506 ft. **Site 4 of 9 in cluster D**

Relative: **Lower**

Actual: **399 ft.**

SPILLS:

Name:	SPILL NUMBER 8601904
Address:	1105 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8601904 / 1987-08-11
Facility ID:	8601904
Facility Type:	ER
DER Facility ID:	59475
Site ID:	142087
DEC Region:	7
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	3415
Spill Date:	1986-06-19
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1986-06-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1987-08-11
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
Latitude:	43.0391313
Longitude:	-76.1473662
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : DEC INVEST. & TOLD F.D. TO USE SORBENT & SAND THE REST.
Remarks:	ON PAVEMENT-55 GAL. DRUM FELL OFF TRUCK-F.D. ON SCENE

All Materials:

Site ID:	142087
Operable Unit ID:	898181
Operable Unit:	01
Material ID:	478370
Material Code:	0028A
Material Name:	ethylene glycol

SPILL NUMBER 8601904 (Continued) **S104643869**

Case No.:	00107211
Material FA:	Hazardous Material
Quantity:	30.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D34 WNW < 1/8 0.096 mi. 506 ft. **EAST ADAMS REDEVELOPMENT - PHASE II AREA** **NY BROWNFIELDS S131764066**
1105-1117 SOUTH STATE STREET **NY PFAS N/A**
SYRACUSE, NY 13202

Site 5 of 9 in cluster D

Relative: Lower

Actual: 399 ft.

BROWNFIELDS:

Name:	EAST ADAMS REDEVELOPMENT - PHASE II AREA
Address:	1105-1117 SOUTH STATE STREET
City,State,Zip:	SYRACUSE, NY 13202
Program:	BCP
Site Code:	659420
Acres:	2.540
HW Code:	C734163
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	12/06/2023
Record Updated Date:	01/08/2025
Update By:	GWPRISCO
Site Description:	"Location: The East Adams Redevelopment Phase II Area site (site) is located at 1105 1117 South State Street and is a 2.540-acre site located in an urban area within the City of Syracuse. The site is bound by a railroad to the north, Oakwood Avenue to the east, Burt Street to the south, and South State Street to the west. Site Features: The site is relatively flat with the topography of the surrounding area gently sloping towards the west-southwest. The site consists of a gravel lot and has no existing buildings at this time. Current Zoning and Land Use: The site is currently inactive and is located within a MX-2: Neighborhood Center District. The surrounding parcels are currently used for a combination of commercial, residential, and religious uses. Past Use of the Site: Historical site uses included both residential and commercial purposes including some petroleum storage use as early as 1910. By 1951, the southwestern portion of the site was developed with a gasoline station and automotive repair business. Additional uses of the site included a scrap yard, paper bailing, metal bailing, and most recently a Salvation Army warehouse, which was present from 1961 to 2003. In the early 2000s, the former buildings were demolished, and the site was configured into its current state as a gravel parking lot. Site Geology and Hydrogeology: The site elevation ranges from 397 to 399 feet above mean sea level. The site is underlain by a fill layer that extends to between about 1.5 and 9.5 feet below ground surface (ft bgs). The fill predominantly consists of tan to dark brown fine-grained sand with varying amounts of silt, clay, gravel, brick, concrete, fibrous vegetation, roots, construction debris, glass, asphalt, wood, coal, slag, and metal. The fill layer is underlain by native soil that predominantly consists of gray to brown fine-grained sand with varying amounts of clay, silt, and gravel. Bedrock was not encountered at soil boring depths down to 23 ft bgs.

EAST ADAMS REDEVELOPMENT - PHASE II AREA (Continued) **S131764066**

Env Problem:

Groundwater depth ranges from approximately 7.93 to 11.48 ft bgs. The groundwater elevation is highest in the northeastern part of the site. Generalized groundwater flow at the site is to the southwest. " "Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), herbicides, and pesticides. Soil vapor samples and an outdoor air sample were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, and metals in soil as well as PFOS and PFOA in groundwater. VOCs are primary contaminants of concern in soil vapor as well. Soils: Nine VOCs were detected at concentrations exceeding the unrestricted use soil cleanup objectives (UUSCOs), protection of groundwater soil cleanup objectives (PGSCOs), and/or restricted residential soil cleanup objectives (RRSCOs)(SCOs). All VOC detections were in the northwest corner of the site. Six VOCs were detected at concentrations exceeding UUSCOs which include: acetone at a maximum concentration of 0.42 parts per million (ppm) (UUSCO 0.05ppm), ethylbenzene at a maximum concentration of 39 ppm (UUSCO 1.0 ppm), naphthalene at a maximum concentration of 58 ppm (UUSCO 12 ppm), n-butylbenzene at a maximum concentration of 20 ppm (UUSCO 12 ppm), n-propylbenzene at a maximum concentration of 52 ppm (UUSCO 3.9 ppm), and sec-butylbenzene at a maximum concentration of 13 ppm (UUSCO 11 ppm). Two VOCs detected at concentrations exceeding RRSCOs include: 1,2,4- trimethylbenzene which was detected at a maximum concentration of 380 ppm (RRSCO 52 ppm) and total xylenes with a maximum concentration of 180 ppm (RRSCO 100 ppm). One VOC, 1,3,5- trimethylbenzene (mesitylene), was detected at concentrations exceeding the PGSCO with a maximum concentration of 120 ppm (PGSCO 8.4 ppm). SVOCs detected sitewide at concentrations exceeding the PGSCOs occurred for two constituents which include benzo(a)anthracene at a maximum concentration of 6.6 ppm (PGSCO 1.0 ppm) and benzo(b)fluoranthene at a maximum concentration of 8.2 ppm (PGSCO 1.7 ppm). Four SVOCs were detected at concentrations exceeding RRSCOs which include: benzo(a)pyrene at a maximum concentration of 6.8 ppm (RRSCO 1.0 ppm), chrysene at a maximum concentration of 6.4 ppm (RRSCO 3.9 ppm), dibenz(a,h)anthracene at a maximum concentration of 1.0 ppm (RRSCO 0.33 ppm), and indeno(1,2,3- cd)pyrene at a maximum concentration of 4.6 ppm (RRSCO 0.5 ppm). One SVOC, benzo(k)fluoranthene was detected in eight samples at a concentration exceeding the UUSCO with a maximum concentration of 2.6 ppm (UUSCO 0.8 ppm). Four pesticides were detected at concentrations exceeding UUSCOs which include: 4,4'-DDD at a maximum concentration of 0.0412 ppm (UUSCO 0.0033 ppm), 4,4'-DDE at a maximum concentration of 0.12 ppm (UUSCO 0.0033 ppm), 4,4'-DDT at a maximum concentration of 1.19ppm (UUSCO 0.0033 ppm), and dieldrin at a maximum concentration of 0.0261 ppm (UUSCO 0.005 ppm). Four metals were detected at concentrations exceeding UUSCOs which include: hexavalent chromium at a maximum concentration of 4.64 ppm (UUSCO 1.0 ppm), trivalent chromium at a maximum concentration of 74.5 ppm (UUSCO 30 ppm), nickel at a maximum concentration of 81.9 ppm (UUSCO 30 ppm), and zinc at a maximum concentration of 2620 ppm (UUSCO 109 ppm). Six metals were detected sitewide at concentrations exceeding RRSCOs include: arsenic which was detected at a maximum concentration of 19.9 ppm (RRSCO 16 ppm), barium with a maximum concentration of 785 ppm (RRSCO 400 ppm), cadmium with a maximum concentration of 7.66 ppm (RRSCO 4.3 ppm), copper with a maximum concentration of 1390 ppm

EAST ADAMS REDEVELOPMENT - PHASE II AREA (Continued) **S131764066**

(RRSCO 270 ppm), lead with a maximum concentration of 1660 ppm (RRSCO 400 ppm), and mercury with a maximum concentration of 68 ppm (RRSCO 0.81 ppm), One metal, manganese, was detected at concentrations exceeding the PGSCOs with a maximum concentration of 3290 ppm (PGSCO 2000 ppm). Perfluorooctanesulfonic acid (PFOS) was detected in eight soil sample above UUSCOs and in seven soil samples above PGSCOs with a maximum concentration of 0.00293 parts per billion (ppb) compared to the PGSCO of 0.001 ppb. Perflurorooctanoic acid (PFOA) was not detected in concentrations exceeding the PGSCO. There were no herbicides detected in soil at concentrations exceeding applicable SCOs. Data does not indicate that there are off-site impacts in soil related to this site. Groundwater: Groundwater sample results were compared to the NYS Ambient Water Quality Standards and Guidance Values (groundwater SCGs). VOCs exceeding applicable groundwater standards, criteria, and guidance (SCGs) occurred in three out of 11 groundwater monitoring wells across the site including 1,2,4,5-tetramethylbenzene at a maximum concentration of 8.9 ppb (SCG 5 ppb) and 1,3,5- trimethylbenzene (mesitylene) at a maximum concentration of 11 ppb (SCG 5 ppb). SVOCs exceeding groundwater SCGs occurred in two out of 11 groundwater monitoring wells across the site including benzo(a)anthracene at a maximum concentration of 0.03 ppb (SCG 0.002 ppb), benzo(b)fluoranthene at a maximum concentration of 0.03 ppb SCG 0.002 ppb), and phenol at a maximum concentration of 2.7 (SCG 1.0 ppb). Five metals in both the dissolved phase and in total exceeded groundwater SCGs throughout the site which include: iron at a maximum concentration of 2,220 ppb (dissolved) and 8,330 ppb (total) (SCG 300 ppb), magnesium at a maximum concentration of 52,400 ppb (dissolved) and 52,600 ppb (total) (SCG 3000 ppb), manganese at a maximum concentration of 13,190 ppb (dissolved) and 13,850 ppb (total) (SCG 300 ppb), selenium at a maximum concentration of 14.4 ppb (dissolved) and 14.6 ppb (total) (SCG 10 ppb), and sodium at a maximum concentration of 208,000 ppb (dissolved) and 220,000 ppb (total) (SCG 20,000 ppb). PFOS was detected in three out of 11 groundwater monitoring wells at concentrations above the applicable groundwater SCG with a maximum detection of 0.0124 ppb (SCG 0.0027 ppb). PFOA and 1,4 Dioxane were not detected in the groundwater monitoring samples above applicable groundwater SCGs. No pesticides, herbicides, or PCBs were detected at concentrations above groundwater SCGs. Data does not indicate that there are off-site impacts in groundwater related to this site. Soil Vapor: Various petroleum VOCs were detected sitewide in the soil vapor samples, most notably hexane at a maximum concentration of 916 micrograms per cubic meter (g/m3). Several chlorinated solvents were detected in the soil vapor samples, most notably tetrachloroethylene at a maximum concentration of 564 g/m3. Data does not indicate any off-site impacts in soil vapor related to this site. "

Health Problem: "The site is completely fenced which restricts public access. Persons who enter the site may come into contact with contaminants in soil by digging below surface soil or otherwise disturbing soil beneath the packed gravel surface. Contaminated groundwater at the site is not used for drinking or other purposes, since the site is served by a public water supply that obtains its water from a source not affected by site contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Soil vapor intrusion is not a current

EAST ADAMS REDEVELOPMENT - PHASE II AREA (Continued) **S131764066**

	concern on-site because the site is vacant; however, the potential exists for the inhalation of site contaminants due to soil vapor intrusion in any future on-site buildings. Environmental sampling indicates that soil vapor intrusion is not a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2024-03-13 10:07:00
Record Upd:	2024-03-14 08:33:00
Updated By:	AYRUSSO
Own Op:	4
Sub Type:	C01
Owner Name:	William J. Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Allyson Carpenter
Owner Company:	East Adams Phase II, L.P.
Owner Address:	100 North Broadway, Suite 100
Owner Addr2:	Not reported
Owner City,St,Zip:	St. Louis, MO 63102
Owner Country:	United States of America
Own Op:	1
Sub Type:	C01
Owner Name:	William J. Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Dan Smith
Owner Company:	Onondaga County Public Library Central Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13205
Owner Country:	United States of America
HW Code:	C734163
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

EAST ADAMS REDEVELOPMENT - PHASE II AREA (Continued) **S131764066**

HW Code:	C734163
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	perfluorooctane sulfonic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	polychlorinated biphenyls (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734163
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2208975
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2024-08-22 09:39:00
Record Updated:	2024-08-22 09:39:00
Updated By:	CFNORRIS

PFAS 3:

Name:	EAST ADAMS REDEVELOPMENT - PHASE II AREA

EAST ADAMS REDEVELOPMENT - PHASE II AREA (Continued) **S131764066**

Address:	1105-1117 SOUTH STATE STREET
City,State,Zip:	SYRACUSE, NY 13202
Site Code:	659420
HW Code:	C734163
Program:	BCP
Class Code:	A
Region:	7
Acres:	2.540
Date Record Added:	12/06/2023
Date Record Updated:	01/08/2025
Water Quantity:	UNKNOWN
Updated By:	GWPRISCO
Site Description:	"Location: The East Adams Redevelopment Phase II Area site (site) is located at 1105 1117 South State Street and is a 2.540-acre site located in an urban area within the City of Syracuse. The site is bound by a railroad to the north, Oakwood Avenue to the east, Burt Street to the south, and South State Street to the west. Site Features: The site is relatively flat with the topography of the surrounding area gently sloping towards the west-southwest. The site consists of a gravel lot and has no existing buildings at this time. Current Zoning and Land Use: The site is currently inactive and is located within a MX-2: Neighborhood Center District. The surrounding parcels are currently used for a combination of commercial, residential, and religious uses. Past Use of the Site: Historical site uses included both residential and commercial purposes including some petroleum storage use as early as 1910. By 1951, the southwestern portion of the site was developed with a gasoline station and automotive repair business. Additional uses of the site included a scrap yard, paper bailing, metal bailing, and most recently a Salvation Army warehouse, which was present from 1961 to 2003. In the early 2000s, the former buildings were demolished, and the site was configured into its current state as a gravel parking lot. Site Geology and Hydrogeology: The site elevation ranges from 397 to 399 feet above mean sea level. The site is underlain by a fill layer that extends to between about 1.5 and 9.5 feet below ground surface (ft bgs). The fill predominantly consists of tan to dark brown fine-grained sand with varying amounts of silt, clay, gravel, brick, concrete, fibrous vegetation, roots, construction debris, glass, asphalt, wood, coal, slag, and metal. The fill layer is underlain by native soil that predominantly consists of gray to brown fine-grained sand with varying amounts of clay, silt, and gravel. Bedrock was not encountered at soil boring depths down to 23 ft bgs. Groundwater depth ranges from approximately 7.93 to 11.48 ft bgs. The groundwater elevation is highest in the northeastern part of the site. Generalized groundwater flow at the site is to the southwest. "
Summary:	"The site is completely fenced which restricts public access. Persons who enter the site may come into contact with contaminants in soil by digging below surface soil or otherwise disturbing soil beneath the packed gravel surface. Contaminated groundwater at the site is not used for drinking or other purposes, since the site is served by a public water supply that obtains its water from a source not affected by site contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Soil vapor intrusion is not a current

EAST ADAMS REDEVELOPMENT - PHASE II AREA (Continued) **S131764066**

concern on-site because the site is vacant; however, the potential exists for the inhalation of site contaminants due to soil vapor intrusion in any future on-site buildings. Environmental sampling indicates that soil vapor intrusion is not a concern for off-site buildings."

Summary:

"Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), herbicides, and pesticides. Soil vapor samples and an outdoor air sample were analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern include VOCs, SVOCs, and metals in soil as well as PFOS and PFOA in groundwater. VOCs are primary contaminants of concern in soil vapor as well. Soils: Nine VOCs were detected at concentrations exceeding the unrestricted use soil cleanup objectives (UUSCOs), protection of groundwater soil cleanup objectives (PGSCOs), and/or restricted residential soil cleanup objectives (RRSCOs)(SCOs). All VOC detections were in the northwest corner of the site. Six VOCs were detected at concentrations exceeding UUSCOs which include: acetone at a maximum concentration of 0.42 parts per million (ppm) (UUSCO 0.05ppm), ethylbenzene at a maximum concentration of 39 ppm (UUSCO 1.0 ppm), naphthalene at a maximum concentration of 58 ppm (UUSCO 12 ppm), n-butylbenzene at a maximum concentration of 20 ppm (UUSCO 12 ppm), n-propylbenzene at a maximum concentration of 52 ppm (UUSCO 3.9 ppm), and sec-butylbenzene at a maximum concentration of 13 ppm (UUSCO 11 ppm). Two VOCs detected at concentrations exceeding RRSCOs include: 1,2,4- trimethylbenzene which was detected at a maximum concentration of 380 ppm (RRSCO 52 ppm) and total xylenes with a maximum concentration of 180 ppm (RRSCO 100 ppm). One VOC, 1,3,5- trimethylbenzene (mesitylene), was detected at concentrations exceeding the PGSCO with a maximum concentration of 120 ppm (PGSCO 8.4 ppm). SVOCs detected sitewide at concentrations exceeding the PGSCOs occurred for two constituents which include benzo(a)anthracene at a maximum concentration of 6.6 ppm (PGSCO 1.0 ppm) and benzo(b)fluoranthene at a maximum concentration of 8.2 ppm (PGSCO 1.7 ppm). Four SVOCs were detected at concentrations exceeding RRSCOs which include: benzo(a)pyrene at a maximum concentration of 6.8 ppm (RRSCO 1.0 ppm), chrysene at a maximum concentration of 6.4 ppm (RRSCO 3.9 ppm), dibenz(a,h)anthracene at a maximum concentration of 1.0 ppm (RRSCO 0.33 ppm), and indeno(1,2,3- cd)pyrene at a maximum concentration of 4.6 ppm (RRSCO 0.5 ppm). One SVOC, benzo(k)fluoranthene was detected in eight samples at a concentration exceeding the UUSCO with a maximum concentration of 2.6 ppm (UUSCO 0.8 ppm). Four pesticides were detected at concentrations exceeding UUSCOs which include: 4,4'-DDD at a maximum concentration of 0.0412 ppm (UUSCO 0.0033 ppm), 4,4'-DDE at a maximum concentration of 0.12 ppm (UUSCO 0.0033 ppm), 4,4'-DDT at a maximum concentration of 1.19ppm (UUSCO 0.0033 ppm), and dieldrin at a maximum concentration of 0.0261 ppm (UUSCO 0.005 ppm). Four metals were detected at concentrations exceeding UUSCOs which include: hexavalent chromium at a maximum concentration of 4.64 ppm (UUSCO 1.0 ppm), trivalent chromium at a maximum concentration of 74.5 ppm (UUSCO 30 ppm), nickel at a maximum concentration of 81.9 ppm (UUSCO 30 ppm), and zinc at a maximum concentration of 2620 ppm (UUSCO 109 ppm). Six metals were detected sitewide at concentrations exceeding RRSCOs include: arsenic which was detected at a maximum concentration of

EAST ADAMS REDEVELOPMENT - PHASE II AREA (Continued) **S131764066**

19.9 ppm (RRSCO 16 ppm), barium with a maximum concentration of 785 ppm (RRSCO 400 ppm), cadmium with a maximum concentration of 7.66 ppm (RRSCO 4.3 ppm), copper with a maximum concentration of 1390 ppm (RRSCO 270 ppm), lead with a maximum concentration of 1660 ppm (RRSCO 400 ppm), and mercury with a maximum concentration of 68 ppm (RRSCO 0.81 ppm), One metal, manganese, was detected at concentrations exceeding the PGSCOs with a maximum concentration of 3290 ppm (PGSCO 2000 ppm). Perfluorooctanesulfonic acid (PFOS) was detected in eight soil sample above UUSCOs and in seven soil samples above PGSCOs with a maximum concentration of 0.00293 parts per billion (ppb) compared to the PGSCO of 0.001 ppb. Perfluorooctanoic acid (PFOA) was not detected in concentrations exceeding the PGSCO. There were no herbicides detected in soil at concentrations exceeding applicable SCOs. Data does not indicate that there are off-site impacts in soil related to this site. Groundwater: Groundwater sample results were compared to the NYS Ambient Water Quality Standards and Guidance Values (groundwater SCGs). VOCs exceeding applicable groundwater standards, criteria, and guidance (SCGs) occurred in three out of 11 groundwater monitoring wells across the site including 1,2,4,5-tetramethylbenzene at a maximum concentration of 8.9 ppb (SCG 5 ppb) and 1,3,5- trimethylbenzene (mesitylene) at a maximum concentration of 11 ppb (SCG 5 ppb). SVOCs exceeding groundwater SCGs occurred in two out of 11 groundwater monitoring wells across the site including benzo(a)anthracene at a maximum concentration of 0.03 ppb (SCG 0.002 ppb), benzo(b)fluoranthene at a maximum concentration of 0.03 ppb SCG 0.002 ppb), and phenol at a maximum concentration of 2.7 (SCG 1.0 ppb). Five metals in both the dissolved phase and in total exceeded groundwater SCGs throughout the site which include: iron at a maximum concentration of 2,220 ppb (dissolved) and 8,330 ppb (total) (SCG 300 ppb), magnesium at a maximum concentration of 52,400 ppb (dissolved) and 52,600 ppb (total) (SCG 3000 ppb), manganese at a maximum concentration of 13,190 ppb (dissolved) and 13,850 ppb (total) (SCG 300 ppb), selenium at a maximum concentration of 14.4 ppb (dissolved) and 14.6 ppb (total) (SCG 10 ppb), and sodium at a maximum concentration of 208,000 ppb (dissolved) and 220,000 ppb (total) (SCG 20,000 ppb). PFOS was detected in three out of 11 groundwater monitoring wells at concentrations above the applicable groundwater SCG with a maximum detection of 0.0124 ppb (SCG 0.0027 ppb). PFOA and 1,4 Dioxane were not detected in the groundwater monitoring samples above applicable groundwater SCGs. No pesticides, herbicides, or PCBs were detected at concentrations above groundwater SCGs. Data does not indicate that there are off-site impacts in groundwater related to this site. Soil Vapor: Various petroleum VOCs were detected sitewide in the soil vapor samples, most notably hexane at a maximum concentration of 916 micrograms per cubic meter (g/m3). Several chlorinated solvents were detected in the soil vapor samples, most notably tetrachloroethylene at a maximum concentration of 564 g/m3. Data does not indicate any off-site impacts in soil vapor related to this site. "

Water Type: perfluorooctane sulfonic acid

PFAS 3:
Water Type: perfluorooctanoic acid

D35 **FORMER SALVATION ARMY** **UST FINDER RELEASE** **1029076786**
WNW **1105 SOUTH STATE ST** **N/A**
< 1/8 **SYRACUSE, NY 0**
0.096 mi.
506 ft. **Site 6 of 9 in cluster D**

Relative: UST FINDER RELEASE:
Lower

Actual: Object ID:	249485
399 ft. Facility ID:	NY59475
Lust ID:	NY404882
Name:	FORMER SALVATION ARMY
Address:	1105 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	2004/08/04 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2276
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1473599999999
Y Coord:	43.0391300000001
Latitude:	43.03913
Longitude:	-76.14736

D36 **SALVATION ARMY** **UST FINDER RELEASE** **1029076787**
WNW **1105 SOUTH STATE ST** **N/A**
< 1/8 **SYRACUSE, NY 0**
0.096 mi.
506 ft. **Site 7 of 9 in cluster D**

Relative: UST FINDER RELEASE:
Lower

Actual: Object ID:	249484
399 ft. Facility ID:	NY59475
Lust ID:	NY9711143
Name:	SALVATION ARMY
Address:	1105 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1998/01/05 15:59:59+00
Status:	No Further Action

SALVATION ARMY (Continued) **1029076787**

Substance:	Not reported
Population within 1500ft:	2273
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.14737
Y Coord:	43.0391300000001
Latitude:	43.03913
Longitude:	-76.1473699999999

D37 **FORMER SALVATION ARMY** **NY LTANKS S102165578**
WNW **1105 SOUTH STATE ST** **NY Spills N/A**
< 1/8 **SYRACUSE, NY**
0.096 mi.
506 ft. **Site 8 of 9 in cluster D**

Relative: **Lower**
Actual: **399 ft.**

LTANKS:

Name:	FORMER SALVATION ARMY
Address:	1105 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0404882 / 2005-03-04
Facility ID:	0404882
Site ID:	61010
Spill Date:	2004-08-04
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	BFMATTHE
Referred To:	Not reported
Reported to Dept:	2004-08-04
CID:	403
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0

FORMER SALVATION ARMY (Continued) **S102165578**

Date Entered In Computer:	2004-08-04
Spill Record Last Update:	2005-03-04
Spiller Name:	DAVID FICKINGER
Spiller Company:	SALVATION ARMY
Spiller Address:	1105 SOUTH STATE ST
Spiller County:	999
Spiller Contact:	DAVID FICKINGER
Spiller Phone:	(315) 475-6181
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	59475
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BM
Remarks:	550 gallon tank.excavation.removing contaminated soil

All Materials:

Site ID:	61010
Operable Unit ID:	888280
Operable Unit:	01
Material ID:	488856
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	SALVATION ARMY
Address:	1105 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9711143 / 2002-08-06
Facility ID:	9711143
Facility Type:	ER
DER Facility ID:	59475
Site ID:	61011
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	1998-01-05
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1998-01-05
CID:	252
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

FORMER SALVATION ARMY (Continued) **S102165578**

UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-01-05
Spill Record Last Update:	2002-08-06
Spiller Name:	CAPT MUHS
Spiller Company:	SALVATION ARMY
Spiller Address:	1105 SOUTH STATE ST
Spiller Company:	001
Contact Name:	CAPT MUHS
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM LIMITED INFORMATION, CONTAMINATION MAY EXIST
Remarks:	SOIL CONTAMINATION DISCOVERED UNDER PUMP ISLAND DISPENSER. WILL BE STOCKPILED FOR REMOVAL.

D38 **THE SALVATION ARMY** **UST FINDER** **1028588420**
WNW **1105 S. STATE ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.096 mi.
506 ft. **Site 9 of 9 in cluster D**

Relative: **Lower**
Actual: **399 ft.**

UST FINDER:

Object ID:	318213
Facility ID:	NY44653
Name:	THE SALVATION ARMY
Address:	1105 S. STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	2276
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-76.147364
Y Coord:	43.039134
Latitude:	43.039134
Longitude:	-76.147364

UST FINDER:

THE SALVATION ARMY (Continued) **1028588420**

Object ID:	1276629
Facility ID:	NY44653
Tank ID:	NY70277
Tank Status:	Closed
Installation Date:	1986/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	5000
Substances:	Not reported
Tank Wall Type:	Not reported

E39 **COMMERCIAL - SOUTH STATE ST X BURT ST** **NY Spills** **S129993953**
WSW **CORNER OF SOUTH STATE ST AND BURT ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.098 mi.
519 ft. **Site 4 of 5 in cluster E**

Relative: **Lower**
Actual: **396 ft.**

SPILLS:

Name:	COMMERCIAL - SOUTH STATE ST X BURT ST
Address:	CORNER OF SOUTH STATE ST AND BURT ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2208975 / 2024-12-03
Facility ID:	2208975
Facility Type:	ER
DER Facility ID:	594437
Site ID:	648324
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3415
Spill Date:	2023-02-06
Investigator:	AYRUSSO
Referred To:	Not reported
Reported to Dept:	2023-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2023-02-06
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2023-02-06
Spill Record Last Update:	2024-12-04
Spiller Name:	Not reported
Spiller Company:	SYRCUSE HOUSING AUTHORITY
Spiller Address:	CORNER OF SOUTH STATE ST AND BURT ST
Spiller Company:	999
Contact Name:	ADAM ETRINGER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	PRODUCT FOUND 5-15'BG IN A PARKING AREA BEING INVESTIGATED DURING PHASE II ACTIVITIES. SYRACUSE HOUSING AUTHORITY ARE RP OF THE INVESTIGATION 04/04/2023 SITE PLACED INTO SITE MGMT PHASE AS WAITING FOR FUNDING FOR FURTHER ACTION. SPILL CONTAINED. 04/24/2023

COMMERCIAL - SOUTH STATE ST X BURT ST (Continued) **S129993953**

WORKING ON BROWNFIELD
APPLICATION, NO WORK PLANNED UNTIL AFTER APPLICATION IS REVIEWED.
02/13/2024 Site denied from BCP
program under ID Number C734161.

Remarks: Product of a phase two environmental investigation. Material was found in a subsurface five to fifteen feet below ground. First occurred on January 19th and January 20th. Unknown amount spilled.

All Materials:

Site ID:	648324
Operable Unit ID:	1395282
Operable Unit:	01
Material ID:	2411011
Material Code:	1429A
Material Name:	petroleum additive
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

F40 **STEWART COURT** **NY Spills** **S102561172**
East **BURT ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.099 mi.
524 ft. **Site 2 of 3 in cluster F**

Relative: **Higher**

Actual: **409 ft.**

SPILLS:

Name:	STEWART COURT
Address:	BURT ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9612359 / 1997-01-29
Facility ID:	9612359
Facility Type:	ER
DER Facility ID:	129432
Site ID:	152474
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	1996-12-26
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1997-01-16
CID:	266
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-16

STEWART COURT (Continued) **S102561172**

Spill Record Last Update:	2004-02-20
Spiller Name:	VINNY HUBER
Spiller Company:	STEWART COURT
Spiller Address:	BURT ST
Spiller Company:	001
Contact Name:	VINNY HUBER
Latitude:	43.0384799
Longitude:	-76.1419450
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM 2004/02/19 - Spill_Time was previously blank and replaced with RCVD_Time to fix a data translation problem... Bob Corcoran THIS SPILL MAY BE CROSS REFERENCED TO SPILL NO. 9612304.
Remarks:	ONGOING PROBLEM WITH TRANSFORMER LEAKING - CALLER WILL BE DOING CLEANUP ******* CALLER WOULD LIKE A CALL BACK

All Materials:

Site ID:	152474
Operable Unit ID:	1040228
Operable Unit:	01
Material ID:	341005
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

I41 **PROJECT ORANGE** **NY CBS** **1000790137**
ENE **520 E TAYLOR ST** **NY AST** **NYD987016136**
< 1/8 **SYRACUSE, NY 13202** **NY CBS AST**
0.101 mi. **NY Spills**
531 ft. **Site 1 of 5 in cluster I** **RCRA NonGen / NLR**
NY AIRS
Relative: Higher **NY MANIFEST**

Actual: 408 ft.

CBS:

Name:	PROJECT ORANGE
Address:	520 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY 13202
CBS Number:	7-000230
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	7
UTMX:	406845.00000
UTMY:	4765829.00000

AST:

Name:	PROJECT ORANGE
Address:	520 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY 13202
Region:	STATE
DEC Region:	7

PROJECT ORANGE (Continued) **1000790137**

Site Status: Unregulated/Closed
Facility Id: 7-000230
Program Type: CBS
UTM X: 406845.00000
UTM Y: 4765829.00000
Expiration Date: N/A
Site Type: Utility (Other than Municipal)

Tank Info:

Tank Number: T-100
Tank Id: 190104
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/1992
Capacity Gallons: 7000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/17/2011
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: T-200
Tank Id: 190105
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 04/01/1992
Capacity Gallons: 7000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 01/17/2011
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

CBS AST:

CBS Number: 7-000230
ICS Number: Not reported
PBS Number: Not reported
MOSF Number: Not reported
SPDES Number: Not reported
Facility Status: IN SERVICE
Facility Type: I
Telephone: (315) 474-8230
Facility Town: SYRACUSE (C)

PROJECT ORANGE (Continued) **1000790137**

Region:	STATE
Expiration Date:	04/29/2002
Total Capacity of All Active Tanks(gal):	14000
Operator:	GENERAL ELECTRIC
Emergency Contact:	JEFF GUYSKY
Emergency Phone:	(315) 474-8230
Owner Name:	PROJECT ORANGE ASSOCIATES, L.P.
Owner Address:	507 PLUM STREET
Owner City,St,Zip:	SYRACUSE, NY 13204
Owner Telephone:	(315) 460-3379
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	NIAGARA MOHAWK ENERGY
Mail Contact Addr:	507 PLUM STREET
Mail Contact Addr2:	Not reported
Mail Contact Contact:	JAMES C. FARATTA
Mail Contact City,St,Zip:	SYRACUSE, NY 13204
Mail Phone:	(315) 460-3379

Tank Id:	T-200
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	04/92
Tank Closed:	Not reported
Capacity (Gal):	7000
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/28/1992
Certified Date:	02/08/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Epoxy Liner
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	54
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	76|08|36 / 43|02|59
Is Updated:	False
Renew Date:	/ /
Is It There:	False
Delinquent:	False
Date Expired:	04/29/94
Owner Mark:	1
Certificate Needs to be Printed:	76|08|36 / 43|02|59

PROJECT ORANGE (Continued) **1000790137**

Fiscal Amt for Registration Fee Correct: 76|08|36 / 43|02|59
Renewal Has Been Printed for Facility: 76|08|36 / 43|02|59
Pre-Printed Renewal App Last Printed: 76|08|36 / 43|02|59

Tank Id:	T-100
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	04/92
Tank Closed:	Not reported
Capacity (Gal):	7000
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	04/28/1992
Certified Date:	02/08/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	54
Haz Percent:	93
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	76|08|36 / 43|02|59
Is Updated:	False
Renew Date:	/ /
Is It There:	False
Delinquent:	False
Date Expired:	04/29/94
Owner Mark:	1
Certificate Needs to be Printed:	76|08|36 / 43|02|59
Fiscal Amt for Registration Fee Correct:	76|08|36 / 43|02|59
Renewal Has Been Printed for Facility:	76|08|36 / 43|02|59
Pre-Printed Renewal App Last Printed:	76|08|36 / 43|02|59

SPILLS:

Name:	PROJECT ORANGE CO-GEN
Address:	520 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0001904 / 2002-06-03
Facility ID:	0001904
Facility Type:	ER
DER Facility ID:	184663
Site ID:	223336
DEC Region:	7

PROJECT ORANGE (Continued) **1000790137**

Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3415
Spill Date:	2000-05-15
Investigator:	CXROSSI
Referred To:	Not reported
Reported to Dept:	2000-05-15
CID:	397
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2000-05-15
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-15
Spill Record Last Update:	2002-06-03
Spiller Name:	JAMES MCCUMBER
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	029 LYMAN HALL
Spiller Company:	001
Contact Name:	CALLER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CTR
Remarks:	caller states his company has found fuel oil on thier property. caller would like a call to give specific location of spill

All Materials:

Site ID:	223336
Operable Unit ID:	823585
Operable Unit:	01
Material ID:	550288
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SYRACUSE UNIVERSITY STEAM STATION
Address:	520 EAST TAYLOR ST
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	1213761 / 2013-01-09
Facility ID:	1213761
Facility Type:	ER
DER Facility ID:	432291
Site ID:	476969
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	A3
SWIS:	3415

PROJECT ORANGE (Continued) **1000790137**

Spill Date:	2012-12-20
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2012-12-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	2012-12-20
Cleanup Meets Std:	False
Last Inspection:	2012-12-20
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-20
Spill Record Last Update:	2013-01-10
Spiller Name:	Not reported
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JAMES MCCUMBER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/20/2012 - Approx 1 gallon of 50% sulfuric acid released onto worker after flexible poly pipe burst, spraying area and worker. Worker immediately placed under water deluge shower, all clothing removed, and eyes rinsed. Approx 1 gallon of sulfuric acid flowed from water deluge area into nearby sanitary sewer. Site is not CBS regulated due to small bulk tank sizes (< 185 gallons), but chemical sulfuraic acid chemical is listed in part 597, so WEP and SU contacted hotline and Fire Department. FD and plant personnel placed sodium bicarb over acid sprayed to floor as well as into sewer in attmept to neutralize acid. Brazell notified for possible municipal notifcation requirement. KCKemp 1/9/2013 - Closure report received and filed. KCKemp
Remarks:	1 gallon possibly into floor drain - FD on scene now -

All Materials:

Site ID:	476969
Operable Unit ID:	1226782
Operable Unit:	01
Material ID:	2224144
Material Code:	0039A
Material Name:	sulfuric acid
Case No.:	07664939
Material FA:	Hazardous Material
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer, Impervious Surface
Oxygenate:	Not reported

Name: 520 E.TAYLOR ST.

PROJECT ORANGE (Continued) **1000790137**

Address:	520 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9211857 / 1993-03-02
Facility ID:	9211857
Facility Type:	ER
DER Facility ID:	184663
Site ID:	212315
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	3415
Spill Date:	1993-01-16
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1993-01-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-03-02
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-19
Spill Record Last Update:	1993-03-02
Spiller Name:	Not reported
Spiller Company:	STEWART AND STEVENSON OP.
Spiller Address:	520 E.TAYLOR ST.
Spiller Company:	001
Contact Name:	Not reported
Latitude:	43.0394313
Longitude:	-76.1434802
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR 01/19/93: ALLWASH HIRED TO WIPE DOWN EQUIPMENT SURROUNDING TRANSFORMER.
Remarks:	TRNSFORMER EXPLODED. OIL IN UNIT VAPORIZED AND BURNED.

All Materials:

Site ID:	212315
Operable Unit ID:	976296
Operable Unit:	01
Material ID:	405241
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	35.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20070101

PROJECT ORANGE (Continued) **1000790137**

Handler Name:		Project Orange
Handler Address:		E Taylor St
Handler City,State,Zip:		SYRACUSE, NY 13202
EPA ID:		NYD987016136
Contact Name:		TRACY JONES
Contact Address:		E TAYLOR ST
Contact City,State,Zip:		SYRACUSE, NY 13202
Contact Telephone:		315-474-8230
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		E TAYLOR ST
Mailing City,State,Zip:		SYRACUSE, NY 13202
Owner Name:	Project Orange Associates Lp	
Owner Type:		Private
Operator Name:	Project Orange Associates Lp	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No

PROJECT ORANGE (Continued) **1000790137**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PROJECT ORANGE ASSOCIATES LP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1100 TOWN & COUNTRY RD STE 800
Owner/Operator City,State,Zip:	ORANGE, CA 92668
Owner/Operator Telephone:	714-667-3800
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PROJECT ORANGE ASSOCIATES LP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1100 TOWN & COUNTRY RD STE 800
Owner/Operator City,State,Zip:	ORANGE, CA 92668
Owner/Operator Telephone:	714-667-3800
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PROJECT ORANGE ASSOCIATES LP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1100 TOWN & COUNTRY RD STE 800
Owner/Operator City,State,Zip:	ORANGE, CA 92668
Owner/Operator Telephone:	714-667-3800
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	PROJECT ORANGE
Federal Waste Generator Description:	Not a generator, verified

PROJECT ORANGE (Continued) **1000790137**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PROJECT ORANGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920928
Handler Name: PROJECT ORANGE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960226
Handler Name: STEWART & STEVENSON OPERATIONS, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: Electric Power Generation, Transmission And Distribution

NAICS Code: 22111
NAICS Description: Electric Power Generation

PROJECT ORANGE (Continued) **1000790137**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AIRS:

Name:	POA COGEN FAC/SYRACUSE UNIV STEAM STA
Address:	520 EAST TAYLOR STREET
City,State,Zip:	SYRACUSE, NY
DECID:	7311500229
Process ID:	E04EI
Latitude:	Not reported
Longitude:	Not reported
FIPS Code:	36067
Auth Type Code:	Not reported
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0013
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	EI0001
Contamination:	1330207
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0071
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	EI0001
Contamination:	108883
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.00000085
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UP0001
Contamination:	SO2
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0
Issue date:	Not reported
Expired Date:	Not reported

PROJECT ORANGE (Continued) **1000790137**

Emission Unit date:	UP0001
Contamination:	7440382
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UP0002
Contamination:	207089
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	UP0002
Contamination:	205992
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.0028
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	US0067
Contamination:	7440417
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	LB
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	0.000875
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	US0034
Contamination:	VOC
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	TON
Permit Status:	Not reported
Auth Status Code:	Not reported
Emissions:	9.23999977
Issue date:	Not reported
Expired Date:	Not reported
Emission Unit date:	US0034
Contamination:	NH3

PROJECT ORANGE (Continued) **1000790137**

EPA Control Code: Not reported
Control Eff: Not reported
Unit: LB

Permit Status: Not reported
Auth Status Code: Not reported
Emissions: 8
Issue date: Not reported
Expired Date: Not reported
Emission Unit date: UP0001
Contamination: 71432
EPA Control Code: Not reported
Control Eff: Not reported
Unit: LB

Permit Status: Not reported
Auth Status Code: Not reported
Emissions: 0
Issue date: Not reported
Expired Date: Not reported
Emission Unit date: UP0002
Contamination: 7439921
EPA Control Code: Not reported
Control Eff: Not reported
Unit: LB

AIRS Detail:
DECID: 7311500229
Facility Name: PROJECT ORANGE ASSOCIATES
Auth Type: Not reported

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 18.5630182001685

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 14099.232

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 1581.9300000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074986
Contaminant: PROPANE

PROJECT ORANGE (Continued) **1000790137**

Amount(Lbs/Yr): 401.81196203313499

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000075070
Contaminant: ACETALDEHYDE
Amount(Lbs/Yr): 60.1188

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 9.1562734104403201E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 0.00426925209660206

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 0.00142430919717961

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 2.1070518105251299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 1.2208364547253801E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 48.095039999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 155981

PROJECT ORANGE (Continued) **1000790137**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2974.3603638999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 527.37820016849003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 920.02368000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 15.549696000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 11143.9488

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000075070
Contaminant: ACETALDEHYDE
Amount(Lbs/Yr): 51.832320000000003

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000075569
Contaminant: PROPANE, 1,2-EPOXY-
Amount(Lbs/Yr): 37.578431999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 1.6845504

Issue Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Expiration Date: Not reported
Year: 2009
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 41.465856000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106990
Contaminant: 1,3-BUTADIENE
Amount(Lbs/Yr): 0.55719744000000004

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000107028
Contaminant: ACROLEIN
Amount(Lbs/Yr): 8.2931711999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 168.45504

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 142538880

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 36070

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 82.931712000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 726

Issue Date: Not reported
Expiration Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Year: 2009
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 8552.3328000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 34147.667200000004

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 76900

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 2561.62834496

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000075569
Contaminant: PROPANE, 1,2-EPOXY-
Amount(Lbs/Yr): 43.586129999999997

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000106990
Contaminant: 1,3-BUTADIENE
Amount(Lbs/Yr): 0.64627710000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000107028
Contaminant: ACROLEIN
Amount(Lbs/Yr): 9.6190079999999991

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 196.23995041932

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009

PROJECT ORANGE (Continued) **1000790137**

CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 652.944438303845

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 452.03845728727703

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 1.2208364547253801E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 226562700

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 2.5434092806778702E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 6.1041822736268797E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 9.1562734104403201E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 1.5260455684067201E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000207089

PROJECT ORANGE (Continued) **1000790137**

Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 4.5203845728727699E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 4.5203845728727699E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 23875.790000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 96.190079999999995

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.25434092806778702

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.19329910533151801

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 0.13225728259524899

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.55955004174913103

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS

PROJECT ORANGE (Continued) **1000790137**

Amount(Lbs/Yr): 1.0682318978847001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.101736371227115

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 2.2382001669965201

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 6.1041822736268804E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.55955004174913103

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.71215459858980301

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.0427292759153882

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.432379577715237

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 1.1699682691118201

PROJECT ORANGE (Continued) **1000790137**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 14.751773827931601

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 1133.5

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 1632.96

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 1.2208364547253801E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 1122.6600000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.30135897152485103

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 13785.5841066304

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 45637.180044799999

Issue Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Expiration Date: Not reported
Year: 2009
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 1085.9436357203001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 3.0135897152485102E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 3.0135897152485102E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2009
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 4.5203845728727699E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 4.3762508960156496E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 0.15771793496112399

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000075569
Contaminant: PROPANE, 1,2-EPOXY-
Amount(Lbs/Yr): 72.104208

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 540.59569891957995

Issue Date: Not reported
Expiration Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Year: 2008
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 1350.5966000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 1.4543095842565299E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 5.0900835448978499E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 411.882437272061

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 1.39371335157917

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 669.30896056709901

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007782505
Contaminant: CHLORINE
Amount(Lbs/Yr): 0.24097209999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 75418.799396311399

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008

PROJECT ORANGE (Continued) **1000790137**

CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 3.83831227954046E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 79.563264000000004

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 17522.873599999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 5.1614684193106804E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.23104842417395

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 30.376819698919601

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 5.2058705842565299E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.87182945748297402

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000107028

PROJECT ORANGE (Continued) **1000790137**

Contaminant: ACROLEIN
Amount(Lbs/Yr): 15.9126528

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 216406.70000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 2.6662342378036299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 1.4543095842565301E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 22779.4172

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 463.367741931068

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 5.41082641931068E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 3.0298116338677702E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000086737
Contaminant: FLUORENE

PROJECT ORANGE (Continued) **1000790137**

Amount(Lbs/Yr): 0.00169669451496595

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 1.0907321881924001E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.667173569450908

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007446119
Contaminant: SULFUR TRIOXIDE
Amount(Lbs/Yr): 478.03050000000002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 21029.214383479

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 1.2735272662244601

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 21727.349999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.56745564775752

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 324.101010179203

PROJECT ORANGE (Continued) **1000790137**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 7.2715479212826395E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 17.573131116433

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000106990
Contaminant: 1,3-BUTADIENE
Amount(Lbs/Yr): 1.0691313600000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 346374720

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 3.4079058092099701

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 1988.088

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.0907321881924001E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 1882.6300000000001

Issue Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Expiration Date: Not reported
Year: 2008
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.30891182795404598

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.12142728735471101

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.66655855945090803

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000075070
Contaminant: ACETALDEHYDE
Amount(Lbs/Yr): 99.454080000000005

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 4.6336774193106803E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 1787.3005892471299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 3.0891182795404602E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.37342776338677702

Issue Date: Not reported
Expiration Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Year: 2008
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 7.4113229212826402E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 159.12652800000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 4929.6454707966004

Issue Date: Not reported
Expiration Date: Not reported
Year: 2008
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 1.9721985803206601E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 3.4707208509727599E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 0.0142561625572363

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440439
Contaminant: CADMIUM
Amount(Lbs/Yr): 0.65357135053999604

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 2.9700338660908899E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007

PROJECT ORANGE (Continued) **1000790137**

CAS #: 007440382
Contaminant: ARSENIC
Amount(Lbs/Yr): 0.118863934643636

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 1.2476824237581801

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 4.9168545388780698E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 22739.680876458198

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 10981.7752

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 2.4254062557236299E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 33.737384148920199

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 17.226256023327199

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000100414

PROJECT ORANGE (Continued) **1000790137**

Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 88.346688

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 5.4131912764591398E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 2.61362980215999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.225931173822908

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 1982.5993453185799

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000109660
Contaminant: PENTANE
Amount(Lbs/Yr): 751.98951771076395

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 25114.202399999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 025321226
Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.347072085097276

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN

PROJECT ORANGE (Continued) **1000790137**

Amount(Lbs/Yr): 225074

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 1.0692121917927201E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007782505
Contaminant: CHLORINE
Amount(Lbs/Yr): 6.4218999999999998E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 5.2060812764591303E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 3.7704742099244499

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 1.6632189650108999E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 1315.2940000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000630080
Contaminant: CARBON MONOXIDE
Amount(Lbs/Yr): 28098.759999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 176.693376

PROJECT ORANGE (Continued) **1000790137**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000075569
Contaminant: PROPANE, 1,2-EPOXY-
Amount(Lbs/Yr): 80.064186000000007

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 1.8231443196545401E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000107028
Contaminant: ACROLEIN
Amount(Lbs/Yr): 17.669337599999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000124389
Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 375223740

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 1919.4400000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 7.1280812786181401E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 462.76278012970101

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 5.3467372764591395E-4

Issue Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Expiration Date: Not reported
Year: 2007
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.65340745053999705

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000075070
Contaminant: ACETALDEHYDE
Amount(Lbs/Yr): 110.43335999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440417
Contaminant: BERYLLIUM
Amount(Lbs/Yr): 7.1653312786181403E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007446119
Contaminant: SULFUR TRIOXIDE
Amount(Lbs/Yr): 127.395

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000108883
Contaminant: TOLUENE
Amount(Lbs/Yr): 359.891790907776

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 1.0692121917927201E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000106990
Contaminant: 1,3-BUTADIENE
Amount(Lbs/Yr): 1.1871586199999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 5472.0460251373997

Issue Date: Not reported
Expiration Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Year: 2007
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 0.154486461036727

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 0.049896568950327

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 80091.310262045998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 607.37614892023203

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.83786748250544996

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.31577738660908899

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 1.36621557840181

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000074840
Contaminant: ETHANE
Amount(Lbs/Yr): 1847.9100000000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007

PROJECT ORANGE (Continued) **1000790137**

CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 0.00142561625572363

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 520.60812764591299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 007440508
Contaminant: COPPER
Amount(Lbs/Yr): 0.51886705723545201

Issue Date: Not reported
Expiration Date: Not reported
Year: 2007
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 3.6703808509727599E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007446119
Contaminant: SULFUR TRIOXIDE
Amount(Lbs/Yr): 204.2595

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440622
Contaminant: VANADIUM
Amount(Lbs/Yr): 0.82467778352829901

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000206440
Contaminant: FLUORANTHENE
Amount(Lbs/Yr): 1.3165050741673499E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000074828
Contaminant: METHANE
Amount(Lbs/Yr): 26925.144680000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 025321226

PROJECT ORANGE (Continued) **1000790137**

Contaminant: DICHLOROBENZENE
Amount(Lbs/Yr): 0.249537576976195

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 001330207
Contaminant: XYLENE, M, O & P MIXT.
Amount(Lbs/Yr): 193.86973939999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007782505
Contaminant: CHLORINE
Amount(Lbs/Yr): 0.1029659

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY075025
Contaminant: PM 2.5
Amount(Lbs/Yr): 22725.288321224001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007439965
Contaminant: MANGANESE
Amount(Lbs/Yr): 0.13658557206119701

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000071432
Contaminant: BENZENE
Amount(Lbs/Yr): 36.819374759708403

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000083329
Contaminant: ACENAPHTHENE
Amount(Lbs/Yr): 8.4851200450040802E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440393
Contaminant: BARIUM
Amount(Lbs/Yr): 1.5776444554454401

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000108883
Contaminant: TOLUENE

PROJECT ORANGE (Continued) **1000790137**

Amount(Lbs/Yr):	394.500112534766
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440417
Contaminant:	BERYLLIUM
Amount(Lbs/Yr):	4.3623916966693804E-3
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440508
Contaminant:	COPPER
Amount(Lbs/Yr):	0.32715715434741499
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440439
Contaminant:	CADMIUM
Amount(Lbs/Yr):	0.39467390386135998
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000075070
Contaminant:	ACETALDEHYDE
Amount(Lbs/Yr):	121.16444568
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	007440382
Contaminant:	ARSENIC
Amount(Lbs/Yr):	7.1811449611156403E-2
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000630080
Contaminant:	CARBON MONOXIDE
Amount(Lbs/Yr):	14638.74
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000074840
Contaminant:	ETHANE
Amount(Lbs/Yr):	1114.45
Issue Date:	Not reported
Expiration Date:	Not reported
Year:	2006
CAS #:	000109660
Contaminant:	PENTANE
Amount(Lbs/Yr):	540.66475011508896

PROJECT ORANGE (Continued) **1000790137**

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000110543
Contaminant: HEXANE
Amount(Lbs/Yr): 374.30636546429298

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000191242
Contaminant: BENZO[G,H,I]PERYLENE
Amount(Lbs/Yr): 4.5439706966693801E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440020
Contaminant: NICKEL METAL AND INSOLUBLE COMPOUNDS
Amount(Lbs/Yr): 0.75339669191714198

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000091576
Contaminant: 2-METHYL NAPHTHALENE
Amount(Lbs/Yr): 8.6053333933387693E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000106990
Contaminant: 1,3-BUTADIENE
Amount(Lbs/Yr): 1.3025060340000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007439987
Contaminant: MOLYBDENUM
Amount(Lbs/Yr): 0.39441111386136002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY210000
Contaminant: OXIDES OF NITROGEN
Amount(Lbs/Yr): 223112.17999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000091203
Contaminant: NAPHTHALENE
Amount(Lbs/Yr): 4.0782545782962298

Issue Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Expiration Date: Not reported
Year: 2006
CAS #: 000107028
Contaminant: ACROLEIN
Amount(Lbs/Yr): 19.386478312000001

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000115071
Contaminant: PROPYLENE
Amount(Lbs/Yr): 0.121086

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000085018
Contaminant: PHENANTHRENE
Amount(Lbs/Yr): 5.3058356738294298E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 010024972
Contaminant: NITROUS OXIDE
Amount(Lbs/Yr): 797.1114

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000050000
Contaminant: FORMALDEHYDE
Amount(Lbs/Yr): 2167.3957408210099

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440484
Contaminant: COBALT
Amount(Lbs/Yr): 3.0118666876685699E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000086737
Contaminant: FLUORENE
Amount(Lbs/Yr): 1.5594755625561901E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000050328
Contaminant: BENZO(A)PYRENE
Amount(Lbs/Yr): 2.9270397697619499E-4

Issue Date: Not reported
Expiration Date: Not reported

PROJECT ORANGE (Continued) **1000790137**

Year: 2006
CAS #: 0NY998100
Contaminant: UNSPECIATED VOC (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 9016.7028232839002

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000218019
Contaminant: CHRYSENE
Amount(Lbs/Yr): 4.7391546546429302E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000074986
Contaminant: PROPANE
Amount(Lbs/Yr): 332.71676930159299

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440473
Contaminant: CHROMIUM
Amount(Lbs/Yr): 0.51201158127809498

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000053703
Contaminant: DIBENZ[A,H]ANTHRACENE
Amount(Lbs/Yr): 2.6455397697619498E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000075569
Contaminant: PROPANE, 1,2-EPOXY-
Amount(Lbs/Yr): 87.8434302

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000120127
Contaminant: ANTHRACENE
Amount(Lbs/Yr): 9.1391533933387703E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000205992
Contaminant: BENZO[B]FLUORANTHENE
Amount(Lbs/Yr): 6.9357400450040805E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006

PROJECT ORANGE (Continued) **1000790137**

CAS #: 007782492
Contaminant: SELENIUM
Amount(Lbs/Yr): 2.4635523393338798E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007446095
Contaminant: SULFUR DIOXIDE
Amount(Lbs/Yr): 7058.6509999999998

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000056553
Contaminant: BENZO(A)ANTHRACENE
Amount(Lbs/Yr): 4.2385336546429302E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000129000
Contaminant: PYRENE
Amount(Lbs/Yr): 1.9537917902789099E-3

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007664417
Contaminant: AMMONIA
Amount(Lbs/Yr): 1169.5119999999999

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 0NY075105
Contaminant: UNSPECIATED PM-10 (EMISSION STATEMENT USE ONLY)
Amount(Lbs/Yr): 85081.554784946202

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007440666
Contaminant: ZINC
Amount(Lbs/Yr): 10.398206743617701

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000106978
Contaminant: BUTANE
Amount(Lbs/Yr): 436.69075970834098

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000124389

PROJECT ORANGE (Continued) **1000790137**

Contaminant: CARBON DIOXIDE
Amount(Lbs/Yr): 376346224

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000207089
Contaminant: BENZO[K]FLUORANTHENE
Amount(Lbs/Yr): 3.8376756546429298E-4

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 000100414
Contaminant: ETHYLBENZENE
Amount(Lbs/Yr): 96.9306816

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007439976
Contaminant: MERCURY
Amount(Lbs/Yr): 9.3296115094503307E-2

Issue Date: Not reported
Expiration Date: Not reported
Year: 2006
CAS #: 007439921
Contaminant: LEAD
Amount(Lbs/Yr): 0.20937917902789099

AIRS Emissions:
County: ONONDAGA
Municipality: SYRACUSE
Facility ID: 7311500229
Facility Name: PROJECT ORANGE ASSOCIATES
SIC Code: 4931

Year: 2015
VOC(tons): 0
NOx(tons): 0
Co(tons): 0
Co2(tons): 0
Particulates: 0
PM10(tons): 0
PM2.5(tons): 0
HAPS: 0
So2: 0

Year: 2010
VOC(tons): 1.95
NOx(tons): 38.45
Co(tons): 18.04
Co2(tons): 75804.77
Particulates: 21.35
PM10(tons): 21.35
PM2.5(tons): 4.28

PROJECT ORANGE (Continued) **1000790137**

HAPS: 0
So2: 0.36

Click this hyperlink while viewing on your computer to access
217 additional NY AIRS: record(s) in the EDR Site Report.

NY MANIFEST:
EPA ID: NYD987016136
Country: USA
Name: Project Orange Assoc Llc
Address: 520 E TAYLOR ST
Address 2: Not reported
City,State,Zip: SYRACUSE, NY 13202
Zip 4: Not reported
Location Address 1: 520 EAST TAYLOR STREET
Location Address 2: Not reported
Location City,State,Zip: SYRACUSE, NY 13202
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Project Orange Assoc Llc
Mailing Contact: Joseph E Murphy
Mailing Address 1: 434 E BRIGHTON AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13210
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154748230

Manifest Data:
Document ID: NYG0926829
Manifest Status: Not reported
Trans1 State ID: AM8365
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 08/19/1997
Trans1 Recv Date: 08/19/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/19/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD987016136
Trans1 EPA ID: NYD013277454
Trans2 EPA ID: Not reported
TSDF ID 1: NYD013277454
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported

PROJECT ORANGE (Continued) **1000790137**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00220
Units:	Gallons (liquids only)
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG1656369
Manifest Status:	Not reported
Trans1 State ID:	49187AK
Year:	1999
Trans2 State ID:	TLK5558OH
Generator Ship Date:	06/15/1999
Trans1 Recv Date:	06/15/1999
Trans2 Recv Date:	06/17/1999
TSD Site Recv Date:	06/18/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	OHD001926740
TSDF ID 1:	OHD001926740
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Mercury
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00075
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

PROJECT ORANGE (Continued) **1000790137**

Document ID:	NYG1658025
Manifest Status:	Not reported
Trans1 State ID:	AM8365
Year:	1999
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/1999
Trans1 Recv Date:	08/05/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/05/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0222624
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	05/30/1997
Trans1 Recv Date:	05/30/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/30/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported

PROJECT ORANGE (Continued) **1000790137**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Wastewater Treatment Sludges From Electroplating Operations, Except From The Following Processes: (1) Sulfuric Acid Anodizing Of Aluminum; (2) Tin Plating On Carbon Steel; (3) Zinc Plating (Segregated Basis) On Carbon Steel; (4) Aluminum Or Zinc-Aluminum Plating On Carbon Steel; (5) Cleaning/Stripping Associated With Tin, Zinc, And Aluminum Plating On Carbon Steel; And (6) Chemical Etching And Milling Of Aluminum.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0221526
Manifest Status:	Not reported
Trans1 State ID:	HU7905
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/1997
Trans1 Recv Date:	04/17/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/17/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

PROJECT ORANGE (Continued) **1000790137**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00650
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0222084
Manifest Status:	Not reported
Trans1 State ID:	AM8365
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	04/24/1997
Trans1 Recv Date:	04/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0222147

PROJECT ORANGE (Continued) **1000790137**

Manifest Status:	Not reported
Trans1 State ID:	HU7905
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	04/25/1997
Trans1 Recv Date:	04/25/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00018
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Year:	2018
Trans2 State ID:	NJD071629976
Generator Ship Date:	12/17/2010
Trans1 Recv Date:	12/17/2010
Trans2 Recv Date:	12/21/2010

PROJECT ORANGE (Continued) **1000790137**

TSD Site Recv Date:	12/31/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	003842193FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Trichlorethylene
Waste Code b:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	7600
Units:	Pounds
Number of Containers:	4
Container Type:	Portable tanks
Handling Method:	Burn
Specific Gravity:	1
Document ID:	NYG0345717
Manifest Status:	Not reported
Trans1 State ID:	EZ1099
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/1998
Trans1 Recv Date:	01/27/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/27/1998
Part A Recv Date:	Not reported

PROJECT ORANGE (Continued) **1000790137**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0346968
Manifest Status:	Not reported
Trans1 State ID:	MX3142
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	03/06/1998
Trans1 Recv Date:	03/06/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/06/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

PROJECT ORANGE (Continued) **1000790137**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0347661
Manifest Status:	Not reported
Trans1 State ID:	EZ1099
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	04/10/1998
Trans1 Recv Date:	04/10/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/10/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987016136
Trans1 EPA ID:	NYD013277454
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD013277454
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

PROJECT ORANGE (Continued) **1000790137**

Click this hyperlink while viewing on your computer to access
64 additional NY MANIFEST: record(s) in the EDR Site Report.

I42 **SYRACUSE HOUSING AUTHORITY TOOMEY AGGO TOWER** **PA MANIFEST** **S110049554**
East **1207 ALMOND STREET** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.104 mi.
548 ft. **Site 2 of 5 in cluster I**

Relative:
Higher

Actual:
410 ft.

PA MANIFEST:

Name:	SYRACUSE HOUSING AUTHORITY TOOMEY AGGO TOWER
Address:	1207 ALMOND STREET
City,State,Zip:	SYRACUSE, NY 13202
Year:	2008
Manifest Number:	000885781FLE
Manifest Type:	T
Generator EPA ID:	NYR000154468
Generator Date:	03/12/2008
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	315-470-4315
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D002
Container Number:	1
Container Type:	DF
Waste Quantity:	55
Unit:	G
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported

I43 **SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE** **RCRA-SQG** **1010566799**
East **1207 ALMOND ST** **E MANIFEST** **NYR000154468**
< 1/8 **SYRACUSE, NY 13202** **NY MANIFEST**
0.104 mi.
548 ft. **Site 3 of 5 in cluster I**

Relative:
Higher

Actual:
410 ft.

RCRA Listings:

Date Form Received by Agency:	20080205
Handler Name:	Syracuse Housing Auth - Toomey Aggo Towe
Handler Address:	Almond St
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NYR000154468
Contact Name:	WILLIAM W GEHRKE
Contact Address:	BURT ST
Contact City,State,Zip:	SYRACUSE, NY 13202
Contact Telephone:	315-470-4315

SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE (Continued) **1010566799**

Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Other
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		ALMOND ST
Mailing City,State,Zip:		SYRACUSE, NY 13202
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE (Continued) **1010566799**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D002
Waste Description: Corrosive Waste

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE HOUSING AUTH
Legal Status: Other
Date Became Current: 19690101
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE HOUSING AUTH
Legal Status: Other
Date Became Current: 19690101
Date Ended Current: Not reported
Owner/Operator Address: 516 BURT ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20080205
Handler Name: SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080206
Handler Name: SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE (Continued) **1010566799**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92511
NAICS Description: Administration Of Housing Programs

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:

Manifest Tracking Number:	011099030FLE
Last Updated Date:	20190225
Shipped Date:	20181128
Received Date:	20181206
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000154468
Generator Name:	Syracuse Housing Auth - Toomey Aggo Towe
Generator Location Street Number:	Not reported
Generator Location Street 1:	1207 ALMOND ST
Generator Location Street 2:	Not reported
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13202
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1207 ALMOND ST
Generator Mail Street 2:	Not reported
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13202
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	VTR000517052
Designated Facility Name:	Enpro Services Of Vermont, Inc.
Designated Facility Mail Street Number:	54
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	54 AVENUE D
Designated Facility Mail City:	WILLISTON
Designated Facility Mail Zip:	05495
Designated Facility Mail State:	VT
Designated Facility Location Street Number:	54
Designated Facility Location Street 1:	54 AVENUE D
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	WILLISTON
Designated Facility Location Zip:	05495
Designated Facility Location State:	VT
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE (Continued) **1010566799**

Manifest Tracking Number:	006546910GBF
Last Updated Date:	20210920
Shipped Date:	20210813
Received Date:	20210910
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000154468
Generator Name:	Syracuse Housing Authority
Generator Location Street Number:	Not reported
Generator Location Street 1:	1207 ALMOND ST
Generator Location Street 2:	Not reported
Generator Location City:	SYACUSE
Generator Location State:	NY
Generator Location Zip:	13210
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	516 BURT ST
Generator Mail Street 2:	Not reported
Generator Mail City:	SYACUSE
Generator Mail Zip:	13202
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID048090633
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	49350 N I-94 SERVICE DRIVE
Designated Facility Mail City:	BELLEVILLE
Designated Facility Mail Zip:	48111
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	49350 N I-94 SERVICE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	BELLEVILLE
Designated Facility Location Zip:	48111
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Wayne Disposal, Inc. Site #2 Landfill
Manifest Residue Indicator:	N
Rejection Indicator:	N

PCB Information:

Manifest Tracking Number:	006546910GBF
Waste Line Number:	1
Article or Container ID:	1
Bulk Identity:	Not reported
Date of Removal:	20210813
Load Type:	ArticleInContainer
Load Type Description:	Article in Container
Waste Type:	PCB Solid
Weight:	50

Manifest Tracking Number:	006546910GBF
Waste Line Number:	1
Article or Container ID:	3
Bulk Identity:	Not reported
Date of Removal:	20210813
Load Type:	ArticleInContainer

SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE (Continued) **1010566799**

Load Type Description: Article in Container
Waste Type: PCB Solid
Weight: 50

Manifest Tracking Number: 006546910GBF
Waste Line Number: 1
Article or Container ID: 2
Bulk Identity: Not reported
Date of Removal: 20210813
Load Type: ArticleInContainer
Load Type Description: Article in Container
Waste Type: PCB Solid
Weight: 50

Transporter:
Manifest Tracking Number: 006546910GBF
Transporter Line Number: 1
Transporter EPA ID: MAC300098399
Transporter Name: Nrc East Environmental Services, Inc.

Manifest Tracking Number: 006546910GBF
Transporter Line Number: 2
Transporter EPA ID: MAD084814136
Transporter Name: Eq Northeast, Inc.

Manifest Tracking Number: 006546910GBF
Transporter Line Number: 3
Transporter EPA ID: MIK593743838
Transporter Name: Us Ecology Transportation Solutions, Inc

Waste Line:
Manifest Tracking Number: 006546910GBF
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3432
U.S. DOT Description: Rq, Un3432, Polychlorinated Biphenyls, Solid, 9, Pgii, Pcb Asbestos, Erg#171
Non-Hazardous Waste Description: Not reported
Number of Containers: 3
Container Type Code: CF
Container Type Description: Fiber or plastic boxes, cartons, cases
Waste Quantity: 150
Quantity Unit of Measure Code: K
Quantity Unit of Measure Description: Kilograms
Waste Quantity, in Tons: 0.1653749
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.1653749
Waste Quantity, in Kilograms: 150
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 150
Management Method Code: H132
Management Method Description: LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported

SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE (Continued) **1010566799**

Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	150
Quantity Non Haz Tons:	0.1653749
State Waste Codes:	NY-B007

NY MANIFEST:

EPA ID:	NYR000154468
Country:	USA
Name:	Syracuse Housing Auth - Toomey Aggo Tower
Address:	1207 ALMOND ST
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	1207 ALMOND ST
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Syracuse Housing Auth - Toomey Aggo Tower
Mailing Contact:	William Gehrke
Mailing Address 1:	516 BURT ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3154704315

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	NYD980761191
Generator Ship Date:	03/12/2008
Trans1 Recv Date:	03/12/2008
Trans2 Recv Date:	03/21/2008
TSD Site Recv Date:	03/25/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000154468
Trans1 EPA ID:	Not reported

SYRACUSE HOUSING AUTH - TOOMEY AGGO TOWE (Continued) **1010566799**

Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	000885781FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

F44 **IN THE STREET** **NY Spills** **S110768530**
ESE **ALMOND AND VAN BUREN** **N/A**
< 1/8 **SYRACUSE, NY**
0.105 mi.
556 ft. **Site 3 of 3 in cluster F**

Relative: **Higher**

Actual: **417 ft.**

SPILLS:

Name:	IN THE STREET
Address:	ALMOND AND VAN BUREN
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1011911 / 2011-04-26
Facility ID:	1011911
Facility Type:	ER
DER Facility ID:	400674
Site ID:	445807
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	3415
Spill Date:	2011-03-01
Investigator:	menash
Referred To:	Not reported
Reported to Dept:	2011-03-01

IN THE STREET (Continued) **S110768530**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-03-02
Spill Record Last Update:	2011-04-26
Spiller Name:	DAVID SHABAN
Spiller Company:	NATIONAL GRID
Spiller Address:	7437 HENRY CLAY BLVD
Spiller Company:	999
Contact Name:	DAVID SHABAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Nat Grid did clean up. Clean up complete.
Remarks:	Clean up is en route.

All Materials:

Site ID:	445807
Operable Unit ID:	1196187
Operable Unit:	01
Material ID:	2192453
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

E45 **SPARKLE CLEANERS INC** **EDR Hist Cleaner** **1020091527**
WSW **234 BURT ST** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.109 mi.
578 ft. **Site 5 of 5 in cluster E**

Relative: EDR Hist Cleaner
Lower

Actual: **396 ft.**

Year:	Name:	Type:
1992	SPARKLE CLEANERS	Drycleaning Plants, Except Rugs
1993	SPARKLE CLEANERS INC	Drycleaning Plants, Except Rugs
1994	SPARKLE CLEANERS INC	Drycleaning Plants, Except Rugs
1995	SPARKLE CLEANERS INC	Drycleaning Plants, Except Rugs
1996	SPARKLE CLEANERS INC	Drycleaning Plants, Except Rugs
1997	SPARKLE CLEANERS INC	Drycleaning Plants, Except Rugs

I46 **SU STEAM STATION** **NY Spills** **S102166608**
ENE **550 E TAYLOR ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.112 mi.
592 ft. **Site 4 of 5 in cluster I**

Relative:
Higher

Actual:
409 ft.

SPILLS:

Name:	SU STEAM STATION
Address:	550 E TAYLOR ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8912216 / 1990-04-04
Facility ID:	8912216
Facility Type:	ER
DER Facility ID:	115025
Site ID:	133848
DEC Region:	7
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	3415
Spill Date:	1990-03-23
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1990-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1990-03-27
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-04-02
Spill Record Last Update:	1990-04-04
Spiller Name:	Not reported
Spiller Company:	INTERFACESVC
Spiller Address:	5834 BUTTERNUT AVE.
Spiller Company:	001
Contact Name:	Not reported
Latitude:	43.0394536
Longitude:	-76.1430509
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR 04/04/90: MOST OF THE OIL WAS CONTAINED IN SECONDARY CONTAINMENT PIPE. SOIL WHICH WAS CONTAMINATED WAS STAGED AND EVENTUALLY REMOVED FROM THE SITE.
Remarks:	BACKHOE BROKE RETURN LINE OF A NEW 4-TANK INSTALLATION.

All Materials:

Site ID:	133848
Operable Unit ID:	937929
Operable Unit:	01
Material ID:	441689
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G

SU STEAM STATION (Continued) **S102166608**

Recovered: 5.00
Resource Affected: Soil
Oxygenate: Not reported

J47 **GREATER SYRACUSE LANDBANK** **NY Spills** **S128661859**
WSW **1210-1214 SOUTH STATE ST** **N/A**
< 1/8 **SYRACUSE, NY**
0.116 mi.
613 ft. **Site 1 of 4 in cluster J**

Relative: **Lower**
Actual: **395 ft.**

SPILLS:

Name:	GREATER SYRACUSE LANDBANK
Address:	1210-1214 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2200433 / 2022-04-20
Facility ID:	2200433
Facility Type:	ER
DER Facility ID:	582257
Site ID:	635449
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	3415
Spill Date:	2022-04-06
Investigator:	DJLASALL
Referred To:	Not reported
Reported to Dept:	2022-04-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-04-15
Spill Record Last Update:	2022-04-20
Spiller Name:	Not reported
Spiller Company:	GREATER SYRACUSE LANDBANK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MIKE STORONSKY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Phase II received and reviewed-minor exceedances noted-spill closed not meeting standards
Remarks:	history of fuel oil tanks in basement - cleanup pending

All Materials:

Site ID:	635449
Operable Unit ID:	1382530
Operable Unit:	01
Material ID:	2396854
Material Code:	9999
Material Name:	other - low level pah

GREATER SYRACUSE LANDBANK (Continued) **S128661859**

Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Groundwater
Oxygenate:	Not reported

J48 **1210 S STATE ST** **US BROWNFIELDS 1027025290**
WSW **1210 S STATE ST** **FINDS N/A**
< 1/8 **SYRACUSE, NY 13202**
0.116 mi.
613 ft. **Site 2 of 4 in cluster J**

Relative: **Lower**

Actual: **395 ft.**

US BROWNFIELDS:

Name:	1210 S State St
Address:	1210 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249193
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-10.0
Parcel Size:	0.11
Latitude:	43.03782683
Longitude:	-76.147597132
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2021-03-19 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-04-06 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y

1210 S STATE ST (Continued) **1027025290**

IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11

1210 S STATE ST (Continued) **1027025290**

NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2762
Below Poverty Percent:	50.1
Meidan Income:	1524
Meidan Income Number:	3821
Meidan Income Percent:	69.31
Vacant Housing Number:	280
Vacant Housing Percent:	13.26
Unemployed Number:	375
Unemployed Percent:	6.8

Name:	1210 S State St
Address:	1210 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249193
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-10.0
Parcel Size:	0.11
Latitude:	43.03782683
Longitude:	-76.147597132
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II SAP
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported

1210 S STATE ST (Continued) **1027025290**

Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	2021-09-05 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-02-25 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported

1210 S STATE ST (Continued) **1027025290**

RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2762
Below Poverty Percent:	50.1
Meidan Income:	1524
Meidan Income Number:	3821
Meidan Income Percent:	69.31
Vacant Housing Number:	280
Vacant Housing Percent:	13.26
Unemployed Number:	375
Unemployed Percent:	6.8

Name:	1210 S State St
Address:	1210 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249193
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-10.0
Parcel Size:	0.11
Latitude:	43.03782683
Longitude:	-76.147597132
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported

1210 S STATE ST (Continued) **1027025290**

Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported

1210 S STATE ST (Continued) **1027025290**

Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2762
Below Poverty Percent:	50.1
Meidan Income:	1524
Meidan Income Number:	3821
Meidan Income Percent:	69.31
Vacant Housing Number:	280
Vacant Housing Percent:	13.26
Unemployed Number:	375
Unemployed Percent:	6.8

Name:	1210 S State St
Address:	1210 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249193
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-10.0
Parcel Size:	0.11
Latitude:	43.03782683
Longitude:	-76.147597132
Census Tract:	36067004200

1210 S STATE ST (Continued) **1027025290**

State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported

1210 S STATE ST (Continued) **1027025290**

Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2762
Below Poverty Percent:	50.1
Meidan Income:	1524
Meidan Income Number:	3821
Meidan Income Percent:	69.31
Vacant Housing Number:	280
Vacant Housing Percent:	13.26
Unemployed Number:	375
Unemployed Percent:	6.8
Name:	1210 S State St
Address:	1210 S State St

1210 S STATE ST (Continued) **1027025290**

City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249193
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-10.0
Parcel Size:	0.11
Latitude:	43.03782683
Longitude:	-76.147597132
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported

1210 S STATE ST (Continued) **1027025290**

Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2762
Below Poverty Percent:	50.1

1210 S STATE ST (Continued) **1027025290**

Meidan Income:	1524
Meidan Income Number:	3821
Meidan Income Percent:	69.31
Vacant Housing Number:	280
Vacant Housing Percent:	13.26
Unemployed Number:	375
Unemployed Percent:	6.8
Name:	1210 S State St
Address:	1210 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249193
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-10.0
Parcel Size:	0.11
Latitude:	43.03782683
Longitude:	-76.147597132
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported

1210 S STATE ST (Continued) **1027025290**

IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

1210 S STATE ST (Continued) **1027025290**

Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2762
Below Poverty Percent:	50.1
Meidan Income:	1524
Meidan Income Number:	3821
Meidan Income Percent:	69.31
Vacant Housing Number:	280
Vacant Housing Percent:	13.26
Unemployed Number:	375
Unemployed Percent:	6.8

FINDS:
Registry ID: 110071090134

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

J49 **1212 S STATE ST** **US BROWNFIELDS** **1027140686**
WSW **1212 S STATE ST** **FINDS** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.118 mi.
623 ft. **Site 3 of 4 in cluster J**

Relative:
Lower

Actual:
395 ft.

US BROWNFIELDS:

Name:	1212 S State St
Address:	1212 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249194
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-11.0
Parcel Size:	0.11
Latitude:	43.0377353
Longitude:	-76.147563102
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported

1212 S STATE ST (Continued) **1027140686**

Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported

1212 S STATE ST (Continued) **1027140686**

RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2699
Below Poverty Percent:	50.38
Meidan Income:	1562
Meidan Income Number:	3696
Meidan Income Percent:	68.99
Vacant Housing Number:	263
Vacant Housing Percent:	12.84
Unemployed Number:	369
Unemployed Percent:	6.89

Name:	1212 S State St
Address:	1212 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249194
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-11.0
Parcel Size:	0.11

1212 S STATE ST (Continued) **1027140686**

Latitude:	43.0377353
Longitude:	-76.147563102
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2021-03-19 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-04-06 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N

1212 S STATE ST (Continued) **1027140686**

Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2699
Below Poverty Percent:	50.38
Meidan Income:	1562
Meidan Income Number:	3696
Meidan Income Percent:	68.99
Vacant Housing Number:	263
Vacant Housing Percent:	12.84
Unemployed Number:	369
Unemployed Percent:	6.89

1212 S STATE ST (Continued) **1027140686**

Name:	1212 S State St
Address:	1212 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249194
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-11.0
Parcel Size:	0.11
Latitude:	43.0377353
Longitude:	-76.147563102
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported

1212 S STATE ST (Continued) **1027140686**

Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5

1212 S STATE ST (Continued) **1027140686**

Below Poverty Number:	2699
Below Poverty Percent:	50.38
Meidan Income:	1562
Meidan Income Number:	3696
Meidan Income Percent:	68.99
Vacant Housing Number:	263
Vacant Housing Percent:	12.84
Unemployed Number:	369
Unemployed Percent:	6.89
Name:	1212 S State St
Address:	1212 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249194
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-11.0
Parcel Size:	0.11
Latitude:	43.0377353
Longitude:	-76.147563102
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported

1212 S STATE ST (Continued) **1027140686**

IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported

1212 S STATE ST (Continued) **1027140686**

Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2699
Below Poverty Percent:	50.38
Meidan Income:	1562
Meidan Income Number:	3696
Meidan Income Percent:	68.99
Vacant Housing Number:	263
Vacant Housing Percent:	12.84
Unemployed Number:	369
Unemployed Percent:	6.89

Name:	1212 S State St
Address:	1212 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249194
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-11.0
Parcel Size:	0.11
Latitude:	43.0377353
Longitude:	-76.147563102
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II SAP
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	2021-09-05 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported

1212 S STATE ST (Continued) **1027140686**

Completion Date:	2022-02-25 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported

1212 S STATE ST (Continued) **1027140686**

Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2699
Below Poverty Percent:	50.38
Meidan Income:	1562
Meidan Income Number:	3696
Meidan Income Percent:	68.99
Vacant Housing Number:	263
Vacant Housing Percent:	12.84
Unemployed Number:	369
Unemployed Percent:	6.89

Name:	1212 S State St
Address:	1212 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249194
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-11.0
Parcel Size:	0.11
Latitude:	43.0377353
Longitude:	-76.147563102
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported

1212 S STATE ST (Continued) **1027140686**

Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported

1212 S STATE ST (Continued) **1027140686**

RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2699
Below Poverty Percent:	50.38
Meidan Income:	1562
Meidan Income Number:	3696
Meidan Income Percent:	68.99
Vacant Housing Number:	263
Vacant Housing Percent:	12.84
Unemployed Number:	369
Unemployed Percent:	6.89

FINDS:
Registry ID: 110071194772

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

J50 **1214 S STATE ST** **US BROWNFIELDS** **1027142013**
WSW **1214 S STATE ST** **FINDS** **N/A**
< 1/8 **SYRACUSE, NY 13202**
0.120 mi.
635 ft. **Site 4 of 4 in cluster J**

Relative: **Lower**

Actual: **394 ft.**

US BROWNFIELDS:

Name:	1214 S State St
Address:	1214 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249195
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-12.0
Parcel Size:	0.11
Latitude:	43.037652612
Longitude:	-76.147505686
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported

1214 S STATE ST (Continued) **1027142013**

Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported

1214 S STATE ST (Continued) **1027142013**

ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2742
Below Poverty Percent:	50.14
Meidan Income:	1524
Meidan Income Number:	3786
Meidan Income Percent:	69.23
Vacant Housing Number:	276
Vacant Housing Percent:	13.18
Unemployed Number:	372
Unemployed Percent:	6.8

Name:	1214 S State St
Address:	1214 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249195
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-12.0
Parcel Size:	0.11
Latitude:	43.037652612
Longitude:	-76.147505686
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y

1214 S STATE ST (Continued) **1027142013**

IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11

1214 S STATE ST (Continued) **1027142013**

NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2742
Below Poverty Percent:	50.14
Meidan Income:	1524
Meidan Income Number:	3786
Meidan Income Percent:	69.23
Vacant Housing Number:	276
Vacant Housing Percent:	13.18
Unemployed Number:	372
Unemployed Percent:	6.8

Name:	1214 S State St
Address:	1214 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249195
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-12.0
Parcel Size:	0.11
Latitude:	43.037652612
Longitude:	-76.147505686
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II SAP
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II SAP
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported

1214 S STATE ST (Continued) **1027142013**

Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255919
Start Date:	2021-09-05 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-02-25 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported

1214 S STATE ST (Continued) **1027142013**

RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2742
Below Poverty Percent:	50.14
Meidan Income:	1524
Meidan Income Number:	3786
Meidan Income Percent:	69.23
Vacant Housing Number:	276
Vacant Housing Percent:	13.18
Unemployed Number:	372
Unemployed Percent:	6.8

Name:	1214 S State St
Address:	1214 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249195
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-12.0
Parcel Size:	0.11
Latitude:	43.037652612
Longitude:	-76.147505686
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported

1214 S STATE ST (Continued) **1027142013**

Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2021-03-19 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-04-06 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported

1214 S STATE ST (Continued) **1027142013**

Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2742
Below Poverty Percent:	50.14
Meidan Income:	1524
Meidan Income Number:	3786
Meidan Income Percent:	69.23
Vacant Housing Number:	276
Vacant Housing Percent:	13.18
Unemployed Number:	372
Unemployed Percent:	6.8

Name:	1214 S State St
Address:	1214 S State St
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249195
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-12.0
Parcel Size:	0.11
Latitude:	43.037652612
Longitude:	-76.147505686
Census Tract:	36067004200

1214 S STATE ST (Continued) **1027142013**

State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported

1214 S STATE ST (Continued) **1027142013**

Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2742
Below Poverty Percent:	50.14
Meidan Income:	1524
Meidan Income Number:	3786
Meidan Income Percent:	69.23
Vacant Housing Number:	276
Vacant Housing Percent:	13.18
Unemployed Number:	372
Unemployed Percent:	6.8
Name:	1214 S State St
Address:	1214 S State St

1214 S STATE ST (Continued) **1027142013**

City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249195
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-18-12.0
Parcel Size:	0.11
Latitude:	43.037652612
Longitude:	-76.147505686
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Lead Other Metals PAHs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	Y
IC Category Proprietary Controls:	Y
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Y
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	N
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Y
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported

1214 S STATE ST (Continued) **1027142013**

Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Y
Additional Engineering Controls Information:	Phase II findings with exceedances of NYSDEC soil cleanup objectives and/or groundwater standards/guidance
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	N
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.11
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2742
Below Poverty Percent:	50.14

1214 S STATE ST (Continued) **1027142013**

Meidan Income:	1524
Meidan Income Number:	3786
Meidan Income Percent:	69.23
Vacant Housing Number:	276
Vacant Housing Percent:	13.18
Unemployed Number:	372
Unemployed Percent:	6.8

FINDS:
Registry ID: 110071198607

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

K51 **S STATE STREET** **NY LTANKS** **S100494186**
WNW **S STATE ST/NEW STREET** **N/A**
< 1/8 **SYRACUSE, NY**
0.123 mi.
649 ft. **Site 1 of 3 in cluster K**

Relative: **Lower**
Actual: **398 ft.**

LTANKS:

Name:	S STATE STREET
Address:	S STATE ST/NEW STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9208359 / 1993-01-26
Facility ID:	9208359
Site ID:	229077
Spill Date:	1992-10-19
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1993-01-26
SWIS:	3415
Investigator:	MENASH
Referred To:	Not reported
Reported to Dept:	1992-10-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-10-20
Spill Record Last Update:	1993-01-27
Spiller Name:	Not reported
Spiller Company:	SYRACUSE HOUSING AUTH
Spiller Address:	Not reported
Spiller County:	001

S STATE STREET (Continued) **S100494186**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	188876
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MN
Remarks:	UNCOVERED 550 GAL TANK WHILE EXCAVATING FOR SEWER LINE. CONTAMINATED SOIL FOUND FROM LEAKING TANK. SOIL TO BE STAGED AND DISPOSED OF BY SYR HOUSING AUTH

All Materials:

Site ID:	229077
Operable Unit ID:	971954
Operable Unit:	01
Material ID:	408947
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

I52 **NYSDOT BIN 1031569** **RCRA NonGen / NLR** **1000889982**
ENE **I-81/EAST ADAMS STREET** **NY MANIFEST** **NY0000202481**
< 1/8 **SYRACUSE, NY 13202**
0.124 mi.
656 ft. **Site 5 of 5 in cluster I**

Relative: **Higher**
Actual: **409 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nysdot Bin 1031569
Handler Address:	I-81/East Adams Street
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NY0000202481
Contact Name:	RICHARD S STEELE
Contact Address:	SOUTH WARREN STREET
Contact City,State,Zip:	SYRACUSE, NY 13202
Contact Telephone:	315-448-7363
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R7
Mailing Address:	SOUTH WARREN STREET
Mailing City,State,Zip:	SYRACUSE, NY 13202

NYSDOT BIN 1031569 (Continued) **1000889982**

Owner Name:	Nysdot	
Owner Type:		State
Operator Name:	Nysdot	
Operator Type:		State
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: Lead

NYSDOT BIN 1031569 (Continued) **1000889982**

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: NYSDOT
Legal Status: State
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 109 S WARREN ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-448-7342
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYSDOT
Legal Status: State
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 109 S WARREN ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-448-7342
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NYSDOT
Legal Status: State
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 109 S WARREN ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-448-7342
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950227
Handler Name: NYSDOT BIN 1031569
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NYSDOT BIN 1031569

NYSDOT BIN 1031569 (Continued) **1000889982**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: NYSDOT BIN 1031569	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19940411
Handler Name: NYSDOT BIN 1031569	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010521
Handler Name: NYSDOT BIN 1031569	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20020227
Handler Name: NYSDOT BIN 1031569	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

NYSDOT BIN 1031569 (Continued) **1000889982**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23412
NAICS Description: Bridge And Tunnel Construction

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NY0000202481
Country: USA
Name: New York State Dept Of Transportation
Address: RTE I-81 OVER E ADAMS ST
Address 2: Not reported
City,State,Zip: SYRACUSE, NY 13202
Zip 4: Not reported
Location Address 1: UNDER I-81 ADAM ST
Location Address 2: Not reported
Location City,State,Zip: SYRACUSE, NY
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: New York State Dept Of Transportation
Mailing Contact: Daniel F Weaver
Mailing Address 1: 3522 JAMES ST SUITE 206
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13206
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154379886

Manifest Data:
Document ID: NYG1987011
Manifest Status: Not reported
Trans1 State ID: AB32265
Year: 2001
Trans2 State ID: Not reported
Generator Ship Date: 07/19/2001
Trans1 Recv Date: 07/19/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/20/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported

NYSDOT BIN 1031569 (Continued) **1000889982**

Generator EPA ID:	NY0000202481
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	12500
Units:	Pounds
Number of Containers:	025
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR986628162
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	11/05/2015
Trans1 Recv Date:	11/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202481
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	008273657FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

NYSDOT BIN 1031569 (Continued) **1000889982**

MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1

Document ID:	NYG3113442
Manifest Status:	Not reported
Trans1 State ID:	AB32265NY
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	10/03/2001
Trans1 Recv Date:	10/03/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/08/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202481
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	32000
Units:	Pounds
Number of Containers:	040

NYSDOT BIN 1031569 (Continued) **1000889982**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	NYB6578505
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/1994
Trans1 Recv Date:	11/01/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000202481
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD066060609
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02500
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

53
NE
1/8-1/4
0.146 mi.
773 ft.

SYRACUSE HOUSING AUTH - PIONEER HOMES BLDG 60 **RCRA-VSQG** **1012186551**
101-102 DYER COURT **NYR000164129**
SYRACUSE, NY 13202

Relative:
Higher

Actual:
407 ft.

RCRA Listings:

Date Form Received by Agency:	20090415
Handler Name:	Syracuse Housing Auth - Pioneer Homes Bldg 60
Handler Address:	Dyer Court
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NYR000164129

SYRACUSE HOUSING AUTH - PIONEER HOMES BLDG 60 (Continued) **1012186551**

Contact Name:		WILLIAM W GEHRKE
Contact Address:		BURT ST
Contact City,State,Zip:		SYRACUSE, NY 13202
Contact Telephone:		315-470-4315
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Other
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		DYER COURT
Mailing City,State,Zip:		SYRACUSE, NY 13202
Owner Name:	Syracuse Housing Authority	
Owner Type:		Other
Operator Name:	Syracuse Housing Authority	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No

SYRACUSE HOUSING AUTH - PIONEER HOMES BLDG 60 (Continued) **1012186551**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SYRACUSE HOUSING AUTHORITY
Legal Status:	Other
Date Became Current:	19540101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYRACUSE HOUSING AUTHORITY
Legal Status:	Other
Date Became Current:	19540101
Date Ended Current:	Not reported
Owner/Operator Address:	516 BURT ST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20090415
Handler Name:	SYRACUSE HOUSING AUTH - PIONEER HOMES BLDG 60
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	92511
NAICS Description:	Administration Of Housing Programs

Facility Has Received Notices of Violations:

Violations:	No Violations Found

SYRACUSE HOUSING AUTH - PIONEER HOMES BLDG 60 (Continued) **1012186551**

Evaluation Action Summary:
Evaluations: No Evaluations Found

54
NNW
1/8-1/4
0.147 mi.
776 ft.

NY1-1 PIONEER HOMES **NY UST** **U004079888**
ADAMS/RENWICK/TAYLOR/STATE **N/A**
SYRACUSE, NY 13202

Relative:
Lower

Actual:
398 ft.

UST:

Name:	NY1-1 PIONEER HOMES
Address:	ADAMS/RENWICK/TAYLOR/STATE
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-498947 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	N/A
UTM X:	406600.05465
UTM Y:	4766007.99600
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	46336
Affiliation Type:	Facility Owner
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	EXECUTIVE DIRECTOR
Contact Name:	WILLIAM SIMMONS
Address1:	516 BURT ST
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 475-6181
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2011-01-14

Site Id:	46336
Affiliation Type:	Mail Contact
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	ANDREW BARSUCH
Address1:	516 BURT ST
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 475-6181
EMail:	ABARSUCH@SYRHOUSING.ORG
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2011-01-14

NY1-1 PIONEER HOMES (Continued) **U004079888**

Site Id:	46336
Affiliation Type:	Facility Operator
Company Name:	NY1-1 PIONEER HOMES
Contact Type:	Not reported
Contact Name:	GREG PALMER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 706-3727
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2011-01-14

Site Id:	46336
Affiliation Type:	Emergency Contact
Company Name:	SYRACUSE HOUSING AUTHORITY
Contact Type:	Not reported
Contact Name:	ANDREW BARSUCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 439-4788
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2011-01-14

Tank Info:

Tank Number:	003
Tank ID:	133569
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	12/01/1984
Date Tank Closed:	04/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

NY1-1 PIONEER HOMES (Continued) **U004079888**

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
B04 - Tank External Protection - Fiberglass
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	133570
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	12/01/1984
Date Tank Closed:	11/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

L55 **917 MONTGOMERY STREET AND BURT STREET** **US BROWNFIELDS 1027025374**
West **917 MONTGOMERY STREET** **FINDS N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.153 mi.
810 ft. **Site 1 of 2 in cluster L**

Relative: **Lower**
Actual: **396 ft.**

US BROWNFIELDS:

Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767
Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805
Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21
Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase I Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Sampling and Analysis Plan Only
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-17 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2021-01-06 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805
Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92
Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21
Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Sampling and Analysis Plan Only
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767
Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805
Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92

Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21
Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Sampling and Analysis Plan Only
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Sampling and Analysis Plan Only
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2019-09-05 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-07-06 00:00:00
Address of Data Sources (URL if available) 1:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767
Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805
Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92

Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21
Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Sampling and Analysis Plan Only
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2019-09-05 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-07-06 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767
Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805
Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92

Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21
Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Sampling and Analysis Plan Only

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767
Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805
Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92

Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21
Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767
Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805
Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92

Name:	917 Montgomery Street And Burt Street
Address:	917 Montgomery Street
City,State,Zip:	SYRACUSE, NY 13202

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Property ID:	244994
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-07-05.0
Parcel Size:	0.21
Latitude:	43.038501681
Longitude:	-76.148664756
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase I Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-17 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2021-01-06 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.21
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2767
Below Poverty Percent:	50.29
Meidan Income:	1562
Meidan Income Number:	3805

917 MONTGOMERY STREET AND BURT STREET (Continued) **1027025374**

Meidan Income Percent:	69.16
Vacant Housing Number:	276
Vacant Housing Percent:	13.08
Unemployed Number:	381
Unemployed Percent:	6.92

FINDS:
Registry ID: 110071090222

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M56 **NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YOR** **NY MANIFEST** **S119079300**
ESE **522 RENWICK AVE** **N/A**
1/8-1/4 **SYRACUSE, NY 13210**
0.154 mi.
811 ft. **Site 1 of 2 in cluster M**

Relative:
Higher

Actual:
427 ft.

NY MANIFEST:

EPA ID:	NYR000229765
Country:	USA
Name:	Nysdot Bin 7706370 - Syracuse Binghamton & New York Railroad Corp
Address:	522 RENWICK AVE
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13210
Zip 4:	Not reported
Location Address 1:	522 RENWICK AVE
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13210
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Nysdot Bin 7706370 - Syracuse Binghamton & New York Railroad Corp
Mailing Contact:	Rick Howard
Mailing Address 1:	1 RAILROAD AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	COOPERSTOWN, NY 13326
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6072016049

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJR986628162
Year:	2018
Trans2 State ID:	Not reported

NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD (Continued) **S119079300**

Generator Ship Date:	11/29/2016
Trans1 Recv Date:	11/29/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/29/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000229765
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	009401721FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1

M57 **NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YOR** **RCRA NonGen / NLR** **1019909605**
ESE **522 RENWICK AVE** **FINDS** **NYR000229765**
1/8-1/4 **SYRACUSE, NY 13210** **ECHO**
0.154 mi.
811 ft. **Site 2 of 2 in cluster M**

Relative: **Higher**
Actual: **427 ft.**

RCRA Listings:

Date Form Received by Agency:	20170418
Handler Name:	Nysdot Bin 7706370 - Syracuse Binghamton & New York Railroad Corp
Handler Address:	Renwick Ave
Handler City,State,Zip:	SYRACUSE, NY 13210
EPA ID:	NYR000229765
Contact Name:	RICHARD M HOWARD
Contact Address:	RAILROAD AVE
Contact City,State,Zip:	COOPERSTOWN, NY 13326

NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD (Continued) **1019909605**

Contact Telephone:	607-547-2555 x222
Contact Fax:	607-547-2555
Contact Email:	RHOWARD@NYSW.COM
Contact Title:	ASSISTANT CHIEF ENGINEER
EPA Region:	02
Land Type:	County
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R7
Mailing Address:	RAILROAD AVE
Mailing City,State,Zip:	COOPERSTOWN, NY 13326
Owner Name:	Onondaga County Industrial Development
Owner Type:	County
Operator Name:	Syracuse Binghamton & New York Railroad
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170530
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No

NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD (Continued) **1019909605**

Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ONONDAGA COUNTY INDUSTRIAL DEVELOPMENT
Legal Status: County
Date Became Current: 19930505
Date Ended Current: Not reported
Owner/Operator Address: 333 W WASHINGTON ST SUITE 130
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-435-3770
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ONONDAGA COUNTY INDUSTRIAL DEVELOPMENT
Legal Status: County
Date Became Current: 19930505
Date Ended Current: Not reported
Owner/Operator Address: 333 W WASHINGTON ST SUITE 130
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-435-3770
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE BINGHAMTON & NEW YORK RAILROAD
Legal Status: Private
Date Became Current: 19930505
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE BINGHAMTON & NEW YORK RAILROAD
Legal Status: Private
Date Became Current: 19930505
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD (Continued) **1019909605**

Historic Generators:

Receive Date:	20170418
Handler Name:	NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20161114
Handler Name:	NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	482112
NAICS Description:	Short Line Railroads

NAICS Code:	488210
NAICS Description:	Support Activities For Rail Transportation

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110070122138

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD (Continued) **1019909605**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019909605
Registry ID: 110070122138

DFR URL:
Name: NYSDOT BIN 7706370 - SYRACUSE BINGHAMTON & NEW YORK RAILROAD CORP
Address: 522 RENWICK AVE
City,State,Zip: SYRACUSE, NY 13210

K58 **SYRACUSE HOUSING AUTHORITY BUILDING & GROUNDS** **RCRA-SQG** **1012211705**
NW **218 NEW ST** **NY MANIFEST** **NYR000171124**
1/8-1/4 **SYRACUSE, NY 13202**
0.166 mi.
878 ft. **Site 2 of 3 in cluster K**

Relative: **Lower**
Actual: **397 ft.**

RCRA Listings:

Date Form Received by Agency:		20100105
Handler Name:		Syracuse Housing Authority Building & Grounds
Handler Address:		New St
Handler City,State,Zip:		SYRACUSE, NY 13202
EPA ID:		NYR000171124
Contact Name:		WILLIAM W GEHRKE
Contact Address:		NEW ST
Contact City,State,Zip:		SYRACUSE, NY 13202
Contact Telephone:		315-470-4315 x4315
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Other
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		NEW ST
Mailing City,State,Zip:		SYRACUSE, NY 13202
Owner Name:	Syracuse Housing Authority	
Owner Type:		Other
Operator Name:	Syracuse Housing Authority	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

SYRACUSE HOUSING AUTHORITY BUILDING & GROUNDS (Continued) **1012211705**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY	
Legal Status:	Other
Date Became Current:	19890101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: SYRACUSE HOUSING AUTHORITY	
Legal Status:	Other
Date Became Current:	19400101
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported

SYRACUSE HOUSING AUTHORITY BUILDING & GROUNDS (Continued) **1012211705**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100105
Handler Name: SYRACUSE HOUSING AUTHORITY BUILDING & GROUNDS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92511
NAICS Description: Administration Of Housing Programs

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYR000171124
Country: USA
Name: Syracuse Housing Authority Building & Grounds
Address: 218 NEW ST
Address 2: Not reported
City,State,Zip: SYRACUSE, NY 13202
Zip 4: Not reported
Location Address 1: 218 NEW ST
Location Address 2: Not reported
Location City,State,Zip: SYRACUSE, NY 13202
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Syracuse Housing Authority Building & Grounds
Mailing Contact: Mark Denny
Mailing Address 1: 516 BURT STREET
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13202
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154704315

SYRACUSE HOUSING AUTHORITY BUILDING & GROUNDS (Continued) **1012211705**

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/13/2010
Trans1 Recv Date:	01/13/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/22/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171124
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	002474327FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	25
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

K59 **SYRACUSE HOUSING AUTHORITY - NEW STREET** **PA MANIFEST** **S111771708**
NW **218 NEW STREET** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.166 mi.
878 ft. **Site 3 of 3 in cluster K**

Relative: **Lower**
Actual: **397 ft.**

PA MANIFEST:

Name:	SYRACUSE HOUSING AUTHORITY - NEW STREET
Address:	218 NEW STREET
City,State,Zip:	SYRACUSE, NY 13202
Year:	2010
Manifest Number:	002474327FLE
Manifest Type:	T
Generator EPA ID:	NYR000171124
Generator Date:	01/13/2010
Mailing Address:	Not reported
Contact Name:	Not reported
Contact Phone:	NULL
TSD EPA ID:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D002
Container Number:	1
Container Type:	DF
Waste Quantity:	25
Unit:	G
Handling Code:	Not reported
TSP EPA ID:	Not reported
Date TSP Sig:	Not reported

---

60 **TRIPP KATIE** **RCRA NonGen / NLR** **1001224468**
SSE **1429 S MCBRIDE ST** **FINDS** **NYR000056853**
1/8-1/4 **SYRACUSE, NY 13210** **ECHO**
0.172 mi. **NY MANIFEST**
906 ft.

Relative: **Lower**
Actual: **399 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Tripp Katie
Handler Address:	S Mcbride St
Handler City,State,Zip:	SYRACUSE, NY 13210
EPA ID:	NYR000056853
Contact Name:	JOHN BYRNES
Contact Address:	S MCBRIDE ST
Contact City,State,Zip:	SYRACUSE, NY 13210
Contact Telephone:	315-476-0996
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

TRIPP KATIE (Continued) **1001224468**

Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		S MCBRIDE ST
Mailing City,State,Zip:		SYRACUSE, NY 13210
Owner Name:	Katie Tripp	
Owner Type:		Private
Operator Name:	Katie Tripp	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008

TRIPP KATIE (Continued) **1001224468**

Waste Description: Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: KATIE TRIPP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1429 S MCBRIDE ST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13210
Owner/Operator Telephone:	315-476-0996
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: KATIE TRIPP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1429 S MCBRIDE ST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13210
Owner/Operator Telephone:	315-476-0996
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: KATIE TRIPP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1429 S MCBRIDE ST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13210
Owner/Operator Telephone:	315-476-0996
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: TRIPP KATIE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: TRIPP KATIE	
Federal Waste Generator Description:	Not a generator, verified

TRIPP KATIE (Continued) **1001224468**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980617
Handler Name: TRIPP KATIE	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004544388

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001224468
Registry ID: 110004544388

DFR URL:
Name: TRIPP KATIE
Address: 1429 S MCBRIDE ST

TRIPP KATIE (Continued) **1001224468**

City,State,Zip: SYRACUSE, NY 13210

NY MANIFEST:
EPA ID: NYR000056853
Country: USA
Name: Katei Tripp Northern Env
Address: 1429 S MCBRIDE ST
Address 2: Not reported
City,State,Zip: SYRACUSE, NY 13210
Zip 4: Not reported
Location Address 1: 1429 S MCBRIDE ST
Location Address 2: Not reported
Location City,State,Zip: SYRACUSE, NY 13202
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Katei Tripp Northern Env
Mailing Contact: Thomas Strong
Mailing Address 1: 1429 S MCBRIDE ST
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13202
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154349848

Manifest Data:
Document ID: PAE9109623
Manifest Status: Not reported
Trans1 State ID: PAAH0549
Year: 1998
Trans2 State ID: Not reported
Generator Ship Date: 07/08/1998
Trans1 Recv Date: 07/08/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/09/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000056853
Trans1 EPA ID: PAD010154045
Trans2 EPA ID: Not reported
TSDF ID 1: PAD010154045
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported

TRIPP KATIE (Continued) **1001224468**

Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00305
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	01.00

---

61 **NYS TEAMSTERS** **NY LTANKS** **S100130095**
NW **NEW STREET** **N/A**
1/8-1/4 **SYRACUSE, NY**
0.172 mi.
910 ft.

Relative: **Lower**

Actual: **397 ft.**

LTANKS:

Name:	NYS TEAMSTERS
Address:	NEW STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9001641 / 1990-09-13
Facility ID:	9001641
Site ID:	100774
Spill Date:	1990-05-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1990-08-27
SWIS:	3415
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1990-05-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-06-01
Spill Record Last Update:	1995-06-02
Spiller Name:	Not reported
Spiller Company:	NYS TEAMSTERS RETIRE FUND
Spiller Address:	7 RUTGERS ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	89437
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR

NYS TEAMSTERS (Continued) **S100130095**

Remarks: 09/13/90: SOME CONTAMINATED SOIL REMOVED FROM THE SITE. CONTACT BRAD SMITH SUTTON REAL ESTATE 424-1111 PETRO-TITE TEST FAILUREVENT PROBLEM SUSPECTED.

All Materials:

Site ID:	100774
Operable Unit ID:	939951
Operable Unit:	01
Material ID:	439970
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	Not reported
Recovered:	5.00
Resource Affected:	Soil
Oxygenate:	Not reported

L62 **WAREHOUSE** **NY UST** **U004339826**
West **908 MONTGOMERY ST** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.179 mi.
943 ft. **Site 2 of 2 in cluster L**

Relative: **Lower**

Actual: **396 ft.**

UST:

Name:	WAREHOUSE
Address:	908 MONTGOMERY ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-991000 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	615705
Affiliation Type:	Facility Owner
Company Name:	MORRISVILLE AUXILIARY CORP
Contact Type:	EXECUTIVE DIRECTOR
Contact Name:	JENNIFER BOWDEN
Address1:	PO BOX 901
Address2:	Not reported
City:	MORRISVILLE
State:	NY
Zip Code:	13408
Country Code:	001
Phone:	(315) 684-6048
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2021-01-14

Site Id:	615705
Affiliation Type:	Mail Contact

WAREHOUSE (Continued) **U004339826**

Company Name:	MORRISVILLE AUXILIARY CORP
Contact Type:	Not reported
Contact Name:	JENNIFER BOWDEN
Address1:	PO BOX 901
Address2:	Not reported
City:	MORRISVILLE
State:	NY
Zip Code:	13408
Country Code:	001
Phone:	(315) 684-6108
EMail:	BOWDENJJ@MORRISVILLE.EDU
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2021-01-14

Site Id:	615705
Affiliation Type:	Facility Operator
Company Name:	WAREHOUSE
Contact Type:	Not reported
Contact Name:	MORRISVILLE AUXILIARY CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2021-01-14

Site Id:	615705
Affiliation Type:	Emergency Contact
Company Name:	MORRISVILLE AUXILIARY CORP
Contact Type:	Not reported
Contact Name:	MORRISVILLE AUXILIARY CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 684-6048
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2021-01-14

Tank Info:

Tank Number:	001
Tank ID:	289270
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1000
Install Date:	Not reported

WAREHOUSE (Continued) **U004339826**

Date Tank Closed: 12/02/2020
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 002
Tank ID: 289271
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: Not reported
Date Tank Closed: 12/02/2020
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

WAREHOUSE (Continued) **U004339826**

Tank Number:	003
Tank ID:	289272
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	12/02/2020
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

---

63 **SYRACUSE UNIVERSITY - BREWSTER/BOLAND** **RCRA NonGen / NLR** **1000552352**
ESE **401 VAN BUREN ST** **FINDS** **NYD986947505**
1/8-1/4 **SYRACUSE, NY 13244** **ECHO**
0.182 mi. **E MANIFEST**
962 ft. **NY MANIFEST**

Relative: **Higher**
Actual: **452 ft.**

RCRA Listings:

Date Form Received by Agency:	20180501
Handler Name:	Syracuse University - Brewster/Boland
Handler Address:	Van Buren St
Handler City,State,Zip:	SYRACUSE, NY 13244
EPA ID:	NYD986947505
Contact Name:	DANIEL G KLACZANY
Contact Address:	LYMAN HALL
Contact City,State,Zip:	SYRACUSE, NY 13244-1270
Contact Telephone:	315-443-9132
Contact Fax:	Not reported
Contact Email:	DGKLACZA@SYR.EDU
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

State District:		NYSDEC R7
Mailing Address:		LYMAN HALL
Mailing City,State,Zip:		SYRACUSE, NY 13244-1270
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20180501
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	NONE
Waste Description:	Not Defined
Waste Code:	X002

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE UNIV BOARD OF TRUSTEES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: TOLLEY ADMIN BLDG
Owner/Operator City,State,Zip: SYRACUSE, NY 13244
Owner/Operator Telephone: 315-443-4132
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE UNIVERSITY BOARD OF TRUSTEES
Legal Status: Private
Date Became Current: 19660901
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE UNIVERSITY BOARD OF TRUSTEES
Legal Status: Private
Date Became Current: 19470415
Date Ended Current: Not reported
Owner/Operator Address: CROUSE-HINDS HALL
Owner/Operator City,State,Zip: SYRACUSE, NY 13244-1270
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180501
Handler Name: SYRACUSE UNIVERSITY - BREWSTER/BOLAND
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19911025
Handler Name: SYRACUSE UNIVERSITY
Federal Waste Generator Description: Not a generator, verified

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SYRACUSE UNIVERSITY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070603
Handler Name: SYRACUSE UNIVERSITY - BREWSTER/BOLAND
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19910410
Handler Name: SYRACUSE UNIVERSITY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070604
Handler Name: SYRACUSE UNIVERSITY - BREWSTER/BOLAND
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61131
NAICS Description: Colleges, Universities, And Professional Schools

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004464268

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000552352
Registry ID: 110004464268

DFR URL:
Name: SYRACUSE UNIVERSITY - BREWSTER/BOLAND
Address: 401 VAN BUREN ST
City,State,Zip: SYRACUSE, NY 13244

E MANIFEST:
Manifest Tracking Number: 001016443VES
Last Updated Date: 20180917
Shipped Date: 20180801
Received Date: 20180810
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYCESQG
Generator Name: Syracuse University-(Brockway)
Generator Location Street Number: Not reported
Generator Location Street 1: 401 VAN BUREN STREET
Generator Location Street 2: BREWSTER/BOLAND/BROCKWAY HALLS
Generator Location City: SYRACUSE
Generator Location State: NY

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Generator Location Zip:	13210-0000
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	C/O EHSS (DAN KLACZANY)
Generator Mail Street 2:	100 COLLEGE PLACE
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13210-0000
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1 EDEN LANE
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	1 EDEN LANE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions Llc
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	001016443VES
Transporter Line Number:	1
Transporter EPA ID:	NJD080631369
Transporter Name:	Veolia Es Technical Solutions
Manifest Tracking Number:	001016443VES
Transporter Line Number:	2
Transporter EPA ID:	NJD054126164
Transporter Name:	Freehold Cartage Inc
Manifest Tracking Number:	001016443VES
Transporter Line Number:	3
Transporter EPA ID:	NJD080631369
Transporter Name:	Veolia Es Technical Solutions
Manifest Tracking Number:	001016443VES
Transporter Line Number:	4
Transporter EPA ID:	NJD054126164
Transporter Name:	Freehold Cartage Inc

Waste Line:

Manifest Tracking Number:	001016443VES
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3432
U.S. DOT Description:	Un3432, Waste Polychlorinated Biphenyls, Solid, (Debris >50-Ppm Pcb'S: Caulk, Poly, Ppe, Concrete), 9, Ii, Rq (1-Lb/ Pcb'S/ B007)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	97
Quantity Unit of Measure Code:	K
Quantity Unit of Measure Description:	Kilograms
Waste Quantity, in Tons:	0.10694244
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.10694244
Waste Quantity, in Kilograms:	97
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	97
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	97
Quantity Non Haz Tons:	0.10694244
State Waste Codes:	NJ-ID27, NY-B, NY-B007
Manifest Tracking Number:	001016443VES
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3432
U.S. DOT Description:	Un3432, Waste Polychlorinated Biphenyls, Solid, (Debris >50-Ppm Pcb'S: Caulk, Poly, Ppe, Concrete), 9, Ii, Rq (1lb/ Pcb'S/ B007)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	96
Quantity Unit of Measure Code:	K
Quantity Unit of Measure Description:	Kilograms
Waste Quantity, in Tons:	0.10583994
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.10583994
Waste Quantity, in Kilograms:	96
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	96
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	96
Quantity Non Haz Tons:	0.10583994
State Waste Codes:	NJ-ID27, NY-B, NY-B007

NY MANIFEST:

EPA ID:	NYD986947505
Country:	USA
Name:	Syracuse University
Address:	401 VAN BUREN ST
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13244
Zip 4:	Not reported
Location Address 1:	401 VAN BUREN ST
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13244
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Syracuse University
Mailing Contact:	Syracuse University
Mailing Address 1:	108 COLLEGE PL BREWSTER BOLAND
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13244
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3154434132

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD054126164
Generator Ship Date:	05/12/2011
Trans1 Recv Date:	05/12/2011
Trans2 Recv Date:	05/24/2011
TSD Site Recv Date:	05/25/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Generator EPA ID:	NYD986947505
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000521519VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	B007
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	10
Units:	Kilograms
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NMD002208627
Generator Ship Date:	06/28/2007
Trans1 Recv Date:	06/28/2007
Trans2 Recv Date:	07/02/2007
TSD Site Recv Date:	07/06/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986947505
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000022147VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	B007
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	10
Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD080631369
Generator Ship Date:	06/06/2007
Trans1 Recv Date:	06/06/2007
Trans2 Recv Date:	06/08/2007
TSD Site Recv Date:	06/08/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986947505
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000021655VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	B007
Waste Code c:	Not reported

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	571
Units:	Kilograms
Number of Containers:	6
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	NYB2605401
Manifest Status:	Not reported
Trans1 State ID:	DT09844CA
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	05/09/1991
Trans1 Recv Date:	05/09/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986947505
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID 1:	KSD980964993
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B006
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02793
Units:	Kilograms
Number of Containers:	001
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Handling Method:	Landfill
Specific Gravity:	01.00

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD054126164
Generator Ship Date:	10/22/2015
Trans1 Recv Date:	10/22/2015
Trans2 Recv Date:	10/29/2015
TSD Site Recv Date:	11/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986947505
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000616657VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	199
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD054126164
Generator Ship Date:	07/18/2014
Trans1 Recv Date:	07/18/2014
Trans2 Recv Date:	07/25/2014
TSD Site Recv Date:	07/29/2014
Part A Recv Date:	Not reported

SYRACUSE UNIVERSITY - BREWSTER/BOLAND (Continued) **1000552352**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD986947505
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000609367VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	144
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

N64 **SOUTH SALINA SIDA** **NY SHWS** **S113916746**
WSW **1016-1018 MONTGOMERY ST.** **N/A**
1/8-1/4 **SYRACUSE, NY 13204**
0.187 mi.
987 ft. **Site 1 of 3 in cluster N**

Relative: **Lower**
Actual: **392 ft.**

SHWS:

Name:	SOUTH SALINA SIDA
Address:	1016-1018 MONTGOMERY ST.
City,State,Zip:	SYRACUSE, NY 13204
Program:	HW
Site Code:	422215
Classification:	N
Region:	7
Acres:	Not reported
HW Code:	734120
Record Add:	11/25/2009
Record Upd:	02/19/2010
Updated By:	BRWOLOSE
Site Description:	"Description Not Available"

SOUTH SALINA SIDA (Continued) **S113916746**

Env Problem:	""
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Syracuse Industrial Development Agency
Owner Address:	201 E. Washington Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

O65 **DR. KING ELEMENTARY SCHOOL** **RCRA-VSQG** **1025504816**
SSE **416 416 E RAYMOR AVENUE** **E MANIFEST** **NYR000240960**
1/8-1/4 **SYRACUSE, NY 13202**
0.209 mi.
1103 ft. **Site 1 of 2 in cluster O**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20190416
Handler Name:	King Elementary School
Handler Address:	E Raynor Ave
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NYR000240960
Contact Name:	ANDREW P MARTIN
Contact Address:	ERIE BLVD W
Contact City,State,Zip:	SYRACUSE, NY 13204
Contact Telephone:	315-413-1221
Contact Fax:	315-435-4235
Contact Email:	AMARTIN@SCSD.US
Contact Title:	LABOR CREWLEADER
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

Actual:
398 ft.

DR. KING ELEMENTARY SCHOOL (Continued) **1025504816**

Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		ERIE BLVD W
Mailing City,State,Zip:		SYRACUSE, NY 13204
Owner Name:	Syracuse City School District	
Owner Type:		Municipal
Operator Name:	Syracuse City School District	
Operator Type:		Municipal
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20190422
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

DR. KING ELEMENTARY SCHOOL (Continued) **1025504816**

Waste Code: D003
Waste Description: Reactive Waste

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D006
Waste Description: Cadmium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D028
Waste Description: 1,2-Dichloroethane

Waste Code: P106
Waste Description: Sodium Cyanide (Or) Sodium Cyanide Na(Cn)

Waste Code: U031
Waste Description: 1-Butanol (I) (Or) N-Butyl Alcohol (I)

Waste Code: U077
Waste Description: Ethane, 1,2-Dichloro- (Or) Ethylene Dichloride

Waste Code: U144
Waste Description: Acetic Acid, Lead(2+) Salt (Or) Lead Acetate

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U160
Waste Description: 2-Butanone, Peroxide (R,T) (Or) Methyl Ethyl Ketone Peroxide (R,T)

Waste Code: U188
Waste Description: Phenol

Waste Code: U219
Waste Description: Thiourea

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: SYRACUSE CITY SCHOOL DISTRICT

DR. KING ELEMENTARY SCHOOL (Continued) **1025504816**

Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 725 HARRISON STREET
Owner/Operator City,State,Zip: SYRACUSE, NY 13210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SYRACUSE CITY SCHOOL DISTRICT
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 725 HARRISON STREET
Owner/Operator City,State,Zip: SYRACUSE, NY 13210
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20190416
Handler Name: KING ELEMENTARY SCHOOL
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 611110
NAICS Description: Elementary And Secondary Schools

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 019376468JJK
Last Updated Date: 20190707
Shipped Date: 20190514
Received Date: 20190601
Manifest Status: Signed
Submission Type: DataImage5Copy

DR. KING ELEMENTARY SCHOOL (Continued) **1025504816**

Origin Type:	Service
Generator EPA ID:	NYR000240960
Generator Name:	Dr. King Elementary School
Generator Location Street Number:	416
Generator Location Street 1:	416 416 E RAYMOR AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13202
Generator Mail Street Number:	416
Generator Mail Street 1:	416 E Raymor Avenue
Generator Mail Street 2:	Not reported
Generator Mail City:	Syracuse
Generator Mail Zip:	13202
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	IND000646943
Designated Facility Name:	Tradebe Treatment & Recycling Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4343 KENNEDY AVE
Designated Facility Mail City:	EAST CHICAGO
Designated Facility Mail Zip:	46312
Designated Facility Mail State:	IN
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4343 KENNEDY AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	EAST CHICAGO
Designated Facility Location Zip:	46312
Designated Facility Location State:	IN
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	019376468JJK
Transporter Line Number:	1
Transporter EPA ID:	CTD021816889
Transporter Name:	Tradebe Transportation, Llc
Manifest Tracking Number:	019376468JJK
Transporter Line Number:	2
Transporter EPA ID:	NYD980769947
Transporter Name:	Hazmat Environmental Group Inc
Manifest Tracking Number:	019376468JJK
Transporter Line Number:	3
Transporter EPA ID:	INR000123497
Transporter Name:	Tradebe Transportation Llc

Waste Line:

Manifest Tracking Number:	019376468JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263 Waste Paint Related Material 3 Ii

DR. KING ELEMENTARY SCHOOL (Continued) **1025504816**

Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	105
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0525
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0525
Waste Quantity, in Kilograms:	47.619076
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	47.619076
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001
Quantity Haz Kg:	47.619076
Quantity Haz Tons:	0.0525
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported
Manifest Tracking Number:	019376468JJK
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263 Waste Paint Related Material 3 Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	71
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0355
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0355
Waste Quantity, in Kilograms:	32.199566
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	32.199566
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N

DR. KING ELEMENTARY SCHOOL (Continued) **1025504816**

Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001
Quantity Haz Kg:	32.199566
Quantity Haz Tons:	0.0355
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

O66 **KING ELEMENTARY SCHOOL** **NY MANIFEST** **S121993506**
SSE **416 E RAYNOR AVE** **NY COOLING TOWERS** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.209 mi.
1103 ft. **Site 2 of 2 in cluster O**

Relative: **Lower**
Actual: **398 ft.**

NY MANIFEST:

EPA ID:	NYR000240960
Country:	USA
Name:	King Elementary School
Address:	416 E RAYNOR AVE
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	416 E RAYNOR AVE
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	King Elementary School
Mailing Contact:	Dr. King Elementary School
Mailing Address 1:	416 E RAYNOR AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3154131221

COOLING TOWERS:

Name:	Not reported
Address:	416 E RAYNOR AVE
City,State,Zip:	SYRACUSE, NY 13202
Equipment Unique ID:	3847

KING ELEMENTARY SCHOOL (Continued) **S121993506**

Equipment Borough:	Not reported
Intended Use:	Air Conditioning
Manufacturer:	bac
Model:	je213
Cooling Capacity:	163
Cooling Capacity Unit:	Tonnage
Commissioned Date:	05/04/2009
Inspection Date:	07/06/2021
Date of Bacteriological Collection:	09/25/2021
Date of Legionella Collection:	10/31/2024
Last Legionella Result > 1,000 CFU/mL:	lt20
Last Sampled Days:	Not reported
Reg Compliant:	Not reported
Last Update Days:	Not reported
CT Status:	Not reported
Equipment Tower Operation Duration:	Not reported
Latitude:	43.035557
Longitude:	-76.144295

N67 **1045-1047 SOUTH SALINA STREET** **US BROWNFIELDS** **1016352211**
WSW **1045 SOUTH SALINA STREET** **FINDS** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.218 mi.
1151 ft. **Site 2 of 3 in cluster N**

Relative: **Lower**
Actual: **391 ft.**

US BROWNFIELDS:

Name:	1045-1047 South Salina Street
Address:	1045 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	14742
Property Alias:	Not reported
Recipient Name:	Syracuse, City of
Grant Type:	Not reported
Property Number:	Not reported
Parcel Size:	Not reported
Latitude:	43.037258
Longitude:	-76.149513
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BP
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported

1045-1047 SOUTH SALINA STREET (Continued) **1016352211**

Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	98229401
Start Date:	2002-09-30 00:00:00
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	2002-09-30 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Not reported
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	U
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Unknown
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported

1045-1047 SOUTH SALINA STREET (Continued) **1016352211**

Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2633
Below Poverty Percent:	54.14
Meidan Income:	1562
Meidan Income Number:	3682
Meidan Income Percent:	75.71
Vacant Housing Number:	281
Vacant Housing Percent:	14.52
Unemployed Number:	369
Unemployed Percent:	7.59

FINDS:
Registry ID: 110039546934

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P68
NNW
1/8-1/4
0.221 mi.
1165 ft.

EAST ADAMS REDEVELOPMENT - PHASE I AREA
100 ANGELOU TERRACE
SYRACUSE, NY 13202

Site 1 of 8 in cluster P

NY BROWNFIELDS **S131764059**
N/A

Relative:
Lower

Actual:
397 ft.

BROWNFIELDS:

Name:	EAST ADAMS REDEVELOPMENT - PHASE I AREA
Address:	100 ANGELOU TERRACE
City,State,Zip:	SYRACUSE, NY 13202
Program:	BCP
Site Code:	658151
Acres:	3.280
HW Code:	C734162
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	10/19/2023
Record Updated Date:	03/21/2024
Update By:	LSZINOMA
Site Description:	"03/20/2024 Site was denied from the Brownfield Cleanup Program (BCP). Based upon review of the BCP application, the proposed site is not a brownfield site as defined in Article 27, Title 14 of the Environmental Conservation Law. Location: The site is located at 100 Angelou Terrace within an urban, mixed-use area in the City of Syracuse, New York. The site is located in the northern portion of an about 11.10-acre tax parcel, identified as Onondaga County Tax Parcel 095.-08-01.0. The site is bound by East Adams Street followed by a parking garage at 817-835 South State Street to the north, South Townsend Street followed by a residential building at 1031-1059 South Townsend Street and Adams Street to the east, residential buildings at 301 311 East Taylor Street to the south, and South State Street followed by a fire station at 900 South State Street and an institutional building at 701 South Warren Street to the west. The site is improved with six, two-story multi-unit residential buildings and associated asphalt-paved parking lots and access roadways in the south-central part of the site. The remainder of the site is comprised of landscaped areas. The area surrounding the site consists of residential, commercial, institutional, and industrial properties. Site Features: According to the May 2023 Phase I Environmental Site Assessment (ESA) and the July 2023 Phase II ESA prepared by EA engineering, P.C. and Its Affiliate EA Science and Technology (EA), the elevation of the site is about elevation (el) 398 feet1. The topography of the site is generally flat with the surrounding area gently sloping towards the west. Current Zoning and Land Use: According to the Rezone Syracuse ordinance and City of Syracuse Zoning Map, the site is located within an MX-2: Neighborhood Center District. The MX-2: Neighborhood Center zoning district is generally characterized as pedestrian-friendly, transit-supportive mix of medium to higher density residential uses and non-residential uses that offer goods and services to surrounding neighborhoods. The surrounding properties are zoned for MX-2: Neighborhood Center Districts, MX-3: Mixed-Use Transition, MX-5: Central Business District, LI: Light Industrial and Employment, and OS: Open Space. Land use within a half-mile radius is urban and includes residential, commercial, institutional/public services, industrial, vacant land, and public parks. The nearest ecological receptor is the Onondaga Creek, located approximately 0.4 miles west of the site. At present, the site is occupied by six residential buildings, asphalt-paved parking lots and access roadways, and landscaped areas. Past Use of

EAST ADAMS REDEVELOPMENT - PHASE I AREA (Continued) **S131764059**

	the Site: Historical documents indicate that the site has been located in a residential and commercial area since as early as 1892. By 1892, the site was developed with several one- to two-story dwellings and a one-story church in the southeastern part of the site. Historical uses of the site also included a fire department (1910 to 1953), junk yard (1910 to 1961), church (1961 to 1982), a gym and auditorium (1951 to 1961), and auto parking (1951). By 1989, the site was occupied by the Syracuse Housing Authority and developed in its present-day configuration. Site Geology and Hydrogeology: According to the U.S. Department of Agriculture s (USDA) Natural Resources Conservation Service (NRCS) Soil Survey Geographic (SSURGO) data for the site, soils at the site are comprised primarily of urban land. Urban land is described as excavated, filled, and made land. According to the Phase II ESA conducted by EA, soil at the site consists of historic fill comprised primarily of brown sand, silt, and clay with varying amounts of gravel, clay, brick, asphalt, glass, and tile to about 3 feet below grade surface (bgs). This layer is underlain by brown to gray silt and clay, fine-grained sand, and gravel to the termination depth of the borings (about 15 feet bgs). Bedrock was not encountered during the investigation. Based on review of the Geologic Map of New York, Finger Lakes Sheet (Fisher, Isachsen, Rickard, dated March 1970) , the site is underlain by bedrock of the Syracuse Foundation, consisting of dolostone, shale, gypsum and salt. Based on measurements collected during the Phase II ESA conducted by EA, groundwater at the site flows to the northwest, following the local topography, towards Onondaga Creek. Groundwater was observed at about 7.3 to 10.3 feet bgs (corresponding to el. 395.21 to el. 390.23). "
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	4
Sub Type:	NNN
Owner Name:	William J Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Rene Battelle

EAST ADAMS REDEVELOPMENT - PHASE I AREA (Continued) **S131764059**

Owner Company:	Onondaga County Public Libraries-Central Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13205
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	William J Simmons
Owner Company:	Syracuse Housing Authority
Owner Address:	516 Burt Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Allyson Carpenter
Owner Company:	East Adams Phase I. L.P.
Owner Address:	100 North Broadway, Suite 100
Owner Addr2:	Not reported
Owner City,St,Zip:	St. Louis, MO 63102
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Q69 **FAMILY DOLLAR #5071** **NY MANIFEST** **S118708542**
West **945 S SALINA ST** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.222 mi.
1174 ft. **Site 1 of 3 in cluster Q**

Relative:
Lower

Actual:
396 ft.

NY MANIFEST:

EPA ID:	NYR000211730
Country:	USA
Name:	Family Dollar #5071
Address:	945 S SALINA ST
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	945 S SALINA ST
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Family Dollar #5071
Mailing Contact:	Family Dollar #5071
Mailing Address 1:	945 S SALINA ST

FAMILY DOLLAR #5071 (Continued) **S118708542**

Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13202
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: PAD982661381
Year: 2018
Trans2 State ID: NJR000063677
Generator Ship Date: 05/17/2016
Trans1 Recv Date: 05/17/2016
Trans2 Recv Date: 05/24/2016
TSD Site Recv Date: 05/25/2016
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000211730
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: RID040098352
TSDF ID 2: Not reported
Manifest Tracking Number: 009248480FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Ignitable Waste
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 13
Units: Pounds
Number of Containers: 1
Container Type: Fiber or plastic boxes, cartons, cases
Handling Method: Landfill
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: PAD982661381

FAMILY DOLLAR #5071 (Continued) **S118708542**

Year:	2018
Trans2 State ID:	NJR000063677
Generator Ship Date:	05/17/2016
Trans1 Recv Date:	05/17/2016
Trans2 Recv Date:	05/24/2016
TSD Site Recv Date:	05/25/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000211730
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	009248480FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Methyl Ethyl Ketone
Waste Code c:	2-Propanone (I) (Or) Acetone (I)
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3
Units:	Pounds
Number of Containers:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	PAD982661381
Year:	2018
Trans2 State ID:	NJR000063677
Generator Ship Date:	05/17/2016
Trans1 Recv Date:	05/17/2016
Trans2 Recv Date:	05/24/2016
TSD Site Recv Date:	05/25/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000211730
Trans1 EPA ID:	Not reported

FAMILY DOLLAR #5071 (Continued) **S118708542**

Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	009248480FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	Corrosive Waste
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	10
Units:	Pounds
Number of Containers:	1
Container Type:	Burlap, cloth, paper or plastic bags
Handling Method:	Treat
Specific Gravity:	1

Q70 **FAMILY DOLLAR #5071** **RCRA-VSQG** **1016974714**
West **945 S SALINA ST** **ECHO** **NYR000211730**
1/8-1/4 **SYRACUSE, NY 13202**
0.222 mi.
1174 ft. **Site 2 of 3 in cluster Q**

Relative: **Lower**
Actual: **396 ft.**

RCRA Listings:

Date Form Received by Agency:	20140806
Handler Name:	Family Dollar #5071
Handler Address:	S Salina St
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NYR000211730
Contact Name:	KEVIN STRAIGHT
Contact Address:	PO BOX 1017
Contact City,State,Zip:	CHARLOTTE, NC 28201
Contact Telephone:	704-708-1909
Contact Fax:	Not reported
Contact Email:	KSTRAIGHT@FAMILYDOLLAR.COM
Contact Title:	PROGRAM MANAGER ENVIRONMENTAL COMPLIANCE
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported

FAMILY DOLLAR #5071 (Continued) **1016974714**

Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		PO BOX 1017
Mailing City,State,Zip:		CHARLOTTE, NC 28201
Owner Name:	Family Dollar Stores	
Owner Type:		Private
Operator Name:	Family Dollar Stores	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20151218
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

FAMILY DOLLAR #5071 (Continued) **1016974714**

Waste Code: D004
Waste Description: Arsenic

Waste Code: D005
Waste Description: Barium

Waste Code: D007
Waste Description: Chromium

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: FAMILY DOLLAR STORES
Legal Status: Private
Date Became Current: 20020516
Date Ended Current: Not reported
Owner/Operator Address: 10301 MONROE RD
Owner/Operator City,State,Zip: MATTHEWS, NC 28105
Owner/Operator Telephone: 866-377-6420
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: FAMILY DOLLAR STORES
Legal Status: Private
Date Became Current: 20020516
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

FAMILY DOLLAR #5071 (Continued) **1016974714**

Historic Generators:
- Receive Date: 20140806
- Handler Name: FAMILY DOLLAR #5071
- Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
- State District Owner: Ny
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 45299
- NAICS Description: All Other General Merchandise Stores

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

ECHO:
- Envid: 1016974714
- Registry ID: 110060282493

DFR URL:
- Name: FAMILY DOLLAR #5071
- Address: 945 S SALINA ST
- City,State,Zip: SYRACUSE, NY 13202

N71 **1049-1071 SOUTH SALINA STREET** **US BROWNFIELDS** **1016352214**
WSW **1049-1071 SOUTH SALINA STREET** **FINDS** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.224 mi.
1182 ft. **Site 3 of 3 in cluster N**

Relative:
Lower

Actual:
390 ft.

US BROWNFIELDS:
- Name: 1049-1071 South Salina Street
- Address: 1049-1071 South Salina Street
- City,State,Zip: SYRACUSE, NY 13202
- Property ID: 14743
- Property Alias: Not reported
- Recipient Name: Syracuse, City of
- Grant Type: Not reported
- Property Number: Not reported
- Parcel Size: Not reported
- Latitude: 43.037208
- Longitude: -76.149506
- Census Tract: 36067004200
- State or Tribal Voluntary Response Program: Not reported

1049-1071 SOUTH SALINA STREET (Continued) **1016352214**

Program Name:	BP
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	98229401
Start Date:	2002-09-30 00:00:00
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	2002-09-30 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Not reported
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	U
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported

1049-1071 SOUTH SALINA STREET (Continued) **1016352214**

RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Unknown
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2563
Below Poverty Percent:	55.02
Meidan Income:	1562
Meidan Income Number:	3603
Meidan Income Percent:	77.35
Vacant Housing Number:	276
Vacant Housing Percent:	14.66
Unemployed Number:	366
Unemployed Percent:	7.86

FINDS:
Registry ID: 110039546961

1049-1071 SOUTH SALINA STREET (Continued) **1016352214**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P72 **SYRACUSE POLICE DEPT GAS DEPOT** **UST FINDER** **1028588826**
NNW **916 S STATE ST** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.227 mi.
1199 ft. **Site 2 of 8 in cluster P**

Relative:
Lower

Actual:
396 ft.

UST FINDER:

Object ID:	318245
Facility ID:	NY45027
Name:	SYRACUSE POLICE DEPT GAS DEPOT
Address:	916 S STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	1786
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, Low Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-76.147611
Y Coord:	43.0408660000001
Latitude:	43.040866
Longitude:	-76.147611

UST FINDER:

Object ID:	1278206
Facility ID:	NY45027
Tank ID:	NY79341
Tank Status:	Closed
Installation Date:	1980/10/01 16:00:00+00
Removal Date:	Not reported

SYRACUSE POLICE DEPT GAS DEPOT (Continued) **1028588826**

Tank Capacity:	10000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1278207
Facility ID:	NY45027
Tank ID:	NY71200
Tank Status:	Closed
Installation Date:	1980/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Not reported
Tank Wall Type:	Not reported

P73 **SYRACUSE POLICE DEPT GAS DEPOT** **NY UST** **U003313254**
NNW **916 S STATE ST** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.227 mi.
1199 ft. **Site 3 of 8 in cluster P**

Relative:
Lower

Actual:
396 ft.

UST:

Name:	SYRACUSE POLICE DEPT GAS DEPOT
Address:	916 S STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-181803 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	N/A
UTM X:	406521.69565
UTM Y:	4765991.90851
Site Type:	Unknown

Affiliation Records:

Site Id:	45027
Affiliation Type:	Facility Owner
Company Name:	SYRACUSE POLICE DEPT GAS DEPOT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	511 S STATE ST
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 425-6165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	45027
Affiliation Type:	Mail Contact
Company Name:	SYRACUSE POLICE DEPT GAS DEPOT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	511 S STATE ST

SYRACUSE POLICE DEPT GAS DEPOT (Continued) **U003313254**

Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 425-6165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	45027
Affiliation Type:	Facility Operator
Company Name:	SYRACUSE POLICE DEPT GAS DEPOT
Contact Type:	Not reported
Contact Name:	SYRACUSE POLICE DEPT GAS DEPOT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 425-6165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	45027
Affiliation Type:	Emergency Contact
Company Name:	SYRACUSE POLICE DEPT GAS DEPOT
Contact Type:	Not reported
Contact Name:	SYRACUSE POLICE GARAGE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 425-6165
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	129827
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	10/01/1980
Date Tank Closed:	09/01/1993
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

SYRACUSE POLICE DEPT GAS DEPOT (Continued) **U003313254**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 002
Tank ID: 129828
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 10000
Install Date: 10/01/1980
Date Tank Closed: 09/01/1993
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

R74 **1073-1079 SOUTH SALINA STREET** **US BROWNFIELDS** **1016352218**
WSW **1073-1079 SOUTH SALINA STREET** **FINDS** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.231 mi.
1219 ft. **Site 1 of 4 in cluster R**

Relative: **Lower**

Actual: **390 ft.**

US BROWNFIELDS:

Name:	1073-1079 South Salina Street
Address:	1073-1079 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	14744
Property Alias:	Not reported
Recipient Name:	Syracuse, City of
Grant Type:	Not reported
Property Number:	Not reported
Parcel Size:	Not reported
Latitude:	43.036912
Longitude:	-76.149464
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BP
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	98229401
Start Date:	2002-12-31 00:00:00
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	2002-12-31 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Not reported
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported

1073-1079 SOUTH SALINA STREET (Continued) **1016352218**

Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	U
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Unknown
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported

1073-1079 SOUTH SALINA STREET (Continued) **1016352218**

Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2598
Below Poverty Percent:	54.51
Meidan Income:	1562
Meidan Income Number:	3674
Meidan Income Percent:	77.09
Vacant Housing Number:	285
Vacant Housing Percent:	14.75
Unemployed Number:	374
Unemployed Percent:	7.85

FINDS:
Registry ID: 110039547005

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

R75 **1101-1111 SOUTH SALINA STREET** **US BROWNFIELDS** **1016352224**
SW **1101-1111 SOUTH SALINA STREET** **FINDS** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.232 mi.
1224 ft. **Site 2 of 4 in cluster R**

Relative:
Lower

Actual:
390 ft.

US BROWNFIELDS:

Name:	1101-1111 South Salina Street
Address:	1101-1111 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	14746
Property Alias:	Not reported
Recipient Name:	Syracuse, City of
Grant Type:	Not reported
Property Number:	Not reported
Parcel Size:	Not reported
Latitude:	43.036312
Longitude:	-76.149452
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BP
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported

1101-1111 SOUTH SALINA STREET (Continued) **1016352224**

Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	98229401
Start Date:	2002-09-30 00:00:00
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	2002-09-30 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Not reported
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	U
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Unknown
RLF Loan - Program Income Used:	Not reported

1101-1111 SOUTH SALINA STREET (Continued) **1016352224**

Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2555
Below Poverty Percent:	53.61
Meidan Income:	1562
Meidan Income Number:	3612
Meidan Income Percent:	75.79
Vacant Housing Number:	283
Vacant Housing Percent:	14.86
Unemployed Number:	354
Unemployed Percent:	7.43

FINDS:
Registry ID: 110039547078

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

R76 **1081-1085 SOUTH SALINA STREET** **US BROWNFIELDS** **1016352220**
WSW **1081-1085 SOUTH SALINA STREET** **FINDS** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.234 mi.
1234 ft. **Site 3 of 4 in cluster R**

Relative:
Lower

Actual:
390 ft.

US BROWNFIELDS:

Name:	1081-1085 South Salina Street
Address:	1081-1085 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	14745
Property Alias:	Not reported
Recipient Name:	Syracuse, City of
Grant Type:	Not reported
Property Number:	Not reported
Parcel Size:	Not reported
Latitude:	43.036813
Longitude:	-76.14945
Census Tract:	36067004200
State or Tribal Voluntary Response Program:	Not reported
Program Name:	BP
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	98229401
Start Date:	2002-09-30 00:00:00
Ownership Entity:	Not reported
Additional Institutional Controls Information:	Not reported
Completion Date:	2002-09-30 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Not reported
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported

1081-1085 SOUTH SALINA STREET (Continued) **1016352220**

Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	U
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Unknown
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported

1081-1085 SOUTH SALINA STREET (Continued) **1016352220**

Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2632
Below Poverty Percent:	53.85
Meidan Income:	1562
Meidan Income Number:	3718
Meidan Income Percent:	76.06
Vacant Housing Number:	288
Vacant Housing Percent:	14.62
Unemployed Number:	378
Unemployed Percent:	7.73

FINDS:
Registry ID: 110039547032

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

R77 **SOUTH SALINA STREET PARCELS** **NY BROWNFIELDS S122449240**
WSW **1081 SOUTH SALINA STREET** **NY Spills N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.234 mi.
1234 ft. **Site 4 of 4 in cluster R**

Relative:
Lower

Actual:
390 ft.

BROWNFIELDS:

Name:	SOUTH SALINA STREET PARCELS
Address:	1081 SOUTH SALINA STREET
City,State,Zip:	SYRACUSE, NY 13202
Program:	BCP
Site Code:	570636
Acres:	1.892
HW Code:	C734140
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	05/22/2018
Record Updated Date:	06/17/2024
Update By:	GWPRISCO
Site Description:	"Location: The site is 1.89 acres and is bordered on the west by South Salina Street, across the street from the former Coyne Textile Services Brownfield Cleanup Program site (ref. Site No. C734144); on the south by a church; to the north by a small glass and mirror shop; and to the east by a community center along Montgomery Street. Site Features: Currently, the site is undeveloped with no structures on the property. The site is a relatively flat lot with broken pavement along with grassed-vegetated areas and some mature trees across the property. Current Zoning and Land Use: The site property is zoned as BA District, which permits the intensive development of land for mixed residential, retail, service and certain industrial uses.

SOUTH SALINA STREET PARCELS (Continued) **S122449240**

Adjacent parcels are zoned for commercial (CA) to the north, west, and southwest, BA to the north and south, and residential (RB) to the east. Other nearby parcels are a mix of industrial, commercial, business, and residential land uses. Past Use of the Site: Previously, the site was used as an above-ground storage tank facility for manufactured gas generated from coal or oil. The approximately 125-foot diameter tank, called a gasometer, stored gas for distribution for city and private lighting, cooking, and heating. The facility operated in the late 1890s until taken out of service sometime before 1951. Thereafter, various uses of the site included a rug cleaner, bottling operation, laundry/dry cleaner, automobile repair, refrigerator repair shop, tailor, plumbing shop, paint shop, and a glass warehouse. The buildings were demolished in the late 1970s and early 1980s and then the site was used as a parking lot. Site Geology and Hydrogeology: The greater portion of the site is underlain with a mix of sand, silt, and clay soils that contain historic fill to a depth of approximately 20 feet. The historic fill contains clay tile, ash, coal and brick. Native soil is located below the fill and consists of peat and marl. The depth to water is approximately 7 to 10 feet below grade with groundwater flow direction to the north-west "

Env Problem:

"A remedial investigation was conducted to assess the nature and extent of contamination at the site. The remedial investigation consisted of the following elements: the evaluation of buried utilities; collection and analysis of eight surface soil samples; the installation of 33 soil borings which included the collection and analysis of 18 subsurface soil samples; the excavation of six test pits with the analysis of one soil sample; and the installation of five groundwater monitoring wells which included two rounds of groundwater monitoring. Soil and groundwater samples were analyzed for a combination of volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), pesticides, herbicides, PCBs, metals (including mercury, cyanide, and hexavalent chromium), 1,4-dioxane, and PFOS/PFOA. Soils: Contaminants of concern have been identified at concentrations that exceed the Restricted-Residential (RR) Soil Cleanup Objectives (SCOs). The contamination of the soils is generally associated within the historical fill material (HFM) at the site. HFM was observed at varying depths from the surface to approximately 20 feet below grade. SVOCs are present in surface soil samples across the site at concentrations that exceed Restricted-Residential Use SCOs. SVOCs and metals are also present in the sub-surface soils within the HFM at concentrations above Restricted Residential Use SCOs. The types and concentrations of SVOCs and metals that have been identified are consistent with those typically found in historically industrialized urban areas. Native soils sampled from beneath the HFM do not exceed RR SCOs for any analytes. These results suggest that the contaminants of concern are contained within the observed on-site HFM. Surface Soil: Sampling depth: 0 to 2 inches A total of eight surface samples were obtained across the site. Laboratory results indicate several SVOCs are above Restricted Residential (RR) use SCOs including, benzo(a)anthracene with concentrations ranging from 1.7 to 5.5 parts per million (ppm) compared to the RR Use SCO value of 1 ppm; benzo(a)pyrene with concentrations ranging from 1.6 to 4.8 ppm compared to the RR Use SCO value of 1 ppm; benzo(b)fluoranthene with concentrations ranging from 2.3 to 6.6 ppm compared to the RR Use SCO value of 1 ppm; chrysene with concentrations ranging 1.7 to 5.2 ppm compared to the RR Use SCO

SOUTH SALINA STREET PARCELS (Continued) **S122449240**

value of 3.9 ppm; dibenzo(a,h)anthracene with concentrations ranging from 0.37 to 0.7 ppm compared to the RR Use SCO value of 0.33 ppm, and indeno (1,2,3-cd)pyrene with concentrations ranging from 1.1 to 2.8 ppm compared to the RR Use SCO value of 0.5 ppm. Sub-Surface Soils: A total of 18 subsurface samples were collected from across the site. Laboratory results of the soils samples obtained from areas containing HFM indicate SVOCs are present at concentrations above Protection of Groundwater SCOs and Restricted-Residential Use SCOs and, to a lesser degree, metals are present at concentrations above Residential-Restricted Use SCOs Laboratory results indicate several SVOCs are above Restricted Residential Use SCOs including, benzo(a)anthracene with concentrations ranging from 1.6 to 51 parts per million (ppm) compared to the RR Use SCO value of 1 ppm; benzo(a)pyrene with concentrations ranging from 1.2 to 39 ppm compared to the RR Use SCO value of 1 ppm; benzo(b)fluoranthene with concentrations ranging from 1.6 to 49 ppm compared to the RR Use SCO value of 1 ppm; benzo(k)fluoranthene with concentrations ranging from 8.2 to 18 ppm compared to the RR Use SCO value of 3.9 ppm; chrysene with concentrations ranging 3.9 to 40 ppm compared to the RR Use SCO value of 3.9 ppm; dibenzo(a,h)anthracene with concentrations ranging from 0.38 to 5.3 ppm compared to the RR Use SCO value of 0.33 ppm; indeno(1,2,3-cd) pyrene with concentrations ranging from 0.72 to 24 ppm compared to the RR Use SCO value of 0.5 ppm, and phenanthrene with a concentration of 100 ppm compared to the RR Use SCO value of 100 ppm. Laboratory results indicate several metals above Restricted Residential Use SCOs including, total copper with a concentration of 495 ppm compared to the RR Use SCO value of 270 ppm; lead with a concentration of 415 ppm compared to the RR Use SCO value of 400 ppm; and total mercury with concentrations ranging from 0.88 to 1.2 ppm compared to the RR Use SCO value of 0.81 ppm. Five test pits were advanced at areas identified as anomalies during a previous geophysical study. At each location, the subsurface contained construction and demolition (C&D) debris, including wood, concrete, brick, asphalt, as well as HFM. Similar observations of fill were made in borings advanced within a large anomaly that coincided with the footprint of the former gasometer. No tanks, vaults, or other subsurface structures were identified while excavating the test pits. In addition, no visual evidence of contamination (e.g., stains or odors) was observed. Due to the presence of ash at test pit TP-4, a sample was collected. Laboratory results indicate no analytes were above Restricted-Residential Use SCOs. Groundwater: Groundwater samples were collected twice, once in October 2019 and again in January 2020, from five groundwater monitoring wells across the site. The depth to groundwater is approximately seven to ten feet below grade with a groundwater flow direction to the northwest. The results of the laboratory analysis indicate the principal groundwater contaminants are volatile organic compounds (VOCs). A number of VOCs were observed above the NYSDEC Technical and Operational Guidance Series (TOGS) groundwater protection standards. The groundwater contamination is primarily located in the central portion of the site in monitoring wells MW-1 and MW-2. Benzene is present at monitoring wells MW-1 and MW-2 with a concentration range from 58 to 190 ppb, compared to the TOGS standard of 1 ppb. Toluene is present in MW-2 with a concentration range from 11 to 40 ppb, compared to the TOGS standard of 5 ppb. Ethylbenzene is present in MW-2 with a concentration range from ND to 19 ppb, compared to the TOGS standard of 5 ppb. P/M xylene is present in MW-2

SOUTH SALINA STREET PARCELS (Continued) **S122449240**

with a concentration range from ND to 20 ppb, compared to the TOGS standard of 5 ppb. O-xylene is present in MW-2 with a concentration range from ND to 12 ppb, compared to the TOGS standard of 5 ppb. Styrene is present in MW-2 with a concentration range from ND to 8.8 ppb, compared to the TOGS standard of 5 ppb. No other VOCs exceeded NYSDEC TOGS values at the site. There are several semi-volatile organic compounds (SVOCs) that are slightly above NYSDEC TOGS groundwater protection values, with no single compound concentration greater than 0.12 parts per billion (ppb). Laboratory results identified the following compounds above the NYSDEC TOGS value of 0.002 ppb: benzo(a) anthracene ranging from 0.02 to 0.12 ppb; benzo(a)pyrene ranging from 0.02 to 0.09 ppb; benzo(b)fluoranthene ranging from 0.01 to 0.11 ppb; benzo (k)fluoranthene ranging from 0.01 to 0.05 ppb; chrysene ranging from 0.01 to 0.07 ppb; and indeno (1,2,3-cd) pyrene ranging from 0.02 to 0.07 ppb. Laboratory analysis of the groundwater for pesticides, herbicides and PCBs are non-detect at concentrations greater than the laboratory detection limits. Laboratory analysis of the groundwater for PFOA and PFOS indicate concentrations that are below NYS DEC/DOH threshold values. Laboratory analysis results for 1,4 dioxane are non-detect. Metals commonly associated with hard water (e.g., iron, magnesium, manganese, sodium) are present at concentrations above the TOGs values in each well. These metals are likely naturally occurring and in this setting are unrelated to the site's past activities. However, in monitoring well MW-1 barium slightly exceeds the TOGS value of 1,000 ppb, with a concentration value of 1,002 ppb. In addition, the general region of central New York has been known for elevated saline (sodium) concentrations in the groundwater. Laboratory analysis of the groundwater from this site supports this with dissolved sodium concentrations range from 35,200 up to 181,000 parts per billion in comparison to the TOGS value of 20,000 parts per billion. Off-site impacts in soil and groundwater are expected to be minimal based on the level and pattern of on-site contamination. SVOCs are present in surface soil and sub-surface soil across the site at concentrations that exceed Restricted-Residential Use SCOs and Protection of Groundwater SCOs. However, the types and concentrations of SVOCs and metals that have been identified in the soil are typically found at historically industrialized urban areas as in this instance. There are moderate levels of VOCs in site groundwater that are primarily located within the central portion of the site. Concentrations of SVOCs in site groundwater are slightly above groundwater protection values, but SVOCs do not readily migrate. Given the moderate concentrations of the contaminants of concern in the soil and groundwater it is anticipated the contaminants concentrations will decrease over time due to adsorption and natural attenuation. As a result, it is expected that off-site impacts from on-site contamination to neighboring properties is minimal. "

Health Problem: "People who enter the site may come into contact with site related soil and groundwater contamination if they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants

SOUTH SALINA STREET PARCELS (Continued) **S122449240**

	in indoor air via the soil vapor intrusion pathway is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future onsite development. Environmental sampling indicates that soil vapor intrusion associated with contamination at the site is not a concern for offsite buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-07 10:39:00
Record Upd:	2020-02-21 11:10:00
Updated By:	CFMANNES
Own Op:	1
Sub Type:	P03
Owner Name:	Gail Montplaisir
Owner Company:	Salina 1st, LLC
Owner Address:	321 West Taylor Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Honora Spillane
Owner Company:	Syracuse Industrial Development Agency
Owner Address:	City Commons Hall, 201 E. Washington St, 7th Fl.
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Christopher F. Mannes, P.E.
Owner Company:	NYS DEC - Region 7 Office
Owner Address:	615 Erie Blvd. West
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13204
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Gail montplaisir
Owner Company:	Salina 1st, LLC
Owner Address:	1341 H Street, Suite 301
Owner Addr2:	Not reported
Owner City,St,Zip:	Wasington, DC 20002
Owner Country:	United States of America
HW Code:	C734140
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN

SOUTH SALINA STREET PARCELS (Continued) **S122449240**

Waste Code:	Not reported
HW Code:	C734140
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	styrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734140
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

SOUTH SALINA STREET PARCELS (Continued) **S122449240**

Crossref ID:	2022-00051127
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2023-10-13 15:52:00
Record Updated:	2023-10-13 15:52:00
Updated By:	ACLOFARO
Crossref ID:	734140
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2022-10-17 15:11:00
Record Updated:	2022-10-17 15:11:00
Updated By:	CFMANNES
Crossref ID:	734120
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2022-10-17 15:18:00
Record Updated:	2022-10-17 15:18:00
Updated By:	CFMANNES

SPILLS:

Name:	CONTRUCTION SITE
Address:	1081 SOUTH SALINA ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2204171 / 2022-08-18
Facility ID:	2204171
Facility Type:	ER
DER Facility ID:	586819
Site ID:	640303
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3415
Spill Date:	2022-08-11
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2022-08-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2022-08-11
Spill Record Last Update:	2022-08-18
Spiller Name:	BERTI
Spiller Company:	PARAGON ENVIRONMENTAL CONTRUCTION
Spiller Address:	1081 SOUTH SALINA ST
Spiller Company:	999
Contact Name:	BERTI
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	handled by chris mannes
Remarks:	Clean up completed.

SOUTH SALINA STREET PARCELS (Continued) **S122449240**

All Materials:

Site ID:	640303
Operable Unit ID:	1387352
Operable Unit:	01
Material ID:	2402272
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

P78 **FIRE STATION #1** **NY UST** **U003313266**
NNW **900 SOUTH STATE ST** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.243 mi.
1282 ft. **Site 4 of 8 in cluster P**

Relative: **Lower**

Actual: **396 ft.**

UST:

Name:	FIRE STATION #1
Address:	900 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-181935 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	06/30/2027
UTM X:	406500.41583
UTM Y:	4766163.01145
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	45039
Affiliation Type:	Mail Contact
Company Name:	CITY OF SYRACUSE FIRE DEPT
Contact Type:	Not reported
Contact Name:	ZACH SMITH
Address1:	FIRE MAINTENANCE
Address2:	312 STATE FAIR BLVD
City:	SYRACUSE
State:	NY
Zip Code:	13204
Country Code:	001
Phone:	(315) 448-4777
EMail:	ZSMITH@SYR.GOV
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2024-07-17

Site Id:	45039
Affiliation Type:	Facility Owner
Company Name:	CITY OF SYRACUSE
Contact Type:	DEPUTYCHIEF - SYRACUSE FIRE DEPT
Contact Name:	ZACH SMITH

FIRE STATION #1 (Continued) **U003313266**

Address1:	CITY HALL - 233 EAST WASHINGTON ST
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 448-8200
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2022-04-26

Site Id:	45039
Affiliation Type:	Emergency Contact
Company Name:	CITY OF SYRACUSE FIRE DEPT
Contact Type:	Not reported
Contact Name:	CHIEF OF FIRE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 473-3230
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2024-07-17

Site Id:	45039
Affiliation Type:	Facility Operator
Company Name:	FIRE STATION #1
Contact Type:	Not reported
Contact Name:	JEFF GROSSO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 473-5495
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2019-03-06

Tank Info:

Tank Number:	001
Tank ID:	129862
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1974
Date Tank Closed:	05/01/1995
Registered:	True
Tank Location:	Underground

FIRE STATION #1 (Continued) **U003313266**

Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 11
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 002
Tank ID: 129863
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 2000
Install Date: 12/01/1974
Date Tank Closed: 05/01/1995
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 11
Date Test: 05/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 137149
Tank Status: In Service

FIRE STATION #1 (Continued) **U003313266**

Material Name:	In Service
Capacity Gallons:	2500
Install Date:	05/01/1995
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
F05 - Pipe External Protection - Jacketed
H05 - Tank Leak Detection - In-Tank System (ATG)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
B00 - Tank External Protection - None
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

P79 **NIAGARA MOHAWK A NATIONAL GRID COMPANY** **NY MANIFEST** **S130581177**
NNW **900 SOUTH STATE STREET** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.243 mi.
1282 ft. **Site 5 of 8 in cluster P**

Relative:
Lower

Actual:
396 ft.

NY MANIFEST:

EPA ID:	NYP000976662
Country:	USA
Name:	Niagara Mohawk A National Grid Company
Address:	900 SOUTH STATE STREET
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	900 SOUTH STATE STREET
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Niagara Mohawk A National Grid Company
Mailing Contact:	Niagara Mohawk
Mailing Address 1:	300 ERIE BOULEVARD W

NIAGARA MOHAWK A NATIONAL GRID COMPANY (Continued) **S130581177**

Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	8008393975

P80 **FIRE STATION #1** **NY AST** **A100472594**
NNW **900 SOUTH STATE ST** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.243 mi.
1282 ft. **Site 6 of 8 in cluster P**

Relative:
Lower

Actual:
396 ft.

AST:

Name:	FIRE STATION #1
Address:	900 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Region:	STATE
DEC Region:	7
Site Status:	Active
Facility Id:	7-181935
Program Type:	PBS
UTM X:	406500.41583
UTM Y:	4766163.01145
Expiration Date:	06/30/2027
Site Type:	Municipality (Incl. Waste Water Treatment Plants, Utilities, Swimming Pools, etc.)

Affiliation Records:

Site Id:	45039
Affiliation Type:	Mail Contact
Company Name:	CITY OF SYRACUSE FIRE DEPT
Contact Type:	Not reported
Contact Name:	ZACH SMITH
Address1:	FIRE MAINTENANCE
Address2:	312 STATE FAIR BLVD
City:	SYRACUSE
State:	NY
Zip Code:	13204
Country Code:	001
Phone:	(315) 448-4777
EMail:	ZSMITH@SYR.GOV
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2024-07-17

Site Id:	45039
Affiliation Type:	Facility Owner
Company Name:	CITY OF SYRACUSE
Contact Type:	DEPUTYCHIEF - SYRACUSE FIRE DEPT
Contact Name:	ZACH SMITH
Address1:	CITY HALL - 233 EAST WASHINGTON ST
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 448-8200
EMail:	Not reported

FIRE STATION #1 (Continued) **A100472594**

Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2022-04-26
Site Id:	45039
Affiliation Type:	Emergency Contact
Company Name:	CITY OF SYRACUSE FIRE DEPT
Contact Type:	Not reported
Contact Name:	CHIEF OF FIRE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(315) 473-3230
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2024-07-17
Site Id:	45039
Affiliation Type:	Facility Operator
Company Name:	FIRE STATION #1
Contact Type:	Not reported
Contact Name:	JEFF GROSSO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 473-5495
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KCKEMP
Date Last Modified:	2019-03-06

Tank Info:

Tank Number:	102
Tank Id:	280124

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J06 - Dispenser - Tank Mounted Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G12 - Tank Secondary Containment - Double-Walled (AG only)
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated

FIRE STATION #1 (Continued) **A100472594**

	above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/22/2019
Capacity Gallons:	1000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	gasoline

P81 **FIRE STATION #1** **UST FINDER** **1028588839**
NNW **900 SOUTH STATE ST** **N/A**
1/8-1/4 **SYRACUSE, NY 13202**
0.243 mi.
1282 ft. **Site 7 of 8 in cluster P**

Relative: **Lower**

Actual: **396 ft.**

UST FINDER:

Object ID:	318283
Facility ID:	NY45039
Name:	FIRE STATION #1
Address:	900 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY 13202
Address Match Type:	Not reported
Open USTs:	1
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	1951
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-76.1476049999999
Y Coord:	43.0426610000001
Latitude:	43.042661
Longitude:	-76.147605

UST FINDER:

Object ID:	1278080
Facility ID:	NY45039

FIRE STATION #1 (Continued) **1028588839**

Tank ID:	NY75944
Tank Status:	Closed
Installation Date:	1974/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1278081
Facility ID:	NY45039
Tank ID:	NY117945
Tank Status:	Closed
Installation Date:	1974/12/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1278082
Facility ID:	NY45039
Tank ID:	NY70628
Tank Status:	Open
Installation Date:	1995/05/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	2500
Substances:	Not reported
Tank Wall Type:	Not reported

P82 **NIAGARA MOHAWK - A NATIONAL GRID CO** **RCRA NonGen / NLR** **1026498246**
NNW **900 SOUTH STATE ST** **E MANIFEST** **NYP000976662**
1/8-1/4 **SYRACUSE, NY 13202**
0.243 mi.
1282 ft. **Site 8 of 8 in cluster P**

Relative: **Lower**
Actual: **396 ft.**

RCRA Listings:

Date Form Received by Agency:	20201217
Handler Name:	Niagara Mohawk - A National Grid Co
Handler Address:	South State St
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NYP000976662
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R7
Mailing Address:	Not reported

NIAGARA MOHAWK - A NATIONAL GRID CO (Continued) **1026498246**

Mailing City,State,Zip:		Not reported
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20220411
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Historic Generators:

Receive Date:	20200930
Handler Name:	NIAGARA MOHAWK, A NATIONAL GRID COMPANY
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

NIAGARA MOHAWK - A NATIONAL GRID CO (Continued) **1026498246**

Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No
Receive Date:	20201217
Handler Name:	NIAGARA MOHAWK - A NATIONAL GRID CO
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

E MANIFEST:

Manifest Tracking Number:	006546866GBF
Last Updated Date:	20201111
Shipped Date:	20201027
Received Date:	20201103
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYP000976662
Generator Name:	Niagara Mohawk, A National Grid Company
Generator Location Street Number:	900
Generator Location Street 1:	900 SOUTH STATE STREET
Generator Location Street 2:	Not reported
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13202
Generator Mail Street Number:	300
Generator Mail Street 1:	ERIE BOULEVARD WEST
Generator Mail Street 2:	Not reported
Generator Mail City:	SYRACUSE
Generator Mail Zip:	13202
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID000724831
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	49350 N I-94 SERVICE DR
Designated Facility Mail Street 2:	ATTN SYLWIA SCOTT

NIAGARA MOHAWK - A NATIONAL GRID CO (Continued) **1026498246**

Designated Facility Mail City:	BELLEVILLE
Designated Facility Mail Zip:	48111
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	49350 NORTH I94 SERVICE DRIVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	BELLEVILLE
Designated Facility Location Zip:	48111
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Michigan Disposal Waste Treatment Plant
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006546866GBF
Transporter Line Number:	1
Transporter EPA ID:	MAC300098399
Transporter Name:	Nrc East Environmental Services Inc

Manifest Tracking Number:	006546866GBF
Transporter Line Number:	2
Transporter EPA ID:	MAD084814136
Transporter Name:	Eq Northeast Inc

Waste Line:

Manifest Tracking Number:	006546866GBF
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3082
U.S. DOT Description:	Na3082, Hazardous Waste, Liquid, N.O.S., 9, Pgiii, Erg#171
Non-Hazardous Waste Description:	Not reported
Number of Containers:	5
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	1500
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.75
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.75
Waste Quantity, in Kilograms:	680.2725
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	680.2725
Management Method Code:	H120
Management Method Description:	COMB. OF CHEMICAL, BIOLOGICAL, AND/OR PHYSICAL TRT
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported

NIAGARA MOHAWK - A NATIONAL GRID CO (Continued) **1026498246**

Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	680.2725
Quantity Haz Tons:	0.75
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

Q83 **SYRACUSE COMMUNITY HEALTH CENTER** **RCRA-SQG** **1016144340**
West **930 S SALINA ST** **FINDS** **NYR000199190**
1/8-1/4 **SYRACUSE, NY 13202** **ECHO**
0.244 mi. **NY MANIFEST**
1290 ft. **Site 3 of 3 in cluster Q**

Relative: **Lower**
Actual: **394 ft.**

RCRA Listings:

Date Form Received by Agency:		20130228
Handler Name:		Syracuse Community Health Center
Handler Address:		S Salina St
Handler City,State,Zip:		SYRACUSE, NY 13202
EPA ID:		NYR000199190
Contact Name:		HARVEY L BOX
Contact Address:		PO BOX 515
Contact City,State,Zip:		SYRACUSE, NY 13205
Contact Telephone:		315-476-7917 x345
Contact Fax:		315-476-7990
Contact Email:		LBOX@HUEBER-BREVER.COM
Contact Title:		PROJECT MANAGER HUEBER BREVER CONST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		S SALINA ST
Mailing City,State,Zip:		SYRACUSE, NY 13202
Owner Name:	Schc Companies Inc	
Owner Type:		Private
Operator Name:	Dr Ruben Cowart	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---

SYRACUSE COMMUNITY HEALTH CENTER (Continued) **1016144340**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150730
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: SCHC COMPANIES INC	
Legal Status:	Private
Date Became Current:	20050614
Date Ended Current:	Not reported
Owner/Operator Address:	819 S SALINA ST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202
Owner/Operator Telephone:	315-476-7921
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: DR RUBEN COWART	
Legal Status:	Private
Date Became Current:	20050614
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20130228
Handler Name:	SYRACUSE COMMUNITY HEALTH CENTER

SYRACUSE COMMUNITY HEALTH CENTER (Continued) **1016144340**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	621111
NAICS Description:	Offices Of Physicians (Except Mental Health Specialists)

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110055471458

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016144340
Registry ID:	110055471458

DFR URL:

Name:	SYRACUSE COMMUNITY HEALTH CENTER
Address:	930 S SALINA ST
City,State,Zip:	SYRACUSE, NY 13202

NY MANIFEST:

EPA ID:	NYR000199190
Country:	USA
Name:	Syracuse Community Health Center
Address:	930 S SALINA ST
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	930 S SALINA ST

SYRACUSE COMMUNITY HEALTH CENTER (Continued) **1016144340**

Location Address 2: Not reported
Location City,State,Zip: SYRACUSE, NY 13202
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Syracuse Community Health Center
Mailing Contact: Syracuse Community Health Center
Mailing Address 1: 930 S SALINA ST
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13202
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3153742549

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYR000115733
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 03/29/2013
Trans1 Recv Date: 03/29/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/05/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000199190
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: PAD067098822
TSDF ID 2: Not reported
Manifest Tracking Number: 005727802FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Ignitable Waste
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported

SYRACUSE COMMUNITY HEALTH CENTER (Continued) **1016144340**

Waste Code 6:	Not reported
Quantity:	20
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2013
Trans1 Recv Date:	03/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/05/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000199190
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	005727802FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	5
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported

SYRACUSE COMMUNITY HEALTH CENTER (Continued) **1016144340**

Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2013
Trans1 Recv Date:	03/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/05/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000199190
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	005727802FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2013
Trans1 Recv Date:	03/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/05/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000199190

SYRACUSE COMMUNITY HEALTH CENTER (Continued) **1016144340**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	005727803FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Benzene, Methyl- (Or) Toluene
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	36
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2013
Trans1 Recv Date:	03/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/11/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000199190
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	005727804FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

SYRACUSE COMMUNITY HEALTH CENTER (Continued) **1016144340**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1030
Units:	Kilograms
Number of Containers:	3
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

S84 **SYRACUSE CITY OF HOUSING AUTH** **RCRA NonGen / NLR** **1004756036**
SSW **1306 S STATE ST** **FINDS** **NY0000969188**
1/8-1/4 **SYRACUSE, NY 13202** **ECHO**
0.245 mi.
1295 ft. **Site 1 of 2 in cluster S**

Relative: **Lower**
Actual: **395 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Syracuse City Of Housing Auth
Handler Address:	S State St
Handler City,State,Zip:	SYRACUSE, NY 13202
EPA ID:	NY0000969188
Contact Name:	EILEEN GILLIGAN
Contact Address:	BURT ST
Contact City,State,Zip:	SYRACUSE, NY 13202
Contact Telephone:	315-475-6181
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R7
Mailing Address:	BURT ST
Mailing City,State,Zip:	SYRACUSE, NY 13202
Owner Name:	City Of Syracuse Community Dev
Owner Type:	Municipal

SYRACUSE CITY OF HOUSING AUTH (Continued) **1004756036**

Operator Name:	City Of Syracuse Community Dev
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CITY OF SYRACUSE COMMUNITY DEV
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	201 E WASHINGTON ST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202-1432

SYRACUSE CITY OF HOUSING AUTH (Continued) **1004756036**

Owner/Operator Telephone: 315-448-8700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CITY OF SYRACUSE COMMUNITY DEV
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 201 E WASHINGTON ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202-1432
Owner/Operator Telephone: 315-448-8700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CITY OF SYRACUSE COMMUNITY DEV
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 201 E WASHINGTON ST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202-1432
Owner/Operator Telephone: 315-448-8700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SYRACUSE CITY OF HOUSING AUTH
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SYRACUSE CITY OF HOUSING AUTH
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19941207

SYRACUSE CITY OF HOUSING AUTH (Continued) **1004756036**

Handler Name: SYRACUSE CITY OF HOUSING AUTH
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004322894

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004756036
Registry ID: 110004322894

DFR URL:
Name: SYRACUSE CITY OF HOUSING AUTH
Address: 1306 S STATE ST
City,State,Zip: SYRACUSE, NY 13202

S85 **NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STA** **RCRA NonGen / NLR** **1031075973**
SSW **1309 S STATE ST MH1303** **E MANIFEST** **NYP000263590**
1/8-1/4 **SYRACUSE, NY 13202**
0.250 mi.
1319 ft. **Site 2 of 2 in cluster S**

Relative: **Lower**

Actual: **396 ft.**

RCRA Listings:

Date Form Received by Agency:		20250421
Handler Name:		Niagara Mohawk Power Corp Mh1303 At 1309 South State St
Handler Address:		S State St Mh1303
Handler City,State,Zip:		SYRACUSE, NY 13202
EPA ID:		NYP000263590
Contact Name:		ERIN URBANSKI
Contact Address:		CROSSROADS PARK DR.
Contact City,State,Zip:		LIVERPOOL, NY 13088
Contact Telephone:		716-329-2302
Contact Fax:		Not reported
Contact Email:		ERIN.URBANSKI@NATIONALGRID.COM
Contact Title:		DIVISIONAL ENGINEER
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		CROSSROADS PARK DR.
Mailing City,State,Zip:		LIVERPOOL, NY 13088
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST (Continued) **1031075973**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250421
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NIAGARA MOHAWK POWER CORP A NATIONAL GRID CO
Legal Status:	Private
Date Became Current:	20000905
Date Ended Current:	Not reported
Owner/Operator Address:	300 ERIE BLVD WEST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202
Owner/Operator Telephone:	315-474-1511
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	NATHAN.BUTERA@NATIONALGRID.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NIAGARA MOHAWK POWER CORP A NATIONAL GRID CO
Legal Status:	Private
Date Became Current:	20000905
Date Ended Current:	Not reported
Owner/Operator Address:	300 ERIE BLVD WEST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202
Owner/Operator Telephone:	315-474-1511
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	NATHAN.BUTERA@NATIONALGRID.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NIAGARA MOHAWK POWER CORP A NATIONAL GRID CO
Legal Status:	Private
Date Became Current:	20000905
Date Ended Current:	Not reported
Owner/Operator Address:	300 ERIE BLVD WEST
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202
Owner/Operator Telephone:	315-474-1511
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST (Continued) **1031075973**

Owner/Operator Email: NATHAN.BUTERA@NATIONALGRID.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: NIAGARA MOHAWK POWER CORP A NATIONAL GRID CO
Legal Status: Private
Date Became Current: 20000905
Date Ended Current: Not reported
Owner/Operator Address: 300 ERIE BLVD WEST
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-474-1511
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: NATHAN.BUTERA@NATIONALGRID.COM

Historic Generators:
Receive Date: 20250228
Handler Name: NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20250421
Handler Name: NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20240116
Handler Name: NIAGARA MOHAWK POWER CORP MH1303
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122

NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST (Continued) **1031075973**

NAICS Description: Electric Power Distribution

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:

Manifest Tracking Number:	018487643FLE
Last Updated Date:	20240502
Shipped Date:	20240214
Received Date:	20240403
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYP000263590
Generator Name:	Niagara Mohawk Power Corporation
Generator Location Street Number:	1309
Generator Location Street 1:	1309 MH1303 AT 1309 SOUTH STATE STREET
Generator Location Street 2:	Not reported
Generator Location City:	SYRACUSE
Generator Location State:	NY
Generator Location Zip:	13202
Generator Mail Street Number:	300
Generator Mail Street 1:	MH1303 at 1309 South State Street
Generator Mail Street 2:	Not reported
Generator Mail City:	Syracuse
Generator Mail Zip:	13202
Generator Mail State:	NY
Generator Contact Company Name:	Niagara Mohawk Power Corporation
Designated Facility EPA ID:	TXD055141378
Designated Facility Name:	Clean Harbors Deer Park, Llc
Designated Facility Mail Street Number:	2027
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	Independence Parkway South
Designated Facility Mail City:	La Porte
Designated Facility Mail Zip:	77571
Designated Facility Mail State:	TX
Designated Facility Location Street Number:	2027
Designated Facility Location Street 1:	Independence Parkway South
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	La Porte
Designated Facility Location Zip:	77571
Designated Facility Location State:	TX
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

PCB Information:

Manifest Tracking Number:	018487643FLE
Waste Line Number:	1
Article or Container ID:	7643-1
Bulk Identity:	Not reported

NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST (Continued) **1031075973**

Date of Removal:	20240117
Load Type:	Container
Load Type Description:	Container
Waste Type:	TSCA PCB Impacted Manhole Debris
Weight:	180.529732
Manifest Tracking Number:	018487643FLE
Waste Line Number:	2
Article or Container ID:	Not reported
Bulk Identity:	TSCA PCB Impacted Water
Date of Removal:	20240117
Load Type:	BulkWaste
Load Type Description:	Bulk Waste
Waste Type:	Not reported
Weight:	1371.209499
Manifest Tracking Number:	018487643FLE
Waste Line Number:	2
Article or Container ID:	Not reported
Bulk Identity:	TSCA PCB Impacted Water
Date of Removal:	20240117
Load Type:	BulkWaste
Load Type Description:	Bulk Waste
Waste Type:	Not reported
Weight:	1390.713967
Manifest Tracking Number:	018487643FLE
Waste Line Number:	2
Article or Container ID:	Not reported
Bulk Identity:	TSCA PCB Impacted Water
Date of Removal:	20240117
Load Type:	BulkWaste
Load Type Description:	Bulk Waste
Waste Type:	Not reported
Weight:	1398.878629

Transporter:

Manifest Tracking Number:	018487643FLE
Transporter Line Number:	1
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.

Waste Line:

Manifest Tracking Number:	018487643FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3432
U.S. DOT Description:	Un3432, Waste Polychlorinated Biphenyls, Solid, 9, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	181
Quantity Unit of Measure Code:	K
Quantity Unit of Measure Description:	Kilograms
Waste Quantity, in Tons:	0.19955237

NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST (Continued) **1031075973**

Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.19955237
Waste Quantity, in Kilograms:	181
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	181
Management Method Code:	H040
Management Method Description:	INCINERATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	181
Quantity Haz Tons:	0.19955237
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	NY-B, NY-B007, TX-OUTS394H

Manifest Tracking Number:	018487643FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN2315
U.S. DOT Description:	Un2315, Waste Polychlorinated Biphenyls, Liquid, 9, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	3
Container Type Code:	TP
Container Type Description:	Portable tanks
Waste Quantity:	4200
Quantity Unit of Measure Code:	K
Quantity Unit of Measure Description:	Kilograms
Waste Quantity, in Tons:	4.630497
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	4.630497
Waste Quantity, in Kilograms:	4200
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	4200
Management Method Code:	H040
Management Method Description:	INCINERATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported

NIAGARA MOHAWK POWER CORP MH1303 AT 1309 SOUTH STATE ST (Continued) **1031075973**

Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D008
Quantity Haz Kg:	4200
Quantity Haz Tons:	4.630497
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	NY-B002, TX-OUTS113H

T86 **MONDO'S AGWAY** **UST FINDER RELEASE** **1029068240**
SW **1127 SO. SALINA ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.268 mi.
1416 ft. **Site 1 of 6 in cluster T**

Relative: **Lower**

Actual: **390 ft.**

UST FINDER RELEASE:

Object ID:	249464
Facility ID:	NY244120
Lust ID:	NY8403634
Name:	MONDO'S AGWAY
Address:	1127 SO. SALINA ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1985/03/25 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1504
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Yes
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.14947
Y Coord:	43.0361
Latitude:	43.0360999999999
Longitude:	-76.1494699999999

T87 **1127 SOUTH SALINA SYRACUSE LLC** **NY LTANKS** **U003313095**
SW **1127 SOUTH SALINA ST** **NY UST** **N/A**
1/4-1/2 **SYRACUSE, NY 13202** **NY Spills**
0.268 mi.
1416 ft. **Site 2 of 6 in cluster T**

Relative: **Lower**

Actual: **390 ft.**

LTANKS:

Name:	MONDO'S AGWAY
Address:	1127 SO. SALINA ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8403634 / 1991-06-17
Facility ID:	8403634
Site ID:	302125
Spill Date:	1985-03-25
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1991-06-17
SWIS:	3415
Investigator:	GREGG
Referred To:	Not reported
Reported to Dept:	1985-03-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Police Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	1993-11-19
Spiller Name:	Not reported
Spiller Company:	EDWARD MONDO
Spiller Address:	341 SO. COLLINGWOOD AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	244120
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TG 06/14/89: CHECKED WELLS WITH J. SEITZ. FREE PRODUCT IN ALL 3 WELLS. 07/10/89: INTERIM ISR GIVEN TO REGIONAL ATTORNEY. MET WITH MR. MONDO AND HE IS HIRING A CONSULTANT TO DO A PHASE I HYDROGEO STUDY. 04/20/91: SITE VISIT TO BE PERFORMED TO CHECK LEVELS IN WELLS AND TO TALK WITH SPILLER. 06/17/91: ALL FREE PRODUCT REMOVED.
Remarks:	LOST 250 GAL. TANK BEING REMOVED FOUND PRODUCT.

All Materials:

Site ID:	302125
Operable Unit ID:	896071
Operable Unit:	01
Material ID:	482430
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

Quantity:	250.00
Units:	G
Recovered:	190.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

UST:

Name:	1127 SOUTH SALINA SYRACUSE LLC
Address:	1127 SOUTH SALINA ST
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-042161 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	11/15/2029
UTM X:	406397.85388
UTM Y:	4765415.76441
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	44246
Affiliation Type:	Facility Operator
Company Name:	1127 SOUTH SALINA SYRACUSE LLC
Contact Type:	Not reported
Contact Name:	1127 SOUTH SALINA SYRACUSE LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 475-7434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2024-12-23

Site Id:	44246
Affiliation Type:	Emergency Contact
Company Name:	1127 SOUTH SALINA SYRACUSE LLC
Contact Type:	Not reported
Contact Name:	SYED KIRMANI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 501-4364
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2024-12-23

Site Id:	44246
Affiliation Type:	Mail Contact

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

Company Name:	1127 SOUTH SALINA SYRACUSE LLC
Contact Type:	PRESIDENT
Contact Name:	SYED KIRMANI
Address1:	26 MILL PLAIN RD
Address2:	Not reported
City:	DANBURY
State:	CT
Zip Code:	06811
Country Code:	001
Phone:	(845) 765-8507
EMail:	PERMIT@SNKPETRO.COM
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2025-02-03

Site Id:	44246
Affiliation Type:	Facility Owner
Company Name:	1127 SOUTH SALINA SYRACUSE LLC
Contact Type:	PRESIDENT
Contact Name:	SYED KIRMANI
Address1:	26 MILL PLAIN RD
Address2:	Not reported
City:	DANBURY
State:	CT
Zip Code:	06811
Country Code:	001
Phone:	(845) 765-8507
EMail:	PERMIT@SNKPETRO.COM
Fax Number:	Not reported
Modified By:	DJLASALL
Date Last Modified:	2025-02-03

Tank Info:

Tank Number:	001
Tank ID:	126775
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	05/01/1985
Date Tank Closed:	06/14/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DJLASALL
Last Modified:	12/23/2024

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B02 - Tank External Protection - Original Sacrificial Anode
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L08 - Piping Leak Detection - Tank Top Sump

Tank Number:	002
Tank ID:	126776
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	0
Install Date:	05/01/1985
Date Tank Closed:	06/14/2007
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DJLASALL
Last Modified:	12/23/2024

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L08 - Piping Leak Detection - Tank Top Sump
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	003
Tank ID:	126777
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

Install Date: 05/01/1985
Date Tank Closed: 06/14/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DJLASALL
Last Modified: 12/23/2024

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B02 - Tank External Protection - Original Sacrificial Anode
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L08 - Piping Leak Detection - Tank Top Sump

Tank Number: 004
Tank ID: 126778
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 0
Install Date: 05/01/1985
Date Tank Closed: 06/14/2007
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DJLASALL
Last Modified: 12/23/2024

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B02 - Tank External Protection - Original Sacrificial Anode

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I02 - Overfill - High Level Alarm
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
L08 - Piping Leak Detection - Tank Top Sump

Tank Number: 005
Tank ID: 126779
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 500
Install Date: 05/01/1985
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DJLASALL
Last Modified: 12/23/2024

Equipment Records:

B07 - Tank External Protection - Retrofitted Sacrificial Anode
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
A00 - Tank Internal Protection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 006
Tank ID: 221423
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 6000
Install Date: 06/21/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: 0
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DJLASALL
Last Modified: 12/23/2024

Equipment Records:

B09 - Tank External Protection - Urethane
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Number: 007
Tank ID: 221424
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 6000
Install Date: 06/21/2007
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: 0
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: DJLASALL
Last Modified: 12/23/2024

Equipment Records:

B09 - Tank External Protection - Urethane
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

Tank Number:	008
Tank ID:	221425
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	06/21/2007
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	0
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	DJLASALL
Last Modified:	12/23/2024

Equipment Records:

B09 - Tank External Protection - Urethane
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
D11 - Pipe Type - Flexible Piping
E04 - Piping Secondary Containment - Double walled UG
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

SPILLS:

Name:	MONDOS SERVICE CENTER
Address:	1127 SOUTH SALINA STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0412947 / 2005-03-14
Facility ID:	0412947
Facility Type:	ER
DER Facility ID:	273915
Site ID:	338576
DEC Region:	7
Spill Cause:	Human Error
Spill Class:	C5
SWIS:	3400
Spill Date:	2005-03-11
Investigator:	MENASH
Referred To:	Not reported
Reported to Dept:	2005-03-11
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-11
Spill Record Last Update:	2005-03-14
Spiller Name:	MARK
Spiller Company:	MONDOS SERVICE CENTER
Spiller Address:	1127 SOUTH SALINA STREET
Spiller Company:	001
Contact Name:	MARK
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	A PINT SPILLED WHEN HE WAS CLEANING AND HE ACCIDENTALLY KICKE DTHE BUCKET ALL CLEANED UP

All Materials:

Site ID:	338576
Operable Unit ID:	1100512
Operable Unit:	01
Material ID:	580805
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	GAS STATION
Address:	1127 SOUTH SALINA ST
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	1808400 / 2018-11-08
Facility ID:	1808400
Facility Type:	ER
DER Facility ID:	43615
Site ID:	579205
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3415
Spill Date:	2018-11-07
Investigator:	CFNORRIS
Referred To:	Not reported
Reported to Dept:	2018-11-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

1127 SOUTH SALINA SYRACUSE LLC (Continued) **U003313095**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-11-07
Spill Record Last Update:	2019-05-28
Spiller Name:	Not reported
Spiller Company:	MONDO'S
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	PATRICK VROOMAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	The stp sump for tank 7 failed visual inspection for a torn boot on sump product line entry boo. Dispenser # 3 and 4 failed visual inspection due to there is no secondary boot on product line.
Remarks:	stp sump failure

All Materials:

Site ID:	579205
Operable Unit ID:	1326930
Operable Unit:	01
Material ID:	2335764
Material Code:	9999
Material Name:	other - stp sump failure
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Site ID:	579205
Operable Unit ID:	1326930
Operable Unit:	01
Material ID:	2345963
Material Code:	2712
Material Name:	gasoline/ethanol
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

U88 **FORMER COYNE TEXTILE** **NY ENG CONTROLS S120706175**
WSW **140 CORTLAND AVENUE** **NY INST CONTROL N/A**
1/4-1/2 **SYRACUSE, NY 13202** **NY BROWNFIELDS**
0.271 mi.
1431 ft. **Site 1 of 2 in cluster U**

Relative: **Lower**
Actual: **390 ft.**

ENG CONTROLS:

Name:	FORMER COYNE TEXTILE
Address:	140 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY 13202
Site Code:	507968

FORMER COYNE TEXTILE (Continued) **S120706175**

HW Code: C734144
Control Code: 15
Control Type: ENG
Date Record Added: 11/05/2021
Date Rec Updated: 12/28/2021
Updated By: MJBELVEG
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards

FORMER COYNE TEXTILE (Continued) **S120706175**

	Onondaga Lake."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	po box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Onondaga County Public Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Dino Peios
Owner Company:	JMA Tech properties, LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	Liverpool, NY 13088
Owner Country:	United States of America

FORMER COYNE TEXTILE (Continued) **S120706175**

Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America

FORMER COYNE TEXTILE (Continued) **S120706175**

Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	CELLH LLC
Owner Address:	7645 Henry Clay Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
HW Code:	C734144
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	beryllium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	thallium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C734144-06-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 08:30:00
Record Updated:	2020-02-10 08:30:00
Updated By:	MJBELVEG
Crossref ID:	2005960
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2020-10-28 13:03:00
Record Updated:	2020-10-28 13:03:00
Updated By:	MJBELVEG
Crossref ID:	C734144-05-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-09-09 10:05:00
Record Updated:	2021-09-09 10:05:00
Updated By:	MJBELVEG
Crossref ID:	2021-00048750
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00
Updated By:	MJBELVEG
Crossref ID:	2021-00048743
Cross Ref Type Code:	25

FORMER COYNE TEXTILE (Continued) **S120706175**

Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00
Updated By:	MJBELVEG
Crossref ID:	1412187
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-05-20 10:56:00
Record Updated:	2015-05-20 10:56:00
Updated By:	SMFITZGE
Crossref ID:	1408779
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-05-20 10:58:00
Record Updated:	2015-05-20 10:58:00
Updated By:	SMFITZGE
Crossref ID:	C734144A
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2019-01-02 13:56:00
Record Updated:	2019-01-02 13:56:00
Updated By:	MJBELVEG

Name:	FORMER COYNE TEXTILE
Address:	140 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY 13202
Site Code:	507968
HW Code:	C734144
Control Code:	36
Control Type:	ENG
Date Record Added:	11/05/2021
Date Rec Updated:	12/28/2021
Updated By:	MJBELVEG
Site Description:	"Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the

FORMER COYNE TEXTILE (Continued) **S120706175**

site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	po box 678

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Onondaga County Public Library
Owner Address: 447 South Salina Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Dino Peios
Owner Company: JMA Tech properties, LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: Liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	XRN LLC
Owner Address:	7645 Henry Clay Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	JMA EDGE SERVICES, LLC
Owner Address:	7645 Henry Clay Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	PREVAIL NY LLC
Owner Address:	7645 Henry Clay Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	CELLH LLC
Owner Address:	7645 Henry Clay Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
HW Code:	C734144
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	iron

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	beryllium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	thallium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Code:	Not reported
Crossref ID:	C734144-06-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 08:30:00
Record Updated:	2020-02-10 08:30:00
Updated By:	MJBELVEG
Crossref ID:	2005960
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2020-10-28 13:03:00
Record Updated:	2020-10-28 13:03:00
Updated By:	MJBELVEG
Crossref ID:	C734144-05-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-09-09 10:05:00
Record Updated:	2021-09-09 10:05:00
Updated By:	MJBELVEG
Crossref ID:	2021-00048750
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00
Updated By:	MJBELVEG
Crossref ID:	2021-00048743
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00
Updated By:	MJBELVEG
Crossref ID:	1412187
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-05-20 10:56:00
Record Updated:	2015-05-20 10:56:00
Updated By:	SMFITZGE
Crossref ID:	1408779
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-05-20 10:58:00
Record Updated:	2015-05-20 10:58:00
Updated By:	SMFITZGE
Crossref ID:	C734144A
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2019-01-02 13:56:00
Record Updated:	2019-01-02 13:56:00
Updated By:	MJBELVEG

Name:	FORMER COYNE TEXTILE
Address:	140 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY 13202
Site Code:	507968
HW Code:	C734144
Control Code:	13
Control Type:	ENG

FORMER COYNE TEXTILE (Continued) **S120706175**

Date Record Added: 11/05/2021
Date Rec Updated: 12/28/2021
Updated By: MJBELVEG
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and

FORMER COYNE TEXTILE (Continued) **S120706175**

	barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	po box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Onondaga County Public Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Dino Peios
Owner Company:	JMA Tech properties, LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	Liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Company:	CELLH LLC
Owner Address:	7645 Henry Clay Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
HW Code:	C734144
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	beryllium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

FORMER COYNE TEXTILE (Continued) **S120706175**

HW Code:	C734144
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	thallium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C734144-06-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 08:30:00
Record Updated:	2020-02-10 08:30:00
Updated By:	MJBELVEG
Crossref ID:	2005960
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2020-10-28 13:03:00
Record Updated:	2020-10-28 13:03:00
Updated By:	MJBELVEG
Crossref ID:	C734144-05-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-09-09 10:05:00
Record Updated:	2021-09-09 10:05:00
Updated By:	MJBELVEG
Crossref ID:	2021-00048750
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00
Updated By:	MJBELVEG
Crossref ID:	2021-00048743
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00

FORMER COYNE TEXTILE (Continued) **S120706175**

Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

INST CONTROL:
Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202
Site Code: 507968
Control Name: Monitoring Plan
HW Code: C734144
Control Code: 31
Control Type: INST
Dt record added: 11/05/2021
Dt rec updated: 12/28/2021
Updated By: MJBELVEG
Site Code: 507968
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the

FORMER COYNE TEXTILE (Continued) **S120706175**

site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	po box 678

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Onondaga County Public Library
Owner Address: 447 South Salina Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Dino Peios
Owner Company: JMA Tech properties, LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: Liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: CELLH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
HW Code: C734144
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: iron

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: beryllium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: thallium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Code: Not reported
Crossref ID: C734144-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 08:30:00
Record Updated: 2020-02-10 08:30:00
Updated By: MJBELVEG
Crossref ID: 2005960
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-28 13:03:00
Record Updated: 2020-10-28 13:03:00
Updated By: MJBELVEG
Crossref ID: C734144-05-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-09 10:05:00
Record Updated: 2021-09-09 10:05:00
Updated By: MJBELVEG
Crossref ID: 2021-00048750
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 2021-00048743
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202
Site Code: 507968
Control Name: Site Management Plan
HW Code: C734144
Control Code: 32

FORMER COYNE TEXTILE (Continued) **S120706175**

Control Type: INST
Dt record added: 11/05/2021
Dt rec updated: 12/28/2021
Updated By: MJBELVEG
Site Code: 507968
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."

FORMER COYNE TEXTILE (Continued) **S120706175**

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	po box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Onondaga County Public Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Dino Peios
Owner Company:	JMA Tech properties, LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	Liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6

FORMER COYNE TEXTILE (Continued) **S120706175**

Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6

FORMER COYNE TEXTILE (Continued) **S120706175**

Sub Type: P03
Owner Name: Dino peios
Owner Company: CELLH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
HW Code: C734144
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: beryllium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: chromium

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: thallium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C734144-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 08:30:00
Record Updated: 2020-02-10 08:30:00
Updated By: MJBELVEG
Crossref ID: 2005960
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-28 13:03:00
Record Updated: 2020-10-28 13:03:00
Updated By: MJBELVEG
Crossref ID: C734144-05-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-09 10:05:00
Record Updated: 2021-09-09 10:05:00
Updated By: MJBELVEG
Crossref ID: 2021-00048750
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 2021-00048743
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier

FORMER COYNE TEXTILE (Continued) **S120706175**

Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202
Site Code: 507968
Control Name: IC/EC Plan
HW Code: C734144
Control Code: 34
Control Type: INST
Dt record added: 11/05/2021
Dt rec updated: 12/28/2021
Updated By: MJBELVEG
Site Code: 507968
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services

FORMER COYNE TEXTILE (Continued) **S120706175**

began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "

Health Problem: "Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."

Dump: False
Structure: False
Lagoon: False
Landfill: True
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2017-05-18 08:36:00
Record Upd: 2021-05-25 15:20:00
Updated By: MJBELVEG
Own Op: 1
Sub Type: E
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Address: po box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Onondaga County Public Library
Owner Address: 447 South Salina Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Dino Peios
Owner Company: JMA Tech properties, LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: Liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: CELLH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
HW Code: C734144
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	beryllium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	thallium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	xylene (mixed)

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C734144-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 08:30:00
Record Updated: 2020-02-10 08:30:00
Updated By: MJBELVEG
Crossref ID: 2005960
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-28 13:03:00
Record Updated: 2020-10-28 13:03:00
Updated By: MJBELVEG
Crossref ID: C734144-05-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-09 10:05:00
Record Updated: 2021-09-09 10:05:00
Updated By: MJBELVEG
Crossref ID: 2021-00048750
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 2021-00048743
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202
Site Code: 507968
Control Name: Ground Water Use Restriction
HW Code: C734144

FORMER COYNE TEXTILE (Continued) **S120706175**

Control Code: 08
Control Type: INST
Dt record added: 11/05/2021
Dt rec updated: 12/28/2021
Updated By: MJBELVEG
Site Code: 507968
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards

FORMER COYNE TEXTILE (Continued) **S120706175**

	Onondaga Lake."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	po box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Onondaga County Public Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Dino Peios
Owner Company:	JMA Tech properties, LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	Liverpool, NY 13088
Owner Country:	United States of America

FORMER COYNE TEXTILE (Continued) **S120706175**

Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America

FORMER COYNE TEXTILE (Continued) **S120706175**

Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: CELLH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
HW Code: C734144
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: beryllium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: thallium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C734144-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 08:30:00
Record Updated: 2020-02-10 08:30:00
Updated By: MJBELVEG
Crossref ID: 2005960
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-28 13:03:00
Record Updated: 2020-10-28 13:03:00
Updated By: MJBELVEG
Crossref ID: C734144-05-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-09 10:05:00
Record Updated: 2021-09-09 10:05:00
Updated By: MJBELVEG
Crossref ID: 2021-00048750
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 2021-00048743
Cross Ref Type Code: 25

FORMER COYNE TEXTILE (Continued) **S120706175**

Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202
Site Code: 507968
Control Name: Landuse Restriction
HW Code: C734144
Control Code: 25
Control Type: INST
Dt record added: 11/05/2021
Dt rec updated: 12/28/2021
Updated By: MJBELVEG
Site Code: 507968
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a

FORMER COYNE TEXTILE (Continued) **S120706175**

machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "

Health Problem: "Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."

Dump: False
Structure: False
Lagoon: False
Landfill: True
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2017-05-18 08:36:00
Record Upd: 2021-05-25 15:20:00
Updated By: MJBELVEG
Own Op: 1
Sub Type: E
Owner Name: Dino peios

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Company: Ranalli/Taylor St., LLC
Owner Address: po box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Onondaga County Public Library
Owner Address: 447 South Salina Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Dino Peios
Owner Company: JMA Tech properties, LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: Liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: CELLH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
HW Code: C734144
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER COYNE TEXTILE (Continued) **S120706175**

HW Code:	C734144
Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	beryllium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	thallium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C734144-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 08:30:00
Record Updated: 2020-02-10 08:30:00
Updated By: MJBELVEG
Crossref ID: 2005960
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-28 13:03:00
Record Updated: 2020-10-28 13:03:00
Updated By: MJBELVEG
Crossref ID: C734144-05-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-09 10:05:00
Record Updated: 2021-09-09 10:05:00
Updated By: MJBELVEG
Crossref ID: 2021-00048750
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 2021-00048743
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202
Site Code: 507968
Control Name: Environmental Easement

FORMER COYNE TEXTILE (Continued) **S120706175**

HW Code: C734144
Control Code: J
Control Type: INST
Dt record added: 11/05/2021
Dt rec updated: 12/28/2021
Updated By: MJBELVEG
Site Code: 507968
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600

FORMER COYNE TEXTILE (Continued) **S120706175**

feet west of the site, which flows in a northerly direction towards Onondaga Lake."
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem: "Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump: False
Structure: False
Lagoon: False
Landfill: True
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2017-05-18 08:36:00
Record Upd: 2021-05-25 15:20:00
Updated By: MJBELVEG
Own Op: 1
Sub Type: E
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: po box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Onondaga County Public Library
Owner Address: 447 South Salina Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Dino Peios
Owner Company: JMA Tech properties, LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: Liverpool, NY 13088

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: CELLH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
HW Code: C734144
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: beryllium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER COYNE TEXTILE (Continued) **S120706175**

HW Code: C734144
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: thallium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C734144-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 08:30:00
Record Updated: 2020-02-10 08:30:00
Updated By: MJBELVEG
Crossref ID: 2005960
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-28 13:03:00
Record Updated: 2020-10-28 13:03:00
Updated By: MJBELVEG
Crossref ID: C734144-05-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-09 10:05:00
Record Updated: 2021-09-09 10:05:00
Updated By: MJBELVEG
Crossref ID: 2021-00048750
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 2021-00048743

FORMER COYNE TEXTILE (Continued) **S120706175**

Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202
Site Code: 507968
Control Name: O&M Plan
HW Code: C734144
Control Code: 33
Control Type: INST
Dt record added: 11/05/2021
Dt rec updated: 12/28/2021
Updated By: MJBELVEG
Site Code: 507968
Site Description: "Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than

FORMER COYNE TEXTILE (Continued) **S120706175**

100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."

Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: po box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: Ranalli/Taylor St., LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Onondaga County Public Library
Owner Address: 447 South Salina Street
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Dino Peios
Owner Company: JMA Tech properties, LLC
Owner Address: PO Box 678
Owner Addr2: Not reported
Owner City,St,Zip: Liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: CELLH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
HW Code: C734144
Waste Type: 1,1 dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Code: Not reported
HW Code: C734144
Waste Type: iron
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: trans-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: beryllium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: magnesium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: bis(2-ethylhexyl)phthalate
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: benzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: copper
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: chromium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: isopropylbenzene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: lead
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: barium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: manganese
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: sodium
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C734144
Waste Type: thallium
Waste Quantity: UNKNOWN
Waste Code: Not reported

FORMER COYNE TEXTILE (Continued) **S120706175**

HW Code: C734144
Waste Type: xylene (mixed)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C734144-06-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 08:30:00
Record Updated: 2020-02-10 08:30:00
Updated By: MJBELVEG
Crossref ID: 2005960
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-10-28 13:03:00
Record Updated: 2020-10-28 13:03:00
Updated By: MJBELVEG
Crossref ID: C734144-05-17
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2021-09-09 10:05:00
Record Updated: 2021-09-09 10:05:00
Updated By: MJBELVEG
Crossref ID: 2021-00048750
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 2021-00048743
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2021-11-04 07:19:00
Record Updated: 2021-11-04 07:19:00
Updated By: MJBELVEG
Crossref ID: 1412187
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:56:00
Record Updated: 2015-05-20 10:56:00
Updated By: SMFITZGE
Crossref ID: 1408779
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2015-05-20 10:58:00
Record Updated: 2015-05-20 10:58:00
Updated By: SMFITZGE
Crossref ID: C734144A
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2019-01-02 13:56:00
Record Updated: 2019-01-02 13:56:00
Updated By: MJBELVEG

BROWNFIELDS:
Name: FORMER COYNE TEXTILE
Address: 140 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY 13202

FORMER COYNE TEXTILE (Continued) **S120706175**

Program:	BCP
Site Code:	507968
Acres:	3.255
HW Code:	C734144
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	05/15/2015
Record Updated Date:	01/08/2025
Update By:	GWPRISCO
Site Description:	"Location: The site is located at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous site areas. South Clinton Street and the 5G manufacturing facility and offices are known as 140 Cortland Avenue and consist of two parcels of land totaling approximately 2.4 acres. The other site area is known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street, and constitute two parcels totaling approximately 0.86 acres. The site limits are generally bounded by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and vacant commercial/industrial buildings to the west. The site is currently active and zoned for commercial use. Site Features: 140 Cortland Ave. and the South Clinton Street area consists of one building used for the manufacturing of 5G products. These parcels also consist of sidewalks, driveways, parking areas, and limited vegetation. The other area consists of a small park and a parking lot. Current Zoning and Land Use: The site is currently active as a 5G manufacturing facility and is zoned for commercial use. The general area surrounding the site is highly developed and consists of commercial and industrial facilities. Several rows of multifamily houses are located northwest of the site. Past Use of the Site: For more than 100 years, the site was used for industrial purposes, including a machine shop and rug manufacturing before Coyne Textile Services began operation in 1938. As an industrial dry-cleaning facility, the site utilized tetrachloroethene (PCE) and Stoddard solvent (a non-chlorinated solvent) until 2000. Several property owners had structures on what is now the employee parking lot, dating back to 1892 when the location was a brick and mortar building that housed a stone cutting facility. Syracuse Transit Corporation had a bus storage and repair building on the parcel beginning in 1951. From 1989 until acquisition by the current owner, the parcel was used for employee parking and a small greenspace. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. LLC purchased the property in 2016 and entered a Brownfield Cleanup Agreement (BCA) in September 2017. Site Geology and Hydrogeology: The site has an approximate elevation of 390 feet above mean sea level and is relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient, which slopes downward to Onondaga Creek. Site soils are tight and consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The exact depth of the bedrock is unknown at the site, but it is known to be at a depth greater than 80 feet bgs. The estimated depth to groundwater is less than 15 feet below ground surface. The groundwater in the area appears to be brackish saline. Groundwater at the site is assumed to flow to the northwest toward Onondaga Creek. However, localized flow directions in the area of the site may vary

FORMER COYNE TEXTILE (Continued) **S120706175**

	as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the site, which flows in a northerly direction towards Onondaga Lake."
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene (PCE) and barium in soil, 1,1-dichloroethene, isopropylbenzene (Cumene), tetrachloroethene, trichloroethene, xylene (Total), cis-1,2-dichloroethene, trans-1,2-dichloroethene, benzene, vinyl chloride, bis(2-Ethylhexyl)phthalate, barium, and magnesium in groundwater and tetrachloroethene and trichloroethene in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial action are complete and measures are in place to prevent people from coming into contact with remaining contamination."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	True
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2017-05-18 08:36:00
Record Upd:	2021-05-25 15:20:00
Updated By:	MJBELVEG
Own Op:	1
Sub Type:	E
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	po box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	Ranalli/Taylor St., LLC
Owner Address:	PO Box 678
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Onondaga County Public Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Dino Peios
Owner Company:	JMA Tech properties, LLC
Owner Address:	PO Box 678

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Addr2: Not reported
Owner City,St,Zip: Liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties Holdings LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: Document Repository
Sub Type: B99
Owner Name: Web Application
Owner Company: DECInfo Locator

Owner Address:
Owner Addr2: Not reported
Owner City,St,Zip: NY
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA Tech Properties, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA TECH LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: XRN LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: JMA EDGE SERVICES, LLC
Owner Address: 7645 Henry Clay Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: liverpool, NY 13088
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Dino peios
Owner Company: PREVAIL NY LLC
Owner Address: 7645 Henry Clay Blvd.

FORMER COYNE TEXTILE (Continued) **S120706175**

Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino peios
Owner Company:	CELLH LLC
Owner Address:	7645 Henry Clay Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	liverpool, NY 13088
Owner Country:	United States of America
HW Code:	C734144
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	iron
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	beryllium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	magnesium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	bis(2-ethylhexyl)phthalate
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	copper

FORMER COYNE TEXTILE (Continued) **S120706175**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	isopropylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	manganese
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	thallium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C734144-06-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 08:30:00
Record Updated:	2020-02-10 08:30:00
Updated By:	MJBELVEG
Crossref ID:	2005960
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2020-10-28 13:03:00
Record Updated:	2020-10-28 13:03:00
Updated By:	MJBELVEG
Crossref ID:	C734144-05-17
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2021-09-09 10:05:00
Record Updated:	2021-09-09 10:05:00
Updated By:	MJBELVEG
Crossref ID:	2021-00048750
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00

FORMER COYNE TEXTILE (Continued) **S120706175**

Updated By:	MJBELVEG
Crossref ID:	2021-00048743
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2021-11-04 07:19:00
Record Updated:	2021-11-04 07:19:00
Updated By:	MJBELVEG
Crossref ID:	1412187
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-05-20 10:56:00
Record Updated:	2015-05-20 10:56:00
Updated By:	SMFITZGE
Crossref ID:	1408779
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2015-05-20 10:58:00
Record Updated:	2015-05-20 10:58:00
Updated By:	SMFITZGE
Crossref ID:	C734144A
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2019-01-02 13:56:00
Record Updated:	2019-01-02 13:56:00
Updated By:	MJBELVEG

U89 **RENALLI TAYLOR ST LLC** **NY LTANKS** **1000311573**
WSW **140 CORTLAND AVE** **NY CBS** **NYD013250618**
1/4-1/2 **SYRACUSE, NY 13202** **NY CBS AST**
0.271 mi. **NY BROWNFIELDS**
1431 ft. **Site 2 of 2 in cluster U** **NY Spills**
RCRA NonGen / NLR
Relative: **ICIS**
Lower **US AIRS**
FINDS
Actual: **ECHO**
390 ft. **PFAS ECHO**
NY DRYCLEANERS
NY MANIFEST
RI MANIFEST

LTANKS:

Name:	COYNE TEXTILE
Address:	140 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9604373 / 1996-07-02
Facility ID:	9604373
Site ID:	156885
Spill Date:	1996-07-01
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1996-07-01
CID:	282

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-01
Spill Record Last Update:	1996-07-03
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	DJ SMITH
Spiller Phone:	(315) 475-1626
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	132732
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM CLOSE SPILL REFER TO DIV. OF WATER.
Remarks:	waste water sludge is the spill it went on to the road and went into a storm drain.

All Materials:

Site ID:	156885
Operable Unit ID:	1032027
Operable Unit:	01
Material ID:	350664
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

CBS:

Name:	COYNE TEXTILE SERVICES
Address:	140 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY 13202
CBS Number:	7-000217
Program Type:	CBS
Facility Status:	Active
Expiration Date:	08/19/2017
Dec Region:	7
UTMX:	406264.72814
UTMY:	4765538.10119

CBS AST:

CBS Number:	7-000217
ICS Number:	7-178107
PBS Number:	7-072842

RENALLI TAYLOR ST LLC (Continued) **1000311573**

MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	I
Telephone:	(315) 475-1626
Facility Town:	SYRACUSE (C)
Region:	STATE
Expiration Date:	08/19/2001
Total Capacity of All Active Tanks(gal):	883
Operator:	JIM BARNES
Emergency Contact:	D.J. SMITH
Emergency Phone:	(315) 475-1626
Owner Name:	COYNE TEXTILE SERVICES
Owner Address:	140 CORTLAND AVENUE
Owner City,St,Zip:	SYRACUSE, NY 13202
Owner Telephone:	(315) 475-1626
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	COYNE TEXTILE SERVICES
Mail Contact Addr:	140 CORTLAND AVENUE
Mail Contact Addr2:	PO BOX 4854
Mail Contact Contact:	D.J. SMITH
Mail Contact City,St,Zip:	SYRACUSE, NY 13202
Mail Phone:	(315) 475-1626

Tank Id:	006
CAS Number:	7705080
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	11/95
Tank Closed:	Not reported
Capacity (Gal):	437
Chemical:	Ferric chloride
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	01/11/1999
Certified Date:	07/09/1999
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	43|02| / 76|09|
Is Updated:	False

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Renew Date:	09/27/93
Is It There:	False
Delinquent:	False
Date Expired:	08/19/93
Owner Mark:	1
Certificate Needs to be Printed:	43|02| / 76|09|
Fiscal Amt for Registration Fee Correct:	43|02| / 76|09|
Renewal Has Been Printed for Facility:	43|02| / 76|09|
Pre-Printed Renewal App Last Printed:	43|02| / 76|09|

Tank Id:	002
CAS Number:	1330207
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	11/91
Tank Closed:	00/00
Capacity (Gal):	5000
Chemical:	Xylene (mixed)
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	12/22/1993
Certified Date:	07/09/1999
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	Epoxy Liner
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Galvanized Steel
Pipe Internal:	None
Pipe External:	Wrapped (Piping
Pipe Flag:	Wrapped (Piping
Leak Detection:	Concrete Pad w/channels
Overfill Protection:	Catch Basin
Haz Percent:	10
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	43|02| / 76|09|
Is Updated:	False
Renew Date:	09/27/93
Is It There:	False
Delinquent:	False
Date Expired:	08/19/93
Owner Mark:	1
Certificate Needs to be Printed:	43|02| / 76|09|
Fiscal Amt for Registration Fee Correct:	43|02| / 76|09|
Renewal Has Been Printed for Facility:	43|02| / 76|09|
Pre-Printed Renewal App Last Printed:	43|02| / 76|09|

Tank Id:	003
CAS Number:	1330207
Federal ID:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Tank Status:	In Service
Install Date:	11/91
Tank Closed:	00/00
Capacity (Gal):	5000
Chemical:	Xylene (mixed)
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	12/22/1993
Certified Date:	07/09/1999
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	Epoxy Liner
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Galvanized Steel
Pipe Internal:	None
Pipe External:	Wrapped (Piping
Pipe Flag:	Wrapped (Piping
Leak Detection:	Concrete Pad w/channels
Overfill Protection:	Catch Basin
Haz Percent:	10
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	43|02| / 76|09|
Is Updated:	False
Renew Date:	09/27/93
Is It There:	False
Delinquent:	False
Date Expired:	08/19/93
Owner Mark:	1
Certificate Needs to be Printed:	43|02| / 76|09|
Fiscal Amt for Registration Fee Correct:	43|02| / 76|09|
Renewal Has Been Printed for Facility:	43|02| / 76|09|
Pre-Printed Renewal App Last Printed:	43|02| / 76|09|

Tank Id:	004
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	07/93
Tank Closed:	01/99
Capacity (Gal):	220
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	12/22/1993
Certified Date:	07/09/1999
Substance:	Single Hazardous Substance on DEC List

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	Catch Basin
Haz Percent:	98
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	43|02| / 76|09|
Is Updated:	False
Renew Date:	09/27/93
Is It There:	False
Delinquent:	False
Date Expired:	08/19/93
Owner Mark:	1
Certificate Needs to be Printed:	43|02| / 76|09|
Fiscal Amt for Registration Fee Correct:	43|02| / 76|09|
Renewal Has Been Printed for Facility:	43|02| / 76|09|
Pre-Printed Renewal App Last Printed:	43|02| / 76|09|

Tank Id:	001
CAS Number:	127184
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	07/91
Tank Closed:	00/00
Capacity (Gal):	275
Chemical:	Tetrachloroethylene
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	00
Tank Error Status:	No Missing Data
Date Entered:	08/13/1991
Certified Date:	07/09/1999
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	01
Pipe Flag:	01
Leak Detection:	00
Overfill Protection:	04
Haz Percent:	99
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	43|02| / 76|09|

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Is Updated:	False
Renew Date:	09/27/93
Is It There:	False
Delinquent:	False
Date Expired:	08/19/93
Owner Mark:	1
Certificate Needs to be Printed:	43|02| / 76|09|
Fiscal Amt for Registration Fee Correct:	43|02| / 76|09|
Renewal Has Been Printed for Facility:	43|02| / 76|09|
Pre-Printed Renewal App Last Printed:	43|02| / 76|09|

Tank Id:	005
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/92
Tank Closed:	Not reported
Capacity (Gal):	446
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	2
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	12/22/1993
Certified Date:	07/09/1999
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	98
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	43|02| / 76|09|
Is Updated:	False
Renew Date:	09/27/93
Is It There:	False
Delinquent:	False
Date Expired:	08/19/93
Owner Mark:	1
Certificate Needs to be Printed:	43|02| / 76|09|
Fiscal Amt for Registration Fee Correct:	43|02| / 76|09|
Renewal Has Been Printed for Facility:	43|02| / 76|09|
Pre-Printed Renewal App Last Printed:	43|02| / 76|09|

BROWNFIELDS:

Name:	FORMER COYNE TEXTILE - OFF-SITE
Address:	140 CORTLAND AVENUE

RENALLI TAYLOR ST LLC (Continued) **1000311573**

City,State,Zip:	SYRACUSE, NY 13202
Program:	BCP
Site Code:	580830
Acres:	Not reported
HW Code:	C734144A
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	12/27/2018
Record Updated Date:	02/27/2024
Update By:	GWPRISCO
Site Description:	"Location: The on-site portion is located in an urban area at 140 Cortland Avenue in the City of Syracuse and consists of two non-contiguous Site areas. The former main laundry facility and offices are known as 140 Cortland Avenue (Tax Map No. 094.-05-06.0) and consist of one parcel of land totaling approximately 1.75 acres. The park and employee parking area are known as 1002-1022 South Salina Street/Cortland Avenue and 1024-1040 South Salina Street/Tallman Street and consists of two parcels totaling approximately 1.70 acres. The on-site limits are generally bound by commercial buildings to the north, South Salina Street to the east, Tallman Street to the south and South Clinton Street to the west. The off-site portion that currently needs investigation is approximately 8.5 acres located mainly to the west of the on-site portion. Site Features: 140 Cortland Ave. consists of the currently vacant former laundering facility and offices, sidewalks and limited vegetation. The building is a concrete block building with a slab-on-grade foundation. The other area consists of a small park and a fenced in asphalt parking lot. The off-site area is relatively flat and there are several buildings with both industrial and commercial use space. The area also consists of multiple parking lots and some green space. Current Zoning and Land Use: The on-site portion of the site is currently inactive and is zoned for commercial use. The off-site area is zoned for commercial and industrial use. Several rows of multifamily houses are located west of the area. Past Use of the Site: The 140 Cortland Avenue property was owned by various entities of Coyne Textile Services since the mid-1930s and was utilized as an industrial laundry prior to the company filing for bankruptcy and ceasing operations in late 2015. Dry cleaning using PCE and Stoddard solvent (a petroleum mixture made from distilled alkanes, cycloalkanes (naphthenes) and aromatic compounds) was conducted at the property until 2000. These dry cleaning products were stored in aboveground storage tanks (ASTs). Three underground storage tanks (USTs) were historically closed in place and were identified as being located beneath the dry cleaning room floor and the boiler room at 140 Cortland Avenue. A gasoline filling station was present in the southern portion of the Site in the 1980s. Prior to the Site being developed by Coyne Textile Services in the 1930s, the Site and surrounding area consisted primarily of single family residences. The former employee parking lot and park located east of the former laundering facility was owned by Coyne Textile Services from 1989-2015. Since 1989 this area was utilized as a parking lot and park. Historically, a building was utilized by the Syracuse Transit Corporation Bus Lines on the southern portion of the parking lot for bus storage and repairs from at least the 1940s to 1980s. The Syracuse Street Car barn also occupied this area in the early 1900s. The northern portion of the former employee parking lot and park was occupied by small stores in the early 1900s and a gasoline filling

RENALLI TAYLOR ST LLC (Continued) **1000311573**

station was present on this portion of the parcel from at least the 1950s to 1970s. Coyne Textile Services filed for bankruptcy and ceased operations in late 2015. Ranalli/Taylor St. purchased the property in 2016 and entered a BCA in September 2017. The past use of most of the off-site area is currently unknown. But some of the area was used by Coyne Textile Services to park and maintain their truck fleet. Another portion of the area was used to manufacture garage door parts, faucets, and inked ribbon spools, clips and strips. Site Geology and Hydrogeology: Both the on-site and off-site areas sites have an approximate elevation of 390 feet above mean sea level and are relatively flat. The surrounding areas to the east and west have a relatively steep topographic gradient which slopes downward to Onondaga Creek. Soils consist of Urban Land with the bedrock anticipated to be of Paleozoic era, stratified sequence. The bedrock geology underlying the Site is the Syracuse Formation, which consists of dolostone, shale, gypsum, and salts. The estimated depth to groundwater is less than 20 feet below ground surface. Groundwater at the sites is assumed to flow to the west toward Onondaga Creek. However, localized flow directions in the area of the sites may vary as a result of underground utilities or other heterogeneous subsurface conditions. Onondaga Creek is located approximately 600 feet west of the on-site portion, which flows in a northerly direction towards Onondaga Lake."

Env Problem:

"Nature and Extent of Contamination: On-site soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater was also sampled for Emerging Contaminants (ECs). Soil vapor was analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern appear to be VOCs and metals with minor detection's of ECs, PCBs, and SVOCs. No off-site samples were taken during the on-site Remedial Investigation. However, there is some off-site groundwater data. See the Groundwater section below. Soil Surface Soils: Only one VOC, acetone, was detected in the surface soil sample collected from Coyne Park at a concentration of 0.427 ppm which exceeds the Part 375 Unrestricted SCO of 0.05 ppm but is less than the Part 375 Commercial SCO of 500 ppm. SVOCs, PCBs, metals, and pesticides contamination were not identified in the surface soil sample. There is currently no off-site surface soil data. Subsurface Soils: Only one VOC, Tetrachloroethene (PCE), was detected at a concentration exceeding the Part 375 Commercial SCO of 150 milligram per kilogram (mg/kg). The PCE concentration is 460mg/kg and this sample was located in the NW corner of the on-site building. There are several other compounds including 1,1- Dichloroethene at a maximum of 1.45mg/kg, 1,2,4 Trimethylbenzene at a maximum of 4.31mg/kg, 2-Butanone (MEK) at a maximum of 0.115mg/kg, trichloroethene at a maximum of 38.3mg/kg, vinyl chloride at a maximum of 12.3mg/kg, cis-1,2-Dichloroethene at a maximum of 424mg/kg, trans-1,2-Dichloroethene at a maximum of 3.46mg/kg, acetone at a maximum of 5.9mg/kg, and Benzene at a maximum of 0.39mg/kg, that were detected above Part 375 Unrestricted SCOs. SVOCs detected at concentrations exceeding their respective Part 375 Unrestricted SCOs, but below Part 375 Commercial SCOs, include benzo(a)anthracene at a maximum of 2.42mg/kg, Benzo(a)pyrene at a maximum of 2.28mg/kg, Benzo(b)fluoranthene at a maximum of 3.06mg/kg, Benzo(k)fluoranthene at a maximum of 1.64mg/kg, Chrysene at a maximum of 2.42mg/kg, and Indeno(1,2,3-cd)pyrene at a maximum of 0.79mg/kg. No SVOCs were detected at concentrations exceeding the Part 375

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Commercial SCOs. Pesticides were not detected in any of the subsurface samples. PCBs, including Aroclor 1242 and Aroclor 1260 were detected at concentrations above their respective Part 375 Unrestricted SCO of 0.1 mg/kg, but below the Part 375 Commercial SCO. The maximum Total PCBs concentration was 0.74 mg/kg. Low concentrations of metals were found across the on-site area. Barium was detected at a concentration of 404 mg/kg, which exceeds the Part 375 Commercial SCO of 400 mg/kg. However, this value was qualified, by Pace, with a JH qualifier. This sample was located near the location of the former folding/product storage area. Several other metals were detected above unrestricted SCOs including copper at a maximum of 114mg/kg, lead at a maximum of 776mg/kg, nickel at a maximum of 56.2mg/kg, zinc at a maximum of 315mg/kg, and mercury at a maximum of 1.4mg/kg. No offsite soil samples were taken during the RI however some off-site subsurface soils were sampled in 2015. Off-site subsurface soil data shows four SVOCs above Industrial SCOs in MW-4 at a depth of 8-10 feet. These SVOCs are Benzo(a)anthracene at a maximum of 20 mg/kg, Benzo(a)pyrene at a maximum of 17 mg/kg, Benzo(b)fluoranthene at a maximum of 21 mg/kg, and Dibenzo(a,h)anthracene at a maximum of 2.4 mg/kg. No other contaminants were above industrial SCOs. Groundwater (GW) No PCBs or Pesticides were detected within the groundwater. VOCs detected in groundwater above the GW standard include 1,1-Dichloroethene at a maximum of 18ug/kg, benzene at a maximum of 104ug/kg, isopropylbenzene (Cumene) at a maximum of 121ug/kg, tetrachloroethene at a maximum of 21,400ug/kg, trichloroethene at a maximum of 1,980ug/kg, vinyl chloride at a maximum of 1,560ug/kg, xylene (Total) at a maximum of 6.3ug/kg, cis-1,2-Dichloroethene at a maximum of 4,550ug/kg, and trans-1,2-Dichloroethene at a maximum of 27.5ug/kg. Most of the VOC GW impacts were located in the NW portion of the on-site building but VOC impacts were detected throughout the site. Only one SVOC exceeded GW standards and that was bis(2-Ethylhexyl)phthalate at a maximum of 11ug/kg. This was located in the NW portion of the on-site building. Metals that exceeded the GW standards include barium at a maximum of 2.940ug/kg, beryllium at a maximum of 7ug/kg, chromium at a maximum of 55ug/kg, copper at a maximum of 1,120ug/kg, lead at a maximum of 27ug/kg, magnesium at a maximum of 204,000ug/kg, and thallium at a maximum of 14.5ug/kg. Metals within the GW were detected throughout the whole site. ECs detected in the GW include 6:2FTS at a maximum of 33ng/kg, Perfluorobutanesulfonic acid (PFBS) at a maximum of 14ng/kg, Perfluorobutanoic acid (PFBA) at a maximum of 330ng/kg, Perfluorodecanoic acid (PFDA) at a maximum of 2.1ng/kg, Perfluoroheptanesulfonic Acid (PFHpS) at a maximum of 24ng/kg, Perfluoroheptanoic acid (PFHpA) at a maximum of 160ng/kg, Perfluorohexanesulfonic acid (PFHxS) at a maximum of 25ng/kg, Perfluorohexanoic acid (PFHxA) at a maximum of 350ng/kg, Perfluorononanoic acid (PFNA) at a maximum of 75ng/kg, Perfluorooctanesulfonic acid (PFOS) at a maximum of 2,000ng/kg, Perfluorooctanoic acid (PFOA) at a maximum of 300ng/kg, Perfluoropentanoic acid (PFPeA) at a maximum of 360ng/kg, and 1,4-Dioxane at a maximum of 1.7ng/kg. Most of the ECs were detected in the NW portion of the on-site building. No off-site wells were sampled during the remedial investigation. However, off-sites wells were sampled previously in 2015. There are 4 monitoring wells off-site located to the northwest of the on-site area. Each of these wells have contaminants that exceed NYSDEC TOGS 1.1.1 water quality

RENALLI TAYLOR ST LLC (Continued) **1000311573**

	standards and guidance values. The following contaminants were detected above the GW standards at one or more of the wells: Tetrachloroethene at a maximum of 3100ug/L, benzene at a maximum of 4.4ug/L, vinyl chloride at a maximum of 3200ug/L, trans-1,2-dichloroethene at a maximum of 230ug/L, Trichloroethene at a maximum of 2000ug/L, cis-1,2-dichloroethene at a maximum of 5600ug/kg, and 1,1-Dichloroethene at a maximum of 15ug/L. Soil Vapor Soil vapor detection's that need additional action were detected all throughout the on-site building. Compounds detected needing additional action include: 1,1,1 - Trichloroethane at a maximum of 5.3ug/m3, Tetrachloroethene at a maximum of 1,090ug/m3, Trichloroethene at a maximum of 106ug/m3, and cis-1,2-Dichloroethene at a maximum of 38.4ug/m3. There is currently no off-site soil vapor data. "
Health Problem:	"Volatile organic compounds in groundwater or soil vapor originating from the Former Coyne Textile site (C734144) may move off-site into overlying buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Investigations are needed to determine if soil vapor intrusion is a potential concern for these off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2019-01-02 13:58:00
Record Upd:	2019-01-02 13:58:00
Updated By:	MJBELVEG
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	C734144A
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

HW Code:	C734144A
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	trans-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	1,1 dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C734144A
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C734144
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2019-01-02 13:56:00
Record Updated:	2019-01-02 13:56:00
Updated By:	MJBELVEG

SPILLS:

Name:	COYNE TEXTILE SERVICES
Address:	140 CORTLAND ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9909798 / 1999-11-30
Facility ID:	9909798
Facility Type:	ER
DER Facility ID:	65005
Site ID:	68200
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	1999-11-12
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1999-11-12
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-12
Spill Record Last Update:	2000-02-15
Spiller Name:	D J SMITH
Spiller Company:	COYNE TEXTILE SERVICES
Spiller Address:	140 CORTLAND ST
Spiller Company:	001
Contact Name:	D J SMITH
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	2 CAUSES FAILED LEVEL CONTROL VALVE AND OVER FLOW PIPE BROKE - SPILL CLEANED UP

All Materials:

Site ID:	68200
Operable Unit ID:	1088487
Operable Unit:	01
Material ID:	298867
Material Code:	0060A
Material Name:	wastewater
Case No.:	Not reported
Material FA:	Other
Quantity:	100.00
Units:	G
Recovered:	100.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	COMMERCIAL BUILDING (COYNE TEXTILE)
Address:	140 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	0905092 / 2010-01-12
Facility ID:	0905092
Facility Type:	ER
DER Facility ID:	366482
Site ID:	417341
DEC Region:	7
Spill Cause:	Housekeeping
Spill Class:	C6
SWIS:	3415
Spill Date:	2009-08-01
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2009-08-01
CID:	Not reported
Water Affected:	ONONDAGA CREEK
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Fire Department
Cleanup Ceased:	2009-08-03
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

RENALLI TAYLOR ST LLC (Continued) **1000311573**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-08-01
Spill Record Last Update:	2010-01-12
Spiller Name:	Not reported
Spiller Company:	COYNE TEXTILE
Spiller Address:	140 CORTLAND AVE
Spiller Company:	999
Contact Name:	CHIEF DUFFY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	FD advised 2 40 CY ISO containers caught fire due to suspected spontaneous combustion of oily rags stored inside. FD used several thousand gallons of water to extinguish fire, causing oily surface water to flow into area storm drains. Awaiting FD report from Lt. Galloway.
Remarks:	2 large containers found with rags soaked with engine oil,cooking oil,auto grease, and printer ink caught on fire.Request DEC call back. Not reported

All Materials:

Site ID:	417341
Operable Unit ID:	1173560
Operable Unit:	01
Material ID:	2165500
Material Code:	0046A
Material Name:	cooking grease
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil, Surface Water
Oxygenate:	Not reported

Site ID:	417341
Operable Unit ID:	1173560
Operable Unit:	01
Material ID:	2165501
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil, Surface Water
Oxygenate:	Not reported

Name:	COYNE TEXTILE SERVICES
Address:	140 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0301230 / 2003-05-05
Facility ID:	0301230
Facility Type:	ER
DER Facility ID:	132732

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Site ID:	101722
DEC Region:	7
Spill Cause:	Other
Spill Class:	C6
SWIS:	3415
Spill Date:	2003-05-04
Investigator:	MENASH
Referred To:	Not reported
Reported to Dept:	2003-05-04
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-04
Spill Record Last Update:	2003-05-05
Spiller Name:	DJ SMITH
Spiller Company:	COYNE TEXTILE SERVICES
Spiller Address:	140 CORTLAND AV
Spiller Company:	001
Contact Name:	DJ SMITH
Latitude:	43.0372833
Longitude:	-76.1502534
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MN SPILL TURNED OVER TO WATER DEPT.
Remarks:	spontainious heating caused a fire in the facility - the fire dept responded - oils inks & blanket wash & water put on the fire by fd were washed down the storm sewer

All Materials:

Site ID:	101722
Operable Unit ID:	867623
Operable Unit:	01
Material ID:	571447
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	1200.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	CONSTRUCTION SITE
Address:	140 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2005960 / 2020-10-29
Facility ID:	2005960
Facility Type:	ER
DER Facility ID:	132732

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Site ID:	611773
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3415
Spill Date:	2020-09-30
Investigator:	MJBELVEG
Referred To:	Not reported
Reported to Dept:	2020-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-10-01
Spill Record Last Update:	2020-10-29
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KARYN MEHMANN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	cleanup pending brownfield cleanup number c734144

All Materials:

Site ID:	611773
Operable Unit ID:	1358921
Operable Unit:	01
Material ID:	2370364
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Groundwater
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20160302
Handler Name:	Coyne Textile Services
Handler Address:	Cortland Ave
Handler City,State,Zip:	SYRACUSE, NY 13221
EPA ID:	NYD013250618
Contact Name:	JOHN D WESSELS
Contact Address:	CORTLAND AVE
Contact City,State,Zip:	SYRACUSE, NY 13221
Contact Telephone:	315-475-1626

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Contact Fax:		315-475-0057
Contact Email:		JOHN.WESSELS@COYNETEXTILESERVICES.COM
Contact Title:		CORPORATE ENVIRONMENTAL AFFAIRS
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R7
Mailing Address:		CORTLAND AVE
Mailing City,State,Zip:		SYRACUSE, NY 13221
Owner Name:	Coyne International Enterprises	
Owner Type:		Private
Operator Name:	Coyne Textile Services	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20160323
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Sub-Part P Indicator: No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:
Year: 2011

Click Here for Biennial Reporting System Data:
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2007

Click Here for Biennial Reporting System Data:
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichloroethylene

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COYNE TEXTILE SERVICES
Legal Status:	Private
Date Became Current:	19390524
Date Ended Current:	Not reported
Owner/Operator Address:	140 CORTLAND AVE
Owner/Operator City,State,Zip:	SYRACUSE, NY 13221
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	STANLEY COYNE INT ENTERPRISES CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	140 CORTLAND AVE
Owner/Operator City,State,Zip:	SYRACUSE, NY 13202
Owner/Operator Telephone:	315-475-1626
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COYNE TEXTILE SERVICES
Legal Status:	Private
Date Became Current:	19290524
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COYNE TEXTILE SERVICES
Legal Status:	Private
Date Became Current:	19290524
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COYNE INTERNATIONAL ENTERPRISES
Legal Status:	Private
Date Became Current:	19390524
Date Ended Current:	Not reported
Owner/Operator Address:	140 CORTLAND AVE
Owner/Operator City,State,Zip:	SYRACUSE, NY 13221
Owner/Operator Telephone:	315-475-1626

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COYNE TEXTILE SERVICES
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COYNE TEXTILE SEVICES
Legal Status: Federal
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE INTERNATIONAL ENTERPRISES
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE INTERNATIONAL ENTERPRISES, INC.
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE INTERNATIONAL ENTERPRISES
Legal Status: Private
Date Became Current: 19390524
Date Ended Current: Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Owner/Operator Address: 140 CORTLAND AVE
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: 315-475-1626
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COYNE TEXTILE SERVICES
Legal Status: Private
Date Became Current: 20021121
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE TEXTILE SEVICESCOYNE INTERNATIONAL
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COYNE TEXTILE SERVICES
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE INTERNATIONAL ENTERPRISES
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NO NAME FOUND

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE INTERNATIONAL ENTERPRISES
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: COYNE TEXTILE SERVICES
Legal Status: Private
Date Became Current: 19390524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STANLEY COYNE INT ENTERPRISES CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE
Owner/Operator City,State,Zip: SYRACUSE, NY 13202
Owner/Operator Telephone: 315-475-1626
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE INTERNATIONAL ENTERPRISES, INC.
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Owner/Operator Indicator: Operator
Owner/Operator Name: COYNE TEXTILE SERVICES
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: COYNE INTERNATIONAL ENTERPRISES, INC.
Legal Status: Private
Date Became Current: 19290524
Date Ended Current: Not reported
Owner/Operator Address: 140 CORTLAND AVE.
Owner/Operator City,State,Zip: SYRACUSE, NY 13221
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100219
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20120223
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140314
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160208
Handler Name:	COYNE TEXTILE SERVICES
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060215
Handler Name:	COYNE TEXTILE SERVICES
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	COYNE TEXTILE SERVICES
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20160302
Handler Name:	COYNE TEXTILE SERVICES
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Electronic Manifest Broker: Not reported

Receive Date: 19930412
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20021121
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920228
Handler Name: COYNE TEXTILE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940516
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator

RENALLI TAYLOR ST LLC (Continued) **1000311573**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960222
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980211
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020207
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040216
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060216
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080126
Handler Name: COYNE TEXTILE SERVICES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 812332
NAICS Description: Industrial Launderers

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20070830
Actual Return to Compliance Date:	20071015
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20070920
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYJGE
Enforcement Responsible Sub-Organization: R7
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19901116
Actual Return to Compliance Date:	19910114
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Scheduled Compliance Date: 19910110
Enforcement Identifier: 002
Date of Enforcement Action: 19901210
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Manifest
Date Violation was Determined: 19880104
Actual Return to Compliance Date: 19880106
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19880106
Enforcement Identifier: 001
Date of Enforcement Action: 19880104
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20140812
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYBRS
Evaluation Responsible Sub-Organization: R7

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20120201
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2OSK
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20100504
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYJGE
Evaluation Responsible Sub-Organization:	R7
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20070830
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYJGE
Evaluation Responsible Sub-Organization:	R7
Actual Return to Compliance Date:	20071015
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20030609
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYBRS
Evaluation Responsible Sub-Organization:	R7
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Former Citation:	Not reported
Evaluation Date:	19991223
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYBRS
Evaluation Responsible Sub-Organization:	R7
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19901116
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19910114
Scheduled Compliance Date:	19910110
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19880104
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19880106
Scheduled Compliance Date:	19880106
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19870910
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ICIS:
Enforcement Action ID: NY000A0000731150034200304

RENALLI TAYLOR ST LLC (Continued) **1000311573**

FRS ID:	110000807431
Action Name:	COYNE TEXTILE SERVICES 360670009900304
Facility Name:	COYNE TEXTILE SERVICES
Facility Address:	140 CORTLAND AVE SYRACUSE, NY 132023411
Enforcement Action Type:	Notice of Violation
Facility County:	ONONDAGA
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7218
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	43.037514
Longitude in Decimal Degrees:	-76.150328
Permit Type Desc:	Not reported
Program System Acronym:	NY0000007311500342
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000731150034200007
FRS ID:	110000807431
Action Name:	COYNE TEXTILE SERVICES 360670009900007
Facility Name:	COYNE TEXTILE SERVICES
Facility Address:	140 CORTLAND AVE SYRACUSE, NY 132023411
Enforcement Action Type:	Administrative Order
Facility County:	ONONDAGA
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	7218
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	43.037514
Longitude in Decimal Degrees:	-76.150328
Permit Type Desc:	Not reported
Program System Acronym:	NY0000007311500342
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

Enforcement Action ID:	NY000A0000731150034200005
FRS ID:	110000807431
Action Name:	COYNE TEXTILE SERVICES 360670009900005
Facility Name:	COYNE TEXTILE SERVICES
Facility Address:	140 CORTLAND AVE SYRACUSE, NY 132023411
Enforcement Action Type:	Notice of Violation
Facility County:	ONONDAGA
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7218
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	43.037514
Longitude in Decimal Degrees:	-76.150328
Permit Type Desc:	Not reported
Program System Acronym:	NY0000007311500342
Facility NAICS Code:	812320

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Tribal Land Code: Not reported

US AIRS MINOR:
Envid: 1000311573
Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
D and B Number: Not reported
Primary SIC Code: 7218
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: Not reported
Activity Status Date: 1999-11-10 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-03-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-11-10 00:00:00
Activity Status Date: 1999-11-10 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
Air Operating Status Code: OPR

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-04-02 00:00:00
Activity Status Date: 1999-04-02 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-12-10 00:00:00
Activity Status Date: 2002-12-10 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-10-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000007311500342
Facility Registry ID: 110000807431
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-12-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110070913211

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Registry ID: 110000807431

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database
The Air Facility System (AFS) contains compliance and permit data for stationary sources of air pollution regulated by the EPA, state, and local air pollution agencies.
ICIS-Air (AIR) AIR is the modernization of the Air Facility System (AFS) into the Integrated Compliance Information System (ICIS). AIR contains enforcement, compliance, and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies.
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000311573
Registry ID:	110000807431

DFR URL:

Name:	COYNE TEXTILE SERVICES
Address:	140 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY 13202

PFAS ECHO:

Facility ID:	110070913211
Name:	Renalli Taylor St Llc
Address:	140 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY 13202
Latitude:	43.03709
Longitude:	-76.15031
Count:	1
County:	ONONDAGA
Status:	Inactive
Region:	02
Industry:	Electronics Industry

ECHO Facility Report:

Facility Percent Minority:	46.285
Facility Derived Tribes:	Onondaga Nation - 5 mile(s), Oneida Indian Nation - 10 mile(s)

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Facility Population:	5165.42
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	36067
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	04140201
Facility Derived WBD:	041402011507
Facility Derived CD113:	24
Facility Derived CB2010:	360670042002018
Facility Major Flag:	-
Facility Active Flag:	-
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	NYR000247932
RCRA Permit Types:	Other
RCRA NAICS:	334220
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-

RENALLI TAYLOR ST LLC (Continued) **1000311573**

DRYCLEANERS:

Name:	COYNE TEXTILE SERVICES
Address:	140 CORTLAND AVE.
City,State,Zip:	SYRACUSE, NY 13202
Facility ID:	7-3115-00342
Phone Number:	315-475-1626
Region:	Not reported
Registration Effective Date:	12/2/1999 0:00
Inspection Date:	09/16/2012
Install Date:	99/16
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

NY MANIFEST:

EPA ID:	NYR000247932
Country:	USA
Name:	Renalli Taylor St Llc
Address:	140 CORTLAND AVE
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	140 CORTLAND AVE
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Renalli Taylor St Llc
Mailing Contact:	Renalli Taylor St Llc
Mailing Address 1:	140 CORTLAND AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2155807192

EPA ID:	NYD013250618
Country:	USA
Name:	Coyne Textile Services
Address:	140 CORLAND AVE
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13221
Zip 4:	Not reported
Location Address 1:	140 CORTLAND AVE
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13221
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Code: BP

Mailing:
Mailing Name: Coyne Textile Services
Mailing Contact: Ed Brewer
Mailing Address 1: 140 CORTLAND AVENUE
Mailing Address 2: Not reported
Mailing City,State,Zip: SYRACUSE, NY 13221
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 3154751626

Manifest Data:
Document ID: NYC1051187
Manifest Status: Not reported
Trans1 State ID: NYNS7863
Year: 1991
Trans2 State ID: Not reported
Generator Ship Date: 06/24/1991
Trans1 Recv Date: 06/24/1991
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/24/1991
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD013250618
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NYD000824581
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 01950
Units: Pounds

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Number of Containers:	010
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC3058604
Manifest Status:	Not reported
Trans1 State ID:	NYLJ5601
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/1994
Trans1 Recv Date:	06/03/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/06/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD982743312
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00585
Units:	Pounds
Number of Containers:	003
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG2914911
Manifest Status:	Not reported
Trans1 State ID:	CT9751

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	07/27/2001
Trans1 Recv Date:	07/27/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/30/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	34700
Units:	Pounds
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG2915415
Manifest Status:	Not reported
Trans1 State ID:	CTV35108
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	09/05/2001
Trans1 Recv Date:	09/05/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/06/2001
Part A Recv Date:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	42560
Units:	Pounds
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC1106223
Manifest Status:	Not reported
Trans1 State ID:	NYNS7863
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/1991
Trans1 Recv Date:	07/22/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000824581
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02730
Units:	Pounds
Number of Containers:	014
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG2915928
Manifest Status:	Not reported
Trans1 State ID:	V17860CT
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	08/15/2001
Trans1 Recv Date:	08/15/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/15/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Quantity:	37680
Units:	Pounds
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG2912184
Manifest Status:	Not reported
Trans1 State ID:	S9751CT
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	04/05/2001
Trans1 Recv Date:	04/05/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/05/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	43160
Units:	Pounds
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG2912445
Manifest Status:	Not reported
Trans1 State ID:	CTV35108
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2001
Trans1 Recv Date:	04/19/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/2001

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	42640
Units:	Pounds
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG2913138
Manifest Status:	Not reported
Trans1 State ID:	V17860CT
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2001
Trans1 Recv Date:	05/14/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	37500
Units:	Pounds
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG2913381
Manifest Status:	Not reported
Trans1 State ID:	S9751CT
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	05/29/2001
Trans1 Recv Date:	05/29/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/29/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD080469935
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	38120
Units:	Pounds
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Document ID:	NYG2914191
Manifest Status:	Not reported
Trans1 State ID:	CTV35108
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	06/25/2001
Trans1 Recv Date:	06/25/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/26/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013250618
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	05000
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
1075 additional NY MANIFEST: record(s) in the EDR Site Report.

RI MANIFEST:

Name:	Not reported
Address:	140 CORTLAND
City,State,Zip:	SYRACUSE, NY 13221-0000
EPA Id:	NYD013250618
GEN Cert Date:	4/10/1997
Manifest Document Number:	CTF0386557
Waste Description:	FLAM LIQ
TSDF Id:	CTD021816889
TSDF Name:	UNITED OIL RECOVERY INC
Qty:	5250
WT/Vol Units:	G

RENALLI TAYLOR ST LLC (Continued) **1000311573**

TSDF Date:	Not reported
Transporter 2 Id:	Not reported
Item Number:	1
Transporter 2 Name:	Not reported
Transporter Name 2:	UNITED IND SVS
Transporter EPAID:	CTD021816889
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D001
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D001
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	UNITED OIL RECOVERY INC
TSDF Id:	CTD021816889
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD013250618
Manifest Docket Number:	CTF0386557
Quarter:	Not reported
Waste Description:	FLAM LIQ
Transporter Contact Name:	Not reported
Quantity:	5250
Transporter Contact Email:	Not reported
WT/Vol Units:	G

RENALLI TAYLOR ST LLC (Continued) **1000311573**

Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	UNITED IND SVS
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/10/1997
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported
Transporter Receipt Date:	Not reported
Number Of Containers:	0
Container Type:	Not reported
Waste Code1:	D001
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	UNITED OIL RECOVERY INC
TSDF Id:	CTD021816889
Transporter Name 2:	Not reported
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD013250618
Manifest Docket Number:	CTF0386557
Quarter:	Not reported
Waste Description:	FLAM LIQ
Transporter Contact Name:	Not reported
Quantity:	5250
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	UNITED IND SVS
Billing Name:	Not reported
Transporter EPA ID:	CTD021816889
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/10/1997
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	Not reported
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	Not reported
Manifest Updated Date:	Not reported

T90 **MONDO'S SERVICE STATION** **UST FINDER RELEASE** **1029074539**
SW **1133 SOUTH SALINA** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.271 mi.
1433 ft. **Site 3 of 6 in cluster T**

Relative: **Lower**
Actual: **390 ft.**

UST FINDER RELEASE:

Object ID:	249465
Facility ID:	NY332326
Lust ID:	NY703031
Name:	MONDO'S SERVICE STATION
Address:	1133 SOUTH SALINA
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	2007/06/13 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1519
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Yes
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.14946
Y Coord:	43.0360200000001
Latitude:	43.03602
Longitude:	-76.14946

T91 **MONDO'S SERVICE STATION** **NY LTANKS** **S108639805**
SW **1133 SOUTH SALINA** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.271 mi.
1433 ft. **Site 4 of 6 in cluster T**

Relative: **Lower**
Actual: **390 ft.**

LTANKS:

Name:	MONDO'S SERVICE STATION
Address:	1133 SOUTH SALINA
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0703031 / 2007-10-04
Facility ID:	0703031
Site ID:	382878
Spill Date:	2007-06-13
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility

MONDO'S SERVICE STATION (Continued) **S108639805**

Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	RJBRAZEL
Referred To:	Not reported
Reported to Dept:	2007-06-13
CID:	444
Water Affected:	SHEEN
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2007-06-13
Spill Record Last Update:	2007-10-04
Spiller Name:	JOHN LAVALLEY
Spiller Company:	MONDO'S SERVICE STATION
Spiller Address:	1133 SOUTH SALINA
Spiller County:	999
Spiller Contact:	JOHN LAVALLEY
Spiller Phone:	(315) 573-2577
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	332326
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	FOUND SHEEN AND ODOR WHILE REMOVING TANKS:

All Materials:

Site ID:	382878
Operable Unit ID:	1140258
Operable Unit:	01
Material ID:	2130319
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

V92 **ADAMS & STATE ST. GARAGE** **NY LTANKS** **S105054364**
NNW **ADAMS & STATE STREET** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.274 mi.
1445 ft. **Site 1 of 2 in cluster V**

Relative: LTANKS:
Lower

Name:	ADAMS & STATE ST. GARAGE
Address:	ADAMS & STATE STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9108385 / 1991-11-07
Facility ID:	9108385

Actual:
396 ft.

ADAMS & STATE ST. GARAGE (Continued) **S105054364**

Site ID:	210798
Spill Date:	1991-11-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1991-11-07
SWIS:	3415
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1991-11-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-11-06
Spill Record Last Update:	1997-03-10
Spiller Name:	Not reported
Spiller Company:	ONONDAGA COUNTY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	174767
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR 11/07/91: EPS HIRED BY ONONDAGA COUNTY TO CLEAN AND REMOVE TANKS. 8 BARRELS OFWATER PUMPED FROM THE TWO TANKS FOR DISPOSAL. ALSO ONE BARREL OF SOIL. NO RESIDUAL CONTAMINATION REMAINING IN SOIL SURROUNDING TANKS.
Remarks:	ONE TANK WAS DISCOVERED ON 11/05/91 AT 3:00. ON MORNING OF 11/06/91 THERE WAS ANOTHER TANK LOCATED WHICH WAS DAMAGED AND PRODUCT SPILLED.

All Materials:

Site ID:	210798
Operable Unit ID:	958676
Operable Unit:	01
Material ID:	420535
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

V93 **ADAMS & STATE ST. GARAGE** **UST FINDER RELEASE** **1029062545**
NNW **ADAMS & STATE STREET** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.274 mi.
1445 ft. **Site 2 of 2 in cluster V**

Relative: **Lower**
Actual: **396 ft.**

UST FINDER RELEASE:

Object ID:	249474
Facility ID:	NY174767
Lust ID:	NY9108385
Name:	ADAMS & STATE ST. GARAGE
Address:	ADAMS & STATE STREET
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1991/11/06 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1993
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1475399999999
Y Coord:	43.04274
Latitude:	43.04274
Longitude:	-76.14754

W94 **V.A. MEDICAL CENTER** **NY LTANKS** **S103479683**
East **800 IRIVING AVENUE** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.277 mi.
1463 ft. **Site 1 of 2 in cluster W**

Relative: **Higher**
Actual: **502 ft.**

LTANKS:

Name:	VA HOSPITAL
Address:	800 IRIVING AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0402165 / 2004-09-29
Facility ID:	0402165
Site ID:	242917
Spill Date:	2004-05-27
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other

V.A. MEDICAL CENTER (Continued) **S103479683**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	BFMATTHE
Referred To:	Not reported
Reported to Dept:	2004-05-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-27
Spill Record Last Update:	2004-09-29
Spiller Name:	JOHN SLICK
Spiller Company:	VA HOSPITAL
Spiller Address:	800 IRVING AVE
Spiller County:	001
Spiller Contact:	JOHN SLICK
Spiller Phone:	(315) 425-3761
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	186304
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was BM
	CLOSURE REPORT SHOWS CLEAN.
Remarks:	3000 GALLON TANK WAS REMOVED HAD HOLES AND CONTAMINATED SOIL: THOUGHT TO BE EMPTIED UNSURE WHAT RELEASED: NOT MUCH IN HOLE:

All Materials:

Site ID:	242917
Operable Unit ID:	885972
Operable Unit:	01
Material ID:	489804
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	V.A. MEDICAL CENTER
Address:	800 IRIVING AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9807877 / 2002-08-06
Facility ID:	9807877
Site ID:	242920
Spill Date:	1998-09-28
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3

V.A. MEDICAL CENTER (Continued) **S103479683**

Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1998-09-28
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-09-28
Spill Record Last Update:	2002-08-06
Spiller Name:	JAMES LITTLEFIELD
Spiller Company:	V.A. MEDICAL CENTER
Spiller Address:	800 IRVING AVE
Spiller County:	001
Spiller Contact:	JAMES LITTLEFIELD
Spiller Phone:	(716) 892-5052
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	186304
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM NO DATA SUBMITTED
Remarks:	WORK SITE PHONE #716-830-3093 DON ALDRICH - POSS LEAKING PIPES FROM TANK

W95 **V.A. MEDICAL CENTER** **UST FINDER RELEASE** **1029063478**
East **800 IRIVING AVENUE** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.277 mi.
1463 ft. **Site 2 of 2 in cluster W**

Relative:
Higher

Actual:
502 ft.

UST FINDER RELEASE:

Object ID:	249570
Facility ID:	NY186304
Lust ID:	NY9807877
Name:	V.A. MEDICAL CENTER
Address:	800 IRIVING AVENUE
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1998/09/28 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2150
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported

V.A. MEDICAL CENTER (Continued) **1029063478**

WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1381
Y Coord:	43.03939
Latitude:	43.0393899999999
Longitude:	-76.1380999999999

X96 **CASTLE REST NURSE HOME** **UST FINDER RELEASE** **1029058680**
South **401 E CASTLE ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.288 mi.
1523 ft. **Site 1 of 2 in cluster X**

Relative: **Higher**
Actual: **405 ft.**

UST FINDER RELEASE:

Object ID:	249524
Facility ID:	NY127530
Lust ID:	NY9011086
Name:	CASTLE REST NURSE HOME
Address:	401 E CASTLE ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1991/01/18 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2016
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1439999999999
Y Coord:	43.03432

CASTLE REST NURSE HOME (Continued) **1029058680**

Latitude: 43.03432
Longitude: -76.144

X97 **CASTLE REST NURSE HOME** **NY LTANKS** **S102677879**
South **401 E CASTLE ST** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.288 mi.
1523 ft. **Site 2 of 2 in cluster X**

Relative:
Higher

Actual:
405 ft.

LTANKS:

Name:	CASTLE REST NURSE HOME
Address:	401 E CASTLE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9011086 / 1991-01-31
Facility ID:	9011086
Site ID:	149961
Spill Date:	1991-01-18
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1991-01-20
SWIS:	3415
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1991-01-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-01-31
Spill Record Last Update:	1991-01-31
Spiller Name:	Not reported
Spiller Company:	CASTLE REST NURSING HOME
Spiller Address:	401 E.CASTLE ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	127530
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR 01/31/91: MOST OF THE SPILL WAS CONTAINED ON A CONCRETE PAD BENEATH THE VENT WHERE THE OVERFILL DISCHARGED SOME CONTAMINATED SOIL WAS STAGED IN DRUMS AT THE SCENE. TO BE REMOVED BY EPS.
Remarks:	CUSTOMER ORDERED TOO MUCH FUEL FOR TANK. FUEL WENT INTO DITCH ON OUT-SIDE OF BUILDING.

All Materials:

Site ID:	149961
Operable Unit ID:	948098
Operable Unit:	01
Material ID:	431177

CASTLE REST NURSE HOME (Continued) **S102677879**

Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

98 SYRACUSE UNIV **NY LTANKS S105997874**
ESE 900 IRVING AVE **NY Spills N/A**
1/4-1/2 SYRACUSE, NY
0.293 mi.
1547 ft.

Relative: Higher
Actual: 497 ft.

LTANKS:

Name:	SYRACUSE CARRIER DOME
Address:	900 IRVING AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0210237 / 2003-10-31
Facility ID:	0210237
Site ID:	96874
Spill Date:	2003-01-10
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2003-01-10
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-10
Spill Record Last Update:	2003-10-31
Spiller Name:	CATHY STRICKLAND
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	CATHY STRICKLAND
Spiller Phone:	(607) 756-4253
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	243755
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	TANK TEST FAILURE AT ABOVE LOCATION. REPLACE MANWAY LID AND RESTEST.

All TTF:

SYRACUSE UNIV (Continued) **S105997874**

Facility ID:	0210237
Spill Number:	0210237
Spill Tank Test:	1527928
Site ID:	96874
Tank Number:	Not reported
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	0210237
Spill Number:	0210237
Spill Tank Test:	1527929
Site ID:	96874
Tank Number:	UNK
Tank Size:	3000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	96874
Operable Unit ID:	861489
Operable Unit:	01
Material ID:	513627
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	SYRACUSE UNIV
Address:	900 IRVING AVE
City,State,Zip:	SYRACUSE, NY

SYRACUSE UNIV (Continued) **S105997874**

Spill Number/Closed Date:	0300735 / 2003-04-22
Facility ID:	0300735
Facility Type:	ER
DER Facility ID:	243755
Site ID:	301633
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	2003-04-21
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2003-04-21
CID:	207
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-21
Spill Record Last Update:	2003-04-22
Spiller Name:	HEATHER BADGER
Spiller Company:	SYRACUSE UNIV AMBULANCE
Spiller Address:	900 IRVING AVE
Spiller Company:	001
Contact Name:	JIM MCCUMBER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	cleanup complete

All Materials:

Site ID:	301633
Operable Unit ID:	868899
Operable Unit:	01
Material ID:	508807
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	9.00
Units:	G
Recovered:	9.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Y99 **680 SOUTH SALINA ST GAS STATION** **NY LTANKS** **S106011637**
WNW **680 SOUTH SALINA ST** **NY Spills** **N/A**
1/4-1/2 **SYRACUSE, NY 13202**
0.307 mi.
1623 ft. **Site 1 of 2 in cluster Y**

Relative: **Lower**

Actual: **396 ft.**

LTANKS:

Name:	JUPP CORP
Address:	680 SOUTH SALINA ST
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	1600634 / 2019-12-10
Facility ID:	1600634
Site ID:	525912
Spill Date:	2016-04-18
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D4
Cleanup Ceased:	2017-06-20
SWIS:	3415
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2016-04-18
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-04-18
Spill Record Last Update:	2019-12-10
Spiller Name:	HARMANDEEP SINGH SEKHON
Spiller Company:	ABMH PROPERTIES LLC
Spiller Address:	81-18-242 ST
Spiller County:	001
Spiller Contact:	BALJIP KAUR
Spiller Phone:	(315) 422-1225
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	43841
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	4/19/2016 - Per John Gramz / Primetime Services, 6,000 gallon UST Tank 857A failed tank tightness test when product discovered in interstitial space. This was the sole remaining functional UST at this location. Previously 8,000 gallon UST Tank 859 (master) failed, effectively also removing satellite 4,000 gallon UST Tank 857B from service due to lack of submersible. PBS # is 7-102830. Contacted Facility owner and operator to determine permanent closure plans for these tanks. KCKemp
Remarks:	inner wall failed test, tank is OOS. unfurther.

All Materials:

Site ID:	525912
Operable Unit ID:	1274858
Operable Unit:	01
Material ID:	2279520
Material Code:	0009
Material Name:	gasoline

680 SOUTH SALINA ST GAS STATION (Continued) **S106011637**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	JUPP CORP
Address:	680 SOUTH SALINA ST
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	1600634 / 2019-12-10
Facility ID:	1600634
Site ID:	525912
Spill Date:	2016-04-18
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D4
Cleanup Ceased:	2017-06-20
SWIS:	3415
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2016-04-18
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-04-18
Spill Record Last Update:	2019-12-10
Spiller Name:	BALJIT KAUR
Spiller Company:	JUPP CORP
Spiller Address:	680 SOUTH SALINA ST
Spiller County:	999
Spiller Contact:	BALJIP KAUR
Spiller Phone:	(315) 422-1225
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	43841
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	4/19/2016 - Per John Gramz / Primetime Services, 6,000 gallon UST Tank 857A failed tank tightness test when product discovered in interstitial space. This was the sole remaining functional UST at this location. Previously 8,000 gallon UST Tank 859 (master) failed, effectively also removing satellite 4,000 gallon UST Tank 857B from service due to lack of submersible. PBS # is 7-102830. Contacted Facility owner and operator to determine permanent closure plans for these tanks. KCKemp
Remarks:	inner wall failed test, tank is OOS. unfurther.

All Materials:

Site ID:	525912
Operable Unit ID:	1274858

680 SOUTH SALINA ST GAS STATION (Continued) **S106011637**

Operable Unit:	01
Material ID:	2279520
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	DESIMONES SERVICE STA.
Address:	680 S. SALINA ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8705408 / 1987-10-28
Facility ID:	8705408
Site ID:	265820
Spill Date:	1987-09-28
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1987-10-28
SWIS:	3415
Investigator:	AJMARSCH
Referred To:	Not reported
Reported to Dept:	1987-09-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-05
Spill Record Last Update:	1997-11-19
Spiller Name:	Not reported
Spiller Company:	DESIMONES GAS STATION
Spiller Address:	680 S. SALINA ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	216600
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JM / / : REMOVED CONTAMINATED SOIL. HAULED AWAY BY ENV. OIL.
Remarks:	EXCAVATION REVEALED CONTAMINATED SOIL.

All Materials:

Site ID:	265820
Operable Unit ID:	909231
Operable Unit:	01
Material ID:	468011

680 SOUTH SALINA ST GAS STATION (Continued) **S106011637**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	DESIMONES GAS STATION
Address:	680 S SALINA ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0211565 / 2003-07-21
Facility ID:	0211565
Facility Type:	ER
DER Facility ID:	235787
Site ID:	291210
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3415
Spill Date:	2003-02-21
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2003-02-21
CID:	365
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-21
Spill Record Last Update:	2003-10-06
Spiller Name:	ERNIE DESIMONE
Spiller Company:	DESIMONES GAS STATION
Spiller Address:	680 S SALINA ST
Spiller Company:	001
Contact Name:	ERNIE DESIMONE
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	possilby former leaking tanks or surface spills - got lab results back today indicating gasoline contamination

All Materials:

Site ID:	291210
Operable Unit ID:	862674
Operable Unit:	01
Material ID:	2106927
Material Code:	1213A

680 SOUTH SALINA ST GAS STATION (Continued) **S106011637**

Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	True

Site ID:	291210
Operable Unit ID:	862674
Operable Unit:	01
Material ID:	573999
Material Code:	2645A
Material Name:	BTEX
Case No.:	Not reported
Material FA:	Oxygenates
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	True

Site ID:	291210
Operable Unit ID:	862674
Operable Unit:	01
Material ID:	511351
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	True

Name:	680 SOUTH SALINA ST GAS STATION
Address:	680 SOUTH SALINA ST
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	1703133 / 2017-08-17
Facility ID:	1703133
Facility Type:	ER
DER Facility ID:	43841
Site ID:	554293
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	3415
Spill Date:	2017-06-27
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2017-06-27
CID:	Not reported
Water Affected:	NONE
Spill Source:	Non Major Facility > 1,100 gal

680 SOUTH SALINA ST GAS STATION (Continued) **S106011637**

Spill Notifier:	Other
Cleanup Ceased:	2017-08-17
Cleanup Meets Std:	False
Last Inspection:	2017-06-27
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2017-06-29
Spill Record Last Update:	2020-06-17
Spiller Name:	BALJIT KAUR
Spiller Company:	680 S. SALINA ST LLC
Spiller Address:	3987 WEST LANGERWOOD LN
Spiller Company:	999
Contact Name:	BALJIT KAUR
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	6/27/2017 - PRODUCT OBSERVED BENEATH TANKS WHILE REMOVING TANKS. KCKEMP 8/17/2017 - Closure Report received and filed. Awaiting soil disposal by LSFS. KCKemp
Remarks:	Not reported

All Materials:

Site ID:	554293
Operable Unit ID:	1302370
Operable Unit:	01
Material ID:	2308755
Material Code:	2712
Material Name:	gasoline/ethanol
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

Y100 **DESIMONES SERVICE STA.** **UST FINDER RELEASE** **1029065966**
WNW **680 S. SALINA ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.307 mi.
1623 ft. **Site 2 of 2 in cluster Y**

Relative: **Lower**
Actual: **396 ft.**

UST FINDER RELEASE:

Object ID:	249455
Facility ID:	NY216600
Lust ID:	NY8705408
Name:	DESIMONES SERVICE STA.
Address:	680 S. SALINA ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1987/09/28 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	722
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No

DESIMONES SERVICE STA. (Continued) **1029065966**

SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1509
Y Coord:	43.0411
Latitude:	43.0411
Longitude:	-76.1508999999999

T101 **1202-04 SOUTH SALINA STREET** **US BROWNFIELDS** **1027025399**
SW **1202-04 SOUTH SALINA STREET** **FINDS** **N/A**
1/4-1/2 **SYRACUSE, NY 13202**
0.308 mi.
1628 ft. **Site 5 of 6 in cluster T**

Relative: **Lower**
Actual: **390 ft.**

US BROWNFIELDS:

Name:	1202-04 South Salina Street
Address:	1202-04 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249199
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-06.0
Parcel Size:	0.09
Latitude:	43.035199564
Longitude:	-76.149780199
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported

1202-04 SOUTH SALINA STREET (Continued) **1027025399**

Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-11 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-09-02 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported

1202-04 SOUTH SALINA STREET (Continued) **1027025399**

RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.09
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2476
Below Poverty Percent:	49.48
Meidan Income:	2749
Meidan Income Number:	3710
Meidan Income Percent:	74.14
Vacant Housing Number:	333
Vacant Housing Percent:	16.56
Unemployed Number:	328
Unemployed Percent:	6.55

Name:	1202-04 South Salina Street
Address:	1202-04 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249199
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-06.0
Parcel Size:	0.09
Latitude:	43.035199564
Longitude:	-76.149780199
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported

1202-04 SOUTH SALINA STREET (Continued) **1027025399**

Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported

1202-04 SOUTH SALINA STREET (Continued) **1027025399**

Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.09
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2476
Below Poverty Percent:	49.48
Meidan Income:	2749
Meidan Income Number:	3710
Meidan Income Percent:	74.14
Vacant Housing Number:	333
Vacant Housing Percent:	16.56
Unemployed Number:	328
Unemployed Percent:	6.55

Name:	1202-04 South Salina Street
Address:	1202-04 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249199
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-06.0
Parcel Size:	0.09
Latitude:	43.035199564

1202-04 SOUTH SALINA STREET (Continued) **1027025399**

Longitude:	-76.149780199
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported

1202-04 SOUTH SALINA STREET (Continued) **1027025399**

Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.09
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2476
Below Poverty Percent:	49.48
Meidan Income:	2749
Meidan Income Number:	3710
Meidan Income Percent:	74.14
Vacant Housing Number:	333
Vacant Housing Percent:	16.56
Unemployed Number:	328
Unemployed Percent:	6.55

1202-04 SOUTH SALINA STREET (Continued) **1027025399**

FINDS:
Registry ID: 110071090247

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

T102 **1146 S SALINA STREET** **US BROWNFIELDS** **1027025398**
SW **1146 S SALINA STREET** **FINDS** **N/A**
1/4-1/2 **SYRACUSE, NY 13202**
0.315 mi.
1661 ft. **Site 6 of 6 in cluster T**

Relative: **Lower**
Actual: **390 ft.**

US BROWNFIELDS:

Name:	1146 S Salina Street
Address:	1146 S Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249198
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-05.0
Parcel Size:	0.16
Latitude:	43.035297968
Longitude:	-76.149961667
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported

1146 S SALINA STREET (Continued) **1027025398**

Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	U
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported

1146 S SALINA STREET (Continued) **1027025398**

RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2442
Below Poverty Percent:	50.02
Meidan Income:	2749
Meidan Income Number:	3666
Meidan Income Percent:	75.09
Vacant Housing Number:	330
Vacant Housing Percent:	16.73
Unemployed Number:	325
Unemployed Percent:	6.66

Name:	1146 S Salina Street
Address:	1146 S Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249198
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-05.0
Parcel Size:	0.16
Latitude:	43.035297968
Longitude:	-76.149961667
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported

1146 S SALINA STREET (Continued) **1027025398**

Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-11 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-09-02 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	U
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported

1146 S SALINA STREET (Continued) **1027025398**

RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2442
Below Poverty Percent:	50.02
Meidan Income:	2749
Meidan Income Number:	3666
Meidan Income Percent:	75.09
Vacant Housing Number:	330
Vacant Housing Percent:	16.73
Unemployed Number:	325
Unemployed Percent:	6.66

Name:	1146 S Salina Street
Address:	1146 S Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	249198
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-05.0
Parcel Size:	0.16
Latitude:	43.035297968
Longitude:	-76.149961667
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported

1146 S SALINA STREET (Continued) **1027025398**

Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	U
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported

1146 S SALINA STREET (Continued) **1027025398**

Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	Not reported
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2442
Below Poverty Percent:	50.02
Meidan Income:	2749
Meidan Income Number:	3666
Meidan Income Percent:	75.09
Vacant Housing Number:	330
Vacant Housing Percent:	16.73
Unemployed Number:	325
Unemployed Percent:	6.66

FINDS:
Registry ID: 110071090246

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA)

1146 S SALINA STREET (Continued) **1027025398**

performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

103
North
1/4-1/2
0.317 mi.
1674 ft.

CENTRO PARKING INC.
SUNY HEALTH SRV. CENTER
SYRACUSE, NY

NY LTANKS **S100782289**
N/A

Relative:
Lower

Actual:
398 ft.

LTANKS:

Name:	CENTRO PARKING INC.
Address:	SUNY HEALTH SRV. CENTER
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9311487 / 2001-02-12
Facility ID:	9311487
Site ID:	323404
Spill Date:	1993-12-23
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1993-12-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1993-12-31
Spill Record Last Update:	2001-02-12
Spiller Name:	Not reported
Spiller Company:	NYS DORMITORY
Spiller Address:	161 DELAWARE AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	260522
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM 12/27/93: SPOKE W/ MIKE,ONFORMED HIM TO PUMP DOWN TANKS AND TO CONTACT HOWARD FOR PROPER CLOSURE OF THE TANK. 09/28/95: This is additional information about material spilled from the translation of the old spill file: TANK FAILURE.
Remarks:	TANKS WAS TESTED JAN 93 OK;NOW APPEARS TO BE TAKING ON WATER. CALLER TO INVEST WITH POSSIBLE CONTRACTOR.

All Materials:

Site ID:	323404
Operable Unit ID:	993371

CENTRO PARKING INC. (Continued) **S100782289**

Operable Unit:	01
Material ID:	390524
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

104 SW 1/4-1/2 0.321 mi. 1693 ft.

1208-18 SOUTH SALINA STREET
1208-18 SOUTH SALINA STREET
SYRACUSE, NY 13202

US BROWNFIELDS 1027025381
FINDS N/A

Relative: Lower

Actual: 391 ft.

US BROWNFIELDS:

Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-11 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-09-02 00:00:00

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.33
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155
Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5

Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.33
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155
Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5

Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.33
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155
Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5

Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase I Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-17 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2021-01-08 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.33
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155
Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5
Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.33
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5

Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase I Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase II Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-17 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2021-01-08 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.33
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155
Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5

Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.33

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155
Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5

Name:	1208-18 South Salina Street
Address:	1208-18 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	245001
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	094.-21-07.0
Parcel Size:	0.33
Latitude:	43.034993998
Longitude:	-76.149833005
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Phase II Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	PAHs Petroleum Products VOCs
Contaminants Found at Actionable Level:	PAHs Petroleum Products VOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-11 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2022-09-02 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	Y
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported

1208-18 SOUTH SALINA STREET (Continued) **1027025381**

Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.33
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2513
Below Poverty Percent:	49.47
Meidan Income:	2155
Meidan Income Number:	3762
Meidan Income Percent:	74.06
Vacant Housing Number:	341
Vacant Housing Percent:	16.74
Unemployed Number:	330
Unemployed Percent:	6.5

FINDS:
Registry ID: 110071090229

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

105
East
1/4-1/2
0.338 mi.
1786 ft.

SYRACUSE UNIVERISTY
OFF SKYTOP RD
SYRACUSE, NY

NY LTANKS **S106719258**
N/A

Relative:
Higher

Actual:
519 ft.

LTANKS:

Name:	SYRACUSE UNIVERISTY
Address:	OFF SKYTOP RD
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0311616 / 2004-05-04
Facility ID:	0311616
Site ID:	207927
Spill Date:	2004-01-14
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2004-01-14
CID:	402
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-14
Spill Record Last Update:	2004-05-05
Spiller Name:	JIM MCOMBER
Spiller Company:	SYRACUSE UNIVERISTY
Spiller Address:	OFF SKYTOP RD
Spiller County:	001
Spiller Contact:	JIM MCOMBER
Spiller Phone:	(315) 443-4132
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	172539
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	the univ. has in grown transformers and the caller is stateing that his engineers think that they are leeking.

All Materials:

Site ID:	207927
Operable Unit ID:	876978
Operable Unit:	01
Material ID:	500410
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil

SYRACUSE UNIVERISTY (Continued) **S106719258**

Oxygenate:	Not reported
Site ID:	207927
Operable Unit ID:	876978
Operable Unit:	01
Material ID:	500409
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

106
NW
1/4-1/2
0.348 mi.
1835 ft.

HARRISON PL & E ADAMS ST **NY LTANKS** **S103824165**
HARRISON PL & E ADAMS ST **N/A**
SYRACUSE, NY

Relative:
Lower

Actual:
394 ft.

LTANKS:

Name:	HARRISON PL & E ADAMS ST
Address:	HARRISON PL & E ADAMS ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9814193 / 1999-04-26
Facility ID:	9814193
Site ID:	97685
Spill Date:	1999-02-25
Spill Cause:	Tank Failure
Spill Source:	Passenger Vehicle
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1999-02-25
CID:	205
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-25
Spill Record Last Update:	1999-04-26
Spiller Name:	Not reported
Spiller Company:	KATHLEEN MCLAGGEN
Spiller Address:	CANDLEWWOD GARDENS A41
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	86992

HARRISON PL & E ADAMS ST (Continued) **S103824165**

Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	GAS TANK SPRUNG A LEAK. CLEANUP COMPLETED.

All Materials:

Site ID:	97685
Operable Unit ID:	1071620
Operable Unit:	01
Material ID:	310897
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Z107 **743 IRVING AVE.** **NY LTANKS** **S100130939**
ENE **743 IRVING AVE** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.350 mi.
1848 ft. **Site 1 of 2 in cluster Z**

Relative:
Higher

Actual:
498 ft.

LTANKS:

Name:	743 IRVING AVE.
Address:	743 IRVING AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9101558 / 1991-05-08
Facility ID:	9101558
Site ID:	180766
Spill Date:	1991-05-08
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1991-05-08
SWIS:	3415
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1991-05-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	CROUSE IRVING HOSPITAL
Spiller Address:	743 IRVING AVE.
Spiller County:	001
Spiller Contact:	Not reported

743 IRVING AVE. (Continued) **S100130939**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	151618
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR 05/08/91: CONTENTS OF TANK LEAKED AS TANK WAS BEING REMOVED FROM TANK PIT.SOIL WAS EVCAVATED FROM SITE IMMEADIATELY AND STAGED FOR DISPOSAL. Not reported
Remarks:	CONTAMINATED SOIL DISCOVERED DURING TANK REMOVAL.

All Materials:

Site ID:	180766
Operable Unit ID:	952671
Operable Unit:	01
Material ID:	427664
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	8.00
Resource Affected:	Soil
Oxygenate:	Not reported

Z108 **743 IRVING AVE.** **UST FINDER RELEASE** **1029060626**
ENE **743 IRVING AVE** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.350 mi.
1848 ft. **Site 2 of 2 in cluster Z**

Relative: **Higher**
Actual: **498 ft.**

UST FINDER RELEASE:

Object ID:	249572
Facility ID:	NY151618
Lust ID:	NY9101558
Name:	743 IRVING AVE.
Address:	743 IRVING AVE
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1991/05/08 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	2412
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported

743 IRVING AVE. (Continued) **1029060626**

Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1378
Y Coord:	43.0408800000001
Latitude:	43.04088
Longitude:	-76.1377999999999

AA109 **SUNY UPSTATE** **NY LTANKS** **U003077876**
NE **750 EAST ADAMS ST** **NY CBS** **N/A**
1/4-1/2 **SYRACUSE, NY 13202** **NY AST**
0.357 mi. **NY CBS AST**
1886 ft. **Site 1 of 2 in cluster AA** **NY Spills**
NY MANIFEST

Relative:
Higher

Actual:
443 ft.

LTANKS:

Name:	SUNY UPSTATE
Address:	750 EAST ADAMS ST
City,State,Zip:	SYRACUSE, NY 13202
Spill Number/Closed Date:	1406531 / 2015-07-22
Facility ID:	1406531
Site ID:	500005
Spill Date:	2014-09-19
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	D4
Cleanup Ceased:	2015-07-22
SWIS:	3415
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2014-09-19
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2014-09-19
Spill Record Last Update:	2015-07-22
Spiller Name:	ROB ANDRUS
Spiller Company:	SUNY UPSTATE
Spiller Address:	750 EAST ADAMS ST
Spiller County:	999
Spiller Contact:	ROB ANDRUS
Spiller Phone:	(315) 464-4019
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	455022
Latitude:	Not reported
Longitude:	Not reported

SUNY UPSTATE (Continued) **U003077876**

DEC Memo: 4/15/2015 - PBS #7-129410. Vent repaired temporarily. Spill to remain open until tank tightness tested. KCKemp 7/22/2015 - Vent repaired and tank tested tight. Spill closed. KCKemp

Remarks: VENT PIPE CRUSHED DURING CONSTRUCTION. PRIMARY DOES NOT HOLD PRESSURE. NO LEAK SUSPECTED DUE TO RECENT CONSTRUCTION IN AREA THAT MAY HAVE CRUSHED VENT PIPE.

All Materials:

Site ID: 500005
Operable Unit ID: 1249408
Operable Unit: 01
Material ID: 2250990
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Resource Affected: Soil
Oxygenate: Not reported

CBS:

Name: SUNY HEALTH SCIENCE CENTER
Address: 750 EAST ADAMS STREET
City,State,Zip: SYRACUSE, NY 13210
CBS Number: 7-000251
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 7
UTMX: 407100.14033
UTMY: 4766179.96721

AST:

Name: SUNY HEALTH SCIENCE CENTER
Address: 750 EAST ADAMS STREET
City,State,Zip: SYRACUSE, NY 13210
Region: STATE
DEC Region: 7
Site Status: Unregulated/Closed
Facility Id: 7-000251
Program Type: CBS
UTM X: 407100.14033
UTM Y: 4766179.96721
Expiration Date: N/A
Site Type: School

Tank Info:

Tank Number: H100
Tank Id: 190756
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Plastic
Tank Status: Closed - In Place

SUNY UPSTATE (Continued) **U003077876**

Pipe Model:	Not reported
Install Date:	10/01/1993
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

CBS AST:

CBS Number:	7-000251
ICS Number:	Not reported
PBS Number:	7-129410
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	G
Telephone:	(315) 464-4230
Facility Town:	SYRACUSE (C)
Region:	STATE
Expiration Date:	10/07/1999
Total Capacity of All Active Tanks(gal):	0
Operator:	PHYSICAL PLANT
Emergency Contact:	PHYSICAL PLANT
Emergency Phone:	(315) 464-4230
Owner Name:	SUNY HEALTH SCIENCE CENTER
Owner Address:	750 EAST ADAMS STREET
Owner City,St,Zip:	SYRACUSE, NY 13210
Owner Telephone:	(315) 464-4230
Owner Type:	State Government
Owner Sub Type:	State University of New York
Mail Name:	SUNY HEALTH SCIENCE CENTER
Mail Contact Addr:	750 EAST ADAMS STREET
Mail Contact Addr2:	Not reported
Mail Contact Contact:	GARY W. KITTELL
Mail Contact City,St,Zip:	SYRACUSE, NY 13210
Mail Phone:	(315) 464-4448

Tank Id:	H100
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	0
Install Date:	10/93
Tank Closed:	00/00
Capacity (Gal):	1500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	10/04/1993
Certified Date:	08/07/1997

SUNY UPSTATE (Continued) **U003077876**

Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	3115
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	/ /
Is It There:	False
Delinquent:	False
Date Expired:	10/07/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	07/06/1999

SPILLS:

Name:	SUNY MED UNIVERSITY
Address:	750 EAST ADAMS
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0209530 / 2003-06-01
Facility ID:	0209530
Facility Type:	ER
DER Facility ID:	125125
Site ID:	146952
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	3415
Spill Date:	2002-12-16
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2002-12-16
CID:	252
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2002-12-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-16
Spill Record Last Update:	2003-11-20
Spiller Name:	ROBERT ANDRUS
Spiller Company:	SUNY MED UNIVERSITY

SUNY UPSTATE (Continued) **U003077876**

Spiller Address: 750 EAST ADAMS
Spiller Company: 001
Contact Name: ROBERT ANDRUS
Latitude: 43.0426655
Longitude: -76.1406306
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks: SPILL IS UNDER INVESTIGATION AT THIS TIME. ARRANGEMENTS FOR CLEANUP TO BE MADE.

All Materials:
Site ID: 146952
Operable Unit ID: 860817
Operable Unit: 01
Material ID: 512951
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

Name: SUNY
Address: 750 EAST ADAMS
City,State,Zip: SYRACUSE, NY
Spill Number/Closed Date: 9201660 / 1992-06-01
Facility ID: 9201660
Facility Type: ER
DER Facility ID: 125125
Site ID: 323015
DEC Region: 7
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3415
Spill Date: 1992-05-11
Investigator: HDWARNER
Referred To: Not reported
Reported to Dept: 1992-05-11
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: 1992-05-11
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-06-01
Spill Record Last Update: 1993-03-27
Spiller Name: Not reported
Spiller Company: SUNY HEALTH SCIENCE
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

SUNY UPSTATE (Continued) **U003077876**

Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was HW 06/01/92: SMALL QUANTITY OF TRANSFORMER OIL SPILLED ONTO CONCRETE PAD. MATERIAL CLEANED UP BY SUNY.
Remarks:	TRANSFORMER LEAKING AT PIPING ONTO CONCRETE PAD. OIL CONTAINS LESS THAN 50 PPM PCB.

All Materials:

Site ID:	323015
Operable Unit ID:	965748
Operable Unit:	01
Material ID:	412952
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	UPSTATE MEDICAL UNIVERSITY
Address:	750 EAST ADAMS
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1107526 / 2011-09-15
Facility ID:	1107526
Facility Type:	ER
DER Facility ID:	125125
Site ID:	455228
DEC Region:	7
Spill Cause:	Other
Spill Class:	D4
SWIS:	3415
Spill Date:	2011-09-14
Investigator:	DJLASALL
Referred To:	Not reported
Reported to Dept:	2011-09-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-14
Spill Record Last Update:	2011-09-15
Spiller Name:	ROBERT NOBLE
Spiller Company:	LECHASE CONSTRUCTION
Spiller Address:	750 EAST ADAMS
Spiller Company:	999
Contact Name:	ROBERT NOBLE

SUNY UPSTATE (Continued) **U003077876**

Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	spoke with Mr. Noble. source of spill was old oil lantern buried in ground. Soil and lantern removed to 5 gallon pail. Clean Harbors to handle disposal. NFA
Remarks:	FOUND SOME TYPE OF GREEN OOZE SEEPING OUT WHILE DIGGING TO PUT IN A NEW WATER LINE. UNKNOWN WHAT THE MTERIAL IS OR HOW MUCH IS THERE.

All Materials:

Site ID:	455228
Operable Unit ID:	1205382
Operable Unit:	01
Material ID:	2202228
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SUNY UPSTATE MEDICAL
Address:	750 EAST ADAMS
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1004281 / 2010-08-05
Facility ID:	1004281
Facility Type:	ER
DER Facility ID:	125125
Site ID:	437549
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	3415
Spill Date:	2010-07-16
Investigator:	cxrossi
Referred To:	Not reported
Reported to Dept:	2010-07-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-07-16
Spill Record Last Update:	2010-08-05
Spiller Name:	CLAUDE THAUVETTE
Spiller Company:	SUNY UPSTATE MEDICAL
Spiller Address:	750 EAST ADAMS
Spiller Company:	999
Contact Name:	CLAUDE THAUVETTE
Latitude:	Not reported

SUNY UPSTATE (Continued) **U003077876**

Longitude:	Not reported
DEC Memo:	Small drip from return line of generator. Fitting is not working properly and at time of report contractor is changing out equiptment to stop release. Contaminated soil has been removed and staged on poly and covered. More soil will be removed.
Remarks:	clean up underway

All Materials:

Site ID:	437549
Operable Unit ID:	1188222
Operable Unit:	01
Material ID:	2183136
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	4.00
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYD063053656
Country:	USA
Name:	Suny Health Science Center
Address:	750 EAST ADAMS STREET
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13210-0000
Zip 4:	Not reported
Location Address 1:	750 E ADAMS ST
Location Address 2:	302 CAMPUS ACTIVITIES BLDG
Location City,State,Zip:	SYRACUSE, NY 13210
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Suny Health Science Center
Mailing Contact:	Environ Health & Safety
Mailing Address 1:	750 E ADAMS ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13210
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3154644019

Manifest Data:

Document ID:	NYB2182635
Manifest Status:	Not reported
Trans1 State ID:	LLNJ-0001
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/1990

SUNY UPSTATE (Continued) **U003077876**

Trans1 Recv Date:	03/29/1990
Trans2 Recv Date:	03/30/1990
TSD Site Recv Date:	04/02/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD041767765
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	FLD980711071
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01400
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC7142433
Manifest Status:	Not reported
Trans1 State ID:	MU2534
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	08/15/2003
Trans1 Recv Date:	08/15/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/15/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	TXR000050930

SUNY UPSTATE (Continued) **U003077876**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD982743312
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00010
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC7142635
Manifest Status:	Not reported
Trans1 State ID:	NY64167JC
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	09/15/2003
Trans1 Recv Date:	09/15/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/16/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD982743312
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste

SUNY UPSTATE (Continued) **U003077876**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00006
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	2-Propyn-1-Ol (Or) Propargyl Alcohol
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00040
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Acetyl Chloride (C,R,T)
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported

SUNY UPSTATE (Continued) **U003077876**

Quantity:	00040
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	2,4-Dinitrophenol (Or) Phenol, 2,4-Dinitro-
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00040
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported

SUNY UPSTATE (Continued) **U003077876**

Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Ignitable Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

SUNY UPSTATE (Continued) **U003077876**

Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Osmium Oxide Oso4, (T-4)- (Or) Osmium Tetroxide
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00012

SUNY UPSTATE (Continued) **U003077876**

Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cyanogen Bromide (Cn)Br
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Sodium Cyanide (Or) Sodium Cyanide Na(Cn)
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

SUNY UPSTATE (Continued) **U003077876**

Waste Code 12:	2-Propenal (Or) Acrolein
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Corrosive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

SUNY UPSTATE (Continued) **U003077876**

Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Reactive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported

SUNY UPSTATE (Continued) **U003077876**

Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Dimethyl Sulfate (Or) Sulfuric Acid, Dimethyl Ester
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Benzene, (Chloromethyl)- (Or) Benzyl Chloride
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00040
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	2-Propenamide (Or) Acrylamide
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00200
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Phenol
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00400
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

SUNY UPSTATE (Continued) **U003077876**

Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Selenious Acid (Or) Selenium Dioxide
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	2-Propenamide (Or) Acrylamide
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Silver Cyanide (Or) Silver Cyanide Ag(Cn)
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00005

SUNY UPSTATE (Continued) **U003077876**

Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Mercury
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	ILA7730584
Manifest Status:	Not reported
Trans1 State ID:	3890
Year:	1999
Trans2 State ID:	1513
Generator Ship Date:	04/09/1999
Trans1 Recv Date:	04/09/1999
Trans2 Recv Date:	04/15/1999
TSD Site Recv Date:	04/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063053656
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

SUNY UPSTATE (Continued) **U003077876**

Waste Code 7:	Corrosive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00010
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Corrosive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Reactive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00005
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
1478 additional NY MANIFEST: record(s) in the EDR Site Report.

AB110 **1357 SALINA STREET SOUTH** **US BROWNFIELDS** **1027025371**
SSW **1357 SALINA STREET SOUTH** **FINDS** **N/A**
1/4-1/2 **SYRACUSE, NY 13202**
0.372 mi.
1965 ft. **Site 1 of 2 in cluster AB**

Relative: **Lower**
Actual: **399 ft.**

US BROWNFIELDS:

Name:	1357 Salina Street South
Address:	1357 Salina Street South
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244990
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	085.-05-15.0
Parcel Size:	0.53
Latitude:	43.033768983
Longitude:	-76.148237007
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y

1357 SALINA STREET SOUTH (Continued) **1027025371**

Program Name:	BF
AA Activity Funded:	Phase I Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	2020-09-17 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2021-01-12 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported

1357 SALINA STREET SOUTH (Continued) **1027025371**

RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.53
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2319
Below Poverty Percent:	47.67
Meidan Income:	2749
Meidan Income Number:	3548
Meidan Income Percent:	72.93
Vacant Housing Number:	358
Vacant Housing Percent:	18.68
Unemployed Number:	290
Unemployed Percent:	5.96

Name:	1357 Salina Street South
Address:	1357 Salina Street South
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244990

1357 SALINA STREET SOUTH (Continued) **1027025371**

Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	085.-05-15.0
Parcel Size:	0.53
Latitude:	43.033768983
Longitude:	-76.148237007
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported

1357 SALINA STREET SOUTH (Continued) **1027025371**

Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.53
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2319
Below Poverty Percent:	47.67
Meidan Income:	2749
Meidan Income Number:	3548
Meidan Income Percent:	72.93

1357 SALINA STREET SOUTH (Continued) **1027025371**

Vacant Housing Number:	358
Vacant Housing Percent:	18.68
Unemployed Number:	290
Unemployed Percent:	5.96
Name:	1357 Salina Street South
Address:	1357 Salina Street South
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	244990
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	085.-05-15.0
Parcel Size:	0.53
Latitude:	43.033768983
Longitude:	-76.148237007
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	N
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported

1357 SALINA STREET SOUTH (Continued) **1027025371**

Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	N
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Not reported
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.53
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported

1357 SALINA STREET SOUTH (Continued) **1027025371**

Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2319
Below Poverty Percent:	47.67
Meidan Income:	2749
Meidan Income Number:	3548
Meidan Income Percent:	72.93
Vacant Housing Number:	358
Vacant Housing Percent:	18.68
Unemployed Number:	290
Unemployed Percent:	5.96

FINDS:
Registry ID: 110071090219

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

111 JMA CAMPUS PLAN **NY BROWNFIELDS** **S132119353**
WSW 623 ONEIDA STREET **N/A**
1/4-1/2 SYRACUSE, NY 13202
0.374 mi.
1977 ft.

Relative: Lower
Actual: 390 ft.

BROWNFIELDS:

Name:	JMA CAMPUS PLAN
Address:	623 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY 13202
Program:	BCP
Site Code:	667687
Acres:	6.960
HW Code:	C734166
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	05/15/2024
Record Updated Date:	06/11/2024
Update By:	GWPRISCO
Site Description:	"Location: The JMA Campus Plan (Site) is a 6.96-acre property located in an urban area at 623 Oneida Street, in the City of Syracuse, Onondaga County, New York. The Site limits are bounded by West Taylor Street to the north, the former South Clinton Street to the east, Tallman Street to the south, and Oneida Street to the west. The Site is comprised of what was once 24 separate, contiguous parcels, that were recently re-zoned to form a single parcel. Site Features: The Site features include gravel or paved parking lots, small green space areas, and three vacant buildings. Current Zoning and Land Use: The Site is zoned industrial and consists of the following features: Gravel or paved parking lots, Limited green space areas, and Three

JMA CAMPUS PLAN (Continued) **S132119353**

vacant buildings; Neighboring properties include various commercial and industrial facilities in all directions, with the closest residences located approximately 0.1-miles to the west. Onondaga Creek, a tributary to Onondaga Lake, is located approximately 580-feet to the west of the Site. The site is depicted as Census Block 360670042002 which is classified as Enzone Type AB and is Listed as a disadvantaged community. The Site entire 6.96-acre project Site is within this boundary. Past Use of the Site: The Site has historically primarily been utilized by industrial facilities as far back as the early 1900 s with various occupants including: Syracuse Stamp, a manufacturer of high-quality garage door hardware, gate faucets and inked ribbon spools since 1908. This property is a potential source of contamination given the use of heavy machinery and metals. Underground storage tanks were also previously located on the site. Tompkins USA a manufacturer of knitting machinery and equipment for the textile industry located in Syracuse since 1914. This property is a potential source of contamination given the use of heavy machinery for textiles. Sources of heat likely also included coal burning equipment and fuel oil from bulk storage tanks. Horizon Transport, a junk yard and storage facility. This property is a potential source of contamination given the junk yard/scrap yard uses for many years, the disarray of the facility, and multiple leaking vehicles and drums observed on the property. Coyne Textile Fleet Truck Maintenance Facility. This property is a potential source of chlorinated VOC contamination given the history as a Coyne Textile property. Trucks from the Coyne fleet were often taken to this property for repair, washing, etc. Evidence of contamination was observed during the previous environmental investigations. Site Geology and Hydrogeology: According to the USDA Web Soil Survey for Onondaga County, soils beneath the Site consist of Urban Land. Review of the USGS Geologic Map of New York indicates the bedrock geology of the area consists of the Syracuse Formation of the Upper Silurian age. Generally, the bedrock consists of dolostone and shale. Regional groundwater flow direction, inferred from topographic mapping of the area and historical investigations, is generally west towards Onondaga Creek. "

Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Dino Peios

JMA CAMPUS PLAN (Continued) **S132119353**

Owner Company:	JMA Tech Properties, LLC
Owner Address:	PO Box 580
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13205
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Dino Peios
Owner Company:	JMA Tech Properties, LLC
Owner Address:	PO Box 580
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13205
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Onondaga Public Library Central Branch
Owner Address:	447 South Salina St
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Dino Peios
Owner Company:	JMA Tech Properties, LLC
Owner Address:	PO Box 580
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13205
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AC112 **SPILL NUMBER 9900884** **UST FINDER RELEASE** **1029059726**
SSW **116 EAST CASTLE ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.375 mi.
1979 ft. **Site 1 of 2 in cluster AC**

Relative: UST FINDER RELEASE:
Lower

Actual:
402 ft.

Object ID:	249470
Facility ID:	NY140221
Lust ID:	NY9900884
Name:	SPILL NUMBER 9900884
Address:	116 EAST CASTLE ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1999/04/23 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1855

SPILL NUMBER 9900884 (Continued) **1029059726**

Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1484599999999
Y Coord:	43.03308
Latitude:	43.0330799999999
Longitude:	-76.14846

AC113 **CASTLE REST NURSING HOME** **NY LTANKS** **S104620147**
SSW **116 EAST CASTLE ST** **NY Spills** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.375 mi.
1979 ft. **Site 2 of 2 in cluster AC**

Relative: **Lower**
Actual: **402 ft.**

LTANKS:

Name:	SPILL NUMBER 9900884
Address:	116 EAST CASTLE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9900884 / 2000-03-20
Facility ID:	9900884
Site ID:	166430
Spill Date:	1999-04-23
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1999-04-23
CID:	504
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1999-04-23
Spill Record Last Update:	2002-06-03

CASTLE REST NURSING HOME (Continued) **S104620147**

Spiller Name:	Not reported
Spiller Company:	HOWARD NURSING HM
Spiller Address:	116 EAST CASTLE ST
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	140221
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM BM WENT TO TANK PULL, CM TOOK OVER SITE
Remarks:	PULLED TANK, FOUND CONTAMINATION.

All Materials:

Site ID:	166430
Operable Unit ID:	1075649
Operable Unit:	01
Material ID:	308001
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	CASTLE REST NURSING HOME
Address:	116 EAST CASTLE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9711111 / 1998-01-06
Facility ID:	9711111
Facility Type:	ER
DER Facility ID:	140221
Site ID:	166429
DEC Region:	7
Spill Cause:	Other
Spill Class:	C3
SWIS:	3415
Spill Date:	1998-01-05
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1998-01-05
CID:	351
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

CASTLE REST NURSING HOME (Continued) **S104620147**

Remediation Phase:	0
Date Entered In Computer:	1998-01-05
Spill Record Last Update:	1998-01-05
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	KEVIN KUTZSCHER
Latitude:	43.0330781
Longitude:	-76.1484564
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM 01/05/98 ON SITE: GRIFFEN INDUSDTRIAL SERVICES ON SITE FOR CLEAN UP, OVER FILL LOSS THROUGH VENT PIPE, STAIN ON BRICKWALL AND GRASSY AREA DOWN BELOW, DEBRIS AND SOIL DRUMMED UP AND DISPOSED.
Remarks:	CALLER STATES THAT THE NURSING HOME OVER ORDERED FUEL AND THAT THERE IS NO WAY TO GAUGE THE TANK TO MEASURE THE AMOUNT OF FUEL IN IT

114
West
1/4-1/2
0.383 mi.
2023 ft.

S&F AUTOMOTIVE **NY LTANKS** **S100494064**
420 ONEIDA ST **N/A**
SYRACUSE, NY

Relative:
Lower

Actual:
390 ft.

LTANKS:

Name:	S&F AUTOMOTIVE
Address:	420 ONEIDA ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9207347 / 1992-10-05
Facility ID:	9207347
Site ID:	194355
Spill Date:	1992-09-24
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	D5
Cleanup Ceased:	1992-10-05
SWIS:	3415
Investigator:	MENASH
Referred To:	Not reported
Reported to Dept:	1992-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-25
Spill Record Last Update:	1992-10-05
Spiller Name:	Not reported
Spiller Company:	S & F AUTOMOTIVE
Spiller Address:	420 ONEIDA ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7

S&F AUTOMOTIVE (Continued) **S100494064**

DER Facility ID: 161962
Latitude: Not reported
Longitude: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was MN
10/05/92: NO RESPONSE MADE.
Remarks: VEHICLE LEAKED ONTO PAVEMENT AND OIL SWEEPED INTO STORM SEWER BY S&F PERSONNEL.

All Materials:
Site ID: 194355
Operable Unit ID: 974302
Operable Unit: 01
Material ID: 407985
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

AD115 **CENTRAL BUS CNYRTA MAIN GARAGE** **NY LTANKS** **S121997192**
SW **200 CORTLAND AVE** **NY Spills** **N/A**
1/4-1/2 **SYRACUSE, NY 13202** **NY COOLING TOWERS**
0.384 mi.
2025 ft. **Site 1 of 2 in cluster AD**

Relative:
Lower

Actual:
390 ft.

LTANKS:
Name: CENTRAL NY INC
Address: 200 CORTLAND AVE
City,State,Zip: SYRACUSE, NY
Spill Number/Closed Date: 9213577 / 1995-12-28
Facility ID: 9213577
Site ID: 275090
Spill Date: 1993-03-09
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: E6
Cleanup Ceased: Not reported
SWIS: 3415
Investigator: BFMATTHE
Referred To: Not reported
Reported to Dept: 1993-03-09
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-03-11
Spill Record Last Update: 1995-12-28
Spiller Name: Not reported
Spiller Company: CENTRAL NY INC

CENTRAL BUS CNYRTA MAIN GARAGE (Continued) **S121997192**

Spiller Address: 2OO CORTLAND AVE
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 7
DER Facility ID: 363839
Latitude: Not reported
Longitude: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was BM
03/12/93: MR DAVID RYAN CONTACTED DEC ON3-12-93 AND STATED THAT THE TANK WAS RETESTED AND IT PASSED.
Remarks: TANK TEST FAILURE CLEMENT WILL RETEST

All Materials:
Site ID: 275090
Operable Unit ID: 980879
Operable Unit: 01
Material ID: 403348
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

SPILLS:
Name: CENTRAL BUS CNYRTA MAIN GARAGE
Address: 200 CORTLAND AVE
City,State,Zip: SYRACUSE, NY 13202
Spill Number/Closed Date: 2106666 / 2022-01-14
Facility ID: 2106666
Facility Type: ER
DER Facility ID: 353019
Site ID: 625565
DEC Region: 7
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3415
Spill Date: 2021-10-15
Investigator: CFNORRIS
Referred To: Not reported
Reported to Dept: 2021-10-15
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 2021-10-15
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

CENTRAL BUS CNYRTA MAIN GARAGE (Continued) **S121997192**

Date Entered In Computer:	2021-10-15
Spill Record Last Update:	2022-01-14
Spiller Name:	NATHAN DOW
Spiller Company:	CENTRAL BUS CNYRTA
Spiller Address:	200 CORTLAND AVE
Spiller Company:	999
Contact Name:	NATHAN DOW
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	RP WILL MANAGE EXCAVATION AND SAMPLING. SEVERAL SPILL AREAS IN SOIL OFF TARVIA AT GARAGE.
Remarks:	No drains impacted. 10-15 Gallons lost, c/u pending

All Materials:

Site ID:	625565
Operable Unit ID:	1372706
Operable Unit:	01
Material ID:	2386052
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CENTRO OF SYRACUSE
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2107306 / 2021-11-08
Facility ID:	2107306
Facility Type:	ER
DER Facility ID:	363839
Site ID:	628220
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3415
Spill Date:	2021-11-08
Investigator:	DJLASALL
Referred To:	Not reported
Reported to Dept:	2021-11-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-11-08
Spill Record Last Update:	2021-11-08
Spiller Name:	Not reported

CENTRAL BUS CNYRTA MAIN GARAGE (Continued) **S121997192**

Spiller Company:	CENTRO OF SYRACUSE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	NATHAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	spill cleaned up by Centro. NFA
Remarks:	cleanup in progress

All Materials:

Site ID:	628220
Operable Unit ID:	1375346
Operable Unit:	01
Material ID:	2388804
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Impervious Surface
Oxygenate:	Not reported

Name:	COMMERCIAL/INDUSTRIAL
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2306995 / 2023-11-22
Facility ID:	2306995
Facility Type:	ER
DER Facility ID:	363839
Site ID:	659026
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3415
Spill Date:	2023-11-20
Investigator:	DJLASALL
Referred To:	Not reported
Reported to Dept:	2023-11-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2023-11-20
Spill Record Last Update:	2023-11-22
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	200 CORTLAND AVE
Spiller Company:	999
Contact Name:	CLAIRE DEL SATTI

CENTRAL BUS CNYRTA MAIN GARAGE (Continued) **S121997192**

Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Petroleum contaminated soil encountered during excavation for utility conduit. PID readings of around 80 ppm noted. Approximately one yard or less of impacted soil segregated for sampling and disposal. Advised caller to treat any further impacted soil encountered within the excavation area in the same manner. NFA
Remarks:	Petroleum contamination, cleanup pending

All Materials:

Site ID:	659026
Operable Unit ID:	1405877
Operable Unit:	01
Material ID:	2423200
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

COOLING TOWERS:

Name:	Not reported
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY 13202
Equipment Unique ID:	7749
Equipment Borough:	Not reported
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	VF1-036-21L/X
Cooling Capacity:	85
Cooling Capacity Unit:	Tonnage
Commissioned Date:	08/10/2001
Inspection Date:	05/04/2022
Date of Bacteriological Collection:	06/06/2022
Date of Legionella Collection:	10/02/2024
Last Legionella Result > 1,000 CFU/mL:	lt20
Last Sampled Days:	Not reported
Reg Compliant:	Not reported
Last Update Days:	Not reported
CT Status:	Not reported
Equipment Tower Operation Duration:	Not reported
Latitude:	43.036343
Longitude:	-76.150772

AD116 **CNY CENTRO INC** **NY LTANKS** **S103570665**
SW **200 CORTLAND AVE** **NY CBS** **N/A**
1/4-1/2 **SYRACUSE, NY 13205** **NY Spills**
0.384 mi. **NY AIRS**
2025 ft. **Site 2 of 2 in cluster AD**

Relative:
Lower

Actual:
390 ft.

LTANKS:

Name:	CNY CENTRO INC.
Address:	200 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9413883 / 2002-08-06
Facility ID:	9413883
Site ID:	230780
Spill Date:	1995-01-18
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1995-01-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-08
Spill Record Last Update:	2002-08-06
Spiller Name:	Not reported
Spiller Company:	CNY CENTRO INC.
Spiller Address:	200 CORTLAND AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	190176
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM NO REPORT SUBMITTED
Remarks:	TANK TEST FAILURE.

All Materials:

Site ID:	230780
Operable Unit ID:	1011411
Operable Unit:	01
Material ID:	372631
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil

CNY CENTRO INC (Continued) **S103570665**

Oxygenate: Not reported

Name: CNY CENTRO, INC.
Address: 200 CORTLAND AVENUE
City,State,Zip: SYRACUSE, NY
Spill Number/Closed Date: 9508450 / 1995-10-11
Facility ID: 9508450
Site ID: 230781
Spill Date: 1995-10-11
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: D5
Cleanup Ceased: 1995-12-31
SWIS: 3415
Investigator: CFMANNES
Referred To: Not reported
Reported to Dept: 1995-10-11
CID: 266
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1995-10-11
Spill Record Last Update: 1996-01-02
Spiller Name: DAVID RYAN
Spiller Company: CNY CENTRO, INC.
Spiller Address: 200 CORTLAND AVENUE
Spiller County: 001
Spiller Contact: DAVID RYAN
Spiller Phone: (315) 442-3325
Spiller Extention: Not reported
DEC Region: 7
DER Facility ID: 190176
Latitude: Not reported
Longitude: Not reported
DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks: OVERFLOW FROM VENT DURING FILLING. ONTO SOIL. HOWARD FROM SYRACUSE OFFICE NOTIFIED. SOIL TO BE CLEANED UP.

All Materials:
Site ID: 230781
Operable Unit ID: 1022909
Operable Unit: 01
Material ID: 362970
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

CNY CENTRO INC (Continued) **S103570665**

Site ID:	230781
Operable Unit ID:	1022909
Operable Unit:	01
Material ID:	362971
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Resource Affected:	Soil
Oxygenate:	Not reported

CBS:

Name:	CNY CENTRO INC.
Address:	200 CORTLAND AVE.
City,State,Zip:	SYRACUSE, NY 13205
CBS Number:	7-000172
Program Type:	CBS
Facility Status:	Active
Expiration Date:	08/11/2026
Dec Region:	7
UTMX:	406071.56450
UTMY:	4765375.47900

SPILLS:

Name:	SYRACUSE CENTRO BUS
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0911732 / 2010-06-25
Facility ID:	0911732
Facility Type:	ER
DER Facility ID:	363839
Site ID:	424569
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3415
Spill Date:	2010-02-03
Investigator:	MJROMOCK
Referred To:	Not reported
Reported to Dept:	2010-02-03
CID:	Not reported
Water Affected:	N/A
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-03
Spill Record Last Update:	2011-03-28

CNY CENTRO INC (Continued) **S103570665**

Spiller Name:	STEVE PROSONIC
Spiller Company:	SYRACUSE CENTRO BUS
Spiller Address:	200 CORTLAND AVE
Spiller Company:	999
Contact Name:	STEVE PROSONIC
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	3/3/10 - Called CENTRO bus garage. Vehicle Lift in garage is leaking. The lift has been taken out of service. Repairs and cleanup to be effected in near future. CENTRO to call NYSDEC when work will be done. 03/25/2010 - Inspected site. Met with Dave Ryan of CENTRO Bus. leaking hydrualic system has been removed. Underground pipe has been excavted and soil samples collected from spill area after cleanup. Photos were taken. Closure report to be submitted by CENTRO. 6/22/10 - Rec'd closure documents. Closing file. 3/28/11 - Call from CENTRO garage. Excavation of this spill site underway. Exvation report to be submitted to NYSDEC.
Remarks:	DUE TO A BROKEN HYDRAULIC FLUID LINE ABOUT 12 GALLONS SPILLED TO SOIL. CLEAN UP PENDING.

All Materials:

Site ID:	424569
Operable Unit ID:	1180334
Operable Unit:	01
Material ID:	2174215
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	12.00
Units:	G
Recovered:	12.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CENTRAL NY TRANSPORT AUTH
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1901686 / 2019-05-20
Facility ID:	1901686
Facility Type:	ER
DER Facility ID:	363839
Site ID:	588580
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	2019-05-17
Investigator:	CXROSSI
Referred To:	Not reported
Reported to Dept:	2019-05-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle

CNY CENTRO INC (Continued) **S103570665**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2019-05-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-05-17
Spill Record Last Update:	2019-05-20
Spiller Name:	NATHAN DOW
Spiller Company:	CENTRAL NY TRANSPORT AUTH
Spiller Address:	200 CORTLAND AVE
Spiller Company:	999
Contact Name:	NATHAN DOW
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	loss to sewer and soil- c/u pending vac truck

All Materials:

Site ID:	588580
Operable Unit ID:	1336238
Operable Unit:	01
Material ID:	2345579
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil, Sewer
Oxygenate:	Not reported

Name:	PAVEMENT AND SOIL
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1904009 / 2019-08-01
Facility ID:	1904009
Facility Type:	ER
DER Facility ID:	363839
Site ID:	591988
DEC Region:	7
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	3415
Spill Date:	2019-07-19
Investigator:	CFNORRIS
Referred To:	Not reported
Reported to Dept:	2019-07-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

CNY CENTRO INC (Continued) **S103570665**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2019-07-19
Spill Record Last Update:	2019-08-01
Spiller Name:	NATHAN DOW
Spiller Company:	CNYRTA
Spiller Address:	200 CORTLAND AVE
Spiller Company:	999
Contact Name:	NATHAN DOW
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	HYDRAULIC OIL SPILL TO PAVEMENT. NO SOIL OR DRAINS AFFECTED. EPS TO COLLECT SPEEDI-DRI
Remarks:	clean up has started

All Materials:

Site ID:	591988
Operable Unit ID:	1339598
Operable Unit:	01
Material ID:	2349194
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Resource Affected:	Impervious Surface
Oxygenate:	Not reported

Name:	GARAGE
Address:	200 CORTLAND AVE.
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0910008 / 2010-06-25
Facility ID:	0910008
Facility Type:	ER
DER Facility ID:	371679
Site ID:	422746
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3415
Spill Date:	2009-12-09
Investigator:	MJROMOCK
Referred To:	Not reported
Reported to Dept:	2009-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

CNY CENTRO INC (Continued) **S103570665**

Date Entered In Computer:	2009-12-09
Spill Record Last Update:	2010-06-25
Spiller Name:	STEVE PROSONIC
Spiller Company:	CNY CENTRO
Spiller Address:	200 CORTLAND AVE.
Spiller Company:	999
Contact Name:	STEVE PROSONIC
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Lift removed from service . To be excavted and remediated in near future. 6/22/10 Rec'd closure documentation. Closing file.
Remarks:	UNDERGROUND HYDRAULIC LINE FAILURE, SPILL AMOUNT UNKNOWN AT THIS TIME, LEAKED MAINLY INTO GRAVEL UNDER BUILDING, CLEANUP PENDING FURTHER INVESTIGATION.

All Materials:

Site ID:	422746
Operable Unit ID:	1178574
Operable Unit:	01
Material ID:	2172031
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CNY BUS GARAGE
Address:	200 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0500747 / 2005-06-02
Facility ID:	0500747
Facility Type:	ER
DER Facility ID:	190176
Site ID:	343801
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	3415
Spill Date:	2005-04-15
Investigator:	MENASH
Referred To:	Not reported
Reported to Dept:	2005-04-18
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

CNY CENTRO INC (Continued) **S103570665**

Date Entered In Computer:	2005-04-18
Spill Record Last Update:	2005-06-02
Spiller Name:	RAYMOND CROSSLEY
Spiller Company:	CNY BUS GARAGE
Spiller Address:	200 CORTLAND AVE
Spiller Company:	001
Contact Name:	RAYMOND CROSSLEY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	LINES TO LIFTS ROTTED OUT: WILL START WORKING ON TOMORROW, TO LOCATE PROBLEM:

All Materials:

Site ID:	343801
Operable Unit ID:	1102480
Operable Unit:	01
Material ID:	582699
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	72.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CENTRAL BUS
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0902638 / 2009-06-08
Facility ID:	0902638
Facility Type:	ER
DER Facility ID:	363839
Site ID:	414692
DEC Region:	7
Spill Cause:	Other
Spill Class:	C3
SWIS:	3415
Spill Date:	2009-06-03
Investigator:	MJROMOCK
Referred To:	Not reported
Reported to Dept:	2009-06-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-04
Spill Record Last Update:	2009-06-08
Spiller Name:	STEVE PROSONIC

CNY CENTRO INC (Continued) **S103570665**

Spiller Company:	CNYRTA GARAGE
Spiller Address:	200 CORTLAND AVE
Spiller Company:	999
Contact Name:	STEVE PROSONIC
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	06/04/09 -Inspected site. Solvent spilled when a parts cleaner cabinet that had been disposed of in a dumpster tipped over. Some solvent had been inadvertenly left in the cabinet and leaked out. Spill fell to the ground and paved area near the dumpster. Some blacktop was picked up along with some contaminated soil. Environmental Products and Services is scheduled to pick up the excavated material for disposal. 06/08/09 - Excavated material picked up from Centro Garage. Material was picked up by Environmental Products and Services. Rec'd copy of Dispoal documents. Closing file.
Remarks:	CALLER STATES THAT THE PRODUCT WAS IN A DUMPSTER AND WHEN THE DUMPSTER WAS PICKED UP THE PRODUCT SPILLED TO SOIL AND PAVEMENT. CLEAN UP IS IN PROGRESS, SPILL IS CONTAINED.

All Materials:

Site ID:	414692
Operable Unit ID:	1171074
Operable Unit:	01
Material ID:	2162861
Material Code:	0014A
Material Name:	mineral/white spirits
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	8.00
Resource Affected:	Soil, Impervious Surface
Oxygenate:	Not reported

Name:	REPAIR BAYS 18 & 19
Address:	200 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0700048 / 2008-02-01
Facility ID:	0700048
Facility Type:	ER
DER Facility ID:	190176
Site ID:	379293
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D3
SWIS:	3415
Spill Date:	2007-04-02
Investigator:	kacahill
Referred To:	Not reported
Reported to Dept:	2007-04-02
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party

CNY CENTRO INC (Continued) **S103570665**

Cleanup Ceased:	2007-07-27
Cleanup Meets Std:	False
Last Inspection:	2007-05-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-04-02
Spill Record Last Update:	2008-02-01
Spiller Name:	DAVID RYAN
Spiller Company:	REPAIR BAYS 18 & 19
Spiller Address:	200 CORTLAND AVE
Spiller Company:	001
Contact Name:	DAVID RYAN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Spoke to David Ryan. Source of spill is a leak in seals in hydraulic lift. Preventative maintenance conducted on 3/20 and 3/23 on this lift and seals were in tact at that time. On 3/30/07, they noticed that oil was down 40 gallons. They called in their contractor, Filtrec, and they tested the system today. They fixed the seals but the system is still leaking under the slab. They have hired C&S to retrofit all of the lifts. Onondaga Creek is about 500 feet from this facility. I indicated to Dave that he would need to collect confirmation samples and run for STARS and PCBs. He said he would call me once work is scheduled, estimated for next week. 4/12/07 Contacted Dave to get an update on the work. Since work will cost in excess of $15,000, it has to be approved by the board. The next board meeting is not until end of the month. 04/27/07 Spoke to Dave. The board approved the proposal. Work scheduled to beging week of May 7th. 05/17/07 Filtrec removed slab and pipe runs from oil pump to lift. Source of spill determined to be leak in one of the pipes. DEC inspected floor and piping. Filtrec will remove affected subgrade material, and new pump and piping will be installed. Centro plans to retrofit all lifts this year. Asked Dave Ryan for copy of the confirmation sampling analytical results and soil disposal receipts. 01/08/08 Contacted Dave Ryan to request confirmation sample results and disposal receipts so spill can be closed. 02/01/08 Received analytical results and disposal receipts. Closed spill.
Remarks:	NOT YET CLEANED; HAD SIMILAR LEAK IN JUNE OF 05’;

All Materials:

Site ID:	379293
Operable Unit ID:	1136783
Operable Unit:	01
Material ID:	2126736
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00

CNY CENTRO INC (Continued) **S103570665**

Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	200 CORTLAND AVE
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1214613 / 2013-01-15
Facility ID:	1214613
Facility Type:	ER
DER Facility ID:	433182
Site ID:	477861
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3415
Spill Date:	2013-01-15
Investigator:	cxrossi
Referred To:	Not reported
Reported to Dept:	2013-01-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-01-15
Spill Record Last Update:	2013-01-15
Spiller Name:	Not reported
Spiller Company:	PERSONAL VEHICLE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	STEVE PROSONIC
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	15 qts - speedi dri in use

All Materials:

Site ID:	477861
Operable Unit ID:	1227659
Operable Unit:	01
Material ID:	2225102
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Resource Affected:	Impervious Surface
Oxygenate:	Not reported

CNY CENTRO INC (Continued) **S103570665**

Name:	CENTRO
Address:	200 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0107608 / 2003-10-07
Facility ID:	0107608
Facility Type:	ER
DER Facility ID:	190176
Site ID:	299297
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	2001-10-22
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2001-10-25
CID:	257
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-10-25
Spill Record Last Update:	2003-10-07
Spiller Name:	BOB PALLADINE
Spiller Company:	CENTRO
Spiller Address:	200 CORTLAND AVE
Spiller Company:	001
Contact Name:	BOB PALLADINE
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	leaking lift

All Materials:

Site ID:	299297
Operable Unit ID:	845718
Operable Unit:	01
Material ID:	532426
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CENTRO GARAGE-CORTLAND AV
Address:	200 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9301095 / 1993-04-23

CNY CENTRO INC (Continued) **S103570665**

Facility ID:	9301095
Facility Type:	ER
DER Facility ID:	190176
Site ID:	299298
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D5
SWIS:	3415
Spill Date:	1993-04-22
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1993-04-22
CID:	Not reported
Water Affected:	ONON.CREEK
Spill Source:	Commercial Vehicle
Spill Notifier:	DEC
Cleanup Ceased:	1993-04-23
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SYRACUSE LADDER AND SCFFO
Spiller Address:	621 HIAWATHA BLVD. WEST
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR
Remarks:	HYRAULIC LINE RUPTURED ON DELIVERY TRUCK IN CENTRO PARKING LOT. SPILL WAS NOT PROPERLY REPORTED NOR CLEANED UP.

All Materials:

Site ID:	299298
Operable Unit ID:	979699
Operable Unit:	01
Material ID:	401825
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Surface Water
Oxygenate:	Not reported

Name:	REGION TRANSIT AUTHORITY
Address:	200 CORTLAND AVENUE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9702247 / 2002-08-06
Facility ID:	9702247
Facility Type:	ER
DER Facility ID:	190176

CNY CENTRO INC (Continued) **S103570665**

Site ID:	299299
DEC Region:	7
Spill Cause:	Other
Spill Class:	C3
SWIS:	3415
Spill Date:	1997-05-21
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1997-05-21
CID:	370
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-21
Spill Record Last Update:	2002-08-06
Spiller Name:	ABOVE
Spiller Company:	REGION TRANSIT AUTHORITY
Spiller Address:	200 CORTLAND AVE
Spiller Company:	001
Contact Name:	ABOVE
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	REMOVING 5 TANKS SPILL FROM 4TH TANK 20 GALS SPILL TO GROUND AND MINIMAL TO GROUNDWATER ON SITE SPILL CONTAINED AND CLEANED

Click this hyperlink while viewing on your computer to access
2 additional NY SPILL: record(s) in the EDR Site Report.

AIRS:

Name:	CNY CENTRO INC
Address:	200 CORTLAND AVE
City,State,Zip:	SYRACUSE, NY 13205
DECID:	7311500050
Process ID:	Not reported
Latitude:	Not reported
Longitude:	Not reported
FIPS Code:	Not reported
Auth Type Code:	AFR
Permit Status:	Issued
Auth Status Code:	2
Emissions:	Not reported
Issue date:	07/31/2015
Expired Date:	07/31/2025
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

CNY CENTRO INC (Continued) **S103570665**

Permit Status:	Expired
Auth Status Code:	7
Emissions:	Not reported
Issue date:	11/29/2012
Expired Date:	07/31/2015
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

Permit Status:	Expired
Auth Status Code:	7
Emissions:	Not reported
Issue date:	06/02/1999
Expired Date:	11/29/2012
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

AA117 **CLARK HALL; CROUSE IRVIN.** **NY LTANKS** **S100129395**
NE **ELIZABETH BLACKWELL ST** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.384 mi.
2026 ft. **Site 2 of 2 in cluster AA**

Relative: **Higher**

Actual: **419 ft.**

LTANKS:

Name:	CLARK HALL; CROUSE IRVIN.
Address:	ELIZABETH BLACKWELL ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8709940 / 1988-04-12
Facility ID:	8709940
Site ID:	114725
Spill Date:	1988-02-18
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1988-04-12
SWIS:	3415
Investigator:	CSCUIPLY
Referred To:	Not reported
Reported to Dept:	1988-02-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-03-07
Spill Record Last Update:	1988-05-12
Spiller Name:	Not reported
Spiller Company:	CROUSE IRVING HOSPITAL
Spiller Address:	IRVING AVE.
Spiller County:	001

CLARK HALL; CROUSE IRVIN. (Continued) **S100129395**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	100049
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CC 02/22/88: TANKS PULLED ON 02/19/88. EXPLOSIVE VAPORS PERSIST. 04/12/88: TANKS: CONTAMINATED SOIL REMOVED. DISCHARGE INTO STORM SEWER SUBSIDED.
Remarks:	FAILURE RATE +.279 GPH

All Materials:

Site ID:	114725
Operable Unit ID:	914871
Operable Unit:	01
Material ID:	461729
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AE118 **MARATHON WATER SUPPLY** **NY LTANKS** **S100153235**
NNW **MARATHON SCHOOL BUS GARAG** **N/A**
1/4-1/2 **MARATHON, NY**
0.389 mi.
2054 ft. **Site 1 of 2 in cluster AE**

Relative:
Lower

Actual:
397 ft.

LTANKS:

Name:	MARATHON WATER SUPPLY
Address:	MARATHON SCHOOL BUS GARAG
City,State,Zip:	MARATHON, NY
Spill Number/Closed Date:	9104876 / 1996-04-22
Facility ID:	9104876
Site ID:	64963
Spill Date:	1991-07-09
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	1234
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1991-08-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True

MARATHON WATER SUPPLY (Continued) **S100153235**

Remediation Phase:	0
Date Entered In Computer:	1991-08-06
Spill Record Last Update:	1996-05-31
Spiller Name:	Not reported
Spiller Company:	MARATHON CENTRAL SCHOOL
Spiller Address:	MAIN ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	62505
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR 08/06/91: VISITED SITE W/D.VOLLMER. VERBAL NOTIFICATION TO SCHOOL SUPER LARRY HAYES THAT GROUNDWATER STUDY IS LIKELY. 08/30/91: WELLS INSTALLED AND SAMPLED AT SITE. CONTAMINATED SOIL BEING EXCAVATED AND STAGED ON SITE IN ATTEMPT TO MINIMIZE FURTHER MIGRATION OF EXISTING PLUME. 11/12/91: SAMPLE ANALYSIS FROM MONITORING WELLS INSTALLED.NEARLY ALL WELLS FREE OF CONTAMINATION. 02/12/92: SCHOOL DISTRICT HAS TAKEN OVER CLEANUP AND MONITORING. NO FURTHER STATE FUNDS TO BE EXPENDED. 04/22/96 REC'D LETTER FROM VILLAGE STATINGTHAT THE BACKUP WELL IS NO LONGER BEING USED AS PART OF VILLAGE WATER SYSTEM.
Remarks:	PUBLIC WELL CONTAMINATED WITH LOW LEVEL OF BTX.

All Materials:

Site ID:	64963
Operable Unit ID:	958928
Operable Unit:	01
Material ID:	423930
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	25.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AF119 **BYRNE DAIRY** **NY LTANKS** **S105998214**
West **KING ST** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.390 mi.
2057 ft. **Site 1 of 2 in cluster AF**

Relative: **Lower**
Actual: **390 ft.**

LTANKS:

Name:	BYRNE DAIRY
Address:	KING ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0211606 / 2003-07-30
Facility ID:	0211606
Site ID:	109545
Spill Date:	2003-02-22
Spill Cause:	Tank Overfill

BYRNE DAIRY (Continued) **S105998214**

Spill Source:	Commercial/Industrial
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2003-02-22
CID:	396
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-22
Spill Record Last Update:	2003-07-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	TIM DEREAMER
Spiller Phone:	(716) 727-4523
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	96112
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	tank overflow due to having the wrong trank size info.

All Materials:

Site ID:	109545
Operable Unit ID:	862693
Operable Unit:	01
Material ID:	511393
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Resource Affected:	Soil
Oxygenate:	Not reported

AF120 **BYRNE DAIRY** **NY LTANKS** **S100128532**
West **235 KING STREET** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.394 mi.
2082 ft. **Site 2 of 2 in cluster AF**

Relative: LTANKS:
Lower

Name:	BYRNE DAIRY
Address:	235 KING STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8603904 / 1988-01-15

Actual:
390 ft.

BYRNE DAIRY (Continued) **S100128532**

Facility ID:	8603904
Site ID:	198191
Spill Date:	1986-09-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-01-15
SWIS:	3415
Investigator:	VOLLMER
Referred To:	Not reported
Reported to Dept:	1986-09-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-09-17
Spill Record Last Update:	1988-01-15
Spiller Name:	Not reported
Spiller Company:	BYRNE DAIRY
Spiller Address:	235 KING ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	164948
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JR / / : CLEMETT CO. IS TANK TESTER COMPANY.
Remarks:	TANK TESTED OUT OF TOLERANCE -.657 PER HOUR

All Materials:

Site ID:	198191
Operable Unit ID:	901148
Operable Unit:	01
Material ID:	476717
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

121
NNW
1/4-1/2
0.397 mi.
2098 ft.

HARRISON CONVENTION CTR
HARRISON & MONTGOMERY
SYRACUSE, NY 0

UST FINDER RELEASE **1029058859**
N/A

Relative:
Lower

Actual:
394 ft.

UST FINDER RELEASE:

Object ID:	249469
Facility ID:	NY129785
Lust ID:	NY9010462
Name:	HARRISON CONVENTION CTR
Address:	HARRISON & MONTGOMERY
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1990/12/28 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1746
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.14884
Y Coord:	43.04427
Latitude:	43.0442699999999
Longitude:	-76.14884

AB122
SSW
1/4-1/2
0.412 mi.
2175 ft.

1400-20 SALINA STREET SOUTH
1400-20 SALINA STREET SOUTH
SYRACUSE, NY 13205

Site 2 of 2 in cluster AB

US BROWNFIELDS FINDS **1027142012**
N/A

Relative:
Lower

Actual:
401 ft.

US BROWNFIELDS:

Name:	1400-20 Salina Street South
Address:	1400-20 Salina Street South
City,State,Zip:	SYRACUSE, NY 13205
Property ID:	244991
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	085.-13-14.0
Parcel Size:	0.65

1400-20 SALINA STREET SOUTH (Continued) **1027142012**

Latitude:	43.032959779
Longitude:	-76.148897602
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported

1400-20 SALINA STREET SOUTH (Continued) **1027142012**

ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Building Materials Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	0.65
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2623
Below Poverty Percent:	48.98
Meidan Income:	2521
Meidan Income Number:	3969
Meidan Income Percent:	74.12
Vacant Housing Number:	435
Vacant Housing Percent:	21.17
Unemployed Number:	281
Unemployed Percent:	5.25

1400-20 SALINA STREET SOUTH (Continued) **1027142012**

Name:	1400-20 Salina Street South
Address:	1400-20 Salina Street South
City,State,Zip:	SYRACUSE, NY 13205
Property ID:	244991
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Hazardous
Property Number:	085.-13-14.0
Parcel Size:	0.65
Latitude:	43.032959779
Longitude:	-76.148897602
Census Tract:	36067005300
State or Tribal Voluntary Response Program:	Y
Program Name:	BF
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Not reported
Contaminants Found at Actionable Level:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96255719
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	N
Institutional Controls Required:	U
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	U
State/tribal program ID:	Not reported

1400-20 SALINA STREET SOUTH (Continued) **1027142012**

Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Building Materials Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	0.65
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2623

1400-20 SALINA STREET SOUTH (Continued) **1027142012**

Below Poverty Percent:	48.98
Meidan Income:	2521
Meidan Income Number:	3969
Meidan Income Percent:	74.12
Vacant Housing Number:	435
Vacant Housing Percent:	21.17
Unemployed Number:	281
Unemployed Percent:	5.25

FINDS:
Registry ID: 110071198606

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on Brownfields properties assessed or cleaned up with grant funding, as well as information on Targeted Brownfields Assessments (TBA) performed by EPA Regions.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AE123 **SPILL NUMBER 8601815** **NY LTANKS** **S104619136**
North **600 S. STATE ST @ CIVIC CTR.** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.427 mi.
2257 ft. **Site 2 of 2 in cluster AE**

Relative:
Lower

Actual:
397 ft.

LTANKS:

Name:	SPILL NUMBER 8601815
Address:	600 S. STATE ST @ CIVIC CTR.
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8601815 / 1988-01-15
Facility ID:	8601815
Site ID:	137258
Spill Date:	1986-06-16
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1988-01-15
SWIS:	3415
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1986-06-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1986-07-09
Spill Record Last Update:	1995-01-03
Spiller Name:	Not reported
Spiller Company:	SEARS OIL
Spiller Address:	Not reported

SPILL NUMBER 8601815 (Continued) **S104619136**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	117430
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was UK
Remarks:	SPILLER TO CLEANUP

All Materials:

Site ID:	137258
Operable Unit ID:	899258
Operable Unit:	01
Material ID:	559760
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

124
WNW
1/4-1/2
0.436 mi.
2304 ft.

Relative:
Lower

Actual:
390 ft.

BYRNE DAIRY INC.
240 ONEIDA STREET
SYRACUSE, NY 13202

NY LTANKS **U003313193**
NY UST **N/A**
NY CBS
NY AST
NY Spills
NY SPDES

LTANKS:

Name:	BYRNE DAIRY
Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9804457 / 2000-11-08
Facility ID:	9804457
Site ID:	64142
Spill Date:	1998-07-09
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	HDWARNER
Referred To:	Not reported
Reported to Dept:	1998-07-09
CID:	204
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

BYRNE DAIRY INC. (Continued) **U003313193**

Date Entered In Computer:	1998-07-09
Spill Record Last Update:	2000-11-08
Spiller Name:	JOHN MCNANARA
Spiller Company:	BYRNE DAIRY
Spiller Address:	240 ONIEDA STREET
Spiller County:	001
Spiller Contact:	JOHN HERMAN
Spiller Phone:	(315) 697-8437
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	142067
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was HW
Remarks:	CONTAMINATION FOUND IN SPILL AREA

Name:	BYRNE DAIRY
Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9703387 / 1997-06-30
Facility ID:	9703387
Site ID:	109079
Spill Date:	1997-06-11
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1997-06-11
CID:	999
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-06-18
Spill Record Last Update:	1997-06-18
Spiller Name:	RON STODDARD
Spiller Company:	BYRNE DAIRY
Spiller Address:	240 ONEIDA ST
Spiller County:	001
Spiller Contact:	RON STODDARD
Spiller Phone:	(315) 475-2111
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	142067
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	DURING EXCAVATION FOR ADDITION TO FACTORY UNCOVERED LIMITED AMOUNT OF CONTAMINAED SOIL FROM TANK REMOVAL - OLD SPILL NO. 87-8332 .O5 YRD

Name:	BYRNE DAIRY

BYRNE DAIRY INC. (Continued) **U003313193**

Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8708332 / 1988-02-04
Facility ID:	8708332
Site ID:	168673
Spill Date:	1987-12-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-02-04
SWIS:	3415
Investigator:	AJMARSCH
Referred To:	Not reported
Reported to Dept:	1987-12-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-05
Spill Record Last Update:	1988-02-08
Spiller Name:	Not reported
Spiller Company:	BYRNE DAIRY
Spiller Address:	NEIL MCLAIN
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	142067
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JM / / : TANKS WERE ABANDONED AND FILLED IN PLACE ON 01/07/88. NO CONTAMINATION FOUND. TANKS WERE MANIFOLDED TOGETHER.
Remarks:	TWO 3,000 GAL. TANKS MANIFOLDED TOGETHER. FAILURE RATE UNKNOWN.

All Materials:

Site ID:	168673
Operable Unit ID:	912967
Operable Unit:	01
Material ID:	463723
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

UST:

BYRNE DAIRY INC. (Continued) **U003313193**

Name:	BYRNE DAIRY INC.
Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY 13202
Id/Status:	7-162175 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	7
Expiration Date:	N/A
UTM X:	405992.32117
UTM Y:	4766113.61803
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	44909
Affiliation Type:	Facility Owner
Company Name:	BYRNE DAIRY INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	240 ONEIDA ST.
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 475-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	44909
Affiliation Type:	Mail Contact
Company Name:	BYRNE DAIRY INC.
Contact Type:	Not reported
Contact Name:	JOHN MCNAMARA
Address1:	240 ONEIDA ST.
Address2:	Not reported
City:	SYRACUSE
State:	NY
Zip Code:	13202
Country Code:	001
Phone:	(315) 475-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	44909
Affiliation Type:	Facility Operator
Company Name:	BYRNE DAIRY INC.
Contact Type:	Not reported
Contact Name:	BYRNE DAIRY INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

BYRNE DAIRY INC. (Continued) **U003313193**

Phone:	(315) 475-2111
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	44909
Affiliation Type:	Emergency Contact
Company Name:	BYRNE DAIRY INC.
Contact Type:	Not reported
Contact Name:	JOHN MCNAMARA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(315) 475-2121
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	129206
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

BYRNE DAIRY INC. (Continued) **U003313193**

Tank Number: 002
Tank ID: 129207
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 10000
Install Date: 05/01/1974
Date Tank Closed: 07/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 03
Date Test: 11/01/1996
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 003
Tank ID: 129208
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

BYRNE DAIRY INC. (Continued) **U003313193**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 004
Tank ID: 129209
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 3000
Install Date: Not reported
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

CBS:

Name: BYRNE DAIRY
Address: 240 ONEIDA STREET
City,State,Zip: SYRACUSE, NY 13202
CBS Number: 7-000339
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 7
UTMX: 406024.08117
UTMY: 4766063.70714

Name: UPSTATE FARMS DAIRY, LLC
Address: 240 ONEIDA ST
City,State,Zip: SYRACUSE, NY 13202
CBS Number: 7-000299
Program Type: CBS
Facility Status: Active
Expiration Date: 11/29/2025
Dec Region: 7

BYRNE DAIRY INC. (Continued) **U003313193**

UTMX: 405992.32117
UTMY: 4766113.61803

AST:
Name: BYRNE DAIRY
Address: 240 ONEIDA STREET
City,State,Zip: SYRACUSE, NY 13202
Region: STATE
DEC Region: 7
Site Status: Unregulated/Closed
Facility Id: 7-000339
Program Type: CBS
UTM X: 406024.08117
UTM Y: 4766063.70714
Expiration Date: N/A
Site Type: Manufacturing (Other than Chemical)/Processing

Tank Info:

Tank Number: 54-1050-1
Tank Id: 195202
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Plastic
Tank Status: Administratively Closed
Pipe Model: Not reported
Install Date: 11/01/2003
Capacity Gallons: 685
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/02/2015
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

SPILLS:
Name: BYRNE DAIRY
Address: 240 ONEIDA ST
City,State,Zip: SYRACUSE, NY 13202
Spill Number/Closed Date: 1308782 / 2014-01-07
Facility ID: 1308782
Facility Type: ER
DER Facility ID: 360242
Site ID: 489538
DEC Region: 7
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 3415
Spill Date: 2013-12-02
Investigator: KCKEMP
Referred To: Not reported
Reported to Dept: 2013-12-02
CID: Not reported
Water Affected: NONE
Spill Source: Commercial/Industrial

BYRNE DAIRY INC. (Continued) **U003313193**

Spill Notifier:	Responsible Party
Cleanup Ceased:	2014-01-07
Cleanup Meets Std:	True
Last Inspection:	2013-12-02
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-12-02
Spill Record Last Update:	2014-01-07
Spiller Name:	TOM CORP
Spiller Company:	BYRNE DAIRY
Spiller Address:	240 ONEIDA ST
Spiller Company:	999
Contact Name:	TOM CORP
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/02/2013 - Dock leveller being tested burst hydraulic hose, spilling approx 3 gallons non-PCB hydraulic oil to concrete and pavement. Spill booms and absorbent used to prevent spilled oil from reaching sotrm drainage system. EP&S contracted to clean area after hydraulics were repaired. BECI Donk advised. KCKemp 1/7/2014 - Disposal receipt and bill of lading rec4eived and filed. Spill closed. BECI Donk advised. KCKemp
Remarks:	Loss to pavement, c/u pending

All Materials:

Site ID:	489538
Operable Unit ID:	1239116
Operable Unit:	01
Material ID:	2239085
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Resource Affected:	Impervious Surface
Oxygenate:	Not reported

Name:	240 ONEIDA ST
Address:	240 ONEIDA ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	1008505 / 2010-11-15
Facility ID:	1008505
Facility Type:	ER
DER Facility ID:	397022
Site ID:	441997
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	2010-11-14
Investigator:	cxrossi
Referred To:	Not reported

BYRNE DAIRY INC. (Continued) **U003313193**

Reported to Dept:	2010-11-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2010-11-14
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-11-14
Spill Record Last Update:	2010-11-15
Spiller Name:	CHRISTIAN BRUNELLE
Spiller Company:	BYRNE DAIRY
Spiller Address:	240 ONEIDA ST
Spiller Company:	999
Contact Name:	PAUL SPENCER
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Byrne Dairy garbage truck broke a hydraulic line. Fluid spread to surrounding pavement, roadway,and two catch basins. Plant workers cleaned up pavement with speedy dry and cleaned the furthermost affected catch basin with absorbent pads. Catch basin next to building which received a great amount, flows back to plant to be treated with other milk waste materials and then discharges to sanitary sewer according to CHRISTIAN BRUNELLE. ~ctr~ 11/15/10
Remarks:	Caller advised hydraulic fluid spilled onto pavement. Clean up is in process.

All Materials:

Site ID:	441997
Operable Unit ID:	1192529
Operable Unit:	01
Material ID:	2187859
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	25.00
Resource Affected:	Soil, Sewer
Oxygenate:	Not reported

SPDES:

Name:	Upstate Farms Dairy, Llc
Address:	240 ONEIDA ST
City,State,Zip:	SYRACUSE, NY
Permit Number:	NYR00G338
State-Region:	07
Expiration Date:	Not reported
Current Major Minor Status:	Not reported

BYRNE DAIRY INC. (Continued) **U003313193**

Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	Not reported
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	UPSTATE NIAGARA COOPERATIVE INC.
Non-Gov Permit Street Address:	PO BOX 268
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	General Permit
Name:	Byrne Dairy Fluid Milk Plant
Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY 13202-3373
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY067
Non-Gov Permit Affiliation Type Desc:	Billing
Non-Gov Permit Org Formal Name:	TOM CORP
Non-Gov Permit Street Address:	ULTRA DAIRY 6700 WEST BENEDICT RD
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	EAST SYRACUSE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	13057
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BYRNE DAIRY INC
Non-Gov Facility Street Address:	BYRNE DAIRY FLUID MILK PLANT
Non-Gov Facility Supplemental Location:	2394 US RTE 11
Non-Gov Facility City:	LAFAYETTE
Non-Gov Facility State Code:	NY

BYRNE DAIRY INC. (Continued) **U003313193**

Non-Gov Facility Zip Code:	13084
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported

Name:	Byrne Dairy Fluid Milk Plant
Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY 13202-3373
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY067

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	TOM CORP
Non-Gov Permit Street Address:	BYRNE DAIRY FLUID MILK PLANT
Non-Gov Permit Supplemental Location:	ULTRA DAIRY 6700 WEST BENEDICT RD
Non-Gov Permit City:	EAST SYRACUSE
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	13057
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BYRNE DAIRY INC
Non-Gov Facility Street Address:	BYRNE DAIRY FLUID MILK PLANT
Non-Gov Facility Supplemental Location:	2394 US RTE 11
Non-Gov Facility City:	LAFAYETTE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	13084
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported

Name:	Byrne Dairy Fluid Milk Plant
Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY 13202-3373
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY067

Non-Gov Permit Affiliation Type Desc:	Permittee
Non-Gov Permit Org Formal Name:	BYRNE DAIRY INC
Non-Gov Permit Street Address:	2394 US 11
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	LAFAYETTE
Non-Gov Permit State Code:	NY

BYRNE DAIRY INC. (Continued) **U003313193**

Non-Gov Permit Zip Code:	13084
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BYRNE DAIRY INC
Non-Gov Facility Street Address:	BYRNE DAIRY FLUID MILK PLANT
Non-Gov Facility Supplemental Location:	2394 US RTE 11
Non-Gov Facility City:	LAFAYETTE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	13084
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported

Name:	Byrne Dairy Fluid Milk Plant
Address:	240 ONEIDA STREET
City,State,Zip:	SYRACUSE, NY 13202-3373
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	NY067

Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Owner
Non-Gov Facility Org Formal Name:	BYRNE DAIRY INC
Non-Gov Facility Street Address:	BYRNE DAIRY FLUID MILK PLANT
Non-Gov Facility Supplemental Location:	2394 US RTE 11
Non-Gov Facility City:	LAFAYETTE
Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	13084
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported

AG125 **ATLAS SERVICES** **NY LTANKS** **S100129276**
West **TAYLOR ST; KING ST** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.439 mi.
2319 ft. **Site 1 of 2 in cluster AG**

Relative: **Lower**

Actual: **390 ft.**

LTANKS:

Name:	ATLAS SERVICES
Address:	TAYLOR ST; KING ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8707432 / 1988-01-05
Facility ID:	8707432
Site ID:	243223
Spill Date:	1987-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1988-01-05
SWIS:	3415
Investigator:	AJMARSCH
Referred To:	Not reported
Reported to Dept:	1987-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-12-04
Spill Record Last Update:	1995-06-02
Spiller Name:	Not reported
Spiller Company:	ATLAS SERVICES
Spiller Address:	KING STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	199799
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JM / / : 12/02/87 RETESTED AND FAILED AT .676 GPH. TANK HAS BEEN PUMPED OUT. WILL REMOVE TANK AS SOON AS POSSIBLE.
Remarks:	4,000 GAL. TANK FAILURE RATE .111. WILL ISOLATE AND RETEST.

All Materials:

Site ID:	243223
Operable Unit ID:	913121
Operable Unit:	01
Material ID:	466382
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00

ATLAS SERVICES (Continued) **S100129276**

Resource Affected: Groundwater
Oxygenate: Not reported

126
East
1/4-1/2
0.445 mi.
2348 ft.

SYRACUSE UNIVERSITY
M17 SKYTOP RD
SYRACUSE, NY

NY LTANKS **S103479036**
N/A

Relative:
Higher

Actual:
560 ft.

LTANKS:

Name:	SYRACUSE UNIVERSITY
Address:	M17 SKYTOP RD
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9805513 / 1998-09-21
Facility ID:	9805513
Site ID:	156486
Spill Date:	1998-08-03
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1998-08-03
CID:	233
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-08-03
Spill Record Last Update:	1998-12-01
Spiller Name:	PAT STOCK
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	111 COLLEGE PL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	132435
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	tank was found to be bad when doing unrelated digging in area tank has been pulled and soil stock pilled

AH127 **HARRISON PARKING GARAGE** **UST FINDER RELEASE** **1029056971**
NW **WARREN & HARRISON ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.452 mi.
2387 ft. **Site 1 of 2 in cluster AH**

Relative: UST FINDER RELEASE:
Lower

Actual: Object ID:	249457
392 ft. Facility ID:	NY105583
Lust ID:	NY9010749
Name:	HARRISON PARKING GARAGE
Address:	WARREN & HARRISON ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1991/01/05 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1512
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Yes
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1508499999999
Y Coord:	43.0443000000001
Latitude:	43.0443
Longitude:	-76.15085

AH128 **HARRISON PARKING GARAGE** **NY LTANKS** **S105054356**
NW **WARREN & HARRISON ST** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.452 mi.
2387 ft. **Site 2 of 2 in cluster AH**

Relative: LTANKS:
Lower

Actual: Name:	HARRISON PARKING GARAGE
392 ft. Address:	WARREN & HARRISON ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9010749 / 1999-11-26
Facility ID:	9010749
Site ID:	121632
Spill Date:	1991-01-05
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial

HARRISON PARKING GARAGE (Continued) **S105054356**

Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	VOLLMER
Referred To:	Not reported
Reported to Dept:	1991-01-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1991-01-13
Spill Record Last Update:	1999-11-26
Spiller Name:	Not reported
Spiller Company:	HARRISON PARK GARAGE CORP
Spiller Address:	SUITE 702 - MONY TOWER 2
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	105583
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was DV 04/10/91: OPTIONS FOR ON SITE REMEDIATION OF SOIL UNDER STUDY. 02/28/92: PAASIVE SOIL VENT TO BE INCLUDED IN FINAL CONSTRUCTION PHASE.
Remarks:	CONTAMINATED SOIL DISCOVERED WHEN EXCAVATING FOR NEW PARKING GARAGE.

All Materials:

Site ID:	121632
Operable Unit ID:	947890
Operable Unit:	01
Material ID:	562056
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AG129 **ATLAS LINEN** **UST FINDER RELEASE** **1029069745**
West **320 WEST TAYLOR ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.458 mi.
2417 ft. **Site 2 of 2 in cluster AG**

Relative: **Lower**
Actual: **390 ft.**

UST FINDER RELEASE:

Object ID:	249446
Facility ID:	NY263105
Lust ID:	NY1641
Name:	ATLAS LINEN
Address:	320 WEST TAYLOR ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	2000/05/09 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	517
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Yes
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1531199999999
Y Coord:	43.0388400000001
Latitude:	43.03884
Longitude:	-76.15312

---

130 **HUTCHING PSYCH CTR TANK 007** **NY LTANKS** **S108956928**
NNE **620 MADISON ST** **NY Spills** **N/A**
1/4-1/2 **SYRACUSE, NY 13210**
0.463 mi.
2445 ft.

Relative: **Lower**
Actual: **401 ft.**

LTANKS:

Name:	HUTCHINGS PSYCH CENTER
Address:	620 MADISON ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0211660 / 2004-11-26
Facility ID:	0211660
Site ID:	187125
Spill Date:	2003-02-24
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Spill Class:	C3
Cleanup Ceased:	2004-11-15
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	2003-02-24
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2004-10-04
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-24
Spill Record Last Update:	2005-01-03
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	TRACIE SHIFFLET
Spiller Phone:	(315) 473-4908
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	156365
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	gross failure. believe that the leak is in the upper part of the tank and that there is no product leak.

All TTF:

Facility ID:	0211660
Spill Number:	0211660
Spill Tank Test:	1528042
Site ID:	187125
Tank Number:	10
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	187125
Operable Unit ID:	862725
Operable Unit:	01
Material ID:	511448
Material Code:	0001A
Material Name:	#2 fuel oil

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	False

SPILLS:

Name:	HUTCHING PSYC-BUILDING 10
Address:	620 MADISON AVE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0709106 / 2008-02-06
Facility ID:	0709106
Facility Type:	ER
DER Facility ID:	339717
Site ID:	390129
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	2007-11-20
Investigator:	hdwarner
Referred To:	Not reported
Reported to Dept:	2007-11-21
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2007-11-20
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-11-21
Spill Record Last Update:	2008-05-27
Spiller Name:	MIKE HOLIDAY
Spiller Company:	HUTCHING PSYC-BUILDING 10
Spiller Address:	620 MADISON AVE
Spiller Company:	001
Contact Name:	ANDREW AMELO
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	HAS SPOKEN TO HARRY WARRNER FROM REGION 7 HAD STOPPED BY AND SEEN THE EXCAVATION AND DEEMED IT VISUALLY CLEAN; OIL SEPERATOR IS THE TYPE OF TANK;' THE SEAL AROUND THE TOP OF THE CONCRETE TANK APPEARS TO HAVE FAILED;

All TTF:

Facility ID:	0709106
Spill Number:	0709106
Spill Tank Test:	2365808
Site ID:	390129
Tank Number:	Not reported

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Tank Size:	750
Material:	0066
EPA UST:	Not reported
UST:	True
Cause:	03
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	390129
Operable Unit ID:	1147242
Operable Unit:	01
Material ID:	2137643
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HUTCHINGS PC
Address:	620 MADISON ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0908714 / 2009-11-04
Facility ID:	0908714
Facility Type:	ER
DER Facility ID:	156365
Site ID:	421364
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	2009-09-29
Investigator:	hdwarner
Referred To:	Not reported
Reported to Dept:	2009-11-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-03
Spill Record Last Update:	2009-11-04

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Spiller Name:	Not reported
Spiller Company:	HUTCHINGS PC
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RICH HOWARD
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Not reported
Remarks:	4000gal ust removed/Atlantic Testing was on site for tank pull and soil testing.Soil test show soil contamination. Harry Warner has been advised

All Materials:

Site ID:	421364
Operable Unit ID:	1177255
Operable Unit:	01
Material ID:	2170023
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	421364
Operable Unit ID:	1177255
Operable Unit:	01
Material ID:	2170019
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HUTCHINGS PSYCH CENTER
Address:	620 MADISON ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0208287 / 2002-11-12
Facility ID:	0208287
Facility Type:	ER
DER Facility ID:	156365
Site ID:	187124
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	3415
Spill Date:	2002-11-11
Investigator:	CXROSSI
Referred To:	Not reported
Reported to Dept:	2002-11-11

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-11
Spill Record Last Update:	2002-11-12
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	RICK HOWARD
Latitude:	43.0453880
Longitude:	-76.1412335
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CTR SUMP DISCHARGE CONNECTS TO SANITARY SEWER ACCORDING TO RICK HOWARD
Remarks:	HYDRAULIC FAILURE AT ABOVE LOCATION ON ELEVATOR. MATERIAL MAY HAVE DRAINED INTO PUMP PIT WHICH FLOWS INTO STORM SEWER AT ABOVE LOCATION. REPAIR COMPANY ON SCENE. CALLER REQUESTS CALLBACK AND CAN BE REACHED ON CELL # 315-243-5852.

All Materials:

Site ID:	187124
Operable Unit ID:	859770
Operable Unit:	01
Material ID:	515296
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	5.00
Resource Affected:	Sewer
Oxygenate:	Not reported

Name:	BUILDING 12
Address:	620 MADISON ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9814456 / 2002-08-06
Facility ID:	9814456
Facility Type:	ER
DER Facility ID:	156365
Site ID:	187126
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	1999-02-27
Investigator:	CFMANNES
Referred To:	Not reported

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Reported to Dept:	1999-03-03
CID:	382
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-03
Spill Record Last Update:	2002-08-06
Spiller Name:	TOM ZIENTEK
Spiller Company:	HUTCHINGS PSYCHIATRIC
Spiller Address:	620 MADISON ST
Spiller Company:	001
Contact Name:	TOM ZIENTEK
Latitude:	43.0453880
Longitude:	-76.1412335
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM SPOKE WITH TOM ZIENTEK: RECOVERED 40 GAL, WIPED DOWN SUMP PIT, DIPOSED OF OIL BY MEANS OF COLLECTION TANK THAT IS PUMPED AND DISPOSED BY CONTRACTORS ON A PERIODIC BASIS.
Remarks:	A BROKEN FUEL LINE TO A BOILER CAUSED THE SPILL. SPILL WAS ON BASEMENT FLOORING AND WAS CLEANED UP.

All Materials:

Site ID:	187126
Operable Unit ID:	1072037
Operable Unit:	01
Material ID:	311144
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	40.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HUTCHINGS
Address:	620 MADISON ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9312426 / 1994-01-22
Facility ID:	9312426
Facility Type:	ER
DER Facility ID:	156365
Site ID:	297513
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	1994-01-22
Investigator:	GREGG

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Referred To:	Not reported
Reported to Dept:	1994-01-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-01-22
Cleanup Meets Std:	True
Last Inspection:	1994-01-22
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	GRIFFITH OIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was TG
Remarks:	AIR POCKET DEVELOPED WHILE FILLING TANK. EPS HIRED TO CLEAN UP.

All Materials:

Site ID:	297513
Operable Unit ID:	994439
Operable Unit:	01
Material ID:	387855
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HUTCHINGS PSYCH CENTER
Address:	620 MADISON STREET
City,State,Zip:	SYRACUSE, NY 13210
Spill Number/Closed Date:	0807781 / 2008-12-02
Facility ID:	0807781
Facility Type:	ER
DER Facility ID:	354391
Site ID:	405145
DEC Region:	7
Spill Cause:	Other
Spill Class:	C4
SWIS:	3415
Spill Date:	2008-10-09
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2008-10-09
CID:	Not reported
Water Affected:	Not reported

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Local Agency
Cleanup Ceased:	2008-12-02
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-10-09
Spill Record Last Update:	2017-06-12
Spiller Name:	Not reported
Spiller Company:	HUTCHINGS PSYCH CENTER
Spiller Address:	20 MADISON STREET
Spiller Company:	999
Contact Name:	TRACI SHIFFLET BUILDING #1
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Closed as NFA not meeting stds due to SVOC contamination that could not be remediated. See report in eDox. 6/12/2017 - Additional soil removal report received and filed. KCKemp
Remarks:	Not reported

All Materials:

Site ID:	405145
Operable Unit ID:	1161780
Operable Unit:	01
Material ID:	2152983
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	HUTCHINGS PSYCH CENTER
Address:	620 MADISON ST
City,State,Zip:	SYRACUSE, NY 13210
Spill Number/Closed Date:	0807277 / 2008-11-13
Facility ID:	0807277
Facility Type:	ER
DER Facility ID:	353576
Site ID:	404617
DEC Region:	7
Spill Cause:	Other
Spill Class:	C4
SWIS:	3415
Spill Date:	2008-09-29
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2008-09-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Spill Notifier:	Other
Cleanup Ceased:	2008-11-13
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-29
Spill Record Last Update:	2008-11-13
Spiller Name:	TRACIE SHIFFLET
Spiller Company:	HUTCHINGS
Spiller Address:	620 MADISON ST
Spiller Company:	999
Contact Name:	TRACIE SHIFFLET
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Minor SVOC exceedences from tank removal per eDoc'd results.KCKemp
Remarks:	Soil test results came back showing oil contamination. No clean up is scheduled.

All Materials:

Site ID:	404617
Operable Unit ID:	1161264
Operable Unit:	01
Material ID:	2152459
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	HUTCHING PSYCH CTR TANK 007
Address:	620 MADISON ST
City,State,Zip:	SYRACUSE, NY 13210
Spill Number/Closed Date:	0807003 / 2008-11-13
Facility ID:	0807003
Facility Type:	ER
DER Facility ID:	353576
Site ID:	404315
DEC Region:	7
Spill Cause:	Other
Spill Class:	C4
SWIS:	3415
Spill Date:	2008-09-22
Investigator:	KCKEMP
Referred To:	Not reported
Reported to Dept:	2008-09-22
CID:	Not reported
Water Affected:	NONE
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Other
Cleanup Ceased:	2008-11-13
Cleanup Meets Std:	True

HUTCHING PSYCH CTR TANK 007 (Continued) **S108956928**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-09-22
Spill Record Last Update:	2008-11-13
Spiller Name:	RICK HOWARD
Spiller Company:	NYS OFFICE OF MENTAL HEALTH
Spiller Address:	44 HOLLAND AVE
Spiller Company:	001
Contact Name:	RICK HOWARD
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Analytical results indicate soil contamination - tight site, no addl excavation required. Closed NFA not meeting stds. Spoils to stay on site and used as fill.
Remarks:	Analytical results indicate soil contamination

All Materials:

Site ID:	404315
Operable Unit ID:	1160980
Operable Unit:	01
Material ID:	2152169
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

131 NNW 1/4-1/2 0.473 mi. 2499 ft. **MONTGOMERY STREET**
MONGOMERY ST AND MADISON
SYRACUSE, NY

NY LTANKS **S106719238**
N/A

Relative: Lower

Actual: 395 ft.

LTANKS:

Name:	MONTGOMERY STREET
Address:	MONGOMERY ST AND MADISON
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	0310457 / 2003-12-15
Facility ID:	0310457
Site ID:	316015
Spill Date:	2003-12-10
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	HDWARNER
Referred To:	Not reported
Reported to Dept:	2003-12-10
CID:	404
Water Affected:	Not reported

MONTGOMERY STREET (Continued) **S106719238**

Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-10
Spill Record Last Update:	2003-12-15
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	BARB WHITE
Spiller Phone:	(315) 435-8884
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	254763
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was HW
Remarks:	no response required. just need a spill number. a leak in a gas tank caused the spill.

All Materials:

Site ID:	316015
Operable Unit ID:	875549
Operable Unit:	01
Material ID:	499312
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AI132 **CHIMES BUILDING** **NY BROWNFIELDS** **S132119340**
NW **500-550 SOUTH SALINA STREET** **N/A**
1/4-1/2 **SYRACUSE, NY 13202**
0.476 mi.
2513 ft. **Site 1 of 3 in cluster AI**

Relative:
Lower

Actual:
391 ft.

BROWNFIELDS:

Name:	CHIMES BUILDING
Address:	500-550 SOUTH SALINA STREET
City,State,Zip:	SYRACUSE, NY 13202
Program:	BCP
Site Code:	662655
Acres:	1.255
HW Code:	C734165
SWIS:	3415
Town:	Syracuse (c)
Record Added Date:	01/24/2024
Record Updated Date:	08/02/2024
Update By:	IABEILBY

CHIMES BUILDING (Continued) **S132119340**

Site Description: "Location: The site is located in the central portion of the City of Syracuse commercial district. The 1.255-acre site is surrounded by South Salina Street to the east, West Onondaga Street to the north, South Clinton Street to the west, and an office building to the south. Neighboring development is primarily commercial in nature. The surrounding properties include a parking garage and the Syracuse Transit Hub / CENTRO Bus Station located to the east, across South Salina Street; the Marriott Downton Syracuse hotel to the northeast, across South Salina Street; the Salt City Market to the north, across West Onondaga Street; a rail line that runs north to south to the west, across South Clinton Street; and the United States Department of Veterans Affairs building and parking lot to the south. There are currently no surface water bodies on or adjacent to the subject property. The closest surface water body is Onondaga Creek, located approximately 200 feet west of the site. Onondaga Creek Flows through the area in a general northerly direction and empties into the southern end of Onondaga Lake approximately 2.04 miles north of the site. Onondaga Creek originates in the Tully Lakes watershed and generally flows in a northerly direction through the Tully and Onondaga Valleys. Site Features: The subject property is currently developed with a 12-story steel frame and masonry building that is used for mixed commercial and residential use. The building was constructed in 1927 with an addition added to the southern corner of the building in 1970. The building fronts on South Salina Street and West Onondaga Street. The exterior portions of the property consist of asphalt paved parking lot to the west and south of the building. The parking lot is accessed via South Salina Street to the east and is surrounded by a wrought iron or steel fence. The site is located at 399 feet above mean sea level (amsl) on the eastern portion and slopes to a surface elevation of about 393 feet amsl along the lower western portion. Current Zoning and Land Use: The site is currently zoned for Central Business District (MX-5) under the City of Syracuse s City Zoning Ordinance (March 2023). The site s current land use is office building per Onondaga County GIS. The building that occupies the Site is partially occupied by a mix of residential and commercial tenants at this time. The commercial tenants and their operations are as follows: (1) Level 3 Communications, LLC (also known as CenturyLink), occupies space on the second floor for use as a fiber cable hub facility (head end). Their space consists of fiber, electronics, and building mechanicals to regulate room temperature and power equipment. The space does not actively occupy employees, only equipment service employees, as needed. (2) Charter Communications (also known as Spectrum), occupies two spaces in the basement of the building for use as a fiber cable hub facility (head end). Their space consists of fiber, electronics, and building mechanicals to regulate room temperature and power equipment. The space does not actively occupy employees, only equipment service employees, as needed. (3) Northland Communications occupies space on the second and the elevator penthouse for use as a fiber cable hub facility (head end). Their space consists of fiber, electronics, and building mechanicals to regulate room temperature and power equipment. The space does not actively occupy employees, only equipment service employees, as needed. (4) Casa Mia Food LLC operates a retail grocery store/pizzeria on the first floor of the building and utilizes the building for a retail store and food prep area, and backroom merchandise storage area with coolers. The store is actively occupied by employees daily and is open to the public.

CHIMES BUILDING (Continued) **S132119340**

(5) Metro by T Mobile operates a retail wireless store on the first floor of the building, fronting South Salina Street. Their operation consists of a retail area for cellular telephones and accessories, and a small back room for storage of merchandise. The store is actively occupied by employees daily and is open to the public. (6) Dish Wireless occupies space on the rooftop of the building and their space consists of fiber cable and antennas for use in transmitting cellular wireless signals. The space does not actively occupy employees, only equipment service employees, as needed. The properties surrounding the Site are zoned for a combination of Central Business District (MX-5) and Light Industry and Employment (LI). The properties surrounding the Site have a combination of land uses including office buildings, motor vehicle service, parking garage, public transportation, hotel, row buildings, railroad, and vacant commercial uses. Past Use of the Site: The subject property and surrounding area have a long history of commercial and residential use. Prior to the existing structure, the site was occupied by multiple dwellings on the western portion, stores on the eastern and northeastern portion, and a Women Christian Association home on the southeastern portion. In the early 1900s, some of the dwellings on the northwestern corner of the site had been replaced with stores and a furniture repair shop. The existing Chimes Building was reportedly constructed between 1927 and 1929. By the mid-1900s (c. 1950s), the Chimes Building contained a bank, offices, and store fronts, and the remainder of the property had been redeveloped with a restaurant building located adjacent to the Chimes Building on the north section of the site, another commercial building containing a store and restaurant on the northwest portion of the site, and a filling station with two gasoline tanks on the southeastern portion of the site. A dry-cleaning facility was also present on the southeastern portion of the subject property in the 1960s. Site Geology and Hydrogeology: The site is located within the Erie-Ontario Lowlands physiographic province of New York. The surficial geology at and ion the vicinity of the site is mapped as lacustrine silt and clay on the Surficial Geology Map of New York, Finger Lakes Sheet, dated 1986. Lacustrine silt and clay is a generally laminated formation of clay and silt that was deposited in proglacial lakes. These soils are generally calcareous, and variable in thickness, up to 50 meters. The soil lithology observed across the site during past environmental investigations generally consists of an upper layer of historical fill material (HFM), which was comprised of a heterogenous mix of gravel, brick fragments, ash, coal fragments, cinders, and slag. The depth of the HFM ranged in depths from approximately 0.5 feet to 13 feet below ground surface (bgs). This fill material was generally underlain by natural deposits comprised of a mixture of clay/silt, fine to medium sand, and fine to medium gravel and cobble. The bedrock beneath and in the vicinity of the site is mapped as dolostone, shale, gypsum, and salt of the Syracuse Formation on the Geologic Map of New York, Finger Lakes Sheet, dated 1970. Bedrock has not been investigated during previous environmental investigations. The groundwater table ranged from 22 feet to 28 feet bgs across the site. Based on the overserved topography of the site and the surrounding area, it is believed the groundwater on the site and within the vicinity of the site likely flows west toward Onondaga Creek. "

Env Problem: "Information submitted with the BCP application regarding the environmental condition at the site are currently under review and

CHIMES BUILDING (Continued) **S132119340**

	will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	4
Sub Type:	E
Owner Name:	Maarten Jacobs
Owner Company:	Chimes Syracuse LLC
Owner Address:	484 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Maarten Jacobs
Owner Company:	Chimes Syracuse LLC
Owner Address:	484 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Maarten Jacobs
Owner Company:	Chimes Syracuse LLC
Owner Address:	484 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Dan Smith
Owner Company:	Onondaga County Public Library Central Library
Owner Address:	447 South Salina Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13205
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	2307739
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2024-03-13 09:31:00
Record Updated:	2024-03-13 09:31:00

CHIMES BUILDING (Continued) **S132119340**

Updated By: AYRUSSO

AI133 **500 SOUTH SALINA STREET** **UST FINDER RELEASE** **1029058890**
NW **500 SOUTH SALINA STREET** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.476 mi.
2513 ft. **Site 2 of 3 in cluster AI**

Relative: UST FINDER RELEASE:
Lower

Actual: Object ID:	249451
391 ft. Facility ID:	NY130242
Lust ID:	NY9960057
Name:	500 SOUTH SALINA STREET
Address:	500 SOUTH SALINA STREET
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	2000/02/21 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1161
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Yes
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.15216
Y Coord:	43.0440400000001
Latitude:	43.04404
Longitude:	-76.1521599999999

AI134 **THE CHIMES BUILDING** **US BROWNFIELDS** **1031288681**
NW **500-550 SOUTH SALINA STREET** **N/A**
1/4-1/2 **SYRACUSE, NY 13202**
0.476 mi.
2513 ft. **Site 3 of 3 in cluster AI**

Relative: US BROWNFIELDS:
Lower

Actual: Name:	The Chimes Building
391 ft. Address:	500-550 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202

THE CHIMES BUILDING (Continued) **1031288681**

Property ID:	258433
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Not reported
Property Number:	096.-5-01.0
Parcel Size:	1.3
Latitude:	43.043830117
Longitude:	-76.152480429
Census Tract:	36067003200
State or Tribal Voluntary Response Program:	Y
Program Name:	4B
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals SVOCs
Contaminants Found at Actionable Level:	Lead Other Metals SVOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96219123
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported

THE CHIMES BUILDING (Continued) **1031288681**

Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	N
Past use commercial acreage:	1.3
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	N
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2410
Below Poverty Percent:	48.97
Meidan Income:	3135
Meidan Income Number:	3382

THE CHIMES BUILDING (Continued) **1031288681**

Meidan Income Percent:	68.73
Vacant Housing Number:	704
Vacant Housing Percent:	23.8
Unemployed Number:	369
Unemployed Percent:	7.5
Name:	The Chimes Building
Address:	500-550 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	258433
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Not reported
Property Number:	096.-5-01.0
Parcel Size:	1.3
Latitude:	43.043830117
Longitude:	-76.152480429
Census Tract:	36067003200
State or Tribal Voluntary Response Program:	Y
Program Name:	4B
AA Activity Funded:	Phase I Environmental Assessment
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals SVOCs
Contaminants Found at Actionable Level:	Lead Other Metals SVOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	EPA
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96219123
Start Date:	2023-11-20 00:00:00
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	2024-01-10 00:00:00
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported

THE CHIMES BUILDING (Continued) **1031288681**

IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	1.3
NFA Letter Date Received:	Not reported
Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported

THE CHIMES BUILDING (Continued) **1031288681**

ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2410
Below Poverty Percent:	48.97
Meidan Income:	3135
Meidan Income Number:	3382
Meidan Income Percent:	68.73
Vacant Housing Number:	704
Vacant Housing Percent:	23.8
Unemployed Number:	369
Unemployed Percent:	7.5

Name:	The Chimes Building
Address:	500-550 South Salina Street
City,State,Zip:	SYRACUSE, NY 13202
Property ID:	258433
Property Alias:	Not reported
Recipient Name:	Greater Syracuse Property Development Corporation
Grant Type:	Not reported
Property Number:	096.-5-01.0
Parcel Size:	1.3
Latitude:	43.043830117
Longitude:	-76.152480429
Census Tract:	36067003200
State or Tribal Voluntary Response Program:	Y
Program Name:	4B
AA Activity Funded:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Activity Funded:	Phase I Environmental Assessment
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Contaminants REC:	Lead Other Metals SVOCs
Contaminants Found at Actionable Level:	Lead Other Metals SVOCs
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Contaminants Found Below Actionable Level:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Climate Adapt Mitig - Planning or Assessment:	Not reported
Cooperative Agreement Number:	96219123
Start Date:	Not reported
Ownership Entity:	Private
Additional Institutional Controls Information:	Not reported
Completion Date:	Not reported
Address of Data Sources (URL if available) 1:	Not reported
Cleanup Required:	U
Indicates Cleanup/Treatment Tech Implemented:	Not reported
Institutional Controls Required:	Not reported

THE CHIMES BUILDING (Continued) **1031288681**

IC Category Proprietary Controls:	Not reported
Excavation and Disposal of Soils:	Not reported
Extraction of contaminants:	Not reported
IC Cat. Info. Devices:	Not reported
Removal of materials (tanks and piping, etc.):	Not reported
IC Cat. Gov. Controls:	Not reported
Reduction of Contam Bioremediation/Phytoremediation:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
Cleanup of structures:	Not reported
IC in place date:	Not reported
Additional Cleanup/Treatment Tech Info:	Not reported
IC in place:	Not reported
Address of Data Source (URL if available) 2:	Not reported
Indicate whether Engineering Controls are required:	Not reported
State/tribal program ID:	Not reported
Cover Technologies (e.g., Capping):	Not reported
Security (e.g., Guard, Fence):	Not reported
Immobilization Process:	Not reported
Engineering Barriers (e.g., Slurry Walls, Sheet):	Not reported
Other:	Not reported
Additional Engineering Controls Information:	Not reported
Address of Data Source (URL if available) 3:	Not reported
Indicate whether Engineering Controls are in place:	Not reported
Date Engineering Controls put into place:	Not reported
ACRES Cleaned Up:	Not reported
Section 128(a) State/Tribal:	Not reported
Multipurpose - Cost Share Amount:	Not reported
Cleanup - Cost Share Amount:	Not reported
RLF Loan - Total Loan Amount:	Not reported
RLF - Loan Signed Date:	Not reported
RLF Loan - Anticipated Repayment Start Date:	Not reported
RLF Loan - Anticipated Repayment End Date:	Not reported
RLF Loan - Interest Rate:	Not reported
RLF Loan - EPA Funds Used:	Not reported
Contaminant Cleanup:	Not reported
RLF Loan - Cost Share Used:	Not reported
Media Affected:	Ground Water Soil
RLF Loan - Program Income Used:	Not reported
Media Cleanup:	Not reported
RLF Loan - Discounted:	Not reported
RLF Loan - Discount Percentage:	Not reported
RLF Subgrant - Total Subgrant Amount:	Not reported
RLF Subgrant - Signed Date:	Not reported
RLF Subgrant - EPA Funds Used:	Not reported
RLF Subgrant - Cost Share Used:	Not reported
RLF Subgrant - Program Income Used:	Not reported
RLF Direct Cleanup - Total Funding Amt:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
RLF Direct Cleanup - Source of Funding:	Not reported
RLF Leveraged - Funding Source Type:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
RLF Leveraged - Entity Providing Funding:	Not reported
RLF Leveraged - Funding Amount:	Not reported
Cleanup Completion Doc - NFA Letter Received:	Not reported
Past use commercial acreage:	1.3
NFA Letter Date Received:	Not reported

THE CHIMES BUILDING (Continued) **1031288681**

Past use industrial acreage:	Not reported
Cleanup Comp Doc - Letter/Signed Rep Qualified Pro:	Not reported
Future use greenspace acreage:	Not reported
Letter/Signed Report Date Received:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Cleanup Completion Doc- Other forms of Doc:	Not reported
Future use industrial acreage:	Not reported
Climate Adapt and Mitiga - Demo or Cleanup:	Not reported
ReDev Activity Funded:	Not reported
Amount of Funding Expended on this Activity 2:	Not reported
Number of Redevelopment Jobs Leveraged:	Not reported
Climate Adaptation and Mitigation Redevelopment:	Not reported
Radius:	0.5
Below Poverty Number:	2410
Below Poverty Percent:	48.97
Meidan Income:	3135
Meidan Income Number:	3382
Meidan Income Percent:	68.73
Vacant Housing Number:	704
Vacant Housing Percent:	23.8
Unemployed Number:	369
Unemployed Percent:	7.5

---

135 SSW 1/4-1/2 0.482 mi. 2543 ft.

MIDSTATE AUTO
PO BOX 11298
SYRACUSE, NY

NY SWF/LF **S110119917**
N/A

Relative: Higher

Actual: 406 ft.

SWF/LF:

Name:	MIDSTATE AUTO
Address:	PO BOX 11298
City,State,Zip:	SYRACUSE, NY
Flag:	INACTIVE
Region Code:	7
Phone Number:	Not reported
Owner Name:	Frank Tuddeo
Owner Type:	Private
Owner Address:	1543 South Salina St. Syracuse
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13206
Owner Email:	Not reported
Owner Phone:	3154723393
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	[7073260]
Active:	No
East Coordinate:	406482
North Coordinate:	4764971
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported

MIDSTATE AUTO (Continued) **S110119917**

Authorization #: Not reported
Authorization Date: Not reported
Expiration Date: Not reported
Operator Name: Jeff Reitz
Operator Type: Not reported
Laste Date: Not reported

AJ136 **H.S.M.PACKAGING CORP** **UST FINDER RELEASE** **1029063640**
WNW **123 LARNED ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.487 mi.
2570 ft. **Site 1 of 2 in cluster AJ**

Relative: **Lower**

Actual: **390 ft.**

UST FINDER RELEASE:

Object ID:	249439
Facility ID:	NY188268
Lust ID:	NY9605294
Name:	H.S.M.PACKAGING CORP
Address:	123 LARNED ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1996/07/24 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	849
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	Yes
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.15377
Y Coord:	43.04089
Latitude:	43.0408899999999
Longitude:	-76.1537699999999

AJ137 **H.S.M.PACKAGING CORP** **NY LTANKS** **S102234009**
WNW **123 LARNED ST** **N/A**
1/4-1/2 **SYRACUSE, NY**
0.487 mi.
2570 ft. **Site 2 of 2 in cluster AJ**

Relative: **Lower**

Actual: **390 ft.**

LTANKS:

Name:	H.S.M.PACKAGING CORP
Address:	123 LARNED ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9605294 / 1996-09-30
Facility ID:	9605294
Site ID:	228231
Spill Date:	1996-07-24
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1996-07-24
CID:	199
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-07-24
Spill Record Last Update:	1996-11-15
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	BOB DAVEY
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	188268
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM
Remarks:	working on const site a tank was found underground - tank is believed to be a 3000 gal tank - there is residue of contamination around the tank in the soil - tank will be pumped out tonight and tank dug out tomarrow - caller states tom mclaughlin from the region office was notified

All Materials:

Site ID:	228231
Operable Unit ID:	1036177
Operable Unit:	01
Material ID:	348043
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

H.S.M.PACKAGING CORP (Continued) **S102234009**

Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AK138 **DISTRICT HEATING & COOLING PLANT** **NY LTANKS** **S104514136**
NNW **601 S STATE ST** **NY Spills** **N/A**
1/4-1/2 **SYRACUSE, NY 13202** **NY AIRS**
0.488 mi. **NY MANIFEST**
2576 ft. **Site 1 of 2 in cluster AK**

Relative: **Lower**
Actual: **397 ft.**

LTANKS:

Name:	STEAM STATION
Address:	601 S. STATE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	8602554 / 1988-12-12
Facility ID:	8602554
Site ID:	93875
Spill Date:	1986-07-18
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1988-11-28
SWIS:	3415
Investigator:	HDWARNER
Referred To:	Not reported
Reported to Dept:	1986-07-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1986-07-25
Spill Record Last Update:	1988-12-12
Spiller Name:	Not reported
Spiller Company:	ONONDAGA COUNTY STEAM STA
Spiller Address:	PAUL ELLARD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	84107
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was HW
Remarks:	08/18/86: 200-300 GALLONS OF 6 FUEL ENTERED GROUNDWATER VIA TANK FALUIRE. EOI EMPTIED OLD TANK AND RECOVERED SPILLED PRODUCT. ENVIRONMENTAL OIL CO. WAS CALLED BY ONONDAGA COUNTY STEAM STATION & RESPONDED. GROUNDWATER CLEANUP BEING PERFORMED.

All Materials:

Site ID:	93875
Operable Unit ID:	899836

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Operable Unit:	01
Material ID:	478984
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

SPILLS:

Name:	STEAM STATION-S.STATE ST.
Address:	601 S. STATE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9106022 / 1991-09-05
Facility ID:	9106022
Facility Type:	ER
DER Facility ID:	84107
Site ID:	190544
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	3415
Spill Date:	1986-09-04
Investigator:	ROMOCKI
Referred To:	Not reported
Reported to Dept:	1991-09-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1991-09-05
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1991-09-04
Spill Record Last Update:	1991-09-05
Spiller Name:	Not reported
Spiller Company:	ONON. CO. STEAM STATION
Spiller Address:	601 S.STATE ST.
Spiller Company:	001
Contact Name:	Not reported
Latitude:	43.0462538
Longitude:	-76.1474007
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MR 09/04/91: CONTRACTOR WILL ATTEMPT TO EXCAVATE CONTAMINATED SOIL. 09/05/91: CONTAMINATED SOIL EXCAVATED AND STAGED ON SITE. SOIL SAMPLES TO BE TAKEN FROM WALL OF EXCAVATION TO DOCUMENT CONDITIONS AFTER EXCAVATING.
Remarks:	CONTAMINATED SOIL DISCOVERED DURING TANK REMOVAL.

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

All Materials:

Site ID:	190544
Operable Unit ID:	960360
Operable Unit:	01
Material ID:	421774
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	25.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	STEAM PLANT GARAGE
Address:	601 SOUTH STATE ST
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	2307378 / 2023-12-20
Facility ID:	2307378
Facility Type:	ER
DER Facility ID:	604827
Site ID:	659433
DEC Region:	7
Spill Cause:	Equipment Failure
Spill Class:	D2
SWIS:	3442
Spill Date:	2023-12-06
Investigator:	DGMILLER
Referred To:	Not reported
Reported to Dept:	2023-12-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2023-12-06
Spill Record Last Update:	2023-12-20
Spiller Name:	JESSE
Spiller Company:	ONONDAGA CO
Spiller Address:	601 SOUTH STATE ST
Spiller Company:	999
Contact Name:	JESSE
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Cleaned up by rp
Remarks:	Clean up pending

All Materials:

Site ID:	659433
Operable Unit ID:	1406269

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Operable Unit:	01
Material ID:	2423654
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.50
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

AIRS:

Name:	DISTRICT HEATING & COOLING PLANT
Address:	601 S STATE ST
City,State,Zip:	SYRACUSE, NY 13202
DECID:	7311500112
Process ID:	Not reported
Latitude:	Not reported
Longitude:	Not reported
FIPS Code:	Not reported
Auth Type Code:	AFR
Permit Status:	Issued
Auth Status Code:	2
Emissions:	Not reported
Issue date:	06/11/2008
Expired Date:	Not reported
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Expired
Auth Status Code:	7
Emissions:	Not reported
Issue date:	07/05/2006
Expired Date:	06/11/2008
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported
Permit Status:	Expired
Auth Status Code:	7
Emissions:	Not reported
Issue date:	03/08/2004
Expired Date:	07/05/2006
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

NY MANIFEST:

EPA ID:	NY0000033688
Country:	USA
Name:	Syracuse City Of Public Service Building
Address:	601 SOUTH STATE ST
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13202
Zip 4:	Not reported
Location Address 1:	601 SOUTH STATE ST
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13202
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Syracuse City Of Public Service Building
Mailing Contact:	Roger Widay
Mailing Address 1:	511 S STATE ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3154358367

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986980753
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/2009
Trans1 Recv Date:	05/26/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/12/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD010154045
TSDF ID 2:	Not reported
Manifest Tracking Number:	000634225JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	750
Units:	Pounds
Number of Containers:	2
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986980753
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/2009
Trans1 Recv Date:	05/26/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/12/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD010154045
TSDF ID 2:	Not reported
Manifest Tracking Number:	000634225JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Lead
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Quantity: 1100
Units: Pounds
Number of Containers: 3
Container Type: Fiber or plastic boxes, cartons, cases
Handling Method: Landfill
Specific Gravity: 1

Document ID: VTA0064296
Manifest Status: Not reported
Trans1 State ID: NYPD7793
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 06/14/1994
Trans1 Recv Date: 06/14/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/20/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000033688
Trans1 EPA ID: NYD012928347
Trans2 EPA ID: Not reported
TSDF ID 1: VTD982766537
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00050
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00

Document ID: MAH7549900
Manifest Status: Not reported
Trans1 State ID: 13908MA
Year: 1995
Trans2 State ID: 4938BSOK
Generator Ship Date: 11/13/1995
Trans1 Recv Date: 11/13/1995
Trans2 Recv Date: 11/20/1995
TSD Site Recv Date: 11/20/1995

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	MAD000604447
Trans2 EPA ID:	ARD981908551
TSDF ID 1:	MAD000604447
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Potassium Cyanide (Or) Potassium Cyanide K(Cn)
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	PAC8097202
Manifest Status:	Not reported
Trans1 State ID:	PAAH0147
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	12/02/1993
Trans1 Recv Date:	12/02/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/03/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	06/25/2010
Trans1 Recv Date:	06/25/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/12/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	002472766FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	160

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Units:	Kilograms
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYR000115733
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/24/2011
Trans1 Recv Date:	02/24/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/28/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	003548146FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H071
Waste Code a:	Chromium
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1536
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Treat
Specific Gravity:	1
Document ID:	NYB7540893
Manifest Status:	Not reported
Trans1 State ID:	13908MA
Year:	1995

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Trans2 State ID:	98115FNY
Generator Ship Date:	11/13/1995
Trans1 Recv Date:	11/13/1995
Trans2 Recv Date:	11/14/1995
TSD Site Recv Date:	11/14/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	NYD982792814
Trans2 EPA ID:	NYD982792814
TSDF ID 1:	NYD000632372
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Reactive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Specific Gravity:	01.00
Document ID:	NYB7540902
Manifest Status:	Not reported
Trans1 State ID:	13908MA
Year:	1995
Trans2 State ID:	5245BFOK
Generator Ship Date:	11/13/1995
Trans1 Recv Date:	11/13/1995
Trans2 Recv Date:	11/15/1995
TSD Site Recv Date:	11/16/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	MAD000604447
Trans2 EPA ID:	ARD981908551
TSDF ID 1:	NCD000648451
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Benzene, 1,1'-(2,2,2-Trichloroethylidene)Bis[4-Chloro- (Or) Ddt
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	2,4-Dinitrophenol (Or) Phenol, 2,4-Dinitro-
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Waste Code 16:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Reactive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00020
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB6726231
Manifest Status:	Not reported
Trans1 State ID:	R39387ME
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	02/28/1995
Trans1 Recv Date:	02/28/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/04/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000033688
Trans1 EPA ID:	CTD982191942
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980700942
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs

DISTRICT HEATING & COOLING PLANT (Continued) **S104514136**

Handling Method:	Burn
Specific Gravity:	01.00

AK139 **STEAM STATION-S.STATE ST.** **UST FINDER RELEASE** **1029078785**
NNW **601 S. STATE ST** **N/A**
1/4-1/2 **SYRACUSE, NY 0**
0.488 mi.
2576 ft. **Site 2 of 2 in cluster AK**

Relative: **Lower**
Actual: **397 ft.**

UST FINDER RELEASE:

Object ID:	249477
Facility ID:	NY84107
Lust ID:	NY9106022
Name:	STEAM STATION-S.STATE ST.
Address:	601 S. STATE ST
City,State,Zip:	SYRACUSE, NY 0
Address Match Type:	Not reported
Reported Date:	1986/09/04 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1605
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-76.1473999999999
Y Coord:	43.04625
Latitude:	43.04625
Longitude:	-76.1474

140 ESE 1/4-1/2 0.498 mi. 2627 ft. — **MANLEY FIELD GROUNDS**, **MANLEY FIELD HOUSE**, **SYRACUSE, NY** — **NY LTANKS** — **S100493611** / **N/A**

Relative: Higher

Actual: 562 ft.

LTANKS:

Name:	MANLEY FIELD GROUNDS
Address:	MANLEY FIELD HOUSE
City,State,Zip:	SYRACUSE, NY
Spill Number/Closed Date:	9202927 / 1992-06-11
Facility ID:	9202927
Site ID:	293002
Spill Date:	1992-06-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1992-06-11
SWIS:	3415
Investigator:	CFMANNES
Referred To:	Not reported
Reported to Dept:	1992-06-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-06-15
Spill Record Last Update:	1992-11-02
Spiller Name:	Not reported
Spiller Company:	SYRACUSE UNIVERSITY
Spiller Address:	COMSTOCK & WEST COLVIN
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	7
DER Facility ID:	237165
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM 06/11/92: VISITED SITE : OBSERVED TANK PULL SOME TAR FROM AROUND TANK LEACH OUT INTO GROUND WATER TANK WAS IN GOOD CONDITION (NO HOLES OBSERVED) SOIL SAMPLE TAKEN = 1 YARD OF SOIL TO BE LANDFILLED.
Remarks:	4' DIA X 11' LONG TANK DISCOVERED WHILE EXCAVATING FOR NEW CONSTRUCTION CLEAN HARBORS TO TAKE SAMPLES & HAVE TANK TESTED 463-134? SOIL HAS BEEN STOCK PILED ON POLY GREG CUSIAK IS CONTACT @ CLEAN HARBO

All Materials:

Site ID:	293002
Operable Unit ID:	966957
Operable Unit:	01
Material ID:	410756
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported

MANLEY FIELD GROUNDS (Continued) **S100493611**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

141
WSW
1/2-1
0.719 mi.
3796 ft.

BROWN MANUFACTURING SITE FORMER
101 CHESTER ST
SYRACUSE, NY 13207

NY SHWS **S105859104**
NY ENG CONTROLS **N/A**
NY INST CONTROL
NY ERP
NY MANIFEST

Relative:
Lower

Actual:
390 ft.

SHWS:

Name:	FORMER BROWN MANUFACTURING SITE
Address:	101 CHESTER STREET
City,State,Zip:	SYRACUSE, NY 13207
Program:	HW
Site Code:	465076
Classification:	C
Region:	7
Acres:	0.800
HW Code:	734141
Record Add:	06/07/2012
Record Upd:	01/07/2021
Updated By:	JPCOOK
Site Description:	"See Site # B00024."
Env Problem:	"See Site # B00024."
Health Problem:	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-06-11 10:46:00
Record Upd:	2016-06-15 11:38:00
Updated By:	JPCOOK
Own Op:	1
Sub Type:	C01
Owner Name:	Owen Kerney
Owner Company:	City of Syracuse TD
Owner Address:	201 E. Washington St, Suite 5000
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
HW Code:	734141
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

HW Code:	734141
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	SELENIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	734141

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 734141
Waste Type: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

ENG CONTROLS:
Name: FORMER BROWN MANUFACTURING SITE
Address: 101 CHESTER STREET
City,State,Zip: SYRACUSE, NY 13207
Site Code: 57206
HW Code: B00024
Control Code: 15
Control Type: ENG
Date Record Added: 06/11/2012
Date Rec Updated: 10/27/2022
Updated By: GWPRISCO
Site Description: "Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till.

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

	Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."
Env Problem:	"Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified by the investigation."
Health Problem:	"Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."
	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	43:02:00. / 76:09:28.
Dell:	False
Record Add:	2003-10-28 13:52:00
Record Upd:	2012-10-04 14:34:00
Updated By:	ldennist
Own Op:	1
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	City of Syracuse
Owner Address:	203 City Hall, 233 E Washington St
Owner Addr2:	Not reported
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	6
Sub Type:	C01
Owner Name:	Ben Walsh
Owner Company:	City of Syracuse
Owner Address:	203 City Hall
Owner Addr2:	233 E Washington Street
Owner City,St,Zip:	SYRACUSE (C), NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Local History & Genealogy Department
Owner Company:	Onondaga County Public Library
Owner Address:	The Galleries of Syracuse
Owner Addr2:	447 South Salina Street
Owner City,St,Zip:	Syracuse, NY 13202
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Joshua Cook
Owner Company:	NYSDEC Region 7
Owner Address:	615 Erie Blvd West
Owner Addr2:	Not reported

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Owner City,St,Zip:	Syracuse, NY 13204
Owner Country:	United States of America
HW Code:	B00024
Waste Type:	Petroleum Products
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	PHENANTHRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	SELENIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	BENZ(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	BENZO(B)FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	Chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	ARSENIC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	DIBENZ[A,H]ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Code:	Not reported
HW Code:	B00024
Waste Type:	NAPHTHALENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	BENZO[K]FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	BARIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	B00024
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYR000223016
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-11-13 13:18:00
Record Updated:	2015-11-13 13:18:00
Updated By:	JPCOOK
Crossref ID:	7-601599
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-01-03 13:17:00
Record Updated:	2017-01-03 13:17:00
Updated By:	JPCOOK
Crossref ID:	NYWII-B00024-12-14
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-03-06 11:54:00
Record Updated:	2018-03-06 11:54:00
Updated By:	JPCOOK
Crossref ID:	C300654
Cross Ref Type Code:	23

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2018-03-06 11:55:00
Record Updated:	2018-03-06 11:55:00
Updated By:	JPCOOK
Crossref ID:	B 5431 P 745
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-07-28 13:09:00
Record Updated:	2017-07-28 13:09:00
Updated By:	JPCOOK

INST CONTROL:

Name:	FORMER BROWN MANUFACTURING SITE
Address:	101 CHESTER STREET
City,State,Zip:	SYRACUSE, NY 13207
Site Code:	57206
Control Name:	Monitoring Plan
HW Code:	B00024
Control Code:	31
Control Type:	INST
Dt record added:	06/11/2012
Dt rec updated:	10/27/2022
Updated By:	GWPRISCO
Site Code:	57206
Site Description:	"Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."

Env Problem: "Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified by the investigation."

Health Problem: "Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."

Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 43:02:00. / 76:09:28.
Dell: False
Record Add: 2003-10-28 13:52:00
Record Upd: 2012-10-04 14:34:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: Not reported
Owner Company: City of Syracuse
Owner Address: 203 City Hall, 233 E Washington St
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Ben Walsh
Owner Company: City of Syracuse
Owner Address: 203 City Hall
Owner Addr2: 233 E Washington Street
Owner City,St,Zip: SYRACUSE (C), NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Local History & Genealogy Department
Owner Company: Onondaga County Public Library
Owner Address: The Galleries of Syracuse
Owner Addr2: 447 South Salina Street
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Joshua Cook
Owner Company: NYSDEC Region 7
Owner Address: 615 Erie Blvd West
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13204

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Owner Country: United States of America
HW Code: B00024
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: SELENIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

HW Code: B00024
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYR000223016
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-11-13 13:18:00
Record Updated: 2015-11-13 13:18:00
Updated By: JPCOOK
Crossref ID: 7-601599
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-01-03 13:17:00
Record Updated: 2017-01-03 13:17:00
Updated By: JPCOOK
Crossref ID: NYWII-B00024-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:54:00
Record Updated: 2018-03-06 11:54:00
Updated By: JPCOOK
Crossref ID: C300654
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Record Added Date: 2018-03-06 11:55:00
Record Updated: 2018-03-06 11:55:00
Updated By: JPCOOK
Crossref ID: B 5431 P 745
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-28 13:09:00
Record Updated: 2017-07-28 13:09:00
Updated By: JPCOOK

Name: FORMER BROWN MANUFACTURING SITE
Address: 101 CHESTER STREET
City,State,Zip: SYRACUSE, NY 13207
Site Code: 57206
Control Name: IC/EC Plan
HW Code: B00024
Control Code: 34
Control Type: INST
Dt record added: 06/11/2012
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57206
Site Description: "Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

southwest to northeast in this area."
Env Problem: "Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified by the investigation."
Health Problem: "Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 43:02:00. / 76:09:28.
Dell: False
Record Add: 2003-10-28 13:52:00
Record Upd: 2012-10-04 14:34:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: Not reported
Owner Company: City of Syracuse
Owner Address: 203 City Hall, 233 E Washington St
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Ben Walsh
Owner Company: City of Syracuse
Owner Address: 203 City Hall
Owner Addr2: 233 E Washington Street
Owner City,St,Zip: SYRACUSE (C), NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Local History & Genealogy Department
Owner Company: Onondaga County Public Library
Owner Address: The Galleries of Syracuse
Owner Addr2: 447 South Salina Street
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Joshua Cook
Owner Company: NYSDEC Region 7
Owner Address: 615 Erie Blvd West
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13204
Owner Country: United States of America
HW Code: B00024

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: SELENIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NAPHTHALENE

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYR000223016
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-11-13 13:18:00
Record Updated: 2015-11-13 13:18:00
Updated By: JPCOOK
Crossref ID: 7-601599
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-01-03 13:17:00
Record Updated: 2017-01-03 13:17:00
Updated By: JPCOOK
Crossref ID: NYWII-B00024-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:54:00
Record Updated: 2018-03-06 11:54:00
Updated By: JPCOOK
Crossref ID: C300654
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:55:00
Record Updated: 2018-03-06 11:55:00

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Updated By: JPCOOK
Crossref ID: B 5431 P 745
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-28 13:09:00
Record Updated: 2017-07-28 13:09:00
Updated By: JPCOOK

Name: FORMER BROWN MANUFACTURING SITE
Address: 101 CHESTER STREET
City,State,Zip: SYRACUSE, NY 13207
Site Code: 57206
Control Name: Site Management Plan
HW Code: B00024
Control Code: 32
Control Type: INST
Dt record added: 06/11/2012
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57206
Site Description: "Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."
Env Problem: "Nature and Extent of Contamination: Prior to remediation, the

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified by the investigation."

Health Problem: "Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 43:02:00. / 76:09:28.
Dell: False
Record Add: 2003-10-28 13:52:00
Record Upd: 2012-10-04 14:34:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: Not reported
Owner Company: City of Syracuse
Owner Address: 203 City Hall, 233 E Washington St
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Ben Walsh
Owner Company: City of Syracuse
Owner Address: 203 City Hall
Owner Addr2: 233 E Washington Street
Owner City,St,Zip: SYRACUSE (C), NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Local History & Genealogy Department
Owner Company: Onondaga County Public Library
Owner Address: The Galleries of Syracuse
Owner Addr2: 447 South Salina Street
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Joshua Cook
Owner Company: NYSDEC Region 7
Owner Address: 615 Erie Blvd West
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13204
Owner Country: United States of America
HW Code: B00024
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Code: Not reported
HW Code: B00024
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: SELENIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

HW Code: B00024
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYR000223016
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-11-13 13:18:00
Record Updated: 2015-11-13 13:18:00
Updated By: JPCOOK
Crossref ID: 7-601599
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-01-03 13:17:00
Record Updated: 2017-01-03 13:17:00
Updated By: JPCOOK
Crossref ID: NYWII-B00024-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:54:00
Record Updated: 2018-03-06 11:54:00
Updated By: JPCOOK
Crossref ID: C300654
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:55:00
Record Updated: 2018-03-06 11:55:00
Updated By: JPCOOK
Crossref ID: B 5431 P 745

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-28 13:09:00
Record Updated: 2017-07-28 13:09:00
Updated By: JPCOOK

Name: FORMER BROWN MANUFACTURING SITE
Address: 101 CHESTER STREET
City,State,Zip: SYRACUSE, NY 13207
Site Code: 57206
Control Name: Soil Management Plan
HW Code: B00024
Control Code: 14
Control Type: INST
Dt record added: 06/11/2012
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57206
Site Description: "Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."
Env Problem: "Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified by the investigation."
Health Problem: "Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 43:02:00. / 76:09:28.
Dell: False
Record Add: 2003-10-28 13:52:00
Record Upd: 2012-10-04 14:34:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: Not reported
Owner Company: City of Syracuse
Owner Address: 203 City Hall, 233 E Washington St
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Ben Walsh
Owner Company: City of Syracuse
Owner Address: 203 City Hall
Owner Addr2: 233 E Washington Street
Owner City,St,Zip: SYRACUSE (C), NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Local History & Genealogy Department
Owner Company: Onondaga County Public Library
Owner Address: The Galleries of Syracuse
Owner Addr2: 447 South Salina Street
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Joshua Cook
Owner Company: NYSDEC Region 7
Owner Address: 615 Erie Blvd West
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13204
Owner Country: United States of America
HW Code: B00024
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: SELENIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: FLUORANTHENE

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYR000223016
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-11-13 13:18:00
Record Updated: 2015-11-13 13:18:00
Updated By: JPCOOK
Crossref ID: 7-601599
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-01-03 13:17:00
Record Updated: 2017-01-03 13:17:00
Updated By: JPCOOK
Crossref ID: NYWII-B00024-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:54:00
Record Updated: 2018-03-06 11:54:00
Updated By: JPCOOK
Crossref ID: C300654
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:55:00
Record Updated: 2018-03-06 11:55:00
Updated By: JPCOOK
Crossref ID: B 5431 P 745
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Record Added Date: 2017-07-28 13:09:00
Record Updated: 2017-07-28 13:09:00
Updated By: JPCOOK

Name: FORMER BROWN MANUFACTURING SITE
Address: 101 CHESTER STREET
City,State,Zip: SYRACUSE, NY 13207
Site Code: 57206
Control Name: Environmental Easement
HW Code: B00024
Control Code: J
Control Type: INST
Dt record added: 06/11/2012
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57206
Site Description: "Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."
Env Problem: "Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified by the investigation."
Health Problem: "Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 43:02:00. / 76:09:28.
Dell: False
Record Add: 2003-10-28 13:52:00
Record Upd: 2012-10-04 14:34:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: Not reported
Owner Company: City of Syracuse
Owner Address: 203 City Hall, 233 E Washington St
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Ben Walsh
Owner Company: City of Syracuse
Owner Address: 203 City Hall
Owner Addr2: 233 E Washington Street
Owner City,St,Zip: SYRACUSE (C), NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Local History & Genealogy Department
Owner Company: Onondaga County Public Library
Owner Address: The Galleries of Syracuse
Owner Addr2: 447 South Salina Street
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Joshua Cook
Owner Company: NYSDEC Region 7
Owner Address: 615 Erie Blvd West
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13204
Owner Country: United States of America
HW Code: B00024
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Code: Not reported
HW Code: B00024
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: SELENIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

HW Code: B00024
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYR000223016
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-11-13 13:18:00
Record Updated: 2015-11-13 13:18:00
Updated By: JPCOOK
Crossref ID: 7-601599
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-01-03 13:17:00
Record Updated: 2017-01-03 13:17:00
Updated By: JPCOOK
Crossref ID: NYWII-B00024-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:54:00
Record Updated: 2018-03-06 11:54:00
Updated By: JPCOOK
Crossref ID: C300654
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:55:00
Record Updated: 2018-03-06 11:55:00
Updated By: JPCOOK
Crossref ID: B 5431 P 745
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-28 13:09:00
Record Updated: 2017-07-28 13:09:00

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Updated By: JPCOOK

Name: FORMER BROWN MANUFACTURING SITE
Address: 101 CHESTER STREET
City,State,Zip: SYRACUSE, NY 13207
Site Code: 57206
Control Name: Ground Water Use Restriction
HW Code: B00024
Control Code: 08
Control Type: INST
Dt record added: 06/11/2012
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57206
Site Description: "Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."
Env Problem: "Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

by the investigation."
Health Problem: "Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 43:02:00. / 76:09:28.
Dell: False
Record Add: 2003-10-28 13:52:00
Record Upd: 2012-10-04 14:34:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: Not reported
Owner Company: City of Syracuse
Owner Address: 203 City Hall, 233 E Washington St
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Ben Walsh
Owner Company: City of Syracuse
Owner Address: 203 City Hall
Owner Addr2: 233 E Washington Street
Owner City,St,Zip: SYRACUSE (C), NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Local History & Genealogy Department
Owner Company: Onondaga County Public Library
Owner Address: The Galleries of Syracuse
Owner Addr2: 447 South Salina Street
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Joshua Cook
Owner Company: NYSDEC Region 7
Owner Address: 615 Erie Blvd West
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13204
Owner Country: United States of America
HW Code: B00024
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: SELENIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO[K]FLUORANTHENE

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYR000223016
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-11-13 13:18:00
Record Updated: 2015-11-13 13:18:00
Updated By: JPCOOK
Crossref ID: 7-601599
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-01-03 13:17:00
Record Updated: 2017-01-03 13:17:00
Updated By: JPCOOK
Crossref ID: NYWII-B00024-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:54:00
Record Updated: 2018-03-06 11:54:00
Updated By: JPCOOK
Crossref ID: C300654
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:55:00
Record Updated: 2018-03-06 11:55:00
Updated By: JPCOOK
Crossref ID: B 5431 P 745
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-28 13:09:00
Record Updated: 2017-07-28 13:09:00
Updated By: JPCOOK

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Name: FORMER BROWN MANUFACTURING SITE
Address: 101 CHESTER STREET
City,State,Zip: SYRACUSE, NY 13207
Site Code: 57206
Control Name: Landuse Restriction
HW Code: B00024
Control Code: 25
Control Type: INST
Dt record added: 06/11/2012
Dt rec updated: 10/27/2022
Updated By: GWPRISCO
Site Code: 57206
Site Description: "Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."
Env Problem: "Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified by the investigation."
Health Problem: "Measures are in place to control the potential for coming into

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

contact with remaining subsurface soil and groundwater contamination."
Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: 43:02:00. / 76:09:28.
Dell: False
Record Add: 2003-10-28 13:52:00
Record Upd: 2012-10-04 14:34:00
Updated By: ldennist
Own Op: 1
Sub Type: C01
Owner Name: Not reported
Owner Company: City of Syracuse
Owner Address: 203 City Hall, 233 E Washington St
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: 6
Sub Type: C01
Owner Name: Ben Walsh
Owner Company: City of Syracuse
Owner Address: 203 City Hall
Owner Addr2: 233 E Washington Street
Owner City,St,Zip: SYRACUSE (C), NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Local History & Genealogy Department
Owner Company: Onondaga County Public Library
Owner Address: The Galleries of Syracuse
Owner Addr2: 447 South Salina Street
Owner City,St,Zip: Syracuse, NY 13202
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Joshua Cook
Owner Company: NYSDEC Region 7
Owner Address: 615 Erie Blvd West
Owner Addr2: Not reported
Owner City,St,Zip: Syracuse, NY 13204
Owner Country: United States of America
HW Code: B00024
Waste Type: Petroleum Products
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PHENANTHRENE
Waste Quantity: UNKNOWN

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Waste Code: Not reported
HW Code: B00024
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: SELENIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(B)FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: ARSENIC
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: DIBENZ[A,H]ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: LEAD
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

HW Code: B00024
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: COPPER
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BARIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: B00024
Waste Type: BENZO(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYR000223016
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-11-13 13:18:00
Record Updated: 2015-11-13 13:18:00
Updated By: JPCOOK
Crossref ID: 7-601599
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-01-03 13:17:00
Record Updated: 2017-01-03 13:17:00
Updated By: JPCOOK
Crossref ID: NYWII-B00024-12-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:54:00
Record Updated: 2018-03-06 11:54:00
Updated By: JPCOOK
Crossref ID: C300654
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2018-03-06 11:55:00
Record Updated: 2018-03-06 11:55:00
Updated By: JPCOOK
Crossref ID: B 5431 P 745
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-28 13:09:00
Record Updated: 2017-07-28 13:09:00
Updated By: JPCOOK

ERP:
Name: FORMER BROWN MANUFACTURING SITE

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Address:	101 CHESTER STREET
City,State,Zip:	SYRACUSE, NY 13207
Site Code:	57206
Program:	ERP
HW Code:	B00024
Site Class:	C
Class N:	C
SWIS:	3415
Region:	7
Town:	Syracuse (c)
Acres:	0.800
Record Added:	10/28/2003
Record Updated:	02/05/2024
Updated By:	GWPRISCO
Site Description:	"Location: The Former Brown Manufacturing site is located at 101 Chester Street in a residential portion of the City of Syracuse, Onondaga County. The site is located at the southeast corner of the intersection of Chester Street and Bellevue Avenue and is bordered to the north by Bellevue Avenue with residential properties and a community garden beyond, to the south by a residential property on Chester Street, to the east by residential properties along Huron Street, and to the west by Chester Street with a supermarket on the other side of Chester Street. Site Features: The site is vacant and is a generally flat parcel of land covered with grass. Current Zoning and Land Use: The site is currently vacant. Most of the surrounding parcels are residential parcels, several of which are also vacant. Past Use of the Site: The site was formerly the location of the Brown Manufacturing Corporation, an automobile parts manufacturing facility which burned down in August of 1981. Prior uses that appear to have led to site contamination include disposal of waste oil/sludge into a disposal pit and underground quenching trough. Following the fire, a remediation contractor reportedly removed and disposed of approximately 100 drums of PCB-contaminated waste oil, the contents of the disposal pit and quenching trough, and a ruptured electrical transformer. Site Geology and Hydrogeology: The investigation of the site identified two soil units. The top unit consists of fill generally ranging from 1 to 4 feet thick, but up to 8 to 12 feet thick in some areas. The fill is comprised of sand, crushed stone, concrete debris, brick, ash, cinders and wood debris. The fill was underlain by a dense silty layer that also contained some clay and fine sand which was approximately 6 to 8 feet thick. A sandy, gravelly layer was present across the site at approximately 10 to 12 feet below grade, and was underlain by more silt, clay and fine sand. The geology of the area generally consists of glaciolacustrine silt and clay, with alluvial sands and gravels present in some areas near Onondaga Creek. Those units are underlain by glacial till. Groundwater at the site was generally encountered around 9 to 11 feet below grade and flows south towards Onondaga Creek, which is located approximately 450 feet south of the site and flows generally southwest to northeast in this area."
Env Problem:	"Nature and Extent of Contamination: Prior to remediation, the primary contaminants of concern at the site included polychlorinated biphenyls (PCBs), petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and metals in soil. The most-highly contaminated soils were removed during remediation. Contaminants remain in soil below a two-foot clean soil cover system, which will be managed under a Site Management Plan. Groundwater contamination was not identified

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

by the investigation."
Health Problem: "Measures are in place to control the potential for coming into contact with remaining subsurface soil and groundwater contamination."
Not reported

NY MANIFEST:

EPA ID:	NYR000223016
Country:	USA
Name:	Brown Manufacturing Site Former
Address:	101 CHESTER ST
Address 2:	Not reported
City,State,Zip:	SYRACUSE, NY 13207
Zip 4:	Not reported
Location Address 1:	101 CHESTER STREET
Location Address 2:	Not reported
Location City,State,Zip:	SYRACUSE, NY 13207
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Brown Manufacturing Site Former
Mailing Contact:	Joshua Cook
Mailing Address 1:	201 E WASHINGTON ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SYRACUSE, NY 13202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3154267411

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD084814136
Year:	2018
Trans2 State ID:	MIK435642742
Generator Ship Date:	11/01/2016
Trans1 Recv Date:	11/01/2016
Trans2 Recv Date:	11/02/2016
TSD Site Recv Date:	11/18/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000223016
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID048090633
TSDF ID 2:	Not reported
Manifest Tracking Number:	015187140JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

BROWN MANUFACTURING SITE FORMER (Continued) **S105859104**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	B007
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	2727
Units:	Kilograms
Number of Containers:	3
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Landfill
Specific Gravity:	1

142
NNW
1/2-1
0.970 mi.
5120 ft.

NIMO - SYRACUSE - ERIE MGP **EDR MGP** **1008408047**
300 ERIC BLVD WEST **N/A**
SYRACUSE, NY 13202

Relative:
Lower

Actual:
400 ft.

EDR MGP:

No additional information available

Count: 3 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SYRACUSE	S108146406	ROTONDO WAREHOUSE	WEST DIVISION STREET	13204	NY SHWS, NY HSWDS
SYRACUSE	S113492639	SIDA PROPERTIES	SOUTH SALINA/MONTGOMERY STREET	13202	NY SHWS
SYRACUSE	S106905168	OLD TIP-TOP BAKERY	SHONNARD STREET	13204	NY SHWS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/27/2025
Date Data Arrived at EDR: 04/01/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 23

Source: EPA
Telephone: N/A
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 07/07/2025
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/27/2025
Date Data Arrived at EDR: 04/01/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 23

Source: EPA
Telephone: N/A
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 07/07/2025
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/27/2025
Date Data Arrived at EDR: 04/01/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 23

Source: EPA
Telephone: N/A
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 07/07/2025
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/20/2024
Date Data Arrived at EDR: 12/18/2024
Date Made Active in Reports: 12/20/2024
Number of Days to Update: 2

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/20/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 03/27/2025
Date Data Arrived at EDR: 04/01/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 23

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 07/21/2025
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 03/27/2025
Date Data Arrived at EDR: 04/01/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 23

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 07/21/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 11/11/2024
Date Data Arrived at EDR: 11/25/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 85

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 04/30/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 01/29/2025
Date Data Arrived at EDR: 02/18/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 12/02/2024
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 01/29/2025
Date Data Arrived at EDR: 02/18/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/10/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 02/20/2025
Date Data Arrived at EDR: 03/20/2025
Date Made Active in Reports: 06/09/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/16/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/02/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 04/23/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 1

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 03/26/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/15/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/08/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 03/17/2025
Date Data Arrived at EDR: 03/19/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 12/06/2024
Date Data Arrived at EDR: 12/11/2024
Date Made Active in Reports: 03/03/2025
Number of Days to Update: 82

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 01/31/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 05/28/2025
Number of Days to Update: 78

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 03/03/2025
Date Data Arrived at EDR: 03/04/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 78

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/09/2024
Date Data Arrived at EDR: 09/11/2024
Date Made Active in Reports: 12/06/2024
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 02/20/2025
Date Data Arrived at EDR: 03/20/2025
Date Made Active in Reports: 06/09/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 05/21/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 04/21/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/09/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 04/30/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 02/20/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 68

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 02/20/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 68

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 01/24/2025
Date Data Arrived at EDR: 01/27/2025
Date Made Active in Reports: 04/11/2025
Number of Days to Update: 74

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 04/24/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 03/27/2025
Date Data Arrived at EDR: 04/01/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 23

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 07/07/2025
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/11/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/02/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/30/2025
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 72

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/13/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/08/2025
Next Scheduled EDR Contact: 07/21/2025
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 04/03/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/08/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 04/28/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/12/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 7

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/15/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 01/13/2025
Date Data Arrived at EDR: 01/15/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 82

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/15/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/25/2025
Date Data Arrived at EDR: 05/01/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 20

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 01/01/2025
Date Data Arrived at EDR: 01/17/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 80
Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/10/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35
Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 02/26/2025
Date Data Arrived at EDR: 03/03/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 35
Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2024
Date Data Arrived at EDR: 10/02/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 100
Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/03/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 03/26/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 27
Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 04/10/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/10/2025
Date Data Arrived at EDR: 01/22/2025
Date Made Active in Reports: 04/21/2025
Number of Days to Update: 89

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 04/22/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 01/27/2025
Date Made Active in Reports: 04/21/2025
Number of Days to Update: 84

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/26/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/03/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/01/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 02/12/2025
Date Data Arrived at EDR: 02/12/2025
Date Made Active in Reports: 02/27/2025
Number of Days to Update: 15

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/15/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 03/27/2025
Date Data Arrived at EDR: 04/01/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 23

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 07/07/2025
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/18/2025
Date Made Active in Reports: 03/20/2025
Number of Days to Update: 30

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 02/19/2025
Date Data Arrived at EDR: 02/21/2025
Date Made Active in Reports: 03/20/2025
Number of Days to Update: 27

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/02/2024
Date Data Arrived at EDR: 08/20/2024
Date Made Active in Reports: 10/09/2024
Number of Days to Update: 50

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/20/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 05/28/2025
Date Data Arrived at EDR: 05/28/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 6

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Quarterly

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 05/22/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

FINDS: Facility Index System/Facility Registry System
Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/22/2025
Date Data Arrived at EDR: 05/05/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 16

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 05/05/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 12/21/2024
Date Data Arrived at EDR: 12/27/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 03/27/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites
A listing of unexploded ordnance site locations

Date of Government Version: 02/14/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 84

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 04/03/2025
Next Scheduled EDR Contact: 07/21/2025
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing
A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/14/2025
Next Scheduled EDR Contact: 09/01/2025
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/13/2025
Date Data Arrived at EDR: 02/13/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 75

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/13/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 03/07/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 03/23/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 04/17/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 03/03/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 05/15/2024
Date Data Arrived at EDR: 03/06/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 89

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 06/05/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 03/24/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 04/29/2025
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 04/02/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 03/27/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: No Update Planned

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 03/27/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Varies

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data
The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 01/12/2025
Date Data Arrived at EDR: 01/14/2025
Date Made Active in Reports: 03/20/2025
Number of Days to Update: 65

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 04/15/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Varies

UST FINDER: UST Finder Database
EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 05/08/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database
US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 05/08/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Semi-Annually

E MANIFEST: Hazardous Waste Electronic Manifest System
EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 02/17/2025
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/14/2025
Number of Days to Update: 23

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 06/04/2025
Next Scheduled EDR Contact: 09/29/2025
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List
A list of records included in the Environmental Remediation database whose material is listed as Perfluorooctanoic Acid or Perfluorooctane Sulfonic Acid.

Date of Government Version: 02/03/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/22/2025
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 12/12/2022
Date Data Arrived at EDR: 08/10/2023
Date Made Active in Reports: 10/25/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 04/24/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 05/01/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 01/09/2025
Date Data Arrived at EDR: 01/29/2025
Date Made Active in Reports: 04/11/2025
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 04/10/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 02/24/2025
Date Data Arrived at EDR: 03/20/2025
Date Made Active in Reports: 06/09/2025
Number of Days to Update: 81

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 03/05/2025
Date Data Arrived at EDR: 03/13/2025
Date Made Active in Reports: 05/27/2025
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 02/20/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 05/28/2025
Number of Days to Update: 78

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Semi-Annually

FIN ASSURANCE 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 03/26/2025
Date Data Arrived at EDR: 03/27/2025
Date Made Active in Reports: 06/18/2025
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/17/2025
Next Scheduled EDR Contact: 10/06/2025
Data Release Frequency: Quarterly

FIN ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 08/30/2024
Date Data Arrived at EDR: 08/30/2024
Date Made Active in Reports: 09/13/2024
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 12/12/2024
Date Data Arrived at EDR: 01/28/2025
Date Made Active in Reports: 04/11/2025
Number of Days to Update: 73

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 04/29/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 01/27/2025
Date Data Arrived at EDR: 01/28/2025
Date Made Active in Reports: 04/11/2025
Number of Days to Update: 73

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 04/29/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 04/24/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 01/09/2025
Date Data Arrived at EDR: 01/15/2025
Date Made Active in Reports: 04/04/2025
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 04/10/2025
Next Scheduled EDR Contact: 07/28/2025
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/08/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 02/23/2025
Date Data Arrived at EDR: 02/25/2025
Date Made Active in Reports: 05/09/2025
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 05/27/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 01/07/2025
Date Made Active in Reports: 03/25/2025
Number of Days to Update: 77

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 04/08/2025
Next Scheduled EDR Contact: 07/21/2025
Data Release Frequency: Varies

NYC LAND USE: New York City Land Use Information
Land use colors

Date of Government Version: 02/21/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 05/28/2025
Number of Days to Update: 78

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/10/2025
Next Scheduled EDR Contact: 09/22/2025
Data Release Frequency: Varies

MGP: Manufactured Gas Plants Listing
From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

Date of Government Version: 02/28/2025
Date Data Arrived at EDR: 03/04/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 06/16/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

NYC OER: OER Cleanup Sites Listing
Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

Date of Government Version: 03/03/2025
Date Data Arrived at EDR: 03/04/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 78

Source: Office of Environmental Remediation
Telephone: 212-788-8841
Last EDR Contact: 06/02/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Varies

ILI: New York State Inactive Landfill Initiative
A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. Inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants.

Date of Government Version: 05/16/2024
Date Data Arrived at EDR: 05/30/2024
Date Made Active in Reports: 08/26/2024
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-8671
Last EDR Contact: 04/24/2025
Next Scheduled EDR Contact: 08/11/2025
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: No Update Planned

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 05/21/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 05/21/2025
Next Scheduled EDR Contact: 09/08/2025
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database
This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/16/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 02/04/2025
Date Data Arrived at EDR: 02/14/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 80

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/22/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 02/04/2025
Date Data Arrived at EDR: 02/14/2025
Date Made Active in Reports: 05/05/2025
Number of Days to Update: 80

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/22/2025
Next Scheduled EDR Contact: 08/04/2025
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 02/02/2025
Date Data Arrived at EDR: 02/04/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 79

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/06/2025
Next Scheduled EDR Contact: 08/18/2025
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 03/27/2025
Next Scheduled EDR Contact: 07/14/2025
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/03/2025
Next Scheduled EDR Contact: 07/21/2025
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/07/2025
Next Scheduled EDR Contact: 08/25/2025
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 04/03/2025
Next Scheduled EDR Contact: 07/21/2025
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 09/15/2025
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

EAST ADAMS REDEVELOPMENT - PHASE 8 AREA
409 BURT STREET
SYRACUSE, NY 13202

TARGET PROPERTY COORDINATES

Latitude (North):	43.038714 - 43° 2' 19.37''
Longitude (West):	76.145026 - 76° 8' 42.09''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	406726.4
UTM Y (Meters):	4765535.0
Elevation:	404 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115660 SYRACUSE WEST, NY
Version Date:	2019
East Map:	14115658 SYRACUSE EAST, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General West

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3605950004E	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
3605950003E	FEMA Q3 Flood data
3605950015E	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
SYRACUSE WEST	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Paleozoic
System:	Silurian
Series:	Upper Silurian (Cayugan)
Code:	S3 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 8026569.2s



Target Property
SSURGO Soil
Water

SITE NAME:	East Adams Redevelopment - Phase 8 Area	CLIENT:	Langan
ADDRESS:	409 Burt Street Syracuse NY 13202	CONTACT:	Lexi Haley
LAT/LONG:	43.038714 / 76.145026	INQUIRY #:	8026569.2s
		DATE:	June 23, 2025 11:38 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Cazenovia

Soil Surface Texture: silt loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 92 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	11 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 6.6
2	11 inches	35 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 6.6
3	35 inches	59 inches	gravelly silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 6.6

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000868922	0 - 1/8 Mile SSW
A2	USGS40000868997	0 - 1/8 Mile NE
A3	USGS40000869022	1/8 - 1/4 Mile NE
4	USGS40000868887	1/8 - 1/4 Mile SE
B5	USGS40000868833	1/8 - 1/4 Mile SSE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
6	USGS40000868998	1/8 - 1/4 Mile WNW
B7	USGS40000868806	1/4 - 1/2 Mile SSE
B8	USGS40000868805	1/4 - 1/2 Mile SSE
9	USGS40000869054	1/4 - 1/2 Mile WNW
C10	USGS40000869128	1/4 - 1/2 Mile North
C11	USGS40000869129	1/4 - 1/2 Mile NNW
12	USGS40000869100	1/4 - 1/2 Mile NE
13	USGS40000869010	1/4 - 1/2 Mile ENE
14	USGS40000869138	1/4 - 1/2 Mile NNE
D15	USGS40000869066	1/4 - 1/2 Mile ENE
C16	USGS40000869167	1/4 - 1/2 Mile North
D17	USGS40000869078	1/4 - 1/2 Mile ENE
E18	USGS40000869139	1/4 - 1/2 Mile NW
F19	USGS40000869182	1/4 - 1/2 Mile NNW
20	USGS40000869194	1/4 - 1/2 Mile NNE
F21	USGS40000869183	1/4 - 1/2 Mile NNW
22	USGS40000869166	1/4 - 1/2 Mile NNE
E23	USGS40000869168	1/4 - 1/2 Mile NNW
24	USGS40000868777	1/4 - 1/2 Mile SW
25	USGS40000869218	1/4 - 1/2 Mile North
G26	USGS40000868795	1/4 - 1/2 Mile SE
E27	USGS40000869169	1/4 - 1/2 Mile NW
28	USGS40000869228	1/4 - 1/2 Mile North
G29	USGS40000868776	1/4 - 1/2 Mile SE
30	USGS40000869165	1/4 - 1/2 Mile NE
H31	USGS40000869205	1/4 - 1/2 Mile NNW
I32	USGS40000868967	1/4 - 1/2 Mile West
J33	USGS40000869140	1/4 - 1/2 Mile NW
J34	USGS40000869154	1/4 - 1/2 Mile NW
H35	USGS40000869206	1/4 - 1/2 Mile NW
J36	USGS40000869170	1/4 - 1/2 Mile NW
H37	USGS40000869246	1/4 - 1/2 Mile NNW
I38	USGS40000868946	1/2 - 1 Mile West
39	USGS40000869260	1/2 - 1 Mile NNW
H40	USGS40000869229	1/2 - 1 Mile NNW
K41	USGS40000869120	1/2 - 1 Mile WNW
K42	USGS40000869110	1/2 - 1 Mile WNW
43	USGS40000869219	1/2 - 1 Mile NW
L44	USGS40000869204	1/2 - 1 Mile NE
L45	USGS40000869203	1/2 - 1 Mile NE
46	USGS40000869282	1/2 - 1 Mile NNE
47	USGS40000868757	1/2 - 1 Mile SW
M48	USGS40000869337	1/2 - 1 Mile North
M49	USGS40000869336	1/2 - 1 Mile North
M50	USGS40000869335	1/2 - 1 Mile NNE
N51	USGS40000869370	1/2 - 1 Mile North
52	USGS40000869321	1/2 - 1 Mile NNE
O53	USGS40000869207	1/2 - 1 Mile NW
54	USGS40000868711	1/2 - 1 Mile SW
55	USGS40000869295	1/2 - 1 Mile NW
N56	USGS40000869396	1/2 - 1 Mile North
57	USGS40000869409	1/2 - 1 Mile North

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
58	USGS40000869208	1/2 - 1 Mile WNW
O59	USGS40000869230	1/2 - 1 Mile NW
Q62	USGS40000869410	1/2 - 1 Mile NNW
Q64	USGS40000869423	1/2 - 1 Mile NNW
R65	USGS40000869310	1/2 - 1 Mile NW
R66	USGS40000869283	1/2 - 1 Mile NW
S67	USGS40000869270	1/2 - 1 Mile NW
68	USGS40000868690	1/2 - 1 Mile SW
69	USGS40000869397	1/2 - 1 Mile NNW
70	USGS40000869452	1/2 - 1 Mile NNE
71	USGS40000869408	1/2 - 1 Mile NNE
72	USGS40000869460	1/2 - 1 Mile North
S73	USGS40000869311	1/2 - 1 Mile NW
T74	USGS40000869474	1/2 - 1 Mile North
75	USGS40000869209	1/2 - 1 Mile WNW
76	USGS40000869461	1/2 - 1 Mile NNW
U77	USGS40000869424	1/2 - 1 Mile NNW
T78	USGS40000869550	1/2 - 1 Mile North
V79	USGS40000869488	1/2 - 1 Mile NNE
U80	USGS40000869462	1/2 - 1 Mile NNW
U81	USGS40000869437	1/2 - 1 Mile NNW
82	USGS40000868550	1/2 - 1 Mile SSE
83	USGS40000869377	1/2 - 1 Mile NW
84	USGS40000869533	1/2 - 1 Mile North
W85	USGS40000869501	1/2 - 1 Mile NNW
X86	USGS40000869534	1/2 - 1 Mile North
W87	USGS40000869502	1/2 - 1 Mile NNW
V88	USGS40000869517	1/2 - 1 Mile NNE
X89	USGS40000869535	1/2 - 1 Mile NNW
90	USGS40000869453	1/2 - 1 Mile NNW
91	USGS40000869565	1/2 - 1 Mile North
Y92	USGS40000869489	1/2 - 1 Mile NNW
Y93	USGS40000869503	1/2 - 1 Mile NNW
X94	USGS40000869549	1/2 - 1 Mile North
95	USGS40000869566	1/2 - 1 Mile NNW
96	USGS40000868652	1/2 - 1 Mile SW
97	USGS40000869516	1/2 - 1 Mile NNE
98	USGS40000868537	1/2 - 1 Mile SSW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
P60	NYWS50000072550	1/2 - 1 Mile NNW
P61	NYWS50000072549	1/2 - 1 Mile NNW
P63	NYWS50000072462	1/2 - 1 Mile NNW

PHYSICAL SETTING SOURCE MAP - 8026569.2s



- County Boundary
- Major Roads
- Contour Lines
- Airports
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	East Adams Redevelopment - Phase 8 Area	CLIENT:	Langan
ADDRESS:	409 Burt Street Syracuse NY 13202	CONTACT:	Lexi Haley
LAT/LONG:	43.038714 / 76.145026	INQUIRY #:	8026569.2s
		DATE:	June 23, 2025 11:38 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
SSW
0 - 1/8 Mile
Lower

FED USGS **USGS40000868922**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1686		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	195912
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	155	Well Hole Depth Units:	ft

A2
NE
0 - 1/8 Mile
Higher

FED USGS **USGS40000868997**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1687		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19630709
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	69	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1963-07-09
Feet below surface:	14.7	Feet to sea level:	Not Reported
Note:	Not Reported		

A3
NE
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000869022**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 553		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	75	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

4
SE **FED USGS** **USGS40000868887**
1/8 - 1/4 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 550		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	30	Well Hole Depth Units:	ft

B5
SSE **FED USGS** **USGS40000868833**
1/8 - 1/4 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 548		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	65	Well Hole Depth Units:	ft

6
WNW **FED USGS** **USGS40000868998**
1/8 - 1/4 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1689		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610824
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	166.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1961-08-24
Feet below surface:	9.5	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B7
SSE **FED USGS** **USGS40000868806**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1772		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	20000522
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	67	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	2000-05-22
Feet below surface:	7.6	Feet to sea level:	Not Reported
Note:	Not Reported		

B8
SSE **FED USGS** **USGS40000868805**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1517		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610327
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	55	Well Hole Depth Units:	ft

9
WNW **FED USGS** **USGS40000869054**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1067		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19860207
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	151	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1986-02-07
Feet below surface:	8.7	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C10
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869128**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 580		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	113	Well Hole Depth Units:	ft

C11
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869129**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 581		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	101	Well Hole Depth Units:	ft

12
NE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000869100**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1699		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196809
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	20	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1968-09
Feet below surface:	11.3	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

13
ENE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000869010**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1700		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	197010
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	61	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1970-10
Feet below surface:	5	Feet to sea level:	Not Reported
Note:	Not Reported		

14
NNE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869138**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 554		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	63	Well Hole Depth Units:	ft

D15
ENE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000869066**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1698		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196708
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	58	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C16
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869167**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 579		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	115	Well Hole Depth Units:	ft

D17
ENE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000869078**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 518		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	49	Well Hole Depth Units:	ft

E18
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869139**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 578		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	122	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F19
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869182**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1068		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19700729
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	109.6	Well Hole Depth Units:	ft

20
NNE
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869194**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 552		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	81	Well Hole Depth Units:	ft

F21
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869183**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 582		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	119	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

22
NNE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000869166**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1693		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	197306
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	68	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1973-06
Feet below surface:	10	Feet to sea level:	Not Reported
Note:	Not Reported		

E23
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869168**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 577		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	102	Well Hole Depth Units:	ft

24
SW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000868777**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1685		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19631015
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	87.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1963-10-15
Feet below surface:	14	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

25
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869218**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1678		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196301
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	101	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1963-01
Feet below surface:	27	Feet to sea level:	Not Reported
Note:	Not Reported		

G26
SE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000868795**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1753		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	1962
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	129.5	Well Hole Depth Units:	ft

E27
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869169**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1501		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19640228
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	140	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1964-02-28
Feet below surface:	20	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

28
North
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869228**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1675		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19720309
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	112.7	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1972-03-09
Feet below surface:	15	Feet to sea level:	Not Reported
Note:	Not Reported		

G29
SE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000868776**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1754		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	1962
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	62	Well Hole Depth Units:	ft

30
NE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000869165**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1697		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196708
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	51.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1967-08
Feet below surface:	8.5	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H31
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869205**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1099		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19640217
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	140	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1964-02-17
Feet below surface:	19.0	Feet to sea level:	Not Reported
Note:	Not Reported		

I32
West
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000868967**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1073		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19790316
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	72	Well Hole Depth Units:	ft

J33
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869140**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 245	Type:	Well
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	36
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J34
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869154**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 246	Type:	Well
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	65	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

H35
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869206**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1679		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19700114
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	68.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1970-01-14
Feet below surface:	27	Feet to sea level:	Not Reported
Note:	Not Reported		

J36
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869170**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 248	Type:	Well
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	56
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H37
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000869246**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1500		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19640206
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	140	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1964-02-06
Feet below surface:	5	Feet to sea level:	Not Reported
Note:	Not Reported		

I38
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000868946**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1502		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19900308
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	70	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1990-03-08
Feet below surface:	13.9	Feet to sea level:	Not Reported
Note:	Not Reported		

39
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869260**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1677		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19720418
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	114	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1972-04-18
Feet below surface:	43.7	Feet to sea level:	Not Reported
Note:	Not Reported		

H40
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869229**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1098		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19640210
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	160	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1964-02-10
Feet below surface:	16.0	Feet to sea level:	Not Reported
Note:	Not Reported		

K41
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869120**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1716		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19580721
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	91	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1958-07-21
Feet below surface:	25	Feet to sea level:	Not Reported
Note:	Not Reported		

K42
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869110**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 549		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported

Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	91	Well Hole Depth Units:	ft

43
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869219**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 13	Type:	Well
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

L44
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000869204**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1633		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	1977
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	42.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1977
Feet below surface:	21.1	Feet to sea level:	Not Reported
Note:	Not Reported		

L45
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000869203**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1695		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196910
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	42	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1969-10
Feet below surface:	19	Feet to sea level:	Not Reported
Note:	Not Reported		

46
NNE **FED USGS** **USGS40000869282**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1696		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196910
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	80	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1969-10
Feet below surface:	16.7	Feet to sea level:	Not Reported
Note:	Not Reported		

47
SW **FED USGS** **USGS40000868757**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1072		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19980811
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	77	Well Hole Depth Units:	ft

M48
North **FED USGS** **USGS40000869337**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1513		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610603
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	110	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1961-06-03
Feet below surface:	21.4	Feet to sea level:	Not Reported
Note:	Not Reported		

M49
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000869336**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 551		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	102	Well Hole Depth Units:	ft

M50
NNE
1/2 - 1 Mile
Lower

FED USGS **USGS40000869335**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1523		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610407
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	127.3	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1961-04-07
Feet below surface:	28	Feet to sea level:	Not Reported
Note:	Not Reported		

N51
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869370**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1522		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610417
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	76	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1961-04-17
Feet below surface:	16	Feet to sea level:	Not Reported
Note:	Not Reported		

52
NNE **FED USGS** **USGS40000869321**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1694		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196910
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	56	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1969-10
Feet below surface:	13.8	Feet to sea level:	Not Reported
Note:	Not Reported		

O53
NW **FED USGS** **USGS40000869207**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1868		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	20020920	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	70
Well Hole Depth Units:	ft		

54
SW **FED USGS** **USGS40000868711**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1070		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	20010326
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	61	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

55
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869295**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1690		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19710922
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	101.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1971-09-22
Feet below surface:	29	Feet to sea level:	Not Reported
Note:	Not Reported		

N56
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869396**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 555		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	74	Well Hole Depth Units:	ft

57
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000869409**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1681		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19570716
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	32	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

58
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869208**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1777		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19950223
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	80	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1995-02-23
Feet below surface:	8	Feet to sea level:	Not Reported
Note:	Not Reported		

O59
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869230**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1867		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	20020923	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	69
Well Hole Depth Units:	ft		

P60
NNW
1/2 - 1 Mile
Lower

NY WELLS **NYWS50000072550**

WELLS:

DEC Well #:	OD02380	Well Depth (ft):	80
Bedrock Depth (ft):	-999	Groundwater Depth (ft):	30
Casing Depth (ft):	71	Casing 1 Diameter (in):	8
Casing 1 Length (ft):	64	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	Y
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	200
Well Purpose:	Not Reported	Driller Registration #:	NYRD10142
Report Date:	12-DEC-13	Drilling Start Date:	23-MAY-13
Drilling Completion Date:	24-MAY-13		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

P61
NNW
1/2 - 1 Mile
Lower

NY WELLS **NYWS50000072549**

WELLS:

DEC Well #:	OD02379	Well Depth (ft):	76
Bedrock Depth (ft):	77	Groundwater Depth (ft):	30
Casing Depth (ft):	67	Casing 1 Diameter (in):	8
Casing 1 Length (ft):	60	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	Y
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	200
Well Purpose:	Not Reported	Driller Registration #:	NYRD10142
Report Date:	12-DEC-13	Drilling Start Date:	21-MAY-13
Drilling Completion Date:	22-MAY-13		

Q62
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869410**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1682		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19710709
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	48	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1971-07-09
Feet below surface:	12.5	Feet to sea level:	Not Reported
Note:	Not Reported		

P63
NNW
1/2 - 1 Mile
Lower

NY WELLS **NYWS50000072462**

WELLS:

DEC Well #:	OD02290	Well Depth (ft):	100
Bedrock Depth (ft):	95	Groundwater Depth (ft):	20
Casing Depth (ft):	84	Casing 1 Diameter (in):	6
Casing 1 Length (ft):	84	Casing 2 Diameter (in):	Not Reported
Casing 2 Length (ft):	Not Reported	Screened Well:	Y
Screen Length (ft):	Not Reported	Avg Discharge Rate (gpm):	100
Well Purpose:	Not Reported	Driller Registration #:	NYRD10142
Report Date:	11-APR-12	Drilling Start Date:	03-APR-12
Drilling Completion Date:	03-APR-12		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q64
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869423**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 571		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	40	Well Hole Depth Units:	ft

R65
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869310**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1866		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	20051101	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	70
Well Hole Depth Units:	ft		

R66
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869283**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1854	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Unconfined single aquifer	Construction Date:	Not Reported
Well Depth:	101	Well Depth Units:	ft
Well Hole Depth:	101	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S67
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869270**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1865		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	20051118	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	101
Well Hole Depth Units:	ft		

68
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000868690**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1071		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	20010322
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	61	Well Hole Depth Units:	ft

69
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869397**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1692		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	196812
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	40	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1968-12
Feet below surface:	22	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

70
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000869452**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1853	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	New York and New England carbonate-rock aquifers		
Formation Type:	Vernon Shale	Aquifer Type:	Confined multiple aquifer
Construction Date:	20060215	Well Depth:	410
Well Depth Units:	ft	Well Hole Depth:	410
Well Hole Depth Units:	ft		

71
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000869408**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1688		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140202
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19690529
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	60	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1969-05-29
Feet below surface:	12.7	Feet to sea level:	Not Reported
Note:	Not Reported		

72
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869460**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 572		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	39	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S73
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869311**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1864		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	20051122	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	71
Well Hole Depth Units:	ft		

T74
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869474**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1516		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610412
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	58	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1961-04-12
Feet below surface:	21	Feet to sea level:	Not Reported
Note:	Not Reported		

75
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869209**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 250	Type:	Well
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	132
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

76
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869461**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1680		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	26	Well Hole Depth Units:	ft

U77
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869424**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1767		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19890910
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	47	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1989-09-10
Feet below surface:	22	Feet to sea level:	Not Reported
Note:	Not Reported		

T78
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869550**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 520		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	52	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V79
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000869488**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1518		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610510
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	72	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1961-05-10
Feet below surface:	32	Feet to sea level:	Not Reported
Note:	Not Reported		

U80
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869462**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1529		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19700713
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	58	Well Hole Depth Units:	ft

U81
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869437**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 574		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	101	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

82
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000868550**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 547		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	24	Well Hole Depth Units:	ft

83
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869377**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1869		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	20000914	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	75
Well Hole Depth Units:	ft		

84
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869533**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 565		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	60	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W85
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000869501**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1779		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19900403
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	29.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1990-04-03
Feet below surface:	12	Feet to sea level:	Not Reported
Note:	Not Reported		

X86
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869534**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 563		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	40	Well Hole Depth Units:	ft

W87
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000869502**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 558		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	55	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V88
NNE **FED USGS** **USGS40000869517**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1603		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19620702
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	70	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1962-07-02
Feet below surface:	31	Feet to sea level:	Not Reported
Note:	Not Reported		

X89
NNW **FED USGS** **USGS40000869535**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1525		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19600420
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	42	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1960-04-20
Feet below surface:	21	Feet to sea level:	Not Reported
Note:	Not Reported		

90
NNW **FED USGS** **USGS40000869453**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 573		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	100	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

91
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869565**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1631		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	1977
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	23	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1977
Feet below surface:	15.5	Feet to sea level:	Not Reported
Note:	Not Reported		

Y92
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869489**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 556		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	65	Well Hole Depth Units:	ft

Y93
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40000869503**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 557		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	55	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

X94
North
1/2 - 1 Mile
Higher

FED USGS **USGS40000869549**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD 522		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	36	Well Hole Depth Units:	ft

95
NNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000869566**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1515		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19610424
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	35	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1961-04-24
Feet below surface:	12	Feet to sea level:	Not Reported
Note:	Not Reported		

96
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000868652**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1691		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19730103
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	71.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1973-01-03
Feet below surface:	14.2	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

97
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000869516**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1604		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19620628
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	64	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1962-06-28
Feet below surface:	31	Feet to sea level:	Not Reported
Note:	Not Reported		

98
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000868537**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	OD1773		
Type:	Well: Test hole not completed as a well		
Description:	Not Reported	HUC:	04140201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	19901102
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	26.5	Well Hole Depth Units:	ft

Ground water levels,Number of Measurements:	1	Level reading date:	1990-11-02
Feet below surface:	11.7	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
ONONDAGA	CAMILLUS	980	11.38	6	188.3
ONONDAGA	CICERO	275	1.96	1.28	30.5
ONONDAGA	CLAY	328	2	1.19	30.4
ONONDAGA	DE WITT	754	10.01	3.76	346.7
ONONDAGA	ELBRIDGE	129	13.42	6.2	96.1
ONONDAGA	FABIUS	26	5.17	3.03	26.5
ONONDAGA	GEDDES	291	9.25	4.79	99.3
ONONDAGA	LAFAYETTE	105	7.39	4.25	95.6
ONONDAGA	LYSANDER	272	4.14	2.1	89.1
ONONDAGA	MANLIUS	1,442	11.4	5.03	341.8
ONONDAGA	MARCELLUS	251	5.91	3.39	98
ONONDAGA	ONONDAGA	294	10.8	5.9	89.4
ONONDAGA	OTISCO	21	7.32	3.64	40.1
ONONDAGA	POMPEY	105	6.84	4.7	35
ONONDAGA	SALINA	449	2.49	1.49	69.5
ONONDAGA	SKANEATELES	203	4.39	2.43	105.7
ONONDAGA	SPAFFORD	16	3.66	2.32	8.8
ONONDAGA	SYRACUSE	2,334	6.8	3.48	185.4
ONONDAGA	TULLY	140	18.29	8.48	165.2
ONONDAGA	VAN BUREN	119	6.68	2.5	70.1

Federal EPA Radon Zone for ONONDAGA County: 1

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for ONONDAGA COUNTY, NY

Number of sites tested: 476

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	1.760 pCi/L	76%	21%	3%
Basement	3.000 pCi/L	62%	29%	9%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Appendix G Resumes of Environmental Professionals

BRIAN GOCHENAUR, QEP

ASSOCIATE PRINCIPAL

ENVIRONMENTAL SCIENTIST

Mr. Gochenaur is an environmental project manager with 20 years of experience in environmental due diligence, site investigation and remediation, fuel oil storage tank investigation and removal, soil vapor intrusion assessments, in-situ remedial technology, spill closure, vapor barrier and sub-slab depressurization system design and construction, emergency response, environmental and geotechnical site investigations, and health and safety monitoring. He has extensive experience with the New York State Department of Environmental Conservation (NYSDEC) Brownfield Cleanup, Voluntary Cleanup and Spill Programs and New York City Department of Environmental Protection (NYCDEP) "E" Designated and New York City Voluntary Cleanup Program (BCP) sites. His areas of expertise include Phase I Environmental Site Assessments, Phase II Site Investigations, and environmental consulting and oversight on large scale construction projects.

EDUCATION

B.S., Environmental Science
University of Florida

PROFESSIONAL REGISTRATION

Qualified Environmental Professional (QEP) certified by the Institute of Professional Environmental Practice

40-Hour OSHA (HAZWOPER)

SELECTED PROJECTS

- 440 Washington Street, E-Designated services, New York, NY
- 3514 Surf Avenue, Tall Residential and Retail Building, Brooklyn, NY
- ARO 242 West 53, Tall Residential Building, New York, NY
- NY Aquarium Shark Exhibit, Soil Characterization and Excavation Oversight, Coney Island Neighborhood, Brooklyn, NY
- 60 West Street, Site Investigation and Redevelopment, Brooklyn, NY
- 535 4th Avenue, BCP Auto Repair Cleanup and Redevelopment, Brooklyn, NY
- 1525 Bedford Avenue, BCP Gas Station Cleanup and Redevelopment, Brooklyn, NY
- 220 Eleventh Avenue, Residential Building, New York, NY
- 432 Rodney Street, Residential Building, Brooklyn, NY
- 563 Sackett Street, Brooklyn, NY
- 362 West 125th Street, Residential Building, New York, NY
- Bedford Armory Redevelopment, Brooklyn, NY
- 268 West Street, BCP Redevelopment of Former Commercial and Industrial Site, New York, NY
- 110 125th Street, Soil Excavation and Remediation, New York, NY
- Former Roseland Ballroom Redevelopment, Soil Characterization and Excavation Oversight, New York, NY
- 42 Crosby Street, "E" Designated Site Investigation and Remediation, New York, NY
- New York School Construction Authority, Various Locations, In-House Environmental Consulting, Five Boroughs of New York City
- EZ Serve Portfolio, GE Capital, Various Phase II Site Investigations, FL, GA, LA, and MS
- Beth Elohim Child Daycare Center, Lead Based Paint Abatement, Brooklyn, NY
- Price Battery, Environmental Protection Agency (EPA) Lead Fallout Superfund Site, Hamburg, PA

- Clark Portfolio, GE Capital, Various Phase II Locations, MI, IL, ID, and OH
- Tops Plaza Portfolio, Prudential Real Estate Investors, Various Phase II Locations, NY
- Cingular Wireless Portfolio, Cingular Wireless, Various Locations Phase I and II Locations, WA
- Queens Center Mall Expansion, Remedial Oversight, Elmhurst, NY
- Soka Gakkai International-USA, Cultural Center, Brooklyn, NY
- 1752 Shore Parkway, Environmental Remediation, Brooklyn, NY
- Bedford Union Armory, NYS Brownfield Cleanup Program, Brooklyn, NY
- NYCEDC Manhattan Greenway – Harlem River, New York, NY
- 445 Gerard Avenue, Residential Building, Bronx, NY
- Towne Gardens North, Residential Building, Buffalo, NY

DANIEL DEAN, PG

SENIOR PROJECT MANAGER

ENVIRONMENTAL ENGINEERING, REMIDIATION

Daniel Dean is an environmental engineer with 19 years of expertise in environmental remediation, compliance, and assessment. He manages diverse environmental projects successfully from conception to completion on schedule and within budgets.

SELECTED PROJECTS

- Utah Department of Environmental Quality, Division of Environmental Response and Remediation Brownfields Assessment Grant, Multiple Locations, UT*
- Confidential Client, Salt Lake City, UT*
- Salt Lake County Brownfields Assessment Grant, Multiple Locations, UT*
- Spanish Fork City Brownfields Assessment Grant, Spanish Fork City, UT*
- Green River Brownfields Assessment Grant, Green River, UT*
- Assessment of Explosive Gases in Soil, Provo, UT*
- Baseline Groundwater Radiological Assessment, West Valley City, UT*
- Stadium Chevron Petroleum Release, Provo, UT*
- TA Travel Center Petroleum Release, Provo, UT*
- Former Kanab Firing Range, Kanab, UT*
- Former Mark Steel Facility, Salt Lake City, UT*
- Biotreatment of Mine Drainage, Rico, CO*
- Montage Hotel, Deer Valley, UT*
- Sierra Zinc Mine and Mill, Colville, WA*
- Empire Canyon, Park City, UT*
- Richardson Flat Tailings Site, Park City, UT*
- Flagstaff Smelter, Sandy UT*
- Remediation of Hazardous Mill Tailings from Gray Eagle Mill, Joshua Tree National Park, CA*
- Preliminary Assessment of Potentially Hazardous Sites, Tule Springs Fossil Beds National Monument, NV*
- Site Inspection for Former Firing Range, Lassen Volcanic National Park, CA*
- Stehekin and Newhalem Firing Ranges, North Cascades National Park Complex, WA*
- Block P Mine Complex and Mill Tailings Site, Hughesville, MT*
- The Doe Run Company NPDES Permitting Compliance, Viburnum, MO*

EDUCATION

B.S, Earth Science
California Polytechnic State University - San Luis Obispo

PROFESSIONAL REGISTRATION

Professional Geologist (PG) in UT

Certified UST Consultant in UT

Certified Environmental Specialist

40-Hour HAZWOPER (renewed annually)

LTAP Stormwater Inspector Training in UT

AFFILIATIONS

Rocky Mountain Association of Environmental Professionals

**Work performed prior to joining Langan.*

SELECTED PUBLICATIONS, REPORTS, AND PRESENTATIONS

Fricke, James Ross; Dean, Daniel Miller: Use of a Biological Polishing Step to Improve Bioassay Test Results.—In: Brown, A.; Figueroa, L. & Wolkersdorfer, Ch.: Reliable Mine Water Technology (Vol I).—p. 337—341; Denver, Colorado, USA. 2013.

Dan Dean and Jim Fricke (REMC, Inc), Terry Moore and Tony R Brown (BP/Atlantic Richfield Remediation Management) and A.C. “Sandy” Riese (EnSci, Inc). Use of Constructed Wetlands to Reduce Metals in Drainage from a High Altitude Mine System, SW Colorado: Treatment Options and Vertical System. Proceedings of the 24th Annual British Columbia-MEND ML/ARD Workshop. November 2017.

Daniel M. Dean, James R. Fricke, Arthur C. Riese, Terry J. Moore, Anthony R. Brown. Passive Treatment of Circumneutral Mine Drainage from the St. Louis Mine Tunnel, Rico CO: Part 2—Vertical Biotreatment Train Pilot Study. Mine Water and the Environment. May 2022.

MAXWELL G. SHARP, CABI, EIT

STAFF ENGINEER

ENVIRONMENTAL ENGINEERING

Maxwell is an experienced environmental engineer with a bachelor's degree from Syracuse University and a master's degree from the Colorado School of Mines. He has a strong background in data analysis and validation and gained invaluable experience overseeing daily effluent sampling at a wastewater treatment plant in Butte, Montana. In his current role, Maxwell is responsible for conducting Phase I and Phase II Environmental Site Assessments (ESAs), soil, groundwater, and soil vapor sampling, performing asbestos-related building inspections, as well as managing stormwater permitting and compliance. Additionally, he excels in data analysis and report writing.

Maxwell's diverse background includes providing compliance services for the Berkely Pit Mine in Butte, Montana, conducting stormwater and groundwater sampling across polluted sites in Colorado, Nebraska, and Kansas. He has also contributed to the development of compliance reports for wastewater treatment and played a key role in the operations and maintenance of sump pump stations for the Regional Transportation District (RTD). Moreover, he has worked on abandoned monitoring wells in Wyoming, showcasing his versatility and expertise in the field.

SELECTED PROJECTS

- Distribution Center (DALz1), Phase I Environmental Site Assessment (ESA), Cleburne, TX
- Distribution Center (DGC3), Phase I Environmental Site Assessment (ESA), Oklahoma City, OK
- Distribution Center (LAS2), Phase II Environmental Site Investigation (ESI), Las Vegas, NV
- Distribution Center (Project Falcon), Environmental Construction Oversight and Air Monitoring, Kansas City, MO
- Distribution Center (WCO5), Phase I and Phase II Environmental Site Assessment (ESA), Montrose, CO
- Distribution Center (WMT4), Phase I and Phase II Environmental Site Assessment (ESA), Kalispell, MT
- Distribution Center (WUT9), Phase I and Phase II Environmental Site Assessment (ESA), Price, UT
- East Houston Oil and Gas Properties, Environmental Engineering Services, Baytown, TX
- Equipment Rental and Maintenance Facility (Wagner), Phase I Environmental Site Assessment (ESA), Colorado Springs, CO
- Equipment Rental and Maintenance Facility (Wagner), Phase I Environmental Site Assessment (ESA) and Phase II Environmental Site Investigation (ESI), Denver, CO
- Former Lumen Communications Campus (Stacklot), Regulated Building Materials (RBM) Services, Denver, CO
- Gardner Cryogenics- Manufacturing Facility, Phase II Environmental Site Investigation (ESI), Liberal, KS

EDUCATION

M.S., Environmental Engineering, Colorado School of Mines

B.S., Environmental Engineering, Syracuse University

PROFESSIONAL REGISTRATION

Colorado Department of Public Health & Environment (CDPHE), Certified Asbestos Building Inspector (29350)

Asbestos Hazard Emergency Response Act of 1986 (AHERA), Certified Asbestos Building Inspector

Engineer-in-Training (EIT), CO

40-Hour OSHA HAZWOPER

8-Hour OSHA HAZWOPER Refresher

Utah Certified Asbestos Building Inspector

- Victory Crossing, Mixed-Use Development (Rocky Mountain Arsenal Wildlife Refuge), Environmental and Geotechnical Engineering Services, Commerce City, CO
- Wasatch Peaks Ranch, Private Ski Resort, Geotechnical Observation, Peterson, UT
- 5595 Federal Boulevard, Phase I and Phase II Environmental Site Assessment (ESA), Denver, CO
- 16270 E. Arapahoe Road, Mechanically Stabilized Earth (MSE) Wall Repair, Geotechnical Observation, Foxfield, CO

OLIVIA MILLER

STAFF GEOLOGIST

ENVIRONMENTAL ENGINEERING

Ms. Miller is a staff geologist with over 4 years of experience in Phase I ESA's and due diligence. She has worked on various projects throughout Long Island, New York City, New Jersey, Connecticut, and Massachusetts. Ms. Miller is responsible for providing site exploration activities including, contaminated site investigation and remediation work; soil and groundwater sampling; vapor intrusion investigation; remedial investigation, design, implementation, and monitoring; pilot tests; data management, processing, and evaluation; and report preparation.

SELECTED PROJECTS

- Alafia/Brooklyn Development Center, Brooklyn, NY
- 95 Lombardy Street, Brooklyn, NY
- 98 Anthony Street, Brooklyn, NY
- 250 Water Street, New York, NY
- 305 Nevins Street, Brooklyn, NY
- 36-24 12th Street, Astoria, NY
- 111 Washington Street, New York, NY
- President Street Properties, Brooklyn, NY
- 353-361 Bedford Avenue, Brooklyn, NY
- Bronx Point, BCP Services, Bronx, NY
- Willets Point Redevelopment, Flushing, NY
- NYPD 116th Precinct, Rosedale, NY
- 8 Carlisle Street, New York, NY
- Jamaica Hospital Medical Center, Jamaica, NY
- 77-57 Vleigh Pl., BCP Services, Flushing, NY*
- LaGuardia Airport, Queens, NY*
- Former Darby Drugs, 80-100 Banks Avenue, Rockville Centre, NY*
- Georgica Ventures, East Hampton, NY*
- Residential fuel spill, Nesconset, NY*
- Alphamed Bottles, Central Islip, NY*

EDUCATION

B.S., Geology
Stony Brook University

PROFESSIONAL REGISTRATION

OSHA 40-Hour HAZWOPER

OSHA 10-Hour

Construction Safety and Health

NYSDEC 4-Hour Erosion and Sediment Control Training

AFFILIATIONS

Long Island Association of Professional Geologists (LIAPG) – Board Member

**Projects represent experience with a previous firm*