October 24, 2025

Ms. Angela Orlando
Quanta Services, Inc. and Affiliates
2727 North Loop West
Houston, Texas 77008

RE: Phase I Environmental Site Assessment
Commercial Property
24 Anderson Road
Buffalo (Cheektowaga), Erie County, New York 14225
Farmer Project No.: 235.984

Dear Ms. Orlando,

Farmer Environmental Group LLC is pleased to submit this Phase I Environmental Site Assessment (ESA) report to Quanta Services, Inc. and Affiliates. This report discusses background information, purpose and scope of work, execution of work, conclusions and recommendations (if applicable) for the Subject Property.

Regarding the continued viability of this ESA, ASTM International Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E1527-21) states that an ESA "meeting or exceeding" this practice and completed less than 180 days prior to the date of acquisition of the property or (for transactions not involving an acquisition) the date of the intended transaction is presumed to be valid. Based on this viability statement, this ESA report is presumed to be valid for 180 days after October 1, 2025.

We appreciate the opportunity to provide professional environmental services to you and if you have any questions or comments regarding this report, please contact the undersigned at (972) 285-1051.

Sincerely,
Farmer Environmental Group, LLC

Matt Burleigh
Director of Environmental Services

Roy D. King
Environmental Project Manager

Phase I Environmental Site Assessment

Commercial Property
24 Anderson Road
Buffalo (Cheektowaga), Erie County, New York

October 24, 2025

Prepared for:

Ms. Angela Orlando
Quanta Services, Inc. and Affiliates
2727 North Loop West
Houston, Texas 77008

Prepared by:

Farmer Environmental Group, LLC
309 North Galloway Avenue, Suite 105
Mesquite, Texas 75149

Farmer Project No. 235.984

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Commercial Property
24 Anderson Road
Buffalo (Cheektowaga), Erie County, New York

TABLE OF CONTENTS

EXECUTIVE SUMMARY 1
1.0 INTRODUCTION 4
1.1 Purpose 4
1.2 Scope of Services 5
1.3 Significant Assumptions 7
1.4 Limitations and Exceptions 7
1.5 Special Terms and Conditions 8
1.6 User Reliance 8
2.0 SUBJECT PROPERTY OVERVIEW 10
3.0 SITE BACKGROUND/OPERATING HISTORY 12
3.1 History of Ownership/Title Records 12
3.2 Review of Aerial Photographs 12
3.3 Historical Maps and Documents 14
3.4 Previous Assessment Reports 16
3.5 Interviews Regarding Historical Uses 18
3.6 Summary of Historical Information 19
4.0 ENVIRONMENTAL SETTING 21
4.1 Topography 21
4.2 Geology 21
4.3 Hydrology 21
5.0 RESULTS OF THE ON-SITE INVESTIGATION 23
5.1 Methodology and Limiting Conditions 23
5.2 Observations 23
5.3 Adjoining Property Observations 26
6.0 REGULATORY/GOVERNMENTAL AGENCY INQUIRIES 27
6.1 Federal and State Regulatory Agencies 27
6.2 Local Government Inquiries 35
6.3 Limited Vapor Encroachment Screening 36
7.0 CONCLUSIONS 38
8.0 CERTIFICATION AND QUALIFICATIONS 39
9.0 REFERENCES 40

APPENDICES

Appendix A	Figure 1 – Topographic Site Map
	Figure 2 – Aerial Site Map
Appendix B	Subject Property Documents
Appendix C	Subject Property Photographs
Appendix D	ASTM Questionnaires and Records of Communication
Appendix E	Historical Resources
Appendix F	Regulatory Database Report and Documentation
Appendix G	Prior Environmental Reports
Appendix H	Farmer Qualifications

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Commercial Property
24 Anderson Road
Buffalo (Cheektowaga), Erie County, New York

EXECUTIVE SUMMARY

On September 11, 2025, Farmer Environmental Group, LLC (Farmer) was contracted by Quanta Services, Inc. and Affiliates (the "Client" herein) to conduct a Phase I Environmental Site Assessment (ESA) of a commercial property located at 24 Anderson Road in Buffalo (Cheektowaga), Erie County, New York (the "Subject Property"), as shown on Figure 1 and Figure 2 herein and further detailed in this report. The scope of service, objectives, extent and limitations of the services and this report are described in more detail in the text of this report.

This Phase I ESA was performed in general accordance with the ASTM International Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E1527-21) and is further described in the applicable sections and appendices of this report (Limitations and Scope of Work) with consideration of general industry standards. The purpose of this Phase I ESA was to identify *recognized environmental conditions* as defined by ASTM E1527-21.

The Subject Property consisted of a commercial property located at 24 Anderson Road in Cheektowaga, Erie County, New York. Based on information obtained from the Erie County Online Mapping System (ECOMS), a property survey prepared by BME Associates, and Farmer's site reconnaissance, the Subject Property encompassed 1.045 acres of land improved with a commercial building including offices and warehouse areas. According to the Key Site Manager, Green Mountain Electric Supply (GMES) recently vacated the building which they had occupied since approximately 2023. GMES had previously used the Subject Property for wholesale of electrical equipment and supplies. The Erie County data identified the current owner of the Subject Property as Recovery Real Estate Holdings LLC.

The Subject Property improvements included a single-story commercial building containing 25,200 square feet (SF) of office and warehouse space apparently constructed in the 1940s. A second-floor office space was present in the southeastern corner of the building and a second-floor bathroom and storage area were located over the northeastern corner of the building. The Subject Property building appeared to consist of masonry and block construction situated on a concrete slab foundation. Additional improvements included asphalt-paved access drives (via Anderson Road) and surface parking areas (north and south of the building), concrete-paved flatwork and limited perimeter security fencing. Interior finishes within the office areas appeared to include wood-framed walls covered with painted and textured sheetrock or wood paneling, drop-down tiled ceilings and carpet- or tile-covered floors. Interior finishes within the warehouse areas appeared to be limited to concrete flooring with exposed steel supports. The warehouse was equipped with one grade-level loading dock door in the western wall of the building. The general Subject Property observations and mechanical systems are discussed in Section 5.2.

The findings and conclusions of this assessment are as follows:

Report Section		De Minimis Condition	Historical REC	CREC	REC	Description
3.6	Historical Information				X	See Note 1
5.2	Sewage Disposal/Septic System					
5.2	Storage Tanks and Associated Equipment					
5.2	Hazardous Chemicals and Petroleum Products					
5.2	Surface Staining, Corrosion, and Stressed Vegetation					
5.2	Polychlorinated Biphenyls					
5.2	Drains, Sumps, and Pre-Treatment Systems					
5.2	Pits, Ponds, and Lagoons					
5.2	Solid Waste Disposal					
5.2	Wastewater Discharges					
5.2	Wells and Cisterns					
5.2	Railroad Spurs and Pipelines					
5.3	Adjoining Properties					
6.1	Federal and State Regulatory Agencies				X	See Note 2
6.2	Local Government Inquires					
6.3	Limited Vapor Encroachment Screening				X	See Note 3
NA	Other					

REC – Recognized Environmental Condition / CREC – Controlled Recognized Environmental Condition / NA – Not Applicable

Farmer has performed a Phase I ESA in general conformance with the scope and limitations of ASTM E1527-21 of the Subject Property. Any exceptions to or deletions from, this practice are described in applicable sections of this report.

- This assessment has revealed no evidence of *recognized environmental conditions* in connection with the Subject Property except for the following.

Note 1

As discussed in Section 3.6, the Subject Property building has since 1963 been occupied by Kolk Manufacturing Inc. (silverware manufacturer), Bison Electrical Co. (electrical supplies warehouse), Buff Imprints, Inc. (silkscreen and textiles printing operation) and Davis Electrical Supply Co. (early-1980s to 2022). Based on the potential for the historical, on-site use and possible release of chlorinated solvents which have been documented in soil and groundwater at the Subject Property (see below and Section 3.4), Farmer's review of historical resources, regulatory records and site reconnaissance has identified a *recognized environmental condition* attributable to historical uses of the Subject Property.

Note 2

The former south-adjoining Rotary Company (RoCo) located at 1746 Dale Road was previously operated as a metal and plastic fabricating facility from 1946 to 1994. Environmental site assessments in the late-1990s and early-2000s identified chlorinated volatile organic compounds (CVOCs) in soil and groundwater at the RoCo property, on the west-adjoining Upstate Farms Cooperative (UFC) facility and on the Subject Property. During this period, Trichloroethylene (TCE) was identified in soil and groundwater beneath the RoCo property as well as adjacent sites

at concentrations exceeding New York State Department of Environmental Conservation (NYSDEC) Unrestricted Use Soil Cleanup Objectives (SCOs) and Class GA (groundwater used for potable water) standards.

RoCo entered into the NYSDEC Voluntary Cleanup Program (VCP) in 2001, which resulted in treatment of impacted groundwater using Hydrogen Release Compound or HRC®. In 2007, RoCo also completed soil vapor and indoor air sampling in the southern portion of the Subject Property building. TCE was detected in sub-slab soil vapor/indoor air samples collected from within the Subject Property building (SS#5 and SS#6), with concentrations observed at SS#6 (17.7 / 1.08 micrograms per cubic meter, µg/m^3 or parts per billion – ppb) exceeding the current (May 2017, updated 2024) New York State Department of Health (NYSDOH) soil vapor/indoor Air Matrix A Guidelines for sub-slab soil vapor mitigation. At the time of the 2007 investigation, NYSDOH guidelines recommended only continued monitoring. Application of HRC® resulted in significant reduction of chlorinated VOC concentrations in both groundwater and soil gas. Operation of a soil vapor extraction (SVE) system further provided significant reductions in some contaminants.

A deed restriction was filed in 2011 for the RoCo property and a Site Management Plan (SMP) was instituted to control uses of the property. The SMP indicated continuing soil vapor intrusion (sub-slab vapor and indoor air) monitoring on the Subject Property at sampling locations SS#5 and SS#6. Regulatory records indicated the Subject Property owner reportedly did not allow access to the Subject Property building for the recommended sampling.

In the early 2010s, RoCo reportedly abandoned the site and terminated participation in the VCP. In 2017, new site owners completed additional groundwater and soil vapor sampling at the site, and groundwater sampling on the Subject Property (see Section 3.4). However, total VOC concentrations rebounded by 2017 (dehalogenated from TCE to Dichloroethylene [DCE] and vinyl Chloride [VC]), requiring updated monitoring in the northwest corner of the RoCo property. During groundwater sampling in May 2020, cis-DCE and VC were detected on the RoCo property at concentrations (8,800 and 23,000 micrograms per liter, µg/L or ppb, respectively) exceeding applicable Class GA standards. During this same period, only concentrations of cis-DCE were detected in Subject Property groundwater (well GW-1) above Class GA standards.

Based on historical releases of CVOCs at the RoCo site that were documented to have impacted Subject Property soil, groundwater and soil vapor at concentrations that exceed NYSDEC standards / guidance and are indicative of potential vapor intrusion, the regulatory listings associated with the RoCo facility appear to represent a *recognized environmental condition* in connection with the Subject Property.

Note 3

The impacts to on-site groundwater and soil vapor have been documented due to releases of chlorinated solvents to the subsurface at the south-adjoining RoCo property, which appears to represent a VEC to the Subject Property. This VEC appears to represent a *recognized environmental condition* in connection with the Subject Property.

This summary is for convenience only and should not be relied upon without first reading the full contents of this report, including appended materials.

1.0 INTRODUCTION

1.1 Purpose

The purpose of this practice is to define good commercial and customary practice in the United States of America for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. § 9601) and petroleum products. As such, this practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner or bona fide prospective purchaser limitations on CERCLA liability (hereinafter, the "landowner liability protections" or "LLPs"): that is, the practice that constitutes all appropriate inquiries into the previous ownership and uses of the property consistent with good commercial and customary standards and practices as defined at 42 U.S.C. § 9601(35)(B) (See Appendix X1 for an outline of CERCLA's liability and defense provisions). Controlled substances are not included within the scope of this practice. Persons conducting an environmental site assessment as part of an EPA Brownfields Assessment and Characterization Grant awarded under CERCLA 42 U.S.C. § 9604(k)(2)(B) must include controlled substances as defined in the Controlled Substances Act (21 U.S.C. § 802) within the scope of the assessment investigations to the extent directed in the terms and conditions of the specific grant or cooperative agreement. Additionally, an evaluation of business environmental risk (BER) associated with a parcel of commercial real estate may necessitate investigation beyond that identified in this practice (see 1.4 and Section 13).

The purpose of this Phase I ESA is to identify, to the extent feasible pursuant to the processes prescribed by ASTM E1527-21, *recognized environmental conditions* in connection with the Subject Property.

Recognized Environmental Condition - The goal of the processes established by this practice is to identify *recognized environmental conditions*. The term *recognized environmental condition* means *(1)* the presence of hazardous substances or petroleum products in, on or at the Subject Property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on or at the Subject Property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on or at the Subject Property under conditions that pose a material threat of a future release to the environment. A *de minimis condition* is not a *recognized environmental condition*.

For the purposes of this definition, "likely" is that which is neither certain nor proved but can be expected or believed by a reasonable observer based on the logic and/or experience of the environmental professional, and/or available evidence as stated in the report to support the opinions given therein.

Controlled Recognized Environmental Condition - *Recognized environmental condition* affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls (for example, activity and use limitations or other property use limitations).

Historical Recognized Environmental Condition – A previous release of hazardous substances or petroleum products affecting the Subject Property that has been addressed to the satisfaction of

the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the Subject Property to any controls (for example, activity and use limitations or other property use limitations). A *historical recognized environmental condition* is not a *recognized environmental condition*.

De Minimis Condition - A condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis condition* is not a *recognized environmental condition* nor a *controlled recognized environmental condition*.

1.2 Scope of Services

The scope of services was performed in general conformance with ASTM E1527-21 and is further described in the applicable sections of this report with consideration of general industry standards. The purpose of this ESA was to identify "*recognized environmental conditions*" as defined by ASTM E1527-21. The scope of this contract included the following tasks.

TASK 1: Subject Property reconnaissance
TASK 2: Surrounding land use observations
TASK 3: Geological, hydrological and topographical information
TASK 4: Historical review of the Subject Property and adjoining area records and use
TASK 5: Regulatory review of current and past activities on the Subject Property and nearby properties
TASK 6: Data evaluation
TASK 7: Report preparation

Non-scope considerations, including but not limited to soil sampling, groundwater or surface water testing, building materials sampling, drinking water testing or other sampling and testing were not included in the scope of services of this ESA. This ESA is not a compliance audit, health and safety audit or an additional phase of environmental or engineering services and may not be construed as such. Where analytical results are available, the potential for contamination from these sources was evaluated and the results were included in this assessment.

The Phase I ESA consisted of a historical review of the Subject Property and area use, regulatory database review, assessment of the physical setting, Subject Property and area reconnaissance and a report of Farmer's findings, opinions, conclusions and recommendations. Data gaps or deviations from this standard (if applicable) are described in pertinent sections of this report.

Subject Property and Area Use

By reviewing or obtaining selected sources of reasonably ascertainable public information, Farmer reviewed the current and historical uses of the Subject Property. The Phase I ESA historical review attempts to extend back until at least 1940 or, for uses prior to that date, back to the time the Subject Property was undeveloped. Sources of historical use information relating to the Subject Property and its adjoining properties were acquired and/or reviewed according to the reasonable availability of the information, the time limits provided for data acquisition and review, as permitted, by the project schedule and cost and Farmer's judgment of the likely value of the information for indicating environmental concerns. Historical sources reviewed by Farmer are identified in Section 9.0 (provided in Appendix E) and typically include local city directories, aerial

photographs and topographic maps. If available through the database provider, the historical sources reviewed also included historical fire insurance maps.

Regulatory Status Review

Farmer reviewed a report of select regulatory databases published for the local area to identify facilities potentially constituting a suspect *recognized environmental condition* in connection with the Subject Property. Farmer reviewed the databases to identify recorded facilities located on or in close proximity to, the Subject Property using the ASTM E1527-21 standard environmental record sources and recommended approximate minimum search distances.

Farmer attempted to obtain additional information regarding listed facilities that, in its professional judgment, may constitute *recognized environmental conditions* in connection with the Subject Property. In addition, local agencies were contacted regarding recorded information, incidents or activities of environmental concern relating to the Subject Property and its nearby properties.

If deemed reasonably ascertainable, necessary or within the Client-approved scope of work, Farmer has conducted additional file review to obtain sufficient information in connection with regulatory listings of potential environmental concern, if insufficient information was provided via standard sources. If, in Farmer's opinion, such a review is not warranted, Farmer has explained within the report the justification for not conducting additional regulatory file review.

As an alternative, Farmer may have reviewed files/records from an alternative source(s) such as on-site records, user provided records, records from local government agencies, interviews with regulatory officials and/or other individuals knowledgeable about the environmental conditions that resulted in the standard environmental record source listing.

Subject Property Physical Setting

Farmer obtained and reviewed reasonably ascertainable published Subject Property information to characterize the physical setting of the Subject Property. Sources reviewed are identified in Section 4.0 of this report. If reasonably ascertainable, Farmer reviewed the current United States Geological Survey (USGS) 7.5 Minute Topographic Map showing the area on which the Subject Property is located. Farmer reviewed one or more physical setting sources at the discretion of the Environmental Professional to obtain information about the geologic, hydrogeologic, hydrologic or topographic characteristics of the Subject Property. Discretionary physical setting sources may have been sought if (1) conditions had been identified in which hazardous substances or petroleum products are likely to be present on-site or to migrate to the Subject Property from off-site sources and (2) more information is generally obtained, pursuant to local good commercial or customary practice.

Subject Property and Area Reconnaissance

The Subject Property and area reconnaissance consisted of field observations of the Subject Property and adjoining land areas by Farmer personnel experienced in conducting environmental site assessments. Farmer observed and documented current uses of the Subject Property and indicators of hazardous chemicals, petroleum products, storage tanks, odors, pools of liquid, drums, containers, polychlorinated biphenyls (PCBs), heating and cooling systems, stains, corrosion, drains and sumps, pits, ponds, lagoons, stressed vegetation, wastes, wells and septic systems. The area reconnaissance was performed in publicly accessible areas on foot within

areas that were reasonably accessible and at Farmer's discretion by automobile along public roads.

1.3 Significant Assumptions

Information obtained from the Client, the Client's representative, Subject Property owner(s), individuals interviewed, prior environmental reports, regulatory information and information obtained from referenced sources was considered accurate unless Farmer's reasonable inquiries clearly revealed otherwise. Conditions observed were considered representative of areas that were not observed unless otherwise indicated.

The primary direction of groundwater flow was assumed to be dictated by topography and readily accessible geologic information, unless otherwise indicated by measurement of potentiometric surface or other quantifiable data. Additionally, the groundwater flow direction was assumed to control the distribution of impact, if present.

1.4 Limitations and Exceptions

A Phase I ESA is conducted to permit formulation of an opinion as to the potential for environmental liabilities at the Subject Property based on the gathering of limited information and observations. A Phase I ESA is not a comprehensive site characterization and should not be construed as such. The purpose of conducting the Phase I ESA is to reduce, not eliminate, the risk of an entity in its plans or purposes for the Subject Property. The conclusions expressed by Farmer regarding the conditions of the Subject Property addressed herein are based solely on the limited observations made and the data collected during this Phase I ESA. The beneficiaries of this Phase I ESA are hereby advised that conditions observed are subject to change.

The findings and conclusions presented in this ESA are relative to the dates the work was conducted and should not be relied on to represent conditions at later dates. The opinions included herein are based on information obtained during the assessment and Farmer's experience. If additional information becomes available that may influence Farmer's environmental assessment findings, Farmer requests the opportunity to review the information, reassess the potential concerns and modify Farmer's opinions, if warranted.

This assessment included visual observations to identify obvious features or conditions indicative of recognized environmental conditions.

Although this assessment has attempted to identify recognized environmental conditions, Farmer cannot eliminate all uncertainty as to recognized environmental conditions in connection with the Subject Property nor represent or warrant that the Subject Property contains no hazardous substances or petroleum products or other latent conditions beyond those identified through the scope of work identified herein. Other features, conditions and constituents may have escaped detection due to: (1) the limited scope of this assessment as driven by Client objectives, (2) the inaccuracy of public records or information reviewed by Farmer, (3) environmental incidents that may have gone undetected or unreported prior to this assessment, (4) inaccessible areas and/or (5) deliberate concealment of detrimental information.

Farmer's professional services have been performed using the degree of care and skill ordinarily exercised, under similar conditions, by reputable environmental consultants undertaking similar studies and practicing in this locality during the same timeframe. No other warranties, express or

implied, are intended or made with respect to this report or Farmer's services. This assessment was not exhaustive and users of this report should consider the scope and limitations related to these services when developing opinions as to risks associated with the Subject Property. These potential risks may be more thoroughly evaluated as an additional service in an effort to further reduce, but not eliminate, uncertainty. Upon request, Farmer can provide options for additional research or assessment and anticipated additional cost and timing requirements.

This report presents an assessment of the Subject Property as defined by information provided by the Client, Client's representative or Key Site Manager. Farmer's findings, opinions, conclusions and recommendations are based on the locations and boundaries of the Subject Property as evident in the field and on maps, plats and/or descriptive information provided by the Client, Client's representative or Key Site Manager.

Farmer assumes the genuineness of the documents and that the information provided in this document or statements are true and accurate to the extent of these limitations. Farmer has prepared this Phase I ESA report in a professional manner using the degree of skill and care exercised for similar projects under similar conditions by reputable and competent environmental consultants. Farmer will not be responsible for conditions or consequences arising from relevant facts concealed, withheld or not fully disclosed at the time the report was prepared.

This Phase I ESA was conducted for the benefit of Quanta Services, Inc. and Affiliates and may only be relied upon, reissued or otherwise reproduced under the express written consent of Quanta Services, Inc. and Affiliates and Farmer. Farmer is not responsible for the conclusions, opinions or recommendations made by others based on this information.

1.5 Special Terms and Conditions

The work was conducted in general conformance with Farmer's proposal to conduct a Phase I ESA of the Subject Property authorized by Quanta Services, Inc. and Affiliates on September 11, 2025 and the terms and conditions established therein. The User is defined as the party seeking to use ASTM E1527-21 to complete an ESA of the Subject Property. The User of this Phase I ESA is Farmer's Client, Quanta Services, Inc. and Affiliates.

1.6 User Reliance

This report represents Farmer's services as of the date hereof. As Farmer's final document, it may not be altered after final issuance. This assessment and report were prepared on behalf of and for the exclusive use of Quanta Services, Inc. and Affiliates solely for its use and reliance, subject to the terms and conditions agreed upon between Farmer and Quanta Services, Inc. and Affiliates. The Client and Farmer were solely involved in shaping the scope of services. Accordingly, reliance on this report by any other party may involve assumptions leading to an unintended interpretation of findings and opinions. As such, reliance by other parties on the contents of this document is not granted and any such reliance shall be at the sole risk of the using party. With the consent of Farmer and the Client and for a fee, Farmer may offer reliance to third parties or contract with other parties to develop findings and opinions related to such party's specific risk management objectives.

Farmer maintains a common-law copyright on this report and services. Reproduction of or reliance upon this report may not be considered without mutual written consent of Farmer and the Client.

The observations and conclusions presented in this report reflect only those conditions apparent on the day of the field reconnaissance. Subsequent changes in Subject Property use or materials, equipment or chemicals could alter Subject Property conditions. Other limitations of this Phase I ESA (if encountered) are described in applicable sections of this report.

2.0 SUBJECT PROPERTY OVERVIEW

Subject Property Description:
The Subject Property consisted of a commercial property located at 24 Anderson Road in Cheektowaga, Erie County, New York. Based on information obtained from ECOMS, a property survey prepared by BME Associates, and Farmer's site reconnaissance, the Subject Property encompassed 1.045 acres of land improved with a commercial building including offices and warehouse areas. According to the Key Site Manager, GMES recently vacated the building which they had occupied since approximately 2023. GMES had previously used the Subject Property for wholesale of electrical equipment and supplies. The ECOMS data identified the current owner of the Subject Property (ECOMS Property ID 102.03-2-29) as Recovery Real Estate Holdings LLC. Copies of the ECOMS records, which include a brief legal description and parcel map of the Subject Property, are included in the appendices.

According to ECOMS data, the Subject Property has been zoned General Manufacturing District (M2). An assessment of conformance with zoning regulations was not included as part of this Phase I ESA.

Description of On-site Structures:
The Subject Property improvements included a single-story commercial building containing 25,200 SF of office and warehouse space apparently constructed in the 1940s. A second-floor office space was present in the southeastern corner of the building and a second-floor bathroom and storage area were located over the northeastern corner of the building. The Subject Property building appeared to consist of masonry and block construction situated on a concrete slab foundation. Additional improvements included asphalt-paved access drives (via Anderson Road) and surface parking areas (north and south of the building), concrete-paved flatwork and limited perimeter security fencing. Interior finishes within the office areas appeared to include wood-framed walls covered with painted and textured sheetrock or wood paneling, drop-down tiled ceilings and carpet- or tile-covered floors. Interior finishes within the warehouse areas appeared to be limited to concrete flooring with exposed steel supports. The warehouse was equipped with one grade-level loading dock door in the western wall of the building. The general Subject Property observations and mechanical systems are discussed in Section 5.2.

Subject Property Utilities:
The Subject Property was reportedly provided with drinking water by the Erie County Water Authority (ECWA) and sanitary sewer services by the Town of Cheektowaga. National Grid reportedly provided electricity to the Subject Property and National Fuel Gas (NFG) reportedly provided natural gas to the Subject Property. The heating, ventilation and air conditioning (HVAC) system on the Subject Property consisted of a roof-mounted, natural gas and electric powered unit with standard ventilation air ducts within office areas. Individual natural gas-fired radiant heating systems were also observed within the warehouse portions of the building. Hot water was provided by a natural gas-fired water heater. Storage of heating oil for use in mechanical systems was not observed or reported at the Subject Property.

ASTM Questionnaires:
The environmental questionnaires, as prescribed by ASTM E1527-21, was not completed by the ESA report user or the current owner of the Subject Property. Under the current ASTM E1527-21, the lack of a completed questionnaire constitutes a "data gap". Based on the information gathered for this assessment, including an interview with the Key Site Manager, it is the opinion of Farmer that the lack of this information does not constitute a significant data gap or significantly

affect Farmer's ability to identify *recognized environmental conditions* in connection with the Subject Property.

3.0 SITE BACKGROUND/OPERATING HISTORY

3.1 History of Ownership/Title Records

A chain-of-title was not included in the scope-of-work for this project. The User of this Phase I ESA did not provide Farmer with land title records and the User of this Phase I ESA has not identified environmental liens or activity and use limitations (AULs) associated with the Subject Property.

ASTM E1527-21 defines AULs as legal or physical restrictions or limitations on the use of, or access to, a site or facility: (1) to reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil, soil vapor, groundwater, and/or surface water on the property, or (2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or engineering controls, are intended to prevent adverse impacts to individuals or populations that may be exposed to hazardous substances and petroleum products in the soil, soil vapor, groundwater, and/or surface water on a property.

According to the ECOMS information, the current owner of the Subject Property was identified as Recovery Real Estate Holdings LLC. The ECOMS information indicated that the current owner was granted ownership in 2023. Prior owners were identified as Kolk Manufacturing Co. (1953), Garkol, Inc. (1981) and Divita Richard / Family Partnership (1981). Ownership details prior to 1953 were not provided in the ECOMS documentation obtained by Farmer.

In addition to the ECOMS data, Farmer obtained an Environmental Lien and AUL Search report (dated October 7, 2025) for the Subject Property from Environmental Data Resources, Inc. (EDR), which provides the results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

The EDR Environmental Lien and AUL Search report and Farmer's review of the regulatory database report (discussed in Section 6.1) and limited research/review of ECOMS data did not reveal evidence of environmental liens or AULs associated with the Subject Property, ECOMS Property Identifier 102.03-2-29 or Instrument Number 2023-11416/6822. A copy of the EDR Environmental Lien and AUL Search report is provided in Appendix E.

3.2 Review of Aerial Photographs

EDR provided historical aerial photographs to Farmer for review. Aerial photographs dated 1938, 1951, 1958, 1966, 1974, 1978, 1983, 1985, 1995, 2008, 2011, 2015, 2019 and 2022 were purchased from EDR. Copies of the aerial photographs are provided in Appendix E. In addition, various historical aerial photographs dated from 1995 to 2025 were reviewed via Google Earth®. The following is a summary of the observations made from these photographs. It should be noted that due to the scale and clarity of some of the aerial photographs, specific details with regard to structure types and/or uses observed by Farmer were difficult to discern. Unless otherwise noted, aspects on and/or in close proximity to the Subject Property appeared similar to earlier aerial photographs.

1938
The Subject Property appeared to consist of undeveloped land. A series of railcars was depicted in the eastern portion of the north-adjoining property and extending onto the northeast corner of the Subject Property. An unpaved road adjoined the eastern Subject Property boundary, followed by a two-story commercial building. A small shed and larger concrete apron were depicted on the south-adjoining property, followed by a public roadway (then called Walden Avenue, currently Dale Road). Beyond Dale Road were residences to the south and southeast and a cemetery to the southwest.

1951
The eastern portion of the current commercial building was depicted on the Subject property, adjacent to a newly paved roadway (currently Anderson Road). The east-adjoining commercial building had been expanded and the current commercial buildings were present on the north-adjoining and further north properties. A warehouse was depicted in the western portion of the south-adjoining property. Additional commercial properties had been developed in the Subject Property area and a new freeway and interchange had been constructed northeast and north of the Subject Property.

1958
The on-site building appeared to have been expanded to the west and Anderson Road had been extended further north. A commercial building was present in the northern portion of the property on the south side of Dale Road (currently Niagara Transformer Company or NTC) and additional commercial buildings were depicted in the Subject Property area.

1966
The Subject Property building had been expanded to its current extent and the west-adjoining property had been developed with most of the structures currently related to dairy operations. The south-adjoining property building had also been expanded.

1974 – 1995
No changes were depicted on the Subject Property during this period. Two large and one smaller, horizontal aboveground storage tanks (ASTs) were depicted in the southern portion of the NTC property. Although some trees remained on the two properties adjoining the east side of the NTC facility, the properties appeared to be almost entirely used for storage of equipment organized in rows and areas based on type. Use of those properties for storage was not observed again throughout this period.

2002 – March 2021
No changes were depicted on the Subject Property during this period. By 2011, paving a majority of the NTC property was depicted along with creation of a small parking lot. By 2014, a large industrial building had been constructed in the eastern portion of the NTC property. In addition, a stormwater detention pond was added along the eastern side of that property.

July 2021 – 2025
The central portion of the south-adjoining building had burned down with no apparent cleanup activities conducted until June 2023. By April 2024, the eastern portion of the south adjoining building remained and the concrete foundation for the central and western portions of that building were visible. Throughout this period, the Subject Property appeared to be inactive. The 2024 and later aerial photograph appeared to depict the Subject Property and surrounding properties in or near the state of development observed during Farmer's field reconnaissance.

3.3 Historical Maps and Documents

Fire Insurance Maps

In the late nineteenth century, companies began preparing maps for use by fire insurance companies and municipalities. These maps show construction materials of specific structures in developed urban areas. With the advent of retail gasoline service stations, the approximate locations of tanks were commonly noted, often without AST or underground storage tank (UST) designations. In addition, the locations of chemical storage and uses of retail, commercial and industrial buildings were often described. These maps were updated and expanded geographically periodically through the twentieth century.

Historical fire insurance maps were provided to Farmer by EDR for review. Historical fire insurance maps dated 1939 and 1949 were purchased from EDR. Copies of the fire insurance maps are provided in Appendix E.

1939

The Subject Property was depicted north of Walden Avenue with a series of railroad tracks crossing the central and eastern portions on a north-south orientation. A vacant commercial building was shown on the east-adjoining property and Walden Avenue was depicted to the south followed by residences

1949

The railroad tracks had been replaced by a one-story factory building and one story shed in the eastern section of the Subject Property. The east-adjoining factory building had expanded and was labeled as Road Machinery Sales & Service. A contractor's equipment warehouse and repair shop were shown on the south-adjoining property.

No historical land uses indicative of apparent environmental concern (e.g., gasoline stations, dry cleaning facilities) were identified on or in close proximity to the Subject Property on the historical fire insurance maps reviewed by Farmer.

Historical Topographic Maps

Farmer was provided with the following historical U.S. Geological Survey (USGS) topographic maps by EDR for review: 1894 and 1901 (Buffalo 15-Minute Series Quadrangle) and 1946, 1948, 1950, 1965, 2013, 2016 and 2019 (Buffalo NE 7.5-Minute Series Quadrangle). Additionally, Farmer obtained a 2023 Buffalo NE 7.5-Minute Quadrangle topographic map from the USGS website.

Farmer's review of the referenced topographic maps indicated that the Subject Property was located at an approximate elevation of 655 feet above mean sea level (AMSL). The primary topography of the Subject Property was shown to slope gradually to the south toward Cayuga Creek located approximately two miles south of the Subject Property. The structures and land uses identified on the topographic maps appeared to correspond to the observations made during Farmer's review of aerial photography. In addition, no features indicative of apparent environmental concern (e.g., oil/gas wells, pipelines) were depicted on or in close proximity to the Subject Property.

Other Historical Maps

Farmer requested historical maps for review from the Client, Subject Property owner, Key Site Manager and/or local agencies such as site surveys, as-built plans and other available maps.

With the exception of maps obtained from referenced sources, no other historical maps were provided for review.

Historical City Directories

Farmer obtained historical city directory information for the Subject Property and surrounding properties from EDR. Various directories dating from 1938 to 2022 were available for review and/or researched by EDR over approximate five-year intervals.

The results of this research are detailed as follows:

Location Relative to Subject Property	Address	Listings
Subject Property	20 Anderson Road	I C S Systems (1976)
	24 Anderson Road	Kolk Manufacturing Inc. metal stamping (1963 – 1970), Bison Electrical Co. & Buff Imprints, Inc. (1976) and Davis Electrical Supply Co. (1981 – 2022)
West	1730 Dale Road	Frontier Federate Co-Operative Inc. milk distributor (1963), Upstate Milk Company and associated entities (1968 – 2022)
North	40 Anderson Road	Screen Equipment Co. Inc. (1963-1976), SEDCO (1995), Five Star Industries (2005-2010), DIMAR Manufacturing (2022)
Northeast	45 Anderson Road	Child & Family Services (1981-1991), CH Heist Corp. administrative offices (1995-2000), Laidlaw Education Services (2005), First Student (2010-2022), Laidlaw Transit (2022)
East	25-37 Anderson Road	Dustex Corp. exhaust fans (1963), Macander Corp. (1970), ANDCO, Inc. (1981-1985), Air Niagara, Inc. (1985), Summa Graphics (1985), Delavan Industries (1985), ACTS Testing Labs (1991-2017, Ryder Truck Rental (1991), Bison Foods Co. (2005), Kinor Dairy (2005), Upstate Farms (2005-2014), Upstate Niagara Coop. (2010)
South	1746 Dale Road	Tele-Scale Inc. scientific instruments (1963-1970), Rotary Hospital Equipment Corp surgical gloves (1963), Rotary Company sheet metal works (1963 – 2005), Aquionics Corp. (1968), TNGLG LLC (2017), Diversified Manufacturing Inc. (2022)

With the exception of manufacturing and printing operations identified at adjoining and nearby properties, no listings indicative of apparent environmental concern (e.g., gas stations, dry cleaning facilities) were identified in or in close proximity to the Subject Property. Regulated facilities are discussed in Section 6.1.

Other Historical Resources

Other historical sources include sources that are credible to an environmental professional and that identify past uses of the Subject Property. This category includes, but is not limited to miscellaneous newspaper archives, internet sites, Google Street View, community organizations, local libraries, historical societies, current owners or occupants of neighboring properties, or records in the files and/or personal knowledge of the Subject Property owner and/or occupants. Farmer may have reviewed other historical sources for the Subject Property, as needed and reasonably ascertainable.

Farmer's review of Google Street View imagery indicated that the Subject Property was occupied by Davis Electrical Supply from at least September 2007 until July 2023. The south-adjoining property was unlabeled and shown to have burned down in the May 2022 and July 2023 images.

Remaining nearby land uses and commercial businesses did not appear to be indicative of apparent environmental concern in the Google Street View imagery reviewed by Farmer.

3.4 Previous Assessment Reports

Farmer requested copies of previous reports relating to the environmental conditions and history of the Subject Property from the report User, the Subject Property Owner and/or the Key Site Manager. The following previous assessment reports were provided for review and inclusion in this report.

***Report on ASTM Phase I Environmental Site Assessment,* Davis Electrical Supply Co., Inc., 24 Anderson Road, Buffalo (Cheektowaga), New York, prepared by Haley & Aldrich (H & A), H & A Project No. 0203877-011, dated November 4, 2022.**

Based on descriptive information and site maps provided in the H & A report, the property assessed by H & A appeared to correspond to the Subject Property assessed by Farmer. At the time of the H & A assessment, the Subject Property appears to have been utilized for electrical supply and lighting retail, storage and distribution by Dale Electrical Supply Co. Inc. The H & A conclusions section stated the following.

> **REC #1: Chlorinated volatile organic compounds identified in subject property soil, groundwater, soil vapor and indoor air**
>
> The former Rotary Company, Inc. (RoCo Ltd.) site at 1746 Dale Road, located adjacent to and south of the subject property, is a New York State Department of Environmental Conservation (NYSDEC) Class P Non-Registry Inactive Hazardous Waste Site (Site #915300). Trichloroethene (TCE) and related chlorinated volatile organic compound (CVOC) contamination have been identified in soil, groundwater, and soil vapor beneath the RoCo Ltd. site, with the highest concentrations observed in the northwest corner of the RoCo Ltd. site, approximately 25 feet from the southern subject property boundary. In the early-2000's subsurface investigation activities conducted on behalf of RoCo Ltd. were performed to assess whether the CVOC contamination extended onto the southern portions of the subject property. Results of these investigation activities identified CVOC concentrations in subject property soil and groundwater exceeding NYSDEC Unrestricted Use Soil Cleanup Objectives (SCOs) and Class GA Groundwater Standards (Class GA standards), respectively.
>
> RoCo Ltd. signed a Voluntary Cleanup Agreement (VCA; VCP Site # V00422) in 2001 to complete site investigation activities and address the CVOC contamination at the 1746 Dale Road site and adjacent properties, including the subject property. Remedial actions taken in the 2000's included in-situ bioremediation to treat impacted groundwater. In 2007, RoCo Ltd. completed soil vapor and indoor air sampling in the southern portion of the subject property building. TCE was detected in co-located subslab soil vapor/indoor air samples collected from within the subject property building, with concentrations observed at one sampling location exceeding the current May 2017 NYSDOH soil vapor/indoor Air Matrix A Guidelines for sub-slab soil vapor mitigation.
>
> In 2011 a deed restriction was filed for the 1746 Dale Road site, and site uses became governed by a Site Management Plan (SMP). Although the SMP does not govern activities on the subject property, it recommends continued soil vapor intrusion monitoring

in the subject property building. Regulatory records indicate the subject property owner has not allowed access to the 24 Anderson Road building for the recommended sub-slab soil vapor and indoor air sampling. In the early 2010's RoCo Ltd. reportedly abandoned the site and terminated the VCA. Between 2014 and 2020, the new site owners periodically sampled groundwater on the subject property. In May 2020, concentrations of cis-1,2-Dichloroethene (cis-DCE) were detected in subject property groundwater above Class GA standards.

The presence of CVOCs in subject property soil, groundwater, soil vapor, and indoor air due to historical releases of CVOCs at the off-site and adjacent 1746 Dale Road property is considered an REC.

De Minimis #1: Interior floor drain/catch basin containing standing water

A floor drain/catch basin reportedly connected to the municipal sanitary sewer via a nearby sump pit was observed in the warehouse portion of the subject property building during the subject property reconnaissance. It appears this area of the building was previously a portion of the original subject property factory/mechanical facility operated by Kolk Manufacturing in the 1950s and 1960s. Standing water was observed in the catch basin during the subject property reconnaissance. The Key Site Manager indicated the drain does not consistently contain water, and evidence of current or historical disposal of oil or hazardous materials into the drain was not observed or reported. The observation of standing water in the drain/catch basin suggests the drain may be blocked and/or not completely discharging to the sanitary sewer. Due to the uncertain source of water in the drain, and known groundwater contamination beneath the subject property, the function of the drain and connection to the municipal sanitary sewer should be assessed to confirm subject property groundwater is not collecting in the drain for prolonged periods.

SUMMARY AND RECOMMENDATIONS

In summary, we identified one (1) REC and one (1) de minimis condition during this Phase I.

To address the REC and de minimis condition listed above, we recommend the following:

- Sampling and analysis of sub-slab soil vapor and indoor air in the subject property building for VOCs. Results should be compared to the 2017 New York State Department of Health (NYSDOH) Updates to Soil Vapor/Indoor Air Decision Matrices, to assess whether continued monitoring or mitigation is needed.

- Trace the outlet of the floor drain/catch basin to assess for blockages that may be causing standing water to periodically collect in the drain, and to confirm discharge to the municipal sanitary sewer.

***Report on Phase II Vapor Intrusion Investigation,* Davis Electrical Supply Co., Inc., 24 Anderson Road, Buffalo, New York, prepared by H & A, H & A Project No. 0203877-014, dated February 8, 2023.**

To address the *recognized environmental condition* associated with chlorinated solvents in soil gas, subslab vapors and indoor air, H & A conducted two phases of investigation. The initial

investigation completed in December 2022 consisted of the sampling for two subslab Vapor Pins® in the southern portion of the Subject Property building and an upwind air sample with analyses for VOCs. Although chlorinated VOCs were detected in each sample, only the concentrations of TCE were sufficiently elevated (2.84 µg/m^3 to 900 µg/m^3) such that the NYSDOH Guidance recommended "mitigation". Tetrachloroethylene (PCE) and Carbon Tetrachloride were also detected in the outdoor air sample.

H & A returned to the Subject Property in January 2023 to assess indoor air contaminant concentrations in areas more frequently occupied by employees. Analyses of three indoor air samples revealed concentrations exceeding the NYSDOH Guidance for TCE in each sample (2.55 µg/$m^3$to 4.26 µg/m^3) as well as PCE in one sample (Bullpen – 2.05 µg/m^3).

H & A's conclusions are the following.

> Based on the results of the soil vapor intrusion investigation, the REC identified in the October 2022 Phase I ESA has been confirmed. The concentrations of TCE detected in both the sub-slab and indoor air result in a recommendation of "mitigation" per the NYSDOH Guidance. Though TCE was also present in outdoor air, which may impact the indoor air results, the concentrations of TCE present in soil vapor beneath the subject property building slab also exceed NYSDOH Guidance criteria for mitigation.
>
> Based on prior records review, the source of the TCE and related compounds at the subject property are anticipated to be from the Dale Road (former RoCo Ltd.) property to the south, which has known and documented impacts resulting from former metal fabrication conducted at that facility. Installation of a mitigation system is recommended to address the soil vapor beneath the slab and mitigate the potential for VOC impacted soil vapor intrusion into the building indoor airspace. The mitigation system should include a combination of sealing of preferential pathways for vapor intrusion in conjunction with the installation of a sub-slab depressurization system (SSDS), which reduces the potential for migration of VOC impacted soil vapors from beneath the building slab into the indoor airspace.

***Report on Sub-Slab Depressurization System Installation,* 24 Anderson Road, Buffalo, New York, prepared by H & A, H & A Project No. 0207713-000, dated May 3, 2023.**

The SSDS was installed in March 2023 and consisted of four roof-mounted Radon fans connected by manifold piping to 14 suction points within the Subject Property building footprint. Note that this installation was not conducted under a regulatory program and was installed voluntarily. No information pertaining to the continued operation, maintenance, sampling or effectiveness of this system has been reviewed by Farmer.

3.5 Interviews Regarding Historical Uses

The Key Site Manager (Mr. Dan Vanderhoof) was interviewed in person at the Subject Property on the day of Farmer's site reconnaissance (September 22, 2025). According to the Key Site Manager, no reportable/significant spills or leaks of hazardous substances or petroleum products have occurred at the Subject Property to his knowledge. Mr. Vanderhoof stated that he was not aware of fires, chemical spills or emergency responses on or attributable to the Subject Property. Mr. Vanderhoof was not aware of devaluation of the Subject Property due to environmental concerns, land use restrictions, environmental related litigation or environmental related violations

or citations. Other than as may be discussed in Section 5.2 (as applicable), no indications of ASTs, USTs or underground mechanical systems (e.g., oil/water separators, septic systems) were observed by Farmer or reported by the Key Site Manager.

Farmer was unable to interview contacts for previous Subject Property ownership due to an inability to identify appropriate contacts, lack of response and/or confidentiality concerns. Farmer considers the lack of interviews regarding historical uses of the Subject Property to represent a limitation under ASTM E1527-21. Based on the information gathered for this assessment, it is the opinion of Farmer that this limitation regarding historical uses of the Subject Property does not constitute a significant data gap or significantly affect Farmer's ability to identify *recognized environmental conditions* in connection with the Subject Property. Due to the observed uses of the adjacent properties, no adjacent property or facility owners were interviewed for the purposes of this ESA. None of the adjacent properties appeared to be abandoned sites.

3.6 Summary of Historical Information

Subject Property

In consideration of the available historical information identified during this Phase I ESA, the Subject Property appears to have been vacant land developed with train tracks from at least 1938 until the late-1940s or early-1950s. The tracks were removed and eastern portion of the current Subject Property building was constructed. Westward expansion of the building occurred through the 1960s. Original occupants of the building are not known; however, since 1963, the building has been occupied by Kolk Manufacturing Inc. (silverware manufacturer), Bison Electrical Co. (electrical supplies warehouse), Buff Imprints, Inc. (silkscreen and textiles printing operation) and Davis Electrical Supply Co. from the early-1980s to 2022.

Historical occupants of the Subject Property appear to have included activities indicative of potential environmental concern such as metal utensil manufacturing and cleaning and printing operations. Based on the potential for the historical, on-site use and possible release of chlorinated solvents, Farmer's review of historical resources, regulatory records and site reconnaissance has identified a *recognized environmental condition* attributable to historical uses of the Subject Property.

Nearby Properties

From the late-1930s until the early-1950s, the general area of the Subject Property appears to have been occupied by residences or undeveloped land utilized for agricultural purposes. Commercial development activities appear to have been initiated in the general area of the Subject Property during the early-1950s. Historical uses of the nearby properties appear to have included general commercial, manufacturing and light industrial facilities engaged in activities indicative of potential environmental concern such as fleet refueling, metal and electric transformer fabrication and multiple types of manufacturing. Based on Farmer's review of historical resources, referenced sources and regulatory database report (discussed in Section 6.1) and in consideration of Farmer's area reconnaissance, it appears the historical use of the south-adjoining facility (1746 Dale Road) represents a *recognized environmental condition* in connection with the Subject Property.

Data failure was encountered during this assessment, as the earliest documented historical land use was a 1938 aerial photograph depicting the Subject Property crossed by four railroad tracks. It should be noted that earlier topographic maps did not provide sufficient detail with respect to the Subject Property vicinity. This was not considered to represent a significant data gap that

affected the ability of the environmental professional to identify *recognized environmental conditions*. If instances of data failure resulted in significant data gaps that affected the ability of the environmental professional to identify *recognized environmental conditions*, those data gaps are discussed in applicable sections of the ESA.

4.0 ENVIRONMENTAL SETTING

4.1 Topography

Based on a review of the USGS Buffalo NE, New York Topographic Map (7.5-Minute Quadrangle), the Subject Property was located at an approximate elevation of 655 feet AMSL. The primary topography of the Subject Property was shown to slope gradually to the south toward Cayuga Creek located approximately two miles south of the Subject Property. Farmer's on-site observations generally corresponded to the information provided by the topographic maps. It should be noted that development activities on and in close proximity to the Subject Property, such as adjoining roadways, have influenced the local topography resulting in variable flow direction of surface water (when present).

4.2 Geology

According to information received from EDR, the geology at the Subject Property is characterized as a stratified sequence of the Paleozoic Era, Devonian System and Middle Devonian Series. The geology in this system consists primarily of limestone. Farmer's review of the United States Geological Survey (USGS) Mineral Resources online data mapping system indicated that the Subject Property is underlain by the Middle Devonian Onondaga and Bois Blanc Limestones. This formation is approximately 150 feet thick in the Subject Property vicinity.

Soil Conservation Service STATSGO data compiled by EDR indicated the soil surface was characterized as the Cazenovia soil component. These soils have moderate infiltration rates (Class B) and are moderately well drained. These are deep and moderately deep soils with moderately coarse textures. Farmer's review of the Natural Resource Conservation Service's Web Soil Survey confirmed that the predominant soils located on the Subject Property consisted of the Cazenovia or Urban (unclassified) soils.

4.3 Hydrology

Farmer's assessment of wetlands and potential jurisdictional Waters of the U.S. was limited to research of published information, interviews and visual observations. It should be noted that wetlands cannot be definitively identified through visual observation alone. Defensible wetland delineations require taxonomic classification of site vegetation, an investigation into the surface and subsurface hydrology of the site and identification of hydric soils. This level of delineation is outside of the scope of work for this assessment. Farmer's site reconnaissance and review of historical resources did not indicate the presence of former or current surface water features on the Subject Property.

Farmer's review of the United States Department of the Interior National Wetland Inventory (NWI) digital map obtained from the United States Fish and Wildlife Service's (USFWS) Wetlands Mapper did not identify designated wetlands on or immediately adjoining the Subject Property.

Farmer's review of the Federal Emergency Management Agency (FEMA) Flood Insurance Rate Map (FIRM) Community Panel Number FM36029C0219H (effective June 7, 2019) indicated that the Subject Property was located within Zone X (non-shaded), which is an area determined to be outside the 0.2 percent annual chance floodplain.

Groundwater occasionally occurs in shallow, discontinuous or "perched" water bearing units where the soils are in contact with the unweathered bedrock or an impermeable soil layer. These shallow units are infrequently utilized but are the water bearing zones with the potential to be impacted by releases from UST facilities or other surface/subsurface sources. Flow direction in these units is highly variable but is generally toward the nearest downgradient water body (lakes, creeks, rivers) and can be approximated by observing the surface topography. Recharge areas for these perched aquifers are very localized and they can be influenced by surface development of impervious cover (buildings, parking lots, roads), major road construction (underpasses, utility trenches) and variations in annual rainfall. A subsurface investigation including the installation of a minimum of three monitor wells would be required to accurately determine groundwater gradient on the Subject Property. Based on the results of subsurface investigation activities on the south-adjoining property, the anticipated depth to perched groundwater on the Subject Property is approximately one to ten feet below ground surface (bgs) and the subsurface gradient would be anticipated to be toward the south.

5.0 RESULTS OF THE ON-SITE INVESTIGATION

Mr. Matt Burleigh, Principal for Farmer, conducted a field investigation of the Subject Property on September 22, 2025. At the time of the field investigation, the weather was clear with temperatures in the 80s (°F). The Subject Property was not obstructed by weather-related or natural obstructions. The Subject Property location map is included in Appendix A as Figure 2. Photographs of the Subject Property and surrounding properties are provided in Appendix C.

5.1 Methodology and Limiting Conditions

Farmer visually and physically observed accessible areas of the Subject Property. Farmer was able to access a majority of the interior spaces of the Subject Property, the exterior areas, the Subject Property perimeter and portions of the adjoining public right-of-way areas. Limitations imposed by physical obstructions or other limiting conditions included the following.

- The areas behind walls, above drop-down tiled ceilings, confined spaces and the roof were inaccessible during the site visit.

The Key Site Manager reported no known environmental concerns in the inaccessible areas. Based on the information gathered for this assessment, it is the opinion of Farmer that the limiting conditions discussed above did not significantly affect Farmer's ability to identify *recognized environmental conditions* in connection with the Subject Property.

5.2 Observations

Subject Property Overview

The Subject Property consisted of a commercial property located at 24 Anderson Road in Cheektowaga, Erie County, New York. Based on information obtained from ECOMS, a property survey prepared by BME Associates, and Farmer's site reconnaissance, the Subject Property encompassed 1.045 acres of land improved with a commercial building including offices and warehouse areas. According to the Key Site Manager, GMES recently vacated the building which they had occupied since approximately 2023. GMES had previously used the Subject Property as a wholesaler of electrical equipment and supplies.

The Subject Property improvements included a single-story commercial building containing 25,200 SF of office and warehouse space apparently constructed in the 1940s. A second-floor office space was present in the southeastern corner of the building and a second-floor bathroom and storage area were located over the northeastern corner of the building. The Subject Property building appeared to consist of masonry and block construction situated on a concrete slab foundation. Additional improvements included asphalt-paved access drives (via Anderson Road) and surface parking areas (north and south of the building), concrete-paved flatwork and limited perimeter security fencing. Interior finishes within the office areas appeared to include wood-framed walls covered with painted and textured sheetrock or wood paneling, drop-down tiled ceilings and carpet- or tile-covered floors. Interior finishes within the warehouse areas appeared to be limited to concrete flooring with exposed steel supports. The warehouse was equipped with one grade-level loading dock door in the western wall of the building.

Interviews with Owners/Representatives

The Key Site Manager (Mr. Vanderhoof) escorted Farmer during the field reconnaissance and answered general questions concerning the environmental conditions on the Subject Property.

The information provided by the Key Site Manager is identified in appropriate sections of this report.

Stormwater Drainage Observations
Stormwater drainage from the roof areas on the Subject Property would appear to flow to perimeter gutters and downspouts, then to the paved (or vegetated) surface areas. The stormwater from the ground level surface areas drains (via sheetflow) to adjoining properties or public roadways. The stormwater appears to flow to the municipal stormwater drainage system. No significant surface staining was noted on the Subject Property or near the adjacent drains.

Source of Drinking Water
The Erie County Water Authority currently provides drinking water service to the Subject Property. According to the most recent Annual Drinking Water Quality Report (2024), the drinking water meets or exceeds all state and federal regulations with respect to drinking water quality. The Key Site Manager reported no issues with respect to the Subject Property drinking water.

Sewage Disposal/Septic System
The Town of Cheektowaga currently provides sanitary sewer service to the Subject Property. No septic systems or sewage pretreatment systems were observed or reported to be on the Subject Property.

Storage Tanks and Associated Equipment
No indications of ASTs, USTs or associated equipment (e.g., fill ports) were observed or reported on the Subject Property.

Hazardous Chemicals and Petroleum Products
No hazardous chemicals or petroleum products were observed on the Subject Property.

Odors
No unusual odors were detected on the Subject Property at the time of the investigation.

Surface Staining, Corrosion and Stressed Vegetation
No significant surface staining, corrosion or stressed vegetation was observed on the Subject Property during Farmer's site reconnaissance. Minor automotive fluid stains were observed in the paved parking areas on the Subject Property. However, by direction of ASTM E1527-21, these stains do not constitute a *recognized environmental condition* in connection with the Subject Property.

Polychlorinated Biphenyls (PCBs)
PCBs were commonly used in electrical and hydraulic equipment prior to an EPA ban on this chemical in 1978. Farmer included observations of the Subject Property systems for potential PCB containing equipment.

Farmer observed three pole-mounted electric transformers near the eastern boundary of the Subject Property. Labeling regarding PCB content was not apparent. The transformers appeared to be in good condition and no leaking or staining was observed on or near this equipment. The transformers appeared to be owned and maintained by Oncor. Any spills or releases of the dielectric fluids or malfunctioning transformer equipment should be reported to Oncor with a request to remediate any releases. No other potential PCB-containing equipment such as hydraulic lifts was observed or reported on the Subject Property.

Heating and Cooling Systems
The HVAC system on the Subject Property consisted of a roof-mounted, natural gas and electric powered unit with standard ventilation air ducts within office areas. Individual natural gas-fired radiant heating systems were also observed within the warehouse portions of the building. Hot water was provided by a natural gas-fired water heater. Storage of heating oil for use in mechanical systems was not observed or reported at the Subject Property.

Drains, Sumps or Pre-treatment Systems
Interior drains appeared to be limited to restrooms, sinks and one floor drain and one sump pit in the warehouse. The warehouse floor drain was dry and appeared to be connected to the sump observed in the corner of the warehouse. The sump was equipped with a pump that appeared to discharge to the municipal sanitary sewer system. No exterior drains were observed or reported on the Subject Property. Farmer observed no indications of improper use or disposal associated with the drains. No additional drains, sumps or pre-treatment systems were reported or observed on the Subject Property.

Based on Farmer's observations and information provided by the Key Site Manager, the on-site drains and sump pump system do not appear to represent a *recognized environmental condition* in connection with the Subject Property.

Pits, Ponds or Lagoons
No pits, ponds or lagoons were observed on the Subject Property.

Solid Waste Disposal
No trash receptacles were observed within the building on the Subject Property; however a solid waste dumpster was observed in the northwest corner of the Subject Property. The waste materials observed within this container appeared non-hazardous in nature. No litter resulting from unauthorized dumping was observed on the Subject Property.

Farmer's review of the NYSDEC DECInfoLocator website for closed/active landfills and solid waste facilities inventory did not reveal documented disposal facilities on or in close proximity to the Subject Property.

Wastewater Discharges
With the exception of sanitary sewer discharge typical of office uses, no evidence of industrial wastewater discharges was observed or reported to occur at the Subject Property.

Wells or Cisterns
No water supply wells, petroleum-related wells or cisterns were observed or reported on the Subject Property. However, Farmer observed an environmental monitor well near the western side of the Subject Property building. According to reports discussed in Section 3.4, this monitor well was labeled GW-2. An additional monitor well (GW-1) was indicated in the reports, but not observed by Farmer, just north of the eastern portion of the southern Subject Property boundary. Depth to water reported in these two wells was less than five feet bgs. Groundwater samples collected from GW-1 were impacted by chlorinated solvents with the concentration of cis-DCE (34 µg/L) reported above the Class GA groundwater standard of 5 µg/L. The on-site monitor wells were discussed in Section 3.

Farmer's review of the NYSDEC DECInfoLocator website Viewer for Oil, Gas and Pipeline Data did not reveal the presence of oil or gas wells on or immediately adjoining the Subject Property.

Railroad Spurs or Pipelines

No active or inactive railroad spurs or petroleum pipeline systems were observed on or adjacent to the Subject Property.

Farmer's review of the National Pipeline Mapping System (NPMS) did not reveal the presence of natural gas or petroleum pipelines in close proximity to the Subject Property. However, it is anticipated that small diameter NFG natural gas distribution lines are located on and/or adjoining the Subject Property.

5.3 Adjoining Property Observations

Adjoining properties were visually examined from public access rights-of-way to make a cursory assessment of the current land use and its potential for recognized environmental conditions that may have impact on the Subject Property. Reconnaissance of adjoining properties was performed by viewing land use from legal boundaries or by walking upon the adjoining properties that were legally accessible. Adjoining developments to the Subject Property are as follows:

North: Dimar Manufacturing (40 Anderson Road);
East: Anderson Road followed by First Student, Inc. (45 Anderson Road) and UNC (25-37 Anderson Road);
South: Vacant and fire-damage commercial building (1746 Dale Road); and
West: Upstate Farms Cooperative (1730 Dale Road).

Farmer's observation of the adjoining/nearby properties did not identify facilities that may represent *recognized environmental conditions* in connection with the Subject Property. Regulated facilities located in the vicinity of the Subject Property are described in Section 6.0.

6.0 REGULATORY/GOVERNMENTAL AGENCY INQUIRIES

6.1 Federal and State Regulatory Agencies

State and Federal regulatory database information for the vicinity of the Subject Property was obtained from EDR. The EDR database records follow the ASTM E1527-21 search distances and availability. In some cases, additional database records are available and these databases are described if properties or facilities are identified that may pose a *recognized environmental condition* in connection with the Subject Property. Unless otherwise stated, the regulatory records reviewed by Farmer were considered to provide sufficient information to evaluate the potential existence of a *recognized environmental condition*, *historical recognized environmental condition*, *controlled recognized environmental condition* or a *de minimis condition* in connection with the Subject Property.

A radius map and summarization page of the findings of the EDR research is included with the database information, which is provided in Appendix F. In addition, EDR has provided definitions for the various database functions.

In summary, the EDR research included a review of the following databases:

- US Environmental Protection Agency (EPA) National Priorities List (NPL);
- EPA Resource Conservation and Recovery Information System (RCRIS) Treatment, Storage and Disposal Facilities (RCRIS TSD) list;
- EPA RCRIS Corrective Actions (CORRACTS) database;
- EPA RCRIS Violations/Enforcement Actions (RCRA Violator) list;
- EPA Superfund Enterprise Management System (SEMS) – formerly the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS)
- EPA CERCLIS No Further Remedial Action Planned (NFRAP) sites list;
- EPA RCRIS Large Generators (RCRIS LG)/Small Generators (RCRIS SG) lists;
- EPA Emergency Response Notification System (ERNS) list;
- New York State Superfund list;
- New York State CERCLIS Equivalent (SCL) database;
- New York Industrial Hazardous Waste (IHW) database;
- New York Leaking Underground Storage Tanks (LUST) list;
- New York registered UST and AST list;
- New York Solid Waste/Landfills Permit Application (SWLF) file;
- New York Voluntary Cleanup Program (VCP); and
- New York Spills Report.

The following tables include the approximate minimum search distances and a list of the databases reviewed. These databases were selected based on minimum requirements of ASTM E1527-21. The number of facilities indicates the number of regulated facilities identified by the database provider to be present within the approximate minimum search distance for a particular database.

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		1	0	2	NR	NR	3
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		1	0	0	0	NR	1
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		3	1	NR	NR	NR	4
RCRA-VSQG	0.250		4	2	NR	NR	NR	6
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		3	0	2	0	NR	5
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	1	2	NR	NR	3
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		4	3	4	NR	NR	11
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		2	3	NR	NR	NR	5
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY CBS	0.250		1	0	NR	NR	NR	1
NY MOSF	0.500		0	0	0	NR	NR	0
NY AST	0.250		2	2	NR	NR	NR	4
NY CBS AST	0.250		1	0	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		2	0	0	NR	NR	2
NY INST CONTROL	0.500		3	0	0	NR	NR	3
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		1	0	0	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		1	0	0	NR	NR	1
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	1	NR	NR	1
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	1	0	0	NR	1
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125	1	20	NR	NR	NR	NR	21
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		7	6	NR	NR	NR	13
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		1	0	NR	NR	NR	1
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
FINDS	0.001		0	NR	NR	NR	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		1	0	NR	NR	NR	1
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	0.001		0	NR	NR	NR	NR	0
UST FINDER RELEASE	0.500		3	4	4	NR	NR	11
UST FINDER	0.250		2	3	NR	NR	NR	5
E MANIFEST	0.250		4	7	NR	NR	NR	11
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	0.001		0	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0
NY Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY HSWDS	0.500		1	0	1	NR	NR	2
NY LEAD	0.001		0	NR	NR	NR	NR	0
NY MANIFEST	0.250		12	8	NR	NR	NR	20
MI MANIFEST	0.250		1	0	NR	NR	NR	1
NJ MANIFEST	0.250		2	0	NR	NR	NR	2
NY SPDES	0.001		0	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	1	NR	NR	1
NY UIC	0.001		0	NR	NR	NR	NR	0
NY COOLING TOWERS	0.001		0	NR	NR	NR	NR	0
NY MGP	1.000		0	0	0	0	NR	0
NY NYC LAND USE	0.001		0	NR	NR	NR	NR	0
NY ILI	0.500		0	0	2	NR	NR	2
NY NYC OER	1.000		0	0	0	0	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.001		0	NR	NR	NR	NR	0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		1	83	41	19	0	0	144

NR – Not Requested at this Search Distance
TP – Target Property

The Subject Property address (24 Anderson Road) was identified on the NY Spills regulatory databases. According to the regulatory database report, the Subject Property listings were associated with "Nancy O'Neil Auto Fire". The spill of five gallons of gasoline occurred during a vehicle fire at or adjacent to the Subject Property in 1987. The database report stated that the spill was cleaned up by the Town of Cheektowaga and that no further action was required.

Based on Farmer's review of the regulatory database report and in consideration of Farmer's site reconnaissance, the regulatory listing associated with the Subject Property does not appear to represent a *recognized environmental condition* in connection with the Subject Property.

Farmer reviewed the regulatory information provided in the database report to identify listed facilities located within the approximate minimum search distances. If encountered, significant facilities identified are discussed below along with their distance from the Subject Property, the regulatory database on which the facility was listed, the apparent hydrologic relationship to the Subject Property, information provided in the database report, Farmer's observation of the facility during the area reconnaissance (if pertinent) and/or comments and whether or not the facility was considered to be a potential environmental concern to the Subject Property. Additional facilities may have been identified by the database provider but not presented as follows based on Farmer's judgment of significance. Those facilities are documented for reference by the reader in the appended regulatory database report.

Facility Name: **Rotary Company / RoCo, LTD.**
Facility Address: **1746 Dale Road**
Approximate Distance / Direction: **Adjoining / South**
Topographic Relationship: **Down-gradient**
Database Listing(s): **HSWS, SHWS, EC, IC, VCP, Spills, Manifest, SEMS-Archive, RCRA NonGen, FINDS, ECHO**

Summary of Adjacent Facility/Property Listing:
The former RoCo site is a NYSDEC Class P Non-Registry Inactive Hazardous Waste Site (Site #915300). Historical records indicated that the site was previously operated as a metal and plastic fabricating facility from 1946 to 1994. Environmental site assessments in the late-1990s and early-2000s identified CVOCs in soil and groundwater at this property and on the west-adjoining UNC facility and on the Subject Property. During this period, TCE was identified in soil and groundwater beneath the site and adjacent sites at concentrations exceeding NYSDEC Unrestricted Use SCOs and Class GA standards.

RoCo entered into the NYSDEC VCP in 2001, which resulted in treatment of impacted groundwater using HRC®. In 2007, RoCo also completed soil vapor and indoor air sampling in the southern portion of the Subject Property building. TCE was detected in sub-slab soil

vapor/indoor air samples collected from within the Subject Property building (SS#5 and SS#6), with concentrations observed at SS#6 (17.7 / 1.08 µg/m^3) exceeding the current (May 2017, updated 2024) NYSDOH soil vapor/indoor Air Matrix A Guidelines for sub-slab soil vapor mitigation. At the time of the 2007 investigation, NYSDOH guidelines recommended only continued monitoring. Application of HRC® resulted in significant reduction of chlorinated VOC concentrations in both groundwater and soil gas. Operation of an SVE system further provided significant reductions in some contaminants.

A deed restriction was filed in 2011 for the RoCo property and a SMP was instituted to control uses of the property. The SMP indicated continuing soil vapor intrusion (sub-slab vapor and indoor air) monitoring on the Subject Property at sampling locations SS#5 and SS#6. Regulatory records indicated the Subject Property owner reportedly did not allow access to the Subject Property building for the recommended sampling.

In the early 2010s, RoCo reportedly abandoned the site and terminated participation in the VCP. In 2017, new site owners completed additional groundwater and soil vapor sampling at the site, and groundwater sampling on the Subject Property (see Section 3.4). However, total VOC concentrations rebounded by 2017 (dehalogenated from TCE to DCE and VC), requiring updated monitoring in the northwest corner of the RoCo property. During groundwater sampling in May 2020, cis-DCE and VC were detected on the RoCo property at concentrations (8,800 and 23,000 µg/L, respectively) exceeding applicable Class GA standards. During this same period, only concentrations of cis-DCE were detected in Subject Property groundwater (well GW-1) above Class GA standards.

Based on historical releases of CVOCs at the RoCo site that were documented to have impacted Subject Property soil, groundwater and soil vapor at concentrations that exceed NYSDEC standards / guidance and are indicative of potential vapor intrusion, the regulatory listings associated with the RoCo facility appear to represent a *recognized environmental condition* in connection with the Subject Property.

Facility Name:	**ACTS Testing Labs Inc. / Upstate Farms Cooperative, Inc. / Building Addition Excavation**
Facility Address:	**25 Anderson Road**
Approximate Distance / Direction:	**Adjoining / East**
Topographic Relationship:	**Cross-gradient**
Database Listing(s):	**RCRA NonGen, FINDS, ECHO, Manifest, Spills**

Summary of Adjacent Facility/Property Listing:

According to the regulatory database report, petroleum contaminated soil was encountered during utility excavations 2011 and NYSDEC issued NY Spill No. 1101569 for the release. Petroleum contaminated soil was reportedly excavated and removed from the site, and NYSDEC closed the spill file and issued a no further action determination. The RCRA database identified waste streams including ignitable and corrosive waste, as well as halogenated solvents (PCE, TCE, etc.). ACTS Testing Labs was classified as a Small Quantity Generator (SQG) of these wastes in 1993, a Large Quantity Generator (LQG) in 2001 and was no longer considered a generator in 2006 and 2007. Upstate Farms Cooperative (UNC) was classified as an LQG of TCE in 2001 and was no longer a generator in 2007. Compliance Evaluations conducted in 1995 and 1999 yielded no violations. The Manifest database indicated numerous shipments of off-specification reagents in small quantities as well as 55-gallon drums of chlorinated solvents.

Based on the topographic relationship, excavation of the impacted soils, current regulatory status, and lack of reported violations, the regulatory listings associated with the east-adjoining facility do not appear to represent a *recognized environmental condition* in connection with the Subject Property.

Facility Name:	**SECO Corp., Dimar Manufacturing**
Facility Address:	**40 Anderson Road**
Approximate Distance / Direction:	**Adjoining / North**
Topographic Relationship:	**Up-gradient**
Database Listing(s):	**RCRA, RAATS, PFAS ECHO, FINDS, ECHO, Manifest (NY, NJ & E), Spills**

Summary of Adjacent Facility/Property Listing:

According to the regulatory database report, the previous occupant (SECO Corp) and current occupant (Dimar Manufacturing) were listed as RCRA SQGs of ignitable wastes, Methyl Ethyl Ketone (MEK) and numerous non-halogenated solvents. The database report indicated SECO Corp received a written, informal violation for unspecified reasons in 1993. Violations associated with Dimar Manufacturing were not noted in the database report. Compliance Evaluations conducted in 2013 and 2022 yielded no violations. The Manifest databases indicated shipments of drums containing Chromium, MEK and other nonhalogenated solvents from 2012 to 2018.

Per- and Poly-Fluoroalkyl Substances (PFAS) are a class of man-made chemicals that have been widely used in industrial processes and in consumer products as early as the 1940s. PFAS products are also used in aqueous film forming foams (AFFF) used in firefighting and emergency response actions, numerous industrial processes, landfills, car washes and wastewater treatment effluent to name a few industries. Only two constituents, Perfluorooctane Sulfonicacid (PFOS) and its salts and isomers, and Perfluorooctanoic Acid (PFOA), have been classified as hazardous substances. Although the north-adjoining facility does not appear to have been investigated with respect to PFAS substances, the potential presence of these compounds does not appear to represent an environmental concern.

Facility Name:	**UNC / Upstate Milk**
Facility Address:	**1730 Dale Road**
Approximate Distance / Direction:	**Adjoining / West**
Topographic Relationship:	**Cross-gradient**
Database Listing(s):	**RCRA-VSQG, CBS, AST, UST, LTANKS, Manifest, Spills, SPDES**

Summary of Adjacent Facility/Property Listing:

According to the regulatory database report, the Upstate Milk Cooperatives site was listed in NYSDEC's Petroleum Bulk Storage (PBS) database due to the current or historical presence of two active USTs, eight closed USTs, and five ASTs. The closed USTs ranged in size from 1,000 gallons to 10,000 gallons and were generally installed in the 1970s and removed in the early-1990s. The active USTs were 8,000-gallons and 12,000-gallons in capacity and were installed in 1993. The USTs were identified as having contained gasoline, diesel fuel and new/waste oils. The ASTs ranged in size from 250 gallons to 1,500 gallons and were indicated as storing Chlorine, Sodium Hydroxide, Ammonia and Phosphoric Acid.

The site was also listed in the NYSDEC Chemical Bulk Storage (CBS) facility database for storage of the above-listed chemicals. The RCRA database identified no violations associated with the

very small quantity generator (VSQG) listing for this facility, which shipped ignitable and corrosive wastes.

Database records identified multiple petroleum spills at the site associated with incidental releases during UST/AST fillings/dispensing. The spills have reportedly been closed by the NYSDEC. Subsurface petroleum contamination has also been periodically observed during UST removal activities and during subsurface utility replacement/repairs. Database records indicate the petroleum spills were cleaned up through limited excavations and soil removal, and that the NYSDEC indicated no further action was necessary.

Based on the topographic relationship, removal of USTs, excavation of the impacted soils, current regulatory status, and lack of reported violations or impacts to groundwater, the regulatory listings associated with the UNC / Upstate Milk facility do not appear to represent a *recognized environmental condition* in connection with the Subject Property.

Based upon the distance of separation, current regulatory status, type of regulatory listings identified for these facilities, conditions typical of the identified facility activities, topographic relationship and/or lack of reported releases, the remaining regulated facilities identified in the regulatory database report do not appear to represent a *recognized environmental condition* in connection with the Subject Property.

EDR provides three proprietary databases that identify historical manufactured gas plants, cleaners and auto stations that are known to EDR, typically based on city directory reviews and/or Sanborn Maps. Facilities included on this database typically operated before current regulations requiring notification/registration. These facilities may not be listed on regulatory databases but may be suspect *recognized environmental conditions* due to proximity to the Subject Property. Farmer reviewed the historical facility databases and no historical facilities were identified.

The database report listed five “orphan” facilities (facilities that were not mapped in the database report due to poor or inadequate address information). Based upon Farmer’s area reconnaissance, distance of separation, type of regulatory listings identified for these facilities, conditions typical of the identified facility activities and/or topographic relationship, the orphan facilities do not appear to represent a *recognized environmental condition* in connection with the Subject Property.

6.2 Local Government Inquiries

Town of Cheektowaga

Farmer submitted an open records request to the Town of Cheektowaga for the Subject Property for distribution to pertinent city departments. According to the responses (dated September 30 and October 1, 2025), the Fire Marshall confirmed that a fire had occurred at the south-adjoining property but provided no additional details. The remaining documents provided in response to this request included an April 13, 2023, Certificate of Occupancy and Commercial Operating Permit issued to DiVita Family Partnership.

Farmer reviewed building permits as researched by EDR in provided in their Building Permit Report dated October 1, 2025. These included but were not limited to a change in commercial tenant and planning/zoning use and a certificate of occupancy with dates ranging from 2022 to 2023. No permits indicative of apparent environmental concern were identified in the EDR Building Permit Report.

Erie County / Local Emergency Planning Committee

Farmer submitted an open records request to Erie County and the Erie County Local Emergency Planning Committee (LEPC) for the Subject Property for distribution to pertinent county departments. No response has been received to date. Farmer will issue a written addendum to this report if requested information is received that identifies potential *recognized environmental conditions* in connection with the Subject Property.

New York Department of Environmental Conservation

Farmer submitted an open records request to the NYSDEC for the Subject Property and adjoining/nearby properties of concern. Records obtained from the NYSDEC were discussed in Section 6.1.

Farmer's review of the regulatory database report did not reveal nearby facilities requiring additional file review. General information obtained from the NYSDEC is discussed in applicable sections of this report.

6.3 Limited Vapor Encroachment Screening

In general accordance with ASTM E1527-21, Farmer has utilized the referenced sources, EDR Vapor Encroachment Screen and visual reconnaissance in order to assess the potential for vapor migration, attributable to substances such as volatile organic compounds (VOCs), which may represent a vapor encroachment condition (VEC) in connection with the Subject Property. ASTM International has published a *Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM E2600-15). ASTM E2600-15 defines a VEC as the presence or likely presence of vapors from chemicals of concern (COCs) in the subsurface of a property caused by the release of vapors on or near the property. The presence within a building of hazardous substances such as vapors that have migrated into a building from a "release into the environment" (i.e., from a release outside of the building) can result in CERCLA liability. Vapor migration in the subsurface is described in ASTM E2600-15; however, ASTM E1527-21 states that "nothing in this practice should be construed to require application of the ASTM E2600-15 standard to achieve compliance with all appropriate inquiries".

Farmer conducted a Limited Vapor Encroachment Screening (VES) of the Subject Property utilizing general procedures laid out in ASTM E2600-15. The practices laid out in ASTM E2600-15 provide useful information for evaluation of the potential condition using terminology that is clearly defined and widely recognized. Additionally, ASTM E2600-15 presents assessment approaches that are beyond the scope of ASTM E1527-21 and this Phase I ESA. Although this Limited VES draws upon the concepts laid out in ASTM E2600-15 and uses the terminology defined therein, this section represents assessment procedures required by ASTM E1527-21, but less than an ASTM International Tier 1 VES as described in ASTM E2600-15. Moreover, the information on which this Limited VES is based is limited solely to that identified during the course of the Phase I ESA.

The following table presents the *approximate minimum search distance* for Standard Environmental Record Sources for petroleum and non-petroleum COCs to identify potential areas of concern generated via the EDR Vapor Encroachment Screen. The term "*approximate minimum search distance"* is measured from the Subject Property to a known or suspect source of soil and/or groundwater contamination. These record sources were selected based on minimum requirements of ASTM E2600-15 and were augmented to include facilities that are commonly encountered and identified through other sources considered in a Phase I ESA. The

number of facilities indicates the number of known or suspect contaminated sites identified during review of the standard record sources.

STANDARD ENVIRONMENTAL RECORDS	Default Area of Concern (Miles)*	property	1/10	> 1/10
Lists of Federal NPL (Superfund) sites	1.0	0	0	0
Lists of Federal Delisted NPL sites	1.0	0	0	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders	0.5	0	0	0
Lists of Federal CERCLA sites with NFRAP	0.5	0	1	0
Lists of Federal RCRA facilities undergoing Corrective Action	1.0	0	0	0
Lists of Federal RCRA TSD facilities	0.5	0	0	0
Lists of Federal RCRA generators	0.25	0	2	1
Federal institutional controls / engineering controls registries	0.5	0	0	0
Federal ERNS list	0.001	0	0	-
Lists of state- and tribal (Superfund) equivalent sites	not searched	-	-	-
Lists of state- and tribal hazardous waste facilities	1.0	0	1	0
Lists of state and tribal landfills and solid waste disposal facilities	0.5	0	0	0
Lists of state and tribal leaking storage tanks	0.5	0	2	2
Lists of state and tribal registered storage tanks	0.5	0	2	1
State and tribal institutional control / engineering control registries	0.5	0	1	0
Lists of state and tribal voluntary cleanup sites	0.5	0	1	0
Lists of state and tribal brownfield sites	0.5	0	0	0
ADDITIONAL ENVIRONMENTAL RECORDS				
Local Brownfield lists	0.5	0	0	0
Local Lists of Landfill / Solid Waste Disposal Sites	0.5	0	0	0
Local Lists of Hazardous waste / Contaminated Sites	1.0	0	0	0
Local Lists of Registered Storage Tanks	0.25	0	0	0
Local Land Records	0.001	0	0	-
Records of Emergency Release Reports	0.125	1	3	2
Other Ascertainable Records	1.0	0	13	6
EDR HIGH RISK HISTORICAL RECORDS				
EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	0.001	0	0	-
EDR RECOVERED GOVERNMENT ARCHIVES				
EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	0.001	0	0	-

Property = Subject Property

Vapor Encroachment Condition (VEC) Classifications:
VEC Exists *VEC Does not exist*

Based on information summarized in the preceding table and as may be discussed elsewhere in this report, impacts to on-site groundwater and soil vapor have been documented due to releases of chlorinated solvents to the subsurface at the south-adjoining property, which represents a VEC to the Subject Property.

7.0 CONCLUSIONS

Farmer has performed a Phase I ESA in general conformance with the scope and limitations of ASTM E1527-21 of the Subject Property. Any exceptions to or deletions from, this practice are described in applicable sections of this report.

This assessment has revealed no evidence of *recognized environmental conditions* in connection with the Subject Property except for the following.

- The Subject Property has historically been used for the manufacture of silverware utensils and printing on textiles, operations with a significant potential for the use and possible release of chlorinated VOCs, which appears to represent a *recognized environmental condition* attributable to historical uses of the Subject Property.

- Historical releases of chlorinated solvents at the south-adjoining RoCo facility have resulted in the presence of chlorinated VOCs in groundwater and soil gas at the Subject Property at concentrations in excess of applicable regulatory criteria. Although treatment of subsurface media using HRC® in the mid-2000s resulted in a significant reduction in contaminant load, CVOC concentrations rebounded in both soil vapor and groundwater. These impacts represent a *recognized environmental condition* in connection with the Subject Property.

- The impacts to the on-site groundwater and soil vapor at the Subject Property appear to represent a VEC to the Subject Property. This VEC accordingly represents a *recognized environmental condition* in connection with the Subject Property.

8.0 CERTIFICATION AND QUALIFICATIONS

Signature of Environmental Professional(s)

I declare that, to the best of my professional knowledge and belief, I meet the definition of *Environmental Professional* as defined in § 312.10 of 40 CFR § 312. I have the specific qualifications based on education, training and experience to assess a property of the nature, history and setting of the Subject Property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.



Matt Burleigh
Environmental Professional

Qualifications of Farmer Personnel

In accordance with ASTM E1527-21, this report includes the qualifications of the *Environmental Professional* and the qualifications of the personnel conducting the site reconnaissance and interviews, if conducted by someone other than an *Environmental Professional*. These qualifications are documented in the appendices.

9.0 REFERENCES

References used in preparation of this report are cited throughout the text and/or provided below.

Erie County Online Mapping System website for property information and map depicting boundaries of the Subject Property available at: https://gis.erie.gov/Html5Viewer133/index.html?viewer=ErieCountyNY.HTML5_2_11_0

EDR Environmental Lien and AUL Search, Commercial Property, 24 Anderson Road, Buffalo, New York 14225, Inquiry Number 8127688.7, dated October 1, 2025

Historical Aerial Photographs, purchased from EDR, dated 1938, 1951, 1958, 1966, 1974, 1978, 1983, 1985, 1995, 2008, 2011, 2015, 2019 and 2022

EDR-Certified Sanborn Map Report, Commercial Property, 24 Anderson Road, Buffalo, New York 14225, Inquiry Number 8127688.3, dated October 2, 2025

Historical Topographic Maps, purchased from EDR, 1894 and 1901 (Buffalo, NY 15-Minute Series Quadrangle) and 1946, 1948, 1950, 1965, 2013, 2016 and 2019 (Buffalo NE, NY 7.5-Minute Series Quadrangle)

EDR-City Directory Image Report, Commercial Property, 24 Anderson Road, Buffalo, New York 14225, Inquiry Number 8127688.5, dated October 6, 2025

Report on ASTM Phase I Environmental Site Assessment, Davis Electrical Supply Co., Inc., 24 Anderson Road, Buffalo (Cheektowaga), New York, prepared by H & A, H & A Project No. 0203877-011, dated November 4, 2022

Report on Phase II Vapor Intrusion Investigation, Davis Electrical Supply Co., Inc., 24 Anderson Road, Buffalo, New York, prepared by H & A, H & A Project No. 0203877-014, dated February 8, 2023

Report on Sub-Slab Depressurization System Installation, 24 Anderson Road, Buffalo, New York, prepared by H & A, H & A Project No. 0207713-000, dated May 3, 2023

United States Department of Agriculture Natural Resources Conservation Service Web Soil Survey available at: https://websoilsurvey.nrcs.usda.gov/app/WebSoilSurvey.aspx

Federal Emergency Management Agency (FEMA) Flood Insurance Rate Map (FIRM), Community Panel Number FM36029C0219H (dated June 7, 2019) available at: http://fema.maps.arcgis.com/apps/webappviewer/index.html

Erie County Water Authority 2024 Water Quality Report available at: https://www.ecwa.org/files/pdf/2024_annual_water_quality_report.pdf

US Department of Transportation National Pipeline Mapping System at: https://www.npms.phmsa.dot.gov


EDR-Radius Map *with Geocheck,* Commercial Property, 24 Anderson Road, Buffalo, New York 14225, Inquiry Number 8127688.2, dated October 1, 2025

US EPA Envirofacts website at: http://www.epa.gov/enviro/

EDR-Vapor Encroachment Screen, Commercial Property, 24 Anderson Road, Buffalo, New York 14225, Inquiry Number 8127688.2s, dated October 24, 2025

APPENDIX A

Figures



Source: USGS Buffalo NE, NY 7.5-Minute Quadrangle, dated 2019.


LEGEND	
N	Approximate Subject Property Boundary

TOPOGRAPHIC SITE MAP

Commercial Property
24 Anderson Road
Cheektowaga, Erie County, New York 14225

FIGURE 1
Job No: 235.984

FARMER ENVIRONMENTAL GROUP



Source: Google Earth® image dated June 11, 2024.

LEGEND	
N	Approximate Subject Property Boundary
	Inferred Groundwater Gradient
	**Identified on Regulatory Database*

AERIAL SITE MAP

Commercial Property
24 Anderson Road
Cheektowaga, Erie County, New York 14225

FIGURE 2
Job No: 235.984

FARMER ENVIRONMENTAL GROUP

APPENDIX B

Subject Property Documents

OWNER'S POLICY OF TITLE INSURANCE

Issued by **Chicago Title Insurance Company**

Chicago Title Insurance Company

POLICY NUMBER
HB2016-60026

Any notice of claim and any other notice or statement in writing required to be given to the Company under this Policy must be given to the Company at the address shown in Section 18 of the Conditions.

COVERED RISKS

SUBJECT TO THE EXCLUSIONS FROM COVERAGE, THE EXCEPTIONS FROM COVERAGE CONTAINED IN SCHEDULE B, AND THE CONDITIONS, Chicago Title Insurance Company (the "Company") insures, as of Date of Policy and, to the extent stated in Covered Risks 9 and 10, after Date of Policy, against loss or damage, not exceeding the Amount of Insurance, sustained or incurred by the Insured by reason of:

1. Title being vested other than as stated in Schedule A.
2. Any defect in or lien or encumbrance on the Title. This Covered Risk includes but is not limited to insurance against loss from
   (a) A defect in the Title caused by
      (i) forgery, fraud, undue influence, duress, incompetency, incapacity, or impersonation;
      (ii) failure of any person or Entity to have authorized a transfer or conveyance;
      (iii) a document affecting Title not properly created, executed, witnessed, sealed, acknowledged, notarized, or delivered;
      (iv) failure to perform those acts necessary to create a document by electronic means authorized by law;
      (v) a document executed under a falsified, expired, or otherwise invalid power of attorney;
      (vi) a document not properly filed, recorded, or indexed in the Public Records including failure to perform those acts by electronic means authorized by law; or
      (vii) a defective judicial or administrative proceeding.
   (b) The lien of real estate taxes or assessments imposed on the Title by a governmental authority due or payable, but unpaid.
   (c) Any encroachment, encumbrance, violation, variation, or adverse circumstance affecting the Title that would be disclosed by an accurate and complete land survey of the Land. The term "encroachment" includes encroachments of existing improvements located on the Land onto adjoining land, and encroachments onto the Land of existing improvements located on adjoining land.
3. Unmarketable Title.
4. No right of access to and from the Land.
5. The violation or enforcement of any law, ordinance, permit, or governmental regulation (including those relating to building and zoning) restricting, regulating, prohibiting, or relating to
   (a) the occupancy, use, or enjoyment of the Land;
   (b) the character, dimensions, or location of any improvement erected on the Land;
   (c) the subdivision of land; or
   (d) environmental protection

   if a notice, describing any part of the Land, is recorded in the Public Records setting forth the violation or intention to enforce, but only to the extent of the violation or enforcement referred to in that notice.
6. An enforcement action based on the exercise of a governmental police power not covered by Covered Risk 5 if a notice of the enforcement action, describing any part of the Land, is recorded in the Public Records, but only to the extent of the enforcement referred to in that notice.
7. The exercise of the rights of eminent domain if a notice of the exercise, describing any part of the Land, is recorded in the Public Records.
8. Any taking by a governmental body that has occurred and is binding on the rights of a purchaser for value without Knowledge.

Copyright American Land Title Association. All rights reserved. The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association

OWNER'S POLICY OF TITLE INSURANCE

Issued by **Chicago Title Insurance Company**

Chicago Title Insurance Company

POLICY NUMBER
HB2016-60026

9. Title being vested other than as stated in Schedule A or being defective
   (a) as a result of the avoidance in whole or in part, or from a court order providing an alternative remedy, of a transfer of all or any part of the title to or any interest in the Land occurring prior to the transaction vesting Title as shown in Schedule A because that prior transfer constituted a fraudulent or preferential transfer under federal bankruptcy, state insolvency, or similar creditors' rights laws; or
   (b) because the instrument of transfer vesting Title as shown in Schedule A constitutes a preferential transfer under federal bankruptcy, state insolvency, or similar creditors' rights laws by reason of the failure of its recording in the Public Records
      (i) to be timely, or
      (ii) to impart notice of its existence to a purchaser for value or to a judgment or lien creditor.
10. Any defect in or lien or encumbrance on the Title or other matter included in Covered Risks 1 through 9 that has been created or attached or has been filed or recorded in the Public Records subsequent to Date of Policy and prior to the recording of the deed or other instrument of transfer in the Public Records that vests Title as shown in Schedule A.

The Company will also pay the costs, attorneys' fees, and expenses incurred in defense of any matter insured against by this Policy, but only to the extent provided in the Conditions.

IN WITNESS WHEREOF, the Company has caused this Policy to be signed with the facsimile signatures of its President and Secretary and sealed as required by its By-Laws.

Countersigned: Harris Beach PLLC Melanie Marotta
Authorized Signature

Chicago Title Insurance Company

By:

Michael J. Nolan
President

Attest:

Marjorie Nemzura
Secretary

Chicago Title Insurance Company
Harris Beach
99 Garnsey Road
Pittsford, NY 14534

Phone: 585-419-8520 Fax: 585-955-4081

Copyright American Land Title Association. All rights reserved. The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association

EXCLUSIONS FROM COVERAGE

The following matters are expressly excluded from the coverage of this policy, and the Company will not pay loss or damage, costs, attorneys' fees, or expenses that arise by reason of:

1. (a) Any law, ordinance, permit, or governmental regulation (including those relating to building and zoning) restricting, regulating, prohibiting, or relating to
   (i) the occupancy, use, or enjoyment of the Land;
   (ii) the character, dimensions, or location of any improvement erected on the Land;
   (iii) the subdivision of land; or
   (iv) environmental protection;
   or the effect of any violation of these laws, ordinances, or governmental regulations. This Exclusion 1(a) does not modify or limit the coverage provided under Covered Risk 5.
   (b) Any governmental police power. This Exclusion 1(b) does not modify or limit the coverage provided under Covered Risk 6.
2. Rights of eminent domain. This Exclusion does not modify or limit the coverage provided under Covered Risk 7 or 8.
3. Defects, liens, encumbrances, adverse claims, or other matters
   (a) created, suffered, assumed, or agreed to by the Insured Claimant;
   (b) not Known to the Company, not recorded in the Public Records at Date of Policy, but Known to the Insured Claimant and not disclosed in writing to the Company by the Insured Claimant prior to the date the Insured Claimant became an Insured under this policy;
   (c) resulting in no loss or damage to the Insured Claimant;
   (d) attaching or created subsequent to Date of Policy (however, this does not modify or limit the coverage provided under Covered Risk 9 and 10); or
   (e) resulting in loss or damage that would not have been sustained if the Insured Claimant had paid value for the Title.
4. Any claim, by reason of the operation of federal bankruptcy, state insolvency, or similar creditors' rights laws, that the transaction vesting the Title as shown in Schedule A, is
   (a) a fraudulent conveyance or fraudulent transfer; or
   (b) a preferential transfer for any reason not stated in Covered Risk 9 of this policy.
5. Any lien on the Title for real estate taxes or assessments imposed by governmental authority and created or attaching between Date of Policy and the date of recording of the deed or other instrument of transfer in the Public Records that vests Title as shown in Schedule A.

CONDITIONS

1 DEFINITION OF TERMS

The following terms when used in this policy mean:

(a) "Amount of Insurance": The amount stated in Schedule A, as may be increased or decreased by endorsement to this policy, increased by Section 8(b), or decreased by Sections 11 and 12 of these Conditions.

(b) "Date of Policy": The date designated as "Date of Policy" in Schedule A.

(c) "Entity": A corporation, partnership, trust, limited liability company, or other similar legal entity.

(d) "Insured": The Insured named in Schedule A.

(i) the term "Insured" also includes

(A) successors to the Title of the Insured by operation of law as distinguished from purchase, including heirs, devisees, survivors, personal representatives, or next of kin;

(B) successors to an Insured by dissolution, merger, consolidation, distribution, or reorganization;

(C) successors to an Insured by its conversion to another kind of Entity;

(D) a grantee of an Insured under a deed delivered without payment of actual valuable consideration conveying the Title

(1) if the stock, shares, memberships, or other equity interests of the grantee are wholly-owned by the named Insured,

(2) if the grantee wholly owns the named Insured,

(3) if the grantee is wholly-owned by an affiliated Entity of the named Insured, provided the affiliated Entity and the named Insured are both wholly-owned by the same person or Entity, or

(4) if the grantee is a trustee or beneficiary of a trust created by a written instrument established by the Insured named in Schedule A for estate planning purposes.

(ii) With regard to (A), (B), (C), and (D) reserving, however, all rights and defenses as to any successor that the Company would have had against any predecessor Insured.

(e) "Insured Claimant": An Insured claiming loss or damage.

(f) "Knowledge" or "Known": Actual knowledge, not constructive knowledge or notice that may be imputed to an Insured by reason of the Public Records or any other records that impart constructive notice of matters affecting the Title.

(g) "Land": The land described in Schedule A, and affixed improvements that by law constitute real property. The term "Land" does not include any property beyond the lines of the area described in Schedule A, nor any right, title, interest, estate, or easement in abutting streets, roads, avenues, alleys, lanes, ways, or waterways, but this does not modify or limit the extent that a right of access to and from the Land is insured by this policy.

(h) "Mortgage": Mortgage, deed of trust, trust deed, or other security instrument, including one evidenced by electronic means authorized by law.

(i) "Public Records": Records established under state statutes at Date of Policy for the purpose of imparting constructive notice of matters relating to real property to purchasers for value and without Knowledge. With respect to Covered Risk 5(d), "Public Records" shall also include environmental protection liens filed in the records of the clerk of the United States District Court for the district where the Land is located.

(j) "Title": The estate or interest described in Schedule A.

(k) "Unmarketable Title": Title affected by an alleged or apparent matter that would permit a prospective purchaser or lessee of the Title or lender on the Title to be released from the obligation to purchase, lease, or lend if there is a contractual condition requiring the delivery of marketable title.

Copyright American Land Title Association. All rights reserved. The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association

2. CONTINUATION OF INSURANCE

The coverage of this policy shall continue in force as of Date of Policy in favor of an Insured, but only so long as the Insured retains an estate or interest in the Land, or holds an obligation secured by a purchase money Mortgage given by a purchaser from the Insured, or only so long as the Insured shall have liability by reason of warranties in any transfer or conveyance of the Title. This policy shall not continue in force in favor of any purchaser from the Insured of either (i) an estate or interest in the Land, or (ii) an obligation secured by a purchase money Mortgage given to the Insured.

3. NOTICE OF CLAIM TO BE GIVEN BY INSURED CLAIMANT

The Insured shall notify the Company promptly in writing (i) in case of any litigation as set forth in Section 5(a) of these Conditions, (ii) in case Knowledge shall come to an Insured hereunder of any claim of title or interest that is adverse to the Title, as insured, and that might cause loss or damage for which the Company may be liable by virtue of this policy, or (iii) if the Title, as insured, is rejected as Unmarketable Title. If the Company is prejudiced by the
the failure of the Insured Claimant to provide prompt notice, the Company's liability to the Insured Claimant under the policy shall be reduced to the extent of the prejudice.

4. PROOF OF LOSS

In the event the Company is unable to determine the amount of loss or damage, the Company may, at its option, require as a condition of payment that the Insured Claimant furnish a signed proof of loss. The proof of loss must describe the defect, lien, encumbrance, or other matter insured against by this policy that constitutes the basis of loss or damage and shall state, to the extent possible, the basis of calculating the amount of the loss or damage.

5. DEFENSE AND PROSECUTION OF ACTIONS

(a) Upon written request by the Insured, and subject to the options contained in Section 7 of these Conditions, the Company, at its own cost and without unreasonable delay, shall provide for the defense of an Insured in litigation in which any third party asserts a claim covered by this policy adverse to the Insured. This obligation is limited to only those stated causes of action alleging matters insured against by this policy. The Company shall have the right to select counsel of its choice (subject to the right of the Insured to object for reasonable cause) to represent the Insured as to those stated causes of action. It shall not be liable for and will not pay the fees of any other counsel. The Company will not pay any fees, costs, or expenses incurred by the Insured in the defense of those causes of action that allege matters not insured against by this policy.

(b)The Company shall have the right, in addition to the options contained in Section 7 of these Conditions, at its own cost, to institute and prosecute any action or proceeding or to do any other act that in its opinion may be necessary or desirable to establish the Title, as insured, or to prevent or reduce loss or damage to the Insured. The Company may take any appropriate action under the terms of this policy, whether or not it shall be liable to the Insured. The exercise of these rights shall not be an admission of liability or waiver of any provision of this policy. If the Company exercises its rights under this subsection, it must do so diligently.

(c) Whenever the Company brings an action or asserts a defense as required or permitted by this policy, the Company may pursue the litigation to a final determination by a court of competent jurisdiction, and it expressly reserves the right, in its sole discretion, to appeal any adverse judgment or order.

6. DUTY OF INSURED CLAIMANT TO COOPERATE

(a) In all cases where this policy permits or requires the Company to prosecute or provide for the defense of any action or proceeding and any appeals, the Insured shall secure to the Company the right to so prosecute or provide defense in the action or proceeding, including the right to use, at its option, the name of the Insured for this purpose. Whenever requested by the Company, the Insured, at the Company's expense, shall give the Company all reasonable aid (i) in securing evidence, obtaining witnesses, prosecuting or defending the action or proceeding, or effecting settlement, and (ii) in any other lawful act that in the opinion of the Company may be necessary or desirable to establish the Title or any other matter as insured. If the Company is prejudiced by the failure of the Insured to furnish the required cooperation, the Company's obligations to the Insured under the policy shall terminate, including any liability or obligation to defend
, prosecute, or continue any litigation, with regard to the matter or matters requiring such cooperation.

(b) The Company may reasonably require the Insured Claimant to submit to examination under oath by any authorized representative of the Company and to produce for examination, inspection, and copying, at such reasonable times and places as may be designated by the authorized representative of the Company, all records, in whatever medium maintained, including books, ledgers, checks, memoranda, correspondence, reports, e-mails, disks, tapes, and videos whether bearing a date before or after Date of Policy, that reasonably pertain to the loss or damage. Further, if requested by any authorized representative of the Company, the Insured Claimant shall grant its permission, in writing, for any authorized representative of the Company to examine, inspect, and copy all of these records in the custody or control of a third party that reasonably pertain to the loss or damage. All information designated as confidential by the Insured Claimant provided to the Company pursuant to this Section shall not be disclosed to others unless, in the reasonable judgment of the Company, it is necessary in the administration of the claim. Failure of the Insured Claimant to submit for examination under oath, produce any reasonably requested information, or grant permission to secure reasonably necessary information from third parties as required in this subsection, unless prohibited by law or governmental regulation, shall terminate any liability of the Company under this policy as to that claim.

7. OPTIONS TO PAY OR OTHERWISE SETTLE CLAIMS; TERMINATION OF LIABILITY

In case of a claim under this policy, the Company shall have the following additional options:

(a) to Pay or Tender Payment of the Amount of Insurance.

To pay or tender payment of the Amount of Insurance under this policy together with any costs, attorneys' fees, and expenses incurred by the Insured Claimant that were authorized by the Company up to the time of payment or tender of payment and that the Company is obligated to pay.

Upon the exercise by the Company of this option, all liability and obligations of the Company to the Insured under this policy, other than to make the payment required in this subsection, shall terminate, including any liability or obligation to defend, prosecute, or continue any litigation.

(b) to Pay or Otherwise Settle With Parties Other Than the Insured or With the Insured Claimant.

(i) To pay or otherwise settle with other parties for or in the name of an Insured Claimant any claim insured against under this policy. In addition, the Company will pay any costs, attorneys' fees, and expenses incurred by the Insured Claimant that were authorized by the Company up to the time of payment and that the Company is obligated to pay; or

Copyright American Land Title Association. All rights reserved. The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association

(ii) To pay or otherwise settle with the Insured Claimant the loss or damage provided for under this policy, together with any costs, attorneys' fees, and expenses incurred by the Insured Claimant that were authorized by the Company up to the time of payment and that the Company is obligated to pay.

Upon the exercise by the Company of either of the options provided for in subsections (b)(i) or (ii), the Company's obligations to the Insured under this policy for the claimed loss or damage, other than the payments required to be made, shall terminate, including any liability or obligation to defend, prosecute, or continue any litigation

8. DETERMINATION AND EXTENT OF LIABILITY

This policy is a contract of indemnity against actual monetary loss or damage sustained or incurred by the Insured Claimant who has suffered loss or damage by reason of matters insured against by this policy.

(a) The extent of liability of the Company for loss or damage under this policy shall not exceed the lesser of

(i) the Amount of Insurance; or

(ii) (ii) the difference between the value of the Title as insured and the value of the Title subject to the risk insured against by this policy.

(b) If the Company pursues its rights under Section 5 of these Conditions and is unsuccessful in establishing the Title, as insured,

(i) the Amount of Insurance shall be increased by 10%, and

(ii) the Insured Claimant shall have the right to have the loss or damage determined either as of the date the claim was made by the Insured Claimant or as of the date it is settled and paid.

(c) In addition to the extent of liability under (a) and (b), the Company will also pay those costs, attorneys' fees, and expenses incurred in accordance with Sections 5 and 7 of these Conditions

9. LIMITATION OF LIABILITY

a) If the Company establishes the Title, or removes the alleged defect, lien, or encumbrance, or cures the lack of a right of access to or from the Land, or cures the claim of Unmarketable Title, all as insured, in a reasonably diligent manner by any method, including litigation and the completion of any appeals, it shall have fully performed its obligations with respect to that matter and shall not be liable for any loss or damage caused to the Insured.

(b) In the event of any litigation, including litigation by the Company or with the Company's consent, the Company shall have no liability for loss or damage until there has been a final determination by a court of competent jurisdiction, and disposition of all appeals, adverse to the Title, as insured.

(c) The Company shall not be liable for loss or damage to the Insured for liability voluntarily assumed by the Insured in settling any claim or suit without the prior written consent of the Company.

10. REDUCTION OF INSURANCE; REDUCTION OR TERMINATION OF LIABILITY

All payments under this policy, except payments made for costs, attorneys' fees, and expenses, shall reduce the Amount of Insurance by the amount of the payment.

11. LIABILITY NONCUMULATIVE

The Amount of Insurance shall be reduced by any amount the Company pays under any policy insuring a Mortgage to which exception is taken in Schedule B or to which the Insured has agreed, assumed, or taken subject, or which is executed by an Insured after Date of Policy and which is a charge or lien on the Title, and the amount so paid shall be deemed a payment to the Insured under this policy.

12. PAYMENT OF LOSS

When liability and the extent of loss or damage have been definitely fixed in accordance with these Conditions, the payment shall be made within 30 days.

13. RIGHTS OF RECOVERY UPON PAYMENT OR SETTLEMENT

(a) Whenever the Company shall have settled and paid a claim under this policy, it shall be subrogated and entitled to the rights of the Insured Claimant in the Title and all other rights and remedies in respect to the claim that the Insured Claimant has against any person or property, to the extent of the amount of any loss, costs, attorneys' fees, and expenses paid by the Company. If requested by the Company, the Insured Claimant shall execute documents to evidence the transfer to the Company of these rights and remedies. The Insured Claimant shall permit the Company to sue, compromise, or settle in the name of the Insured Claimant and to use the name of the Insured Claimant in any transaction or litigation involving these rights and remedies.

If a payment on account of a claim does not fully cover the loss of the Insured Claimant, the Company shall defer the exercise of its right to recover until after the Insured Claimant shall have recovered its loss.

(b) The Company's right of subrogation includes the rights of the Insured to indemnities, guaranties, other policies of insurance, or bonds, notwithstanding any terms or conditions contained in those instruments that address subrogation rights.

14. ARBITRATION

Either the Company or the Insured may demand that the claim or controversy shall be submitted to arbitration pursuant to the Title Insurance Arbitration Rules of the American Land Title Association ("Rules"). Except as provided in the Rules, there shall be no joinder or consolidation with claims or controversies of other persons. Arbitrable matters may include, but are not limited to, any controversy or claim between the Company and the Insured arising out of or relating to this policy, any service in connection with its issuance or the breach of a policy provision, or to any other controversy or claim arising out of the transaction giving rise to this policy.

All arbitrable matters when the Amount of Insurance is $2,000,000 or less shall be arbitrated at the option of either the Company or the Insured. All arbitrable matters when the Amount of Insurance is in excess of $2,000,000 shall be arbitrated only when agreed to by both the Company and the Insured. Arbitration pursuant to this policy and under the Rules shall be binding upon the parties. Judgment upon the award rendered by the Arbitrator(s) may be entered in any court of competent jurisdiction.

15. LIABILITY LIMITED TO THIS POLICY; POLICY ENTIRE CONTRACT

(a) This policy together with all endorsements, if any, attached to it by the Company is the entire policy and contract between the Insured and the Company. In interpreting any provision of this policy, this policy shall be construed as a whole.

(b) Any claim of loss or damage that arises out of the status of the Title or by any action asserting such claim shall be restricted to this policy.

(c) Any amendment of or endorsement to this policy must be in writing and authenticated by an authorized person, or expressly incorporated by Schedule A of this policy.

(d) Each endorsement to this policy issued at any time is made a part of this policy and is subject to all of its terms and provisions. Except as the endorsement expressly states, it does not (i) modify any of the terms and provisions of the policy, (ii) modify any prior endorsement, (iii) extend the Date of Policy, or (iv) increase the Amount of Insurance.

16. SEVERABILITY

In the event any provision of this policy, in whole or in part, is held invalid or unenforceable under applicable law, the policy shall be deemed not to include that provision or such part held to be invalid, but all other provisions shall remain in full force and effect.

Copyright American Land Title Association. All rights reserved. The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association

17. CHOICE OF LAW; FORUM

(a) Choice of Law: The Insured acknowledges the Company has underwritten the risks covered by this policy and determined the premium charged therefor in reliance upon the law affecting interests in real property and applicable to the interpretation, rights, remedies, or enforcement of policies of title insurance of the jurisdiction where the Land is located.

Therefore, the court or an arbitrator shall apply the law of the jurisdiction where the Land is located to determine the validity of claims against the Title that are adverse to the Insured and to interpret and enforce the terms of this policy. In neither case shall the court or arbitrator apply its conflicts of law principles to determine the applicable law.

(b) Choice of Forum: Any litigation or other proceeding brought by the Insured against the Company must be filed only in a state or federal court within the United States of America or its territories having appropriate jurisdiction.

18. NOTICES, WHERE SENT

Any notice of claim and any other notice or statement in writing required to be given to the Company under this policy must be given to the Company at:

Chicago Title Insurance Company
National Claims Administration
PO Box 45023
Jacksonville, Florida 32232-5023

Copyright American Land Title Association. All rights reserved. The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association

Chicago Title Insurance Company

Chicago Title Insurance Company
AMERICAN LAND TITLE ASSOCIATION OWNERS POLICY (6/17/06)
WITH NEW YORK COVERAGE ENDORSEMENT APPENDED (A.L.T.A.)

Policy No.:	Date of Policy:	Amount of Insurance:
HB2016-60026	April 28, 2023	$1,300,000.00

SCHEDULE A

1. **Name of Insured**

   Recovery Real Estate Services LLC, a Delaware limited liability company

2. **The estate or interest in the Land which is covered by this Policy is:**

   Fee Simple

3. **Title is vested in:**

   Recovery Real Estate Holdings LLC a Delaware LLC by deed recorded May 2, 2023 in Liber 11416 of Deeds at page 6822.

4. **The Land referred to in this policy is described as follows: -SEE ATTACHED DESCRIPTION-**

Harris Beach PLLC

Authorized Signatory

Harris Beach
99 Garnsey Road Pittsford, NY 14534
Phone: 585-419-8520 Fax: 585-955-4081

Copyright American Land Title Association. All rights reserved.
The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE A
LEGAL DESCRIPTION

All that tract or parcel of land situate in the Town of Cheektowaga, County Of Erie and State of New York, being part of Lot No. 24, Township 11, Range 7 of the Holland Land Company's Survey, described as follows:

Commencing at a point in a line drawn parallel with the westerly boundary line of lands conveyed by General American Transportation Corporation, formerly General American Tank Car Corporation to Walden Properties Inc. by deed dated August 28, 1946 and recorded in Erie County Clerk's Office in liber 3980 of Deeds page 480 on September 17, 1946 which line runs northerly along the center of a private roadway 100 feet wide, the vehicular portion of which is 30 feet wide from a point in the center line of Walden Avenue distant 365 feet southeasterly measured along said center line of Walden Avenue from the point of intersection of the said center line of Walden Avenue with the westerly boundary line of the lands conveyed by the aforesaid deed to Walden Properties Inc. which point of commencement is distant 372.5 feet northerly from the center line of Walden Avenue (said point of beginning being the southeast corner of lands conveyed by the Walden Properties Inc. to Screen Equipment Co. Inc. by deed dated October 1, 1948 and recorded in said Clerk's Office in liber 4407 of Deeds page 546 on October 1, 1948): running thence westerly at right angles with the said center line of said private roadway and along the southerly line of lands conveyed to the said Screen Equipment Co. Inc. as described in said deed for a distance of 345.6 feet to the west line of lands conveyed to Walden Properties Inc. by deed aforesaid: running thence southerly along the west line of lands conveyed to Walden Properties Inc. by deed aforesaid, 129 feet to a point: thence easterly at right angles for the distance of 106.20 feet: thence southerly at right angles for a distance of 23 feet: thence easterly at right angles for the distance of 239.4 feet to the center line of said private roadway 100 feet wide: thence northerly along the said center line of said private roadway 152 feet to the point or place of beginning.

Excepting and excluding therefrom that portion of the above premises conveyed to the Town of Cheektowaga by deed recorded in Erie County Clerk's Office in liber 6222 of Deeds page 679.

And more modernly described as

ALL THAT TRACT OR PARCEL OF LAND containing 1.045 acres more or less, situate in the Holland and Holland Purchase, Township 11, Range 7, Town Lot 24, Town of Cheektowaga, County of Eire, and State of New York, as shown on the drawing entitled "Map of a Survey, 24 Anderson Road," prepared by BME Associates, having drawing number 8901-565, last revised March 21, 2023, being more particularly bounded and described as follows:

Beginning at the intersection of the westerly right-of-way line of Anderson Road (Right-of-Way Width Varies) with the southerly boundary line of lands now or formerly of Peter L Krog & Fred J Hanania (T.A. No. 102.03-2-28); thence

1) S 00°30'38" W, along said westerly right-of-way line of Anderson Road, a distance of 152.00 feet to a point on the northerly boundary line of lands now or formerly of Dale Anderson LLC (T.A. No. 102.03-2-30); thence

Copyright American Land Title Association. All rights reserved.
The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE A
LEGAL DESCRIPTION (CONTINUED)

2) N 89°29'22" W, along said northerly boundary line of lands of Dale Anderson LLC, a distance of 209.40 feet to a point; thence

3) N 00°30'38" E, continuing along said northerly boundary line of lands of Dale Anderson LLC, a distance of 23.00 feet to a point; thence

4) N 89°29'22" W, continuing along said northerly boundary line of lands of Dale Anderson LLC, a distance of 106.20 feet to a point on the easterly boundary line of lands now of formerly of Upstate Farms Cooperative Inc. (T.A. No. 102.03-2-20.111); thence

5) N 00°30'38" E, along said easterly boundary line of lands of Upstate Farms Cooperative Inc., a distance of 129.00 feet to a point on the aforementioned southerly boundary line of lands of Peter L Krog & Fred J Hanania; thence

6) S 89°29'22" E, along said southerly boundary line of lands of Peter L Krog & Fred K Hanania, a distance of 315.60 feet to the Point of Beginning.

Copyright American Land Title Association. All rights reserved.
The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

SCHEDULE B

This policy does not insure against loss or damage, and the Company will not pay costs, attorneys' fees, or expenses that arise by reason of:

1. Rights and claims of parties in possession not shown of record, under unrecorded lease agreement dated December 10, 2022 by and between DiVita Family Partnership L.P. and Green Mountain Electric Supply, Inc.

2. Future installments of special assessments for improvements payable with County taxes.

3. Unpaid water charges, if any.

4. Any state of facts an inspection of premises would disclose.

5. New York Real Property Tax Law Sections 302 and 520 may affect the real estate tax liability if the premises described in Schedule "A" have a tax exemption. Pursuant to the Real Property Tax Law, the exemption of the premises from taxation terminates immediately upon the acquisition of title by a non-exempt entity. The premises shall be taxed pro rata for the unexpired term of that taxable year and subsequent thereon at the full valuation without benefit of such tax exemption.

6. Exceptions as disclosed by Survey no. 8901 made by BME Associates and dated October 21, 2022 last revised March 21, 2023 as follows:

   a. Brick and concrete building erected within lines of record title.
   b. Variations between line of fence and westerly line of insured premises
   c. Overhead wires traverse insured premises
   d. Monitoring well adjacent to southerly boundary line
   e. Rights of others in and to Anderson Road.
   f. GV (gas valve) and WV (water valve) in easterly portion of insured premises and in right of way.
   h. Variations between measured and record angle measurements.

Copyright American Land Title Association. All rights reserved.
The use of this Form is restricted to ALTA licensees and ALTA members in good standing as of the date of use. All other uses are prohibited. Reprinted under license from the American Land Title Association.

Chicago Title Insurance Company

LAND SAME AS SURVEY ENDORSEMENT

Attached to and made a part of Policy No. HB2016-60026

The Company hereby assures the Insured that said Land is the same as that delineated on the plat of a survey made by Survey no. 8901 made by BME Associates and dated October 21, 2022 last revised March 21, 2023

The Company hereby insures said Assured against loss which said Assured shall sustain in the event said assurances herein shall prove to be incorrect.

The total liability of the Company under said policy and any endorsement therein shall not exceed, in the aggregate, the face amount of said policy and costs which the Company is obligated under the Conditions thereof to pay.

This endorsement is made part of the policy and is subject to all of the terms and provisions thereof and of any prior endorsements thereto. Except to the extent expressly stated, it neither modifies any of the terms and provisions of the policy and any prior endorsements, nor does it extend the effective date of the policy and any prior endorsements, nor does it increase the face amount thereof.

Chicago Title Insurance Company

Dated: April 28, 2023

By:

President

Countersigned:

By: Hans Beach PLLC Melanie Merritt

Authorized Signatory

Note: This endorsement shall not be valid or binding until countersigned by an authorized signatory.

By:

Secretary

Chicago Title Insurance Company

WAIVER OF ARBITRATION ENDORSEMENT (OWNER'S OR LOAN POLICY)

Attached to and made a part of policy No. HB2016-60026

The policy is amended by deleting therefrom:

(A) If this endorsement is attached to an ALTA Loan Policy: Condition 13.

(B) If this endorsement is attached to an ALTA Owner's Policy: Condition 14.

(C) If this endorsement is attached to a TIRSA Owner's Extended Protection Policy: Condition 12.

This endorsement is made a part of the Policy and is subject to all of the terms and provisions thereof and of any other endorsements thereto. Except to the extent expressly stated, it neither modifies any of the terms and provisions of the Policy and any other endorsements, nor does it extend the effective date of the Policy and any other endorsements, nor does it increase the face amount thereof.

Chicago Title Insurance Company

Dated: April 28, 2023

Countersigned:

By: _____
Authorized Signatory

Note: This endorsement shall not be valid or binding until countersigned by an authorized signatory.

By: _____
President

By: _____
Secretary

Chicago Title Insurance Company

POLICY AUTHENTICATION ENDORSEMENT

Attached to and made part of Policy Number: HB2016-60026

When the policy is issued by the Company with a policy number and Date of Policy, the Company will not deny liability under the policy or any endorsements issued with the policy solely on the grounds that the policy or endorsements were issued electronically or lack signatures in accordance with the Conditions.

This endorsement is issued as part of the policy. Except as it expressly states, it does not (i) modify any of the terms and provisions of the policy, (ii) modify any prior endorsements, (iii) extend the Date of Policy, or (iv) increase the Amount of Insurance. To the extent a provision of the policy or a previous endorsement is inconsistent with an express provision of this endorsement, this endorsement controls. Otherwise, this endorsement is subject to all of the terms and provisions of the policy and of any prior endorsements.

Chicago Title Insurance Company

DATED: April 28, 2023

Countersigned: _____
Authorized Signatory



Chicago Title Insurance Company

STANDARD NEW YORK ENDORSEMENT

(OWNER'S POLICY)

1. The following is added as a Covered Risk:

   "11. Any statutory lien arising under Article 2 of the New York Lien Law for services, labor or materials furnished prior to the date hereof, and which has now gained or which may hereafter gain priority over the estate or interest of the insured as shown in Schedule A of this policy."

2. Exclusion Number 5 is deleted, and the following is substituted:

   5. Any lien on the Title for real estate taxes, assessments, water charges or sewer rents imposed by governmental authority and created or attaching between Date of Policy and the date of recording of the deed or other instrument of transfer in the Public Records that vests Title as Shown in Schedule A.

This endorsement is issued as part of the policy. Except as it expressly states, it does not (i) modify any of the terms and provisions of the policy, (ii) modify any prior endorsements, (iii) extend the Date of Policy, or (iv) increase the Amount of Insurance. To the extent a provision of the policy or a previous endorsement is inconsistent with an express provision of this endorsement, this endorsement controls. Otherwise, this endorsement is subject to all of the terms and provisions of the policy and of any prior endorsements.

Chicago Title Insurance Company

DATED: April 28, 2023

By: _____
President

Countersigned: _____
Authorized Signatory

By: _____
Secretary

Town of Cheektowaga, NY



9/12/2025, 3:12:01 PM

1:921

0 0.01 0.01 0.02 mi

0 0.01 0.01 0.03 km

Maxar, Microsoft, Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

Property Details - 24 Anderson Rd, Cheektowaga, 14225 - 102.03-2-29 - SWIS: 143089 (Cheektowaga)

Structure

Building 1	
Number of Identical Buildings	1
Actual Year Built	1961
Effective Year Built	1990
Construction Quality	2.0
Condition	3 - Normal
Building Perimeter	754
Gross Floor Area	25200
Number of Stories	2.0
Story Height	14
Air Conditioning %	0%
Sprinkler %	100%
Number of Elevators	
Basement Perimeter	
Basement Sq. Ft	





2025 Final Assessment Information

Land Assessed Value	$77,000
Total Assessed Value	$740,000
Equalization Rate	75.00%
Full Market Value	$986,667
Partial Construction	No
County Taxable	$740,000
Municipal Taxable	$740,000
School Taxable	$740,000
Village Taxable	$0
Agricultural District	No

Property Description

Property Location	24 Anderson Rd
Property Type	449 - Other Storage
Neighborhood Code	506
SWIS	143089
Water Supply	3 - Comm/public
Utilities	4 - Gas & elec
Sewer Type	3 - Comm/public
Zoning	
School	Cheektowaga
Book	11416
Page	6822
Grid East	1097673
Grid North	1058591
Roll Section	1
Acres	1.05
Front	152.00
Depth	345.60

Last Property Sale

Deed Date	05/02/2023
Deed Book	11416
Deed Page	6822
Contract Date	
Sale Date	05/02/2023
Full Sale Price	$1,300,000
Net Sale Price	$1,300,000
Usable For Valuation	No
Arms Length	No
Prior Owner	Divita Family Partnership LP

Owner Information								
Owner Name	Address 1	Address 2	PO Box	City	State	Zip	Unit Name	Unit Number
Recovery Real Estate Holdings	356 Rathe Rd			Colchester	VT	05446		

Sales										
Deed Date	Deed Book	Deed Page	Contract Date	Sale Date	Last Physical Inspection Date	Sale Price	Net Sale Price	Usable for Valuation	Arms Length	Prior Owner
05/02/2023	11416	6822		05/02/2023		$1,300,000	$1,300,000	No	No	Divita Family Partnership LP
11/10/2022	11410	3886		11/10/2022		$1	$1	No	No	Richard DiVita
10/30/2020	11368	6897		10/30/2020		$1	$1	No	No	Richard Divita

No Exemption Data Found


Land						
Site #	Land Type	Acres	Front	Depth	Sq Ft	Soil Rating
1	01 - Primary	1.05				

Commercial Site Uses


Site #	Commercial Use	Total Units	Total Rentable Area (sqft.)
1	E04 - Row office	0	5958
1	F05 - Row storage	0	19242

Improvements

Site #	Structure Code	SqFt	Dimensions	Quantity	Overall Condition	Actual Year Built	Effective Year Built
1	LP4 - Pavng-asphlt		18500.00 x 4.00	1.00	3 - Normal	1965	
1	OH1 - Ovrhdoor-com	169.00		1.00	3 - Normal	1990	


Subject Property
(Approximate)
NOTES
REVISION TABLE
SPECIAL DISTRICTS
LEGEND
DIVISION OF REAL PROPERTY TAX SERVICES
ERIE COUNTY, NEW YORK
TOWN OF CHEEKTOWAGA
102.03

USGS Mineral Resources Online Map





Map Scale: 1:534 if printed on A landscape (11" x 8.5") sheet.

N

Meters
0 5 10 20 30

Feet
0 25 50 100 150

Map projection: Web Mercator Corner coordinates: WGS84 Edge tics: UTM Zone 17N WGS84

MAP LEGEND

Area of Interest (AOI)

- Area of Interest (AOI)

Soils

- Soil Map Unit Polygons
- Soil Map Unit Lines
- Soil Map Unit Points

Special Point Features

- Blowout
- Borrow Pit
- Clay Spot
- Closed Depression
- Gravel Pit
- Gravelly Spot
- Landfill
- Lava Flow
- Marsh or swamp
- Mine or Quarry
- Miscellaneous Water
- Perennial Water
- Rock Outcrop
- Saline Spot
- Sandy Spot
- Severely Eroded Spot
- Sinkhole
- Slide or Slip
- Sodic Spot
- Spoil Area
- Stony Spot
- Very Stony Spot
- Wet Spot
- Other
- Special Line Features

Water Features

- Streams and Canals

Transportation

- Rails
- Interstate Highways
- US Routes
- Major Roads
- Local Roads

Background

- Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:15,800.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Erie County, New York
Survey Area Data: Version 25, Sep 4, 2025

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: May 13, 2023—May 27, 2023

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
Ud	Urban land	1.0	100.0%
Totals for Area of Interest		**1.0**	**100.0%**

National Flood Hazard Layer FIRMette

78°46'38"W 42°54'26"N



78°46'W 42°54'N

Feet 0 250 500 1,000 1,500 2,000

1:6,000

Basemap Imagery Source: USGS National Map 2023

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 Cross Sections with 1% Annual Chance
- 17.5 Water Surface Elevation
- Coastal Transect
- Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 8/20/2024 at 1:02 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

U.S. Fish and Wildlife Service
National Wetlands Inventory

Wetland Map



August 20, 2024

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

National Wetlands Inventory (NWI)
This page was produced by the NWI mapper

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

ABOUT THE ERIE COUNTY WATER AUTHORITY


The ECWA was created in 1949 by a special act of the New York State Legislature to ensure that the people and the industry of Erie County would have a safe, plentiful supply of water for the future. Since 1953, the ECWA has produced and reliably delivered water of the highest quality to its customers at an affordable rate. As an independent public-benefit corporation, ECWA is not an agency of New York State and is independent of Erie County government. ECWA operates as a financially self-sustaining public utility and pays all its operating expenses from revenues generated by the sale of water to its over 550,000 customers.

To comply with State Regulations, ECWA will be annually issuing a report describing the quality of your drinking water. The purpose of this report is to raise your understanding of drinking water and awareness of the need to protect our drinking water sources. Last year, your tap water met all New York State drinking water health standards. We are proud to report our system did not violate a maximum contaminant level or any other water quality standard. This report provides an overview of last year's water quality. Included are details about where your water comes from, what it contains, and how it compares to state standards.

If you have any questions about this report or concerns about your drinking water, please contact Sabrina Figler, Director of Water Quality, @ 716-685-8574. We want you to be informed about your drinking water. If you want to learn more, please attend any of our regularly scheduled Board meetings. The schedule may be found on www.ecwa.org. Board meetings are also streamed live and archived for later viewing from this website.

WHERE DOES OUR WATER COME FROM?

In general, the sources of drinking water, both tap and bottled, include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally occurring minerals, and in some cases, radioactive material, and can pick up substances resulting from the presence of animal or human activities. Contaminants that may be present in source water include microbial contaminants, inorganic contaminants, pesticides and herbicides, organic chemical contaminants, and radioactive contaminants. To ensure that tap water is safe to drink, the State and the EPA prescribe regulations which limit the number of certain contaminants in water provided by public systems. The State Department's and the FDA's regulations establish limits for contaminants in bottled water which must provide the same protection for public health.



Our source waters are Lake Erie and the Niagara River. The ECWA's Sturgeon Point Treatment Plant in the Town of Evans draws water from Lake Erie to supply the southern area of Erie County and some communities in Chautauqua and Cattaraugus Counties. The Van de Water Treatment Plant in the Town of Tonawanda draws water from the Niagara River and provides water to the northern area of Erie County and to some customers of Monroe County Water Authority (MCWA) through an interconnection at the border to Genesee County. The MCWA operates in Genesee County. We do not directly serve any customers within Monroe County. These two plants serve more than 550,000 people through 174,558 service connections in Western New York. The water is treated by conventional treatment and filtration and chlorine disinfection. The ECWA is one of the many systems in NYS that adds a low level of fluoride to drinking water to provide consumer dental health protection. During 2024, our system did not experience any restriction of our water source.

FACTS AND FIGURES

In 2024, the ECWA produced approximately 26.19 billion gallons of high-quality water for residential, commercial, and industrial use in thirty-six municipalities. The daily average of water treated and pumped into the distribution system was 71.77 million gallons. The highest single day produced 88.10 million gallons. The amount of water delivered to customers was 15.99 billion gallons. Authorized unbilled consumption such as plant processes, flushing water mains, equipment and hydrant testing and fighting fires accounted for 0.596 billion gallons. Meter inaccuracies, unauthorized consumption and known leaks accounted for 8.65 billion gallons. Losses due to unknown transmission and distribution leaks, services leaks and tank leakage and overflows account for 0.954 billion gallons. In 2024, residential water customers paid $4.64/1000 gallons. The 2024 residential average customer bill was $92.68 per quarter or $370.72 for the year.

ARE THERE CONTAMINANTS IN OUR DRINKING WATER?

As the state regulations require, we routinely test your drinking water for numerous contaminants. These contaminants include total coliform, turbidity, inorganic compounds, nitrate, lead and copper, volatile organic compounds, total trihalomethanes, haloacetic acids, radiological and synthetic organic compounds. The table presented below depicts which compounds were detected in your drinking water. The state allows us to test for some contaminants less than once per year because the concentration of these contaminants does not change frequently. Some of our data, though representative, are more than one year old. The sample date is directly noted.

It should be noted that all drinking water, including bottled drinking water, may be reasonably expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the EPA's Safe Drinking Water Hotline @ 1-800-426-4791 or the Erie County Health Department @ 716-961-6800.

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

DETECTED CONTAMINANTS

CONTAMINANT	VIOLATION YES/NO	DATE OF HIGHEST OCCURENCE	LEVEL DETECTED (Avg/Max); (Range)	UNIT MEASUREMENT	MCLG	REGULATORY LIMIT (MCL, TT OR AL)	LIKELY SOURCE OF CONTAMINATION
Inorganic Contaminants & Physical Tests							
Barium	No	4/24/2024	0.0201-0.0222 mg/L; Average=0.0212mg/L	mg/L	2.0 mg/L	2.0 mg/L	Erosion of natural deposits; discharge of drilling wastes; discharge from metal refineries.
Chloride	No	1/31/2024	15.1-31.7 mg/L; Average=19.3 mg/L	mg/L	NE	250 mg/L	Naturally occurring or indicative of road salt contamination
Chlorine	No	11/12/2024	1.30-1.85 mg/L; Average=1.59 mg/L	mg/L	NA	MRDL=4.0 mg/L	Added for disinfection.
Copper[2]	No	8/2024	ND-110 ug/L; 90th percentile=36.2 ug/L, 0 of 76 above AL	ug/L	1300 ug/L	AL=1300 ug/L	Corrosion of home plumbing systems; natural erosion; leaching from wood preservatives
Fluoride	No	9/22/2024	0.20-1.09 mg/L; Average=0.68 mg/L	mg/L	NA	2.2 mg/L	Erosion of natural deposits; water additive that promotes strong teeth; discharge from aluminum and fertilizer facilities.
Lead[3]	No	7/2024	ND-40.1 ug/L; 90th percentile =7.36 ug/L, 3 of 76 above AL	ug/L	0 ug/L	AL=15 ug/L	Home plumbing corrosion; natural erosion.
Nickel	No	4/24/2024	0.98-1.05 ug/L. Average=1.02 ug/L	ug/L	NE	NR	Nickel enters ground water and surface water by dissolution of rocks and soils, from atmospheric fall out; from biological decay and from waste disposal.
Nitrates	No	5/20/2024	0.19-0.23 mg/L Average = 0.21 mg/L	mg/L	10 mg/L	10 mg/L	Nitrates are naturally present in soils, water, air, and plants. Other sources are fertilizer and sewage run-off,
Manganese	No	2/8/2024	0.0-6.08 ug/L; Average=0.89 ug/L	ug/L	NE	NR	Naturally occurring, indication of landfill contamination.
pH	No	7/22/2024	7.30-8.18; Average=7.97	SU	NE	NR	Naturally occurring; adjusted for corrosion control.
Distribution System Turbidity	No	7/18/2024	0.09-0.96 NTU; Average=0.20 NTU	NTU	NA	TT =/<5 NTU	Soil runoff
Entry Point Turbidity[1]	No	1/29/2024	0.13 NTU highest level detected; Lowest monthly % <0.30 NTU=100%	NTU	NA	TT=95% of samples </= 0.30 NTU	Soil runoff
Total Organic Carbon	No	2/7/2024	1.49-2.39 mg/L; Average =1.78 mg/L	mg/L	NA	TT	Naturally occurring in the environment
Disinfection By-products							
Total Trihalomethanes	No	8/19/2024	13.7-62.9 ug/L; LRAA = 52[4]	ug/L	NE	LRAA = 80	By-product of water disinfection (chlorination)
Total Haloacetic Acids	No	5/23/2024	8.92-53.2 ug/L; LRAA = 41[4]	ug/L	NE	LRAA = 60	By-product of water disinfection (chlorination)
Radiological Contaminants							
Radium 228	No	7/19	ND	pCi/L	NE	NE	Erosion of natural deposits.
Combined Radium 226/228	No	7/19	ND	pCi/L	0	5.0	Erosion of natural deposits.

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

1 – Turbidity is a measure of the cloudiness of the water. We test it because it is a good indicator of the effectiveness of our filtration system. State regulations require that turbidity must always be below 1 NTU in the combined filter effluent. The regulations require that 95% of the entry point turbidity samples collected have measurements below 0.3 NTU. Our highest single system turbidity measurement, 0.130 NTU, for the year occurred in January 29, 2024

2 – The level presented represents the 90th percentile of the 76 sites tested. A percentile is a value on a scale of 100 that indicates the percent of a distribution that is equal to or below it. The 90th percentile is equal to or greater than 90% of the copper values detected at your water system. In this case, 76 samples were collected at your water system and the 90th percentile value was the ninth highest sample at 36.2 ug/L.

3 - The 90th percentile value of lead was the ninth highest sample at 7.36 ug/L. The action limit for lead was exceeded at 3 of the 76 sites tested.

4 – This level represents the highest locational running annual average calculated from data collected.

Definitions and Abbreviations:

Maximum Contaminant Level (MCL): The highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible.

Maximum Contaminant Level Goal (MCLG): The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

Maximum Residual Disinfectant Level (MRDL): The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG): The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contamination.

Action Level (AL): The concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

Treatment Technique (TT): A required process intended to reduce the level of a contaminant in drinking water.

Non-Detects (ND): Laboratory analysis indicates that the constituent is not present.

Nephelometric Turbidity Unit (NTU): A measure of the clarity of water. Turbidity more than 5 NTU is just noticeable to the average person.

Milligrams per liter (mg/l): Corresponds to one part of liquid in one million parts of liquid (parts per million - ppm).

Micrograms per liter (ug/l): Corresponds to one part of liquid in one billion parts of liquid (parts per billion - ppb).

Nanograms per liter (ng/l): Corresponds to one part of liquid in one trillion parts of liquid (parts per trillion - ppt).

Picocuries per liter (pCi/L): A measure of the radioactivity in water.

AL = Action Level: The concentration of the highest contaminant

LRAA = Locational Running Annual Average

ND = Not Detected: Laboratory analysis indicates the constituent is not present

NE = Not Established ***NR*** =Not Regulated

NA = Not Applicable ***SU*** = Standard Units

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

WHAT DOES THIS INFORMATION MEAN?

As you can see from the table, our system had no violations. We have learned through our testing that some contaminants have been detected; however, these contaminants were detected below the level allowed by the State. It should be noted that the action level for lead was exceeded in three homes, meaning the concentration was greater than 15 ppb. We are required to present the following information on lead in drinking water: Lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. The Erie County Water Authority is responsible for providing high quality drinking water and removing lead pipes but cannot control the variety of materials used in plumbing components in your home. You share the responsibility for protecting yourself and your family from the lead in your home plumbing. You can take responsibility by identifying and removing lead materials within your home plumbing and taking steps to reduce your family's risk. Before drinking tap water, flush your pipes for several minutes by running your tap, taking a shower, doing laundry or a load of dishes. You can also use a filter certified by an American National Standards Institute accredited to reduce lead in drinking water. If you are concerned about lead in your water and wish to have your water tested, contact the ECWA Water Quality Laboratory's Director of Water Quality at 716-685-8574. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available at *http://www.epa.gov/safewater/lead*.

IS OUR WATER SYSTEM MEETING OTHER RULES THAT GOVERN OPERATIONS?

During 2024, our system was in compliance with applicable State drinking water operating, monitoring, and reporting requirements.

INFORMATION ON RADON

Radon is a naturally occurring radioactive gas found in soil and outdoor air that may also be found in drinking water and indoor air. Some people exposed to elevated radon levels over many years in drinking water may have an increased risk of getting cancer. The main risk is lung cancer from radon entering indoor air from soil under homes.

In 2019, we collected a sample from each water treatment plant that were analyzed for radon. The results showed no detection of the radiological parameters. For additional information call your state radon program (1-800-458-1158) or call EPA's Radon Hotline (1-800-SOS-Radon).

DO I NEED TO TAKE SPECIAL PRECAUTIONS?

Although our drinking water met or exceeded state and federal regulations, some people may be more vulnerable to disease causing microorganisms or pathogens in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice from their health care provider about their drinking water. EPA/CDC guidelines on appropriate means to lessen the risk of infection by microbial pathogens are available from the Safe Drinking Water Hotline (800-426-4791).

INFORMATION ON FLUORIDE ADDITION

Our system is one of the many drinking water systems in New York State that provides drinking water with a controlled, low level of fluoride for consumer dental health protection. According to the United States Centers for Disease Control, fluoride is highly effective in preventing cavities when present in drinking water at a properly controlled level. To ensure that the fluoride supplement in your water provides optimal dental protection, we monitor fluoride levels daily to make sure fluoride is maintained at a target level of 0.7 mg/L. During 2024, monitoring showed that fluoride levels in your water were within 0.2 mg/l of the target level for 99% of the time.

INFORMATION ON LEAD SERVICE LINE INVENTORY

A lead service line (LSL) is defined as any portion of pipe that is made of lead which connects the water main to the building inlet. An LSL may be owned by the water system, owned by the property owner, or both. In accordance with the federal Lead and Copper Rule Revisions (LCRR), our system has prepared a lead service line inventory and have made it publicly accessible by posting a link to the inventory on our website @ www.ecwa.org.

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

INFORMATION ON UNREGULATED CONTAMINANTS

COMPOUNDS TESTED BUT NOT DETECTED				
Arsenic	Alachlor	Di-n-butyl phthalate	Metribuzin	Radium 226
4-Androstene-3,17-dione	Aldicarb	Di(2-ethylhexyl) adipate	Oxamyl (Vydate)	1,1-Dichloroethylene
Baygon	Aldicarb Sulfone	1,2-Dibromo-3-chloropropane	Oxyfluorfin	cis-1,2-Dichloroethylene
2-Chlorotoluene	Aldicarb Sulfoxide	Dibromomethane	PCB 1016	trans-1,2-Dichloroethylene
4-Chlorotoluene	Aldrin	Dicamba	PFDA	1,2-Dichloropropane
17beta-Estradiol	alpha -BHC	Dichlorodifluoromethane	PFDoA	1,3-Dichloropropane
17alpha-Ethynyl estradiol	Anatoxin-a	Dieldrin	PFHxA	2,2-Dichloropropane
2,4-D	Asbestos	Isopropylbenzene	PFTA	1,1-Dichloropropene
1,3 Butadiene	Atrazine	p-Isopropyltoluene	PFTrDA	cis-1,3-Dichloropropene
1,2-Dichlorobenzene	Benzene	Lindane	PFUnA	trans-1,3-Dichloropropene
1,3-Dichlorobenzene	Benzo(a)pyrene	Mercury	Permethrin	1,4-Dioxane
1,4-Dichlorobenzene	Chlorpyrifos	Methiocarb	Pichloram	3-Hydroxycarbofuran
1,1-Dichloroethane	Chromium, Total	Methomyl	Profenofos	2,3,7,8-TCDD (Dioxin)
1,2-Dichloroethane	Cobalt	Methoxychlor	Propachlor	2,4,5-TP (Silvex)
1,2,3-Trichloropropane	Cyanide	MTBE	Propylene Glycol	1,1,1,2-Tetrachloroethane
1,2,4-Trimethylbenzene	Cylindrospermopsin	Methylene Chloride	n-Propylbenzene	1,1,2,2-Tetrachloroethane
1,3,5-Trimethylbenzene	Dalapon	Metolachlor	Quinoline	1,2,3-Trichlorobenzene
Chlordane	Heptachlor	9CL-PF30NS	Xylenes (o,m and p)	Chlorobenzene
1,2,4-Trichlorobenzene	Di-Chlorodifluoromethane	Hexachlorobenzene	N-E-t-FOSAA	Heptachlor Epoxide

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

COMPOUNDS TESTED BUT NOT DETECTED				
1,1,1-Trichloroethane	Carbon Tetrachloride	Glyphosate	Perfluorodecanoic acid	o-Toluidine
1,1,2-Trichloroethane	Chloroethane	Gross Alpha Particles	Perfluoroheptanoic acid	Total Mircocystin
Beryllium	Chloromethane	Gross Beta Particles	Perfluorohexanesulfonic acid	Toxaphene
Bromide	Dimethipin	Hexachlorobutadiene	Perfluorononanoic acid	Tribufos
Bromobenzene	Dinoseb	Hexachlorocyclopentadiene	Perfluorooctane sulfonate	Trichloroethylene
Bromochloromethane	Diquat	PCB 1221	Perfluorooctanoic acid	Trichlorofluoromethane
Bromomethane	Endothall	PCB 1232	11Cl-PF3OUDS	Vinyl Chloride
Butachlor	Endrin	PCB 1242	ADONA	Zinc
Butylated hydroxyanisole	Equillin	PCB 1248	Selenium	
n-Butylbenzene	Estriol	PCB 1254	Simazine	
sec-Butylbenzene	Estrone	PCB 1260	Styrene	
t-Butylbenzene	Ethoprop	N-MeFOSAA	Tebuconazole	
Cadmium	Ethylbenzene	HFPO-DA	Tetrachloroethylene	
Carbaryl	Ethylene Dibromide (EDB)	Pentachlorophenol	Thallium	
Carbofuran	GenX	Perfluorobutanesulfonic acid	Toluene	

UNREGULATED PERFLUOROALKYL SUBSTANCES DETECTED					
CONTAMINANT	**VIOLATION**	**DATE OF SAMPLE**	**LEVEL DETECTED**	**UNIT MEASUREMENT**	**MCLG OR HEALTH ADVISORY LEVEL**
Perfluorobutanoic Acid (PFBA) [1]	No	7/1/2024	2.23	ng/L	NA

1- Unregulated perfluoroalkyl substance detected as part of ECWA's quarterly sampling for regulatory PFAS/PFOA testing for the New York State Department of Health.

USEPA Health Advisory Levels identify the concentration of a contaminant in drinking water at which adverse health effects and/or aesthetic effects are not anticipated to occur over specific exposure durations. Health Advisory Levels are not to be construed as legally enforceable federal standards and are subject to change as new information becomes available. The Maximum Contaminant Level Goal (MCLG) is the level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

Nanograms per liter (ng/l): Corresponds to one part of liquid in one trillion parts of liquid (parts per trillion - ppt).

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

WHY SAVE WATER AND HOW TO AVOID WASTING IT

The Erie County Water Authority encourages water conservation. Although Lake Erie and the Niagara River are a good supply of water, it must not be wasted. Our system has an adequate amount of water to meet present and future demands; however, there are several reasons why it is important to conserve water:

- Saving water, saves energy to process and deliver it to homes, businesses, and farms, and in turn, helps preserve the environment.
- Saving water reduces the cost of energy required to pump water and the need to construct costly new wells, pumping systems and water towers; and
- Saving water lessens the strain on the water system during a dry spell or drought, helping to avoid severe water use restrictions so that essential firefighting needs are met.
- Hydro-electric power requires water for its production.
- The planet is causing more water to evaporate as temperatures increase and droughts become all too common in some parts of the US and the World.

You can play a role in conserving water by becoming conscious of the amount of water your household is using, and by looking for ways to use less whenever you can. It is not hard to conserve water. Conservation tips include:

- Turn taps off tightly to prevent drips
- Repair leaks promptly
- Use an aerator or water flow reducer attachment to reduce water usage
- Volunteer in your community to protect water sources
- Join beach, stream or wetland cleanups
- Practice smart lawn watering and plant native species in your garden.
- Sweep, don't wash, sidewalks and driveways. Instead of using a hose, use a broom or a leaf blower and save 3-5 gallons of water per minute.

SYSTEM IMPROVEMENTS

ECWA spent 36.7 million dollars in system-wide infrastructure upgrades including:

- Sturgeon Point Filter Gallery Piping Replacement - $16,404,580
- Sturgeon Point Shoreline Stabilization Project - $1,433,228
- Sturgeon Point Wash Water Tank Replacement - $2,878,522
- Van de Water Filter Valve Replacement - $252,786
- Van de Water Residuals Treatment System Upgrades - $448,192
- LCRR Program Management (Curb Box Replacements) - $473,465
- Various VFD Upgrades - $305,462
- Pump Station and Distribution System Equipment Upgrades and Replacements (Various Locations) - $397,438
- Various Communications and SCADA Equipment Upgrades - $488,276
- Guenther Pump Station Rehabilitation Project - $280,399
- Newstead Pump Station Improvement Project - $568,277
- Waterline Replacement (Towns of Hamburg, West Seneca, and City of Lackawanna) - $3,138,558
- Waterline Replacement (Towns of Hamburg, West Seneca, and Cheektowaga) - $1,327,127
- Waterline Replacement (Towns of West Seneca and Cheektowaga) - $842,784
- Waterline Replacement (City of Tonawanda) - $412,652
- Waterline Replacement (Sheridan Dr./I-290) - $376,151
- Waterline Replacement (Town of Amherst) - $110,940

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY

AREAS SERVED

PUBLIC WATER SUPPLY NAME	PWS ID	POPULATION
ECWA Direct	NY1400443	313,380
Lease Managed Alden areas		345
ECWA Amherst	NY1400399	92,697
ECWA Boston	NY1421897	7,250
ECWA Evans	NY1400445	12,338
ECWA Hamburg Village	NY1400515	6,984
ECWA Lancaster	NY1400421	29,018
ECWA Newstead	NY1422651	5,801
ECWA Orchard Park	NY1421762	24,582
ECWA West Seneca	NY1404543	23,557

POPULATION SERVED

Direct Service/Lease Managed	515,952
Bulk Sale (within Erie County)	26,174
Silver Creek	2,617

CLOSING

Thank you for allowing us to continue to provide your family with quality drinking water this year. We ask that all our customers help us protect our water sources, which are the heart of our community.

For additional or large print copies of this report, please call 716-849-8444, or visit www.ecwa.org or email your request to questionscomments@ecwa.org.

2024 ANNUAL WATER QUALITY REPORT

ERIE COUNTY WATER AUTHORITY


New York State Department of Health Source Water Assessment

The New York State Department of Health completed a draft Source Water Assessment of the supply's raw water sources under the state's Source Water Assessment Program (SWAP). The purpose of this program is to compile, organize, and evaluate information regarding possible and actual threats to the quality of public water supply (PWS) sources. It is important to note that source water assessment reports estimate the potential for untreated drinking water sources to be impacted by contamination. These reports do not address the safety or quality of treated finished potable tap water. The Great Lakes' watershed is exceptionally large and too big for a detailed evaluation in the SWAP. General drinking water concerns for public water supplies, which use these sources include storm generated turbidity, wastewater, toxic sediments, shipping related spills, and problems associated with exotic species (e.g., zebra mussels – intake clogging and taste and odor problems). The SWAP is based on the analysis of the contaminant inventory compiled for the drainage areas deemed most likely to impact drinking water quality at this public water supply's raw water intakes. Separate assessments were completed for the Lake Erie source and the Niagara River source. The assessment found a moderate susceptibility to contamination for the Lake Erie source. The amount of agricultural land in the assessment area results in elevated potential of disinfection byproduct precursors and pesticides contamination. While there are some facilities present, permitted discharges do not likely represent an important threat to source water quality based on their density in the assessment area. There is also noteworthy contamination susceptibility associated with other discrete contaminant sources, and these facility types include: landfills. The assessment found an elevated susceptibility to contamination for the Niagara River source. The amount of agricultural (and to a lesser extent residential) lands in the assessment area results in elevated potential for microbials, disinfection byproduct precursors, and pesticides contamination. There is also a high density of sanitary wastewater discharges, which results in elevated susceptibility for all contaminant categories. Non-sanitary wastewater discharges may also contribute to contamination. There is also considerable contamination susceptibility associated with other discrete contaminant sources, and these facility types include: chemical bulk storage, inactive hazardous waste sites, landfills, Resource Conservation and Recovery Act facilities and Toxics Release Inventory facilities. If you have any questions about New York State's Source Water Assessment Program, please contact the Director of Environmental Health, Erie County Health Department at (716) 961-6800.

The seal of the Partnership for Safewater as seen on this document indicates that we are part of a select group of water systems nationwide who have voluntarily committed themselves toward an initiative-taking approach to strengthen the safety of drinking water for our customers above and beyond the current regulatory requirements. For additional information on the Partnership for Safewater visit www.awwa.org/science/partnership.

Pipeline and Hazardous Materials Safety Administration

NATIONAL PIPELINE MAPPING SYSTEM



Legend

- Accidents (Liquid)
- Incidents (Gas)
- Gas Transmission Pipelines
- Hazardous Liquid Pipelines

500 m
1000 ft

Pipelines depicted on this map represent gas transmission and hazardous liquid lines only. Gas gathering and gas distribution systems are not represented.

This map should never be used as a substitute for contacting a one-call center prior to excavation activities. Please call 811 before any digging occurs.

Questions regarding this map or its contents can be directed to npms@dot.gov.

Projection: Web Mercator


Datum: WGS84

Map produced by the Public Viewer application at www.npms.phmsa.dot.gov

Basemap image © OpenStreetMap contributors

Date Printed: Oct 22, 2025

NYSDEC Map



August 20, 2024

1:9,028

0 0.07 0.15 0.3 mi

0 0.13 0.25 0.5 km

Province of Ontario, Ontario MNR, Esri Canada, Esri, HERE, Garmin, INCREMENT P, Intermap, USGS, METI/NASA, EPA, USDA

NYS Department of Environmental Conservation
Not a legal document

DECinfo Locator Legend (Active Layers)

Permits and Registrations

Hazardous Waste Treatment, Storage & Disposal Facilities


Active Landfills


Transfer Facilities


Combustion Facilities


Inactive Solid Waste Landfills


Wastewater Facilities (SPDES)


Multi-Sector General Permits (MSGP)


Petroleum Bulk Storage Facilities


Major Oil Storage Facilities


Chemical Bulk Storage Facilities


Permitted and Reclaimed Mines


Oil, Gas and Other Regulated Wells


Water Wells


Projects of Interest

Environmental Cleanup

Environmental Easements

Remediation Parcels


Active Sites


No-Action Sites


Closed Sites

Sediment Caps


Sediment Caps

Legal Information

APPENDIX C

Subject Property Photographs




Photo 1: Eastern elevation of the Subject Property building.



Photo 2: Northern elevation of the Subject Property building.



Photo 3: View of the southern elevation of the Subject Property building.



Photo 4: View of the western elevation of the Subject Property building.



Photo 5: Monitor well on the western side of the Subject Property building.



Photo 6: Warehouse sump pit and pump in the warehouse portion of the building.




Photo 7: Inside view of the sump pit and pump in the warehouse.



Photo 8. Unidentified floor penetration near the northern warehouse wall.



Photo 9: Floor drain grate in warehouse. No water was visible in bottom of drain.



Photo 10: : Soil vapor sampling point in warehouse.



Photo 11: Western view inside warehouse.




Photo 12: Eastern view inside warehouse.



Photo 13: View inside the showroom area at the entrance of the Subject Property building.



Photo 14: Typical office inside the office portion of the Subject Property building.



Photo 15: Typical office inside the office portion of the Subject Property building.




Photo 16: View of the restroom in office portion of the Subject Property.



Photo 17: Stairway from the front office leading to second story offices.



Photo 18: Typical second story office.




Photo 19: View of HVAC system room in the office area.



Photo 20: Lighting fixture samples for the lighting supply company previously occupying the building.



Photo 21: Adjoining property to the north.



Photo 22: Adjoining property to the south.



Photo 23: Adjoining property to the west.



Photo 24: Adjoining property to the west.

APPENDIX D

ASTM Questionnaires and Records of Communication

The Town of Cheektowaga

Office of Building and Plumbing Inspections
275 Alexander Avenue
Alexander Community Center- Second Floor
Cheektowaga, New York 14211
(716) 686-3490

November 10, 2022

Richard DiVita
60 Bryant Wood South
Amherst, New York 14228

RE: 24 Anderson Road, Cheektowaga, NY 14225 SBL: 102.03-2-29

To Whom it May Concern:

Pursuant to your request please be advised of the following:

1. The subject property is currently zoned M2-Manufacturing as confirmed by the attached zoning map excerpt.

2. The subject property is not within any overlay district and the site was not developed in a PUD.

3. The properties to the north, east and south are zoned M2-Manufacturing and the properties to the west are Zoned M1-Light Manufacturing as confirmed by the attached zoning map excerpt.

4. The site was developed prior to the Town's Site Plan approval requirements found in section 260-47.1 of the Zoning Law of the Town of Cheektowaga.

5. A search of records available to this office revealed no valid operating permit permits for the following property-see attached application

6. A search of certificates of occupancy/compliance revealed no certificates available.

7. A search of records available to this office revealed that there are no open violations with the subject property.

Sincerely,
Town of Cheektowaga

Suzanne Sanscrainte
Assistant Code Enforcement Officer

ArcGIS Web Map



11/10/2022, 9:31:41 AM

Zoning Districts
- AG, Special Aggregates
- R, Residence
- RS, Residence Single Family
- RA, Residential Apartment
- RMH, Residential Mobile Home
- RSC, Residential Senior Citizen
- NS, Neighborhood Service
- CF, Community Facilities
- C, Retail Business
- CM, General Commercial
- MS, Motor Service
- M1, Light Manufacturing
- M2, General Manufacturing
- District Lines
- Parcels (2022)
- Road Labels

1:1,128

0 0.01 0.01 0.03 mi

0 0.01 0.03 0.05 km

Esri Community Maps Contributors, Province of Ontario, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA

ArcGIS Web AppBuilder

N
W E
S

TOWN of CHEEKTOWAGA
OFFICE of FIRE SAFETY
Application for Operating Permit

Permit application Fee $100.00 payable at time of filing.

FOR OFFICIAL USE ONLY

____/____ 20____ _____ _____-_____ ____/____ 20____ ☐ AM ☐ PM

Date of Application | Received By | Operating Permit No. | Inspection Date

Payment date: ___/___ 20___ **Fee waived if attached to Building Permit** (Building Permit No.: _____ - _____)

☐ ½ hour ☐ 1 hour ☐ A ☐ B ☐ M ☐ H ☐ R1 ☐ R2 ☐ S ☐ I ☐ E

APPLICANT to COMPLETE the PINK PORTION !

TYPE OF OPERATING PERMIT:

☐ Public Assembly ☐ Hazardous Materials ☐ Institutional ☐ Commercial ☐ Other

_____ _____ _____

Name of Business | Daytime Phone No. | Cell Phone No.

_____ Cheektowaga, NY _____ _____

Address of Business | Email Address

_____ _____ _____

Owner's Name | Daytime Phone No. | Cell Phone No.

_____ _____, ___ _____ _____

Owner's Address | City | State | Zip code | email address

Local Key Holder Information:

_____ _____ _____

Name | Daytime Phone No. | Cell Phone No.

_____ _____, ___ _____ _____

Address | City | State | Zip code | email address

INDICATE TYPE OF BUSINESS _____

If Day Care facility (number of children ____ , NYSOC&FS License #_____ Expiration Date _____

ADDITIONAL INFORMATION AND REQUIREMENTS ON REVERSE SIDE

Return this Application and the appropriate Fee to:

The Town of Cheektowaga Office of Fire Safety

275 Alexander Avenue, Cheektowaga, New York 14211

All attachments, certifications or drawings can be emailed to Firesafety@tocny.org.

Any additional questions should be directed to the Office of Fire Safety at (716) 686-3490.

Fire Protection Equipment Reports

(indicate all reports being provided with application)

The following information for all applicable fire protection equipment *must* be submitted to the Town of Cheektowaga Office of Fire Safety, before a permit or renewal of an existing permit will be issued!

Elevator Testing Reports.....	☐ Yes	☐ No	☐ N/A
Emergency Lighting Testing Reports as per IFC 604.6.....	☐ Yes	☐ No	☐ N/A
Exit Signs Maintained in working order.....	☐ Yes	☐ No	☐ N/A
Fire Alarm / Detection System Testing Certification as per NFPA 72.....	☐ Yes	☐ No	☐ N/A
Fire Extinguisher Annual Recertification as per NFPA 10.....	☐ Yes	☐ No	☐ N/A
Fire Pump Annual Testing Certification as per NFPA 25.....	☐ Yes	☐ No	☐ N/A
Fire Suppression System (Ansul) Testing Certification as per NFPA 17...	☐ Yes	☐ No	☐ N/A
Hood System Cleaning Certification.....	☐ Yes	☐ No	☐ N/A
Private Hydrant Inspection / Testing Certification as per NFPA 25.....	☐ Yes	☐ No	☐ N/A
Sprinkler System Testing Certification as per NFPA 25.....	☐ Yes	☐ No	☐ N/A

An Operating Permit *will not* be issued unless the above indicated documents have been submitted!

Knox Box has been installed.....	☐ Yes	☐ No	☐ N/A
Secured Keys are current.....	☐ Yes	☐ No	☐ N/A

For hazardous materials on site please attach a recent copy of :

Hazardous Materials Report Form as required by

General Municipal Law §209-u

Operation of a commercial business without a permit is a violation of the Town of Cheektowaga Fire Prevention Code and punishable by a fine and/or jail.

I HEREBY ACKNOWLEDGE THAT I HAVE READ THIS APPLICATION, THAT THE INFORMATION PROVIDED IS CORRECT, AND THAT I AM THE OWNER, OR AM DULY AUTHORIZED TO ACT ON THE OWNER'S BEHALF, AND AS SUCH HEREBY AGREE TO COMPLY WITH THE APPLICATION REQUIREMENTS OF THE FIRE PREVENTION CODE. I FURTHER UNDERSTAND THAT THIS PERMIT IS NOT A LICENSE.

Applicant's Signature _____ Applicant's Title _____

Return this Application and the appropriate Fee to:

The Town of Cheektowaga Office of Fire Safety

275 Alexander Avenue, Cheektowaga, New York 14211

All attachments, certifications or drawings can be emailed to Firesafety@tocny.org.

Any additional questions should be directed to the Office of Fire Safety at (716) 686-3490.

OFFICE OF FIRE PREVENTION AND CONTROL

HAZARDOUS MATERIALS REPORT FORM
(General Municipal Law, § 209-u)

The information entered herein is essential to your local fire chief for the protection of your employees, the firefighters and citizens in the immediate area, and to reduce damage to your property in the event of a fire or an emergency.

Every fire insurance policyholder, engaged in commerce in this state, is required by law to report the presence of hazardous materials at their business address.

Failure to file in accordance with the provisions of section 209-u of the General Municipal Law could result in a fine.

A separate report is required annually for each business address.

[redacted]

Hazardous Materials Location*

Firm Name _____ Street Add. Only _____

Bus. Add. _____ Bldg. Name or No. _____

City, State, Zip _____ City, State, Zip _____

Tel. No. _____ Policy Anniv. Date _____

Name
Emergency Contact _____ Bus. Tel. _____ Home Tel. _____

_____
(Signature and Title of Person Completing Form)

*It is suggested that a separate form be filled out for each building that contains hazardous materials.

EXEMPTIONS

Requests for exemptions from this law must be made in writing, attached to this form, and filed annually with your local fire department not later than the anniversary date of your policy.

All exemptions approved shall expire on the next policy anniversary date.

Exemptions denied shall require that the insured file a completed hazardous materials report form within 15 days of denial.

FOR FIRE DEPARTMENT USE ONLY



Exemptions: Approved _____ Denied _____ Additional Information Needed _____

_____ _____
(Date) (Signature of Fire Chief)

_____ _____
(Fire Department Name and Address) (Print Name of Fire Chief)

0347 (12/02)

V Hazardous Material Listing (attach additional sheets if necessary)
Note: Definitions of symbols are on the second page of the instruction sheet.

Identifying Symbol	Material Description & Proper Shipping Name	Total Amount	Identifying Symbol	Material Description & Proper Shipping Name	Total Amount
					
					
					
					
					
					
					

VI Special Considerations/Remarks:

Instructions for Hazardous Material Listing

Identifying Symbol: This area identifies different classes of hazardous material. Most material will fall within one of these classes. If a particular material falls within two or more classes, it should be listed in each applicable class.

Two additional boxes are provided for material that does not fall within any class. These boxes may also be used if additional space is needed to further identify previously listed categories.

Amounts to be reported are shown in Table 1 below.

NOTE: SHIPPING AND PACKAGING LABELS MAY BE OF ASSISTANCE IN IDENTIFYING THE CLASS OF MATERIAL.

Hazardous Material Description and Proper Shipping Name

This area is reserved for the description and name of any hazardous material within a given class. If there is more than one material within a certain class, at a given location, then the most prevalent or most common should be used (indicate "most common").

Total Amount

List the total amount of reportable material within the given class. If the amounts vary from day to day, then the average amount should be listed.

Identifying Symbol	Hazardous Material Description and Proper Shipping Name	Total Amount
	Ethyl Chloride	60 gals.
	(most common)	

Special Considerations/Remarks

This area is reserved for the policyholder and the fire chief for making any notes or comments they feel are pertinent. Several examples are listed below:

1. Building has a sprinkler system.
2. Adjacent building is a school.
3. Guard dogs are on the premises from 6:00 p.m. to 6:00 a.m.
4. Hazardous material amounts may vary greatly from day to day.
5. Poor water supply.
6. Access to the building is poor.
7. Flammable liquid is stored in the same building as oxidizer.

Table 1

Amounts to be Reported

1. Explosives and Blasting Agents - any amount
2. Poison Gas - any amount
3. Poison and Irritant - any amount
4. Flammable Liquid - over 5 gallons inside a building and over 10 gallons outside a building
5. Flammable Solid - any amount
6. Flammable Gas - over 2,000 cubic feet at normal temperature
7. Nonflammable Gas - over 6,000 cubic feet at normal temperature
8. Oxidizer - over 50 pounds
9. Organic Peroxide - over 10 pounds
10. Combustible Liquid - over 25 gallons inside a building and over 60 gallons outside a building
11. Radioactive Material - any amount
12. Corrosive Material - over 55 gallons
13. Dangerous When Wet Material - any amount
14. Etiologic Material - any amount

(OVER)

F100965-001 (4/82)
New York State Department of State, Office of Fire Prevention and Control

Hazardous Material Definitions

The following definitions have been abstracted from the Code of Federal Regulations, Title 49-Transportation, Parts 100 to 199. Refer to the referenced sections for complete details.

NOTE: Rulemaking proposals are outstanding or are contemplated concerning some of these definitions.

Hazardous Material - Means a substance or material which has been determined by the Secretary of Transportation to be capable of posing an unreasonable risk to health, safety and property, when transported in commerce, and which has been so designated. (Sec. 171.8)

Multiple Hazards - A material meeting the definitions of more than one hazard class is classed according to the sequence given in Sec. 173.2.

HAZARD CLASS	DEFINITIONS
EXPLOSIVES	An Explosive - Any chemical compound, mixture or device, the primary or common purpose of which is to function by explosion, i.e., with substantially instantaneous release of gas and heat, unless such compound, mixture or device is otherwise specifically classified in Parts 170-189. (Sec. 173.50)
CLASS A EXPLOSIVE	Detonating or otherwise of maximum hazard. The nine types of Class A explosives are defined in Sec. 173.53.
CLASS B EXPLOSIVE	In general, function by rapid combustion rather than detonation and include some explosive devices such as special fireworks, flash powders, etc. Flammable hazard. (Sec. 173.88)
CLASS C EXPLOSIVE	Certain types of manufactured articles containing Class A or Class B explosives, or both, as components but in restricted quantities, and certain types of fireworks. Minimum hazard. (Sec. 173.100)
BLASTING AGENTS	A material designed for blasting which has been tested in accordance with Sec. 173.114a(b) and found to be so insensitive that there is very little probability of accidental initiation to explosion or of transition from deflagration to detonation. (Sec. 173.114a(a))
COMBUSTIBLE LIQUID	Any liquid having a flash point above 100°F. and below 200°F. as determined by tests listed in Sec. 173.115(d). Exceptions to this are found in Sec. 173.115(b).
CORROSIVE MATERIAL	Any liquid or solid that causes visible destruction of human skin tissue or a liquid that has a severe corrosion rate on steel. See Sec. 173.240(a) and (b) for details.
FLAMMABLE LIQUID	Any liquid having a flash point below 100°F. as determined by tests listed in Sec. 173.115(d). Exceptions are listed in Sec. 173.115(a).
COMPRESSED GAS	Compressed Gas - Any material or mixture having in the container a pressure exceeding 40 psia at 70°F., or a pressure exceeding 104 psia at 130°F.; or any liquid flammable material having a vapor pressure exceeding 40 psia at 100°F. (Sec. 173.300(a))
FLAMMABLE GAS	Any compressed gas meeting the requirements for lower flammability limit, flammability limit range, flame projection, or flame propagation criteria as specified in Sec. 173.300(b).
NONFLAMMABLE GAS	Any compressed gas other than a flammable compressed gas.
FLAMMABLE SOLID	Any solid material, other than an explosive, which is liable to cause fires through friction, retained heat from manufacturing or processing, or which can be ignited readily and when ignited burns so vigorously and persistently as to create a serious transportation hazard. (Sec. 173.150)
ORGANIC PEROXIDE	An organic compound containing the bivalent -0-0 structure and which may be considered a derivative of hydrogen peroxide where one or more of the hydrogen atoms have been replaced by organic radicals must be classed as an organic peroxide unless...(See Sec. 173.151(a) for details)
OXIDIZER	A substance such as chlorate, permanganate, inorganic peroxide, or a nitrate, that yields oxygen readily to stimulate the combustion of organic matter. (See Sec. 173.151)
POISON A (Poison Gas)	Extremely Dangerous Poisons - Poisonous gases or liquids of such nature that a very small amount of the gas, or vapor of the liquid, mixed with air is dangerous to life. (Sec. 173.326)
POISON B (Poison)	Less Dangerous Poisons - Substances, liquids, or solids (including pastes and semi-solids), other than Class A or Irritating materials, which are known to be so toxic to man as to afford a hazard to health during transportation; or which, in the absence of adequate data on human toxicity, are presumed to be toxic to man. (Sec. 173.343)
IRRITATING MATERIAL	A liquid or solid substance which upon contact with fire or when exposed to air gives off dangerous or intensely irritating fumes, but not including any poisonous material, Class A. (Sec. 173.381)
ETIOLOGIC AGENT	An "etiologic agent" means a viable micro-organism, or its toxin which causes or may cause human disease. (Sec. 173.386) (Refer to the Department of Health, Education and Welfare Regulations, Title 42, CFR, Sec. 72.25(c) for details.)
RADIOACTIVE MATERIAL	Any material, or combination of materials, that spontaneously emits ionizing radiation, and having a specific activity greater than 0.002 microcuries per gram. (Sec. 173.389) NOTE: See Sec. 173.389(a) through (l) for details.
WATER REACTIVE MATERIAL (SOLID)	Means any solid substance (including sludges and pastes) which, by interaction with water, is likely to become spontaneously flammable or to give off flammable or toxic gases in dangerous quantities.

Commercial Property
24 Anderson Road
Buffalo, NY 14225

Inquiry Number: 8127688.8
October 01, 2025

EDR Building Permit Report

Target Property and Adjoining Properties

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

About This Report

Executive Summary

Findings

Glossary

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILD FAX PROPERTY HISTORY

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

A search of building department records was conducted by Environmental Data Resources, Inc (EDR) on behalf of Farmer Environmental Group on Oct 01, 2025.

TARGET PROPERTY

24 Anderson Road
Buffalo, NY 14225

SEARCH METHODS

EDR searches available lists for both the Target Property and Surrounding Properties.

RESEARCH SUMMARY

Building permits identified: **YES**

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Buffalo

Year	*Source*	*TP*	*Adjoining*
2025	City of Buffalo, Permit Office		
2024	City of Buffalo, Permit Office		
2023	City of Buffalo, Permit Office		
2022	City of Buffalo, Permit Office		
2021	City of Buffalo, Permit Office		
2020	City of Buffalo, Permit Office		
2019	City of Buffalo, Permit Office		
2018	City of Buffalo, Permit Office		
2017	City of Buffalo, Permit Office		
2016	City of Buffalo, Permit Office		
2015	City of Buffalo, Permit Office		
2014	City of Buffalo, Permit Office		
2013	City of Buffalo, Permit Office		
2012	City of Buffalo, Permit Office		
2011	City of Buffalo, Permit Office		X
2010	City of Buffalo, Permit Office		
2009	City of Buffalo, Permit Office		
2008	City of Buffalo, Permit Office		
2007	City of Buffalo, Permit Office		
2006	City of Buffalo, Permit Office		
2005	City of Buffalo, Permit Office		
2004	City of Buffalo, Permit Office		
2003	City of Buffalo, Permit Office		
2002	City of Buffalo, Permit Office		X
2001	City of Buffalo, Permit Office		
2000	City of Buffalo, Permit Office		X
1999	City of Buffalo, Permit Office		
1998	City of Buffalo, Permit Office		

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

Year	Source	TP	Adjoining
1997	City of Buffalo, Permit Office		
1996	City of Buffalo, Permit Office		
1995	City of Buffalo, Permit Office		

Cheektowaga town

Year	Source	TP	Adjoining
2025	Town of Cheektowaga, Community Development		X
2024	Town of Cheektowaga, Community Development		X
2023	Town of Cheektowaga, Community Development		X
	Town of Cheektowaga, Community Development	X	
2022	Town of Cheektowaga, Community Development		X
	Town of Cheektowaga, Community Development	X	
2021	Town of Cheektowaga, Community Development		X
2020	Town of Cheektowaga, Community Development		
2019	Town of Cheektowaga, Community Development		X
2018	Town of Cheektowaga, Community Development		X
2017	Town of Cheektowaga, Community Development		X
2016	Town of Cheektowaga, Community Development		X
2015	Town of Cheektowaga, Community Development		X
2014	Town of Cheektowaga, Community Development		X
2013	Town of Cheektowaga, Community Development		X
2012	Town of Cheektowaga, Community Development		X
2011	Town of Cheektowaga, Community Development		X
2010	Town of Cheektowaga, Community Development		X
2009	Town of Cheektowaga, Community Development		X
2008	Town of Cheektowaga, Community Development		X
2007	Town of Cheektowaga, Community Development		X
2006	Town of Cheektowaga, Community Development		
2005	Town of Cheektowaga, Community Development		
2004	Town of Cheektowaga, Community Development		X
2003	Town of Cheektowaga, Community Development		X
2002	Town of Cheektowaga, Community Development		X
2001	Town of Cheektowaga, Community Development		X
2000	Town of Cheektowaga, Community Development		X
1999	Town of Cheektowaga, Community Development		X
1998	Town of Cheektowaga, Community Development		
1997	Town of Cheektowaga, Community Development		X
1996	Town of Cheektowaga, Community Development		X
1995	Town of Cheektowaga, Community Development		X

Name: JurisdictionName
Years: Years
Source: Source
Phone: Phone

BUILDING DEPARTMENT RECORDS SEARCHED

Name: Buffalo
Years: 1995-2025
Source: City of Buffalo, Permit Office, BUFFALO, NY
Phone: (716) 851-4667

Name: Cheektowaga town
Years: 1995-2025
Source: Town of Cheektowaga, Community Development, Cheektowaga, NY
Phone: (716) 686-3434

Name: Ithaca town
Years: 1955-2019
Source: Town of Ithaca, Building and Code Enforcement Department, BUFFALO, NY
Phone: (607) 273-1783

Name: Amherst town
Years: 1995-2022
Source: Town of Amherst, Building Department, BUFFALO, NY
Phone: (716) 631-7080

Name: Tonawanda town
Years: 1990-2025
Source: Town of Tonawanda, Building Department, BUFFALO, NY
Phone: (716) 695-1800

Name: West Seneca town
Years: 1995-2022
Source: Town of, Code Enforcement, BUFFALO, NY
Phone: (716) 558-3242

Name: Clarence town
Years: 1990-2019
Source: Town of Clarence Building Department, BUFFALO, NY
Phone: (716) 741-8950

TARGET PROPERTY FINDINGS

TARGET PROPERTY DETAIL

24 Anderson Road
Buffalo, NY 14225

24 ANDERSON ROAD

Date:	**4/13/2023**
Permit Type:	
Description:	
Permit Description:	
Work Class:	Com. Change in Tenant
Proposed Use:	
Permit Number:	2023-0359
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Green Mountain Electric Supply

Date:	**4/13/2023**
Permit Type:	
Description:	
Permit Description:	
Work Class:	F. OP (Commercial)
Proposed Use:	
Permit Number:	2023-0362
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DiVita Family Partnership

TARGET PROPERTY FINDINGS

Date:	**11/10/2022**
Permit Type:	
Description:	
Permit Description:	
Work Class:	PZ Use Compliance Review
Proposed Use:	
Permit Number:	2022-3044
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	DiVita Family Partnership

ADJOINING PROPERTY FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

ANDERSON RD

25 ANDERSON RD

Date:	**11/1/2013**
Permit Type:	
Description:	**Remove and replace entry stairs**
Permit Description:	
Work Class:	Com. Interior Alteration
Proposed Use:	
Permit Number:	11-2013-Com. Interior Alteration-25 Anderson Rd
Status:	
Valuation:	$50,000.00
Contractor Company:	
Contractor Name:	Allied Builders Inc.

Work Class:	Com. Interior Alteration
Proposed Use:	
Permit Number:	11-2013-Com. Interior Alteration-25 Anderson Rd
Status:	
Valuation:	$7,000.00
Contractor Company:	
Contractor Name:	Grandview Const Inc

ADJOINING PROPERTY FINDINGS

Date: **11/1/2012**
Permit Type:
Description:

Permit Description:
Work Class: Com. Sign
Proposed Use:
Permit Number: 2012-0772
Status:
Valuation: $9,240.00
Contractor Company:
Contractor Name: Ulrich Sign Co Inc

Date: **4/18/2011**
Permit Type: **Commerical**
Description: **interior remodel-contractor OTB/ Plumber Aurora Plumbing Co.-Kimil will be exterior plumber**

Permit Description:
Work Class: Interior Alteration
Proposed Use:
Permit Number: 2011-31181
Status: BP Application For Building Permit
Valuation: $672,000.00
Contractor Company:
Contractor Name: OTB

C.O. Issued Date: **2/7/2013**
Date: **1/13/2011**
Permit Type: **Commerical**
Description: **TYPE II B CONSTRUCTION - B OCCUPANY - SPRINKLERED**

Permit Description:
Work Class: Interior Alteration
Proposed Use:
Permit Number: 2010-30906
Status: BP Certificate Of Occupancy - Final
Valuation: $80,000.00
Contractor Company:
Contractor Name: Grandview Const Inc

ADJOINING PROPERTY FINDINGS

C.O. Issued Date: **5/20/2010**
Date: **3/8/2010**
Permit Type: **Commerical**
Description: **Interior alteration**

Permit Description:
Work Class: Interior Alteration
Proposed Use:
Permit Number: 2010-27758
Status: BP Certificate Of Occupancy - Final
Valuation: $28,000.00
Contractor Company:
Contractor Name: Grandview Const Inc

Date: **7/26/2001**
Permit Type: **NA**
Description: **Install sign, ASA: , Co Type: COO, Insp: DJU, Type: S, Plan No:**

Permit Description:
Work Class: SIGNS
Proposed Use:
Permit Number: 2001-07402
Status: BP Application For Building Permit
Valuation: $820.00
Contractor Company:
Contractor Name:

Date: **12/1/2000**
Permit Type: **NA**
Description: **Interior remodeling, ASA: , Co Type: COC, Insp: GLP, Type: C, Plan No: 190-00R**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2000-06629
Status: BP Application For Building Permit
Valuation: $300,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**10/10/2000**
Permit Type:	**NA**
Description:	**Repair/Remodel Int./Ext. Office Building, ASA: , Co Type: COC, Insp: GLP, Type: C,**
Permit Description:	
Work Class:	COMMERICAL
Proposed Use:	
Permit Number:	2000-06540
Status:	BP Application For Building Permit
Valuation:	$600,000.00
Contractor Company:	
Contractor Name:	

Date:	**11/8/1999**
Permit Type:	**NA**
Description:	**Interior remodeling (Tenant space), ASA: , Co Type: COO, Insp: EJS, Type: C, Plan**
Permit Description:	
Work Class:	COMMERICAL
Proposed Use:	
Permit Number:	1999-05265
Status:	BP Application For Building Permit
Valuation:	$200.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

40 ANDERSON RD

Date: **10/11/2018**
Permit Type:
Description:

Permit Description:
Work Class: P. Exterior Sewer Repair
Proposed Use:
Permit Number: 2018-2838
Status:
Valuation: $2,000.00
Contractor Company:
Contractor Name: DV Brown*

Date: **7/27/2018**
Permit Type:
Description:

Permit Description:
Work Class: Com. Sign
Proposed Use:
Permit Number: 2018-1983
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Santoro Signs Inc*

Date: **3/1/2014**
Permit Type:
Description: **Application sent out for annual inspection**

Permit Description:
Work Class: OP (Hazardous Materials)
Proposed Use:
Permit Number: 3-2014-OP (Hazardous Materials)-40 Anderson Rd
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Krog Peter L &

ADJOINING PROPERTY FINDINGS

Date: **3/25/2013**
Permit Type:
Description:

Permit Description:
Work Class: OP (Hazardous Materials)
Proposed Use:
Permit Number: OP-2013-0313
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Krog Peter L &

C.O. Issued Date: **3/23/2010**
Date: **2/17/2010**
Permit Type: **Commerical**
Description: **change of tenant**

Permit Description:
Work Class: Change in Commercial Occupant
Proposed Use:
Permit Number: 2010-27712
Status: BP Certificate Of Compliance
Valuation: $0.00
Contractor Company:
Contractor Name:

45 ANDERSON RD

Date: **12/3/2012**
Permit Type:
Description:

Permit Description:
Work Class: P Misc
Proposed Use:
Permit Number: 2012-1132
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: H.K. Frey Sons, Inc.

ADJOINING PROPERTY FINDINGS

Date: **4/22/2008**
Permit Type: **Commerical**
Description: **Erect free standing single face sign**

Permit Description:
Work Class: Free Standing Signs
Proposed Use:
Permit Number: 2008-21383
Status: BP Application For Building Permit
Valuation: $1,500.00
Contractor Company:
Contractor Name: Fast Sign

Date: **10/14/2003**
Permit Type: **NA**
Description: **Extend entryway, ASA: , Co Type: COO, Insp: GLP, Type: C, Plan No:**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2003-10396
Status: BP Application For Building Permit
Valuation: $6,000.00
Contractor Company:
Contractor Name:

Date: **8/13/2003**
Permit Type: **NA**
Description: **Remodel office bldg, ASA: , Co Type: COO, Insp: GLP, Type: C, Plan No: 119-03**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2003-09978
Status: BP Application For Building Permit
Valuation: $20,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**4/26/1996**
Permit Type:	**NA**
Description:	**Erect conc. blk. addition, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No: 25-96**

Permit Description:	
Work Class:	COMMERICAL
Proposed Use:	
Permit Number:	1996-01324
Status:	BP Application For Building Permit
Valuation:	$9,500.00
Contractor Company:	
Contractor Name:	

Date:	**8/1/1995**
Permit Type:	**NA**
Description:	**Replace windows, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No:**

Permit Description:	
Work Class:	COMMERICAL
Proposed Use:	
Permit Number:	1995-00729
Status:	BP Application For Building Permit
Valuation:	$5,828.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

47 ANDERSON RD

Date: **10/27/2023**
Permit Type:
Description:

Permit Description:
Work Class: PZ Use Compliance Review
Proposed Use:
Permit Number: 2022-1933
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

Date: **1/3/2018**
Permit Type:
Description:

Permit Description:
Work Class: Zoning Review
Proposed Use:
Permit Number: 2017-2824
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Thomas Augello Esq

Date: **5/24/1999**
Permit Type: **NA**
Description: **Erect warehouse, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No: 55-99**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 1999-04612
Status: BP Application For Building Permit
Valuation: $100,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

51 ANDERSON RD

Date:	**5/10/2022**
Permit Type:	
Description:	
Permit Description:	
Work Class:	PZ Use Compliance Review
Proposed Use:	
Permit Number:	2022-0695
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Rajesh Patel

Date:	**7/24/2017**
Permit Type:	
Description:	
Permit Description:	
Work Class:	Zoning Review
Proposed Use:	
Permit Number:	2017-1226
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Aardee & Sons, Inc.

ADJOINING PROPERTY FINDINGS

60 ANDERSON RD

Date:	**3/10/2010**
Permit Type:	**Commerical**
Description:	**Interior Alteration**
Permit Description:	
Work Class:	Interior Alteration
Proposed Use:	
Permit Number:	2010-27765
Status:	BP Application For Building Permit
Valuation:	$29,000.00
Contractor Company:	
Contractor Name:	Best Drywall & Ceiling

Date:	**1/12/2010**
Permit Type:	**Residential**
Description:	**install 2 roof drains and two down spouts**
Permit Description:	
Work Class:	Miscellaneous
Proposed Use:	
Permit Number:	2010-27477
Status:	BP Application For Building Permit
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A Garelick & Sons Inc

C.O. Issued Date:	**1/20/2011**
Date:	**11/25/2009**
Permit Type:	**Commerical**
Description:	**change in occupancy**
Permit Description:	
Work Class:	Change in Commercial Occupant
Proposed Use:	
Permit Number:	2009-24810
Status:	BP Certificate Of Occupancy - Final
Valuation:	$1,000.00
Contractor Company:	
Contractor Name:	TBD

ADJOINING PROPERTY FINDINGS

Date: **11/16/2009**
Permit Type: **Commerical**
Description: **construct loading dock**

Permit Description:
Work Class: Warehouse Steel/Block
Proposed Use:
Permit Number: 2009-24811
Status: BP Application For Building Permit
Valuation: $45,000.00
Contractor Company:
Contractor Name: Legacy Building Co LLC

Date: **4/15/2002**
Permit Type: **NA**
Description: **Repair roof, ASA: , Co Type: COO, Insp: GLP, Type: C, Plan No:**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2002-08186
Status: BP Application For Building Permit
Valuation: $17,000.00
Contractor Company:
Contractor Name:

Date: **12/26/2001**
Permit Type: **NA**
Description: **Install ground sign, ASA: , Co Type: COO, Insp: DJU, Type: S, Plan No:**

Permit Description:
Work Class: SIGNS
Proposed Use:
Permit Number: 2001-07887
Status: BP Application For Building Permit
Valuation: $1,800.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

61 ANDERSON RD

Date:	**12/20/2012**
Permit Type:	
Description:	
Permit Description:	
Work Class:	P Misc
Proposed Use:	
Permit Number:	2012-1352
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Gross PHC LLC

C.O. Issued Date:	**3/23/2010**
Date:	**2/17/2010**
Permit Type:	**Commerical**
Description:	**change in tenant**
Permit Description:	
Work Class:	Change in Commercial Occupant
Proposed Use:	
Permit Number:	2010-27713
Status:	BP Certificate Of Compliance
Valuation:	$0.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

74 ANDERSON RD

Date:	**6/9/2011**
Permit Type:	**REPAIR**
Description:	
Permit Description:	**RENOVATIONS TO EXISTING BLDG**
Work Class:	
Proposed Use:	
Permit Number:	168419
Status:	Open
Valuation:	$800.00
Contractor Company:	
Contractor Name:	

C.O. Issued Date:	**4/27/2011**
Date:	**4/13/2011**
Permit Type:	**REPAIR**
Description:	
Permit Description:	**RENOVATIONS TO EXISTING BLDG**
Work Class:	
Proposed Use:	
Permit Number:	166554
Status:	Complete
Valuation:	$8,000.00
Contractor Company:	
Contractor Name:	

Date:	**9/16/2002**
Permit Type:	**NA**
Description:	**Install (3) wall signs, ASA: , Co Type: COO, Insp: DJU, Type: S, Plan No:**
Permit Description:	
Work Class:	SIGNS
Proposed Use:	
Permit Number:	2002-09070
Status:	BP Application For Building Permit
Valuation:	$500.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date:
Permit Type:
Description:

Permit Description:
Work Class:
Proposed Use:
Permit Number:
Status:
Valuation: $0.00
Contractor Company:
Contractor Name:

83 ANDERSON RD

Date: **4/25/2024**
Permit Type:
Description:

Permit Description:
Work Class: Com. Misc
Proposed Use:
Permit Number: 2024-1089
Status:
Valuation: $54,000.00
Contractor Company:
Contractor Name:

Date: **4/18/2024**
Permit Type:
Description:

Permit Description:
Work Class: F. OP (Commercial)
Proposed Use:
Permit Number: 2021-1124
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Kabir's II, LLC

ADJOINING PROPERTY FINDINGS

Date: **6/26/2018**
Permit Type:
Description:

Permit Description:
Work Class: F. OP (Commercial)
Proposed Use:
Permit Number: OP-2017-0377
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Kabir's II, LLC

Date: **10/11/2016**
Permit Type:
Description:

Permit Description:
Work Class: Zoning Review
Proposed Use:
Permit Number: 2016-1927
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Kabir's, LLC

Date: **10/1/2014**
Permit Type:
Description: **Holiday Inn Express**

Permit Description:
Work Class: OP (Commercial)
Proposed Use:
Permit Number: 10-2014-OP (Commercial)-83 Anderson Rd
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Kabir's, LLC

ADJOINING PROPERTY FINDINGS

Date: **5/1/2014**
Permit Type:
Description: **Install (3) wall signs and (1) 2 sided pole sign**

Permit Description:
Work Class: Com. Sign
Proposed Use:
Permit Number: 5-2014-Com. Sign-83 Anderson Rd
Status:
Valuation: $10,000.00
Contractor Company:
Contractor Name: Premier Sign Systems

Date: **1/1/2014**
Permit Type:
Description: **Construction of 4 story Holiday Inn Express**

Permit Description:
Work Class: Com./Ind. Building
Proposed Use:
Permit Number: 1-2014-Com./Ind. Building-83 Anderson Rd
Status:
Valuation: $5,810,000.00
Contractor Company:
Contractor Name: Eastern Hospitality

Date: **8/1/2013**
Permit Type:
Description: **Demolition**

Permit Description:
Work Class: Com. Demolition
Proposed Use:
Permit Number: 8-2013-Com. Demolition-83 Anderson Rd
Status:
Valuation: $10,000.00
Contractor Company:
Contractor Name: HH Rauh Contracting

ADJOINING PROPERTY FINDINGS

Date:	**12/20/2012**
Permit Type:	
Description:	
Permit Description:	
Work Class:	P Misc
Proposed Use:	
Permit Number:	2012-1351
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Gross PHC LLC

Date:	**12/27/2002**
Permit Type:	**DEMOLITION**
Description:	**FIRE EMERGENCY DEMOLITION TO GRADE OF A 2 STORY FRAME 1-FAMILY DWELLING AND GARAGE. FUTURE LAND USE VACANT**
Permit Description:	**DEMOLITION PERMIT**
Work Class:	
Proposed Use:	
Permit Number:	48988
Status:	C
Valuation:	$3,823.00
Contractor Company:	
Contractor Name:	BOOTH PATRICIA

Date:	**8/15/2000**
Permit Type:	**SWIM POOLS**
Description:	**PLACE AN INGROUND POOL (27FT X 8FT X 5.5 DEEP) TO THE REAR OF AN EXISTING 1.5 STORY FRAME 1 FAMILY DWELLING**
Permit Description:	**SWIMMING POOLS**
Work Class:	
Proposed Use:	
Permit Number:	22879
Status:	C
Valuation:	$2,000.00
Contractor Company:	
Contractor Name:	BEAUTY POOLS INC.

ADJOINING PROPERTY FINDINGS

90 ANDERSON RD

Date:	**11/1/2013**
Permit Type:	
Description:	**Replace Catch Basin, Extend existing 4' storm sewer to receiver at**
Permit Description:	
Work Class:	P Misc
Proposed Use:	
Permit Number:	11-2013-P Misc-90 Anderson Rd
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	A. Gareleck & Sons Inc.

Date:	**8/28/1996**
Permit Type:	**NA**
Description:	**Erect wall sign, ASA: , Co Type: COO, Insp: DJU, Type: S, Plan No:**
Permit Description:	
Work Class:	SIGNS
Proposed Use:	
Permit Number:	1996-01924
Status:	BP Application For Building Permit
Valuation:	$1,750.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

DALE RD

1730 DALE RD

Date: **3/19/2025**
Permit Type:
Description:

Permit Description:
Work Class: Com./Ind. Building
Proposed Use:
Permit Number: 2025-0635
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Upstate Farms Cooperative Inc

Date: **3/11/2025**
Permit Type:
Description:

Permit Description:
Work Class: PZ Project Review
Proposed Use:
Permit Number: 2024-3549
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Upstate Farms Cooperative Inc

ADJOINING PROPERTY FINDINGS

Date: **2/14/2025**
Permit Type:
Description:

Permit Description:
Work Class: PZ Use Compliance Review
Proposed Use:
Permit Number: 2024-3495
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Upstate Farms Cooperative Inc

Date: **10/27/2021**
Permit Type:
Description:

Permit Description:
Work Class: P. Water Line/Service
Proposed Use:
Permit Number: 2021-2742
Status:
Valuation: $10,000.00
Contractor Company:
Contractor Name: Upstate Farms Cooperative Inc

Date: **5/24/2017**
Permit Type:
Description:

Permit Description:
Work Class: Com. Misc
Proposed Use:
Permit Number: 2017-0723
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: BRD Inc

ADJOINING PROPERTY FINDINGS

Date: **4/24/2017**
Permit Type:
Description:

Permit Description:
Work Class: P. Com. Plumbing Permit
Proposed Use:
Permit Number: 2017-0868
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: A. Gareleck & Sons Inc.*

Date: **9/2/2016**
Permit Type:
Description:

Permit Description:
Work Class: P. Exterior Drainage
Proposed Use:
Permit Number: 2016-1974
Status:
Valuation: $6,000.00
Contractor Company:
Contractor Name: A. Gareleck & Sons Inc.

Date: **2/19/2016**
Permit Type:
Description:

Permit Description:
Work Class: Com. Interior Alteration
Proposed Use:
Permit Number: 2016-0068
Status:
Valuation: $60,000.00
Contractor Company:
Contractor Name: BRD Inc

ADJOINING PROPERTY FINDINGS

Date: **9/1/2014**
Permit Type:
Description: **Reroute storm sewer**

Permit Description:
Work Class: P Misc
Proposed Use:
Permit Number: 9-2014-P Misc-1730 Dale Rd
Status:
Valuation: $8,500.00
Contractor Company:
Contractor Name: A. Gareleck & Sons Inc.

Date: **7/1/2014**
Permit Type:
Description: **Remove broken concrete catch basin & installl**

Permit Description:
Work Class: P Misc
Proposed Use:
Permit Number: 7-2014-P Misc-1730 Dale Rd
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: A. Gareleck & Sons Inc.

Date: **6/1/2014**
Permit Type:
Description: **Remove broken concrete catch basin & installl**

Permit Description:
Work Class: P Misc
Proposed Use:
Permit Number: 6-2014-P Misc-1730 Dale Rd
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: A. Gareleck & Sons Inc.

ADJOINING PROPERTY FINDINGS

Date: **3/1/2014**
Permit Type:
Description: **Application sent out for annual inspection**

Permit Description:
Work Class: OP (Hazardous Materials)
Proposed Use:
Permit Number: 3-2014-OP (Hazardous Materials)-1730 Dale Rd
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Upstate Farms Cooperative Inc

Date: **3/7/2013**
Permit Type:
Description:

Permit Description:
Work Class: OP (Hazardous Materials)
Proposed Use:
Permit Number: OP-2013-0043
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Upstate Farms Cooperative Inc

Date: **7/1/2011**
Permit Type: **Residential/Commerical**
Description: **as per Greg. Multiple plumbing activities**

Permit Description:
Work Class: Multiple Plumbing Activities
Proposed Use:
Permit Number: 2011-32460
Status: BP Application For Building Permit
Valuation: $0.00
Contractor Company:
Contractor Name: A Garelick & Sons Inc

ADJOINING PROPERTY FINDINGS

C.O. Issued Date: **4/8/2010**
Date: **11/19/2009**
Permit Type: **Commerical**
Description: **Building addition**

Permit Description:
Work Class: Miscellaneous - Commerical
Proposed Use:
Permit Number: 2009-26638
Status: BP Certificate Of Occupancy - Final
Valuation: $49,000.00
Contractor Company:
Contractor Name: Lehigh Construction Group

C.O. Issued Date: **4/17/2008**
Date: **3/10/2008**
Permit Type: **Commerical**
Description: **Addition**

Permit Description:
Work Class: Industrial Masonry
Proposed Use:
Permit Number: 2008-20819
Status: BP Certificate Of Compliance
Valuation: $18,000.00
Contractor Company:
Contractor Name: Lehigh Construction Group

C.O. Issued Date: **11/15/2005**
Date: **8/26/2004**
Permit Type: **Commerical**
Description: **Erect warehouse**

Permit Description:
Work Class: Warehouse Steel/Block
Proposed Use:
Permit Number: 2004-11649
Status: BP Certificate Of Occupancy - Final
Valuation: $0.00
Contractor Company:
Contractor Name: BRD Construction

ADJOINING PROPERTY FINDINGS

Date: **8/7/2003**
Permit Type: **NA**
Description: **Extend warehouse, ASA: , Co Type: COO, Insp: GLP, Type: C, Plan No: 43-03R**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2003-09584
Status: BP Application For Building Permit
Valuation: $495,000.00
Contractor Company:
Contractor Name:

Date: **4/5/2001**
Permit Type: **NA**
Description: **Erect cold storage facility, ASA: , Co Type: COO, Insp: GLP, Type: C, Plan No: 30-**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2001-06846
Status: BP Application For Building Permit
Valuation: $2,350,000.00
Contractor Company:
Contractor Name:

Date: **4/5/2001**
Permit Type: **NA**
Description: **Demolish storage building, ASA: , Co Type: COO, Insp: GLP, Type: R, Plan No:**

Permit Description:
Work Class: DEMOLITION
Proposed Use:
Permit Number: 2001-06923
Status: BP Application For Building Permit
Valuation: $11,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **4/5/2001**
Permit Type: **NA**
Description: **Demolish cold storage, ASA: , Co Type: COO, Insp: GLP, Type: R, Plan No:**

Permit Description:
Work Class: DEMOLITION
Proposed Use:
Permit Number: 2001-06948
Status: BP Application For Building Permit
Valuation: $65,000.00
Contractor Company:
Contractor Name:

Date: **8/4/2000**
Permit Type: **NA**
Description: **Exterior buildout, ASA: , Co Type: COC, Insp: EJS, Type: C, Plan No: 71-00**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2000-05873
Status: BP Application For Building Permit
Valuation: $50,000.00
Contractor Company:
Contractor Name:

Date: **12/28/1997**
Permit Type: **NA**
Description: **Interior remodeling, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No:**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 1997-03279
Status: BP Application For Building Permit
Valuation: $8,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date: **9/19/1997**
Permit Type: **NA**
Description: **Interior remodeling, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No:**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 1997-03050
Status: BP Application For Building Permit
Valuation: $5,000.00
Contractor Company:
Contractor Name:

Date: **6/7/1996**
Permit Type: **NA**
Description: **Remove (2) Tanks, ASA: , Co Type: COO, Insp: MDK, Type: T, Plan No:**

Permit Description:
Work Class: TANKS
Proposed Use:
Permit Number: 1996-01655
Status: BP Application For Building Permit
Valuation: $9,200.00
Contractor Company:
Contractor Name:

Date: **7/1/1995**
Permit Type: **NA**
Description: **Support faclty&pad for mlktnks, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No:**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 1995-00553
Status: BP Application For Building Permit
Valuation: $6,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

1747 DALE RD

Date: **4/8/2025**
Permit Type:
Description:

Permit Description:
Work Class: Com. Misc
Proposed Use:
Permit Number: 2025-0881
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Innovative Mechanical Systems**

Date: **7/6/2017**
Permit Type:
Description:

Permit Description:
Work Class: P. Com. Plumbing Permit
Proposed Use:
Permit Number: 2017-1533
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Niagara Transformer Corp

Date: **6/1/2017**
Permit Type:
Description:

Permit Description:
Work Class: Com./Ind. Building
Proposed Use:
Permit Number: 2017-1144
Status:
Valuation: $200,000.00
Contractor Company:
Contractor Name: Niagara Transformer Corp

ADJOINING PROPERTY FINDINGS

Date: **3/31/2017**
Permit Type:
Description:

Permit Description:
Work Class: P. Multiple Plumb Activ
Proposed Use:
Permit Number: 2017-0673
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: MLP Plumbg & Mechanical*

Date: **1/9/2017**
Permit Type:
Description:

Permit Description:
Work Class: Com./Ind. Building
Proposed Use:
Permit Number: 2016-2215
Status:
Valuation: $2,000,250.00
Contractor Company:
Contractor Name: Niagara Transformer Corp

Date: **1/3/2017**
Permit Type:
Description:

Permit Description:
Work Class: F. Life Safety System
Proposed Use:
Permit Number: 2017-0007
Status:
Valuation: $2,000,000.00
Contractor Company:
Contractor Name: LBM Construction

ADJOINING PROPERTY FINDINGS

Date: **8/5/2016**
Permit Type:
Description:

Permit Description:
Work Class: Com. Demolition
Proposed Use:
Permit Number: 2016-1608
Status:
Valuation: $14,300.00
Contractor Company:
Contractor Name: Guard Const & Contracting

C.O. Issued Date: **1/13/2011**
Date: **1/10/2011**
Permit Type: **Residential**
Description: **Site work storm drains only**

Permit Description:
Work Class: Miscellaneous
Proposed Use:
Permit Number: 2011-31019
Status: BP Certificate Of Compliance
Valuation: $0.00
Contractor Company:
Contractor Name: HK Frey Heating & Plumbing

Date: **10/28/2002**
Permit Type: **NA**
Description: **Erect store building, ASA: , Co Type: COO, Insp: GLP, Type: C, Plan No: 156-02**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 2002-09054
Status: BP Application For Building Permit
Valuation: $65,650.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

Date:	**2/21/2002**
Permit Type:	**NA**
Description:	**Demolish warehouse, ASA: , Co Type: COO, Insp: GLP, Type: R, Plan No:**
Permit Description:	
Work Class:	DEMOLITION
Proposed Use:	
Permit Number:	2002-07954
Status:	BP Application For Building Permit
Valuation:	$5,000.00
Contractor Company:	
Contractor Name:	

Date:	**3/26/1999**
Permit Type:	**NA**
Description:	**Erect shelter over tank farm, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No: 18**
Permit Description:	
Work Class:	COMMERICAL
Proposed Use:	
Permit Number:	1999-04332
Status:	BP Application For Building Permit
Valuation:	$7,275.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

1800 DALE RD

Date: **3/4/2024**
Permit Type:
Description:

Permit Description:
Work Class: Com. Change in Tenant
Proposed Use:
Permit Number: 2024-0079
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Eberl Iron Works, Inc.

Date: **10/24/2019**
Permit Type:
Description:

Permit Description:
Work Class: P. Exterior Sewer Repair
Proposed Use:
Permit Number: 2019-3174
Status:
Valuation: $4,800.00
Contractor Company:
Contractor Name: Roto-Rooter Services*

Date: **3/31/1997**
Permit Type: **NA**
Description: **Erect warehouse, ASA: , Co Type: COO, Insp: EJS, Type: C, Plan No: 10796R**

Permit Description:
Work Class: COMMERICAL
Proposed Use:
Permit Number: 1997-01966
Status: BP Application For Building Permit
Valuation: $225,000.00
Contractor Company:
Contractor Name:

ADJOINING PROPERTY FINDINGS

1810 DALE RD

Date:	**3/26/2021**
Permit Type:	
Description:	
Permit Description:	
Work Class:	PZ Use Compliance Review
Proposed Use:	
Permit Number:	2021-0663
Status:	
Valuation:	$0.00
Contractor Company:	
Contractor Name:	Craig Minchen

1835 DALE RD

Date:	**3/30/2023**
Permit Type:	
Description:	
Permit Description:	
Work Class:	Com. Interior Alteration
Proposed Use:	
Permit Number:	2023-0746
Status:	
Valuation:	$30,000.00
Contractor Company:	
Contractor Name:	

ADJOINING PROPERTY FINDINGS

Date: **1/25/2023**
Permit Type:
Description:

Permit Description:
Work Class: P. Exterior Sewer Repair
Proposed Use:
Permit Number: 2023-0223
Status:
Valuation: $8,500.00
Contractor Company:
Contractor Name: Clarklift Of Buffalo Inc

Date: **9/15/2015**
Permit Type:
Description:

Permit Description:
Work Class: Com. Sign
Proposed Use:
Permit Number: 2015-1103
Status:
Valuation: $1,200.00
Contractor Company:
Contractor Name: Premier Sign Systems

Date: **4/1/2014**
Permit Type:
Description: **Prolift Inc**

Permit Description:
Work Class: OP (Hazardous Materials)
Proposed Use:
Permit Number: 4-2014-OP (Hazardous Materials)-1835 Dale Rd
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Clarklift Of Buffalo Inc

ADJOINING PROPERTY FINDINGS

Date: **12/1/2013**
Permit Type:
Description: **Install one wall sign**

Permit Description:
Work Class: Com. Sign
Proposed Use:
Permit Number: 12-2013-Com. Sign-1835 Dale Rd
Status:
Valuation: $4,220.00
Contractor Company:
Contractor Name: Art Parts Signs, Inc.

Date: **4/4/2013**
Permit Type:
Description:

Permit Description:
Work Class: OP (Hazardous Materials)
Proposed Use:
Permit Number: OP-2013-0361
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Clarklift Of Buffalo Inc

Date: **4/1/2013**
Permit Type:
Description: **Prolift Inc.**

Permit Description:
Work Class: OP (Hazardous Materials)
Proposed Use:
Permit Number: 4-2013-OP (Hazardous Materials)-1835 Dale Rd
Status:
Valuation: $0.00
Contractor Company:
Contractor Name: Clarklift Of Buffalo Inc

ADJOINING PROPERTY FINDINGS

Date: **11/2/2011**
Permit Type: **Residential/Commerical**
Description: **Repair 6 inch fire line and 2 inch domestic water line**

Permit Description:
Work Class: Multiple Plumbing Activities
Proposed Use:
Permit Number: 2011-33687
Status: BP Application For Building Permit
Valuation: $4,500.00
Contractor Company:
Contractor Name: A Garelick & Sons Inc

Date: **6/24/2011**
Permit Type: **Residential/Commerical**
Description: **sewer repair**

Permit Description:
Work Class: Sewer Repair
Proposed Use:
Permit Number: 2011-32362
Status: BP Application For Building Permit
Valuation: $0.00
Contractor Company:
Contractor Name: Cellino Plmbg

Date: **6/2/2008**
Permit Type: **Commerical**
Description: **refacing existing wall sign & pole sign**

Permit Description:
Work Class: Signs
Proposed Use:
Permit Number: 2008-21788
Status: BP Application For Building Permit
Valuation: $4,594.00
Contractor Company:
Contractor Name: Art Parts Signs Inc

ADJOINING PROPERTY FINDINGS

Date:	**2/20/2007**
Permit Type:	**Commerical**
Description:	**DOOSAN**
Permit Description:	
Work Class:	Signs
Proposed Use:	
Permit Number:	2007-17799
Status:	BP Application For Building Permit
Valuation:	$670.00
Contractor Company:	
Contractor Name:	Art Parts

GLOSSARY

General Building Department concepts

- **ICC:** The International Code Council. The governing body for the building/development codes used by all jurisdictions who've adopted the ICC guidelines. MOST of the US has done this. Canada, Mexico, and other countries use ICC codes books and guides as well. There are a few states who have added guidelines to the ICC codes to better fit their needs. For example, California has added seismic retrofit requirements for most commercial structures.
- **Building Department (Permitting Authority, Building Codes, Inspections Department, Building and Inspections):** This is the department in a jurisdiction where an owner or contractor goes to obtain permits and inspections for building, tearing down, remodeling, adding to, re-roofing, moving or otherwise making changes to any structure, Residential or Commercial.
- **Jurisdiction:** This is the geographic area representing the properties over which a Permitting Authority has responsibility.
- **GC:** General Contractor. Usually the primary contractor hired for any Residential or Commercial construction work.
- **Sub:** Subordinate contracting companies or subcontractors. Usually a "trades" contractor working for the GC. These contractors generally have an area of expertise in which they are licensed like Plumbing, Electrical, Heating and Air systems, Gas Systems, Pools etc. (called "trades").
- **Journeymen:** Sub contractors who have their own personal licenses in one or more trades and work for different contracting companies, wherever they are needed or there is work.
- **HVAC (Mechanical, Heating & Air companies):** HVAC = Heating, Ventilation, and Air Conditioning.
- **ELEC (Electrical, TempPole, TPole, TPower, Temporary Power, Panel, AMP Change, Power Release):** Electrical permits can be pulled for many reasons. The most common reason is to increase the AMPs of power in an electrical power panel. This requires a permit in almost every jurisdiction. Other commons reason for Electrical permits is to insert a temporary power pole at a new construction site. Construction requires electricity, and in a new development, power has yet to be run to the lot. The temporary power pole is usually the very first permit pulled for new development. The power is released to the home owner when construction is complete and this sometimes takes the form of a Power Release permit or inspection.
- **"Pull" a permit:** To obtain and pay for a building permit.
- **CBO:** Chief Building Official
- **Planning Department:** The department in the development process where the building /structural plans are reviewed for their completeness and compliance with building codes
- **Zoning Department:** The department in the development process where the site plans are reviewed for their compliance with the regulations associated with the zoning district in which they are situated.
- **Zoning District:** A pre-determined geographic boundary within a jurisdiction where certain types of structures are permitted / prohibited. Examples are Residential structure, Commercial/Retail structures, Industrial/Manufacturing structures etc. Each zoning district has regulations associated with it like the sizes of the lots, the density of the structures on the lots, the number of parking spaces required for certain types of structures on the lots etc.
- **PIN (TMS, GIS ID, Parcel#):** Property Identification Number and Tax Map System number.
- **State Card (Business license):** A license card issued to a contractor to conduct business.
- **Building Inspector (Inspector):** The inspector is a building department employee that inspects building construction for compliance to codes.
- **C.O.:** Certificate of Occupancy. This is the end of the construction process and designates that the owners now have permission to occupy a structure after its building is complete. Sometimes also referred to as a Certificate of Compliance.

GLOSSARY

Permit Content Definitions

- Permit Number: The alphanumerical designation assigned to a permit for tracking within the building department system. Sometimes the permit number gives clues to its role, e.g. a "PL" prefix may designate a plumbing permit.
- Description: A field on the permit form that allows the building department to give a brief description of the work being done. More often than not, this is the most important field for EP's to find clues to the prior use (s) of the property.
- Permit Type: Generally a brief designation of the type of job being done. For example BLDG-RES, BLDG-COM, ELEC, MECH etc.

Sample Building Permit Data

Date: Nov 09, 2000
Permit Type: Bldg -
New Permit Number: 101000000405
Status: Valuation: $1,000,000.00
Contractor Company: OWNER-BUILDER
Contractor Name:

Description: New one store retail (SAV-ON) with drive-thru pharmacy. Certificate of Occupancy.

From: Town of Cheektowaga
To: Kim Burst; Julie Symack
Subject: Freedom of Information Law (FOIL Request) Chris Jackson
Date: Wednesday, October 1, 2025 8:48:51 AM

Name
Chris Jackson
Email
chris.jackson@farmereg.com
Phone
4055193824
Name of Organization/Affiliation
Farmer Environmental Group
Address #1
800 Campbell Road
Address #2
Suite 123
City
Richardson
State
Texas
Zip
75081
Short Title of Records Requested
General Request
Address #1
24 Anderson Road
City
Cheektowaga
State
New York
Zip
14227
FOIL Request/Description of Records Requested
Farmer Environmental Group is performing an Environmental Site Assessment of the following property:

24 Anderson Road
Buffalo (Cheektowaga), Erie County, NY

Your assistance is requested in order to obtain pertinent information for the property we are assessing. Such information may consist of emergency responses to fires or hazardous material spills, code violations, storage/use of petroleum products and/or hazardous materials, ongoing compliance or enforcement actions, or information indicative of environmental concern.

How would you like to receive your documents? (Pursuant to FOIL Law §87(1), a fee of .25 per copy for copies of records up to 9"x14" or the actual cost of reproducing a record will be charged, except when a different fee is prescribed by statute. All requests will be in hard-copy unless otherwise noted and fees established.)

scanned and emailed

Signature

Signature Image

Date

10/01/2025

Chris Jackson

From: Butcher, Gregory <Gregory.Butcher@erie.gov>
Sent: Tuesday, September 30, 2025 8:20 AM
To: Chris Jackson; FOIL, EmerSrvc
Subject: [EXTERNAL]Re: Records Request

Good morning,

I can confirm that we see that there was a fire there, but the Town of Cheektowaga would maintain those records.

https://tocny.org/departments/town-clerk-receiver-of-taxes/foil-request/

Gregory J. Butcher - EMT, AEMD, CEO
Deputy Commissioner
Preparedness - Homeland Security
Erie County Emergency Services
716-858-2944 office
716-341-9273 cell
gregory.butcher@erie.gov

From: Chris Jackson <chris.jackson@farmereg.com>
Sent: Thursday, September 25, 2025 5:08 PM
To: FOIL, EmerSrvc <EmerSrvc.FOIL@erie.gov>
Subject: Records Request

You don't often get email from chris.jackson@farmereg.com. Learn why this is important

[**Caution**: this email is **not** from an Erie County employee: attachments or links **may not be safe**.]

Hello,

Farmer Environmental Group is performing an Environmental Site Assessment of the following property:

1746 Dale Road
Buffalo (Cheektowaga), Erie County, NY

It is our understanding that the Subject Property had a fire incident during 2021. Your assistance is requested to obtain pertinent records for the incident (e.g., fire response report). We appreciate your assistance with this matter and please contact me with any questions.

Best regards,

Chris Jackson
Environmental Department Manager
Farmer Environmental Group, LLC

800 East Campbell Road
Suite 123
Richardson, Texas 75081
Office: (972) 390-8014
Cell: (405) 519-3824
chris.jackson@farmereg.com
www.farmereg.com

Austin • Denver • DFW • Houston • Florida

This email contains confidential & privileged material for the sole use of the intended recipient. Any reviews, use, distribution or disclosure by others is strictly prohibited. If you are not the intended recipient (or authorized to receive for the recipient), please contact the sender by reply email & delete all copies of this message.

TOWN OF CHEEKTOWAGA

Erie County, New York

Certificate of Occupancy - Change in Commercial Tenant

Date: 4/13/2023 9:08:14 AM

Owner: DiVita Family Partnership
60 Bryant Woods S
Amherst, NY 14228

RE: SBL Number: 102.03-2-29
24 Anderson Rd, Cheektowaga, NY 14225
PERMIT Number: 2023-0359
PERMIT TYPE: Com. Change in Tenant
TENANT:

This Certificate of Occupancy is issued in accordance with the requirements of Title 19 NYCRR, Chapter XXXII, Part 1203, and is relevant to the location contained in approved Permit Number 2023-0359 issued on April 13, 2023.

The work performed at 24 Anderson Rd, under this permit complies with the relevant provisions of the NYS Uniform Fire Prevention and Building Code and the Local Law of the TOWN OF CHEEKTOWAGA, NY, based on documents submitted and relevant inspections performed.

Construction Type: V-B

Occupancy Class: S-1

Occupant Load: 98

Fire Alarm Present: No

Automatic sprinkler system is provided: Yes and is required: Yes

Conditions: None unless noted below

Richard Coburn
Supervising Code Enforcement Officer

4-13-2023
Date

Building and Plumbing Department
275 Alexander Avenue
Cheektowaga, New York 14211
(716) 686-3470

TOWN OF CHEEKTOWAGA

FIRE SAFETY OFFICE
275 ALEXANDER AVENUE
CHEEKTOWAGA, NY 14211
(716) 686-3470

COMMERCIAL OPERATING PERMIT

PERMIT #: 2023-0362

PERMIT ISSUED: 04/13/2023
EXPIRATION DATE: 04/13/2026

Green Mountain Electric Supply

24 Anderson

802-391-4926

THE ABOVE NAMED INDIVIDUAL/BUSINESS IS HEREBY GRANTED A PERMIT TO CONDUCT THE FOLLOWING BUSINESS AT THE ABOVE LOCATION:

Storage

IN ACCORDANCE WITH SECTION 70-27 (PERMITS) AND SECTION(s) 70-29 (REQUIRED FIRE CODES PERMITS) OF THE FIRE PREVENTION CODE OF THIS JURISDICTION.

APPROVED BY FIRE INSPECTOR

Joseph Ehnes

DATE
04/13/2023

FIRE DISTRICT
Rescue Fire District

THIS PERMIT MUST BE POSTED ON THE ABOVE MENTIONED PREMISES

APPENDIX E

Historical Resources

Commercial Property
24 Anderson Road
Buffalo, NY 14225

Inquiry Number: 8127688.7
October 07, 2025

EDR Environmental Lien and AUL Search

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search

The EDR Environmental Lien Search Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations (AULs), such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel number and/or legal description
- search for ownership information
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.
- search for publicly available environmental encumbering instrument(s) filed on or after the recording of the current deed; between the recording of the current deed and the most current publicly available date
- provide a copy of any environmental encumbrance(s)
- provide a copy of the current deed when available

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2024 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search

TARGET PROPERTY INFORMATION

ADDRESS

24 Anderson Road
Commercial Property
Buffalo, NY 14225

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

AULs: Found ☐ Not Found ☒

RESEARCH SOURCE

Source 1:

Erie Recorder
Erie, NY

PROPERTY INFORMATION

Deed 1:

Type of Deed:	Bargain & Sale Deed
Title is vested in:	Recovery Real Estate Holdings LLC
Title received from:	DiVita Family Partnership LP
Deed Dated	5/1/2023
Deed Recorded:	5/2/2023
Book:	11416
Page:	6822
Volume:	NA
Instrument:	2023074546
Docket:	NA
Land Record Comments:	see exhibit
Miscellaneous Comments:	NA
Legal Description:	see exhibit
Legal Current Owner:	Recovery Real Estate Holdings LLC
Parcel # / Property Identifier:	14225-102.03-2-29
Comments:	see exhibit

Deed Exhibit 1

ERIE COUNTY CLERK'S OFFICE

County Clerk's Recording Page

Return to:

Party 1:
DIVITA FAMILY PARTNERSHIP LP

Party 2:
RECOVERY REAL ESTATE HOLDINGS LLC

Book Type: D Book: 11416 Page: 6822
Page Count: 4
Doc Type: DEED
Rec Date: 05/02/2023
Rec Time: 03:17:42 PM
Control #: 2023074546
UserID: ERECORD
Trans #: 23059616
Document Sequence Number
TT2022017906

Recording Fees:

RECORDING	$40.00
COE CO $1 RET	$1.00
COE STATE $14.25 GEN	$14.25
COE STATE $4.75 RM	$4.75
RP5217 CNTY $9	$9.00
RP5217 ST-NON RES $241	$241.00
TP584	$10.00

Consideration Amount: 1300000.00

BASIC MT	$0.00
SONYMA MT	$0.00
ADDL MT/NFTA	$0.00
SP MT/M-RAIL	$0.00
NY STATE TT	$5,200.00
ROAD FUND TT	$6,500.00

Total: $12,020.00

STATE OF NEW YORK
ERIE COUNTY CLERK'S OFFICE

WARNING – THIS SHEET CONSTITUTES THE CLERK'S ENDORSEMENT REQUIRED BY SECTION 319&316-a (5) OF THE REAL PROPERTY LAW OF THE STATE OF NEW YORK. DO NOT DETACH. THIS IS NOT A BILL.

Michael P. Kearns
Erie County Clerk

BARGAIN AND SALE DEED
WITH COVENANTS AGAINST GRANTOR'S ACTS

THIS INDENTURE, made as of the 15th day of May, 2023.

BETWEEN DiVita Family Partnership, L.P., a New York limited partnership, with an address of 10550 Keller Road, Clarence, New York 14031, party of first part

and

Recovery Real Estate Holdings LLC, a Delaware limited liability company with an address of 356 Rathe Road, Colchester, Vermont 05446, party of second part

WITNESSETH, that the party of the first part, in consideration of One and No More Dollars ($1.00 & No More) and other valuable consideration paid by the party of the second part, does hereby grant and release unto the party of the second part, the heirs or successors and assigns of the party of the second part forever,

ALL THAT TRACT OR PARCEL OF LAND, as described on the attached Schedule "A".

TOGETHER with all right, title and interest, if any, of the party of the first part in and to any streets and roads abutting the above described premises to the center lines thereof;

TOGETHER with the appurtenances and all the estate and rights of the party of the first part in and to said premises;

TO HAVE AND TO HOLD the premises herein granted unto the party of the second part, the heirs or successors and assigns of the party of the second part forever.

AND the party of the first part covenants that the party of the first part has not done or suffered anything whereby the said premises have been encumbered in any way whatever, except as aforesaid.

AND the party of the first part, in compliance with Section 13 of the Lien Law, covenants that the party of the first part will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvement and will apply the same first to the payment of the cost of the improvement before using any part of the total of the same for any other purpose. The word "party" shall be construed as if it read "parties" whenever the sense of this indenture so requires. This is not a conveyance of all or substantially all of the assets of the Grantor.

IN WITNESS WHEREOF, the party of the first part has set their hand and seal the day and year first written above.

DiVita Family Partnership, L.P.

By: _____
Richard DiVita, General Partner

STATE OF Florida)
COUNTY OF Sarasota) **SS:**

On the 8 day of March in the year 2023, before me, the undersigned, a notary public in and for said state, personally appeared Richard DiVita, personally known to me or proved to me on the basis of satisfactory evidence to be the individual whose name is subscribed to the within instrument and acknowledged to me that he executed the same in his capacity, and that by his signature on the instrument, the individual or the person upon behalf of which the individual acted, executed the instrument.

_____
Notary Public

NOTARY PUBLIC STATE OF FLORIDA

Mark Dymarkowski
Comm.: HH 150660
My Commission Expires:
July 8, 2025

Schedule A

All that tract or parcel of land situate in the Town of Cheektowaga, County Of Erie and State of New York, being part of Lot No. 24, Township 11, Range 7 of the Holland Land Company's Survey, described as follows:

Commencing at a point in a line drawn parallel with the westerly boundary line of lands conveyed by General American Transportation Corporation, formerly General American Tank Car Corporation to Walden Properties Inc. by deed dated August 28, 1946 and recorded in Erie County Clerk's Office in liber 3980 of Deeds page 480 on September 17, 1946 which line runs northerly along the center of a private roadway 100 feet wide, the vehicular portion of which is 30 feet wide from a point in the center line of Walden Avenue distant 365 feet southeasterly measured along said center line of Walden Avenue from the point of intersection of the said center line of Walden Avenue with the westerly boundary line of the lands conveyed by the aforesaid deed to Walden Properties Inc. which point of commencement is distant 372.5 feet northerly from the center line of Walden Avenue (said point of beginning being the southeast corner of lands conveyed by the Walden Properties Inc. to Screen Equipment Co. Inc. by deed dated October 1, 1948 and recorded in said Clerk's Office in liber 4407 of Deeds page 546 on October 1, 1948): running thence westerly at right angles with the said center line of said private roadway and along the southerly line of lands conveyed to the said Screen Equipment Co. Inc. as described in said deed for a distance of 345.6 feet to the west line of lands conveyed to Walden Properties Inc. by deed aforesaid: running thence southerly along the west line of lands conveyed to Walden Properties Inc. by deed aforesaid, 129 feet to a point: thence easterly at right angles for the distance of 106.20 feet: thence southerly at right angles for a distance of 23 feet: thence easterly at right angles for the distance of 239.4 feet to the center line of said private roadway 100 feet wide: thence northerly along the said center line of said private roadway 152 feet to the point or place of beginning.

Excepting and excluding therefrom that portion of the above premises conveyed to the Town of Cheektowaga by deed recorded in Erie County Clerk's Office in liber 6222 of Deeds page 679.

Commercial Property

24 Anderson Road

Buffalo, NY 14225

Inquiry Number: 8127688.11

October 01, 2025

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

10/01/25

Site Name:

Commercial Property
24 Anderson Road
Buffalo, NY 14225
EDR Inquiry # 8127688.11

Client Name:

Farmer Environmental Group
309 North Galloway
Mesquite, TX 75149
Contact: Roy David King

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2022	1"=500'	Flight Year: 2022	USDA/NAIP
2019	1"=500'	Flight Year: 2019	USDA/NAIP
2015	1"=500'	Flight Year: 2015	USDA/NAIP
2011	1"=500'	Flight Year: 2011	USDA/NAIP
2008	1"=500'	Flight Year: 2008	USDA/NAIP
1995	1"=500'	Acquisition Date: March 28, 1995	USGS/DOQQ
1985	1"=500'	Flight Date: April 27, 1985	USDA
1983	1"=500'	Flight Date: March 17, 1983	USDA
1978	1"=500'	Flight Date: October 21, 1978	USDA
1974	1"=500'	Flight Date: April 17, 1974	USGS
1966	1"=500'	Flight Date: June 12, 1966	USDA
1958	1"=500'	Flight Date: October 06, 1958	USDA
1951	1"=500'	Flight Date: October 13, 1951	USDA
1938	1"=500'	Flight Date: September 06, 1938	USDA

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 2022
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 2019
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 2015
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 2011
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 2008
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1995
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1985
= 500'
N
EDR




INQUIRY #: 8127688.11

YEAR: 1983

= 500'

N

EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1978
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1974
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1966
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1958
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1951
= 500'
N
EDR


Subject Property
(Approximate)
INQUIRY #: 8127688.11
YEAR: 1938
= 500'
N
EDR

Commercial Property

24 Anderson Road

Buffalo, NY 14225

Inquiry Number: 8127688.3

October 02, 2025

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

10/02/25

Site Name:

Commercial Property
24 Anderson Road
Buffalo, NY 14225
EDR Inquiry # 8127688.3

Client Name:

Farmer Environmental Group
309 North Galloway
Mesquite, TX 75149
Contact: Roy David King

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Farmer Environmental Group were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 56BB-4BA3-B518

PO # 235.974

Project 235.985

Maps Provided:

1949
1939

Sanborn® Library search results

Certification #: 56BB-4BA3-B518

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Farmer Environmental Group (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1949 Source Sheets




Volume 1, Sheet 32
1949

1939 Source Sheets



Volume 1, Sheet 32
1939



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #56BB-4BA3-B518


Site Name:	Commercial Property
Address:	24 Anderson Road
City, ST, ZIP:	Buffalo, NY 14225
Client:	Farmer Environmental Group
EDR Inquiry:	8127688.3
Order Date:	10/02/2025
Certification #:	56BB-4BA3-B518
Copyright	1949

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600

Volume 1, Sheet 32





N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #56BB-4BA3-B518


Site Name: Commercial Property
Address: 24 Anderson Road
City, ST, ZIP: Buffalo, NY 14225
Client: Farmer Environmental Group
EDR Inquiry: 8127688.3
Order Date: 10/02/2025
Certification #: 56BB-4BA3-B518
Copyright: 1939

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600

Volume 1, Sheet 32





N

Commercial Property
24 Anderson Road
Buffalo, NY 14225

Inquiry Number: 8127688.4
October 02, 2025

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

10/02/25

Site Name:

Commercial Property
24 Anderson Road
Buffalo, NY 14225
EDR Inquiry # 8127688.4

Client Name:

Farmer Environmental Group
309 North Galloway
Mesquite, TX 75149
Contact: Roy David King

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Farmer Environmental Group were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 235.974
Project: 235.985

Coordinates:

Latitude:	42.905232 42° 54' 19" North
Longitude:	-78.772249 -78° 46' 20" West
UTM Zone:	Zone 17 North
UTM X Meters:	681862.55
UTM Y Meters:	4752698.65
Elevation:	656.00' above sea level

Maps Provided:

2019
2016
2013
1965
1950
1948
1946
1901, 1905
1894

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.


Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2019 Source Sheets



Buffalo NE
2019
7.5-minute, 24000



Lancaster
2019
7.5-minute, 24000

2016 Source Sheets



Buffalo NE
2016
7.5-minute, 24000



Lancaster
2016
7.5-minute, 24000

2013 Source Sheets



Buffalo NE
2013
7.5-minute, 24000




Lancaster
2013
7.5-minute, 24000

1965 Source Sheets



Buffalo NE
1965
7.5-minute, 24000
Aerial Photo Revised 1942



Lancaster
1965
7.5-minute, 24000
Aerial Photo Revised 1942

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1950 Source Sheets



Buffalo NE
1950
7.5-minute, 24000
Aerial Photo Revised 1942



Lancaster
1950
7.5-minute, 24000
Aerial Photo Revised 1942




BUFFALO VICINITY 1 OF 2
1950
7.5-minute, 24000

1948 Source Sheets



Buffalo NE
1948
7.5-minute, 24000
Aerial Photo Revised 1942

1946 Source Sheets




BUFFALO NE
1946
7.5-minute, 25000

1901, 1905 Source Sheets



Buffalo
1901
15-minute, 62500



Depew
1905
15-minute, 62500

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.


1894 Source Sheets



Buffalo
1894
15-minute, 62500

Historical Topo Map

2019



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo NE, 2019, 7.5-minute
NE, Lancaster, 2019, 7.5-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Buffalo NE, 2016, 7.5-minute
NE, Lancaster, 2016, 7.5-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N

Historical Topo Map

2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Buffalo NE, 2013, 7.5-minute
NE, Lancaster, 2013, 7.5-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N

Historical Topo Map

1965



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Buffalo NE, 1965, 7.5-minute
NE, Lancaster, 1965, 7.5-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N

Historical Topo Map

1950



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo NE, 1950, 7.5-minute
NE, Lancaster, 1950, 7.5-minute
TP, BUFFALO VICINITY 1 OF 2, 1950, 7.5-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Buffalo NE, 1948, 7.5-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N

Historical Topo Map

1946



UNMAPPED

This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, BUFFALO NE, 1946, 7.5-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo, 1901, 15-minute
E, Depew, 1905, 15-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Buffalo, 1894, 15-minute

SITE NAME: Commercial Property
ADDRESS: 24 Anderson Road
Buffalo, NY 14225
CLIENT: Farmer Environmental Group

N

Commercial Property
24 Anderson Road
Buffalo, NY 14225

Inquiry Number: 8127688.5
October 06, 2025

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available business directory data at approximately five year intervals.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	*Target Street*	*Cross Street*	*Source*
2022	☑	☑	EDR Digital Archive
2017	☑	☑	Cole Information
2014	☑	☑	Cole Information
2010	☑	☑	Cole Information
2005	☑	☑	Cole Information
2000	☑	☑	Cole Information
1995	☑	☑	Cole Information
1991	☑	☑	Haines Criss-Cross Directory
1985	☑	☑	Haines Criss-Cross Directory
1981	☑	☑	Haines Criss-Cross Directory
1976	☑	☑	Haines Criss-Cross Directory
1970	☑	☑	Haines Criss-Cross Directory
1968	☑	☑	Haines Criss-Cross Directory
1963	☑	☑	Polk's City Directory
1959	☐	☐	Polk's City Directory
1956	☐	☐	Polk's City Directory
1951	☐	☐	Polk's City Directory
1946	☐	☐	Polk's City Directory
1942	☐	☐	Polk's City Directory
1938	☐	☐	Polk's City Directory

EXECUTIVE SUMMARY

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	***Target Street***	***Cross Street***	***Source***

FINDINGS

TARGET PROPERTY STREET

24 Anderson Road
Buffalo, NY 14225

Year	*CD Image*	*Source*	
ANDERSON RD			
2022	pg A2	EDR Digital Archive	
2017	pg A5	Cole Information	
2014	pg A7	Cole Information	
2010	pg A9	Cole Information	
2005	pg A11	Cole Information	
2000	pg A13	Cole Information	
1995	pg A15	Cole Information	
1991	pg A17	Haines Criss-Cross Directory	
1985	pg A19	Haines Criss-Cross Directory	
1981	pg A22	Haines Criss-Cross Directory	
1976	pg A24	Haines Criss-Cross Directory	
1970	pg A26	Haines Criss-Cross Directory	
1968	pg A28	Haines Criss-Cross Directory	
1963	pg A30	Polk's City Directory	
1959	-	Polk's City Directory	Street not listed in Source
1956	-	Polk's City Directory	Street not listed in Source
1951	-	Polk's City Directory	Street not listed in Source
1946	-	Polk's City Directory	Street not listed in Source
1942	-	Polk's City Directory	Street not listed in Source
1938	-	Polk's City Directory	Street not listed in Source

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*	
DALE RD			
2022	pg. A4	EDR Digital Archive	
2017	pg. A6	Cole Information	
2014	pg. A8	Cole Information	
2010	pg. A10	Cole Information	
2005	pg. A12	Cole Information	
2000	pg. A14	Cole Information	
1995	pg. A16	Cole Information	
1991	pg. A18	Haines Criss-Cross Directory	
1985	pg. A20	Haines Criss-Cross Directory	
1985	pg. A21	Haines Criss-Cross Directory	
1981	pg. A23	Haines Criss-Cross Directory	
1976	pg. A25	Haines Criss-Cross Directory	
1970	pg. A27	Haines Criss-Cross Directory	
1968	pg. A29	Haines Criss-Cross Directory	
1963	pg. A31	Polk's City Directory	
1963	pg. A32	Polk's City Directory	
1959	-	Polk's City Directory	Street not listed in Source
1956	-	Polk's City Directory	Street not listed in Source
1951	-	Polk's City Directory	Street not listed in Source
1946	-	Polk's City Directory	Street not listed in Source
1942	-	Polk's City Directory	Street not listed in Source
1938	-	Polk's City Directory	Street not listed in Source

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ANDERSON RD 2022

24	DAVIS ELECTRICAL SUPPLY CO INC
	DAVIS ELECTRICAL SUPPLY COMPANY INC
	EAN WHALEN
	KORFF ELECTRIC INC
	RICH HICKMAN
	RICHARD A DIVITA
25	ANNA DARATA
	BRENDA MELLIGAN
	CHUCK GROFF
	DAVE FARENHOLTZ
	DAVID WILLCOX
	DUDNEY JOSEPH
	FRANK ZGRABLICH
	HEATHER PETERSEN
	MARIANNE MALCZEWSKI
	MARK SERLING
	MIKE MESSURO
	ROXANNE FLAHERTY
	SCOTT MORGANTE
	STATE FARM A
	STATE FARM INSURANCE COS
	STEVE MRZYGUT
	STEVE PINGREE
	UPSTATE FARMS
	UPSTATE FARMS CHEESE, LLC
	UPSTATE FARMS COOP, INC
	UPSTATE NIAGARA
	UPSTATE NIAGARA CO-OP INC
	UPSTATE NIAGARA COOP
	UPSTATE NIAGARA COOP INC
	UPSTATE NIAGARA COOPERATIVE
	UPSTATE NIAGARA COOPERATIVE INC
	UPSTATE NIAGARA COOPERATIVE, INC
	UPSTATE NIAGARA COOPERTIVE INC
	UPSTATENIAGARACOOPERATIVE2CINC
	URS CORPORATION
40	DIMAR MANUFACTURING
	STEVE POMIETLASZ
45	FIRST STUDENT
	LAIDLAW TRANSIT
	MARK KASHMANIAN
	RON BARTKOWIAK
47	JOHN DI FIORE
	KRIS SELVAGGI
	QUINCAILLERIE RICHELIEU LTEE RICHELIEU HARDWARE LTD
	RICHELIEU BUFFALO
	THRUWAY HARDWOOD & PLYWOOD CORPORATION
51	AARDEE & SONS INC
	ANILKUMAR DHOLAK
	ITHACA HOTELS LLC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ANDERSON RD 2022 (Cont'd)

51	JAYESH PATEL
	RAJESH PATEL
	ROSEWOOD HOTELS LLC
	RUDRA MANAGEMENT
74	MULLER TOOL INC
	PAUL BANKO
83	HOLIDAY INN EXPRESS
	KABIRS LLC
90	AMY HORNBERGER
	DONALD ROHAUER
	UPSTATE NIAGARA
	UPSTATE NIAGARA COOPERATIVE
107	CAMMERON SCOTT
	KATHY RAMOS
	MARRIOTT INTERNATIONAL
	RESIDENCE INN BUFFALO GALLERIA MALL

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

DALE RD 2022

1655	DELTA SONIC
1730	BECKS CREAMERY
	BOB HALL
	LARRY DARCH
	OLEG STEZHERINSKIY
	STATE FARM INSURANCE
	UPSTATE NIAGARA COOP
	UPSTATE NIAGARA COOP INC
1746	CHARLES HUSVAR
	DIVERSIFIED MFG INC
1747	GREGORY ZDZINSKI
	MARY GLEDHILL
	NIAGARA TRANSFORMER
	NIAGARA TRANSFORMER CORP
	NIAGARA TRANSFORMER CORPORATION
	ROBERT BLAKE
1755	FRANK DUCOLI
	NIAGARA TRANSFORMER CORPORATION
1800	CLARK
	UPSTATE STEEL
1810	BUFFALO CLUTCH CO INC
1835	PROLIFT INC
	SCOTT WEINHOLTZ
1845	COOK MOVING SYSTEMS INC
	DONNA THIELKE
	GREG FIERLE
	OJ GLENN MOVING & STORAGE INC
1850	BUFFALO SPRING IN
	STACY MINCER

Target Street	Cross Street	Source
✓	-	Cole Information

ANDERSON RD 2017

24	DAVIS ELECTRICAL SUPPLY COMPANY INC
25	ACTS TESTING LABS INC
	STATE FARM INSURANCE
45	FIRST STUDENT
47	THRUWAY HARDWOOD & PLYWOOD CORP
51	AARDEE & SONS INC
74	MULLER TOOL INC
83	HOLIDAY INN EXPRESS CHEEKTOWAGA NORT
	KABIRS LLC
	REIMANN & GEORGER CORP
90	EXPERT LOCKSMITH INC
107	RESIDENCE INN BUFFALO GALLERIA MALL

Target Street	Cross Street	Source
-	✓	Cole Information

DALE RD 2017

1655	DELTA SONIC CAR WASH SYSTEMS
1730	STATE FARM INSURANCE
1746	TNGLG LLC
1747	NIAGARA TRANSFORMER CORP
1800	UPSTATE STEEL INC
1810	BUFFALO CLUTCH CO INC
1835	PROLIFT INC
1845	COOK MOVING SYSTEMS INC
	GO MINIS
	IHRIG MOVING & STORAGE
	UNITED VAN LINES
1850	VALLEN SAFETY SUPPLY CO

Target Street	Cross Street	Source
✓	-	Cole Information

ANDERSON RD 2014

22	OSVATH, JOSEPH
24	DAVIS ELECTRICAL SUPPLY COMPANY INC
	DAVIS ELECTRICAL SUPPLY COMPANY INCO
25	STATE FARM INSURANCE
	UPSTATE FARMS COOPERATIVE
45	FIRST STUDENT
47	THRUWAY & PLYWOOD CORPORATION
	THRUWAY HARDWOOD & PLYWOOD CORP
51	AARDEE & SONS INC
74	MULLER TOOL INC
	MULLER TOOL INCORPORATED
83	KABIRS LLC
90	EXPERT LOCKSMITH INCORPORATED
	UPSTATE MILK CORP
107	RESIDENCE INN BUFFALO CHEEKTOWAGA

Target Street	Cross Street	Source
-	✓	Cole Information

DALE RD 2014

1492	OCCUPANT UNKNOWN,
1730	BECKS CREAMERY DIVISION OF UPSTATE M
	SEALTEST MILK PRODUCTS
	STATE FARM INSURANCE
1747	NIAGARA TRANSFORMER CORPORATION
1800	UPSTATE STEEL
	UPSTATE STEEL INCORPORATED
1810	BUFFALO CLUTCH COMPANY INCORPORATED
1835	PROLIFT INC
	PROLIFT INCORPORATED
1845	COOK MOVING SYSTEMS INC
	COOK MOVING SYSTEMS INCORPORATED
	IHRIG MOVING & STORAGE
	OJ GLENN MOVING & STORAGE INC
	UNITED VAN LINES
1850	BUFFALO SPRING
1860	UPSTATE REBAR LLC

Target Street	Cross Street	Source
✓	-	Cole Information

ANDERSON RD 2010

22	OSVATH, JOSEPH
24	DAVIS ELECTRICAL SUPPLY CO INC
25	UPSTATE NIAGARA COOP INC
40	FIVE STAR INDUSTRIES
45	FIRST STUDENT INC
74	MULLER TOOL INC
	U S MICROOPTICAL SOLUTIONS
83	REIMANN & GEORGER CORP
90	UPSTATE MILK CORP
	UPSTATE MILK EMPL FCU
	UPSTATE NIAGARA COOP INC
107	RESIDENCE INNCHEEKTOWAGA

Target Street	Cross Street	Source
-	✓	Cole Information

DALE RD 2010

1492	MERCURI, MICHAELENE R
1496	WALKER, ROBIN L
1800	UPSTATE STEEL INC
1810	BUFFALO CLUTCH CO INC
1845	COOK MOVING SYSTEMS INC
	IHRIG MOVING & STORAGE
	O J GLENN MOVING & STORAGE INC
1850	BUFFALO SPRING

Target Street	Cross Street	Source
✓	-	Cole Information

ANDERSON RD 2005

24	DAVIS ELECTRICAL SUPPLY CO
25	BISON FOODS CO
	KINOR DAIRY LLC
	UPSTATE FARMS
	UPSTATE FARMS COOPERATIVE INC
40	FIVE STAR INDUSTRIES INC
45	LAIDLAW EDUCATION SERVICES
47	THRUWAY HARDWOOD & PLYWOOD CORP
51	ONYX INDUSTRIAL SVCES INC
60	ADVISION INC
74	MULLER TOOL INC
90	UMEFCU
	UPSTATE MILK EMPL FED CREDIT UN
107	RESIDENCE INN
	THARALDSON PROPERTIES INC

Target Street	Cross Street	Source
-	✓	Cole Information

DALE RD 2005

1492	MERCURI, MICHEALENE
1496	WALKER, ROBIN L
1501	PETROCY JEWELERS
1746	ROTARY CO
1747	NIAGARA TRANSFORMER CORP
1800	UPSTATE STEEL INC
1835	ADVANCE PWR SWEEPERS SCRUBBERS
	PROLIFT INC
1845	GLENN O J MOVING AND STORAGE INC
	UNITED VAN LINES CORP
1850	BUFFALO SPRING & EQUIPMENT CO

Target Street	Cross Street	Source
✓	-	Cole Information

ANDERSON RD 2000

24	DAVIS DAVID F ATTORNEY DAVIS ELECTRICAL SUPPLY
25	ACTS TESTING LABS INCORPORATED
	OLIVERIO DANIEL C ATTORNEY
40	FIVE STAR INDUSTRIES
45	HEIST C H CORP
	HEIST C H CORPORATION ADMINISTRATIVE OFFICE
47	THRUWAY HARDWOOD & PLYWOOD CORPORATION
60	ADVISION
	PAYLESS SIGNS
74	MULLER TOOL INCORPORATED
83	REIMANN & GEORGER INCORPORATED WAREHOUSE
90	UPSTATE MILK CORPORATION
107	RYDER TRUCK RENTAL AND LEASING
	RYDER TRUCK RENTAL ONE WAY INCORPORATED

Target Street	Cross Street	Source
-	✓	Cole Information

DALE RD 2000

1500	PETROCY JEWELERS
1621	GOLBERT, ANN M
1730	BECKS CREAMERY DIVISON OF UPSTATE MILK CO OP INCORPORATED
	SEALTEST MILK PRODS
	UPSTATE MILK COMPANY OPERATIVES INCORPORATED
1746	ROTARY COMPANY INCORPORATED THE METL SPECLTS
1747	NIAGARA TRANSFORMER CORPORATION
1800	UPSTATE STEEL INCORPORATED
1810	BUFFALO CLUTCH COMPANY INCORPORATED
1835	ADVANCE POWER SWEEPERS & SC
	CLARKLIFT OF BUFFALO INCORPORATED
1845	COOK MOVING SYSTEMS INCORPORATED
	UNITED VAN LINES
	UNITED VAN LINES AGENT
1850	VALLEN SAFETY SUPPLY COMPANY

Target Street	Cross Street	Source
✓	-	Cole Information

ANDERSON RD 1995

24	DAVIS ELECTRICAL SUPPLY COMPANY INCORPORATED
25	ACTS TESTING LABS INC-CORPORATE OFCS & CONSUMER PRODUCT TEST
	OLIVERIO, DANIEL C, ATTY
37	DIVITA & TRACEY, CPAS
	TRACEY, THOMAS F, CPA
40	SECO-CORP
45	HEIST C H CORP-ADMINISTRATIVE OFC
60	ADVISION
74	MULLER TOOL INC
83	REIMANN & GEORGER INC, BOAT LIFTS & HOISTS-MARINE DIV
107	RYDER TRUCK RENTAL AND LEASING-ADMINISTRATIVE OFFICE
	RYDER TRUCK RENTAL AND LEASING-CUSTOMER SERVICE
	RYDER TRUCK RENTAL AND LEASING-RENTAL OFFICE
	RYDER TRUCK RENTAL-ONE-WAY INC-INFORMATION & RESERVATIONS


Target Street	Cross Street	Source
-	✓	Cole Information

DALE RD 1995

1730	BECK'S CREAMERY DIV OF UPSTATE MILK CO-OP INC
	SEALTEST MILK PRODS
	UPSTATE MILK CO-OPERATIVES INC
	UPSTATE MILK CO-OPERATIVES INC-CUSTOMER ORDER DEPT
1746	ROTARY CO INC THE, METL SPECLTS
1747	NIAGARA TRANSFORMER CORP
1800	UPSTATE STEEL INC
1810	BUFFALO CLUTCH CO INC
1835	ADVANCE AUTOMATIC FLOOR MACHINES
	ADVANCE POWER SWEEPERS & SCRUBBERS
	CLARK INDSTRL TRUCKS
	CLARKLIFT OF BUFFALO INCORPORATED
1845	COOK INTERNATIONAL MOVERS
	COOK INTERNATIONAL MOVERS INC
	COOK MOVING SYSTEMS INC
	UNITED VAN LINES AGENT
	UNITED VAN LINES-AGENT
1850	BUFFALO FIRE & SAFETY EQUIPT CO INC DIV OF FSG INDUSTRIES
	EMED GLOVE CO DIV OF FSG INDUSTRIES
	FSG INDUSTRIES

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

ANDERSON RD 1991



THE HAINES

ANDERSON RD 14225
CHEEKTOWAGA

X DALE RD

7	XXXX	00
24	*DAVIS ELCTL SPL INC	896-0100
25	*A C T S TESTNG LABS	897-3300 9
	*RYDER TRUCK RENTAL	893-5000 0
	*RYDER TRUCK RENTAL	893-5642 +1
37	*OIVITA RICHO A CPA	896-7100
	*OIVITA&CO PC CPA	896-7100
40	*SECO CORP	893-0455
43	XXXX	00
45	*CHILD&FAMILY SVCES	896-7485
47	XXXX	00
51	*GERARD MFG CO INC	894-1100 +1
57	XXXX	00
60	*AOVISION INC	854-2400 9
74	*CREATIVE PLASTICS	895-3971 9
	*MULLER TOOL INC	895-3658
83	*REIMANN&GEORGER INC	892-0224 9
107	*RYDER TRUCK RENTAL	894-7100 8
	*SYSCO FROSTED FOODS	894-8901 +1
130	XXXX	00


X WALDEN AV

NO S	*HEIST C H CORP ADMN	894-3035
	* 16 BUS 5 RES	3 NEW

ANDOVER AV 14215
BUFFALO

Target Street	Cross Street	Source
-	✓	Haines Criss-Cross Directory

DALE RD 1991



BUFFALO T

DALE RD 14225
CHEEKTOWAGA

	X WALDEN AV		
1492	XXXX	00	
1496	XXXX	00	
1500	BLOCHBERGER Terry	893-5310	+1
1572	XXXX	00	
1600	BROWAREK B	894-4514	0
	BROWAREK Henry Mrs	894-6697	
	*LITTLE ACRES TAVERN	B96-5433	4
1621	*BUDZYNSKI ANTHONY	894-2430	6
	FRELOCK Michael R	893-7988	+1
1625	XXXX	00	
1703	XXXX	00	
1711	MICHALSKI B Jr	893-7497	9
1712	XXXX	00	
1790	*BECKS CREAMERY DIV	892-2121	9
	*SEALTEST MILK PROOS	892-2121	
	*UPSTATE MILK COOPS	892-3434	5
	*UPSTATE MILK COOPS	892-2121	6
1732	XXXX	00	
1746	*ROTARY CO INC THE	894-4425	
1747	*NIAGRA TRANSFORMER	B96-6500	2
1765	XXXX	00	
1800	*WEAVER METAL&ROOFN	891-8844	
1810	*BUFLO CLUTCH CO INC	892-2828	2
1820	XXXX	00	
1835	*ADVANCE ATMTC MACH	895-8600	
	*ADVANCE POWER SWPRS	895-8600	
	*CLARK INDSTRL TRCKS	895-8600	
	*CLARKLIFT BUFLO INC	895-8600	
1845	*AUTO TRANS EXPRESS	897-0700	3
	*COOK INTL MOVERS	897-0700	
	*COOK MOVING SYSTEMS	897-0700	
	*UNITO VAN LINES	897-0700	2
1850	*BUFLO FIRE&SFTY EOP	897-4014	2
	*EMEO GLOVE CO DIV	897-4014	5
	*F S G INDUSTRIES	B97-4014	5
	*STEINWACHS SFTY SPL	897-4014	5

* 22 BUS 14 RES 2 NEW

DALE RD 14127
ORCHARD PARK

1	MAXWELL R Steven	662-1835	+1
3	STORM John F	662-5358	

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

ANDERSON RD 1985

37	HANSEN EDWIN C	649-5274
38	VIRTUE JAS R	649-5174
*	0 BUS 12 RES	3 NEW

ANDERSON RD 14225 CHEEKTOWAGA


7	XXXX	00	
24	DAVIS ELECTL SUPL	896-01DD	8
25	AIR NIAGARA INC	894-2355	+5
	ANDCO INC	896-8181	
	ANDERSON A E JR	896-8181	
	ANDERSON A E 3D	896-8181	
	SUMMA GRAPHICS INC	895-D220	4
40	S E C O DIV	893-0455	
43	DELAVAN INDUSTRIES	895-6560	+5
45	CHILD&FAMILY SVCES	896-7485	1
47	XXXX	00	
51	BANCK E H CONSTR CO	897-533D	+5
57	XXXX	00	
60	UNDERWRITERS SLVG	897-2675	+5
74	MULLER TOOL INC	895-3658	6
83	VONDUNGEN E BUFLO	892-0159	
107	RYDER TRUCK RENTAL	688-4388	+5
	RYDER TRUCK RENTAL	694-4229	+5
	RYDER TRUCK RENTAL	694-1896	+5
	RYDER TRUCK RENTAL	631-5129	+5
	RYDER TRUCK RENTAL	884-1117	+5
	RYDER TRUCK RENTAL	891-7411	+5
130	D D S TRUCKING	893-4822	4
	WORLD AUTO PAINTING	892-7222	7
NO #	HEIST C H CORP ADMN	894-3035	
*	20 BUS 5 RES	10 NEW	

ANDOVER AV 14215 BUFFALO

EAST FROM
417 OLYMPIC AV

Target Street	Cross Street	Source
-	✓	Haines Criss-Cross Directory

DALE RD 1985



* 0 BUS 110 RES 10 NEW

DALE RD 14225
CHEEKTOWAGA

1492	XXXX	00	
1496	DEPCZYNSKI JAMES P	996-2760	3
1572	XXXX	00	
1600	BROWAREK HENRY MRS	894-6697	
	CZERWONKA JOS A	893-0392	
	LITTLE ACRES TAVERN	896-5433	4
1621	BUDZYNSKI ANTNONY	892-3423	
	MAGUDA LAWRENCE A	897-4854	4
	STADALBRTS CMTRY	892-3423	0
1625	XXXX	00	
1703	UPSTATE MILK CO	895-8992	6
1711	RUSSELL S	891-5910	3
1712	BUFLO OLTY BURL VLT	892-2310	4
	WILBERT VAULT WNY	894-6900	3
1730	SEALTEST DAIRY PROD	892-2121	9
	UPSTATE MILK CO	892-3434	+5
1732	XXXX	00	
1746	ROTARY CO INC THE	894-4425	
1747	NIAGRA TRANSFORMER	896-6500	2
1765	XXXX	00	
1800	WEAVER METAL&ROOFN	891-8844	8
1810	BUFLO CLUTCN CO INC	892-2828	2
1820	PATRIOT TRUCKING	894-0893	+5
	PRODUCTV TRNSPRT SV	896-5880	4

MAY NOT BE KEYPUNCHED, ENTERED INTO A COMPUT

Target Street	Cross Street	Source
-	✓	Haines Criss-Cross Directory

DALE RD 1985

DIRECTORY

DALE RD

1835	ADVANCE ATMTC MACH	895-8600	2
	CLARK INDSTRL TRCKS	895-8600	
	CLARKLIFT BUFLO INC	895-8600	2
1945	AUTO TRANS EXPRESS	897-0700	3
	COOK INTL MOVEPS	897-0700	
	COOK MOVING SYSTEMS	887-0700	
	UNITD VAN LNS AGENT	887-0700	2
1850	BUFLO FIRE&SFTY EQP	897-4014	2
	EMED GLOVE CO DIV	897-4014	+5
	F S G INDUSTRIES	897-4014	+5
	STEINWACH SFTY SPL	897-4014	+5
	YEN INDSTRL PRODS	894-0034	+5

* 26 BUS 10 RES 6 NEW

DALE RD 14127
ORCHARD PARK

1	TRACY JACK M	662-3554	
3	STORM JOHN F	662-5358	
5	BUTLER JOHN P	662-5080	7
7	MURPHY CHARLES E	662-7508	7

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

ANDERSON RD 1981

* 0 BUS 11 RES 0 NEW

ANDERSON RD 14225
CHEEKTOWAGA

7	C S M ENTRPRS LTD	893-1990	+1
24	DAVIS ELECTL SUPL C	896-0100	8
	DAVIS PAUL P	896-0100	8
	DAVIS RONALD B	896-0100	8
24½	DAVIS NEAL	892-6236	8
25	ANDCO INC	896-8181	8
	ANDCO INC ANDERSON	896-8181	+1
	ANOCO INC ANDPECO	896-8181	+1
	ANDERSON A E JR	896-8181	8
	ANDERSON A E 3D	896-8181	8
	ANDRECO REFCTRY SVC	896-1224	0
40	SCREEN EQUIPT	893-0455	
45	CHILD&FAMILY SVCES	896-7485	+1
47	MOODY OLSTAD INC	894-2773	+1
51	XXXX	00	
57	XXXX	00	
60	UNDERWRITERS SLVG	893-2370	
74	MULLER TOOL INC	895-3658	6
83	VONOUNCEN EMIL INC	892-0159	3
107	ALL STATES TRCKING	891-8181	9
	OOYLE TRANSPORT AGC	891-8181	0
	ELTO TRUCK REPR INC	892-7100	9
	GATEWAY TRANSPRTN	891-8181	9
	JONES MOTOR LNCR DI	891-8181	9
	MURPHY E L	891-8181	9
130	WORLD AUTO PAINTING	892-7222	7
NO #	HEIST C H ADMN OFC	894-3035	3

* 24 BUS 3 RES 5 NEW

ANDOVER AV 14215
BUFFALO

X OLYMPIC AVE

Target Street	Cross Street	Source
-	✓	Haines Criss-Cross Directory

DALE RD 1981

199	NEWTON DAVID	695-1626	+1
*	0 BUS 111 RES	10 NEW	

DALE RD 14225
CHEEKTOWAGA

1492	XXXX	00	
1496	XXXX	00	
1572	FULLAGAR MICHAEL	894-2545	0
1600	BROWAREK HENRY MRS	894-6697	3
	CZERWONKA JOS A	893-0392	
	LITTLE ACRES RSTRNT	896-9290	4
1621	BUDZYNSKI ANTHONY	892-3423	
	STADALBERTS CEMETRY	892-3423	0
1625	XXXX	00	
1703	UPSTATE MILK CPRTVE	895-8992	6
1711	BASINSKI ARTHUR	891-5910	0
1712	OCONNELL PRECAST	894-6900	8
1730	SEALTEST DAIRY PROD	892-2121	8
	UPSTATE MILK COOP	892-2121	0
1732	XXXX	00	
1746	ROTARY CO INC THE	894-4425	
1747	NIACARA TRANSFORMER	896-6500	+1
1765	XXXX	00	
1800	WEAVER METAL&ROOFN	891-8844	8
1810	XXXX	00	
1820	AT HOME AUTO TNE UP	896-3011	+1
1835	CLARKLIFT BUFFALO	895-8600	+1
1845	COOK INTERNATNL MVR	897-0700	9
	COOK MOVING SYSTEMS	897-0700	5
	UNITD VAN LINES	897-0700	
1850	BUFFALO FIRE&SAFETY	897-4014	0
*	15 BUS 11 RES	3 NEW	

DALE RD 14127
ORCHARD PARK

1	TRACY JACK M	662-3554	
3	STORM JOHN E	662-5358	2

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

ANDERSON RD 1976

```
36 VIRTUE JAS R                    649-5174
   *    D BUS    11 RES     D NEW

ANDERSON RD  14225  CHEEKTOWAGA

20*I C S SYSTEMS INC          891-5444  5
24*8ISON ELECTRICAL CO8       892-5055  5
  *8UFF IMPRINTS INC          897-4821+6
  *COURNAN PETER P            897-4821+6
  *SHEFF RONALD R             897-4821+6
25  XXXX                      00
40*SCREEN EQUIPT CO           893-0455
51*ANDCO INC                  896-8181  2
  *ANOERSON A E JR            896-8181
  *ANDERSON A E 3D            896-8181  2
6D*UNDERWRITERS SLVG          893-237D  9
74*MULLER TOOL INC            895-3658+6
83*VONOUNGEN EMIL 8FLO892-D159  3
1D7*8AKER ROOS CO             892-7100
  *PATENT SCAFFOLOING         892-7100
  *WELCH J H CO               892-7100
13D*8UOGET GAS INC            893-3754+6
  *SERV O THERM INC           896-3787  5
NO #*HEIST C H CORP           894-3035  3
   *   18 8US     1 RES      5 NEW

ANDOVER AV  14215  BUFFALO

   X     OLYMPIC AVE
11 8LOCK HENRY                834-3935
```

Target Street	Cross Street	Source
-	✓	Haines Criss-Cross Directory

DALE RD 1976

```
191  XXXX                    00
199 ESPOSITO ANTHONY         692-5538
    *   0 BUS  114 RES   20 NEW



DALE RD  14225  CHEEKTOWAGA


1492  XXXX                   00
1496 BOCKNER STEPHEN JR      896-5751 3
1500 BAEHRE DANIEL R         892-9251 3
1572  XXXX                   00
1600 BROWAREK HENRY MRS      894-6697 3
     CZERWONKA JOS A         893-0392
    *LITTLE ACRES RSTRNT     896-9290 4
1621 BUDZYNSKI ANTHONY       893-5815
    *BUDZYNSKI ANTHONY       892-3423
    *ST ADALBERTS CMTRY      892-3423 5
1625 BUDZYNSKI L SR          892-2582
1703*UPSTATE MILK CO GAR     895-8992+6
1711 SHOWALTER GERALD A      897-1207 3
1712*HERALD VAULT MFG         894-6900
    *WILBERT BURIAL VALT     894-6900
1730*ALL STAR DAIRY           892-2121 9
    *SEALTEST DAIRY PROD     892-3600 2
    *UPSTATE MILK CPRTVE     892-2121 5
1732  XXXX                   00
1746*ROTARY CO INC THE        894-4425
1747*NGRA TRANSFRMR CORP      896-6500 4
1800*KISTNER CONCRT PROD      894-2267
1810*CASE FOOD SVCES INC     895-5063 4
    *THREE COIN VNDG INC     895-2392 2
1845*COOK MOVING SYSTEMS     897-0700 5
    *UNITED VAN LNS AGNT     897-0700 9
1850*R&F MOLD CO INC          896-6550
    *THRUWAY MOLDERS INC     896-6550
    *  18 BUS   10 RES    1 NEW
```

mputer or photocopied, in ony monner whatsoever exce

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

ANDERSON RD 1970



38 VIRTUE JAS R 649-5174
* 0 BUS 12 RES 2 NEW

ANDERSON RD 14225 CHEEKTOWAGA


24*KOLK MFG CO INC 895-6100
25*MACANDER CORP 896-7868 9
40*SCREEN EQUIPT CO 893-0455
51*ANDERSON A E JR 896-8181
*ANOFRSON CONSTR WRH 896-8181
*ANOERSON LEONARD A 896-8181
*FORNES E J 896-8181
60*UNOERWRITERS SLVG 893-2370 9
74*MUILLER TOOL&DIE 895-3658
83*VON DUNGEN EMIL BUF 892-0159
107*BAKER ROOS CO 892-7100
*PATENT SCAFFOLDING 892-7100
*WFLCH J H CO 892-7100
NO **HEIST C H OHIO CORP 894-3035
* 14 BUS 0 RES 0 NEW

ANDOVER AV 14215 BUFFALO

X OLYMPIC AVE
11 BLOCK HENRY 834-3935
14 SCHILLO LAURA 835-4804

Target Street	Cross Street	Source
-	✓	Haines Criss-Cross Directory

DALE RD 1970



```
    =    0 BUS    BB RES    25 NEW

DALE RD  14225  CHEEKTOWAGA


1492 EICH WM D                 896-3047
1500 GOSPODARSKI A             895-2298
     STELTER ROBERT J          895-3894 9
1572 TROJANOSKI J M            893-4757
1600 CZERWONKA JOS A           893-0392
     EVANS RAYMOND C           896-6056 R
    *LITTLE ACRES RESTNT       896-9290
1621=BUDZYNSKI ANTHONY         892-3423
     BUDZYNSKI ANTHONY         893-5815
    *ST ADALBERTS CEMTRY       892-3423
1625 BUDZYNSKI L SR            892-2582
1711 CROTTY THOMAS             893-2945 9
1712*HERALD VAULT MFG          894-6900
    *WILBERT BURIAL VALT       894-6900
1730*ALL STAR DAIRY             892-2121 9
    *ARCADE FARMS CO           892-2121 R
    *BUF MILK CO OP ASSC       892-2121
    *CLOVERLEAF DAIRY          892-3600
    *GENESEE MILK PRODCR       892-2121
    *UPSTATE MILK CO OP        892-2121
1732*FAIRMONT FOODS CO         897-0707+0
1746*ROTARY CO INC THE         894-4425
    *TELE SCALE INC            894-4425
1747*NIGRA TRANSFORMER         896-6500
1800*KISTNER CONCRT PROD       894-2267
    *KISTNER SEPTIC TANK       894-2267
1810*ALLIED ODOR&IMPRVMT       892-7304
1845*COOK INTRNTL MOVRS        897-0700
    *INTRNTL MVRS COOK         897-0700 R
    *UNITED VAN LNS AGNT       897-0700 9
1850*REF MOLD CO INC           896-6550
    *THRUWAY MOLDERS INC       896-6550
    *   23 BUS     9 RES     1 NEW

DALE RD  14127  ORCHARD PARK

   1 TRACY JACK M              662-3554 9
```

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

ANDERSON RD 1968



SCHOEPPERLE A MRS 649-3A23
37 HANSEN EDWIN C 649-5274
38 VIRTUE JAS R 649-5174
* 0 BUS 12 RES 1 NF*

ANDERSON RD 14225 CHEEKTOWAGA

24*KDLK MFG CO INC 895-6100
40*SCREEN EQUIPT CO 893-0A55
51*ANDERSON A E JR 896-8181
*ANDERSON A E JR 896-8181
*ANDERSON A E CONSTR 896-8181
*ANDERSON CONSTR WRH 896-8181
*ANDERSON LEONARD A 896-8181
*FORNES E J 896-8181
60*UNDERWRITERS SAL CO 893-2370
7A*MULLER TOOL&DIE 895-3658
83*PROCESSING EQP CO 897-1200*B
*VON DUNGEN EMIL BUF 892-0159
107*BAKER RODS CO 892-7100
*PATENT SCAFFOLDING 892-7100
*WELCH J H CO 892-7100
130*KDLK MFG CO PLANT 2 896-8835
ND **HEIST C H OHIO CORP 894-3035
* 17 BUS 0 RES 1 NEW

ANDOVER AV 14215

11 BLOCK HENRY 834-3935
14 SCHILLO LAURA 835-4804
15 WAGNER CARL F 833-8716
18 MAURT CLYDE V 836-4698*B

Target Street	Cross Street	Source
-	✓	Haines Criss-Cross Directory

DALE RD 1968

```
191  RODNEY CECIL T                692-0626
199  ESPOSITO ANTHONY              692-5538
     *    0 BUS    71 RES    10 NEW

DALE RD  14225  CHEEKTOWAGA

1492 FICH WM D                     896-3047
1496 BOCKNER STEPH JR              896-5270
1500 GOSPODARSKI A                 895-2298
     PETROCY EDW                   895-1923
1572 TROJANOSKI J M                893-4757
1600 CZERWONKA JOS A               893-0392
     EVANS RAYMOND C               896-6056+A
     *LITTLE ACRES RESTNT          896-9290
1621 BUDZYNSKI ANTHONY             893-5815
     *BUDZYNSKI ANTHONY            892-3423
     *ST ADALBERTS CEMTRY          892-3823
1625 BUDZYNSKI L SR                892-2582
1711 FILIPCZAK ZBIGNIEW            893-2945
1712*HERALD VAULT MFG               894-6900
     *WILBERT BURIAL VAULT         894-6900
1730*ARCADE FARMS CO                892-2121+A
     *BUF MILK CO OP ASSC          892-2121
     *CLOVERLEAF DAIRY             892-3600
     *GENESEE MILK PRODCR          892-2121
     *UPSTATE MILK CO OP           892-2121
1732*FAIRMONT FOODS CO              897-0707+A
1746*AQUIONICS CORP                 894-4425
     *ROTARY CO INC THE            894-4425
     *TELE SCALE INC               894-4425
1747*NIAGARA TRANSFORMER           896-6500
1800*KISTNER CONCRT PRDC           894-2267
     *KISTNER SEPTIC TANK          894-2267
1810*ALLIED DOOR&IMPRVMT          892-7304
1845*COOK GEO J INC                897-0700+B
     *COOK INTRNTL MOVRS           897-0700
     *INTRNTL MVRS COOK            897-0700+A
     *UNITED VAN LINES             897-0700+A
1850*R&F MOLD CO INC               896-6550
     *THRUWAY MOLDERS INC          896-6550
     *   24 BUS    10 RES     6 NEW

DALE RD  14127  ORCHARD PARK

   3 JANECK R FRED                 662-5690+B
   5 COX RICHD M                   662-9129
     COX RUTH M                    662-9090+B
   9 ROTH R E                      662-3636+A
```

Target Street	Cross Street	Source
✓	-	Polk's City Directory

ANDERSON RD 1963

65 Thorpe Wm A © NX3-1945
South Nicholas dr intersects

238

ANDERSON ROAD (Cheektowaga)—
From 1747 Dale rd north to 1775 Walden av

Zone 25

24 Kolk Mfg Co Inc Mtl Stamping TX5-6100

25 Dustex Corp exhaust fans TX2-6841

40 Screen Equip Co Inc TX3-0455

51 Guslan Realty Corp TX6-8181

Anderson A E Constn Corp contrs TX6-8181

60 Underwriters Salvage Co TX3-2371

74 Muller Tool & Die TX5-3658

83 VonDungen Emil Inc steel fabricators TX2-0159

Heist C H Ohio Inc painting contr TX4-3035

107 Welch J H Co Inc contrs equip TX2-7100

Patent Scaffolding Co Inc TX2-7100

130 Metalform Products Co sht mtl fabricating TX6-8835

Walden av intersects

210

ANDRES PLACE (Cheektowaga)—
From 425 Geo Urban blvd north to


Target Street	Cross Street	Source
-	✓	Polk's City Directory

DALE RD 1963

191 Rodney Cecil T © NX2-0626
199 Esposito Anthony S © NX2-5538
Ellicott Creek rd intersects

238

DALE ROAD (Cheektowaga)—From 1585 Walden av southeast to Thruway
Zone 25
1492 Janicki John S © TX4-3973
1496 Bockner Steph F © TX3-7865
1500 Petrocy Edw © TX5-1923
Gospodarski Angeline TX5-2298
The av begins
1572 Trojanoski Jos M TX3-4757
1600 Angielczyk Danl TX2-5979
Little Acres restr TX6-9290
Czerwonka Jos A © TX3-0392
1601 Vacant
1625 StAdalbert Cemetery TX2-3423
Budzynski Lawrence TX2-3423
1711 Holy Mother of the Rosary Cemetery TX3-2945
Filipczak Zbigniew TX3-2945
1712 Herald Vault Mfg Corp TX4-6900
1730 Frontier Federated Co-operative Inc milk distr TX2-2121
1746 Rotary Hosp Equip Corp surgical gloves TX4-4425
Rotary Co Inc sht mtl wkrs TX4-4425



3774

BUFFALO,

DALE RD–Contd

1746–Contd

Tele-Scale Inc scientific instruments TX4-4425

1747 Niagara Transformer Corp telev parts TX6-6500

Anderson rd begins

1800 Kistner Septic Tank Co Inc TX4-2267

1810 Allied Door & Improvement Co TX2-7304

1820 New York State Thruway Mtce (Sec 6)

1850 R & F Mold Co Inc TX6-6550

Thruway Molders Inc TX6-6550

240

DALEWOOD DRIVE (Amherst)–From 270 Willow Ridge rd east, northeast to Chestnut Ridge rd

2 Vacant

8 Leahan John P © 694-3492

9 Under Constn

Appendix F

Regulatory Database Report and Documentation

Commercial Property
24 Anderson Road
Buffalo, NY 14225

Inquiry Number: 8127688.2s
October 02, 2025

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	624
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-11
Physical Setting Source Map Findings	A-13
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

24 ANDERSON ROAD
BUFFALO, NY 14225

COORDINATES

Latitude (North):	42.9052320 - 42° 54' 18.83''
Longitude (West):	78.7722490 - 78° 46' 20.09''
Universal Tranverse Mercator:	Zone 17
UTM X (Meters):	681867.7
UTM Y (Meters):	4752484.0
Elevation:	656 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14122104 BUFFALO NE, NY
Version Date:	2019
Northeast Map:	14122160 LANCASTER, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20221109
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
24 ANDERSON ROAD
BUFFALO, NY 14225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	NANCY O'NEIL AUTO FI	24 ANDERSON ROAD	NY Spills		TP
A2	ROTARY COMPANY	1746 DALE ROAD	NY HSWDS	Higher	33, 0.006, South
A3	ROCO, LTD.	1746 DALE ROAD	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY VCP	Higher	33, 0.006, South
A4	ROTARY CO INC	1746 DALE RD	SEMS-ARCHIVE, RCRA NonGen / NLR, FINDS, ECHO	Higher	33, 0.006, South
B5	ACTS TESTING LABS IN	25 ANDERSON RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	113, 0.021, East
B6	UPSTATE FARMS COOPER	25 ANDERSON RD	RCRA NonGen / NLR, FINDS, ECHO	Lower	113, 0.021, East
B7	BUILDING ADDITION EX	25 ANDERSON ROAD	NY Spills	Lower	113, 0.021, East
8	NIAGARA TRANSFORMER	DALE ROAD	NY Spills	Higher	125, 0.024, SW
A9	SECO CORP	40 ANDERSON RD	NJ MANIFEST	Lower	128, 0.024, North
A10	DIMAR MANUFACTURING	40 ANDERSON RD	RCRA-SQG, E MANIFEST, NY MANIFEST	Lower	128, 0.024, North
A11	DIMAR MANUFACTURING	40 ANDERSON RD	PFAS ECHO	Lower	128, 0.024, North
A12	SECO CORP	40 ANDERSON ROAD	RCRA NonGen / NLR, RAATS, FINDS, ECHO, NY MANIFEST	Lower	128, 0.024, North
C13	FIELD - POSSIBLY WET	52 ANDERSON	NY Spills	Lower	197, 0.037, North
D14	UPSTATE NIAGARA COOP	1730 DALE RD	UST FINDER	Higher	202, 0.038, NW
D15	UPSTATE MILK	1730 DALE STREET	UST FINDER RELEASE	Higher	202, 0.038, NW
D16	UPSTATE FARM COOPERA	1730 DALE RD.	NY LTANKS, NY CBS AST, NY Spills, NY SPDES	Higher	202, 0.038, NW
D17	UPSTATE NIAGARA	1730 DALE RD	RCRA-VSQG, NY LTANKS, NY CBS, NY AST, E MANIFEST,...	Higher	202, 0.038, NW
D18	UPSTATE MILK	1730 DALE ROAD	UST FINDER RELEASE	Higher	202, 0.038, NW
D19	UPSTATE NIAGARA COOP	1730 DALE RD	NY UST	Higher	202, 0.038, NW
C20	ADVISION INK	60 ANDERSON ST	NY MANIFEST	Lower	284, 0.054, North
C21	ADVISION INC	60 ANDERSON ST	RCRA-VSQG, FINDS, ECHO	Lower	284, 0.054, North
B22	VACANT MANUFACTURING	1800 DALE RD	NY Spills	Lower	332, 0.063, ESE
E23	NIAGARA TRANSFORMER	1747 DALE ROAD	NY Spills	Lower	397, 0.075, South
E24	NIAGARA TRANSFORMER	1747 DALE ROAD	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY...	Lower	397, 0.075, South
E25	PLANT	1747 DALE RD	NY Spills	Lower	397, 0.075, South
E26	NIAGARA TRANSFORMER	1747 DALE ROAD	CORRACTS, RCRA-SQG, 2020 COR ACTION, US AIRS, E...	Lower	397, 0.075, South
C27	MULLER TOOL	74 ANDERSON ROAD	NY Spills	Lower	412, 0.078, North
F28	BUFFALO CLUTCH CO IN	1810 DALE RD	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	455, 0.086, ESE
G29	VON DUNGEN EMIL BFLO	83 ANDERSON RD	RCRA NonGen / NLR, FINDS, ECHO	Lower	473, 0.090, NNE
G30	C H HEIST CORP & SUB	63 ANDERSON RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	480, 0.091, NNE
31	VEOLIA ES INDUSTRIAL	51 ANDERSON RD	RCRA NonGen / NLR, NY MANIFEST, NJ MANIFEST	Lower	481, 0.091, ENE
H32	CLARK LIFT	1835 DALE ROAD	UST FINDER RELEASE	Lower	549, 0.104, SE
H33	PROLIFT INC	1835 DALE RD	RCRA-VSQG, NY Spills, FINDS, ECHO, NY MANIFEST	Lower	549, 0.104, SE
H34	CLARKLIFT OF BUFFALO	1835 DALE ROAD	UST FINDER	Lower	549, 0.104, SE
H35	CLARK LIFT	1835 DALE ROAD	NY LTANKS, NY Spills	Lower	549, 0.104, SE
H36	CLARKLIFT OF BUFFALO	1835 DALE ROAD	NY UST	Lower	549, 0.104, SE
E37	NIAGARA TRANSFORMER	MAIN BLD 1747 DALE R	NY Spills	Lower	554, 0.105, South
F38	BUSINESS	1850 DALE RD	NY Spills	Lower	593, 0.112, ESE
F39	FORMER BUFFALO SPRIN	1820-1850 DALE ROAD	NY Spills	Lower	593, 0.112, ESE

MAPPED SITES SUMMARY

Target Property Address:
24 ANDERSON ROAD
BUFFALO, NY 14225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
F40	PAVEMENT	1850 DALE ROAD	NY Spills	Lower	593, 0.112, ESE
I41	NIAGARA TRANSFORMER	1755 DALE RD	RCRA-SQG, E MANIFEST, NY MANIFEST	Lower	640, 0.121, SSE
I42	NIAGARA TRANSFORMER	1755 DALE ROAD	NY AST	Lower	640, 0.121, SSE
I43	CONCRETE	1755 DALE RD	NY SHWS, NY INST CONTROL, NY BROWNFIELDS, NY...	Lower	640, 0.121, SSE
I44		1755 DALE RD	MI MANIFEST	Lower	640, 0.121, SSE
I45	MANUFACTURING	1755 DALE RD	NY Spills	Lower	640, 0.121, SSE
I46	INDUSTRIAL	1755 DALE RD	NY Spills	Lower	640, 0.121, SSE
I47	INDUSTRIAL	1755 DALE RD	NY Spills	Lower	640, 0.121, SSE
H48	CLARKLIFT OF BUFFALO	DALE ROAD	NY LTANKS	Lower	659, 0.125, SE
H49	VSE CORPORATION CORR	1845 DALE RD	NY MANIFEST	Lower	678, 0.128, SE
H50	VSE CORPORATION CORR	1845 DALE RD	RCRA NonGen / NLR, E MANIFEST	Lower	678, 0.128, SE
51	MAIER-SCHULE INC	1745 WALDEN AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	692, 0.131, North
J52	RYDER TRANSPORTATION	107 ANDERSON ROAD	UST FINDER	Lower	804, 0.152, NNE
J53	RYDER TRANSPORTATION	107 ANDERSON ROAD	NY UST	Lower	804, 0.152, NNE
J54	RYDER TRUCK RENTAL I	107 ANDERSON ROAD	UST FINDER RELEASE	Lower	804, 0.152, NNE
J55	RYDER TRUCK RENTAL I	107 ANDERSON RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	804, 0.152, NNE
J56	RYDER TRUCK RENTAL I	107 ANDERSON ROAD	NY LTANKS, NY Spills	Lower	804, 0.152, NNE
J57	RYDER TRANSPORTATION	107 ANDERSON ROAD	NY AST	Lower	804, 0.152, NNE
J58	RYDER TRUCK RENTALS	107 ANDERSON ROAD	UST FINDER RELEASE	Lower	804, 0.152, NNE
K59	PAUL BATT BUICK INC	1717 WALDEN AVE	UST FINDER	Lower	831, 0.157, NNW
K60	ASPEN DENTAL	1717 WALDEN AVE	RCRA-VSQG, NY UST, NY AST, FINDS, ECHO, E...	Lower	831, 0.157, NNW
L61	SCOTT AVIATION DIV.O	1735 WALDEN AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	909, 0.172, NNW
M62	BUFFALO SPRING	1765 WALDEN AVENUE	UST FINDER RELEASE	Lower	973, 0.184, NNE
M63	BUFFALO SPRING	1765 WALDEN AVENUE	NY LTANKS, NY Spills	Lower	973, 0.184, NNE
N64	OFFICE/WAREHOUSE DEV	1655 WALDEN AVENUE	NY MANIFEST, NY SPDES	Higher	1032, 0.195, WNW
N65	DELTA SONIC WALDEN A	1655 WALDEN AVE	RCRA-SQG, E MANIFEST	Higher	1032, 0.195, WNW
L66	PETSMART	1734 WALDEN AVE	E MANIFEST	Lower	1132, 0.214, NNW
L67	DELAVAN INDUSTRIES I	1728 WALDEN AVE	NY UST	Lower	1137, 0.215, NNW
L68	DELAVAN INDUSTRIES I	1728 WALDEN AVE	UST FINDER	Lower	1137, 0.215, NNW
L69	DELAVAN INDUSTRIES	1728 WALDEN AVE	NY SWF/LF, NY LTANKS, RCRA NonGen / NLR, FINDS,...	Lower	1137, 0.215, NNW
L70	DELEVAN INDUSTRIES	1728 WALDEN AVENUE	UST FINDER RELEASE	Lower	1137, 0.215, NNW
L71	OFFICE DEPOT	1730 WALDEN AVENUE	E MANIFEST	Lower	1139, 0.216, NNW
M72	PERA-BATT COLLISION	1775 WALDEN AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1145, 0.217, NNE
O73	MCKESSON	2873 BROADWAY, SUITE	E MANIFEST	Lower	1202, 0.228, SSE
O74	MCKESSON PHARMA BUFF	2873 BROADWAY	E MANIFEST	Lower	1202, 0.228, SSE
P75	ERNST STEEL		NY DEL SHWS	Lower	1207, 0.229, North
76	UNIVERSAL JOINT SALE	1696 WALDEN AVE	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	1257, 0.238, NNW
P77	ERNST STEEL	1746 WALDEN AVE.	SEMS-ARCHIVE	Lower	1401, 0.265, North
P78	ERNST STEEL	1728-1746 WALDEN AVE	NY SHWS	Lower	1401, 0.265, North

MAPPED SITES SUMMARY

Target Property Address:
24 ANDERSON ROAD
BUFFALO, NY 14225

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
P79	ERNST STEEL SLF	1728-1746 WALDEN AVE	NY SWF/LF, NY ILI	Lower	1401, 0.265, North
Q80	NYNEX	1620 WALDEN AVENUE	NY LTANKS, NY Spills	Higher	1484, 0.281, NW
Q81	NYNEX ENTERPRISES	1620 WALDEN AVENUE	UST FINDER RELEASE	Higher	1484, 0.281, NW
Q82	NYNEX WALDEN	1620 WALDEN AVENUE	UST FINDER RELEASE	Higher	1484, 0.281, NW
Q83	NYNEX	1620 WALDEN AVENUE	UST FINDER RELEASE	Higher	1484, 0.281, NW
84	ABITIBI BOWATER - BU	2835 BROADWAY	NY SWRCY	Lower	1545, 0.293, SSE
85	DELAVAN INDUSTRIES	1722 AND 1728 WALDEN	NY SHWS, NY VAPOR REOPENED	Lower	1558, 0.295, NNW
86	ELLICOTT DRUG	1650 WALDEN AVENUE	UST FINDER RELEASE	Lower	1598, 0.303, NW
87	NYS THRUWAY RADIO TO	I90 WB WALDEN INTERC	NY LTANKS	Higher	1876, 0.355, NE
R88	REXEL USA	505 DUKE ROAD	SEMS-ARCHIVE, NY Spills, RCRA NonGen / NLR, FINDS,...	Lower	2030, 0.384, ESE
R89	BUFFALO FORGE CO. PL	505 DUKE ROAD	NY AST, NY HSWDS	Lower	2030, 0.384, ESE
90	BASIL FORD INC	1540 WALDEN AVE	NY LTANKS, NY UST, NY AST, NY Spills	Higher	2142, 0.406, WNW
91	KENNEDY INDUSTRIAL P	575 KENNEDY RD	NY LTANKS, RCRA NonGen / NLR, NY MANIFEST	Lower	2298, 0.435, SSW
92	NYS THRUWAY AUTHORIT	WALDEN AVE THRUWAY R	NY SWF/LF, NY ILI	Higher	2588, 0.490, NNE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
NANCY O'NEIL AUTO FI 24 ANDERSON ROAD CHEEKTOWAGA, NY	NY Spills Spill Number/Closed Date: 8607251 / 1987-02-27 Site ID: 133126 Spill Date: 1987-02-27	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-LQG ---------- RCRA - Large Quantity Generators

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

EXECUTIVE SUMMARY

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF UST ---------- Major Oil Storage Facilities Database
NY MOSF ---------- Major Oil Storage Facility Site Listing
NY MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land
NY TANKS ---------- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE ---------- Registered Waste Tire Storage & Facility List
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
US CDL ---------- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---------- Historical Petroleum Bulk Storage Database

NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
MINES MRDS ---- Mineral Resources Data System
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
UXO ---- Unexploded Ordnance Sites
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
PFAS NPL ---- Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES ---- Federal Sites PFAS Information
PFAS TSCA ---- PFAS Manufacture and Imports Information
PFAS TRIS ---- List of PFAS Added to the TRI
PFAS RCRA MANIFEST ---- PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR ---- PFAS Contamination Site Location Listing

PFAS WQP ---- Ambient Environmental Sampling for PFAS
PFAS NPDES ---- Clean Water Act Discharge Monitoring Information
PFAS PROJECT ---- NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS ECHO FIRE TRAIN ---- Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT ---- All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC ---- Aqueous Foam Related Incidents Listing
BIOSOLIDS ---- ICIS-NPDES Biosolids Facility Data
NY PFAS ---- PFAS Contamination Site Location Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY DRYCLEANERS ---- Registered Drycleaners
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY LEAD ---- Lead-based Paint Testing Results
NY UIC ---- Underground Injection Control Wells
NY COOLING TOWERS ---- Registered Cooling Towers
NY MGP ---- Manufactured Gas Plants Listing
NY NYC LAND USE ---- New York City Land Use Information
NY NYC OER ---- OER Cleanup Sites Listing

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP ---- EDR Proprietary Manufactured Gas Plants
EDR Hist Auto ---- EDR Exclusive Historical Auto Stations
EDR Hist Cleaner ---- EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 06/26/2025 has revealed that there are 3 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROTARY CO INC Site ID: 0201378 EPA Id: NYD002104016	***1746 DALE RD***	***S 0 - 1/8 (0.006 mi.)***	***A4***	***47***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ERNST STEEL Site ID: 0201812 EPA Id: NYD980508246	1746 WALDEN AVE.	N 1/4 - 1/2 (0.265 mi.)	P77	551
REXEL USA Site ID: 0201292 EPA Id: NYD000631903	***505 DUKE ROAD***	***ESE 1/4 - 1/2 (0.384 mi.)***	***R88***	***569***

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA TRANSFORMER EPA ID:: NYD002106177	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E26***	***237***

EXECUTIVE SUMMARY

Lists of Federal RCRA generators

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 4 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DELTA SONIC WALDEN A EPA ID:: NYR000246322	***1655 WALDEN AVE***	***WNW 1/8 - 1/4 (0.195 mi.)***	***N65***	***476***

Lower Elevation	Address	Direction / Distance	Map ID	Page
DIMAR MANUFACTURING EPA ID:: NYR000196881	***40 ANDERSON RD***	***N 0 - 1/8 (0.024 mi.)***	***A10***	***84***
NIAGARA TRANSFORMER EPA ID:: NYD002106177	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E26***	***237***
NIAGARA TRANSFORMER EPA ID:: NYR000171371	***1755 DALE RD***	***SSE 0 - 1/8 (0.121 mi.)***	***I41***	***341***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 6 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE NIAGARA EPA ID:: NYD986933075	***1730 DALE RD***	***NW 0 - 1/8 (0.038 mi.)***	***D17***	***144***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ADVISION INC EPA ID:: NYD986927879	***60 ANDERSON ST***	***N 0 - 1/8 (0.054 mi.)***	***C21***	***179***
BUFFALO CLUTCH CO IN EPA ID:: NYD986887172	***1810 DALE RD***	***ESE 0 - 1/8 (0.086 mi.)***	***F28***	***272***
PROLIFT INC EPA ID:: NYD013706577	***1835 DALE RD***	***SE 0 - 1/8 (0.104 mi.)***	***H33***	***312***
ASPEN DENTAL EPA ID:: NYD067532242	***1717 WALDEN AVE***	***NNW 1/8 - 1/4 (0.157 mi.)***	***K60***	***446***
UNIVERSAL JOINT SALE EPA ID:: NYD000818583	***1696 WALDEN AVE***	***NNW 1/8 - 1/4 (0.238 mi.)***	***76***	***535***

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 04/30/2025 has revealed that there are 5 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROCO, LTD. Site Code: 514720	***1746 DALE ROAD***	***S 0 - 1/8 (0.006 mi.)***	***A3***	***11***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA TRANSFORMER Site Code: 56636 Class Code: Site is properly closed - requires continued management.	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E24***	***193***
CONCRETE Site Code: 407317	***1755 DALE RD***	***SSE 0 - 1/8 (0.121 mi.)***	***I43***	***372***
ERNST STEEL Site Code: 56552	1728-1746 WALDEN AVE	N 1/4 - 1/2 (0.265 mi.)	P78	552
DELAVAN INDUSTRIES Site Code: 56630	***1722 AND 1728 WALDEN***	***NNW 1/4 - 1/2 (0.295 mi.)***	***85***	***564***

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 06/04/2025 has revealed that there are 3 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYS THRUWAY AUTHORIT	***WALDEN AVE THRUWAY R***	***NNE 1/4 - 1/2 (0.490 mi.)***	***92***	***622***

Lower Elevation	Address	Direction / Distance	Map ID	Page
DELAVAN INDUSTRIES	***1728 WALDEN AVE***	***NNW 1/8 - 1/4 (0.215 mi.)***	***L69***	***490***
ERNST STEEL SLF	***1728-1746 WALDEN AVE***	***N 1/4 - 1/2 (0.265 mi.)***	***P79***	***554***

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking

underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 08/03/2025 has revealed that there are 11 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE FARM COOPERA	***1730 DALE RD.***	***NW 0 - 1/8 (0.038 mi.)***	***D16***	***129***
Spill Number/Closed Date: 9603891 / 1996-10-02				
Spill Number/Closed Date: 0408128 / 2004-10-25				
Site ID: 246981				
Site ID: 332775				
Spill Date: 1996-06-20				
Spill Date: 2004-10-22				
UPSTATE NIAGARA	***1730 DALE RD***	***NW 0 - 1/8 (0.038 mi.)***	***D17***	***144***
Spill Number/Closed Date: 0010155 / 2001-02-28				
Spill Number/Closed Date: 8706123 / 1987-10-23				
Site ID: 246979				
Site ID: 126108				
Spill Date: 2000-12-09				
Spill Date: 1987-10-20				
NYNEX	***1620 WALDEN AVENUE***	***NW 1/4 - 1/2 (0.281 mi.)***	***Q80***	***555***
Spill Number/Closed Date: 8909925 / 1990-08-13				
Site ID: 111723				
Spill Date: 1990-01-12				
NYS THRUWAY RADIO TO	I90 WB WALDEN INTERC	NE 1/4 - 1/2 (0.355 mi.)	87	568
Spill Number/Closed Date: 0075337 / 2000-09-20				
Site ID: 269058				
Spill Date: 2000-08-01				
BASIL FORD INC	***1540 WALDEN AVE***	***WNW 1/4 - 1/2 (0.406 mi.)***	***90***	***593***
Spill Number/Closed Date: 1104332 / 2012-09-27				
Site ID: 451935				
Spill Date: 2011-07-19				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CLARK LIFT	***1835 DALE ROAD***	***SE 0 - 1/8 (0.104 mi.)***	***H35***	***330***
Spill Number/Closed Date: 9207999 / 1994-04-18				
Site ID: 226678				
Spill Date: 1992-10-15				
CLARKLIFT OF BUFFALO	DALE ROAD	SE 0 - 1/8 (0.125 mi.)	H48	397
Spill Number/Closed Date: 8606943 / 1988-03-29				
Site ID: 109281				
Spill Date: 1987-02-12				
RYDER TRUCK RENTAL I	***107 ANDERSON ROAD***	***NNE 1/8 - 1/4 (0.152 mi.)***	***J56***	***433***
Spill Number/Closed Date: 8707899 / 1988-03-18				
Spill Number/Closed Date: 9612615 / 1997-01-24				
Spill Number/Closed Date: 9810363 / 2001-08-16				
Site ID: 84181				
Site ID: 84182				
Site ID: 174499				
Spill Date: 1987-12-13				
Spill Date: 1996-09-16				

Spill Date: 1998-11-17

BUFFALO SPRING ***1765 WALDEN AVENUE*** ***NNE 1/8 - 1/4 (0.184 mi.)*** ***M63*** ***471***
Spill Number/Closed Date: 9705918 / 1997-10-23
Site ID: 248082
Spill Date: 1997-08-15

DELAVAN INDUSTRIES ***1728 WALDEN AVE*** ***NNW 1/8 - 1/4 (0.215 mi.)*** ***L69*** ***490***
Spill Number/Closed Date: 8701865 / 1987-08-07
Spill Number/Closed Date: 8701908 / 1987-08-07
Site ID: 131793
Site ID: 131794
Spill Date: 1987-06-04
Spill Date: 1987-06-05

KENNEDY INDUSTRIAL P ***575 KENNEDY RD*** ***SSW 1/4 - 1/2 (0.435 mi.)*** ***91*** ***614***
Spill Number/Closed Date: 9407179 / 1994-12-19
Site ID: 78080
Spill Date: 1994-08-25

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 5 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE NIAGARA COOP Database: UST, Date of Government Version: 06/16/2025	1730 DALE RD	NW 0 - 1/8 (0.038 mi.)	D19	162

Lower Elevation	Address	Direction / Distance	Map ID	Page
CLARKLIFT OF BUFFALO Database: UST, Date of Government Version: 06/16/2025	1835 DALE ROAD	SE 0 - 1/8 (0.104 mi.)	H36	334
RYDER TRANSPORTATION Database: UST, Date of Government Version: 06/16/2025	107 ANDERSON ROAD	NNE 1/8 - 1/4 (0.152 mi.)	J53	421
ASPEN DENTAL Database: UST, Date of Government Version: 06/16/2025	***1717 WALDEN AVE***	***NNW 1/8 - 1/4 (0.157 mi.)***	***K60***	***446***
DELAVAN INDUSTRIES I Database: UST, Date of Government Version: 06/16/2025	1728 WALDEN AVE	NNW 1/8 - 1/4 (0.215 mi.)	L67	486

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 06/16/2025 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE NIAGARA	***1730 DALE RD***	***NW 0 - 1/8 (0.038 mi.)***	***D17***	***144***

Facility Status: Active
CBS Number: 9-000064

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 4 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE NIAGARA	***1730 DALE RD***	***NW 0 - 1/8 (0.038 mi.)***	***D17***	***144***
Database: AST, Date of Government Version: 06/16/2025 Facility Id: 9-387118				

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA TRANSFORMER	1755 DALE ROAD	SSE 0 - 1/8 (0.121 mi.)	I42	368
Database: AST, Date of Government Version: 06/16/2025 Facility Id: 9-601377				
RYDER TRANSPORTATION	107 ANDERSON ROAD	NNE 1/8 - 1/4 (0.152 mi.)	J57	441
Database: AST, Date of Government Version: 06/16/2025 Facility Id: 9-022292				
ASPEN DENTAL	***1717 WALDEN AVE***	***NNW 1/8 - 1/4 (0.157 mi.)***	***K60***	***446***
Database: AST, Date of Government Version: 06/16/2025 Facility Id: 9-385107				

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE FARM COOPERA	***1730 DALE RD.***	***NW 0 - 1/8 (0.038 mi.)***	***D16***	***129***
Facility Status: 1 Facility Status: 1 CBS Number: 9-000064				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 04/30/2025 has revealed that there are 2 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROCO, LTD. Site Code: 57001	***1746 DALE ROAD***	***S 0 - 1/8 (0.006 mi.)***	***A3***	***11***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA TRANSFORMER Site Code: 56636	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E24***	***193***

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 04/30/2025 has revealed that there are 3 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROCO, LTD. Site Code: 57001	***1746 DALE ROAD***	***S 0 - 1/8 (0.006 mi.)***	***A3***	***11***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA TRANSFORMER Site Code: 56636	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E24***	***193***
CONCRETE Site Code: 418419	***1755 DALE RD***	***SSE 0 - 1/8 (0.121 mi.)***	***I43***	***372***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there is 1 NY VCP site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROCO, LTD. Database: VCP, Date of Government Version: 04/30/2025 Site Code: 57001	***1746 DALE ROAD***	***S 0 - 1/8 (0.006 mi.)***	***A3***	***11***

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 04/30/2025 has revealed that there is 1 NY BROWNFIELDS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONCRETE	***1755 DALE RD***	***SSE 0 - 1/8 (0.121 mi.)***	***I43***	***372***
Site Code: 418419				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

Registered Recycling Facility List from the Department of Environmental Conservation.

A review of the NY SWRCY list, as provided by EDR, and dated 06/04/2025 has revealed that there is 1 NY SWRCY site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ABITIBI BOWATER - BU	2835 BROADWAY	SSE 1/4 - 1/2 (0.293 mi.)	84	564

Local Lists of Hazardous waste / Contaminated Sites

NY DEL SHWS: A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

A review of the NY DEL SHWS list, as provided by EDR, and dated 04/30/2025 has revealed that there is 1 NY DEL SHWS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ERNST STEEL		N 1/8 - 1/4 (0.229 mi.)	P75	533
Site Code Id: 915022				

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 08/03/2025 has revealed that there are 20 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROCO, LTD.	***1746 DALE ROAD***	***S 0 - 1/8 (0.006 mi.)***	***A3***	***11***
Spill Number/Closed Date: 0702536 / 2008-02-20				
Site ID: 382280				
Spill Date: 2007-05-31				
NIAGARA TRANSFORMER	DALE ROAD	SW 0 - 1/8 (0.024 mi.)	8	81
Spill Number/Closed Date: 0075690 / 2001-07-09				

Site ID: 247668
Spill Date: 2001-03-01

UPSTATE FARM COOPERA	***1730 DALE RD.***	***NW 0 - 1/8 (0.038 mi.)***	***D16***	***129***

Spill Number/Closed Date: 0075304 / 2000-09-20
Spill Number/Closed Date: 0408704 / 2004-11-09
Spill Number/Closed Date: 9901856 / 1999-05-18
Site ID: 246980
Site ID: 333441
Site ID: 126109
Spill Date: 2000-08-17
Spill Date: 2004-11-06
Spill Date: 1999-05-17

Lower Elevation	Address	Direction / Distance	Map ID	Page
BUILDING ADDITION EX	25 ANDERSON ROAD	E 0 - 1/8 (0.021 mi.)	B7	80

Spill Number/Closed Date: 1101569 / 2011-08-17
Site ID: 449029
Spill Date: 2011-05-11

FIELD - POSSIBLY WET	52 ANDERSON	N 0 - 1/8 (0.037 mi.)	C13	124

Spill Number/Closed Date: 1306582 / 2013-09-23
Site ID: 487206
Spill Date: 2013-09-23

VACANT MANUFACTURING	1800 DALE RD	ESE 0 - 1/8 (0.063 mi.)	B22	187

Spill Number/Closed Date: 9700454 / 1998-03-10
Spill Number/Closed Date: 2305260 / 2023-10-05
Site ID: 143280
Site ID: 657198
Spill Date: 1997-04-09
Spill Date: 2023-09-19

NIAGARA TRANSFORMER	1747 DALE ROAD	S 0 - 1/8 (0.075 mi.)	E23	191

Spill Number/Closed Date: 0404644 / 2004-07-30
Spill Number/Closed Date: 0413613 / 2005-03-31
Site ID: 312662
Site ID: 342766
Spill Date: 2004-07-29
Spill Date: 2005-03-30

NIAGARA TRANSFORMER	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E24***	***193***

Spill Number/Closed Date: 1308841 / 2014-11-03
Spill Number/Closed Date: 0510258 / 2006-02-17
Spill Number/Closed Date: 1007053 / 2010-12-20
Spill Number/Closed Date: 1212665 / 2012-12-19
Spill Number/Closed Date: 9000362 / 1990-04-24
**Additional key fields are available in the Map Findings section*
Site ID: 489601
Site ID: 356198
Site ID: 440437
Site ID: 475819
Site ID: 297062
**Additional key fields are available in the Map Findings section*
Spill Date: 2013-12-04
Spill Date: 2005-11-30
Spill Date: 2010-10-01

Spill Date: 2012-11-27
Spill Date: 1990-04-10
**Additional key fields are available in the Map Findings section*

PLANT	1747 DALE RD	S 0 - 1/8 (0.075 mi.)	E25	236
Spill Number/Closed Date: 1305910 / 2014-11-03				
Site ID: 486496				
Spill Date: 2013-09-04				
MULLER TOOL	74 ANDERSON ROAD	N 0 - 1/8 (0.078 mi.)	C27	271
Spill Number/Closed Date: 8705639 / 1987-10-13				
Site ID: 329614				
Spill Date: 1987-10-02				
PROLIFT INC	***1835 DALE RD***	***SE 0 - 1/8 (0.104 mi.)***	***H33***	***312***
Spill Number/Closed Date: 9700333 / 1997-04-07				
Site ID: 109282				
Spill Date: 1997-04-01				
CLARK LIFT	***1835 DALE ROAD***	***SE 0 - 1/8 (0.104 mi.)***	***H35***	***330***
Spill Number/Closed Date: 9300470 / 1993-04-16				
Spill Number/Closed Date: 9708106 / 1997-10-17				
Site ID: 226679				
Site ID: 226680				
Spill Date: 1993-04-07				
Spill Date: 1997-10-01				
NIAGARA TRANSFORMER	MAIN BLD 1747 DALE R	S 0 - 1/8 (0.105 mi.)	E37	336
Spill Number/Closed Date: 1301247 / 2014-10-29				
Site ID: 481622				
Spill Date: 2013-05-07				
BUSINESS	1850 DALE RD	ESE 0 - 1/8 (0.112 mi.)	F38	338
Spill Number/Closed Date: 1706984 / 2018-08-13				
Site ID: 561323				
Spill Date: 2017-10-18				
FORMER BUFFALO SPRIN	1820-1850 DALE ROAD	ESE 0 - 1/8 (0.112 mi.)	F39	339
Spill Number/Closed Date: 2503901 / Not Reported				
Site ID: 681290				
Spill Date: 2021-11-16				
PAVEMENT	1850 DALE ROAD	ESE 0 - 1/8 (0.112 mi.)	F40	340
Spill Number/Closed Date: 1801656 / 2018-05-14				
Site ID: 570196				
Spill Date: 2018-05-14				
CONCRETE	***1755 DALE RD***	***SSE 0 - 1/8 (0.121 mi.)***	***I43***	***372***
Spill Number/Closed Date: 1310803 / 2014-10-29				
Spill Number/Closed Date: 1310240 / 2014-11-03				
Site ID: 491673				
Site ID: 491080				
Spill Date: 2014-02-14				
Spill Date: 2014-01-23				
MANUFACTURING	1755 DALE RD	SSE 0 - 1/8 (0.121 mi.)	I45	391
Spill Number/Closed Date: 2500897 / Not Reported				
Spill Number/Closed Date: 1606171 / 2017-02-07				
Site ID: 678187				
Site ID: 532773				
Spill Date: 2025-05-01				

Spill Date: 2016-09-21

INDUSTRIAL Spill Number/Closed Date: 1409312 / 2015-05-29 Spill Number/Closed Date: 2003440 / 2020-07-30 Site ID: 502923 Site ID: 609166 Spill Date: 2014-12-15 Spill Date: 2020-07-28	1755 DALE RD	SSE 0 - 1/8 (0.121 mi.)	I46	394
INDUSTRIAL Spill Number/Closed Date: 2308473 / 2024-01-22 Site ID: 662587 Spill Date: 2024-01-22	1755 DALE RD	SSE 0 - 1/8 (0.121 mi.)	I47	396

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/02/2025 has revealed that there are 13 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROTARY CO INC EPA ID:: NYD002104016	***1746 DALE RD***	***S 0 - 1/8 (0.006 mi.)***	***A4***	***47***
PERA-BATT COLLISION EPA ID:: NYD981557556	***1775 WALDEN AVE***	***NNE 1/8 - 1/4 (0.217 mi.)***	***M72***	***514***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ACTS TESTING LABS IN EPA ID:: NY0000075648	***25 ANDERSON RD***	***E 0 - 1/8 (0.021 mi.)***	***B5***	***57***
UPSTATE FARMS COOPER EPA ID:: NYR000093880	***25 ANDERSON RD***	***E 0 - 1/8 (0.021 mi.)***	***B6***	***76***
SECO CORP EPA ID:: NYD056136526	***40 ANDERSON ROAD***	***N 0 - 1/8 (0.024 mi.)***	***A12***	***108***
VON DUNGEN EMIL BFLO EPA ID:: NYD002104982	***83 ANDERSON RD***	***NNE 0 - 1/8 (0.090 mi.)***	***G29***	***286***
C H HEIST CORP & SUB EPA ID:: NYD063650873	***63 ANDERSON RD***	***NNE 0 - 1/8 (0.091 mi.)***	***G30***	***291***
VEOLIA ES INDUSTRIAL EPA ID:: NYR000177576	***51 ANDERSON RD***	***ENE 0 - 1/8 (0.091 mi.)***	***31***	***298***
VSE CORPORATION CORR EPA ID:: NYR000247387	***1845 DALE RD***	***SE 1/8 - 1/4 (0.128 mi.)***	***H50***	***399***
MAIER-SCHULE INC EPA ID:: NYD002129922	***1745 WALDEN AVE***	***N 1/8 - 1/4 (0.131 mi.)***	***51***	***404***
RYDER TRUCK RENTAL I	***107 ANDERSON RD***	***NNE 1/8 - 1/4 (0.152 mi.)***	***J55***	***428***

EPA ID:: NYD074009812

SCOTT AVIATION DIV.O	***1735 WALDEN AVE***	***NNW 1/8 - 1/4 (0.172 mi.)***	***L61***	***466***

EPA ID:: NYD000811067

DELAVAN INDUSTRIES	***1728 WALDEN AVE***	***NNW 1/8 - 1/4 (0.215 mi.)***	***L69***	***490***

EPA ID:: NYD980559496

2020 COR ACTION: The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

A review of the 2020 COR ACTION list, as provided by EDR, and dated 09/30/2017 has revealed that there is 1 2020 COR ACTION site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NIAGARA TRANSFORMER	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E26***	***237***

EPA ID:: NYD002106177

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 06/23/2025 has revealed that there is 1 PFAS ECHO site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DIMAR MANUFACTURING	40 ANDERSON RD	N 0 - 1/8 (0.024 mi.)	A11	107

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 11 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE MILK	1730 DALE STREET	NW 0 - 1/8 (0.038 mi.)	D15	128
UPSTATE MILK	1730 DALE ROAD	NW 0 - 1/8 (0.038 mi.)	D18	161
NYNEX ENTERPRISES	1620 WALDEN AVENUE	NW 1/4 - 1/2 (0.281 mi.)	Q81	561
NYNEX WALDEN	1620 WALDEN AVENUE	NW 1/4 - 1/2 (0.281 mi.)	Q82	562
NYNEX	1620 WALDEN AVENUE	NW 1/4 - 1/2 (0.281 mi.)	Q83	563

Lower Elevation	Address	Direction / Distance	Map ID	Page
CLARK LIFT	1835 DALE ROAD	SE 0 - 1/8 (0.104 mi.)	H32	312
RYDER TRUCK RENTAL I	107 ANDERSON ROAD	NNE 1/8 - 1/4 (0.152 mi.)	J54	427

Lower Elevation	Address	Direction / Distance	Map ID	Page
RYDER TRUCK RENTALS	107 ANDERSON ROAD	NNE 1/8 - 1/4 (0.152 mi.)	J58	444
BUFFALO SPRING	1765 WALDEN AVENUE	NNE 1/8 - 1/4 (0.184 mi.)	M62	470
DELEVAN INDUSTRIES	1728 WALDEN AVENUE	NNW 1/8 - 1/4 (0.215 mi.)	L70	508
ELLICOTT DRUG	1650 WALDEN AVENUE	NW 1/4 - 1/2 (0.303 mi.)	86	567

UST FINDER: EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

A review of the UST FINDER list, as provided by EDR, and dated 06/08/2023 has revealed that there are 5 UST FINDER sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE NIAGARA COOP	1730 DALE RD	NW 0 - 1/8 (0.038 mi.)	D14	125

Lower Elevation	Address	Direction / Distance	Map ID	Page
CLARKLIFT OF BUFFALO	1835 DALE ROAD	SE 0 - 1/8 (0.104 mi.)	H34	329
RYDER TRANSPORTATION	107 ANDERSON ROAD	NNE 1/8 - 1/4 (0.152 mi.)	J52	419
PAUL BATT BUICK INC	1717 WALDEN AVE	NNW 1/8 - 1/4 (0.157 mi.)	K59	445
DELAVAN INDUSTRIES I	1728 WALDEN AVE	NNW 1/8 - 1/4 (0.215 mi.)	L68	489

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 06/02/2025 has revealed that there are 11 E MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UPSTATE NIAGARA	***1730 DALE RD***	***NW 0 - 1/8 (0.038 mi.)***	***D17***	***144***
DELTA SONIC WALDEN A	***1655 WALDEN AVE***	***WNW 1/8 - 1/4 (0.195 mi.)***	***N65***	***476***

Lower Elevation	Address	Direction / Distance	Map ID	Page
DIMAR MANUFACTURING	***40 ANDERSON RD***	***N 0 - 1/8 (0.024 mi.)***	***A10***	***84***
NIAGARA TRANSFORMER	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E26***	***237***
NIAGARA TRANSFORMER	***1755 DALE RD***	***SSE 0 - 1/8 (0.121 mi.)***	***I41***	***341***
VSE CORPORATION CORR	***1845 DALE RD***	***SE 1/8 - 1/4 (0.128 mi.)***	***H50***	***399***
ASPEN DENTAL	***1717 WALDEN AVE***	***NNW 1/8 - 1/4 (0.157 mi.)***	***K60***	***446***
PETSMART	1734 WALDEN AVE	NNW 1/8 - 1/4 (0.214 mi.)	L66	481
OFFICE DEPOT	1730 WALDEN AVENUE	NNW 1/8 - 1/4 (0.216 mi.)	L71	510
MCKESSON	2873 BROADWAY, SUITE	SSE 1/8 - 1/4 (0.228 mi.)	O73	529
MCKESSON PHARMA BUFF	2873 BROADWAY	SSE 1/8 - 1/4 (0.228 mi.)	O74	532

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there are 2 NY HSWDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROTARY COMPANY	1746 DALE ROAD	S 0 - 1/8 (0.006 mi.)	A2	10
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
BUFFALO FORGE CO. PL	***505 DUKE ROAD***	***ESE 1/4 - 1/2 (0.384 mi.)***	***R89***	***590***

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 12/31/2019 has revealed that there are 20 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROCO, LTD. EPA ID: NYD002104016	***1746 DALE ROAD***	***S 0 - 1/8 (0.006 mi.)***	***A3***	***11***
UPSTATE NIAGARA EPA ID: NYD986933075	***1730 DALE RD***	***NW 0 - 1/8 (0.038 mi.)***	***D17***	***144***
OFFICE/WAREHOUSE DEV EPA ID: NYR000246322	***1655 WALDEN AVENUE***	***WNW 1/8 - 1/4 (0.195 mi.)***	***N64***	***474***
PERA-BATT COLLISION EPA ID: NYD981557556	***1775 WALDEN AVE***	***NNE 1/8 - 1/4 (0.217 mi.)***	***M72***	***514***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
ACTS TESTING LABS IN EPA ID: NY0000075648	***25 ANDERSON RD***	***E 0 - 1/8 (0.021 mi.)***	***B5***	***57***
DIMAR MANUFACTURING EPA ID: NYR000196881	***40 ANDERSON RD***	***N 0 - 1/8 (0.024 mi.)***	***A10***	***84***
SECO CORP EPA ID: NYD056136526	***40 ANDERSON ROAD***	***N 0 - 1/8 (0.024 mi.)***	***A12***	***108***
ADVISION INK EPA ID: NYD986927879	60 ANDERSON ST	N 0 - 1/8 (0.054 mi.)	C20	169
NIAGARA TRANSFORMER EPA ID: NYD002106177	***1747 DALE ROAD***	***S 0 - 1/8 (0.075 mi.)***	***E24***	***193***
BUFFALO CLUTCH CO IN EPA ID: NYD986887172	***1810 DALE RD***	***ESE 0 - 1/8 (0.086 mi.)***	***F28***	***272***
C H HEIST CORP & SUB	***63 ANDERSON RD***	***NNE 0 - 1/8 (0.091 mi.)***	***G30***	***291***

EPA ID: NYD063650873				
VEOLIA ES INDUSTRIAL EPA ID: NYR000177576	***51 ANDERSON RD***	***ENE 0 - 1/8 (0.091 mi.)***	***31***	***298***
PROLIFT INC EPA ID: NYD013706577	***1835 DALE RD***	***SE 0 - 1/8 (0.104 mi.)***	***H33***	***312***
NIAGARA TRANSFORMER EPA ID: NYR000171371	***1755 DALE RD***	***SSE 0 - 1/8 (0.121 mi.)***	***I41***	***341***
VSE CORPORATION CORR EPA ID: NYR000247387	1845 DALE RD	SE 1/8 - 1/4 (0.128 mi.)	H49	399
MAIER-SCHULE INC EPA ID: NYD002129922	***1745 WALDEN AVE***	***N 1/8 - 1/4 (0.131 mi.)***	***51***	***404***
RYDER TRUCK RENTAL I EPA ID: NYD074009812	***107 ANDERSON RD***	***NNE 1/8 - 1/4 (0.152 mi.)***	***J55***	***428***
ASPEN DENTAL EPA ID: NYD067532242	***1717 WALDEN AVE***	***NNW 1/8 - 1/4 (0.157 mi.)***	***K60***	***446***
DELAVAN INDUSTRIES EPA ID: NYD980559496	***1728 WALDEN AVE***	***NNW 1/8 - 1/4 (0.215 mi.)***	***L69***	***490***
UNIVERSAL JOINT SALE EPA ID: NYD000818583	***1696 WALDEN AVE***	***NNW 1/8 - 1/4 (0.238 mi.)***	***76***	***535***

MI MANIFEST: A generator who transports, or offers for transportation, hazardous waste for off-site treatment, storage or disposal must prepare a hazardous waste manifest to accompany such shipment.

A review of the MI MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there is 1 MI MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	1755 DALE RD	SSE 0 - 1/8 (0.121 mi.)	I44	390

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 2 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SECO CORP EPA Id: NYD056136526	40 ANDERSON RD	N 0 - 1/8 (0.024 mi.)	A9	83
VEOLIA ES INDUSTRIAL EPA Id: NYR000177576	***51 ANDERSON RD***	***ENE 0 - 1/8 (0.091 mi.)***	***31***	***298***

NY VAPOR REOPENED: "Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil. Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for

exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

A review of the NY VAPOR REOPENED list, as provided by EDR, and dated 01/01/2022 has revealed that there is 1 NY VAPOR REOPENED site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DELAVAN INDUSTRIES	***1722 AND 1728 WALDEN***	***NNW 1/4 - 1/2 (0.295 mi.)***	***85***	***564***
Facility Status: Complete (No Further Action)				
Site Code: 915138				

NY ILI: A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. Inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants.

A review of the NY ILI list, as provided by EDR, and dated 07/01/2025 has revealed that there are 2 NY ILI sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NYS THRUWAY AUTHORIT	***WALDEN AVE THRUWAY R***	***NNE 1/4 - 1/2 (0.490 mi.)***	***92***	***622***


Lower Elevation	Address	Direction / Distance	Map ID	Page
ERNST STEEL SLF	***1728-1746 WALDEN AVE***	***N 1/4 - 1/2 (0.265 mi.)***	***P79***	***554***

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 5 records.

Site Name	Database(s)
NYS THRUWAY EXIT 52	NY SHWS
PYRAMID COMPANY	NY SHWS
NYS THRUWAY EXIT DMP	SEMS-ARCHIVE
BROADWAY GARAGE	NY SWF/LF
CTS CRUSHING & RECYCLING	NY SWF/LF

OVERVIEW MAP - 8127688.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Commercial Property	CLIENT:	Farmer Environmental Group
ADDRESS:	24 Anderson Road Buffalo NY 14225	CONTACT:	Roy David King
		INQUIRY #:	8127688.2s
LAT/LONG:	42.905232 / 78.772249	DATE:	October 02, 2025 9:31 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 8127688.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Commercial Property	CLIENT:	Farmer Environmental Group
ADDRESS:	24 Anderson Road Buffalo NY 14225	CONTACT:	Roy David King
		INQUIRY #:	8127688.2s
LAT/LONG:	42.905232 / 78.772249	DATE:	October 02, 2025 9:33 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		1	0	2	NR	NR	3
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		1	0	0	0	NR	1
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		3	1	NR	NR	NR	4
RCRA-VSQG	0.250		4	2	NR	NR	NR	6
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		3	0	2	0	NR	5
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		0	1	2	NR	NR	3
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		4	3	4	NR	NR	11
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		2	3	NR	NR	NR	5
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY CBS	0.250		1	0	NR	NR	NR	1
NY MOSF	0.500		0	0	0	NR	NR	0
NY AST	0.250		2	2	NR	NR	NR	4
NY CBS AST	0.250		1	0	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		2	0	0	NR	NR	2
NY INST CONTROL	0.500		3	0	0	NR	NR	3
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		1	0	0	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		1	0	0	NR	NR	1
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	1	NR	NR	1
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	1	0	0	NR	1
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
NY Spills	0.125	1	20	NR	NR	NR	NR	21
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		7	6	NR	NR	NR	13
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		1	0	NR	NR	NR	1
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
FINDS	0.001		0	NR	NR	NR	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		1	0	NR	NR	NR	1
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	0.001		0	NR	NR	NR	NR	0
UST FINDER RELEASE	0.500		3	4	4	NR	NR	11
UST FINDER	0.250		2	3	NR	NR	NR	5
E MANIFEST	0.250		4	7	NR	NR	NR	11
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	0.001		0	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0
NY Financial Assurance	0.001		0	NR	NR	NR	NR	0
NY HSWDS	0.500		1	0	1	NR	NR	2
NY LEAD	0.001		0	NR	NR	NR	NR	0
NY MANIFEST	0.250		12	8	NR	NR	NR	20
MI MANIFEST	0.250		1	0	NR	NR	NR	1
NJ MANIFEST	0.250		2	0	NR	NR	NR	2
NY SPDES	0.001		0	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	1	NR	NR	1
NY UIC	0.001		0	NR	NR	NR	NR	0
NY COOLING TOWERS	0.001		0	NR	NR	NR	NR	0
NY MGP	1.000		0	0	0	0	NR	0
NY NYC LAND USE	0.001		0	NR	NR	NR	NR	0
NY ILI	0.500		0	0	2	NR	NR	2
NY NYC OER	1.000		0	0	0	0	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY RGA LF	0.001		0	NR	NR	NR	NR	0
- Totals --		1	83	41	19	0	0	144

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target
Property

NANCY O'NEIL AUTO FIRE
24 ANDERSON ROAD
CHEEKTOWAGA, NY

NY Spills **S102175488**
N/A

Site 1 of 8 in cluster A

Actual:
656 ft.

SPILLS:

Name:	NANCY O'NEIL AUTO FIRE
Address:	24 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	8607251 / 1987-02-27
Facility ID:	8607251
Facility Type:	ER
DER Facility ID:	114579
Site ID:	133126
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1530
Spill Date:	1987-02-27
Investigator:	PRINGLE
Referred To:	Not reported
Reported to Dept:	1987-02-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	1987-02-27
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-02-27
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	NANCY O'NEIL
Spiller Address:	123 N. MAIN STREET
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9049825
Longitude:	-78.7716525
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : TELECON 02/27/87, CLEANED UP BY TOWN OF CHEEKTOWAGA, NO FURTHER ACTION REQUIRED.
Remarks:	Not reported

All Materials:

Site ID:	133126
Operable Unit ID:	903899
Operable Unit:	01
Material ID:	472768
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A2
South
< 1/8
0.006 mi.
33 ft.

ROTARY COMPANY
1746 DALE ROAD
BUFFALO, NY 14225

Site 2 of 8 in cluster A

NY HSWDS **S108146691**
N/A

Relative:
Higher

Actual:
656 ft.

HSWDS:

Facility ID:	Not reported
Region:	9
Facility Status:	None
Owner Type:	Puplic
Owner:	Unknown
Owner Address:	Unknown
Owner Phone:	Unknown
Operator Type:	Puplic
Operator:	William Weiss
Operator:	William Weiss
Operator Phone:	(716)894-4425
EPA ID:	NYD002104016
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Industrial Site
Owner City State:	Not reported
Operator City State:	Buffalo
Quadrange:	Buffalo Northeast
Latitude:	42 52 50 N
Longitude:	78 51 00 W
Acres:	0.00
Operator Date:	1852
Close Date:	Unknown
Completed:	PA
Active:	Unknown
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	Yes
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	No
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	Unknown
Surface Water Contamination:	Unknown
Surface Water Body Class:	Unknown
Groundwater Contamination:	No
Groundwater Classification:	Unknown
Drinking Water Contamination:	No
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	No
Hazardous Exposure:	No
Site Has Controlled Acess:	Yes

ROTARY COMPANY (Continued) **S108146691**

Ambient Air Contamination:	Unknown
Direct Contact:	No
EPA Hazardous Ranking System Score:	Unknown
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

A3 **ROCO, LTD.** **NY SHWS** **S105114396**
South **1746 DALE ROAD** **NY ENG CONTROLS** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225** **NY INST CONTROL**
0.006 mi. **NY VCP**
33 ft. **Site 3 of 8 in cluster A** **NY Spills**
NY MANIFEST

Relative:
Higher

Actual:
656 ft.

SHWS:

Name:	ROCO, LTD.
Address:	1746 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Program:	HW
Site Code:	514720
Classification:	P
Region:	9
Acres:	0.833
HW Code:	915300
Record Add:	10/09/2015
Record Upd:	04/15/2025
Updated By:	AECAPRIO
Site Description:	Location: The ROCO Ltd. site is an approximately 0.833-acre site, located in an urban area, at 1746 Dale Road in the Town of Cheektowaga, Erie County. It is at the intersection of Anderson and Dale Roads. The Niagara Transformer inactive hazardous waste site (site #915146) and the adjacent Niagara Transformer brownfield cleanup site (site #C915234) both lie to the south, across Dale Road. Site Features: A one-story, 33,000-square-foot, cement block on-grade

ROCO, LTD. (Continued) **S105114396**

building occupies most of the site. There is an asphalt-covered parking lot in the southeast corner of the site and a few feet of asphalt and gravel-covered ground around the perimeter of the building. The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. Current Zoning and Land Use: The area is zoned for general manufacturing and the building is currently vacant. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. Operations included metal preparation and finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. The site building was later used as a product warehouse by the neighboring dairy product processing company until early 2010. Site Geology and Hydrogeology The overburden soil is comprised of fine to coarse sand in the upper two feet followed by a silty clay with some sand to a depth of 15 feet below ground surface (fbgs). Depth to bedrock at the site is unknown, however, bedrock was encountered at depths ranging from 44 to 54 fbgs at the Niagara Transformer site across Dale Road to the south. Depth to groundwater varies from approximately 1 to 7 fbgs and generally flows southward.

Env Problem: Nature and Extent of Contamination: Based upon investigations done to date the primary contaminants of concern at the site include tetrachloroethene (PCE), trichloroethene (TCE), cis-1,2-dichloroethene and vinyl chloride. A site investigation, conducted under the Voluntary Cleanup Program (VCP) by the previous owner, indicated a plume of contaminated groundwater mounded beneath the metal preparation room in the northwest corner of the building. The plume extends to the west beneath a paved parking lot and to the south beneath the building. Groundwater flow is to the south, but it appeared that the downgradient edge of the plume was within the site boundary. A second, smaller and less concentrated area of groundwater contamination was also found on the north side of the building. The concentrations of TCE and PCE found in the soils sampled beneath the metal prep room and the near vicinity were above the soil cleanup objectives (SCOs) for the Protection of Groundwater but below the SCOs for industrial use. In-situ treatment of the groundwater using a hydrogen-release compound (HRC) was performed in 2005 and again in 2008. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room were reduced from 67,400 parts per billion (ppb) in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 ppb by March 2010. Monitoring data from March 2010 also indicated that the injected HRC had not been fully expended, so further injections were not recommended. The Voluntary Cleanup Agreement was terminated in 2013 after the previous owner abandoned the required groundwater monitoring program. Groundwater was sampled and analyzed again in 2014 by the current site owner. Total volatile organic compound (VOC) concentrations beneath the metal prep room remain high at 61,219 ppb. Elevated concentrations of chlorinated solvents were also found in the soil vapor beneath the metal preparation room, at concentrations that require mitigation. A soil vacuum extraction system (SVE) was installed in the metal prep room in 2015 to address the source area of the groundwater contamination and to mitigate the

ROCO, LTD. (Continued) **S105114396**

potential effects of soil vapor intrusion (SVI). The remedial work plan required monitoring of the SVE system and site groundwater with a re-evaluation of the SVE remedy after the first year of operation. Earlier investigations also included the SVI evaluation of a commercial building north and adjacent to the site. The concentrations of TCE found in the sub-slab soil vapor and indoor air warrant further characterization/monitoring.

Health Problem: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: Not reported
Owner Company: Dale Anderson LLC
Owner Address: c/o P.O. Box 244
Owner Addr2: Not reported
Owner City,St,Zip: Athol Springs, NY 14010
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

ENG CONTROLS:

Name: ROCO, LTD.
Address: 1746 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 57001
HW Code: V00422
Control Code: 15
Control Type: ENG
Date Record Added: 02/28/2011
Date Rec Updated: 03/14/2013
Updated By: DSSZYMAN
Site Description: Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply

ROCO, LTD. (Continued) **S105114396**

store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to

ROCO, LTD. (Continued) **S105114396**

	71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.
Health Problem:	Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-03-02 15:25:00
Record Upd:	2012-10-01 12:24:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Weiss
Owner Company:	ROCO LTD.
Owner Address:	P.O. Box 971
Owner Addr2:	Not reported
Owner City,St,Zip:	New London, CT 03257
Owner Country:	United States of America
Own Op:	1
Sub Type:	05
Owner Name:	Not reported
Owner Company:	Dale Anderson LLC
Owner Address:	210 Sawyer Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Tonawanda, NY 14150
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	B9-0588-01
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2011-02-09 10:16:00
Record Updated:	2011-02-09 10:16:00
Updated By:	dplocey
Crossref ID:	2011001752
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-02-09 10:12:00
Record Updated:	2011-02-09 10:12:00
Updated By:	dplocey
Name:	ROCO, LTD.

ROCO, LTD. (Continued) **S105114396**

Address:	1746 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Site Code:	57001
HW Code:	V00422
Control Code:	22
Control Type:	ENG
Date Record Added:	02/28/2011
Date Rec Updated:	03/14/2013
Updated By:	DSSZYMAN
Site Description:	Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.
Env Problem:	Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination

ROCO, LTD. (Continued) **S105114396**

	was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.
Health Problem:	Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-03-02 15:25:00
Record Upd:	2012-10-01 12:24:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Weiss
Owner Company:	ROCO LTD.
Owner Address:	P.O. Box 971
Owner Addr2:	Not reported
Owner City,St,Zip:	New London, CT 03257
Owner Country:	United States of America
Own Op:	1
Sub Type:	05
Owner Name:	Not reported
Owner Company:	Dale Anderson LLC
Owner Address:	210 Sawyer Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Tonawanda, NY 14150
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported

ROCO, LTD. (Continued) **S105114396**

Crossref ID: B9-0588-01
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-02-09 10:16:00
Record Updated: 2011-02-09 10:16:00
Updated By: dplocey
Crossref ID: 2011001752
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-02-09 10:12:00
Record Updated: 2011-02-09 10:12:00
Updated By: dplocey

INST CONTROL:
Name: ROCO, LTD.
Address: 1746 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 57001
Control Name: Building Use Restriction
HW Code: V00422
Control Code: 26
Control Type: INST
Dt record added: 02/28/2011
Dt rec updated: 03/14/2013
Updated By: DSSZYMAN
Site Code: 57001
Site Description: Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002.

ROCO, LTD. (Continued) **S105114396**

Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-03-02 15:25:00
Record Upd: 2012-10-01 12:24:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Weiss

ROCO, LTD. (Continued) **S105114396**

Owner Company: ROCO LTD.
Owner Address: P.O. Box 971
Owner Addr2: Not reported
Owner City,St,Zip: New London, CT 03257
Owner Country: United States of America
Own Op: 1
Sub Type: 05
Owner Name: Not reported
Owner Company: Dale Anderson LLC
Owner Address: 210 Sawyer Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Tonawanda, NY 14150
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: B9-0588-01
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-02-09 10:16:00
Record Updated: 2011-02-09 10:16:00
Updated By: dplocey
Crossref ID: 2011001752
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-02-09 10:12:00
Record Updated: 2011-02-09 10:12:00
Updated By: dplocey

Name: ROCO, LTD.
Address: 1746 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 57001
Control Name: Deed Restriction
HW Code: V00422
Control Code: A
Control Type: INST
Dt record added: 02/28/2011
Dt rec updated: 03/14/2013
Updated By: DSSZYMAN
Site Code: 57001
Site Description: Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land

ROCO, LTD. (Continued) **S105114396**

Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied

ROCO, LTD. (Continued) **S105114396**

and/or if new construction occurs.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-03-02 15:25:00
Record Upd: 2012-10-01 12:24:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Weiss
Owner Company: ROCO LTD.
Owner Address: P.O. Box 971
Owner Addr2: Not reported
Owner City,St,Zip: New London, CT 03257
Owner Country: United States of America
Own Op: 1
Sub Type: 05
Owner Name: Not reported
Owner Company: Dale Anderson LLC
Owner Address: 210 Sawyer Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Tonawanda, NY 14150
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: B9-0588-01
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-02-09 10:16:00
Record Updated: 2011-02-09 10:16:00
Updated By: dplocey
Crossref ID: 2011001752
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-02-09 10:12:00
Record Updated: 2011-02-09 10:12:00
Updated By: dplocey

Name: ROCO, LTD.
Address: 1746 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 57001
Control Name: Monitoring Plan
HW Code: V00422
Control Code: 31
Control Type: INST
Dt record added: 02/28/2011
Dt rec updated: 03/14/2013
Updated By: DSSZYMAN

ROCO, LTD. (Continued) **S105114396**

Site Code: 57001

Site Description: Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is

ROCO, LTD. (Continued) **S105114396**

	part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.
Health Problem:	Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-03-02 15:25:00
Record Upd:	2012-10-01 12:24:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Weiss
Owner Company:	ROCO LTD.
Owner Address:	P.O. Box 971
Owner Addr2:	Not reported
Owner City,St,Zip:	New London, CT 03257
Owner Country:	United States of America
Own Op:	1
Sub Type:	05
Owner Name:	Not reported
Owner Company:	Dale Anderson LLC
Owner Address:	210 Sawyer Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Tonawanda, NY 14150
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	B9-0588-01
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2011-02-09 10:16:00
Record Updated:	2011-02-09 10:16:00
Updated By:	dplocey
Crossref ID:	2011001752
Cross Ref Type Code:	25

ROCO, LTD. (Continued) **S105114396**

Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-02-09 10:12:00
Record Updated:	2011-02-09 10:12:00
Updated By:	dplocey
Name:	ROCO, LTD.
Address:	1746 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Site Code:	57001
Control Name:	Landuse Restriction
HW Code:	V00422
Control Code:	25
Control Type:	INST
Dt record added:	02/28/2011
Dt rec updated:	03/14/2013
Updated By:	DSSZYMAN
Site Code:	57001
Site Description:	Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.
Env Problem:	Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at

ROCO, LTD. (Continued) **S105114396**

the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-03-02 15:25:00
Record Upd: 2012-10-01 12:24:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Weiss
Owner Company: ROCO LTD.
Owner Address: P.O. Box 971
Owner Addr2: Not reported
Owner City,St,Zip: New London, CT 03257
Owner Country: United States of America
Own Op: 1
Sub Type: 05
Owner Name: Not reported
Owner Company: Dale Anderson LLC

ROCO, LTD. (Continued) **S105114396**

Owner Address: 210 Sawyer Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Tonawanda, NY 14150
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: B9-0588-01
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-02-09 10:16:00
Record Updated: 2011-02-09 10:16:00
Updated By: dplocey
Crossref ID: 2011001752
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-02-09 10:12:00
Record Updated: 2011-02-09 10:12:00
Updated By: dplocey

Name: ROCO, LTD.
Address: 1746 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 57001
Control Name: Site Management Plan
HW Code: V00422
Control Code: 32
Control Type: INST
Dt record added: 02/28/2011
Dt rec updated: 03/14/2013
Updated By: DSSZYMAN
Site Code: 57001
Site Description: Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments

ROCO, LTD. (Continued) **S105114396**

of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.

Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

ROCO, LTD. (Continued) **S105114396**

Dell: Not reported
Record Add: 2011-03-02 15:25:00
Record Upd: 2012-10-01 12:24:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Weiss
Owner Company: ROCO LTD.
Owner Address: P.O. Box 971
Owner Addr2: Not reported
Owner City,St,Zip: New London, CT 03257
Owner Country: United States of America
Own Op: 1
Sub Type: 05
Owner Name: Not reported
Owner Company: Dale Anderson LLC
Owner Address: 210 Sawyer Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Tonawanda, NY 14150
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: B9-0588-01
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-02-09 10:16:00
Record Updated: 2011-02-09 10:16:00
Updated By: dplocey
Crossref ID: 2011001752
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-02-09 10:12:00
Record Updated: 2011-02-09 10:12:00
Updated By: dplocey

Name: ROCO, LTD.
Address: 1746 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 57001
Control Name: Ground Water Use Restriction
HW Code: V00422
Control Code: 08
Control Type: INST
Dt record added: 02/28/2011
Dt rec updated: 03/14/2013
Updated By: DSSZYMAN
Site Code: 57001
Site Description: Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the

ROCO, LTD. (Continued) **S105114396**

south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program.

ROCO, LTD. (Continued) **S105114396**

The VCA was terminated in 2013.
Health Problem: Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2011-03-02 15:25:00
Record Upd: 2012-10-01 12:24:00
Updated By: ldennist
Own Op: 6
Sub Type: 03
Owner Name: William Weiss
Owner Company: ROCO LTD.
Owner Address: P.O. Box 971
Owner Addr2: Not reported
Owner City,St,Zip: New London, CT 03257
Owner Country: United States of America
Own Op: 1
Sub Type: 05
Owner Name: Not reported
Owner Company: Dale Anderson LLC
Owner Address: 210 Sawyer Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Tonawanda, NY 14150
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: B9-0588-01
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2011-02-09 10:16:00
Record Updated: 2011-02-09 10:16:00
Updated By: dplocey
Crossref ID: 2011001752
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2011-02-09 10:12:00
Record Updated: 2011-02-09 10:12:00
Updated By: dplocey

VCP:
Name: ROCO, LTD.
Address: 1746 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225

ROCO, LTD. (Continued) **S105114396**

Program Type:	VCP
Site Code:	57001
HW Code:	V00422
Site Class:	C
SWIS:	1530
Region:	9
Town:	Cheektowaga
Acres:	0.883
Date Record Added:	12/22/2000
Date Record Updated:	03/17/2017
Updated By:	CRSTANIS
Site Description:	Location: The ROCO Ltd. site is located on the corner of Anderson and Dale Roads, in a commercial/industrial area of the Town of Cheektowaga. Site Features: The properties to the east, west and north of the site include a commercial office building, a dairy product processing and distribution center, and an electrical supply store respectively. The Niagara Transformer facility, a class 4 inactive hazardous waste site (site #915146), and the adjacent Niagara Transformer brownfield site (site #C915234) both lie to the south of the site across Dale Road. A cemetery is located to the southwest of the site. The nearest residential property lies approximately 1,000 feet to the southeast of the site. A one-story 33,000 square foot cement block and cement on-grade building occupies most of the site with the exception of an asphalt-covered parking lot in the southeast corner and a few feet of asphalt and gravel-covered ground around the perimeter of the building. Current Zoning and Land Use: The facility is currently vacant and zoned for manufacturing. Until early 2010, the building was being used as a product warehouse by the neighboring dairy product processing company. Past Use of the Site: ROCO Ltd., formerly Rotary Company, Inc., operated a metal and plastic fabricating facility at the site from 1946 to 1994. The operations included metal preparation, finishing and precision sheet metal fabrication including shearing, punching, forming, welding, iron phosphate surface treatment, painting and silk screening, machining and heat treating and polishing. Environmental assessments of the site and adjacent property completed between 1998 and 2000 found that the groundwater and soil were contaminated with chlorinated solvents. The contamination was located primarily in the northwest corner of the facility, beneath the metal preparation room where parts were cleaned. ROCO Ltd. signed a Voluntary Cleanup Agreement in 2001, to complete the site investigation and address the contamination. A Site Investigation report was issued in 2002. Remedial actions taken at the site were documented in a series of Remedial Action Plan reports dated 2007-2009. A deed Restriction was filed in 2011 limiting the site usage to industrial and a Site Management Plan was approved in 2011. Continued monitoring of the groundwater was required and further treatment might be indicated but the owner stopped work. The VCA was terminated in 2013. The property was purchased by Dale Anderson LLC later that year.
Env Problem:	Nature and Extent of Contamination: Prior to Remediation: Based upon investigations done to date the primary contaminants of concern at the site include trichloroethene, cis-1,2-dichloroethene and vinyl chloride. The site investigation indicated a plume of contaminated groundwater mounded beneath the metal preparation room, in the northwest corner of the building, extending to the west beneath a paved parking lot and to the south beneath the building. The groundwater flows to the south but it appeared that the downgradient

ROCO, LTD. (Continued) **S105114396**

edge of the contaminant plume was within the site boundary. A second, smaller and less concentrated hot spot of groundwater contamination was also found on the north side of the building. In-situ treatment (hydrogen release compound) was implemented began in 2005. In-situ treatment was repeated in 2008. One of the site specific remedial objectives was to reduce the groundwater contaminant concentrations to levels compatible with the use of the site. Elevated concentrations of chlorinated solvents have been found in the soil vapor beneath the metal preparation room. The room is not currently used and institutional controls on the use and access to the room is part of the site management plan. Post-Remediation: A 2009 Supplemental Remedial Action Plan Report found the remedial objective had been achieved for the groundwater outside of the metal preparation room area. Concentrations of vinyl chloride in the groundwater beneath the metal preparation room was reduced from 67,400 ppb in June 2009 to 138 ppb in August 2009 but rebounded to 71,600 in March 2010. Monitoring also indicated that the HRC injected had not been fully expended; further injections were not recommended. The volunteer failed to continue the groundwater monitoring program. The VCA was terminated in 2013.

Health Problem:	Direct contact with contaminants in the soil is unlikely because the majority of the site is covered with buildings and pavement. People are not coming into contact with the contaminated groundwater because the area is served by a public water supply that is not affected by the contamination. The potential for soil vapor intrusion to occur on-site will be evaluated should the site building be re-occupied and/or if new construction occurs.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2011-03-02 15:25:00
Record Upd:	2012-10-01 12:24:00
Updated By:	ldennist
Own Op:	6
Sub Type:	03
Owner Name:	William Weiss
Owner Company:	ROCO LTD.
Owner Address:	P.O. Box 971
Owner Addr2:	Not reported
Owner City,St,Zip:	New London, CT 03257
Owner Country:	United States of America
Own Op:	1
Sub Type:	05
Owner Name:	Not reported
Owner Company:	Dale Anderson LLC
Owner Address:	210 Sawyer Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Tonawanda, NY 14150
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported

ROCO, LTD. (Continued) **S105114396**

Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	B9-0588-01
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2011-02-09 10:16:00
Record Updated:	2011-02-09 10:16:00
Updated By:	dplocey
Crossref ID:	2011001752
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2011-02-09 10:12:00
Record Updated:	2011-02-09 10:12:00
Updated By:	dplocey

SPILLS:

Name:	NIAGARA TRANSFORMER
Address:	1746 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0702536 / 2008-02-20
Facility ID:	0702536
Facility Type:	ER
DER Facility ID:	331703
Site ID:	382280
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	1530
Spill Date:	2007-05-31
Investigator:	rjjonak
Referred To:	Not reported
Reported to Dept:	2007-05-31
CID:	444
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-05-31
Spill Record Last Update:	2008-02-20
Spiller Name:	BOB FISHLOCK
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1746 DALE ROAD
Spiller Company:	001
Contact Name:	BOB FISHLOCK
Latitude:	42.9048415
Longitude:	-78.7721967
DEC Memo:	5/31/2007: RJJ TELECON BOB FISHLOCK,NIAGARA TRANSFORMER,HE SAID THAT DUE TO HUMAN ERROR,A FILL CAP WAS LEFT OPEN ON A TANKER,WHICH CAUSED ~3 GAL OF MINERAL OIL TO SPILL OUT ALL INTO THEIR COLLECTION PIT INSIDE THEIR BUILDING...THEY QUICKLY USED ABSORBANTS TO SOAK UP AND CLEAN UP THE SPILL...NONE

ROCO, LTD. (Continued) **S105114396**

Remarks:	OF THE OIL REACHED ANY WATERWAYS...IT WAS ALL CONTAINED AND RECOVERED...THEY PLACED ALL THE MATERIAL INTO THEIR PROFILED DUMPSTER FOR DISPOSAL...MR. FISHLOCK WILL SEND ME THE DISPOSAL RECEIPTS WHEN IT GETS FULL AND DISPOSED OF. 2/20/2008: RECEIVED THE DISPOSAL RECEIPTS FOR THE MATERIAL TAKEN TO VEOLIA ENVIRONMENTAL SOLUTIONS IN OHIO...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. A CAP WAS LEFT OPEN ON A TANKER AND IS CLEANED UP:

All Materials:

Site ID:	382280
Operable Unit ID:	1139683
Operable Unit:	01
Material ID:	2129725
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

NY MANIFEST:

EPA ID:	NYD002104016
Country:	USA
Name:	Diversified Manufacturing
Address:	1746 DALE RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225
Zip 4:	Not reported
Location Address 1:	1746 DALE RD
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Diversified Manufacturing
Mailing Contact:	William M Weiss Vice Pre
Mailing Address 1:	PO BOX 472
Mailing Address 2:	Not reported
Mailing City,State,Zip:	LOCKPORT, NY 14095
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168944425

Manifest Data:

Document ID:	NYB4921056
Manifest Status:	Not reported
Trans1 State ID:	11588P
Year:	1995

ROCO, LTD. (Continued) **S105114396**

Trans2 State ID:	Not reported
Generator Ship Date:	07/07/1995
Trans1 Recv Date:	07/07/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/10/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980681571
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	00.90

Document ID:	NYB4919085
Manifest Status:	Not reported
Trans1 State ID:	PD9796NY
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	03/09/1995
Trans1 Recv Date:	03/09/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980681571
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported

ROCO, LTD. (Continued) **S105114396**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	00.90

Document ID:	ARA6927990
Manifest Status:	Not reported
Trans1 State ID:	PC936H245
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/05/1994
Trans1 Recv Date:	10/05/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/09/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	ARD069748192
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00015
Units:	Pounds

ROCO, LTD. (Continued) **S105114396**

Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ethene, Trichloro- (Or) Trichloroethylene
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00015
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Corrosive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00015
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYA6463692
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	NY67940GN
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	870311
Trans1 Recv Date:	870311
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870311
Part A Recv Date:	870408
Part B Recv Date:	870318
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	NYD038641601
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD038641601
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported

ROCO, LTD. (Continued) **S105114396**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	INA1139612
Manifest Status:	Not reported
Trans1 State ID:	61521SNY
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	08/20/1997
Trans1 Recv Date:	08/20/1997
Trans2 Recv Date:	08/21/1997
TSD Site Recv Date:	08/23/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	IND058484114
TSDF ID 1:	IND093219012
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00275
Units:	Gallons (liquids only)
Number of Containers:	005
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Corrosive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00275

ROCO, LTD. (Continued) **S105114396**

Units:	Gallons (liquids only)
Number of Containers:	005
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	INA1139621
Manifest Status:	Not reported
Trans1 State ID:	615215NY
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	06/06/1997
Trans1 Recv Date:	06/06/1997
Trans2 Recv Date:	06/10/1997
TSD Site Recv Date:	06/12/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	IND058484114
TSDF ID 1:	IND093219012
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl

ROCO, LTD. (Continued) **S105114396**

	Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00250
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Ignitable Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	INA1139627
Manifest Status:	Not reported
Trans1 State ID:	615215NY
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/1997
Trans1 Recv Date:	10/23/1997

ROCO, LTD. (Continued) **S105114396**

Trans2 Recv Date:	10/28/1997
TSD Site Recv Date:	11/01/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	NYD051809952
Trans2 EPA ID:	IND058484114
TSDF ID 1:	IND093219012
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00875
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00110

ROCO, LTD. (Continued) **S105114396**

Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	INA1064185
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	11/06/1996
Trans1 Recv Date:	11/06/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/15/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	IND058484114
Trans2 EPA ID:	Not reported
TSDF ID 1:	IND093219012
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends

ROCO, LTD. (Continued) **S105114396**

	Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00050
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00090
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00300
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	INA1083933

ROCO, LTD. (Continued) **S105114396**

Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	01/16/1996
Trans1 Recv Date:	01/16/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/28/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	IND058484114
Trans2 EPA ID:	Not reported
TSDF ID 1:	IND093219012
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported

ROCO, LTD. (Continued) **S105114396**

Waste Code 10: Not reported
Waste Code 11: Not reported
Quantity: 00055
Units: Pounds
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYB6752808
Manifest Status: Not reported
Trans1 State ID: NYPD1946
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 12/09/1994
Trans1 Recv Date: 12/09/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/12/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD002104016
Trans1 EPA ID: NYD980769947
Trans2 EPA ID: Not reported
TSDF ID 1: OHD980681571
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00055
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 00.90

Document ID: NYB4157523
Manifest Status: Not reported
Trans1 State ID: T607AE
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 01/13/1994
Trans1 Recv Date: 01/13/1994

ROCO, LTD. (Continued) **S105114396**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/24/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002104016
Trans1 EPA ID:	OHD982061350
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980681571
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	00.90

Click this hyperlink while viewing on your computer to access
35 additional NY MANIFEST: record(s) in the EDR Site Report.

A4 **ROTARY CO INC** **SEMS-ARCHIVE** **1000156599**
South **1746 DALE RD** **RCRA NonGen / NLR** **NYD002104016**
< 1/8 **BUFFALO, NY 14225** **FINDS**
0.006 mi. **ECHO**
33 ft. **Site 4 of 8 in cluster A**

Relative:
Higher

Actual:
656 ft.

SEMS Archive:

Site ID:	0201378
EPA ID:	NYD002104016
Name:	ROTARY CO INC
Address:	1746 DALE RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225
Cong District:	38
FIPS Code:	36029
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

ROTARY CO INC (Continued) **1000156599**

Region:	02
Site ID:	0201378
EPA ID:	NYD002104016
Site Name:	ROTARY CO INC
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-04-25 05:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201378
EPA ID:	NYD002104016
Site Name:	ROTARY CO INC
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1981-04-01 05:00:00
Finish Date:	1981-04-01 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0201378
EPA ID:	NYD002104016
Site Name:	ROTARY CO INC
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1986-04-25 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Diversified Mfg Inc
Handler Address:	Dale Rd
Handler City,State,Zip:	BUFFALO, NY 14225
EPA ID:	NYD002104016
Contact Name:	BRENT NICHOLSON
Contact Address:	OHIO ST
Contact City,State,Zip:	LOCKPORT, NY 14094
Contact Telephone:	716-434-5585
Contact Fax:	Not reported

ROTARY CO INC (Continued) **1000156599**

Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		County
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		OHIO ST
Mailing City,State,Zip:		LOCKPORT, NY 14094
Owner Name:	Diversified Mfg Inc	
Owner Type:		County
Operator Name:	Diversified Mfg Inc	
Operator Type:		County
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

ROTARY CO INC (Continued) **1000156599**

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F009
Waste Description:	Spent Stripping And Cleaning Bath Solutions From Electroplating Operations In Which Cyanides Are Used In The Process.
Waste Code:	F017
Waste Description:	Not Defined
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: DIVERSIFIED MFG INC	
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 472
Owner/Operator City,State,Zip:	LOCKPORT, NY 14095
Owner/Operator Telephone:	716-434-5585

ROTARY CO INC (Continued) **1000156599**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DIVERSIFIED MFG INC
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 472
Owner/Operator City,State,Zip: LOCKPORT, NY 14095
Owner/Operator Telephone: 716-434-5585
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DIVERSIFIED MFG INC
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 472
Owner/Operator City,State,Zip: LOCKPORT, NY 14095
Owner/Operator Telephone: 716-434-5585
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19941003
Handler Name: DIVERSIFIED MFG INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DIVERSIFIED MFG INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DIVERSIFIED MFG INC

ROTARY CO INC (Continued) **1000156599**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19990315
Handler Name:	DIVERSIFIED MFG INC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980130
Handler Name:	THE ROTARY COMPANY, INC.
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	332313
NAICS Description:	Plate Work Manufacturing

NAICS Code:	332322
NAICS Description:	Sheet Metal Work Manufacturing

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported

ROTARY CO INC (Continued) **1000156599**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19990920
Actual Return to Compliance Date: 19990921
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19991021
Enforcement Identifier: 000
Date of Enforcement Action: 19990921
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYNSL
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

ROTARY CO INC (Continued) **1000156599**

SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19961119
Actual Return to Compliance Date: 19961218
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19961219
Enforcement Identifier: 000
Date of Enforcement Action: 19961119
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYRFR
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 19961119
Actual Return to Compliance Date: 19961218
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19961219
Enforcement Identifier: 000
Date of Enforcement Action: 19961119
Enforcement Responsible Agency: State

ROTARY CO INC (Continued) **1000156599**

Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYRFR
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

ROTARY CO INC (Continued) **1000156599**

SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20010731
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRFR
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19990920
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYNSL
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	19990921
Scheduled Compliance Date:	19991021
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19961112
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRFR
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	19961218
Scheduled Compliance Date:	19961219
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19961112
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRFR
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	19961218
Scheduled Compliance Date:	19961219
Date of Request:	Not reported

ROTARY CO INC (Continued) **1000156599**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19930421
Evaluation Responsible Agency:	EPA Contractor/Grantee
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2TRC
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110009464855

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000156599
Registry ID:	110009464855

DFR URL:

Name:	DIVERSIFIED MFG.
Address:	1746 Dale Rd
City,State,Zip:	BUFFALO, NY 14225

B5 **ACTS TESTING LABS INC** **RCRA NonGen / NLR** **1000871603**
East **25 ANDERSON RD** **FINDS** **NY0000075648**
< 1/8 **BUFFALO, NY 14225** **ECHO**
0.021 mi. **NY MANIFEST**
113 ft. **Site 1 of 4 in cluster B**

Relative:
Lower

Actual:
655 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Acts Testing Labs Inc
Handler Address:	Anderson Rd
Handler City,State,Zip:	BUFFALO, NY 14225-4928

ACTS TESTING LABS INC (Continued) **1000871603**

EPA ID:		NY0000075648
Contact Name:		PAMELA POLNIAK
Contact Address:		ANDERSON RD
Contact City,State,Zip:		BUFFALO, NY 14225-4928
Contact Telephone:		716-897-3300
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		ANDERSON RD
Mailing City,State,Zip:		BUFFALO, NY 14225-4928
Owner Name:	Anderson Road Properties	
Owner Type:		Private
Operator Name:	Anderson Road Properties	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No

ACTS TESTING LABS INC (Continued) **1000871603**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ANDERSON ROAD PROPERTIES
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2401 FOREST RD PO BOX 823
Owner/Operator City,State,Zip:	AMHERST, NY 14226-0823

ACTS TESTING LABS INC (Continued) **1000871603**

Owner/Operator Telephone: 716-636-7500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANDERSON ROAD PROPERTIES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2401 FOREST RD PO BOX 823
Owner/Operator City,State,Zip: AMHERST, NY 14226-0823
Owner/Operator Telephone: 716-636-7500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANDERSON ROAD PROPERTIES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2401 FOREST RD PO BOX 823
Owner/Operator City,State,Zip: AMHERST, NY 14226-0823
Owner/Operator Telephone: 716-636-7500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: ACTS TESTING LABS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ACTS TESTING LABS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19931201

ACTS TESTING LABS INC (Continued) **1000871603**

Handler Name: ACTS TESTING LABS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: ACTS TESTING LABS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 54138
NAICS Description: Testing Laboratories And Services

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

ACTS TESTING LABS INC (Continued) **1000871603**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19990909
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTCT
Evaluation Responsible Sub-Organization:	R9

ACTS TESTING LABS INC (Continued) **1000871603**

Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19950922
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYNSL
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004310237

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000871603
Registry ID:	110004310237
DFR URL:	
Name:	ACTS TESTING LABS INC
Address:	25 Anderson Rd
City,State,Zip:	BUFFALO, NY 14225

NY MANIFEST:

EPA ID:	NY0000075648
Country:	USA
Name:	Acts Testing Labs Inc
Address:	25 ANDERSON RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225-4928
Zip 4:	Not reported
Location Address 1:	25 ANDERSON ST
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14227

ACTS TESTING LABS INC (Continued) **1000871603**

Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Acts Testing Labs Inc
Mailing Contact: Pam Polniak
Mailing Address 1: 25 ANDERSON ST
Mailing Address 2: Not reported
Mailing City,State,Zip: BUFFALO, NY 14227
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7168973300

Manifest Data:
Document ID: VTA0061051
Manifest Status: Not reported
Trans1 State ID: PP8404NY
Year: 1995
Trans2 State ID: Not reported
Generator Ship Date: 05/02/1995
Trans1 Recv Date: 05/02/1995
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/04/1995
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NY0000075648
Trans1 EPA ID: NYD986903904
Trans2 EPA ID: Not reported
TSDF ID 1: VTD982766537
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Arsenic
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00001
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Treat
Specific Gravity: 01.00
Waste Code 7: Mercury

ACTS TESTING LABS INC (Continued) **1000871603**

Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	VTA0050451
Manifest Status:	Not reported
Trans1 State ID:	JS3984NY
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/1994
Trans1 Recv Date:	04/19/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/20/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	Not reported
TSDF ID 1:	VTD982766537
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Phenol
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00001

ACTS TESTING LABS INC (Continued) **1000871603**

Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 12:	Mercury
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00001
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 17:	Corrosive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00001
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	VTA0050453
Manifest Status:	Not reported
Trans1 State ID:	JS3984NY
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/1994
Trans1 Recv Date:	04/19/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/19/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	Not reported
TSDF ID 1:	VTD982766537
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl

ACTS TESTING LABS INC (Continued) **1000871603**

Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00002
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Barium
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00002
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	VTA0050454
Manifest Status:	Not reported
Trans1 State ID:	JS3984NY
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/1994
Trans1 Recv Date:	04/19/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/20/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	Not reported
TSDF ID 1:	VTD982766537
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

ACTS TESTING LABS INC (Continued) **1000871603**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Pyridine
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Methane, Dichloro- (Or) Methylene Chloride
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00003
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00001
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	VTA0050470
Manifest Status:	Not reported
Trans1 State ID:	PP8404NY
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/1994
Trans1 Recv Date:	08/29/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/30/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	Not reported
TSDF ID 1:	VTD982766537
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

ACTS TESTING LABS INC (Continued) **1000871603**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00004
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00001
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 12:	Corrosive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00001
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYB4689729
Manifest Status:	Not reported
Trans1 State ID:	86044DNY
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/1994
Trans1 Recv Date:	05/10/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/20/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD986903904

ACTS TESTING LABS INC (Continued) **1000871603**

Trans2 EPA ID:	Not reported
TSDF ID 1:	GAD093380814
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB4890744
Manifest Status:	Not reported
Trans1 State ID:	PP8404NY
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	05/12/1995
Trans1 Recv Date:	05/12/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/30/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	Not reported
TSDF ID 1:	GAD093380814
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported

ACTS TESTING LABS INC (Continued) **1000871603**

Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG0564327
Manifest Status:	Not reported
Trans1 State ID:	T3K757NJ
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	12/22/1998
Trans1 Recv Date:	12/22/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/28/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NJD054126164
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980681571
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl

ACTS TESTING LABS INC (Continued) **1000871603**

	Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00060
Units:	Gallons (liquids only)
Number of Containers:	012
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn

ACTS TESTING LABS INC (Continued) **1000871603**

Specific Gravity:	01.00
Waste Code 17:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB8492436
Manifest Status:	Not reported
Trans1 State ID:	NY14236P
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	01/15/1998
Trans1 Recv Date:	01/15/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/16/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980681571
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent

ACTS TESTING LABS INC (Continued) **1000871603**

	Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG1111419
Manifest Status:	Not reported
Trans1 State ID:	11279PNY
Year:	1999
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/1999
Trans1 Recv Date:	01/29/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/01/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980681571
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

ACTS TESTING LABS INC (Continued) **1000871603**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	VTA0060163
Manifest Status:	Not reported
Trans1 State ID:	NY71596E
Year:	1996
Trans2 State ID:	NYPP8404
Generator Ship Date:	07/22/1996
Trans1 Recv Date:	07/22/1996
Trans2 Recv Date:	07/22/1996
TSD Site Recv Date:	07/24/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000075648
Trans1 EPA ID:	NYD986903904
Trans2 EPA ID:	NYD986903904
TSDF ID 1:	VTD982766537
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Pyridine
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00001
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Naphthalene

ACTS TESTING LABS INC (Continued) **1000871603**

Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00001
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00001
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 17:	Arsenic Oxide As2o3 (Or) Arsenic Trioxide
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00001
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
23 additional NY MANIFEST: record(s) in the EDR Site Report.

B6 **UPSTATE FARMS COOPERATIVE INC** **RCRA NonGen / NLR** **1004762135**
East **25 ANDERSON RD** **FINDS** **NYR000093880**
< 1/8 **CHEEKTOWAGA, NY 14225** **ECHO**
0.021 mi.
113 ft. **Site 2 of 4 in cluster B**

Relative:
Lower

Actual:
655 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Upstate Farms Cooperative Inc
Handler Address:	Anderson Rd
Handler City,State,Zip:	CHEEKTOWAGA, NY 14225
EPA ID:	NYR000093880
Contact Name:	TIMOTHY HARNER
Contact Address:	W MAIN ST
Contact City,State,Zip:	LEROY, NY 14482
Contact Telephone:	716-768-2247
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private

UPSTATE FARMS COOPERATIVE INC (Continued) **1004762135**

Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		W MAIN ST
Mailing City,State,Zip:		LEROY, NY 14482
Owner Name:	Upstate Farms Cooperative Inc	
Owner Type:		Private
Operator Name:	Upstate Farms Cooperative Inc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D000

UPSTATE FARMS COOPERATIVE INC (Continued) **1004762135**

Waste Description: Not Defined

Waste Code: D040
Waste Description: Trichloroethylene

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: UPSTATE FARMS COOPERATIVE INC
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 7115 W MAIN ST
Owner/Operator City,State,Zip: LEROY, NY 14482
Owner/Operator Telephone: 716-768-2247
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UPSTATE FARMS COOPERATIVE INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 7115 W MAIN ST
Owner/Operator City,State,Zip: LEROY, NY 14482
Owner/Operator Telephone: 716-768-2247
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UPSTATE FARMS COOPERATIVE INC
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 7115 W MAIN ST
Owner/Operator City,State,Zip: LEROY, NY 14482
Owner/Operator Telephone: 716-768-2247
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: UPSTATE FARMS COOPERATIVE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

UPSTATE FARMS COOPERATIVE INC (Continued) **1004762135**

Receive Date: 20070101
Handler Name: UPSTATE FARMS COOPERATIVE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010205
Handler Name: UPSTATE FARMS COOPERATIVE INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004566997

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004762135
Registry ID: 110004566997

UPSTATE FARMS COOPERATIVE INC (Continued) **1004762135**

DFR URL:
Name: UPSTATE FARMS COOPERATIVE INC
Address: 25 Anderson Rd
City,State,Zip: CHEEKTOWAGA, NY 14225

B7 **BUILDING ADDITION EXCAVATION** **NY Spills** **S111011907**
East **25 ANDERSON ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY**
0.021 mi.
113 ft. **Site 3 of 4 in cluster B**

Relative: **Lower**

Actual: **655 ft.**

SPILLS:

Name:	BUILDING ADDITION EXCAVATION
Address:	25 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	1101569 / 2011-08-17
Facility ID:	1101569
Facility Type:	ER
DER Facility ID:	403636
Site ID:	449029
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1530
Spill Date:	2011-05-11
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2011-05-11
CID:	Not reported
Water Affected:	NONE
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2011-05-11
Spill Record Last Update:	2011-08-17
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	PAT LEAD
Latitude:	42.9048714
Longitude:	-78.7710368
DEC Memo:	5/12/2011: RJJ AT SITE AT 1000...WHILE EXCAVATING FOR A NEW ADDITION ON THEIR EXISTING BUILDING,UPSTATE NIAGARA HAS ENCOUNTERED PETROLEUM CONTAMINATION IN THE TRENCH...THEY HAVE HIRED HAZARD EVALUATIONS TO ADDRESS THIS ISSUE...PETE BOJCZUK,HAZARD EVALUATIONS,WILL DRAFT A WORKPLAN TO REMEDIATE,THEN I WILL REVIEW IT...FOR NOW,ALL WORK HAS STOPPED UNTIL THIS CAN BE RESOLVED...PETE WILL KEEP ME INFORMED. 5/17/2011: RJJ AT SITE AT 1330...HAZARD EVALUATIONS HAS FINISHED EXCAVATING

BUILDING ADDITION EXCAVATION (Continued) **S111011907**

THE CONTAMINATED SOIL ON SITE...THEY REMOVED ~150 TONS OF PETROLEUM CONTAMINATED SOIL FROM 3
DIFFERENT EXCAVATIONS...THE LARGEST(~30X20'X4')IS WHERE THE NEW ADDITION WILL BE,ADJACENT TO THE
EXISTING BUILDING,IS THE ONLY EXCAVATION THAT STILL HAS A SMALL AMOUNT OF STAINED SOIL REMAINING
WHICH IS RIGHT UP TO THE BUILDING...THE 2 OTHER SMALL EXCAVATIONS APPEAR TO HAVE ONLY AN ORGANIC
LAYER AND NO ODORS OF ANY KIND...HAZARD OBTAINED ALL THE CONFIRMATORY SOIL SAMPLES,PER MY
INSTRUCTIONS,AND WILL SEND ME THEIR REPORT. 8/15/2011: RECEIVED THE FINAL REPORT FROM HAZARD
EVALUATIONS,WHICH INCLUDES THE CONFIRMATORY SOIL SAMPLE RESULTS FROM THE EXCAVATION(ALL THE RESULTS
ARE ALL BELOW OUR CP-51 GUIDANCE VALUES,HOWEVER,SOME STAINED SOIL STILL REMAINS UP TO THE
BUILDING)...ALSO,THEY TRANSPORTED 210 TONS OF PETROLEUM IMPACED SOIL TO NOCO'S BIO-REMEDIATION
TERMINAL(TONAWANDA TERMINAL,RECEIPTS INCLUDED)...I WILL DISCUSS THIS WITH SAC. 8/17/2011: AFTER
REVIEWING SPILL REPORT,SAC SAID THAT WE CAN MAKE THIS SITE 'INACTIVE'...DRAFTED & SENT AN
'INACTIVE' LETTER TO PROPERTY OWNER...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.

Remarks: COMPANY IS CONSTRUCTING AN ADDITION TO THEIR BUILDING AND DURING THE DIGGING OF THE FOOTER TRENCHES THAT ENCOUNTERED A PETROLEUM SMELLING MATERIAL APPROX. 4 BGS. HAZARD EVAL ON SITE AND RECORDED A 257 PPM ON THE PID AND ALSO NOTED IT SMELLED LIKE PETROLEUM. CONSTRUCTION WORK AND STOPPED AND THEY WANT TO DELIENATE ANDREMOVE THE CONTAMINATED SOIL NEXT WEEK.

All Materials:

Site ID:	449029
Operable Unit ID:	1199252
Operable Unit:	01
Material ID:	2195609
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

8
SW
< 1/8
0.024 mi.
125 ft.

NIAGARA TRANSFORMER **NY Spills** **S104953776**
DALE ROAD **N/A**
CHEEKTOWAGA, NY

Relative: Higher

Actual: 657 ft.

SPILLS:

Name:	NIAGARA TRANSFORMER
Address:	DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0075690 / 2001-07-09
Facility ID:	0075690

NIAGARA TRANSFORMER (Continued) **S104953776**

Facility Type:	ER
DER Facility ID:	95983
Site ID:	247668
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1530
Spill Date:	2001-03-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2001-03-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-29
Spill Record Last Update:	2001-07-30
Spiller Name:	FRED DARBY
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	PO BOX 233
Spiller Company:	001
Contact Name:	FRED DARBY
Latitude:	42.9047820
Longitude:	-78.7731220
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 03/29/01 RMC/JOHN DARBY/PHONE. DID HAVE SPILL OF 150 GALLONS INSIDE, WAS CLEANED UP IMMEDIATELY, DID NOT KNOW SPILL HAD TO BE REPORTED, RMC ADVISED THAT ANY AMOUNT OVER 5 GALLONS REQUIRES REPORTING, AND THAT AMOUNTS UNDER 5 GALLONS MUST BE REPORTED IF NOT IMMEDIATELY CLEANED UP FROM A HARD SURFACE. RMC TO FAX REQUIRMENTS. 06/12/01 RMC/FILE. NO DISPOSAL RECEIPTS YET, RMC CONTACTED JOHN DARBY, HE HAS DISPOSED OF THE MATERIALS GENERATED AND WILL FAX DISPOSAL RECEIPTS, DUE 6/30/01 07/09/01 RMC/FILE. RECEIVED DISPOSAL RECEIPTS, OK, CLOSE OUT
Remarks:	EMPLOYEE MENTIONED 400 GALLON MINERAL OIL SPILL LAST WEEK BUT IT HAS NOT BEEN REPORTED.

All Materials:

Site ID:	247668
Operable Unit ID:	838556
Operable Unit:	01
Material ID:	539272
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	150.00

NIAGARA TRANSFORMER (Continued) **S104953776**

Oxygenate: Not reported

A9 **SECO CORP** **NJ MANIFEST** **S108793956**
North **40 ANDERSON RD** **N/A**
< 1/8 **BUFFALO, NY 14225**
0.024 mi.
128 ft. **Site 5 of 8 in cluster A**

Relative: **Lower**

Actual: **655 ft.**

NJ MANIFEST:

EPA ID:	NYD056136526
Name:	SECO CORP
Address:	40 ANDERSON RD
City,State,Zip:	BUFFALO, NY 14225
County:	Not reported
Mailing Address:	40 ANDERSON RD
Mailing City,State,Zip:	BUFFALO 14225
Telephone:	7168930455
Emergency Telephone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPAID:	Not reported
Generator Flag:	X
Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	000000

Manifest Data:

EPA ID:	NYD056136526
Manifest Number:	000256131SKS
Date Shipped:	08/23/2007
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	NJD071629976
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/23/2007
Date Trans2 Transported Waste:	09/04/2007
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/04/2007
TSDF EPA Facility Name:	Not reported

SECO CORP (Continued) **S108793956**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H14
Quantity:	200
Unit:	P

A10 **DIMAR MANUFACTURING** **RCRA-SQG** **1015747219**
North **40 ANDERSON RD** **E MANIFEST** **NYR000196881**
< 1/8 **CHEEKTOWAGA, NY 14225** **NY MANIFEST**
0.024 mi.
128 ft. **Site 6 of 8 in cluster A**

Relative: **Lower**

Actual: **655 ft.**

RCRA Listings:

Date Form Received by Agency:	20120913
Handler Name:	Dimar Manufacturing
Handler Address:	Anderson Rd
Handler City,State,Zip:	CHEEKTOWAGA, NY 14225
EPA ID:	NYR000196881
Contact Name:	JASON LOCK
Contact Address:	ANDERSON RD
Contact City,State,Zip:	CHEEKTOWAGA, NY 14225
Contact Telephone:	716-240-9315
Contact Fax:	716-240-9879
Contact Email:	JLOCK@DIMARMFG.COM
Contact Title:	PLANT MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R9
Mailing Address:	ANDERSON RD
Mailing City,State,Zip:	CHEEKTOWAGA, NY 14225
Owner Name:	Peter L Krog & Fred J Hanana
Owner Type:	Private
Operator Name:	Dimar Manufacturing
Operator Type:	Private

DIMAR MANUFACTURING (Continued) **1015747219**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

DIMAR MANUFACTURING (Continued) **1015747219**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: DIMAR MANUFACTURING	
Legal Status:	Private
Date Became Current:	20120515
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PETER L KROG & FRED J HANANA	
Legal Status:	Private
Date Became Current:	19980401
Date Ended Current:	Not reported
Owner/Operator Address:	4 CENTRE DR
Owner/Operator City,State,Zip:	ORCHARD PARK, NY 14127
Owner/Operator Telephone:	716-667-1234
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20120913
Handler Name: DIMAR MANUFACTURING	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	332322
NAICS Description:	Sheet Metal Work Manufacturing

NAICS Code:	332999
NAICS Description:	All Other Miscellaneous Fabricated Metal Product Manufacturing

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20221027
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYBRI
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130531
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTRN
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

E MANIFEST:

Manifest Tracking Number:	018976158FLE
Last Updated Date:	20250109
Shipped Date:	20241203
Received Date:	20241211
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	40
Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	40

DIMAR MANUFACTURING (Continued) **1015747219**

Generator Mail Street 1:	ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 OLD DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 OLD DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012359496FLE
Last Updated Date:	20230309
Shipped Date:	20230202
Received Date:	20230208
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	40
Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	40
Generator Mail Street 1:	ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 OLD DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 OLD DENISON AVE
Designated Facility Location Street 2:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012366711FLE
Last Updated Date:	20210730
Shipped Date:	20210701
Received Date:	20210707
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	40
Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	40
Generator Mail Street 1:	ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 OLD DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 OLD DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012367025FLE
Last Updated Date:	20240604
Shipped Date:	20211108
Received Date:	20211117
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	40

DIMAR MANUFACTURING (Continued) **1015747219**

Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	40
Generator Mail Street 1:	ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 OLD DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 OLD DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012367512FLE
Last Updated Date:	20200212
Shipped Date:	20181218
Received Date:	20190102
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	40
Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	40
Generator Mail Street 1:	ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 DENISON AVE

DIMAR MANUFACTURING (Continued) **1015747219**

Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012369833FLE
Last Updated Date:	20191126
Shipped Date:	20190521
Received Date:	20190529
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	Not reported
Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	40 ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	010452019FLE
Last Updated Date:	20220316
Shipped Date:	20220214
Received Date:	20220216

DIMAR MANUFACTURING (Continued) **1015747219**

Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	40
Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	40
Generator Mail Street 1:	ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 OLD DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 OLD DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	010453420FLE
Last Updated Date:	20230422
Shipped Date:	20230404
Received Date:	20230405
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000196881
Generator Name:	Dimar Manufacturing
Generator Location Street Number:	40
Generator Location Street 1:	40 ANDERSON RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	40
Generator Mail Street 1:	ANDERSON RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY

DIMAR MANUFACTURING (Continued) **1015747219**

Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 OLD DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 OLD DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	010453420FLE
Transporter Line Number:	1
Transporter EPA ID:	NYD986903904
Transporter Name:	Environmental Service Group Ny Inc The

Waste Line:

Manifest Tracking Number:	010453420FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1993
U.S. DOT Description:	Un1993, Waste Flammable Liquids N.O.S., (Petroleum Distillates), 3, Ii Erg#128 (Csi #042862)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	55
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.2293578
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2293578
Waste Quantity, in Kilograms:	208.03441
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	208.03441
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D007, D008
Quantity Haz Kg:	208.03441
Quantity Haz Tons:	0.2293578
Quantity Non Haz Kg:	Not reported
Quantity Non Haz Tons:	Not reported
State Waste Codes:	Not reported

NY MANIFEST:

EPA ID:	NYR000196881
Country:	USA
Name:	Dimar Manufacturing
Address:	40 ANDERSON RD
Address 2:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14225
Zip 4:	Not reported
Location Address 1:	40 ANDERSON RD
Location Address 2:	Not reported
Location City,State,Zip:	CHEEKTOWAGA, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Dimar Manufacturing
Mailing Contact:	Dimar Manufacturing
Mailing Address 1:	40 ANDERSON RD
Mailing Address 2:	Not reported
Mailing City,State,Zip:	CHEEKTOWAGA, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/27/2018
Trans1 Recv Date:	04/27/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/02/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	008903200FLE
Import Indicator:	N

DIMAR MANUFACTURING (Continued) **1015747219**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/17/2017
Trans1 Recv Date:	10/17/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/26/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	008907875FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	110
Units:	Gallons (liquids only)
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/2016
Trans1 Recv Date:	04/15/2016
Trans2 Recv Date:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

TSD Site Recv Date:	04/20/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	007173006FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904

DIMAR MANUFACTURING (Continued) **1015747219**

Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	04/15/2016
Trans1 Recv Date:	04/15/2016
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/20/2016
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	007173006FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Chromium
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Corrosive Waste
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	NYD986903904
Generator Ship Date:	04/11/2013
Trans1 Recv Date:	04/11/2013
Trans2 Recv Date:	04/16/2013
TSD Site Recv Date:	04/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	006024785FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Chromium
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Lead
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	110
Units:	Gallons (liquids only)
Number of Containers:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	NYD986903904
Generator Ship Date:	04/11/2013
Trans1 Recv Date:	04/11/2013
Trans2 Recv Date:	04/16/2013
TSD Site Recv Date:	04/25/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	006024785FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

DIMAR MANUFACTURING (Continued) **1015747219**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/2012
Trans1 Recv Date:	10/12/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	005168199FLE
Import Indicator:	N

DIMAR MANUFACTURING (Continued) **1015747219**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/15/2017
Trans1 Recv Date:	05/15/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/17/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	008907574FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	2200
Units:	Pounds
Number of Containers:	4
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	09/20/2013
Trans1 Recv Date:	09/20/2013
Trans2 Recv Date:	Not reported

DIMAR MANUFACTURING (Continued) **1015747219**

TSD Site Recv Date:	10/02/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	006025025FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904

DIMAR MANUFACTURING (Continued) **1015747219**

Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/2014
Trans1 Recv Date:	05/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	006690573FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Not reported
Waste Code e:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn

DIMAR MANUFACTURING (Continued) **1015747219**

Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD986903904
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/2014
Trans1 Recv Date:	05/07/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000196881
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980897656
TSDF ID 2:	Not reported
Manifest Tracking Number:	006690573FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Chromium
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Lead
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
5 additional NY MANIFEST: record(s) in the EDR Site Report.

A11
North
< 1/8
0.024 mi.
128 ft.

DIMAR MANUFACTURING
40 ANDERSON RD
CHEEKTOWAGA, NY 14225

Site 7 of 8 in cluster A

PFAS ECHO **1027351882**
N/A

Relative:
Lower

Actual:
655 ft.

PFAS ECHO:

Facility ID:	110046536584
Name:	Dimar Manufacturing
Address:	40 ANDERSON RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Latitude:	42.9057
Longitude:	-78.77157
Count:	1
County:	ERIE
Status:	Active
Region:	02
Industry:	Metal Machinery Mfg

ECHO Facility Report:

Facility Percent Minority:	38.2
Facility Derived Tribes:	Tuscarora Nation - 18 mile(s), Tonawanda Band of Seneca - 18 mile(s)
Facility Population:	3851.47
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	36029
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	04120103
Facility Derived WBD:	041201040601
Facility Derived CD113:	26
Facility Derived CB2010:	360290107001026
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	1
Facility Date Last Inspection:	10/27/2022
Facility Days Last Inspection:	968
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	0
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-

DIMAR MANUFACTURING (Continued) **1027351882**

CAA SICS:	-
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	NYR000196881
RCRA Permit Types:	SQG
RCRA NAICS:	332999 332322
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-

A12 **SECO CORP** **RCRA NonGen / NLR** **1000324744**
North **40 ANDERSON ROAD** **RAATS** **NYD056136526**
< 1/8 **BUFFALO, NY 14225** **FINDS**
0.024 mi. **ECHO**
128 ft. **Site 8 of 8 in cluster A** **NY MANIFEST**

Relative: **Lower**
Actual: **655 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Seco Corp
Handler Address:		Anderson Rd
Handler City,State,Zip:		BUFFALO, NY 14225
EPA ID:		NYD056136526
Contact Name:		PAUL DIONNE
Contact Address:		PO BOX 208
Contact City,State,Zip:		BUFFALO, NY 14225
Contact Telephone:		716-893-0455
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		PO BOX 208
Mailing City,State,Zip:		BUFFALO, NY 14225
Owner Name:	Process Technology Group	
Owner Type:		Private
Operator Name:	Process Technology Group	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No

SECO CORP (Continued) **1000324744**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PROCESS TECHNOLOGY GROUP

SECO CORP (Continued) **1000324744**

Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PROCESS TECHNOLOGY GROUP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PROCESS TECHNOLOGY GROUP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SECO CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SECO CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

SECO CORP (Continued) **1000324744**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870526
Handler Name: SECO CORP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

SECO CORP (Continued) **1000324744**

Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19931101
Actual Return to Compliance Date:	19950210
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	19940105
Enforcement Identifier:	000
Date of Enforcement Action:	19931203
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	R2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported

SECO CORP (Continued) **1000324744**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2MD
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20001003
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYTCT
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19950210
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYNSL
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19921001
Evaluation Responsible Agency: EPA Contractor/Grantee
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: R2TRC
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 19950210
Scheduled Compliance Date: 19940105

SECO CORP (Continued) **1000324744**

Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

RAATS:

Entry No: 1
Facility ID: NYD056136526
Type: Not reported
Docket No: Not reported
Region: 02
Issue Date: 12/03/1993
Final Date: Not reported
Status: Notice of Violation
Additional: Not reported
Action ID: 000003724
Action: Notice of Violation
Violation No: Not reported
Viol No Cited: 1 262.34(D)
Total No Cited: Not reported
Reg Type: CFR
Prop. Penalty: .00
Final Penalty: .00
Total Prop. Penalty: .00
Comments: Not reported

Entry No: 1
Facility ID: NYD056136526
Type: Not reported
Docket No: Not reported
Region: 02
Issue Date: 12/03/1993
Final Date: Not reported
Status: Notice of Violation
Additional: Not reported
Action ID: 000003724
Action: Notice of Violation
Violation No: Not reported
Viol No Cited: 2 NYCRR 372.2(A)(8)(III)
Total No Cited: Not reported
Reg Type: CFR
Prop. Penalty: .00
Final Penalty: .00
Total Prop. Penalty: .00
Comments: Not reported

FINDS:

Registry ID: 110004360389

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.

SECO CORP (Continued) **1000324744**

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000324744
Registry ID:	110004360389
DFR URL:	
Name:	SECO CORPORATION
Address:	40 Anderson Road
City,State,Zip:	BUFFALO, NY 14225

NY MANIFEST:

EPA ID:	NYD056136526
Country:	USA
Name:	Five Star Industries
Address:	40 ANDERSON RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225
Zip 4:	Not reported
Location Address 1:	40 ANDERSON ROAD
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Five Star Industries
Mailing Contact:	Seco Corporation
Mailing Address 1:	40 ANDERSON ROAD
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168930455

Manifest Data:

Document ID:	NYC3141336
Manifest Status:	Not reported
Trans1 State ID:	NYRW9920
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	07/20/1994
Trans1 Recv Date:	07/20/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/21/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

SECO CORP (Continued) **1000324744**

Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00047
Units:	Gallons (liquids only)
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC0655075
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	12/28/1990
Trans1 Recv Date:	12/28/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/28/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

SECO CORP (Continued) **1000324744**

MGMT Method Type Code: Not reported
Waste Code 1: Tetrachloroethylene
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00258
Units: Pounds
Number of Containers: 003
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYC1545434
Manifest Status: Not reported
Trans1 State ID: NYGA6403
Year: 1992
Trans2 State ID: Not reported
Generator Ship Date: 04/14/1992
Trans1 Recv Date: 04/14/1992
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/14/1992
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD056136526
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00303
Units: Pounds
Number of Containers: 004
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYC1545581
Manifest Status: Not reported

SECO CORP (Continued) **1000324744**

Trans1 State ID:	NYGR1992
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	10/30/1992
Trans1 Recv Date:	10/30/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/07/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00506
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC0368447
Manifest Status:	Not reported
Trans1 State ID:	000000000
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/1990
Trans1 Recv Date:	07/09/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/09/1990

SECO CORP (Continued) **1000324744**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00303
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC0690456
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	01/24/1991
Trans1 Recv Date:	01/24/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/24/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

SECO CORP (Continued) **1000324744**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00303
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC2315147
Manifest Status:	Not reported
Trans1 State ID:	NYNA1635
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	05/26/1993
Trans1 Recv Date:	05/26/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/26/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00050
Units:	Gallons (liquids only)
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

SECO CORP (Continued) **1000324744**

Document ID:	NJA1965779
Manifest Status:	Not reported
Trans1 State ID:	08690
Year:	1995
Trans2 State ID:	08690
Generator Ship Date:	03/07/1995
Trans1 Recv Date:	03/07/1995
Trans2 Recv Date:	03/13/1995
TSD Site Recv Date:	03/14/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ILD984908202
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00532
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYA9683267
Manifest Status:	C - Completed copy
Trans1 State ID:	NYML4624
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	891005
Trans1 Recv Date:	891005

SECO CORP (Continued) **1000324744**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	891005
Part A Recv Date:	891012
Part B Recv Date:	891012
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00258
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NYC3675238
Manifest Status:	Not reported
Trans1 State ID:	NY21631AH
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	07/25/1997
Trans1 Recv Date:	07/25/1997
Trans2 Recv Date:	08/01/1997
TSD Site Recv Date:	08/02/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

SECO CORP (Continued) **1000324744**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00500
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	TXA0070388
Manifest Status:	Not reported
Trans1 State ID:	88888
Year:	1996
Trans2 State ID:	88888
Generator Ship Date:	12/10/1996
Trans1 Recv Date:	12/10/1996
Trans2 Recv Date:	12/18/1996
TSD Site Recv Date:	01/13/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056136526
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	NYD980769947
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Chromium
Waste Code 2:	Not reported

SECO CORP (Continued) **1000324744**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00225
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00250
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
111 additional NY MANIFEST: record(s) in the EDR Site Report.

C13 **FIELD - POSSIBLY WETLANDS** **NY Spills** **S113916326**
North **52 ANDERSON** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.037 mi.
197 ft. **Site 1 of 4 in cluster C**

Relative: SPILLS:
Lower

Actual: Name:	FIELD - POSSIBLY WETLANDS
654 ft. Address:	52 ANDERSON
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1306582 / 2013-09-23
Facility ID:	1306582
Facility Type:	ER
DER Facility ID:	442309
Site ID:	487206
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	D4
SWIS:	1530
Spill Date:	2013-09-23
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2013-09-23

FIELD - POSSIBLY WETLANDS (Continued) **S113916326**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-09-23
Spill Record Last Update:	2013-09-23
Spiller Name:	Not reported
Spiller Company:	BUFFALO REDI MIX
Spiller Address:	1971 HAMBURG TURNPIKE
Spiller Company:	001
Contact Name:	SANTO RIZZO
Latitude:	42.9066918
Longitude:	-78.7715249
DEC Memo:	9/23/13:SAC GAVE COPY OF REPORT TO ECO CARL GILL - DEC LAW ENFORCEMENT. ECO GILL CONTACTED ECO CHUCK WILSON TO FOLLOW UP WITH INSPECTION. NO FURTHER WORK IS REQUIRED BY SPILLS. NO PAPER FILE.
Remarks:	Concrete truck is dumping its excess product into an area the caller believes is wetland.

All Materials:

Site ID:	487206
Operable Unit ID:	1236838
Operable Unit:	01
Material ID:	2236350
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

D14 **UPSTATE NIAGARA COOPERATIVES INC** **UST FINDER** **1028597410**
NW **1730 DALE RD** **N/A**
< 1/8 **BUFFALO, NY 14225**
0.038 mi.
202 ft. **Site 1 of 6 in cluster D**

Relative:
Higher

Actual:
657 ft.

UST FINDER:

Object ID:	315619
Facility ID:	NY53794
Name:	UPSTATE NIAGARA COOPERATIVES INC
Address:	1730 DALE RD
City,State,Zip:	BUFFALO, NY 14225
Address Match Type:	Not reported
Open USTs:	2
Closed USTs:	8
TOS USTs:	0
Population 1500ft:	2

UPSTATE NIAGARA COOPERATIVES INC (Continued) **1028597410**

Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Open UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-78.7733679999999
Y Coord:	42.9055290000001
Latitude:	42.905529
Longitude:	-78.773368

UST FINDER:

Object ID:	1310268
Facility ID:	NY53794
Tank ID:	NY92883
Tank Status:	Closed
Installation Date:	1975/02/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1310269
Facility ID:	NY53794
Tank ID:	NY92884
Tank Status:	Closed
Installation Date:	1972/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1310270
Facility ID:	NY53794
Tank ID:	NY93059
Tank Status:	Closed
Installation Date:	1972/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	1000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1310271
Facility ID:	NY53794
Tank ID:	NY93060
Tank Status:	Closed

UPSTATE NIAGARA COOPERATIVES INC (Continued) **1028597410**

Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	10000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1310272
Facility ID:	NY53794
Tank ID:	NY96853
Tank Status:	Closed
Installation Date:	1975/02/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1310273
Facility ID:	NY53794
Tank ID:	NY96854
Tank Status:	Closed
Installation Date:	1975/02/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1310274
Facility ID:	NY53794
Tank ID:	NY121233
Tank Status:	Closed
Installation Date:	1978/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1310275
Facility ID:	NY53794
Tank ID:	NY121234
Tank Status:	Closed
Installation Date:	1978/06/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1310276
Facility ID:	NY53794
Tank ID:	NY95432
Tank Status:	Open
Installation Date:	1993/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Not reported
Tank Wall Type:	Not reported
Object ID:	1310277

UPSTATE NIAGARA COOPERATIVES INC (Continued) **1028597410**

Facility ID:	NY53794
Tank ID:	NY97054
Tank Status:	Open
Installation Date:	1993/08/01 15:59:59+00
Removal Date:	Not reported
Tank Capacity:	8000
Substances:	Not reported
Tank Wall Type:	Not reported

D15 **UPSTATE MILK** **UST FINDER RELEASE** **1029071727**
NW **1730 DALE STREET** **N/A**
< 1/8 **BUFFALO, NY 0**
0.038 mi.
202 ft. **Site 2 of 6 in cluster D**

Relative:
Higher

Actual:
657 ft.

UST FINDER RELEASE:

Object ID:	244716
Facility ID:	NY282796
Lust ID:	NY8706123
Name:	UPSTATE MILK
Address:	1730 DALE STREET
City,State,Zip:	BUFFALO, NY 0
Address Match Type:	Not reported
Reported Date:	1987/10/20 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	4
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.7742699999999
Y Coord:	42.9052
Latitude:	42.9052
Longitude:	-78.77427

D16 **UPSTATE FARM COOPERATIVE, INC.** **NY LTANKS** **S103825081**
NW **1730 DALE RD.** **NY CBS AST** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225** **NY Spills**
0.038 mi. **NY SPDES**
202 ft. **Site 3 of 6 in cluster D**

Relative:
Higher

Actual:
657 ft.

LTANKS:

Name:	UPSTATE MILK
Address:	1730 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9603891 / 1996-10-02
Facility ID:	9603891
Site ID:	246981
Spill Date:	1996-06-20
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1996-07-19
SWIS:	1530
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1996-06-20
CID:	266
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1996-06-20
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-06-21
Spill Record Last Update:	2002-04-04
Spiller Name:	ROGER GROVE
Spiller Company:	UPSTATE MILK
Spiller Address:	1730 DALE ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	202786
Latitude:	42.9052021
Longitude:	-78.7742747
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 6/20/96: JDC ON SITE AND MET W/ JOE KLOC, ELMWOOD TANK - EXCAVATION WAS FREE OF ANY VISIABLE CONTAMINATION. POST TEST SAMPLES COLLECTED, CONTAMINATED SOILS STAGED ON SITE. 7/16/96: RECEIVED POST TEST RESULTS AND FOUND SATISFACTORY. NEED DISPOSAL RECEIPTS. 10/2/96: JDC TELCON W/ ELMWOOD TANK AND REQUESTED SOIL DISPOSAL RECEIPTS. RECEIVED RECEIPTS, NO FURTHER ACTION REQUIRED, SITE IS CLOSED.
Remarks:	SOIL CONTAMINATION ASSOCIATED WITH TWO 4000 GALLON UNDERGROUND GASOLINE TANKS.

All Materials:

Site ID:	246981
Operable Unit ID:	1031535
Operable Unit:	01
Material ID:	350166
Material Code:	0009
Material Name:	gasoline

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	UPSTATE FARMS
Address:	1730 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14227
Spill Number/Closed Date:	0408128 / 2004-10-25
Facility ID:	0408128
Site ID:	332775
Spill Date:	2004-10-22
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	1530
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2004-10-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-22
Spill Record Last Update:	2004-10-25
Spiller Name:	CHARLES BOWMAN
Spiller Company:	UPSTATE FARMS
Spiller Address:	1730 DALE ROAD
Spiller County:	001
Spiller Contact:	CHARLES BOWMAN
Spiller Phone:	(716) 647-2525
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	268072
Latitude:	42.9050050
Longitude:	-78.7735530
DEC Memo:	10/25/2004: RJJ TELECON JOHN ZIFFINO,GRIFFITH ENERGY,HE SAID THAT WHILE DELIVERING DIESEL FUEL,A SMALL AMOUNT OF FUEL,<1 QUART,SPILLED OUT OF THE VENT PIPE,ALL ON THE CONCRETE PAD...THE DRIVER USED ABSORBANTS TO CLEAN UP THE SPILL AND THEN DISPOSED THE MATERIAL IN THEIR DUMPSTER...NONE OF THE FUEL REACHED ANY SOIL OR WATERWAYS...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY *****
Remarks:	1 QUART LEAKED OUT, ALL CLEANED UP WITH PADS:

All Materials:

Site ID:	332775
Operable Unit ID:	1094987
Operable Unit:	01
Material ID:	575118

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CBS AST:

CBS Number:	9-000064
ICS Number:	9-003902
PBS Number:	9-387118
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	D
Telephone:	(716) 892-2121
Facility Town:	CHEEKTOWAGA
Region:	STATE
Expiration Date:	05/12/2003
Total Capacity of All Active Tanks(gal):	4500
Operator:	DANIEL DUNN
Emergency Contact:	PAT WEED
Emergency Phone:	(716) 537-2029
Owner Name:	UPSTATE FARM COOPERATIVE, INC.
Owner Address:	1730 DALE RD.
Owner City,St,Zip:	CHEEKTOWAGA, NY 14225
Owner Telephone:	(716) 892-2121
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	UPSTATE FARM COOPERATIVE, INC.
Mail Contact Addr:	1730 DALE RD.
Mail Contact Addr2:	Not reported
Mail Contact Contact:	DAN DUNN
Mail Contact City,St,Zip:	CHEEKTOWAGA, NY 14225
Mail Phone:	(716) 892-2121

Tank Id:	1
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/99
Tank Closed:	Not reported
Capacity (Gal):	1500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	50
Tank Error Status:	No Missing Data
Date Entered:	12/08/1999
Certified Date:	02/05/2001
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	None

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

External Protection:	None,None
Pipe Location:	None
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	00
Overfill Protection:	20
Haz Percent:	43
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	2
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/99
Tank Closed:	Not reported
Capacity (Gal):	1500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	50
Tank Error Status:	No Missing Data
Date Entered:	12/08/1999
Certified Date:	02/05/2001
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	None
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	00
Overfill Protection:	20
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	3
CAS Number:	7697372
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/99
Tank Closed:	Not reported
Capacity (Gal):	1500
Chemical:	Nitric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	50
Tank Error Status:	No Missing Data
Date Entered:	12/08/1999
Certified Date:	02/05/2001
Substance:	More than one Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None,None
Pipe Location:	None
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	00
Overfill Protection:	20
Haz Percent:	14
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	002
CAS Number:	7664382
Federal ID:	Not reported

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Tank Status:	In Service
Install Date:	09/90
Tank Closed:	11/99
Capacity (Gal):	1400
Chemical:	Phosphoric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	03/14/1991
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	22
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	001
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	08/84
Tank Closed:	11/99
Capacity (Gal):	1500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	05/12/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	004
CAS Number:	7664382
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	08/84
Tank Closed:	11/99
Capacity (Gal):	1500
Chemical:	Phosphoric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	05/12/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Haz Percent:	31
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	003
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	08/84
Tank Closed:	11/99
Capacity (Gal):	1500
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	05/12/1989
Certified Date:	02/05/2001
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	High Level Alarm
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	002
CAS Number:	7782505

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Federal ID:	Not reported
Tank Status:	In Service
Install Date:	06/70
Tank Closed:	00/00
Capacity (Gal):	250
Chemical:	Chlorine
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	05/12/1989
Certified Date:	02/05/2001
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	005
CAS Number:	7664417
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/60
Tank Closed:	00/00
Capacity (Gal):	250
Chemical:	Ammonia
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	05/12/1989
Certified Date:	02/05/2001

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Steel/Iron
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430
Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Tank Id:	006
CAS Number:	7664417
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/60
Tank Closed:	00/00
Capacity (Gal):	250
Chemical:	Ammonia
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	2
Date Entered:	05/12/1989
Certified Date:	02/05/2001
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Steel/Iron
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	1430

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Lat/Long:	42|57|00 / 78|46|01
Is Updated:	False
Renew Date:	02/01/93
Is It There:	False
Delinquent:	False
Date Expired:	05/12/95
Owner Mark:	1
Certificate Needs to be Printed:	42|57|00 / 78|46|01
Fiscal Amt for Registration Fee Correct:	42|57|00 / 78|46|01
Renewal Has Been Printed for Facility:	42|57|00 / 78|46|01
Pre-Printed Renewal App Last Printed:	42|57|00 / 78|46|01

Click this hyperlink while viewing on your computer to access additional NY_AST_CBS: detail in the EDR Site Report.

SPILLS:

Name:	UPSTATE FARMS COOPERATIVE
Address:	1730 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0075304 / 2000-09-20
Facility ID:	0075304
Facility Type:	ER
DER Facility ID:	202786
Site ID:	246980
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1530
Spill Date:	2000-08-17
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	2000-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2000-08-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-17
Spill Record Last Update:	2002-04-04
Spiller Name:	TOM RUGGIERI (TRITEC ENV)
Spiller Company:	UPSTATE FARMS COOPERATIVE
Spiller Address:	1730 DALE ROAD
Spiller Company:	001
Contact Name:	PAT WEED
Latitude:	42.9052021
Longitude:	-78.7742747
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 08/17/00: MJS TELECON FROM PAT WEED. TOOK REPORT, HE SAID CONTAMINATED SOILS FOUND WHILE EXCAVATING FOR SEWER WORK. REPRESENTATIVE FROM TRI-TEC ON THE WAY FROM ROCHESTER TO LOOK AT SITUATION. MJS TELECON WITH PAT

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

WEED AND TOM RUGGIERI OF TRI-TEC ENVIRONMENTAL HEALTH AND SAFETY. EXCAVATION IS APPROX TWO FEET
DEEP. THEY FOUND SPOTTY CONTAMINATED SOILS, APPEARS TO BE LOCALIZED. CONTAMINATION IS POSSIBLY FROM
OLD FILL. THEY PLAN TO EXCAVATE, SEGREGATE AND STAGE SOILS FOR DISPOSAL. THEY WILL OBTAIN SIDEWALL
SAMPLES. IF CONTAMINATION FOUND TO BE WIDESPREAD, FURTHER WORK MAY BE REQUIRED. MJS SITE
INSPECTION, MET WITH TOM RUGGIERI, TRITEC. THEY ARE EXCAVATING CONTAMINATED SOILS AND STAGING FOR
DISPOSAL. CONTAMINATION APPEARS TO BE A SMALL LOCALIZED POCKET FROM UNKNOWN SOURCE. OIL IS BLACK
AND HEAVY, CONSISTENT WITH A HEAVY FUEL OIL OR TAR, POSSIBLY A MASTIC COATING. IMPACTED SOILS ARE
APPROX FOUR FEET FROM BUILDING FOUNDATION. SURROUNDING SOILS ARE VISUALLY CLEAN (CLAY). IT APPEARS
THEY WILL BE READILY ABLE TO CLEAN UOP EXCAVATION WITH LIMITED SOIL REMOVAL. THEY HAVE HIRED
OP-TECH TO SAMPLE EXCAVATION AND DISPOSE OF SOILS. MJS TELECON FROM TOM RUGGIERI. CONTAMINATION WAS
LIMITED TO THE BACKFILL OF THE ORIGINAL SEWER TRENCH. ALL CONTAMINATION STOCKPILED FOR DISPOSAL AND
GRAB SAMPLE OBTAINED FROM THE BOTTOM (WORST CASE) OF THE EXCAVATION. HE WILL FORWARD SAMPLE RESULTS
AND OP-TECH WILL HANDLE THE SOIL DISPOSAL. NEED SAMPLE RESULTS AND SOIL DISPOSAL DOCUMENTATION FOR
FILE CLOSURE. 08/22/00: MJS SENT LETTER TO RP FOR SOIL DISPOSAL AND SAMPLE RESULTS. 08/28/00: MJS
RECEIVED FAX OF SOIL SAMPLE RESULTS. ALL COMPOUNDS ON 8021/8270 ARE NON-DETECT. NEED SOIL DISPOSAL
DOCUMENTATION FOR FILE CLOSURE. 09/19/00: MJS TELECON PAT WEED. ADVISED HIM THAT WE NEED DISPOSAL
DOCUMENTATION FOR FILE CLOSURE. HE WILL OBTAIN COPY OF MANIFEST AND FORWARD. 09/20/00: MJS RECEIVED
COPY OF NON-HAZ WASTE MANIFEST FOR 20 TON MINIMUM. SOIL DISPOSED AT CID CHAFFEE LANDFILL. NO
FURTHER ACTION NECESSARY. MJS CLOSE FILE, LETTER TO RP. 10/16/00: RECEIVED ANALYTICAL RESULTS AND
WEIGHT TICKETS FOR CONTAMINATED SOIL. MJS FILED INFO.

Remarks: WORK BEING PERFORMED ON SANITARY SEWER. DIESEL FUEL CONTAMINATION FOUND WHILE EXCAVATING.

All Materials:

Site ID:	246980
Operable Unit ID:	838179
Operable Unit:	01
Material ID:	538859
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name: UPSTATE FARMS

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Address:	1730 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14227
Spill Number/Closed Date:	0408704 / 2004-11-09
Facility ID:	0408704
Facility Type:	ER
DER Facility ID:	268072
Site ID:	333441
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1530
Spill Date:	2004-11-06
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2004-11-06
CID:	38
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-11-06
Spill Record Last Update:	2004-11-09
Spiller Name:	ZASSINO,JOHN
Spiller Company:	GRIFFTH ENERGY
Spiller Address:	760 BROOKS AV
Spiller Company:	001
Contact Name:	CHARLES BOWMAN
Latitude:	42.9050050
Longitude:	-78.7735530
DEC Memo:	11/6/2004: DURING A DELIVERY OF DIESEL FUEL,ABOUT 1 CUP OF FUEL CAME OUT OF THE VENT PIPE...IT SPILLED ON THE CONCRETE PAD...THE DRIVER USED ABSORBANTS TO SOAK UP THE SPILL AND WILL DISPOSE THE MATERIAL IN THEIR DUMPSTER...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT. ***** NOTE,COMPUTER FILE ONLY *****
Remarks:	during refill 1 cup of diesel fuel came out vent pipe. Driver is using pads to clean up

All Materials:

Site ID:	333441
Operable Unit ID:	1095596
Operable Unit:	01
Material ID:	575719
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Name:	UPSTATE MILK
Address:	1730 DALE STREET
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9901856 / 1999-05-18
Facility ID:	9901856
Facility Type:	ER
DER Facility ID:	109060
Site ID:	126109
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1530
Spill Date:	1999-05-17
Investigator:	BRENNAN
Referred To:	Not reported
Reported to Dept:	1999-05-17
CID:	386
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-05-17
Spill Record Last Update:	2000-12-22
Spiller Name:	Not reported
Spiller Company:	UPSTATE MILK
Spiller Address:	1730 DALE STREET
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9052021
Longitude:	-78.7742747
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was KAB 05/18/99: KAB DISCUSSED AFTER-HOURS SPILL WITH DUTY OFFICER, MARK HANS. MR. HANS INDICATED THAT INCIDENT WAS ALREADY HANDLED BY THE TIME THAT HE RECEIVED THE CALL AND THAT, BECAUSE IT WAS AN AIR RELEASE, DID NOT REQUIRE RESPONSE BY SPILL PERSONNEL. SPILL RESP0NDER NOT NOTIFIED, NO FURTHER ACTION POSSIBLE.
Remarks:	150lb tank burst inside building erie co hazmat team on scene cleanup started building evacuated

All Materials:

Site ID:	126109
Operable Unit ID:	1080612
Operable Unit:	01
Material ID:	305382
Material Code:	0025A
Material Name:	ammonia
Case No.:	07664417
Material FA:	Hazardous Material
Quantity:	150.00
Units:	L
Recovered:	.00

UPSTATE FARM COOPERATIVE, INC. (Continued) **S103825081**

Oxygenate: Not reported

SPDES:

Name:	Upstate Niagara Cooperative Inc
Address:	1730 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14227
Permit Number:	NYR00C349
State-Region:	9
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	Not reported
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Not reported

D17 **UPSTATE NIAGARA** **RCRA-VSQG** **1000911940**
NW **1730 DALE RD** **NY LTANKS** **NYD986933075**
< 1/8 **BUFFALO, NY 14225** **NY CBS**
0.038 mi. **NY AST**
202 ft. **Site 4 of 6 in cluster D** **E MANIFEST**
NY MANIFEST

Relative: Higher

Actual: 657 ft.

RCRA Listings:

Date Form Received by Agency:	20240604
Handler Name:	Upstate Niagara Cooperative Inc
Handler Address:	Dale Rd
Handler City,State,Zip:	BUFFALO, NY 14225-4921
EPA ID:	NYD986933075
Contact Name:	STEVEN RAZZOLINI
Contact Address:	DALE RD
Contact City,State,Zip:	BUFFALO, NY 14225
Contact Telephone:	716-892-3156 x2595
Contact Fax:	Not reported
Contact Email:	SRAZZOLINI@UNCDAIRY.COM
Contact Title:	SAFETY MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R9
Mailing Address:	DALE RD
Mailing City,State,Zip:	BUFFALO, NY 14225
Owner Name:	Upstate Niagara Cooperative Inc
Owner Type:	Private
Operator Name:	Upstate Niagara Cooperative Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

UPSTATE NIAGARA (Continued) **1000911940**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20240604
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UPSTATE MILK COOPERATIVES INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1730 DALE RD
Owner/Operator City,State,Zip:	BUFFALO, NY 14225
Owner/Operator Telephone:	716-895-8992
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	UPSTATE NIAGARA COOPERATIVE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1730 DALE RD
Owner/Operator City,State,Zip:	BUFFALO, NY 14225
Owner/Operator Telephone:	716-895-8992
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	UPSTATE MILK COOPERATIVES INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1730 DALE RD

UPSTATE NIAGARA (Continued) **1000911940**

Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 716-895-8992
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UPSTATE NIAGARA COOPERATIVE INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 368 PLEASANT VIEW DR
Owner/Operator City,State,Zip: LANCASTER, NY 14086
Owner/Operator Telephone: 716-895-8992
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: UPSTATE MILK COOPERATIVES INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1730 DALE RD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 716-895-8992
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: UPSTATE MILK COOPERATIVES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: UPSTATE MILK COOPERATIVES INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

UPSTATE NIAGARA (Continued) **1000911940**

Receive Date: 20070101
Handler Name: UPSTATE MILK COOPERATIVES INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19941017
Handler Name: UPSTATE MILK COOPERATIVES INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20240604
Handler Name: UPSTATE NIAGARA COOPERATIVE INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 311511
NAICS Description: Fluid Milk Manufacturing

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LTANKS:
Name: UPSTATE FARMS PLANT
Address: 1730 DALE ROAD

UPSTATE NIAGARA (Continued) **1000911940**

City,State,Zip:	BUFFALO, NY
Spill Number/Closed Date:	0010155 / 2001-02-28
Facility ID:	0010155
Site ID:	246979
Spill Date:	2000-12-09
Spill Cause:	Tank Overfill
Spill Source:	Commercial Vehicle
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	1500
Investigator:	JFOTTO
Referred To:	Not reported
Reported to Dept:	2000-12-09
CID:	199
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	2000-12-11
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-09
Spill Record Last Update:	2002-04-04
Spiller Name:	Not reported
Spiller Company:	UPSTATE FARMS
Spiller Address:	62 DEWEY AVENUE
Spiller County:	001
Spiller Contact:	MIKE OMERA
Spiller Phone:	(716) 458-1880
Spiller Extention:	5357
DEC Region:	9
DER Facility ID:	277716
Latitude:	42.9052021
Longitude:	-78.7742747
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 12/11/00: JFO ON SITE, MET WITH MIKE. SPILL HAS BEEN CLEANED UP. A SLIGHT SHEEN REMAINS ON A PUDDLE NEAR THE PUMPS. MIKE WILL USE PADS TO REMOVE THE SHEEN. THREE 30 GALLON DRUMS FOR DISPOSAL. I WILL CALL MIKE OMERA TOMORROW. 12/12/00: JFO TELECON WITH VINCE DEMAIORIBUS, THE CALLER FROM UPSTATE MILK. HE WILL CONTACT THE COMPANY THAT OWNS THEIR DUMPSTER FOR PERMISSION TO PUT CLEANUP MATERIAL IN IT. IF THEY REFUSE TO ALLOW IT, HE WILL THEN SAMPLE AND ANALYZE FOR TCLP BENZENE AND IGNITABILITY AND DISPOSE OF MATERIAL AT A LANDFILL. HE WILL CALL BACK TO LET ME KNOW. 12/18/00: JFO CALL FROM VINCE DEMAIORIBUS OF UPSTATE. ENVIRONMENTAL SOLUTIONS WILL BE DISPOSING OF THE CLEANUP MATERIAL. RECEIPTS AND ANY ANALYTICAL TO FOLLOW. 02/14/01: JFO CALL TO MR DEMAIORIBUS. NOT IN LEFT A MESSAGE ON HIS V-MAIL. 02/28/01: JFO RECEIVED THE DISPOSAL RECEIPT FOR THE 3 DRUMS. NO FURTHER ACTION REQUIRED. CLOSED
Remarks:	WHILE FILLING TANK OPERATOR OVERFILLED - ALL MATERAL CONFINED TO CONCRETE PAD - ALL MATERAL SOAKED UP WITH SPEEDY DRY

All Materials:

Site ID:	246979
Operable Unit ID:	831117
Operable Unit:	01
Material ID:	544073
Material Code:	0008

UPSTATE NIAGARA (Continued) **1000911940**

Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7.00
Units:	G
Recovered:	7.00
Oxygenate:	Not reported

Name:	UPSTATE MILK
Address:	1730 DALE STREET
City,State,Zip:	BUFFALO, NY
Spill Number/Closed Date:	8706123 / 1987-10-23
Facility ID:	8706123
Site ID:	126108
Spill Date:	1987-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1987-10-23
SWIS:	1502
Investigator:	ROSS
Referred To:	Not reported
Reported to Dept:	1987-10-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-10-21
Spill Record Last Update:	1987-10-23
Spiller Name:	Not reported
Spiller Company:	UPSTATE MILK
Spiller Address:	1730 DALE STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	282796
Latitude:	42.9052021
Longitude:	-78.7742747
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : TANK TO BE EXCAVATED, ISOLATED AND RETESTED. / / : LQR TELCON TANK TESTER 10/23/87 HE ADMITS TO MAKING A MATH ERROR,TANK IS TIGHT.
Remarks:	4000 GAL UDERGROUND TANK TEST LEAK RATE 0.216 GPH

All TTF:

Facility ID:	8706123
Spill Number:	8706123
Spill Tank Test:	1531977
Site ID:	126108
Tank Number:	Not reported
Tank Size:	0

UPSTATE NIAGARA (Continued) **1000911940**

Material: 0008
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 126108
Operable Unit ID: 912160
Operable Unit: 01
Material ID: 465141
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

CBS:
Name: UPSTATE NIAGARA COOPERATIVE, INC.
Address: 1730 DALE RD
City,State,Zip: BUFFALO, NY 14225
CBS Number: 9-000064
Program Type: CBS
Facility Status: Active
Expiration Date: 05/12/2027
Dec Region: 9
UTMX: 191947.85802
UTMY: 4757284.48188

AST:
Name: UPSTATE NIAGARA COOPERATIVES INC
Address: 1730 DALE RD
City,State,Zip: BUFFALO, NY 14225
Region: STATE
DEC Region: 9
Site Status: Active
Facility Id: 9-387118
Program Type: PBS
UTM X: 191951.56225
UTM Y: 4757229.43359
Expiration Date: 08/17/2027
Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:
Site Id: 53794
Affiliation Type: Facility Operator

UPSTATE NIAGARA (Continued) **1000911940**

Company Name:	UPSTATE NIAGARA COOPERATIVES INC
Contact Type:	Not reported
Contact Name:	FLOYD POPE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 892-2121
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-09-26

Site Id:	53794
Affiliation Type:	Facility Owner
Company Name:	UPSTATE NIAGARA COOPERATIVES INC
Contact Type:	FLEET MANAGER
Contact Name:	JOHN CARPENTER
Address1:	368 PLEASANT VIEW DR.
Address2:	Not reported
City:	LANCASTER
State:	NY
Zip Code:	14086
Country Code:	001
Phone:	(716) 892-3156
EMail:	Not reported
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2023-10-13

Site Id:	53794
Affiliation Type:	Emergency Contact
Company Name:	UPSTATE NIAGARA COOPERATIVES INC
Contact Type:	Not reported
Contact Name:	DOUGLAS EVANS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 949-0470
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2022-09-14

Site Id:	53794
Affiliation Type:	Mail Contact
Company Name:	UPSTATE NIAGARA COOPERATIVES INC.
Contact Type:	FLEET MANAGER
Contact Name:	JOHN CARPENTER
Address1:	1730 DALE ROAD
Address2:	Not reported
City:	BUFFALO

UPSTATE NIAGARA (Continued) **1000911940**

State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(585) 615-8940
EMail:	JCARPENTER@UNCDAIRY.COM
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2023-10-13

Tank Info:

Tank Number:	003
Tank Id:	171612
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1984
Capacity Gallons:	300
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	PTDIEZ
Last Modified:	10/13/2023
Material Name:	waste oil/used oil

Tank Number:	004
Tank Id:	171613
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

UPSTATE NIAGARA (Continued) **1000911940**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
C01 - Pipe Location - Aboveground
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	06/01/1997
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/06/2007
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	005
Tank Id:	247313
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/18/2013
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	PTDIEZ
Last Modified:	10/13/2023
Material Name:	motor oil

UPSTATE NIAGARA (Continued) **1000911940**

Tank Number: 5-A
Tank Id: 177851
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:
G00 - Tank Secondary Containment - None
J03 - Dispenser - Gravity
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I00 - Overfill - None
C01 - Pipe Location - Aboveground
H99 - Tank Leak Detection - Other

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 06/01/1995
Capacity Gallons: 250
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 06/01/1997
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: lube oil

E MANIFEST:
Manifest Tracking Number: 006701987SKS
Last Updated Date: 20190902
Shipped Date: 20190726
Received Date: 20190806
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: CESQG
Generator Name: Upstate Niagara
Generator Location Street Number: Not reported
Generator Location Street 1: 1730 DALE RD
Generator Location Street 2: Not reported
Generator Location City: BUFFALO
Generator Location State: NY
Generator Location Zip: 14225
Generator Mail Street Number: Not reported
Generator Mail Street 1: 1730 Dale Rd
Generator Mail Street 2: Not reported
Generator Mail City: Buffalo
Generator Mail Zip: 14225
Generator Mail State: NY
Generator Contact Company Name: Not reported
Designated Facility EPA ID: KYD053348108
Designated Facility Name: Not reported

UPSTATE NIAGARA (Continued) **1000911940**

Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	3700 LaGrange Road
Designated Facility Mail City:	Smithfield
Designated Facility Mail Zip:	40068
Designated Facility Mail State:	KY
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	3700 LaGrange Road
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Smithfield
Designated Facility Location Zip:	40068
Designated Facility Location State:	KY
Designated Facility Contact Company Name:	Safety-Kleen Systems, Inc.
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	006701988SKS
Last Updated Date:	20190904
Shipped Date:	20190726
Received Date:	20190805
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Upstate Niagara
Generator Location Street Number:	Not reported
Generator Location Street 1:	1730 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1730 Dale Rd
Generator Mail Street 2:	Not reported
Generator Mail City:	Buffalo
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD000816629
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	4879 Spring Grove Avenue
Designated Facility Mail City:	Cincinnati
Designated Facility Mail Zip:	45232
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	4879 Spring Grove Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Cincinnati
Designated Facility Location Zip:	45232
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Spring Grove Resource Recovery Inc.
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	006701989SKS

UPSTATE NIAGARA (Continued) **1000911940**

Last Updated Date:	20210812
Shipped Date:	20190726
Received Date:	20190815
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD986933075
Generator Name:	Upstate Milk Cooperatives Inc
Generator Location Street Number:	1730
Generator Location Street 1:	1730 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225-4921
Generator Mail Street Number:	1730
Generator Mail Street 1:	DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD000724153
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2900 Rockefeller Avenue
Designated Facility Mail City:	Cleveland
Designated Facility Mail Zip:	44115
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2900 Rockefeller Avenue
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Cleveland
Designated Facility Location Zip:	44115
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Clean Harbors Environmental Services, Inc.
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006701989SKS
Transporter Line Number:	1
Transporter EPA ID:	TXR000081205
Transporter Name:	Safety-Kleen Systems, Inc.

Manifest Tracking Number:	006701989SKS
Transporter Line Number:	2
Transporter EPA ID:	NYD982792814
Transporter Name:	Franks Vacuum Truck Service Inc

Manifest Tracking Number:	006701989SKS
Transporter Line Number:	3
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.

Waste Line:

UPSTATE NIAGARA (Continued) **1000911940**

Manifest Tracking Number:	006701989SKS
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1789
U.S. DOT Description:	Un1789, Waste Un1789, Waste Hydrochloric Acid Solution, 8, Pg Ii, 8, Pg Ii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	2
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	75
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.31276062
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.31276062
Waste Quantity, in Kilograms:	283.6833
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	283.6833
Management Method Code:	H070
Management Method Description:	CHEMICAL TREATMENT
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D002
Quantity Haz Kg:	283.6833
Quantity Haz Tons:	0.31276062
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T

NY MANIFEST:

EPA ID:	NYD986933075
Country:	USA
Name:	Upstate Milk Cooperatives Inc
Address:	1730 DALE RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225-4921
Zip 4:	Not reported
Location Address 1:	1730 DALE ROAD
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

UPSTATE NIAGARA (Continued) **1000911940**

Mailing:
- Mailing Name: Upstate Milk Cooperatives Inc
- Mailing Contact: Paul Bertalan Jr
- Mailing Address 1: 1730 DALE ROAD
- Mailing Address 2: Not reported
- Mailing City,State,Zip: BUFFALO, NY 14225
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 7168958992

Manifest Data:
- Document ID: Not reported
- Manifest Status: Not reported
- Trans1 State ID: MAD039322250
- Year: 2018
- Trans2 State ID: Not reported
- Generator Ship Date: 01/24/2008
- Trans1 Recv Date: 01/24/2008
- Trans2 Recv Date: Not reported
- TSD Site Recv Date: 01/25/2008
- Part A Recv Date: Not reported
- Part B Recv Date: Not reported
- Generator EPA ID: NYD986933075
- Trans1 EPA ID: Not reported
- Trans2 EPA ID: Not reported
- TSDF ID 1: OHD986975399
- TSDF ID 2: Not reported
- Manifest Tracking Number: 001859168FLE
- Import Indicator: N
- Export Indicator: N
- Discr Quantity Indicator: N
- Discr Type Indicator: N
- Discr Residue Indicator: N
- Discr Partial Reject Indicator: N
- Discr Full Reject Indicator: N
- Manifest Ref Number: Not reported
- Alt Facility RCRA ID: Not reported
- Alt Facility Sign Date: Not reported
- MGMT Method Type Code: H010
- Waste Code a: B004
- Waste Code b: Not reported
- Waste Code c: Not reported
- Waste Code e: Not reported
- Waste Code f: Not reported
- Waste Code g: Not reported
- Waste Code 1: Not reported
- Waste Code 2: Not reported
- Waste Code 3: Not reported
- Waste Code 4: Not reported
- Waste Code 5: Not reported
- Waste Code 6: Not reported
- Quantity: 311
- Units: Kilograms
- Number of Containers: 1
- Container Type: Metal boxes, cartons, cases (including roll-offs)
- Handling Method: Recycle

UPSTATE NIAGARA (Continued) **1000911940**

Specific Gravity: 1

Document ID: NJA2540223
Manifest Status: Not reported
Trans1 State ID: 08690
Year: 1996
Trans2 State ID: Not reported
Generator Ship Date: 04/30/1996
Trans1 Recv Date: 04/30/1996
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/02/1996
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986933075
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002182897
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Benzene
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 01540
Units: Pounds
Number of Containers: 004
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYG3875778
Manifest Status: Not reported
Trans1 State ID: 242614IN
Year: 2005
Trans2 State ID: Not reported
Generator Ship Date: 02/08/2005
Trans1 Recv Date: 02/08/2005
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/25/2005
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986933075
Trans1 EPA ID: IND058484114
Trans2 EPA ID: Not reported

UPSTATE NIAGARA (Continued) **1000911940**

TSDF ID 1:	OHD980613541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00075
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Corrosive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00035
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Corrosive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Corrosive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00075
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs

UPSTATE NIAGARA (Continued) **1000911940**

Handling Method: Burn
Specific Gravity: 01.00

D18 **UPSTATE MILK** **UST FINDER RELEASE** **1029064843**
NW **1730 DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 0**
0.038 mi.
202 ft. **Site 5 of 6 in cluster D**

Relative:
Higher

Actual:
657 ft.

UST FINDER RELEASE:

Object ID:	244717
Facility ID:	NY202786
Lust ID:	NY9603891
Name:	UPSTATE MILK
Address:	1730 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1996/06/20 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	4
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.7742699999999
Y Coord:	42.9052
Latitude:	42.9052
Longitude:	-78.77427

D19 **UPSTATE NIAGARA COOPERATIVES INC** **NY UST** **U004064900**
NW **1730 DALE RD** **N/A**
< 1/8 **BUFFALO, NY 14225**
0.038 mi.
202 ft. **Site 6 of 6 in cluster D**

Relative:
Higher

Actual:
657 ft.

UST:

Name:	UPSTATE NIAGARA COOPERATIVES INC
Address:	1730 DALE RD
City,State,Zip:	BUFFALO, NY 14225
Id/Status:	9-387118 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	08/17/2027
UTM X:	191951.56225
UTM Y:	4757229.43359
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	53794
Affiliation Type:	Facility Operator
Company Name:	UPSTATE NIAGARA COOPERATIVES INC
Contact Type:	Not reported
Contact Name:	FLOYD POPE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 892-2121
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-09-26

Site Id:	53794
Affiliation Type:	Facility Owner
Company Name:	UPSTATE NIAGARA COOPERATIVES INC
Contact Type:	FLEET MANAGER
Contact Name:	JOHN CARPENTER
Address1:	368 PLEASANT VIEW DR.
Address2:	Not reported
City:	LANCASTER
State:	NY
Zip Code:	14086
Country Code:	001
Phone:	(716) 892-3156
EMail:	Not reported
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2023-10-13

Site Id:	53794
Affiliation Type:	Emergency Contact
Company Name:	UPSTATE NIAGARA COOPERATIVES INC
Contact Type:	Not reported
Contact Name:	DOUGLAS EVANS
Address1:	Not reported

UPSTATE NIAGARA COOPERATIVES INC (Continued) **U004064900**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 949-0470
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2022-09-14

Site Id:	53794
Affiliation Type:	Mail Contact
Company Name:	UPSTATE NIAGARA COOPERATIVES INC.
Contact Type:	FLEET MANAGER
Contact Name:	JOHN CARPENTER
Address1:	1730 DALE ROAD
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(585) 615-8940
EMail:	JCARPENTER@UNCDAIRY.COM
Fax Number:	Not reported
Modified By:	PTDIEZ
Date Last Modified:	2023-10-13

Tank Info:

Tank Number:	001
Tank ID:	170899
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	12000
Install Date:	08/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	PTDIEZ
Last Modified:	10/13/2023

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring

UPSTATE NIAGARA COOPERATIVES INC (Continued) **U004064900**

I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
A99 - Tank Internal Protection - Other
J00 - Dispenser - None
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Number:	002
Tank ID:	170900
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	08/01/1993
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	PTDIEZ
Last Modified:	10/13/2023

Equipment Records:

B02 - Tank External Protection - Original Sacrificial Anode
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser
B01 - Tank External Protection - Painted/Asphalt Coating
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A99 - Tank Internal Protection - Other
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Number:	008
Tank ID:	236642
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	09/10/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

UPSTATE NIAGARA COOPERATIVES INC (Continued) **U004064900**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Tank Number: 1
Tank ID: 165730
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 02/01/1975
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 10/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 2
Tank ID: 165731
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 02/01/1975
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 10/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI

UPSTATE NIAGARA COOPERATIVES INC (Continued) **U004064900**

Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 3
Tank ID: 165732
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 02/01/1975
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 01
Date Test: 10/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 4
Tank ID: 165733
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1978
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

UPSTATE NIAGARA COOPERATIVES INC (Continued) **U004064900**

Tightness Test Method: 01
Date Test: 10/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 5
Tank ID: 177850
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 06/01/1978
Date Tank Closed: 08/01/1993
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 10/01/1987
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 6
Tank ID: 165735
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 06/01/1972
Date Tank Closed: Not reported

UPSTATE NIAGARA COOPERATIVES INC (Continued) **U004064900**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 7
Tank ID: 165736
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 1000
Install Date: 06/01/1972
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

C20 **ADVISION INK** **NY MANIFEST** **S121446528**
North **60 ANDERSON ST** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.054 mi.
284 ft. **Site 2 of 4 in cluster C**

Relative:
Lower

Actual:
654 ft.

NY MANIFEST:

EPA ID:	NYD986927879
Country:	USA
Name:	Advision Ink
Address:	60 ANDERSON ST
Address 2:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14225
Zip 4:	Not reported
Location Address 1:	P O BOX 200
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Advision Ink
Mailing Contact:	Body Shop Mgr
Mailing Address 1:	P O BOX 200
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168923000

Manifest Data:

Document ID:	NYB5132673
Manifest Status:	Not reported
Trans1 State ID:	P52019IL
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/1994
Trans1 Recv Date:	04/14/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/15/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

ADVISION INK (Continued) **S121446528**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00160
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG2992941
Manifest Status:	Not reported
Trans1 State ID:	P207004IL
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	10/25/2001
Trans1 Recv Date:	10/25/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/26/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends

ADVISION INK (Continued) **S121446528**

Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00050
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYH0668889
Manifest Status: Not reported
Trans1 State ID: P207004IL
Year: 2004
Trans2 State ID: Not reported
Generator Ship Date: 10/06/2004
Trans1 Recv Date: 10/06/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/14/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986927879
Trans1 EPA ID: NJD080631369
Trans2 EPA ID: Not reported
TSDF ID 1: OHD093945293
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported

ADVISION INK (Continued) **S121446528**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00145
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG1386387
Manifest Status:	Not reported
Trans1 State ID:	P207004IL
Year:	1999
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/1999
Trans1 Recv Date:	05/06/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00165
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

ADVISION INK (Continued) **S121446528**

Document ID:	NYG2869425
Manifest Status:	Not reported
Trans1 State ID:	P207004IL
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	10/10/2003
Trans1 Recv Date:	10/10/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC6611174
Manifest Status:	Not reported
Trans1 State ID:	NY92765AT
Year:	2002
Trans2 State ID:	T1618DNJ
Generator Ship Date:	05/02/2002
Trans1 Recv Date:	05/02/2002

ADVISION INK (Continued) **S121446528**

Trans2 Recv Date:	05/08/2002
TSD Site Recv Date:	05/09/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NYD071629976
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00550
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00650
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYB7896474
Manifest Status:	Not reported
Trans1 State ID:	P52019IL

ADVISION INK (Continued) **S121446528**

Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/1995
Trans1 Recv Date:	10/12/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/13/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	ILD099202681
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00190
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG0164466
Manifest Status:	Not reported
Trans1 State ID:	P207004IL
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/1997
Trans1 Recv Date:	10/13/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	NJD080631369

ADVISION INK (Continued) **S121446528**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYG2624292
Manifest Status:	Not reported
Trans1 State ID:	P207004IL
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	10/23/2000
Trans1 Recv Date:	10/23/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/26/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986927879
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

ADVISION INK (Continued) **S121446528**

Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00170
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYG1725255
Manifest Status: Not reported
Trans1 State ID: P207004IL
Year: 1999
Trans2 State ID: Not reported
Generator Ship Date: 11/30/1999
Trans1 Recv Date: 11/30/1999
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/03/1999
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986927879
Trans1 EPA ID: NJD080631369
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents

ADVISION INK (Continued) **S121446528**

Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00065
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYB4346829
Manifest Status: Not reported
Trans1 State ID: P22295IL
Year: 1992
Trans2 State ID: Not reported
Generator Ship Date: 11/04/1992
Trans1 Recv Date: 11/04/1992
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/10/1992
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986927879
Trans1 EPA ID: ILD099202681
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00202
Units: Gallons (liquids only)
Number of Containers: 001

ADVISION INK (Continued) **S121446528**

Container Type:	Cargo tanks (tank trucks)
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
19 additional NY MANIFEST: record(s) in the EDR Site Report.

C21 **ADVISION INC** **RCRA-VSQG** **1000457529**
North **60 ANDERSON ST** **FINDS** **NYD986927879**
< 1/8 **CHEEKTOWAGA, NY 14225** **ECHO**
0.054 mi.
284 ft. **Site 3 of 4 in cluster C**

Relative: **Lower**
Actual: **654 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Advision Inc
Handler Address:		Anderson St
Handler City,State,Zip:		CHEEKTOWAGA, NY 14225
EPA ID:		NYD986927879
Contact Name:		Not reported
Contact Address:		PO BOX 200
Contact City,State,Zip:		BUFFALO, NY 14225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		PO BOX 200
Mailing City,State,Zip:		BUFFALO, NY 14225
Owner Name:	Advision Inc	
Owner Type:		Private
Operator Name:	Advision Inc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N

ADVISION INC (Continued) **1000457529**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ADVISION INC	
Legal Status:	Private
Date Became Current:	Not reported

ADVISION INC (Continued) **1000457529**

Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ADVISION INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ADVISION INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990714
Handler Name: ADVISION INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ADVISION INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

ADVISION INC (Continued) **1000457529**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ADVISION INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19901017
Handler Name: ADVISION INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920229
Handler Name: ADVISION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 33995
NAICS Description: Sign Manufacturing

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported

ADVISION INC (Continued) **1000457529**

Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20070405
Actual Return to Compliance Date:	20070615
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	002
Date of Enforcement Action:	20070412
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20070625
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYTRN
Enforcement Responsible Sub-Organization:	R9
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported

ADVISION INC (Continued) **1000457529**

SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20020411
Actual Return to Compliance Date: 20020514
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20020423
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYALS
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported

ADVISION INC (Continued) **1000457529**

Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported

ADVISION INC (Continued) **1000457529**

SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20110301
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYNSL
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20070405
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTRN
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20070615
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020411
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYALS
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20020514
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19990603
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYNSL
Evaluation Responsible Sub-Organization:	R9

ADVISION INC (Continued) **1000457529**

Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19921002
Evaluation Responsible Agency:	EPA Contractor/Grantee
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2TRC
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004454411

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000457529
Registry ID: 110004454411

DFR URL:
Name: ADVISION INC
Address: 60 Anderson St
City,State,Zip: CHEEKTOWAGA, NY 14225

B22 **VACANT MANUFACTURING SITE** **NY Spills** **S102561458**
ESE **1800 DALE RD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.063 mi.
332 ft. **Site 4 of 4 in cluster B**

Relative:
Lower

Actual:
654 ft.

SPILLS:

Name:	UPSTATE STEEL
Address:	1800 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9700454 / 1998-03-10
Facility ID:	9700454

VACANT MANUFACTURING SITE (Continued) **S102561458**

Facility Type:	ER
DER Facility ID:	122211
Site ID:	143280
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1530
Spill Date:	1997-04-09
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1997-04-09
CID:	196
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	1997-04-14
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-09
Spill Record Last Update:	1998-03-19
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	EVAN CASEY
Latitude:	42.9043564
Longitude:	-78.7707079
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 04/10/97: JDC ON SITE AND MET W/ EVAN CASEY, GREAT LAKES ENVIR, OBSERVED MINOR SHEEN IN TRENCH. NO SOURCE TO THE SHEEN WAS DETERMINED, SUSPECT OLD SPILLAGE MAY BE THE CAUSE. SEVERAL YARDS OF SOIL STAGED ON PLASTIC ON SITE HAD NO VISABLE CONTAMINATION. 4/11/97: WATER IN TRENCH PUMPED TO SEWER DRAIN THROUGH SORBENT MATERIAL, NO FREE PRODUCT OBSERVED. MET EARL LODER, EMERGENCY COORD. FOR CHTW, AND ADVISED HIM OF THE CURRENT STATUS, HE WILL DRIVE BY THE SITE OVER WEEKEND WHILE PUMP REMAINS ACTIVE. BOOM WAS ESTABLISHED AROUND STORM DRAINS AS A PERCAUTION. 4/14/97: JDC ON SITE AND MET W/ MR CASEY, NO NEW CONTAMINATION WAS ENCOUNTERED ALONG TRENCH LINE. SORBENT MATERIALS REMAIN IN PLACE AT THE SUMP PUMP AND STORM DRAIN. MINOR SHEEN WAS PRESENT IN THE TRENCH PUDDLES, AGAIN NO SOURCE HAS BEEN DETERMINED. WILL CONTINUE TO MONITOR SITE. 4/15/97: JDC ON SITE AND FOUND NO SHEEN OR FREE PRODUCT IN TRENCHED AND FOUNDATION AREAS. WILL CONTINUE TO MONITOR THRU THE WEEK. WHEN FOUNDATION IS COMPLETE WILL REQUEST FINAL SITE ENVIRONMENTAL REPORT. 3/10/98: RECEIVED FINAL DISPOSAL AND SAMPLING PACKAGE, FOUND INFORMATION SATISFACTORY. NO FURTHER ACTION REQUIRED, SITE CLOSED.
Remarks:	CALLER STATES THAT CONST. WAS BEING DONE ON SITE. WHILE DIGGING FOR A

VACANT MANUFACTURING SITE (Continued) **S102561458**

FOUNDATION A SHEEN WAS NOTICED ON SOME WATER. POSS MIXTURE OF FUEL OIL AND GASOLINE. MR CASEY REQUEST CALL IN AM 04/10/97 ON PAGER OR HIS CELL PHONE.

All Materials:

Site ID:	143280
Operable Unit ID:	1043249
Operable Unit:	01
Material ID:	337050
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	143280
Operable Unit ID:	1043249
Operable Unit:	01
Material ID:	337051
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	VACANT MANUFACTURING SITE
Address:	1800 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	2305260 / 2023-10-05
Facility ID:	2305260
Facility Type:	ER
DER Facility ID:	602792
Site ID:	657198
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	1530
Spill Date:	2023-09-19
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2023-09-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

VACANT MANUFACTURING SITE (Continued) **S102561458**

Date Entered In Computer:	2023-09-19
Spill Record Last Update:	2023-10-05
Spiller Name:	KEVIN AND BONNIE CHMIELOWIEC
Spiller Company:	PROPERTY OWNER
Spiller Address:	250 LAKE AVENUE
Spiller Company:	001
Contact Name:	THOMAS BOHLEN
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	9/22/23:RECEIVED A PHASE II REPORT BY GREAT LAKES ENVIRONMENTAL DATED 12/21/22 & A PHASE II REPORT BY GZA DATED 9/19/23. 10/5/23:REVIEWED PHASE II REPORTS. SOIL SAMPLE ANALTICAL RESULTS EXCEEDED SOIL GUIDANCE VALUES AND GROUNDWATER SAMPLE RESULTS EXCEEDED GROUNDWATER SAMPLES. HOWEVER, BASED ON SITE CONDITIONS, RECOMMEND INACTIVE STATUS. 10/6/23: I LETTER SENT. NO FURTHER ACION REQUIRED AT THIS TIME.
Remarks:	Metals found also. Small quantity. No further investigation is believed to be necessary. No cleanup at the moment.

All Materials:

Site ID:	657198
Operable Unit ID:	1404099
Operable Unit:	01
Material ID:	2421074
Material Code:	9999
Material Name:	other - toluene
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	657198
Operable Unit ID:	1404099
Operable Unit:	01
Material ID:	2421073
Material Code:	0854A
Material Name:	benzene
Case No.:	00071432
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

E23 **NIAGARA TRANSFORMER** **NY Spills** **S106697786**
South **1747 DALE ROAD** **N/A**
< 1/8 **BUFFALO, NY**
0.075 mi.
397 ft. **Site 1 of 5 in cluster E**

Relative: **Lower**

Actual: **653 ft.**

SPILLS:

Name:	INTERIOR TO NIAGRA TRANSF
Address:	1747 DALE RD.
City,State,Zip:	BUFFALO, NY
Spill Number/Closed Date:	0404644 / 2004-07-30
Facility ID:	0404644
Facility Type:	ER
DER Facility ID:	252099
Site ID:	312662
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1502
Spill Date:	2004-07-29
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	2004-07-29
CID:	405
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-29
Spill Record Last Update:	2004-07-30
Spiller Name:	JOHN DARBY
Spiller Company:	INTERIOR TO NIAGRA TRANSF
Spiller Address:	1747 DALE RD.
Spiller Company:	001
Contact Name:	JOHN DARBY
Latitude:	42.9048060
Longitude:	-78.7732260
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 7/30/04 FG SPOKE TO JOHN DARBY WHO SAID THE WASTE IS PLACED IN THE REGULAR WASTE STREAM. NO FURTHER WORK REQUIRED. THE SITE IS CLOSED. ELECTRONIC FILE ONLY.
Remarks:	LEAKY BUSHING ON TRANSFORMER, WAS CONATAINED AND CLEANED, WANST NEAR ANY DRAINS, DID NOT EXIT BULIDING

All Materials:

Site ID:	312662
Operable Unit ID:	887878
Operable Unit:	01
Material ID:	488624
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00

NIAGARA TRANSFORMER (Continued) **S106697786**

Units:	G
Recovered:	3.00
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE ROAD
City,State,Zip:	BUFFALO, NY
Spill Number/Closed Date:	0413613 / 2005-03-31
Facility ID:	0413613
Facility Type:	ER
DER Facility ID:	289099
Site ID:	342766
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1500
Spill Date:	2005-03-30
Investigator:	JFOTTO
Referred To:	Not reported
Reported to Dept:	2005-03-30
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-30
Spill Record Last Update:	2005-03-31
Spiller Name:	JOHN DARBY
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JOHN DARBY
Latitude:	42.9048060
Longitude:	-78.7732260
DEC Memo:	03/31/05 THIS IS A SMALL SPILL THAT WAS CLEANED UP BY THE RP. NO ACTION NECESSSARY BY SPILLS. CLOSED THERE IS NO PAPER FILE FOR THIS SPILL
Remarks:	PRODUCT CONTAINED TO THE TINSIDE OF THE BUIDING AND HAS BEEN CLEANED UP. DUE TO A LOOSE VALVE ON A LIQUID TRANSFORMER THAT IS MANUFACTURED AT THE PLANT.

All Materials:

Site ID:	342766
Operable Unit ID:	1101478
Operable Unit:	01
Material ID:	581645
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G

NIAGARA TRANSFORMER (Continued) **S106697786**

Recovered: 2.00
Oxygenate: Not reported

E24 **NIAGARA TRANSFORMER - DALE ROAD** **NY SHWS** **S107788907**
South **1747 DALE ROAD** **NY ENG CONTROLS** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225** **NY INST CONTROL**
0.075 mi. **NY Spills**
397 ft. **Site 2 of 5 in cluster E** **NY MANIFEST**

Relative:
Lower

Actual:
653 ft.

SHWS:
Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Program: HW
Site Code: 56636
Classification: Site is properly closed - requires continued management.
Region: 9
Acres: 3.590
HW Code: 915146
Record Add: 11/18/1999
Record Upd: 03/08/2023
Updated By: AECAPRIO
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

	contamination in soil, surface water and sediment is being managed under a Site Management Plan.
Health Problem:	Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1958
Disp Term:	present
Lat/Long:	42:54:13:0 / 78:46:22:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2020-11-06 14:05:00
Updated By:	DPLOCEY
Own Op:	4
Sub Type:	E
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	.
Owner City,St,Zip:	Buffalo, NY 14225
Owner Country:	United States of America
HW Code:	915146
Waste Type:	PCB-AROCLOR 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	915146
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD002106177
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2011-03-31 10:04:00
Updated By:	DADESNOY
Crossref ID:	NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code:	27
Cross Ref Type:	Alternate Site Name
Record Added Date:	2011-06-16 00:00:00
Record Updated:	2011-06-16 00:00:00
Updated By:	jdjarrat
Crossref ID:	NYD002106177
Cross Ref Type Code:	05

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

ENG CONTROLS:
Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
HW Code: 915146
Control Code: 18
Control Type: ENG
Date Record Added: 12/29/2010
Date Rec Updated: 11/17/2022
Updated By: AECAPRIO
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

	contamination in soil, surface water and sediment is being managed under a Site Management Plan.
Health Problem:	Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1958
Disp Term:	present
Lat/Long:	42:54:13:0 / 78:46:22:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2020-11-06 14:05:00
Updated By:	DPLOCEY
Own Op:	4
Sub Type:	E
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	.
Owner City,St,Zip:	Buffalo, NY 14225
Owner Country:	United States of America
HW Code:	915146
Waste Type:	PCB-AROCLOR 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	915146
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD002106177
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2011-03-31 10:04:00
Updated By:	DADESNOY
Crossref ID:	NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code:	27
Cross Ref Type:	Alternate Site Name
Record Added Date:	2011-06-16 00:00:00
Record Updated:	2011-06-16 00:00:00
Updated By:	jdjarrat
Crossref ID:	NYD002106177
Cross Ref Type Code:	05

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2001-05-10 16:31:00
Updated By:	REGTRANS
Crossref ID:	915234
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2009-03-10 13:12:00
Record Updated:	2009-03-10 13:12:00
Updated By:	DMMOLOUG
Name:	NIAGARA TRANSFORMER - DALE ROAD
Address:	1747 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Site Code:	56636
HW Code:	915146
Control Code:	15
Control Type:	ENG
Date Record Added:	12/29/2010
Date Rec Updated:	11/17/2022
Updated By:	AECAPRIO
Site Description:	Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.
Env Problem:	Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

	under a Site Management Plan.
Health Problem:	Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1958
Disp Term:	present
Lat/Long:	42:54:13:0 / 78:46:22:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2020-11-06 14:05:00
Updated By:	DPLOCEY
Own Op:	4
Sub Type:	E
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	.
Owner City,St,Zip:	Buffalo, NY 14225
Owner Country:	United States of America
HW Code:	915146
Waste Type:	PCB-AROCLOR 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	915146
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD002106177
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2011-03-31 10:04:00
Updated By:	DADESNOY
Crossref ID:	NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code:	27
Cross Ref Type:	Alternate Site Name
Record Added Date:	2011-06-16 00:00:00
Record Updated:	2011-06-16 00:00:00
Updated By:	jdjarrat
Crossref ID:	NYD002106177
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

INST CONTROL:
Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
Control Name: Monitoring Plan
HW Code: 915146
Control Code: 31
Control Type: INST
Dt record added: 12/29/2010
Dt rec updated: 11/17/2022
Updated By: AECAPRIO
Site Code: 56636
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed under a Site Management Plan.

Health Problem: Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1958
Disp Term: present
Lat/Long: 42:54:13:0 / 78:46:22:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2020-11-06 14:05:00
Updated By: DPLOCEY
Own Op: 4
Sub Type: E
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: .
Owner City,St,Zip: Buffalo, NY 14225
Owner Country: United States of America
HW Code: 915146
Waste Type: PCB-AROCLOR 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915146
Waste Type: PCB aroclor 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD002106177
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2011-03-31 10:04:00
Updated By: DADESNOY
Crossref ID: NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code: 27
Cross Ref Type: Alternate Site Name
Record Added Date: 2011-06-16 00:00:00
Record Updated: 2011-06-16 00:00:00
Updated By: jdjarrat
Crossref ID: NYD002106177

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
Control Name: Landuse Restriction
HW Code: 915146
Control Code: 25
Control Type: INST
Dt record added: 12/29/2010
Dt rec updated: 11/17/2022
Updated By: AECAPRIO
Site Code: 56636
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed under a Site Management Plan.

Health Problem: Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1958
Disp Term: present
Lat/Long: 42:54:13:0 / 78:46:22:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2020-11-06 14:05:00
Updated By: DPLOCEY
Own Op: 4
Sub Type: E
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: .
Owner City,St,Zip: Buffalo, NY 14225
Owner Country: United States of America
HW Code: 915146
Waste Type: PCB-AROCLOR 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915146
Waste Type: PCB aroclor 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD002106177
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2011-03-31 10:04:00
Updated By: DADESNOY
Crossref ID: NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code: 27
Cross Ref Type: Alternate Site Name
Record Added Date: 2011-06-16 00:00:00
Record Updated: 2011-06-16 00:00:00
Updated By: jdjarrat

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Crossref ID: NYD002106177
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
Control Name: Ground Water Use Restriction
HW Code: 915146
Control Code: 08
Control Type: INST
Dt record added: 12/29/2010
Dt rec updated: 11/17/2022
Updated By: AECAPRIO
Site Code: 56636
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.
Env Problem: Remediation at the site is complete. Prior to remediation the primary

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed under a Site Management Plan.

Health Problem: Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1958
Disp Term: present
Lat/Long: 42:54:13:0 / 78:46:22:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2020-11-06 14:05:00
Updated By: DPLOCEY
Own Op: 4
Sub Type: E
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: .
Owner City,St,Zip: Buffalo, NY 14225
Owner Country: United States of America
HW Code: 915146
Waste Type: PCB-AROCLOR 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915146
Waste Type: PCB aroclor 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD002106177
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2011-03-31 10:04:00
Updated By: DADESNOY
Crossref ID: NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code: 27
Cross Ref Type: Alternate Site Name
Record Added Date: 2011-06-16 00:00:00
Record Updated: 2011-06-16 00:00:00

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Updated By: jdjarrat
Crossref ID: NYD002106177
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
Control Name: IC/EC Plan
HW Code: 915146
Control Code: 34
Control Type: INST
Dt record added: 12/29/2010
Dt rec updated: 11/17/2022
Updated By: AECAPRIO
Site Code: 56636
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Env Problem:	Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed under a Site Management Plan.
Health Problem:	Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1958
Disp Term:	present
Lat/Long:	42:54:13:0 / 78:46:22:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2020-11-06 14:05:00
Updated By:	DPLOCEY
Own Op:	4
Sub Type:	E
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	.
Owner City,St,Zip:	Buffalo, NY 14225
Owner Country:	United States of America
HW Code:	915146
Waste Type:	PCB-AROCLOR 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	915146
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD002106177
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2011-03-31 10:04:00
Updated By:	DADESNOY
Crossref ID:	NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code:	27
Cross Ref Type:	Alternate Site Name
Record Added Date:	2011-06-16 00:00:00

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Record Updated: 2011-06-16 00:00:00
Updated By: jdjarrat
Crossref ID: NYD002106177
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
Control Name: Soil Management Plan
HW Code: 915146
Control Code: 14
Control Type: INST
Dt record added: 12/29/2010
Dt rec updated: 11/17/2022
Updated By: AECAPRIO
Site Code: 56636
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

surface. Both aquifers flow southward.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed under a Site Management Plan.
Health Problem: Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.
Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1958
Disp Term: present
Lat/Long: 42:54:13:0 / 78:46:22:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2020-11-06 14:05:00
Updated By: DPLOCEY
Own Op: 4
Sub Type: E
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: .
Owner City,St,Zip: Buffalo, NY 14225
Owner Country: United States of America
HW Code: 915146
Waste Type: PCB-AROCLOR 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915146
Waste Type: PCB aroclor 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD002106177
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2011-03-31 10:04:00
Updated By: DADESNOY
Crossref ID: NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code: 27
Cross Ref Type: Alternate Site Name

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Record Added Date: 2011-06-16 00:00:00
Record Updated: 2011-06-16 00:00:00
Updated By: jdjarrat
Crossref ID: NYD002106177
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
Control Name: Deed Restriction
HW Code: 915146
Control Code: A
Control Type: INST
Dt record added: 12/29/2010
Dt rec updated: 11/17/2022
Updated By: AECAPRIO
Site Code: 56636
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of gravel and sand overlying bedrock. The depth of the perched

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

	ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.
Env Problem:	Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed under a Site Management Plan.
Health Problem:	Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1958
Disp Term:	present
Lat/Long:	42:54:13:0 / 78:46:22:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2020-11-06 14:05:00
Updated By:	DPLOCEY
Own Op:	4
Sub Type:	E
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	John Darby
Owner Company:	Niagara Transformer Corporation
Owner Address:	1747 Dale Road
Owner Addr2:	.
Owner City,St,Zip:	Buffalo, NY 14225
Owner Country:	United States of America
HW Code:	915146
Waste Type:	PCB-AROCLOR 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	915146
Waste Type:	PCB aroclor 1260
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	NYD002106177
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2011-03-31 10:04:00
Updated By:	DADESNOY
Crossref ID:	NIAGARA TRANSFORMER CORPORATION
Cross Ref Type Code:	27

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Cross Ref Type: Alternate Site Name
Record Added Date: 2011-06-16 00:00:00
Record Updated: 2011-06-16 00:00:00
Updated By: jdjarrat
Crossref ID: NYD002106177
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

Name: NIAGARA TRANSFORMER - DALE ROAD
Address: 1747 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 56636
Control Name: Site Management Plan
HW Code: 915146
Control Code: 32
Control Type: INST
Dt record added: 12/29/2010
Dt rec updated: 11/17/2022
Updated By: AECAPRIO
Site Code: 56636
Site Description: Location: The Niagara Transformer Dale Road site is an approximately 3.59-acre site located in an urban area at 1747 Dale Road in the Town of Cheektowaga, Erie County. There is a cemetery to the west of the site, a railroad yard to the south, a vacant lot to the east and commercial buildings to the north. Site Features: There is a manufacturing facility consisting of a main building and a small storage building on the site. Current Zoning and Land Use: The site is zoned for industrial manufacturing and processing and there is currently an active electrical transformer manufacturing operation on site. Past Use of the Site: Reportedly, between 1958 and the late 1970s, waste transformer oil containing polychlorinated biphenyls (PCBs) was routinely disposed on site by spreading it in the parking lot for dust control and using it as a weed killer along the south perimeter of the site. In 1990 an oily leachate seeping into a perimeter drainage ditch was found to contain approximately 60,000 parts per million (ppm)of PCBs. Sediment samples collected immediately downstream also contained high levels of PCBs. Niagara Transformer entered into an Order on Consent with DEC and performed a Remedial Investigation/Feasibility Study (RI/FS) on site under that Order. The RI Report indicated that PCB contamination had migrated beyond the site perimeter drainage ditch. Elevated levels of PCBs were also found in the surface soil of the cemetery immediately adjacent to the site. Site Geology and Hydrogeology: The soils on site consist of a surface layer of fill material, up to 3.5 feet of asphalt and gravel subgrade, and miscellaneous shotrock and silty clay. Beneath this is a forty to fifty foot thick layer of silty clay till and clay which separates two groundwater aquifers, one perched above the clay and the other beneath, in a two to three foot layer of

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

gravel and sand overlying bedrock. The depth of the perched ground-water varies from six inches to three feet below ground surface. Both aquifers flow southward.

Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil, surface water and sediments. Remedial actions have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil, surface water and sediment is being managed under a Site Management Plan.

Health Problem: Exposures via drinking water are not expected because groundwater is not used as a drinking water source in the area. The remedial actions consisting of contaminated soil and sediment removal from on and off the site along with deed restrictions will reduce the potential for exposure.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: 1958
Disp Term: present
Lat/Long: 42:54:13:0 / 78:46:22:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2020-11-06 14:05:00
Updated By: DPLOCEY
Own Op: 4
Sub Type: E
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: NNN
Owner Name: John Darby
Owner Company: Niagara Transformer Corporation
Owner Address: 1747 Dale Road
Owner Addr2: .
Owner City,St,Zip: Buffalo, NY 14225
Owner Country: United States of America
HW Code: 915146
Waste Type: PCB-AROCLOR 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 915146
Waste Type: PCB aroclor 1260
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: NYD002106177
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2011-03-31 10:04:00
Updated By: DADESNOY
Crossref ID: NIAGARA TRANSFORMER CORPORATION

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Cross Ref Type Code: 27
Cross Ref Type: Alternate Site Name
Record Added Date: 2011-06-16 00:00:00
Record Updated: 2011-06-16 00:00:00
Updated By: jdjarrat
Crossref ID: NYD002106177
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS
Crossref ID: 915234
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2009-03-10 13:12:00
Record Updated: 2009-03-10 13:12:00
Updated By: DMMOLOUG

SPILLS:

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1308841 / 2014-11-03
Facility ID:	1308841
Facility Type:	ER
DER Facility ID:	431127
Site ID:	489601
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	1530
Spill Date:	2013-12-04
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2013-12-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-12-04
Spill Record Last Update:	2014-11-03
Spiller Name:	TED RZEPECKI
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE RD.
Spiller Company:	001
Contact Name:	TED RZEPECKI
Latitude:	42.9034814
Longitude:	-78.7724468
DEC Memo:	12/4/2013: RJJ TELECON TED RZEPECKI,NIAGARA TRANSFORMER,HE SAID THAT DUE TO HUMAN ERROW,~4 GALS. OF NON-PCB TRANSFORMER OIL(MINERAL OIL) SPILLED OUT,ALL INSIDE THEIR

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

FACILITY,ALL ON THEIR CONCRETE
FLOOR...NIAGARA TRANSFORMER PERSONNEL USED ABSORBANT PADS TO CONTAIN AND CLEANED UP THIS SPILL,THEN
THEY PLACED ALL THE SPILL MATERIAL INTO 1-55 GAL DRUM,WHICH THEY WILL DISPOSE OF...NONE OF THE OIL
REACHED ANY FLOOR DRAINS,IT WAS ALL RECOVERED...TED WILL SEND ME THE DISPOSAL RECEIPTS. 10/31/2014:
RECEIVED THE DISPOSAL RECEIPTS FOR THE 7 DRUMS OF SPILL MATERIAL TAKEN TO SPRING GROVE RESOURSE
RECOVERY,INC.,IN OHIO...THE SPILL HAS BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION
NEEDED...SPILL CLOSED OUT.

Remarks: spill to paved area in side building/clean up underway

All Materials:

Site ID:	489601
Operable Unit ID:	1239177
Operable Unit:	01
Material ID:	2239159
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	4.00
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0510258 / 2006-02-17
Facility ID:	0510258
Facility Type:	ER
DER Facility ID:	240383
Site ID:	356198
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1530
Spill Date:	2005-11-30
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2005-11-30
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2005-11-30
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-30
Spill Record Last Update:	2006-03-24
Spiller Name:	ROBERT FISHLOCK

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE ROAD
Spiller Company:	001
Contact Name:	ROBERT FISHLOCK
Latitude:	42.9048060
Longitude:	-78.7732260
DEC Memo:	11/30/2005: ROBERT FISHLOCK,NIAGARA TRANSFORMER,TELECON RJJ,HE SAID THAT A VALVE WAS LEFT OPEN,CAUSING 15 GAL OF MINERAL OIL TO SPILL ALL ON THE CONCRETE FLOOR WHILE THEY WERE FILLING TRANSFORMERS...THEY USED SPEEDY-DRY AND ABSORBANTS TO CLEAN UP AND CONTAIN THE SPILL...SINCE THEY HAVE NO FLOOR DRAINS,NONE OF THE OIL REACHED ANY WATERWAYS...MR. FISHLOCK WILL SEND ME THE ANALYTICAL RESULTS FROM THE OIL AND DISPOSAL RECEIPTS FOR THE MATERIAL...RJJ AT SITE AT 1000...MEET WITH ROBERT FISHLOCK,PLANT MANAGER,HE SHOWN AND EXPLAINED WHAT HAD HAPPENED...DUE TO HUMAN ERROR,(THE VALVE WAS LEFT OPEN)15 GAL OF MINERAL OIL SPILLED OUT FROM ONE OF THEIR LARGE TRANSFORMERS,WHICH THEY WERE FILLING UP WITH MINERAL OIL,INSIDE THEIR BUILDING...THEY PLACED ABSORBANT PADS AND SPEEDI-DRY TO SOAK UP AND CONTAIN THE SPILL...ALL THE OIL WAS CONTAINED ON CONCRETE AND RECOVERED...MR. FISHLOCK WILL SEND ME THE DISPOSAL RECEIPTS FOR THE MATERIAL. 2/17/2006: RECEIVED THE DISPOSAL RECEIPTS FOR THE MATERIAL TAKEN TO CWM LANDFILL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	MALFUNCTION IN A VALVE, CONTAINED AND IS IN PROCESS OF CLEANING UP

All Materials:

Site ID:	356198
Operable Unit ID:	1113512
Operable Unit:	01
Material ID:	2103570
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	False

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	1007053 / 2010-12-20
Facility ID:	1007053
Facility Type:	ER
DER Facility ID:	366322
Site ID:	440437
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	D3

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

SWIS:	1530
Spill Date:	2010-10-01
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2010-10-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-01
Spill Record Last Update:	2011-01-25
Spiller Name:	ROBERT FISHLOCK
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE RD
Spiller Company:	999
Contact Name:	ROBERT FISHLOCK
Latitude:	42.9034814
Longitude:	-78.7724468
DEC Memo:	10/1/2010: RJJ TELECON ROBERT FISHLOCK,NIAGARA TRANSFORMER,HE SAID THAT A FORK TRUCK PUNCTURED A 55 GAL DRUM OF MINERAL OIL,CAUSING ~3 GAL TO LEAK OUT,ALL ON THE ASHPALT PARKING LOT...NIAGARA TRANSFORMER PERSONNEL SPREAD SPEEDI DRY/ABSORBANTS TO SOAK UP & CONTAIN THE SPILL,THEN PLACED ALL THE MATERIAL IN THEIR PROFILIED DUMPSTER,WHICH THEY WILL DISPOSE OF,WHEN IT GETS FULL...NONE OF THE OIL REACHED ANY SOIL OR WATERWAYS...ALL THE MINERAL OIL HAS BEEN REMOVERED...MR. FISHLOCK WILL SEND ME THE DISPOSAL RECEIPTS. 12/20/2010: RECEIVED THE DISPOSAL RECEIPTS FOR THE MATERIAL TAKEN TO SPRING GROVE RESOURCE RECOVERY INC.,IN OHIO...THE SPILL HAS BEEN CLEANED UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	fork truck punctured drum onto pavement and concrete. Clean up complete

All Materials:

Site ID:	440437
Operable Unit ID:	1191053
Operable Unit:	01
Material ID:	2186162
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER SITE

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Address:	1747 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1212665 / 2012-12-19
Facility ID:	1212665
Facility Type:	ER
DER Facility ID:	431127
Site ID:	475819
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1530
Spill Date:	2012-11-27
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2012-11-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-27
Spill Record Last Update:	2012-12-19
Spiller Name:	BOB FISHLOCK
Spiller Company:	NIAGARA TRANSFORMER SITE
Spiller Address:	1747 DALE RD
Spiller Company:	001
Contact Name:	BOB FISHLOCK
Latitude:	42.9034814
Longitude:	-78.7724468
DEC Memo:	11/27/12:SAC INSPECT SITE. MET W/BOB FISHLOCK - NIAGARA TRANSFORMER. MR. FISHLOCK SAID NIAGARA TRANSFORMER IS A MANUFACTURER OF NEW TRANSFORMERS. THEY HAD COMPLETED A UNIT THAT WAS READY TO BE FILLED W/THE SOYBEAN BASED DIELECTRIC FLUID. HOWEVER, THEY FORGOT TO INSTALL A VALVE AND HAD DUCT TAPE COVERING THE PORT. THEY BEGAN TO FILL UP THE UNIT AND ONCE THERE WAS ENOUGH ELEVATION HEAD PRESSURE, THE DUCT TAPE FAILED TO HOLD AND THE PRODUCT SPILLED TO THE FLOOR. ABSORBENT PADS AND SPEEDI-DRY WERE APPLIED TO THE AREA. THE SPILL AREA WAS AROUND AND IN THE IMMEDIATE VICINITY OF THE UNIT. THEY WILL LIFT THE UNIT UP TO CLEAN UP THE PRODUCT THAT LEAKED UNDER IT. RECEIVED COPY OF THE MSDS. MR. FISHLOCK SAID THEY WILL SEND IN DISPOSAL RECEIPTS. HE ANTICIPATES DISPOSAL WILL TAKE PLACE IN THE JANUARY-FEBRUARY TIME FRAME WHEN THEY HAVE A SCHEDULED PICK UP. 12/19/12:RECEIVED DISPOSAL RECEIPT. NO FURTHER WORK IS REQUIRED. NO PAPER FILE.
Remarks:	Soy Bean base fluid spilled onto painted floor inside the site, contained. Cleanup is underway.

All Materials:

Site ID:	475819

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Operable Unit ID:	1225659
Operable Unit:	01
Material ID:	2222942
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9000362 / 1990-04-24
Facility ID:	9000362
Facility Type:	ER
DER Facility ID:	240383
Site ID:	297062
DEC Region:	9
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	1530
Spill Date:	1990-04-10
Investigator:	LYONS
Referred To:	Not reported
Reported to Dept:	1990-04-10
CID:	Not reported
Water Affected:	SLOAN DITCH
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	1990-04-24
Cleanup Meets Std:	True
Last Inspection:	1990-04-13
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-04-24
Spill Record Last Update:	1990-05-02
Spiller Name:	Not reported
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE ROAD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9045580
Longitude:	-78.7722390
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 04/10/90: MEL INSPECTION. OILY SUBSTANCE LEAKING INTO DRAINAGE DITCH. BOOMS PLACED IN DITCH, AND SAMPLES TAKEN. NIAGARA TRANSFORMER NOTIFIED. CONTAINMENT ACCOMPLISHED BY NIAGARA TRANSFORMER. 04/11/90: MEL/RNL INSPECTION. MET WITH COMPANY OFFICIALS TO DISCUSS CONTAINMENT, AND INVESTIGATIVE MEASURES. 5.7% PCB'S FOUND IN OIL SAMPLE BY ACTS TESTING LAB. RNL CONTACTED SOLID

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Remarks: WASTE. 04/12/90: MEETING AT DEC
SOLID WASTE DIVISION. IT WAS AGREED THAT SOLID WASTE WOULD OVERSEE INVESTIGATION AND REMEDIATION.
ALSO MET AT NIAGARA TRANS. WITH SOLID WASTE PERSONNEL TO REVIEW SITE.
04/13/90: MEL INSPECTION. MET
DAVE LOCEY, ENVIRONMENTAL OIL, AND NIAGARA TRANS. OFFICIALS ON SITE TO OVERSEE INSTALLATION OF PIPE
DAMS, AND SAMPLING. SPILL GROUP NO LONGER INVOLVED, FILE TO BE CLOSED.
UNKNOWN OILY SUBSTANCE BLEEDING INTO DRAINAGE DITCH FROM DITCH BANK, PCB LEAKAGE PROBABLY FROM OLD DUMP SITE

All Materials:

Site ID:	297062
Operable Unit ID:	938702
Operable Unit:	01
Material ID:	438759
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9704159 / 1999-08-23
Facility ID:	9704159
Facility Type:	ER
DER Facility ID:	240383
Site ID:	297063
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	1530
Spill Date:	1997-05-23
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	1997-05-23
CID:	999
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1997-05-23
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-08
Spill Record Last Update:	1999-10-08
Spiller Name:	JOHN DARBY
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	PO BOX 233
Spiller Company:	001

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Contact Name:	Not reported
Latitude:	42.9045580
Longitude:	-78.7722390
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 05/23/97: MNP SITE INSPECTION, MET FRED DARBY OF NIAGARA TRANSFORMER, CLEANUP UNDERWAY, SPILL ONTO PARKING LOT AND SURRONDING GROUND 05/28/97: MNP TELECON TO ROBERT LOCEY, HE SAID OK TO DISPOSE AS NON-PCB OIL 05/28/97: MNP TELECON TO FRED DARBY, NEED DISPOSAL RECEIPTS 07/16/98: SENT LETTER TO NIAGARA TRANSFORMER REQUESTING A DISPOSAL RECEIPT 08/12/99: TELECON TO BILL POWERS WITH NIAGARA TRANSFORMER. HE SAID HE WILL SUBMIT DISPOSAL RECEIPTS ALONG WITH A COVER LETTER EXPLAINING THE DOCUMENTATION. 08/13/99: RECEIVED DISPOSAL RECEIPTS. NO FURTHER WORK IS REQUIRED. SITE CAN BE CLOSED.
Remarks:	A TRANSFORMER WAS OVERFILLED SPILLING OIL ONTO THE DOCK - SPILL HAS BEEN CONTAINED AND NIAGRA TRANSPORTATION WILL BE CLEANING IT UP

All Materials:

Site ID:	297063
Operable Unit ID:	1047383
Operable Unit:	01
Material ID:	333418
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	400.00
Units:	G
Recovered:	400.00
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0304482 / 2003-12-05
Facility ID:	0304482
Facility Type:	ER
DER Facility ID:	240383
Site ID:	297060
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	1530
Spill Date:	2003-07-28
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2003-07-28
CID:	418
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-28
Spill Record Last Update:	2006-03-24
Spiller Name:	JOHN DARBY
Spiller Company:	NIAGARA TRASFORMER
Spiller Address:	1747 DALE ROAD
Spiller Company:	001
Contact Name:	JOHN DARBY
Latitude:	42.9045580
Longitude:	-78.7722390
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 7/29/2003: RJJ TELECON JOHN DARBY,NIAGARA TRANSFORMER,HE SAID THAT ONE OF THEIR OIL PROCESSING PLANT PIECES OF EQUIPMENT BROKE,SPILLING 20 GAL OF MINERAL OIL,ALL ON THE CONCRETE FLOOR...THEY SPREAD SPEEDY-DRY ON IT AND PLACED ABSORBANT PADS TO CONTAIN THE SPILL...NONE OF THE MINERAL OIL REACHED ANY RECEIVERS,IT WAS ALL CONTAINED...JOHN WILL HAVE WASTE-STREAM PICK UP THE MATERIAL AND SEND ME THE RECEIPTS. 12/5/2003: RECEIVED THE DISPOSAL RECEIPTS FOR THE 2-55 GAL DRUMS OF WASTE MATERIAL...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	SPILL HAS BEEN CLEANED UP USING PADS AND SPEEDY DRI. THE SPILL IS FROM A OIL PROCESSING PLANT EQUIPMENT.

All Materials:

Site ID:	297060
Operable Unit ID:	871296
Operable Unit:	01
Material ID:	505338
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9000361 / 1990-04-24
Facility ID:	9000361
Facility Type:	ER
DER Facility ID:	240383
Site ID:	297061
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	1530
Spill Date:	1990-04-10

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Investigator:	LYONS
Referred To:	Not reported
Reported to Dept:	1990-04-10
CID:	Not reported
Water Affected:	SLOAN DITCH
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	1990-04-13
Cleanup Meets Std:	True
Last Inspection:	1990-04-13
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-04-24
Spill Record Last Update:	1990-05-02
Spiller Name:	Not reported
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE ROAD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9045580
Longitude:	-78.7722390
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 04/10/90: MEL INSPECTION. MET RON GODFREY ON SITE. POOR HOUSEKEEPING AT DRUM STORAGE AREA RESULTING IN CONTAMINATION OF APPROX. 150' OF DITCH. INFORMED NIAGARA TRANSFORMER THAT DITCH NEEDED TO BE EXCAVATED. 04/11/90: MEL/RNL INSPECTION. MET WITH COMPANY OFFICIALS TO DISCUSS CLEAN UP REQUIREMENTS. PCB'S FOUND AT SITE, RNL CONTACTED SOLID WASTE. 04/12/90: MEETING AT DEC SOLID WASTE DIVISION. SOLID WASTE TO OVERSEE SITE REMEDIATION DUE TO PRESENCE OF PCB'S. SPILL GROUP WILL NO LONGER BE INVOLVED. 04/13/90: MEL/ DAVE LOCEY INSPECTION. MET ENVIRONMENTAL OIL, AND NIAGARA TRANS. OFFICIALS ON SITE TO OVERSEE INSTALLATION OF PIPE DAMS AND SAMPLING. NO FURTHER ACTION REQUIRED BY SPILL GROUP, FILE TO BE CLOSED.
Remarks:	RUN OFF FROM DRUM STORAGE AREA DRAINING INTO STORM SYSTEM.

All Materials:

Site ID:	297061
Operable Unit ID:	939741
Operable Unit:	01
Material ID:	438758
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	TRUCK AT NIAGARA TRANSFOR
Address:	1747 DALE ROAD

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9714125 / 1998-11-09
Facility ID:	9714125
Facility Type:	ER
DER Facility ID:	240383
Site ID:	297064
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1530
Spill Date:	1998-03-20
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1998-03-20
CID:	999
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1998-03-20
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-20
Spill Record Last Update:	1998-12-03
Spiller Name:	ALAN MURRAY
Spiller Company:	FLEET TRANSPORT COMPANY
Spiller Address:	2926 WEST MAIN ROAD
Spiller Company:	001
Contact Name:	JOHN DARBY
Latitude:	42.9045580
Longitude:	-78.7722390
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 03/20/98: MJS SITE INSPECT. MET WITH ALAN MURRAY(FLEET). APPROX FIVE GALLONS SPILLED FROM VALVE UNDER TANKER. FLEET SPREAD SPEEDI-DRI. THEY HIRED OHM INC(NOT YET ON SITE) TO CLEAN SPILL AND DISPOSE. THEY WILL FORWARD DISPOSAL RECEIPT. 3/20/98 - KAB/EARL LODER, CHEEKTOWAGA DISASTER COORDINATOR/TELECON - SPILLAGE WAS APPROXIMATELY 10 GALS. OF MINERAL OIL TO SOIL; NONE WENT TO MONITORING WELLS. SOIL WAS REMOVED BY OHM, CONTRACTOR HIRED BY NIAGARA TRANSFORMER TO PERFORM CLEANUP. 07/15/98: MJS REVIEW FILE. NEED DISPOSAL DOCUMENTATION. MJS TELECON TO RP. LEFT MESSAGE FOR ALAN MURRAY TO CALL REGARDING DISPOSAL. 07/15/98: MJS TELECON FROM MR MURRAY. HE WILL LOCATE COPY OF DISPOSAL RECEIPT AND FORWARD. 10/20/98: MJS REVIEW FILE. STILL NEED DISPOSAL RECEIPT. MJS TELECON TO ALAN MURRAY. HE STATED THAT SAFETY OFFICE WAS SUPPOSED TO FORWARD THE DOCUMENTATION AFTER OUR LAST CONVERSATION. HE STATED THAT HE WOULD OBTAIN THE DOCUMENTATION AND FORWARD TO ME. 11/09/98: RECEIVED DISPOSAL MANIFEST FOR WASTE. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE.
Remarks:	spillage of 10-50 gals of mineral oil to parking lot while filling

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

tank (a/g). no safety switch

All Materials:

Site ID:	297064
Operable Unit ID:	1056994
Operable Unit:	01
Material ID:	325099
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Oxygenate:	Not reported

Name:	IN PARKING LOT
Address:	1747 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0614044 / 2007-04-03
Facility ID:	0614044
Facility Type:	ER
DER Facility ID:	240383
Site ID:	379214
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	1530
Spill Date:	2007-03-31
Investigator:	sacaland
Referred To:	Not reported
Reported to Dept:	2007-03-31
CID:	41
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-03-31
Spill Record Last Update:	2007-04-03
Spiller Name:	BOB FISHLOCK
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE ROAD
Spiller Company:	001
Contact Name:	ABOVE
Latitude:	42.9034814
Longitude:	-78.7724468
DEC Memo:	4/3/07:RECEIVED DISPOSAL RECEIPT. SMALL NUISANCE SPILL - NO FURTHER ACTION REQUIRED.
Remarks:	DRIVER IN VEHICLE PARKED IN LOT - NO GAS CAP ON TRUCK, POSSIBLY CAUSING SPILL WHEN VEHICLE WAS MOVED

All Materials:

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Site ID:	379214
Operable Unit ID:	1136703
Operable Unit:	01
Material ID:	2126651
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1747 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0904993 / 2009-07-30
Facility ID:	0904993
Facility Type:	ER
DER Facility ID:	366322
Site ID:	417226
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1530
Spill Date:	2009-07-30
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2009-07-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-07-30
Spill Record Last Update:	2009-07-30
Spiller Name:	BOB FISHLOCK
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE RD
Spiller Company:	999
Contact Name:	BOB FISHLOCK
Latitude:	42.9034814
Longitude:	-78.7724468
DEC Memo:	07/30/09 RMC/SITE. MINOR SPILL TO CONCRETED INSIDE. NO SEWERS IMPACTED. REPORTED AS BEING CLEANED UP. NO ACTION REQUIRED. CLOSE OUT. NO PAPER FILE.
Remarks:	LEVEL GAUGE FAILED RESULTING IN AN OVER FILL ABOUT 7 GALLON SPILLED TO CONCRETE. CLEAN UP WAS DONE.

All Materials:

Site ID:	417226
Operable Unit ID:	1173461

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Operable Unit:	01
Material ID:	2165387
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7.00
Units:	G
Recovered:	7.00
Oxygenate:	Not reported

Click this hyperlink while viewing on your computer to access
5 additional NY SPILL: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYD002106177
Country:	USA
Name:	Niagara Transformer Corp
Address:	1747 DALE RD
Address 2:	Not reported
City,State,Zip:	BUFFALO,, NY 14225
Zip 4:	Not reported
Location Address 1:	1747 DALE ROAD
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Niagara Transformer Corp
Mailing Contact:	Gabel Herman Exec Vp
Mailing Address 1:	PO BOX 233
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168966500

Manifest Data:

Document ID:	NYA3440878
Manifest Status:	C - Completed copy
Trans1 State ID:	46937ANY
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880630
Trans1 Recv Date:	880630
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880630
Part A Recv Date:	880706
Part B Recv Date:	880712
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	NYD043815703
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NYG2632536
Manifest Status:	Not reported
Trans1 State ID:	33447MA
Year:	2001
Trans2 State ID:	H205
Generator Ship Date:	02/23/2001
Trans1 Recv Date:	02/23/2001
Trans2 Recv Date:	02/28/2001
TSD Site Recv Date:	03/05/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	OHD009865825
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00200
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG2633031
Manifest Status:	Not reported
Trans1 State ID:	619006ME
Year:	2001
Trans2 State ID:	619006ME
Generator Ship Date:	03/21/2001
Trans1 Recv Date:	03/21/2001
Trans2 Recv Date:	03/22/2001
TSD Site Recv Date:	04/06/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	MAD039322250
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00400
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG2633643
Manifest Status:	Not reported
Trans1 State ID:	33447MA
Year:	2001
Trans2 State ID:	PUF2912OH

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Generator Ship Date:	05/16/2001
Trans1 Recv Date:	05/16/2001
Trans2 Recv Date:	05/22/2001
TSD Site Recv Date:	06/11/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	OHD009865825
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Waste Code 11:	Not reported
Quantity:	00350
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYG2634651
Manifest Status:	Not reported
Trans1 State ID:	614198ME
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	06/20/2001
Trans1 Recv Date:	06/20/2001
Trans2 Recv Date:	06/21/2001
TSD Site Recv Date:	07/06/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	MAD039322250
Trans2 EPA ID:	OHD009865825
TSDF ID 1:	OHD000816629
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00550
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Document ID:	NYH0648729
Manifest Status:	Not reported
Trans1 State ID:	P206995IL
Year:	2003
Trans2 State ID:	Not reported
Generator Ship Date:	08/15/2003
Trans1 Recv Date:	08/15/2003
Trans2 Recv Date:	08/22/2003
TSD Site Recv Date:	08/25/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	NJD080631369
Trans2 EPA ID:	NYD982792814
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00400
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYB8183835
Manifest Status:	Not reported
Trans1 State ID:	35684CNY
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	07/24/1997
Trans1 Recv Date:	07/24/1997

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	17826
Units:	Kilograms
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB8183844
Manifest Status:	Not reported
Trans1 State ID:	XC90486PA
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	07/24/1997
Trans1 Recv Date:	07/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	PAD987347515
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	22471
Units:	Kilograms
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	NYB8183853
Manifest Status:	Not reported
Trans1 State ID:	XC58819PA
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	07/24/1997
Trans1 Recv Date:	07/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	NYD046765574
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	18888
Units:	Kilograms
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

Specific Gravity:	01.00
Document ID:	NYB8183862
Manifest Status:	Not reported
Trans1 State ID:	NY67278K
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	07/24/1997
Trans1 Recv Date:	07/24/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/24/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	NYD000688671
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	22154
Units:	Kilograms
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00
Document ID:	NYB8183871
Manifest Status:	Not reported
Trans1 State ID:	XA99516PA
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	07/22/1997
Trans1 Recv Date:	07/22/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD002106177
Trans1 EPA ID:	PAD987347515
Trans2 EPA ID:	Not reported

NIAGARA TRANSFORMER - DALE ROAD (Continued) **S107788907**

TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B007
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	21791
Units:	Kilograms
Number of Containers:	001
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
1302 additional NY MANIFEST: record(s) in the EDR Site Report.

E25
South
< 1/8
0.075 mi.
397 ft.

PLANT **NY Spills** **S113915709**
1747 DALE RD **N/A**
CHEEKTOWAGA, NY 14225

Site 3 of 5 in cluster E

Relative:
Lower

Actual:
653 ft.

SPILLS:

Name:	PLANT
Address:	1747 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1305910 / 2014-11-03
Facility ID:	1305910
Facility Type:	ER
DER Facility ID:	431127
Site ID:	486496
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	1530
Spill Date:	2013-09-04
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2013-09-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other

PLANT (Continued) **S113915709**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-09-05
Spill Record Last Update:	2014-11-04
Spiller Name:	BOB FISHLOCK
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1747 DALE RD
Spiller Company:	001
Contact Name:	BOB FISHLOCK
Latitude:	42.9034814
Longitude:	-78.7724468
DEC Memo:	9/5/2013: RJJ TELECON BOB FISHLOCK,NIAGARA TRANSFORMER,HE SAID THAT LAST NIGHT,AN EMPLOYEE OVERFILLED A TRANSFORMER,DUE TO HUMAN ERROR,CAUSING ~10-15 GALS. OF SOY-BASED MINERAL OIL TO SPILL OUT,ALL ONTO THEIR CONCRETE FLOOR...SINCE THER ARE NO FLOOR DRAINS,ALL THE OIL POOLED/REMAINED IN A SMALL AREA,UNTIL THE NEXT MORNING,THEN NIAGARA TRANSFORMER PERSONNEL USED ABSORBANTS TO CLEAN-UP THE SPILL...THEY PLACED ALL THE SPILL MATERIAL INTO A DRUM,WHICH WILL BE DISPOSED OF...ALL OF THE SPILL HAS BEEN RECOVERED...BOB FISHLOCK WILL SEND ME THE DISPOSAL RECEIPTS. 11/3/2014: RECEIVED THE DISPOSAL RECEIPTS FOR THE SPILL MATERIAL TAKEN TO SPRING GROVE RESOURSE RECOVERY,INC.,IN OHIO...THE SPILL HAS BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	Contained to floor only no drains - cleaned up

All Materials:

Site ID:	486496
Operable Unit ID:	1236145
Operable Unit:	01
Material ID:	2235487
Material Code:	9999
Material Name:	other - envirotemp/soy based oil
Case No.:	Not reported
Material FA:	Other
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

E26
South
< 1/8
0.075 mi.
397 ft.

NIAGARA TRANSFORMER CORPORATION
1747 DALE ROAD
BUFFALO, NY 14225

Site 4 of 5 in cluster E

CORRACTS **1000232791**
RCRA-SQG **NYD002106177**
2020 COR ACTION
US AIRS
E MANIFEST

Relative:
Lower

Actual:
653 ft.

CORRACTS:

Name:	NIAGARA POWER TRANSFORMER
Address:	1747 DALE RD
Address 2:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: RFA COMPLETED
Actual Date: 19900928
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: CA PRIORITIZATION-LOW CA PRIORITY
Actual Date: 19910321
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: DETERMINATION OF NEED FOR AN INVESTIGATION
Actual Date: 19910321
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: INVESTIGATION IMPOSITION
Actual Date: 19910321
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: INVESTIGATION WORKPLAN APPROVED
Actual Date: 19910321
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: INVESTIGATION COMPLETE
Actual Date: 19931230
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: CMS COMPLETE
Actual Date: 19931230
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: REMEDY DECISION
Actual Date: 19931230
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: CMI WORKPLAN APPROVED
Actual Date: 19950930
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: REMEDY CONSTRUCTION
Actual Date: 19970730
Air Release Indicator: Not reported
Groundwater Release Indicator: Y

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Soil Release Indicator: Y
Surface Water Release Indicator: Y

Name: NIAGARA POWER TRANSFORMER
Address: 1747 DALE RD
Address 2: Not reported
EPA ID: NYD002106177
Area Name: SITEWIDE
Corrective Action: STABILIZATION/INTERIM MEASURES DECISION
Actual Date: 19910321
Air Release Indicator: Not reported
Groundwater Release Indicator: Y
Soil Release Indicator: Y
Surface Water Release Indicator: Y

Click this hyperlink while viewing on your computer to access
7 additional CORRACTS: record(s) in the EDR Site Report.

RCRA Listings:
Date Form Received by Agency: 20210223
Handler Name: Niagara Power Transformer
Handler Address: Dale Rd
Handler City,State,Zip: BUFFALO, NY 14225
EPA ID: NYD002106177
Contact Name: KARL R SCHURKUS
Contact Address: DALE RD
Contact City,State,Zip: BUFFALO, NY 14225
Contact Telephone: 716-896-6500 x160
Contact Fax: 716-896-8871
Contact Email: KSCHURKUS@NPTRANSFORMER.COM
Contact Title: SAFETY MANAGER
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities, Corrective Action Activities
State District Owner: Ny
State District: NYSDEC R9
Mailing Address: DALE RD
Mailing City,State,Zip: BUFFALO, NY 14225
Owner Name: Niagara Power Transformer
Owner Type: Private
Operator Name: Niagara Power Transformer
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No
Off-Site Waste Receipt: No
Universal Waste Indicator: No

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	Yes
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	Yes
Corrective Action Priority Ranking:	Low
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	Yes
Groundwater Controls Indicator:	Yes
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210304
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2,

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F017
Waste Description: Not Defined

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NIAGARA TRANSFORMER CORPORATION
Legal Status: Private
Date Became Current: 19580101
Date Ended Current: Not reported
Owner/Operator Address: 1747 DALE ROAD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NIAGARA TRANSFORMER CORPORATION
Legal Status: Private
Date Became Current: 19580101
Date Ended Current: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Owner/Operator Address: 1747 DALE ROAD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NIAGARA TRANSFORMER CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NIAGARA TRANSFORMER CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NIAGARA TRANSFORMER CORPORATION
Legal Status: Private
Date Became Current: 19580101
Date Ended Current: Not reported
Owner/Operator Address: 1747 DALE ROAD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NIAGARA TRANSFORMER CORPORATION
Legal Status: Private
Date Became Current: 19580101
Date Ended Current: Not reported
Owner/Operator Address: 1747 DALE ROAD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NIAGARA POWER TRANSFORMER

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Legal Status: Private
Date Became Current: 20210201
Date Ended Current: Not reported
Owner/Operator Address: 1747 DALE RD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 716-896-6500
Owner/Operator Telephone Ext: 160
Owner/Operator Fax: 716-896-8871
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NIAGARA TRANSFORMER CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NIAGARA POWER TRANSFORMER
Legal Status: Private
Date Became Current: 19580101
Date Ended Current: Not reported
Owner/Operator Address: 1747 DALE RD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 716-896-6500
Owner/Operator Telephone Ext: 160
Owner/Operator Fax: 716-896-8871
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20100305
Handler Name: NIAGARA TRANSFORMER CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: NIAGARA TRANSFORMER CORPORATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NIAGARA TRANSFORMER CORPORATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20151029
Handler Name: NIAGARA TRANSFORMER CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19801211
Handler Name: NIAGARA TRANSFORMER CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210223
Handler Name: NIAGARA POWER TRANSFORMER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19900301

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Handler Name: NIAGARA TRANSFORMER CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920414
Handler Name: NYD002106177
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: NIAGARA TRANSFORMER CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020226
Handler Name: NIAGARA TRANSFORMER CORPORATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332312
NAICS Description: Fabricated Structural Metal Manufacturing

NAICS Code: 332322
NAICS Description: Sheet Metal Work Manufacturing

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

NAICS Code: 335311
NAICS Description: Power, Distribution, And Specialty Transformer Manufacturing

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20181012
Actual Return to Compliance Date:	20181022
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20181022
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYBMN
Enforcement Responsible Sub-Organization:	R9
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20150708
Actual Return to Compliance Date:	20150813
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150717
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYKHE
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20150708
Actual Return to Compliance Date: 20150813
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150717
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYKHE
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD IS-Container Use and Management
Date Violation was Determined:	20150708
Actual Return to Compliance Date:	20150813
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20150717
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYKHE
Enforcement Responsible Sub-Organization:	R9
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20120801
Actual Return to Compliance Date:	20120801
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20120803
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYTRN
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20120801
Actual Return to Compliance Date: 20120801
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20120803
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYTRN
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Records/Reporting
Date Violation was Determined: 20090305
Actual Return to Compliance Date: 20100427
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20090305
Actual Return to Compliance Date: 20100427
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20090305
Actual Return to Compliance Date:	20100427
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20090305
Actual Return to Compliance Date:	20100427
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20080905
Actual Return to Compliance Date: 20081027
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20080917
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20081113
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYNSL
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20020228
Actual Return to Compliance Date: 20020325
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20020304
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19951214
Actual Return to Compliance Date: 19960223
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19960114
Enforcement Identifier: 000
Date of Enforcement Action: 19951214
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYRFR
Enforcement Responsible Sub-Organization:	R9
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19870911
Actual Return to Compliance Date:	19871007
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19871011
Enforcement Identifier:	001
Date of Enforcement Action:	19870911
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20181012
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYBMN
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: 20181022
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20150708
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYKHE
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: 20150813
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20150708
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYKHE
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: 20150813
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20150708
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYKHE
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: 20150813
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Evaluation Date:	20120801
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTRN
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20120801
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20120801
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTRN
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20120801
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20100427
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYNSL
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20090305
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTCT
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20100427
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20090305
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTCT

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20100427
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20090305
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTCT
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20100427
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20090305
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYTCT
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20100427
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20080905
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYNSL
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20081027
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20061116
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYALS
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20040129
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYEFT
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20020228
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRWK
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20020325
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19991109
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRFR
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19951205
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRFR
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	19960223
Scheduled Compliance Date:	19960114
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19871022
Evaluation Responsible Agency:	State

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19870911
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19871007
Scheduled Compliance Date:	19871011
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19870609
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19851101
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

2020 COR ACTION:

EPA ID:	NYD002106177
Region:	2
Action:	Remedy Construction

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

US AIRS MINOR:

Envid:	1000232791
Region Code:	02
Programmatic ID:	AIR NY0000009143000081
Facility Registry ID:	110000738934
D and B Number:	Not reported
Primary SIC Code:	3612
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000009143000081
Facility Registry ID:	110000738934
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-09-05 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

E MANIFEST:

Manifest Tracking Number:	013726350FLE
Last Updated Date:	20201217
Shipped Date:	20201203
Received Date:	20201208
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD002106177
Generator Name:	Niagara Transformer Corporation
Generator Location Street Number:	1747
Generator Location Street 1:	1747 DALE ROAD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	1747
Generator Mail Street 1:	DALE ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	1923
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Designated Facility Mail State:	MI
Designated Facility Location Street Number:	1923
Designated Facility Location Street 1:	FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	011525952FLE
Last Updated Date:	20180928
Shipped Date:	20180820
Received Date:	20180828
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYD002106177
Generator Name:	Niagara Transformer Corporation
Generator Location Street Number:	Not reported
Generator Location Street 1:	1747 DALE ROAD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1747 DALE ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	011525952FLE
Transporter Line Number:	1
Transporter EPA ID:	NYD097644801
Transporter Name:	Tonawanda Tank Transport Service Inc.

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Waste Line:

Manifest Tracking Number:	011525952FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Rq, Un1263, Waste Paint, 3, Pgii, (F003, F005, D001), Erg#128
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	55
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.2293578
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2293578
Waste Quantity, in Kilograms:	208.03441
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	208.03441
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D035, F003, F005
Quantity Haz Kg:	208.03441
Quantity Haz Tons:	0.2293578
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

Manifest Tracking Number:	011525952FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Non Hazardous Liquid
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	55
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.2293578
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2293578

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Waste Quantity, in Kilograms:	208.03441
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	208.03441
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	208.03441
Quantity Non Haz Tons:	0.2293578
State Waste Codes:	MI-021L

Manifest Tracking Number:	011525952FLE
Waste Line Number:	3
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Fuels Debris
Number of Containers:	1
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	150
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.075
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.075
Waste Quantity, in Kilograms:	68.02725
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	68.02725
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported

NIAGARA TRANSFORMER CORPORATION (Continued) **1000232791**

Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	68.02725
Quantity Non Haz Tons:	0.075
State Waste Codes:	Not reported
Manifest Tracking Number:	011525952FLE
Waste Line Number:	4
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Non Hazardous Solid
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	400
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.2
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2
Waste Quantity, in Kilograms:	181.406
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	181.406
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	181.406
Quantity Non Haz Tons:	0.2
State Waste Codes:	Not reported

C27
North
< 1/8
0.078 mi.
412 ft.

MULLER TOOL
74 ANDERSON ROAD
CHEEKTOWAGA, NY

Site 4 of 4 in cluster C

NY Spills **S104497580**
N/A

Relative:
Lower

Actual:
653 ft.

SPILLS:

Name:	MULLER TOOL
Address:	74 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	8705639 / 1987-10-13
Facility ID:	8705639
Facility Type:	ER
DER Facility ID:	265186
Site ID:	329614
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	1530
Spill Date:	1987-10-02
Investigator:	ROSS
Referred To:	Not reported
Reported to Dept:	1987-10-02
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1987-10-13
Cleanup Meets Std:	True
Last Inspection:	1987-10-13
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-07
Spill Record Last Update:	1987-10-26
Spiller Name:	Not reported
Spiller Company:	MULLER TOOL, INC.
Spiller Address:	74 ANDERSON ROAD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9060268
Longitude:	-78.7716550
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : LQR ON SITE 10/13/87 SPILLER CLEANED UP NO FURTHER ACTION NECESSARY.
Remarks:	SLOPPY HOUSEKEEPING

All Materials:

Site ID:	329614
Operable Unit ID:	909463
Operable Unit:	01
Material ID:	468224
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

MULLER TOOL (Continued) **S104497580**

Site ID:	329614
Operable Unit ID:	909463
Operable Unit:	01
Material ID:	468223
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

F28 **BUFFALO CLUTCH CO INC** **RCRA-VSQG** **1000227774**
ESE **1810 DALE RD** **FINDS** **NYD986887172**
< 1/8 **CHEEKTOWAGA, NY 14225** **ECHO**
0.086 mi. **NY MANIFEST**
455 ft. **Site 1 of 4 in cluster F**

Relative: **Lower**
Actual: **654 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Buffalo Clutch Co Inc
Handler Address:	Dale Rd
Handler City,State,Zip:	CHEEKTOWAGA, NY 14225
EPA ID:	NYD986887172
Contact Name:	Not reported
Contact Address:	DALE RD
Contact City,State,Zip:	CHEEKTOWAGA, NY 14225
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R9
Mailing Address:	DALE RD
Mailing City,State,Zip:	CHEEKTOWAGA, NY 14225
Owner Name:	Donald Hebenstreit & Eugene Walters
Owner Type:	County
Operator Name:	Donald Hebenstreit & Eugene Walters
Operator Type:	County
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DONALD HEBENSTREIT & EUGENE WALTERS
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DONALD HEBENSTREIT & EUGENE WALTERS
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: DONALD HEBENSTREIT & EUGENE WALTERS
Legal Status: County
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990714
Handler Name: BUFFALO CLUTCH CO INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: BUFFALO CLUTCH CO INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BUFFALO CLUTCH CO INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Electronic Manifest Broker: Not reported

Receive Date: 19900116
Handler Name: BUFFALO CLUTCH CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20010511
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRFR
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19980918
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	R2LV

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004440766

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000227774
Registry ID:	110004440766

DFR URL:

Name:	BUFFALO CLUTCH CO INC
Address:	1810 Dale Rd
City,State,Zip:	CHEEKTOWAGA, NY 14225

NY MANIFEST:

EPA ID:	NYD986887172
Country:	USA
Name:	Buffalo Clutch Company
Address:	1810 DALE RD
Address 2:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14225
Zip 4:	Not reported
Location Address 1:	1810 DALE ROAD
Location Address 2:	Not reported
Location City,State,Zip:	CHEEKTOWAGA, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Buffalo Clutch Company
Mailing Contact:	Eugene Walters
Mailing Address 1:	1810 DALE ROAD
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Mailing Phone: 7168922828

Manifest Data:
Document ID: NYC3134057
Manifest Status: Not reported
Trans1 State ID: NYHJ192
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 08/10/1994
Trans1 Recv Date: 08/10/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/11/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986887172
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00076
Units: Gallons (liquids only)
Number of Containers: 005
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00
Waste Code 7: Ignitable Waste
Waste Code 8: Not reported
Waste Code: Not reported
Waste Code 10: Not reported
Waste Code 11: Not reported
Quantity: 00007
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYC5038953
Manifest Status: Not reported

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Trans1 State ID:	PJ4696
Year:	1998
Trans2 State ID:	Not reported
Generator Ship Date:	03/31/1998
Trans1 Recv Date:	03/31/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/31/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00022
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC1539303
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	03/30/1992
Trans1 Recv Date:	03/30/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/30/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00661
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC2291488
Manifest Status:	Not reported
Trans1 State ID:	NYHJ9192
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	05/18/1993
Trans1 Recv Date:	05/18/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/18/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Quantity: 00075
Units: Gallons (liquids only)
Number of Containers: 006
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYC7364125
Manifest Status: Not reported
Trans1 State ID: NYC10826J
Year: 2004
Trans2 State ID: Not reported
Generator Ship Date: 09/14/2004
Trans1 Recv Date: 09/14/2004
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/14/2004
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986887172
Trans1 EPA ID: TXR000050930
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00017
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYC6504401
Manifest Status: Not reported
Trans1 State ID: NY15489
Year: 2001
Trans2 State ID: Not reported
Generator Ship Date: 09/19/2001
Trans1 Recv Date: 09/19/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/20/2001

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00020
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC6575692
Manifest Status:	Not reported
Trans1 State ID:	GN6403
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2001
Trans1 Recv Date:	06/28/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00026
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC6105497
Manifest Status:	Not reported
Trans1 State ID:	NYMJ1781
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	02/07/2000
Trans1 Recv Date:	02/07/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/07/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00025
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Document ID:	NYC6338338
Manifest Status:	Not reported
Trans1 State ID:	LC9100
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	01/05/2001
Trans1 Recv Date:	01/05/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/08/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00026
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC2171046
Manifest Status:	Not reported
Trans1 State ID:	NYH59192
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	02/22/1993
Trans1 Recv Date:	02/22/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/22/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00076
Units:	Gallons (liquids only)
Number of Containers:	006
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	TXR000050930
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	05/20/2008
Trans1 Recv Date:	05/20/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/20/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986887172
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	001145320SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Benzene
Waste Code c:	Tetrachloroethylene
Waste Code e:	Trichlorethylene

BUFFALO CLUTCH CO INC (Continued) **1000227774**

Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	20
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
76 additional NY MANIFEST: record(s) in the EDR Site Report.

G29 **VON DUNGEN EMIL BFLO INC** **RCRA NonGen / NLR** **1000111284**
NNE **83 ANDERSON RD** **FINDS** **NYD002104982**
< 1/8 **BUFFALO, NY 14225** **ECHO**
0.090 mi.
473 ft. **Site 1 of 2 in cluster G**

Relative: **Lower**
Actual: **653 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Von Dungen Emil Bflo Inc
Handler Address:		Anderson Rd
Handler City,State,Zip:		BUFFALO, NY 14225
EPA ID:		NYD002104982
Contact Name:		ROBERT FEIGHTNER
Contact Address:		ANDERSON RD
Contact City,State,Zip:		CHEEKTOWAGA, NY 14225
Contact Telephone:		716-892-0159
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		ANDERSON RD
Mailing City,State,Zip:		CHEEKTOWAGA, NY 14225
Owner Name:	Ownername	
Owner Type:		Private
Operator Name:	Opername	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No

VON DUNGEN EMIL BFLO INC (Continued) **1000111284**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F017
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	OWNERSTREET
Owner/Operator City,State,Zip:	OWNERCITY, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	

VON DUNGEN EMIL BFLO INC (Continued) **1000111284**

Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: OWNERSTREET
Owner/Operator City,State,Zip: OWNERCITY, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: OPERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: OPERSTREET
Owner/Operator City,State,Zip: OPERCITY, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: OPERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: OPERSTREET
Owner/Operator City,State,Zip: OPERCITY, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19801103
Handler Name: VON DUNGEN EMIL BFLO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19010101
Handler Name: VON DUNGEN EMIL BFLO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

VON DUNGEN EMIL BFLO INC (Continued) **1000111284**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: VON DUNGEN EMIL BFLO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: VON DUNGEN EMIL BFLO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800725
Handler Name: VON DUNGEN EMIL BFLO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332313
NAICS Description: Plate Work Manufacturing

NAICS Code: 81131
NAICS Description: Commercial And Industrial Machinery And Equipment (Except Automotive And Electronic) Repair And Maintenance

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported

VON DUNGEN EMIL BFLO INC (Continued) **1000111284**

Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19970421
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRWK
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004338440

VON DUNGEN EMIL BFLO INC (Continued) **1000111284**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000111284
Registry ID: 110004338440

DFR URL:
Name: VON DUNGEN EMIL BFLO INC
Address: 83 Anderson Rd
City,State,Zip: BUFFALO, NY 14225

G30 **C H HEIST CORP & SUBSIDIARIES** **RCRA NonGen / NLR** **1000140450**
NNE **63 ANDERSON RD** **FINDS** **NYD063650873**
< 1/8 **BUFFALO, NY 14225** **ECHO**
0.091 mi. **NY MANIFEST**
480 ft. **Site 2 of 2 in cluster G**

Relative:
Lower

Actual:
653 ft.

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		C H Heist Corp & Subsidiaries
Handler Address:		Anderson Rd
Handler City,State,Zip:		BUFFALO, NY 14225
EPA ID:		NYD063650873
Contact Name:		ANTHONY KARDYSAUSKAS
Contact Address:		ANDERSON RD
Contact City,State,Zip:		BUFFALO, NY 14225
Contact Telephone:		716-894-3035
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		ANDERSON RD
Mailing City,State,Zip:		BUFFALO, NY 14225
Owner Name:	Ownername	
Owner Type:		Private
Operator Name:	Ownername	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No

C H HEIST CORP & SUBSIDIARIES (Continued) **1000140450**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

C H HEIST CORP & SUBSIDIARIES (Continued) **1000140450**

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: C H HEIST CORP & SUBSIDIARIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: C H HEIST CORP & SUBSIDIARIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800815
Handler Name: C H HEIST CORP & SUBSIDIARIES
Federal Waste Generator Description: Not reported
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

C H HEIST CORP & SUBSIDIARIES (Continued) **1000140450**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19960524
Handler Name: C.H. HEIST CORP.	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	23599
NAICS Description:	All Other Special Trade Contractors

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID:	110000838434

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000140450
Registry ID:	110000838434

DFR URL:

Name:	C H HEIST CORP & SUBSIDIARIES
Address:	63 Anderson Rd
City,State,Zip:	BUFFALO, NY 14225

C H HEIST CORP & SUBSIDIARIES (Continued) **1000140450**

NY MANIFEST:

EPA ID:	NYD063650873
Country:	USA
Name:	C H Heist Corp
Address:	63 ANDERSON RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225
Zip 4:	Not reported
Location Address 1:	61 ANDERSON RD
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	C H Heist Corp
Mailing Contact:	C H Heist Corp
Mailing Address 1:	45 ANDERSON ROAD
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168943035

Manifest Data:

Document ID:	TXA0289357
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1996
Trans2 State ID:	88888
Generator Ship Date:	10/04/1996
Trans1 Recv Date:	01/01/1900
Trans2 Recv Date:	10/04/1996
TSD Site Recv Date:	10/14/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063650873
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	ILD984908202
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported

C H HEIST CORP & SUBSIDIARIES (Continued) **1000140450**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00260
Units:	Pounds
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	NYA5389182
Manifest Status:	C - Completed copy
Trans1 State ID:	34153GV/N
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880527
Trans1 Recv Date:	880527
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880527
Part A Recv Date:	880616
Part B Recv Date:	880607
Generator EPA ID:	NYD063650873
Trans1 EPA ID:	NYD043815703
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00275
Units:	Gallons (liquids only)
Number of Containers:	005

C H HEIST CORP & SUBSIDIARIES (Continued) **1000140450**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NJA2156829
Manifest Status:	Not reported
Trans1 State ID:	08690
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	06/30/1995
Trans1 Recv Date:	06/30/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/11/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD063650873
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	05382
Units:	Pounds
Number of Containers:	009
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

31
ENE
< 1/8
0.091 mi.
481 ft.

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT
51 ANDERSON RD
BUFFALO, NY 14225

RCRA NonGen / NLR **1014399668**
NY MANIFEST **NYR000177576**
NJ MANIFEST

Relative:
Lower

Actual:
653 ft.

RCRA Listings:

Date Form Received by Agency:		20120112
Handler Name:		Veolia Es Industrial Services M&D Department
Handler Address:		Anderson Rd
Handler City,State,Zip:		BUFFALO, NY 14225
EPA ID:		NYR000177576
Contact Name:		PAUL D FORD
Contact Address:		COUNTY RD CB SUITE 100
Contact City,State,Zip:		NEENAH, WI 54956
Contact Telephone:		920-749-8100 x756
Contact Fax:		920-749-8110
Contact Email:		PAUL.FORD@VEOLIAES.COM
Contact Title:		M&D COORDINATOR
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		COUNTY RD CB SUITE 100
Mailing City,State,Zip:		NEENAH, WI 54956
Owner Name:	Veolia Es Industrial Services	
Owner Type:		Private
Operator Name:	Veolia Es Industrial Services	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	VEOLIA ES INDUSTRIAL SERVICES
Legal Status:	Private
Date Became Current:	20000318
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	VEOLIA ES INDUSTRIAL SERVICES
Legal Status:	Private
Date Became Current:	20000318
Date Ended Current:	Not reported
Owner/Operator Address:	785 COUNTY RD CB SUITE 100
Owner/Operator City,State,Zip:	NEENAH, WI 54956
Owner/Operator Telephone:	920-749-8100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	VEOLIA ES INDUSTRIAL SERVICES
Legal Status:	Private
Date Became Current:	20000318

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Date Ended Current: Not reported
Owner/Operator Address: 785 COUNTY RD CB SUITE 100
Owner/Operator City,State,Zip: NEENAH, WI 54956
Owner/Operator Telephone: 920-749-8100
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: VEOLIA ES INDUSTRIAL SERVICES
Legal Status: Private
Date Became Current: 20000318
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20120112
Handler Name: VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100830
Handler Name: VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 23829
NAICS Description: Other Building Equipment Contractors

NAICS Code: 333511
NAICS Description: Industrial Mold Manufacturing

Facility Has Received Notices of Violations:
Violations: No Violations Found

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYR000177576
Country: USA
Name: Veolia Environmental Services
Address: 51 ANDERSON RD
Address 2: Not reported
City,State,Zip: BUFFALO, NY 14225
Zip 4: Not reported
Location Address 1: 51 ANDERSON RAOD
Location Address 2: Not reported
Location City,State,Zip: BUFFALO, NY 14225
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Veolia Environmental Services
Mailing Contact: Veolia Environmental Services
Mailing Address 1: 785 COUNTRY ROAD CB SUITE 100
Mailing Address 2: Not reported
Mailing City,State,Zip: NINA, WI 54956
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9024855183

Manifest Data:
Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Year: 2018
Trans2 State ID: TXR000077970
Generator Ship Date: 09/13/2010
Trans1 Recv Date: 09/13/2010
Trans2 Recv Date: 09/21/2010
TSD Site Recv Date: 09/22/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000177576
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: OHD093945293
TSDF ID 2: Not reported
Manifest Tracking Number: 000473808VES
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Benzene
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	470
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	TXR000077970
Generator Ship Date:	09/13/2010
Trans1 Recv Date:	09/13/2010
Trans2 Recv Date:	09/21/2010
TSD Site Recv Date:	09/22/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473808VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	270
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	NJD054126164
Generator Ship Date:	09/13/2010
Trans1 Recv Date:	09/13/2010
Trans2 Recv Date:	09/22/2010
TSD Site Recv Date:	09/24/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473813VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	270
Units:	Pounds
Number of Containers:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Year: 2018
Trans2 State ID: TXR000077970
Generator Ship Date: 09/09/2010
Trans1 Recv Date: 09/09/2010
Trans2 Recv Date: 09/14/2010
TSD Site Recv Date: 09/15/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000177576
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: OHD093945293
TSDF ID 2: Not reported
Manifest Tracking Number: 000473867VES
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code a: Ignitable Waste
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 390
Units: Pounds
Number of Containers: 2
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NJD080631369
Year: 2018
Trans2 State ID: TXR000077970
Generator Ship Date: 09/09/2010
Trans1 Recv Date: 09/09/2010
Trans2 Recv Date: 09/14/2010

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

TSD Site Recv Date:	09/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473867VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Corrosive Waste
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	140
Units:	Pounds
Number of Containers:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	TXR000077970
Generator Ship Date:	09/09/2010
Trans1 Recv Date:	09/09/2010
Trans2 Recv Date:	09/14/2010
TSD Site Recv Date:	09/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473867VES
Import Indicator:	N

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Methyl Ethyl Ketone
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	154
Units:	Pounds
Number of Containers:	2
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	TXR000077970
Generator Ship Date:	09/09/2010
Trans1 Recv Date:	09/09/2010
Trans2 Recv Date:	09/14/2010
TSD Site Recv Date:	09/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473867VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	TXR000077970
Generator Ship Date:	09/09/2010
Trans1 Recv Date:	09/09/2010
Trans2 Recv Date:	09/14/2010
TSD Site Recv Date:	09/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473867VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	540
Units:	Pounds
Number of Containers:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	TXR000077970
Generator Ship Date:	09/09/2010
Trans1 Recv Date:	09/09/2010
Trans2 Recv Date:	09/14/2010
TSD Site Recv Date:	09/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473867VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1100
Units:	Pounds
Number of Containers:	3
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1
Document ID:	Not reported

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	TXR000077970
Generator Ship Date:	09/09/2010
Trans1 Recv Date:	09/09/2010
Trans2 Recv Date:	09/14/2010
TSD Site Recv Date:	09/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD093945293
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473867VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1100
Units:	Pounds
Number of Containers:	4
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NJD080631369
Year:	2018
Trans2 State ID:	TXR000077970
Generator Ship Date:	09/09/2010
Trans1 Recv Date:	09/13/2010
Trans2 Recv Date:	09/14/2010
TSD Site Recv Date:	09/17/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Generator EPA ID:	NYR000177576
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ILD098642424
TSDF ID 2:	Not reported
Manifest Tracking Number:	000473869VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	20
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
9 additional NY MANIFEST: record(s) in the EDR Site Report.

NJ MANIFEST:

EPA ID:	NYR000177576
Name:	VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT
Address:	51 ANDERSON RD
City,State,Zip:	BUFFALO, NY 14225
County:	Not reported
Mailing Address:	COUNTY RD CB SUITE 100
Mailing City,State,Zip:	NEENAH, WI 54956
Telephone:	Not reported
Emergency Telephone:	Not reported
Contact:	PAUL D FORD
Comments:	Not reported
SIC Code:	Not reported
County:	NY029
Municipal:	Not reported
Previous EPAID:	Not reported
Generator Flag:	Not reported

VEOLIA ES INDUSTRIAL SERVICES M&D DEPARTMENT (Continued) **1014399668**

Transporter Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest Data:

EPA ID:	NYR000177576
Manifest Number:	000473813VES
Date Shipped:	09/13/2010
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	NJD054126164
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/13/2010
Date Trans2 Transported Waste:	09/22/2010
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/24/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	N
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D002
Hand Code:	H141
Quantity:	270
Unit:	P

H32 **CLARK LIFT** **UST FINDER RELEASE** **1029063543**
SE **1835 DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 0**
0.104 mi.
549 ft. **Site 1 of 8 in cluster H**

Relative: **Lower**
Actual: **652 ft.**

UST FINDER RELEASE:

Object ID:	244736
Facility ID:	NY187102
Lust ID:	NY9207999
Name:	CLARK LIFT
Address:	1835 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1992/10/15 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	1
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.77017
Y Coord:	42.9042200000001
Latitude:	42.90422
Longitude:	-78.7701699999999

H33 **PROLIFT INC** **RCRA-VSQG** **1000363633**
SE **1835 DALE RD** **NY Spills** **NYD013706577**
< 1/8 **BUFFALO, NY 14225** **FINDS**
0.104 mi. **ECHO**
549 ft. **Site 2 of 8 in cluster H** **NY MANIFEST**

Relative: **Lower**
Actual: **652 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Clarklift Of Buffalo Inc
Handler Address:	Dale Rd
Handler City,State,Zip:	BUFFALO, NY 14225
EPA ID:	NYD013706577
Contact Name:	Not reported
Contact Address:	DALE RD
Contact City,State,Zip:	BUFFALO, NY 14225
Contact Telephone:	Not reported

PROLIFT INC (Continued) **1000363633**

Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		DALE RD
Mailing City,State,Zip:		BUFFALO, NY 14225
Owner Name:	Clarklift Of Buffalo	
Owner Type:		Private
Operator Name:	Clarklift Of Buffalo	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

PROLIFT INC (Continued) **1000363633**

Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CLARKLIFT OF BUFFALO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CLARKLIFT OF BUFFALO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CLARKLIFT OF BUFFALO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED

PROLIFT INC (Continued) **1000363633**

Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990714
Handler Name: CLARKLIFT OF BUFFALO INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: CLARKLIFT OF BUFFALO INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CLARKLIFT OF BUFFALO INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19871112
Handler Name: CLARKLIFT OF BUFFALO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

PROLIFT INC (Continued) **1000363633**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 19950103
Actual Return to Compliance Date: 19950113
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19950203
Enforcement Identifier: 000
Date of Enforcement Action: 19950103

PROLIFT INC (Continued) **1000363633**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYRHG
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20000104
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYKHE
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19941216
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYRHG
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: 19950113
Scheduled Compliance Date: 19950203
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

PROLIFT INC (Continued) **1000363633**

SPILLS:

Name:	NIAGARA TRANSFORMER
Address:	DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9700333 / 1997-04-07
Facility ID:	9700333
Facility Type:	ER
DER Facility ID:	95983
Site ID:	109282
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	1530
Spill Date:	1997-04-01
Investigator:	FXGALLEG
Referred To:	Not reported
Reported to Dept:	1997-04-07
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-04-07
Spill Record Last Update:	1999-10-08
Spiller Name:	Not reported
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	DALE ROAD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9047820
Longitude:	-78.7731220
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 4/7/97 DAVE LOCEY NOTIFIED SPILLS. RP NOTICED OIL STAIN OUTSIDE BUILDING. RP ESTIMATES SPILL HAPPENED OVER THE WINTER. THIS IS AN HWR SITE. THEY HAVE TAKEN A SAMPLE TO CHECK FOR PCB'S. THEY WILL CLEANUP AND DISPOSE ALONG W/PCB CONTAMINATED SOIL WHICH IS THE CLEANUP TAKING PLACE UNDER HWR. RP IS GOING TO CHECK EQUIPMENT TO FIND OUT MALFUNCTION AND PREVENT A REPEAT OF THE SITUATION. MATT WAWROWSKI W/E&E IS ON SITE DOING MONITORING FOR DEC. NO FURTHER ACTION BY SPILLS IS NECESSARY. SITE CAN BE CLOSED.
Remarks:	OVER THE WINTER EQUIPMENT MALFUNTIONED AND CAUSED OIL LEAK TO THE OUTSIDE OF THE BUILDING FAXED BY REGION

All Materials:

Site ID:	109282
Operable Unit ID:	1043128
Operable Unit:	01
Material ID:	336942
Material Code:	0020A

PROLIFT INC (Continued) **1000363633**

Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FINDS:
Registry ID: 110004350096

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Integrated Compliance Information System (ICIS) provides a database that, when complete, will contain integrated enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and it at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000363633
Registry ID:	110004350096

DFR URL:

Name:	PROLIFT INC
Address:	1835 Dale Rd
City,State,Zip:	BUFFALO, NY 14225

NY MANIFEST:

EPA ID:	NYD013706577
Country:	USA
Name:	Clarklift Of Buffalo Inc
Address:	1835 DALE RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225
Zip 4:	Not reported

PROLIFT INC (Continued) **1000363633**

Location Address 1: 1835 DALE ROAD
Location Address 2: Not reported
Location City,State,Zip: BUFFALO, NY 14225
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Clarklift Of Buffalo Inc
Mailing Contact: Clarklift Of Buffalo Inc
Mailing Address 1: 1835 DALE ROAD
Mailing Address 2: Not reported
Mailing City,State,Zip: BUFFALO, NY 14225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7168958600

Manifest Data:
Document ID: NYC1834402
Manifest Status: Not reported
Trans1 State ID: NYEM4533
Year: 1992
Trans2 State ID: Not reported
Generator Ship Date: 09/04/1992
Trans1 Recv Date: 09/04/1992
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/04/1992
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD013706577
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported

PROLIFT INC (Continued) **1000363633**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00024
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC3130380
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	09/15/1994
Trans1 Recv Date:	09/15/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/15/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYA8809626

PROLIFT INC (Continued) **1000363633**

Manifest Status:	C - Completed copy
Trans1 State ID:	NYMJ1780
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880315
Trans1 Recv Date:	880315
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880315
Part A Recv Date:	880318
Part B Recv Date:	880318
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYC3121694
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/1994
Trans1 Recv Date:	06/28/1994
Trans2 Recv Date:	Not reported

PROLIFT INC (Continued) **1000363633**

TSD Site Recv Date:	06/29/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC1330942
Manifest Status:	Not reported
Trans1 State ID:	NYEM4533
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	11/22/1991
Trans1 Recv Date:	11/22/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/22/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

PROLIFT INC (Continued) **1000363633**

Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00027
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYA8890435
Manifest Status: C - Completed copy
Trans1 State ID: NYMJ1780
Year: 1988
Trans2 State ID: Not reported
Generator Ship Date: 880516
Trans1 Recv Date: 880516
Trans2 Recv Date: Not reported
TSD Site Recv Date: 880516
Part A Recv Date: 880520
Part B Recv Date: 880520
Generator EPA ID: NYD013706577
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported

PROLIFT INC (Continued) **1000363633**

Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYC2286909
Manifest Status:	Not reported
Trans1 State ID:	NYEM4533
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	05/04/1993
Trans1 Recv Date:	05/04/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/04/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

PROLIFT INC (Continued) **1000363633**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC1397182
Manifest Status:	Not reported
Trans1 State ID:	NYEM4533
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	12/19/1991
Trans1 Recv Date:	12/19/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/19/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00123
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn

PROLIFT INC (Continued) **1000363633**

Specific Gravity: 01.00

Document ID: NYC3046601
Manifest Status: Not reported
Trans1 State ID: NYGA6403
Year: 1994
Trans2 State ID: Not reported
Generator Ship Date: 05/27/1994
Trans1 Recv Date: 05/27/1994
Trans2 Recv Date: Not reported
TSD Site Recv Date: 05/27/1994
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD013706577
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00027
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NYC4663653
Manifest Status: Not reported
Trans1 State ID: NYIT5466
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 03/03/1997
Trans1 Recv Date: 03/03/1997
Trans2 Recv Date: Not reported

PROLIFT INC (Continued) **1000363633**

TSD Site Recv Date:	03/03/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYA9044166
Manifest Status:	C - Completed copy
Trans1 State ID:	NYEM4533
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880921
Trans1 Recv Date:	880921
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880921
Part A Recv Date:	880926
Part B Recv Date:	880927
Generator EPA ID:	NYD013706577
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported

PROLIFT INC (Continued) **1000363633**

Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
149 additional NY MANIFEST: record(s) in the EDR Site Report.

H34 **CLARKLIFT OF BUFFALO, INC.** **UST FINDER** **1028597981**
SE **1835 DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.104 mi.
549 ft. **Site 3 of 8 in cluster H**

Relative: UST FINDER:
Lower

Actual: Object ID:	315571
652 ft. Facility ID:	NY54381
Name:	CLARKLIFT OF BUFFALO, INC.
Address:	1835 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	2
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported

CLARKLIFT OF BUFFALO, INC. (Continued) **1028597981**

SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	No
WHPA PWS Facility ID:	Not reported
WHPA Water Type:	Not reported
WHPA Facility Type:	Not reported
WHPA HUC12:	Not reported
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-78.770618
Y Coord:	42.9038870000001
Latitude:	42.903887
Longitude:	-78.770618

UST FINDER:

Object ID:	1311796
Facility ID:	NY54381
Tank ID:	NY121390
Tank Status:	Closed
Installation Date:	1979/10/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

H35 **CLARK LIFT** **NY LTANKS S102177770**
SE **1835 DALE ROAD** **NY Spills N/A**
< 1/8 **CHEEKTOWAGA, NY**
0.104 mi.
549 ft. **Site 4 of 8 in cluster H**

Relative: **Lower**

Actual: **652 ft.**

LTANKS:

Name:	CLARK LIFT
Address:	1835 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9207999 / 1994-04-18
Facility ID:	9207999
Site ID:	226678
Spill Date:	1992-10-15
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-04-18
SWIS:	1530
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1992-10-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1992-10-19
Recommended Penalty:	False
Meets Standard:	True

CLARK LIFT (Continued) **S102177770**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-10-19
Spill Record Last Update:	2002-04-17
Spiller Name:	Not reported
Spiller Company:	CLARK LIFT
Spiller Address:	1835 DALE ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	187102
Latitude:	42.9042209
Longitude:	-78.7701730
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/19/92: RMC/SITE - TEST PITS; MANY HAVE A SHEEN. 11/20/92: RMC/SITE - ABOUT 400 YARDS EXCAVATED (ALL NOTED CONTAMINATION). CLEAN HOLE TESTS AND DISPOSAL OPTION DUE 12/30/92. 12/30/92: RMC/AL DIPALO/PHONE - NATURE'S WAY IS HANDLING CLEAN HOLE & BIO-TREATMENT WORK. ANALYTICAL DUE 2/15/93. 02/10/93: RMC RECEIVED CLEAN HOLE RESULTS; OKAY. LETTER SENT. CONTAMINATED SOIL REMEDIATION PLAN AND SCHEDULE DUE 3/15/93. 03/17/93: RMC/RECEIVED LETTER FROM CLARK PLAN TO BIOTREAT, START BY 5/15/93. 07/09/93: RMC/FEELEY/PHONE TO DO BIOTREATMENT WITH WASTE STREAM, UPDATE 8/15/93. 09/23/93: RMC/FEELEY/PHONE BIOTREATMENT APPEARS COMPLETE, TO TAKE SAMPLES, RESULTS DUE 10/30/93. 11/15/93: RMC/FEELEY/PHONE RECEIVED BIO RESULT, SEVERAL EXCEEDANCES, RP TO RETEST, RESULTS DUE 1/15/94. 01/21/94: RMC/FEELEY/PHONE WILL RESAMPLE WHEN WEATHER BREAKS, RESULTS DUE 4/1/94E. 04/18/94: RMC/RECEIVED RETEST RESULTS, NO EXCEEDANCES, CLOSE OUT.
Remarks:	CONTRACTOR FOUND CONTAMINATED SOIL WHILE EXCAVATING TANK.

All TTF:

Facility ID:	9207999
Spill Number:	9207999
Spill Tank Test:	1540695
Site ID:	226678
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	226678
Operable Unit ID:	971644
Operable Unit:	01
Material ID:	557105

CLARK LIFT (Continued) **S102177770**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	WASTE OIL DALE ROAD
Address:	1835 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9300470 / 1993-04-16
Facility ID:	9300470
Facility Type:	ER
DER Facility ID:	187102
Site ID:	226679
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	D3
SWIS:	1530
Spill Date:	1993-04-07
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1993-04-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	DEC
Cleanup Ceased:	1993-04-16
Cleanup Meets Std:	True
Last Inspection:	1993-04-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-04-13
Spill Record Last Update:	1993-04-28
Spiller Name:	Not reported
Spiller Company:	NONE
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
Latitude:	42.9042209
Longitude:	-78.7701730
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 04/09/93: RMC/SITE - NOTED SMALL AMOUNT OF OIL IN DITCH FROM STORM SEWER OUTLET. NO REMEDIATION REQUIRED. WILL REINSPECT 4/12/93. 04/16/93: RMC/SITE - PROMLEM GONE, NO FURTHER ACTION NEEDED.. CLOSE OUT.
Remarks:	WASTE OIL IN DITCH

All Materials:

Site ID:	226679
Operable Unit ID:	979124

CLARK LIFT (Continued) **S102177770**

Operable Unit:	01
Material ID:	401225
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	CLARK LIFT
Address:	1835 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9708106 / 1997-10-17
Facility ID:	9708106
Facility Type:	ER
DER Facility ID:	187102
Site ID:	226680
DEC Region:	9
Spill Cause:	Deliberate
Spill Class:	D6
SWIS:	1530
Spill Date:	1997-10-01
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1997-10-03
CID:	999
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	1997-10-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-09
Spill Record Last Update:	1997-11-12
Spiller Name:	Not reported
Spiller Company:	CLARK LIFT
Spiller Address:	1835 DALE ROAD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9042209
Longitude:	-78.7701730
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/17/97 RMC/PAT FEELEY/SITE RMC INSPECTED PROPERTY INSIDE AND OUT, WASTE OILS TO BISON, SEPERATOR ALSO PUMPED OUT BY BISON, GRIT FROM ZIPPER DRAINS TO MODERN, INSIDE IMMACULATE, OUT SIDE DOES HAVE WASTE OIL SPOTS ON BLACKTOP FROM FORK TRUCKS STAGED FOR REPAIR BUT NOT EXCESSIVE, NO ACTON REQUIRED, CLOSE OUT
Remarks:	DUMPING OIL AND ANTIFREEZE AT SHOP INTO DRAIN - DRAIN HAS A TANK WHICH MAY NOT BE A SEPERATOR - TANK IS PUMPED OUT FOR ONLY SLUDGE (NO

CLARK LIFT (Continued) **S102177770**

FLOATING OIL)

All Materials:

Site ID:	226680
Operable Unit ID:	1051330
Operable Unit:	01
Material ID:	330091
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	226680
Operable Unit ID:	1051330
Operable Unit:	01
Material ID:	330090
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H36 **CLARKLIFT OF BUFFALO, INC.** **NY UST** **U003318266**
SE **1835 DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.104 mi.
549 ft. **Site 5 of 8 in cluster H**

Relative: **Lower**

Actual: **652 ft.**

UST:

Name:	CLARKLIFT OF BUFFALO, INC.
Address:	1835 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Id/Status:	9-444049 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	192167.87038
UTM Y:	4757037.02326
Site Type:	Other

Affiliation Records:

Site Id:	54381
Affiliation Type:	Facility Owner
Company Name:	CLARKLIFT OF BUFFALO, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1835 DALE ROAD
Address2:	Not reported
City:	BUFFALO
State:	NY

CLARKLIFT OF BUFFALO, INC. (Continued) **U003318266**

Zip Code:	14225
Country Code:	001
Phone:	(716) 895-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54381
Affiliation Type:	Mail Contact
Company Name:	CLARKLIFT OF BUFFALO, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1835 DALE ROAD
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 895-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54381
Affiliation Type:	Facility Operator
Company Name:	CLARKLIFT OF BUFFALO, INC.
Contact Type:	Not reported
Contact Name:	CLARKLIFT OF BUFFALO, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 895-8600
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	54381
Affiliation Type:	Emergency Contact
Company Name:	CLARKLIFT OF BUFFALO, INC.
Contact Type:	Not reported
Contact Name:	JOHN A. LINCOLN, JR.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 655-0185
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

CLARKLIFT OF BUFFALO, INC. (Continued) **U003318266**

Date Last Modified: 2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	167786
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	10/01/1979
Date Tank Closed:	10/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	07/01/1987
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

E37 **NIAGARA TRANSFORMER** **NY Spills** **S113493775**
South **MAIN BLD 1747 DALE RD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.105 mi.
554 ft. **Site 5 of 5 in cluster E**

Relative: SPILLS:
Lower

Actual: Name:	NIAGARA TRANSFORMER
651 ft. Address:	MAIN BLD 1747 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1301247 / 2014-10-29
Facility ID:	1301247
Facility Type:	ER
DER Facility ID:	436877
Site ID:	481622
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	1530
Spill Date:	2013-05-07
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2013-05-07

NIAGARA TRANSFORMER (Continued) **S113493775**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-05-07
Spill Record Last Update:	2014-10-29
Spiller Name:	ROBERT FISHLACK
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	MAIN BLD 1747 DALE RD
Spiller Company:	001
Contact Name:	ROBERT FISHLACK
Latitude:	42.9034814
Longitude:	-78.7724468
DEC Memo:	5/8/2013: RJJ TELECON ROBERT FISHLOCK,MANAGER NIAGARA TRANSFORMER,HE SAID THAT YESTERDAY,DUE TO HUMAN ERROR,~2 GALS. OF MINERAL OIL LEAKED OUT FROM ONE OF THEIR NEW TRANSFORMERS,ALL ON THEIR CONCRETE FLOOR,INSIDE THEIR FACILITY...NIAGARA TRANSFORMER PERSONNEL QUICKLY USED ABSORBANTS TO CLEAN-UP THSI SPILL...THEY THEN PLACED ALL THE SPILL MATERIAL IN A DRUM,WHICH WILL BE DISPOSED OF...ALL THE MINERAL OIL HAS BEEN RECOVERED...MR. FISHLOCK WILL SEND ME THE DISPOSAL RECEIPTS. 10/29/2014: RECEIVED THE DISPOSAL RECEIPTS FOR THE 2 DRUMS OF SPILL MATERIAL TAKEN TO THE CLEAN HARBORS EL DORADO LLC,FACILITY IN AR....THE SPILL HAS BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	loss to floor, c/u in progress

All Materials:

Site ID:	481622
Operable Unit ID:	1231387
Operable Unit:	01
Material ID:	2230126
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

F38 **BUSINESS** **NY Spills** **S121119778**
ESE **1850 DALE RD** **N/A**
< 1/8 **CHEEKTOWAGA, NY**
0.112 mi.
593 ft. **Site 2 of 4 in cluster F**

Relative: **Lower**

Actual: **653 ft.**

SPILLS:

Name:	BUSINESS
Address:	1850 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	1706984 / 2018-08-13
Facility ID:	1706984
Facility Type:	ER
DER Facility ID:	514942
Site ID:	561323
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1530
Spill Date:	2017-10-18
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2017-10-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-10-18
Spill Record Last Update:	2018-08-13
Spiller Name:	JEFF SOWINSKI
Spiller Company:	NYSEG
Spiller Address:	150 ERIE ST.
Spiller Company:	999
Contact Name:	JEFF SOWINSKI
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	10/19/17:SAC TELECON JEFF SOWINSKI - NYSEG. MR. SOWINSKI SAID THAT THE SPILL WAS TO THE ASPHALT. ALLIED ENVIRONMENTAL SERVICES HAS BEEN CONTACTED AND WILL BE RESPONDING TO THE SITE. THEY WILL BE CLEANING UP THE SPILL USING SPEEDI-DRY. THE FIELD TEST ON THE PRODUCT CAME BACK AS NON-PCB. 8/8/18:RECEIVED COPY OF BILL OF LADING. NO FURTHER WORK IS REQUIRED.
Remarks:	less than one quart to parking lot. cleanup pending

All Materials:

Site ID:	561323
Operable Unit ID:	1309297
Operable Unit:	01
Material ID:	2316401
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum

BUSINESS (Continued) **S121119778**

Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

F39 **FORMER BUFFALO SPRING/UPSTATE STEEL SITE** **NY Spills** **S132979010**
ESE **1820-1850 DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.112 mi.
593 ft. **Site 3 of 4 in cluster F**

Relative: **Lower**

Actual: **653 ft.**

SPILLS:

Name:	FORMER BUFFALO SPRING/UPSTATE STEEL SITE
Address:	1820-1850 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	2503901 / Not Reported
Facility ID:	2503901
Facility Type:	ER
DER Facility ID:	625116
Site ID:	681290
DEC Region:	9
Spill Cause:	Other
Spill Class:	D5
SWIS:	1530
Spill Date:	2021-11-16
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2025-07-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	1
Date Entered In Computer:	2025-07-25
Spill Record Last Update:	2025-07-25
Spiller Name:	GREGORY SCANDALE
Spiller Company:	LONG LIFE FLEET
Spiller Address:	102 COLLIERY ROAD
Spiller Company:	001
Contact Name:	Not reported
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	7/25/28:RECEIVED PHASE II REPORT FROM DOUG REID - SUBSURFACE INVESTIGATIONS GEOLOGISTS, D.P.G. (SIG).
Remarks:	DURING PHASE II SITE ASSESSMENT REPORT, SOIL AND GW SAMPLE RESULTS WERE ABOVE CP-51 SVOC GUIDANCE VALUES.

All Materials:

Site ID:	681290
Operable Unit ID:	1427908
Operable Unit:	01

FORMER BUFFALO SPRING/UPSTATE STEEL SITE (Continued) **S132979010**

Material ID:	2447847
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

F40 **PAVEMENT** **NY Spills** **S122478606**
ESE **1850 DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY**
0.112 mi.
593 ft. **Site 4 of 4 in cluster F**

Relative: **Lower**
Actual: **653 ft.**

SPILLS:

Name:	PAVEMENT
Address:	1850 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	1801656 / 2018-05-14
Facility ID:	1801656
Facility Type:	ER
DER Facility ID:	523426
Site ID:	570196
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1530
Spill Date:	2018-05-14
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2018-05-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-05-14
Spill Record Last Update:	2018-05-14
Spiller Name:	JEFF
Spiller Company:	NYSEG
Spiller Address:	1850 DALE ROAD
Spiller Company:	999
Contact Name:	JEFF
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	05/14/18 RMC/FILE. MINOR SPILL, NO ACTION REQURED. CLOSE OUT.
Remarks:	less than a pint spilled failed transformer clean up is pending

All Materials:

Site ID:	570196

PAVEMENT (Continued) **S122478606**

Operable Unit ID:	1318044
Operable Unit:	01
Material ID:	2325968
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.13
Units:	G
Recovered:	.13
Oxygenate:	Not reported

I41 **NIAGARA TRANSFORMER CORP** **RCRA-SQG 1012211730**
SSE **1755 DALE RD** **E MANIFEST NYR000171371**
< 1/8 **CHEEKTOWAGA, NY 14225** **NY MANIFEST**
0.121 mi.
640 ft. **Site 1 of 7 in cluster I**

Relative: **Lower**
Actual: **652 ft.**

RCRA Listings:

Date Form Received by Agency:	20210223
Handler Name:	Niagara Power Transformer
Handler Address:	Dale Rd
Handler City,State,Zip:	BUFFALO, NY 14225
EPA ID:	NYR000171371
Contact Name:	KARL R SCHURKUS
Contact Address:	DALE RD
Contact City,State,Zip:	BUFFALO, NY 14225
Contact Telephone:	716-896-6500 x160
Contact Fax:	716-896-8871
Contact Email:	KSCHURKUS@NPTRANSFROMER.COM
Contact Title:	SAFETY MANAGER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R9
Mailing Address:	DALE RD
Mailing City,State,Zip:	BUFFALO, NY 14225
Owner Name: Niagara Power Transformer	
Owner Type:	Private
Operator Name: Niagara Power Transformer	
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210304
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NIAGARA TRANSFORMER CORP	
Legal Status:	Private
Date Became Current:	19830527
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NIAGARA TRANSFORMER CORP	
Legal Status:	Private
Date Became Current:	19830527
Date Ended Current:	Not reported
Owner/Operator Address:	1747 DALE RD
Owner/Operator City,State,Zip:	CHEEKTOWAGA, NY 14225
Owner/Operator Telephone:	716-896-6500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: NIAGARA POWER TRANSFORMER	
Legal Status:	Private
Date Became Current:	20210201
Date Ended Current:	Not reported
Owner/Operator Address:	1755 DALE RD
Owner/Operator City,State,Zip:	BUFFALO, NY 14225
Owner/Operator Telephone:	716-896-6500
Owner/Operator Telephone Ext:	160
Owner/Operator Fax:	716-896-8871
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NIAGARA POWER TRANSFORMER	
Legal Status:	Private
Date Became Current:	20210201
Date Ended Current:	Not reported
Owner/Operator Address:	1755 DALE RD
Owner/Operator City,State,Zip:	BUFFALO, NY 14225
Owner/Operator Telephone:	716-896-6500
Owner/Operator Telephone Ext:	160
Owner/Operator Fax:	716-896-8871
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20100121
Handler Name: NIAGARA TRANSFORMER CORP	
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20210223
Handler Name: NIAGARA POWER TRANSFORMER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 335311
NAICS Description: Power, Distribution, And Specialty Transformer Manufacturing

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20150708
Actual Return to Compliance Date: 20150813
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20150717
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYKHE
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20150708
Actual Return to Compliance Date: 20150813
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Date of Enforcement Action: 20150717
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYKHE
Enforcement Responsible Sub-Organization: R9
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20181012
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYBMN
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20150708
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYKHE
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: 20150813
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20150708

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYKHE
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	20150813
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

E MANIFEST:

Manifest Tracking Number:	013726234FLE
Last Updated Date:	20200207
Shipped Date:	20191204
Received Date:	20191210
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Transformer Corp
Generator Location Street Number:	Not reported
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1747 DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013726312FLE
Last Updated Date:	20200520
Shipped Date:	20200508

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Received Date:	20200512
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Transformer Corp
Generator Location Street Number:	1755
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	1747
Generator Mail Street 1:	DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	1923
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	1923
Designated Facility Location Street 1:	FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013726351FLE
Last Updated Date:	20201215
Shipped Date:	20201203
Received Date:	20201208
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Transformer Corp
Generator Location Street Number:	1755
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	1747
Generator Mail Street 1:	DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	1923
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	1923
Designated Facility Location Street 1:	FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013726387FLE
Last Updated Date:	20210521
Shipped Date:	20210503
Received Date:	20210504
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Power Transformer
Generator Location Street Number:	Not reported
Generator Location Street 1:	1755 DALE ROAD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO,
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1755 DALE ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO,
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK STREET
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	011525950FLE
Last Updated Date:	20180928
Shipped Date:	20180820
Received Date:	20180828
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Transformer Corp
Generator Location Street Number:	Not reported
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1747 DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	012226805FLE
Last Updated Date:	20190307
Shipped Date:	20190108
Received Date:	20190115
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Transformer Corp
Generator Location Street Number:	Not reported
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1747 DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012226853FLE
Last Updated Date:	20191007
Shipped Date:	20190510
Received Date:	20190514
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Transformer Corp
Generator Location Street Number:	Not reported
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1747 DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK ST
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Designated Facility Location Street 1:	1923 FREDERICK ST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015712089FLE
Last Updated Date:	20231122
Shipped Date:	20231016
Received Date:	20231019
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Power Transformer
Generator Location Street Number:	1755
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	1755
Generator Mail Street 1:	DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD066060609
Designated Facility Name:	Chemtron Corporation
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	35850 SCHNEIDER CT
Designated Facility Mail City:	AVON
Designated Facility Mail Zip:	44011
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	35850 SCHNEIDER CT
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	AVON
Designated Facility Location Zip:	44011
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015712131FLE
Last Updated Date:	20240509
Shipped Date:	20240327
Received Date:	20240403
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Generator Name:	Niagara Power Transformer
Generator Location Street Number:	1755
Generator Location Street 1:	1755 DALE RD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	1755
Generator Mail Street 1:	DALE RD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD066060609
Designated Facility Name:	Chemtron Corporation
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	35850 SCHNEIDER CT
Designated Facility Mail City:	AVON
Designated Facility Mail Zip:	44011
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	35850 SCHNEIDER CT
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	AVON
Designated Facility Location Zip:	44011
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015712153FLE
Last Updated Date:	20220202
Shipped Date:	20220114
Received Date:	20220124
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Power Transformer
Generator Location Street Number:	Not reported
Generator Location Street 1:	1755 DALE ROAD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO,
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1755 DALE ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO,
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit, Inc.
Designated Facility Mail Street Number:	Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK STREET
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015712178FLE
Last Updated Date:	20220804
Shipped Date:	20220721
Received Date:	20220728
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYR000171371
Generator Name:	Niagara Transformer Corp.
Generator Location Street Number:	Not reported
Generator Location Street 1:	1755 DALE ROAD
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1755 DALE ROAD
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK STREET
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48211
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	015712232FLE

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Transporter Line Number: 1
Transporter EPA ID: NYD986903904
Transporter Name: Environmental Services Group, Inc. (Ny)

Waste Line:
Manifest Tracking Number: 015712232FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN2491
U.S. DOT Description: Rq, Un2491, Waste, Ethanolamine Solution, 8, Pgiii, D002, Erg#153
Non-Hazardous Waste Description: Not reported
Number of Containers: 5
Container Type Code: DF
Container Type Description: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 275
Quantity Unit of Measure Code: G
Quantity Unit of Measure Description: Gallons
Waste Quantity, in Tons: 1.146789
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 1.146789
Waste Quantity, in Kilograms: 1040.172
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 1040.172
Management Method Code: H110
Management Method Description: STABILIZATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D002
Quantity Haz Kg: 1040.172
Quantity Haz Tons: 1.146789
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: Not reported

Manifest Tracking Number: 015712232FLE
Waste Line Number: 2
U.S. DOT Hazardous Indicator: N
U.S. DOT ID Number: Not reported
U.S. DOT Description: Not reported
Non-Hazardous Waste Description: Non Hazardous Solid
Number of Containers: 4
Container Type Code: BA
Container Type Description: Burlap, cloth, paper, or plastic bags
Waste Quantity: 400
Quantity Unit of Measure Code: P

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.2
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.2
Waste Quantity, in Kilograms:	181.406
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	181.406
Management Method Code:	H110
Management Method Description:	STABILIZATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	181.406
Quantity Non Haz Tons:	0.2
State Waste Codes:	Not reported

Manifest Tracking Number:	015712232FLE
Waste Line Number:	3
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Non Hazardous Solid
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	100
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.05
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.05
Waste Quantity, in Kilograms:	45.3515
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	45.3515
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	45.3515
Quantity Non Haz Tons:	0.05
State Waste Codes:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional US EManifest: record(s) in the EDR Site Report.

NY MANIFEST:

EPA ID:	NYR000171371
Country:	USA
Name:	Niagara Transformer Corp
Address:	1755 DALE RD
Address 2:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14225
Zip 4:	Not reported
Location Address 1:	1755 DALE ROAD
Location Address 2:	Not reported
Location City,State,Zip:	CHEEKTOWAGA, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Niagara Transformer Corp
Mailing Contact:	Niagara Transformer Corp
Mailing Address 1:	1747 DALE ROAD
Mailing Address 2:	Not reported
Mailing City,State,Zip:	CHEEKTOWAGA, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5855945545

Manifest Data:

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/04/2010
Trans1 Recv Date:	03/04/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/05/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: 007060365JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H132
Waste Code a: B007
Waste Code b: Not reported
Waste Code c: Not reported
Waste Code e: Not reported
Waste Code f: Not reported
Waste Code g: Not reported
Waste Code 1: Not reported
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 26762
Units: Kilograms
Number of Containers: 1
Container Type: Dump truck
Handling Method: Landfill
Specific Gravity: 1

Document ID: Not reported
Manifest Status: Not reported
Trans1 State ID: NYD046765574
Year: 2018
Trans2 State ID: Not reported
Generator Ship Date: 03/05/2010
Trans1 Recv Date: 03/05/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/05/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000171371
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD049836679
TSDF ID 2: Not reported
Manifest Tracking Number: 007060363JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: Y
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	31670
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2010
Trans1 Recv Date:	03/05/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/08/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	007060364JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	33094
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD097644801
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/18/2018
Trans1 Recv Date:	01/18/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/23/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	009805851FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Not reported
Waste Code b:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

	One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code e:	Ignitable Waste
Waste Code f:	Methyl Ethyl Ketone
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD097644801
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	01/18/2018
Trans1 Recv Date:	01/18/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/23/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	009805851FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Waste Code b:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code c:	Ignitable Waste
Waste Code e:	Methyl Ethyl Ketone
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	55
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Year:	2018
Trans2 State ID:	NYD982792814
Generator Ship Date:	12/29/2014
Trans1 Recv Date:	12/29/2014
Trans2 Recv Date:	01/05/2015
TSD Site Recv Date:	01/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	008144741FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code a:	Ignitable Waste
Waste Code b:	Methyl Ethyl Ketone
Waste Code c:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

	Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code e:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	500
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MAD039322250
Year:	2018
Trans2 State ID:	NYD982792814
Generator Ship Date:	12/29/2014
Trans1 Recv Date:	12/29/2014
Trans2 Recv Date:	01/05/2015
TSD Site Recv Date:	01/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD053348108
TSDF ID 2:	Not reported
Manifest Tracking Number:	008144741FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Waste Code a:	Ignitable Waste
Waste Code b:	Methyl Ethyl Ketone
Waste Code c:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code e:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	350
Units:	Pounds
Number of Containers:	1
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/12/2010
Trans1 Recv Date:	03/12/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	007060366JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	16592
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD045765574
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	03/23/2010
Trans1 Recv Date:	03/23/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/29/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	005926523JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	10078
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2010
Trans1 Recv Date:	02/17/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/17/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	007060277JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	33203
Units:	Kilograms
Number of Containers:	1

NIAGARA TRANSFORMER CORP (Continued) **1012211730**

Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	NYD046765574
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2010
Trans1 Recv Date:	02/17/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/17/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000171371
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD049836679
TSDF ID 2:	Not reported
Manifest Tracking Number:	007060278JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H132
Waste Code a:	B007
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	32922
Units:	Kilograms
Number of Containers:	1
Container Type:	Dump truck
Handling Method:	Landfill
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
62 additional NY MANIFEST: record(s) in the EDR Site Report.

I42 **NIAGARA TRANSFORMER CORP.** **NY AST** **A100383041**
SSE **1755 DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.121 mi.
640 ft. **Site 2 of 7 in cluster I**

Relative:
Lower

Actual:
652 ft.

AST:

Name:	NIAGARA TRANSFORMER CORP.
Address:	1755 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-601377
Program Type:	PBS
UTM X:	192077.29011
UTM Y:	4756993.12984
Expiration Date:	09/25/2028
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	487264
Affiliation Type:	Facility Owner
Company Name:	NIAGARA TRANSFORMER CORP.
Contact Type:	PRESIDENT
Contact Name:	JOHN F. DARBY
Address1:	1747 DALE ROAD
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 896-6500
EMail:	Not reported
Fax Number:	Not reported
Modified By:	PAREUBEN
Date Last Modified:	2014-06-19

Site Id:	487264
Affiliation Type:	Emergency Contact
Company Name:	NIAGARA TRANSFORMER CORP.
Contact Type:	Not reported
Contact Name:	STAN HATCH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 551-8688
EMail:	Not reported
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-10-04

Site Id:	487264
Affiliation Type:	Facility Operator
Company Name:	STAN HATCH
Contact Type:	Not reported
Contact Name:	STAN HATCH

NIAGARA TRANSFORMER CORP. (Continued) **A100383041**

Address1:	1755 Dale Road
Address2:	Not reported
City:	Buffalo
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 896-6500
EMail:	shatch@nptransformer.com
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-10-04

Site Id:	487264
Affiliation Type:	Mail Contact
Company Name:	NIAGARA POWER TRANSFORMER CORP.
Contact Type:	Not reported
Contact Name:	STEVE KLOCK
Address1:	1747 DALE ROAD
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 896-6500
EMail:	SKLOCK@NPTRANSFORMER.COM
Fax Number:	Not reported
Modified By:	nFormUpd
Date Last Modified:	2023-10-04

Tank Info:

Tank Number:	T-100
Tank Id:	249739

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
B09 - Tank External Protection - Urethane
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
E01 - Piping Secondary Containment - Diking (AG only)
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/03/2013
Capacity Gallons:	20000
Tightness Test Method:	NN

NIAGARA TRANSFORMER CORP. (Continued) **A100383041**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	insulating oil
Tank Number:	T-200
Tank Id:	249740
Equipment Records:	K00 - Spill Prevention - None D01 - Pipe Type - Steel/Carbon Steel/Iron F01 - Pipe External Protection - Painted/Asphalt Coating I03 - Overfill - Automatic Shut-Off A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating J02 - Dispenser - Suction Dispenser L00 - Piping Leak Detection - None G01 - Tank Secondary Containment - Diking (Aboveground) H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G) B09 - Tank External Protection - Urethane I04 - Overfill - Product Level Gauge (A/G) E01 - Piping Secondary Containment - Diking (AG only) C01 - Pipe Location - Aboveground
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/03/2013
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	insulating oil
Tank Number:	T-300
Tank Id:	249741
Equipment Records:	I03 - Overfill - Automatic Shut-Off K00 - Spill Prevention - None D01 - Pipe Type - Steel/Carbon Steel/Iron F01 - Pipe External Protection - Painted/Asphalt Coating A00 - Tank Internal Protection - None B01 - Tank External Protection - Painted/Asphalt Coating H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G) J02 - Dispenser - Suction Dispenser L00 - Piping Leak Detection - None B09 - Tank External Protection - Urethane

NIAGARA TRANSFORMER CORP. (Continued) **A100383041**

G01 - Tank Secondary Containment - Diking (Aboveground)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E01 - Piping Secondary Containment - Diking (AG only)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/03/2013
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	insulating oil

Tank Number:	T-400
Tank Id:	249742

Equipment Records:

K00 - Spill Prevention - None
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
B09 - Tank External Protection - Urethane
F05 - Pipe External Protection - Jacketed
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
E01 - Piping Secondary Containment - Diking (AG only)

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/03/2013
Capacity Gallons:	20000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	insulating oil

I43 **CONCRETE** **NY SHWS** **S110043640**
SSE **1755 DALE RD** **NY INST CONTROL** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225** **NY BROWNFIELDS**
0.121 mi. **NY Spills**
640 ft. **Site 3 of 7 in cluster I**

Relative:
Lower

Actual:
652 ft.

SHWS:
Name: NIAGARA TRANSFORMER CORP. - EAST LOT
Address: 1755 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Program: HW
Site Code: 407317
Classification: N
Region: 9
Acres: 4.640
HW Code: 915234
Record Add: 12/02/2008
Record Upd: 02/19/2013
Updated By: MLDOSTER
Site Description: Location: The site is a vacant 3.2 acre lot located at 1755 Dale Road, Cheektowaga, NY, Erie County. The site is located 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded on the west by a paved driveway and parking lot to the Niagara Transformer Corporation s (NTC) existing manufacturing facility, Dale Road on the north, an active railroad switching yard on the south, and another NTC-owned vacant parcel to the east. Site Features: The area surrounding the site is primarily commercial/light industrial; two residential properties are located approximately 250 feet to the south-southeast of the site, on the opposite side of the railroad yard and Broadway Street. The next nearest residential area is located approximately 1100 feet to the southwest of the site. NTC s manufacturing facility to the west is the remediated NYS Superfund site #915146. Current Zoning/Use(s): The Niagara Transformer Corp. Site is currently zoned as vacant land in a commercial area. Historical Use(s): Polychlorinated Biphenyl s (PCBs) were found in the surface soils during preliminary investigations. As part of its Brownfield Cleanup Program (BCP) application, NTC proposed to further investigate the extent of the site contamination and to excavate and dispose of PCB-contaminated soils as an interim remedial measure (IRM). A Brownfield Cleanup Agreement was executed in November 2009. The soil excavation IRM was completed in April 2010. A draft Remedial Investigation/Alternatives Analysis/IRM report was submitted in May 2010 and submitted for public review. There were no comments provided by the public when the review period closed in August 2010 and the report was finalized. The site s intended use is industrial; NTC proposes to construct a facility to expand its existing electrical transformer manufacturing operations from the adjacent parcel. The Environmental Easement was executed and filed with the Erie County Clerk on July 15, 2010. A Final Engineering Report was submitted in the fall 2010. This report documented the removal actions and provides confirmatory sample analysis indicating the satisfactory removal of PCB impacted soils. A Certificate of Completion was issued on December 24, 2010. Site Geology and Hydrogeology: The Site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site.

CONCRETE (Continued) **S110043640**

	The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.See Site #C915234 for furthe information.
Env Problem:	Post-Remediation: All on-site post-excavation soil sample results were below the 25 ppm Industrial SCO for PCBs, site remediation is complete. The maximum residual PCB concentration detected in any one excavated grid area was 4.8 ppm (Grid 3 Floor). Outside of the IRM-excavated grid areas, the PCB concentrations that remain in the soil/fill on site range from 0.4 to 11.2 ppm.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	JOHN F. DARBY
Owner Company:	NIAGARA TRANSFORMER CORPORATION
Owner Address:	1747 DALE ROAD
Owner Addr2:	P.O. BOX 14225
Owner City,St,Zip:	CHEEKTOWAGA, NY 14225
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	NIAGARA TRANSFORMER CORPORATION
Owner Address:	1747 DALE ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	CHEEKTOWAGA, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	JOHN F. DARBY
Owner Company:	NIAGARA TRANSFORMER CORP
Owner Address:	1747 DALE ROAD
Owner Addr2:	P.O. BOX 233
Owner City,St,Zip:	CHEEKTOWAGA, NY 14225
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

CONCRETE (Continued) **S110043640**

INST CONTROL:

Name:	NIAGARA TRANSFORMER CORP.
Address:	1755 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Site Code:	418419
Control Name:	Monitoring Plan
HW Code:	C915234
Control Code:	31
Control Type:	INST
Dt record added:	07/06/2010
Dt rec updated:	11/18/2022
Updated By:	AECAPRIO
Site Code:	418419
Site Description:	Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.
Env Problem:	Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.
Health Problem:	Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-08-25 16:11:00
Record Upd:	2010-10-26 15:25:00

CONCRETE (Continued) **S110043640**

Updated By: dplocey
Own Op: 6
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: CHRIS BAZAN
Owner Company: CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address: 2580 HARLEM ROAD
Owner Addr2: Not reported
Owner City,St,Zip: CHEEKTOWAGA, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
HW Code: C915234
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915234-10-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2010-10-20 13:37:00
Record Updated: 2010-10-20 13:37:00
Updated By: dplocey
Crossref ID: 2010124669
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2010-10-26 13:32:00
Record Updated: 2010-10-26 13:32:00
Updated By: dplocey

Name: NIAGARA TRANSFORMER CORP.
Address: 1755 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 418419
Control Name: Ground Water Use Restriction
HW Code: C915234
Control Code: 08
Control Type: INST
Dt record added: 07/06/2010
Dt rec updated: 11/18/2022
Updated By: AECAPRIO
Site Code: 418419
Site Description: Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden

CONCRETE (Continued) **S110043640**

Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.

Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.

Health Problem: Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-08-25 16:11:00
Record Upd: 2010-10-26 15:25:00
Updated By: dplocey
Own Op: 6
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: CHRIS BAZAN
Owner Company: CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address: 2580 HARLEM ROAD
Owner Addr2: Not reported
Owner City,St,Zip: CHEEKTOWAGA, NY 14225

CONCRETE (Continued) **S110043640**

Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
HW Code: C915234
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915234-10-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2010-10-20 13:37:00
Record Updated: 2010-10-20 13:37:00
Updated By: dplocey
Crossref ID: 2010124669
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2010-10-26 13:32:00
Record Updated: 2010-10-26 13:32:00
Updated By: dplocey

Name: NIAGARA TRANSFORMER CORP.
Address: 1755 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 418419
Control Name: Environmental Easement
HW Code: C915234
Control Code: J
Control Type: INST
Dt record added: 07/06/2010
Dt rec updated: 11/18/2022
Updated By: AECAPRIO
Site Code: 418419
Site Description: Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a

CONCRETE (Continued) **S110043640**

previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.
Health Problem: Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.
Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-08-25 16:11:00
Record Upd: 2010-10-26 15:25:00
Updated By: dplocey
Own Op: 6
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: CHRIS BAZAN
Owner Company: CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address: 2580 HARLEM ROAD
Owner Addr2: Not reported
Owner City,St,Zip: CHEEKTOWAGA, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
HW Code: C915234
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915234-10-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number

CONCRETE (Continued) **S110043640**

Record Added Date: 2010-10-20 13:37:00
Record Updated: 2010-10-20 13:37:00
Updated By: dplocey
Crossref ID: 2010124669
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2010-10-26 13:32:00
Record Updated: 2010-10-26 13:32:00
Updated By: dplocey

Name: NIAGARA TRANSFORMER CORP.
Address: 1755 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 418419
Control Name: Site Management Plan
HW Code: C915234
Control Code: 32
Control Type: INST
Dt record added: 07/06/2010
Dt rec updated: 11/18/2022
Updated By: AECAPRIO
Site Code: 418419
Site Description: Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.
Health Problem: Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.
Dump: True
Structure: False

CONCRETE (Continued) **S110043640**

Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-08-25 16:11:00
Record Upd: 2010-10-26 15:25:00
Updated By: dplocey
Own Op: 6
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: CHRIS BAZAN
Owner Company: CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address: 2580 HARLEM ROAD
Owner Addr2: Not reported
Owner City,St,Zip: CHEEKTOWAGA, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
HW Code: C915234
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915234-10-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2010-10-20 13:37:00
Record Updated: 2010-10-20 13:37:00
Updated By: dplocey
Crossref ID: 2010124669
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2010-10-26 13:32:00
Record Updated: 2010-10-26 13:32:00
Updated By: dplocey

Name: NIAGARA TRANSFORMER CORP.
Address: 1755 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 418419
Control Name: Soil Management Plan
HW Code: C915234

CONCRETE (Continued) **S110043640**

Control Code: 14
Control Type: INST
Dt record added: 07/06/2010
Dt rec updated: 11/18/2022
Updated By: AECAPRIO
Site Code: 418419
Site Description: Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.
Health Problem: Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.
Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-08-25 16:11:00
Record Upd: 2010-10-26 15:25:00
Updated By: dplocey
Own Op: 6
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported

CONCRETE (Continued) **S110043640**

Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: CHRIS BAZAN
Owner Company: CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address: 2580 HARLEM ROAD
Owner Addr2: Not reported
Owner City,St,Zip: CHEEKTOWAGA, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
HW Code: C915234
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915234-10-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2010-10-20 13:37:00
Record Updated: 2010-10-20 13:37:00
Updated By: dplocey
Crossref ID: 2010124669
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2010-10-26 13:32:00
Record Updated: 2010-10-26 13:32:00
Updated By: dplocey

Name: NIAGARA TRANSFORMER CORP.
Address: 1755 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 418419
Control Name: Landuse Restriction
HW Code: C915234
Control Code: 25
Control Type: INST
Dt record added: 07/06/2010
Dt rec updated: 11/18/2022
Updated By: AECAPRIO
Site Code: 418419
Site Description: Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light

CONCRETE (Continued) **S110043640**

industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.

Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.

Health Problem: Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.

Dump: True
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2009-08-25 16:11:00
Record Upd: 2010-10-26 15:25:00
Updated By: dplocey
Own Op: 6
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported
Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: CHRIS BAZAN
Owner Company: CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address: 2580 HARLEM ROAD
Owner Addr2: Not reported
Owner City,St,Zip: CHEEKTOWAGA, NY 14225
Owner Country: United States of America
Own Op: 1
Sub Type: P02
Owner Name: John F. Darby
Owner Company: Niagara Transformer Corp.
Owner Address: 1747 Dale Road
Owner Addr2: Not reported

CONCRETE (Continued) **S110043640**

Owner City,St,Zip: Cheektowaga, NY 14225
Owner Country: United States of America
HW Code: C915234
Waste Type: POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C915234-10-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2010-10-20 13:37:00
Record Updated: 2010-10-20 13:37:00
Updated By: dplocey
Crossref ID: 2010124669
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2010-10-26 13:32:00
Record Updated: 2010-10-26 13:32:00
Updated By: dplocey

Name: NIAGARA TRANSFORMER CORP.
Address: 1755 DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY 14225
Site Code: 418419
Control Name: IC/EC Plan
HW Code: C915234
Control Code: 34
Control Type: INST
Dt record added: 07/06/2010
Dt rec updated: 11/18/2022
Updated By: AECAPRIO
Site Code: 418419
Site Description: Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.
Env Problem: Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup

CONCRETE (Continued) **S110043640**

	objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.
Health Problem:	Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2009-08-25 16:11:00
Record Upd:	2010-10-26 15:25:00
Updated By:	dplocey
Own Op:	6
Sub Type:	P02
Owner Name:	John F. Darby
Owner Company:	Niagara Transformer Corp.
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	CHRIS BAZAN
Owner Company:	CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address:	2580 HARLEM ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	CHEEKTOWAGA, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	P02
Owner Name:	John F. Darby
Owner Company:	Niagara Transformer Corp.
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
HW Code:	C915234
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C915234-10-09
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2010-10-20 13:37:00
Record Updated:	2010-10-20 13:37:00
Updated By:	dplocey
Crossref ID:	2010124669
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2010-10-26 13:32:00

CONCRETE (Continued) **S110043640**

Record Updated: 2010-10-26 13:32:00
Updated By: dplocey

BROWNFIELDS:

Name:	NIAGARA TRANSFORMER CORP.
Address:	1755 DALE ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Program:	BCP
Site Code:	418419
Acres:	3.200
HW Code:	C915234
SWIS:	1530
Town:	Cheektowaga
Record Added Date:	08/25/2009
Record Updated Date:	12/02/2024
Update By:	AECAPRIO
Site Description:	Location: The Niagara Transformer Corp. site is a 3.2-acre site, located in an urban area, at 1755 Dale Road in the Town of Cheektowaga, Erie County. The site is 1500 feet south of Walden Avenue and 1000 feet west of Interstate 90. The site is bounded by a paved driveway and parking lot to the west, Dale Road to the north, an active railroad switching yard to the south, and a vacant parcel to the east. Site Features: The site has been redeveloped with a large industrial building, which occupies most of the southern portion of the parcel, and an asphalt parking lot just north of the building. The area surrounding the site is primarily commercial/light industrial. The nearest residential area is located approximately 1100 feet to the southwest. Current Zoning and Land Use: The site is currently zoned for industrial use. Past Use of the Site: Polychlorinated biphenyls (PCBs) were found in surface soils during preliminary site investigations. Site Geology and Hydrogeology: The site surface has a gradual slope to the south towards a surface water drainage ditch which lies between the site and railroad yard. The drainage ditch flows westward, past the Niagara Transformer site (#915146) where the ditch has been lined with concrete as part of a previous remedial action. The surface water collects in a storm water retention pond, located approximately 1,100 feet west of the site. The retention pond drains to municipal storm sewers which discharge to the Buffalo River, approximately 3 miles southwest of the site.
Env Problem:	Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polychlorinated biphenyls (PCBs) in soil. Remedial activities have successfully achieved soil cleanup objectives for industrial use. Residual contamination in soil is being managed under a Site Management Plan.
Health Problem:	Remedial activities have eliminated the immediate exposure threat to PCBs, and planned site development will include measures to further eliminate the exposure potential to residual levels of PCBs. The area is served by public water so exposure via drinking water is not expected.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported

CONCRETE (Continued) **S110043640**

Dell:	Not reported
Record Add:	2009-08-25 16:11:00
Record Upd:	2010-10-26 15:25:00
Updated By:	dplocey
Own Op:	6
Sub Type:	P02
Owner Name:	John F. Darby
Owner Company:	Niagara Transformer Corp.
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	CHRIS BAZAN
Owner Company:	CHEEKTOWAGA PUBLIC LIBRARY, ANNA REINSTEIN MEMORIAL BRANCH
Owner Address:	2580 HARLEM ROAD
Owner Addr2:	Not reported
Owner City,St,Zip:	CHEEKTOWAGA, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	P02
Owner Name:	John F. Darby
Owner Company:	Niagara Transformer Corp.
Owner Address:	1747 Dale Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
HW Code:	C915234
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C915234-10-09
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2010-10-20 13:37:00
Record Updated:	2010-10-20 13:37:00
Updated By:	dplocey
Crossref ID:	2010124669
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2010-10-26 13:32:00
Record Updated:	2010-10-26 13:32:00
Updated By:	dplocey

SPILLS:

Name:	NIAGARA TRANSFORMER PLANT
Address:	1755 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1310803 / 2014-10-29
Facility ID:	1310803
Facility Type:	ER
DER Facility ID:	446084
Site ID:	491673
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C4

CONCRETE (Continued) **S110043640**

SWIS:	1530
Spill Date:	2014-02-14
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2014-02-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-02-14
Spill Record Last Update:	2014-10-29
Spiller Name:	TED RZEPRCKI
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1755 DALE RD.
Spiller Company:	001
Contact Name:	TED RZEPECKI
Latitude:	42.9034314
Longitude:	-78.7716867
DEC Memo:	2/14/2014: RJJ TELECON TED RZEPECKI,NIAGARA TRANSFORMER,HE SAID THAT WHILE TESTING A NEW TRANSFORMER SYSTEM,~5 GALS. OF NON-PCB TRANSFORMER OIL LEAKED OUT ALL ONTO THEIR CONCRETE FLOOR,INSIDE THEIR FACILITY...NIAGARA TRANSFORMER PERSONNEL QUICKLY USED ABSORBANT PADS AND CLEANED-UP THIS...NONE OF THE OIL REACHED ANY FLOOR DRAINS,IT HAS ALL BEEN RECOVERED AND WILL BE DISPOSED OF...TED WILL SEND ME THE DISPOSAL RECEIPTS. 10/29/2014: RECEIVED THE DISPOSAL RECEIPTS FOR THE 7-55 GALS. DRUMS OF SPILL MATERIAL TAKEN TO THE SPRING GROVE RESOURCE RECOVERY INC.,IN OHIO...THE SPILL HAS BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	vleanup done

All Materials:

Site ID:	491673
Operable Unit ID:	1241221
Operable Unit:	01
Material ID:	2241528
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

Name:	CONCRETE
Address:	1755 DALE RD

CONCRETE (Continued) **S110043640**

City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1310240 / 2014-11-03
Facility ID:	1310240
Facility Type:	ER
DER Facility ID:	446084
Site ID:	491080
DEC Region:	9
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	1530
Spill Date:	2014-01-23
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2014-01-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-01-23
Spill Record Last Update:	2014-11-03
Spiller Name:	TED RZEPECKI
Spiller Company:	NIAGARA TRANSFORMER CORP
Spiller Address:	1755 DALE RD.
Spiller Company:	001
Contact Name:	TED RZEPECKI
Latitude:	42.9034314
Longitude:	-78.7716868
DEC Memo:	1/23/2014: RJJ TELECON TED RZEPECKI,NIAGARA TRANSFORMER,HE SAID THAT WHILE TESTING A NEW TRANSFORMER,~2 GALS. ON NON-PCB TRANSFORMER OIL LEAKED OUT,ALL ONTO THEIR CONCRETE FLOOR,INSIDE THEIR NEW BUILDING...NIAGARA TRANSFORMER PERSONNEL QUICKLY USED ABSORBANT PADS AND CLEANED-UP THIS SPILL...NONE OF THE OIL REACHED ANY FLOOR DRAINS,IT HAS BEEN ALL RECOVERED...THEY PLACED ALL THE SPILL MATERIAL INTO A DRUM,WHICH WILL BE DISPOSED OF...TED WILL SEND ME THE DISPOSAL RECEIPTS. 10/31/2014: RECEIVED THE DISPOSAL RECEIPTS FOR THE 2 DRUMS OF SPILL MATERIAL TAKEN TO CLEAN HARBORS EL DORADO,LLC,IN AR...THE SPILL HAS BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	Caller advised aprx 2 gal of oil spilled onto concrete floor. Clean up is complete.

All Materials:

Site ID:	491080
Operable Unit ID:	1240627
Operable Unit:	01
Material ID:	2240847
Material Code:	0020A
Material Name:	transformer oil

CONCRETE (Continued) **S110043640**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

I44 **MI MANIFEST** **S130528857**
SSE **1755 DALE RD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.121 mi.
640 ft. **Site 4 of 7 in cluster I**

Relative: MI MANIFEST:
Lower

Actual:
652 ft.

Generator Site ID Manifest:	NYR000171371
Name:	Not reported
Address:	1755 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Manifest Number:	009805851FLE
Manifest Date:	01/23/2018
Transporter Site ID Manifest:	NYD097644801
Transporter Site Legal Name Site Table:	TONAWANDA TANK TRANSPORT SERVICE INC
TSD Site ID Manifest:	MID980991566
TSD Site Legal Name Site Table:	EQ DETROIT INC
Container Number:	Not reported
Container Type:	Not reported
Total Quantity:	55
Unit Of Measure:	G
Waste Number:	F003
Waste Number 2:	F005
Waste Number 3:	D001
Waste Number 4:	D035
Waste Number 5:	Not reported
Waste Number 6:	Not reported

Generator Site ID Manifest:	NYR000171371
Name:	Not reported
Address:	1755 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Manifest Number:	009805851FLE
Manifest Date:	01/23/2018
Transporter Site ID Manifest:	NYD097644801
Transporter Site Legal Name Site Table:	TONAWANDA TANK TRANSPORT SERVICE INC
TSD Site ID Manifest:	MID980991566
TSD Site Legal Name Site Table:	EQ DETROIT INC
Container Number:	Not reported
Container Type:	Not reported
Total Quantity:	55
Unit Of Measure:	P
Waste Number:	F003
Waste Number 2:	F005
Waste Number 3:	D001
Waste Number 4:	D035
Waste Number 5:	Not reported
Waste Number 6:	Not reported

I45 **MANUFACTURING** **NY Spills** **S118951849**
SSE **1755 DALE RD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.121 mi.
640 ft. **Site 5 of 7 in cluster I**

Relative: **Lower**

Actual: **652 ft.**

SPILLS:

Name:	MANUFACTURING
Address:	1755 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	2500897 / Not Reported
Facility ID:	2500897
Facility Type:	ER
DER Facility ID:	446084
Site ID:	678187
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	1530
Spill Date:	2025-05-01
Investigator:	SACALAND
Referred To:	Not reported
Reported to Dept:	2025-05-01
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2025-05-01
Spill Record Last Update:	2025-07-16
Spiller Name:	STAN HATCH
Spiller Company:	NIAGARA TRANSFORMER. LLC
Spiller Address:	1755 DALE RD
Spiller Company:	999
Contact Name:	STAN HATCH
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	5/1/25:SAC TELECON STAN HATCH - NIAGARA TRANSFORMER. MR. HATCH SAID THE OIL PROCESSOR BACKFILLED AND CAUSE PRODUCT TO GO UP THE VENT PIPE. THE VENT PIPE DISCHARGES INTO A CONTAINMENT DIKE. HOWEVER, DUE TO THE WEATHER THIS PAST WINTER, THE VENT PIPE WAS DAMAGED AND CAUSED ABOUT 3 TO 5 GALLONS OF PRODUCT TO SPILL OUTSIDE OF THE DIKE ONTO A CONCRETE PAD AND THEN ONTO THE SOIL. MR. HATCH SAID THEY USED ABSORBENT PADS TO CLEANUP THE CONCRETE. THEY REMOVED THE CONTAMINATED SOIL AND PLACED IT INTO A 55 GALLON DRUM. THEY ALSO POWERWASHED THE CONCRETE AND COLLECTED THE WASHWASTER FOR DISPOSAL. HE SAID HE CONTACTED BRYAN HANN - TRC TO TAKE SAMPLES OF THE CLEANUP AREA. AND THEY HAVE CONTACTED CLEAN HARBORS TO COMPLETE THE DISPOSAL. 5/2/25:SAC TELECON BRYAN HANN. DISCUSSED THE SPILL SITE. SINCE THE SPILL WAS MINOR, MR. HANN WILL DO A VISUAL

MANUFACTURING (Continued) **S118951849**

ASSESSMENT OF THE CLEANUP.
ALTHOUGH IT ENCOMPASSES A SMALL AREA, PART OF THE SPIOLL AREA IS WITHIN A BROWNFIELD. THE TOP
SOILTHAT WILL BE USED TO BACKFILL THE WILL BE ANALYZED AS REQUIRED BY THE BROWNFIELD PROGRAM. MR.
HANN WILL SUBMIT A SITE DRAWING SHWOING THE SUSECTED SPILL LOCATION. ONCE EVERYTHING IS COMPLETED,
MR. HANN WILL SUBMIT A CLEANUP REPORT. SAC RECEIVED eMAIL FROM BRYAN HANN WITH LOT DESCRIPTIONS OF
THE SITE AND AN ATTACHED SITE DRAWING INDICATING WHERE SUSPECTED SPILL LOCATION IS. 5/5/25:SAC SENT
BRYAN HANN eMAIL WITH SITE MAP ATTACHMENT TO VMK. 7/16/25:SAC TELECON BRYAN HANN. MR. HANN SAID HE
COMPLETED THE LETTER REPORT FOR THE SITE AND HAS SUBMITTED IT TO STAN HATCH FOR HIS REVIEW. ONCE HE
RECEIVES IT BACK, HE WILL SEND IT TO SAC. HE ANTICIPATES HE WILL GET IT BACK FROM MR. HATCH THIS
WEEK SO HE WILL SUBMIT IT TO SAC. HE SAID SINCE THIS IS A BROWNFIELD SITE, HE FILLED OUT AN IMPORT
REQUEST FORM FOR 50 CUBIC YARDS WITH THE APPROPRIATE SAMPLE ANALYTICAL RESULTS TO VMK. VMK HAS
APPROVED THE REQUEST FORM. HE IS NOW WAITING FOR MR. HATCH TO OBTAIN THE SOIL FROM HIS CHOSEN
LANDSCAPER. THE SOIL WILL BE USED IN THE SPILL AREA AND OTHER AREAS THROUGH THE SITE NEEDED DUE TO
SNOWPLOW DAMAGE. THE DRUM OF CONTAMINATED MATERIAL FROM THE CLEANUP HAS NOT BEEN DISPOSED. IT WILL
BE DISPOSED ALONG WITH OTHER DRUMS OF MATERIAL UNRELATED TO THE SPILL CLEANUP AS PART OF A BULK RUN.
Not reported

Remarks: malfunction on oil processor

All Materials:

Site ID:	678187
Operable Unit ID:	1424849
Operable Unit:	01
Material ID:	2444413
Material Code:	2630
Material Name:	mineral oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	NIAGARA TRANSFORMER
Address:	1755 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1606171 / 2017-02-07
Facility ID:	1606171
Facility Type:	ER
DER Facility ID:	446084
Site ID:	532773
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3

MANUFACTURING (Continued) **S118951849**

SWIS:	1530
Spill Date:	2016-09-21
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2016-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-09-21
Spill Record Last Update:	2017-02-07
Spiller Name:	ROBERT BLAKE
Spiller Company:	NIAGARA TRANSFORMER CORP.
Spiller Address:	1747 DALE RD.
Spiller Company:	001
Contact Name:	ROBERT BLACK
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	9/21/16:SAC TELECON DISPATCHER SEYLER (BADGE #27) - ERIE COUNTY EMERGENCY SERVICES NOTIFYING COUNTY OF THE SPILL. RJJ AT SITE AT 1200...MEET WITH ROBERT BLAKE,NIAGARA TRANSFORMER MANAGER,HE EXPLAINED/SHOWM ME WHERE THEIR 20K VEGETABLE OIL AST LEAKED OUT ~2000 GALS. OF OIL,ALL INSIDE THEIR SECONDARY CONTAINMENT AREA,DUE TO THE HIGH LEVEL ALARM MALFUNTIONING...ALL THIS VEGETABLE OIL IS ALL CONTAINED IN THIS SECONDARY CONTAINMENT AREA AND THEY HAVE BEGUN TO PUMP-OUT ALL THIS OIL INTO CONTAINERS,WHICH NOCO WILL PICK-UP AND DISPOSE...MR. BLAKE WILL SEND ME THEIR REPORT AND THE DISPOSAL RECEIPTS. 2/7/2017: RECEIVED THE DISPOSAL RECEIPTS FOR THE 2000 GALS OF VEGETABLE OIL TAKEN TO NOCO DISTRIBUTION,LLC. IN TONAWANDA,NY...THE SPILL HAS BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.
Remarks:	1500 to 2000 gals oil to containment/clean up underway

All Materials:

Site ID:	532773
Operable Unit ID:	1281513
Operable Unit:	01
Material ID:	2286785
Material Code:	1856A
Material Name:	vegetable oil (dye/grease)
Case No.:	Not reported
Material FA:	Other
Quantity:	2000.00
Units:	G
Recovered:	2000.00
Oxygenate:	Not reported

I46 **INDUSTRIAL** **NY Spills** **S117393799**
SSE **1755 DALE RD** **N/A**
< 1/8 **CHEEKTOWGA, NY 14225**
0.121 mi.
640 ft. **Site 6 of 7 in cluster I**

Relative:
Lower

Actual:
652 ft.

SPILLS:

Name:	PLANT
Address:	1755 DALE RD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1409312 / 2015-05-29
Facility ID:	1409312
Facility Type:	ER
DER Facility ID:	446084
Site ID:	502923
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1530
Spill Date:	2014-12-15
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2014-12-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-12-15
Spill Record Last Update:	2015-05-29
Spiller Name:	JOHN DARBY
Spiller Company:	NIAGARA TRANSFORMER
Spiller Address:	1755 DALE RD
Spiller Company:	001
Contact Name:	JOHN DARBY
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	12/15/2014: RJJ AT SITE AT 1000...MEET WITH JOHN DARBY,PLANT MANAGER...HE EXPLAINED THAT WHILE TRANSFERING MINERAL-OIL BASED TRANSFORMER OIL INTO ONE OF THEIR 20K AST,~300 GALS. LEAKED OUT,FROM THE TOP OF THE TANK,INTO THEIR SECONDARY CONTAINMENT AREA,DUE TO A FAULITY SENSOR...A SMALL AMOUNT(~5 GALS),SPRAYED OUTSIDE THE CONTAINMENT AREA,HOWEVER,IT WAS ALL RECOVERED ON THE CONCRETE ISLAND...NIAGARA TRANSFORMER PERSONNEL ARE PUMPING OUT ALL THE OIL/WATER,IN THE CONTAINMENT AREA,INTO CONTAINERS,WHICH WILL BE DISPOSED OF,SINCE THIS OIL CAN NOT BE REUSED...NONE OF THE OIL REACHED ANY SOIL OR WATERWAYS,IT WILL ALL RECOVERED...JOHN DARBY WILL SEND ME THE DISPOSAL RECEIPTS. 5/29/2015: RECEIVED THE DISPOSAL RECEIPTS,FROM NIAGARA TRANSFORMER,FOR ALL THE TRANSFORMER OIL TAKEN BY NOCO TO THEIR FACILTY IN BINGHAMTON,NY,FOR

INDUSTRIAL (Continued) **S117393799**

DISPOSAL...THE SPILL HAS BEEN CLEANED-UP & PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.

Remarks: 300 gallons dike system - 5 gallons to loading system - all product contained

All Materials:

Site ID: 502923
Operable Unit ID: 1252288
Operable Unit: 01
Material ID: 2254357
Material Code: 2630
Material Name: mineral oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 300.00
Units: G
Recovered: 300.00
Oxygenate: Not reported

Name: INDUSTRIAL
Address: 1755 DALE RD
City,State,Zip: CHEEKTOWGA, NY 14225
Spill Number/Closed Date: 2003440 / 2020-07-30
Facility ID: 2003440
Facility Type: ER
DER Facility ID: 557477
Site ID: 609166
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 1530
Spill Date: 2020-07-28
Investigator: RMCROSSE
Referred To: Not reported
Reported to Dept: 2020-07-29
CID: Not reported
Water Affected: Not reported
Spill Source: Transformer
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2020-07-29
Spill Record Last Update: 2020-07-30
Spiller Name: KARL SCHURKUS
Spiller Company: NIARGRA TRANSFORMER
Spiller Address: 1755 DALE RD
Spiller Company: 999
Contact Name: KARL SCHURKUS
Latitude: Not reported
Longitude: Not reported
DEC Memo: 07/28/20 RMC/FILE. SPILL TO CONTAINMENT REPORTED AS ALREADY CLEANED UP. NO ACTION REQUIRED. CLOSE

INDUSTRIAL (Continued) **S117393799**

OUT.
Remarks: clean up completed

All Materials:
Site ID: 609166
Operable Unit ID: 1356308
Operable Unit: 01
Material ID: 2367624
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: 20.00
Oxygenate: Not reported

I47 **INDUSTRIAL** **NY Spills** **S131743430**
SSE **1755 DALE RD** **N/A**
< 1/8 **CHEEKTOWAGA, NY 14225**
0.121 mi.
640 ft. **Site 7 of 7 in cluster I**

Relative: SPILLS:
Lower
Name: INDUSTRIAL
Actual: Address: 1755 DALE RD
652 ft. City,State,Zip: CHEEKTOWAGA, NY 14225
Spill Number/Closed Date: 2308473 / 2024-01-22
Facility ID: 2308473
Facility Type: ER
DER Facility ID: 446084
Site ID: 662587
DEC Region: 9
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 1530
Spill Date: 2024-01-22
Investigator: SACALAND
Referred To: Not reported
Reported to Dept: 2024-01-22
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2024-01-22
Spill Record Last Update: 2024-01-22
Spiller Name: Not reported
Spiller Company: UNITED MATERIAL
Spiller Address: Not reported
Spiller Company: 999
Contact Name: EVAN MCCABE

INDUSTRIAL (Continued) **S131743430**

Latitude: Not reported
Longitude: Not reported
DEC Memo: 1/22/24:SAC TELECON EVAN MCCABE - UNITED MATERIALS. MR. MCCABE SAID THEY HAD A SPILL FROM ONE OF
THEIR CONCRETE TRUCKS WHEN THEY WERE DELIVERING TO NIAGARA TRANSFORMER AT 1755 DALE ROAD,
CHEEKTOWAGA. MR. MCCABE SAID THE SPILL WAS TO PAVEMENT ONLY AND THAT UNTIED MATERIAL EMPLOYEES AND
HE WENT TO THE SITE TO APPLY ABSORBENTS TO CLEANUP THE SPILL. THE CLEANUP WAS COMPLETED AND THEY
REMOVED THE CONTAMINATED MATERIAL GENERATED AS A RESULT OF THE CLEANUP. THE AMOUNT OF CONTAMINATED
MATERIAL GENERATED AS A RESULT FO THE CLEANUP WAS MINIMAL AND THEY DISPOSED OF IT THROUGH THEIR
REGUALR WASTE STREAM. CLOSE SPILL FILE.
Remarks: clean up complete

All Materials:
Site ID: 662587
Operable Unit ID: 1409390
Operable Unit: 01
Material ID: 2426898
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 4.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

H48 **CLARKLIFT OF BUFFALO** **NY LTANKS** **S103038057**
SE **DALE ROAD** **N/A**
< 1/8 **CHEEKTOWAGA, NY**
0.125 mi.
659 ft. **Site 6 of 8 in cluster H**

Relative: LTANKS:
Lower
Actual: Name: CLARKLIFT OF BUFFALO
652 ft. Address: DALE ROAD
City,State,Zip: CHEEKTOWAGA, NY
Spill Number/Closed Date: 8606943 / 1988-03-29
Facility ID: 8606943
Site ID: 109281
Spill Date: 1987-02-12
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-03-29
SWIS: 1530
Investigator: PRINGLE
Referred To: Not reported
Reported to Dept: 1987-02-12
CID: Not reported
Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: 1987-08-25

CLARKLIFT OF BUFFALO (Continued) **S103038057**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-02-23
Spill Record Last Update:	1988-04-05
Spiller Name:	Not reported
Spiller Company:	CLARKLIFT OF BUFFALO
Spiller Address:	1835 DALE ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	95983
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : M. PRINGLE INVESTIGATING. / / : MNP SITE INSP. 2/12/87, OIL IN DITCH, SPILLER AGREED TO CLEANUP;TELECON W/WILLIAMS 2/13/87, HIRED FLEISCHMAN'S TO START CLEANUP. / / : MNP SITE INSP. 2/20/87, OIL IN DITCH, CLEANUP UNDERWAY;JDC SITE INSP. 2/23/87, OIL IN DITCH AT GRUNNER & KENNEDY, SEE SPILL #867141. / / : TELECON W/WILLIAMS 2/23/87, AGREED TO START CLEANUP OF OTHER DITCH;MNP SITE INSP. 2/24,26/87, OIL IN DITCH, CLEANUP UNDERWAY. / / : MNP SITE INSP. 3/4/87, OIL REMAINS IN TANK AREA, NO PRODUCT IN DITCHES, ONLY SHEEN;TELECON W/WILLIAMS 3/19/87, TANKS TO BE TESTED 3/23/87. / / : JDC SITE INSP. 3/25/87, SHEEN IN DITCH, PADS & BOOMS TO BE PICKED UP;TELECON W/WILLIAMS 3/25/87, TO PICKUP SORBANTS & SAMPLE CONTAM. SOIL. / / : MNP SITE INSP 04/08/87, ADDITIONAL CLEANUP REQUIRED; LETTER 04/29/87, REPLY 04/29/87 - NG. / / : 4/9,23/87 TELECONS, MARSHALL TANK TO DO CLEANUP, TO CALL W/SCHEDULE;4/30/87 TELECON & MNP INSP, CLEANUP UNDERWAY & OK, CONTAM. SOIL IN DITCH. / / : 6/23/87 INSP, NO CONTAM. IN DITCH, NO FURTHER CLEANUP NEEDED;6/25/87 TELECON W/WILLIAMS, CLEANUP BY M. TANK 6/11/87;HOLD FOR DISP. RECEIPT. / / : 5/6/87 TELECON W/M. KIMMONS HE WILL REMOVE CONTAM. SEDIMENTS FROM DITCH;5/27/87 MNP INSP, CLEANUP IN TANK AREA OK, NO CLEANUP OF DITCH YET. / / : 7/7,10/87 TELECONS W/WILLIAMS, TANK TEST FAILED, TANK TO BE REMOVED;8/25/87 MNP TELECON & INSP. TANK REMOVED, NO CONTAM. SOIL IN EXCAVATION. / / : MNP TELECON 10/19/87, SOIL DISPOSAL RECEIPT TO BE SENT. / / : 12/15/87 LETTER TO CLARKLIFT;12/17/87 MNP TELECON, AGREED TO SEND SAMPLE RESULTS & DISPOSAL RECEIPTS;12/18/87 RECEIVED INCOMPLETE INFO. / / : 2/1/88 MNP TELECON W/WILLIAMS, DOES NOT HAVE INFO., TOLD ME TO CONTACT M. KIMMONS FOR INFO.;2/1/88 MNP TELECON TO M.KIMMONS, TO RETURN CALL;2/19/88 LETTER TO KIMMONS. / / : 3/21/88 LETTER TO CLARKLIRT;3/29/88 RECEIVED DISPOSAL INFO., NO FURTHER ACTION TO BE TAKEN, COMPLETE.
Remarks:	OIL IN DITCH NEAR COOK MOVING & STORAGE ON DALE RD, SOURCE IS CLARKLIFT

All Materials:

Site ID:	109281
Operable Unit ID:	904539
Operable Unit:	01
Material ID:	472494
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported

CLARKLIFT OF BUFFALO (Continued) **S103038057**

Material FA:	Petroleum
Quantity:	700.00
Units:	G
Recovered:	400.00
Oxygenate:	Not reported

H49 **VSE CORPORATION CORRIGAN MOVING LOCATION** **NY MANIFEST** **S130582563**
SE **1845 DALE RD** **N/A**
1/8-1/4 **BUFFALO, NY 14225**
0.128 mi.
678 ft. **Site 7 of 8 in cluster H**

Relative: **Lower**
Actual: **652 ft.**

NY MANIFEST:

EPA ID:	NYR000247387
Country:	USA
Name:	Vse Corporation Corrigan Moving Location
Address:	1845 DALE RD
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225
Zip 4:	Not reported
Location Address 1:	1845 DALE RD
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Vse Corporation Corrigan Moving Location
Mailing Contact:	Vse Corp
Mailing Address 1:	8348 WALKER LN
Mailing Address 2:	Not reported
Mailing City,State,Zip:	ALEXANDRIA, VA 22310
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7033294364

H50 **VSE CORPORATION CORRIGAN MOVING LOCATION** **RCRA NonGen / NLR** **1026498412**
SE **1845 DALE RD** **E MANIFEST** **NYR000247387**
1/8-1/4 **BUFFALO, NY 14225**
0.128 mi.
678 ft. **Site 8 of 8 in cluster H**

Relative: **Lower**
Actual: **652 ft.**

RCRA Listings:

Date Form Received by Agency:	20210513
Handler Name:	Vse Corporation Corrigan Moving Location
Handler Address:	Dale Rd
Handler City,State,Zip:	BUFFALO, NY 14225
EPA ID:	NYR000247387
Contact Name:	CYNDI INSCOE
Contact Address:	WALKER LAND
Contact City,State,Zip:	ALEXANDRIA, VA 22310
Contact Telephone:	703-329-4364
Contact Fax:	Not reported

VSE CORPORATION CORRIGAN MOVING LOCATION (Continued) **1026498412**

Contact Email:		CLINSCOE@VSECORP.COM
Contact Title:		PROGRAM CONTROL ANALYST
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		WALKER LAND
Mailing City,State,Zip:		ALEXANDRIA, VA 22310
Owner Name:	Corrigan Moving Systems	
Owner Type:		Private
Operator Name:	Vse Corporation	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20210513
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

VSE CORPORATION CORRIGAN MOVING LOCATION (Continued) **1026498412**

Hazardous Waste Summary:
Waste Code: P075
Waste Description: Nicotine, & Salts (Or) Pyridine, 3-(1-Methyl-2-Pyrrolidinyl)-,(S)-, & Salts

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CORRIGAN MOVING SYSTEMS
Legal Status: Private
Date Became Current: 20180416
Date Ended Current: Not reported
Owner/Operator Address: 1845 DALE RD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 716-880-1139
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: GGRIESBAUM@CORRIGAN.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: VSE CORPORATION
Legal Status: Other
Date Became Current: 20200220
Date Ended Current: Not reported
Owner/Operator Address: 1845 DALE RD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 703-329-4364
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: CLINSCOE@VSECORP.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: CORRIGAN MOVING SYSTEMS
Legal Status: Private
Date Became Current: 20180416
Date Ended Current: Not reported
Owner/Operator Address: 1845 DALE RD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 716-880-1139
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: GGRIESBAUM@CORRIGAN.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: VSE CORPORATION
Legal Status: Other
Date Became Current: 20200220
Date Ended Current: Not reported
Owner/Operator Address: 1845 DALE RD
Owner/Operator City,State,Zip: BUFFALO, NY 14225
Owner/Operator Telephone: 703-329-4364
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: CLINSCOE@VSECORP.COM

Historic Generators:
Receive Date: 20210513

VSE CORPORATION CORRIGAN MOVING LOCATION (Continued) **1026498412**

Handler Name: VSE CORPORATION CORRIGAN MOVING LOCATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20200917
Handler Name: VSE CORPORATION CORRIGAN MOVING LOCATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 493110
NAICS Description: General Warehousing And Storage

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:
Manifest Tracking Number: 021322925JJK
Last Updated Date: 20201116
Shipped Date: 20201027
Received Date: 20201027
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: NYR000247387
Generator Name: Vse Corporation
Generator Location Street Number: Not reported
Generator Location Street 1: 1845 DALE ROAD
Generator Location Street 2: Not reported
Generator Location City: BUFFALO
Generator Location State: NY
Generator Location Zip: 14225
Generator Mail Street Number: Not reported
Generator Mail Street 1: 8348 WALKER LANE
Generator Mail Street 2: Not reported

VSE CORPORATION CORRIGAN MOVING LOCATION (Continued) **1026498412**

Generator Mail City:	ALEXANDRIA
Generator Mail Zip:	22310
Generator Mail State:	VA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD048415665
Designated Facility Name:	Ross Incineration Services Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	36790 GILES RD
Designated Facility Mail Street 2:	ROSS INCINERATION SERVICES, IN
Designated Facility Mail City:	GRAFTON
Designated Facility Mail Zip:	44044
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	36790 GILES RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	GRAFTON
Designated Facility Location Zip:	44044
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	021322925JJK
Transporter Line Number:	1
Transporter EPA ID:	NYD986903904
Transporter Name:	The Environmental Services Group (Ny) Inc

Waste Line:

Manifest Tracking Number:	021322925JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1654
U.S. DOT Description:	Un1654, Waste Nicotine, 6.1, Pgii Rq:(P075)
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CW
Container Type Description:	Wooden boxes, cartons, cases
Waste Quantity:	515
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.2575
Acute Waste Quantity, in Tons:	0.2575
Non-Acute Waste Quantity, in Tons:	0
Waste Quantity, in Kilograms:	233.56023
Acute Waste Quantity, in Kilograms:	233.56023
Non-Acute Waste Quantity, in Kilorgrams:	0
Management Method Code:	H040
Management Method Description:	INCINERATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported

VSE CORPORATION CORRIGAN MOVING LOCATION (Continued) **1026498412**

Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	P075
Quantity Haz Kg:	233.56023
Quantity Haz Tons:	0.2575
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

51
North
1/8-1/4
0.131 mi.
692 ft.

MAIER-SCHULE INC **RCRA NonGen / NLR** **1000212132**
1745 WALDEN AVE **FINDS** **NYD002129922**
BUFFALO, NY 14225 **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
653 ft.

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Maier-Schule Inc
Handler Address:		Walden Ave
Handler City,State,Zip:		BUFFALO, NY 14225-4924
EPA ID:		NYD002129922
Contact Name:		Not reported
Contact Address:		WALDEN AVE
Contact City,State,Zip:		BUFFALO, NY 14225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		WALDEN AVE
Mailing City,State,Zip:		BUFFALO, NY 14225
Owner Name:	Ned Schule	
Owner Type:		Private
Operator Name:	Ned Schule	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

MAIER-SCHULE INC (Continued) **1000212132**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: NED SCHULE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NED SCHULE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

MAIER-SCHULE INC (Continued) **1000212132**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NED SCHULE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: MAIER-SCHULE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MAIER-SCHULE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MAIER-SCHULE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

MAIER-SCHULE INC (Continued) **1000212132**

Receive Date:	19860609
Handler Name: MAIER-SCHULE INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number: Not reported	
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type: Not reported	
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number: Not reported	
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No

MAIER-SCHULE INC (Continued) **1000212132**

Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19950215
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYRFR
Evaluation Responsible Sub-Organization:	R9
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19900329
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported

MAIER-SCHULE INC (Continued) **1000212132**

Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004339403

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000212132
Registry ID:	110004339403

DFR URL:

Name:	MAIER-SCHULE INC
Address:	1745 Walden Ave
City,State,Zip:	BUFFALO, NY 14225

NY MANIFEST:

EPA ID:	NYD002129922
Country:	USA
Name:	Maier Schule Bmc Incorporated
Address:	1745 WALDEN AVE
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225-4924
Zip 4:	Not reported
Location Address 1:	1745 WALDEN AVENUE
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Maier Schule Bmc Incorporated
Mailing Contact:	Maier Schule Bmc Incorporated
Mailing Address 1:	1745 WALDEN AVENUE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168963200

MAIER-SCHULE INC (Continued) **1000212132**

Manifest Data:

Document ID:	NYA8872918
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	NY
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880623
Trans1 Recv Date:	880623
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880623
Part A Recv Date:	880727
Part B Recv Date:	880701
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00320
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001

MAIER-SCHULE INC (Continued) **1000212132**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA8695754
Manifest Status:	C - Completed copy
Trans1 State ID:	NY88048GS
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880205
Trans1 Recv Date:	880205
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880205
Part A Recv Date:	880219
Part B Recv Date:	880210
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00320
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA8890424
Manifest Status:	C - Completed copy
Trans1 State ID:	NYMJ1780
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880516
Trans1 Recv Date:	880516
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880516
Part A Recv Date:	880520
Part B Recv Date:	880520
Generator EPA ID:	NYD002129922

MAIER-SCHULE INC (Continued) **1000212132**

Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00144
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA9577607
Manifest Status:	C - Completed copy
Trans1 State ID:	000000000
Year:	1989
Trans2 State ID:	000000000
Generator Ship Date:	890718
Trans1 Recv Date:	890718
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890718
Part A Recv Date:	890720
Part B Recv Date:	890724
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

MAIER-SCHULE INC (Continued) **1000212132**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00344
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA9556975
Manifest Status:	C - Completed copy
Trans1 State ID:	000000000
Year:	1989
Trans2 State ID:	000000000
Generator Ship Date:	890628
Trans1 Recv Date:	890628
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890628
Part A Recv Date:	890703
Part B Recv Date:	890703
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported

MAIER-SCHULE INC (Continued) **1000212132**

Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00027
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA9525611
Manifest Status:	C - Completed copy
Trans1 State ID:	000000000
Year:	1989
Trans2 State ID:	000000000
Generator Ship Date:	890622
Trans1 Recv Date:	890622
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890622
Part A Recv Date:	890630
Part B Recv Date:	890627
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

MAIER-SCHULE INC (Continued) **1000212132**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00344
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Document ID:	NYA9096761
Manifest Status:	C - Completed copy
Trans1 State ID:	NYEM4533
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	881103
Trans1 Recv Date:	881103
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	881103
Part A Recv Date:	881109
Part B Recv Date:	881109
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported

MAIER-SCHULE INC (Continued) **1000212132**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00251
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NYA9743365
Manifest Status:	C - Completed copy
Trans1 State ID:	NYEM4533
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890928
Trans1 Recv Date:	890928
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890928
Part A Recv Date:	891002
Part B Recv Date:	891003
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00123
Units:	Pounds
Number of Containers:	002

MAIER-SCHULE INC (Continued) **1000212132**

Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA6779575
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	NY88048GS
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	870902
Trans1 Recv Date:	870902
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870902
Part A Recv Date:	871019
Part B Recv Date:	870917
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD000805911
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00320
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA6806182
Manifest Status:	C - Completed copy
Trans1 State ID:	NY88048GS
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	870928
Trans1 Recv Date:	870928
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870928
Part A Recv Date:	871014
Part B Recv Date:	871001
Generator EPA ID:	NYD002129922

MAIER-SCHULE INC (Continued) **1000212132**

Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00320
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Waste Code 7:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA8612471
Manifest Status:	C - Completed copy
Trans1 State ID:	NY32101GV
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	871222
Trans1 Recv Date:	871222
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880106

MAIER-SCHULE INC (Continued) **1000212132**

Part A Recv Date:	880106
Part B Recv Date:	880114
Generator EPA ID:	NYD002129922
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD981099401
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00252
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
69 additional NY MANIFEST: record(s) in the EDR Site Report.

J52 **RYDER TRANSPORTATION SERVICES (LOC 0194)** **UST FINDER** **1028595502**
NNE **107 ANDERSON ROAD** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.152 mi.
804 ft. **Site 1 of 7 in cluster J**

Relative: UST FINDER:
Lower

Actual: Object ID:	315659
653 ft. Facility ID:	NY52078
Name:	RYDER TRANSPORTATION SERVICES (LOC 0194)
Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Address Match Type:	Not reported

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **1028595502**

Open USTs:	0
Closed USTs:	7
TOS USTs:	0
Population 1500ft:	0
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-78.7714989999999
Y Coord:	42.9067160000001
Latitude:	42.906716
Longitude:	-78.771499

UST FINDER:

Object ID:	1302571
Facility ID:	NY52078
Tank ID:	NY88003
Tank Status:	Closed
Installation Date:	1983/11/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1302572
Facility ID:	NY52078
Tank ID:	NY88004
Tank Status:	Closed
Installation Date:	1983/11/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1302573
Facility ID:	NY52078
Tank ID:	NY88077
Tank Status:	Closed
Installation Date:	1983/11/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	4000
Substances:	Not reported
Tank Wall Type:	Not reported

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **1028595502**

Object ID:	1302574
Facility ID:	NY52078
Tank ID:	NY90822
Tank Status:	Closed
Installation Date:	1983/11/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	8000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1302575
Facility ID:	NY52078
Tank ID:	NY92538
Tank Status:	Closed
Installation Date:	1983/11/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1302576
Facility ID:	NY52078
Tank ID:	NY92539
Tank Status:	Closed
Installation Date:	1983/11/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1302577
Facility ID:	NY52078
Tank ID:	NY92540
Tank Status:	Closed
Installation Date:	1983/11/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	12000
Substances:	Not reported
Tank Wall Type:	Not reported

J53 **RYDER TRANSPORTATION SERVICES (LOC 0194)** **NY UST** **U004081509**
NNE **107 ANDERSON ROAD** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.152 mi.
804 ft. **Site 2 of 7 in cluster J**

Relative: UST:
Lower

Actual:
653 ft.

Name:	RYDER TRANSPORTATION SERVICES (LOC 0194)
Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Id/Status:	9-022292 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	192110.17594
UTM Y:	4757359.96416

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U004081509**

Site Type: Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id: 52078
Affiliation Type: Facility Owner
Company Name: RYDER TRUCK RENTAL. INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 3600 NW 82ND ST
Address2: Not reported
City: MIAMI
State: FL
Zip Code: 33166
Country Code: 001
Phone: (305) 593-3619
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 52078
Affiliation Type: Mail Contact
Company Name: C/O TANKNOLOGY
Contact Type: Not reported
Contact Name: RYDER TRUCK RENTAL, INC
Address1: P.O. BOX 141188
Address2: 8900SHOAL CREEK BLVD
City: AUSTIN
State: TX
Zip Code: 78714-1188
Country Code: 001
Phone: (800) 964-0010
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 52078
Affiliation Type: Facility Operator
Company Name: RYDER TRANSPORTATION SERVICES (LOC 0194)
Contact Type: Not reported
Contact Name: NORM KLOC
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 894-7195
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 52078
Affiliation Type: Emergency Contact
Company Name: RYDER TRUCK RENTAL. INC.
Contact Type: Not reported

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U004081509**

Contact Name:	FRANK PORTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 878-5325
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	160608
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	8000
Install Date:	11/01/1983
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	14
Date Test:	09/01/1995
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode

Tank Number:	2
Tank ID:	160609
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	11/01/1983
Date Tank Closed:	09/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U004081509**

Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 14
Date Test: 09/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J00 - Dispenser - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number: A1
Tank ID: 160610
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 11/01/1983
Date Tank Closed: 09/01/1996
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 14
Date Test: 09/01/1995
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
H99 - Tank Leak Detection - Other
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
G00 - Tank Secondary Containment - None

Tank Number: D1
Tank ID: 160604
Tank Status: Closed - Removed
Material Name: Closed - Removed

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U004081509**

Capacity Gallons:	12000
Install Date:	11/01/1983
Date Tank Closed:	07/14/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	14
Date Test:	10/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground

Tank Number:	D2
Tank ID:	160605
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	12000
Install Date:	11/01/1983
Date Tank Closed:	07/14/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	14
Date Test:	10/01/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J01 - Dispenser - Pressurized Dispenser
I03 - Overfill - Automatic Shut-Off
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U004081509**

F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None

Tank Number: D3
Tank ID: 160606
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 12000
Install Date: 11/01/1983
Date Tank Closed: 07/14/2001
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 14
Date Test: 10/01/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J01 - Dispenser - Pressurized Dispenser
K01 - Spill Prevention - Catch Basin
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode

Tank Number: G1
Tank ID: 160607
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 12000
Install Date: 11/01/1983
Date Tank Closed: 07/14/2001
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 19
Date Test: 02/20/2001
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U004081509**

H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground

J54 **RYDER TRUCK RENTAL INC.** **UST FINDER RELEASE** **1029078244**
NNE **107 ANDERSON ROAD** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 0**
0.152 mi.
804 ft. **Site 3 of 7 in cluster J**

Relative: **Lower**

Actual: **653 ft.**

UST FINDER RELEASE:

Object ID:	244728
Facility ID:	NY77432
Lust ID:	NY8707899
Name:	RYDER TRUCK RENTAL INC.
Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1987/12/13 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	0
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.7714999999999
Y Coord:	42.9067200000001
Latitude:	42.90672
Longitude:	-78.7715

J55 **RYDER TRUCK RENTAL INC** **RCRA NonGen / NLR** **1000211496**
NNE **107 ANDERSON RD** **FINDS** **NYD074009812**
1/8-1/4 **CHEEKTOWAGA, NY 14225** **ECHO**
0.152 mi. **NY MANIFEST**
804 ft. **Site 4 of 7 in cluster J**

Relative: **Lower**
Actual: **653 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Ryder Truck Rental Inc
Handler Address:		Anderson Rd
Handler City,State,Zip:		CHEEKTOWAGA, NY 14225-4932
EPA ID:		NYD074009812
Contact Name:		Not reported
Contact Address:		ANDERSON RD
Contact City,State,Zip:		CHEEKTOWAGA, NY 14225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		ANDERSON RD
Mailing City,State,Zip:		CHEEKTOWAGA, NY 14225
Owner Name:	Ryder Truck Rental	
Owner Type:		Private
Operator Name:	Ryder Truck Rental	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

RYDER TRUCK RENTAL INC (Continued) **1000211496**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RYDER TRUCK RENTAL	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: RYDER TRUCK RENTAL	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: RYDER TRUCK RENTAL	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

RYDER TRUCK RENTAL INC (Continued) **1000211496**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: RYDER TRUCK RENTAL INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: RYDER TRUCK RENTAL INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: RYDER TRUCK RENTAL INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19871209
Handler Name: RYDER TRUCK RENTAL INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

RYDER TRUCK RENTAL INC (Continued) **1000211496**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004368078

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000211496
Registry ID: 110004368078

DFR URL:
Name: RYDER TRUCK RENTAL INC
Address: 107 Anderson Rd
City,State,Zip: CHEEKTOWAGA, NY 14225

NY MANIFEST:
EPA ID: NYD074009812
Country: USA
Name: Ryder Truck Rental
Address: 107 ANDERSON RD
Address 2: Not reported
City,State,Zip: CHEEKTOWAGA, NY 14225-4932
Zip 4: Not reported
Location Address 1: 107 ANDERSON ROAD
Location Address 2: Not reported
Location City,State,Zip: CHEEKTOWAGA, NY 14225
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Ryder Truck Rental
Mailing Contact: Norman Kloc
Mailing Address 1: 107 ANDERSON ROAD
Mailing Address 2: Not reported

RYDER TRUCK RENTAL INC (Continued) **1000211496**

Mailing City,State,Zip: CHEEKTOWAGA, NY 14225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7168947100

Manifest Data:
Document ID: NYA5613885
Manifest Status: K - Completed after the designated time
Trans1 State ID: NYLM6103
Year: 1987
Trans2 State ID: Not reported
Generator Ship Date: 871218
Trans1 Recv Date: 871218
Trans2 Recv Date: Not reported
TSD Site Recv Date: 871221
Part A Recv Date: 880129
Part B Recv Date: 871230
Generator EPA ID: NYD074009812
Trans1 EPA ID: NYD981876006
Trans2 EPA ID: Not reported
TSDF ID 1: NYD043815703
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Cadmium
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 01300
Units: Gallons (liquids only)
Number of Containers: 001
Container Type: Cargo tanks (tank trucks)
Handling Method: Treat
Specific Gravity: 100

J56 **RYDER TRUCK RENTAL INC.** **NY LTANKS** **S103558438**
NNE **107 ANDERSON ROAD** **NY Spills** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY**
0.152 mi.
804 ft. **Site 5 of 7 in cluster J**

Relative: **Lower**

Actual: **653 ft.**

LTANKS:

Name:	RYDER TRUCK RENTAL INC.
Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	8707899 / 1988-03-18
Facility ID:	8707899
Site ID:	84181
Spill Date:	1987-12-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-03-18
SWIS:	1530
Investigator:	MXFRANKS
Referred To:	Not reported
Reported to Dept:	1987-12-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-12-23
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-12-14
Spill Record Last Update:	1988-03-21
Spiller Name:	Not reported
Spiller Company:	RYDER TRUCK RENTAL INC.
Spiller Address:	107 ANDERSON ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	77432
Latitude:	42.9067162
Longitude:	-78.7715011
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF / / : MNP 12/14/87 TELECON, FORD NOT IN, TO RETURN CALL. / / : MF 12/14/87 FRANK FORD CALLED, TWO TANK FAILURES 12K GASOLINE, 2-6K DIESELS MANIFOLDED TOGETHER. TANK TO BE REPLACED ASAP, HE WILL CALL. / / : MF 12/24/87 TELECON BOB RICE, ELMWOOD TANK RETESTED TANKS, BELIEVED TO BE TIGHT, WILL SEND REPORT. / / : MF 12/31/87 TELECON FRANK FORD, TANKS RETESTED TIGHT, HE WILL SEND REPORTS. / / : MF 1/13/88 TELECON FRANK FORD, REPORTS JUST RECEIVED, WILL SEND THEM TO ME SHORTLY. 03/18/88: MF RETEST RESULTS RECEIVED.
Remarks:	Not reported

All TTF:

Facility ID:	8707899
Spill Number:	8707899
Spill Tank Test:	1532647
Site ID:	84181
Tank Number:	Not reported

RYDER TRUCK RENTAL INC. (Continued) **S103558438**

Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	84181
Operable Unit ID:	913528
Operable Unit:	01
Material ID:	463301
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	RYDER TRANSPORTATION SERV
Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9612615 / 1997-01-24
Facility ID:	9612615
Site ID:	84182
Spill Date:	1996-09-16
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	1530
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1996-12-23
CID:	369
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-23
Spill Record Last Update:	1997-01-27
Spiller Name:	CARRIE ANNE VINCH
Spiller Company:	RYDER TRANSPORTATION SERV
Spiller Address:	160 LAWRENCE-PENNINGTON
Spiller County:	001

RYDER TRUCK RENTAL INC. (Continued) **S103558438**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	77432
Latitude:	42.9067162
Longitude:	-78.7715011
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 01/24/97: SPILL REPORT GENERATED FROM TANK CLOSURE REPORT RECEIVED ON 12/23/97. APPROX 550 TONS CONTAMINATED SOIL GENERATED FROM TANK REMOVALS. ALL POST-EXCAVATION SAMPLE RESULTS MEET STARS MEMO #1 GUIDELINES. NO INSPECTION POSSIBLE AT THIS TIME. DISPOSAL DOCUMENTATION INCLUDED IN REPORT. NO FURTHER ACTION NECESARY, MJS CLOSE FILE. LETTER TO RP.
Remarks:	TANK CLOSURE REPORT INDICATES SOIL COMTAMINATION

All Materials:

Site ID:	84182
Operable Unit ID:	1040410
Operable Unit:	01
Material ID:	341264
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	84182
Operable Unit ID:	1040410
Operable Unit:	01
Material ID:	341265
Material Code:	0028A
Material Name:	ethylene glycol
Case No.:	00107211
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	84182
Operable Unit ID:	1040410
Operable Unit:	01
Material ID:	341263
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name: RYDER TRUCK RENTALS

RYDER TRUCK RENTAL INC. (Continued) **S103558438**

Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9810363 / 2001-08-16
Facility ID:	9810363
Site ID:	174499
Spill Date:	1998-11-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1530
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	1998-11-17
CID:	205
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2001-07-20
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-11-17
Spill Record Last Update:	2001-12-21
Spiller Name:	CARRIE ANN BUCK
Spiller Company:	RYDER TRUCK RENTALS
Spiller Address:	19 MINK RUN COURT
Spiller County:	001
Spiller Contact:	SHANE WOOLDRIDGE(CELL)
Spiller Phone:	(315) 415-5532
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	77432
Latitude:	42.9067162
Longitude:	-78.7715011
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 11/17/98: MJS TELECON WITH SHANE WOOLDRIDGE, INTERFACE SERVICES. UPGRADING TANKS AND INSTALLING VEEDER ROOT MONITORING SYSTEM. FREE PRODUCT FOUNG AROUND FILL PIPE. PRODUCT REMOVED WITH VACUUM TRUCK. MR WOOLDRIDGE STATED THAT HE REMOVED ENOUGH CONTAMINATED SOIL TO COMPLETE UPGRADE BUT BULK OF CONTAMINATION REMAINS. THEY PLAN TO CLOSE THIS FACILITY SOON AFTER COMPLETION OF FACILITY ELSEWHERE AND WILL REMOVE ALL CONTAMINATION AT THAT TIME. RYDER TRUCK (CORPORATE) CARRIE ANN BUCK 732-297-8733 DAVE WILLIAMS 732-297-8771 MJS TELECON TO DAVE WILLIAMS AND LEFT MESSAGE FOR HIM TO CALL. 11/18/98: MJS TELECON FROM CRAIG ZINC(GES). HE STATED THAT HE WAS CONTACTED BY CARRIE ANNE BUCK FROM RYDER AND THEY ARE AGAINST INSTALLING A SHALLOW WELL IN TANK PIT FOR MONITORING/PUMPING AND THEIR POSITION IS THAT THEY WILL DEAL WITH CONTAMINATION WHEN THEY REMOVE TANKS IN A YEAR OR SO. MJS STATED THAT SOME WORK WILL HAVE TO BE DONE IF THEY PLAN TO OPERATE SYSTEM. MJS TELECON TO MRS BUCK AND LEFT MESSAGE FOR HER TO CALL. MJS TELECON WITH MRS VINCH. MJS ADVISED HER THAT WORK WILL HAVE TO BE PERFORMED. 11/19/98: MJS SITE INSPECT. INTERFACE IS TRENCHING FOR ELECTRICAL CONDUIT. GRAVEL UNDER ASPHALT IS HEAVILY CONTAMINATED. MJS TELECON TO RYDER AND LEFT MESSAGE FOR CARRIE TO CALL. 11/20/98: MJS TELECON WITH SHANE, INTERFACE. HE RECEIVED PERMISSION FROM RYDER TO INSTALL SHALLOW WELL IN TANK PIT IN ORDER TO MONITOR/PUMP WATER

RYDER TRUCK RENTAL INC. (Continued) **S103558438**

FROM TANK PIT. MJS TELECON WITH CARRIE FROM RYDER AND ADVISED HER THAT THIS DEPARTMENT'S POSITION IS THAT CLEANUP OF SITE MUST BE ADRESSED AND WE WILL BE ASKING FOR REMEDIATION PLAN. CARRIE STATED THAT SHE WILL RESPOND IN WRITING. 02/10/99: RECEIVED LETTER REPORT FROM GES INC. SUMMARIZING EVENTS OF NOVEMBER 1998. CONTAMINATED SOIL STAGED ON SITE PENDING DISPOSAL. 02/12/99: MJS DRAFTED LETTER TO RP. REQUESTED COPY OF INVESTIGATION REPORT FROM 1996 IDENTIFYING CONTAMINATION IN SAME AREA AND STATED THAT THIS SHOULD HAVE BEEN REPORTED PURSUANT TO PBS REGULATIONS AND NAVIGATION LAW. REQUIRED REMEDIATION PROPOSAL AND FURTHER INVESTIGATION IF NECESSARY. 06/02/99: MJS TELECON FROM DOUG LIDDELL, GES INC. REVIEWED REQUIREMENTS FOR SITE REMEDIATION AND HE REQUESTED CONFERENCE CALL WITH MYSELF AND CARRIE ANNE BUCK OF RYDER. MJS AGREED. 06/04/99: MJS CONFERENCE CALL WITH MR LIDDELL AND CARRIE ANNE BUCK. THEY WILL FORWARD INVESTIGATION PROPOSAL FOR MY REVIEW TO DETERMINE EXTENT OF CONTAMINATION AND FORWARD REMEDIATION PROPOSAL BASED ON FINDINGS. 07/20/99: MJS SITE INSPECT. MET WITH JACK RYAN(OKAR) AND JUSTIN FROM GES. GES PERFORMING BORINGS ON SITE WITH AIR KNIFE TECHNIQUE, STARTED YESTERDAY. FINDING SIGNIFICANT AND WIDESPREAD CONTAMINATION ACROSS SITE. SOILS ARE TIGHTLY PACKED SAND AND CLAY. MJS TELECON WITH CRAIG ZINK(GES). 10/04/99: MJS TELECON FROM DOUG LIDDELL, GES. THEY HAVE COMPLETED SOIL DELINEATION AND WILL FORWARD REPORT WITH REMEDIAL PLAN. THEY HAVE BEEN UNSUCCESSFUL AT OBTAINING SITE ACCESS TO ADJACENT PROPERTY(REIMAN GEORGER). TANK FIELD IS IMMEDIATELY ADJACENT TO FENCELINE. REIMAN GEORGER 1849 HARLEM RD BUFFALO, NY 14212 CONTACT: ERIC VON DUNGEN 895-1156 895-1547(FAX) 12/12/2000: RJJ IS TAKING OVER THIS SPILL FROM MJS,WHO HAS LEFT DEC...TELECON DOUG LIDDELL,GES,AND ASKED HIM IF THERE IS ANY INFORMATION ON THIS SITE...HE SAID THAT HE WILL CALL CARRIE ANN BUCK,RYDER TRUCK REPRESENTATIVE,AND GET BACK TO ME. 12/15/2000: CHRIS ANDRZEJEWSKI,GZA,TELECON RJJ,SAID THAT GZA HAS BEEN RETAINED BY RYDER TO DO THE REMEDIATION AT THEIR LOCATION...THEY ARE NO LONGER INVOLVED WITH GES...I TOLD CHRIS THAT I HAVE NO RECORD OF THIS,OR ANY OTHER RECORD,AND HE SAID THAT HE WILL SEND ME ALL THE REPORTS AND LETTERS THAT HAVE BEEN GENERATED BY BOTH GZA AND GES...HE WILL ALSO SEND ME THEIR REMEDIAL PLAN. 12/21/2000: RECEIVED THE PHASE 11 ENVIRONMENTAL SITE ASSESSMENT FROM GZA,AND 3 LETTERS WHICH WERE SENT TO MJS...AFTER I REVIEW ALL OF THIS,I WILL CALL CHRIS(GZA),AND DISCUSS THIS WITH HIM. 12/22/2000: RJJ REVIEWED REPORT AND AGREED WITH GZA'S REMEDIAL ACTION WORK PLAN...FAXED APPROVAL LETTER TO GZA. 3/26/2001: RJJ TELECON CRIS ANDRZEJEWSKI,GZA,HE SAID THAT RYDER IS STILL IN THE PROCESS OF A PROPERTY TRANSACTION,WHEN THE TRANSACTION GETS CLOSER,THEY WILL REMEDIATE THE PROPERTY...CRIS THINKS THIS WILL BE IN A COUPLE OF MONTHS. 6/1/2001: MIKE SMITH,TOLTEST INC.(#412-856-8700),TELECOM RJJ,SAID THAT THEY WILL BE REMEDIATING THE RYDER SITE SOMETIME IN JULY...GZA IS NO LONGER DOING IT...MIKE WILL CALL ME AND KEEP ME INFORMED ON THEIR ACTIONS...HE ALSO SAID THAT PEGGY CARPENTER FROM RYDER IS THE NEW CONTACT PERSON. 7/14/2001; RJJ AT SITE AT 1100...MEET WITH CARRIE ANN BUCK,RYDER,AND CRAIG BUSHEY,TOLTEST...THEY HAVE BEGUN TO REMOVE 4-12000 UST'S ON THE PROPERTY...THEY WILL ALSO REMOVE ALL THE CONTAMINATED SOIL AND TRANSPORT IT TO THEIR BIO-REMEDIATION PLANT,IN OHIO...ON ANOTHER PART OF THE PROPERTY,THEY WILL EXCAVATE THE CONTAMINATED SOIL AND ALSO BIO-REMEDIATE IT...CRAIG WILL TAKE CONFIRMATORY SAMPLES WITH A 1-DAY TURN-AROUND-TIME,TO EXPEDITE THE SITE,SINCE RYDER IS IN A PROPERTY TRANSACTION WITH MARRIOTT HOTELS...ALL THE WORK IS EXPECTED TO BE DONE IN 10 DAYS...I WILL MONITOR THEIR PROGRESS. 7/20/2001: SOIL

RYDER TRUCK RENTAL INC. (Continued) **S103558438**

EXCAVATION IS CONTINUING AND THEY ARE SAMPLING EVERY 30'...WORK SHOULD BE DONE EARLY NEXT WEEK. 8/16/2001: RECEIVED THE FINAL COMPLETED UST,OIL/WATER SEPARATOR,AND IMPACTED SOIL REMOVAL REPORT FROM TOLTEST,INC...THEY REMOVED 4-12000 UST'S,1 OIL/WATER SEPARATOR,20,000 GAL OF GROUNDWATER PUMPED FROM THE UST AREA AND PLACED INTO A FRAC TANK,THEN DISCHARGED TO THE CHEEKTOWAGA SANITARY SEWER,WITH THEIR PERMISSION,AND DISPOSED 9,416.26 TONS OF IMPACTED SOIL AT THEIR BIO-TREATMENT PLANT IN SEVILLE,OHIO,AND SAMPLED THE ENTIRE AREA...THE ANALYTICAL RESULTS ONLY HAVE A FEW COMPOUNDS SLIGHTLY HIGHER THAN OUR GUILDANCE VALUES...ALL THE SOIL DISPOSAL RECEIPTS AND THE REQUIRED PAPERWORK IS IN THE REPORT...I WILL DRAFT AND SEND AN 'INACTIVE' LETTER TO MS. CARRIE ANNE VINCH-BUCK,FRON RYDER TRANSPORTATION SERVICES...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT.

Remarks: CALLER DOING TANK UPGRADE, FOUND CONTAMINATED SOIL.

All Materials:

Site ID:	174499
Operable Unit ID:	1071273
Operable Unit:	01
Material ID:	314235
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	RYDER TRANSPORTATION
Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0175279 / 2002-05-02
Facility ID:	0175279
Facility Type:	ER
DER Facility ID:	77432
Site ID:	69808
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	1530
Spill Date:	2001-08-23
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2001-10-12
Recommended Penalty:	False
UST Trust:	False

RYDER TRUCK RENTAL INC. (Continued) **S103558438**

Remediation Phase:	0
Date Entered In Computer:	2001-08-23
Spill Record Last Update:	2002-05-02
Spiller Name:	GARY THARALDSON
Spiller Company:	THARALDSON DEVELOPMENT,CO
Spiller Address:	1201 PAGE DRIVE
Spiller Company:	001
Contact Name:	MIKE SMITH
Latitude:	42.9067162
Longitude:	-78.7715011
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 8/23/2001: RJJ AT SITE AT 1100...MEET WITH BUEL RUMMENS,SITE COORDINATOR,THARALDSON DEVELOPMENT,CO.,HE SAID THAT THEY ENCOUNTERED CONTAMINATED SOIL WHILE EXCAVATING FOR THE NEW HOTEL...RYDER WILL REMEDIATE THE SITE AS PER SPILL # 9810367,WHICH IS THE SAME SITE BUT THIS CONTAMINATION IS IN A DIFFERENT LOCATION...THEY FOUND CONAMINATION UNDER THE OLD RYDER BUILDINGS AND ALSO IN THE BACK OF THE PROPERTY,NEAR THE THRUWAY...BUEL WILL KEEP ME INFORMED. 10/15/2001: RECEIVED THE ANALYTICAL RESULTS FROM THE SLUDGE AND WATER THEY ENCOUNTERED FROM C.E.M.,INC...ALL THE RESULTS ARE BELOW OUR GUIDANCE VALUES...PETE CHRENZIA,CEM,WILL KEEP ME INFORMED AND ALSO SEND ME THE DISPOSAL RECEIPTS FROM THE SOIL...THEY STILL HAVE CONTAMINATED SOIL NEAR THE THRUWAY TO REMEDIATE. 10/24/2001: MIKE SMITH,TOLTEST,TELECON RJJ SAID THAT HE WILL SEND ME THEIR REPORT ON THE SITE SOON...TOLTEST DID SOME REMEDIATION UNDER THE OLD BUILDINGS FOR RYDER,THEN RYDER TOLD THEM TO STOP WORK,SINCE C.E.M.,INC. WAS HIRED BY THE NEW PROPERTY OWNERS TO REMEDIATE.(THARALDSON DEVELOPMENT CO. OF FARGO,ND.) 10/24/2001: PETE CHRENZIA,C.E.M. TELECON RJJ SAID THAT THEY WILL TAKE 2 SOIL SAMPLES NEAR THE PROPERTY LINE BY BUFFALO SPRING AND ANALYZE THEM FOR 8270/8021 STARS,THIS WILL INDICATE IF ANY CONTAMINATION FROM RYDER PROPERTY MIGRATED TO THEIR'S...PETE WILL KEEP ME INFORMED. 11/1/2001: DRAFTED AND SENT A 'RP' LETTER TO THARALDSON DEVELOPMENT CO.,THE NEW OWNERS OF THE PROPERTY... 11/8/2001: RECEIVED THE ANALYTICAL RESULTS FROM THE 2-SOIL SAMPLES TAKEN NEAR THE PROPERTY-LINE OF BUFFALO SPRING/RYDER...SOME OF THE SVOC'S ARE SLIGHTLY HIGHER THAN OUR TAGA GUIDANCE LEVELS,SO I DISCUSSED THE RESULTS WITH DAN KING/SAC...DAN SAID THAT SINCE I SAW THE EXCAVTION,WHICH HAD OVER A FOOT OF BACKFILLED ASH,THIS COULD ACCOUNT FOR THE ELAVATED LEVELS OF PETROLEUM HYDROCARBONS...WE WILL NOT REQUIRE THARALDSON TO DO ANY OFF-SITE INVESTIGATION ON BUFFALO SPRING'S PROPERTY. 1/23/2002: RECEIVED THE UST,HYDRAULIC LIFT,AND IMPACTED SOIL REMOVAL REPORT FROM TOLTEST,INC.,ON THE FORMER RYDER PROPERTY...IT INCLUDES THE DISPOSAL RECEIPTS FOR 2,961 TONS OF CONTAMINATED SOIL TAKEN TO SEVILLE,OHIO...IT ALSO INCLUDES THE ANALYTICAL RESULTS FROM THE

RYDER TRUCK RENTAL INC. (Continued) **S103558438**

EXCAVATIONS...SOME OF THE RESULTS
ARE ABOVE OUR SOIL GUIDANCE LEVELS,BUT THEY ARE SIMILAR ELEVATED PETROLEUM HYDROCARBON LEVELS DUE
TO THE ENTIRE SITE BEING BACKFILLED WITH ASH... THIS IS WERE TOLTEST STOPPED WORK AND CEM STARTED
FOR THE NEW OWNER'S, THARALDSON DEVELOPMENT...CEM WILL SEND ME THEIR COMPLETE REPORT WHEN THEY
FINISH. 5/2/2002: RECEIVED THE SOIL SAMPLING AND SOIL DISPOSAL REPORT FROM CEM...THEY DISPOSED
5,300 TONS OF CONTAMINATED SOIL AND DISPOSED IT AT THE TONAWANDA LANDFILL...ALL THE DISPOSAL
RECEIPTS ARE INCLUDED IN THIS REPORT...SOME OF THEIR ANALYTICAL RESULTS ARE SLIGHTLY HIGHER THAN
OUR TAGA 4046 LEVELS,HOWEVER,SINCE THE ENTIRE AREA WAS BACKFILLED WITH ASH,THIS ACCOUNTED FOR THE
SLIGHTLY ELEVATED PETROLEUM HYDRCARBONS...BETWEEN TOLTEST AND CEM,8,261 TONS OF CONTAMINATED SOIL
WAS DISPOSED OF AT A LANDFILL...THE SITE WILL BE MADE 'INACTIVE',NO FURTHER WORK WILL BE NEEDED BY
THE PROPERTY OWNER...DRAFTED AND SENT AN 'INACTIVE' LETTER TO 'RP'...SPILL CLOSED OUT.

Remarks: CALLER SAID THAT THEY ENCOUNTERED CONTAMINATED SOIL WHILE EXCAVATING...RYDER WILL REMEDIATE THE AREA.

All Materials:

Site ID:	69808
Operable Unit ID:	853035
Operable Unit:	01
Material ID:	524601
Material Code:	0013
Material Name:	lube oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	69808
Operable Unit ID:	853035
Operable Unit:	01
Material ID:	524602
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J57 **RYDER TRANSPORTATION SERVICES (LOC 0194)** **NY AST** **U003316417**
NNE **107 ANDERSON ROAD** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.152 mi.
804 ft. **Site 6 of 7 in cluster J**

Relative:
Lower

Actual:
653 ft.

AST:

Name:	RYDER TRANSPORTATION SERVICES (LOC 0194)
Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY 14225
Region:	STATE
DEC Region:	9
Site Status:	Unregulated/Closed
Facility Id:	9-022292
Program Type:	PBS
UTM X:	192110.17594
UTM Y:	4757359.96416
Expiration Date:	N/A
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	52078
Affiliation Type:	Facility Owner
Company Name:	RYDER TRUCK RENTAL. INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	3600 NW 82ND ST
Address2:	Not reported
City:	MIAMI
State:	FL
Zip Code:	33166
Country Code:	001
Phone:	(305) 593-3619
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52078
Affiliation Type:	Mail Contact
Company Name:	C/O TANKNOLOGY
Contact Type:	Not reported
Contact Name:	RYDER TRUCK RENTAL, INC
Address1:	P.O. BOX 141188
Address2:	8900SHOAL CREEK BLVD
City:	AUSTIN
State:	TX
Zip Code:	78714-1188
Country Code:	001
Phone:	(800) 964-0010
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52078
Affiliation Type:	Facility Operator
Company Name:	RYDER TRANSPORTATION SERVICES (LOC 0194)
Contact Type:	Not reported
Contact Name:	NORM KLOC

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U003316417**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 894-7195
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	52078
Affiliation Type:	Emergency Contact
Company Name:	RYDER TRUCK RENTAL. INC.
Contact Type:	Not reported
Contact Name:	FRANK PORTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 878-5325
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	59
Tank Id:	171467
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

	H99 - Tank Leak Detection - Other
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F00 - Pipe External Protection - None
	G04 - Tank Secondary Containment - Double-Walled (Underground)
	J01 - Dispenser - Pressurized Dispenser
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/1995
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U003316417**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil
Tank Number:	69
Tank Id:	172412
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
J01 - Dispenser - Pressurized Dispenser

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1996
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/2001
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil
Tank Number:	79
Tank Id:	172413
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C01 - Pipe Location - Aboveground
H99 - Tank Leak Detection - Other
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

RYDER TRANSPORTATION SERVICES (LOC 0194) (Continued) **U003316417**

Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1996
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/2001
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)

Tank Number:	9
Tank Id:	171468
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C01 - Pipe Location - Aboveground
H99 - Tank Leak Detection - Other
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1995
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/2001
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

J58 **RYDER TRUCK RENTALS** **UST FINDER RELEASE** **1029078245**
NNE **107 ANDERSON ROAD** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 0**
0.152 mi.
804 ft. **Site 7 of 7 in cluster J**

Relative: **Lower**

Actual: **653 ft.**

UST FINDER RELEASE:

Object ID:	244729
Facility ID:	NY77432
Lust ID:	NY9810363
Name:	RYDER TRUCK RENTALS

RYDER TRUCK RENTALS (Continued) **1029078245**

Address:	107 ANDERSON ROAD
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1998/11/17 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	0
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.7714999999999
Y Coord:	42.9067200000001
Latitude:	42.90672
Longitude:	-78.7715

K59 **PAUL BATT BUICK INC** **UST FINDER** **1028597216**
NNW **1717 WALDEN AVE** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.157 mi.
831 ft. **Site 1 of 2 in cluster K**

Relative: UST FINDER:
Lower

Actual: Object ID:	315703
655 ft. Facility ID:	NY53621
Name:	PAUL BATT BUICK INC
Address:	1717 WALDEN AVE
City,State,Zip:	CHEEKTOWAGA, NY 14225
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	1
TOS USTs:	0
Population 1500ft:	124
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported

PAUL BATT BUICK INC (Continued) **1028597216**

Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Facility Status:	Closed UST(s)
Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-78.7742029999999
Y Coord:	42.9080050000001
Latitude:	42.908005
Longitude:	-78.774203

UST FINDER:

Object ID:	1309704
Facility ID:	NY53621
Tank ID:	NY95062
Tank Status:	Closed
Installation Date:	Not reported
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported

K60 **ASPEN DENTAL** **RCRA-VSQG** **1000273715**
NNW **1717 WALDEN AVE** **NY UST** **NYD067532242**
1/8-1/4 **CHEEKTOWAGA, NY 14225** **NY AST**
0.157 mi. **FINDS**
831 ft. **Site 2 of 2 in cluster K** **ECHO**
E MANIFEST
Relative: **NY MANIFEST**
Lower

Actual: **655 ft.**

RCRA Listings:

Date Form Received by Agency:	20100916
Handler Name:	Aspen Dental
Handler Address:	Walden Ave
Handler City,State,Zip:	CHEEKTOWAGA, NY 14225
EPA ID:	NYD067532242
Contact Name:	CORRINE D HINGRE
Contact Address:	SANDERS CREEK PKWY
Contact City,State,Zip:	EAST SYRACUSE, NY 13057
Contact Telephone:	315-454-6000 x1458
Contact Fax:	315-454-6001
Contact Email:	CHINGRE@ASPENDENT.COM
Contact Title:	COMPLIANCE SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R9
Mailing Address:	SANDERS CREEK PKWY

ASPEN DENTAL (Continued) **1000273715**

Mailing City,State,Zip:		EAST SYRACUSE, NY 13057
Owner Name:	Carmina Wood Morric Pc	
Owner Type:		Private
Operator Name:	Aspen Dental	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D009
Waste Description:	Mercury

ASPEN DENTAL (Continued) **1000273715**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: PAUL V BATT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAUL V BATT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CARMINA WOOD MORRIC PC	
Legal Status:	Private
Date Became Current:	20101108
Date Ended Current:	Not reported
Owner/Operator Address:	487 MAIN ST
Owner/Operator City,State,Zip:	BUFFALO, NY 14203
Owner/Operator Telephone:	716-842-3165
Owner/Operator Telephone Ext:	103
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: ASPEN DENTAL	
Legal Status:	Private
Date Became Current:	20101108
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAUL V BATT	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212

ASPEN DENTAL (Continued) **1000273715**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: PAUL BATT BUICK INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PAUL BATT BUICK INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870814
Handler Name: PAUL BATT BUICK INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20100916
Handler Name: ASPEN DENTAL
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes

ASPEN DENTAL (Continued) **1000273715**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 62121
NAICS Description: Offices Of Dentists

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

UST:
Name: PAUL BATT BUICK INC
Address: 1717 WALDEN AVE
City,State,Zip: CHEEKTOWAGA, NY 14225
Id/Status: 9-385107 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 9
Expiration Date: N/A
UTM X: 191895.83858
UTM Y: 4757513.03747
Site Type: Other Wholesale/Retail Sales

Affiliation Records:
Site Id: 53621
Affiliation Type: Mail Contact
Company Name: PAUL V BATT PRES
Contact Type: Not reported
Contact Name: Not reported
Address1: 1717 WALDEN AVE
Address2: Not reported
City: CHEEKTOWAGA
State: NY
Zip Code: 14225
Country Code: 001
Phone: (716) 891-5595
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2005-08-25

Site Id: 53621
Affiliation Type: Facility Operator
Company Name: PAUL BATT BUICK INC
Contact Type: Not reported
Contact Name: PAUL BATT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001

ASPEN DENTAL (Continued) **1000273715**

Phone:	(716) 891-5595
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-08-25

Site Id:	53621
Affiliation Type:	Emergency Contact
Company Name:	PAUL V BATT PRES
Contact Type:	Not reported
Contact Name:	ROBERT MOZER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 835-6718
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-08-25

Site Id:	53621
Affiliation Type:	Facility Owner
Company Name:	PAUL V BATT PRES
Contact Type:	PRESIDENT
Contact Name:	PAUL V. BATT
Address1:	1717 WALDEN AVE
Address2:	Not reported
City:	CHEEKTOWAGA
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 891-5595
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-09-21

Tank Info:

Tank Number:	1
Tank ID:	163875
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	05/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	03
Date Test:	09/01/1997

ASPEN DENTAL (Continued) **1000273715**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G07 - Tank Secondary Containment - Excavation Liner
H04 - Tank Leak Detection - Groundwater Well
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)

AST:

Name: PAUL BATT BUICK INC
Address: 1717 WALDEN AVE
City,State,Zip: CHEEKTOWAGA, NY 14225
Region: STATE
DEC Region: 9
Site Status: Unregulated/Closed
Facility Id: 9-385107
Program Type: PBS
UTM X: 191895.83858
UTM Y: 4757513.03747
Expiration Date: N/A
Site Type: Other Wholesale/Retail Sales

Affiliation Records:

Site Id: 53621
Affiliation Type: Mail Contact
Company Name: PAUL V BATT PRES
Contact Type: Not reported
Contact Name: Not reported
Address1: 1717 WALDEN AVE
Address2: Not reported
City: CHEEKTOWAGA
State: NY
Zip Code: 14225
Country Code: 001
Phone: (716) 891-5595
EMail: Not reported
Fax Number: Not reported
Modified By: AESKALSK
Date Last Modified: 2005-08-25

Site Id: 53621
Affiliation Type: Facility Operator
Company Name: PAUL BATT BUICK INC
Contact Type: Not reported
Contact Name: PAUL BATT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported

ASPEN DENTAL (Continued) **1000273715**

Country Code:	001
Phone:	(716) 891-5595
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-08-25

Site Id:	53621
Affiliation Type:	Emergency Contact
Company Name:	PAUL V BATT PRES
Contact Type:	Not reported
Contact Name:	ROBERT MOZER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 835-6718
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-08-25

Site Id:	53621
Affiliation Type:	Facility Owner
Company Name:	PAUL V BATT PRES
Contact Type:	PRESIDENT
Contact Name:	PAUL V. BATT
Address1:	1717 WALDEN AVE
Address2:	Not reported
City:	CHEEKTOWAGA
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 891-5595
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2005-09-21

Tank Info:

Tank Number:	2
Tank Id:	172640
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
F04 - Pipe External Protection - Fiberglass

ASPEN DENTAL (Continued) **1000273715**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/01/1997
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	3
Tank Id:	208096
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/01/2006
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

FINDS:
Registry ID: 110004365339

ASPEN DENTAL (Continued) **1000273715**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000273715
Registry ID:	110004365339

DFR URL:

Name:	ASPEN DENTAL
Address:	1717 Walden Ave
City,State,Zip:	CHEEKTOWAGA, NY 14225

E MANIFEST:

Manifest Tracking Number:	017399511FLE
Last Updated Date:	20220608
Shipped Date:	20220427
Received Date:	20220510
Manifest Status:	Corrected
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	Not reported
Generator Name:	Chipotle #1479-Cheektowaga
Generator Location Street Number:	Not reported
Generator Location Street 1:	1717 WALDEN AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1717 WALDEN AVENUE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980991566
Designated Facility Name:	Eq Detroit, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1923 FREDERICK STREET
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48211
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1923 FREDERICK STREET
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT

ASPEN DENTAL (Continued) **1000273715**

Designated Facility Location Zip: 48211
Designated Facility Location State: MI
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 017399511FLE
Transporter Line Number: 1
Transporter EPA ID: MAD084814136
Transporter Name: Eq Northeast, Inc.

Waste Line:
Manifest Tracking Number: 017399511FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3109
U.S. DOT Description: Rq, Un3109, Waste Organic Peroxide Type F, Liquid, 5.2, Pgii, (D001, D002), Erg#145
Non-Hazardous Waste Description: Not reported
Number of Containers: 2
Container Type Code: CF
Container Type Description: Fiber or plastic boxes, cartons, cases
Waste Quantity: 4
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.002
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.002
Waste Quantity, in Kilograms: 1.8140601
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 1.8140601
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y
Federal Waste Codes: D001, D002
Quantity Haz Kg: 1.8140601
Quantity Haz Tons: 0.002
Quantity Non Haz Kg: 0
Quantity Non Haz Tons: 0
State Waste Codes: Not reported

ASPEN DENTAL (Continued) **1000273715**

NY MANIFEST:

EPA ID:	NYD067532242
Country:	USA
Name:	Paul Batt Buick Incorporated
Address:	1717 WALDEN AVE
Address 2:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14225
Zip 4:	Not reported
Location Address 1:	1717 WALDEN AVENUE
Location Address 2:	Not reported
Location City,State,Zip:	CHEEKTOWAGA, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Paul Batt Buick Incorporated
Mailing Contact:	Paul Batt Buick Incorporated
Mailing Address 1:	1717 WALDEN AVENUE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	CHEEKTOWAGA, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168915595

Manifest Data:

Document ID:	NYC3131897
Manifest Status:	Not reported
Trans1 State ID:	HJ9192
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/1994
Trans1 Recv Date:	09/26/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/27/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported

ASPEN DENTAL (Continued) **1000273715**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00006
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYC3123224
Manifest Status:	Not reported
Trans1 State ID:	NYNA1635
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/1994
Trans1 Recv Date:	07/08/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00008
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00016

ASPEN DENTAL (Continued) **1000273715**

Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 12:	Cadmium
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC3309928
Manifest Status:	Not reported
Trans1 State ID:	NYNA1635
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	10/27/1994
Trans1 Recv Date:	10/27/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/28/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00008
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

ASPEN DENTAL (Continued) **1000273715**

Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00016
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC0368234
Manifest Status:	Not reported
Trans1 State ID:	000000000
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/1990
Trans1 Recv Date:	07/10/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/10/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00090
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC0690221
Manifest Status:	Not reported
Trans1 State ID:	NYHJ9192
Year:	1991

ASPEN DENTAL (Continued) **1000273715**

Trans2 State ID:	Not reported
Generator Ship Date:	01/24/1991
Trans1 Recv Date:	01/24/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/24/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00045
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYC6283787
Manifest Status:	Not reported
Trans1 State ID:	LC4100
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/2000
Trans1 Recv Date:	10/12/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/12/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242

ASPEN DENTAL (Continued) **1000273715**

Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Tetrachloroethylene
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	NYC4407502
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1996
Trans2 State ID:	Not reported
Generator Ship Date:	12/31/1996
Trans1 Recv Date:	12/31/1996
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/31/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported

ASPEN DENTAL (Continued) **1000273715**

Waste Code 1:	Tetrachloroethylene
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00029
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Tetrachloroethylene
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC3015898
Manifest Status:	Not reported
Trans1 State ID:	NYHJ9192
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	05/10/1994
Trans1 Recv Date:	05/10/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/10/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

ASPEN DENTAL (Continued) **1000273715**

Waste Code 6:	Not reported
Quantity:	00007
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00016
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC1889381
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/1992
Trans1 Recv Date:	10/14/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Cadmium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs

ASPEN DENTAL (Continued) **1000273715**

Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYC6575703
Manifest Status:	Not reported
Trans1 State ID:	6403
Year:	2001
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/2001
Trans1 Recv Date:	06/28/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Tetrachloroethylene
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00005
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Document ID:	NYC2413967
Manifest Status:	Not reported
Trans1 State ID:	NYIT5466
Year:	1995
Trans2 State ID:	Not reported
Generator Ship Date:	04/17/1995
Trans1 Recv Date:	04/17/1995
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/18/1995
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD067532242
Trans1 EPA ID:	ILD984908202

ASPEN DENTAL (Continued) **1000273715**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00016
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
158 additional NY MANIFEST: record(s) in the EDR Site Report.

L61 **SCOTT AVIATION DIV.OF ATO INC** **RCRA NonGen / NLR** **1000421262**
NNW **1735 WALDEN AVE** **FINDS** **NYD000811067**
1/8-1/4 **CHEEKTOWAGA, NY 14225** **ECHO**
0.172 mi.
909 ft. **Site 1 of 7 in cluster L**

Relative: **Lower**
Actual: **653 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Scott Aviation Div.Of Ato Inc
Handler Address:	Walden Ave
Handler City,State,Zip:	CHEEKTOWAGA, NY 14225-4924
EPA ID:	NYD000811067
Contact Name:	Not reported
Contact Address:	ERIE ST
Contact City,State,Zip:	LANCASTER, NY 14086
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

SCOTT AVIATION DIV.OF ATO INC (Continued) **1000421262**

State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		ERIE ST
Mailing City,State,Zip:		LANCASTER, NY 14086
Owner Name:	Elvio J Cassiol	
Owner Type:		Private
Operator Name:	Elvio J Cassiol	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20220105
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

SCOTT AVIATION DIV.OF ATO INC (Continued) **1000421262**

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: ELVIO J CASSIOL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ELVIO J CASSIOL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ELVIO J CASSIOL
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: SCOTT AVIATION DIV.OF ATO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SCOTT AVIATION DIV.OF ATO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

SCOTT AVIATION DIV.OF ATO INC (Continued) **1000421262**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SCOTT AVIATION DIV.OF ATO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19800818
Handler Name: SCOTT AVIATION DIV.OF ATO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004331580

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

SCOTT AVIATION DIV.OF ATO INC (Continued) **1000421262**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000421262
Registry ID: 110004331580

DFR URL:
Name: SCOTT AVIATION DIV.OF ATO INC
Address: 1735 Walden Ave
City,State,Zip: CHEEKTOWAGA, NY 14225

M62 **BUFFALO SPRING** **UST FINDER RELEASE** **1029064920**
NNE **1765 WALDEN AVENUE** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 0**
0.184 mi.
973 ft. **Site 1 of 3 in cluster M**

Relative:
Lower

Actual:
653 ft.

UST FINDER RELEASE:
Object ID: 244727
Facility ID: NY203665
Lust ID: NY9705918
Name: BUFFALO SPRING
Address: 1765 WALDEN AVENUE
City,State,Zip: CHEEKTOWAGA, NY 0
Address Match Type: Not reported
Reported Date: 1997/08/15 15:59:59+00
Status: No Further Action
Substance: Not reported
Population within 1500ft: 78
Domestic Wells within 1500ft: 0
Land Use: Developed, Medium Intensity
Within SPA: No
SPA PWS Facility ID: Not reported
SPA Water Type: Not reported
SPA Facility Type: Not reported
SPA HUC12: Not reported
Within WHPA: Yes
WHPA PWS Facility ID: NY1430018_14182
WHPA Water Type: GW - Ground water
WHPA Facility Type: WL - Well
WHPA HUC12: 041201040601
Within 100yr Floodplain: No
Tribe: Not reported
EPA Region: 2
NFA Letter 1: Not reported
NFA Letter 2: Not reported
NFA Letter 3: Not reported
NFA Letter 4: Not reported
Closed With Residual Contaminate: Not reported
Coordinate Source: State
X Coord: -78.7715499999999
Y Coord: 42.90878
Latitude: 42.90878
Longitude: -78.77155

M63 **BUFFALO SPRING** **NY LTANKS** **S102176007**
NNE **1765 WALDEN AVENUE** **NY Spills** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY**
0.184 mi.
973 ft. **Site 2 of 3 in cluster M**

Relative: **Lower**

Actual: **653 ft.**

LTANKS:

Name:	BUFFALO SPRING
Address:	1765 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9705918 / 1997-10-23
Facility ID:	9705918
Site ID:	248082
Spill Date:	1997-08-15
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	1530
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	1997-08-15
CID:	266
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-08-15
Spill Record Last Update:	1997-11-12
Spiller Name:	DEAN BRODIE
Spiller Company:	BUFFALO SPRING
Spiller Address:	1765 WALDEN AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	203665
Latitude:	42.9087764
Longitude:	-78.7715534
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 09/08/97: MJS TELECON FROM DOUG REID AT NFCS. SAMPLE RESULTS ARE RECEIVED AND HE WILL FAX COPY. 09/09/97: MJS REVIEWED SAMPLE RESULTS. TWO SAMPLE RESULTS FROM CENTER OF OLD TANK PIT SLIGHTLY EXCEED STARS #1 GUIDELINES. MJS TELECON WITH MR REID AND EXPLAINED THAT INACTIVE STATUS IS APPROPRIATE. HE STATED THAT CLIENT WANTS TO PURSUE A CLOSED STATUS. HE AGREED TO RESAMPLE USING TCLP METHODOLOGY. COMPLETE REPORT DUE IN 2 WEEKS. 10/23/97: RECEIVED REPORT FROM NFCS. SOIL TCLP RESULTS AND GROUNDWATER RESULTS INDICATE NO EXCEEDENCES OF GUIDANCE VALUES. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. 11/05/97: MJS TELECON FROM DOUG REID. HE REQUESTS CLOSURE LETTER FOR RP. 11/06/97: MJS DRAFTED CLOSURE LETTER.
Remarks:	SOIL CONTAMINATION FOUND DURING SUB-SURFACE INVESTIGATION. WRIITEN REPORT TO FOLLOW.

All Materials:

Site ID:	248082

BUFFALO SPRING (Continued) **S102176007**

Operable Unit ID:	1049172
Operable Unit:	01
Material ID:	331527
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	BUFFALO SPRING
Address:	1765 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0101076 / 2001-08-14
Facility ID:	0101076
Facility Type:	ER
DER Facility ID:	203665
Site ID:	309654
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1530
Spill Date:	2001-04-27
Investigator:	RJJONAK
Referred To:	Not reported
Reported to Dept:	2001-04-27
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-04-27
Spill Record Last Update:	2001-10-23
Spiller Name:	DEAN BRODIE
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ANDY KUCSERIK
Latitude:	42.9087764
Longitude:	-78.7715534
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 4/30/2001: RJJ TELECON ANDY KUCSERIK,BARRON & ASSOCIATES,HE SAID THAT THEY FOUND SOME CONTAMINATED SOIL,WHILE DOING A PHASE 11 FOR THE NEW POTENTIAL BUYER...ANDY WILL KEEP IN CONTACT WITH ME WITH ANY INFORMATION...DRAFTED AND SENT A 'RESPONSIBLE PARTY LETTER' TO CURRENT PROPERTY OWNERS BUFFALO SPRING. 5/4/2001: RECEIVED THE

BUFFALO SPRING (Continued) **S102176007**

SIGNED 'RIGHT-OF-ENTRY' FORM FROM DEAN BRODIE,PRESIDENT OF BUFFALO SPRING. 5/21/2001: RECEIVED A
LETTER FROM DEAN BRODIE EXPLAINING THAT THEY/AND OR BENDERSON WILL REMEDIATE THE PROBLEM,AFTER ALL
THE TESTING AND REPORT COMES BACK. 6/26/2001: RECEIVED THE PHASE 1 REPORT THAT BARRON & ASSOCIATES
DID THIS YEAR AND THE LIMITED PHASE 11 REPORT THAT LCS DID IN 1997 ON THIS PROPERTY,AND A LETTER
FROM CRAIG SLATER,ATTORNEY FOR BENDERSON DEVELOPMENT...MR. SLATER IS REQUESTING THAT WE MAKE THIS
SITE 'INACTIVE',SINCE THE ANALYTICAL (8270) INDICATE THAT ONLY A FEW COMPOUNDS ARE SLIGHTLY OVER
OUR GUILDANCE LEVELS,AND WE MADE THE SITE 'INACTIVE' IN 1997...I DISCUSSED THIS WITH SAL AND PETER
BUECHI,PETER SAID THAT MORE INFOMATION IS NEEDED FOR US TO MAKE THIS SITE 'INACTIVE',SUCH
AS,SUBSURFACE LOGS,8021 TESTING,AND MORE DETAILS ON THE WORK THAT WAS DONE...I WILL CALL ANDY
KUCSERIK,BARRON,AND EXPLAIN THIS TO HIM...DRAFTED AND SENT A LETTER TO CRAIG SLATER ALSO EXPLAINING
THIS. 8/14/2001: RECEIVED THE FINAL REPORT FROM BARRON & ASSOCIATES WHICH INCLUDES THE 8021
ANALYSES,SOIL BORING LOGS,AND THE EXACT LOCATION OF THE BORINGS...ALL THE 8021 RESULTS ARE BELOW
OUR GUILDANCE LEVELS,SINCE THE 8270 RESULTS ARE ONLY SLIGHTLY HIGHER THAN OUR GUILDANCE VALUES,WE
CAN MAKE THIS SITE 'INACTIVE'...DRAFTED AND SENT AN 'INACTIVE' LETTER TO CRAIG SLATER,DEAN BRODIE
FROM BUFFALO SPRING,AND ANDY KUCSERIK FROM BARRON & ASSOCIATES...NO FURTHER ACTION NEEDED...SPILL
CLOSED OUT.

Remarks: SOIL CONTAMINATION DISCOVERED AT ABOVE LOCATION. AREA TO BE EXCAVATED AND RETESTED.

All Materials:

Site ID:	309654
Operable Unit ID:	837976
Operable Unit:	01
Material ID:	536782
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BUFFALO SPRING AND EQUIP.
Address:	1765 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	8710179 / 1988-03-04
Facility ID:	8710179
Facility Type:	ER
DER Facility ID:	203665
Site ID:	248081
DEC Region:	9

BUFFALO SPRING (Continued) **S102176007**

Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	1530
Spill Date:	1988-03-04
Investigator:	MJHINTON
Referred To:	Not reported
Reported to Dept:	1988-03-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	1988-03-04
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-07
Spill Record Last Update:	1988-03-09
Spiller Name:	Not reported
Spiller Company:	BUFFALO SPRING AND EQUIP.
Spiller Address:	1765 WALDEN AVENUE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9087764
Longitude:	-78.7715534
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH 03/07/88: FIRE DEPT CALLED TO SCENE NO ACTION TAKEN FIRE BURNED ALL SPILLED PRODUCT AND EXTINGUISHED ITSELF.
Remarks:	MECHANICS SPILLED GASOLINE INTO TRENCH DRAIN, SPARK FROM NEARBY WELDING TORCH IGNITED SPILLED PRODUCT

All Materials:

Site ID:	248081
Operable Unit ID:	915118
Operable Unit:	01
Material ID:	461958
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

N64 **OFFICE/WAREHOUSE DEVELOPMENT** **NY MANIFEST S123253410**
WNW **1655 WALDEN AVENUE** **NY SPDES N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.195 mi.
1032 ft. **Site 1 of 2 in cluster N**

Relative: NY MANIFEST:
Higher

EPA ID:	NYR000246322
Country:	USA
Name:	Delta Sonic Walden Ave

Actual:
659 ft.

OFFICE/WAREHOUSE DEVELOPMENT (Continued) **S123253410**

Address:	1655 WALDEN AVE
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14225
Zip 4:	Not reported
Location Address 1:	1655 WALDEN AVE
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Delta Sonic Walden Ave
Mailing Contact:	Delta Sonic Walden Ave
Mailing Address 1:	570 DELAWARE AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14202
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7165412332

SPDES:

Name:	Office/Warehouse Development
Address:	1655 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 14225
Permit Number:	NYR10F625
State-Region:	9
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Lake Erie
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	784638 / 425422
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported

OFFICE/WAREHOUSE DEVELOPMENT (Continued) **S123253410**

Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported
Facility Type:	Construction Permit - 2003_present

N65 **DELTA SONIC WALDEN AVE** **RCRA-SQG 1026173295**
WNW **1655 WALDEN AVE** **E MANIFEST NYR000246322**
1/8-1/4 **BUFFALO, NY 14225**
0.195 mi.
1032 ft. **Site 2 of 2 in cluster N**

Relative: **Higher**
Actual: **659 ft.**

RCRA Listings:

Date Form Received by Agency:	20200603
Handler Name:	Delta Sonic Walden Ave
Handler Address:	Walden Ave
Handler City,State,Zip:	BUFFALO, NY 14225
EPA ID:	NYR000246322
Contact Name:	TIMOTHY RIEDY
Contact Address:	DELAWARE AVE
Contact City,State,Zip:	BUFFALO, NY 14202
Contact Telephone:	716-541-2332
Contact Fax:	888-265-9835
Contact Email:	TIMRIEDY@DELTASONICCARWASH.COM
Contact Title:	DIRECTOR OF SAFETY
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R9
Mailing Address:	DELAWARE AVE
Mailing City,State,Zip:	BUFFALO, NY 14202
Owner Name:	Delta Sonic Carwash Systems Inc
Owner Type:	Private
Operator Name:	Delta Sonic Carwash Systems Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

DELTA SONIC WALDEN AVE (Continued) **1026173295**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200604
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent

DELTA SONIC WALDEN AVE (Continued) **1026173295**

Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: DELTA SONIC CARWASH SYSTEMS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 570 DELAWARE AVE
Owner/Operator City,State,Zip: BUFFALO, NY 14202
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DELTA SONIC CARWASH SYSTEMS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 570 DELAWARE AVE
Owner/Operator City,State,Zip: BUFFALO, NY 14202
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20200603
Handler Name: DELTA SONIC WALDEN AVE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

DELTA SONIC WALDEN AVE (Continued) **1026173295**

List of NAICS Codes and Descriptions:
NAICS Code: 81119
NAICS Description: Other Automotive Repair And Maintenance

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E MANIFEST:

Manifest Tracking Number:	012372043FLE
Last Updated Date:	20200723
Shipped Date:	20200617
Received Date:	20200624
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000246322
Generator Name:	Delta Sonic Walden Ave
Generator Location Street Number:	1655
Generator Location Street 1:	1655 WALDEN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	570
Generator Mail Street 1:	DELAWARE AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14202
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012372070FLE
Last Updated Date:	20200728
Shipped Date:	20200626

DELTA SONIC WALDEN AVE (Continued) **1026173295**

Received Date:	20200630
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYR000246322
Generator Name:	Delta Sonic Walden Ave
Generator Location Street Number:	1655
Generator Location Street 1:	1655 WALDEN AVE
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	570
Generator Mail Street 1:	DELAWARE AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	BUFFALO
Generator Mail Zip:	14202
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	OHD980897656
Designated Facility Name:	Chemical Solvents Inc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	1010 DENISON AVE
Designated Facility Mail City:	CLEVELAND
Designated Facility Mail Zip:	44109
Designated Facility Mail State:	OH
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	1010 DENISON AVE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	CLEVELAND
Designated Facility Location Zip:	44109
Designated Facility Location State:	OH
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	012372070FLE
Transporter Line Number:	1
Transporter EPA ID:	NYR000176958
Transporter Name:	Sun Environmental Corp
Manifest Tracking Number:	012372070FLE
Transporter Line Number:	2
Transporter EPA ID:	NYD986903904
Transporter Name:	Environmental Service Group Ny Inc The

Waste Line:

Manifest Tracking Number:	012372070FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1263
U.S. DOT Description:	Un1263, Waste Paint Related Material, 3, Ii, Rq
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1

DELTA SONIC WALDEN AVE (Continued) **1026173295**

Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	50
Quantity Unit of Measure Code:	G
Quantity Unit of Measure Description:	Gallons
Waste Quantity, in Tons:	0.20850709
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.20850709
Waste Quantity, in Kilograms:	189.1222
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	189.1222
Management Method Code:	H061
Management Method Description:	FUEL BLENDING
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	Y
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D035, F003, F005
Quantity Haz Kg:	189.1222
Quantity Haz Tons:	0.20850709
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

L66 **PETSMART** **E MANIFEST** **1032238555**
NNW **1734 WALDEN AVE** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.214 mi.
1132 ft. **Site 2 of 7 in cluster L**

Relative: E MANIFEST:
Lower

Manifest Tracking Number:	200006881CLE
Last Updated Date:	20211213
Shipped Date:	20211116
Received Date:	20211124
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Petsmart
Generator Location Street Number:	Not reported
Generator Location Street 1:	1734 WALDEN AVE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1734 WALDEN AVE

Actual:
654 ft.

PETSMART (Continued) **1032238555**

Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980615298
Designated Facility Name:	Petro Chem Processing Group Of Nortru Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	421 Lycaste St.
Designated Facility Mail City:	Detroit
Designated Facility Mail Zip:	48214
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	421 Lycaste St.
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Detroit
Designated Facility Location Zip:	48214
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	015565444FLE
Last Updated Date:	20201221
Shipped Date:	20201209
Received Date:	20201215
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Petsmart
Generator Location Street Number:	Not reported
Generator Location Street 1:	1734 WALDEN AVE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1734 WALDEN AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980615298
Designated Facility Name:	Petro Chem Processing Group Of Nortru Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	421 Lycaste St.
Designated Facility Mail City:	Detroit
Designated Facility Mail Zip:	48214
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	421 Lycaste St.
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Detroit

PETSMART (Continued) **1032238555**

Designated Facility Location Zip:	48214
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	200962350CLE
Last Updated Date:	20241113
Shipped Date:	20241014
Received Date:	20241108
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Petsmart
Generator Location Street Number:	Not reported
Generator Location Street 1:	1734 WALDEN AVE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1734 WALDEN AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980615298
Designated Facility Name:	Petro-Chem Processing Group (Esol)
Designated Facility Mail Street Number:	515
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	421 LYCASTE
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48214
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	421
Designated Facility Location Street 1:	LYCASTE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48214
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	013682511FLE
Last Updated Date:	20200130
Shipped Date:	20200110
Received Date:	20200115
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Petsmart
Generator Location Street Number:	Not reported
Generator Location Street 1:	1734 WALDEN AVE

PETSMART (Continued) **1032238555**

Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1734 WALDEN AVE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980615298
Designated Facility Name:	Petro Chem Processing Group Of Nortru Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	421 Lycaste St.
Designated Facility Mail City:	Detroit
Designated Facility Mail Zip:	48214
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	421 Lycaste St.
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Detroit
Designated Facility Location Zip:	48214
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	013682511FLE
Transporter Line Number:	1
Transporter EPA ID:	MNS000110924
Transporter Name:	Stericycle Specialty Waste Solutions Inc

Waste Line:

Manifest Tracking Number:	013682511FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1950
U.S. DOT Description:	Un1950, Waste Aerosols, Flammable 2.1, Erg#126
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	4
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.002
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.002
Waste Quantity, in Kilograms:	1.8140601
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	1.8140601
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE

PETSMART (Continued) **1032238555**

Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001
Quantity Haz Kg:	1.8140601
Quantity Haz Tons:	0.002
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B
Manifest Tracking Number:	013682511FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3264
U.S. DOT Description:	Un3264, Waste Corrosive Liquid, Acidic, Inorganic, N.O.S. 8, Pg Ii, Erg#154
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	5
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0025
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0025
Waste Quantity, in Kilograms:	2.267575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	2.267575
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D002

PETSMART (Continued) **1032238555**

Quantity Haz Kg:	2.267575
Quantity Haz Tons:	0.0025
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-T
Manifest Tracking Number:	013682511FLE
Waste Line Number:	3
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not reported
U.S. DOT Description:	Not reported
Non-Hazardous Waste Description:	Non Rcra Hazardous Waste, Liquid (Surfactant, Oil),
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	5
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0025
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0025
Waste Quantity, in Kilograms:	2.267575
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	2.267575
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	2.267575
Quantity Non Haz Tons:	0.0025
State Waste Codes:	NY-B, NY-L

L67 **DELAVAN INDUSTRIES INC** **NY UST** **U003316306**
NNW **1728 WALDEN AVE** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.215 mi.
1137 ft. **Site 3 of 7 in cluster L**

Relative: UST:
Lower

Name:	DELAVAN INDUSTRIES INC
Address:	1728 WALDEN AVE
City,State,Zip:	CHEEKTOWAGA, NY 14225
Id/Status:	9-009571 / Unregulated/Closed

Actual:
654 ft.

DELAVAN INDUSTRIES INC (Continued) **U003316306**

Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	N/A
UTM X:	192139.95818
UTM Y:	4757568.43486
Site Type:	Unknown

Affiliation Records:

Site Id:	51949
Affiliation Type:	Facility Owner
Company Name:	DELAVAN INDUSTRIES INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1728 WALDEN AVE
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 894-3120
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	51949
Affiliation Type:	Mail Contact
Company Name:	DELAVAN INDUSTRIES INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	1728 WALDEN AVE
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 894-3120
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	51949
Affiliation Type:	Facility Operator
Company Name:	DELAVAN INDUSTRIES INC
Contact Type:	Not reported
Contact Name:	DELAVAN INDUSTRIES INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 894-3120
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

DELAVAN INDUSTRIES INC (Continued) **U003316306**

Date Last Modified: 2004-03-04

Site Id: 51949
Affiliation Type: Emergency Contact
Company Name: DELAVAN INDUSTRIES INC
Contact Type: Not reported
Contact Name: PETER TERZIAN/PLANT MANAGER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 894-3120
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 169184
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 8000
Install Date: 05/01/1976
Date Tank Closed: 08/01/1987
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 169185
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91

DELAVAN INDUSTRIES INC (Continued) **U003316306**

Capacity Gallons:	2000
Install Date:	05/01/1976
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

L68 **DELAVAN INDUSTRIES INC** **UST FINDER** **1028595350**
NNW **1728 WALDEN AVE** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.215 mi.
1137 ft. **Site 4 of 7 in cluster L**

Relative: **Lower**

Actual: **654 ft.**

UST FINDER:

Object ID:	315717
Facility ID:	NY51949
Name:	DELAVAN INDUSTRIES INC
Address:	1728 WALDEN AVE
City,State,Zip:	CHEEKTOWAGA, NY 14225
Address Match Type:	Not reported
Open USTs:	0
Closed USTs:	2
TOS USTs:	0
Population 1500ft:	46
Private Wells 1500ft:	0
Within 100yr Floodplain:	No
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Facility Status:	Closed UST(s)

DELAVAN INDUSTRIES INC (Continued) **1028595350**

Date of Last Inspection:	Not reported
EPA Region:	2
Tribe:	Not reported
Coordinate Source:	State
X Coord:	-78.7712509999999
Y Coord:	42.9086510000001
Latitude:	42.908651
Longitude:	-78.771251

UST FINDER:

Object ID:	1301929
Facility ID:	NY51949
Tank ID:	NY120387
Tank Status:	Closed
Installation Date:	1976/05/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	8000
Substances:	Not reported
Tank Wall Type:	Not reported

Object ID:	1301930
Facility ID:	NY51949
Tank ID:	NY87578
Tank Status:	Closed
Installation Date:	1976/05/01 16:00:00+00
Removal Date:	Not reported
Tank Capacity:	2000
Substances:	Not reported
Tank Wall Type:	Not reported

L69 **DELAVAN INDUSTRIES** **NY SWF/LF** **1000160238**
NNW **1728 WALDEN AVE** **NY LTANKS** **NYD980559496**
1/8-1/4 **CHEEKTOWAGA, NY 14225** **RCRA NonGen / NLR**
0.215 mi. **FINDS**
1137 ft. **Site 5 of 7 in cluster L** **ECHO**
NY MANIFEST

Relative:
Lower

Actual:
654 ft.

SWF/LF:

Name:	CTS CRUSHING & RECYCLING
Address:	1728 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 0
Flag:	INACTIVE
Region Code:	9
Phone Number:	Not reported
Owner Name:	Custom Topsoil Inc
Owner Type:	Private
Owner Address:	320 Crabapple Lane
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY
Owner Email:	Not reported
Owner Phone:	7166684444
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported

DELAVAN INDUSTRIES (Continued) **1000160238**

Activity Desc:	C&D processing - registration
Activity Number:	[15W11]
Active:	No
East Coordinate:	1
North Coordinate:	1
Accuracy Code:	Not reported
Regulatory Status:	None
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

LTANKS:

Name:	DELEVAN INDUSTRIES
Address:	1728 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	8701865 / 1987-08-07
Facility ID:	8701865
Site ID:	131793
Spill Date:	1987-06-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1987-08-07
SWIS:	1530
Investigator:	ROSS
Referred To:	Not reported
Reported to Dept:	1987-06-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-08-07
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-06-05
Spill Record Last Update:	1987-08-10
Spiller Name:	Not reported
Spiller Company:	DELEVAN INDUSTRIES
Spiller Address:	1728 WALDEN AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	113552
Latitude:	42.9085045
Longitude:	-78.7729699
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : PRODUCT REMOVED FROM TANK 6/4/87. / / : LQR SITE INSP. 08/05/87,SOIL DID NOT SHEEN DISPOSED OF AS FILL. / / : LQR SITE INSP. 08/07/87,SOIL DID NOT SHEEN DISPOSED OF AS FILL. / / : PRODUCT REMOVED FROM TANK 6/4/87;LQR TELCON 06/12/87,LINES TO BE TESTED SOON.

DELAVAN INDUSTRIES (Continued) **1000160238**

/ / : LQR SITE INSP. 07/22/87,TANK REMOVED,SOIL TO BE TURNED OVER AND RESULTS TO FOLLOW. / / : LQR SITE INSP. 06/25/87,TANK REMOVED,SOIL TO BE STAGED.

Remarks: TANK LEAK RATE 0.103 GPH, OTHER TANKS TO BE TESTED, INACTIVE HAZARDOUS WASTE SITE

All TTF:

Facility ID:	8701865
Spill Number:	8701865
Spill Tank Test:	1530907
Site ID:	131793
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	131793
Operable Unit ID:	906273
Operable Unit:	01
Material ID:	471757
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	DELEVAN INDUSTRIES
Address:	1728 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	8701908 / 1987-08-07
Facility ID:	8701908
Site ID:	131794
Spill Date:	1987-06-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1987-08-07
SWIS:	1530
Investigator:	ROSS
Referred To:	Not reported
Reported to Dept:	1987-06-05
CID:	Not reported
Water Affected:	Not reported

DELAVAN INDUSTRIES (Continued) **1000160238**

Spill Notifier:	Tank Tester
Last Inspection:	1987-08-07
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-06-10
Spill Record Last Update:	1987-08-10
Spiller Name:	Not reported
Spiller Company:	DELEVAN INDUSTRIES
Spiller Address:	1728 WALDEN AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	113552
Latitude:	42.9085045
Longitude:	-78.7729699
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : LQR TELCON SPILLER 06/12/87,TANK EMPTIED,LINES TO BE TESTED. / / : LQR TELCON SPILLER 06/22/87,TANK EMPTIED,LINES FAILEDTEST. / / : LQR SITE INSP. 06/25/87,TANK REMOVED SOIL TO BE STAGED. / / : LQR SITE INSP. 07/22/87,TANK REMOVED SOIL TO BE TURNED OVER AND RESULT TO BE SENT. / / : LQR SITE INSP. 08/07/87,SOIL DID NOT SHEEN,SOIL RE USED AT FACILITY FOR FILL.
Remarks:	8000 GALLON DIESEL TANK WOULD HOLD TEST

All TTF:

Facility ID:	8701908
Spill Number:	8701908
Spill Tank Test:	1530916
Site ID:	131794
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	131794
Operable Unit ID:	908541
Operable Unit:	01
Material ID:	471799
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

DELAVAN INDUSTRIES (Continued) **1000160238**

Units: G
Recovered: .00
Oxygenate: Not reported

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Delavan Industries Inc
Handler Address:		Walden Ave
Handler City,State,Zip:		CHEEKTOWAGA, NY 14225
EPA ID:		NYD980559496
Contact Name:		Not reported
Contact Address:		WALDEN AVE
Contact City,State,Zip:		CHEEKTOWAGA, NY 14225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		WALDEN AVE
Mailing City,State,Zip:		CHEEKTOWAGA, NY 14225
Owner Name:	Ryder Systems Inc	
Owner Type:		Private
Operator Name:	Ryder Systems Inc	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No

DELAVAN INDUSTRIES (Continued) **1000160238**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: RYDER SYSTEMS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: RYDER SYSTEMS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

DELAVAN INDUSTRIES (Continued) **1000160238**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RYDER SYSTEMS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19960715
Handler Name: DELAVAN INDUSTRIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: DELAVAN INDUSTRIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: DELAVAN INDUSTRIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860512
Handler Name: DELAVAN INDUSTRIES INC
Federal Waste Generator Description: Small Quantity Generator

DELAVAN INDUSTRIES (Continued) **1000160238**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported

DELAVAN INDUSTRIES (Continued) **1000160238**

Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20021004
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYRFR
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19930303
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYRFR
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported

DELAVAN INDUSTRIES (Continued) **1000160238**

Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004387636

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The New York Department of Environmental Conservation Facility Information System (FIS) database houses all information about facilities that are regulated or of environmental interest to the state of New York.
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000160238
Registry ID: 110004387636

DFR URL:
Name: DELAVAN INDUSTRIES
Address: 1728 Walden Ave
City,State,Zip: CHEEKTOWAGA, NY 14225

NY MANIFEST:
EPA ID: NYD980559496
Country: USA
Name: Commercial Carriers
Address: 1728 WALDEN AVE
Address 2: Not reported
City,State,Zip: CHEEKTOWAGA, NY 14225
Zip 4: Not reported
Location Address 1: 1728 WALDEN AVENUE
Location Address 2: Not reported
Location City,State,Zip: BUFFALO, NY 14225
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Commercial Carriers
Mailing Contact: Kenneth Hamm
Mailing Address 1: 1728 WALDEN AVENUE
Mailing Address 2: Not reported
Mailing City,State,Zip: BUFFALO, NY 14225
Mailing Zip 4: Not reported
Mailing Country: USA

DELAVAN INDUSTRIES (Continued) **1000160238**

Mailing Phone: 7168943120

Manifest Data:
Document ID: TXA0070296
Manifest Status: Not reported
Trans1 State ID: Not reported
Year: 1996
Trans2 State ID: Not reported
Generator Ship Date: 05/17/1996
Trans1 Recv Date: 05/17/1996
Trans2 Recv Date: 05/24/1996
TSD Site Recv Date: 06/03/1996
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980559496
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: ARD981908551
TSDF ID 1: TXD077603371
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Lead
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00534
Units: Pounds
Number of Containers: 001
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: TXA0070320
Manifest Status: Not reported
Trans1 State ID: 65124
Year: 1996
Trans2 State ID: 41853H188
Generator Ship Date: 08/29/1996
Trans1 Recv Date: 08/29/1996
Trans2 Recv Date: 09/06/1996
TSD Site Recv Date: 09/13/1996
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980559496
Trans1 EPA ID: ILD984908202

DELAVAN INDUSTRIES (Continued) **1000160238**

Trans2 EPA ID:	ARD981908551
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Chromium
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00800
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	TXA0070385
Manifest Status:	Not reported
Trans1 State ID:	88888
Year:	1996
Trans2 State ID:	PAAH0346
Generator Ship Date:	11/07/1996
Trans1 Recv Date:	11/07/1996
Trans2 Recv Date:	11/12/1996
TSD Site Recv Date:	11/20/1996
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead

DELAVAN INDUSTRIES (Continued) **1000160238**

Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00185
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	TXA0070393
Manifest Status:	Not reported
Trans1 State ID:	88888
Year:	1996
Trans2 State ID:	8888
Generator Ship Date:	12/12/1996
Trans1 Recv Date:	12/12/1996
Trans2 Recv Date:	12/18/1996
TSD Site Recv Date:	01/13/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	NYD980769947
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00186
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	TXA0070402
Manifest Status:	Not reported
Trans1 State ID:	88888
Year:	1996

DELAVAN INDUSTRIES (Continued) **1000160238**

Trans2 State ID:	40355
Generator Ship Date:	12/31/1996
Trans1 Recv Date:	12/31/1996
Trans2 Recv Date:	01/10/1997
TSD Site Recv Date:	01/13/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	MOD095038998
TSDF ID 1:	TXD077603371
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Lead
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00185
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYA5673483
Manifest Status:	C - Completed copy
Trans1 State ID:	46934ANY
Year:	1989
Trans2 State ID:	Not reported
Generator Ship Date:	890515
Trans1 Recv Date:	890515
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	890515
Part A Recv Date:	890519
Part B Recv Date:	890523
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	NYD099328395
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported

DELAVAN INDUSTRIES (Continued) **1000160238**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NJA2583910
Manifest Status:	Not reported
Trans1 State ID:	08690
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	03/07/1997
Trans1 Recv Date:	03/07/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/14/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene,

DELAVAN INDUSTRIES (Continued) **1000160238**

2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00900
Units: Pounds
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: NJA2583973
Manifest Status: Not reported
Trans1 State ID: 08690
Year: 1997
Trans2 State ID: Not reported
Generator Ship Date: 03/27/1997
Trans1 Recv Date: 03/27/1997
Trans2 Recv Date: Not reported
TSD Site Recv Date: 04/04/1997
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980559496
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002182897
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported

DELAVAN INDUSTRIES (Continued) **1000160238**

Quantity:	00450
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NJA2583999
Manifest Status:	Not reported
Trans1 State ID:	08690
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	04/11/1997
Trans1 Recv Date:	04/11/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00350
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NJA2585202
Manifest Status:	Not reported
Trans1 State ID:	08690

DELAVAN INDUSTRIES (Continued) **1000160238**

Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	05/13/1997
Trans1 Recv Date:	05/13/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/16/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00300
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NJA2585204
Manifest Status:	Not reported
Trans1 State ID:	08690
Year:	1997
Trans2 State ID:	Not reported
Generator Ship Date:	06/06/1997
Trans1 Recv Date:	06/06/1997
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/13/1997
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980559496
Trans1 EPA ID:	ILD984908202

DELAVAN INDUSTRIES (Continued) **1000160238**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00896
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
49 additional NY MANIFEST: record(s) in the EDR Site Report.

L70 **DELEVAN INDUSTRIES** **UST FINDER RELEASE** **1029057598**
NNW **1728 WALDEN AVENUE** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 0**
0.215 mi.
1137 ft. **Site 6 of 7 in cluster L**

Relative: UST FINDER RELEASE:
Lower

Actual:
654 ft.

Object ID:	244723
Facility ID:	NY113552
Lust ID:	NY8701865
Name:	DELEVAN INDUSTRIES
Address:	1728 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1987/06/04 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	119
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity

DELEVAN INDUSTRIES (Continued) **1029057598**

Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.77297
Y Coord:	42.9085000000001
Latitude:	42.9084999999999
Longitude:	-78.77297

Object ID:	244724
Facility ID:	NY113552
Lust ID:	NY8701908
Name:	DELEVAN INDUSTRIES
Address:	1728 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1987/06/05 16:00:00+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	119
Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.77297

DELEVAN INDUSTRIES (Continued) **1029057598**

Y Coord: 42.9085000000001
Latitude: 42.9084999999999
Longitude: -78.77297

L71 **OFFICE DEPOT** **E MANIFEST** **1032219370**
NNW **1730 WALDEN AVENUE** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14225**
0.216 mi.
1139 ft. **Site 7 of 7 in cluster L**

Relative: **Lower**

Actual: **654 ft.**

E MANIFEST:

Manifest Tracking Number:	201039088CLE
Last Updated Date:	20250211
Shipped Date:	20250115
Received Date:	20250203
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Office Depot
Generator Location Street Number:	Not reported
Generator Location Street 1:	1730 WALDEN AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1730 WALDEN AVENUE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980615298
Designated Facility Name:	Petro-Chem Processing Group (Esol)
Designated Facility Mail Street Number:	515
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	421 LYCASTE
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48214
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	421
Designated Facility Location Street 1:	LYCASTE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48214
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	200779453CLE
Last Updated Date:	20240723
Shipped Date:	20240422
Received Date:	20240506
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service

OFFICE DEPOT (Continued) **1032219370**

Generator EPA ID:	CESQG
Generator Name:	Office Depot
Generator Location Street Number:	Not reported
Generator Location Street 1:	1730 WALDEN AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1730 WALDEN AVENUE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980615298
Designated Facility Name:	Petro-Chem Processing Group (Esol)
Designated Facility Mail Street Number:	515
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	421 LYCASTE
Designated Facility Mail City:	DETROIT
Designated Facility Mail Zip:	48214
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	421
Designated Facility Location Street 1:	LYCASTE
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	DETROIT
Designated Facility Location Zip:	48214
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	013682202FLE
Last Updated Date:	20200214
Shipped Date:	20191001
Received Date:	20191108
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Office Depot
Generator Location Street Number:	Not reported
Generator Location Street 1:	1730 WALDEN AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1730 WALDEN AVENUE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	PAD085690592
Designated Facility Name:	Republic Env Sys Inc

OFFICE DEPOT (Continued) **1032219370**

Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2869 Sandstone Drive
Designated Facility Mail City:	Hatfield
Designated Facility Mail Zip:	19440
Designated Facility Mail State:	PA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2869 Sandstone Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Hatfield
Designated Facility Location Zip:	19440
Designated Facility Location State:	PA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	012112305FLE
Last Updated Date:	20190412
Shipped Date:	20190109
Received Date:	20190114
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Office Depot
Generator Location Street Number:	Not reported
Generator Location Street 1:	1730 WALDEN AVENUE
Generator Location Street 2:	Not reported
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	1730 WALDEN AVENUE
Generator Mail Street 2:	Not reported
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	MID980615298
Designated Facility Name:	Petro Chem Processing Group Of Nortru Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	421 Lycaste St.
Designated Facility Mail City:	Detroit
Designated Facility Mail Zip:	48214
Designated Facility Mail State:	MI
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	421 Lycaste St.
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Detroit
Designated Facility Location Zip:	48214
Designated Facility Location State:	MI
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

OFFICE DEPOT (Continued) **1032219370**

Transporter:

Manifest Tracking Number:	012112305FLE
Transporter Line Number:	1
Transporter EPA ID:	MNS000110924
Transporter Name:	Stericycle Specialty Waste Solutions Inc

Waste Line:

Manifest Tracking Number:	012112305FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN1993
U.S. DOT Description:	Un1993, Waste Flammable Liquids, N.O.S. (Acetone, Methyl Ethyl Ketone), 3, Pg Ii, Erg#128
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	4
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.002
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.002
Waste Quantity, in Kilograms:	1.8140601
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	1.8140601
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D035
Quantity Haz Kg:	1.8140601
Quantity Haz Tons:	0.002
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B

M72 **PERA-BATT COLLISION** **RCRA NonGen / NLR** **1000143475**
NNE **1775 WALDEN AVE** **FINDS** **NYD981557556**
1/8-1/4 **CHEEKTOWAGA, NY 14225** **ECHO**
0.217 mi. **NY MANIFEST**
1145 ft. **Site 3 of 3 in cluster M**

Relative: **Higher**
Actual: **656 ft.**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Pera-Batt Collision
Handler Address:		Walden Ave
Handler City,State,Zip:		CHEEKTOWAGA, NY 14225
EPA ID:		NYD981557556
Contact Name:		Not reported
Contact Address:		WALDEN AVE
Contact City,State,Zip:		CHEEKTOWAGA, NY 14225
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		WALDEN AVE
Mailing City,State,Zip:		CHEEKTOWAGA, NY 14225
Owner Name:	Joseph Pera	
Owner Type:		Private
Operator Name:	Joseph Pera	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No

PERA-BATT COLLISION (Continued) **1000143475**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOSEPH PERA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

PERA-BATT COLLISION (Continued) **1000143475**

Owner/Operator Name: JOSEPH PERA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JOSEPH PERA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19950710
Handler Name: PERA-BATT COLLISION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: PERA-BATT COLLISION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PERA-BATT COLLISION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

PERA-BATT COLLISION (Continued) **1000143475**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860915
Handler Name: PERA-BATT COLLISION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: LDR - General
Date Violation was Determined: 19930505
Actual Return to Compliance Date: 19950323
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: EPA
Scheduled Compliance Date: 19941114
Enforcement Identifier: 000
Date of Enforcement Action: 19941014
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: R2
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: R2GVY
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported

PERA-BATT COLLISION (Continued) **1000143475**

Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19930505
Evaluation Responsible Agency: EPA Contractor/Grantee
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: R2TRC
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 19950323
Scheduled Compliance Date: 19941114
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004408150

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000143475
Registry ID: 110004408150

DFR URL:
Name: PERA-BATT COLLISION
Address: 1775 Walden Ave
City,State,Zip: CHEEKTOWAGA, NY 14225

NY MANIFEST:
EPA ID: NYD981557556
Country: USA
Name: Pera Batt Collision & Auto Service
Address: 1775 WALDEN AVE
Address 2: Not reported
City,State,Zip: CHEEKTOWAGA, NY 14225
Zip 4: Not reported
Location Address 1: 1775 WALDEN AVENUE
Location Address 2: Not reported
Location City,State,Zip: CHEEKTOWAGA, NY 14225
Location Zip 4: Not reported

PERA-BATT COLLISION (Continued) **1000143475**

Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Pera Batt Collision & Auto Service
Mailing Contact: Pera Batt Collision & Auto Service
Mailing Address 1: 1775 WALDEN AVENUE
Mailing Address 2: Not reported
Mailing City,State,Zip: CHEEKTOWAGA, NY 14225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7168973700

Manifest Data:
Document ID: NYC1782527
Manifest Status: Not reported
Trans1 State ID: NYEM4533
Year: 1992
Trans2 State ID: Not reported
Generator Ship Date: 08/04/1992
Trans1 Recv Date: 08/04/1992
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/04/1992
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD981557556
Trans1 EPA ID: ILD051060408
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00219
Units: Pounds

PERA-BATT COLLISION (Continued) **1000143475**

Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYA6854433
Manifest Status:	C - Completed copy
Trans1 State ID:	NY58326-G
Year:	1987
Trans2 State ID:	506-TYJ-N
Generator Ship Date:	871027
Trans1 Recv Date:	871027
Trans2 Recv Date:	871102
TSD Site Recv Date:	871104
Part A Recv Date:	871030
Part B Recv Date:	871110
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	ILD051060408
TSDF ID 1:	OHD981099401
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00612
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYC1834413
Manifest Status:	Not reported

PERA-BATT COLLISION (Continued) **1000143475**

Trans1 State ID:	NYEM4533
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	09/04/1992
Trans1 Recv Date:	09/04/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/04/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00219
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC3130391
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	09/16/1994
Trans1 Recv Date:	09/16/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/16/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981557556

PERA-BATT COLLISION (Continued) **1000143475**

Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00112
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYA8809558
Manifest Status:	C - Completed copy
Trans1 State ID:	NYMJ1780
Year:	1988
Trans2 State ID:	Not reported

PERA-BATT COLLISION (Continued) **1000143475**

Generator Ship Date:	880315
Trans1 Recv Date:	880315
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880315
Part A Recv Date:	880318
Part B Recv Date:	880318
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYC3121705
Manifest Status:	Not reported
Trans1 State ID:	NYGA6403
Year:	1994
Trans2 State ID:	Not reported
Generator Ship Date:	06/28/1994
Trans1 Recv Date:	06/28/1994
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/29/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981557556

PERA-BATT COLLISION (Continued) **1000143475**

Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00224
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC1330839
Manifest Status:	Not reported
Trans1 State ID:	NYEM4533
Year:	1991
Trans2 State ID:	Not reported

PERA-BATT COLLISION (Continued) **1000143475**

Generator Ship Date:	11/22/1991
Trans1 Recv Date:	11/22/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/22/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00123
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYC2286911
Manifest Status:	Not reported
Trans1 State ID:	NYEM4533
Year:	1993
Trans2 State ID:	Not reported
Generator Ship Date:	05/04/1993
Trans1 Recv Date:	05/04/1993
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/04/1993
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541

PERA-BATT COLLISION (Continued) **1000143475**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00123
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Document ID:	NYA8982944
Manifest Status:	C - Completed copy
Trans1 State ID:	NYMJ1780
Year:	1988
Trans2 State ID:	Not reported
Generator Ship Date:	880804
Trans1 Recv Date:	880804
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	880804
Part A Recv Date:	880811
Part B Recv Date:	880811
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

PERA-BATT COLLISION (Continued) **1000143475**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00036
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYA6761529
Manifest Status:	C - Completed copy
Trans1 State ID:	NY58326GK
Year:	1987
Trans2 State ID:	NJ506TYJ
Generator Ship Date:	870902
Trans1 Recv Date:	870902
Trans2 Recv Date:	870908
TSD Site Recv Date:	870910
Part A Recv Date:	870909
Part B Recv Date:	870915
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD000805911
Trans2 EPA ID:	ILD051060408
TSDF ID 1:	OHD981099401
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent

PERA-BATT COLLISION (Continued) **1000143475**

	Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00360
Units:	Pounds
Number of Containers:	004
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYC1397103
Manifest Status:	Not reported
Trans1 State ID:	NYEM4533
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	12/19/1991
Trans1 Recv Date:	12/19/1991
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/19/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981557556
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported

PERA-BATT COLLISION (Continued) **1000143475**

Waste Code 6:	Not reported
Quantity:	00123
Units:	Pounds
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
91 additional NY MANIFEST: record(s) in the EDR Site Report.

O73 **MCKESSON** **E MANIFEST** **1032172589**
SSE **2873 BROADWAY, SUITE 100** **N/A**
1/8-1/4 **BUFFALO, NY 14227**
0.228 mi.
1202 ft. **Site 1 of 2 in cluster O**

Relative:
Lower

Actual:
641 ft.

E MANIFEST:

Manifest Tracking Number:	017218482FLE
Last Updated Date:	20221228
Shipped Date:	20221116
Received Date:	20221204
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CESQG
Generator Name:	Mckesson
Generator Location Street Number:	Not reported
Generator Location Street 1:	2873 BROADWAY, SUITE 100
Generator Location Street 2:	Not reported
Generator Location City:	BUFFALO
Generator Location State:	NY
Generator Location Zip:	14227
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2873 Broadway, Suite 100
Generator Mail Street 2:	Not reported
Generator Mail City:	Buffalo
Generator Mail Zip:	14227
Generator Mail State:	NY
Generator Contact Company Name:	McKesson
Designated Facility EPA ID:	ARD069748192
Designated Facility Name:	Clean Harbors El Dorado Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	309 American Circle
Designated Facility Mail City:	El Dorado
Designated Facility Mail Zip:	71730
Designated Facility Mail State:	AR
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	309 American Circle
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	El Dorado
Designated Facility Location Zip:	71730
Designated Facility Location State:	AR
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

MCKESSON (Continued) **1032172589**

Transporter:
Manifest Tracking Number: 017218482FLE
Transporter Line Number: 1
Transporter EPA ID: MAD039322250
Transporter Name: Clean Harbors Environmental Services, Inc.

Manifest Tracking Number: 017218482FLE
Transporter Line Number: 2
Transporter EPA ID: ALR000007237
Transporter Name: Action Resources Incorporated

Manifest Tracking Number: 017218482FLE
Transporter Line Number: 3
Transporter EPA ID: MAD039322250
Transporter Name: Clean Harbors Environmental Services, Inc.

Manifest Tracking Number: 017218482FLE
Transporter Line Number: 4
Transporter EPA ID: ALR000007237
Transporter Name: Action Resources Incorporated

Waste Line:
Manifest Tracking Number: 017218482FLE
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN3249
U.S. DOT Description: Un3249, Waste Medicine, Solid, Toxic, N.O.S. (Warfarin), 6.1, Pg Iii
Non-Hazardous Waste Description: Not reported
Number of Containers: 11
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 385
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.1925
Acute Waste Quantity, in Tons: 0.1925
Non-Acute Waste Quantity, in Tons: 0
Waste Quantity, in Kilograms: 174.60327
Acute Waste Quantity, in Kilograms: 174.60327
Non-Acute Waste Quantity, in Kilorgrams: 0
Management Method Code: H040
Management Method Description: INCINERATION
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: Y

MCKESSON (Continued) **1032172589**

Federal Waste Codes:	P001
Quantity Haz Kg:	174.60327
Quantity Haz Tons:	0.1925
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B
Manifest Tracking Number:	017218482FLE
Waste Line Number:	2
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3249
U.S. DOT Description:	Un3249, Waste Medicine, Solid, Toxic, N.O.S. (Warfarin), 6.1, Pg Iii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	2
Container Type Code:	CF
Container Type Description:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	60
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.03
Acute Waste Quantity, in Tons:	0.03
Non-Acute Waste Quantity, in Tons:	0
Waste Quantity, in Kilograms:	27.2109
Acute Waste Quantity, in Kilograms:	27.2109
Non-Acute Waste Quantity, in Kilorgrams:	0
Management Method Code:	H040
Management Method Description:	INCINERATION
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	P001
Quantity Haz Kg:	27.2109
Quantity Haz Tons:	0.03
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	NY-B

O74 **MCKESSON PHARMA BUFFALO 8326** **E MANIFEST** **1032172561**
SSE **2873 BROADWAY** **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14227**
0.228 mi.
1202 ft. **Site 2 of 2 in cluster O**

Relative:
Lower

Actual:
641 ft.

E MANIFEST:

Manifest Tracking Number:	002232690VES
Last Updated Date:	20240329
Shipped Date:	20240305
Received Date:	20240313
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYCESQG
Generator Name:	Mckesson Pharma Buffalo 8326
Generator Location Street Number:	Not reported
Generator Location Street 1:	2873 BROADWAY
Generator Location Street 2:	DC 8320
Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14227
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2873 BROADWAY
Generator Mail Street 2:	DC 8320
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14227
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	1 EDEN LANE
Designated Facility Mail Street 2:	L.L.C.
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	L.L.C.
Designated Facility Location Street 2:	1 EDEN LANE
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	002357769VES
Last Updated Date:	20250210
Shipped Date:	20250117
Received Date:	20250128
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	NYCESQG
Generator Name:	Mckesson Pharma Buffalo 8326
Generator Location Street Number:	Not reported
Generator Location Street 1:	2873 BROADWAY
Generator Location Street 2:	DC 8320

MCKESSON PHARMA BUFFALO 8326 (Continued) **1032172561**

Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14227
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	2873 BROADWAY
Generator Mail Street 2:	DC 8320
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14227
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NJD980536593
Designated Facility Name:	Not reported
Designated Facility Mail Street Number:	1
Designated Facility Mail Street 1:	1 EDEN LANE
Designated Facility Mail Street 2:	L.L.C.
Designated Facility Mail City:	FLANDERS
Designated Facility Mail Zip:	07836
Designated Facility Mail State:	NJ
Designated Facility Location Street Number:	1
Designated Facility Location Street 1:	L.L.C.
Designated Facility Location Street 2:	1 EDEN LANE
Designated Facility Location City:	FLANDERS
Designated Facility Location Zip:	07836
Designated Facility Location State:	NJ
Designated Facility Contact Company Name:	Veolia Es Technical Solutions
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	002357769VES
Transporter Line Number:	1
Transporter EPA ID:	NJD080631369
Transporter Name:	Veolia Es Technical Solutions

Manifest Tracking Number:	002357769VES
Transporter Line Number:	2
Transporter EPA ID:	NJD054126164
Transporter Name:	Freehold Cartage Inc

P75 **ERNST STEEL** **NY DEL SHWS** **S105973159**
North **N/A**
1/8-1/4 **CHEEKTOWAGA, NY 14209**
0.229 mi.
1207 ft. **Site 1 of 4 in cluster P**

Relative: DEL SHWS:
Lower

Actual:
653 ft.

Name:	ERNST STEEL
Address:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14209
Year:	1996
Site Code Id:	915022
Site Classification:	Not reported
Region:	Not reported
Epa Id Number:	Not reported
Site Type - Dump:	Yes
Site Type - Structure:	No
Site Type - Lagoon:	No

ERNST STEEL (Continued) **S105973159**

Site Type - Landfill:	No
Site Type - Treat Pond:	No
Site Size (Acres):	Not reported
Site Size Comment:	Not reported
Period Assoc/HW Start:	Unknown
Period Assoc/HW End:	1980
Lat/Long:	Not reported
Lat/Long Decimal:	Not reported
Lat/Long (dms):	42 54 399.0 / 78 46 198.0
Hazardous Waste Code:	Not reported
Hazard Waste Disposed:	Dried lead paint sludge
Quantity:	Unknown
Air Data Available:	No
SW Std Contravention:	No
GW Std Contravention:	Yes
Soil Type:	X
Sediment Data Available:	No
GW Std Contravention:	Yes
DW Std Contravention:	No
SW Std Contravention:	No
Air Stand Contraventions:	No
Legal Action Type:	Not reported
State Legal Action:	Yes
Federal Legal Action:	No
Enforce Status Code:	OS
Remedial Act Proposed:	Yes
Rem Act Under Design:	No
Rem Act In Progress:	No
Rem Act Completed:	No
Remedial Action Type:	Not reported
Soil Type:	clay
Depth To Groundwater:	30 ft.
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Owner Phone:	Not reported
Owner Contact Name:	Not reported
Owner During Disposal:	Not reported
Owner During Use:	Ernst Steel Corporation
Operator Name:	Ernst Steel
Operator Address:	Not reported
Operator City,St,Zip:	Not reported
Operator Phone:	Not reported
Operator Contact Name:	Not reported
Oper During Disposal:	Not reported
Site Type:	Not reported
HW Disposal Period:	Not reported
Analytical Data Available:	Not reported
Applicable Std Exceeded:	Not reported
Geotech Info:	Not reported
Depth To Groundwater:	Not reported
Status:	Not reported
Nature Of Action:	Not reported
Env Prob Assessment:	Paint sludge which contains high levels of lead and chromium and alsofailed EP-Toxicity in some areas of the site are currently being removedfrom the site. Groundwater has not been impacted.
Site Description:	Not reported

ERNST STEEL (Continued) **S105973159**

Confirmed HW:	Not reported
Environment Assesment:	Not reported
Health Assesment:	Not reported
Disposal Start Date:	Not reported
Disposal Term Date:	Not reported
Air Violation:	Not reported
Groundwater Violation:	Not reported
Drink Water Violation:	Not reported
Surface Water Violation:	Not reported
Legal New York State:	Not reported
Legal Federal:	Not reported
Legal State:	Not reported
Remedial Action Active:	Not reported
Remedial Action Done:	Not reported
NPL Status:	Not reported
Count Operator:	Not reported
Count Owner:	Not reported
NYTM X:	Not reported
NYTM Y:	Not reported
Co Name:	Not reported
Co Addr:	Not reported
Operator Addr:	Not reported
Operator Addr 2:	Not reported
Operator Addr 3:	Not reported
Operator Addr 4:	Not reported
HWDP From:	Not reported
From To:	Not reported
Assessment of Health:	Not reported
Description:	Not reported
Record Added Date:	Not reported
Record Updated Date:	Not reported
Env Assessment:	Not reported
HW Disposed/Quantity:	Not reported
Assess/Env Prog:	Not reported
Assess/Health Prob:	Not reported
Site Description:	Not reported

---

76 **UNIVERSAL JOINT SALES CO INC** **RCRA-VSQG** **1000339563**
NNW **1696 WALDEN AVE** **FINDS** **NYD000818583**
1/8-1/4 **BUFFALO, NY 14225** **ECHO**
0.238 mi. **NY MANIFEST**
1257 ft.

Relative:
Lower

Actual:
655 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Universal Joint Sales Co Inc
Handler Address:	Walden Ave
Handler City,State,Zip:	BUFFALO, NY 14225-4914
EPA ID:	NYD000818583
Contact Name:	Not reported
Contact Address:	WALDEN AVE
Contact City,State,Zip:	BUFFALO, NY 14225
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Federal Waste Generator Description:		Conditionally Exempt Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		WALDEN AVE
Mailing City,State,Zip:		BUFFALO, NY 14225
Owner Name:	John Sharkey Iii	
Owner Type:		Private
Operator Name:	John Sharkey Iii	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:		Not reported
Handler Date of Last Change:		20150414
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No
Sub-Part P Indicator:		No

Hazardous Waste Summary:

Waste Code:	D000

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: D018
Waste Description: Benzene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: K078
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: JOHN SHARKEY III
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JOHN SHARKEY III
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JOHN SHARKEY III
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, NY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: UNIVERSAL JOINT SALES CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: UNIVERSAL JOINT SALES CO INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: UNIVERSAL JOINT SALES CO INC
Federal Waste Generator Description: Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920415
Handler Name: UNIVERSAL JOINT SALES CO INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004332071

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000339563
Registry ID: 110004332071

DFR URL:
Name: UNIVERSAL JOINT SALES CO INC
Address: 1696 Walden Ave
City,State,Zip: BUFFALO, NY 14225

NY MANIFEST:
EPA ID: NYD000818583
Country: USA
Name: E I Dupont De Nemours
Address: 1696 WALDEN AVE

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Address 2: Not reported
City,State,Zip: BUFFALO, NY 14225-4914
Zip 4: Not reported
Location Address 1: 1696 WALDEN AVENUE
Location Address 2: Not reported
Location City,State,Zip: BUFFALO, NY 14225
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: E I Dupont De Nemours
Mailing Contact: E I Dupont De Nemours
Mailing Address 1: 1696 WALDEN AVENUE
Mailing Address 2: Not reported
Mailing City,State,Zip: BUFFALO, NY 14225
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7168967979

Manifest Data:
Document ID: NYC6108614
Manifest Status: Not reported
Trans1 State ID: NY92865AT
Year: 2000
Trans2 State ID: Not reported
Generator Ship Date: 03/10/2000
Trans1 Recv Date: 03/10/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/10/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000818583
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00032

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Units: Gallons (liquids only)
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYC6185057
Manifest Status: Not reported
Trans1 State ID: Not reported
Year: 2000
Trans2 State ID: Not reported
Generator Ship Date: 07/06/2000
Trans1 Recv Date: 07/06/2000
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/06/2000
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD000818583
Trans1 EPA ID: SCR000075150
Trans2 EPA ID: Not reported
TSDF ID 1: NYD981556541
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00042
Units: Gallons (liquids only)
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Recycle
Specific Gravity: 01.00

Document ID: NYA6103917
Manifest Status: C - Completed copy
Trans1 State ID: Not reported
Year: 1989
Trans2 State ID: Not reported
Generator Ship Date: 890321
Trans1 Recv Date: 890321
Trans2 Recv Date: Not reported
TSD Site Recv Date: 890322
Part A Recv Date: 890330

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Part B Recv Date:	890327
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	OHD980614374
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01560
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	030
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	04641
Units:	Pounds
Number of Containers:	169
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	169
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00150
Units:	Pounds
Number of Containers:	005
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	050
Document ID:	NYC7501105
Manifest Status:	Not reported
Trans1 State ID:	NY10826JF
Year:	2005

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2005
Trans1 Recv Date:	02/08/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/08/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00027
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYA6103935
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/1990
Trans1 Recv Date:	10/22/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/25/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	OHD980614374
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	40256
Units:	Pounds
Number of Containers:	999
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYA6103944
Manifest Status:	Not reported
Trans1 State ID:	OH711V14
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/1990
Trans1 Recv Date:	10/22/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	OHD980614374
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	13835
Units:	Pounds

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Number of Containers:	943
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00120
Units:	Pounds
Number of Containers:	003
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	03600
Units:	Pounds
Number of Containers:	009
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 17:	Ignitable Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00350
Units:	Pounds
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYA6103953
Manifest Status:	Not reported
Trans1 State ID:	OH711V14
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	10/22/1990
Trans1 Recv Date:	10/22/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	OHD980614374
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02400
Units:	Pounds
Number of Containers:	006
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00050
Units:	Pounds
Number of Containers:	003
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	NYC6237663
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	08/29/2000
Trans1 Recv Date:	08/29/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/29/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00043
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00

Document ID:	NYC6124645
Manifest Status:	Not reported
Trans1 State ID:	Not reported
Year:	2000
Trans2 State ID:	Not reported
Generator Ship Date:	05/08/2000
Trans1 Recv Date:	05/08/2000
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/08/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD981556541
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00037
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYA1510326
Manifest Status:	K - Completed after the designated time
Trans1 State ID:	18L746
Year:	1985
Trans2 State ID:	Not reported
Generator Ship Date:	850415
Trans1 Recv Date:	850415
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	850419
Part A Recv Date:	850517
Part B Recv Date:	850515
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	OHD980614374
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00150
Units:	Gallons (liquids only)
Number of Containers:	030
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00209
Units:	Gallons (liquids only)

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Number of Containers:	279
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	100
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00863
Units:	Gallons (liquids only)
Number of Containers:	630
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	100
Waste Code 17:	Ignitable Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00085
Units:	Gallons (liquids only)
Number of Containers:	017
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100

Document ID:	NYA6103881
Manifest Status:	C - Completed copy
Trans1 State ID:	17R778
Year:	1987
Trans2 State ID:	Not reported
Generator Ship Date:	870218
Trans1 Recv Date:	870218
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	870219
Part A Recv Date:	870302
Part B Recv Date:	870302
Generator EPA ID:	NYD000818583
Trans1 EPA ID:	OHD980614374
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD048415665
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported

UNIVERSAL JOINT SALES CO INC (Continued) **1000339563**

Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01560
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	09550
Units:	Pounds
Number of Containers:	634
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	100
Waste Code 12:	Ignitable Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00450
Units:	Pounds
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Waste Code 17:	Corrosive Waste
Waste Code 18:	Not reported
Waste Code 19:	Not reported
Waste Code 20:	Not reported
Waste Code 21:	Not reported
Quantity:	00760
Units:	Pounds
Number of Containers:	019
Container Type:	Fiber or plastic boxes, cartons, cases
Handling Method:	Burn
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
10 additional NY MANIFEST: record(s) in the EDR Site Report.

P77 **ERNST STEEL** **SEMS-ARCHIVE** **1003863735**
North **1746 WALDEN AVE.** **NYD980508246**
1/4-1/2 **BUFFALO, NY 14240**
0.265 mi.
1401 ft. **Site 2 of 4 in cluster P**

Relative:
Lower

Actual:
655 ft.

SEMS Archive:

Site ID:	0201812
EPA ID:	NYD980508246
Name:	ERNST STEEL
Address:	1746 WALDEN AVE.
Address 2:	Not reported
City,State,Zip:	BUFFALO, NY 14240
Cong District:	38
FIPS Code:	36029
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	02
Site ID:	0201812
EPA ID:	NYD980508246
Site Name:	ERNST STEEL
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1983-11-01 05:00:00
Qual:	L
Current Action Lead:	St Perf

Region:	02
Site ID:	0201812
EPA ID:	NYD980508246
Site Name:	ERNST STEEL
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	2
Start Date:	Not reported
Finish Date:	1986-03-17 05:00:00
Qual:	L
Current Action Lead:	St Perf

Region:	02
Site ID:	0201812
EPA ID:	NYD980508246
Site Name:	ERNST STEEL
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1

ERNST STEEL (Continued) **1003863735**

Start Date:	1980-04-01 05:00:00
Finish Date:	1980-04-01 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0201812
EPA ID:	NYD980508246
Site Name:	ERNST STEEL
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1988-08-12 04:00:00
Finish Date:	1988-08-29 04:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0201812
EPA ID:	NYD980508246
Site Name:	ERNST STEEL
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1988-08-29 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

P78 **ERNST STEEL** **NY SHWS** **S108061181**
North **1728-1746 WALDEN AVENUE** **N/A**
1/4-1/2 **CHEEKTOWAGA, NY 14209**
0.265 mi.
1401 ft. **Site 3 of 4 in cluster P**

Relative: SHWS:
Lower

Name:	ERNST STEEL
Address:	1728-1746 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 14209
Program:	HW
Site Code:	56552
Classification:	C
Region:	9
Acres:	3.000
HW Code:	915022
Record Add:	11/18/1999
Record Upd:	10/03/2007
Updated By:	MLDOSTER
Site Description:	This site consists of the rear portions of properties located at 1746 and 1728 Walden Ave., which were part of the former Ernst Steel Corporation and are located at the north-west corner of Walden Ave.

Actual:
655 ft.

ERNST STEEL (Continued) **S108061181**

and Galleria Drive in the Town of Cheektowaga. Wastes such as metal shavings, iron oxide dust, paint sludge and machine cutting oil were disposed at this site. A Phase I investigation was completed in 1987. Samples collected in 1988 and 1990 by DEC have indicated total lead levels of up to 56,700 ppm and total chromium levels at up to 6,270 ppm in soils. A Consent Order (CO) was signed in May 1992 to conduct a removal action and site investigation. US Metal Source removed about 80 cubic yards of the contaminated soil and performed a site investigation. During this investigation more contamination was discovered. A second Consent Order (CO) in June 1995 was executed to remediate the site under an Interim Remedial Measure (IRM). The IRM started during the summer of 1995 and consisted of the excavation of contaminated soils and off-site disposal. The IRM was completed in summer 1996. The Record of Decision (ROD) indicating "No Further Action" was signed in March 1997.

Env Problem:	Paint sludge which contained high levels of lead and chromium and also failed EP-Toxicity in some areas of the site have been removed from the site under an IRM. Groundwater has not been impacted. No known environmental problems remain on site.
Health Problem:	Samples of soil with paint waste that were taken in 1988 and 1990 by DEC contain high levels of total lead and chromium. Additional investigation and sampling in 1992 found an additional estimated 11,000 tons of lead contaminated paint waste material of which 3,000 tons is characteristic hazardous waste. This waste was found just below the ground surface. The site was remediated by removing contaminated soil, constructing buildings and an the installation of an asphalt parking lot reduced the potential for future direct contact exposure. The area is served by public water.
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1980
Lat/Long:	42:54:40:0 / 78:46:20:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Ernst Steel Corporation
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	Ernst Steel
Owner Address:	P.O. BOX 987
Owner Addr2:	Not reported
Owner City,St,Zip:	BUFFALO, NY 14240
Owner Country:	United States of America
Own Op:	1

ERNST STEEL (Continued) **S108061181**

Sub Type:	E
Owner Name:	Not reported
Owner Company:	93-1 Trust Company
Owner Address:	570 DELAWARE AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	BUFFALO, NY 14202
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	ERNST STEEL CORPORATION
Owner Address:	570 DELAWARE AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	BUFFALO, NY 14202
Owner Country:	United States of America
HW Code:	915022
Waste Type:	DRIED LEAD PAINT SLUDGE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	143
Cross Ref Type Code:	14
Cross Ref Type:	Assembly District
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2005-02-24 15:54:00
Updated By:	INITIAL
Crossref ID:	15-S-35
Cross Ref Type Code:	07
Cross Ref Type:	Muni. Waste ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2005-02-24 15:54:00
Updated By:	INITIAL
Crossref ID:	NYD980508246
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2001-05-10 16:31:00
Updated By:	REGTRANS

P79 **ERNST STEEL SLF** **NY SWF/LF** **S126022914**
North **1728-1746 WALDEN AVENUE** **NY ILI** **N/A**
1/4-1/2 **BUFFALO, NY**
0.265 mi.
1401 ft. **Site 4 of 4 in cluster P**

Relative: SWF/LF:
Lower

Actual:
655 ft.

Name:	ERNST STEEL SLF
Address:	1728-1746 WALDEN AVENUE
City,State,Zip:	BUFFALO, NY
Flag:	INACTIVE
Region Code:	9
Phone Number:	Not reported
Owner Name:	93-1 Trust Company
Owner Type:	Not reported
Owner Address:	570 Delaware Ave
Owner Addr2:	Not reported
Owner City,St,Zip:	NY 14202
Owner Email:	Not reported
Owner Phone:	Not reported

ERNST STEEL SLF (Continued) **S126022914**

Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Not reported
Activity Number:	Not reported
Active:	Not reported
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

ILI:

Name:	ERNST STEEL SLF
Address:	1728-1746 Walden Avenue
City,State,Zip:	BUFFALO, NY
Latitude:	42.9100497
Longitude:	-78.773675
Landfill Type:	NYSDEC Inactive Landfill Initiative Solid Waste Site Investigation Priority List
Region:	9
Rank Score:	35
Site Specific Recommendations:	Initiate Investigation in 2027

Q80 **NYNEX** **NY LTANKS** **S110774095**
NW **1620 WALDEN AVENUE** **NY Spills** **N/A**
1/4-1/2 **CHEEKTOWAGA, NY**
0.281 mi.
1484 ft. **Site 1 of 4 in cluster Q**

Relative:
Higher

Actual:
658 ft.

LTANKS:

Name:	NYNEX
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	8909925 / 1990-08-13
Facility ID:	8909925
Site ID:	111723
Spill Date:	1990-01-12
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1990-05-31
SWIS:	1530
Investigator:	LYONS
Referred To:	Not reported
Reported to Dept:	1990-01-16
CID:	Not reported
Water Affected:	Not reported

NYNEX (Continued) **S110774095**

Spill Notifier:	Responsible Party
Last Inspection:	1990-01-19
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-01-29
Spill Record Last Update:	1990-08-13
Spiller Name:	Not reported
Spiller Company:	NYNEX
Spiller Address:	1620 WALDEN AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	97690
Latitude:	42.9073719
Longitude:	-78.7770039
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 01/19/90: 1/19/90 CAF INSP. CONTAM. SOIL REMOVED ABOVE TANK TOP, SOIL STAGED ON PLASTIC, NEEDS DISPOSAL. 07/25/90: MEL RECIEVED SOIL DISPOSAL RECIEPTS. NO FURTHER ACTION NECESSARY, RECOMMEND FILE BE CLOSED. 09/29/95: This is additional information about material spilled from the translation of the old spill file: AMOUNT UNDETERMINED.
Remarks:	6,000 GAL. TANK TAKING ON WATER

All TTF:

Facility ID:	8909925
Spill Number:	8909925
Spill Tank Test:	1536687
Site ID:	111723
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	111723
Operable Unit ID:	935018
Operable Unit:	01
Material ID:	443063
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

NYNEX (Continued) **S110774095**

Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	NYNEX ENTERPRISES
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9008012 / 1991-04-30
Facility ID:	9008012
Facility Type:	ER
DER Facility ID:	97690
Site ID:	111724
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	1530
Spill Date:	1990-10-19
Investigator:	LYONS
Referred To:	Not reported
Reported to Dept:	1990-10-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	1991-03-27
Cleanup Meets Std:	True
Last Inspection:	1991-03-27
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1990-10-24
Spill Record Last Update:	1991-04-30
Spiller Name:	Not reported
Spiller Company:	NYNEX ENTERPRISES
Spiller Address:	1620 WALDEN AVENUE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9073719
Longitude:	-78.7770039
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 10/23/90: MEL INSP. SPILL NOTICED WHILE INVESTIGATING AS TO THE SOURCE OF ANOTHER SPILL. COMPANY MADE AWARE OF SPILLAGE AND HAS AGREED TO CLEAN UP. 04/30/91: MEL RECIEVED DISPOSAL RECIEPTS, NO FURTHER ACTION NECESSARY. RECOMMEND FILE BE CLOSED.
Remarks:	Not reported

All Materials:

Site ID:	111724
Operable Unit ID:	948662
Operable Unit:	01
Material ID:	431845
Material Code:	0008
Material Name:	diesel

NYNEX (Continued) **S110774095**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	NYNEX WALDEN
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9013039 / 1991-09-18
Facility ID:	9013039
Facility Type:	ER
DER Facility ID:	97690
Site ID:	111725
DEC Region:	9
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	1530
Spill Date:	1991-03-21
Investigator:	LYONS
Referred To:	Not reported
Reported to Dept:	1991-03-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1991-07-11
Cleanup Meets Std:	True
Last Inspection:	1991-07-12
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1991-03-27
Spill Record Last Update:	1991-09-18
Spiller Name:	Not reported
Spiller Company:	NYNEX-TRC
Spiller Address:	414 NINTH AVENUE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9073719
Longitude:	-78.7770039
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 03/21/91: MF INSP. CONTAMINATED SOIL EXCAVATED, SHEEN IN EXCAVATION. REQUIRED PLACEMENT OF MW, WILL MONITOR. 07/12/91: MEL INSP. SOIL NO LONGER ON SITE. 09/18/91: MEL RECIEVED DISPOSAL RECIEPTS, NO FURTHER ACTION NECESSARY, RECOMMEND FILE BE CLOSED.
Remarks:	CONTAMINATION FOUND WHILE REMOVING TANKS

All Materials:

Site ID:	111725
Operable Unit ID:	950279
Operable Unit:	01
Material ID:	425941
Material Code:	0009

NYNEX (Continued) **S110774095**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported
Site ID:	111725
Operable Unit ID:	950279
Operable Unit:	01
Material ID:	425940
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported
Name:	NYNEX
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9609495 / 1997-02-05
Facility ID:	9609495
Facility Type:	ER
DER Facility ID:	97690
Site ID:	111726
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	1530
Spill Date:	1996-10-29
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1996-10-29
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	1996-10-30
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-10-29
Spill Record Last Update:	1997-02-26
Spiller Name:	TOM O'BRIEN
Spiller Company:	NYNEX
Spiller Address:	158 STATE STREET RM 1100A
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9073719
Longitude:	-78.7770039

NYNEX (Continued) **S110774095**

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC
10/29/96: JDC ON SITE AND
MET W/ CHAD WALKER, S&W SERVICES, HIRED BY NYNEX TO DO CLEANUP WORK. FOUND NO VISIBLE CONTAMINATION
IN THE EXCAVATION. GW NO FREE PRODUCT, SOILS WILL BE STAGED AND DISPOSED OFF. 1/28/97: SENT LETTER
TO MR O'BRIEN REQUESTING SOIL DISPOSAL DOCS. AND POST TESTING RESULTS ON THE EXCAVATION. 2/3/97:JDC
TELCON W/ DAVE WILLIAMES, NYNEX MAINT SUPER. AT 652-4421 AND OBTAINED NUMBER FOR MR O'BRIEN AT
914-356-4860/ PG-800-759-7243 AND LEFT MESSAGE FOR HIM TO RETURN MY CALL. 2/4/97: JDC TELCON W/
GREG MIKA, ET W/ S&W SERVICES AND REQUESTED FINAL REMEDIATION DATA. RECEIVED GW ANALYSIS AND FOUND
MINOR VIOLATION W/ TOLUENE. CONTAMINATED SOILS INCINERATED, SITE INACTIVE. WILL SEND LETTER.

Remarks: REMOVED LIFT FOUND CONTAMINATION ON WATER TABLE 8' DEEP

All Materials:

Site ID:	111726
Operable Unit ID:	1040969
Operable Unit:	01
Material ID:	345220
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	1620 WALDEN AVE
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0312874 / 2004-02-24
Facility ID:	0312874
Facility Type:	ER
DER Facility ID:	97690
Site ID:	184175
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	D3
SWIS:	1530
Spill Date:	2004-02-20
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2004-02-20
CID:	403
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2004-02-23
Recommended Penalty:	False
UST Trust:	False

NYNEX (Continued) **S110774095**

Remediation Phase:	0
Date Entered In Computer:	2004-02-20
Spill Record Last Update:	2004-02-24
Spiller Name:	KURT SPEILER
Spiller Company:	1620 WALDEN AVE
Spiller Address:	1620 WALDEN AVE
Spiller Company:	001
Contact Name:	KURT SPEILER
Latitude:	42.9073719
Longitude:	-78.7770039
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 02/23/2004 RMC/FILE. RECEIVED REPORT THIS AM. DROVE BY LOCATION, NO SPILLS DEBRIS NOTED, NO ACITON REQUIRED, CLOSE OUT NO PAPER FILE.
Remarks:	ABOUT 3 GALLONS OF TRANSMISSION FLUID WAS SPILLED DURING A TRAFFIC ACCIDENT. 250 LBS. OF SPEEDY DRY WAS USED TO CLEAN UP THE SPILL

All Materials:

Site ID:	184175
Operable Unit ID:	878125
Operable Unit:	01
Material ID:	498048
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

Q81 **NYNEX ENTERPRISES** **UST FINDER RELEASE** **1029079909**
NW **1620 WALDEN AVENUE** **N/A**
1/4-1/2 **CHEEKTOWAGA, NY 0**
0.281 mi.
1484 ft. **Site 2 of 4 in cluster Q**

Relative: **Higher**

Actual: **658 ft.**

UST FINDER RELEASE:

Object ID:	244696
Facility ID:	NY97690
Lust ID:	NY9008012
Name:	NYNEX ENTERPRISES
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1990/10/19 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	215
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported

NYNEX ENTERPRISES (Continued) **1029079909**

Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.777
Y Coord:	42.9073700000001
Latitude:	42.90737
Longitude:	-78.777

Q82 **NYNEX WALDEN** **UST FINDER RELEASE** **1029079910**
NW **1620 WALDEN AVENUE** **N/A**
1/4-1/2 **CHEEKTOWAGA, NY 0**
0.281 mi.
1484 ft. **Site 3 of 4 in cluster Q**

Relative:
Higher

Actual:
658 ft.

UST FINDER RELEASE:

Object ID:	244697
Facility ID:	NY97690
Lust ID:	NY9013039
Name:	NYNEX WALDEN
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1991/03/21 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	215
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State

NYNEX WALDEN (Continued) **1029079910**

X Coord:	-78.777
Y Coord:	42.9073700000001
Latitude:	42.90737
Longitude:	-78.777

Q83 **NYNEX** **UST FINDER RELEASE** **1029079911**
NW **1620 WALDEN AVENUE** **N/A**
1/4-1/2 **CHEEKTOWAGA, NY 0**
0.281 mi.
1484 ft. **Site 4 of 4 in cluster Q**

Relative: **Higher**
Actual: **658 ft.**

UST FINDER RELEASE:

Object ID:	244695
Facility ID:	NY97690
Lust ID:	NY8909925
Name:	NYNEX
Address:	1620 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1990/01/12 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	215
Domestic Wells within 1500ft:	0
Land Use:	Developed, High Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.777
Y Coord:	42.9073700000001
Latitude:	42.90737
Longitude:	-78.777

84
SSE
1/4-1/2
0.293 mi.
1545 ft.

ABITIBI BOWATER - BUFFALO PROCESSING FACILITY
2835 BROADWAY
CHEEKTOWAGA, NY 14227

NY SWRCY **S109135485**
N/A

Relative:
Lower

Actual:
637 ft.

SWRCY:

Name:	ABITIBI BOWATER - BUFFALO PROCESSING FACILITY
Address:	2835 BROADWAY
City,State,Zip:	CHEEKTOWAGA, NY 14227
Region:	9
Facility Address 2:	Not reported
Phone Number:	7168932027
Owner Type:	Private
Owner Name:	Abitibi Bowater
Owner Address:	PO Box 470
Owner Address 2:	Not reported
Owner City,St,Zip:	Hamburg, NY 14075
Owner Email:	Not reported
Owner Phone:	7168932027
Contact Name:	Susan Attridge
Contact Address:	Abitibi Bowater
Contact Address 2:	PO Box 470
Contact City,St,Zip:	Hamburg, NY 14075
Contact Email:	Not reported
Contact Phone:	7168932027
Activity Desc:	RHRF - registration
Activity Number:	[15M21]
Active:	No
East Coordinate:	192107
North Coordinate:	4756500
Accuracy Code:	4.2.1 - Utilization of GIS and Facility Mapping System
Regulatory Status:	Registration
Permit #:	15M21
Auth. Date:	7/2/2008
Expiration Date:	Not reported
Waste Types:	Office Paper;Junk Mail;Paper/Cardboard;Waste Mail;Magazines;Newspaper
Operator Name:	Not reported
Operator Type:	Not reported
Last Date:	Not reported

85
NNW
1/4-1/2
0.295 mi.
1558 ft.

DELAVAN INDUSTRIES
1722 AND 1728 WALDEN AVENUE
CHEEKTOWAGA, NY 14225

NY SHWS **S108061183**
NY VAPOR REOPENED **N/A**

Relative:
Lower

Actual:
654 ft.

SHWS:

Name:	DELAVAN INDUSTRIES
Address:	1722 AND 1728 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 14225
Program:	HW
Site Code:	56630
Classification:	C
Region:	9
Acres:	6.100
HW Code:	915138
Record Add:	11/18/1999
Record Upd:	04/16/2014
Updated By:	MLDOSTER

DELAVAN INDUSTRIES (Continued) **S108061183**

Site Description: Location: The Delavan Industries facility was located at 1728 Walden Avenue in the Town of Cheektowaga, Erie County, New York in a relatively high density mixed industrial /commercial area. The site borders by Walden Avenue to the south, Target Plaza property (the former Ernst Steel property) to the east, a Consolidated Rail Corporation right-of-way to the north and Benderson Development Company property to the west. Site Features: The site is approximately 6.1 acres in size and consists of a shopping plaza and parking areas. Current Zoning/Use(s): The site is currently zoned for commercial use. Historical Use(s): From 1953 to 1977, Ernst Steel operated on this property for fabrication and storage of metal products. In 1977, the Delavan Industries (DI) started an automobile carrier manufacturing facility. The DI facility consisted primarily of one building. The building housed all operations at the facility except the administrative offices which were located in the southwest corner of the site. DI conducted cleaning and painting operations of new and old automobile carriers between 1977 and 1986. In 1986 the majority of the painting operations were moved to another location and the cleaning operations scaled down accordingly. Only touch-up work continued at this facility. All paint work was performed in the paint shop located approximately at the middle of the west side of the building. This was also the location of a paint shop while Ernst Steel occupied the site. In 1987, soil samples were collected by NYSDEC on the Benderson property (west of DI's paint shop). The analyses revealed the presence of 1,1,1 trichloroethane, toluene, ethyl benzene, xylenes, kerosene, metals and semi volatile organic compounds to be present in the disposal area. In 1992, all contaminated soils were removed to the native soil in the disposal area and backfilled with clean fill. The excavation was mostly in the Benderson property and was along the property fence line. The site investigations also showed that the soils in the northern portion of the property were contaminated with elevated levels of metals. In 1996, contaminated soils from the northern portion of the property were excavated and the area was backfilled with clean materials. Site Geology and Hydrogeology: The site topography is very flat. Based on groundwater studies performed at the Pyramid Company site in 1988, groundwater in the area flows to the north-northeast. The aquifers are shallow and of insufficient quality and yield for domestic or industrial usage.

Env Problem: Nature and Extent of Contamination: Prior to Remediation: Delavan Industries used toluene for degreasing. Improper disposal of paint waste, solvents, kerosene and waste oils occurred on the site. Yellow pigments with a strong solvent odor were noted when sampling the soils. The groundwater also had a chemical sheen. The results showed 1,1,1 trichloroethane, toluene, ethyl benzene, kerosene, metals and semi-volatiles to be present in the disposal area. An Order on Consent was signed for a Preliminary Site Assessment in 1990. Based on the findings of this event further work was conducted in 1991 and the results found widespread metals and solvent contamination. All contaminated soil was removed to the native clay in the disposal area. Lead in the soil was removed to below background levels. Post-Remediation: All contaminants were removed to below the recommended cleanup levels in soils. Contaminated soils at the site have been removed and replaced with clean backfill. There are no environmental problems remaining at this site associated with the disposal of hazardous waste.

Health Problem: Remedial activities undertaken at the site have effectively reduced

DELAVAN INDUSTRIES (Continued) **S108061183**

the potential for exposure to site-related contaminants. Therefore, this site no longer poses a public health concern.

Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1987
Lat/Long:	42:54:38:0 / 78:46:27:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	DELAVAN INDUSTRIES
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Delavan Industries, Inc.
Owner Address:	1728 Walden Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Country:	United States of America
Own Op:	4
Sub Type:	E
Owner Name:	Not reported
Owner Company:	DELAVAN INDUSTRIES
Owner Address:	1728 WALDEN AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	CHEEKTOWAGA, NY 14225
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Ryder Automotive Operations
Owner Address:	1450 West Long Lake Road,POBox 7084
Owner Addr2:	Not reported
Owner City,St,Zip:	Troy, MI 480986330
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	DELAVAN INDUSTRIES
Owner Address:	570 DELAWARE AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	BUFFALO, NY 14202
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported

DELAVAN INDUSTRIES (Continued) **S108061183**

Owner Company:	Benderson Development Corp.
Owner Address:	570 Delaware Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Buffalo, NY 14202
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	DELAVAN INDUSTRIES
Owner Address:	1450 WEST LONG LAKE RD.,P.O.BOX 7084
Owner Addr2:	Not reported
Owner City,St,Zip:	TROY, MI 480986330
Owner Country:	United States of America
HW Code:	915138
Waste Type:	1,1,1-TRICHLOROETHANE (F001)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	915138
Waste Type:	TOLUENE (F003)
Waste Quantity:	"
Waste Code:	Not reported
HW Code:	915138
Waste Type:	EP TOX LEAD (D008)
Waste Quantity:	"
Waste Code:	Not reported
Crossref ID:	NYD980559496
Cross Ref Type Code:	05
Cross Ref Type:	EPA Site ID
Record Added Date:	1999-11-18 12:00:00
Record Updated:	2001-05-10 16:31:00
Updated By:	REGTRANS

VAPOR REOPENED:

Name:	DELAVAN INDUSTRIES
Address:	1722 AND 1728 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Site Code:	915138
Facility Status:	Complete (No Further Action)

86
NW
1/4-1/2
0.303 mi.
1598 ft.

ELLICOTT DRUG **UST FINDER RELEASE** **1029064447**
1650 WALDEN AVENUE **N/A**
CHEEKTOWAGA, NY 0

Relative:
Lower

Actual:
652 ft.

UST FINDER RELEASE:

Object ID:	244713
Facility ID:	NY197751
Lust ID:	NY9007918
Name:	ELLICOTT DRUG
Address:	1650 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY 0
Address Match Type:	Not reported
Reported Date:	1990/10/12 15:59:59+00
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	191

ELLICOTT DRUG (Continued) **1029064447**

Domestic Wells within 1500ft:	0
Land Use:	Developed, Medium Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	NY1430018_14182
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	041201040601
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	2
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	State
X Coord:	-78.7757
Y Coord:	42.9077500000001
Latitude:	42.90775
Longitude:	-78.7757

87
NE
1/4-1/2
0.355 mi.
1876 ft.

NYS THRUWAY RADIO TOWER **NY LTANKS** **S104782232**
I90 WB WALDEN INTERCHANGE **N/A**
CHEEKTOWAGA, NY

Relative:
Higher

Actual:
669 ft.

LTANKS:

Name:	NYS THRUWAY RADIO TOWER
Address:	I90 WB WALDEN INTERCHANGE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	0075337 / 2000-09-20
Facility ID:	0075337
Site ID:	269058
Spill Date:	2000-08-01
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	1530
Investigator:	SORGI
Referred To:	Not reported
Reported to Dept:	2000-08-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-30
Spill Record Last Update:	2000-10-05

NYS THRUWAY RADIO TOWER (Continued) **S104782232**

Spiller Name:	TOM CONOPA
Spiller Company:	NYS THRUWAY AUTHORITY
Spiller Address:	3901 GENESEE STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	219152
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 08/30/00: MJS TELECON WITH SCOTT OVERHOFF, EPS INC.. WORK PERFORMED ON 8/28. TANK WAS IN GOOD SHAPE, CONTAMINATION APPEARED TO BE FROM OVERFILLS. 30-40 TONS CONTAMINATED SOILS STAGED ON SITE. CONFIRMATORY SAMPLES OBTAINED AND HE WILL FORWRD RESULTS WHEN RECEIVED. 09/05/00: MJS RECEIVED FAX OF LETTER REPORT AND CONFIRMATORY SAMPLE RESULTS FROM SCOTT OVERHOFF. SOIL SAMPLE RESULTS ALL NON-DETECT FOR 8021/8270. EXCAVATION WATER SAMPLE RESULTS ALL WITHIN STANDARDS EXCEPT NAPTHALENE AT 17.9 PPB. 09/20/00: MJS RECEIVED FAX OF DISPOSAL DOCUMENTATION FROM SCOTT OVERHOFF. 36.98 TONS SOIL DISPOSED AT MODEL CITY LANDFILL. NO FURTHER WORK REQUIRED. FILE INACTIVE. 10/06/00: RNL FILE REVIEW, NEEDS INACTIVE LETTER
Remarks:	DURING REMOVAL OF A 250 GALLON DIESEL TANK, CONTAMINATION OBSERVED IN THE EXCAVATION, TANK WAS IN GOOD SHAPE, CONTRACTOR SUSPECTS OVERFILLS TO BE SOURCE OF CONTAMINATION.

All Materials:

Site ID:	269058
Operable Unit ID:	838201
Operable Unit:	01
Material ID:	538898
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R88 **REXEL USA** **SEMS-ARCHIVE** **1000227732**
ESE **505 DUKE ROAD** **NY Spills** **NYD000631903**
1/4-1/2 **CHEEKTOWAGA, NY 14225** **RCRA NonGen / NLR**
0.384 mi. **FINDS**
2030 ft. **Site 1 of 2 in cluster R** **ECHO**
E MANIFEST
Relative: Lower **NY MANIFEST**

Actual: 651 ft.

SEMS Archive:

Site ID:	0201292
EPA ID:	NYD000631903
Name:	BUFFALO FORGE CO PLANT #2
Address:	505 DUKE RD
Address 2:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14225
Cong District:	38

REXEL USA (Continued) **1000227732**

FIPS Code: 36029
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 02
Site ID: 0201292
EPA ID: NYD000631903
Site Name: BUFFALO FORGE CO PLANT #2
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1986-03-24 05:00:00
Qual: L
Current Action Lead: EPA Perf

Region: 02
Site ID: 0201292
EPA ID: NYD000631903
Site Name: BUFFALO FORGE CO PLANT #2
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1981-05-01 04:00:00
Finish Date: 1981-05-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 02
Site ID: 0201292
EPA ID: NYD000631903
Site Name: BUFFALO FORGE CO PLANT #2
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1987-02-19 05:00:00
Finish Date: 1987-02-23 05:00:00
Qual: N
Current Action Lead: EPA Perf

Region: 02
Site ID: 0201292
EPA ID: NYD000631903
Site Name: BUFFALO FORGE CO PLANT #2
NPL: N
FF: N
OU: 00

REXEL USA (Continued) **1000227732**

Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1987-02-23 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

SPILLS:

Name:	COMMERCIAL
Address:	505 DUKE RD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	2309857 / Not Reported
Facility ID:	2309857
Facility Type:	ER
DER Facility ID:	609198
Site ID:	664031
DEC Region:	9
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	1530
Spill Date:	2024-03-20
Investigator:	CMMIKIDA
Referred To:	Not reported
Reported to Dept:	2024-03-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2024-03-20
Spill Record Last Update:	2024-03-22
Spiller Name:	Not reported
Spiller Company:	AAA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BORALLY MUNOZ
Latitude:	Not reported
Longitude:	Not reported
DEC Memo:	03/20/24 CMM called Corally Munoz with AAA. Corally sent follow up email with spill details and photos. Diesel sheen discovered in parking lot this morning (unknown source). Snow melt/rainy weather migrated sheen and it entered a storm drain. AAA applied speedy dry and swept up waste. Less than a drum of waste generated, and it will be disposed of properly. CMM site inspection. Observed spill area. Minor diesel sheen cleaned up from pavement. Storm drain contained water with a negligible sheen. Flows to adjacent drain. No sheen in adjacent drain. No further cleanup

REXEL USA (Continued) **1000227732**

required. Spoke with AAA supervisor. Sheen was discovered this morning in parking lot. Unkown
source, lot of businesses in the area, any vehicle could have driven through and left sheen.

Remarks: speedy dry put down

All Materials:

Site ID:	664031
Operable Unit ID:	1410835
Operable Unit:	01
Material ID:	2428546
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Cedar Key Assocs Lp-Buffalo Forge Plt
Handler Address:		Duke Rd
Handler City,State,Zip:		CHEEKTOWAGA, NY 14225-5101
EPA ID:		NYD000631903
Contact Name:		MARTIN OLARI
Contact Address:		DELAWARE AVE
Contact City,State,Zip:		BUFFALO, NY 14202
Contact Telephone:		716-886-0211
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		DELAWARE AVE
Mailing City,State,Zip:		BUFFALO, NY 14202
Owner Name:	Buffalo Forge Co	
Owner Type:		Private
Operator Name:	Buffalo Forge Co	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

REXEL USA (Continued) **1000227732**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	F017
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: BUFFALO FORGE CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 985
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	716-847-5121
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: CEDAR KEY ASSOICATES LP	

REXEL USA (Continued) **1000227732**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	570 DELAWARE AVE
Owner/Operator City,State,Zip:	BUFFALO, NY 14202
Owner/Operator Telephone:	716-886-0211
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CEDAR KEY ASSOICATES LP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	570 DELAWARE AVE
Owner/Operator City,State,Zip:	BUFFALO, NY 14202
Owner/Operator Telephone:	716-886-0211
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: BUFFALO FORGE CO	
Legal Status:	Private
Date Became Current:	19990901
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 985
Owner/Operator City,State,Zip:	BUFFALO, NY 14240
Owner/Operator Telephone:	716-847-5121
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: BUFFALO FORGE CO	
Legal Status:	Private
Date Became Current:	19990901
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 985
Owner/Operator City,State,Zip:	BUFFALO, NY 14240
Owner/Operator Telephone:	716-847-5121
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: BUFFALO FORGE CO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 985
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	716-847-5121
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

REXEL USA (Continued) **1000227732**

Historic Generators:

Receive Date:	19990708
Handler Name:	CEDAR KEY ASSOCS LP-BUFFALO FORGE PLT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	CEDAR KEY ASSOCS LP-BUFFALO FORGE PLT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	CEDAR KEY ASSOCS LP-BUFFALO FORGE PLT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20000210
Handler Name:	CEDAR KEY ASSOCS LP-BUFFALO FORGE PLT
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19940513
Handler Name:	BUFFALO FORGE CO.
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

REXEL USA (Continued) **1000227732**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960319
Handler Name: BUFFALO FORGE CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 33341
NAICS Description: Ventilation, Heating, Air-Conditioning, And Commercial Refrigeration Equipment Manufacturing

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

REXEL USA (Continued) **1000227732**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19911121
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier: NYNSL
Evaluation Responsible Sub-Organization: R9
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported

REXEL USA (Continued) **1000227732**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19880126
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110000875063

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000227732
Registry ID:	110000875063

DFR URL:

Name:	CEDAR KEY ASSOCS LP-BUFFALO FORGE PLT
Address:	505 Duke Rd
City,State,Zip:	CHEEKTOWAGA, NY 14225

E MANIFEST:

Manifest Tracking Number:	013401938JJK
Last Updated Date:	20220519
Shipped Date:	20220510
Received Date:	20220510
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Web
Generator EPA ID:	NYSCESQG
Generator Name:	Rexel Usa
Generator Location Street Number:	505
Generator Location Street 1:	505 DUKE ROAD
Generator Location Street 2:	SUITE 400

REXEL USA (Continued) **1000227732**

Generator Location City:	CHEEKTOWAGA
Generator Location State:	NY
Generator Location Zip:	14225
Generator Mail Street Number:	505
Generator Mail Street 1:	DUKE ROAD
Generator Mail Street 2:	SUITE 400
Generator Mail City:	CHEEKTOWAGA
Generator Mail Zip:	14225
Generator Mail State:	NY
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NYR000192005
Designated Facility Name:	American Lamp Recycling Llc
Designated Facility Mail Street Number:	55
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	RIVERVIEW DRIVE
Designated Facility Mail City:	MARLBORO
Designated Facility Mail Zip:	12542
Designated Facility Mail State:	NY
Designated Facility Location Street Number:	55
Designated Facility Location Street 1:	RIVERVIEW DR
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	MARLBORO
Designated Facility Location Zip:	12542
Designated Facility Location State:	NY
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	013401938JJK
Transporter Line Number:	1
Transporter EPA ID:	NYR000192005
Transporter Name:	American Lamp Recycling Llc

Waste Line:

Manifest Tracking Number:	013401938JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA3077
U.S. DOT Description:	Rq, Na3077, Hazardous Waste, Solid, N.O.S., (Mercury), 9, Pg Iii, D009, Crushed Lamps Containing Mercury For Recycling
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	183
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.0915
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.0915
Waste Quantity, in Kilograms:	82.99325
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	82.99325
Management Method Code:	H011
Management Method Description:	MERCURY RECOVERY

REXEL USA (Continued) **1000227732**

Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D009
Quantity Haz Kg:	82.99325
Quantity Haz Tons:	0.0915
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

NY MANIFEST:

EPA ID:	NYD000631903
Country:	USA
Name:	Buffalo Forge Co C/O Cedar Key Associate
Address:	505 DUKE RD
Address 2:	Not reported
City,State,Zip:	CHEEKTOWAGA, NY 14225-0000
Zip 4:	Not reported
Location Address 1:	505 DUKE RD
Location Address 2:	Not reported
Location City,State,Zip:	BUFFALO, NY 14225
Location Zip 4:	Not reported
Facility Status:	Not reported
Total Tanks:	Not reported
Code:	BP

Mailing:

Mailing Name:	Buffalo Forge Co C/O Cedar Key Associate
Mailing Contact:	Buffalo Forge Co C/O Cedar Key Associate
Mailing Address 1:	505 DUKE RD
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BUFFALO, NY 14225
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7168972900

Manifest Data:

Document ID:	NYA4129885
Manifest Status:	C - Completed copy
Trans1 State ID:	S62088NY
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	860310
Trans1 Recv Date:	860310
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860310

REXEL USA (Continued) **1000227732**

Part A Recv Date:	860317
Part B Recv Date:	860318
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	NYD043815703
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00880
Units:	Gallons (liquids only)
Number of Containers:	016
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100

Document ID:	LAA9134040
Manifest Status:	Not reported
Trans1 State ID:	750748NY
Year:	1990
Trans2 State ID:	Not reported
Generator Ship Date:	01/16/1990
Trans1 Recv Date:	01/16/1990
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/19/1990
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	NYD982792814
Trans2 EPA ID:	Not reported
TSDF ID 1:	LAD981057706
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported

REXEL USA (Continued) **1000227732**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	01374
Units:	Pounds
Number of Containers:	003
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	01.00
Document ID:	NYA4129920
Manifest Status:	C - Completed copy
Trans1 State ID:	R94983NY
Year:	1986
Trans2 State ID:	Not reported
Generator Ship Date:	860606
Trans1 Recv Date:	860606
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	860606
Part A Recv Date:	860613
Part B Recv Date:	860613
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	NYD043815703
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD043815703
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

REXEL USA (Continued) **1000227732**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00385
Units:	Gallons (liquids only)
Number of Containers:	007
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	100
Document ID:	NYA1252935
Manifest Status:	C - Completed copy
Trans1 State ID:	NY6250-RV
Year:	1985
Trans2 State ID:	Not reported
Generator Ship Date:	850627
Trans1 Recv Date:	850627
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	850627
Part A Recv Date:	850711
Part B Recv Date:	850709
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	NYD074026402
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980592653
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00550
Units:	Gallons (liquids only)
Number of Containers:	010
Container Type:	Metal drums, barrels, kegs
Handling Method:	Recycle
Specific Gravity:	100
Document ID:	NYB2403963
Manifest Status:	Not reported
Trans1 State ID:	10254P
Year:	1991
Trans2 State ID:	Not reported
Generator Ship Date:	09/07/1991
Trans1 Recv Date:	09/07/1991

REXEL USA (Continued) **1000227732**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/1991
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD067539940
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	B004
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	08325
Units:	Kilograms
Number of Containers:	001
Container Type:	Portable tanks
Handling Method:	Landfill
Specific Gravity:	01.00

Document ID:	MOA0814920
Manifest Status:	Not reported
Trans1 State ID:	H1144D111
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	08/14/1992
Trans1 Recv Date:	08/14/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID 1:	MOD980962849
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported

REXEL USA (Continued) **1000227732**

Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00440
Units:	Gallons (liquids only)
Number of Containers:	008
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

Document ID:	MOA1028920
Manifest Status:	Not reported
Trans1 State ID:	H1144
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	10/28/1992
Trans1 Recv Date:	10/28/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/30/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID 1:	MOD980962849
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat

REXEL USA (Continued) **1000227732**

Specific Gravity:	01.00
Waste Code 7:	Corrosive Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	MOB1028920
Manifest Status:	Not reported
Trans1 State ID:	H1144
Year:	1992
Trans2 State ID:	Not reported
Generator Ship Date:	10/28/1992
Trans1 Recv Date:	10/28/1992
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/30/1992
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	MOD095038998
Trans2 EPA ID:	Not reported
TSDF ID 1:	MOD980962849
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Corrosive Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00
Waste Code 7:	Ignitable Waste
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported

REXEL USA (Continued) **1000227732**

Waste Code 11:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 12:	Corrosive Waste
Waste Code 13:	Not reported
Waste Code 14:	Not reported
Waste Code 15:	Not reported
Waste Code 16:	Not reported
Quantity:	00055
Units:	Gallons (liquids only)
Number of Containers:	001
Container Type:	Metal drums, barrels, kegs
Handling Method:	Treat
Specific Gravity:	01.00

Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MID021087275
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2008
Trans1 Recv Date:	10/14/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	005058459JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Corrosive Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported

REXEL USA (Continued) **1000227732**

Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported
Manifest Status:	Not reported
Trans1 State ID:	MID021087275
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2008
Trans1 Recv Date:	10/14/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	005058459JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	3
Units:	Pounds
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1
Document ID:	Not reported

REXEL USA (Continued) **1000227732**

Manifest Status:	Not reported
Trans1 State ID:	MID021087275
Year:	2018
Trans2 State ID:	Not reported
Generator Ship Date:	10/14/2008
Trans1 Recv Date:	10/14/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/17/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000631903
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	005058459JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code a:	Ignitable Waste
Waste Code b:	Not reported
Waste Code c:	Not reported
Waste Code e:	Not reported
Waste Code f:	Not reported
Waste Code g:	Not reported
Waste Code 1:	Not reported
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	1
Units:	Gallons (liquids only)
Number of Containers:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Handling Method:	Landfill
Specific Gravity:	1

Click this hyperlink while viewing on your computer to access
12 additional NY MANIFEST: record(s) in the EDR Site Report.

R89 **BUFFALO FORGE CO. PLANT #2** **NY AST** **S108146531**
ESE **505 DUKE ROAD** **NY HSWDS** **N/A**
1/4-1/2 **CHEEKTOWAGA, NY 14225**
0.384 mi.
2030 ft. **Site 2 of 2 in cluster R**

Relative:
Lower

Actual:
651 ft.

AST:

Name:	ERS OPERATION WESTERN
Address:	505 DUKE RD.
City,State,Zip:	BUFFALO, NY 14225
Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-601925
Program Type:	PBS
UTM X:	Not reported
UTM Y:	Not reported
Expiration Date:	10/01/2025
Site Type:	Trucking/Transportation/Fleet Operation

Affiliation Records:

Site Id:	634920
Affiliation Type:	Facility Owner
Company Name:	CEDAR KEY ASSOCIATES, LP
Contact Type:	DIRECTOR OF SAFETY AND PROPERTY MGMT
Contact Name:	BRENT DAHLHAUS
Address1:	570 DELAWARE AVE.
Address2:	Not reported
City:	BUFFALO
State:	NY
Zip Code:	14202
Country Code:	001
Phone:	(716) 878-9626
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2022-03-30

Site Id:	634920
Affiliation Type:	Mail Contact
Company Name:	AAA WESTERN & CENTRAL NEW YORK
Contact Type:	Not reported
Contact Name:	BRENT DAHLHAUS
Address1:	100 INTERNATIONAL DR.
Address2:	Not reported
City:	WILLIMASVILLE
State:	NY
Zip Code:	14221
Country Code:	001
Phone:	(716) 630-3261
EMail:	SAFETY@NYAAA.COM
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2022-03-30

Site Id:	634920
Affiliation Type:	Facility Operator
Company Name:	ERS OPERATION WESTERN
Contact Type:	Not reported
Contact Name:	AAA WESTERN & CENTRAL NEW YORK

BUFFALO FORGE CO. PLANT #2 (Continued) **S108146531**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2022-03-30

Site Id:	634920
Affiliation Type:	Emergency Contact
Company Name:	CEDAR KEY ASSOCIATES, LP
Contact Type:	Not reported
Contact Name:	BRENT DAHLHAUS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(585) 764-5449
EMail:	Not reported
Fax Number:	Not reported
Modified By:	VMKREUTZ
Date Last Modified:	2022-03-30

Tank Info:

Tank Number:	DU-UO-01
Tank Id:	294855

Equipment Records:

L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
J00 - Dispenser - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/2010
Capacity Gallons:	266
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

BUFFALO FORGE CO. PLANT #2 (Continued) **S108146531**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

HSWDS:

Facility ID:	Not reported
Region:	9
Facility Status:	None
Owner Type:	Puplic
Owner:	Buffalo Forge Co.
Owner Address:	490 Broadway
Owner Phone:	(716)847-5718
Operator Type:	Same
Operator:	Unknown
Operator:	Unknown
Operator Phone:	Unknown
EPA ID:	NYD000631903
Registry:	Not on NYS Registry of Inactive Haz Waste Disposal Sites
Registry Site ID:	Unknown
RCRA Permitted:	Unknown
Site Code:	Industrial Site
Owner City State:	Buffalo
Operator City State:	Not reported
Quadrange:	Buffalo Southeast
Latitude:	42 54 15 N
Longitude:	78 45 40 W
Acres:	20.00
Operator Date:	1965
Close Date:	Unknown
Completed:	SIfd
Active:	Unknown
PCB's Disposed:	No
Pesticides Disposed:	No
Metals Disposed:	Yes
Asbestos Disposed:	No
Volatile Organic Compounds Disposed:	Yes
Semi Volatile Organic Compounds Disposed:	No
Analytical Info Exists for Air:	Not reported
Analytical Info Exists for Ground:	None
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Sediments:	Not reported
Analytical Info Exists for Surface:	Not reported
Analytical Info Exists for Substance:	Not reported
Analytical Info Exists for Waste:	Not reported
Analytical Info Exists for Leachate:	Not reported
Analytical Info Exists for EP Toxicity:	Not reported
Analytical Info Exists for TCLP:	Not reported
Threat to Environment/Public Health:	None
Surface Water Contamination:	No
Surface Water Body Class:	Unknown
Groundwater Contamination:	No
Groundwater Classification:	Unknown
Drinking Water Contamination:	No
Drinking Water Supply is Active:	Unknown
Any Known Fish or Wildlife:	No

BUFFALO FORGE CO. PLANT #2 (Continued) **S108146531**

Hazardous Exposure:	No
Site Has Controlled Acess:	Yes
Ambient Air Contamination:	No
Direct Contact:	Yes
EPA Hazardous Ranking System Score:	0
Inventory:	F
Nefrap:	Not reported
Mailing:	Not reported
Tax Map No:	Not reported
Qualify:	0
Next Action:	Not reported
Agencies:	Not reported
Air:	Not reported
Building:	Not reported
Site Desc:	Not reported
Drink:	Not reported
Eptox:	Not reported
Fish:	Not reported
Ground:	Not reported
Ground Desc:	Not reported
Hazardous Threat:	Not reported
Haz Threat Desc:	Not reported
Leachate:	Not reported
Preparer:	Not reported
Sediment:	Not reported
Soil:	Not reported
Surface:	Not reported
Status:	Not reported
Surface Soil:	Not reported
Surface:	Not reported
TCLP:	Not reported
Waste:	Not reported

90
WNW
1/4-1/2
0.406 mi.
2142 ft.

BASIL FORD INC
1540 WALDEN AVE
CHEEKTOWAGA, NY 14225

NY LTANKS **U003317407**
NY UST **N/A**
NY AST
NY Spills

Relative:
Higher

Actual:
672 ft.

LTANKS:

Name:	BASIL FORD
Address:	1540 WALDEN
City,State,Zip:	CHEEKTOWAGA, NY 14225
Spill Number/Closed Date:	1104332 / 2012-09-27
Facility ID:	1104332
Site ID:	451935
Spill Date:	2011-07-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	E6
Cleanup Ceased:	Not reported
SWIS:	1530
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	2011-07-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other

BASIL FORD INC (Continued) **U003317407**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2011-07-19
Spill Record Last Update:	2012-09-27
Spiller Name:	ROB SINGISER
Spiller Company:	BASIL FORD
Spiller Address:	1540 WALDEN AVENUE
Spiller County:	001
Spiller Contact:	BILL BOHN
Spiller Phone:	(716) 362-2984
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	406525
Latitude:	42.9068365
Longitude:	-78.7806847
DEC Memo:	07/19/11 RMC/FILE. REPAIR AND REPORTS WILL BE SUBMITTED. DUE 8/30/11. 09/22/11 RMC/FILE. DID NOT RECEIVE REPORT. CALLED JOHN GRAMZ. WAS A FAILURE OF A NYLON BUSHING THAT WAS REPAIRED. WILL CHECK ON REPORT. DUE 10/30/11. 02/01/12 RMC/FILE. NO REPORT RECEIVED. CHECKED PBS AND EDOCS NOTHING IN THOSE FILES EITHER. CONTACTED JOHN GRAMZ AND REQUESTED IT BE SENT DUE 2/21/12. 04/25/12 RMC/FILE. NO REPORT RECEIVED. CONTACTED JOHN GRAMZ AGAIN. REPAIRS WERE DONE AND TEST PASSED. DUE 5/7/12. 08/08/12 RMC/FILE. NO REPORT RECEIVED. LETTER. RESPONSE DUE 9/12/12 08/22/12 RMC/FILE. RECIEVED TIGHTNESS TEST RESULTS AFTER REPAIR. PASSED. CLOSE OUT. NO PAPER FILE.
Remarks:	Tank test failure 2k regular. Water in space. Tank and line tested good but water in space is failure. Bushing at the top will be replaced. Another test will be done after. Reports will be submitted.

UST:

Name:	BASIL FORD INC
Address:	1540 WALDEN AVE
City,State,Zip:	CHEEKTOWAGA, NY 14225
Id/Status:	9-383074 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	9
Expiration Date:	08/17/2027
UTM X:	191398.41898
UTM Y:	4757491.54642
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	53446
Affiliation Type:	Facility Owner
Company Name:	BASIL FORD INC
Contact Type:	OWNER
Contact Name:	CHARLES BASIL
Address1:	1540 WALDEN AVE
Address2:	Not reported
City:	CHEEKTOWAGA
State:	NY
Zip Code:	14225
Country Code:	001

BASIL FORD INC (Continued) **U003317407**

Phone:	(716) 893-1000
EMail:	JDECKER@BASILFORD.COM
Fax Number:	Not reported
Modified By:	IRKULAKO
Date Last Modified:	2024-10-11

Site Id:	53446
Affiliation Type:	Emergency Contact
Company Name:	BASIL FORD INC
Contact Type:	Not reported
Contact Name:	JAMIE DECKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 893-1000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AESKALSK
Date Last Modified:	2016-03-31

Site Id:	53446
Affiliation Type:	Mail Contact
Company Name:	BASIL FORD INC
Contact Type:	PARTS MANAGER
Contact Name:	JAMIE DECKER
Address1:	1540 WALDEN AVE
Address2:	Not reported
City:	CHEEKTOWAGA
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 893-1000
EMail:	JDECKER@BASILFORD.COM
Fax Number:	Not reported
Modified By:	IRKULAKO
Date Last Modified:	2024-01-23

Site Id:	53446
Affiliation Type:	Facility Operator
Company Name:	BASIL FORD INC
Contact Type:	Not reported
Contact Name:	RICARDO TORRES
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(716) 893-1000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	IRKULAKO
Date Last Modified:	2024-10-11

BASIL FORD INC (Continued) **U003317407**

Tank Info:

Tank Number:	02
Tank ID:	165175
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2000
Install Date:	11/01/1987
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

F05 - Pipe External Protection - Jacketed
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B04 - Tank External Protection - Fiberglass
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring

Tank Number:	1
Tank ID:	165174
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	Not reported
Date Tank Closed:	11/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

BASIL FORD INC (Continued) **U003317407**

Equipment Records:

H99 - Tank Leak Detection - Other
I00 - Overfill - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

AST:

Name:	BASIL FORD INC
Address:	1540 WALDEN AVE
City,State,Zip:	CHEEKTOWAGA, NY 14225
Region:	STATE
DEC Region:	9
Site Status:	Active
Facility Id:	9-383074
Program Type:	PBS
UTM X:	191398.41898
UTM Y:	4757491.54642
Expiration Date:	08/17/2027
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	53446
Affiliation Type:	Facility Owner
Company Name:	BASIL FORD INC
Contact Type:	OWNER
Contact Name:	CHARLES BASIL
Address1:	1540 WALDEN AVE
Address2:	Not reported
City:	CHEEKTOWAGA
State:	NY
Zip Code:	14225
Country Code:	001
Phone:	(716) 893-1000
EMail:	JDECKER@BASILFORD.COM
Fax Number:	Not reported
Modified By:	IRKULAKO
Date Last Modified:	2024-10-11

Site Id:	53446
Affiliation Type:	Emergency Contact
Company Name:	BASIL FORD INC
Contact Type:	Not reported
Contact Name:	JAMIE DECKER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(716) 893-1000
EMail:	Not reported
Fax Number:	Not reported

BASIL FORD INC (Continued) **U003317407**

Modified By: AESKALSK
Date Last Modified: 2016-03-31

Site Id: 53446
Affiliation Type: Mail Contact
Company Name: BASIL FORD INC
Contact Type: PARTS MANAGER
Contact Name: JAMIE DECKER
Address1: 1540 WALDEN AVE
Address2: Not reported
City: CHEEKTOWAGA
State: NY
Zip Code: 14225
Country Code: 001
Phone: (716) 893-1000
EMail: JDECKER@BASILFORD.COM
Fax Number: Not reported
Modified By: IRKULAKO
Date Last Modified: 2024-01-23

Site Id: 53446
Affiliation Type: Facility Operator
Company Name: BASIL FORD INC
Contact Type: Not reported
Contact Name: RICARDO TORRES
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (716) 893-1000
EMail: Not reported
Fax Number: Not reported
Modified By: IRKULAKO
Date Last Modified: 2024-10-11

Tank Info:

Tank Number: 01
Tank Id: 226146
Material Code: 0015
Common Name of Substance: Motor Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping

BASIL FORD INC (Continued) **U003317407**

F00 - Pipe External Protection - None
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/2004
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: motor oil

Tank Number: 03
Tank Id: 226147
Material Code: 2642
Common Name of Substance: Used Oil (Heating, On-Site Consumption)

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Plastic
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 10/01/1994
Capacity Gallons: 1100
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 10/07/2015
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: used oil (heating, on-site consumption)

Tank Number: 04
Tank Id: 226148
Material Code: 2642
Common Name of Substance: Used Oil (Heating, On-Site Consumption)

BASIL FORD INC (Continued) **U003317407**

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	10/01/1994
Capacity Gallons:	1100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/07/2015
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)
Tank Number:	05
Tank Id:	226149
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1994
Capacity Gallons:	275
Tightness Test Method:	NN

BASIL FORD INC (Continued) **U003317407**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil
Tank Number:	06
Tank Id:	226150
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1994
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/31/2013
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)
Tank Number:	07
Tank Id:	226151
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

BASIL FORD INC (Continued) **U003317407**

E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/1994
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/31/2013
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)

Tank Number:	08A
Tank Id:	226152
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/01/1994
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	VMKREUTZ
Last Modified:	08/03/2022
Material Name:	motor oil

BASIL FORD INC (Continued) **U003317407**

Tank Number: 08B
Tank Id: 226153
Material Code: 0015
Common Name of Substance: Motor Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/01/1994
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: VMKREUTZ
Last Modified: 08/03/2022
Material Name: motor oil

Tank Number: 10
Tank Id: 233791
Material Code: 2642
Common Name of Substance: Used Oil (Heating, On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron

BASIL FORD INC (Continued) **U003317407**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2008
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)

Tank Number:	11
Tank Id:	233792
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/2008
Capacity Gallons:	160
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/2014
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil

Tank Number:	12
Tank Id:	233793
Material Code:	0015
Common Name of Substance:	Motor Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)

BASIL FORD INC (Continued) **U003317407**

K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	11/01/2008
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	05/01/2014
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil
Tank Number:	13
Tank Id:	233794
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2008
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

BASIL FORD INC (Continued) **U003317407**

Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: used oil (heating, on-site consumption)

Tank Number: 14
Tank Id: 233795
Material Code: 0021
Common Name of Substance: Transmission Fluid

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/2004
Capacity Gallons: 275
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: transmission fluid

Tank Number: 15
Tank Id: 233796
Material Code: 0021
Common Name of Substance: Transmission Fluid

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None

BASIL FORD INC (Continued) **U003317407**

D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/2004
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/15/2021
Register:	True
Modified By:	VMKREUTZ
Last Modified:	08/03/2022
Material Name:	transmission fluid
Tank Number:	16
Tank Id:	255631

Equipment Records:

D10 - Pipe Type - Copper
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/31/2013
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)
Tank Number:	17
Tank Id:	260220

Equipment Records:

D10 - Pipe Type - Copper

BASIL FORD INC (Continued) **U003317407**

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J04 - Dispenser - On Site Heating System (Suction)
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/07/2015
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: used oil (heating, on-site consumption)

Tank Number: 18
Tank Id: 294870

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 03/15/2022
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022

BASIL FORD INC (Continued) **U003317407**

Material Name: motor oil

Tank Number: 19
Tank Id: 303445

Equipment Records:
J00 - Dispenser - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/08/2024
Capacity Gallons: 500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: IRKULAKO
Last Modified: 01/03/2025
Material Name: used oil (heating, on-site consumption)

Tank Number: 20
Tank Id: 303446

Equipment Records:
J00 - Dispenser - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 10/08/2024

BASIL FORD INC (Continued) **U003317407**

Capacity Gallons: 500
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: IRKULAKO
Last Modified: 01/03/2025
Material Name: used oil (heating, on-site consumption)

Tank Number: 21
Tank Id: 303442

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
D07 - Pipe Type - Plastic
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B05 - Tank External Protection - Jacketed

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/13/2024
Capacity Gallons: 400
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: IRKULAKO
Last Modified: 01/03/2025
Material Name: motor oil

Tank Number: 22
Tank Id: 303443

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
D07 - Pipe Type - Plastic
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
F00 - Pipe External Protection - None

BASIL FORD INC (Continued) **U003317407**

H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B05 - Tank External Protection - Jacketed

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 08/13/2024
Capacity Gallons: 400
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: IRKULAKO
Last Modified: 01/03/2025
Material Name: motor oil

Tank Number: 23
Tank Id: 303441

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
D07 - Pipe Type - Plastic
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B05 - Tank External Protection - Jacketed

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Plastic
Tank Status: In Service
Pipe Model: Not reported
Install Date: 09/13/2024
Capacity Gallons: 400
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: IRKULAKO
Last Modified: 01/03/2025
Material Name: motor oil

Tank Number: 24
Tank Id: 303444

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

BASIL FORD INC (Continued) **U003317407**

K00 - Spill Prevention - None
D07 - Pipe Type - Plastic
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
B05 - Tank External Protection - Jacketed

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Plastic
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/13/2024
Capacity Gallons:	400
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	IRKULAKO
Last Modified:	01/03/2025
Material Name:	transmission fluid

SPILLS:

Name:	BASIL FORD
Address:	1540 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9606988 / 1996-12-16
Facility ID:	9606988
Facility Type:	ER
DER Facility ID:	147271
Site ID:	175149
DEC Region:	9
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	1530
Spill Date:	1996-08-31
Investigator:	COOKE
Referred To:	Not reported
Reported to Dept:	1996-09-03
CID:	349
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1996-12-11
Cleanup Meets Std:	True
Last Inspection:	1996-09-03
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-09-03
Spill Record Last Update:	2002-03-29
Spiller Name:	JOE BASIL JR
Spiller Company:	BASIL FORD

BASIL FORD INC (Continued) **U003317407**

Spiller Address:	1540 WALDEN AVENUE
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9068947
Longitude:	-78.7800001
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 9/3/96: JDC ON SITE AND WAS UNABLE TO MET W/ ANY OFFICIAL REPRESENTATIVE, THEY WERE ALL IN MEETINGS. RECEIVED CALL FROM JOE bASIL AND DISCUSSED CLEANUP ACTIONS. NO FREE PRODUCT WAS DETECTED. THE POST WHEN REMOVED GAVE A STRONG PETROLEUM ODOR. GASOLINE TANK IS WITHIN 10 FEET OF THE POST AND IS A DOUBLEWALL FIBERGLASS. CLEANUP WORK SHOULD BEGIN NEXT WEEK, HE WILL NOTIFY WHEN WORK WILL START. 9/9/96: SENT LETTER OUTLINING CLEANUP REQUIREMENTS. 10/3/96: JDC TELCON W/ JOE BASIL, CONTAMINATED SOILS EXCAVATED, SOURCE SUSPECTED TO BE OLD SPILLAGE FROM FUEL DISPENSER. POST TEST REPORTEDLY SHOWS NO CONTAMINATION. 11/26/96: JDC LEFT MESSAGE FOR J. BASIL TO RETURN MY CALL. 12/16/96: JDC REVIEWD CLOSURE REPORT AND FOUND INFORMATION COMPLETE. 186 YRDS OF SOIL REMOVED AND DISPOSED OF. POST TEST ANALYSIS COMPLETE AND BELOW DETECTION. NO FURTHER ACTION REQUIRED, SENT CLOSURE LETTER.
Remarks:	removed post from ground near ust - when removing gasoline odor was noted

All Materials:

Site ID:	175149
Operable Unit ID:	1038121
Operable Unit:	01
Material ID:	346254
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	ADSORBANT FROM AUTO ACCID
Address:	1540 WALDEN AVENUE
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9806070 / 1998-09-12
Facility ID:	9806070
Facility Type:	ER
DER Facility ID:	147271
Site ID:	175150
DEC Region:	9
Spill Cause:	Traffic Accident
Spill Class:	D4
SWIS:	1530
Spill Date:	1998-08-15
Investigator:	SACALAND
Referred To:	Not reported

BASIL FORD INC (Continued) **U003317407**

Reported to Dept:	1998-08-15
CID:	365
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-15
Spill Record Last Update:	1998-09-17
Spiller Name:	Not reported
Spiller Company:	UNKNOWN AUTOMOBILES
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
Latitude:	42.9068947
Longitude:	-78.7800001
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 8/15/98: SAC TELECON RICH SWINIUCH - DUTY OFFICER, TRAFFIC ACCIDENT CAUSED SMALL SPILL, FIRE DEPT. PUT DOWN SPEEDY-DRI, REQUESTED WHAT TO DO WITH SPEEDY-DRI, DUE TO SMALL AMOUNT, WILL DISPOSE IN REGULAR WASTE STREAM.
Remarks:	CALLER STATED THEY DIDN'T WANT TO REPORT SPILL BUT THEY WANTED SOMEONE TO COME & CLEAN UP THE SPEEDI-DRY - THERE MUST HAVE BEEN AN ACCIDENT - NO FURTHER INFO

All Materials:

Site ID:	175150
Operable Unit ID:	1067248
Operable Unit:	01
Material ID:	317242
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

91 **KENNEDY INDUSTRIAL PARK** **NY LTANKS** **1000555876**
SSW **575 KENNEDY RD** **RCRA NonGen / NLR** **NYD986984235**
1/4-1/2 **CHEEKTOWAGA, NY 14227** **NY MANIFEST**
0.435 mi.
2298 ft.

Relative:
Lower

Actual:
628 ft.

LTANKS:

Name:	KENNEDY INDUSTRIAL PARK
Address:	575 KENNEDY ROAD
City,State,Zip:	CHEEKTOWAGA, NY
Spill Number/Closed Date:	9407179 / 1994-12-19
Facility ID:	9407179
Site ID:	78080

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

Spill Date:	1994-08-25
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-12-19
SWIS:	1530
Investigator:	RMCROSSE
Referred To:	Not reported
Reported to Dept:	1994-08-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1994-08-29
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-08-29
Spill Record Last Update:	1994-12-22
Spiller Name:	Not reported
Spiller Company:	KENNEDY INDUSTRIAL PARK
Spiller Address:	575 KENNEDY ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	9
DER Facility ID:	72705
Latitude:	42.8988321
Longitude:	-78.7760410
DEC Memo:	Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 08/29/94: RMC/SITE HOLE OPEN, NO VISUAL CONTAMINATION LEFT, REMOVED ABOUT 25 YARDS SOIL, TESTING AND DISPOSAL DUE 10/30/94. 09/30/94: RMC/RECEIVED CLOSURE REPORT, QUESTION ON SOIL EXCAVATED, GREEN TO SAMPLE EXCAVATED SOIL WHICH WAS PUT BACK INTO HOLE., RESULTS DUE 11/30/94. 10/18/94: RMC/RECEIVED ADDITIONAL SAMPLE RESULTS, NO EXCEEDANCES, DISPOSAL LETTER, RESPONSE DUE 11/14/94. 12/12/94: RMC/RECEIVED ADDITIONAL SAMPLE RESULTS, NO EXCEEDANCES, DISPOSAL LETTER, RESPONSE DUE 11/14/94REVISED TO 12/30/94. 12/19/94: RMC/RECEIVED DISPOSAL RECEIPTS, OK, SPILL COMPLETE, CLOSE OUT.
Remarks:	FOUND 500 GALLON TANK WHILE EXCAVATING FOR BUILDING

All Materials:

Site ID:	78080
Operable Unit ID:	1004616
Operable Unit:	01
Material ID:	380195
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

RCRA Listings:

Date Form Received by Agency:		20070101
Handler Name:		Kennedy Industrial Park
Handler Address:		Kennedy Rd
Handler City,State,Zip:		CHEEKTOWAGA, NY 14227
EPA ID:		NYD986984235
Contact Name:		Not reported
Contact Address:		KENNEDY RD
Contact City,State,Zip:		CHEEKTOWAGA, NY 14227
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		02
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Ny
State District:		NYSDEC R9
Mailing Address:		KENNEDY RD
Mailing City,State,Zip:		CHEEKTOWAGA, NY 14227
Owner Name:	Broadway Warehouse Co	
Owner Type:		Private
Operator Name:	Broadway Warehouse Co	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
202 GPRA Corrective Action Baseline:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BROADWAY WAREHOUSE CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	575 KENNEDY RD
Owner/Operator City,State,Zip:	CHEEKTOWAGA, NY 14227
Owner/Operator Telephone:	716-897-1606
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	BROADWAY WAREHOUSE CO

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 575 KENNEDY RD
Owner/Operator City,State,Zip: CHEEKTOWAGA, NY 14227
Owner/Operator Telephone: 716-897-1606
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BROADWAY WAREHOUSE CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 575 KENNEDY RD
Owner/Operator City,State,Zip: CHEEKTOWAGA, NY 14227
Owner/Operator Telephone: 716-897-1606
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: KENNEDY INDUSTRIAL PARK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: KENNEDY INDUSTRIAL PARK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: KENNEDY INDUSTRIAL PARK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19941014
Handler Name: KENNEDY INDUSTRIAL PARK
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
EPA ID: NYD986984235
Country: USA
Name: Car Gen Company
Address: 575 KENNEDY RD
Address 2: Not reported
City,State,Zip: CHEEKTOWAGA, NY 14227
Zip 4: Not reported
Location Address 1: 575 KENNEDY ROAD
Location Address 2: Not reported
Location City,State,Zip: BUFFALO, NY 14227
Location Zip 4: Not reported
Facility Status: Not reported
Total Tanks: Not reported
Code: BP

Mailing:
Mailing Name: Car Gen Company
Mailing Contact: Edward Mrozinski
Mailing Address 1: 575 KENNEDY DRIVE
Mailing Address 2: Not reported
Mailing City,State,Zip: BUFFALO, NY 14227
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 0000000000

Manifest Data:

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

Document ID:	NJA1965963
Manifest Status:	Not reported
Trans1 State ID:	NY44126AB
Year:	1994
Trans2 State ID:	08690
Generator Ship Date:	11/29/1994
Trans1 Recv Date:	11/29/1994
Trans2 Recv Date:	12/01/1994
TSD Site Recv Date:	12/02/1994
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986984235
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	ILD984908202
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	02465
Units:	Pounds
Number of Containers:	005
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00
Waste Code 7:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code 8:	Not reported
Waste Code:	Not reported
Waste Code 10:	Not reported
Waste Code 11:	Not reported

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

Quantity: 04930
Units: Pounds
Number of Containers: 010
Container Type: Fiberboard or plastic drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: MIA2363627
Manifest Status: Not reported
Trans1 State ID: E37435ME
Year: 1992
Trans2 State ID: Not reported
Generator Ship Date: 12/31/1991
Trans1 Recv Date: 12/31/1991
Trans2 Recv Date: 01/02/1992
TSD Site Recv Date: 01/02/1992
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD986984235
Trans1 EPA ID: NYD097644801
Trans2 EPA ID: MID980684088
TSDF ID 1: MID980615298
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code 1: Ignitable Waste
Waste Code 2: Not reported
Waste Code 3: Not reported
Waste Code 4: Not reported
Waste Code 5: Not reported
Waste Code 6: Not reported
Quantity: 00110
Units: Gallons (liquids only)
Number of Containers: 002
Container Type: Metal drums, barrels, kegs
Handling Method: Burn
Specific Gravity: 01.00

Document ID: MIA2363627
Manifest Status: Not reported
Trans1 State ID: E37435ME
Year: 1991
Trans2 State ID: Not reported
Generator Ship Date: 12/31/1991
Trans1 Recv Date: 12/31/1991
Trans2 Recv Date: 01/02/1992
TSD Site Recv Date: 01/02/1992

KENNEDY INDUSTRIAL PARK (Continued) **1000555876**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986984235
Trans1 EPA ID:	NYD097644801
Trans2 EPA ID:	MID980684088
TSDF ID 1:	MID980615298
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code 1:	Ignitable Waste
Waste Code 2:	Not reported
Waste Code 3:	Not reported
Waste Code 4:	Not reported
Waste Code 5:	Not reported
Waste Code 6:	Not reported
Quantity:	00110
Units:	Gallons (liquids only)
Number of Containers:	002
Container Type:	Metal drums, barrels, kegs
Handling Method:	Burn
Specific Gravity:	01.00

92
NNE
1/4-1/2
0.490 mi.
2588 ft.

NYS THRUWAY AUTHORITY LANDFILL **NY SWF/LF** **S126309072**
WALDEN AVE THRUWAY RAMP (NEAR WALDEN AVE EXIT 52) **NY ILI** **N/A**
CHEEKTOWAGA, NY

Relative:
Higher

Actual:
660 ft.

SWF/LF:

Name:	NYS THRUWAY AUTHORITY LANDFILL
Address:	WALDEN AVE THRUWAY RAMP (NEAR WALDEN AVE EXIT 52)
City,State,Zip:	CHEEKTOWAGA, NY
Flag:	INACTIVE
Region Code:	9
Phone Number:	Not reported
Owner Name:	NYS Thruway Authority
Owner Type:	Not reported
Owner Address:	455 Cayuga Road, Suite 800
Owner Addr2:	Not reported
Owner City,St,Zip:	Cheektowaga, NY 14225
Owner Email:	Not reported
Owner Phone:	716-896-9312
Contact Name:	Tom Moore
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported

NYS THRUWAY AUTHORITY LANDFILL (Continued) **S126309072**

Contact Phone:	716-635-6291 (office) and 716-982-7450 (cell)
Activity Desc:	MSW, dumping of litter, road sweepings, cans, tires, car parts, wood, dirt, cardboard, roadside trash, empty paint drums
Activity Number:	Not reported
Active:	Not reported
East Coordinate:	Not reported
North Coordinate:	Not reported
Accuracy Code:	2: Fair; Perimeter unclear
Regulatory Status:	no permit applied for or granted as of 1973
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

ILI:

Name:	NYS THRUWAY AUTHORITY LANDFILL
Address:	Walden Ave Thruway Ramp (Near Walden Ave Exit 52)
City,State,Zip:	CHEEKTOWAGA, NY
Latitude:	42.911759
Longitude:	-78.767283
Landfill Type:	NYSDEC Inactive Landfill Initiative Solid Waste Site Investigation Priority List
Region:	9
Rank Score:	36
Site Specific Recommendations:	Initiate Investigation in 2027

Count: 5 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BUFFALO	S105842493	BROADWAY GARAGE	BROADWAY ROAD	0	NY SWF/LF
CHEEKTOWAGA	S113916922	NYS THRUWAY EXIT 52	EXIT 52 (WALDEN AVE) INTERCHAN		NY SHWS
CHEEKTOWAGA	1003863686	NYS THRUWAY EXIT DMP	EXIT 52 N.Y. THRUWAY	14225	SEMS-ARCHIVE
CHEEKTOWAGA	S106905194	PYRAMID COMPANY	NORTH OF WALDEN AVE., WEST OF		NY SHWS
CHEEKTOWAGA	S105842002	CTS CRUSHING & RECYCLING	THRUWAY MALL	14227	NY SWF/LF

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/05/2025
Date Data Arrived at EDR: 06/20/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 03/11/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 07/29/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/19/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/02/2024
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/19/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/10/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 06/04/2025
Date Data Arrived at EDR: 08/12/2025
Date Made Active in Reports: 09/15/2025
Number of Days to Update: 34

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 08/03/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/05/2025
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/04/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 04/23/2025
Date Made Active in Reports: 04/24/2025
Number of Days to Update: 1

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 06/16/2025
Date Data Arrived at EDR: 06/16/2025
Date Made Active in Reports: 09/12/2025
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/16/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 06/16/2025
Date Data Arrived at EDR: 06/16/2025
Date Made Active in Reports: 09/12/2025
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/16/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 06/16/2025
Date Data Arrived at EDR: 06/16/2025
Date Made Active in Reports: 09/12/2025
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/16/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 06/16/2025
Date Data Arrived at EDR: 06/16/2025
Date Made Active in Reports: 09/12/2025
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/16/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/15/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/08/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/18/2024
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 01/07/2025
Date Data Arrived at EDR: 01/16/2025
Date Made Active in Reports: 04/07/2025
Number of Days to Update: 81

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 06/16/2025
Date Data Arrived at EDR: 06/16/2025
Date Made Active in Reports: 09/12/2025
Number of Days to Update: 88

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 09/16/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 06/11/2025
Date Made Active in Reports: 09/09/2025
Number of Days to Update: 90

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 06/10/2025
Date Made Active in Reports: 09/08/2025
Number of Days to Update: 90

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/09/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 06/01/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 84

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 09/03/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/09/2024
Date Data Arrived at EDR: 09/11/2024
Date Made Active in Reports: 12/06/2024
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 06/04/2025
Date Data Arrived at EDR: 06/18/2025
Date Made Active in Reports: 09/15/2025
Number of Days to Update: 89

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 09/02/2025
Number of Days to Update: 90

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/15/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/08/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 04/25/2025
Date Data Arrived at EDR: 04/25/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 74

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 07/28/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/11/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 08/03/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/05/2025
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 08/04/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 07/23/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 6

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 07/23/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/07/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 06/25/2025
Next Scheduled EDR Contact: 10/13/2025
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/11/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 7

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/14/2025
Date Data Arrived at EDR: 04/15/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 84

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/14/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/29/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 8

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/05/2025
Date Data Arrived at EDR: 04/11/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/09/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 28

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2024
Date Data Arrived at EDR: 10/02/2024
Date Made Active in Reports: 01/10/2025
Number of Days to Update: 100

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 09/30/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 27
Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 07/08/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 08/28/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 09/17/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 04/22/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 86
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2025
Date Data Arrived at EDR: 05/02/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 76
Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/13/2026
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16
Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 09/29/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/28/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 05/15/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 75

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/01/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/18/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 07/01/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 09/24/2025
Number of Days to Update: 85

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 84

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 05/28/2025
Date Data Arrived at EDR: 05/28/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 6
Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/09/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Quarterly

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88
Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

FINDS: Facility Index System/Facility Registry System
Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/22/2025
Date Data Arrived at EDR: 05/05/2025
Date Made Active in Reports: 05/21/2025
Number of Days to Update: 16
Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing
A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82
Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/12/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites
A listing of unexploded ordnance site locations

Date of Government Version: 02/14/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 84
Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 06/22/2025
Date Data Arrived at EDR: 06/25/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 63
Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/13/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 77

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 09/24/2025
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 05/15/2024
Date Data Arrived at EDR: 03/06/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 89

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: No Update Planned

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 04/13/2025
Date Data Arrived at EDR: 04/15/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Varies

UST FINDER: UST Finder Database

EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database

US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

E MANIFEST: Hazardous Waste Electronic Manifest System

EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 08/13/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 12/12/2022
Date Data Arrived at EDR: 08/10/2023
Date Made Active in Reports: 10/25/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

A list of records included in the Environmental Remediation database whose material is listed as Perfluorooctanoic Acid or Perfluorooctane Sulfonic Acid.

Date of Government Version: 04/30/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/23/2025
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 08/05/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 04/10/2025
Date Data Arrived at EDR: 04/17/2025
Date Made Active in Reports: 07/08/2025
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/09/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 06/17/2025
Date Data Arrived at EDR: 06/18/2025
Date Made Active in Reports: 09/12/2025
Number of Days to Update: 86

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 09/17/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 06/03/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 05/28/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 05/30/2025
Date Data Arrived at EDR: 06/10/2025
Date Made Active in Reports: 09/08/2025
Number of Days to Update: 90

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Semi-Annually

FIN ASSURANCE 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 06/09/2025
Date Data Arrived at EDR: 06/18/2025
Date Made Active in Reports: 09/12/2025
Number of Days to Update: 86

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 09/17/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

FIN ASSURANCE 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/03/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 04/16/2025
Date Data Arrived at EDR: 04/29/2025
Date Made Active in Reports: 07/18/2025
Number of Days to Update: 80

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 04/28/2025
Date Data Arrived at EDR: 04/29/2025
Date Made Active in Reports: 07/21/2025
Number of Days to Update: 83

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 07/24/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/17/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/09/2025
Date Data Arrived at EDR: 07/15/2025
Date Made Active in Reports: 07/30/2025
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/09/2025
Next Scheduled EDR Contact: 10/27/2025
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 05/26/2025
Date Data Arrived at EDR: 05/27/2025
Date Made Active in Reports: 08/21/2025
Number of Days to Update: 86

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 07/01/2025
Date Data Arrived at EDR: 07/07/2025
Date Made Active in Reports: 09/26/2025
Number of Days to Update: 81

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/07/2025
Next Scheduled EDR Contact: 10/20/2025
Data Release Frequency: Varies

ILI: New York State Inactive Landfill Initiative

A solid waste site priority list of mitigation and remedial activities to address sites causing, or substantially contributing to, impairments of drinking water quality. Inactive solid waste disposal sites, primarily landfills, and their potential impact on New York?s drinking water resources from site-related contaminants, with a focus on emerging contaminants.

Date of Government Version: 07/01/2025
Date Data Arrived at EDR: 07/29/2025
Date Made Active in Reports: 08/13/2025
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8671
Last EDR Contact: 07/22/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

NYC OER: OER Cleanup Sites Listing

Properties remediated under OER's oversight, both in the E-Designation program and the NYC Voluntary Cleanup Program. Includes sites completed and in progress.

Date of Government Version: 06/01/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/25/2025
Number of Days to Update: 84

Source: Office of Environmental Remediation
Telephone: 212-788-8841
Last EDR Contact: 09/03/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

NYC LAND USE: New York City Land Use Information

Land use colors

Date of Government Version: 02/21/2025
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 05/28/2025
Number of Days to Update: 78

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/08/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Varies

MGP: Manufactured Gas Plants Listing

From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel for heating, cooking, and lighting. Today, the New York State DEC is overseeing the investigation and cleanup of contamination left behind from these plants.

Date of Government Version: 08/27/2025
Date Data Arrived at EDR: 08/27/2025
Date Made Active in Reports: 09/17/2025
Number of Days to Update: 21

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 11/27/2023
Date Data Arrived at EDR: 11/28/2023
Date Made Active in Reports: 02/06/2024
Number of Days to Update: 70

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/19/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 08/19/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database
This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 03/28/2025
Date Data Arrived at EDR: 05/08/2025
Date Made Active in Reports: 07/24/2025
Number of Days to Update: 77

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 03/28/2025
Date Data Arrived at EDR: 05/08/2025
Date Made Active in Reports: 07/24/2025
Number of Days to Update: 77

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 07/16/2025
Next Scheduled EDR Contact: 11/03/2025
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/04/2025
Date Data Arrived at EDR: 05/06/2025
Date Made Active in Reports: 07/21/2025
Number of Days to Update: 76

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/06/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

COMMERCIAL PROPERTY
24 ANDERSON ROAD
BUFFALO, NY 14225

TARGET PROPERTY COORDINATES

Latitude (North):	42.905232 - 42° 54' 18.84''
Longitude (West):	78.772249 - 78° 46' 20.10''
Universal Tranverse Mercator:	Zone 17
UTM X (Meters):	681867.7
UTM Y (Meters):	4752484.0
Elevation:	656 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14122104 BUFFALO NE, NY
Version Date:	2019
Northeast Map:	14122160 LANCASTER, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3602310005E	FEMA Q3 Flood data

Additional Panels in search area:	FEMA Source Type
NO PANEL ID	FEMA Q3 Flood data
3602310010F	FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
BUFFALO NE	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Devonian
Series:	Middle Devonian
Code:	D2 *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 8127688.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Commercial Property	CLIENT:	Farmer Environmental Group
ADDRESS:	24 Anderson Road Buffalo NY 14225	CONTACT:	Roy David King
		INQUIRY #:	8127688.2s
LAT/LONG:	42.905232 / 78.772249	DATE:	October 02, 2025 9:34 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Cazenovia

Soil Surface Texture: silt loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 92 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	11 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 6.6
2	11 inches	31 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 6.6
3	31 inches	59 inches	gravelly silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 6.6

Soil Map ID: 3

Soil Component Name: Ovid

Soil Surface Texture: silt loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 38 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	9 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand.	Max: 1.4 Min: 0.42	Max: 8.4 Min: 7.4
2	9 inches	20 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand.	Max: 1.4 Min: 0.42	Max: 8.4 Min: 7.4
3	20 inches	59 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand.	Max: 1.4 Min: 0.42	Max: 8.4 Min: 7.4

Soil Map ID: 4

Soil Component Name: Odessa

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 31 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	9 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 7.4
2	9 inches	22 inches	silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 7.4
3	22 inches	59 inches	silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 1.4 Min: 0.42	Max: 8.4 Min: 7.4

Soil Map ID: 5

Soil Component Name: Lakemont

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 7 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	9 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0 Min: 0	Max: 8.4 Min: 7.4
2	9 inches	29 inches	silty clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0 Min: 0	Max: 8.4 Min: 7.4
3	29 inches	59 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0 Min: 0	Max: 8.4 Min: 7.4

Soil Map ID: 6

Soil Component Name: Urban

Soil Surface Texture: silt loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 31 inches

No Layer Information available.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000864980	1/4 - 1/2 Mile ESE
2	USGS40000864911	1/4 - 1/2 Mile SE
3	USGS40000865124	1/4 - 1/2 Mile ENE
4	USGS40000865239	1/2 - 1 Mile NNE
5	USGS40000865096	1/2 - 1 Mile WNW
6	USGS40000864890	1/2 - 1 Mile WSW
7	USGS40000864786	1/2 - 1 Mile SSE
8	USGS40000865286	1/2 - 1 Mile NNE
9	USGS40000864713	1/2 - 1 Mile SSE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG20000036572	1/4 - 1/2 Mile NW
2	NYOG20000036694	1/2 - 1 Mile South

PHYSICAL SETTING SOURCE MAP - 8127688.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Commercial Property	CLIENT:	Farmer Environmental Group
ADDRESS:	24 Anderson Road Buffalo NY 14225	CONTACT:	Roy David King
		INQUIRY #:	8127688.2s
LAT/LONG:	42.905232 / 78.772249	DATE:	October 02, 2025 9:34 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
ESE **FED USGS** **USGS40000864980**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 310		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-30	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

2
SE **FED USGS** **USGS40000864911**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 306		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-29	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

3
ENE **FED USGS** **USGS40000865124**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 324		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-31	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

4
NNE
1/2 - 1 Mile
Lower

FED USGS **USGS40000865239**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 330		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-34	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

5
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000865096**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 321		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-33	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

6
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000864890**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 304		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-32	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

7
SSE **FED USGS** **USGS40000864786**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 296		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-28	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

8
NNE **FED USGS** **USGS40000865286**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 333		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-35	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

9
SSE **FED USGS** **USGS40000864713**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	E 291		
Type:	Well: Test hole not completed as a well		
Description:	Niagara Project: BNE-27	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
NW
1/4 - 1/2 Mile

OIL_GAS **NYOG20000036572**

OIL_GAS:

API #:	31029105480000	Well Name:	Ellicott Drug Co. 1
Well Type:	Gas Development	Well Status:	Plugged and Abandoned
Owner:	Bryant Woods North Assoc. LLC	Operator:	1896
Permit Date:	Not Reported	SPUD Date:	Not Reported
Completion Date:	31-AUG-74	Plug Date:	Not Reported
Field Name:	Buffalo	Formation:	Medina
Borehole Slant:	Vertical	True Depth (ft):	1048
Measured Length (ft):	1048		
URL:	http://extapps.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31029105480000		

2
South
1/2 - 1 Mile

OIL_GAS **NYOG20000036694**

OIL_GAS:

API #:	31029131110000	Well Name:	Fee 2
Well Type:	Dry Hole	Well Status:	Plugged and Abandoned
Owner:	Amer. Standard/Heat Trans.Div.	Operator:	394
Permit Date:	Not Reported	SPUD Date:	Not Reported
Completion Date:	03-FEB-78	Plug Date:	Not Reported
Field Name:	West Seneca	Formation:	Medina
Borehole Slant:	Vertical	True Depth (ft):	1248
Measured Length (ft):	1248		
URL:	http://extapps.dec.ny.gov/cfmx/extapps/GasOil/search/wells/index.cfm?api=31029131110000		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
ERIE	ALDEN	123	5.69	1.93	185.3
ERIE	AMHERST	864	2.57	1.15	115.6
ERIE	AURORA	436	10.94	4.46	215.6
ERIE	BOSTON	101	9.51	4.47	49.9
ERIE	BRANT	9	12.9	4.13	78.7
ERIE	BUFFALO	936	1.18	0.62	63.2
ERIE	CHEEKTOWAGA	444	1.03	0.71	30.8
ERIE	CLARENCE	244	6.79	2.37	207.8
ERIE	COLDEN	45	5.4	3.44	38
ERIE	COLLINS	48	11.83	4.76	115.1
ERIE	CONCORD	180	15.75	7.87	163
ERIE	EDEN	163	6.74	3.33	206.7
ERIE	ELMA	282	8.17	3.15	213.6
ERIE	EVANS	121	5.77	2.92	92.3
ERIE	GRAND ISLAND	85	1.41	1.03	7.5
ERIE	HAMBURG	753	4.9	2.2	136.8
ERIE	HOLLAND	55	8.09	3.57	122.9
ERIE	KENMORE	146	0.75	0.56	4.8
ERIE	LACKAWANNA	42	1.45	0.83	11.4
ERIE	LANCASTER	177	2.76	1.17	155.1
ERIE	MARILLA	239	28.88	9.31	371.9
ERIE	NEWSTEAD	88	3.44	2.35	18
ERIE	NO. COLLINS	28	7.97	3.88	75.6
ERIE	ORCHARD PARK	490	4.8	2.37	116.9
ERIE	SARDINIA	25	22.28	8.33	121.2
ERIE	TONAWANDA	392	1.04	0.72	18.9
ERIE	W. SENECA	266	2.51	1.35	55.8
ERIE	WALES	44	11.97	4.35	181.7

Federal EPA Radon Zone for ERIE County: 1

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for ERIE COUNTY, NY

Number of sites tested: 622

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	1.000 pCi/L	89%	11%	0%
Basement	1.150 pCi/L	87%	11%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Commercial Property
24 Anderson Road
Buffalo, NY 14225

Inquiry Number: 8127688.2s
October 24, 2025

EDR Vapor Encroachment Screen

Prepared using EDR's Vapor Encroachment Worksheet

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	**ES1**
Primary Map	**2**
Secondary Map	**3**
Map Findings	**4**
Record Sources and Currency	**GR-1**

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

The EDR Vapor Encroachment Worksheet enables EDR's customers to make certain online modifications that effects maps, text and calculations contained in this Report. As a result, maps, text and calculations contained in this Report may have been so modified. EDR has not taken any action to verify any such modifications, and this report and the findings set forth herein must be read in light of this fact. Environmental Data Resources shall not be responsible for any customer's decision to include or not include in any final report any records determined to be within the relevant minimum search distances.

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by EDR. The report was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property Involved in Real Estate Transactions (E 2600).

STANDARD ENVIRONMENTAL RECORDS	Default Area of Concern (Miles)*	property	1/10	> 1/10
Lists of Federal NPL (Superfund) sites	1.0	0	0	0
Lists of Federal Delisted NPL sites	1.0	0	0	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders	0.5	0	0	0
Lists of Federal CERCLA sites with NFRAP	0.5	0	1	0
Lists of Federal RCRA facilities undergoing Corrective Action	1.0	0	0	0
Lists of Federal RCRA TSD facilities	0.5	0	0	0
Lists of Federal RCRA generators	0.25	0	2	1
Federal institutional controls / engineering controls registries	0.5	0	0	0
Federal ERNS list	0.001	0	0	-
Lists of state- and tribal (Superfund) equivalent sites	not searched	-	-	-
Lists of state- and tribal hazardous waste facilities	1.0	0	1	0
Lists of state and tribal landfills and solid waste disposal facilities	0.5	0	0	0
Lists of state and tribal leaking storage tanks	0.5	0	2	2
Lists of state and tribal registered storage tanks	0.5	0	2	1
State and tribal institutional control / engineering control registries	0.5	0	1	0
Lists of state and tribal voluntary cleanup sites	0.5	0	1	0
Lists of state and tribal brownfield sites	0.5	0	0	0

ADDITIONAL ENVIRONMENTAL RECORDS				
Local Brownfield lists	0.5	0	0	0
Local Lists of Landfill / Solid Waste Disposal Sites	0.5	0	0	0
Local Lists of Hazardous waste / Contaminated Sites	1.0	0	0	0
Local Lists of Registered Storage Tanks	0.25	0	0	0
Local Land Records	0.001	0	0	-
Records of Emergency Release Reports	0.125	1	3	2
Other Ascertainable Records	1.0	0	13	6

EDR HIGH RISK HISTORICAL RECORDS				
EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	0.001	0	0	-

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	0.001	0	0	-

*The Default Area of Concern may be adjusted by the environmental professional using experience and professional judgement. Each category may include several databases, and each database may have a different distance. A list of individual databases is provided at the back of this report.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

COMMERCIAL PROPERTY
24 ANDERSON ROAD
BUFFALO, NY 14225

COORDINATES

Latitude (North):	42.905232 - 42° 54′ 18.833313″
Longitude (West):	78.772249 - 78° 46′ 20.090332″
Elevation:	656 ft. above sea level

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records.

Site	Database(s)
NANCY O'NEIL AUTO FIRE 24 ANDERSON ROAD CHEEKTOWAGA, NY	NY Spills Spill Number/Closed Date: 8607251 / 1987-02-27 Spill Date: 1987-02-27 Site ID: 133126

EXECUTIVE SUMMARY

SEARCH RESULTS

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
ROCO, LTD. VCP: VCP ENG CONTROLS: ENG CONTROLS SHWS: SHWS NY Spills: SPILLS MANIFEST: NY MANIFEST INST CONTROL: INST CONTROL	1746 DALE ROAD	<1/10 S	▲ A3	11
ROTARY CO INC FINDS: FINDS SEMS-ARCHIVE: SEMS-ARCHIVE RCRA NonGen / NLR: RCRA NonGen / NLR ECHO: ECHO	1746 DALE RD	<1/10 S	▲ A4	11
DIMAR MANUFACTURING RCRA-SQG: RCRA-SQG E MANIFEST: E MANIFEST MANIFEST: NY MANIFEST	40 ANDERSON RD	<1/10 N	◆ A8	12
UPSTATE FARM COOPERATIVE, INC. SPDES: SPDES NY Spills: SPILLS CBS AST: CBS AST LTANKS: LTANKS	1730 DALE RD.	<1/10 NW	▲ D13	13
UPSTATE NIAGARA E MANIFEST: E MANIFEST RCRA-VSQG: RCRA-VSQG CBS: CBS LTANKS: LTANKS MANIFEST: NY MANIFEST AST: AST	1730 DALE RD	<1/10 NW	▲ D14	13
RYDER TRUCK RENTAL INC. NY Spills: SPILLS LTANKS: LTANKS	107 ANDERSON ROAD	1/10 - 1/3 NNE	◆ J18	14
ASPEN DENTAL ECHO: ECHO FINDS: FINDS E MANIFEST: E MANIFEST RCRA-VSQG: RCRA-VSQG UST: UST MANIFEST: NY MANIFEST AST: AST	1717 WALDEN AVE	1/10 - 1/3 NNW	◆ K21	15
BUFFALO SPRING NY Spills: SPILLS LTANKS: LTANKS	1765 WALDEN AVENUE	1/10 - 1/3 NNE	◆ M23	15

ADDITIONAL ENVIRONMENTAL RECORDS

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
NANCY O'NEIL AUTO FIRE NY Spills: SPILLS	24 ANDERSON ROAD	Property	▲ A1	11
ROTARY COMPANY HSWDS: HSWDS	1746 DALE ROAD	<1/10 S	▲ A2	11
ROCO, LTD. VCP: VCP ENG CONTROLS: ENG CONTROLS SHWS: SHWS NY Spills: SPILLS MANIFEST: NY MANIFEST INST CONTROL: INST CONTROL	1746 DALE ROAD	<1/10 S	▲ A3	11
ROTARY CO INC FINDS: FINDS SEMS-ARCHIVE: SEMS-ARCHIVE RCRA NonGen / NLR: RCRA NonGen / NLR ECHO: ECHO	1746 DALE RD	<1/10 S	▲ A4	11
ACTS TESTING LABS INC FINDS: FINDS RCRA NonGen / NLR: RCRA NonGen / NLR ECHO: ECHO MANIFEST: NY MANIFEST	25 ANDERSON RD	<1/10 E	◆ B5	12
UPSTATE FARMS COOPERATIVE INC RCRA NonGen / NLR: RCRA NonGen / NLR ECHO: ECHO FINDS: FINDS	25 ANDERSON RD	<1/10 E	◆ B6	12
BUILDING ADDITION EXCAVATION NY Spills: SPILLS	25 ANDERSON ROAD	<1/10 E	◆ B7	12
DIMAR MANUFACTURING RCRA-SQG: RCRA-SQG E MANIFEST: E MANIFEST MANIFEST: NY MANIFEST	40 ANDERSON RD	<1/10 N	◆ A8	12
DIMAR MANUFACTURING PFAS ECHO: PFAS ECHO	40 ANDERSON RD	<1/10 N	◆ A9	12
SECO CORP RAATS: RAATS RCRA NonGen / NLR: RCRA NonGen / NLR FINDS: FINDS ECHO: ECHO MANIFEST: NY MANIFEST	40 ANDERSON ROAD	<1/10 N	◆ A10	13
UPSTATE NIAGARA COOPERATIVES INC UST FINDER: UST FINDER	1730 DALE RD	<1/10 NW	▲ D11	13
UPSTATE MILK UST FINDER RELEASE: UST FINDER RELEASE	1730 DALE STREET	<1/10 NW	▲ D12	13

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
UPSTATE FARM COOPERATIVE, INC. SPDES: SPDES NY Spills: SPILLS CBS AST: CBS AST LTANKS: LTANKS	1730 DALE RD.	<1/10 NW	▲ D13	13
UPSTATE NIAGARA E MANIFEST: E MANIFEST RCRA-VSQG: RCRA-VSQG CBS: CBS LTANKS: LTANKS MANIFEST: NY MANIFEST AST: AST	1730 DALE RD	<1/10 NW	▲ D14	13
UPSTATE MILK UST FINDER RELEASE: UST FINDER RELEASE	1730 DALE ROAD	<1/10 NW	▲ D15	14
RYDER TRANSPORTATION SERVICES (LOC 0194) UST FINDER: UST FINDER	107 ANDERSON ROAD	1/10 - 1/3 NNE	◆ J16	14
RYDER TRUCK RENTAL INC. UST FINDER RELEASE: UST FINDER RELEASE	107 ANDERSON ROAD	1/10 - 1/3 NNE	◆ J17	14
RYDER TRUCK RENTAL INC. NY Spills: SPILLS LTANKS: LTANKS	107 ANDERSON ROAD	1/10 - 1/3 NNE	◆ J18	14
RYDER TRUCK RENTALS UST FINDER RELEASE: UST FINDER RELEASE	107 ANDERSON ROAD	1/10 - 1/3 NNE	◆ J19	14
PAUL BATT BUICK INC UST FINDER: UST FINDER	1717 WALDEN AVE	1/10 - 1/3 NNW	◆ K20	14
ASPEN DENTAL ECHO: ECHO FINDS: FINDS E MANIFEST: E MANIFEST RCRA-VSQG: RCRA-VSQG UST: UST MANIFEST: NY MANIFEST AST: AST	1717 WALDEN AVE	1/10 - 1/3 NNW	◆ K21	15
BUFFALO SPRING UST FINDER RELEASE: UST FINDER RELEASE	1765 WALDEN AVENUE	1/10 - 1/3 NNE	◆ M22	15
BUFFALO SPRING NY Spills: SPILLS LTANKS: LTANKS	1765 WALDEN AVENUE	1/10 - 1/3 NNE	◆ M23	15

EDR HIGH RISK HISTORICAL RECORDS

Name	Address	Dist/Dir	Map ID	Page


Not Reported

EDR RECOVERED GOVERNMENT ARCHIVES

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
Not Reported				

PRIMARY MAP - 8127688.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Commercial Property	CLIENT:	Farmer Environmental Group
ADDRESS:	24 Anderson Road Buffalo NY 14225	CONTACT:	Roy David King
		INQUIRY #:	8127688.2s
LAT/LONG:	42.905232 / 78.772249	DATE:	October 02, 2025 9:31 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

SECONDARY MAP - 8127688.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Upgradient Area

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Commercial Property	CLIENT:	Farmer Environmental Group
ADDRESS:	24 Anderson Road Buffalo NY 14225	CONTACT:	Roy David King
		INQUIRY #:	8127688.2s
LAT/LONG:	42.905232 / 78.772249	DATE:	October 02, 2025 9:30 am

Copyright © 2025 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS

LEGEND

FACILITY NAME **FACILITY ADDRESS, CITY, ST, ZIP**		EDR SITE ID NUMBER
◆ **MAP ID#**	Direction Distance Range (Distance feet / miles) Relative Elevation Feet Above Sea Level	ASTM 2600 Record Sources found in this report. Each database searched has been assigned to one or more categories. For detailed information about categorization, see the section of the report Records Searched and Currency.

Worksheet:

Comments:
Comments may be added on the online Vapor Encroachment Worksheet.

DATABASE ACRONYM: Applicable categories (A hoverbox with database description).

NANCY O'NEIL AUTO FIRE 24 ANDERSON ROAD, CHEEKTOWAGA, NY,			S102175488
▲ A1	Target Property 656 ft. Above Sea Level		Records of Emergency Release Reports

Worksheet:

Impact on Target Property: VEC does not exist

ROTARY COMPANY 1746 DALE ROAD, BUFFALO, NY, 14225			S108146691
▲ A2	S <1/10 Equal Elevation	(33 ft. / 0.006 mi.) 656 ft. Above Sea Level	Other Ascertainable Records

Worksheet:

Impact on Target Property: VEC Exists

ROCO, LTD. 1746 DALE ROAD, CHEEKTOWAGA, NY, 14225			S105114396
▲ A3	S <1/10 Equal Elevation	(33 ft. / 0.006 mi.) 656 ft. Above Sea Level	Lists of state- and tribal hazardous waste facilities State and tribal institutional control / engineering control registries Lists of state and tribal voluntary cleanup sites Records of Emergency Release Reports Other Ascertainable Records

Worksheet:

Impact on Target Property: VEC Exists

ROTARY CO INC 1746 DALE RD, BUFFALO, NY, 14225	1000156599

▲ A4	S <1/10	(33 ft. / 0.006 mi.)	Lists of Federal CERCLA sites with NFRAP Other Ascertainable Records
	Equal Elevation	656 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC Exists

ACTS TESTING LABS INC 25 ANDERSON RD, BUFFALO, NY, 14225			1000871603
◆ B5	E <1/10	(113 ft. / 0.021 mi.)	Other Ascertainable Records
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

UPSTATE FARMS COOPERATIVE INC 25 ANDERSON RD, CHEEKTOWAGA, NY, 14225			1004762135
◆ B6	E <1/10	(113 ft. / 0.021 mi.)	Other Ascertainable Records
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

BUILDING ADDITION EXCAVATION 25 ANDERSON ROAD, CHEEKTOWAGA, NY,			S111011907
◆ B7	E <1/10	(113 ft. / 0.021 mi.)	Records of Emergency Release Reports
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

DIMAR MANUFACTURING 40 ANDERSON RD, CHEEKTOWAGA, NY, 14225			1015747219
◆ A8	N <1/10	(128 ft. / 0.024 mi.)	Lists of Federal RCRA generators Other Ascertainable Records
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

DIMAR MANUFACTURING 40 ANDERSON RD, CHEEKTOWAGA, NY, 14225			1027351882
◆ A9	N <1/10	(128 ft. / 0.024 mi.)	Other Ascertainable Records
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

SECO CORP 40 ANDERSON ROAD, BUFFALO, NY, 14225			1000324744
◆ A10	N <1/10	(128 ft. / 0.024 mi.)	Other Ascertainable Records
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

UPSTATE NIAGARA COOPERATIVES INC 1730 DALE RD, BUFFALO, NY, 14225			1028597410
▲ D11	NW <1/10	(202 ft. / 0.038 mi.)	Other Ascertainable Records
	1 ft. Higher Elevation	657 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

UPSTATE MILK 1730 DALE STREET, BUFFALO, NY, 0			1029071727
▲ D12	NW <1/10	(202 ft. / 0.038 mi.)	Other Ascertainable Records
	1 ft. Higher Elevation	657 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

UPSTATE FARM COOPERATIVE, INC. 1730 DALE RD., CHEEKTOWAGA, NY, 14225			S103825081
▲ D13	NW <1/10	(202 ft. / 0.038 mi.)	Lists of state and tribal leaking storage tanks Lists of state and tribal registered storage tanks Records of Emergency Release Reports Other Ascertainable Records
	1 ft. Higher Elevation	657 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

UPSTATE NIAGARA 1730 DALE RD, BUFFALO, NY, 14225			1000911940
▲ D14	NW <1/10	(202 ft. / 0.038 mi.)	Lists of Federal RCRA generators Lists of state and tribal leaking storage tanks Lists of state and tribal registered storage tanks Other Ascertainable Records
	1 ft. Higher Elevation	657 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

UPSTATE MILK 1730 DALE ROAD, CHEEKTOWAGA, NY, 0			1029064843
▲ D15	NW <1/10	(202 ft. / 0.038 mi.)	Other Ascertainable Records
	1 ft. Higher Elevation	657 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

RYDER TRANSPORTATION SERVICES (LOC 0194) 107 ANDERSON ROAD, CHEEKTOWAGA, NY, 14225			1028595502
◆ J16	NNE 1/10 - 1/3	(804 ft. / 0.152 mi.)	Other Ascertainable Records
	3 ft. Lower Elevation	653 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

RYDER TRUCK RENTAL INC. 107 ANDERSON ROAD, CHEEKTOWAGA, NY, 0			1029078244
◆ J17	NNE 1/10 - 1/3	(804 ft. / 0.152 mi.)	Other Ascertainable Records
	3 ft. Lower Elevation	653 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

RYDER TRUCK RENTAL INC. 107 ANDERSON ROAD, CHEEKTOWAGA, NY,			S103558438
◆ J18	NNE 1/10 - 1/3	(804 ft. / 0.152 mi.)	Lists of state and tribal leaking storage tanks Records of Emergency Release Reports
	3 ft. Lower Elevation	653 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

RYDER TRUCK RENTALS 107 ANDERSON ROAD, CHEEKTOWAGA, NY, 0			1029078245
◆ J19	NNE 1/10 - 1/3	(804 ft. / 0.152 mi.)	Other Ascertainable Records
	3 ft. Lower Elevation	653 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

PAUL BATT BUICK INC 1717 WALDEN AVE, CHEEKTOWAGA, NY, 14225	1028597216

◆ K20	NNW 1/10 - 1/3	(831 ft. / 0.157 mi.)	Other Ascertainable Records
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

ASPEN DENTAL
1717 WALDEN AVE, CHEEKTOWAGA, NY, 14225 **1000273715**

◆ K21	NNW 1/10 - 1/3	(831 ft. / 0.157 mi.)	Lists of Federal RCRA generators Lists of state and tribal registered storage tanks Other Ascertainable Records
	1 ft. Lower Elevation	655 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

BUFFALO SPRING
1765 WALDEN AVENUE, CHEEKTOWAGA, NY, 0 **1029064920**

◆ M22	NNE 1/10 - 1/3	(973 ft. / 0.184 mi.)	Other Ascertainable Records
	3 ft. Lower Elevation	653 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

BUFFALO SPRING
1765 WALDEN AVENUE, CHEEKTOWAGA, NY, **S102176007**

◆ M23	NNE 1/10 - 1/3	(973 ft. / 0.184 mi.)	Lists of state and tribal leaking storage tanks Records of Emergency Release Reports
	3 ft. Lower Elevation	653 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
ENVIRONMENTAL RECORDS						
Federal NPL site list						
US	NPL	National Priority List	EPA	06/26/2025	07/01/2025	07/17/2025
US	Proposed NPL	Proposed National Priority List Sites	EPA	06/26/2025	07/01/2025	07/17/2025
US	NPL LIENS	Federal Superfund Liens	EPA	10/15/1991	02/02/1994	03/30/1994
Federal CERCLIS list						
US	SEMS	Superfund Enterprise Management System	EPA	06/26/2025	07/01/2025	07/17/2025
Federal RCRA CORRACTS facilities list						
US	CORRACTS	Corrective Action Report	EPA	06/02/2025	06/03/2025	06/16/2025
Federal RCRA TSD facilities list						
US	RCRA-TSDF	RCRA - Treatment, Storage and Disposal	Environmental Protection Agency	06/02/2025	06/04/2025	06/16/2025
Federal RCRA generators list						
US	RCRA-LQG	RCRA - Large Quantity Generators	Environmental Protection Agency	06/02/2025	06/04/2025	06/16/2025
US	RCRA-SQG	RCRA - Small Quantity Generators	Environmental Protection Agency	06/02/2025	06/04/2025	06/16/2025
US	RCRA-VSQG	RCRA - Very Small Quantity Generators (Formerly Conditionall	Environmental Protection Agency	06/02/2025	06/04/2025	06/16/2025
Federal institutional controls / engineering controls registries						
US	LUCIS	Land Use Control Information System	Department of the Navy	03/11/2025	04/02/2025	06/24/2025
US	US ENG CONTROLS	Engineering Controls Sites List	Environmental Protection Agency	05/19/2025	05/20/2025	07/29/2025
US	US INST CONTROLS	Institutional Controls Sites List	Environmental Protection Agency	05/19/2025	05/20/2025	07/29/2025
Federal ERNS list						
US	ERNS	Emergency Response Notification System	National Response Center, United States Coast	06/10/2025	06/12/2025	06/16/2025
State and tribal - equivalent CERCLIS						
NY	SHWS	Inactive Hazardous Waste Disposal Sites in New York State	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
State and tribal landfill / solid waste disposal						
NY	SWF/LF	Facility Register	Department of Environmental Conservation	06/04/2025	08/12/2025	09/15/2025
State and tribal leaking storage tank lists						
US	INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land	EPA Region 1	11/18/2024	01/16/2025	04/07/2025
US	INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land	EPA Region 7	01/07/2025	01/16/2025	04/07/2025
US	INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land	Environmental Protection Agency	01/07/2025	01/16/2025	04/07/2025
US	INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land	EPA Region 4	11/18/2024	01/16/2025	04/07/2025
US	INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land	EPA Region 8	11/18/2024	01/16/2025	04/07/2025
US	INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land	EPA Region 10	11/18/2024	01/16/2025	04/07/2025
US	INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land	EPA Region 6	11/18/2024	01/16/2025	04/07/2025
US	INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land	EPA, Region 5	11/18/2024	01/16/2025	04/07/2025
NY	LTANKS	Spills Information Database	Department of Environmental Conservation	08/03/2025	08/04/2025	08/05/2025
NY	HIST LTANKS	Listing of Leaking Storage Tanks	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
State and tribal registered storage tank lists						
NY	TANKS	Storage Tank Faciliy Listing	Department of Environmental Conservation	06/16/2025	06/16/2025	09/12/2025
NY	UST	Petroleum Bulk Storage (PBS) Database	Department of Environmental Conservation	06/16/2025	06/16/2025	09/12/2025
NY	CBS UST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	MOSF UST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	AST	Petroleum Bulk Storage	Department of Environmental Conservation	06/16/2025	06/16/2025	09/12/2025
NY	CBS AST	Chemical Bulk Storage Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	MOSF AST	Major Oil Storage Facilities Database	NYSDEC	01/01/2002	02/20/2002	03/22/2002
NY	CBS	Chemical Bulk Storage Site Listing	Department of Environmental Conservation	06/16/2025	06/16/2025	09/12/2025
NY	MOSF	Major Oil Storage Facility Site Listing	Department of Environmental Conservation	06/16/2025	06/16/2025	09/12/2025
US	INDIAN UST R9	Underground Storage Tanks on Indian Land	EPA Region 9	10/15/2024	01/16/2025	04/07/2025
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 4	11/08/2024	01/16/2025	04/07/2025
US	INDIAN UST R10	Underground Storage Tanks on Indian Land	EPA Region 10	11/18/2024	01/16/2025	04/07/2025
US	INDIAN UST R6	Underground Storage Tanks on Indian Land	EPA Region 6	11/18/2024	01/16/2025	04/07/2025
US	INDIAN UST R5	Underground Storage Tanks on Indian Land	EPA Region 5	11/18/2024	01/16/2025	04/07/2025
US	INDIAN UST R1	Underground Storage Tanks on Indian Land	EPA, Region 1	11/18/2024	01/16/2025	04/07/2025
US	INDIAN UST R8	Underground Storage Tanks on Indian Land	EPA Region 8	11/18/2024	01/16/2025	04/07/2025
US	INDIAN UST R7	Underground Storage Tanks on Indian Land	EPA Region 7	01/07/2025	01/16/2025	04/07/2025
US	FEMA UST	Underground Storage Tank Listing	FEMA	04/08/2025	04/23/2025	04/24/2025
State and tribal institutional control / engineering control registries						
NY	ENV RES DECL	Environmental Restrictive Declarations	New York City Department of City Planning	05/15/2025	06/11/2025	09/09/2025
NY	RES DECL	Restrictive Declarations Listing	NYC Department of City Planning	05/15/2025	06/10/2025	09/08/2025
NY	ENG CONTROLS	Registry of Engineering Controls	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
NY	INST CONTROL	Registry of Institutional Controls	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
State and tribal voluntary cleanup sites						
US	INDIAN VCP R7	Voluntary Cleanup Priority Lisitng	EPA, Region 7	03/20/2008	04/22/2008	05/19/2008
US	INDIAN VCP R1	Voluntary Cleanup Priority Listing	EPA, Region 1	07/27/2015	09/29/2015	02/18/2016
NY	VCP NYC	Voluntary Cleanup Program Listing NYC	New York City Office of Environmental Protect	06/01/2025	06/02/2025	08/25/2025
NY	VCP	Voluntary Cleanup Agreements	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
State and tribal Brownfields sites						
NY	BROWNFIELDS	Brownfields Site List	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
NY	ERP	Environmental Restoration Program Listing	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
Other Records						
US	CONSENT	Superfund (CERCLA) Consent Decrees	Department of Justice, Consent Decree Library	03/31/2025	05/02/2025	07/17/2025
US	ROD	Records Of Decision	EPA	07/29/2025	08/04/2025	08/12/2025
US	LIENS 2	CERCLA Lien Information	Environmental Protection Agency	06/26/2025	07/01/2025	07/17/2025
NY	DEL SHWS	Delisted Registry Sites	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
US	DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations	EPA, Region 9	01/12/2009	05/07/2009	09/21/2009
NY	SWTIRE	Registered Waste Tire Storage & Facility List	Department of Environmental Conservation	06/02/2025	06/04/2025	09/02/2025
NY	SWRCY	Registered Recycling Facility List	Department of Environmental Conservation	06/04/2025	06/18/2025	09/15/2025
NY	HIST UST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006
NY	HIST AST	Historical Petroleum Bulk Storage Database	Department of Environmental Conservation	01/01/2002	06/02/2006	07/20/2006

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	COAL ASH EPA	Coal Combustion Residues Surface Impoundments List	Environmental Protection Agency	01/12/2017	03/05/2019	11/11/2019
US	US FIN ASSUR	Financial Assurance Information	Environmental Protection Agency	06/02/2025	06/03/2025	06/16/2025
US	2020 COR ACTION	2020 Corrective Action Program List	Environmental Protection Agency	09/30/2017	05/08/2018	07/20/2018
US	US AIRS (AFS)	Aerometric Information Retrieval System Facility Subsystem (	EPA	10/12/2016	10/26/2016	02/03/2017
US	COAL ASH DOE	Steam-Electric Plant Operation Data	Department of Energy	12/31/2023	10/16/2024	01/14/2025
US	US HIST CDL	National Clandestine Laboratory Register	Drug Enforcement Administration	04/04/2025	06/02/2025	08/12/2025
US	LEAD SMELTER 2	Lead Smelter Sites	American Journal of Public Health	04/05/2001	10/27/2010	12/02/2010
US	EPA WATCH LIST	EPA Watch List	Environmental Protection Agency	08/30/2013	03/21/2014	06/17/2014
US	LEAD SMELTER 1	Lead Smelter Sites	Environmental Protection Agency	06/26/2025	07/01/2025	07/17/2025
US	US AIRS MINOR	Air Facility System Data	EPA	10/12/2016	10/26/2016	02/03/2017
US	FUSRAP	Formerly Utilized Sites Remedial Action Program	Department of Energy	03/03/2023	03/03/2023	06/09/2023
US	PCB TRANSFORMER	PCB Transformer Registration Database	Environmental Protection Agency	09/13/2019	11/06/2019	02/10/2020
US	SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing	Environmental Protection Agency	07/30/2021	02/03/2023	02/10/2023
US	Delisted NPL	National Priority List Deletions	EPA	06/26/2025	07/01/2025	07/17/2025
US	SEMS-ARCHIVE	Superfund Enterprise Management System Archive	EPA	06/26/2025	07/01/2025	07/17/2025
US	RCRA NonGen / NLR	RCRA - Non Generators / No Longer Regulated	Environmental Protection Agency	06/02/2025	06/04/2025	06/16/2025
US	HMIRS	Hazardous Materials Information Reporting System	U.S. Department of Transportation	06/11/2025	06/12/2025	06/16/2025
US	DOT OPS	Incident and Accident Data	Department of Transporation, Office of Pipeli	03/31/2025	04/22/2025	07/17/2025
US	US CDL	Clandestine Drug Labs	Drug Enforcement Administration	04/04/2025	06/02/2025	08/12/2025
US	US BROWNFIELDS	A Listing of Brownfields Sites	Environmental Protection Agency	09/09/2024	09/11/2024	12/06/2024
US	DOD	Department of Defense Sites	USGS	06/07/2021	07/13/2021	03/09/2022
US	FEDLAND	Federal and Indian Lands	U.S. Geological Survey	04/02/2018	04/11/2018	11/06/2019
US	FUDS	Formerly Used Defense Sites	U.S. Army Corps of Engineers	07/23/2025	07/23/2025	07/29/2025
US	UMTRA	Uranium Mill Tailings Sites	Department of Energy	05/15/2025	05/15/2025	07/29/2025
US	ODI	Open Dump Inventory	Environmental Protection Agency	06/30/1985	08/09/2004	09/17/2004
US	US MINES	Mines Master Index File	Department of Labor, Mine Safety and Health A	05/01/2025	05/20/2025	07/29/2025
US	MINES VIOLATIONS	MSHA Violation Assessment Data	DOL, Mine Safety & Health Admi	07/01/2025	07/01/2025	09/24/2025
US	US MINES 2	Ferrous and Nonferrous Metal Mines Database Listing	USGS	04/08/2025	05/20/2025	08/12/2025
US	US MINES 3	Active Mines & Mineral Plants Database Listing	USGS	04/14/2011	06/08/2011	09/13/2011
US	PRP	Potentially Responsible Parties	EPA	06/26/2025	07/01/2025	07/29/2025
US	TRIS	Toxic Chemical Release Inventory System	EPA	12/31/2023	02/11/2025	02/18/2025
US	TSCA	Toxic Substances Control Act	EPA	12/31/2020	06/14/2022	03/24/2023
US	FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA/Office of Prevention, Pesticides and Toxi	04/09/2009	04/16/2009	05/11/2009
US	FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA	04/09/2009	04/16/2009	05/11/2009
US	HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HIST FTTS INSP	FIFRA/TSCA Tracking System Inspection & Enforcement Case Lis	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	SSTS	Section 7 Tracking Systems	EPA	04/14/2025	04/15/2025	07/08/2025
US	ICIS	Integrated Compliance Information System	Environmental Protection Agency	11/18/2016	11/23/2016	02/10/2017
US	PADS	PCB Activity Database System	EPA	07/01/2024	10/02/2024	01/10/2025
US	MLTS	Material Licensing Tracking System	Nuclear Regulatory Commission	05/07/2025	05/07/2025	06/03/2025
US	RADINFO	Radiation Information Database	Environmental Protection Agency	07/01/2019	07/01/2019	09/23/2019
US	FINDS	Facility Index System/Facility Registry System	EPA	04/22/2025	05/05/2025	05/21/2025
US	RAATS	RCRA Administrative Action Tracking System	EPA	04/17/1995	07/03/1995	08/07/1995
US	RMP	Risk Management Plans	Environmental Protection Agency	04/05/2025	04/11/2025	07/08/2025
US	BRS	Biennial Reporting System	EPA/NTIS	12/31/2023	02/19/2025	03/07/2025
US	PWS	Public Water System Data	EPA	12/17/2013	01/09/2014	10/15/2014
US	INDIAN RESERV	Indian Reservations	USGS	12/31/2014	07/14/2015	01/10/2017

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	INDIAN ODI	Report on the Status of Open Dumps on Indian Lands	Environmental Protection Agency	12/31/1998	12/03/2007	01/24/2008
US	IHS OPEN DUMPS	Open Dumps on Indian Land	Department of Health & Human Serivces, Indian	02/07/2024	11/13/2024	11/19/2024
US	ABANDONED MINES	Abandoned Mines	Department of Interior	05/28/2025	05/28/2025	06/03/2025
NY	AIRS	Air Emissions Data	Department of Environmental Conservation	04/10/2025	04/17/2025	07/08/2025
NY	COAL ASH	Coal Ash Disposal Site Listing	Department of Environmental Conservation	06/17/2025	06/18/2025	09/12/2025
NY	PFAS 2	New York State Inactive Landfill Initiative	Department of Environmental Conservation	12/12/2022	08/10/2023	10/25/2023
NY	DRYCLEANERS	Registered Drycleaners	Department of Environmental Conservation	06/03/2025	06/04/2025	08/25/2025
NY	PFAS 3	PFAS Environmental Site Remediation List	Department of Environmental Conservation	04/30/2025	05/06/2025	07/23/2025
NY	E DESIGNATION	E DESIGNATION SITE LISTING	New York City Department of City Planning	05/30/2025	06/10/2025	09/08/2025
NY	FIN ASSURANCE 1	Financial Assurance Information Listing	Department of Environmental Conservation	06/09/2025	06/18/2025	09/12/2025
NY	FIN ASSURANCE 2	Financial Assurance Information Listing	Department of Environmental Conservation	06/02/2025	06/03/2025	08/25/2025
NY	HIST SPILLS	SPILLS Database	Department of Environmental Conservation	01/01/2002	07/08/2005	07/14/2005
NY	HSWDS	Hazardous Substance Waste Disposal Site Inventory	Department of Environmental Conservation	01/01/2003	10/20/2006	11/30/2006
NY	LIENS	Spill Liens Information	Office of the State Comptroller	04/25/2025	04/25/2025	07/08/2025
NY	NY MANIFEST	Facility and Manifest Data	Department of Environmental Conservation	12/31/2019	11/30/2023	12/01/2023
NY	SPDES	State Pollutant Discharge Elimination System	Department of Environmental Conservation	07/09/2025	07/15/2025	07/30/2025
NY	SPILLS	Spills Information Database	Department of Environmental Conservation	08/03/2025	08/04/2025	08/05/2025
NY	SPILLS 80	SPILLS80 data from FirstSearch	FirstSearch	11/02/2010	01/03/2013	03/07/2013
NY	SPILLS 90	SPILLS90 data from FirstSearch	FirstSearch	12/14/2012	01/03/2013	02/12/2013
NY	UIC	Underground Injection Control Wells	Department of Environmental Conservation	05/26/2025	05/27/2025	08/21/2025
NY	VAPOR REOPENED	Vapor Intrusion Legacy Site List	Department of Environmenal Conservation	01/01/2022	02/08/2022	05/06/2022
US	PFAS ATSDR	PFAS Contamination Site Location Listing	Department of Health & Human Services	06/24/2020	03/17/2021	11/08/2022
US	E MANIFEST	Hazardous Waste Electronic Manifest System	Environmental Protection Agency	06/02/2025	06/04/2025	08/13/2025
US	AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	BIOSOLIDS	ICIS-NPDES Biosolids Facility Data	Environmental Protection Agency	04/13/2025	04/15/2025	07/08/2025
NY	NYC LEAD 2	Recent Lead Paint Violations	New York City Department of Housing Preservat	04/28/2025	04/29/2025	07/21/2025
NY	MGP	Manufactured Gas Plants Listing	Department of Environmental Conservation	08/27/2025	08/27/2025	09/17/2025
US	DOCKET HWC	Hazardous Waste Compliance Docket Listing	Environmental Protection Agency	05/06/2021	05/21/2021	08/11/2021
US	PFAS NPDES	Clean Water Act Discharge Monitoring Information	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	MINES MRDS	Mineral Resources Data System	USGS	06/04/2024	11/22/2024	02/18/2025
NY	NYC OER	OER Cleanup Sites Listing	Office of Environmental Remediation	06/01/2025	06/02/2025	08/25/2025
US	PFAS PT 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	PFAS ECHO	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	PFAS NPL	Superfund Sites with PFAS Detections Information	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
NY	NYC LAND USE	New York City Land Use Information	New York City Department of City Planning	02/21/2025	03/11/2025	05/28/2025
NY	PFAS	PFAS Contamination Site Location Listing	Department of Environmental Conservation	01/16/2019	05/08/2019	06/24/2019
US	FUELS PROGRAM	EPA Fuels Program Registered Listing	EPA	05/07/2025	05/13/2025	07/29/2025
NY	ILI	New York State Inactive Landfill Initiative	Department of Environmental Conservation	07/01/2025	07/29/2025	08/13/2025
US	UST FINDER	UST Finder Database	Environmental Protection Agency	06/08/2023	10/04/2023	01/18/2024
US	UST FINDER RELEASE	UST Finder Releases Database	Environmental Protecton Agency	06/08/2023	10/31/2023	01/18/2024
US	PCS	Permit Compliance System	EPA, Office of Water	12/16/2016	01/06/2017	03/10/2017
US	FEDERAL FACILITY	Federal Facility Site Information listing	Environmental Protection Agency	05/05/2025	06/20/2025	08/27/2025
US	PFAS ECHO FIRE TRAIN	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	PFAS FEDERAL SITES	Federal Sites PFAS Information	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	PFAS TRIS	List of PFAS Added to the TRI	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	PFAS WQP	Ambient Environmental Sampling for PFAS	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
NY	COOLING TOWERS	Registered Cooling Towers	Department of Health	07/01/2025	07/07/2025	09/26/2025

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing	Environmental Protection Agency	06/23/2025	06/26/2025	09/24/2025
US	ECHO	Enforcement & Compliance History Information	Environmental Protection Agency	06/22/2025	06/25/2025	08/27/2025
US	PFAS TSCA	PFAS Manufacture and Imports Information	Environmental Protection Agency	06/23/2025	06/26/2025	08/27/2025
US	PFAS PROJECT	NORTHEASTERN UNIVERSITY PFAS PROJECT	Social Science Environmental Health Research	05/15/2024	03/06/2025	06/03/2025
US	UXO	Unexploded Ordnance Sites	Department of Defense	02/14/2025	03/11/2025	06/03/2025
NY	NYC LEAD	Lead-based Paint Testing Results	New York City Department of Education	04/16/2025	04/29/2025	07/18/2025
HISTORICAL USE RECORDS						
US	EDR MGP	EDR Proprietary Manufactured Gas Plants	EDR, Inc.			
US	EDR Hist Auto	EDR Exclusive Historical Auto Stations	EDR, Inc.			
US	EDR Hist Cleaner	EDR Exclusive Historical Cleaners	EDR, Inc.			
NY	RGA HWS	Recovered Government Archive State Hazardous Waste Facilitie	Department of Environmental Conservation		07/01/2013	12/30/2013
NY	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Environmental Conservation		07/01/2013	01/10/2014
COUNTY RECORDS						
NY	AST - CORTLAND	Cortland County Storage Tank Listing	Cortland County Health Department	08/20/2019	08/20/2019	10/16/2019
NY	UST - CORTLAND	Cortland County Storage Tank Listing	Cortland County Health Department	08/20/2019	08/20/2019	10/16/2019
NY	AST - NASSAU	Registered Tank Database	Nassau County Health Department	11/27/2023	11/28/2023	02/06/2024
NY	AST NCFM	Storage Tank Database	Nassau County Office of the Fire Marshal	02/15/2011	02/23/2011	03/29/2011
NY	TANKS NASSAU	Registered Tank Database in Nassau County	Nassau County Department of Health	11/27/2023	11/28/2023	02/06/2024
NY	UST - NASSAU	Registered Tank Database	Nassau County Health Department	11/27/2023	11/28/2023	02/06/2024
NY	UST NCFM	Storage Tank Database	Nassau County Office of the Fire Marshal	02/15/2011	02/23/2011	03/29/2011
NY	AST - ROCKLAND	Petroleum Bulk Storage Database	Rockland County Health Department	02/02/2017	03/17/2017	09/22/2017
NY	UST - ROCKLAND	Petroleum Bulk Storage Database	Rockland County Health Department	02/02/2017	03/17/2017	09/22/2017
NY	AST - SUFFOLK	Storage Tank Database	Suffolk County Department of Health Services	06/28/2018	12/06/2018	02/07/2019
NY	TANKS SUFFOLK	Storage Tank Database	Department of Health Services	06/28/2018	02/05/2019	03/08/2019
NY	UST - SUFFOLK	Storage Tank Database	Suffolk County Department of Health Services	06/28/2018	12/06/2018	02/07/2019
NY	AST - WESTCHESTER	Listing of Storage Tanks	Westchester County Department of Health	03/28/2025	05/08/2025	07/24/2025
NY	UST - WESTCHESTER	Listing of Storage Tanks	Westchester County Department of Health	03/28/2025	05/08/2025	07/24/2025

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX G

Prior Environmental Reports

1746 DALE ROAD SITE
GROUNDWATER INVESTIGATION REPORT
OCTOBER 2014

BACKGROUND

The property at 1746 Dale Road in Cheektowaga, NY (see Figure 1), was previously owned by Roco Ltd., and was the subject of a site investigation/remedial action under the Voluntary Cleanup Program (VCP) by Roco, Ltd. dating back to 2000. Subsurface volatile organic (VOC) contamination has been associated with the use of trichloroethylene (TCE) dating back to the 1950s. Site investigations revealed contamination beneath the old metal prep room in the northwest corner of the 33,000-sf single story building, with trichloroethylene (TCE) levels as high as 153,000 ppb in groundwater well GW-3.

Roco LTD entered into the Voluntary Cleanup Program in 2002 and, following site investigations, implemented an in-situ bioremediation system to treat groundwater. The treatment consisted of the injection of a hydrogen release compound from 2005 through 2009. Over this period, site reports show TCE reductions in GW-3 down to 10 ppb, and total VOCs to 138 ppb. The site was abandoned in 2009 immediately after the submittal of a Site Management Plan by Roco Ltd., and turned over to the NYSDEC.

Messrs. Cash Cunningham and Mark Kuczka purchased the property in an auction in early 2014, and held discussions with the NYSDEC regarding measures to investigate current environmental conditions and to explore options for remediation of residual contamination at the site. Since the VCP remediation system and associated groundwater monitoring was terminated by Roco Ltd. a few years ago, the current owners retained IEG to take the first step of characterizing groundwater contamination in and around the northwest corner of the property, and to develop the course of further action.

GROUNDWATER SAMPLING AND ANALYSIS

Seven monitoring wells (see Figure 2) were found at the site from the VCP activities. Five wells (excluding MW-6) were purged and sampled in August 2014 for VOCs. Since GW-4 and GW-7 are relatively close with MW-6 in the middle, MW-6 was not sampled. The purging had to be performed over two days due the slow recharge of all the wells. At the same time, a subslab soil vapor sample (designated SV-01) was collected inside the northwest corner of the building next to monitoring well GW-3.

Table 1 provides field measurements and analytical results for the groundwater samples, while Table 2 provides analytical results for VOCs in the soil vapor sample SV-01. Figure 2 shows groundwater levels and total VOCs for the monitoring wells, and total VOCs for the soil vapor sample. Laboratory analytical reports are attached.

GROUNDWATER LEVEL AND FLOW

According to data in previous reports, the site has a ground elevation of around 653' along the northern boundary, and 643 along the southern boundary. The building occupies the bulk of the property. Groundwater levels at the monitoring wells ranged from 652.2' amsl at GW-2 to 635.9' amsl at GW-5. Levels at all wells remained essentially the same as in 2005 to 2007. The general groundwater flow is from the north to the south consistent with previous reports. There appears to be a westerly component in the northwest corner of the property.

VOCS IN GROUNDWATER AND SOIL VAPOR

VOCs IN GROUNDWATER: Up to eight VOCs were found in the six wells sampled, with GW-3 having the highest levels. GW-3 had 61,219 µg/L total VOCs, while the other four wells ranged from 5.4 to 572 µg/L. Trichloroethene (TCE) ranged from non-detect in GW-7 to 10 µg/L at GW-3. Two

VOCs, cis-1,2-dichloroethene (DCE) and vinyl chloride (VC), were the highest at 34,000 and 27,000 µg/L respectively in GW-3.

TCE is the source compound at this site, while DCE and VC are degradation products associated with in-situ bioremediation of groundwater from 2003 to 2009. According to 2009 Site Management Plan by Leader Professional Services, TCE, DCE and VC had dropped to 9.87, non-detect and 138 µg/L respectively the groundwater at GW-3 in August 2009.

VOCs IN SUBLAB SOIL VAPOR: Six VOCs were detected in the subslab soil vapor sample, ranging from 210 µg/m^3 toluene to 2,300 µg/m^3 cis-1,2-dichloroethene and 190,000 µg/m^3 TCE, significantly above the 250 µg/m^3 NYSDOH guideline. In comparison, TCE was reported to be 303 µg/m^3 in a subslab soil vapor sample near GW-3 in 2006.

ASSESSMENT

The bioremediation process appears to have significantly reduced TCE, the source compound, in the source area. However, DCE and VC, the degradation products, appears to have rebounded from the low levels reported in 2009, when the bioremediation system was abandoned by the previous owners. Over this period, the subslab soil vapor also seems to have accumulated significant levels of TCE, far exceeding previously reported levels. The elevated levels of VOCs appear to persist within the source area beneath the floor in the northwest corner of the building.


FUTURE COURSE OF ACTION

Over a decade has passed since the groundwater bioremediation system was implemented and five years since the remediation was abandoned. Contaminant levels in the source warrant further action to protect building occupants as wells as prevent further migration of contaminants. The areas outside the building are at significantly lower levels and don't appear to warrant immediate action.

Given the above scenario, IEG recommends a phased course of action, beginning with a subslab soil vapor extraction system, followed by a groundwater pump and treat system, in the source area. This would most likely be the fastest way to achieve the previously established remedial action objectives. The recommended phases are as follows:

Phase 1: Install and operate a subslab vapor extraction system (SVES) for at least a year as a first step to mitigating VOC levels below the floor in the northwest corner of the building where GW-3 is located. The TCE is probably at saturation levels beneath the slab, and, if so, will dissipate rapidly as the soil vapor is extracted. Initially, a vapor phase carbon drum could be used to treat the soil vapor before discharge to the atmosphere. The carbon drum can be discontinued once the VOC levels drop below allowable discharge limits. Continue to assess groundwater quality at GW-3 and immediate vicinity.


Phase 2: Install a groundwater extraction and treatment system (GETS) in the source area if the SVES does not significantly lower groundwater VOC levels. The GETS may include a groundwater pumping well by GW-3, and treatment by an air-stripper or carbon adsorption.



RoCo Ltd. Site, 1746 Dale Rd., Cheektowaga, NY
SITE LOCATION MAP & AERIAL PHOTO

FIGURE 1

IEG



LEGEND

GW-1	Groundwater Monitoring Well
	Subslab vapor sample
651.3'	Groundwater elevation
224	*Total VOC concentration (µg/L)*

Base Map Source: Site Management Plan, RoCo Ltd. Site (NYSDEC #V00422-9), Leader Professional Services, April 2009

RoCo Ltd. Site, Cheektowaga, NY
SITE LAYOUT WITH MONITORING WELL LOCATIONS

FIGURE 2

IEG

TABLE 1

GROUNDWATER SAMPLING: FIELD RECORD/ANALYTICAL DATA

PROJECT:	ROCO SITE GROUNDWATER I/R			**DATE:**	8/25/14 and 8/26/14		
LOCATION:	1746 DALE ROAD, CHEEKTOWAGA, NY			**ON-SITE:**	R. Allen/D. Iyer		
CLIENT:	CASH REALTY			**WEATHER:**	Partly cloudy, warm		
WELL NUMBER	**GW-1**	**GW-2**	**GW-3**	**GW-4**	**GW-5**	**GW-6**	**GW-7**
NORTHING	not available						
EASTING							
WATER LEVEL MEASUREMENTS							
GROUND ELEVATION (ft)	~652.5						
TOR ELEVATION (ft)	652.59	653.88	652.94	653.00	642.57	648.99	650.37
Depth to Bottom from TOR (ft)	13.81	13.67	13.57	12.4	17.46	--	14.35
Depth to Water from TOR (ft)	1.26	1.7	2.44	2.98	6.63	--	4.03
Bottom Elevation (ft. amsl))	638.78	640.21	639.37	640.6	625.11	--	636.02
Water Elevation (ft. amsl))	651.33	652.18	650.5	650.02	635.94	--	646.34
Length of Water Column (ft)	12.6	12.0	11.1	9.4	10.8	--	10.3
One Well Volume (gal)	2.0	2.0	1.8	1.5	1.8	--	1.7
Three Well Volumes (gal)	6.1	5.9	5.4	4.6	5.3	--	5.0
FIELD PARAMTERS: INITIAL (8/25/14) / FINAL (8/26/14)							
TURBIDITY (ntu)	12	16	28	26	14	--	75
	8	10	38	21	85	--	10
TEMPERATURE (°F)	24.7	23.3	21.5	25.5	25.7	--	22.9
	24.9	22.3	17.7	26.3	25.2	--	22.4
pH (s.u.)	7.91	7.87	7.25	7.37	7.62	--	8.14
	7.73	7.91	7.21	7.19	7.79	--	7.81
Sp. Conductivity (µmhos/cm)	867	2979	1811	>3999	637	--	1972
	845	3105	3512	>3999	680	--	2915
TDS (mg/L)	438	1491	903	>2000	318	--	996
	422	1553	1749	>2000	340	--	1453
ORP (mv)	44	59	-57	-111	62	--	55
	54	74	-56	-129	25	--	9
REMARKS: Some wells had broken riser and/or damaged casing/cover							
NOTE: 2" riser: one well volume in gallons = **0.163** **x Length of Water Column in feet**							
ANALYTICAL DATA - VOLATILE ORGANIC COMPOUNDS (µg/L)							
Acetone	ND	ND	66.0	6.5 J	ND	NA	ND
2-Butanone	ND	ND	64.0	ND	ND		ND
1,1-Dichloroethene	1.0	ND	38.0	ND	ND		1.8 J
Carbon disulfide	ND	ND	0.84 J	ND	ND		ND
Chloroform	ND	ND	ND	ND	0.41 J		ND
cis-1,2-Dichloroethene	190	9.9	34000	100.0	2.8		330
trans-1,2-Dichloroethene	1.9	ND	40.0	4.4	ND		ND
Tetrachloroethene	ND	ND	ND	ND	ND		ND
Toluene	ND	ND	ND	ND	ND		ND
Trichloroethene	3.3	2.3	10.0	8.2	2.2		ND
Vinyl chloride	28.0	4.7	27000	18.0	ND		240
Total VOCs	224	16.9	61219	137	5.4		572
NOTE: Only detected organics are listed; ND = Not Detected; NA = Not Analyzed							

TABLE 2

SUBSLAB SOIL VAPOR SAMPLING: ANALYTICAL DATA

PROJECT:	ROCO SITE GROUNDWATER I/R	**DATE:**	8/25/2014
LOCATION:	1746 DALE ROAD, CHEEKTOWAGA, NY	**ON-SITE:**	R. Allen/D. Iyer
CLIENT:	CASH REALTY	**WEATHER:**	Partly cloudy, warm

SAMPLE ID	SV-01 (near monitoring well GW-3)	
ANALYTICAL DATA - VOLATILE ORGANIC COMPOUNDS		
UNITS	**(ppb v/v)**	**($\mu g/m^3$)**
Acetone	ND	ND
2-Butanone	ND	ND
1,1-Dichloroethene	200 J	800 J
Carbon disulfide	ND	ND
Chloroform	ND	ND
cis-1,2-Dichloroethene	590	2300
trans-1,2-Dichloroethene	ND	ND
Tetrachloroethene	100 J	710 J
Toluene	56 J	210 J
Trichloroethene	35000.0	190000
Vinyl chloride	ND	ND
Total VOCs	35946	194020

NOTE: Only detected organics are listed; ND = Not Detected

October 30, 2007

Mr. David Locey
New York State Department of Environmental Conservation
270 Michigan Avenue
Buffalo, NY 14203-2999

Re: RoCo LTD.
Site #V-00422-9
Cheektowaga, Erie County

Dear Mr. Locey:

Attached is the final Intrusive Soil Vapor Sampling and Analysis Work Plan for the RoCo, Ltd. Site. This plan incorporates the revisions that you suggested in your letter to Mr. Dennis Harkawik dated October 16, 2007. Each revision is briefly discussed below:

1. NYSDEC suggested that sub-slab samples be collected from within the office space of the RoCo building and within the Davis Electric building. The only office space that is within the RoCo building is on the opposite side of the structure from the known groundwater and soil contamination. In addition, that area of the building is elevated off of the ground and has a crawl space beneath it. Due to the distance from the known contaminate source, Leader suggests that no samples be collected in this area unless ambient air samples or sub-slab air samples, collected in the vicinity of the contaminate plume, indicate potential human health risks. Sample locations that are described on Page 3 of the work plan already include the office space on the first floor of the Davis Electric building.
2. A revision has been made to the sampling technique to include purging of the tubing on Page 3 of the Work Plan.
3. Quality control and quality assurance issues (blind duplicate sample and DUSR report) have been addressed and are now included in the Work Plan on Page 4.

Please review this Work Plan and provide us with written approval to proceed with its implementation.

Please feel free to contact us with any questions.

Sincerely,

Jonathan Neubauer
Project Manager
The Leader Group

(716) 565-0963 (office)
(716) 725-2804 (cell)
jneubauer@leaderlink.com

cc: Mr. Cameron O'Connor, NYSDOH
Mr. Jeffery Wittlinger, Leader
Dennis Harkawik, Esq. (JFM)
Michael Shannon, Esq. (Farner & Farner)

VOLUNTARY CLEANUP PROGRAM INTRUSIVE SOIL VAPOR SAMPLING AND ANALYSIS WORK PLAN

Prepared For:

RoCo, LTD.
1746 Dale Road
Cheektowaga, New York

Prepared By:

LEADER PROFESSIONAL SERVICES, INC.
2813 Wehrle Drive, Suite No. 1
Williamsville, New York 14221

October, 2007

147.007

TABLE OF CONTENTS

1.0 SITE DESCRIPTION 1

2.0 BACKGROUND INFORMATION 1

3.0 INTRUSIVE SOIL VAPORS SAMPLING AND ANALYSIS PLAN 2

4.0 SCHEDULE OF WORK 5

5.0 REPORTING REQUIREMENTS 6

Appendix A:	Remedial Action Progress Report (April 2007)
Appendix B:	NYSDEC Correspondence (David Locey, July 2007)
Appendix C:	EPA Analytical Method TO-15 Analyte List
Appendix D:	Soil Vapor Intrusion Questionnaire and Building Inventory Forms
Appendix E:	New York State Department of Health "Guidance for Evaluating Soil Vapor Intrusion in the State of New York.

1.0 SITE DESCRIPTION

Leader Professional Services, Inc. ("Leader") was retained by RoCo, LTD ("RoCo") to prepare an Intrusive Soil Vapor Sampling and Analysis Work Plan, under the current New Yorks State Department of Health ("NYSDOH") guidelines, for the property at 1746 Dale Road, Cheektowaga, Erie County, New York (hereafter referred to as "the Site"). The format and content of this Sampling and Analysis Work Plan generally conforms to the NYSDOH guidance document entitled "Guidance for Evaluating Soil Vapor Intrusion in the State of New York" (see Appendix E).

2.0 BACKGROUND INFORMATION

Leader submitted a Remedial Action ("RA") Progress Report to the New York State Department of Environmental Conservation ("NYSDEC") in April of 2007 (see Appendix A). The RAP Report discussed the monitoring and sampling activities that have taken place at the Site and provided a progress assessment of the remedial activities.

In a letter dated July 13, 2007, Mr. David Locey of the NYSDEC stated that after reviewing the aforementioned RAP report, additional information was needed to determine if the residual groundwater contamination posed any potential health risks. The letter indicated that the NYSDEC requires an evaluation of soil vapors from beneath the building slab and air samples from within and outside of the subject building (see Appendix B).

3.0 SCOPE OF WORK

The scope of this Intrusive Soil Vapor Sampling and Analysis Plan has been developed to assess the extent of soil vapors infiltrating Site structures which may pose possible human health risks. As a result of the previous studies that have been conducted at the Site and on the Upstate Farms Cooperative, Inc. property, the area of concern has been identified. Thus, the primary objective of this Soil Vapor Sampling and Analysis Plan will be to identify and quantify potential intrusive soil vapors. No additional contaminants or areas will be addressed by this plan because the Site and vicinity have already been sufficiently studied.

Task 1: Project Coordination

Communications relative to the project will be executed according to an agreement between Upstate Farms Cooperative, Inc. and RoCo. Site access issues and agreements will be discussed to ensure that Leader and its subcontractors have access to the Site, Upstate Farms Cooperative, Inc. property and Davis Electrical Supply Company property.

Task 2: Soil Vapor Sampling and Analytical Testing Program

Figure 1 is the proposed sampling location plan; however, actual sample locations will be refined based on the findings of photo ionization detector ("PID") measurements obtained in the field and any materials, structures or work operations which may interfere with sampling. Approximately fourteen (14) samples will be collected during this Soil Vapor Intrusion study.

Prior to initiation of sampling activities, an inventory of all on-Site chemicals or other possible Volatile Organic Compound ("VOC") emitting materials will be taken and concentrations recorded utilizing a PID capable of detecting VOC compounds in parts per billion ("PPB"). An Indoor Air Quality Questionnaire and Building Inventory will be completed for each structure during the pre sampling inventory. A copy of the Indoor Air Quality Questionnaire and Building Inventory is included in Appendix D.

In order to assess background concentrations, two (2) samples will be collected outside of the RoCo building. One (1) sample will be collected upwind of the building and one (1) sample will be collected downwind of the structure. Each of these samples will be collected from a height of approximately 5 to 6 feet above ground surface ("ABS") and away from any known contaminant sources (i.e., vehicle pathways, HVAC units, etc.).

Based on previous concentrations in soil and groundwater samples (see Figure 1), twelve (12) additional samples will be collected from within the RoCo structure and from within the Davis Electric Supply structure. Within the RoCo Site structure, sub-slab samples will be collected in the vicinity of GW-3, BH-13, BH-6 and BH-10. In addition, ambient indoor air samples will be collected at or near the sub-slab sample locations. Sub-slab samples will be collected in the Davis Electric Supply structure in the vicinity of GW-2 and BH 16 as shown on Figure 1. In addition, ambient indoor air samples will be collected at or near the sub-slab sample locations.

Sub-slab samples will be collected by advancing a one-inch diameter hole through the floor slab utilizing a hammer drill. One quarter inch inert tubing will then be inserted into the hole at a depth not to exceed two-inches into sub slab material. A backfill material will be used to secure the tubing in place (i.e., inert glass beads or washed #1 crushed stone) and the tube will be secured using modeling clay or other inert surface seal materials. The tubing will then be purged of at least two tube volumes before being attached to a one liter Summa canister with a predetermined flow rate (i.e., not to exceed 0.2 liters per minute) adjusted to obtain a 24-hour composite sample.

The samples will be secured 24 hours after commencement of sampling activities. The samples will then be transported under proper chain of custody to Paradigm Environmental Laboratories ("Paradigm") for analysis via EPA Method TO-15 (see Analyte list included as Attachment C).

For quality control/quality assurance purposes, one (1) blind duplicate sample will be collected and analyzed, and Paradigm will provide Leader with all necessary analytical data needed to perform a Data Usability Summary Report ("DUSR"). Ms. Mary Ellen Holvey, CIH, of Leader will review all of the data and generate a DUSR report to be included with the findings report.

Task 3: Restoration

The penetrations through the concrete floors at the RoCo and Davis Electric buildings will be sealed with a cement-based patch material. The areas where penetrations are advanced will be swept and cleaned of debris.

4.0 SCHEDULE OF WORK

Below are the anticipated sequence, schedule and projected completion dates for the key project milestones. Note that these dates may change based on internal and NYSDEC / NYSDOH review periods and weather conditions beyond Leader's control.

Task Description	Duration	Projected Completion Date
Review and Approval of Work Plan	4 Weeks	October 2007
Implementation of Pre Sampling Inventory	1 Day	November 2007
Sampling Event	2 Days	November 2007
Analysis and Reporting	2 Weeks	December 2007
Report Preparation, Revision and Approval	2 Weeks	December 31, 2007

5.0 REPORTING REQUIREMENTS

5.1 Progress Reports

Due to the short duration of the field investigation portion of this project, no intermediate progress reports are planned. Leader or a representative of RoCo will contact NYSDEC and inform them of the progress of the study.

5.2 Intrusive Soil Vapor Sampling and Analysis Report

A written report will be prepared relating the findings of the study. This report will include the following:

- Introduction
- Purpose and Scope of Work
- Description of Investigation Activities
- Investigation Findings
- Exposure and Human Health Risk Assessment
- Conclusions and Recommendations

Appendix A
Remedial Action Progress Report
(April 2007)

Privileged and Confidential
Attorney Work Product



VOLUNTARY CLEANUP PROGRAM
REMEDIAL ACTION PLAN REPORT

FOR:
ROCO, LTD SITE
1746 DALE ROAD
CHEEKTOWAGA, NEW YORK

MARCH 2007

LEADER PROFESSIONAL SERVICES, INC.
2813 WEHRLE DRIVE, SUITE NO. 1
WILLIAMSVILLE, NEW YORK 14221
716-565-0963

Privileged and Confidential
Attorney Work Product

VOLUNTARY CLEANUP PROGRAM
REMEDIAL ACTION PLAN REPORT

ROCO, LTD SITE
1746 DALE ROAD
CHEEKTOWAGA, NEW YORK

Prepared For:

RoCo, Ltd.
P.O. Box 971
Colby Hill Road
New London, New Hampshire 03257

Prepared By:

Leader Professional Services, Inc.
2813 Wehrle Drive, Suite 1
Williamsville, New York 14221

March 24, 2007

Project No. 147.007

Table of Contents

1. INTRODUCTION 1

1.1 Background 1

1.2 Purpose 1

1.3 Scope of Work 2

2. FIELD ACTIVITIES 3

2.1 HRC Injection Activities 3

2.2 Groundwater Monitoring Program 4

2.2.1 Groundwater Elevation Measurements 4
2.2.2 Reduction/Oxidation Measurements 4
2.2.3 Groundwater Sampling and Testing 4
2.2.4 Monitoring Schedule 5

3. RESULTS 7

3.1 Groundwater Flow Conditions 7

3.2 Reduction/Oxidation Conditions 7

3.3 Bioremediation Indicators 7

3.4 Volatile Organic Compound Conditions 8

3.5 Site-Specific RAOs 8

4. CONCLUSIONS 10

5. RECOMMENDATIONS 11

6. LIMITATIONS AND USE OF REPORT 12

APPENDICES

Appendix A	Tables
Appendix B	Figures
Appendix C	Analytical Laboratory Reports
Appendix D	Photographs

1. INTRODUCTION

Leader Professional Services, Inc. ("Leader") was retained by RoCo, Ltd. ("RoCo") to implement a Remedial Action Plan ("RAP") and a groundwater monitoring program, under the Voluntary Cleanup Program ("VCP") guidelines, for the property at 1746 Dale Road, Cheektowaga, Erie County, New York (hereafter referred to as "the Site"). This RAP Report includes a summary of the September 2005 remedial activities and the subsequent monitoring results obtained at the Site.

1.1 Background

Leader prepared and submitted a March 2004 VCP Supplemental Site Investigation ("SSI"), Bioremediation Pilot Study ("BPS") and RAP document for the Site that was approved by NYSDEC for implementation (see the March 2004 submittal for additional background information regarding the Site). Implementation of the RAP portion of this document was delayed due to a pending potential property transaction. The monitoring well repair and Hydrogen Release Compound ("HRC®-X") injection portion of the RAP was ultimately implemented in September 2005. These remedial activities were followed by monthly groundwater level and water quality measurements through February 2007. Bimonthly analytical testing summaries for three (3) of the monitoring wells were submitted electronically to the New York State Department of Environmental Conservation ("NYSDEC") throughout the course of the monitoring program. NYSDEC requested that a summary report be submitted to assess the progress of the remedial activities to date.

1.2 Purpose

The purpose of this RAP Report is to summarize the effectiveness of the September 2005 HRC®-X injections in enhancing the natural biodegradation of chlorinated solvents in the Site's groundwater.

1.3 Scope of Work

The RAP consisted of the following tasks:

- Zebra Environmental, Inc. ("Zebra") was mobilized to the Site on September 20-22, 2005 and HRC®-X was injected at twenty-five (25) locations;
- Approximately 1,440 pounds of HRC®-X was injected into the subsurface soils throughout the areas of chlorinated solvent concentrations above applicable NYSDEC recommended cleanup objections for soil or groundwater standards;
- The month prior to HRC®-X injection and each month following, Leader monitored field parameters (i.e., Redox and groundwater measurements) in GW-1, GW-2, GW-3, GW-4, GW-5, GW-6 and GW-7;
- Every other month starting with December 2005, one groundwater sample was collected from GW-1, GW-3, and GW-7 and analyzed for sulfate, total organic carbon ("TOC"), dissolved iron and target compound list ("TCL") volatile organic compound ("VOC") analysis using USEPA Method 8260;
- Bi-monthly reports were electronically submitted to NYSDEC; and
- This written report was prepared relating the findings of the RAP monitoring program.

2. FIELD ACTIVITIES

This section summarizes the RAP field activities, which involved a full-scale bioremediation program at the Site. The activities summarized herein were conducted in general accordance with the NYSDEC-approved Health and Safety Plan and QA/QC Plan for this VCP. Photographs taken during the RAP field activities are included in Appendix D.

2.1 HRC Injection Activities

Zebra mobilized the following equipment to the Site for the implementation of the RAP: 1) a track unit; 2) a core drill; 3) a GS2000 pump; and 4) HRC®-X. The injection points were drilled and HRC®-X was injected into the points. A core drill was used for each interior injection point to core through the concrete floor within the building structure.

The Geoprobe unit was used to bore to the desired depth. The pump was then attached to the Geoprobe unit and the HRC®-X was injected into the ground under 2,000-pounds per square-inch of pressure. The HRC®-X was poured through a screen into a pump unit for injection. The screen was used to prevent solidified clumps of HRC®-X from clogging the pump unit. After completion of the injections, each point was covered and sealed with asphalt.

The number of injection points and the pounds of HRC®-X applied at each point were estimated by Regenesis (i.e., the HRC®-X Supplier), based on the level of contamination in the area. Approximately 1,440 pounds of HRC®-X was injected into the subsurface soils throughout the areas of chlorinated solvent concentrations above applicable NYSDEC recommended cleanup objections for soil or groundwater standards. The amount of HRC®-X proposed was estimated by Regenesis based on empirical equations that take into account the contaminant levels, soil conditions and groundwater conditions. Table 1 – HRC®-X Dispersion Remedial Plan (see Appendix A) includes the loading amounts for each injection point. Figure 1 (see Appendix B) includes the twenty-five (25) injection point locations. Injection points IP-1 through IP-6 were located within the

interior of the Site building, injection points IP-7 through IP-18 were located west of the Site on the Upstate Farms Cooperative, Inc. property, and injection points IP-19 through IP-25 were located north of the Site on the Davis Electrical Supply Company property.

2.2 Groundwater Monitoring Program

The groundwater monitoring program consisted of the following two (2) tasks: 1) monthly groundwater elevation and Redox measurements in the seven (7) monitoring wells; and 2) bi-monthly groundwater sampling analytical testing. These tasks are summarized in the following sections.

2.2.1 Groundwater Elevation Measurements

The depth to groundwater was measured in each well using a Solinist water level indicator. Water level measurements were obtained to the nearest hundredth of a foot. These data are included on Table 2 in Appendix A.

The groundwater elevations measured on December 22, 2005, April 16 2006, July 28, 2006 and October 18, 2006 were plotted on a Site map (see Appendix B – Figures 2 through 5 Groundwater Contour Maps). Linear interpolation methods were used to approximate the groundwater contours.

2.2.2 Reduction/Oxidation Measurements

Reduction/Oxidation ("Redox") measurements were obtained from October 2005 through February 2007 (see Table 2 – Appendix A). Measurements were taken to the nearest 1.0 mV using an ORPTestr™ reduction/oxidation meter.

2.2.3 Groundwater Sampling and Testing

Field samples were collected in accordance with the Site-specific QA/QC Plan. The monitoring wells were purged and allowed to recharge prior to each sampling event. Samples were collected using dedicated tubing and check valves to prevent cross-contamination. Groundwater samples from GW-1, GW-3 and GW-7 were submitted

bimonthly to Paradigm Environmental Laboratories for analyses for TCL VOC analysis USEPA Method 8260, TOC, Dissolved Iron, and Sulfate.

2.2.4 Monitoring Schedule

The month prior to HRC®-X injection (August 2005) and each month following, Leader monitored field parameters (i.e., Redox and groundwater measurements) in GW-1, GW-2, GW-3, GW-4, GW-5, GW-6 and GW-7. Groundwater samples were collected from GW-1, GW-3, and GW-7 on a bimonthly basis starting with December 2005.

Following completion of the first 12-month period of monitoring, Leader contacted NYSDEC and it was agreed to extend the monitoring program another 6 months prior to preparation of this RAP report. This extension was based on groundwater quality data that indicated that the HRC®-X was still having a positive effect on reducing contaminant levels. The following schedule presents the monitoring program for the RAP to date.

Month	Groundwater Measurements	Redox	Analytical Testing
August 2005	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7
September 2005	X	Meter Malfunction	
October 2005	X	X	
November 2005	X	X	
December 2005	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7
January 2006	X	X	
February 2006	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7
March 2006	X	X	
April 2006	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7

May 2006	X	X	
June 2006	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7
July 2006	X	X	
August 2006	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7
September 2006	X	X	
October 2006	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7
November 2006	X	X	
December 2006	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7
January 2007	X	X	
February 2007	X	X	Sulfate, TOC, Iron, VOCs in Monitoring Wells GW-1, GW-3, and GW-7

3. RESULTS

3.1 Groundwater Flow Conditions

Based on the groundwater elevations measured in the monitoring wells (see Table 1), it appears that the general direction of groundwater flow is from north to the south. However, the data show a localized groundwater high point in the area of monitoring well GW-3 (see Appendix B – Figures 2 through 5). Thus, groundwater appears to flow radially away from GW-3 in all directions. This condition may be the result of underground utilities, potential roof water infiltration through the concrete trench inside the building or heterogeneous subsurface conditions under the building.

3.2 Reduction/Oxidation Conditions

Monthly Redox measurements were obtained from all monitoring wells from October 2005 through February 2007. Based on these measurements, it appears that reducing conditions were present in the majority of the monitoring wells through November 2006. There has been a slight upward trend in Redox levels in GW-1, GW-2, GW-4, GW-6 and GW-7 since the November 2006 event. Redox levels in GW-3 and GW-5 have remained relatively constant or decreased since November 2006. The upward trend at some of the monitoring well locations may indicate that the HRC®-X is expended at these locations.

3.3 Bioremediation Indicators

Groundwater samples from monitoring wells GW-3, GW-4 and GW-7 were submitted for TOC, Dissolved Iron, and Sulfate (see Appendix A - Table 3). Based on technical input from Regenesis, bioremediation activity is indicated by a decrease in sulfate concentrations, an increase in TOC concentrations and an increase in iron concentrations.

The samples from GW-1 indicate a decrease in sulfate, an increase in TOC and relatively no change in iron. Thus, bioremediation appears to be occurring at GW-1. The samples from GW-3 indicate a decrease in sulfate, an increase in TOC and an increase in iron. Thus, bioremediation appears to be occurring at GW-3. The samples from GW-7

indicate an increase in sulfate, a decrease in TOC and relatively no change in iron. Significant bioremediation does not appear to be occurring at GW-7.

3.4 Volatile Organic Compound Conditions

Table 4 (Appendix A) includes the VOC concentrations in GW-1, GW-3 and GW-7 for the RAP monitoring period. Trichloroethylene ("TCE") concentrations were reduced by the HRC®-X in all three (3) monitoring wells. The concentrations of VOCs in the February 2007 groundwater sample from GW-1 were only slightly above NYSDEC groundwater standards. The only VOC detected in the February 2007 sample from GW-7 was DCE at a concentration of 616 ppb; however, in October 2006, the DCE concentration was only 9.09 ppb.

Figure 6 includes the VOC data for GW-3 from 2001 through February 2007. As shown on Figure 6, major VOC concentration changes occurred after the September 2005 HRC®-X injection. TCE concentrations have dropped from the historical high of 161,000 ppb (10/24/02) down to less than 2,000 ppb (2/26/07). The concentrations of the TCE daughter products, cis-1,2-dichloroethene ("DCE") and vinyl chloride ("VC"), have increased orders of magnitude in GW-3 indicating biodegradation at the source. The total VOC concentration in GW-3 has dropped from over 100,000 ppb (TCE and DCE combined) in September 2005 to 40,600 ppb (DCE and VC combined) in February 2007.

3.5 Site-Specific RAOs

The general Remedial Action Objectives ("RAOs") for this VCP are summarized below.

- To prevent future exposure of human or animal receptors to contaminated groundwater or soil; and
- To prevent or mitigate the migration of contaminants that will cause groundwater contamination above the site-specific RAOs

As stated in the RAP, bioremediation using HRC®-X may not result in groundwater concentrations at all monitoring well locations being below drinking water standards

(e.g., the groundwater standard for trichloroethylene ["TCE"] is 0.7 ppb). Thus, Site-specific RAOs have been developed that achieve the General RAOs while providing for some flexibility should future remedial efforts reach a point of diminishing returns. These site-specific RAOs are summarized below.

- Future residual groundwater and/or soil contamination will not pose an unacceptable risk to human health and the environment;
- The residual groundwater and soil contamination, if present, will be compatible with the anticipated future use of the site; and
- An approximate "zero slope" will be reached with regard to groundwater quality (i.e., continued treatment will not result in a decrease in the concentration of analytes in the groundwater).

This approach is reasonable based on the following site-specific conditions:

- The local groundwater currently has no beneficial use and is unlikely to be used in the foreseeable future;
- The present lack of completed pathways of human exposure and the absence of a significant threat to public health;
- The technical impracticability of restoring the groundwater to pre-release conditions, given the inaccessibility of the source area and the heterogeneous subsurface conditions; and
- The site's commercial/industrial setting and the absence of sensitive environmental receptors.

As of February 2007, these objectives have been generally achieved at monitoring wells GW-1 and GW-7. The concentrations of DCE and VC in monitoring well GW-3 do not appear to have reached a "zero slope" with regard to VOC concentration reduction.

4. CONCLUSIONS

Below are the conclusions that have been developed based on the results of the RAP monitoring program.

1) Based on the groundwater elevations measured in the monitoring wells, it appears that the general direction of groundwater flow is from north to the south. However, the data show a localized groundwater high point in the area of monitoring well GW-3. Thus, groundwater appears to flow radially away from GW-3 in all directions.

2) Monthly Redox measurements were obtained from all monitoring wells from October 2005 through February 2007. Based on these measurements, it appears that reducing conditions were present in the majority of the monitoring wells through November 2006. The subsequent upward trend at some of the monitoring well locations may indicate that the HRC®-X is expended at these locations.

3) The analyses for sulfate, TOC and dissolved iron were conducted to evaluate HRC®-X activity. Bioremediation, as a result of the HRC®-X, appears to be continuing at GW-1 and GW-3.

4) TCE concentrations were reduced by the HRC®-X in all three (3) monitoring wells.

5) The total VOC concentration in GW-3 has dropped from over 100,000 ppb (TCE and DCE combined) in September 2005 to 40,600 ppb (DCE and VC combined) in February 2007.

6) As of February 2007, the RAOs have been generally achieved at monitoring wells GW-1 and GW-7. The concentrations of DCE and VC in monitoring well GW-3 do not appear to have reached a "zero slope" with regard to VOC concentration reduction.

5. RECOMMENDATIONS

Based on the results of the RAP monitoring program, the HRC®-X was effective in reducing chlorinated solvent concentrations in groundwater at the Site. Based on monitoring of the bioremediation indicator parameters, the initial injection of HRC®-X does not appear to have reached its useful life as of February 2007. Thus, continued monitoring is recommended for another six (6) months. A dissolved gas analysis (i.e., methane, ethane and ethene) of GW-3 will be included in one of the future sampling events to evaluate how much gas is present. If it appears that the concentrations of DCE and VC at GW-3 are not reducing, an additional limited injection of HRC in the area of GW-3 should be considered to increase the degradation rate.

Based on conversations with the NYSDEC and the New York State Department of Health ("NYSDOH"), soil gas ventilation and monitoring issues will be evaluated following remediation. Sampling soil gas vapors beneath the building following completion of the RAP will allow for a more representative sampling program and a more effective ventilation system design, if required. Leader will meet with the NYSDEC and the NYSDOH following the completion of remedial activities.

6. LIMITATIONS AND USE OF REPORT

This RAP report was prepared by Leader Professional Services, Inc. in accordance with generally accepted practices of other consultants preparing similar reports, and we observed that degree of care and skill generally exercised by other consultants under similar circumstances and conditions. The analyses and conclusions submitted in this report are based upon data and information, provided by others, and are contingent upon their validity.

This Voluntary Cleanup Program RAP report was prepared exclusively for RoCo for specific application to the Site in accordance with generally accepted engineering practice. No other warranty, expressed or implied, is made.

APPENDIX A
TABLES

TABLE 1 HRC-X INJECTION QUANTITIES
RoCo, Ltd. 1746 Dale Road, Cheektowaga, New York

Injection Point Designation	Approximate Depth of Injection Point (ft)	Approximate Pounds of HRC-X Injected
IP-1	12	90
IP-2	12	90
IP-3	12	90
IP-4	12	90
IP-5	12	90
IP-6	12	90
IP-7	12	40
IP-8	12	40
IP-9	12	60
IP-10	12	60
IP-11	12	60
IP-12	12	60
IP-13	12	60
IP-14	12	60
IP-15	12	60
IP-16	12	60
IP-17	12	60
IP-18	12	40
IP-19	12	40
IP-20	12	40
IP-21	12	40
IP-22	12	40
IP-23	12	40
IP-24	12	40
IP-25	12	40
	TOTAL =	**1,480**

NOTE - See Figure 1 for injection point locations.

TABLE 2 - GROUNDWATER DEPTH AND ELEVATION DATA
RoCo, Ltd. 1746 Dale Road, Cheektowaga, New York

Groundwater Depths and Elevations														
	GW-1		GW-2		GW-3		GW-4		GW-5		GW-6		GW-7	
Date	Depth (Ft.)	Elev. (Ft.)	Depth (Ft.)	Elev. (Ft.)	Depth (Ft.)	Elev. (Ft.)	Depth (Ft.)	Elev. (Ft.)	Depth (Ft.)	Elev. (Ft.)	Depth (Ft.)	Elev. (Ft.)	Depth (Ft.)	Elev. (Ft.)
09/22/05	1.16	654.63	1.60	655.32	3.06	655.28	3.14	655.26	11.10	648.41	2.92	655.47	3.78	654.53
10/31/05	1.30	654.49	1.52	655.40	2.60	655.74	3.16	655.24	8.14	651.37	3.49	654.90	4.58	653.73
11/29/05	0.85	654.94	1.05	655.87	1.80	656.54	2.66	655.74	7.82	651.69	3.26	655.13	3.41	654.90
12/22/05	0.78	655.01	0.89	656.03	1.65	656.69	2.58	655.82	9.20	650.31	3.24	655.15	3.65	654.66
01/20/06	0.80	654.99	1.02	655.90	1.95	656.39	2.66	655.74	8.19	651.32	1.94	656.45	3.35	654.96
03/01/06	1.27	654.52	1.67	655.25	2.85	655.49	3.38	655.02	8.42	651.09	3.30	655.09	4.02	654.29
03/27/06	1.71	654.08	1.72	655.20	2.94	655.40	3.39	655.01	8.42	651.09	2.86	655.53	4.00	654.31
04/18/06	1.48	654.31	1.69	655.23	2.77	655.57	3.15	655.25	8.48	651.03	3.60	654.79	3.76	654.55
05/17/06	1.15	654.64	1.71	655.21	2.47	655.87	3.05	655.35	8.35	651.16	3.85	654.54	3.72	654.59
06/14/06	1.61	654.18	2.00	654.92	2.91	655.43	3.37	655.03	8.33	651.18	3.45	654.94	3.89	654.42
07/28/06	1.58	654.21	1.95	654.97	2.80	655.54	3.20	655.20	8.16	651.35	3.43	654.96	3.90	654.41
08/08/06	1.52	654.27	1.87	655.05	2.72	655.62	3.12	655.28	8.10	651.41	3.41	654.98	3.92	654.39
09/22/06	1.27	654.52	1.56	655.36	2.40	655.94	2.77	655.63	7.93	651.58	3.31	655.08	3.36	654.95
10/18/06	0.78	655.01	1.04	655.88	1.57	656.77	2.17	656.23	6.86	652.65	2.97	655.42	2.57	655.74
11/27/06	1.67	654.12	1.85	655.07	2.91	655.43	3.23	655.17	8.24	651.27	3.43	654.96	3.45	654.86
12/11/06	1.16	654.63	1.38	655.54	2.61	655.73	2.89	655.51	8.28	651.23	3.66	654.73	3.97	654.34
01/26/07	1.07	654.72	1.44	655.48	2.54	655.80	2.63	655.77	8.17	651.34	3.64	654.75	3.71	654.60
02/26/07	1.60	654.19	1.52	655.40	2.70	655.64	2.70	655.70	8.47	651.04	4.70	653.69	3.97	654.34




TABLE 3 - REDOX MEASUREMENTS
RoCo, Ltd. 1746 Dale Road, Cheektowaga, New York

	REDOX (mV)						
Date	GW-1	GW-2	GW-3	GW-4	GW-5	GW-6	GW-7
10/31/05	11	56	-167	-140	-17	-198	-41
11/29/05	91	104	-115	-129	95	-146	114
12/22/05	10	-16	-151	-145	-25	-39	-125
01/20/06	102	125	-95	-85	-95	171	182
03/01/06	-94	-1	-68	-83	123	146	133
03/27/06	-79	-7	-97	-98	130	151	136
04/18/06	44	71	-138	-151	148	179	162
05/17/06	-144	-22	-134	-206	122	-190	-87
06/14/06	-132	-17	-132	-153	28	-217	-207
07/28/06	-74	40	-90	-70	87	-110	-111
08/08/06	-72	51	-84	-68	92	-119	-105
09/22/06	-122	-5	-135	-150	116	-110	-139
10/18/06	-112	-66	-127	-106	78	-29	-115
11/27/06	-37	13	-80	-120	121	-102	-68
12/11/06	12	223	-129	-92	68	72	58
01/26/07	-3	176	-147	-76	38	49	51
02/26/07	-46	201	-94	-81	34	48	49

T




TABLE 4 - BIOREMEDIATION WATER QUALITY PARAMETERS

RoCo, Ltd. 1746 Dale Road, Cheektowaga, New York

ANALYTE	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	Total Change
Sample Collection Date:	09/23/05	12/27/05	03/01/06	04/18/16	06/14/06	08/08/06	10/18/06	12/11/06	02/26/07	04/12/07	
Units:	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	
Sulfate	37.0	31.0	30	30	36	36	25	26	27	25	-32%
Total Organic Carbon	1.60	19.9	1.5	1.7	2.5	2.6	3.1	2.2	3.0	1.1	-0.5
Dissolved Iron	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1	0.00

ANALYTE	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	Total Change
Sample Collection Date:	09/23/05	12/27/05	03/01/06	04/18/06	06/14/06	08/08/06	10/18/06	12/11/06	02/26/07	04/12/07	
Units:	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	
Sulfate	99.0	ND<2.0	ND<2.0	ND<2.0	ND<2.0	ND<2.0	5.1	ND<2.0	ND<2.0	ND<2.0	-100%
Total Organic Carbon	35.7	608	1,230	2,130	750	770	285	227.00	202.00	186.00	150.3
Dissolved Iron	0.82	63.7	35.50	36.00	86.10	<0.1	60.0	47.4	44.1	40.5	39.68

ANALYTE	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	Total Change
Sample Collection Date:	09/23/05	12/27/05	03/01/06	04/18/06	06/14/06	08/08/06	10/18/06	12/11/06	02/26/07	04/12/07	
Units:	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	
Sulfate	59	73	71	70	71	62	10	35	86	78	32%
Total Organic Carbon	3.3	5.5	3.1	3.3	7.1	4.6	4.1	3.4	4.4	3.1	-0.2
Dissolved Iron	<0.1	<0.1	<0.1	<0.1	1.08	<0.1	<0.1	<0.1	<0.1	<0.1	0.00

Notes:

1) Concentrations are in mg/l, or ppm.
2) NA (Not Available)
3) Desired sulfate decrease.
4) Desired TOC increase of 20-500 ppm.
5) Desired iron increase of 2-30 ppm. increase
6) Total change measured from 9/22/05 value and 2/26/07 value.

TABLE 5 - GROUNDWATER ANALYSIS FOR VOLATILE ORGANIC COMPOUNDS

RoCo, Ltd. 1746 Dale Road, Cheektowaga, New York

VOLATILE ORGANIC COMPOUNDS	NYSDEC CLASS GA STANDARD	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1	GW-1
Sample Collection Date:	NA	11/9/01	9/23/02	10/24/02	11/26/02	12/31/02	1/28/03	2/27/03	6/27/03	9/26/05	12/27/05	3/1/06	4/18/06	6/14/06	8/8/06	10/18/06	12/11/06	2/26/07	4/12/07
Units:	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L
Tetrachloroethene (PCE)	5.00	ND<5.00	NS	NS	NS	NS	NS	NS	NS	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00
Trichloroethene (TCE)	5.00	7.09	NS	NS	NS	NS	NS	NS	NS	ND<2.00	ND<2.00	52.40	ND<2.00	ND<2.00	2.04	ND<2.00	3.29	3.26	2.92
cis-1,2-Dichloroethene (DCE)	5	481	NS	NS	NS	NS	NS	NS	NS	E 276	154	16	206	152	195	153	158	112	116
trans-1,2-Dichloroethene	5.00	5.42	NS	NS	NS	NS	NS	NS	NS	2.54	2.10	ND<2.00	3.40	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00	ND<2.00
Vinyl Chloride	2	291	NS	NS	NS	NS	NS	NS	NS	121	ND<2.00	ND<2.00	ND<2.00	20.80	102.00	4.15	ND<2.00	3.80	ND<2.00
Benzene	1.00	ND<5.00	NS	NS	NS	NS	NS	NS	NS	ND<0.70	ND<0.70	ND<0.71	ND<2.00	ND<0.70	ND<0.70	ND<0.70	ND<0.70	ND<0.70	ND<0.70


VOLATILE ORGANIC COMPOUNDS	NYSDEC CLASS GA STANDARD	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3	GW-3
Sample Collection Date:	NA	11/9/01	9/23/02	10/24/02	11/26/02	12/31/02	1/28/03	2/27/03	6/27/03	9/26/05	12/27/05	3/1/06	4/18/06	6/14/06	8/8/06	10/18/06	12/11/06	2/26/07	4/12/07
Units:	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L
Tetrachloroethene (PCE)	5.00	ND<1,000	ND<400	ND<2,000	ND<1,000	ND<2,000	ND<2,000	ND<2,000	ND<2,000	ND<1,000	ND<2,000	ND<1,000	ND<1,000	ND<2,000	ND<1,000	ND<100	ND<2,000	ND<2,000	ND<2,000
Trichloroethene (TCE)	5.00	71,600	52,500	161,000	84,600	80,300	122,000	102,000	153,000	75,600	ND<2,000	ND<1,000	ND<1,000	ND<2,000	ND<1,000	ND<100	ND<2,000	ND<2,000	ND<2,000
cis-1,2-Dichloroethene (DCE)	5	4,860	5,010	7,500	4,190	3,390	4,570	4,410	7,210	38,400	60,500	57,800	89,400	48,600	26,300	2,590	19,800	19,100	22,600
trans-1,2-Dichloroethene	5.00	ND<1,000	ND<400	ND<2,000	ND<1,000	ND<2,000	ND<2,000	ND<2,000	ND<2,000	ND<1,000	ND<2,000	ND<1,000	ND<1,000	ND<2,000	ND<1,000	ND<100	ND<2,000	ND<2,000	ND<2,000
Vinyl Chloride	2	ND<1,000	ND<400	ND<2,000	ND<1,000	ND<2,000	ND<2,000	ND<2,000	ND<2,000	ND<1,000	8,630	20,400	37,800	34,700	48,700	5,730	39,700	21,500	54,700
Benzene	1.00	ND<1,000	ND<140	ND<700	ND<350	ND<700	ND<700	ND<700	ND<700	ND<350	ND<700	ND<350	ND<350	ND<350	ND<350	ND<35.0	ND<700	ND<700	ND<700


VOLATILE ORGANIC COMPOUNDS	NYSDEC CLASS GA STANDARD	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7	GW-7
Sample Collection Date:	11/9/01	7/16/02	9/23/02	10/24/02	11/26/02	12/31/02	1/28/03	2/27/03	6/27/03	9/26/05	12/27/05	3/1/06	4/18/06	6/14/06	8/8/06	10/18/06	12/11/06	2/26/07	4/12/07
Units:	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L
Tetrachloroethene (PCE)	5.00	ND<100	NS	NS	NS	NS	NS	NS	ND<10.0	ND<40	ND<20	ND<20	ND<20	ND<200	ND<20	ND<2.00	ND<20	ND<20	ND<20
Trichloroethene (TCE)	5.00	624	NS	NS	NS	NS	NS	NS	158	545	ND<20	94.00	128.0	ND<200	ND<20	ND<2.00	ND<20	ND<20	ND<20
cis-1,2-Dichloroethene (DCE)	5	6,120	NS	NS	NS	NS	NS	NS	582	4,350	1,530	1,800	2,080	1,770	648	9.09	308.00	616.00	685.00
trans-1,2-Dichloroethene	5.00	ND<100	NS	NS	NS	NS	NS	NS	ND<10.0	62.40	ND<20	23.50	ND<20	ND<200	ND<20	ND<2.00	ND<20	ND<20	ND<20
Vinyl Chloride	2	1,410	NS	NS	NS	NS	NS	NS	36.0	686	23.4	ND<20	ND<20	342.00	992.00	24.70	ND<20	ND<20	ND<20
Benzene	1.00	ND<35.0	NS	NS	NS	NS	NS	NS	ND<3.50	ND<14.0	ND<7.00	ND<7.00	ND<7.00	ND<70	ND<7.00	ND<0.7	ND<0.7	ND<0.7	ND<0.7

Notes:


1) First post-injection sampling event was 9/26/05
2) ND (Non-Detected above laboratory detection limit)
3) NA (Not Available), NS (Not Sampled)
4) Green shaded values indicate an exceedence of NYCRR Part 703 Class GA groundwater standards.

APPENDIX B
FIGURES


ANDERSON ROAD
DALE ROAD
THE ROTARY COMPANY, INC.
LEGEND:
B-1 BORE HOLE LOCATION-PREVIOUS STUDIES
BH-8 BORE HOLE LOCATION-SI
GW-4 MONITORING WELL-SI
BH-15 BORE HOLE LOCATION-SSI
GW-7 MONITORING WELL-SSI
IP-5 INJECTION POINT LOCATION-RAP
NOTES:
1) SITE PLAN PREPARED BY McINTOSH & McINTOSH, P.C.
2) LOCATIONS OF SITE FEATURES AND SAMPLING LOCATIONS ARE APPROXIMATE.
RAP HRC-X INJECTION POINTS
RoCo, Ltd.
1




Title: GROUNDWATER CONTOUR MAP FOR DECEMBER 22, 2005 RoCo, Ltd., Cheektowaga, New York	Lander Professional Services, Inc.	Project Number: 147.007 Date: MARCH 2007 Drawn By: KCC / Checked By: JAW Books:	Figure Number: 2
Prepared For: RoCo, Ltd.			



NOTES:

1) GROUNDWATER ELEVATION MEASUREMENTS OBTAINED ON APRIL 18, 2006 USING AN ELECTRONIC WATER LEVEL INDICATOR.
2) GROUNDWATER CONTOUR LINES ARE BASED UPON LINEAR INTERPOLATION BETWEEN MONITORING WELLS AND SHOULD BE CONSIDERED ACCURATE TO THE DEGREE IMPLIED BY THE METHOD USED.
3) WELL MONITORING POINT ELEVATIONS WERE OBTAINED BY McINTOSH & McINTOSH, PC AND REFERENCED TO NGVD.

Title: GROUNDWATER CONTOUR MAP FOR APRIL 18, 2006 RoCo, Ltd., Cheektowaga, New York	Leader Professional Services, Inc.	Project Number: 147.000 Date: MARCH 2007 Drawn By: KCC / Checked By: JAW Scale: NONE	Figure Number: 3
Prepared For: RoCo, Ltd.			



Title: GROUNDWATER CONTOUR MAP FOR JULY 25, 2006 RoCo, Ltd., Cheektowaga, New York	Lozier Professional Services, Inc.	Project Number: 147.007 Date: MARCH 2007 Drawn By: KCC Checked By: JAW Scale: NONE	Figure Number: 4
Prepared For: RoCo, Ltd.			




REPUTED OWNER
TRONCAR
PETRARCA CO-OP
L-8644, P-378
ASPHALT PARKING AREA
REPUTED OWNER
RICHARD A. RIVETA
L-9058, P-672
BUILDING
MW-2
MW ELEV.
666.66'
BH-6
BH-5
ASPHALT
BH-19
BH-18
BH-17
MW-7
MW ELEV.
666.74'
MW-6
MW ELEV.
666.47'
MW-4
MW ELEV.
666.25'
BH-7
MW-3
MW ELEV.
666.77'
BH-8
106.20' DEED
BH-4
BH-9
60' DEED
MW-5
MW ELEV.
666.65'
140.40' DEED
BH-14
BH-13
BH-10
BH-12
BH-11
BENCHMARK TOP OF METAL PLUGGED AT CORNER OF POWER CONCRETE HOUSING AREA - ELEV. 667.69
ONE STORY BUILDING NO. 1748
REPUTED OWNER
T.E. ROTARY COMPANY, INC.
L-5485, P-488
L-5485, P-488
2nd DESCRIBED PARCEL
ASPHALT PARKING AREA
123.77' DEED
MW-1
MW ELEV.
665.69'
110.00'
1.0'
75.7'
BH-1
BH-2
ASPHALT PARKING AREA
DALE ROAD
(66.0' WIDE)
177.65' DEED
350.77' DEED ADDITION
(FORMERLY WALDEN AVENUE)
147.79' DEED
ANDERSON ROAD
(FORMERLY 100.0' WIDE RIGHT-OF-WAY)
(FORMERLY GRISS ROAD)
LEGEND
OE OVERHEAD ELECTRIC
OE/T OVERHEAD ELECTRIC & TELEPHONE
CHAIN LINK FENCE
POWER POLE
MW-1 MONITORING WELL
BH-1 BORE HOLE LOCATION
NOTES:
1) GROUNDWATER ELEVATION MEASUREMENTS OBTAINED ON OCTOBER 18, 2006 USING AN ELECTRONIC WATER LEVEL INDICATOR.
2) GROUNDWATER CONTOUR LINES ARE BASED UPON LINEAR INTERPOLATION BETWEEN MONITORING WELLS AND SHOULD BE CONSIDERED ACURATE TO THE DEGREE IMPLIED BY THE METHOD USED.
3) WELL MONITORING POINT ELEVATIONS WERE OBTAINED BY MCINTOSH & MCINTOSH, PC AND REFERENCED TO MSVD.
Title
GROUNDWATER CONTOUR MAP FOR OCTOBER 18, 2006
RoCo, Ltd., Cheektowaga, New York
Prepared For
RoCo, Ltd.
Lozier Professional Services, Inc.
Project Number 147.007
Date: MARCH 2007
Drawn By: KCC
Checked By: JAW
Scale: NONE
Figure Number
5

Figure 6
VOC Concentration Data for GW-3



June 15, 2020

Dale Anderson, LLC
1746 Dale Road
Cheektowaga, New York
Via email: Psycus@yahoo.com

Re: **Compliance Management Report**
SVES Evaluation and Monitoring Well Sampling
1746 Dale Road
Cheektowaga, New York
NYSDEC Site No: 915330
WGS Project No. 18110

To Whom it may concern

Wittman GeoSciences, PLLC (WGS) was retained by Dale Anderson, LLC to complete SSDS Evaluation and Monitoring Well Sampling for the above-referenced (subject) site. WGS previously reviewed the New York State Department of Environmental Conservation (NYSDEC) records associated with the site. Additionally, WGS had several conversations with NYSDEC representative David Locey, regarding site status and work needed to meet NYSDEC requirements.

BACKGROUND

The site at 1746 Dale Road, located in Cheektowaga, NY, was previously owned by RoCo Ltd. Previous site investigation and remedial work was completed on site, dating to 2000. Subsurface volatile organic compound (VOC) contamination were identified on-site, associated with past operations dating to the 1950s. Trichloroethylene (TCE) was identified in the northwestern area of the building, in an old metal prep room, at concentrations of approximately 153,000 parts per billion (ppb) in groundwater well GW3.

RoCo. Ltd. entered into a Voluntary Cleanup Agreement (VCA #B9-0588-01; Site #V00422) with NYSDEC in 2001. RoCo completed in-situ bioremediation system to treat groundwater, including injection of a hydrogen release compound from 2002 to 2008. During this timeframe, reports showed TCE reduction in GW-3 to 10 ppb, and total VOCs to 138 ppb. A Site Management Plan was submitted; however, RoCo abandoned the site and further remedial work was not completed.

Dale Anderson LLC purchased the property in auction in 2014. IEG completed groundwater sampling of existing on-site wells, and vapor intrusion sampling within the metals prep room. Groundwater testing results identified total VOCs at GW3 at concentration of 61,219 ppb, with the other five wells ranging from 5.4 to 572 ppb. The VOCs detected within GW3 included cis-1,2-dichloroethene (DCE) and vinyl chloride (VC) at concentrations of 34,000 ppm and 27,000 ppb, respectively. IEG noted that TCE was a source compound at the site, and DCE and VCE are degradation products associated with the in-situ bioremediation that was completed.

One sub-slab soil vapor sample was collected by IEG in 2014, which identified TCE at a concentration of 190,000 ug/m^3. TCE was previously detected in a sub-slab soil vapor sample near GW3 at a concentration of 303 ug/m^3. IEG noted that the DCE and VC, which were TCE degradation products, appeared to have rebounded in groundwater from the 2009 levels. Additionally, sub-slab soil vapor also appeared to have accumulated significant levels of TCE, far exceeding previous reported levels.

Due to the high levels of TCE in the sub-slab sample in the metal prep room, IEG installed a sub-slab vapor extraction system (SVES) in the northwestern corner of the site building. The SVES consisted on two (2) soil vapor extraction points, as shown on Figure 1. A carbon drum was used to treat the soil vapor before discharge to the atmosphere, to address the TCE concentrations. IEG indicated that carbon drum could be discontinued once VOCs levels decrease.

IEG also indicated that a soil vapor intrusion investigation would be completed at the northern adjoining property at 24 Anderson Road, due to a 2007 investigation which indicated that monitoring was recommended in the building. However, WGS understands that after several attempts by Dale Anderson LLC, the northern adjoining property owner has not allowed access to complete further sampling.

SVES EVALUATION

The existing SVES was installed as part of the previously approved NYSDEC work plan. Initial SVES sampling was to include monitoring vacuum at select locations on a weekly basis, as well as SVES influent and effluent sampling on a monthly basis. The vacuum testing and the influent/effluent sampling has not been completed since 2016.

The metal prep room had an approximate one-foot wide by 4-inch deep trench around the room, which limited vacuum effectiveness. The trench was located within one to two feet from the vapor extraction points, and likely impacted, and limited, the vacuum influence area. In order to increase the efficiency of the SVES, the trench was filled with concrete about one month prior to completion of SVES evaluation.

The SVES includes a Radonaway GS501 fan, capable of a maximum vacuum of 4.2 inches of water column and 95 cubic feet per minute open flow. Communication testing was completed within the metal prep room, to evaluate vacuum measurements of the sub slab floor in various locations. Vacuum testing locations are included on Figure 2. The testing confirmed that a vacuum is present under the metal prep room with the current SVES configuration. Additionally, the vacuum extents to the south, into the next room. Further vacuum testing was done after removal of the carbon drum, in which a greater vacuum was realized, as well as a slightly larger area, also shown on Figure 2. Based on communication testing, the SVES, as currently configured, does provide vacuum throughout the metal prep room.

SVES SYSTEM VAPOR SAMPLING AND RESULTS

WGS collected in-line sampling at the two existing vapor extraction points. The sampling was completed from access ports located approximately one to two feet above the concrete floor, allowing each sample to be collected prior to carbon filtration. A one-liter summa canister was

used to collect the sample. The canister was equipped with a grab sample regulator, allowing a grab sample to be collected over a short period of time, ranging from 5 to 10 minutes.

Each vapor extraction point sample was analyzed for VOCs via TO-15. Results are presented on Table 1 and included in Attachment A. NYSDOH has specific air guideline values for limited compounds as presented in Table 3.1 in the Guidance for Evaluating Soil Vapor Intrusion in the State of New York, dated October 2006, with various updates. NYSDOH does not have air guidance for sub-slab sample results specifically. NYSDOH guidance does provide "background levels" of compounds for outdoor air and indoor air. Within Appendix C of the guidance, NYSDOH provides USEPA the 2001 Building Assessment and Survey Evaluation (BASE) Database, which is a study of measured concentrations of VOCs from 100 randomly selected public and commercial buildings (Table C2 of NYSDOH guidance document). The NYSDOH guidance indicated that the 90th percentile values from the USEPA BASE data for indoor air for office and commercial buildings can be considered for initial benchmark values.

A summary of the detected concentrations are included in Table 1. New York State currently does not have standards, criteria or guidance values for concentrations of VOCs in sub-slab vapor samples. A summary of the results for vapor extraction points is as follows.

- **SV-01/VP1** – Seventeen (17) compounds were detected above method detection limits. Four compounds were detected at levels which exceeded the 90th percentile for indoor air. TCE was detected at a concentration of 67.7 ug/m^3; cis-DCE was detected at a concentration of 16.3 ug/m^3; and VC was detected at a concentration of 6.16 ug/m^3. NYSDOH does not have sub-slab vapor guidance values.

- **SV-02/VP2** – Three (3) compounds were detected above method detection limits, with only one compound exceeding the 90th percentile for indoor air. TCE was detected at a concentration of 57.5 ug/m^3. NYSDOH does not have sub-slab vapor guidance values.

WGS provided available historical sub-slab vapor samples that have been collected at the site, which are included on Table 2. Initial sub-slab sample was collected in the metals prep room was collected in 2007, which identified TCE at a concentration of 303 ug/m3. Additionally, a sub-slab sample was collected in 2014, post groundwater remedial efforts, identified TCE at 190,000 ug/m$^{3.}$ Current sub-slab, in-line samples showed a significant decrease in TCE concentration to 67.7 ug/m^3, as well as decrease in cis-DCE concentration from 2014.

MONITORING WELL ASSESSMENT

Groundwater monitoring wells GW1 to GW5, and GW7 were measured sampled in May 2020, as part of monitoring requirements. Each well was assessed for condition and usability. The following were noted for each well, and summarized on the well data sheets in Attachment B:

- GW1 – The road box cover is missing, allowing the riser to be exposed. However, a J-plug is present. Road box repair/replacement is needed.

- GW-2 – J-plug is missing and requires replacement.

- GW-3 – Well appeared to be in good condition,

- GW-4 – Road box is damage and requires replacement.

- GW-5 – Well appeared to be in good condition.

- GW-7 – Well appeared to be in good condition.

MONITORING WELL SAMPLING

Prior to sample collection, static groundwater levels were measured at each of the monitoring wells. Groundwater depths and relative elevations are included on Table 2. Groundwater depth was generally encountered 1.5 to 6 feet below grade in. Figure 3 presents the estimated groundwater flow direction, which generally appeared to be a south to southwesterly direction.

The wells were purged and field measurements of pH, specific conductivity, temperature and turbidity were recorded and monitored for stabilization prior to sampling. Purging was considered complete when pH, specific conductivity, and temperature stabilized. Groundwater samples were collected using low flow sampling techniques. The purged water was stored in a 20-gallon drum for future off-site disposal. Well data sheets are included in Attachment B.

The six groundwater samples were analyzed for total compound list (TCL) VOCs. Groundwater samples were placed in pre-cleaned laboratory-provided sample bottles, labeled and preserved in accordance with USEPA SW-846 methodology, and transported under chain-of-custody to Alpha Analytical, a NYSDOH ELAP certified analytical laboratory.

MONITORING WELL SAMPLING RESULTS

Table 3 presents the results of detected groundwater parameters to the Class GA Groundwater Criteria per NYSDEC Division of Water Technical and Operational Guidance Series (TOGS) 1.1.1 Ambient Water Quality Standards and Guidance Values and Groundwater Effluent Limitations (June 1998). Up to five VOCs were detected in the six samples, as summarized below and included in Attachment C.

- GW1 – Four VOCs were detected above method detection limit. Cis-DCE was detected at a concentration of 34 ppb, which exceeds the Class GA Criteria of 5 ppb.

- GW2 – Three VOCs were detected above method detection limits, and also below their respective Class GA Criteria.

- GW3 – Two VOCs were detected above method detection limits. VC was detected at a concentration of 23,000 ppb and cis-DCE was detected at concentration of 8,800, both exceed their respective Class GA Criteria of 2 ppb and 5 ppb, respectively.

- GW4 – Five VOCs were detected above method detection limit. Four of the detected VOCs exceed their respective Class GA Criteria, including VC at 250 ppb; trans-DCE at 43 ppb; TCE at 91 ppb; and cis-DCE at 280 ppb.

- GW5 – Two VOCs were detected above method detection limit, as well as below their respective Class GA Criteria.

- GW7 – Five VOCs were detected above method detection limit. VC was detected at a concentration of 96 ppb and cis-DCE was detected at a concentration of 94 ppb. Both exceeded their respective Class GA Criteria of 2 ppb and 5 ppb, respectively.

Groundwater sample results did not identify initial contaminants of concern being TCE, but rather degradation compounds cis-DCE and VC. TCE was no longer detected in the six wells sampled, however, both VC and DCE concentrations are present. Historical groundwater testing results from 2014 to present are included on Table 4.

In general, VC and cis-DCE concentrations have generally been consistent, to a slight decrease for the past six years in GW1, GW2, GW3, GW5 and GW7. However, both VC and cis-DCE concentration have slightly increased in GW4. The main area of groundwater impacts remains under the northwestern portion of the building, under the former metals prep room, as depicted on Figure 4. The potential impact from the source area generally appears to extend west, south and easterly, with limited extent to the north.

CONCLUSIONS AND RECOMMENDATIONS

The SVES evaluation results confirmed that a vacuum is present under the area of concern, with the current system configuration. As the communication testing confirmed presence of a vacuum, WGS recommends that current SVES performance monitoring requirements to include weekly vacuum levels be discontinued. The manometer located on the SVES extraction line should be checked monthly, to assure the system is operational.

Based on communication testing, a greater vacuum was realized upon removal of the carbon filter. The carbon filter was initially designed and required due to the high concentration of TCE at 190,000 ug/m^3. However, current TCE concentrations at the vapor points were identified at 67.7 ug/m3 at SV-01/VP1 and 57.5 ug/m3 at SV-02/VP2. The current concentration of TCE at each of the vapor points has significantly decreased, as well as overall VOC concentrations. WGS recommends removal of the carbon filtration, at this time.

Groundwater monitoring included sampling six wells, identified as GW1 to GW5, and GW7. Three wells, including GW1, GW2, and GW4 were in poor condition, and with required replacement and/or repair of road box and J-plugs.

Groundwater testing results did not identify initial contaminants of concern being TCE, but rather degradation compounds cis-DCE and VC, since 2014. Historical groundwater testing results from 2014 to present are included on Table 4. In general, VC and cis-DCE concentrations have generally been consistent, to a slight decrease for the past six years in GW1, GW2, GW3,

GW5 and GW7. However, both VC and cis-DCE concentration have slightly increased in GW4. The main area of groundwater impacts remains under the northwestern portion of the building, under the former metals prep room, as depicted on Figure 4. Due to the generally consistent results, WGS recommends reduction of sampling frequency from quarterly to semi-annually.

In summary, WGS recommends the following alternations to current monitoring requirements:

Sub-slab SVES Monitoring

- Remove requirement for monitoring vacuum levels on weekly basis, as communication testing confirmed presence of vacuum within required area.

- Complete visual monitoring of SVES manometer monthly, to assure system is operational.

- Remove the need for carbon filtration, due to significant decrease in TCE concentration.

- Reduce SVES vapor monitoring requirements to collection of effluent samples at VP1 and VP2 on an annual basis. Samples should be grab samples and analyzed for VOCs via USEPA Method TO15.

Off-site Monitoring

- Eliminate requirement for sub-slab vapor sampling at northern adjoining property. Based on current groundwater testing results, the area of impact does not appear to extend to the north, rather migrating south to southwesterly. Additionally, Dale Anderson LLC, current property owner, has made attempts to request entry into the northern property building, and have been denied entry.

Groundwater Monitoring

- Repair existing wells, as listed below.
  - GW1 – The road box cover is missing, allowing the riser to be exposed. However, a J-plug is present. Road box repair/replacement is needed.
  - GW-2 – J-plug is missing and requires replacement.
  - GW-4 – Road box is damage and requires replacement.

- Complete semi-annual groundwater sampling from the one location within the metal prep room, identified as GW3. The groundwater sample will be analyzed for VOCs via USEPA Method 8260.


- Due to generally consistent groundwater testing results over past several sampling rounds, reduce monitoring requirements from quarterly to yearly, to be completed on the six sampled wells. Groundwater samples will be analyzed for VOCs via USEPA Method 8260.

Reporting

- Completion of annual reports to provide results of annual SVES point sampling and groundwater testing results.
- Provide recommendations, as needed.

I trust this report satisfies your present needs. If you have any questions concerning the information presented in this report, please contact me directly. Thank you for the opportunity to provide these site assessment services.

Sincerely,
WITTMAN GEOSCIENCES, PLLC



Michele M. Wittman, P.G.
Principal

Attachments: Tables
Figures
Attachment A – SVES Sampling Results
Attachment B – Monitoring Well Data Sheets
Attachment C – Monitoring Well Testing Results

TABLES

Table 1
Vacuum Measurements (in. H2O)
Tuesday, May 5, 2020
ROCO, 1764 Dale Road, Cheektowaga
Site No: 915300

System Configuration	B1	B2	B3	B4	B5	B6	B7
Current	0.130	0.027	0.023	0.071	0.126	0.104	0.027
Carbon Bypass	0.129	0.026	0.027	0.076	0.124	0.108	0.030

System Configuration	B8	B9	B10	B11	B12	B13	B14
Current	0.078	0.195	0.040	0.004	0.000	0.000	0.000
Carbon Bypass	0.075	0.201	0.038	0.017	0.014	0.000	0.000

System Configuration	VP1	VP2	S1 (Pre-Carbon)	S2 (GP501 Fan)
Current	0.595	0.715	0.843	1.960
Carbon Bypass	0.652	0.777	0.958	1.811

1. Vacumm point locations included on Figure 2.

Table 2
Vapor Point Sampling Results
ROCO, 1764 Dale Road, Cheektowaga
Site No: 915300

Parameter	Table C2 Commercial Indoor Air Background (90%)	NYSDOH Air Guideline Value	**SV-01/VP1**	**SV-02/VP2**
			5/5/2020	**5/5/2020**
			L2018596-01	**L2018596-02**
Volatile Organics in Air				
2,2,4-Trimethylpentane	NV		1.07	0.934 U
Bromodichloromethane	NV		32	1.34 U
Carbon disulfide	4.2		0.931	0.623 U
Carbon tetrachloride	<1.3		4.3	1.26 U
Chloroform	1.1		367	0.977 U
Chloromethane	3.7		0.514	0.413 U
cis-1,2-Dichloroethene	<1.9		16.3	0.793 U
Dibromochloromethane	NV		8.6	1.7 U
Dichlorodifluoromethane	16.5		2.56	2.54
Ethylbenzene	5.7		1.49	0.869 U
n-Hexane	NV		0.913	0.705 U
o-Xylene	7.9		2.26	0.869 U
p/m-Xylene	22.2		6.78	1.74 U
Tetrachloroethene	15.9	30	1.94	1.36 U
Toluene	43		7.91	1.05
Trichloroethene	4.2	2	67.7	57.5
Vinyl chloride	<1.9		6.16	0.511 U

Notes:

1. Compounds detected in one or more samples included in this table. For a list of all compounds, refer to analytical report in Attachment C.
2. Analytical testing for VOCs via TO-15 completed by Alpha Laboratories, LLC.
3. Results present in ug/m^3 or microgram per cubic meter.
4. Samples were collected via a grab sample collected over approximate 10-minute time.
5. 90th percentile values as presented in C2 (EPA 2001: Building assessment and survey evaluation (BASE) database) Appendix C, in the NYSDOH Guidance Manual, as indicated for Indoor and Outdoor air only.
6. Air Guidance Values from "Guidance for Evaluating Soil Vapor Intrusion in the State of New York" dated October 2006, prepared by New York State Department of Health.
7. NYSDOH does not currently have standards, criteria or guidance values for concentrations in sub-slab vapor. The detection of VOCs in sub-slab vapor samples does not necessarily indicate soil vapor intrusion is occurring or action should be taken to address exposures.
8. Grey shaded values represent exceedance of table C2 guidance values; yellow shaded values represent exceedance of NYSDOH Air Guidance Values.
9. ND = Non Detect; NV = No Value; NT = Not Tested

Table 3
Historical Chlorinated Solvent Air Sampling Results
Various Air Sampling Sources
ROCO, 1764 Dale Road, Cheektowaga
Site No: 915300

		Initial SubSlab		Subslab Vapor	Combined Vapor Point Sampling Port			Vapor Point	
Parameter	NYSDOH Air Guideline Value	SS#1 11/27/2007	AM#1 11/27/2007	SV-1 8/25/2014	11/14 Before 11/14/2015	3/5 Before 3/5/2016	10/25 Before 10/25/2016	SV-01/VP1 5/5/2020	SV-02/VP2 5/5/2020
Volatile Organics in Air									
1,1,1-Trichloroethane		ND	ND	NR	NR	NR	NR	1.09 U	1.09 U
1,1-Dichloroethene		NR	NR	800 J	<0.59	<0.59	1.3	0.793 U	0.793 U
cis-1,2-Dichloroethene		NR	NR	2300	NR	11	8.3	16.3	0.793 U
Tetrachloroethene	30	2	ND	710 J	<1.0	0.75	<0.82	1.94	1.36 U
trans-1,2-Dichloroethene		NR	NR	ND	NR	NR	NR	0.793 U	0.793 U
Trichloroethene	2	303	3.84	190000	<0.81	39	67	67.7	57.5
Vinyl chloride		NR	NR	ND	1.2	13	NR	6.16	0.511 U

Notes:

1. Table created from past testing results from initial sub-slab sample, second sub-slab sample in 2014, and vapor point locations
2. Results present in ug/m^3 or microgram per cubic meter.
3. NYSDOH does not currently have standards, criteria or guidance values for concentrations in sub-slab vapor.
4. Yellow shaded values represent exceedance of NYSDOH Air Guidance Values.
5. ND = Non Detect; NV = No Value; NT = Not Tested; NR = not reported

Table 4
Groundwater Elevations
ROCO, 1764 Dale Road, Cheektowaga
Site No: 915300

Location	Top of Riser Elevation	Depth to Water (feet)	Groundwater Elevation	Well Depth (feet)	Well Bottom Elevation
GW1	652.59	1.40	651.19	14.10	638.49
GW2	653.88	1.50	652.38	13.75	640.13
GW3	652.94	2.25	650.69	13.77	639.17
GW4	653.00	2.83	650.17	12.70	640.30
GW5	642.57	6.26	636.31	14.57	628.00
GW7	650.37	3.12	647.25	14.60	635.77

Table 5
Groundwater Sampling Results
ROCO, 1764 Dale Road, Cheektowaga
Site No: 915300

Parameter	Class GA	GW-1	GW-2	GW-3	GW-4	GW-5	GW-7
Sampling Date		5/5/2020	5/5/2020	5/5/2020	5/5/2020	5/5/2020	5/5/2020
Lab Sample ID		L2018539-02	L2018539-05	L2018539-06	L2018539-03	L2018539-01	L2018539-04
Volatile Organics by GC/MS (ug/l)							
Vinyl chloride	2	0.81 J	0.3 J	23000 *	250	1 U	96
1,1-Dichloroethene	5	0.5 U	0.5 U	50 U	4.4	0.5 U	0.41 J
trans-1,2-Dichloroethene	5	2.5 U	2.5 U	250 U	43	2.5 U	2.5 U
Trichloroethene	5	2	0.27 J	50 U	91	3.3	0.5 U
cis-1,2-Dichloroethene	5	34	1 J	8800	280	2.9	94
Acetone	50	5 U	5 U	500 U	10 U	5 U	2.4 J
Methyl Acetate	NV	0.33 J	2 U	200 U	4 U	2 U	0.27 J
Total VOCs		37.1	1.6	31800	668.4	6.2	193.1

Notes:

1. Analytical testing performed by Alpha Analytical. Compounds detected in one or more samples are presentin this table. Refer to appendix for full analytical report.
2. ug/L = parts per billion; mg/L = parts per million.
3. ND = not detected above method detection limit; NT = not tested; NV = no value.
4. Analytical results compared to NYSDEC Division of Water Technical and Operational Guidance Series (TOGS 1.1.1)
5. * = Concentration of analyte exceeded range of the calibration curve, which required a re-analysis at a higher dilution factor.
6. E = Concentration of analyte exceeds the range of the calibration curve and/or linear range of the instrument.
7. J = Estimated value. The target analyte is below the reporting limit (RL), but above the method dectection limit (MDL).
8. P = The RPD between the results for the two columns exceeds the method-specified criteria.
9. Shading indicates: exceeds NYSDEC Class GA criteria

Table 6
Historical Chlorinated Solvent Groundwater Sampling Results - 2014 to 2020
ROCO, 1764 Dale Road, Cheektowaga
Site No: 915300

Parameter	**Class GA**	GW-1				GW-2				GW-3			
Sampling Date		8/25/14	3/21/16	5/22/17	5/5/2020	8/25/14	3/21/16	5/22/17	5/5/2020	8/25/14	3/21/16	5/22/17	5/5/2020
Volatile Organics by GC/MS (ug/l)													
Tetrachloroethene (PCE)	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
Trichloroethene	5	3.3	ND	ND	2	2.3	ND	ND	0.27 J	10	ND	ND	ND
cis-1,2-Dichloroethene	5	190	45.5	50.8	34	9.9	ND	4.83	1 J	34000	2260	2540	8800
trans-1,2-Dichloroethene	5	1.9	ND	ND	ND	ND	ND	ND	ND	40	ND	ND	ND
Vinyl chloride	2	28	11.9	16.1	0.81 J	4.7	ND	15.8	0.3 J	27000	19800	21100	23000


Parameter	**Class GA**	GW-4				GW-5				GW-7			
Sampling Date		8/25/14	3/21/16	5/22/17	5/5/2020	8/25/14	3/21/16	5/22/17	5/5/2020	8/25/14	3/21/16	5/22/17	5/5/2020
Volatile Organics by GC/MS (ug/l)													
Tetrachloroethene (PCE)	5	ND	ND	ND	ND	ND	ND	ND	ND	ND	NT	NT	ND
Trichloroethene	5	8.2	ND	ND	91	2.2	ND	2.63	3.3	ND	NT	NT	ND
cis-1,2-Dichloroethene	5	100	ND	ND	280	2.8	ND	ND	2.9	330	NT	NT	94
trans-1,2-Dichloroethene	5	4.4	ND	ND	43	ND	ND	ND	ND	ND	NT	NT	ND
Vinyl chloride	2	18	ND	3.64	250	ND	ND	ND	ND	ND	NT	NT	96

FIGURES



WITTMAN GeoSciences, PLLC

WITTMAN GEOSCIENCES, PLLC	Site Features	DRAWN BY: MMW	SCALE: NTS	PROJECT: 18110
	1764 Dale Road, Cheektowaga, NY	CHECKED BY: MMW	DATE: 05/2020	FIGURE NO: 1



WITTMAN
GeoSciences, PLLC

WITTMAN GEOSCIENCES, PLLC	Date: 06/2020	**Vacuum Testing Results**	Project: 18110
	Scale: as noted	1764 Dale Road, Cheektowaga, NY	Figure: 2



WITTMAN GeoSciences, PLLC

WITTMAN GEOSCIENCES, PLLC	**Groundwater Contour Map**	DRAWN BY: MMW	SCALE: NTS	PROJECT: 18110
	1764 Dale Road, Cheektowaga, NY	CHECKED BY: MMW	DATE: 05/2020	FIGURE NO: 3



WITTMAN GeoSciences, PLLC

WITTMAN GEOSCIENCES, PLLC	**Total VOC Isopleth Map**	DRAWN BY: MMW	SCALE: NTS	PROJECT: 18110
	1764 Dale Road, Cheektowaga, NY	CHECKED BY: MMW	DATE: 05/2020	FIGURE NO: 4

HALEY ALDRICH

www.haleyaldrich.com

REPORT ON

ASTM PHASE I ENVIRONMENTAL SITE ASSESSMENT
DAVIS ELECTRICAL SUPPLY CO., INC.
24 ANDERSON ROAD
BUFFALO (CHEEKTOWAGA), NEW YORK



by
Haley & Aldrich of New York
Rochester, New York

for
Green Mountain Electric Supply, Inc. and GMS Realty, LLP
c/o Harris Beach PLLC
Pittsford, New York

File No. 0203877-011
November 2022

HALEY & ALDRICH OF NEW YORK
200 Town Centre Drive
Suite 2
Rochester, NY 14623
585.359.9000

4 November 2022
File No. 0203877-011

Green Mountain Electric Supply, Inc. and GMS Realty, LLP
c/o Harris Beach PLLC
99 Garnsey Road
Pittsford, New York 14534

Attention: Mr. Sean McCabe

Subject: ASTM Phase I Environmental Site Assessment
Davis Electrical Supply Co., Inc.
24 Anderson Road
Buffalo (Cheektowaga), New York

Ladies and Gentlemen:

The enclosed report presents the results of a Phase I Environmental Site Assessment (Phase I) conducted at the above-referenced property, located at 24 Anderson Road in Buffalo (Cheektowaga), New York (herein referred to as the "subject property"). This work was performed by Haley & Aldrich of New York (Haley & Aldrich), in accordance with our proposal to Green Mountain Electric Supply, Inc. and GMS Realty, LLP dated 16 September 2022 ("Agreement") as authorized on 27 September 2022. This Phase I was conducted in conformance with the scope and limitations of the ASTM International (ASTM) E1527-13 and E1527-21 Standard Practice for Environmental Site Assessments[1].

The objective of a Phase I is to assess whether known and suspect "recognized environmental conditions" (REC), controlled RECs (CREC), or historical RECs (HREC) are associated with the subject property, as defined in the ASTM E1527-13 and E1527-21 Standards.

[1] The ASTM Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E 1527 13 Standard) as referenced in 40 CFR Part 312 (the All Appropriate Inquiries [AAI] Rule). Additionally, Haley & Aldrich's Phase I Environmental Site Assessments incorporated the procedures set forth in ASTM E 1527-21, which have not yet been approved by the U.S. Environmental Protection Agency (EPA) to meet the requirements of 40 CFR 312, AAI.

Thank you for the opportunity to perform these services for you. Please do not hesitate to contact us if you have any questions or comments.

Sincerely yours,
HALEY & ALDRICH OF NEW YORK

Andrew L. Nichols
Technical Specialist

Claire L. Mondello
Senior Associate

Enclosures

https://haleyaldrich.sharepoint.com/sites/GreenMountainElectricSupply/Shared Documents/0203877-011.Buffalo and Lockport Phase Is/Phase I ESA/Buffalo/Deliverable/2022_1104_Phase I ESA-Anderson Rd,Buffalo, NY_F.docx

Executive Summary

Haley & Aldrich of New York (Haley & Aldrich) has performed a Phase I Environmental Site Assessment (Phase I) of the 24 Anderson Road property in Buffalo (Cheektowaga), New York, (herein referred to as the "subject property"). The scope of work is described and conditioned by our proposal dated 16 September 2022. This Phase I was performed for Green Mountain Electric Supply, Inc. (GMES) and GMS Realty, LLP (GMS) who seek to purchase the subject property for use in electric supply, storage, wholesaling, and distribution activities. This Phase I was performed in conformance with the scope and limitations of the ASTM International (ASTM) E1527-13 and E1527-21 Standards and All Appropriate Inquiries (AAI) Rule.

SUBJECT PROPERTY DESCRIPTION

The subject property is a 1.05-acre land parcel developed with a single-story concrete block structure built on a slab-on-grade foundation. A second-floor office space occupies the southeastern corner of the subject property building, and a second-floor bathroom and storage area are located over the northeastern corner of the building. Exterior areas of the subject property consist of asphalt-paved parking and loading areas. The subject property is currently used for electrical supply equipment retailing, warehousing, and distribution.

OBJECTIVE

The objective of a Phase I is to assess whether "recognized environmental conditions" (REC), controlled RECs (CREC), or historical RECs (HREC) are associated with the subject property. Our conclusions are intended to help the user evaluate the "business environmental risk" associated with the subject property. Our opinion regarding an REC's potential impact on the subject property is based on the scope of our work, the information obtained during the course of our work, the conditions prevailing at the time our work was performed, the applicable regulatory requirements in effect at the time our work was performed, our experience evaluating similar sites, and on our understanding of the client's intention to purchase the subject property.

SIGNIFICANT DATA GAPS

Our ability to identify and evaluate RECs at the subject property is conditioned upon significant data gaps identified as part of this Phase I. The ASTM E1527-21 Standard defines a significant data gap as a data gap that affects the ability of the environmental professional to identify a REC.

No significant data gaps were identified during the performance of this Phase I. Thus, it is our opinion that sufficient information was obtained to identify subject property conditions indicative of releases or threatened releases of hazardous substances and petroleum hydrocarbons. Our opinion is limited by the conditions prevailing at the time our work is performed and the applicable regulatory requirements in effect.

RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a REC as (1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely

release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

The following REC listed below was identified in connection with the subject property.

REC #1: Chlorinated volatile organic compounds identified in subject property soil, groundwater, soil vapor and indoor air

The former Rotary Company, Inc. (RoCo Ltd.) site at 1746 Dale Road, located adjacent to and south of the subject property, is a New York State Department of Environmental Conservation (NYSDEC) Class P Non-Registry Inactive Hazardous Waste Site (Site #915300). Trichloroethene (TCE) and related chlorinated volatile organic compound (CVOC) contamination have been identified in soil, groundwater, and soil vapor beneath the RoCo Ltd. site, with the highest concentrations observed in the northwest corner of the RoCo Ltd. site, approximately 25 feet from the southern subject property boundary. In the early-2000's subsurface investigation activities conducted on behalf of RoCo Ltd. were performed to assess whether the CVOC contamination extended onto the southern portions of the subject property. Results of these investigation activities identified CVOC concentrations in subject property soil and groundwater exceeding NYSDEC Unrestricted Use Soil Cleanup Objectives (SCOs) and Class GA Groundwater Standards (Class GA standards), respectively.

RoCo Ltd. signed a Voluntary Cleanup Agreement (VCA; VCP Site # V00422) in 2001 to complete site investigation activities and address the CVOC contamination at the 1746 Dale Road site and adjacent properties, including the subject property. Remedial actions taken in the 2000's included in-situ bioremediation to treat impacted groundwater. In 2007, RoCo Ltd. completed soil vapor and indoor air sampling in the southern portion of the subject property building. TCE was detected in co-located sub-slab soil vapor/indoor air samples collected from within the subject property building, with concentrations observed at one sampling location exceeding the current May 2017 NYSDOH soil vapor/indoor Air Matrix A Guidelines for sub-slab soil vapor mitigation.

In 2011 a deed restriction was filed for the 1746 Dale Road site, and site uses became governed by a Site Management Plan (SMP). Although the SMP does not govern activities on the subject property, it recommends continued soil vapor intrusion monitoring in the subject property building. Regulatory records indicate the subject property owner has not allowed access to the 24 Anderson Road building for the recommended sub-slab soil vapor and indoor air sampling. In the early 2010's RoCo Ltd. reportedly abandoned the site and terminated the VCA. Between 2014 and 2020, the new site owners periodically sampled groundwater on the subject property. In May 2020, concentrations of cis-1,2-Dichloroethene (cis-DCE) were detected in subject property groundwater above Class GA standards.

The presence of CVOCs in subject property soil, groundwater, soil vapor, and indoor air due to historical releases of CVOCs at the off-site and adjacent 1746 Dale Road property is considered an REC.

CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines a CREC as a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls.

CRECs were not identified in connection with the subject property.

HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527-21 Standard defines an HREC as a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls. A historical recognized environmental condition is not a recognized environmental condition.

HRECs were not identified in connection with the subject property.

DE MINIMIS CONDITIONS

The ASTM E1527-21 Standard defines *de minimis* conditions as a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. The ASTM E1527-21 Standard notes that conditions determined to be *de minimis* are not recognized environmental conditions.

The following *de minimis* condition listed below was identified in connection with the subject property.

***De Minimis* #1: Interior floor drain/catch basin containing standing water**

A floor drain/catch basin reportedly connected to the municipal sanitary sewer via a nearby sump pit was observed in the warehouse portion of the subject property building during the subject property reconnaissance. It appears this area of the building was previously a portion of the original subject property factory/mechanical facility operated by Kolk Manufacturing in the 1950s and 1960s. Standing water was observed in the catch basin during the subject property reconnaissance. The Key Site Manager indicated the drain does not consistently contain water, and evidence of current or historical disposal of oil or hazardous materials into the drain was not observed or reported. The observation of standing water in the drain/catch basin suggests the drain may be blocked and/or not completely discharging to the sanitary sewer. Due to the uncertain source of water in the drain, and known groundwater contamination beneath the subject property, the function of the drain and connection to the municipal sanitary sewer should be assessed to confirm subject property groundwater is not collecting in the drain for prolonged periods.

SUMMARY AND RECOMMENDATIONS

In summary, we identified one (1) REC and one (1) de minimis condition during this Phase I.

To address the REC and *de minimis* condition listed above, we recommend the following:

- Sampling and analysis of sub-slab soil vapor and indoor air in the subject property building for VOCs. Results should be compared to the 2017 New York State Department of Health (NYSDOH) Updates to Soil Vapor/Indoor Air Decision Matrices, to assess whether continued monitoring or mitigation is needed.

- Trace the outlet of the floor drain/catch basin to assess for blockages that may be causing standing water to periodically collect in the drain, and to confirm discharge to the municipal sanitary sewer.

The remainder of this report contains additional information regarding the Phase I, the resulting findings summarized above, and limitations affecting this report.

HALEY ALDRICH

www.haleyaldrich.com

REPORT ON

PHASE II VAPOR INTRUSION INVESTIGATION
DAVIS ELECTRICAL SUPPLY CO.
24 ANDERSON ROAD
BUFFALO, NEW YORK

by
Haley & Aldrich of New York
Rochester, New York

for
Green Mountain Electric Supply, Inc. and GMS Realty, LLP
c/o Harris Beach PLLC
Pittsford, New York

File No. 0203877-014
February 2023



HALEY & ALDRICH OF NEW YORK
200 Town Centre Drive
Suite 2
Rochester, NY 14623
585.359.9000

8 February 2023
File No. 0203877-014

Green Mountain Electric Supply, Inc. and GMES Realty, LLP
c/o Harris Beach PLLC
99 Garnsey Road
Pittsford, New York 14534

Attention: Mr. Jeremy Speich
Mr. Sean McCabe

Subject: Phase II Vapor Intrusion Investigation
Davis Electrical Supply Co.
24 Anderson Road
Buffalo, New York

Ladies and Gentlemen:

Haley & Aldrich of New York (Haley & Aldrich) is pleased to provide the results of a Phase II Vapor Intrusion Investigation performed at the Davis Electrical Supply Co. in Buffalo, New York (the Subject Property) in support of the purchase by Green Mountain Electric Supply, Inc. (GMES) and its affiliated company, GMS Realty, LLP (GMS). Haley & Aldrich previously prepared a Phase I Environmental Site Assessment (Phase I ESA) in October 2022 on behalf of Green Mountain Electric Supply, Inc. (GMES) through request of its counsel, Harris Beach, PLLC. This investigation was requested by GMES as a follow-up to address a Recognized Environmental Condition (REC) identified during the Phase I ESA.

Background and Site Description

The subject property occupies approximately 1.05 acres of land located at 24 Anderson Road, Buffalo New York (parcel number 102.03-2-29). The subject property is improved with an approximately 25,000 square foot commercial retail and warehousing facilities operated by GMES as Davis Electrical Supply Co., Inc. an electrical equipment wholesale and supply business.

The October 2022 Phase I ESA identified a REC in connection with the property, which included chlorinated volatile organic compounds (VOCs) identified in subject property soil, groundwater, soil vapor and indoor air related to a former New York State Department of Environmental Conservation (NYSDEC) Voluntary Cleanup Program (VCP) site (RoCo, Ltd., V00422) that abuts the subject property to the south at 1746 Dale Road. That site is now listed as an Inactive Hazardous Waste Site (#915300). Elevated chlorinated VOCs, primarily trichloroethene (TCE) are present in groundwater, soil, and soil vapor at the Dale Road property and may have impacted the southern portion of the subject property. In 2007, RoCo Ltd. completed soil vapor and indoor air sampling in the southern portion of the subject property building. TCE was detected in co-located sub-slab soil vapor/indoor air samples collected from

within the subject property building, with concentrations observed at one sampling location exceeding the current May 2017 New York State Department of Health (NYSDOH) Soil Vapor/Indoor Air Matrix A Guidelines for sub-slab soil vapor mitigation. Sample locations sampled by RoCo Ltd. are shown on Figure 1.

In 2011 a deed restriction was filed for the adjacent VCP property, and site uses became governed by a Site Management Plan (SMP). Although the SMP does not govern activities on the subject property, it recommends continued soil vapor intrusion monitoring in the subject property building. Regulatory records indicate the subject property's previous owner did not allow access to the 24 Anderson Road building for the recommended sub-slab soil vapor and indoor air sampling. In the early 2010s RoCo Ltd. reportedly abandoned the VCP site and terminated the VCA. Between 2014 and 2020 groundwater was periodically sampled on the subject property. In May 2020, concentrations of cis-1,2-Dichloroethene (cis-DCE) were detected in subject property groundwater above Class GA standards.

In order to address the REC identified in our Phase I, sampling of the sub-slab vapor and indoor air at the subject property to confirm the current presence/absence of chlorinated compound-impacted vapors in and beneath the subject property was recommended. At the request of GMES, that investigation was conducted in two Phases in December 2022 and January 2023 as described below.

Investigation Methods

Vapor intrusion investigation activities were completed in general accordance with the New York State Department of Health (NYSDOH) Guidance for Evaluating Soil Vapor Intrusion in the State of New York dated October 2006 and updated May 2017 (NYSDOH Guidance). Investigation methods are described below.

DECEMBER 2022 SOIL VAPOR AND INDOOR AIR SAMPLING

Investigation Procedure

Initial sub-slab vapor and indoor air testing was conducted on the southern half of the subject property building between 5 and 6 December 2022 per the following procedure. Prior to sampling, on 5 December 2022, Haley & Aldrich completed an inventory of the materials stored and/or used in the building areas being sampled to document potential sources of VOCs that could impact the results of indoor air testing. Areas adjacent to sampling locations in the facility were screened with a MiniRae® 3000 Photoionization Detector (PID). Several products stored near the sample locations that may potentially contain volatile constituents were identified and the product labels were reviewed. Detectable concentrations of VOCs were not identified adjacent to the sampling locations or proximate to products stored within the building. The inventory forms are included in Appendix A.

Following the inventory, Haley & Aldrich installed temporary sub-slab sampling points at two locations (HA-5, and HA-6) approximate to SS-5 and SS-6 collected by others in 2007 (Figures 1 and 2) using Vapor Pins®. An electric hammer drill was used to advance a 1.5-inch diameter hole through the first 2-inches of the concrete floor slab to create space for point installation and removal. A 5/8-inch-diameter drill bit

was then used to advance the hole through the remaining thickness of the concrete floor slab. A vacuum equipped with HEPA filtration was used to recover dust and debris while drilling into the concrete. At each location, temporary Vapor Pins® were installed by hammering the pin into the 5/8-inch diameter holes. Following point installation, each sampling port was screened for VOCs using a PID Detectable concentrations of VOCs were not identified within the sample ports. Following installation of the sampling points, the sample location was allowed to equilibrate prior to sample collection.

On 6 December 2022, Haley & Aldrich collected two co-located sub-slab vapor and indoor air samples at locations HA-5 and HA-6, and one outdoor air sample upwind from the building (Figure 2). Prior to sampling the sub-slab points, a helium tracer gas test was performed as a leak test methodology to evaluate sample integrity at each sub-slab air sampling location prior to sampling. To perform the test, an enclosure was placed over the sealed sub-slab sample location. The sample tubing was run through a hole in the enclosure, and a silicone gasket was used to seal the interface between the tubing and the enclosure. The enclosure was then sealed at the ground surface with a foam gasket. A tank containing high-purity helium was connected to the side port of the enclosure and helium was released within the enclosure. Following the application of the tracer gas, approximately 1 liter of sub-slab air was purged using a personal sample pump at a rate of approximately 0.2 liters per minute (L/min) into a 1-liter Tedlar® bag. The contents of the Tedlar® bag were analyzed outside the building for helium using a Radiodetection/Dielectric MGD-2002 Multi-gas Detector, for total VOCs with a photoionization detector (PID). Detectable concentrations of VOCs were not identified in the purge samples. The remaining contents of the Tedlar® bag containing the sub-slab purged air were subsequently discharged to outdoor air.

The SUMMA® canisters used at the indoor air and outdoor air sampling locations were placed so that the intake of the flow controllers was at the approximate height of the breathing zone for facility workers (36 – 54 inches above the floor). The sub-slab air sample SUMMA® canisters were placed on the facility floor and connected to the sampling points.

The samples were collected in batch certified laboratory provided canisters fitted with flow controllers to collect the samples over an 8-hour period. Following sample collection, the temporary Vapor Pins® were removed and the previously drilled holes were filled with concrete. Windows and doors capable of being closed remained closed during the sampling event. Field forms are included in Appendix A.

The samples were submitted to Alpha Analytical, Inc. (a NYSDOH ELAP-certified laboratory) and analyzed for VOCs via EPA Method TO-15 or TO-15 SIM where required to achieve lower detection limits. The samples were shipped at ambient temperature under a Chain-of-Custody (COC) to the laboratory. SUMMA® canister vacuum readings were recorded before and after sampling to document the sample collection. The final vacuum reading recorded at the end of the sampling period were placed on the COC form prior to shipping to the laboratory and each canister vacuum was checked upon arrival at the laboratory to confirm sample integrity during shipment.

Results

The results from the subset of chlorinated VOCs, which have applicable comparison criteria are summarized in Table I. The analytical results included in the laboratory reports in Appendix B were compared to the NYSDOH Evaluation Matrices included in the Guidance for Evaluating Soil Vapor Intrusion in the State of New York dated October 2006 and updated May 2017 (NYSDOH Guidance).

- Concentrations of TCE detected in both the sub-slab and indoor air samples at HA-5 and HA-6, when compared to the NYSDOH Guidance matrices, resulted in a recommended action of "Mitigation." TCE was also identified in ambient outdoor air.
- Cis-1,2-Dichloroethene (cis-1,2-DCE), a breakdown product of TCE, was detected in both the sub-slab and indoor air samples at HA-5 and HA-6. When compared to the NYSDOH Guidance matrices, the concentrations at HA-5 resulted in a recommended action of "Monitor."
- Carbon Tetrachloride and Tetrachloroethene (PCE) were detected in the indoor air at both HA-5 and HA-6. PCE was also detected at low concentrations in the sub-slab at SV-6. Those compounds however were also detected in the outdoor air sample, which likely influenced the conditions within the building.

JANUARY 2023 INDOOR AIR SAMPLING

Investigation Procedure

To further understand indoor air quality within the building, Haley & Aldrich completed an indoor air sampling event on January 23, 2023. Three indoor air samples were collected in occupied areas of the subject property as directed by GMES including the retail floor, lighting showroom area, and employee office area (a.k.a., the bullpen), and one outdoor air sample upwind from the building (see Figure 2). Prior to sampling, Haley & Aldrich completed an inventory similar to the December 2022 event. Field forms are included in Appendix A. Indoor air samples were collected using similar methods as the December 2022 sampling event in batch-certified laboratory provided canisters fitted with flow controllers to collect samples over a 4-hour period. The Samples were submitted to Alpha Analytical, Inc. (a NYSDOH ELAP-certified laboratory) and analyzed for VOCs via EPA Method TO-15 SIM. The samples were shipped at ambient temperature under a COC to the laboratory. SUMMA® canister vacuum readings were recorded before and after sampling to document the sample collection. The final vacuum reading recorded at the end of the sampling period were placed on the COC form prior to shipping to the laboratory and each canister vacuum was checked upon arrival at the laboratory to confirm sample integrity during shipment.

Results

The results from the subset of chlorinated VOCs are summarized in Table I. The full data analytical results are included in the laboratory reports in Appendix B.

- Concentrations of TCE detected in all indoor air samples exceed the highest risk criteria for indoor air in the NYSDOH Guidance that even in the absence of sub-slab samples suggest a recommended action of "Mitigation."

- Cis-1,2-DCE concentrations were detected that exceeded the "Monitor" criteria (showroom and retail floor areas) and highest risk "Mitigate" criteria (bullpen) in the NYSDOH Guidance.
- Carbon Tetrachloride and PCE were also detected, however as with the December 2022 event, those compounds were present in the outdoor air sample as well suggesting those results are influenced by outdoor ambient conditions.

Evaluation and Conclusion

Based on the results of the soil vapor intrusion investigation, the REC identified in the October 2022 Phase I ESA has been confirmed. The concentrations of TCE detected in both the sub-slab and indoor air result in a recommendation of "mitigation" per the NYSDOH Guidance. Though TCE was also present in outdoor air, which may impact the indoor air results, the concentrations of TCE present in soil vapor beneath the subject property building slab also exceed NYSDOH Guidance criteria for mitigation.

Based on prior records review, the source of the TCE and related compounds at the subject property are anticipated to be from the Dale Road (former RoCo Ltd.) property to the south, which has known and documented impacts resulting from former metal fabrication conducted at that facility. Installation of a mitigation system is recommended to address the soil vapor beneath the slab and mitigate the potential for VOC impacted soil vapor intrusion into the building indoor airspace. The mitigation system should include a combination of sealing of preferential pathways for vapor intrusion in conjunction with the installation of a sub-slab depressurization system (SSDS), which reduces the potential for migration of VOC impacted soil vapors from beneath the building slab into the indoor airspace. *Haley & Aldrich Construction Services (HCS) provided a proposal to GMES and GMS to perform communication testing and install a SSDS within the subject property building on 17 January 2023. The proposal was authorized on 20 January 2023. Communication testing commenced on 6 February 2023.*

We appreciate the opportunity to provide environmental consulting services on this project. Please do not hesitate to call if you have any questions or comments.

Sincerely yours,
HALEY & ALDRICH OF NEW YORK

Santa E. McKenna
Assistant Project Manager

Claire L. Mondello
Senior Associate

Enclosures:
Table I – Sub-slab and Indoor Air Analytical Results
Figure 1 – Site Map
Figure 2 – Sample Location Plan Sub-Slab and Indoor Air December 2022 and January 2023
Appendix A – Field and Inventory Forms
Appendix B – Laboratory Data Reports

TABLES

TABLE I
SUB-SLAB AND INDOOR AIR ANALYTICAL RESULTS
DAVIS ELECTRIC, 24 ANDERSON ROAD
BUFFALO, NEW YORK
FILE NO.: 0203877-014

	NYSDOH Matrix Criteria						December 2022 Sub-Slab/Indoor Air Sampling							January 2023 Indoor Air Sampling			
Location Name	NYSDOH Sub-Slab Vapor Criteria			NYSDOH Indoor Air Criteria			HA-OA	HA5-SV	HA5-IA	*Recommended Action Per NYSDOH Matrices*	HA6-SV	HA6-IA	*Recommended Action Per NYSDOH Matrices*	HA1-0A	HA1-IA (Showroom)	HA2-IA (Retail Floor)	HA3-IA (Bullpen)
Sample Name							HA-OA-120622-1648	HA5-SV-120622-1618	HA5-IA-120622-1618		HA3-SV-011823-1555	HA2-IA-011823-1555		HA1-OA-012323-1450	HA1-IA-012323-1442	HA2-IA-012323-1447	HA3-IA-012323-1443
Sample Date							12/6/2022	12/6/2022	12/6/2022		12/6/2022	12/6/2022		1/23/2023	1/23/2023	1/23/2023	1/23/2023
Sample Type							Field Sample	Field Sample	Field Sample		Field Sample	Field Sample		Field Sample	Field Sample	Field Sample	Field Sample
Lab Sample ID							L2269268-05	L2269268-01	L2269268-02		L2269268-03	L2269268-04		L2304398-04	L2304398-01	L2304398-02	L2304398-03
Soil Description	**Range 1**	**Range 2**	**Range 3**	**Range 1**	**Range 2**	**Range 3**	Outdoor Air	Subslab Vapor	Indoor Air		Subslab Air	Indoor Air		Outdoor Air	Indoor Air	Indoor Air	Indoor Air
Chlorinated VOCs																	
Matrix A																	
1,1-Dichloroethene	< 6	6 - 60	> 60	< 0.2	0.2 - 1	> 1	0.793 U	0.793 U	0.79 U	No Further Action	0.793 U	0.793 U	No Further Action	0.793 U	0.79 U	0.79 U	0.793 U
cis-1,2-Dichloroethene	< 6	6 - 60	> 60	< 0.2	0.2 - 1	> 1	0.79 U	**35.8**	**0.23**	**Monitor**	**4.12**	**0.115**	No Further Action	0.79 U	**0.48**	**0.325**	**2.05**
Carbon tetrachloride	< 6	6 - 60	> 60	< 0.2	0.2 - 1	> 1	**0.459**	1.26 U	***0.465***	No Further Action	1.26 U	***0.453***	No Further Action	**0.403**	***0.371***	***0.396***	***0.396***
Trichloroethene	< 6	6 - 60	> 60	< 0.2	0.2 - 1	> 1	**0.511**	**300**	***2.84***	**Mitigate**	**90.8**	***1.26***	**Mitigate**	0.107 U	**4.26**	**2.79**	**2.55**
Matrix B																	
1,1,1-Trichloroethane	< 100	100 - 1000	> 1000	< 3	3 - 10	> 10	1.09 U	1.09 U	1.09 U	No Further Action	1.09 U	1.09 U	No Further Action	1.09 U	1.09 U	1.09 U	1.09 U
Tetrachloroethene	< 100	100 - 1000	> 1000	< 3	3 - 10	> 10	**1.21**	1.36 U	***0.366***	No Further Action	**10.9**	***0.753***	No Further Action	**0.136**	***0.407***	***0.197***	***0.203***
Methylene chloride (Dichloromethane)	< 100	100 - 1000	> 1000	< 3	3 - 10	> 10	1.74 U	1.74 U	1.74 U	No Further Action	1.74 U	1.74 U	No Further Action	1.74 U	1.74 U	1.74 U	1.74 U
Matrix C																	
Vinyl chloride	< 6	6 - 60	> 60	< 0.2	NA	> 0.2	0.051 U	0.511 U	0.051 U	No Further Action	**1.91**	0.051 U	No Further Action	0.051 U	0.051 U	0.051 U	0.051 U

Notes and Abbreviations:
µg/m3: micrograms per cubic meter
Criteria from New York State Department of Health "Guidance for Evaluating Soil Vapor Intrusion, October 2006 (updated May 2017)"

All results displayed in µg/m3.
Bold indicates a detection about the laboratory reporting limit.
U: Compound not detected above laboratory reporting limit.
Shaded values exceed applicable criteria shown.
Recommended action is based on a matrix considering both sub-slab vapor and indoor air criteria. Recommended action is not shown for 1/23/2023 Indoor Air samples only.
Grey highlight is the outdoor air sample, included for comparison purposes.
Italicized indoor air detections were also identified in the Outdoor Air sample and likely impacted by outdoor conditions

FIGURE

DIMAR MANUFACTURING
40 ANDERSON ROAD

POLE-MOUNTED
TRANSFORMERS

UPSTATE FARMS
COOPERATIVE
1730 DALE RD.

WAREHOUSE

RETAIL FLOOR

SHOWROOM

OFFICES
(2-STORY)

ANDERSON RD

OFFICE BUILDING
25 ANDERSON RD.

ROCO LTD
1746 DALE RD.

DALE RD

GW-2
SS#6
B-7A
B-6A
BH-6
BH-5
B-6
GW-3
GW-7
GW-6
GW-4
BH-4
BH-3
BH-15
BH-16
SS#5
GW-1
BH-17
B-5A
GW-5

LEGEND

- GROUNDWATER MONITORING WELL
- SOIL BORING
- CO-LOCATED SUB-SLAB SOIL VAPOR AND INDOOR AIR
- FLOOR DRAIN
- SUMP
- GROUNDWATER VOC CONCENTRATION EXCEEDS NYSDEC TOGS GA STANDARD DURING 2020 SAMPLING
- 2007 SAMPLING OF SUB-SLAB SOIL VAPOR AND INDOOR AIR EXCEED THE 2017 NYSDOH SOIL VAPOR/INDOOR AIR MATRIX A GUIDELINES FOR MITIGATION
- HISTORICAL CONCENTRATIONS OF TRICHLOROETHENE IN SOIL EXCEED NYSDEC UNRESTRICTED USE SOIL CLEANUP OBJECTIVES (SCO)
- SUBJECT PROPERTY BOUNDARY
- PARCEL BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. TAX PARCEL BOUNDARY SOURCE: NYSGIS
3. AERIAL IMAGERY SOURCE: NEARMAP, 18 AUGUST 2022

N

0 50 100
SCALE IN FEET

HALEY ALDRICH


DAVIS ELECTRICAL SUPPLY CO.
24 ANDERSON ROAD
BUFFALO, NEW YORK

SITE PLAN

FEBRUARY 2023

FIGURE 1

GIS: C:\Users\anichols\haleyaldrich.com\Green Mountain Electric Supply - General\GIS\Maps\2022_11203877_011_0001_SITE_PLAN_BUFFALO.mxd - anichols - 11/16/2022 12:31:56 PM



LEGEND

- CO-LOCATED SUB-SLAB SOIL VAPOR AND INDOOR AIR SAMPLE, DECEMBER 2022
- INDOOR AIR SAMPLE, JANUARY 2023
- AMBIENT/OUTDOOR AIR SAMPLE, DECEMBER 2022 AND JANUARY 2023
- FLOOR DRAIN
- SUMP
- 2022 SUB-SLAB SOIL VAPOR AND 2022/2023 INDOOR AIR SAMPLING RESULTS EXCEED THE 2017 NYSDOH SOIL VAPOR/INDOOR AIR MATRIX A TCE GUIDELINES FOR MITIGATION
- SUBJECT PROPERTY BOUNDARY
- PARCEL BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. TAX PARCEL BOUNDARY SOURCE: NYSGIS
3. TCE = TRICHLOROETHENE
4. NYSDOH = NEW YORK STATE DEPARTMENT OF HEALTH
5. AERIAL IMAGERY SOURCE: NEARMAP, 18 AUGUST 2022

N

0 40 80
SCALE IN FEET

HALEY ALDRICH

DAVIS ELECTRICAL SUPPLY CO.
24 ANDERSON ROAD
BUFFALO, NEW YORK

SAMPLE LOCATION PLAN
SUB-SLAB VAPOR AND INDOOR AIR
DECEMBER 2022 AND JANUARY 2023

FEBRUARY 2023

FIGURE 2


GIS: C:\Users\anichols\haleyaldrich.com\Green Mountain Electric Supply - General\GIS\Maps\2023_02\203877_014_0001_SAMPLE_LOCATION_PLAN.mxd - anichols - 2/3/2023 9:45:13 AM

HALEY ALDRICH

www.haleyaldrich.com

REPORT ON

SUB-SLAB DEPRESSURIZATION SYSTEM INSTALLATION
24 ANDERSON ROAD
BUFFLALO, NEW YORK



by

Haley & Aldrich Construction Services, Inc.
Rochester, New York

for

Green Mountain Electric Supply, Inc. and GMS Realty, LLP
Pittsford, New York

File No. 0207713-000
May 2023

HALEY & ALDRICH CONSTRUCTION
SERVICES, INC.
200 Town Centre Drive
Suite 2
Rochester, NY 14623
585.359.9000

3 May 2023
File No. 0207713-000

Green Mountain Electric Supply, Inc. and GMS Realty, LLP
c/o Harris Beach PLLC
99 Garnsey Road
Pittsford, New York 14534

Attention: Mr. Jeremy Speich

Subject: Sub-Slab Depressurization System Installation
24 Anderson Road
Buffalo, New York

Ladies and Gentlemen:

Haley & Aldrich Construction Services (Haley & Aldrich) is pleased to submit this letter report documenting construction activities associated with the installation of a sub-slab depressurization system (SSDS) at the Green Mountain Electric Supply, Inc. (GMES) warehousing and commercial retail building located at 24 Anderson Road, in Buffalo, New York ("subject property"). Haley & Aldrich and its sub-contractor, Mitigation Tech of Brockport, New York (Mitigation Tech), performed project construction activities in accordance with Haley & Aldrich's proposal to GMES and its affiliated company, GMS Realty, LLP (GMS), dated 17 January 2023, and authorized by GMES on 20 January 2023.

Project Background

The subject property occupies approximately 1.05 acres of land located at 24 Anderson Road in Buffalo New York (parcel number 102.03-2-29). The subject property is improved with an approximately 25,000 square foot commercial retail and warehousing facility operated by GMES as Davis Electrical Supply Co., Inc., an electrical equipment wholesale and supply business.

A former New York State Department of Environmental Conservation (NYSDEC) Voluntary Cleanup Program (VCP) site and now listed Inactive Hazardous Waste Site (RoCo, Ltd., #915300) abuts the subject property to the south at 1746 Dale Road. The Dale Road site is impacted with elevated chlorinated volatile organic compounds (VOCs, e.g., solvents), primarily trichloroethene (TCE) in groundwater and soil vapor, that have historically impacted the southern portion of the subject property. Haley & Aldrich identified migrated contamination as a Recognized Environmental Condition (REC) in a Phase I Environmental Site Assessment (ESA) dated November 2022 and subsequently confirmed current TCE impacts to soil vapor beneath and in indoor air within the subject property building during a limited vapor sampling events conducted on the subject property in December 2022 and January 2023. The

investigation results were summarized in a letter report previously provided to GMES, dated 8 February 2023.

Concentrations of TCE detected in co-located sub-slab and indoor air samples collected in December 2023 exceeded guidance criteria for "mitigation," as presented in the New State Department of Health (NYSDOH) Evaluation Matrices included in the Guidance for Evaluating Soil Vapor Intrusion in the State of New York dated October 2006 and updated May 2017 (NYSDOH Guidance). Haley & Aldrich of New York recommended GMES seal preferential pathways for vapor intrusion into the subject property building and install a SSDS to address the soil vapor beneath the slab and mitigate the potential for VOC-impacted soil vapor intrusion into the building indoor airspace.

Sub-Slab Depressurization System Design and Construction

Mitigation Tech in collaboration with Haley & Aldrich, designed and installed the subject property SSDS between 17 February 2023 and 15 March 2023. Haley & Aldrich personnel observed activities associated with SSDS installation. Project construction activities are summarized in a Construction Completion Report (CCR) prepared by Mitigation Tech, dated 23 March 2023, and included in Appendix A.

PRE-DESIGN SUB-SLAB COMMUNICATION TESTING

Mitigation Tech conducted pre-construction diagnostic sub-slab air communication testing beneath the subject property concrete building floor slab to facilitate SSDS design. On 6 February 2023, Mitigation Tech drilled small diameter vacuum holes and large core borings into the concrete slab at proposed suction point locations. Vacuum was applied to suction points and differential pressure measurements were recorded at nearby test points at varying distances to estimate the expected radius of influence for typical suction points. Mitigation Tech used those data to perform volumetric airflow analyses to determine the number of suction points needed to meet system performance objectives, where was determined to be 14.

SSDS CONSTRUCTION AND PERFORMANCE EVALUATION

The as-built SSDS consists of four (4) roof-mounted fans connected by manifold piping to fourteen (14) suction points within the subject property building footprint. SSDS components and installation activities are described in the CCR prepared by Mitigation Tech (Appendix A). The SSDS component layout is shown on the figure titled, "Record Drawing – 3/15/2023," prepared by Haley & Aldrich and included with the CCR.

Following SSDS construction, Mitigation Tech conducted a performance evaluation to assess the as-built system performance as witnessed by Haley & Aldrich. The system design objective was to create and maintain a minimum negative pressure differential of 0.004 inches of water column (in.w.c.) below the building's concrete slab relative to its indoor air ambient pressure. On 15 March 2023, Mitigation Tech established eighteen (18) test points in the concrete slab throughout the subject property building to assess if sub-slab area depressurization (i.e., negative pressure differential) met or exceeded system design objectives. As presented in the CCR, vacuum readings at each test point met or exceeded the

system design objectives. SSDS operation and maintenance guidelines, as well as performance monitoring recommendations are presented in the CCR.

Conclusions

Based on both Haley & Aldrich's construction observations and SSDS construction details and performance evaluation information provided in the CCR, Mitigation Tech installed a SSDS meeting project design objectives and in general conformance with NYSDOH guidance. Migrated contamination from the Dale Road site likely remains in soil, groundwater, and soil vapor beneath the subject property. However, the SSDS meets design criteria to prevent intrusion of VOC-impacted vapors into indoor air. Installation and continued operation of the SSDS addresses the indoor impacts from subsurface conditions identified in the REC in the November 2022 Phase I ESA and confirmed as part of Phase II activities in December 2022 and January 2023.


Note that this installation was not conducted under a regulatory program and done voluntarily. There are portions of Sections 5 and 6 of the appended CCR that are included for reference, but are not required by a regulatory agency, agreement, or order (e.g., Annual Certification). Regular maintenance and monitoring are recommended for continued operation and effectiveness of the system.

We appreciate the opportunity to provide environmental consulting services on this project. Please do not hesitate to call if you have any questions or comments.

Sincerely yours,
HALEY & ALDRICH CONSTRUCTION SERVICES, INC.



Mark N. Ramsdell, P.E. (NY)
Senior Construction Project Manager



Claire L. Mondello
Senior Associate

Enclosures:
Appendix A – Mitigation Tech Construction Completion Report
Figure – Record Drawing

https://haleyaldrich.sharepoint.com/sites/GreenMountainElectricSupply/Shared Documents/0207713.Buffalo NY (Construction)/Deliverable/2023_0503_24AndersonRoad_SSDS_Installation_Letter_Report_R1.docx


References

1. NYSDOH, 2006. *Final Guidance for Evaluating Soil Vapor Intrusion in the State of New York*. October.

2. NYSDOH, 2017. Update to Soil Vapor / Indoor Air Decision Matrices (https://www.health.ny.gov/environmental/indoors/vapor_intrusion/update.htm). October 2006.

3. Mitigation Tech, 2023. Sub-Slab Depressurization System Construction Completion Report, Green Mountain Electrical Supply – 24 Anderson Road, Buffalo, NY, prepared by Mitigation Tech, dated 23 March 2023.

FIGURES



LEGEND

- BUILDING COLUMN
- CO-LOCATED SUB-SLAB SOIL VAPOR AND INDOOR AIR SAMPLE, DECEMBER 2022
- AMBIENT/OUTDOOR AIR SAMPLE, DECEMBER 2022
- 2022 SUB-SLAB SOIL VAPOR AND INDOOR AIR SAMPLING RESULTS EXCEED THE 2017 NYSDOH SOIL VAPOR/INDOOR AIR MATRIX A TRICHLOROETHENE (TCE) GUIDELINES FOR MITIGATION
- SUBJECT PROPERTY BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. NYSDOH = NEW YORK STATE DEPARTMENT OF HEALTH
3. AERIAL IMAGERY SOURCE: NEARMAP, 18 AUGUST 2022

N

0 30 60

SCALE IN FEET

RECORD DRAWING - 3/15/2023

HALEY ALDRICH

GREEN MOUNTAIN ELECTRICAL SUPPLY
24 ANDERSON ROAD
BUFFALO, NEW YORK

BUILDING PLAN AND SUB-SLAB INSTALLATION

JANUARY 2023

FIGURE 1

GIS: C:\Users\anichols\haleyaldrich.com\Green Mountain Electric Supply - General\GIS\Maps\2023_01\203877_014_0001_BUILDING_PLAN.mxd - anichols - 1/5/2023 10:19:23 AM

APPENDIX H

Farmer Qualifications

MATT BURLEIGH, P.G., CAPM
Vice President & Director of Environmental Services

EXPERIENCE

Mr. Burleigh has over 25 years of experience as an Environmental Geologist, Project Manager, and Laboratory Analyst. Mr. Burleigh has had extensive experience managing and providing services in all phases of project development, implementation and evaluation including Phase I/II ESAs, SWPPP/SPCC Plans and UST removal/closure projects. He is knowledgeable in ASTM E1527 – 05 ASTM Standard Practice Environmental Site Assessments: Phase I Environmental Site Assessment Process and EPA All Appropriate Inquiry (AAI). He has performed extensive site surveys, report writing, technical specifications and drawing preparation and review, research and review of codes, laws and regulations, review of contractors' submittals, and environmental site assessments and audits. He has managed numerous environmental site assessments at locations in Texas and throughout the United States and Canada. He has managed project management staff, while effectively allocating resources to ensure that quality services are provided to clients.

Mr. Burleigh has performed Phase II and Phase III subsurface investigations, remediation and risk assessments in order to predict the movement and fate of contaminants. Hydro-geologic assessments have included conducting aquifer pumping/slug tests, and groundwater modeling. He has assisted in the construction and maintenance of groundwater remediation systems used to recover organic compounds from the groundwater and soil. Mr. Burleigh has conducted Receptor Surveys and Drinking Water Survey Reports to support TCEQ PST, Dry Cleaner Remediation Program (DCRP) applications, and TRRP Affected Property Assessment Reports (APAR). Mr. Burleigh is experienced in management, consulting and interaction with clients, developers, brokers, legal counsel and litigants, and regulatory agencies.

Mr. Burleigh also managed the Underground Storage Tank Program for local municipal transportation company for a period of time. Responsibilities included arranging for periodic maintenance and routine testing of tank equipment including tank tightness testing, automatic tank gauge (ATG) maintenance and repair, line tightness testing, leak detector testing and assuring upgrade requirements met the Final UST Technical Deadlines for Tank Owners and Operators.

Prior to entering the environmental consulting, Mr. Burleigh worked as a laboratory analyst for Texas Instruments Defense Systems and Electronics Group. Those duties included metals analysis using inductively coupled plasma spectroscopy to assure parts used in the defense systems met all military specifications.

Mr. Burleigh has completed environmental investigations for a wide variety of clients including major oil companies, municipalities, utility companies, nationwide corporate/industrial facilities, development companies, financial institutions and real estate companies.

LICENSES AND CERTIFICATIONS

- TCEQ LPST Corrective Action Project Manager (CAPM 00107)
- Texas Board of Professional Geoscientists-Geology, License Number 4468

EDUCATION

- B.S. Geology, McNeese State University, 1985
- M.S. Geochemistry, University of Texas at Dallas, 1996

CONTINUING EDUCATION

- Texas Natural Resource Conservation Commission (TCEQ) PST Remediation Workshop
- TCEQ Risk-Based Assessment Workshop
- Project Management Training
- LPST Corrective Action Project Manager Training
- Hazardous Waste Operations and Emergency Response Training
- American Petroleum Institute Hands-On Risk Assessment and Modeling Training

PUBLICATIONS

Burleigh, G.M., 1996, A Detailed Geochemical Study of Soil lead at a Former Lead-Acid Battery Recycling Site, M.Sc. Thesis, The University of Texas at Dallas, 149 p.

ROY D. KING

Environmental Project Manager

EXPERIENCE

Mr. King has over 20 years of experience as an Environmental Scientist and Project Manager. He has successfully resolved business-related environmental issues in all phases of project development, implementation and evaluation including Phase I/II/III ESAs, SWPPP/SPCC Plans and UST removal/closure projects. Mr. King has a broad range of experience in ASTM E1527 – 13 ASTM Standard Practice Environmental Site Assessments: Phase I Environmental Site Assessment Process and EPA All Appropriate Inquiry (AAI). He has performed extensive site surveys, report writing, technical specifications and drawing preparation and review, contract management, and environmental site assessments and audits. He has managed numerous environmental site assessments at locations in Texas and throughout the United States as well as Central America. He has managed project management staff, while effectively allocating resources to ensure that quality services are provided to clients.

Mr. King has performed Phase II and Phase III subsurface investigations, remediation and risk assessments in short order and minimal expenditure. Hydrogeologic assessments have included conducting aquifer pumping/slug tests and groundwater modeling. He has assisted in the construction and maintenance of groundwater remediation systems including traditional and alternative technologies. Mr. King has conducted Receptor Surveys and Drinking Water Surveys to support TCEQ PST, Dry Cleaner Remediation Program (DCRP) applications, and TRRP Affected Property Assessment Reports (APAR). He has also served as a FERC Environmental Inspector for construction of pipelines, cavern wells and compressor stations. Mr. King is experienced in management, consulting and interaction with clients, developers, brokers, legal counsel and litigants, and regulatory agencies.

Mr. King has completed environmental investigations for a wide variety of clients including major oil companies, municipalities, utility companies, nationwide corporate/industrial facilities, development companies, financial institutions and real estate companies.

EDUCATION

- B.S. Biology, University of North Texas, 1990

CONTINUING EDUCATION

- Texas Natural Resource Conservation Commission (TCEQ) PST Remediation Workshop
- TCEQ Risk-Based Assessment Workshop
- CLE International, Austin, Texas, Texas Wetlands Conference
- LPST Corrective Action Project Manager Training
- Hazardous Waste Operations and Emergency Response Training