Phase I
Environmental Site Assessment

Location:

Pilgrim Village- Sublots 3, 4, and 5
903 and 951 Ellicott Street
Buffalo, New York 14209

Prepared for:

Primecore, LLC
c/o Mr. Ara Kervandjian
120 West Cherry Lane
State College, Pennsylvania 16803

LaBella Project No. 2231229
Award/Client Project No. N/A

March 24, 2023

LaBella
Powered by partnership.

Table of Contents

Executive Summary **1**

1.0 Introduction **6**

1.1 Purpose 6

1.2 Scope of Work 8

1.3 Data Gaps 9

1.4 Limitations and Exceptions of Assessment 10

1.5 Reliance 10

2.0 Subject Property and Vicinity Description **11**

2.1 Building Summary 12

2.2 Physical and Hydrogeological Setting 12

3.0 User-Provided Information **13**

3.1 Reason For Performing Phase I ESA 13

4.0 Site Reconnaissance **14**

4.1 Site Reconnaissance Summary of Findings 17

5.0 Subject Property History and Use **18**

5.1 Sanborn Fire Insurance Maps 18

5.2 City Directories 19

5.3 Aerial Photographs 21

5.4 Topographic Maps 21

5.5 Municipal Records 22

5.6 Recorded Land Title Records 24

5.7 Additional Sources 24

5.8 Review of Previous Reports 24

5.9 Historical Summary of Findings 28

6.0 Regulatory Information **32**

6.1 Regulatory Report Summary 32

6.2 Enforcement Action/Permitted Activities/Institutional Controls 36

6.3 Regulatory Agency File and Records Review 36

6.4 Regulatory Information Summary 36

7.0 Interviews **37**

7.1 Owner/Subject Property Representative 37

7.2 Current Occupants 37

7.3 Former Owners/Operators/Occupants 37

7.4 Neighbors 37

7.5 Local Government Official 38

7.6 State Regulator 38

7.7 State and/or County Health Department 38

7.8 Summary of Interviews 38
8.0 Additional Services/ASTM Non-Scope Considerations 39
8.1 Emerging Contaminants 39
9.0 Findings and Opinions 40
9.1 Additional Investigation 42
10.0 Conclusions 44
11.0 Environmental Professional Statement 45
12.0 References 46
13.0 List of Abbreviations/Acronyms 47

Table of Appendices

Site Maps
Hydrogeologic Information
User Provided Information
Site Reconnaissance Worksheet
Site Photographs
Historical Information
Owner/Operator Questionnaire
Municipal Information
Regulatory Information
Qualifications
Previous Reports

EXECUTIVE SUMMARY

LaBella Associates, D.P.C. (LaBella) has been contracted by Primecore, LLC to perform a Phase I Environmental Site Assessment (ESA) report for the Pilgrim Village- Sublots 3, 4, and 5 property, 903 and 951 Ellicott Street, Buffalo, Erie County, New York (hereinafter referred to as the "Subject Property").

This assessment was prepared according to the ASTM E1527-13/21 as a portion of the User's requirements in the All Appropriate Inquiries process and to satisfy the due diligence requirements set for Primecore, LLC.

The Subject Property is further described as follows:

Subject Property Name	Pilgrim Village- Sublots 3, 4, and 5
Subject Property Address	903 and 951 Ellicott Street, Buffalo, Erie County, New York
Subject Property Acreage (approximate)	6.72
Parcel ID(s)	100.71-3-1.12 and a portion of 100.71-3-1.11
Current Owner	McGuire PV Holding LP
Current Subject Property Use/ Development	Developed with three two-story apartment buildings and one single-story storage garage
Public Thoroughfares and Access/Egress	Best Street to the north, Michigan Avenue to the east, East North Street to the south, Ellicott Street to the west
Exterior Areas	Maintained landscaping and grassy areas, asphalt and gravel parking lots, and concrete sidewalks
Surrounding Area	Urban
Subject Property Utilities	
Electric Source	Public
Natural Gas Source (if provided)	Public
Potable Water Source	Public
Sanitary Wastewater Disposal	Public
Non-Sanitary Wastewater Disposal	N/A

Based on LaBella's review of historical records, the history of the Subject Property is summarized as follows:

Time Period	Apparent Use/Development
In or before 1889 through at least 1974	Developed with several former residential and commercial buildings throughout the property, including a former soap factory, auto repair shop/private garage, window cleaning company, an aluminum and brass manufacturing facility, a carting & storage company, and auto garage/collision shop.
1980 through present	Developed with the existing buildings (including former apartment buildings that were demolished in 2015), used residentially as the Pilgrim Village housing complex.

Based on the results of this assessment, the following RECs have been identified in connection with the Subject Property:

- The Subject Property was historically used/developed with the following:
  - A soap factory in at least 1889 historically addressed at 919 Ellicott Street (western-central portion of the property). This former building/property was also used as an aluminum and brass specialty manufacturing facility (W.A. Eckert Manufacturing Co.) between at least 1925 and 1935, historically addressed at 917-919 Ellicott Street.
  - An auto repair shop/garage between at least 1925 and 1950 historically addressed as 931-935 Ellicott Street (northwest portion of the property). A gasoline UST was depicted within Ellicott Street, directly west of the auto repair shop, between at least 1925 and 1951. Municipal records indicate the installation of one 550-gallon UST at 933 Ellicott Street in 1945 and the removal of one 550-gallon UST at 931-935 Ellicott Street in 1974. Additionally, this former building was also used as a window cleaning company and associated maintenance company/building between at least 1955 and 1971.
  - A carting and storage facility between at least 1930 and 1960 historically addressed at 86 East North Street (southwest portion of the property) and was also identified as an auto garage/collision shop between at least 1967 and 1972. Municipal records indicate that at least 4 former gasoline USTs were installed and filled in place or removed from this site between at least 1947 and 1968.
- According to investigation and remedial reports provided and reviewed, several soil and groundwater investigations had been conducted on the southwest portion of the Subject Property identified as Sublot 4, since 2014, which identified the presence of urban fill material within the subsurface of Sublot 4 containing concentrations of metals exceeding NYSDEC Part 375 Soil Cleanup Objectives. Sublot 4 was subsequently accepted into the NYSDEC BCP (Site ID C915294) in 2015. A NYSDEC BCP Remedial Investigation was

implemented at the Subject Property in 2015 which included comprehensive investigation of the surface soil, subsurface soil, and groundwater at Sublot 4 and evaluation of remedial alternatives (i.e. Alternatives Analysis) to establish a remedial approach to support demolition of the apartment complex occupying the Subject Property at that time, and to redevelop Sublot 4 with a new mixed-use commercial and residential building. The results of the Remedial Investigation suggested that the subsurface impact present at Sublot 4 appeared to be primarily related to urban fill material occurring on Sublot 4 to a maximum depth of approximately 10 feet below the ground surface (ft bgs). VOCs, pesticides, and PCBs were detected at the Subject Property at concentrations exceeding their respective NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives and Groundwater Class GA Standards; however, the primary contaminants of concern at Sublot 4 appear to consist of SVOCs and metals present in both soil and groundwater, which is typical of properties overlain by urban fill material. Based on the contents of the May 2019 Remedial Investigation and Alternatives Analysis Report, it appears that the remedial approach selected by the owner of Sublot 4 included pursuit of an Unrestricted Track 1 cleanup. It should be noted that based on LaBella's interview with the NYSDEC, the Remedial Investigation and Alternatives Analysis Report has not been finalized, and the NYSDEC has not provided formal approval of the Remedial Investigation and Alternatives Analysis Report or the remedial approach suggested within that document. Per LaBella's interview with the NYSDEC, the NYSDEC reported that should another entity, such as Primecore, LLC, desire continuing with the BCP, that such can likely be pursued through submission of a Brownfield Cleanup Agreement Amendment, and preparation of a new Alternatives Analysis Report to match any alternative re-development approaches and corresponding cleanup strategies contemplated for Sublot 4.

- Additionally, according to an October 2022 settlement agreement executed by the owner of Sublot 4 and other parties, slag fill material was imported to Sublot 4 in or around December of 2019 and was utilized to backfill the foundations of the former apartment complex following demolition of said structures. Field screening and laboratory analysis of the slag material conducted by several consultants independently in 2020 determined that the slag backfill exhibited elevated radiological levels consistent with TENORM. According to a January 2023 report documenting the remediation of the slag, prepared by C&S, a removal action was conducted at Sublot 4 between October 18, 2022 and December 13, 2022 that resulted in the excavation and off-site disposal of 5,164.49 tons of TENORM slag from within and around the building foundations and internal Subject Property roadway. Following the removal of the slag, the radiological contractor that was commissioned to complete this work (AMS) performed a post-remedial radiological survey that confirmed the cleanup criteria established in the remedial work plan had been achieved. That is, the post-remedial survey determined that 95% of the survey measurements or counts were less than the upper tolerance limit of the background measurements; and that no single measurement exceeded two times the background measurement. AMS issued a letter dated December

22, 2022 summarizing the post-remedial radiological survey that was submitted to the NYSDEC. In response to this submittal, the NYSDEC transmitted an e-mail on December 27, 2022 noting that they had no comments on the survey report. LaBella understands that, in light of Primcore's plan to remove all urban fill from the Subject Property prior to redevelopment, Primecore has elected not to commission an independent Certified Health Physicist to review the risk assessment prepared following the completion of the TENORM slag removal from Sublot 4.

- Based on the collective documentation reviewed, environmental assessment of Sublot 3 and Sublot 5 was included within at least two Phase I ESA's, Phase II ESAs, and a geotechnical assessment conducted for the greater Site including Sublot 4. Generally speaking, it appears that the focus of the subsurface investigations and geotechnical assessment were related to project planning efforts for Sublot 4, and only limited subsurface data was generated related to Sublot 3 and Sublot 5. The limited subsurface data available for Sublot 3 and Sublot 5 did identify similar subsurface conditions to those encountered on Sublot 4, with urban fill material being encountered to a maximum depth of approximately eight feet bgs, and limited soil samples collected from both Sublot 3 and Sublot 5 identifying metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives. Furthermore, it should also be noted that "perimeter" subsurface soil samples collected as part of the BCP Remedial Investigation for Sublot 4 consistently identified SVOCs, pesticides, and metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives along the parcel boundary shared with Sublot 3 and Sublot 5. The extent and severity of the subsurface impact present at Sublot 3 and Sublot 5 is unknown.

LaBella notes that although historic operations/uses of potential concern did not appear to be specifically targeted as part of previous subsurface investigations, the investigations were generally located proximate to and within the general vicinity of a majority of the historic operations/uses. Additionally, LaBella recently completed a Phase II ESA on Sublots 3 and 5, in March 2023, to assess if historic operations/uses have impacted the subsurface of the Subject Property. The Phase II ESA report has been provided to Primecore, LLC under separate cover.

Based on the results of this assessment, no CRECs, HRECs, de minimis conditions, or significant data gaps have been identified in connection with the Subject Property.

While not considered a REC, CREC, HREC, de minimis condition, or significant data gap at this time, LaBella also notes the following:

- Seven unlabeled 55-gallon drums were observed along the western exterior of the garage building located on the southeastern portion of the property. The contents of these drums were unknown. No evidence of leaks or staining was observed on or around the drums at the time of LaBella's site visit.

- Several fill material piles consisting of mixed dirt, stone, and concrete were observed on the southeast portion of the property, reportedly associated with construction activities. No evidence of staining was observed in the areas of the fill material piles at the time of LaBella's site visit.

Based on the findings of this assessment, additional investigation would be recommended; however, LaBella recently completed a Phase II ESA on Sub Lots 3 and 5, in March 2023, to assess if historic operations/uses have impacted the subsurface of the Subject Property. The Phase II ESA report has been provided to Primecore, LLC under separate cover.

Remedial activities proposed for the on-site contamination at Sub Lot 4 should be submitted and approved by the NYSDEC under the Brownfield Cleanup Agreement established for Sub Lot 4.

1.0 INTRODUCTION

LaBella has been contracted by Primecore, LLC to perform a Phase I Environmental Site Assessment report for the Pilgrim Village- Sublots 3, 4, and 5 property, 903 and 951 Ellicott Street, Buffalo, Erie County, New York.

The findings of this report are based upon an assessment of the condition of the Subject Property within the Scope of Work and objective described below as of the date of the site observations and documentation review. This assessment was prepared according to the ASTM Standard Practices E1527-13/21 as a portion of the User's requirements in the All Appropriate Inquiries process and to satisfy the due diligence requirements set for Primecore, LLC. The information contained in this report is considered privileged and confidential and is intended solely for the use of the parties listed on the cover of this report, as it applies to the Subject Property.

1.1 Purpose

This investigation was requested to identify, to the extent feasible, RECs in connection with the Subject Property, including the identification of conditions indicative of releases and threatened releases of hazardous substances and petroleum products on, or in the vicinity of the Subject Property This Phase I ESA report was conducted in conformance with the Scope and Limitations of ASTM Standard Practice E1527-13/21.

The performance of ASTM Standard Practices E1527-13/21 is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs and the potential liability for contamination to be present in connection with the Subject Property recognizing reasonable limits of time and cost. It is also intended to satisfy one of the requirements to satisfy "all appropriate inquiry" as defined by 42 U.S.C §9601(35)(B), for the purposes of qualifying for innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on CERCLA Liability. The User should understand that this practice does not address whether requirements in addition to all appropriate inquiry have been met in order to qualify for landowner liability protections; including (1) the continuing obligation not to impede the integrity and effectiveness of activity and use limitations, (2) the duty to take reasonable steps to prevent releases, or (3) the duty to comply with legally required release reporting obligations.

The objective of this Phase I ESA was to determine the following, using our professional judgment, by means of the Scope of Work hereafter described:

1. A general description of the Subject Property.
2. The current and historical usage of the Subject Property and adjoining properties.
3. Whether RECs exist or have the potential to exist in, on, or at the Subject Property.
4. Whether Subject Property conditions suggest further evaluation based on the presence or probable presence of RECs.

5. Provide information which may assist the Client in evaluating the fair market value of the Subject Property.

A REC is defined by ASTM as (1) the presence of hazardous substances or petroleum products in, on, or at the Subject Property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the Subject Property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the Subject Property under conditions that pose a material threat of a future release to the environment. A de minimis condition is not a recognized environmental condition.

A Controlled REC is defined by ASTM as a recognized environmental condition affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations).

A Historical REC is defined by ASTM as a previous release of hazardous substances or petroleum products affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the Subject Property to any controls (for example, activity and use limitations or other property use limitations). A historical recognized environmental condition is not a recognized environmental condition.

A de minimis condition is defined by ASTM as a condition related to a release that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a de minimis condition is not a recognized environmental condition nor a controlled recognized environmental condition.

The term “data gap” means a lack of or inability to obtain information required by this practice despite good faith efforts by the Environmental Professional to gather such information. Data gaps may result from incompleteness in any of the activities required by this practice, including, but not limited to, site reconnaissance (for example, an inability to conduct the site visit), and interviews (for example, an inability to interview the key site manager, regulatory officials, etc.). A significant data gap is one that affects the ability of the environmental professional to identify a REC.

The term "data failure" means the failure to achieve the historical research objective as specified in ASTM E-1527-13/21 even after reviewing the standard historical resources that are reasonably ascertainable and likely to be useful. Data failure is one type of data gap.

Migration refers to the movement of hazardous substances or petroleum products in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface.

An Environmental Professional is a person who possesses sufficient specific education, training, and experience necessary to exercise professional judgment to develop opinions and conclusions regarding conditions indicative of releases or threatened releases on, at, in, or to a property, sufficient to meet the objectives and performance factors defined in the ASTM Standard Practice E1527-13/21 and §312.20 of 40 CFR §312. Specifically, an Environmental Professional is defined as a person having one of the following qualifications; (1) A state- or tribal-issued certification or license and three years of relevant, full-time work experience; (2) A bachelor's degree or higher in science or engineering and five years of relevant, full-time work experience; or, (3) 10 years of relevant, full-time work experience.

1.2 Scope of Work

This Phase I Environmental Site Assessment has been prepared in accordance with ASTM E1527-13/21, which has been devised to address the site assessment portion for 40 CFR 312 - Innocent Landowners, Standards for Conducting All Appropriate Inquiries. The Scope of Work performed in this assessment is intended to identify RECs, CRECs, HRECs, de minimis conditions, and Significant Data Gaps through the following tasks:

1. Review of information provided by the User related to environmental cleanup liens; specialized knowledge or experience regarding the Subject Property; the relationship of the purchase price to the fair market value of the property, if the property were not contaminated; and, commonly known or reasonably available information about the Subject Property.
2. Review of local, state, and federal environmental records.
3. Review of historical sources of information to identify the use of the Subject Property dating back to 1940 or first Subject Property development, whichever is earlier.
4. Review of physical and geological settings.
5. Interviews with current and past owners, operators, and occupants to evaluate the potential for environmental contamination to be present at the Subject Property.
6. Inspection of the Subject Property and adjacent properties, to visually identify areas of concern. Adjacent properties were inspected from public roadways and the Subject Property boundaries to the extent possible.
7. The preparation of this report documenting all appropriate inquiries.

The work for this report has been performed in accordance with generally accepted environmental engineering practices for this region. The findings of this report are based upon the opinion and judgment of an Environmental Professional and are dependent upon LaBella's knowledge, the information supplied during the interviews, and data and information solicited from governmental agencies. LaBella makes no other warranty or representation, either expressed or implied, nor is one intended to be included as part of its services, proposals, contracts, or reports.

In addition, LaBella cannot provide guarantees, certifications, or warranties that the Subject Property is or is not free of contamination without a subsurface investigation involving drilling, vapor analysis, laboratory soil analysis, groundwater monitoring well installation, and laboratory groundwater analysis. Even with such a program, the data and samples from any given soil boring or monitoring

well will indicate conditions that apply only at that particular location, and such conditions may not necessarily apply to the general Subject Property as a whole.

1.2.1 Significant Assumptions

Significant assumptions made in the performance of this Phase I ESA are as follows:

- Regional groundwater flow follows major topographic gradients.
- Representations made during interviews are accurate.

1.3 Data Gaps

LaBella encountered the following data gaps through the completion of this Phase I Environmental Site Assessment:

Nature of Data Gap	Details/Description	Data Sources Consulted
Limitations to Site Inspection[1]	Observations were limited due to parked vehicles, stored materials, and construction-related areas. LaBella inspected representative portions and apartments of the apartment buildings.	N/A
Historical Use	Historical uses were not obtained for each five-year period.	Aerial photographs, Sanborn maps, city directories, municipal records, previous studies
Regulatory Records Review	LaBella has yet to receive complete responses from all regulatory information requests.	NYSDOH, NYSDEC, a complete response from the City of Buffalo
Interviews	LaBella has not been able to identify and/or contact any historical owners, operators, or occupants.	Current owners, municipal, and/or User-provided records to identify historical ownership information.
User	LaBella has yet to receive a completed User Questionnaire.	User
Any data gaps determined by the Environmental Professional to be significant are further discussed within the Findings and Opinions section of this report. [1] See Limitations and Exceptions of Assessment below for additional limitations of the site visit.		

1.4 Limitations and Exceptions of Assessment

ASTM E1527-13/21 expressly recognized the fact that no ESA can wholly eliminate uncertainty regarding the potential for RECs in connection with a property. LaBella's work is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs in connection with the Subject Property, and its Scope of Work reflects recognition of the reasonable limits of time and cost.

The work for this report has been performed in accordance with the master service agreement signed with Primecore, LLC. The conclusions of this report are based upon LaBella's opinion and judgment and are necessarily dependent on information supplied by the individuals, entities, and agencies contacted through the course of this assessment. LaBella makes no other warranty or representation, either expressed or implied, nor is one intended to be included as part of its services, proposals, contracts, or reports.

The actual presence of asbestos, radon, lead-based paint, lead in drinking water, wetlands, regulatory compliance, endangered species, indoor air quality, mold, substances not defined as hazardous substances, cultural and historical resources, archeological resources, ecological resources, industrial hygiene, health and safety, biological agents, and/or high voltage power lines, are not included in the Scope of Work of this assessment unless agreed to by Primecore, LLC and LaBella; in such a case, these additional services/ASTM Non-Scope Considerations are discussed in Section 8.0 below. Should Primecore, LLC desire any of these additional services, such can be completed by LaBella under separate cover; however, they are not included in the Scope of Work of the Phase I ESA.

The site reconnaissance was limited to visual observations of accessible areas only. No attempt was made to observe conditions in spaces not generally accessible, including but not limited to:

1. Entering crawlspaces and attics
2. Walking on roofs
3. Viewing the interior of pipe chases or plenum
4. Viewing spaces concealed by walls, floors, ceilings, interior finishes, etc.
5. Viewing areas inaccessible due to topographic features or locked doors, obscured by snow cover, vegetative growth, vehicles, etc.

The site reconnaissance was also limited to visual observations within the perimeter of the Subject Property and other accessible areas only. At the time of the site reconnaissance, a representative portion of the Subject Property and common areas were visually inspected.

1.5 Reliance

Primecore, LLC may rely upon the findings of this report and should be aware of the agreed upon Scope of Work and the limitations associated with this Scope of Work.

2.0 SUBJECT PROPERTY AND VICINITY DESCRIPTION

The Subject Property is summarized in the tables below. Property boundaries for the purpose of this assessment were determined based on provided survey mapping and/or tax maps obtained through municipal sources. Subject Property Location and Tax Parcel maps for the Subject Property are located in the Site Maps Appendix.

Subject Property Name	Pilgrim Village- Sublots 3, 4, and 5
Subject Property Address	903 and 951 Ellicott Street, Buffalo, Erie County, New York
Subject Property Acreage (approximate)	6.72
Parcel ID(s)	100.71-3-1.12 and a portion of 100.71-3-1.11
Current Owner	McGuire PV Holding LP
Current Subject Property Use/ Development	Developed with three two-story apartment buildings and one single-story storage garage
Public Thoroughfares and Access/Egress	Best Street to the north, Michigan Avenue to the east, East North Street to the south, Ellicott Street to the west
Exterior Areas	Maintained landscaping and grassy areas, asphalt and gravel parking lots, and concrete sidewalks
Surrounding Area	Urban
Subject Property Utilities	
Electric Source	Public
Natural Gas Source (if provided)	Public
Potable Water Source	Public
Sanitary Wastewater Disposal	Public
Non-Sanitary Wastewater Disposal	N/A

2.1 Building Summary

Structure(s) located on the Subject Property are summarized in the following table:

Building Name	Apartment Buildings 1, 2, and 3	Garage
Square Footage	3,150; 4,374; and 6,155	1,218
Foundation Type	Full basement	Slab-on-grade
Number of Stories	Two	One
Construction Date	1980	
Heating/Cooling Source	Natural gas and electric	Not heated or cooled
Current Use	Apartments	Storage of property maintenance materials and equipment

2.2 Physical and Hydrogeological Setting

Based on a review of provided records, the following information was obtained regarding the physical and hydrogeological setting of the Subject Property:

Topography	Generally level
Elevation (feet above mean sea level)	Approximately 644
Subject Property Water Bodies	None
Nearest Water Body	Niagara River/approximately 1.8 miles to the west
Apparent Groundwater Flow	North
Soil Map Unit(s)	Urban land consists of areas that have been so altered or obscured by urban works and structures that identification of the soils is not feasible. Areas are mainly in the closely built-up parts of the city.
Geological Information	Onondaga and Bois Blanc Limestones from the Middle Devonian period. The primary and secondary rock types consist of limestone and sandstone, respectively.

3.0 USER-PROVIDED INFORMATION

In accordance with the ASTM E1527-13/21, a "User" is defined as the party seeking to complete an environmental site assessment of the property. If the user is aware of any specialized knowledge or experience that is material to RECs in connection with the Subject Property, it is the user's responsibility to communicate any information based on such specialized knowledge or experience to the Environmental Professional. The User Questionnaire was not completed. A copy of the blank User Questionnaire is included in the User Provided Information Appendix.

3.1 Reason For Performing Phase I ESA

According to ASTM 1527-13/21, either the User shall make known to the Environmental Professional the reason why the User wants to have the Phase I ESA performed or, if the User does not identify the purpose of the Phase I ESA, the Environmental Professional shall assume the purpose is to qualify for the Landowner Liability Protections under the Brownfields Amendments. The User did not identify the reason for conducting the Phase I ESA.

4.0 SITE RECONNAISSANCE

LaBella conducted a site reconnaissance of the Subject Property as well as observations of adjacent properties as viewed from the Subject Property boundaries and public roadways, to the extent possible, to visually identify areas of concern. The site reconnaissance was conducted on March 13, 2023 by Christopher Finn, Environmental Analyst with LaBella. At the time of the site reconnaissance, LaBella was accompanied by Samanatha Scavulli, Property Manager associated with the Subject Property for 1.5 years.

Observations discussed in this Section are noted on Figure 3. Copies of the field notes taken during the site visit are included in the Site Reconnaissance Worksheet Appendix. Representative photographs of the Subject Property at the time of the site reconnaissance are included in the Site Photographs Appendix.

At the time of the site reconnaissance, a representative portion of apartments and common areas were visually inspected within each apartment building. In addition, visual observations were limited at the time of the site visit due to on-going construction activities, material storage, and parked vehicles. Additional site visit limitations are discussed in Section 1.4.

Past Uses of Subject Property

No apparent indicators that would indicate historical uses of the Subject Property (e.g., signs, equipment, etc.) were observed at the time of the site reconnaissance. However, reported former building foundations were observed on the southern portions of the property on Sublots 4 and 5 and are reportedly associated with former residential/apartment buildings.

Hazardous Substances and Petroleum Products

No apparent hazardous substances or petroleum products were observed on the Subject Property.

Unidentified Substance Containers

Seven unlabeled 55-gallon drums were observed along the western exterior of the garage building located on the southeastern portion of the property. The contents of these drums were unknown. No evidence of leaks or staining was observed on or around the drums at the time of LaBella's site visit.

Storage Tanks

No apparent indications of aboveground or underground storage tanks (e.g., fill ports, vent pipes, access ways) were observed at the Subject Property at the time of the site visit.

Solid, Hazardous, and/or Regulated Wastes

The following wastes were noted, stored, or generated on the Subject Property:

Material	Source/Process	Storage Location/Quantity	Transporter/ Hauler
General refuse/ recyclables	Residential and/or commercial operations	Several cans exterior each building	City of Buffalo

Evidence of fill material was observed in the southeastern portion of the Subject Property which included mixed piles of soil, stone, and concrete, reportedly associated with on-site construction activities.

Odors

No apparent strong, pungent, or noxious odors were observed at the Subject Property at the time of the site reconnaissance.

Standing Water/Pools of Liquid

No apparent pools, sumps, or standing water containing liquids likely to be hazardous substances or petroleum products were observed at the Subject Property at the time of the site visit.

PCB-Containing Equipment

The following potential PCB-containing equipment was observed at the time of the site reconnaissance:

Potential PCB-Containing Equipment	Location	Evidence of Leaks
Three Pad-Mounted Transformers	One near each apartment building	None

Stains and Corrosion

No apparent stains or corrosion were observed at the time of the site reconnaissance.

Stressed Vegetation

No apparent stressed vegetation was observed at the time of the site reconnaissance.

Drains and Sumps

Floor drains and sumps were observed within the basements of the apartment buildings and reportedly discharge to the public sewer system. No leaks, stains, spills, or unusual odors were noted in the vicinity of the drains at the time of the site visit. The sumps reportedly collect storm water and discharges to the public sewer system.

Wastewater

Non-sanitary wastewater does not appear to be generated or discharged at the Subject Property.

Septic Systems and/or Cesspools

No apparent indications of septic systems or cesspools were observed at the time of the site reconnaissance or are reported to be located on the Subject Property.

Wells

No apparent potable, monitoring, irrigation, dry, or injection wells were observed at the time of the site reconnaissance or are reported to be located on the Subject Property.

Additional Information

Sheet piling was observed along the perimeter of Sub Lot 4 at the time of the site visit. Due to observational limitations at the time of the site visit, it is unknown if the sheet piling is installed around the entirety of Sub Lot 4, or if it was installed along partial sections of the perimeter of Sub Lot 4. The sheet piling was likely installed as part of remedial preparations associated with the proposed removal of fill material from the subsurface of Sub Lot 4. Evidence of the sheet piling is included in select photographs taking during the site visit, which are included herein.

Adjacent Property Use

The Subject Property is bordered by the following properties:

Direction	Current Use/Occupant	Apparent Past Use	Potential Concerns Visible During Site Visit
North	Alpha Book Publisher and residential (66-98 Best Street), parking lot (960 Ellicott Street)	Commercial, residential	No
East	Apartments under construction (951 Ellicott Street, 1100 Michigan Avenue) and Buffalo City Mission (150 North East Street)	Residential, commercial	No
South	Parking lot (121 North East Street), Kaleida Health Medical Building (101 North East Street), Gates Vascular Institute (851 Ellicott Street), and parking ramp (854 Ellicott Street)	Medical and commercial, parking lots	No
West	Buffalo Hearing and Speech (50 North East Street), Vacant lots (49-50 St Paul), and Niagara Mohawk Electrical (45-53 Best Street)	Medical, commercial, vacant	No

Refer to Regulatory Information below for additional information regarding the north, south, east, and west adjacent properties.

4.1 Site Reconnaissance Summary of Findings

Observations made by LaBella during the site reconnaissance identified the following features indicative of the presence or likely presence of hazardous substances or petroleum products in, on, or at the Subject Property:

- Seven unlabeled 55-gallon drums were observed along the western exterior of the garage building located on the southeastern portion of the property. The contents of these drums were unknown. No evidence of leaks or staining was observed on or around the drums at the time of LaBella's site visit.
- Several fill material piles consisting of mixed dirt, stone, and concrete were observed on the southeast portion of the property, reportedly associated with construction activities. No evidence of staining was observed in the areas of the fill material piles at the time of LaBella's site visit.

5.0 SUBJECT PROPERTY HISTORY AND USE

LaBella attempted to review reasonably ascertainable and readily available standard sources of historical information as defined by the ASTM E1527-13/21 in order to identify all obvious uses of the Subject Property back to the first developed use or 1940, whichever is earlier (i.e., the historical research objective according to ASTM). Uses of the properties adjacent to the Subject Property are identified in this report only to the extent that this information was revealed in the course of researching the Subject Property itself and were determined at the discretion of the Environmental Professional. As such, LaBella reviewed only as many of these sources as necessary to achieve the historical research objective. Data failures and data gaps are identified, defined, and evaluated for their significance in Section 1.3 of this report.

Additional/historical addresses of the Subject Property were identified through the review of historical sources as 65-93 Best Street, 68-132 East North Street, 903-935 Ellicott Street, 64-74 (even and odd) St. Paul Street, 810 Elm Street, and 6-48 (even and odd) Welmont Place; these addresses were searched as part of the City Directory review discussed below.

5.1 Sanborn Fire Insurance Maps

The apparent historical use of the Subject Property and surrounding area, as depicted by the Sanborn maps, is summarized in the table below. A copy of the Sanborn maps is included in the Historical Information Appendix.

Former on-site streets that transected portions of the Subject Property between at least 1889 and 1951 included: Oak Street running north-south in the central portion (identified as Welmont Place between 1889 and 1951), St. Paul Street on the western-central portion running east-west, and Elm Street running north-south along the eastern property border.

Year	Location	Occupant/Development
1889, 1899	Subject Property	Developed with numerous dwellings and a few storefronts throughout and the Jabesh Harris Soap factory on the western-central portion of the property. By 1899, the Soap Factory was converted into 'Homestead Laundry'
	Surrounding Area	Heavily developed with dwellings, storefronts, and commercial buildings
1925, 1951	Subject Property	Developed with numerous dwellings and a few storefronts throughout, a plumbing shop on the northern portion, an auto repair shop with a gasoline UST depicted within Ellicott Street on the northwest portion (north of St. Paul Street), and W.A. Eckert Manufacturing Company-manufacturer of aluminum and brass specialties on the western-central portion. By 1951, the W.A. Eckert Mfg. Co. building was removed from the Subject Property, the auto repair shop was

Year	Location	Occupant/Development
		identified as a private garage, a restaurant was located on the northwest corner of the property, and a private garage was depicted on the southern portion of the property which appeared to be associated with a storefront/dwelling
	Surrounding Area	Heavily developed with residential, commercial, and industrial buildings
1981, 1986	Subject Property	Developed with 11 residential buildings (including the existing apartment buildings) and one maintenance building (existing garage), identified as Pilgrim Village
	Surrounding Area	Heavily developed with residential and commercial buildings including various medical related buildings

The following adjacent property uses of potential concern were identified:

- The south adjacent property historically addressed as 77 East North Street was identified as E.A. Cook Wagon Works Inc. in at least 1925 and E.A. Cook Body Corp. in at least 1951; both operations included repairing, woodworking, and auto painting.
- The west adjacent property historically addressed as 888 Ellicott Street/938 Ellicott Street was identified as an auto repairing facility between at least 1925 and 1951.
- The west adjacent property historically addressed as 908 Ellicott Street was identified as an auto garage with two gasoline USTs between at least 1925 and 1951.

5.2 City Directories

City Directory research was completed by ERIS. Identified occupants associated with the Subject Property are detailed in the table below. Copies of street directories are included in the Historical Information Appendix.

Year	Occupant Listings
1930	Several residential and commercial listings including W A Eckert Manufacturing Co. aluminum specialties (917-919 Ellicott Street), St. Paul Auto Repair Shop (931-935 Ellicott Street), and PJ Garvey Carting and Storage Inc. (86 East North Street)
1935	Several residential and commercial listings including Eckert Manufacturing Co. aluminum ware manufacturers (917 Ellicott Street), St. Paul Auto Repair Shop (931-935 Ellicott Street), and PJ Garvey Carting and Storage Inc. (86 East North Street)
1940	Several residential and commercial listings including St. Paul Auto Repair shop and Nebrjch & Co. auto electric repairs (931-935 Ellicott Street) and PJ Garvey Carting and Storage Inc. (86 East North Street)

Year	Occupant Listings
1946, 1950	Several residential and commercial listings including PJ Garvey Carting and Storage Inc. (86 East North Street) and Pepsi Cola Bottling Corp. garage (931-935 Ellicott Street)
1955, 1960	Several residential and commercial listings including Main Window Cleaning Co. Inc. and Main Building Maintenance Co. (931-935 Ellicott Street) and P J Garvey Carting and Storage Inc. (86 East North Street)
1965	Several residential and commercial listings including Main Window Cleaning Co. Inc. and Main Building Maintenance Co. (935 Ellicott Street) and Blake Window Cleaner Co. Inc. (79 Best Street)
1971	Several residential and commercial listings, including AAA Window Cleaning/Main Building Maintenance/Main Window Cleaning (935 Ellicott Street) and D. Nelson Collision and Painting (86 East North Street)
1976	Private individual/residential listing (72 East North Street)
1980	Private individuals/residential listings (78, 96, 100, 106, 110, and 118 East North Street)
1985, 1990, 1995, 2003, 2008, 2012, 2016, 2020, 2022	Subject Property addresses not listed with the exception of 77 Best Street which was identified as a private individual/residential listing in at least 1985 and 1990

Review of the city directories indicated that properties surrounding the Subject Property were historically utilized for industrial, commercial, and residential purposes. The following adjacent property uses of potential concern were identified:

- The north adjacent property addressed as 963 Ellicott Street was identified as a dry cleaner in at least 1935.
- The north adjacent property addressed as 68 Best Street was identified as a clothes cleaner in at least 1930.
- The south adjacent property addressed as 77 East North Street was identified as an auto body manufacturer between at least 1930 and 1960.
- The west adjacent property addressed as 908 Ellicott Street was identified as an auto repair/service garage between at least 1930 and 1960.
- The west adjacent property addressed as 938 Ellicott Street was identified as an auto repair facility between at least 1930 and 1950 and a machinery company in at least 1955.

5.3 Aerial Photographs

The table below outlines observations of the Subject Property and surrounding area obtained from the review of aerial photographs. Copies of aerial photographs are included in the Historical Information Appendix.

Year	Location	Development
1958, 1963, 1966	Subject Property	Heavily developed with apparent residential and commercial buildings
	Surrounding Area	Extensive residential and commercial development
1974	Subject Property	A majority of the former residential and commercial structures were removed and the property appeared to consist of grassy/ vegetated land and former streets that transected the property; one suspect residential building remained on the southwest corner, one suspect commercial building remained on the southern portion, and at least two suspect residential buildings and one suspect commercial building remained on the northwest portion
	Surrounding Area	Residential and commercial development and several vacant grassy lots/land
1985, 1995, 2005, 2008, 2011, 2015, 2019	Subject Property	Developed with several apparent apartment buildings, including the existing subject buildings, with associated parking and grassy/ green areas. By 2019, several of the former apartment buildings on the southwest portion of the property were removed.
	Surrounding Area	Residential and commercial development

5.4 Topographic Maps

As sufficient information was obtained through a review of Sanborn maps, city directories, aerial photographs, and municipal records, topographic maps were not reviewed as part of this assessment.

5.5 Municipal Records

LaBella obtained municipal records from the City of Buffalo and the Buffalo Property Record Card website. In addition, limited assessment information was obtained from the Landmax Data Systems, Inc. website. The following information was obtained from these records. Copies of municipal records are included in the Municipal Information Appendix.

	Findings/Details
Parcel ID(s)	100.71-3-1.12 and a portion of 100.71-3-1.11
Subject Property Size (acres)	6.72
Current Owner	McGuire PV Holding LP
Former Owners	Pilgrim Village, Senior Housing Development
Square Footage of Building(s)/Date(s) of Construction	4,374-square foot apartment building/1980 6,155-square foot apartment building/1980 3,150-square foot apartment building/1980 2,083-square foot apartment building/1980 1,218-square-foot storage building/1980
Provided Utilities	All public

A summary of relevant permits/records obtained from the City of Buffalo Permits and Inspections office and City of Buffalo Fire Department/Bureau of Fire Precention is included in the following table:

Year	Structure/Permit
1933	Use brick building for a public garage at 937 Ellicott Street
1940	Demolish factory building at 917 Ellicott Street
1942	Alter brick garage at Pepsi Cola Co. at 931 Ellicott Street
1945	Approval for installation of one 550-gallon gasoline UST at 933 Ellicott Street (Pepsicola Co. Garage)
1947	Installation of one 1,000-gallon gasoline UST at 86 East North Street; a sketch included depicts a house and office building with a 1,000-gallon tank (located 15 feet from East North Street) and a pump, with a note indicating that the new 1,000-gallon tank was replacing an existing 280-gallon tank
1964	Installation of one 4,000-gallon UST and filling of one 1,000-gallon tank with concrete at 86 East North Street
1965	One 4,000-gallon gasoline UST at 86 East North Street was filled with water/ concrete and the associated pump was removed, all lines were capped, and the electric service to the pump was disconnected; a sketch included depicts 86

Year	Structure/Permit
	East North Street including a dwelling, a truck garage, one new 4,000-gallon tank, one pump, one fill for the new tank, and an old tank which was filled with concrete
February 1966	Bureau of Fire Prevention correspondence for 86 East North Street indicating that P.J. Garvey and Co. had moved and the private gas pump had been removed
October 1967	Bureau of Fire Prevention inspection of 86 East North Street, indicating use as Nelson Collision and Painting, occupied by David Nelson: the inspection identified spray painting operations (which were identified as illegal as the property was not licensed to do so) and poor housekeeping of combustibles
July 1968	Removal of one 4,000-gallon tank
March 1970	Bureau of Fire Prevention inspection of 86 East North Street, indicating use as a repair garage occupied by David Nelson: the inspection identified spray painting operations (which were identified as illegal as the property was not licensed to do so) and poor housekeeping of combustibles
November 1972	Bureau of Fire Prevention inspection of 86 East North Street, indicating use as a repair garage occupied by David Nelson: the inspection identified painting operations (which were identified as illegal as the property was not licensed to do so), use of kerosene floor heater, apparent oil and grease deposits on the floor, and poor housekeeping of combustibles
1971-1973	Numerous permits to demolish former residential buildings at various addresses on East North Street, Welmont Place, St. Paul Street, Elm Street, Ellicott Street, and Best Street for Oak Street Redevelopment Project
1973	Abandoned building at St. Paul and Ellicott has a curb pump and gasoline UST, formerly occupied by Main Window Cleaning Company (931-935 Ellicott Street)
1974	Removal of one 550-gallon UST at 931-935 Ellicott Street
1974	Demolish one story brick commercial building at 931 Ellicott Street (64 St. Paul)
1980-1981	Various permits related to the construction of Pilgrim Village housing
2015	Demolish five two-story dwellings in the Pilgrim Village Housing Complex (903 Ellicott Street/38 Holloway Boulevard)

5.6 Recorded Land Title Records

According to the ASTM Standard Practice E1527-13/21, "the user should either engage a title company or title professional to undertake a review of reasonably ascertainable land title records and lien records for environmental liens or activity and use limitations currently recorded against or relating to the property or to negotiate such an engagement of a title company or title professional as an addition to the Scope of Work to be performed by the Environmental Professional."

Title records were not provided to LaBella for review.

5.7 Additional Sources

No additional historical sources were reviewed.

5.8 Review of Previous Reports

On February 9, 2023, LaBella completed the following tasks:

- Reviewed the following documents provided by the Client.
  - Phase I Environmental Site Assessment (ESA) dated July 2014
  - Geotechnical Engineering Report dated July 10, 2014
  - Phase II Subsurface Investigation dated July 23, 2014
  - Supplemental Subsurface Investigation dated September 22, 2014
  - Phase I ESA dated November 24, 2015
  - Brownfield Cleanup Agreement, Agreement Amendments, and supporting documentation
  - Gamma Investigation dated February 5, 2020
  - Radiological Screening & Analysis of Slag Backfill dated July 31, 2020
  - Lot 4 Narrative dated November 25, 2020
  - Technologically Enhanced Naturally Occurring Radioactive Material (TENORM) Remediation Inspection dated January 12, 2023
- Phone interview with the New York State Department of Environmental Conservation (NYSDEC) on February 3, 2023.
- Obtained and reviewed the NYSDEC Remedial Investigation and Alternatives Analysis Report dated May 2019 from C&S Engineers, Inc. (C&S).
- Phone interview with Austin Master Services (AMS) on February 7, 2023.

The following is a summary of the information obtained from the previous reports. It should be noted that the 2014 and 2015 reports were conducted on the entire Pilgrim Village apartment complex which included all of 903 and 951 Ellicott Street and 1100 Michigan Avenue. The Subject Property portion being assessed by LaBella includes 903 Elicott Street and a portion of 951 Ellicott Street,

which is identified as Sublots 3, 4, and 5; 1100 Michigan Avenue is not included within the Subject Property portion.

Sublot 4 – 903 Ellicott Street

Based on the contents of the documents reviewed associated with the southwest portion of the Subject Property identified as Sublot 4, subsurface assessment began in 2014 which identified the presence of urban fill material within the subsurface of Sublot 4 containing concentrations of metals exceeding NYSDEC Part 375 Soil Cleanup Objectives. Sublot 4 was subsequently accepted into the NYSDEC BCP (Site ID C915294) in 2015. A NYSDEC BCP Remedial Investigation was implemented at the Subject Property in 2015 which included comprehensive investigation of the surface soil, subsurface soil, and groundwater at Sublot 4 and evaluation of remedial alternatives (i.e. Alternatives Analysis) to establish a remedial approach to support demolition of the apartment complex occupying the Subject Property at that time, and to redevelop Sublot 4 with a new mixed-use commercial and residential building. Although operations of potential environmental risk included a suspected aluminum & brass manufacturer, a commercial laundry facility, and two gasoline USTs identified to have been present on limited portions of Sublot 4 historically, the results of the Remedial Investigation suggest that the subsurface impact present at Sublot 4 appeared to be primarily related to urban fill material occurring on Sublot 4 to a maximum depth of approximately 10 feet below the ground surface (ft bgs). VOCs, pesticides, and poly-chlorinated biphenyls (PCBs) were detected at the Subject Property at concentrations exceeding their respective NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives and Groundwater Class GA Standards; however, the primary contaminants of concern at Sublot 4 appear to consist of SVOCs and metals present in both soil and groundwater, which is typical of properties overlain by urban fill material. Based on the contents of the May 2019 Remedial Investigation and Alternatives Analysis Report, it appears that the remedial approach selected by the owner of Sublot 4 included pursuit of an Unrestricted Track 1 cleanup. It should be noted that based on LaBella's interview with the NYSDEC, the Remedial Investigation and Alternatives Analysis Report has not been finalized, and the NYSDEC has not provided formal approval of the Remedial Investigation and Alternatives Analysis Report or the remedial approach suggested within that document. Per LaBella's interview with the NYSDEC, the NYSDEC reported that should another entity, such as Primecore, LLC, desire continuing with the BCP, that such can likely be pursued through submission of a Brownfield Cleanup Agreement Amendment, and preparation of a new Alternatives Analysis Report to match any alternative re-development approaches and corresponding cleanup strategies contemplated for Sublot 4.

According to an October 2022 settlement agreement executed by the owner of Sublot 4 and other parties, slag fill material was imported to Sublot 4 in or around December of 2019 and was utilized to backfill the foundations of the former apartment complex following demolition of said structures. Field screening and laboratory analysis of the slag material conducted by several consultants independently in 2020 determined that the slag backfill exhibited elevated radiological levels consistent with TENORM. AMS was retained to remove and dispose of the slag in late 2022.

According to the January 2023 report documenting the remediation of the slag, prepared by C&S, a removal action was conducted at Sublot 4 between October 18, 2022 and December 13, 2022 that resulted in the excavation and off-site disposal of 5,164.49 tons of TENORM slag from within and around the building foundations and internal Subject Property roadway. Waste manifests and disposal receipts contained in the C&S report document that the slag removed from Sublot 4 was disposed at the Carbon Limestone Landfill in Lowellville, Ohio. According to the settlement agreement, this landfill is reportedly authorized by the State of Ohio Department of Health Bureau of Environmental Health and Radiological Protection to accept low-level radioactive waste with total radium content of less than 7.0 picocuries per gram (pCi/g). During an interview conducted by LaBella on February 7, 2023, a representative from AMS confirmed that an In-situ Object Counting System (ISOCS) was used to measure total radium levels in each truckload of TENORM slag before exiting Sublot 4 to verify the landfill's waste acceptance criteria were satisfied prior to transporting the material to the disposal facility. According to AMS, the ISOCS measurement for each truckload shipped to the Carbon Limestone Landfill was less than 7.0 pCi/gram of total radium, and all material removed from Sublot 4 was accepted by said landfill.

Following the removal of the slag, the radiological contractor that was commissioned to complete this work (AMS) performed a post-remedial radiological survey that confirmed the cleanup criteria established in the remedial work plan had been achieved. That is, the post-remedial survey determined that 95% of the survey measurements or counts were less than the upper tolerance limit of the background measurements; and that no single measurement exceeded two times the background measurement. AMS issued a letter dated December 22, 2022 summarizing the post-remedial radiological survey that was submitted to the NYSDEC. In response to this submittal, the NYSDEC transmitted an e-mail on December 27, 2022 noting that they had no comments on the survey report.

Sublot 3 & Sublot 5 – 951 Ellicott Street

Based on the collective documentation reviewed, environmental assessment of Sublot 3 and Sublot 5 was included within at least two Phase I ESA's, Phase II ESAs, and a geotechnical assessment conducted for the greater Site including Sublot 4. Although the Phase I ESA's revealed historical operations of potential environmental risk including an aluminum & brass manufacturer, a commercial laundry facility, an automotive repair operation, and a gasoline UST present beneath Ellicott Street proximate the southwest boundary of Sublot 3, historical use of Sublot 3 and Sublot 5 appears to have primarily consisted of residences. It is unclear whether targeted subsurface assessment of the automotive repair operation and a gasoline UST was conducted within the 2014 subsurface investigations; however, several subsurface investigation locations (i.e., soil borings) were generally located proximate to and within the general vicinity of the historical aluminum & brass manufacturer and commercial laundry facility. Generally speaking, it appears that the focus of the subsurface investigations and geotechnical assessment were related to project planning efforts for Sublot 4, and only limited subsurface data was generated related to Sublot 3 and Sublot 5. The limited subsurface data available for Sublot 3 and Sublot 5 did identify similar subsurface conditions to those encountered on Sublot 4, with urban fill material being encountered to a maximum depth of

approximately eight feet bgs, and limited soil samples collected from both Sublot 3 and Sublot 5 identifying metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives. Furthermore, it should also be noted that "perimeter" subsurface soil samples collected as part of the BCP Remedial Investigation for Sublot 4 consistently identified SVOCs, pesticides, and metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives along the parcel boundary shared with Sublot 3 and Sublot 5. The extent and severity of the subsurface impact present at Sublot 3 and Sublot 5 is unknown.

Conclusions: Sublot 4 – 903 Ellicott Street

1. It appears that the Remedial Investigation completed for Sublot 4 is generally consistent with environmental consulting and engineering practices for the region at that time. Although the NYSDEC and NYSDOH have not provided formal comment on, or accepted the Remedial Investigation, and formal review and comment by the NYSDEC and NYSDOH will be required to confirm the adequacy of the Remedial Investigation, it appears likely that the Remedial Investigation is sufficient to evaluate and establish a remedial approach to support redevelopment of Sublot 4. Based on LaBella's conversations with the NYSDEC, the NYSDEC is reportedly willing to "transfer" the BCP to another entity such as Primecore, LLC through execution of a Brownfield Cleanup Agreement Amendment. Alternatively, if Primecore, LLC would prefer to remove Sublot 4 from the NYSDEC BCP, the current Brownfield Cleanup Agreement should be rescinded.

2. Based upon LaBella's review of the documents provided and discussion with the NYSDEC on this topic, as well as our experience on other sites containing TENORM slag, the scope and outcome of the TENORM removal action performed at Sublot 4 in 2022 appears appropriate and reasonable. Although a third party Certified Health Physicist (CHP) was not engaged within the scope of work to provide a formal opinion, the potential presence of residual slag fragments on Sublot 4 does not appear to represent an unacceptable health risk to future occupants or site workers based upon the conclusions of the CHP at AMS that conducted the risk assessment.

Conclusions: Sublot 3 & Sublot 5 – 951 Ellicott Street

1. Although the subsurface information available for Sublot 3 and Sublot 5 is highly limited, based on the collective information examined within the scope of this review and the limited number of environmental concerns identified within the previous Phase I ESA's, the primary environmental risk associated with Sublot 3 and Sublot 5 appears to be related to the unknown extent and severity of the subsurface impact identified associated with the urban fill material present within the subsurface of Sublot 3 and Sublot 5. There is the potential that the subsurface conditions at Sublot 3 and 5 are consistent with the subsurface conditions present at Sublot 4; however, additional assessment would be required to evaluate the subsurface conditions at Sublot 3 and Sublot 5.

Subsequent to LaBella's February 2023 review, the following was concluded/completed:

- Additional assessment/investigation on Sub Lots 3 and 5 are in the process of being complete by LaBella; the results of that investigation are provided under separate cover.
- LaBella understands that, in light of Primcore's plan to remove all urban fill from the Subject Property prior to redevelopment, Primecore has elected not to commission an independent Certified Health Physicist to review the risk assessment prepared following the completion of the TENORM slag removal from Sublot 4.
- Emerging Contaminants Groundwater Sampling Results, completed by C&S, dated February 20, 2020, was supplied to LaBella on February 23, 2023; the results were also forwarded to the NYSDEC for review/comments on February 24, 2023. According to a response from Benjamin McPherson, Professional Engineer for the NYSDEC Division of Environmental Remediation, on February 24, 2023, the Emerging Contaminants Groundwater Sampling Results were reviewed and it was determined that the results for 1,4-dioxane and PFAS were below the current guidance values for the respective compounds.

5.9 Historical Summary of Findings

Based on LaBella's review of historical sources, the history of the Subject Property is as follows:

Time Period	Apparent Use/Development
In or before 1889 through at least 1974	Developed with several former residential and commercial buildings throughout the property, including a former soap factory, auto repair shop/private garage, window cleaning company, an aluminum and brass manufacturing facility, a carting & storage company, and auto garage/collision shop.
1980 through present	Developed with the existing buildings (including former apartment buildings that were demolished in 2015), used residentially as the Pilgrim Village housing complex.

Based on LaBella's review of historical information, the adjacent properties were historically utilized for industrial, commercial, and residential purposes. The following adjacent property uses of potential concern were identified:

- The north adjacent property historically addressed as 963 Ellicott Street was identified as a dry cleaner in at least 1935.
- The north adjacent property addressed as 68 Best Street was identified as a clothes cleaner in at least 1930.
- The south adjacent property historically addressed as 77 East North Street was identified as an auto repair/auto body manufacturer between at least 1925 and 1960.
- The west adjacent property addressed as 908 Ellicott Street was identified as an auto repair facility between at least 1925 and 1960 and included two gasoline USTs between at least 1925 and 1951.
- The west adjacent property addressed as 938 Ellicott Street (historically addressed at 888 Ellicott Street) was identified as an auto repair facility between at least 1925 and 1951.

No visual evidence or records were identified suggesting a significant environmental concern to the Subject Property based on the historic adjacent uses. Refer to Section 6.1.2 for additional information.

LaBella's historical research identified the following conditions indicative of the presence or likely presence of hazardous substances or petroleum products in, on, or at the Subject Property:

- The Subject Property was historically used/developed with the following:
  - A soap factory in at least 1889 historically addressed at 919 Ellicott Street (western-central portion of the property). This former building/property was also used as an aluminum and brass specialty manufacturing facility (W.A. Eckert Manufacturing Co.) between at least 1925 and 1935, historically addressed at 917-919 Ellicott Street.
  - An auto repair shop/garage between at least 1925 and 1950 historically addressed as 931-935 Ellicott Street (northwest portion of the property). A gasoline UST was depicted within Ellicott Street, directly west of the auto repair shop, between at least 1925 and 1951. Municipal records indicate the installation of one 550-gallon UST at 933 Ellicott Street in 1945 and the removal of one 550-gallon UST at 931-935 Ellicott Street in 1974. Additionally, this former building was also used as a window cleaning company and associated maintenance company/building between at least 1955 and 1971.
  - A carting and storage facility between at least 1930 and 1960 historically addressed at 86 East North Street (southwest portion of the property) and was also identified as an auto garage/collision shop between at least 1967 and 1972. Municipal records indicate that at least 4 former gasoline USTs were installed and filled in place or removed from this site between at least 1947 and 1968.
- According to investigation and remedial reports provided and reviewed, several soil and groundwater investigations had been conducted on the southwest portion of the Subject Property identified as Sublot 4, since 2014, which identified the presence of urban fill material within the subsurface of Sublot 4 containing concentrations of metals exceeding NYSDEC Part 375 Soil Cleanup Objectives. Sublot 4 was subsequently accepted into the NYSDEC BCP (Site ID C915294) in 2015. A NYSDEC BCP Remedial Investigation was implemented at the Subject Property in 2015 which included comprehensive investigation of the surface soil, subsurface soil, and groundwater at Sublot 4 and evaluation of remedial alternatives (i.e. Alternatives Analysis) to establish a remedial approach to support demolition of the apartment complex occupying the Subject Property at that time, and to redevelop Sublot 4 with a new mixed-use commercial and residential building. Although operations of potential environmental risk included an aluminum & brass manufacturer, a soap factory/laundry facility, and two gasoline USTs identified to have been present on limited portions of Sublot 4 historically, the results of the Remedial Investigation suggested that the subsurface impact present at Sublot 4 appeared to be primarily related to urban fill material occurring on Sublot 4 to a maximum depth of approximately 10 feet below the ground surface (ft bgs). VOCs,

pesticides, and poly-chlorinated biphenyls (PCBs) were detected at the Subject Property at concentrations exceeding their respective NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives and Groundwater Class GA Standards; however, the primary contaminants of concern at Sublot 4 appear to consist of SVOCs and metals present in both soil and groundwater, which is typical of properties overlain by urban fill material. Based on the contents of the May 2019 Remedial Investigation and Alternatives Analysis Report, it appears that the remedial approach selected by the owner of Sublot 4 included pursuit of an Unrestricted Track 1 cleanup. It should be noted that based on LaBella's interview with the NYSDEC, the Remedial Investigation and Alternatives Analysis Report has not been finalized, and the NYSDEC has not provided formal approval of the Remedial Investigation and Alternatives Analysis Report or the remedial approach suggested within that document. Per LaBella's interview with the NYSDEC, the NYSDEC reported that should another entity, such as Primecore, LLC, desire continuing with the BCP, that such can likely be pursued through submission of a Brownfield Cleanup Agreement Amendment, and preparation of a new Alternatives Analysis Report to match any alternative re-development approaches and corresponding cleanup strategies contemplated for Sublot 4.

- Additionally, according to an October 2022 settlement agreement executed by the owner of Sublot 4 and other parties, slag fill material was imported to Sublot 4 in or around December of 2019 and was utilized to backfill the foundations of the former apartment complex following demolition of said structures. Field screening and laboratory analysis of the slag material conducted by several consultants independently in 2020 determined that the slag backfill exhibited elevated radiological levels consistent with TENORM. AMS was retained to remove and dispose of the slag in late 2022. According to the January 2023 report documenting the remediation of the slag, prepared by C&S, a removal action was conducted at Sublot 4 between October 18, 2022 and December 13, 2022 that resulted in the excavation and off-site disposal of 5,164.49 tons of TENORM slag from within and around the building foundations and internal Subject Property roadway. Waste manifests and disposal receipts contained in the C&S report document that the slag removed from Sublot 4 was disposed at the Carbon Limestone Landfill in Lowellville, Ohio. According to the settlement agreement, this landfill is reportedly authorized by the State of Ohio Department of Health Bureau of Environmental Health and Radiological Protection to accept low-level radioactive waste with total radium content of less than 7.0 picocuries per gram (pCi/g). During an interview conducted by LaBella on February 7, 2023, a representative from AMS confirmed that an In-situ Object Counting System (ISOCS) was used to measure total radium levels in each truckload of TENORM slag before exiting Sublot 4 to verify the landfill's waste acceptance criteria were satisfied prior to transporting the material to the disposal facility. According to AMS, the ISOCS measurement for each truckload shipped to the Carbon Limestone Landfill was less than 7.0 pCi/gram of total radium, and all material removed from Sublot 4 was accepted by said landfill. Following the removal of the slag, the radiological contractor that was commissioned to complete this work (AMS) performed a post-remedial radiological survey that confirmed the cleanup criteria established in the remedial work plan had been achieved. That is, the post-remedial survey determined that 95% of the survey

measurements or counts were less than the upper tolerance limit of the background measurements; and that no single measurement exceeded two times the background measurement. AMS issued a letter dated December 22, 2022 summarizing the post-remedial radiological survey that was submitted to the NYSDEC. In response to this submittal, the NYSDEC transmitted an e-mail on December 27, 2022 noting that they had no comments on the survey report.

- Based on the collective documentation reviewed, environmental assessment of Sublot 3 and Sublot 5 was included within at least two Phase I ESA's, Phase II ESAs, and a geotechnical assessment conducted for the greater Site including Sublot 4. Although the Phase I ESA's revealed historical operations of potential environmental risk including an automotive repair operation and a gasoline UST present beneath Ellicott Street proximate the southwest boundary of Sublot 3, the historical use of Sublot 3 and Sublot 5 appears to have primarily consisted of residences. It is unclear whether targeted subsurface assessment of the automotive repair operation and a gasoline UST was conducted within the 2014 subsurface investigations; however, several subsurface investigation locations (i.e., soil borings) were generally located proximate to and within the general vicinity of the historical operations/ UST. Generally speaking, it appears that the focus of the subsurface investigations and geotechnical assessment were related to project planning efforts for Sublot 4, and only limited subsurface data was generated related to Sublot 3 and Sublot 5. The limited subsurface data available for Sublot 3 and Sublot 5 did identify similar subsurface conditions to those encountered on Sublot 4, with urban fill material being encountered to a maximum depth of approximately eight feet bgs, and limited soil samples collected from both Sublot 3 and Sublot 5 identifying metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives. Furthermore, it should also be noted that "perimeter" subsurface soil samples collected as part of the BCP Remedial Investigation for Sublot 4 consistently identified SVOCs, pesticides, and metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives along the parcel boundary shared with Sublot 3 and Sublot 5. The extent and severity of the subsurface impact present at Sublot 3 and Sublot 5 is unknown.
- LaBella understands that, in light of Primcore's plan to remove all urban fill from the Subject Property prior to redevelopment, Primecore has elected not to commission an independent Certified Health Physicist to review the risk assessment prepared following the completion of the TENORM slag removal from Sublot 4.
- Emerging Contaminants Groundwater Sampling Results, completed by C&S, dated February 20, 2020, was supplied to LaBella on February 23, 2023; the results were also forwarded to the NYSDEC for review/comments on February 24, 2023. According to a response from Benjamin McPherson, Professional Engineer for the NYSDEC Division of Environmental Remediation, on February 24, 2023, the Emerging Contaminants Groundwater Sampling Results were reviewed and it was determined that the results for 1,4-dioxane and PFAS were below the current guidance values for the respective compounds.

6.0 REGULATORY INFORMATION

Federal, state, and tribal environmental regulatory information was provided by ERIS, an independent research firm, which completed an ASTM-compliant regulatory records search. This search was completed to ASTM-defined search distances; however, it should be noted that the distances searched may have been modified based on LaBella's experience due to the geology or nature of the area, as permitted under ASTM E-1527-13/21. Additionally, ERIS conducted a search of supplemental Federal, state, tribal, and local databases to augment the ASTM-specified search; any relevant listings from these supplemental searches are summarized in the following sections. The ERIS report, dated February 24, 2023 is included in the Regulatory Information Appendix.

The review of regulatory information was completed to evaluate the potential for environmental impact to the Subject Property, including contaminant migration from off-Subject Property locations. This evaluation included a review of regulatory records along with geologic/ hydrogeologic information, topographical information, and/or distance relative to the Subject Property.

6.1 Regulatory Report Summary

A complete list of the databases reviewed is included within the ERIS report. Below is a summary of the identified listings within their respective search distance:

Regulatory Report Summary

Database	Search Radius	Target Property	Within 0.12mi	0.12mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED TANKS	0.25	0	1	0	-	-	1
ENG	0.5	0	1	0	1	-	2
ERP	0.5	0	0	0	1	-	1
FINDS/FRS	0.02	0	2	-	-	-	2
GEN MANIFEST	0.125	0	16	-	-	-	16
HMIRS	0.125	0	2	-	-	-	2
INST	0.5	0	2	0	1	-	3
LST	0.5	0	10	11	21	-	42
MRDS	1.0	0	0	0	0	1	1
NY MANIFEST	0.125	0	1	-	-	-	1
NY SPILLS	0.5	0	24	21	73	-	118

Database	Search Radius	Target Property	Within 0.12mi	0.12mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
PCB	0.5	0	0	0	1	-	1
RCRA CORRACTS	1.0	0	0	0	1	0	1
RCRA LQG	0.25	0	6	2	-	-	8
RCRA NON GEN	0.25	0	8	11	-	-	19
RCRA SQG	0.25	0	3	1	-	-	4
RCRA TSD	0.5	0	0	0	2	-	2
RCRA VSQG	0.25	0	1	2	-	-	3
SHWS	1.0	0	1	0	0	3	4
SSTS	0.25	0	2	0	-	-	2
SWF/LF	0.5	0	0	2	0	-	2
TIER 2	0.125	0	15	-	-	-	15
UST	0.25	0	3	3	-	-	6
AIR PERMITS	0.25	0	3	2	-	-	5
ALT FUELS	0.25	0	23	0	-	-	23
AST	0.25	0	4	3	-	-	7
BROWNFIELDS	0.5	1	6	2	2	-	11
COOLING TOWERS	0.125	0	11	-	-	-	11

6.1.1 Subject Property Listings

The Subject Property, listed as Pilgrim Village Redevelopment/Campus Square at 903 Ellicott Street, was identified as an active Brownfield (BCP) cleanup site (Site Code C915294). Refer to the Review of Previous Reports section for additional information.

Due to the nature and status of the listing, a REC has been identified in association with the regulatory record attached to the Subject Property.

6.1.2 Adjacent Property Listings

The following regulatory listings associated with adjacent properties were identified:

Niagara Mohawk-National Grid at Manhole at Best Street and Ellicott Street (northwest): listed twice as a RCRA (ID No. NYP000972208) Non-Generator with no violations listed and as an FRS/FINDS and Manifest site in association with the RCRA generator listings.

Former Pilgrim Village Senior Apartments at 951 Ellicott Street (east): Brownfield site, Code #C915363 has a remediation completed status. From the late 1800s through the mid-1970s, this site was occupied by dense residential housing with several small shops and developed with the Pilgrim Village Senior apartments in the 1970s. The sub-surface of this property consists of urban fill predominately consisting of sand, silt, crushed rock, asphalt, and brick from 2 to 6 feet below the ground surface. Prior to remediation, the primary contaminants of concern were SVOCs, arsenic, barium, copper, lead, mercury, and zinc in soil above unrestricted and restricted residential soil cleanup objectives. Excavation of the impacted areas was completed. Remedial activities have successfully achieved soil cleanup objectives for unrestricted use.

Former Pilgrim Village Family Apartments at 1100 Michigan Avenue (east):

- NY Spill No. 1508707 involved the discovery of petroleum odors in soil during a Phase II investigation. Samples were collected and analyzed and results indicated that three VOCs were detected slightly above CP-51 SCOs. It was determined no further work was needed and the NYSDEC assigned the spill an inactive status on November 23, 2015.
- Brownfield site, Code #C915362 has a remediation completed status. From the late 1800s through the mid-1970s, this property was occupied by dense residential housing and several small shops and included a gasoline filling station on the northeast corner of the parcel at the corner of Best Street and Michigan Avenue from at least 1951 through at least the 1960s. In the 1970s, this property was redeveloped into the Pilgrim Village Senior Apartments. The sub-surface consists of urban fill which is predominantly sand, silt, crushed rock, asphalt, and brick from the ground surface to approximately 2 to 11 feet below ground surface. Prior to remediation, the primary contaminants of concern were VOCs, SVOCs, arsenic, barium, lead, mercury, and zinc in soil. Petroleum related VOCs were present in groundwater in the northeast portion of the site. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use.

Buffalo City Mission - 150 East North Street (southeast)

- Cooling Tower facility associated with air conditioning.
- Brownfield site, Code #C915190 with a No Further Action at this Time status. A BCP application was submitted in 2005 for the investigation of vacant land in support of the construction of a new housing facility. The application included an assessment conducted in 2004 which did not identify RECs, however, in at least 1951, this property was utilized as a vehicle service station; it was believed that the operations were short-lived as the facility was not identified in Polk Directories dated 1948 or 1957 and no other records were discovered identifying environmental concerns. The site was denied entry into the BCP based on the lack of environmental issues identified at this site.

University at Buffalo/Buffalo General Hospital - 875 Ellicott Street (south)

- NY Spills: Spill #0751355 involved a gauge on a boiler failing causing a release of approximately 40 gallons of petroleum to the ground. Safety Kleen was hired to clean up the spill. No further action was required and the spill was assigned a closed status on May 9, 2008.
- LST #9310029 involved a tank overfill causing petroleum to run down the sidewalk. The area was cleaned and no further action was required. The spill was assigned a closed status on December 16, 1994.
- RCRA (No. NYR000195461) LQG with no violations listed.
- Manifest and FRS/FINDS listings associated with the RCRA listing

Building Site of General Hospital - Corner of North Street and Ellicott Street (southwest): NY Spills: Spill #0910563 involved a hydraulic line breaking on construction machinery causing approximately 50 gallons of fluid to collect in a depression on the ground. The liquid and impacted soil was collected and disposed of. No water or drains were affected. The spill was assigned an inactive status on February 1, 2010.

854 Ellicott Street (south): Alt Fuels listings associated with electric charging stations.

50 East North Street (west): Cooling Towers associated with air conditioning.

Due to the nature and/or status of the listings, lack of violations and active reported releases, and/or flow of groundwater to the north (away from the Subject Property), there does not appear to be a REC for the Subject Property in association with the adjacent regulatory listings at this time.

6.1.3 Additional Listings

Based on the distance, status, and/or topographic gradient from the Subject Property, none of the other sites listed within the database report are considered likely to have current or former releases of hazardous substances and/or petroleum products with the potential to migrate to the Subject Property.

6.1.4 Unmappable Listings

Unmapped facilities were identified within the ERIS report. The specific location of these listings could not be determined due to incomplete or inaccurate address information. Based on the limited address information available for the listings, they do not appear to be associated with the Subject Property or adjacent properties.

6.2 Enforcement Action/Permitted Activities/Institutional Controls

Provided Information indicates that the Subject Property is subject to environmental enforcement actions/activities associated with Brownfield cleanup/remedial activities as discussed above.

6.3 Regulatory Agency File and Records Review

The purpose of the regulatory file review is to obtain sufficient information to assist the Environmental Professional in determining if a recognized environmental condition, controlled recognized environmental condition, historical recognized environmental condition, de minimis condition, or significant data gap exists at the Subject Property in connection with the identified listings. Regulatory listings identified in the database report for the Subject Property and adjacent properties were evaluated in order to determine the need for a regulatory file review. Based on this evaluation, the following was concluded:

- As sufficient information was included within previous studies provided to LaBella and within the ERIS report, no file review was warranted.

6.4 Regulatory Information Summary

LaBella's review of regulatory information identified the following conditions indicative of the presence or likely presence of hazardous substances or petroleum products in, on, or at the Subject Property.

- The southwest portion of the Subject Property, identified as Sublot 4, is an active Brownfield (BCP) Site (Code #C915214).

7.0 INTERVIEWS

Interviews were completed with representatives of the owner/operator of the Subject Property, Subject Property occupants, neighbors, and/or former owners/operators, to the extent possible, to further assess Subject Property operations and/or potential environmental concerns.

Additional information was obtained through federal, state, tribal, and/or local agencies or via the submission of Records Requests, as documented below.

7.1 Owner/Subject Property Representative

Samantha Scavulli, Property Manager, was interviewed as part of this assessment on March 13, 2023. According to information obtained through the interview the Subject Property is developed with apartments buildings that are connected to the public sewer and water systems. The apartment buildings are heated via natural gas. The southwest portion of the Subject Property (Sublot 4) is listed as an Active BCP.

In addition, Samantha Scavulli did not have knowledge of: 1) environmental liens or governmental notifications relating to past or recurrent violations of environmental laws with respect to the property or any facility located on the property; 2) information regarding past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any hazardous substance or petroleum product; or 3) any previous ESAs of the property that might indicate the presence of hazardous substances or petroleum products on, or contamination of, the property or recommended further assessment of the property.

The notes from the interview are included in the Owner/Operator Questionaire Appendix.

7.2 Current Occupants

See Section 7.1 above.

7.3 Former Owners/Operators/Occupants

No past owners/occupants were contacted because no contact information was provided through available municipal records or through a focused online search.

7.4 Neighbors

The Subject Property is not an abandoned property; therefore, interviews with the neighboring property owners were not conducted.

7.5 Local Government Official

A FOIL request was submitted to the City of Buffalo clerk, Tianna Marks on February 23, 2023, requesting copies of building department, assessment, and fire marshal records on file for the Subject Property. A complete response has not been received as of the date of this report. However, LaBella conducted a search of available permits and records at the City of Buffalo Permits and Inspection Department and Fire Bureau/Fire Department. Relevant records are discussed in Section 5.5 above. A copy of the FOIL request and the records obtained are included in the Municipal Information Appendix.

7.6 State Regulator

A FOIL request was submitted to the NYSDEC on February 23, 2023. A letter dated February 23, 2023, stated that the NYSDEC received LaBella's FOIL request and had initiated a records search. As of the date of this report submission, a complete response has not been received from the NYSDEC. A copy of the FOIL request is included in the Municipal Information Appendix.

7.7 State and/or County Health Department

A FOIL request was submitted to the NYSDOH on February 23, 2023. As of the date of this report submission, a response has not been received from the NYSDOH. A copy of the FOIL request is included in the Municipal Information Appendix.

7.8 Summary of Interviews

LaBella's interviews and/or review of provided records did not identify conditions indicative of the presence or likely presence of hazardous substances or petroleum products in, on, or at the Subject Property other than the Subject Property Sublot 4 identified as an active Brownfield site.

8.0 ADDITIONAL SERVICES/ASTM NON-SCOPE CONSIDERATIONS

8.1 Emerging Contaminants

Hazardous substances are those defined as such pursuant to CERCLS 42 U.S.C. § 9601(14), as interpreted by USEPA regulations and the courts. There are some substances that others may assume to be classified as hazardous substances that are in fact not defined (or not yet defined) as hazardous substances under CERCLA through interpretation by USEPA regulations.

These and any other "emerging contaminants," where they are not identified as a hazardous substance by CERCLA, as interpreted by USEPA regulations and the courts, are not included in the scope of E1527-13/21. Some of these substances may be considered a "hazardous substance" (or equivalent) under applicable state laws. In those instances, where a Phase I ESA is performed to satisfy both federal and state requirements, or as directed by the user of the report, it is permissible to include analysis and/or discussion of these substances in the same manner as any other Non-Scope Consideration. If and when such emerging contaminants are defined as hazardous substances under CERCLA, as interpreted by USEPA regulations and the courts, such substances shall be evaluated within the scope of ASTM E1527-13/21.

Emerging Contaminants Groundwater Sampling Results, completed by C&S, dated February 20, 2020, was supplied to LaBella on February 23, 2023; the results were also forwarded to the NYSDEC for review/comments on February 24, 2023. According to a response from Benjamin McPherson, Professional Engineer for the NYSDEC Division of Environmental Remediation, on February 24, 2023, the Emerging Contaminants Groundwater Sampling Results were reviewed and it was determined that the results for 1,4-dioxane and PFAS were below the current guidance values for the respective compounds.

9.0 FINDINGS AND OPINIONS

The Subject Property, 903 and 951 Ellicott Street, Buffalo, New York, includes 6.72-acres of land and is developed with three two-story apartment buildings and one maintenance storage garage that were constructed in 1980. The Subject Property has been used residentially, identified as Pilgrim Village housing complex since construction. Prior to 1980, the Subject Property was extensively developed with residential buildings and various commercial structures.

Based on the results of this assessment, the following RECs have been identified in connection with the Subject Property:

- The Subject Property was historically used/developed with the following:
  - A soap factory in at least 1889 historically addressed at 919 Ellicott Street (western-central portion of the property). This former building/property was also used as an aluminum and brass specialty manufacturing facility (W.A. Eckert Manufacturing Co.) between at least 1925 and 1935, historically addressed at 917-919 Ellicott Street.
  - An auto repair shop/garage between at least 1925 and 1950 historically addressed as 931-935 Ellicott Street (northwest portion of the property). A gasoline UST was depicted within Ellicott Street, directly west of the auto repair shop, between at least 1925 and 1951. Municipal records indicate the installation of one 550-gallon UST at 933 Ellicott Street in 1945 and the removal of one 550-gallon UST at 931-935 Ellicott Street in 1974. Additionally, this former building was also used as a window cleaning company and associated maintenance company/building between at least 1955 and 1971.
  - A carting and storage facility between at least 1930 and 1960 historically addressed at 86 East North Street (southwest portion of the property) and was also identified as an auto garage/collision shop between at least 1967 and 1972. Municipal records indicate that at least 4 former gasoline USTs were installed and filled in place or removed from this site between at least 1947 and 1968.
- According to investigation and remedial reports provided and reviewed, several soil and groundwater investigations had been conducted on the southwest portion of the Subject Property identified as Sublot 4, since 2014, which identified the presence of urban fill material within the subsurface of Sublot 4 containing concentrations of metals exceeding NYSDEC Part 375 Soil Cleanup Objectives. Sublot 4 was subsequently accepted into the NYSDEC BCP (Site ID C915294) in 2015. A NYSDEC BCP Remedial Investigation was implemented at the Subject Property in 2015 which included comprehensive investigation of the surface soil, subsurface soil, and groundwater at Sublot 4 and evaluation of remedial alternatives (i.e. Alternatives Analysis) to establish a remedial approach to support demolition of the apartment complex occupying the Subject Property at that time, and to redevelop Sublot 4 with a new mixed-use commercial and residential building. The results

of the Remedial Investigation suggested that the subsurface impact present at Sublot 4 appeared to be primarily related to urban fill material occurring on Sublot 4 to a maximum depth of approximately 10 feet below the ground surface (ft bgs). VOCs, pesticides, and PCBs were detected at the Subject Property at concentrations exceeding their respective NYSDEC Part 375 Unrestricted Use Soil Cleanup Objectives and Groundwater Class GA Standards; however, the primary contaminants of concern at Sublot 4 appear to consist of SVOCs and metals present in both soil and groundwater, which is typical of properties overlain by urban fill material. Based on the contents of the May 2019 Remedial Investigation and Alternatives Analysis Report, it appears that the remedial approach selected by the owner of Sublot 4 included pursuit of an Unrestricted Track 1 cleanup. It should be noted that based on LaBella's interview with the NYSDEC, the Remedial Investigation and Alternatives Analysis Report has not been finalized, and the NYSDEC has not provided formal approval of the Remedial Investigation and Alternatives Analysis Report or the remedial approach suggested within that document. Per LaBella's interview with the NYSDEC, the NYSDEC reported that should another entity, such as Primecore, LLC, desire continuing with the BCP, that such can likely be pursued through submission of a Brownfield Cleanup Agreement Amendment, and preparation of a new Alternatives Analysis Report to match any alternative re-development approaches and corresponding cleanup strategies contemplated for Sublot 4.

- Additionally, according to an October 2022 settlement agreement executed by the owner of Sublot 4 and other parties, slag fill material was imported to Sublot 4 in or around December of 2019 and was utilized to backfill the foundations of the former apartment complex following demolition of said structures. Field screening and laboratory analysis of the slag material conducted by several consultants independently in 2020 determined that the slag backfill exhibited elevated radiological levels consistent with TENORM. According to a January 2023 report documenting the remediation of the slag, prepared by C&S, a removal action was conducted at Sublot 4 between October 18, 2022 and December 13, 2022 that resulted in the excavation and off-site disposal of 5,164.49 tons of TENORM slag from within and around the building foundations and internal Subject Property roadway. Following the removal of the slag, the radiological contractor that was commissioned to complete this work (AMS) performed a post-remedial radiological survey that confirmed the cleanup criteria established in the remedial work plan had been achieved. That is, the post-remedial survey determined that 95% of the survey measurements or counts were less than the upper tolerance limit of the background measurements; and that no single measurement exceeded two times the background measurement. AMS issued a letter dated December 22, 2022 summarizing the post-remedial radiological survey that was submitted to the NYSDEC. In response to this submittal, the NYSDEC transmitted an e-mail on December 27, 2022 noting that they had no comments on the survey report. LaBella understands that, in light of Primcore's plan to remove all urban fill from the Subject Property prior to redevelopment, Primecore has elected not to commission an independent Certified Health

Physicist to review the risk assessment prepared following the completion of the TENORM slag removal from Sublot 4.

- Based on the collective documentation reviewed, environmental assessment of Sublot 3 and Sublot 5 was included within at least two Phase I ESA's, Phase II ESAs, and a geotechnical assessment conducted for the greater Site including Sublot 4. Generally speaking, it appears that the focus of the subsurface investigations and geotechnical assessment were related to project planning efforts for Sublot 4, and only limited subsurface data was generated related to Sublot 3 and Sublot 5. The limited subsurface data available for Sublot 3 and Sublot 5 did identify similar subsurface conditions to those encountered on Sublot 4, with urban fill material being encountered to a maximum depth of approximately eight feet bgs, and limited soil samples collected from both Sublot 3 and Sublot 5 identifying metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives. Furthermore, it should also be noted that "perimeter" subsurface soil samples collected as part of the BCP Remedial Investigation for Sublot 4 consistently identified SVOCs, pesticides, and metals at concentrations exceeding NYSDEC Part 375 Soil Cleanup Objectives along the parcel boundary shared with Sublot 3 and Sublot 5. The extent and severity of the subsurface impact present at Sublot 3 and Sublot 5 is unknown.

LaBella notes that although historic operations/uses of potential concern did not appear to be specifically targeted as part of previous subsurface investigations, the investigations were generally located proximate to and within the general vicinity of a majority of the historic operations/uses. Additionally, LaBella recently completed a Phase II ESA on Sublots 3 and 5, in March 2023, to assess if historic operations/uses have impacted the subsurface of the Subject Property. The Phase II ESA report has been provided to Primecore, LLC under separate cover.

Based on the results of this assessment, no CRECs, HRECs, de minimis conditions, or significant data gaps have been identified in connection with the Subject Property.

While not considered a REC, CREC, HREC, de minimis condition, or significant data gap at this time, LaBella also notes the following:

- Seven unlabeled 55-gallon drums were observed along the western exterior of the garage building located on the southeastern portion of the property. The contents of these drums were unknown. No evidence of leaks or staining was observed on or around the drums at the time of LaBella's site visit.
- Several fill material piles consisting of mixed dirt, stone, and concrete were observed on the southeast portion of the property, reportedly associated with construction activities. No evidence of staining was observed in the areas of the fill material piles at the time of LaBella's site visit.

9.1 Additional Investigation

Based on the findings of this assessment, additional investigation would be recommended; however, LaBella recently completed a Phase II ESA on Sub Lots 3 and 5, in March 2023, to assess if historic operations/uses have impacted the subsurface of the Subject Property. The Phase II ESA report has been provided to Primecore, LLC under separate cover.

Remedial activities proposed for the on-site contamination at Sub Lot 4 should be submitted and approved by the NYSDEC under the Brownfield Cleanup Agreement established for Sub Lot 4.

10.0 CONCLUSIONS

LaBella has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13/21 for 903 and 951 Ellicott Street, Buffalo, New York, the Subject Property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report.

This assessment has revealed the following recognized environmental conditions, controlled recognized environmental conditions, or significant data gaps in connection with the Subject Property:

- REC related to historic on-site uses of potential environmental concern
- REC related to the on-site soil and groundwater contamination identified on Sublot 4 during previous subsurface investigations with remedial action planned under the NYSDEC BCP

This report constitutes the findings of LaBella's investigation conducted for the Subject Property as written and reviewed by the following personnel:



Christopher Finn
Environmental Analyst

Jacquelyn Brayer
Phase I Technical Reviewer

11.0 ENVIRONMENTAL PROFESSIONAL STATEMENT

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in § 312.10 of 40 C.F.R. § 312.

I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 C.F.R. Part 312.



Jacquelyn Brayer
Phase I Technical Reviewer
Environmental Professional

12.0 REFERENCES

	Source
USGS 7.5 Minute Topographic Quadrangle Map of Buffalo, New York	USGS Website
Erie County Soil Survey	ERIS
Federal Environmental Regulatory Listings	ERIS
State Environmental Regulatory Listings	ERIS
Local Landfill or Solid Waste Information	ERIS
Sanborn Fire Insurance Maps	ERIS
City Directories	ERIS
Aerial Photographs	www.historicaerials.com
Historical Topographic Maps	N/A
Historical Atlases	N/A
Previous Reports	Several previous Phase I, Phase II, investigation, and remedial reports dated 2014-2023

13.0 LIST OF ABBREVIATIONS/ACRONYMS

ACM	Asbestos Containing Material
AIRS	Aerometric Information Retrieval System
AST	Aboveground Storage Tank
ASTM	American Society for Testing and Materials
AUL	Activity Use Limitation
BTEX	Benzene, Toluene, Ethylbenzene, and Xylene
CBS	Chemical Bulk Storage
CERCLA	Comprehensive Environmental Response, Compensation and Liability Act
CERCLIS	Comprehensive Environmental Response, Compensation and Liability Information System
CORRACTS	Corrective Action
CP-51	Commissioner's Policy 51
CREC	Controlled Recognized Environmental Condition
DRO	Diesel Range Organics
ECHO	Enforcement Compliance History Online
ERIS	Environmental Risk Information Services
ERNS	Emergency Response and Notification System
FINDS	Facility Index System
FIS	Facility Information System
FOIA	Freedom of Information Act
FOIL	Freedom of Information Law
FRS	Facility Registry Service
Ft. bgs	Feet Below Ground Surface
FWM	Freshwater Wetlands Map
GRO	Gasoline Range Organics
HREC	Historical Recognized Environmental Condition
HS/PP	Hazardous Substances/Petroleum Products
IC/EC	Institutional Control/Engineering Control
ICIS	Integrated Compliance Information System
LAST	Leaking Aboveground Storage Tank
LQG	Large Quantity Generator
LST	Leaking Storage Tank
LTANK	Leaking Tank
LUST	Leaking Underground Storage Tank
mg/kg	Milligrams Per Kilogram
mg/L	Milligrams Per Liter

MOSF	Major Oil Storage Facility
MTBE	Methyl Tert-Butyl Ether
mVOC	Microbial Volatile Organic Compound
N/A	Not Available/Not Applicable
NFRAP	No Further Remedial Action Planned
NPDES	National Pollution Discharge Elimination System
NPL	National Priorities List
NRCS	Natural Resource Conservation Service
NWI	National Wetlands Inventory
NYSDEC	New York State Department of Environmental Conservation
NYSDOH	New York State Department of Health
PAHs	Polycyclic Aromatic Hydrocarbons
PBS	Petroleum Bulk Storage
PCB	Polychlorinated Biphenyl
PCE	Tetrachloroethylene
pCi/L	Pico Curies per Liter
PEC	Potential Environmental Concern
PFAS	Per- and Polyfluoroalkyl Substances
PID	Photoionization Detector
ppb	Parts Per Billion
ppm	Parts Per Million
RCRA	Resource Conservation and Recovery Act
RCRIS	Resource Conservation and Recovery Information System
REC	Recognized Environmental Condition
SDS	Safety Data Sheet
SEMS	Superfund Enterprise Management System
SPDES	State Pollution Discharge Elimination System
SQG	Small Quantity Generator
STARS	Spill Technology and Remediation Series
SVOC	Semi-Volatile Organic Compound
TAL	Target Analyte List
TCE	Trichloroethylene
TCL	Target Compound List
TPH	Total Petroleum Hydrocarbons
TSDF	Treatment, Storage, and Disposal Facility
USDA	United States Department of Agriculture
USEPA	United States Environmental Protection Agency
USFWS	United States Fish and Wildlife Service

USGS	United States Geological Survey
UST	Underground Storage Tank
VCP	Voluntary Cleanup Program
VOC	Volatile Organic Compound
VSQG	Very Small Quantity Generator
µg/L	Micrograms Per Liter
µg/kg	Micrograms Per Kilogram
$\mu g/m^3$	Micrograms Per Cubic Meter

LaBella
Powered by partnership.

Site Maps

Privileged and Confidential



Figure 1 Site Location Map

903 and 951 Ellicott Street
Buffalo New York 14209
Project No. 2231229

LaBella
Powered by partnership

Figure 2 Site Property Tax Map

903 and 951 Ellicott Street
Buffalo, New York 14209
Project No. 2231229

LaBella
Powered by partnership

N

Figure 3 Site Plan

903 and 951 Ellicott Street
Buffalo, New York 14209
Project No. 2231229

LaBella
Powered by partnership

N

Figure 3b Site Plan

903 and 951 Ellicott Street
Buffalo, New York 14209
Project No. 2231229

LaBella
Powered by partnership

Hydrogeologic Information

Privileged and Confidential

PSR
PHYSICAL SETTING REPORT

Property Information

Order Number:		23022300643p
Date Completed:		February 24, 2023
Project Number:		2231229
Project Property:		2231229: Phase I: Pilgrim Village, Sublots 3, 4 & 5, 903 & 951 Ellicott St., Buffalo 903 and 951 Ellicott Street Buffalo NY 14209
Coordinates:		
	Latitude:	42.90295935
	Longitude:	-78.86528268
	UTM Northing:	4752249.32841 Meters
	UTM Easting:	674273.878507 Meters
	UTM Zone:	UTM Zone 17T
	Elevation:	644.41 ft
	Slope Direction:	NNW

Topographic Information....2
Hydrologic Information....4
Geologic Information....8
Soil Information....10
Wells and Additional Sources....17
Summary....18
Detail Report....20
Radon Information....26
Appendix....27
Liability Notice....29

The ERIS ***Physical Setting Report - PSR*** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2016)

Quadrangle(s): Buffalo NE,NY; Buffalo NW,NY

Source: USGS 7.5 Minute Topographic Map

Topographic Information

The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:

Elevation: 644.41 ft
Slope Direction: NNW



Hydrologic Information



Wetland

0 0.075 0.15 0.3 Miles

N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS

Hydrologic Information



Wetland (State Source)

0 0.075 0.15 0.3 Miles

N

This data shows only those wetlands that are currently mapped or officially proposed for addition to the wetland maps and currently regulated under the New York State Freshwater Wetlands Act.

DEC

- Class I
- Class II
- Class III
- Class IV
- Check Zone

APA

- Aquatic Bed Rooted Vascular
- Emergent Non-persistent
- Emergent Persistent
- Forested Broad-leaf Deciduous
- Forested Dead
- Forested Needle-leaf Deciduous
- Forested Needle-leaf Evergreen
- Open Water
- Scrub Shrub Broad-leaf Deciduous
- Scrub Shrub Broad-leaf Evergreen
- Scrub Shrub Dead
- Scrub Shrub Needle-leaf Deciduous
- Scrub Shrub Needle-leaf Evergreen
- Streambed Cobble/Gravel
- Streambed Rubble
- Unconsolidated Bottom Cobble/Gravel
- Unconsolidated Bottom Mud
- Unconsolidated Bottom Sand
- Unconsolidated Shore Cobble/Gravel
- Unconsolidated Shore Sand

Source and Category Description:
DEC: New York State Department of Environmental COnservation; http://www.dec.ny.gov/gis/erm/wetlands.html
APA: Adirondack Park Agency; https://www.apa.ny.gov/gis/index.html

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information



Flood Hazard Zones

Miles
0 0.2 0.4

This map shows FEMA flood hazard zones. FIRM panels are shown to the right, and blank indicates no data is available.

A	AO	X
A99	V	OPEN WATER
AE	VE	NOT POPULATED
AH	D	AREA NOT INCLUDED



Quadrangle(s): Buffalo NE,NY; Buffalo NW,NY

ERIS

Hydrologic Information

The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below.
For detailed Zone descriptions please click the link: https://floodadvocate.com/fema-zone-definitions

Available FIRM Panels in area:	36029C0213H(effective:2019-06-07) 36029C0194H(effective:2019-06-07) 36029C0211H(effective:2019-06-07) 36029C0192H(effective:2019-06-07)

Flood Zone X-12

Zone:	X
Zone subtype:	AREA OF MINIMAL FLOOD HAZARD

Geologic Information



Miles
0 0.225 0.45

N

Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

ERIS

Miles
0 0.3 0.6

Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.

Geologic Unit Dob

Unit Name:	Onondaga and Bois Blanc Limestones
Unit Age:	Middle Devonian
Primary Rock Type:	limestone
Secondary Rock Type:	sandstone
Unit Description:	Onondaga and Bois Blanc Limestones - In New York: Onondaga Limestone-Seneca, Morehouse (cherty), and Clarence Limestone Members, Edgecliff cherty Limestone Member, local coral bioherms; Bois Blanc Limestone-sandy, thin, discontinous.In Ontario: Dundee Limestone; Lucas Formation-dolostone, limestone (Anderdon); Amherstburg Formation-limestone, dolostone, sandstone (Sylvania); Bois Blanc Formation-dolostone, limestone, sandstone (Springvale).

Soil Information



SSURGO Soils

0 0.2 0.4 Miles N

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS

Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit Ud (69.02%)

Map Unit Name:	Urban land

No more attributes available for this map unit

Component Description:

Minor map unit components are excluded from this report.

Map Unit: Ud - Urban land

Component: Urban land (80%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Odessa (5%)
Generated brief soil descriptions are created for major soil components. The Odessa soil is a minor component.

Component: Udorthents (5%)
Generated brief soil descriptions are created for major soil components. The Udorthents soil is a minor component.

Component: Mardin (5%)
Generated brief soil descriptions are created for major soil components. The Mardin soil is a minor component.

Component: Getzville (5%)
Generated brief soil descriptions are created for major soil components. The Getzville soil is a minor component.

Map Unit Ug (3.56%)

Map Unit Name:	Urban land-Cayuga complex
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	69cm
Drainage Class - Dominant:	null
Hydrologic Group - Dominant:	null

Major components are printed below

Cayuga(30%)

horizon H1(0cm to 25cm)	Silt loam
horizon H2(25cm to 66cm)	Silty clay
horizon H3(66cm to 152cm)	Gravelly loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: Ug - Urban land-Cayuga complex

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Cayuga (30%)
The Cayuga component makes up 30 percent of the map unit. Slopes are 0 to 3 percent. This component is on proglacial lake plains, till plains. The parent material consists of clayey glaciolacustrine deposits over loamy till derived from limestone, dolomite, sandstone, or shale. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. A seasonal zone of water saturation is at 27 inches during April,

May. Organic matter content in the surface horizon is about 4 percent. Nonirrigated land capability classification is 2w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 1 percent.

Component: Collamer (4%)
Generated brief soil descriptions are created for major soil components. The Collamer soil is a minor component.

Component: Udorthents (2%)
Generated brief soil descriptions are created for major soil components. The Udorthents soil is a minor component.

Component: Canandaigua (2%)
Generated brief soil descriptions are created for major soil components. The Canandaigua soil is a minor component.

Component: Unnamed soils (2%)
Generated brief soil descriptions are created for major soil components. The Unnamed soils soil is a minor component.

Map Unit Uk (1.09%)

Map Unit Name:	Urban land-Claverack complex
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	54cm
Drainage Class - Dominant:	null
Hydrologic Group - Dominant:	null

Major components are printed below

Claverack(30%)

horizon H1(0cm to 25cm)	Loamy fine sand
horizon H2(25cm to 89cm)	Loamy fine sand
horizon H3(89cm to 152cm)	Clay

Component Description:

Minor map unit components are excluded from this report.

Map Unit: Uk - Urban land-Claverack complex

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Claverack (30%)
The Claverack component makes up 30 percent of the map unit. Slopes are 0 to 3 percent. This component is on proglacial lake plains. The parent material consists of sandy glaciolacustrine deposits, derived primarily from non-calcareous sandstone or granite, that overlie clayey glaciolacustrine deposits. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. A seasonal zone of water saturation is at 21 inches during January, February, March, April, May, November, December. Organic matter content in the surface horizon is about 4 percent. Nonirrigated land capability classification is 2w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 1 percent.

Component: Varysburg (3%)
Generated brief soil descriptions are created for major soil components. The Varysburg soil is a minor component.

Component: Cosad (3%)
Generated brief soil descriptions are created for major soil components. The Cosad soil is a minor component.

Component: Udorthents (2%)
Generated brief soil descriptions are created for major soil components. The Udorthents soil is a minor component.

Component: Cheektowaga (2%)
Generated brief soil descriptions are created for major soil components. The Cheektowaga soil is a minor component.

Soil Information

Map Unit UmA (19.2%)

Map Unit Name:	Urban land-Collamer complex, 1 to 6 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	54cm
Drainage Class - Dominant:	null
Hydrologic Group - Dominant:	null

Major components are printed below

Collamer(30%)

horizon H1(0cm to 25cm)	Silt loam
horizon H2(25cm to 38cm)	Silt loam
horizon H3(38cm to 81cm)	Silty clay loam
horizon H4(81cm to 152cm)	Stratified silt loam to very fine sand to silty clay loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: UmA - Urban land-Collamer complex, 1 to 6 percent slopes

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Collamer (30%)
The Collamer component makes up 30 percent of the map unit. Slopes are 0 to 6 percent. This component is on proglacial lake plains. The parent material consists of silty and clayey glaciolacustrine deposits. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is not flooded. It is not ponded. A seasonal zone of water saturation is at 21 inches during March, April, May. Organic matter content in the surface horizon is about 4 percent. Nonirrigated land capability classification is 2e. This soil does not meet hydric criteria.

Component: Udorthents (3%)
Generated brief soil descriptions are created for major soil components. The Udorthents soil is a minor component.

Component: Niagara (3%)
Generated brief soil descriptions are created for major soil components. The Niagara soil is a minor component.

Component: Canandaigua (2%)
Generated brief soil descriptions are created for major soil components. The Canandaigua soil is a minor component.

Component: Williamson (2%)
Generated brief soil descriptions are created for major soil components. The Williamson soil is a minor component.

Map Unit UnB (1.36%)

Map Unit Name:	Urban land-Colonie complex, 3 to 6 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	null
Hydrologic Group - Dominant:	null

Major components are printed below

Colonie(25%)

horizon H1(0cm to 18cm)	Loamy fine sand
horizon H2(18cm to 152cm)	Fine sand
horizon H3(152cm to 178cm)	Fine sand

Component Description:

Minor map unit components are excluded from this report.

Soil Information

Map Unit: UnB - Urban land-Colonie complex, 3 to 6 percent slopes

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Colonie (25%)
The Colonie component makes up 25 percent of the map unit. Slopes are 3 to 6 percent. This component is on proglacial deltas, proglacial beach ridges. The parent material consists of sandy glaciofluvial or eolian deposits. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. Nonirrigated land capability classification is 2s. This soil does not meet hydric criteria.

Component: Arkport (5%)
Generated brief soil descriptions are created for major soil components. The Arkport soil is a minor component.

Component: Alton (5%)
Generated brief soil descriptions are created for major soil components. The Alton soil is a minor component.

Component: Udorthents (3%)
Generated brief soil descriptions are created for major soil components. The Udorthents soil is a minor component.

Component: Halsey (2%)
Generated brief soil descriptions are created for major soil components. The Halsey soil is a minor component.

Map Unit Uo (0.06%)

Map Unit Name:	Urban land-Cosad complex
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	31cm
Drainage Class - Dominant:	null
Hydrologic Group - Dominant:	null
Major components are printed below	
Cosad(25%)	
horizon H1(0cm to 23cm)	Loamy fine sand
horizon H2(23cm to 53cm)	Loamy fine sand
horizon H3(53cm to 61cm)	Fine sandy loam
horizon H4(61cm to 152cm)	Silty clay

Component Description:

Minor map unit components are excluded from this report.

Map Unit: Uo - Urban land-Cosad complex

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Cosad (25%)
The Cosad component makes up 25 percent of the map unit. Slopes are 0 to 3 percent. This component is on proglacial lake plains. The parent material consists of sandy glaciofluvial or deltaic deposits over clayey glaciolacustrine deposits. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat poorly drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is moderate. This soil is not flooded. It is not ponded. A seasonal zone of water saturation is at 12 inches during January, February, March, April, May, November, December. Organic matter content in the surface horizon is about 5 percent. Nonirrigated land capability classification is 3w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 1 percent.

Component: Rhinebeck (5%)
Generated brief soil descriptions are created for major soil components. The Rhinebeck soil is a minor component.

Component: Red Hook (5%)

Soil Information

Generated brief soil descriptions are created for major soil components. The Red Hook soil is a minor component.

Component: Udorthents (3%)
Generated brief soil descriptions are created for major soil components. The Udorthents soil is a minor component.

Component: Cheektowaga (2%)
Generated brief soil descriptions are created for major soil components. The Cheektowaga soil is a minor component.

Map Unit Up (4.69%)

Map Unit Name:	Urban land-Galen complex
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	54cm
Drainage Class - Dominant:	null
Hydrologic Group - Dominant:	null

Major components are printed below

Galen(25%)

horizon H1(0cm to 20cm)	Very fine sandy loam
horizon H2(20cm to 61cm)	Loamy fine sand
horizon H3(61cm to 91cm)	Loamy fine sand
horizon H4(91cm to 152cm)	Stratified fine sand to very fine sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: Up - Urban land-Galen complex

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Galen (25%)
The Galen component makes up 25 percent of the map unit. Slopes are 0 to 3 percent. This component is on proglacial deltas on lake plains. The parent material consists of deltaic deposits with a high content of fine and very fine sand. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. A seasonal zone of water saturation is at 21 inches during March, April, May. Organic matter content in the surface horizon is about 3 percent. Nonirrigated land capability classification is 2w. This soil does not meet hydric criteria.

Component: Elnora (5%)
Generated brief soil descriptions are created for major soil components. The Elnora soil is a minor component.

Component: Udorthents (5%)
Generated brief soil descriptions are created for major soil components. The Udorthents soil is a minor component.

Component: Lamson (3%)
Generated brief soil descriptions are created for major soil components. The Lamson soil is a minor component.

Component: Minoa (2%)
Generated brief soil descriptions are created for major soil components. The Minoa soil is a minor component.

Map Unit Ut (1.03%)

Map Unit Name:	Urban land-Odessa complex, 0 to 3 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	20cm
Drainage Class - Dominant:	null
Hydrologic Group - Dominant:	null

Soil Information

Major components are printed below

Odessa(25%)

horizon Ap(0cm to 20cm)	Silt loam
horizon Bt/E(20cm to 25cm)	Silty clay loam
horizon Bt1(25cm to 38cm)	Silty clay
horizon Bt2(38cm to 64cm)	Silty clay
horizon C(64cm to 200cm)	Silty clay

Component Description:

Minor map unit components are excluded from this report.

Map Unit: Ut - Urban land-Odessa complex, 0 to 3 percent slopes

Component: Urban (60%)
Generated brief soil descriptions are created for major soil components. The Urban is a miscellaneous area.

Component: Odessa (25%)
The Odessa component makes up 25 percent of the map unit. Slopes are 0 to 3 percent. This component is on lake plains, lake terraces. The parent material consists of red clayey glaciolacustrine deposits derived from calcareous shale. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat poorly drained. Water movement in the most restrictive layer is low. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is high. This soil is not flooded. It is not ponded. A seasonal zone of water saturation is at 8 inches during January, February, March, April, May, November, December. Organic matter content in the surface horizon is about 6 percent. Nonirrigated land capability classification is 3w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 10 percent.

Component: Lakemont (5%)
Generated brief soil descriptions are created for major soil components. The Lakemont soil is a minor component.

Component: Schoharie (5%)
Generated brief soil descriptions are created for major soil components. The Schoharie soil is a minor component.

Component: Churchville (3%)
Generated brief soil descriptions are created for major soil components. The Churchville soil is a minor component.

Component: Rhinebeck (2%)
Generated brief soil descriptions are created for major soil components. The Rhinebeck soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources

N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	ID	Distance (ft)	Direction
	No records found		

Safe Drinking Water Information System (SDWIS)

Map Key	ID	Distance (ft)	Direction
	No records found		

USGS National Water Information System

Map Key	Site Number	Distance (ft)	Direction
1	USGS-425415078520701	645.82	WNW
2	USGS-425405078521001	782.23	WSW
3	USGS-425356078521401	1585.54	SW
4	USGS-425432078520101	1843.81	NNW
5	USGS-425346078521601	2514.90	SSW
6	USGS-425442078515701	2847.44	N
7	USGS-425338078514701	3044.17	SSE
8	USGS-425354078511401	3095.64	ESE
9	USGS-425333078515701	3540.53	S
10	USGS-425333078522001	3834.59	SSW
12	USGS-425400078505901	3950.65	ESE
13	USGS-425413078505601	3953.43	E
14	USGS-425456078515201	4270.10	N
15	USGS-425413078504801	4642.52	E
16	USGS-425501078514801	4794.13	N
17	USGS-425419078504301	5082.22	E

Wells from NWIS

Map Key	ID	Distance (ft)	Direction
	No records found		

State Sources

Oil and Gas Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Underground Injection Control Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Wells and Additional Sources Summary

Water Wells Database

Map Key	Dec Well NO	Distance (ft)	Direction
11	E2343	3930.02	SW

Wells and Additional Sources Detail Report

USGS National Water Information System

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WNW	0.12	645.82	647.47	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425415078520701
Station Name: E 313
Site Type: Well: Test hole not completed as a well
Latitude: 42.90422449000000
Longitude: -78.8683687000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	WSW	0.15	782.23	659.28	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425405078521001
Station Name: E 307
Site Type: Well
Latitude: 42.90144670000000
Longitude: -78.8692020800000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	SW	0.30	1,585.54	650.00	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425356078521401
Station Name: E 300
Site Type: Well
Latitude: 42.89894670000000
Longitude: -78.8703132000000
Date Drilled:

Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	NNW	0.35	1,843.81	655.10	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425432078520101
Station Name: E 325
Site Type: Well: Test hole not completed as a well
Latitude: 42.90894669000000
Longitude: -78.8667020000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	SSW	0.48	2,514.90	636.45	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425346078521601
Station Name: E 298
Site Type: Well
Latitude: 42.89616898000000
Longitude: -78.8708688000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
6	N	0.54	2,847.44	647.05	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425442078515701
Station Name: E 328
Site Type: Well: Test hole not completed as a well

Latitude: 42.91172445000000
Longitude: -78.8655909000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
7	SSE	0.58	3,044.17	617.91	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425338078514701
Station Name: E 292
Site Type: Well: Test hole not completed as a well
Latitude: 42.89394680000000
Longitude: -78.8628128900000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	ESE	0.59	3,095.64	631.67	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425354078511401
Station Name: E 299
Site Type: Well: Test hole not completed as a well
Latitude: 42.89839127000000
Longitude: -78.8536459000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	S	0.67	3,540.53	615.66	FED USGS

Reporting Agency: USGS New York Water Science Center

Site Number: USGS-425333078515701
Station Name: E 288
Site Type: Well: Test hole not completed as a well
Latitude: 42.89255790000000
Longitude: -78.8655907000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
10	SSW	0.73	3,834.59	623.79	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425333078522001
Station Name: E 289
Site Type: Well: Test hole not completed as a well
Latitude: 42.89255789000000
Longitude: -78.8719799000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	ESE	0.75	3,950.65	630.11	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425400078505901
Station Name: E 302
Site Type: Well: Test hole not completed as a well
Latitude: 42.90005795000000
Longitude: -78.8494791000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	E	0.75	3,953.43	650.95	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425413078505601
Station Name: E2649
Site Type: Well
Latitude: 42.90366667000000
Longitude: -78.8490000000000
Date Drilled:
Well Depth: 80
Well Depth Unit: ft
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
14	N	0.81	4,270.10	630.91	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425456078515201
Station Name: E 336
Site Type: Well: Test hole not completed as a well
Latitude: 42.91561330000000
Longitude: -78.8642020000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	E	0.88	4,642.52	640.81	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425413078504801
Station Name: E 311
Site Type: Well: Test hole not completed as a well
Latitude: 42.90366905000000
Longitude: -78.8464235000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	N	0.91	4,794.13	630.60	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425501078514801
Station Name: E 340
Site Type: Well: Test hole not completed as a well
Latitude: 42.91700220000000
Longitude: -78.8630909000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
17	E	0.96	5,082.22	645.40	FED USGS

Reporting Agency: USGS New York Water Science Center
Site Number: USGS-425419078504301
Station Name: E 315
Site Type: Well: Test hole not completed as a well
Latitude: 42.90533570000000
Longitude: -78.8450346000000
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
W Hole Depth Unit:
Formation Type:

Water Wells Database

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
11	SW	0.74	3,930.02	620.53	WATER WELLS

Dec Well NO:	E2343	County:	ERIE
Reg Number:	NYRD10084	Town:	Buffalo
Well Depth:	305	Foil Loc:	DELAWARE AVE
Rock Depth:	52	Latitude:	42 53 36.4
GW Depth:	20	Longitude:	78 52 29.7
Cased Dept:	0	DD Lat:	42.893444
Yt Avg Disc:	200	DD Long:	-78.874917
Scr:	NO		

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *ERIE* County: **1**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *ERIE* County

No Measures/Homes:	4671
Geometric Mean:	14.2
Arithmetic Mean:	4.4
Median:	1.1
Standard Deviation:	1.3
Maximum:	371.9
% >4 pCi/L:	18
% >20 pCi/L:	4
Notes on Data Table:	Table 1. Screening indoor radon data compiled by the New York State Department of Health. Data represent 1-7 day charcoal canister measurements from the lowest level of each home tested.

Appendix

Federal Sources

FEMA National Flood Hazard Layer — **FEMA FLOOD**

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data — **INDOOR RADON**

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data — **PWSV**

List of drinking water violations and enforcement actions from the Safe Drinking Water Information System (SDWIS) made available by the Drinking Water Protection Division of the US EPA's Office of Groundwater and Drinking Water. Enforcement sensitive actions are not included in the data released by the EPA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level — **RADON ZONE**

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS) — **SDWIS**

The Safe Drinking Water Information System (SDWIS) contains information about public water systems as reported to US Environmental Protection Agency (EPA) by the states. Addresses may correspond with the location of the water system, or with a contact address.

Soil Survey Geographic database — **SSURGO**

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data — **US WETLAND**

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo — **US TOPO**

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology — **US GEOLOGY**

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System — **FED USGS**

The U.S. Geological Survey (USGS)'s National Water Information System (NWIS) is the nation's principal repository of water resources data. This database includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data.

Wells from NWIS — **FED USGS**

The U.S. Geological Survey's National Water Information System (NWIS) is the nation's principal repository of water resources data. The NWIS includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data. This NWIW dataset contains select Site Types from the overall NWIS Sites data, limited to the following Group Site Types only: Groundwater Group Site Types: Well, Collector or Ranney type well, Hyporheic-zone well,

Interconnected Wells, Multiple wells; Spring Group Site Type: Spring; and Other Group Site Types: Aggregate groundwater use, Cistern.

State Sources

Oil and Gas Wells **OGW**

The Division of Mineral Resources maintains a data management system on wells regulated under the Oil, Gas and Solution Mining Law (OGSML). To assist the Division in the regulation of wells subject to the OGSML, a database of the wells was created in the early 1980's and significantly upgraded in 1998 by the adoption of the Risk Based Data Management System. This system provides information on well ownership, well owners and operators, registered driller, pluggers and companies that provide financial security instruments.

Regulatory Freshwater Wetlands **WETLAND**

The Regulatory Freshwater Wetlands data are a set of ARC/INFO coverages composed of polygonal and linear features. Coverages are based on official New York State Freshwater Wetlands Maps as described in Article 24-0301 of the Environmental Conservation Law. Coverages are not, however, a legal substitute for the official maps. Coverages are available on a county basis for all areas of New York State outside the Adirondack Park. This dataset is provided by New York State Department of Environmental Conservation.

Underground Injection Control Wells **UIC**

A well permit is required from the Division of Mineral Resources for any brine disposal well deeper than 500 feet. This includes any operation to drill, deepen, plug back or convert a well. Regardless of well depth, the NYSDEC Division of Water must be contacted for a determination of whether a SPDES permit is necessary to operate any brine disposal well.

Water Wells Database **WATER WELLS**

The New York State Department of Environmental Conservation (DEC) Bureau of Water Resource Management works to protect, manage, and conserve New York State's groundwater and surface water supply sources, develop management strategies to enhance and protect these waters, and protect both the groundwater and surface water quality in the New York City Watershed and other major watersheds. This dataset does not include information on wells located in Nassau, Suffolk, Kings, and Queens counties.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

LaBella
Powered by partnership.

User Provided Information

LaBella
Powered by partnership.

USER QUESTIONNAIRE

Project No._____Date: _____
Site Name/ Address: _____
Site Contact (to arrange site visit/conduct Site owner interview): Name: _____
Phone Number:_____Email Address:_____

In order to qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "*Brownfields Amendments*"), the *user* must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. These inquiries must also be conducted by or on behalf of EPA Brownfield Assessment and Characterization grantees. The *user* should provide the following information to the *Environmental Professional*. Failure to conduct these inquiries could result in a determination that "*all appropriate inquiries*" is not complete.

User (Print Name): _____
Title: _____
Signature: _____

Information regarding these questions was obtained from the following parties (if applicable):_____
_____
_____

Purpose of this Assessment: ☐Selling the *property* ☐Purchasing the *property* ☐Construction loan
☐Re-financing the *property* ☐Other (explain):

1. **Title Records**
Land title records (or judicial records where appropriate, see Note 1 below) are filed under federal, tribal, state or local law and should be reviewed to identify environmental liens or activity and use limitations (AULs), if any, that are currently recorded or filed against the *property*. Are land title records available for review? ☐No ☐Yes (If yes, please provide.) ☐Unknown

Note 1 – In certain jurisdictions, federal, tribal, state, or local statues, or regulations specify that environmental liens and AULs be filed in judicial records rather than in land title records. In such cases, judicial records must be searched for environmental liens and AULs.

2. **Environmental liens that are filed or recorded against the *property* (40 CFR 312.25)**
Did a search of *recorded land title records* (or judicial records where appropriate, see Note 1 above) identify any environmental liens filed or recorded against the *property* under federal, tribal, state or local law?
☐No ☐Yes ☐Unknown
Based on review of readily available information: _____
_____
_____
_____

3. **Activity and land use restrictions (AULs) that are in place on the *property* or that have been filed or recorded against the *property* (40 CFR 312.26(a)(1)(v) and (vi))**
Did a search of *recorded land title records* (or judicial records where appropriate, see Note 1 above) identify any AULs, such as *engineering controls*, land use restrictions, or *institutional controls* that are in place at the *property* and/or have been filed or recorded against the *property* under federal, tribal, state, or local law?
☐No ☐Yes ☐Unknown
Based on review of readily available information_____
_____
_____

4. **Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28)**

Do you have any specialized knowledge or experience related to the *property* or nearby properties? For example, are you involved in the same line of business as the current or former *occupants* of the *property* or and *adjoining property* so that you would have specialized knowledge of the chemicals and processes used by this type of business?

☐No ☐Yes ☐Unknown

Based on review of readily available information:_____

5. **Relationship of the purchase price to the fair market value of the *property* if it were not contaminated (40 CFR 312.29)**

Does the purchase price being paid for this *property* reasonably reflect the fair market value of the *property?*

☐No ☐Yes ☐Unknown ☐N/A- there is no transfer of ownership

If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the *property?*

☐No ☐Yes ☐Unknown

Based on review of readily available information: _____

6. **Commonly known or *reasonably ascertainable* information about the *property* (40 CFR 312.30)**

Are you aware of any commonly known or *reasonably ascertainable* information about the *property* that could help the *Environmental Professional* to identify conditions indicative of releases or threatened releases? For example*:*

(a) Do you know of the past uses of the *property?*

☐No ☐Yes ☐Unknown

Based on review of readily available information: _____

(b) Do you know of specific chemicals that are present or once were present at the *property?*

☐No ☐Yes ☐Unknown

Based on review of readily available information: _____

(c) Do you know of spills or other chemical releases that have taken place at the *property?*

☐No ☐Yes ☐Unknown

Based on review of readily available information:_____

(d) Do you know of any environmental cleanups that have taken place at the *property?*

☐No ☐Yes ☐Unknown

Based on review of readily available information:_____

7. **The degree of obviousness of the presence or likely presence of contamination at the *property,* and the ability to detect the contamination by appropriate investigation (40 CFR 312.31)**
   Based on your knowledge and experience related to the *property*, are there any *obvious* indicators that point to the presence or likely presence of releases at that *property*?
   ☐No ☐Yes ☐Unknown
   Based on review of readily available information: _____
   _____
   _____
   _____

   Please provide attachments if necessary to explain any answers to the above questions.

LaBella
Powered by partnership.

Site Reconnaissance Worksheet

Privileged and Confidential

LaBella
Powered by partnership.

Site Reconnaissance Worksheet

Subject Property Name	*Project Number*	*Inspector Name*	*Site Visit Date*
Pilgrim Village		Chris Finn	March 13, 2023

Address, City, County, State	903 and 951 Ellicott Street Buffalo NY		
Acreage	9	*Topography*	level
On-site water bodies:	none	*Nearest water body/direction*	Lake erie 1.3 miles west
Nature of Area (circle one):	*Rural* ☐ *Urban* ☑ *Suburban* ☐		
Additional Roadways	none		

Accompanied By	*Title*	*Years associated with Subject Property*
Samanatha Scavulli		1.5

Current Use *list all occupants and describe nature of operations*	apartments
Past Use (If evident during site visit)	apartments

Utilities:

Electric: Public - Provider:

Natural Gas: Yes ☑ **No** ☐ **- Provider:**

Water Supply: Public ☑ **Private** ☐ **- Provider or Well location(s):**

Sewer/Septic: Public ☑ **Private** ☐ **- Provider or Septic tank/field location(s):**

Storm Drains: Yes ☐ **No** ☑ **- if yes, location**

Drainage location: ☐ **public system** ☐ **pond** ☐ **ditch/channel** ☐ **dry well** ☐ **other:**

Site visit limitations:

☐ Dense Vegetation ☐ Topography ☐ Snow ☑ Parked Vehicles ☑ Stored Materials

☐ Unaccompanied during site inspection

☐ Inaccessible structures/areas (list):

☑ Other: construction

Site Reconnaissance Worksheet

Buildings (add extra pages for additional buildings)

Building Name	Subject Buildings 1-3				
Current Use/Tenants	Apartments				
Former Uses/Tenants	Apartments				
Square Footage:		# of Stories:	Two	Construction Date:	1980
Basement:	☑ Full ☐ Partial ☐ Crawl space ☐ Slab-on-grade				
Heating/Cooling Source	☑ Natural gas ☐ Electric ☐ Fuel oil ☐ Propane ☐ Waste oil ☐ Other:				
Floor/Trench Drains and Sumps (#, locations, discharge point, etc.)	Drains in each units basement, sumps in end units				
Oil-water separator:	Y ☐ N ☑ discharge location:		Age:	Service records	Y ☐ N ☐
Grease trap:	Y ☐ N ☑ discharge location:		Age:	Service records	Y ☐ N ☐
Sediment trap:	Y ☐ N ☑ discharge location:		Age:	Service records	Y ☐ N ☐

NOTES:

(Use this area to describe areas inspected, general observations, stored materials/housekeeping, potential concerns, lifts, compressors, generators, etc.)

Each unit has its own basement with floor drains.
Sumps are located in the end units of each building

Site Reconnaissance Worksheet

Buildings (add extra pages for additional buildings)

Building Name	Subject Building 4				
Current Use/Tenants	Garage				
Former Uses/Tenants	Garage				
Square Footage:		# of Stories:	One	Construction Date:	1980
Basement:	☐ Full ☐ Partial ☐ Crawl space ☑ Slab-on-grade				
Heating/Cooling Source	☐ Natural gas ☐ Electric ☐ Fuel oil ☐ Propane ☐ Waste oil ☐ Other:				
Floor/Trench Drains and Sumps (#, locations, discharge point, etc.)					
Oil-water separator:	Y ☐ N ☐ discharge location:			Age:	Service records Y ☐ N ☐
Grease trap:	Y ☐ N ☐ discharge location:			Age:	Service records Y ☐ N ☐
Sediment trap:	Y ☐ N ☐ discharge location:			Age:	Service records Y ☐ N ☐

NOTES:

(Use this area to describe areas inspected, general observations, stored materials/housekeeping, potential concerns, lifts, compressors, generators, etc.)

No access,

Drums located to the west of the building

Used for storage of landscaping equipment/maintenance supplies from Pilgrim village apartment complex.

LaBella
Powered by partnership.

Site Reconnaissance Worksheet

Hazardous Substances/Petroleum Products (request SDS)

Contents/Container Size	No. of Containers	Location	Use/Purpose	Staining/Evidence of a Release
General cleaning and property maintenance supplies/five-gallons or less				Y ☐ N ☐
				Y ☐ N ☐
				Y ☐ N ☐
				Y ☐ N ☐
				Y ☐ N ☐

Solid, Hazardous, and/or Regulated Wates (request recent disposal receipts)

Material	Source/Process	Storage Location/Quantity	Transporter/Hauler	Staining/Evidence of a Release
General refuse/recyclables	living	bins near SBs	Buffalo	Y ☐ N ☑
Scrap metal				Y ☐ N ☐
Waste cooking grease				Y ☐ N ☐
Waste oil				Y ☐ N ☐
Additional waste automotive fluids				Y ☐ N ☐
Waste manufacturing liquids/solids				Y ☐ N ☐
Waste solvents/cleaners				Y ☐ N ☐
Waste paints/thinners				Y ☐ N ☐
Other: Used oil filters Used tires Used batteries Used rags				Y ☐ N ☐

Parts washer: Y ☐ N ☐ If yes, location:

service provider:

Site Reconnaissance Worksheet

Additional Wastes/Disposed Materials:

Material	Source/Process	Storage Location/Quantity	Staining
Fill dirt/material	piles on Sublot 5	numerous piles	Y ☐ N ☑
Construction and demolition wastes			Y ☐ N ☐
Discarded materials/containers			Y ☐ N ☐
Gravel/stone piles			Y ☐ N ☐
Other (i.e. slag)			Y ☐ N ☐

Unidentified Substance Containers:

Description of Container	Location	Staining/Evidence of a Release
seven 55-gallon drums	West SB4	Y ☐ N ☑
		Y ☐ N ☐
		Y ☐ N ☐

Suspect PCB-Containing Equipment:

Type	#	Location	Leaks?
Pole-mounted Transformers	n/a		Y ☐ N ☐
Pad-mounted transformers			Y ☐ N ☐
Aboveground hydraulic lifts			Y ☐ N ☐
In-ground hydraulic lifts			Y ☐ N ☐
Elevators			Y ☐ N ☐
Compactors			Y ☐ N ☐

Site Reconnaissance Worksheet

Storage Tanks

No./Type (AST/UST)	Location (tank and vent/fill)	Capacity (gallons)	Construction (steel, FRP)	Contents	Installation Date/Age	Staining or Evidence of a Release
n/a						

Evidence of prior tanks (e.g., cut pipes, old vent pipes, patched asphalt and/or concrete, signage, inactive pump island or canopy, etc.):

Request the following documents:

- System Status Report/Print-out (from tank monitoring system)
- Tank Closure Reports
- Tank Installation Documents
- PBS/CBS registration
- Testing Documents (tightness, lines, leak detection, etc.)
- Spill Reports

Additional Notes (e.g., location of dispensers):

LaBella
Powered by partnership.

Site Reconnaissance Worksheet

Additional Observations

Observation	Yes/No	Location	Notes (poor housekeeping, staining, releases, etc.)
Odors	Y ☐ N ☑		
Standing water/pools of liquid	Y ☐ N ☑		
Evidence of former lifts (lift scars, patching, etc.)	Y ☐ N ☑		
Patching (in concrete, asphalt, etc.)	Y ☐ N ☑		
Additional Stains and Corrosion	Y ☐ N ☑		
Stressed Vegetation	Y ☐ N ☑		
Non-sanitary wastewater	Y ☐ N ☑		
Septic System and/or Cesspools	Y ☐ N ☑		
Wells (including monitoring, irrigation, dry wells, underground injection wells)	Y ☐ N ☑		
Air Emissions/Exhaust/SSDS systems	Y ☐ N ☑		
Additional observations of note			

Dry Cleaning: Y ☐ N ☑

Length of operations:

Number and type of machine(s) used location:

Cleaners/solvents used:

Storage location:

Wastes generated: Y ☐ N ☐ Storage location:

Spot cleaning: Y ☐ N ☐

X-Ray and/or Film Developing: Y ☐ N ☑ Digital X-Rays: Y ☐ N ☑

Length of operations:

Silver-recovery system: Y ☐ N ☐

If yes, discharge location

Previous discharges to septic system: Y ☐ N ☐

Site Reconnaissance Worksheet

Nearby Properties

	Adjoining Uses	Address
North	Book publisher, residential, parking lot	66-98 Best, 960 Ellicott
East	Apartment, City Mission	951 + 1100 Ellicott, 150 North East St
South	Parking lot, Kaleida Health, Gates Vascular, Parking Ramp	101, 121 north east, 851 854 Ellicott
West	Buffalo Hearing, Vacant, Niagara Mohawk	50 North East, 49-50 Paul, 53 Best
Noteworthy adjoining and nearby property features:		

Subject Property Sketch (label north): Include buildings, tanks and other significant observations, water bodies, topography slopes, adjoining roads, etc.

Site Photographs

Photo 1 : Northern portion of property - Sublot 3

Photo 2 : Typical exteriors of an apartment building located on the northern portion of the property

Photo 3 : Typical exteriors of an apartment building located on the northern portion of the property

Photo 4 : Typical exterior of an apartment building located on the northern portion of the property

Photo 5 : Typical exterior of an apartment building located on the northern portion of the property

Photo 6 : Typical exterior of an apartment building located on the northern portion of the property

Photo 7 : Subject Building 1 - Representative basement



Photo 8 : Subject Building 1 - Representative basement

Photo 9 : Subject Building 1 - Representative basement drain

Photo 10 : Subject Building 1 - Representative bathroom

Photo 11 : Subject Building 1 - Representative apartment unit interior

Photo 12 : Subject Building 1 - Representative apartment unit interior

Photo 13 : Subject Building 1 - Representative apartment unit interior

Photo 14 : Subject Building 1 - Representative second floor

Photo 15 : Subject Building 4 (storage building)- north exterior

Photo 16 : Subject Building 4 (storage building)- east exterior

Photo 17 : Subject Building 4 (storage building)- south exterior

Photo 18 : Subject Building 4 (storage building)- west exterior

Photo 19 : Unlabeled drums near storage garage on southeast portion of property

Photo 20 : Southeast portion of the Subject Property (looking west)

Photo 21 : Fill piles on southeast portion - Sublot 5

Photo 22 : Fill piles on southeast portion - Sublot 5

Photo 23 : Fill piles on southeast portion - Sublot 5

Photo 24 : Northern portion of property - Sublot 3

Photo 25 : Southwest portion of the property - Sublot 4

Photo 26 : Southwest portion of the property - Sublot 4

Photo 27 : Southwest portion of the property - Sublot 4

Photo 28 : Southwest portion of the property - Sublot 4

Photo 29 : North adjacent properties

Photo 30 : East adjacent properties under construction

Photo 31 : East adjacent properties

Photo 32 : South adjacent properties

Photo 33 : South adjacent properties

Photo 34 : West adjacent properties

Historical Information

FIRE INSURANCE MAPS

Project Property:	2231229: Phase I: Pilgrim Village, Sublots 3, 4 & 5, 903 & 951 Ellicott S 903 and 951 Ellicott Street Buffalo NY 14209
Project No:	2231229
Requested By:	LaBella Associates
Order No:	23022300643
Date Completed:	February 24, 2023

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Listed below, please find the results of our search for historic fire insurance maps from our in-house collection, performed in conjuction with your ERIS report.

Date	City	State	Volume	Sheet Number(s)
1889	Buffalo	New York	1	10, 11, 12, 13
1889	Buffalo	New York	3	101
1899	Buffalo	New York	3	261, 262, 263, 275, 276, 277, 278, 282
1925	Buffalo	New York	1a	83, 84, 85, 86, 87, 88
1951	Buffalo	New York	1a	83, 84, 85, 86, 87, 88
1981	Buffalo	New York	1a	83, 84, 85, 86, 87, 88
1986	Buffalo	New York	1a	83, 84, 85, 86, 87, 88
1986	Buffalo	New York	3	273, 296

Individual Fire Insurance Maps for the subject property and/or adjacent sites are included with the ERIS environmental database report to be used for research purposes only and cannot be resold for any other commercial uses other than for use in a Phase I environmental assessment.

Fire Insurance Map

1889

N

Feet 0 125 250 500 750 1,000

Address: 903 and 951 Ellicott Street Buffalo NY 14209



Map sheet(s):
Volume 1: 10,11,12,13;
Volume 3: 101;

Order Number 23022300643

ERIS

Fire Insurance Map



1899

0 125 250 500 750 1,000

N

Feet

Address: 903 and 951 Ellicott Street Buffalo NY 14209



Map sheet(s):
Volume 3: 261,262,263,275,276,277,278,282;

Order Number 23022300643

ERIS

Fire Insurance Map



1925

N

Feet 0 125 250 500 750 1,000

Address: 903 and 951 Ellicott Street Buffalo NY 14209



Map sheet(s):
Volume 1a: 83,84,85,86,87,88;

Order Number 23022300643

ERIS

Fire Insurance Map



1951

N

0 125 250 500 750 1,000

Feet

Address: 903 and 951 Ellicott Street Buffalo NY 14209



Map sheet(s):
Volume 1a: 83,84,85,86,87,88;

Order Number 23022300643

ERIS

Fire Insurance Map



1981

N

0 125 250 500 750 1,000

Feet

Address: 903 and 951 Ellicott Street Buffalo NY 14209



Map sheet(s):
Volume 1a: 83,84,85,86,87,88;

Order Number 23022300643

ERIS

Fire Insurance Map



1986

N

0 125 250 500 750 1,000

Feet

Address: 903 and 951 Ellicott Street Buffalo NY 14209



Map sheet(s):
Volume 1a: 83,84,85,86,87,88;
Volume 3: 273,296;

Order Number 23022300643

ERIS

CITY DIRECTORY

Project Property:	*2231229: Phase I: Pilgrim Village, Sublots 3, 4 & 5, 903 & 951 Ellicott St., Buffalo* *903 and 951 Ellicott Street* *Buffalo,NY 14209*
Project No:	*2231229*
Requested By:	*LaBella Associates*
Order No:	*23022300643*
Date Completed:	*March 01, 2023*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

March 01, 2023
RE: CITY DIRECTORY RESEARCH
903 and 951 Ellicott Street
Buffalo,NY 14209

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:
BEG-200 of Best St
850-1000 of Ellicott St
ALL of Goodrich St
1000-1150 of Michigan Ave
BEG-200 of North St E
Search Notes:

Search Results Summary

Date	Source	Comment
2022	DIGITAL BUSINESS DIRECTORY	
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2000	DIGITAL BUSINESS DIRECTORY	
1995	HAINES	
1990	HAINES	
1985	HAINES	
1980	HAINES	
1976	HAINES	
1971	HAINES	
1965	POLKS	
1960	POLKS	
1955	POLKS	
1950	POLKS	
1946	POLKS	
1940	POLKS	
1935	POLKS	
1930	POLKS	

2022 BEST ST

SOURCE: DIGITAL BUSINESS DIRECTORY

68	**RODERICK JACKSON**	*RESIDENTIAL*
68	**SHELIA MOSS**	*RESIDENTIAL*
72	**YOLANDA ROLAND**	*RESIDENTIAL*
88	**KENNETH COOPER**	*RESIDENTIAL*
94	**PAUL HENRY**	*RESIDENTIAL*
112	**KEVIN GRANT**	*RESIDENTIAL*
116	**KEYSHARIA WILLIAMS**	*RESIDENTIAL*
120	**EVAN HALL**	*RESIDENTIAL*
120	**JARROD BROWN**	*RESIDENTIAL*
122	**DARYL CATHCART**	*RESIDENTIAL*
126	**SONJA SCOTT**	*RESIDENTIAL*
166	**RICKY WILLIAMS**	*RESIDENTIAL*
178	**WILLIAM STANFORD**	*RESIDENTIAL*
184	**AMANDA CALDERON**	*RESIDENTIAL*
184	**JAMIL KASUMU**	*RESIDENTIAL*
186	**QUINTON ANGEL**	*RESIDENTIAL*

2022 ELLICOTT ST

SOURCE: DIGITAL BUSINESS DIRECTORY

866	**ACCESS FUNDING LLC**	*FINANCING*
875	**ACCUTHERANOSTICS INC**	*LABORATORIES-CLINICAL*
875	**AKINS, TAYLOR**	*NURSES-PRACTITIONERS*
875	**BEAVER, STACY**	*OFFICES OF ALL OTHER MISC HEALTH PRACTITIONERS*
875	**BECK, HIROKO MD**	*PHYSICIANS & SURGEONS*
875	**BLACKLEY, EMMA PA**	*PHYSICIANS ASSISTANTS*
875	**CHU, THOMAS W MD**	*PHYSICIANS & SURGEONS*
875	**DEMARCO, SUSAN E NP**	*NURSES-PRACTITIONERS*
875	**GATES VASCULAR INSTITUTE**	*DRUG ABUSE & ADDICTION INFO & TREATMENT*
875	**GATES VASCULAR INSTITUTE**	*HOSPITALS*
875	**GATES VASCULAR INSTITUTE**	*MEDICAL & SURGICAL SVC ORGANIZATIONS*
875	**GATES VASCULAR INSTITUTE**	*PHYSICIANS & SURGEONS*
875	**HAMBRIDGE, JOANNE NP**	*NURSES-PRACTITIONERS*
875	**HICAR LAB**	*LABORATORIES*
875	**JACOBS INSTITUTE INC**	*ASSOCIATIONS*
875	**SWIATEK, DENISE**	*PHARMACISTS*
875	**TIM HORTONS**	*DOUGHNUTS*
875	**TROEN, BRUCE R MD**	*PHYSICIANS & SURGEONS*
875	**UBNS**	*NONCLASSIFIED ESTABLISHMENTS*
875	**UNIVERSITY BUFFALO DERMATOLOGY**	*PHYSICIANS & SURGEONS*
969	**DELLAVALLE, JOSEPH M DPT**	*PHYSICAL THERAPISTS*
997	**DOROTHY BRYANT**	*RESIDENTIAL*

2022 GOODRICH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

100 **KALEIDA HEALTH**...*ALL OTHER MISC AMBULATORY HEALTH CARE SERVICES*

2022 MICHIGAN AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1031 **ALICE BURGESS**...*RESIDENTIAL*
1031 **ALICE MIKOS**...*RESIDENTIAL*
1031 **COLEEN CONNER**...*RESIDENTIAL*
1031 **DOROTHY SLAUGHTER**...*RESIDENTIAL*
1031 **ERNEST HENDERSON**...*RESIDENTIAL*
1031 **HIGHPOINTE MI SUBACUTE RHB**...*NURSING & CONVALESCENT HOMES*
1031 **JENNIE AYALA**...*RESIDENTIAL*
1031 **LOIS MILLER**...*RESIDENTIAL*
1031 **MARY DOWLING**...*RESIDENTIAL*
1031 **MARYANN GRAMZA**...*RESIDENTIAL*
1031 **MAURICE JONES**...*RESIDENTIAL*
1031 **MYRTLE ANDERSON**...*RESIDENTIAL*
1031 **PATRICIA NAGY**...*RESIDENTIAL*
1031 **PHILLIP JOHNSON**...*RESIDENTIAL*
1031 **UBMD PEDIATRICS OUTPATIENT CTR**...*PHYSICIANS & SURGEONS*
1075 **NATINA PERRY**...*RESIDENTIAL*
1083 **MARK GIST**...*RESIDENTIAL*
1148 **CAMMARATA, MICHAEL S**...*COUNSELORS*
1148 **DON HALE MATERIAL HANDLING**...*MATERIAL HANDLING EQUIPMENT (WHLS)*

2022 NORTH ST E

SOURCE: DIGITAL BUSINESS DIRECTORY

50 **ARMBRUST, KATHERINE M**...*PSYCHOLOGISTS*
50 **BAKER, KELLY A**...*SPEECH & HEARING THERAPY*
50 **BENNETT, KAYTIE**...*PHYSICAL THERAPISTS*
50 **BROWN, TIANA**...*SPEECH PATHOLOGISTS*
50 **BUFFALO HEARING & SPEECH CTR**...*REHABILITATION SERVICES*
50 **BUFFALO HEARING & SPEECH CTR**...*SPEECH PATHOLOGISTS*
50 **CHAMBERLIN, CARRIE**...*SPEECH & HEARING THERAPY*
50 **CZWOJDAK, ALLISON J**...*OFFICES-PHYSICAL, OCCPTNL/SPEECH THRPSTS/AUDLGSTS*
50 **DRZEWIECKI, KIMBERLY**...*NONCLASSIFIED ESTABLISHMENTS*
50 **GOGGINS, REBECCA**...*SOCIAL WORKERS*
50 **HAMM, MEGAN**...*SOCIAL WORKERS*
50 **IRANI, ROSHNELLE**...*PHYSICAL THERAPISTS*
50 **KOWALSKI, ROSINA G**...*PHYSICAL THERAPISTS*
50 **KREHER, SARA**...*SPEECH PATHOLOGISTS*
50 **LEGGETT, KARLI**...*SPEECH PATHOLOGISTS*
50 **MARZULLO, GEORGIA**...*SOCIAL WORKERS*
50 **ROTH, LAURIE A**...*SPEECH & HEARING THERAPY*
50 **RUSINSKI, MELANIE J**...*PHYSICAL THERAPISTS*
150 **CORNERSTONE MANOR**...*SOCIAL SERVICE & WELFARE ORGANIZATIONS*
150 **IESHA AUGHTRY**...*RESIDENTIAL*
150 **ROBERT TAYLOR**...*RESIDENTIAL*
186 **CITY HONORS SCHOOL**...*SCHOOLSUNIVERSITIES & COLLEGES ACADEMIC*
186 **CITY HONORS SCHOOL**...*SCHOOLS*

2020 BEST ST

SOURCE: DIGITAL BUSINESS DIRECTORY

68 **RODERICK JACKSON**...*RESIDENTIAL*
68 **SHELIA MOSS**...*RESIDENTIAL*
72 **YOLANDA ROLAND**...*RESIDENTIAL*
88 **KENNETH COOPER**...*RESIDENTIAL*
94 **PAUL HENRY**...*RESIDENTIAL*
112 **BELINDA GRANT**...*RESIDENTIAL*
116 **KEYSHARIA WILLIAMS**...*RESIDENTIAL*
120 **JARROD BROWN**...*RESIDENTIAL*
122 **DARYL CATHCART**...*RESIDENTIAL*
122 **HENRY TAYLOR**...*RESIDENTIAL*
126 **NISHA SCOTT**...*RESIDENTIAL*
166 **RICKY WILLIAMS**...*RESIDENTIAL*
178 **WILLIAM STANFORD**...*RESIDENTIAL*
184 **AMANDA CALDERON**...*RESIDENTIAL*
186 **QUINTON ANGEL**...*RESIDENTIAL*

2020 ELLICOTT ST

SOURCE: DIGITAL BUSINESS DIRECTORY

866 **ACCESS FUNDING LLC**...*FINANCING*
875 **ACCUTHERANOSTICS INC**...*LABORATORIES-CLINICAL*
875 **AKINS, TAYLOR**...*NURSES-PRACTITIONERS*
875 **BEAVER, STACY**...*OFFICES OF ALL OTHER MISC HEALTH PRACTITIONERS*
875 **BECK, HIROKO MD**...*PHYSICIANS & SURGEONS*
875 **BLACKLEY, EMMA PA**...*PHYSICIANS ASSISTANTS*
875 **CHU, THOMAS W MD**...*PHYSICIANS & SURGEONS*
875 **DEMARCO, SUSAN E NP**...*NURSES-PRACTITIONERS*
875 **DORIZAS, ANDREW S MD**...*PHYSICIANS & SURGEONS*
875 **GATES VASCULAR INSTITUTE**...*MEDICAL & SURGICAL SVC ORGANIZATIONS*
875 **GATES VASCULAR INSTITUTE**...*HOSPITALS*
875 **GATES VASCULAR INSTITUTE**...*DRUG ABUSE & ADDICTION INFO & TREATMENT*
875 **GATES VASCULAR INSTITUTE**...*PHYSICIANS & SURGEONS*
875 **HAMBRIDGE, JOANNE NP**...*NURSES-PRACTITIONERS*
875 **HICAR LAB**...*LABORATORIES*
875 **JACOBS INSTITUTE INC**...*ASSOCIATIONS*
875 **TIM HORTONS**...*DOUGHNUTS*
875 **TROEN, BRUCE R MD**...*PHYSICIANS & SURGEONS*
875 **UBNS**...*NONCLASSIFIED ESTABLISHMENTS*
967 **UNIVERSAL CARPET UPHOLSTERY**...*CARPET & RUG CLEANERS*
969 **DELLAVALLE, JOSEPH M DPT**...*PHYSICAL THERAPISTS*
980 **OSMOSE HOLDINGS INC**...*LUMBER-TREATING (MFRS)*
980 **OSMOSE HOLDINGS INC**...*IMPORTERS (WHLS)*
980 **OSMOSE HOLDINGS INC**...*FISHING TACKLEDEALERS*
980 **OSMOSE HOLDINGS INC**...*WOOD PRODUCTS NEC (MFRS)*
980 **OSMOSE UTILITIES SVC**...*FEDERAL GOVERNMENT CONTRACTORS*
980 **OSMOSE UTILITIES SVC**...*UTILITY CONTRACTORS*
991 **JOVANNA JACOBS**...*RESIDENTIAL*
997 **DOROTHY BRYANT**...*RESIDENTIAL*

2020 GOODRICH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

100 **KALEIDA HEALTH**...*ALL OTHER MISC AMBULATORY HEALTH CARE SERVICES*

2020 MICHIGAN AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1031 **ALICE BURGESS**...*RESIDENTIAL*
1031 **ALICE MIKOS**...*RESIDENTIAL*
1031 **DOROTHY SLAUGHTER**...*RESIDENTIAL*
1031 **ERNEST HENDERSON**...*RESIDENTIAL*
1031 **HIGHPOINTE MI SUBACUTE RHB**...*NURSING & CONVALESCENT HOMES*
1031 **JENNIE AYALA**...*RESIDENTIAL*
1031 **LOIS MILLER**...*RESIDENTIAL*
1031 **MARY DOWLING**...*RESIDENTIAL*
1031 **MARYANN GRAMZA**...*RESIDENTIAL*
1031 **MAURICE JONES**...*RESIDENTIAL*
1031 **MYRTLE ANDERSON**...*RESIDENTIAL*
1031 **PATRICIA NAGY**...*RESIDENTIAL*
1031 **PHILLIP JOHNSON**...*RESIDENTIAL*
1031 **UBMD PEDIATRICS OUTPATIENT CTR**...*PHYSICIANS & SURGEONS*
1075 **NATINA PERRY**...*RESIDENTIAL*
1083 **MARK GIST**...*RESIDENTIAL*
1148 **CAMMARATA, MICHAEL S**...*COUNSELORS*
1148 **DON HALE MATERIAL HANDLING**...*MATERIAL HANDLING EQUIPMENT (WHLS)*

2020 NORTH ST E

SOURCE: DIGITAL BUSINESS DIRECTORY

50 **ARMBRUST, KATHERINE M**...*PSYCHOLOGISTS*
50 **BAKER, KELLY A**...*SPEECH & HEARING THERAPY*
50 **BENNETT, KAYTIE**...*PHYSICAL THERAPISTS*
50 **BUFFALO HEARING & SPEECH CTR**...*REHABILITATION SERVICES*
50 **BUFFALO HEARING & SPEECH CTR**...*SPEECH PATHOLOGISTS*
50 **CHAMBERLIN, CARRIE**...*SPEECH & HEARING THERAPY*
50 **CZWOJDAK, ALLISON J**...*OFFICES-PHYSICAL, OCCPTNL/SPEECH THRPSTS/AUDLGSTS*
50 **DRZEWIECKI, KIMBERLY**...*NONCLASSIFIED ESTABLISHMENTS*
50 **HAMM, MEGAN**...*SOCIAL WORKERS*
50 **IRANI, ROSHNELLE**...*PHYSICAL THERAPISTS*
50 **KOWALSKI, ROSINA G**...*PHYSICAL THERAPISTS*
50 **MARZULLO, GEORGIA**...*SOCIAL WORKERS*
50 **ROTH, LAURIE A**...*SPEECH & HEARING THERAPY*
50 **RUSINSKI, MELANIE J**...*PHYSICAL THERAPISTS*
50 **SMITH, LEANNA**...*NONCLASSIFIED ESTABLISHMENTS*
50 **STAYCHOCK, KRISTIN**...*NONCLASSIFIED ESTABLISHMENTS*
50 **TORRES, NAOMI JOY**...*NONCLASSIFIED ESTABLISHMENTS*
50 **WILBUR, KIMBERLY**...*NONCLASSIFIED ESTABLISHMENTS*
150 **CORNERSTONE MANOR**...*SOCIAL SERVICE & WELFARE ORGANIZATIONS*
150 **IESHA AUGHTRY**...*RESIDENTIAL*
150 **REBEKAH TAYLOR**...*RESIDENTIAL*
186 **CITY HONORS SCHOOL**...*SCHOOLSUNIVERSITIES & COLLEGES ACADEMIC*
186 **CITY HONORS SCHOOL**...*SCHOOLS*

2016 BEST ST

SOURCE: DIGITAL BUSINESS DIRECTORY

68 **SHELIA MOSS**...*RESIDENTIAL*
88 **KENNETH COOPER**...*RESIDENTIAL*
94 **PAUL HENRY**...*RESIDENTIAL*
116 **KEYSHARIA WILLIAMS**...*RESIDENTIAL*
120 **EVAN HALL**...*RESIDENTIAL*
120 **JARROD BROWN**...*RESIDENTIAL*
122 **DARYL CATHCART**...*RESIDENTIAL*
122 **HENRY TAYLOR**...*RESIDENTIAL*
166 **RICKY WILLIAMS**...*RESIDENTIAL*
166 **TEMPIE WILLIAMS**...*RESIDENTIAL*
178 **WILLIAM STANFORD**...*RESIDENTIAL*
186 **QUINTON ANGEL**...*RESIDENTIAL*

2016 ELLICOTT ST

SOURCE: DIGITAL BUSINESS DIRECTORY

854 **ELECTRIC CHARGING STATION**...*ELECTRIC CHARGING STATION*
866 **ACCESS FUNDING LLC**...*FINANCING*
875 **BEAVER, STACY**...*OFFICES OF ALL OTHER MISC HEALTH PRACTITIONERS*
875 **DEMARCO, SUSAN E NP**...*NURSES-PRACTITIONERS*
875 **GATES VASCULAR INSTITUTE**...*PHYSICIANS & SURGEONS*
875 **HICAR LAB**...*LABORATORIES*
875 **HUANG, LAURA**...*NONCLASSIFIED ESTABLISHMENTS*
967 **UNIVERSAL CARPET & UPHOLSTERY**...*CARPET & RUG CLEANERS*
973 **MARQUITA HUNTER**...*RESIDENTIAL*
980 **OSMOSE HOLDINGS INC**...*LUMBER-TREATING (MFRS)*
980 **OSMOSE HOLDINGS INC**...*IMPORTERS (WHLS)*
991 **JOVANNA JACOBS**...*RESIDENTIAL*
997 **DOROTHY BRYANT**...*RESIDENTIAL*

2016 GOODRICH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

80 **BEGGS, BARBARA J**...*SOCIAL WORKERS*
80 **BORCZUCH, JOHN**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **COLLADO, VALERIE A**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **DEMPSEY, BONNIE J**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **DENNIS, JAMES C**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **MARION, RAMONA R**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **MC CULLOCH, NANCY B**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **MILLER-HOLLOWA, LILLIE M**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **PARK, WONHOON MD**...*PHYSICIANS & SURGEONS*
80 **PIERCE, WALTER E**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **WIEDER, CHRISTINE M**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **ZWEIG, CATHERINE R**...*COUNSELORS-LICENSED PROFESSIONAL*
100 **KALEIDA HEALTH**...*ALL OTHER MISC AMBULATORY HEALTH CARE SERVICES*

2016 MICHIGAN AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1031 **ALICE BURGESS**...*RESIDENTIAL*
1031 **ALICE MIKOS**...*RESIDENTIAL*
1031 **ANGELA CARR**...*RESIDENTIAL*
1031 **DOROTHY SLAUGHTER**...*RESIDENTIAL*
1031 **ERNEST HENDERSON**...*RESIDENTIAL*
1031 **HIGHPOINTE ON MI SUBACUTE RHB**...*NURSING & CONVALESCENT HOMES*
1031 **JAMES LEFF**...*RESIDENTIAL*
1031 **JENNIE AYALA**...*RESIDENTIAL*
1031 **KALEIDA HEALTH**...*HEALTH SERVICES*
1031 **LOIS MILLER**...*RESIDENTIAL*
1031 **MARTHA CHILLIS**...*RESIDENTIAL*
1031 **MARY DOWLING**...*RESIDENTIAL*
1031 **MARYANN GRAMZA**...*RESIDENTIAL*
1031 **MAURICE JONES**...*RESIDENTIAL*
1031 **MYRTLE ANDERSON**...*RESIDENTIAL*
1031 **PATRICIA NAGY**...*RESIDENTIAL*
1031 **PHILLIP JOHNSON**...*RESIDENTIAL*
1075 **NATINA PERRY**...*RESIDENTIAL*
1083 **MARK GIST**...*RESIDENTIAL*
1107 **LYNETTE MENNA**...*RESIDENTIAL*
1148 **DON HALE MATERIAL HANDLING**...*MATERIAL HANDLING EQUIPMENT (WHLS)*

2016 NORTH ST E

SOURCE: DIGITAL BUSINESS DIRECTORY

0	**CZWOJDAK, ALLISON J**	*SPEECH PATHOLOGISTS*
50	**BRISSETTE, NANCY L**	*SPEECH & HEARING THERAPY*
50	**BUFFALO HEARING & SPEECH CTR**	*SPEECH PATHOLOGISTS*
50	**CHAMBERLIN, CARRIE**	*SPEECH & HEARING THERAPY*
50	**CZWOJDAK, ALLISON J**	*OFFICES-PHYSICAL, OCCPTNL/SPEECH THRPSTS/AUDLGSTS*
50	**HAGGERTY, MEREDITH**	*HOME HEALTH SERVICE*
50	**KURAS, MICHELLE A**	*SPEECH & HEARING THERAPY*
50	**POLLOCK, PAMELA K**	*SPEECH & HEARING THERAPY*
50	**ROTH, LAURIE A**	*SPEECH & HEARING THERAPY*
50	**RUSINSKI, MELANIE J**	*PHYSICAL THERAPISTS*
50	**SCUTT, KAREN J**	*PHYSICAL THERAPISTS*
150	**CITY MISSION SOCIETY INC**	*ORGANIZATIONS*
150	**CORNERSTONE MANOR**	*SOCIAL SERVICE & WELFARE ORGANIZATIONS*
150	**IESHA AUGHTRY**	*RESIDENTIAL*
150	**ROBERT TAYLOR**	*RESIDENTIAL*
186	**CITY HONORS SCHOOL**	*SCHOOLS*

2012 BEST ST

SOURCE: DIGITAL BUSINESS DIRECTORY

70	**SHAVETTE YOUNG**	*RESIDENTIAL*
94	**HENRY GWENDOLYN**	*RESIDENTIAL*
94	**PAUL HENRY**	*RESIDENTIAL*
96	**MICHAEL GUIZE**	*RESIDENTIAL*
102	**WADE GARNER**	*RESIDENTIAL*
112	**KEVIN GRANT**	*RESIDENTIAL*
118	**BARBARA BROOKS**	*RESIDENTIAL*
118	**MALENE BROOKS**	*RESIDENTIAL*
118	**NATHANIEL BROOKS**	*RESIDENTIAL*
120	**BARBARA BROOKS**	*RESIDENTIAL*
126	**SONJA SCOTT**	*RESIDENTIAL*
166	**EFREM DAWKINS**	*RESIDENTIAL*
166	**TEMPIE WILLIAMS**	*RESIDENTIAL*
178	**HAROLD STANFORD**	*RESIDENTIAL*
178	**WILLIAM STANFORD**	*RESIDENTIAL*
186	**GLENDYLN ANGEL**	*RESIDENTIAL*
186	**QUINTON ANGEL**	*RESIDENTIAL*
189	**ALONZO THOMAS**	*RESIDENTIAL*
190	**JAMES KENNDY**	*RESIDENTIAL*
190	**JAMES KENNEDY**	*RESIDENTIAL*
190	**KENNEDY JAMES**	*RESIDENTIAL*

2012 ELLICOTT ST

SOURCE: DIGITAL BUSINESS DIRECTORY

866 **ACCESS FUNDING LLC**...*FINANCING*
980 **OSMOSE HOLDINGS INC**...*LUMBER-TREATING (MFRS)*
980 **OSMOSE UTILITIES SVC INC**...*UTILITY CONTRACTORS*
997 **DOROTHY BRYANT**...*RESIDENTIAL*

2012 GOODRICH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

80 **ATKINSON, BRENDA A**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **BEGGS, BARBARA J**...*SOCIAL WORKERS*
80 **BORCZUCH, JOHN**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **CLINE-TARBELL, WENDY**...*SOCIAL WORKERS*
80 **COLLADO, VALERIE A**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **DEMPSEY, BONNIE J**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **DENNIS, JAMES C**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **GRIER, ANDREW M**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **GRIFFIN, GREGORY**...*SOCIAL WORKERS*
80 **GRUPP, SUSAN M**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **GULLO, FRANK J**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **KRURNOWSKI, WILLIAM G**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **LANNIE, LEONARD**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **LYNCH, REGINALD L**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **MARION, RAMONA R**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **MC CULLOCH, NANCY B**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **MILLER-HOLLOWA, LILLIE M**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **PARK, WONHOON MD**...*PHYSICIANS & SURGEONS*
80 **PIERCE, WALTER E**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **SYKES, MARILYN**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **WHITEFIELD, KATHLEEN T**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **WIEDER, CHRISTINE M**...*COUNSELORS-LICENSED PROFESSIONAL*
80 **ZWEIG, CATHERINE R**...*COUNSELORS-LICENSED PROFESSIONAL*

1031 **ARTHUR MACKIE**...*RESIDENTIAL*
1031 **STEVEN MACKIE**...*RESIDENTIAL*
1031 **VERA MACKIE**...*RESIDENTIAL*
1148 **DON HALE MATERIAL HANDLING**...*MATERIAL HANDLING EQUIPMENT (WHLS)*

93 total records. Part 1 of 2

50 **ANDERSON, MICHELLE B**...*SPEECH & HEARING THERAPY*
50 **BAKER, KELLY A**...*SPEECH & HEARING THERAPY*
50 **BALON, TRACY A**...*SPEECH & HEARING THERAPY*
50 **BAMRICK, AMY E**...*SPEECH & HEARING THERAPY*
50 **BARONE, SHERRIN M**...*SPEECH & HEARING THERAPY*
50 **BASKERVILL, MAXINE A**...*SPEECH & HEARING THERAPY*
50 **BAUER, CARMILLE A**...*SPEECH & HEARING THERAPY*
50 **BECKER, DONNA G**...*SPEECH & HEARING THERAPY*
50 **BERES, JOANNA**...*SPEECH & HEARING THERAPY*
50 **BOREL, DENISE A**...*SPEECH & HEARING THERAPY*
50 **BRISSETTE, NANCY L**...*SPEECH & HEARING THERAPY*
50 **BROWN, DALE**...*SPEECH & HEARING THERAPY*
50 **BUFFALO HEARING & SPEECH CTR**...*SPEECH PATHOLOGISTS*
50 **CHAMBERLIN, CARRIE**...*SPEECH & HEARING THERAPY*
50 **CHAVANNE, HOPE M**...*SPEECH & HEARING THERAPY*
50 **CORNER, JENNIFER S**...*SPEECH & HEARING THERAPY*
50 **COTTON, STEPHENIE M**...*SPEECH & HEARING THERAPY*
50 **DAUBNER, KEVIN W**...*SPEECH & HEARING THERAPY*
50 **DEROO, WILLIAM E**...*SPEECH & HEARING THERAPY*
50 **DICKINSON, LAURA A**...*SPEECH & HEARING THERAPY*
50 **DORMAN, CATHY A**...*PHYSICAL THERAPISTS*
50 **DUBE, MICHELLE M**...*SPEECH & HEARING THERAPY*
50 **DUHAN, CAROL J**...*SPEECH & HEARING THERAPY*
50 **ELWELL, NANCY K**...*SPEECH & HEARING THERAPY*
50 **FELKER, MONIKA M**...*SPEECH & HEARING THERAPY*
50 **FRISBIE, ERIKA E**...*PHYSICAL THERAPISTS*
50 **FURLANI, MARY ANNE**...*SPEECH & HEARING THERAPY*
50 **GETHOEFER, KIERA A**...*SPEECH & HEARING THERAPY*
50 **GREEN, LISA A**...*SPEECH & HEARING THERAPY*
50 **GREK, JENNIFER L**...*SPEECH & HEARING THERAPY*
50 **GRETKA, JEANETTE A**...*PHYSICAL THERAPISTS*
50 **HARNICK, ADRIENNE**...*PHYSICAL THERAPISTS*
50 **HEIST, THERESA L**...*SPEECH & HEARING THERAPY*
50 **HOMER, MERCY A**...*SPEECH & HEARING THERAPY*
50 **HORSCHEL, JENNIFER T**...*SPEECH & HEARING THERAPY*
50 **JOHNSON, MARY ANNE**...*SPEECH & HEARING THERAPY*
50 **KIRKLAND, CARRIE-ANNE**...*SPEECH & HEARING THERAPY*
50 **KLIPPEL, MELANIE A**...*SPEECH & HEARING THERAPY*
50 **KOWALSKI, JULIE**...*SPEECH & HEARING THERAPY*
50 **KOWALSKI, ROSINA G**...*PHYSICAL THERAPISTS*
50 **KUBIK, ANITA R**...*SPEECH & HEARING THERAPY*
50 **KUEKER, ANDREA R**...*SPEECH & HEARING THERAPY*
50 **KURAS, MICHELLE A**...*SPEECH & HEARING THERAPY*
50 **KWOKA, TRACIE A**...*PHYSICAL THERAPISTS*
50 **LAKE, JENNIFER**...*SPEECH & HEARING THERAPY*
50 **LUCARELLI, MONICA L**...*SPEECH & HEARING THERAPY*
50 **MACKO, MARIA G**...*SPEECH & HEARING THERAPY*
50 **MAGINNIS, SARAH M**...*SPEECH & HEARING THERAPY*
50 **MANCUSO, MARISA B**...*SPEECH & HEARING THERAPY*
50 **MANGO, ROSE-MARIE**...*SPEECH & HEARING THERAPY*
50 **MARSACK, SARAH F**...*SPEECH & HEARING THERAPY*
50 **MEYER, JULIE S**...*SPEECH & HEARING THERAPY*
50 **MILLER, MICHELLE L**...*SPEECH & HEARING THERAPY*
50 **MILLER, STEVEN R**...*SPEECH & HEARING THERAPY*
50 **MISKINES, LINDA R**...*SPEECH & HEARING THERAPY*
50 **PAES, AVERILL M**...*SPEECH & HEARING THERAPY*
50 **PALMER-HOLLAND, PRUDENCE**...*SPEECH & HEARING THERAPY*
50 **PASQUALE, LORI A**...*SPEECH & HEARING THERAPY*
50 **PERGRIM, DENISE C**...*SPEECH & HEARING THERAPY*
50 **POLLOCK, PAMELA K**...*SPEECH & HEARING THERAPY*
50 **RENKEN-MINTZER, SUSAN M**...*SPEECH & HEARING THERAPY*
50 **REYNOLDS, AMY S**...*PHYSICAL THERAPISTS*
50 **RICCIARDI, KAREN M**...*SPEECH & HEARING THERAPY*
50 **ROTH, LAURIE A**...*SPEECH & HEARING THERAPY*
50 **RUMFOLA, JENNIFER**...*SPEECH & HEARING THERAPY*
50 **RUSINSKI, MELANIE J**...*PHYSICAL THERAPISTS*
50 **SACCO, PAMELA J**...*SPEECH & HEARING THERAPY*
50 **SAWYER, SARAH A**...*SPEECH & HEARING THERAPY*

2012 NORTH ST E

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

50 **SCUTT, KAREN J**...*PHYSICAL THERAPISTS*
50 **SHELDON, RENAE**...*SPEECH & HEARING THERAPY*
50 **SMETANIUK, MELISSA M**...*SPEECH & HEARING THERAPY*
50 **STANTON, JANELLE K**...*SPEECH & HEARING THERAPY*
50 **STANTON, KELLY M**...*SPEECH & HEARING THERAPY*
50 **STEGER, MEGHAN L**...*SPEECH & HEARING THERAPY*
50 **STOFFEL, SARA L**...*PHYSICAL THERAPISTS*
50 **STOHL, AMY B**...*SPEECH & HEARING THERAPY*
50 **STONE, HEATHER C**...*SPEECH & HEARING THERAPY*
50 **THOMPSON, BECKY L**...*SPEECH & HEARING THERAPY*
50 **VACANTI-LACHUT, SAMANTHA**...*SPEECH & HEARING THERAPY*
50 **VENTRE, REBECCA L**...*PHYSICAL THERAPISTS*
50 **WACH, JILLIAN L**...*SPEECH & HEARING THERAPY*
50 **WALLS, SUSAN**...*SPEECH & HEARING THERAPY*
50 **WARNER, SHARON**...*SPEECH & HEARING THERAPY*
50 **WASNER, SUSAN**...*PHYSICAL THERAPISTS*
50 **WHIPPLE, BETH A**...*SPEECH & HEARING THERAPY*
50 **WIELGASZ, KIM M**...*SPEECH & HEARING THERAPY*
50 **WILLIAMS, SARAH D**...*SPEECH & HEARING THERAPY*
50 **ZELLER, SARA T**...*SPEECH & HEARING THERAPY*
150 **CITY MISSION SOCIETY INC**...*ORGANIZATIONS*
150 **CORNER STONE MANOR**...*SOCIAL SERVICE & WELFARE ORGANIZATIONS*
150 **TRINA ALSTON**...*RESIDENTIAL*
186 **CITY HONORS SCHOOL**...*SCHOOLS*

2008 BEST ST

SOURCE: DIGITAL BUSINESS DIRECTORY

0 **MASTEN POOL**...*SWIMMING POOLS-PUBLIC*
70 **GLENWOOD H JR YOUNG**...*RESIDENTIAL*
70 **M ROWE**...*RESIDENTIAL*
72 **YOLONDA ROLAND**...*RESIDENTIAL*
86 **CAROL ECKFORD**...*RESIDENTIAL*
86 **VALERIE BARNES**...*RESIDENTIAL*
94 **PAUL T HENRY**...*RESIDENTIAL*
96 **T STROUD**...*RESIDENTIAL*
102 **DOROTHY GUYTON**...*RESIDENTIAL*
104 **PAULA BANKS**...*RESIDENTIAL*
104 **RENALDO MILES**...*RESIDENTIAL*
122 **MATTIE L DAVIS**...*RESIDENTIAL*
130 **ELVIE CHISM**...*RESIDENTIAL*
130 **MARVIN HARRIS**...*RESIDENTIAL*
130 **N HATTEN**...*RESIDENTIAL*
166 **SUGAR R WILLIAMS**...*RESIDENTIAL*
166 **T M WILLIAMS**...*RESIDENTIAL*
178 **WILLIAM P STANFORD**...*RESIDENTIAL*
184 **R L BROWN**...*RESIDENTIAL*
189 **JONNIE M THOMAS**...*RESIDENTIAL*
190 **JAMES KENNEDY**...*RESIDENTIAL*
200 **C KIRKABERNATHY**...*RESIDENTIAL*

2008 ELLICOTT ST

SOURCE: DIGITAL BUSINESS DIRECTORY

975 **A COSTNER**...*RESIDENTIAL*
975 **ANTHONY COSTNER**...*RESIDENTIAL*
980 **OSMOSE HOLDINGS INC**...*HOLDING COMPANY*
991 **EUGENE JACOBS**...*RESIDENTIAL*
991 **GREGORY BRIDGES**...*RESIDENTIAL*
997 **DOROTHY BRYANT**...*RESIDENTIAL*

2008 GOODRICH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

80 **COMMUNITY MENTAL HEALTH CTR**...*MENTAL HEALTH SERVICES*
80 **KALEIDA HEALTH**...*ALCOHOLISM INFORMATION & TREATMENT CTRS*
80 **MARIA NICKOLOVA MD**...*PHYSICIANS & SURGEONS*
80 **MICHAEL S MOGERMAN MD**...*PHYSICIANS & SURGEONS*

2008 MICHIGAN AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1031 **ARTHUR J MACKIE**...*RESIDENTIAL*
1049 **RICHARD GLOSTER**...*RESIDENTIAL*
1075 **NATINA PERRY**...*RESIDENTIAL*
1087 **BOBBIE LEE**...*RESIDENTIAL*
1095 **LAMON COOK**...*RESIDENTIAL*
1099 **SHUNDRA SMITH**...*RESIDENTIAL*
1103 **C YOUNG**...*RESIDENTIAL*
1103 **JAMES SMITH**...*RESIDENTIAL*
1111 **BARBARA BENTON**...*RESIDENTIAL*
1148 **DON HALE MATERIAL HANDLING**...*WHOL MATERIAL HANDLING EQUIPMENT*

2008 NORTH ST E

SOURCE: DIGITAL BUSINESS DIRECTORY

50 **BUFFALO HEARING & SPEECH CTR**...*SCHOOLS*
50 **BUFFALO HEARING AND SPEECH**...*CHARITY*
50 **BUFFALO HEARING AND SPEECH CTR**...*SPEECH THERAPY AND HEARING TESTING SERVICE*
186 **CITY HONORS SCHOOL**...*PUBLIC HIGH SCHOOL*

2003 BEST ST

SOURCE: DIGITAL BUSINESS DIRECTORY

0	**MASTEN POOL**
68	**CARL RICHARDSON**...*RESIDENTIAL*
70	**GLENWOOD H JR YOUNG**...*RESIDENTIAL*
86	**TANISHA BROOKS**...*RESIDENTIAL*
88	**ALICIA BRAY**...*RESIDENTIAL*
94	**CHARLES E HENRY**...*RESIDENTIAL*
94	**PAUL T HENRY**...*RESIDENTIAL*
102	**DOROTHY GUYTON**...*RESIDENTIAL*
102	**T DUNNEMANN**...*RESIDENTIAL*
122	**J LANG**...*RESIDENTIAL*
122	**SHARON LEE**...*RESIDENTIAL*
130	**A WASHINGTON**...*RESIDENTIAL*
166	**SUGAR R WILLIAMS**...*RESIDENTIAL*
166	**T M WILLIAMS**...*RESIDENTIAL*
178	**WM P STANFORD**...*RESIDENTIAL*
184	**RENDER L BROWN**...*RESIDENTIAL*
189	**JONNIE MAE THOMAS**...*RESIDENTIAL*
190	**JAMES KENNEDY**...*RESIDENTIAL*
192	**HUBERT HARPER**...*RESIDENTIAL*
200	**JAMES WINTERS JONES**...*RESIDENTIAL*

2003 ELLICOTT ST

SOURCE: DIGITAL BUSINESS DIRECTORY

967	**MULTI CULTURAL POTENTIAL CTR**
967	**NU-JA CLEANING SVC**
967	**UNIVERSAL CARPET & UPHOLSTERY**
975	**A COSTNER**...*RESIDENTIAL*
980	**OSMOSE INC**...*POLES, POSTS AND PILINGS: TREATED WOOD*
991	**EUGENE JACOBS**...*RESIDENTIAL*
997	**VERNON SHAW**...*RESIDENTIAL*

2003 GOODRICH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

80 **KALEIDA HEALTH**
80 **NICKOLOVA MARIA MD**...*INTERNAL MEDICINE PRACTITIONERS*
80 **PATO CARLOS MD**...*INTERNAL MEDICINE PRACTITIONERS*
80 **PATO MICHELE T MD**...*INTERNAL MEDICINE PRACTITIONERS*

2003 MICHIGAN AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1031 **ARTHUR J MACKIE**...*RESIDENTIAL*
1035 **UGENE MORROW**...*RESIDENTIAL*
1039 **T MORRIS**...*RESIDENTIAL*
1049 **RICHARD GLOSTER**...*RESIDENTIAL*
1049 **ROBERT APPLEWHITE**...*RESIDENTIAL*
1069 **TRACI M LEWIS**...*RESIDENTIAL*
1083 **RUTH RICHARDSON**...*RESIDENTIAL*
1095 **LAMON COOK**...*RESIDENTIAL*
1148 **DON HALE MATERIAL HANDLING**

2003 NORTH ST E

SOURCE: DIGITAL BUSINESS DIRECTORY

50 **BUFFALO HEARING & SPEECH CTR**
186 **CITY HONORS SCHOOL**...*PUBLIC ELEMENTARY AND SECONDARY SCHOOLS*

2000 BEST ST

SOURCE: DIGITAL BUSINESS DIRECTORY

68 **CARL RICHARDSON**...*RESIDENTIAL*
68 **KIM AVERY MUHAMMED**...*RESIDENTIAL*
86 **TANISHA BROOKS**...*RESIDENTIAL*
88 **ALICIA BRAY**...*RESIDENTIAL*
94 **CHARLES E HENRY**...*RESIDENTIAL*
94 **PAUL T HENRY**...*RESIDENTIAL*
102 **DOROTHY GUYTON**...*RESIDENTIAL*
102 **T DUNNEMANN**...*RESIDENTIAL*
122 **J LANG**...*RESIDENTIAL*
122 **SHARON LEE**...*RESIDENTIAL*
184 **RENDER L BROWN**...*RESIDENTIAL*
190 **JAMES KENNEDY**...*RESIDENTIAL*
192 **HUBERT HARPER**...*RESIDENTIAL*
200 **JAMES WINTERS JONES**...*RESIDENTIAL*

2000 ELLICOTT ST

SOURCE: DIGITAL BUSINESS DIRECTORY

967 **NU-JA CLEANING SVC**
967 **UNIVERSAL CARPET & UPHOLSTERY**
973 **JAMES L MOORE**...*RESIDENTIAL*
973 **TAMIKA BRYANT**...*RESIDENTIAL*
975 **A COSTNER**...*RESIDENTIAL*
975 **J LAWSON**...*RESIDENTIAL*
980 **OSMOSE INC**...*VIDEO AND AUDIO EQUIPMENT*
991 **EUGENE JACOBS**...*RESIDENTIAL*

2000 GOODRICH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

80 **KALEIDA HEALTH**
80 **KALEIDA HEALTH SYSTEM**
80 **KASHIN JEFFREY MD**...*INTERNAL MEDICINE PRACTITIONERS*
80 **NICKOLOVA MARIA MD**...*INTERNAL MEDICINE PRACTITIONERS*
80 **PATO MICHELE T MD**...*INTERNAL MEDICINE PRACTITIONERS*

2000 MICHIGAN AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1031 **ARTHUR J MACKIE**...*RESIDENTIAL*
1035 **UGENE MORROW**...*RESIDENTIAL*
1039 **T MORRIS**...*RESIDENTIAL*
1049 **RICHARD GLOSTER**...*RESIDENTIAL*
1049 **ROBERT APPLEWHITE**...*RESIDENTIAL*
1069 **TRACI M LEWIS**...*RESIDENTIAL*
1083 **RUTH RICHARDSON**...*RESIDENTIAL*
1095 **LAMON COOK**...*RESIDENTIAL*
1148 **DON HALE MATERIAL HANDLING**

2000 NORTH ST E

SOURCE: DIGITAL BUSINESS DIRECTORY

50 **BUFFALO HEARING & SPEECH CTR**
186 **CITY HONORS SCHOOL**...*PUBLIC ELEMENTARY AND SECONDARY SCHOOLS*

1995 BEST ST

SOURCE: HAINES



BERYL DR
X LUCID DR
BEST 14209 BUFFALO
WEALTH CODE 0.5
EAST FROM 1119 MAIN
X SUMMER
X MAIN
X ELLICOTT
X WELMONT PL
X MICHIGAN AV
ZIP CODE 14204
WEALTH CODE 0.0
X MASTEN AVE
X PEACH
X GRAPE
X JEFFERSON AVE
ZIP CODE 14208
WEALTH CODE 0.0
X EARL PL
X HIGH
X PERSHING AV
X TIMON
X ROEHRER AV
BEST 14208 CONT.
X WOHLERS AV
X LINDEN PK
X NORWAY PK
X SHERMAN
X KENSINGTON EXWY
ZIP CODE 14211
WEALTH CODE 0.0
X FOX
X HERMAN
X WEST PARADE AVE
X GUILFORD
X ELM
X RICH
X SWEENEY
X FILLMORE AVE
BEST 14006 ANGOLA
WEALTH CODE 2.0
BEST 14075 HAMBURG
WEALTH CODE 5.8
X MEADOW LN
COPYRIGHT HAINES & CO., IN

1995 ELLICOTT ST

SOURCE: HAINES



ELLER AV
ELLICOTT
ELLICOTT N
X SENECA
X SWAN
X BEST
ELLICOTT 14203 BUFFALO
WEALTH CODE 0.0
NORTH FROM 74 SENECA
X SOUTH DIVISION RD
X NORTH DIVISION RD
X EAGLE
X CLINTON
X BROADWAY
X WILLIAM
X EAST MOHAWK
X HERSEE AL
X HURON
X GENESEE
X EAST CHIPPEWA
ZIP CODE 14209
WEALTH CODE 0.0
X ST PAUL
X BEST
X EDNA PL
X DODGE
X COE PL
X SOUTHAMPTON
X NORTHAMPTON
ELLICOTT 14006 ANGOLA
WEALTH CODE 1.8
X MONROE
X MADISON AV
X JEFFERSON AV
X ADAMS AV
X KENNEDY AV
X EISENHOWER AV
X DAWN AV
X RILEY
ELLICOTT N 14221 WILLIAMSVILLE
WEALTH CODE 6.2
X MAIN
X SWAN PL
X FRANKLIN
X EAGLE
X BELMON
X EDWARI
X CHALM
X STANT
ELLICOTT S WILLIAMSVI
WEALTH CO

INFORMATION ON THIS PAGE MAY NOT BE KEYPUNCHED, ENTERED INTO A COMPUTER OR PHOTOCOP

1995 GOODRICH ST

SOURCE: HAINES

GOODRICH 14203
BUFFALO

EAST FROM 1005 MAIN

X MAIN

26 XXXX 00

X ELLICOTT

80 ★BUFLO GEN HSP PSYCH 845-2902 +5
★GRASER HAROLD P MD 845-2656
★KO HAK J MD 845-2163 +5
★RAFFERTY GEORGE MD 845-2935 +5
★WILLIS DANIEL J MD 845-2656 4

82 XXXX 00

112 ★PROGRSV HOME CARE 845-3780 +5
★PROGRSV HOME CARE 852-0284 +5

X ELM

★ 7 BUS 2 RES 5 NEW

1995 MICHIGAN AVE

SOURCE: HAINES



MICHIGAN AV — BUFFALO

MICHIGAN AV 14203 CONT
CARTER Maggie 856-6378 0
CAVER Edith 854-1001
CHAMBLEY E M 855-0712 2
CHEATHAM Edward 854-8779 4
COLEMAN W M 842-1869 9
COLVIN Dora 852-1891 2
COOPER Ann E 856-8626 +5
CRAION Allen 852-5872 +5
CUMMINGSREID D 854-0714 2
DAVENPORT Irene 856-9438 +5
DAVIS B 854-9719
DAVIS Ernest 854-1741 2
DAVIS Estelle 847-1415 9
DAWSON I 856-8915 +5
DAY E R 854-3204 3
ESTARFAA K 854-6455 3
FEASTER Agnes 854-6438 9
FOSTER D 855-3475 +5
GIST Garfield R 847-6906 3
GONZALEZ Ada M 849-0426 +5
GREGORY Leroy 856-0571
GRICE Thomas 849-0477
HALL Hattie 856-9071
HARRIS I 855-2044 3
HAYNES William 842-6987 4
HILSON Eugene 856-8688 2
HOOGE E M 852-4779 8
HOWARD Alberta 852-0124 0
HOWARD C 849-0096
JACKSON A B 847-1142 2
JACKSON D M 853-4266 0
JAMES J 856-7455 4
JOHNSON Andy Sr 842-6306 +5
JOHNSON T 854-3123
JONES L D 855-1320 +5
JONES Louise 856-7004 2
KELLEY Albert E 852-7831 2
KING I 847-0161
KING P 854-6353 2
LAWSON Arthur J 856-6358 +5
LEWIS J 852-9742 4
LEWIS L 854-2670 0
LEWIS Robert 856-7593 1
LINDEN O Mrs 856-0088 9
MITCHELL Thedo 856-1285
MOON Pauline 847-0914 9
MOORE L 852-2991 1
OVERTON A B 852-7342 2
PALMER Samuel 852-1651 6
PEAK Lillie Mae 856-3815 3
PEAKE L 856-7707
PRICE C 854-1079 6
PRICE Rose 852-6745 2
RAY Annie 847-1793 1
REDMOND Nadine 852-7145 4
REID William 852-3618 1
RIPPY Kenneth A Rev 856-3612
ROBINSON I 852-2688 1
ROBINSON M 852-0876 9
RODDY Donald 854-7832 3
SHAW E 856-8550 2
SHEARIN Jessie 857-7060 2
SHEARIN Jessie 856-7060 +5
SIMPKINS L 856-4989 1
SLAUGHTER S 854-0814 1
SMITH Kenneth Leroy 852-7634
★ST JOHN TOWERS 855-1505
STONE Alfonso J 852-4790 +5
SWAIN Jessie 845-6318 2
SWAIN N 856-6918 4
TALTON E 852-3249 9
THOMAS M 852-1034 9
THOMAS R 856-0198
THOMPKINS Bobbie 856-7938 9
THOMPSON Eugene R 856-5937 2
THOMPSON Zenobia 856-6225
TINKER Alberta 847-2479 +5
TURNER J 856-5479
WALKER Hazel 856-8499
WALLACE Inez 847-1610 2
WATSON Serless 847-1413 8
WHITE E 855-2457
WILLIAMS B 842-1013
WILLIAMS R 847-6994 +5
WOOD A 852-3844 2
WRIGHT Cartella 845-0099 0

865
866 GADDY Alice M 853-7549
868 XXXX 00
870 HARRIS R 842-1327 +5
872 XXXX 00
874 XXXX 00
876 XXXX 00

X VIRGINIA
897 ★CALLOWAY K 842-0307 6
907 ★KEMPKER Wm 856-8355
909 HILL Freddie 855-3147 4
913 XXXX 00
917 ★GIBSON Cynthia A 856-1878
GIBSON Jas E 856-1878
921 XXXX 00
925 XXXX 00
927 XXXX 00
939 XXXX 00

X CARLTON
955 XXXX 00
967 ★REED Mamie 884-0760
975 XXXX 00
977 XXXX 00
983 COUNCIL George 881-6943 3
LEWIS Joe 884-8931 +5
987 XXXX 00
989 THOMPSON Frank 884-1122
993 ★ROSS Samuel 884-1810
995 XXXX 00
997 XXXX 00
1001 XXXX 00

X HIGH
1027 XXXX 00
1029 XXXX 00
1031 ★MACKIE Arthur J 882-2480
1033 XXXX 00
1035 XXXX 00
1039 MORRIS T 881-2507 +5
1043 XXXX 00

X GOODRICH
1045 XXXX 00
1049 GLOSTER Richard 885-3298

ZIP CODE 14209

WEALTH CODE 0 0

X E NORTH
1076 XXXX 00
1079 XXXX 00
1083 RICHARDSON Ruth 885-6784
1087 XXXX 00
1091 XXXX 00
1095 COOK Lamon 886-0025 +5
1107 XXXX 00
1119 XXXX 00

X BEST
1137 XXXX 00
1141 XXXX 00
1144 ★BEST AUTOMOTIVE SRV 885-1121 7

MICHIGAN AV 14209 CONT
1145 XXXX 00
1148 ★DON HALE MTRL HNDLG 885-6951 0
1149 XXXX 00
1157 COOLEY Vivian 882-2507 +5

X EDNA PL
1164 XXXX 00
1170 COLLINS Gloria 881-0456 +5
★NEAL P M 883-0851 1
1172 ★WARREN Fred 886-5637 4
1173 XXXX 00
1174 ★BROWN Sam 883-1217
1184 ★BEULAH CH&HOME SNTS 882-5180 +5
1188 XXXX 00

X DODGE
1199 XXXX 00
1202 XXXX 00
1203 XXXX 00
1206 WRIGHT Kirby 886-5899 +5
1207 GUESS James N 883-2278
1208 ★SALTER Louise M 885-3917
1209 XXXX 00
1214 KELLAM Harold F 884-8565
PRICE James W 881-3039 1
1215 XXXX 00
1218 HAMILTON Willie 886-1615 1
JACKSON C 882-6456 +5
1220 XXXX 00
1221 ★ST MARKS CH GOD 881-3097
1233 XXXX 00

X SOUTHAMPTON
1236 ★DIXON Mckinley M 882-3945
1237 XXXX 00
1239 XXXX 00
1241 DOCKETT Gertrude 886-1434 +5
1242 ROGERS Hebron Jr 886-7327 +5
1243 XXXX 00
1244 AKBAR Shahad 881-1073 4
MCMILLAN Curtis A 881-6491
1245 XXXX 00
1248 XXXX 00
1249 XXXX 00
1255 HALL Norman 883-8649 2

X NORTHAMPTON
1263 XXXX 00
1269 DOUGLAS John A 886-5105
1279 EDWARDS Lynette E 886-2063 +5
1288 XXXX 00
1289 XXXX 00
1292 BLUE Jas 885-0716
1296 XXXX 00

X EATON
1298 CAGGINS Dessie 883-0381
TONEY Marvin Jr 886-5526 +5
1301 XXXX 00
1302 XXXX 00
1303 XXXX 00
1304 ★PATTERSON Henry 885-4177 1
1305 SHELTON Samaria 886-4266 +5
1307 ★HARRISFREEDMAN 884-6104 +5
1309 XXXX 00
1311 XXXX 00
1312 XXXX 00
1314 JENKINS Corrine 883-3317
1327 ★CARY AUTO SVCE 886-9312

X RILEY
X LAUREL
1364 KING N G 881-1276 1
1365 JONES J 886-7494
1366 HAIRSTON Wanda 883-9859 4
1368 XXXX 00
1370 BEDFORD Johnny C 884-3119 0
BEDFORD Wilson M 882-1116
1371 XXXX 00
1372 COLEMAN Annie 886-3523
HALL J 886-4179
1373 XXXX 00
1375 XXXX 00
1377 XXXX 00
1380 XXXX 00

X E UTICA
1399 XXXX 00
1400 XXXX 00
1407 BURDETT S 881-6165 3
1407½ AVANT A 884-1223 3
1409 ANDERSON Shirley 883-5484 3
1410 XXXX 00
1411 XXXX 00
1415 XXXX 00
1416 XXXX 00
1420 ★INTL EXTERMINATORS 884-5710 3
1421 XXXX 00
1423 HARVILLE E 882-8536 +5
1427 XXXX 00
1429 XXXX 00

X GLENWOOD AVE
1436 ★OS STORE 884-2977 4
1439 XXXX 00
1440 XXXX 00
1450 ★NELSONS ATO RPR&PNT 881-6813
1451 XXXX 00
1460 XXXX 00

X EMERSON PL
1461 ★ANTIOCH FSH CHURCH 883-6580 +5
1464 SHINGLES Willie 885-0724
1466 HARDY Jermaine 885-1217 +5
LESTER Margaret 886-3127 +5
1470 BANKS M L 881-3217
NEELY Relerford 883-1528

X WOODLAWN AVE
1504 XXXX 00
1506 XXXX 00
1516 FIELDS David 883-9228
1518 XXXX 00
1520 XXXX 00
1525 ★BETHEL AME CHURCH 886-1650
★BETHEL AME FED CRDT 882-2997 3
★BETHEL HEAD START 876-0226 4

X E FERRY
1571 XXXX 00
1581 ★NIAGRA FRNTR TRANS 855-6519 9

X MAIN
X HARVARD PL
NO # ★BUFLO CTY WRKS BRDG 851-5698 0
★ 64 BUS 296 RES 46 NEW

MICHIGAN AV S (91)
14203 BUFFALO

54 BUILDING
★GENL MILLS ELEVATOR 857-3655 1
★GENL MILLS EMPLYMNT 857-3506 1
★GENL MILLS ENGRG 857-3528 4
★GENL MILLS GEN INFO 856-6060 1
★GENL MILLS HEALTH 857-3501 1
★GENL MILLS HMN RSRC 857-3548 1
★GENL MILLS INS CLMS 857-3576 1
★GENL MILLS MATERIAL 857-3612 1
★GENL MILLS MILLING 857-3639 1
★GENL MILLS MNTNC 857-3555 1
★GENL MILLS MNTNC 857-3647 1
★GENL MILLS PACKAGNG 857-3579 1
★GENL MILLS PACKAGNG 857-3634 1
★GENL MILLS PAYABLE 857-3526 4
★GENL MILLS PAYROLL 857-3532 1
★GENL MILLS PROCESSG 857-3674 1
★GENL MILLS PURCHASG 857-3515 1
★GENL MILLS QLTY LAB 857-3543 1
★GENL MILLS QLTY LAB 857-3677 1
★GENL MILLS SECURITY 857-3506 1
★GENL MILLS SHIPPING 857-3606 1

MICHIGAN AV S
★GENL MILLS SHIPP
★GENL MILLS SHIPP
★GENL MILLS SHIPP
★GENL MILLS SHIPP
★GENL MILLS SHIPP
★GENL MILLS SHIPP
54
★ 27 BUS 0 R

MICHIGAN RD
JAVA VILLAGE

WEALTH CODE 2

4764 XXXX
4822 FEITSHANS Leon
4846 BARBER Raymon
4847 MAISCHOSS G D
4871 DAWSON Ernest
4891 XXXX
4920 XXXX
4921 XXXX
4997 XXXX
5005 CLAUSS Sally C
5028 ★FARRANT L
★HAPPY FBRS CI
5134 SPOYER Eugene
5399 GATH Paul E
5426 XXXX
5438 DRIVER Raymor
5448 CARLSON Davi
5463 STAMP Julian A
5483 FREYBURGER
5512 PAULY H
5579 FALCONER Go
5754 DAY Gordon
5798 ALMETER Anth
5808 HOFFMAN Ber
5887 JANDZINSKI L
6070 BARTZ William
RAMSEY Bill J
SETLOCK Will
NO # ★FREYBURGER
NO # PETERSEN P
NO # PRATT P
NO # WANNENWET
★ 2 BUS

MID COUNT
ORCHARD F

65 ★SOUTHTWNS
75 ★CHILDREN
★SOUTH TWN
★SOUTHTWNS
80 ★COCA COLA
100 ★CHEMLAWN
★TRUGREEN
★TRUGREEN
105 ★BUFLO CIR
115 ★AMES IRON
★FITZGIBBO
★INDSTRL C
★KISCO BOU
★MUIRHEAD
★WEBSTER
140 ★BISON DAT
★COMPTEK
145 ★MATRIX ME
★ 18 BUS

MIDDLE LN
ANGOLA

WEALTH

X SHO
45 ANDERSO
48 ★DOMSTER
49 XXXX
53 XXXX
61 ★CHIAVET
71 PEZZIME
72 PALMER
77 ★KORDAS
88 XXXX
89 LIBERATI
92 ★GOTTORI
GOTTORI
95 ★WISKOP
96 GZYL An
101 ★FORD W
102 XXXX
104 XXXX
112 ★REED GI
117 ★WHEELE
118 ★TRUBY
125 MULBUR
NO # KRIEGE
★ 0 BUS

MIDDLE
CHAFFEE

WEAL

12550 LARIVI
★ 0 BU

MIDDLE
EAST C

WEA

9525 RUSS
9582 APA
BALL
BETT
BIRIN
BRAN
DARL
JAME
LIGH
LUKE
MCC
MCC
MELI
ORN
PER
PRIN
STEI
STR
TIM
WEI
WIN
ZYB

9582
9589 LAN
LAN
9676 ★UNI
9776 DIC
9782 HE
9794 GA

1995 NORTH ST E

SOURCE: HAINES



NORTH 14141
SPRINGVILLE

WEALTH CODE 3.8

NORTH 14204
BUFFALO

WEALTH CODE 0.0

EAST FROM 1039 MAIN

NORTH E 14204 CONT..

NORTH 14211

WEALTH CODE 0.0

NORTH 14224
WEST SENECA

WEALTH CODE 4.0

1990 BEST ST

SOURCE: HAINES



BEST 14209 BUFFALO

EAST FROM 1119 MAIN

ZIP CODE 14211

ZIP CODE 14204

ZIP CODE 14208

BEST 14006 ANGOLA

BEST 14075 HAMBURG

BEST 14208 CONT..

BETHFOR
BLASDEL

BETHLEH
LACKAW

BETINA
AMHERS

BETTY L
CHEEKT

COPYRIGHT HAINES & CO., INC. INFO

1990 ELLICOTT ST

SOURCE: HAINES



ELLER AV 14211
BUFFALO
NORTH FROM
196 HEMINWAY

X HEMINGWAY
1 SUSZCZYNSKI J A 896-2553 9
2 XXXX 00
5 SLOANE I John 896-8233
6 COUTO A C 893-5664 +0
HOLMWOOD J M 892-1255 9
7 CRUMLISH J 897-1899 9
8 MORELLA Kevin 891-4239 9
11 WIELOSZYNSKI D 892-8505 +0
WIELOSZYNSKI Jay 892-8505 +0
12 NADOLNY M J 896-0001 6
14 LIEBLER Walter Jr 894-4378
15 BLESS R F 892-6242 7
CARON V F 895-4642 8
17 DAVLIN Lavelle 895-5268 8
HIGGINBOTHAM N 893-2181
18 ZIMMER Chas A 893-5899
19 OSENKARSKI William 895-1440
20 SCHWEITZER Geo 893-1501
23 BRADER Harry R 892-2745
24 LOS A 892-6383 3
25 STINSON John 893-1395 3
26 RYBAK Donald 891-5909 6
27 XXXX 00
30 STREICHER Paul R 894-9216
31 TOMASZEWSKI John A 895-2342 +0
32 SCHNEIDER Franklin 893-3332
33 CHRUSCICKI E 892-0002 3
WOJTKOWIAK Florian 895-5458 2
36 MURPHY Robert E 897-3906
37 XXXX 00
38 WOOD D F 896-3729
39 BEBACK Ronald 893-7643 7
LYSIAK Henry P 892-7298 3
41 XXXX 00
42 HOERNER Catharine 895-7526
44 JEDD Raymond 894-3047 8
47 MASTANDREA Vincent 897-1232 3
48 BAKER Ernest 892-3586
BAKER M 895-0431 9
49 XXXX 00
50 LEGGIO S 895-4459 8
SMITH M 895-2752 +0
51 ZIOLKOWSKI Alex 895-0934
53 PORTER E 892-9201 +0
56 PAJAK Jerome 894-4566
57 GERLACH Bernard 895-6447
ZYGLIS Wayne 896-0447 9
58 WOJCIK James J 895-0321 9
60 OLSZEWSKI M 896-1458 7
61 KELLY Timothy J 894-4348 2
62 OLEARCZYK John 894-6760

X YONKERS
65 JANUSZ Richard J 897-2239
67 RUPER B 894-0069 +0
71 BUCKLEY Peter 896-1137 5
72 KURZDORFER Leon J 895-5943
73 HEUBUSCH K 894-9049 9
76 MCILVENE Thomas 896-8602 6
77 OLEKSY David D 892-8216 8
78 SNYDER Charles P 893-6956
81 XXXX 00
82 BENNETTREY B 894-6163 9
REY James R 894-6163 8
85 ZAPKA August 892-1833
86 ESENWEIN J W 896-5195
89 BURKE M 896-1139 +0
91 PAWLACZYK Henry 895-6165
92 XXXX 00
94 HURLEY Edward 894-0089 3
95 XXXX 00
97 XXXX 00
98 XXXX 00
99 VALENTINE James P 894-6508
100 RADZIKOWSKI Leon 897-4006
RADZIKOWSKI Raymond 895-2739
103 WYZANOWSKI Henry C 893-9184
104 ZISKOWSKI C 892-7348
105 GIMBRONE Carmen 895-2809 6
106 PTAK Stevie 895-9434 1
109 XXXX 00
110 KEEFE Daniel J 894-9657 8
111 CHIARMONTE Joseph S 895-6029 +0
114 PIATEK Joseph S 893-8447
115 SNIATECKI Jerome P 891-5464 1
119 SCHARMACH Edw 896-0436
120 CHROSTOWSKI D 894-1736 5
121 SZYMANKIEWICZ Edw 894-0527
126 ALESSI Daniel 894-7603 6
127 XXXX 00
129 XXXX 00
133 MOEHRLE Paul 892-4178
134 XXXX 00
137 BUTTS Clarence G 895-3592
139 KRZEMINSKI David 892-7024 +0
MCCABE Charles 3D 896-3536 9
144 RUHLAND Ted 892-9228

X GENESEE
* 0 BUS 95 RES 10 NEW

ELLICOTT 14203
BUFFALO
NORTH FROM
74 SENECA

X SENECA
74 XXXX 00

X SWAN
121 *ERIE CO CLG CMPS 842-2770 3
*FACULTY STDNT ASSOC 842-6408 +0

X SOUTH DIVISION RD
X NORTH DIVISION RD
181 BUILDING
*ALEXANDER TOUR&TRVL 852-1780 +0
*BLUE BIRD COACH LNS 855-7811 3
*BURGER KING RSTRNT 856-0342
*CANADA COACH LINES 855-7511 3
*GREYHOUND BUS AGENT 855-7531 +0
*GREYHOUND BUS BAG 855-7526
*GREYHOUND BUS CHRTR 855-3519 +0
*GREYHOUND BUS DLVY 855-7529 2
*GREYHOUND BUS PCKG 855-7524
*METROBUS CHRTR SERV 855-7527 5
*METROBUS COMPLAINTS 855-7227 5
*METROBUS INFO 855-7277 7
*METROBUS INFRMTN 855-7211 5
*METROBUS INVSTGN 855-7906 5
*METROBUS PERSONNEL 855-7338 7
*NIAGRA FRNTR TRANS 855-7211 5
*NIAGRA FRNTR TRANS 855-7363 7
*NIAGRA FRNTR TRANS 856-2026 7
*NIAGRA FRNTR TRANS 855-7300 7
*NIAGRA FRNTR TRANS 855-7277 7
*TRAILWAYS BUS SYSTM 852-1750 4
*TRAILWAYS BUS SYSTM 856-8885 4
*TRAILWAYS TOUR SV 847-1755 2
181
187 XXXX 00
189 XXXX 00

X EAGLE
210 *SENECA PAPER 854-6864 3

ELLICOTT 14203 CONT.

X CLINTON
X BROADWAY
X WILLIAM
285 *STANFORD DSPLY STDO 852-8060
298 *B&G REFRIGRATN 856-9300
300 MOLLE Patrick 856-7655 +0
PLATT Richard 854-1760 4
SCHEUER R 849-0848 +0
301 *EMULSO CORP 854-2889
303 *ELLICOTT MOHAWK SRV 855-9376
*MATTIOLI PARKING 854-9864

X EAST MOHAWK
X HERSEE AL
321 XXXX 00
332 *BUFLO FIRE INFO 842-1111 2
333 *FERGUSON ELEC CONST 852-2010
*FERGUSON W JR 852-2010
338 *HORTON COFFEE CO 854-1177
350 XXXX 00

X HURON
365 XXXX 00
367 *BRUNNER SIMON ELEC 852-3824
*HURONELL CORP 852-3824
*METALIZING CO BUFLO 852-3824
SIMON Bert 842-6484 4
*SIMON BERT 852-3824
*SIMON ELECTRIC CO 852-3824
*WILBERT CONST CO 852-3824
369 *STERNS ELEC INC 854-0194
371 XXXX 00
379 *CELLULAR TELE WNY 852-1968 7
381 XXXX 00
393 XXXX 00
395 XXXX 00

X GENESEE
X EAST CHIPPEWA
419 XXXX 00
423 XXXX 00
427 XXXX 00
431 XXXX 00
433 *NIGRELLIS FRT&VGTBL 852-7578
*TOMS FRUIT&VEGETBLE 852-7578
435 *COMBAT VETERANS A C 855-1480 5
437 *GOLDEN SWAN TAVERN 855-9785 2
WIDLAK Edward S 855-1875 2
439 *GREAT PRESENTATIONS 855-2255 7
*HASTINGS MARKG DEVC 852-6640
*KENSINGTON MARKING 852-6641 7
445 XXXX 00
455 *BUGENHAGEN R DVM 852-8276 7
*CRITTER CRTN PT SLN 852-0831 +0
*ELLICOTT SMALL ANML 852-8276 1
*FENICHEL J E DVM 852-8276 +0
*GERARD DAVID G 856-0353 5
*MCCLELLAND VET HOSP 852-8276
*OLEARY TIMOTHY DVM 852-8276 +0
*YARTZ FRANKLIN DVM 852-8276 1
461 XXXX 00
475 *WEHLE ELCTRNCS INC 854-3270
*WEHLE ELEC CO 854-3270
477 XXXX 00
481 *J H W WHSL FLORIST 855-1651 9
501 XXXX 00
511 XXXX 00
519 XXXX 00
520 XXXX 00

X EAST TUPPER
567 PIZZUTO Joseph A 845-6483 3
RISCEN D 852-2827 +0
587 XXXX 00
596 *EASTMAN LSNG CORP 855-0555 9

X GOODELL
X BURTON
674 *ULRICH RESTRNT 855-8409

X VIRGINIA
X CARLTON
752 XXXX 00
760 *ST JUDE CENTER 882-2987
ULASZESKI Edw J Rev 882-2987
766 *AMER LUNG ASSN 886-4655
*AMER LUNG ASSN 883-5864 5
*ASTHMA AMER LUNG 886-4655
*CHRISTMAS SEALS 886-4655
*EMPHYSEMA AMER LUNG 886-4655
*LUNG ASSN OF WNY 886-4655 3
770 XXXX 00
774 XXXX 00
782 *KEVIN HOUSE 882-1818 5
788 *BUFLO MEDICAL GRP 886-6915 +0

X HIGH
X GOODRICH
X E NORTH

ZIP CODE 14209

903 XXXX 00
X ST PAUL
929 XXXX 00
935 XXXX 00

X BEST
967 *P&R WIRE FORMING 883-6644
969 XXXX 00
980 *DAUGHERTY GERALD L 882-5740 3
*OSMOSE WOOD PRSRVG 882-5905
*SURDAM JOHN L 882-5905
*TIMBER SPCLTYS LTD 882-2137 9

X EDNA PL
991 JACOBS Eugene 886-4503
996 XXXX 00
997 SHAW Vernon 885-1977
1000 XXXX 00
1001 XXXX 00
1002 XXXX 00
1007 *CALVARY CHRSTN METH 881-6947 6
1010 XXXX 00

X DODGE
1040 XXXX 00
1042 BONO Andrew J 886-3541 5
1044 ANDREWS E J 882-0187 4
1047 XXXX 00

X COE PL
1050 XXXX 00

X SOUTHAMPTON
1058 BROWN Donna 882-3704 +0
1060 XXXX 00
1061 GREEN Thomas 884-4633
1062 FOSTER James 883-0012 +0
1063 XXXX 00
1066 XXXX 00
1068 GRANT John 883-4035
1070 XXXX 00
1072 GRANT Fannie V 883-2885
WALLACE Inez 886-7371 9
1075 XXXX 00

X NORTHAMPTON
1084 XXXX 00
1087 *JOHNSON G 886-6140 6
1088 MONTGOMERY Earl 884-3899
1101 COBBS E 886-0879 9
1102 COLEMAN S 881-2940 +0
1109 LEE Hosley Jr 883-8802 6
1113 WILLIAMS Wilbert 884-9318
1117 WARD Ray 886-8009 7

1990 GOODRICH ST

SOURCE: HAINES



GOODRICH 14203
BUFFALO
EAST FROM 1005 MAIN

X MAIN
26 XXXX 00
X ELLICOTT
80 *COMNTY ACTION DART 853-0350
*GRASER HAROLD P MD 845-2656 2
82 XXXX 00
112 XXXX 00
X ELM
* 2 BUS 3 RES 0 NEW

Report ID: 23022300643 - 03/01/2023
www.erisinfo.com

1990 MICHIGAN AVE

SOURCE: HAINES



1990 NORTH ST E

SOURCE: HAINES



1985 BEST ST

SOURCE: HAINES

BERRYWOOD AV 14006
ANGOLA

BERTHA PL 14220
BUFFALO

NORTH FROM
1320 SOUTH PARK AV

BERWIN DR 14226
SNYDER

BERWYN AV 14215
BUFFALO

EAST FROM
384 OLYMPIC AV

BERYL DR 14225
CHEEKTOWAGA

BEST 14209 BUFFALO
EAST FROM 1119 MAIN

ZIP CODE 14204

ZIP CODE 14208

ZIP CODE 14211

COPYRIGHT HAINES & CO., INC. INFORMATION ON THIS PAGE MAY NOT BE KI

1985 ELLICOTT ST

SOURCE: HAINES

ELLICOTT 14203 BUFFALO

NORTH FROM
74 SENECA

ELLICOTT 14006 ANGOLA

ELLICOTT N 14221 WILLIAMSVILLE

ZIP CODE 14209

COPYRIGHT HAINES & CO., INC. INFORMATION ON THIS PAGE MAY NOT BE KEY

1985 GOODRICH ST

SOURCE: HAINES



0 BUS 5 RES 0 NEW

GOODRICH 14203
BUFFALO

EAST FROM 1005 MAIN

MAIN
XXXX 00
ELLICOTT
CHILD&ADLSCNT CLNC 856-9753 2
COMNTY ACTION DART 853-0350 8
GRASER HAROLD P MD 845-2656 2
JOSEPH BRIAN S MD 845-2658 3
COWPER TURNER ARCHT 842-6530 4
COWPER TURNER VENTR 842-6220 4
XXXX 00
APARTMENTS
BRITZZALARO T M 856-9632 +5
FORBES C 856-0774 +5
MESLIN L 854-1355 +5
JANIS S 847-2134 +5
KOSTRZEBSKI B 856-7264 +5
MCKNIGHT K 856-6590 +5
PUSCIO CHRISTINA M 852-6626 +5
SEMLITSCH A M 856-7137 +5
SENIOR M K 856-2870 +5

ELM
6 BUS 11 RES 9 NEW

GOODRICH

1985 MICHIGAN AVE

SOURCE: HAINES



BUFFALO

MICHIGAN AV 14203 CONT

CAVER EDITH 854-1001 4
CAWTHON A E 842-0579 3
CHERRY CLEVIE 842-6949 4
COKER MATTIE J 856-7435 4
CREWS F 856-8037 3
DAVIS T R 854-9719 4
DICKSON M M 856-2943 3
EDMONDS LULA 856-6921 3
ELSTON HOWARD 856-2479 +5
ENGLISH B 856-1078 3
FINCH P 856-0680 3
FLULLEN BETTY ANN 849-0530 3
GARRETT A B 847-1247 4
GREGORY LEROY 856-0571 3
GRICE THOMAS 849-0477 4
GRIGGS M V 856-0467 3
HALL HATTIE 856-9071 3
HANCOCK E 842-1127 3
HARRIS M 856-4088 3
HILSON S 847-1714 4
HOWARD C 849-0096 4
IVORY J 852-4295 +5
JACKSON ARTHUR 856-1868 4
JACKSON WILEY 856-6750 +5
JOHNSON T 854-3123 3
JOHNSTON JAMES R 856-4328 3
KING ANNIE REV 856-9097 4
KING T 847-0161 3
KING T 842-0021 3
KIRKLAND GAVIN 852-7156 +5
LACEY R 856-3586 3
MAHMOOD SLEIMAN 854-1802 +5
MARTIN JAMES HOWARD 842-0106 3
MAULDIN BESSIE M 855-2460 +5
MCDANIELS ALEXANDER 842-6140 3
MCGARRAH M M 854-8868 3
MITCHELL C 856-3971 +5
MITCHELL THEDO 856-1285 3
MOORE ALVIN 856-4198 3
MORGAN WILLIE 847-1677 3
MORTON M E 842-6743 3
OVERTON R 856-4882 4
PEAKE L 856-7707 4
PEGUES J E 842-2296 +5
PERKINS EVA 856-1227 3
PORTER E 854-3773 +5
POWELL RHODA 856-1947 3
READ HAROLD T MRS 842-0271 4
REESE JAMES 855-1699 3
RICHARDSON JULIUS 856-9217 4
RIPPY KENNETH A REV 856-3612 3
RIVERS ZANNIE 856-0260 3
RUCKS MARY LOUISE 842-1162 3
SAVAGE WILLIE MAE 855-1016 3
SCHIENER CLARA M 852-3875 3
SHEARIN J 852-0450 3
SHIELDS GUSSIE 852-7870 4
SIMS BESSIE BELL 855-1891 4
SMITH DAVID 856-8958 3
SMITH EDWARD 856-5086 3
SMITH HARVEY L 856-7488 3
SMITH KENNETH LEROY 852-7634 +5
STAFFORD MEALLO 856-4316 3
ST JOHN TOWERS 855-1505 3
SWAIN N 856-6918 3
THOMAS R 856-0198 4
THOMPSON ZENOBIA 856-6225 +5
THORNTON ANNIE MAE 856-5077 3
TURNER J 856-5479 3
TURNER NADINE 854-3795 3
VAUGHN ROBT 856-2570 4
WALKER ERNESTINE 856-4885 3
WALKER HAZEL 856-8499 3
WEBSTER M 852-3507 +5
WHITE E 855-2457 +5
WHITE LEE A 842-0827 3
WILLIAMS B 842-1013 3
WILLIAMS I 842-0528 4
WILLIAMS JOHNNIE 847-6678 3
WILLIAMS JOSEPH 842-1967 4
WILLIAMS LAWRENCE 842-2295 4
WILSON ALICE 847-0861 3
WILSON M E 842-1837 3
WRIGHT M 847-0682 +5

865
866 GADDY ALICE M 853-7549
PITTS J M 854-3138 4
868 XXXX 00
870 XXXX 00
876 MARCHANY M 849-0251 4
X VIRGINIA
907 KEMPKER WM 856-8355
909 JONES M E 856-5890 2
913 KENNEDY JAMES 847-0846 3
PATTERSON S REV 854-5918 +5
915 JACKSON LILLIE B 854-7191 +5
917 GIBSON JAS E 856-1878
921 XXXX 00
925 XXXX 00
927 XXXX 00
939 XXXX 00
X CARLTON
955 XXXX 00
967 REED MAMIE 884-0760 4
975 XXXX 00
977 XXXX 00
983 COUNCIL GEORGE 881-4130 +5
987 XXXX 00
989 THOMPSON FRANK 884-1122
993 ROSS SAMUEL 884-1810
995 XXXX 00
1001 XXXX 00
X HIGH
1027 XXXX 00
1029 XXXX 00
1031 MACKIE ARTHUR J 882-2480
MURRAY ELLA M 885-6937
1033 XXXX 00
1035 XXXX 00
1039 KIRKWOOD FRANK C JR 883-2363 9
STORY IDOTHA 881-7094 +5
1043 XXXX 00
X GOODRICH
1045 XXXX 00
1049 GLOSTER RICHARD 885-3298 2
THOMAS L 886-4767 4
1053 MOORE G 886-6595 4
1057 HORTON D J 883-3606 +5
1059 XXXX 00
1061 XXXX 00
1065 TRAUTMAN GERTRUDE 883-9349
1069 SCOTT HENRY 886-2820 6

ZIP CODE 14209

X E NORTH
1075 WHITE M 886-6586 +5
1079 WRIGHT EARNEST 882-1718 9
1083 RICHARDSON RUTH 885-6764 +5
1091 COOK LAMON 886-0025 9
1095 XXXX 00
1098 XXXX 00
1103 GRAVES E 884-3026 3
1107 XXXX 00
1111 SAVAGE AGNES JONES 886-3794 +5
1119 MANN J L 886-3521 9
1127 FERGUSON P 884-0714 3
X BEST
1137 XXXX 00
1141 XXXX 00
1144 MOYNIHANS COLLISION 881-1957
1145 XXXX 00
1148 TUTTON ELECTRIC CO 884-7686

MICHIGAN AV 14209 CONT

1149 XXXX 00
1157 COOLEY EXCELL 881-2581
COOLEY HATTIE M 881-2581
X EDNA PL
1164 XXXX 00
1165 XXXX 00
1166 XXXX 00
1167 XXXX 00
1170 NEAL AUSTIN 883-0461
1171 XXXX 00
1172 BROWN CHARLES 881-1943 +5
JOHNSON EZEL 885-1635 +5
WALL C 885-1873 +5
1173 GARRY LOUISE 884-9252
1174 BROWN SAM 883-1217
1175 XXXX 00
1176 XXXX 00
1183 XXXX 00
1184 BEULAH CH&HM CHRIST 881-6126 4
1187 XXXX 00
1188 FARRIS B 881-0959 1
1189 EARNEST&CARRIES MKT 884-8442
X DODGE
1199 BRADLEY R 885-2773 +5
1202 XXXX 00
1203 TAFF C 882-7895 3
1206 DOCKETT GERTRUDE 886-1434
1207 GUESS JAMES N 883-2278 9
1208 SALTER LOUISE M 885-3917
1209 XXXX 00
1214 KELLAM HAROLD F 884-8565 3
1215 FELDER B 881-5711 3
1218 BENSON CHAS 886-2222
WILLIAMS DAVE 882-0741
1220 XXXX 00
1221 ST MARKS CH GOD 881-3097 0
1233 XXXX 00
X SOUTHAMPTON
1236 DIXON MCKINLEY M 882-3945
1237 JOHNSON LILLIE 882-9543
1239 JONES MILTON H 881-4027
1241 XXXX 00
1242 XXXX 00
1243 XXXX 00
1244 COOPER E 884-8213 2
MCMILLAN CURTIS A 881-6491
1245 XXXX 00
1248 XXXX 00
1249 HOPKINS BEVERLY 881-0397 6
ROBINSON TONY W 884-5790 4
X NORTHAMPTON
1263 JACKSON D 883-4185 4
1265 RUBYS BEAUTY LOUNGE 885-8030 4
1269 DOUGLAS JOHN A 886-5105 2
1288 DIXON JAMES 884-6484 4
1289 XXXX 00
1292 BLUE JAS 885-0716
1296 XXXX 00
X EATON
1298 CAGGINS DESSIE 883-0381
SMITH JOHN H 882-3106 +5
1301 XXXX 00
1302 BURTON JOHNIE 881-5579 6
1303 XXXX 00
1304 XXXX 00
1305 SMITH LARRY L 881-5647 +5
1309 XXXX 00
1311 XXXX 00
1312 XXXX 00
1314 JENKINS CORRINE 883-3317
1315 XXXX 00
1316 XXXX 00
1318 HUDSON ALLEN E 885-0976
1319 XXXX 00
1321 XXXX 00
1323 PUGH WADE 885-3859
1325 XXXX 00
1327 CARY AUTO SVCE 886-9312
X RILEY
1331 XXXX 00
1337 KILLEBREW JOHN L 886-2068
1339 XXXX 00
1341 XXXX 00
X LAUREL
1363 XXXX 00
1364 COX MOZELLE 886-3579 0
MADISON EUGENIA 882-8526
1365 JONES J 886-7494 2
1366 HOLLOWAY P 882-0995 7
NEWMAN A 885-2409 4
1368 XXXX 00
1370 BEDFORD WILSON M 882-1116
1371 XXXX 00
1372 COLEMAN ANNIE 886-3523
HALL GEORGE 886-4179
1373 XXXX 00
1375 XXXX 00
1377 XXXX 00
1380 XXXX 00
X E UTICA
1399 ADAMS CHARLES 884-7437 +5
1400 XXXX 00
1407 XXXX 00
1409 XXXX 00
1410 XXXX 00
1411 BROOKS Z L 881-4552 +5
1415 HAMES ORA LEE 883-9492 1
STEWART R T 886-6492 1
1416 XXXX 00
1420 A 1 EXTERMINATING 691-5900 3
INTL EXTERMINATORS 884-5710
1423 WALKER L 882-8827 0
1427 XXXX 00
1429 XXXX 00
X GLENWOOD AVE
1436 GAMBINO DANL J 884-2977 1
WEBERS MKT 884-2977
1439 XXXX 00
1440 XXXX 00
1450 NELSONS AUTO REPR 881-6813 7
TUBOR INDUSTRIES 881-6236 +5
1451 XXXX 00
1460 BATCHELOR WALTER 882-8049 7
TANNER MABLE 885-8966
X EMERSON PL
1461 ANTIOCH F B H CH 881-4009 2
1464 SHINGLES P 884-9998 +5
SHINGLES WILLIE 885-0724
1466 CURRY D 882-3054 4
CYLAR S 883-2814 +5
1470 BANKS M L 881-3217 2
NEELY RELERFORD 883-1528
X WOODLAWN AVE
1500 XXXX 00
1504 SMITH RICKIE D 883-5099 +5
1506 XXXX 00
1510 XXXX 00
1512 SCOTT CHAS S SR 886-7268
1516 FIELDS DAVID 883-9226
1518 XXXX 00
1520 XXXX 00
1525 BETHEL AME CHURCH 886-1650
BETHEL CENTER 2 883-3569 3
BETHEL HEAD START 884-6631 +5
BETHEL HEAD START 882-6521 +5
X E FERRY
1571 XXXX 00
X MAIN
NO # BUFF CTY ENGR BRDGE 855-5698 2
NO # TOKYU CAR CORP 852-5640 4
62 BUS 338 RES 53 NEW

MID COUNTY
ORCHARD P
65 PROCESSING
WILCO MAC
75 SOUTH TWN
80 CHEMLAWN
CHEMLAWN
105 BUFLO CIRC
115 FRANCE HA
HAYDEN PRE
M G S
145 FRASER HA
9 BUS

MIDDLE LN
ANGOLA
45 ANDERSON
48 DOMSTER C
49 XXXX
53 ASCHBACH
61 EMMETT J C
71 PEZZIMENT
72 WITZEL KEN
77 KORDASIEW
88 PFEIFFER L
89 XXXX
101 FORD WILL
102 OHARA JOH
104 XXXX
112 REED GLEN
117 XXXX
118 XXXX
125 SCHULER F
NO # KRIEGER H
NO # TRUBY LEC
0 BUS

MIDDLE RD
CHAFFEE
12550 LARIVIERE
NO # NEAMON D
0 BUS

MIDDLE RD
EAST CONC
26 LAZELL ST
9075 PIWOWAR
9782 BETTINGE
9992 SIMINSKI
10320 TOMCZYK
10381 HASKINS
10629 DUNN LES
11509 HURLBUR
11779 HOPKINS
11945 EGOLIES
11949 SPENCER
11969 ROBLEE D
SPENCER
12059 BARR CL
NO # ALIANELL
NO # BALLANT
NO # CHERRY
NO # CLARK R
NO # COONS D
NO # CORDES
NO # DEGOLIE
NO # DEGOLIE
NO # DEGOLIE
NO # DEGOLIE
NO # DOMES
NO # EDWARD
NO # EVERTS
NO # FARR KE
NO # HARMAN
NO # HEARY J
NO # HERMAN
NO # HODSON
NO # HOPKINS
NO # IDZIK TH
NO # LAWTON
NO # MCCOO
NO # MEYER
NO # ORDIWA
NO # PERKIN
NO # PERKIN
NO # PERKIN
NO # PRESTO
NO # SCHROE
NO # SCHWE
NO # SMITH
NO # SMITH
NO # SZYMA
NO # TURRI
NO # WESTF
NO # WILLIA
NO # WULFF
0 BU

MIDDLE R
SARDINIA
11609 SAWCH
12510 FRASE
NO # HARTL
NO # HOCH
NO # MALIN
NO # MARTI
0 BU

MIDDLE
SPRINGV
8097 DAVIS
8399 KOZA
8423 FRAN
8435 SCHN
8668 KEST
KEST
8763 LIGH
8965 HEBD
8968 HAVE
8982 BRYA
9100 BACH
9111 HEBE
9131 HILL
9134 WIDE
9283 DEW
9358 WAL
9415 KNIC
NO # BIEH
NO # BOC
NO # GEN
NO # GRA
NO # HAU
NO # HOF
NO # JER
NO # JOH
NO # KIN
NO # LAN
NO # PAL
NO # SEI
NO # SHI
NO # VA
NO # WI
NO # WI

COPYRIGHT HAINES & CO., INC. INFORMATION ON THIS PAGE MAY NOT BE KEYPUNCHED, ENTERED INTO A COMPUTER OR PHO

1985 NORTH ST E

SOURCE: HAINES



NORTH 14075 CONT

83 GOULD ROYAL F 649-3946 8
84 HARRINGTON EMEROY 649-5013
87 CORBISHLEY M K 648-1499 1
88 BLINSTON MILES 649-2330
92 BURY V K 649-8678
93 LOOMIS ROBERT M 648-1797 3
98 MARINACCIO WILLIAM 648-5224 6
104 GARDNER RICHARD P 649-3251
108 CROSBY DONNA H 649-2460
114 MERRICK MICHAEL P 648-6834 3
124 JAYNE LLOYD S 649-4898
130 WEISS ROBERT J 649-0626 9
138 OSBORNE EDWIN J 649-5786 8
148 XXXX 00
151 KLUCKHORN THOMAS W 648-4874 3
158 HULEM ROBT A 649-8366
177 LIDDELL WILLIAM C 649-7326
* 0 BUS 42 RES 1 NEW

NORTH 14141 SPRINGVILLE

5 DIAZ JOSEPH 592-9427 4
9 MIHALIK JOHN 592-7419 1
12 CHURCH SCOTT P 592-9260 3
15 FAILEY OTIS G 592-7309 3
17 HESSE ELMER N 3D 592-2965 4
19 NELLIGAN J 592-4075 +5
21 KING THOMAS E 592-2291 8
22 WEBER MARK 592-7647 +5
29 SLAUGHENHAUPT C 592-7969 2
32 TALBOT ROBERT A 592-4077 +5
33 XXXX 00
36 HUTTON E M 592-4471 3
46 PRIEL NELSON 592-3819 6
106 **HOLLAND G DASONS 592-4852** 2
122 STURZENBECKER A 592-7474
132 GOODEMOTE LEON W 592-7855
140 DELISLE GERALD F 592-7707
154 FORRESTER GEO M 592-4315
180 GEIGER PAUL D 592-4939
211 ELLIS GORDON 592-4571
283 **SPRINGVL ELEMENTARY 592-3260** 4
8718 SHULTES G E 592-9262 2
8730 SCHMIDT FRED J 592-2669 2
8742 LINDSLEY HARRISON 592-3539
8796 **DAVE SNYDERS AUTO 592-4996** 3
KING THOMAS E CO 592-3130 1
SNYDERS D AUTO REPR 592-4996 4
8798 **SPRINGVL MFG CO 592-4957** 2
8992 THIEBOLT ARTHUR 592-7542 2
8996 KRAUSE GERALD W 592-4434 8
9000 BAKER C L 592-7805 3
J JS SMALL ENGINE 592-7789 3
9032 WHITE GLENN D 592-9405 4
9098 AHLES JOHN J 592-2162 3
9152 SIMINSKI EDWARD 592-9165 2
9170 FOLTS MARK F 592-3173 7
9230 EMERSON PARK APTS
BROWNE MARTIN M 592-9776 2
EMERSON PARK 592-2594 7
KNICKERBOCKER R 592-7446 +5
NEWMAN J 592-9410 3
OFFHAUS MARK H 592-3961 4
PALCIC FRANK J 592-4018 8
ROLAND THEODORE W 592-3047 +5
ROTHLEDER WILBUR E 592-9106 8
SMITHMEYER JOS JR 592-9933 4
VOLK EDW A 592-2568 7
WAITE DONALD T 592-2543 3
ZANKL L M 592-9489 9

9230
9260 HODY JOHN J 592-2008 1
9320 XXXX 00
NO # ARBOGAST JOHN H 592-3114
NO # BOSER MELVIN G 592-7574 2
NO # BOTSFORD ROBERT K 592-9526 2
NO # CONNOLLY RON 592-7887 2
NO # EVANS WM G 592-4796
NO # FARNER ROBT G 592-4837
NO # FARNER RONALD E 592-4396
NO # FILARECKI WM F 592-4403
NO # FULLER SHERWOOD 592-4888 4
NO # HIGBEE WELLMAN 592-2311
NO # HOUCH LAVERN 592-9258 9
NO # KAZMARK RAYMOND 592-7281
NO # KEYS CLYDE W 592-7521
NO # KRAUS R L 592-7082 3
NO # KREZMIEN LAWRENCE 592-2183 0
NO # KRUSE DON 592-4070 1
NO # LANEY WILLIAM C 592-4585
NO # LEAVELL JEFFREY W 592-9409 3
NO # MARZEC VICTORIA 592-2358 1
NO # MCCOOL DALE 592-4491 3
NO # MEYERS EARL 592-7374
NO # MRUGALA STANLEY J 592-4407
NO # OTT GILBERT 592-7235
NO # OTT RICHARD 592-3189 2
NO # OWEN LYLE E 592-2772
NO # READING RALPH 592-9360 4
NO # ROBBINS R 592-4839 4
NO # SCHUE JEFFREY 592-2648 8
NO # SCHWEJCKERT CHAS H 592-7007
NO # SEIDER CAM 592-4663
NO # SEIDER GARY 592-2280 4
NO # SEYMOUR FRANK E SR 592-2343
NO # SHERWOOD CLAIR C 592-4436
NO # SMITH TIMOTHY L 592-4758 0
NO # SNYDER DAVID 592-4780
NO # SNYDER RICHARD 592-4424 4
NO # STROKE D 592-4717 2
NO # TAFT M J 592-3192 8
NO # WILSON C A 592-7416 9
NO # WOHLHUETER LAWRENCE 592-2674
NO # ZIMMER CHARLES 592-3523 6
* 8 BUS 83 RES 5 NEW

NORTH E 14204 BUFFALO

EAST FROM 1039 MAIN

177 SUMLING ROBERT 886-3621
X MAPLE
X MULBERRY
223 PACE H 886-4839 +5
237 **MACEDONIA BAPT CH 886-3489**
X MASTEN AVE
X LOCUST
249 RICHLEY CLEMENT 884-2644 2
TOELLNER E W REV 854-2644
257 NEVILLES M L 885-1475 8
261 BROWN LEO 881-6424 +5
HOLLEY LENORA 882-8206 2
HOLLIE EFFIE 882-5072
267 KERSHAW GWENDOLYN 882-5095 4
X LEMON
275 BELL PAUL W 882-0798 9
THOMAS J 883-8009
277 EATMAN JAMES 881-2688 4
283 ARMSTRONG CALVIN E 883-6531 1
X ORANGE
301 GREEN L L 885-1087 4
309 PETERS JAS B 886-4003
314 BRANCH JOHN MRS 884-1083
320 MATTHEWS JAMES 883-3840 0
X PEACH
343 **BETHLEHEM BAPT CH 882-1446** 9
X GRAPE
358 BELL KATHERINE 881-5720 8
361 BARRETT EDW 886-2547
GREEN D 886-0621 4
363 BENSON ANTHONY REV 883-5452 0
MOUNT MORIAH MSNRY 885-8778 4

NORTH E 14204 CONT

X ROSE
X JEFFERSON AVE

ZIP CODE 14211

X TIMON
509 FUQUA ELISHA 883-0231
X JOHNSON
542 ANDERSON LOVETTA 882-6492 +5
543 GASKIN FRED 881-0817
GASKIN MCKINLEY 882-4056 4
549 CONLEY ROBERT H 886-4117
JOHNSON A 881-6050 +5
RIVERS WILLIE 885-0683 9
550 HOWARD WILLIS REV 881-5311 8
X SHERMAN
587 HOUSTON ALEX 896-8324 3
589 HARRIS ANDREW 892-1088
X FOX
614 CARRIER WAYNE 892-3305 4
618 STEVENS ALONZIA L 894-7496
620 DAVIS LOIS 893-9880 +5
X HERMAN
* 3 BUS 34 RES 5 NEW

NORTH AV 14224 WEST SENECA

100 ZYDEL STANLEY T 668-3531 7
106 BUSSMAN MICHL 668-6662 7
114 LITKE RANDAL C SR 668-3368 3
117 ZYGAJ JOHN E 668-0083 2
124 SMITH L 668-0523 6
125 LAWNICZAK L M 668-4547 7
131 WOZNY WALTER F 668-2566 3
134 LUBY JOHN F 668-0770 3
135 HAAS ARTHUR J JR 668-6967 7
138 STANKIEWICZ WALTER 668-6080 1
139 LAWNICZAK JOSEPH A 668-2839 7
141 ZIMPFER HOWARD 668-4123
144 BURGER CARL L 668-4798
145 PASCALE PASQUALE C 668-7142 7
150 DOROBIALA ROBERT J 668-4988
155 XXXX 00
156 COLELLO JOHN N 668-2250 7
191 SEIBERT J VICTOR 675-0199 1
204 HARMAN GEO H 668-3032 7
205 ALBERSTADT C 668-4063 +5
LONG JOHN M 668-2129 3
212 SISSON H N 668-2713 8
215 NORTHEM GEO A 668-7886
216 CRISP JAMES R 668-1031 7
KAMINSKI S M 668-5335 2
219 JACOBS DANIEL J 668-3387
223 LANG HAROLD 668-1425
224 BORSCHEL FRANKLIN 668-2014
227 LENT JOHN 668-2594 7
230 SMIGIELSKI FRANCIS 668-6768
236 MITZEL BRIAN G 668-1326
MUSCHAWEK ROBERT 2D 668-2475
242 BORCHERT FLORIAN H 668-2475
BORCHERT JANICE 668-1944 7
250 KELLER MAGDALEN L 668-4590 +5
MCKEE JAMES 3D 668-0849 +5
251 RADWAN RICHARD 668-3419 7
254 MULLENHOFF GEO W 668-2429 7
270 CIRBUS PAUL V 668-2141 7
274 DUST CLARENCE L 668-5242 7
278 BRALLA RICHD A 668-4322 7
281 DURST EDWIN W 668-2329 7
285 SUTTON NORMAN 668-3272 7
286 COOPERDOCK STEVEN G 668-2215 1
290 QUIGLEY EDW F 668-8483 1
291 WEBER MICHAEL H 668-5825 7
294 KIRKLAND THERESA 668-2964 7
298 SPEIDEL LEO P 668-1974 7
302 SCOTT PETER J 668-3653 7
305 HINES B J 668-7177
308 HAMMER CHARLES J JR 668-7177
* 0 BUS 51 RES 3 NEW

NORTH AV 14120 N TONAWANDA

261 DRAGAN DENNIS R 694-9686 9
265 BEHM WM J 693-6294
268 FEHRMAN ARTHUR C 693-3924
269 FITZGERALD GERALD 694-0865 3
270 SALEFSKE WAYNE C 693-5892
272 XXXX 00
273 PHELAN DONALD H 695-2785
277 KOHLER JOHN 695-1468
280 NOWARK DARWIN D 693-2866 3
281 TODD WILLIAM E 693-5012
284 BROECKER KENT D 692-1442
287 STANGE KENNETH A 692-6439
288 SONNEN DAVID M 693-0282
292 HUSACK L I 692-7753 7
293 MOELLER E E 693-8668 +5
296 CHAMPAGNE JAMES L 692-6768 5
297 HROMOWYK EDW 692-5049
300 DUNCH ALEX 692-3190
301 SAMANKA ALEX 693-3809
305 BARRACLOUGH JOHN JR 693-1755 9
308 SEMPLE ROBERT 694-2179 8
311 HY ROBERT H 692-4636 6
312 KLEPACZKA JOHN 692-7439 6
316 DIEREMYER JOHN A 692-6723 1
317 GROSE KENNETH 695-2273
320 REIF WM W 692-2532 +5
325 LAWRENCE MICHAEL R 695-9129 9
328 FINGERLOW HAROLD W 693-2131 0
329 DICK WILLIAM C 692-2158
333 PLETCHER MADELINE E 693-3999
336 XXXX 00
337 DRAKE ELMER 693-1855 7
344 STAKE RICHARD M 693-1810 +5
345 MELLENTINE CARL W 693-0085
349 MILLIMAN GEO J 693-6067 1
352 GAUDA KEVIN J 695-3543 1
353 PILARSKI JAMES J 693-7007 9
362 GUIZE DONALD R 692-3813
363 CLARK CHAS 692-3290
368 JULIUS T W 694-1697 5
369 LORINCZ M I 694-1329 0
374 STANGE DENNIS 694-1374 3
377 CAMPBELL GARY G 692-0695
KILLION JOSEPH C 695-9022 +5
ROCHEVOT MARK 692-5645
380 SIPIOR CASIMER J 694-3221 +5
384 PIORKOWSKI M F JR 693-3170
387 KANTANISTA M L 694-8387 4
391 SIRADAS LYNN M 694-8855 3
TOLLAR ROBT J 692-2694
392 SCULL DENNIS R 694-5755
400 BOWMAN DONALD E SR 693-4218
403 TAKACS JOSEPH JR 693-0244 +5
404 KURZDORFER JOHN 692-2785
410 THIELE GUY 693-0496 +5
411 ADAMS M 692-7328
417 KOKOSZKA VINCENT W 692-2069 9
420 POMARANSKI JOHN 694-7043
425 KOPCHO DEAN P 694-0960
429 GREENLAND M D 693-0963
432 FOSE HAROLD 693-8083
433 ZAYATZ ROBT A 693-3681
436 HELINSKI L 694-2609 3
444 AKINS VERNON D 694-8178
PAUL S M 695-2150
445 BROWN THOS R 695-2589 9
449 HANES LYNN B 693-1237
452 DAWES MICHAEL A

1980 BEST ST

SOURCE: HAINES



BERWYN AV 14215 CONT

69 XXXX 00
73 MAULUCCI DANL P 835-0173
MAULUCCI PASQUALE 835-2107
74 ANDERSON ROBERT G 833-2664 +0
HERNANDEZ RALPH 837-2965 9
77 WANAT ROSE 837-4267 1
WANAT STANLEY JR 834-0988
78 XXXX 00
79 XXXX 00
80 GRUBER JOSEPH 837-3320 5
83 ZELLER WALTER J 835-3677
84 SCHLAU NORMAN E 833-9658
88 JONES J B 833-5579
90 KUECHLE FRANK J 835-0595 5
93 STANCIL M 834-9045 9
STANCIL WILLIE R 838-5089 9
94 DRESCHER C J 833-5402
96 DRESCHER EDWIN H 832-7181
99 LYNCH JESS J 835-3801 2
100 XXXX 00
101 WILLIAMS ALBERT 837-6069 8
102 XXXX 00
105 XXXX 00
106 XXXX 00
109 RUBER FRED W 834-8075
110 SORRELLS U JAMES 837-5010 3
X BAILEY AVE
* 0 BUS 66 RES 5 NEW

BERYL DR 14225 CHEEKTOWAGA

14 LORRENS PETER T 892-9328 8
MUELLER G 894-5243 +0
YARIS JOSEPH J 894-0321 9
24 KELLER WM E 893-8438
34 CLARK TIMOTHY 896-1640 +0
COTTONE TONY 893-3672 8
OLSZEWSKI DAVID M 896-2985 +0
46 XXXX 00
54 IACOVINO EMIL 896-6130 8
66 WIATR ROBERT J 892-8261 2
79 MUCCI CARMEN 893-3707
85 GRUBER JOHN B 894-3368 2
125 PERESAN ALEX 893-5322 4
129 GARDNER M W 895-9529 +0
KRAS BERNARD 892-1619 8
136 REIS G W 894-6837 5
140 XXXX 00
141 HIRSCHAUER MATHW 893-8093
145 SAULINO ANNIO 895-6286
149 PATCHILL CHAS 895-4570
150 PYTLEWSKI EUGENE F 892-7943 5
153 WILD JOHN L JR 896-7464
156 KOLLER EDW J 892-9748
159 MIRANDO SALVATORE T 895-3565
160 SNIUSZKA ANTHONY 894-3478
163 XXXX 00
167 BICKERT LOUISE 896-6986 7
* 0 BUS 27 RES 4 NEW

BEST 14209 BUFFALO

X ELLICOTT
68 FOSTER CLAUDIA M 881-1557 9
X WELMONT PL
88 XXXX 00
93 XXXX 00
94 HENRY CHARLES E 886-0298 5
HENRY PAUL T 882-3695 8
96 GRIFFEN D 881-4919 7
97 XXXX 00
102 GUYTON DOROTHY 884-5204
KELLY GWENDOLYN 886-7275 9
120 SLAUGHTER GERALDINE 885-2731
122 ROBERSON WILLIE 882-5033
X ELM
126 MCGRAW J 885-1622 9
130 WASHINGTON PAMELA 884-6108 9
160 WALKER J 884-5679 9
161 XXXX 00
162 LITTLE MERLE 881-6957 7
163 XXXX 00
164 XXXX 00
165 XXXX 00
166 WILLIAMS SUGAR RAY 881-2311 +0
167 XXXX 00
174 XXXX 00
178 STANFORD WM P 885-5398
189 THOMAS JOHNNIE M 885-1410 +0
190 BYRD A 886-1684 9
192 HARPER HUBERT 886-5798 1
196 XXXX 00
200 JONES JAMES W 883-7826 5
202 SHOWERS ROOSEVELT 884-3094 6
204 XXXX 00
206 GAYLES RONALD L 884-4608 +0
HOGG R O 884-3253
208 FOWLER ELOISE MRS 885-1177
210 PIERCE WILLIE C 884-9237
212 CALLAHAN SALLIE M 885-4150
216 XXXX 00
218 XXXX 00
222 XXXX 00

ZIP CODE 14204

X MASTEN AVE
X PEACH
329 FRASIER MAMIE L 886-5056
JOHNSON JOHNNY 886-5521 1
331 OGDEN JOHN O 885-5786 9
339 AGEE HELEN E 886-3863 1
341 XXXX 00
345 PATTERSON LOLA 886-2157
347 GARNETT ROYAL 886-6888 9
JELKS FRANK 885-6028
357 SCOTT EDWARD 883-0658 3
359 XXXX 00
361 XXXX 00
363 XXXX 00
369 CHISM ELVIE 881-1972
ROBESON MONTGOMERY 884-4928 +0
370 XXXX 00
X JEFFERSON AVE

ZIP CODE 14208

399* **HERSCHELS AUTO SVCE 886-3465** 7
401 WAFFORD L MRS 886-0606
WRIGHT ROBERT J 883-2940 +0
403 XXXX 00
409* **STADIUM LIQ STORE 882-1838**
410 XXXX 00
413 GIDNEY DONALD E 886-7103 7
* **TRI ME BEAUTY BAR 886-9316**
419 XXXX 00
427 BURROUGHS JOHN H 881-0560 7
429 WATTS LUTHER JR 881-4257 7
433 WATTS LUTHER 882-0253 2
435 EVANS WILLIE 882-0170 +0
* **LINDE&GRAY HTG CO 883-0533**
REGER C C 883-5167 4
445 XXXX 00
453 XXXX 00
457 HARDY ARTHUR W 882-2708
458 NEWTON LOLITA E 884-8510 +0
460 TILLMAN HOWARD 883-3518
461 WALKER JAS 883-9528
464 XXXX 00
465* **GREENS DELICATESSEN 885-1899** 6
466 BRADY HIRIAM R 886-0337 +0
469 TURNER G 884-7235 9
470 XXXX 00
472 XXXX 00
473 PARMER LUETHEL 883-2617 2
476 HOWARD CARRIE 885-6379 6
477 AUSTIN HILDRATH 884-3442 1
480 WARD HELEN R 883-4316 8
485* **ST NY SUBSTNC MSTN 886-1425** +0
* **ST NY YTH MSTN PRK 886-1425** +0
X TIMON
488 NORMAN MARY E 885-6590 9
WILLIAMS KENNETH 886-2811 9
492 CLARK JOHN 886-7658
494 WOODRUFF FRANK J 885-3128
496 HESTER B 886-1980 6
KIRKLAND WILLA M 884-6199 +0
498 HALL W 886-7564 1
500 DAVIS H 885-2980 9
502 HILL COLUMBUS MRS 886-3578
518 COLEMAN G 886-1646 5
522 TERRELL ANN 886-4549 +0
528 KELLEY ALBERT E MRS 886-3538
530* **FLIERL RAYMOND C 884-3300**
* **NIAGRA FRNTR SEWING 884-3300** 3
534 SMITH MAXINE 883-2797 7
SMITH RUTH 886-4757 7
536 XXXX 00
537 XXXX 00
541 EDMUNDS U M 884-1573
543 XXXX 00
548 XXXX 00
550 XXXX 00
551 MC BRIDE ARTHUR 885-8884 +0
553 CAPPS BRAIS S 885-8634 2
CAPPS INEZ B 886-6840
555 XXXX 00
556 XXXX 00
557 BETHEL O NATHANIEL 886-3274 8
561 RAMSEY MICHELLE 882-7174 +0
563 XXXX 00
X SHERMAN

ZIP CODE 14211

X FOX
623 YOUNG TABERNACLE H 892-0985 +0
X HERMAN
X WEST PARADE AVE
643* **CONSORTIUM HUMAN SV 892-3011** 8
* **GOOD SHEPHERD 832-4480** 9
653 XXXX 00
657 WATTS V J 895-2889
659 STAPLES ROBERT 897-0117 6
661 KING S L 893-8934 8
X GUILFORD
669 GEORGE H M 893-0475 4
673 WILEY JOHNNIE B 893-5010 9
675 ROTHBALLER OTTO MRS 895-5502
679 NUNN I 897-4286 9
681 MATHIS JUANITA 897-4079 +0
683 HOLLEY W-JR REV 893-5995 +0
685 XXXX 00
687* **WORTHS LOUNGE 896-9579** 4
X RICH
697 DEE HENRY W 895-0040
MUELLER GEO J 894-3275
699 XXXX 00
701 MILLER M 892-1434 +0
703 SMITH ARAMENTHA 896-6149 4
711 HONER HELEN J 893-8800 +0
713 XXXX 00
717 PIERCE MARY 892-3612 9
* **TRIUMPH THE CHURCH 897-4661** 6
X SWEENEY
723 WILLIAMS JUANITA 894-5819 9
WILLIAMS WILFRED C 896-1473 9
727 XXXX 00
729 EGLETON NORMA J 893-3870 +0
733 XXXX 00
737 XXXX 00
739 BROWN V P 895-7311 4
WILEY J 894-0091 +0
WOOTEN BETTIE J 892-4269 8
743 FORMANIAK TED E 894-3392
SCHENACK V 893-4927 5
747 DAVIS JOEL L 893-6618 +0
X MYERS
753 DUBOSE D 891-8829 6
755 LAND AUGUST H 892-0898 +0
LAND TOMMY 894-0081 1
759 XXXX 00
761 XXXX 00
775* **SC BUFF ELEM 59 894-4522**
781 BRAND WILLIE 892-9566 7
X FILLMORE AVE
783 WILLIAMS BENNIE 894-8746 7
785 PICONE CARL F 892-5304
791 FIGURSKI ALEXNDR J 894-8927
793 BUCZKO STANLEY 896-5289
797 SIMON WM L 892-3786
799 DENNEE ARTHUR A 893-0374 4
801 XXXX 00
805 KOLEK LEO 896-5282
KRUPA JOS 893-6186
807 SZYMKOWIAK M M 894-2079
809 RIVERS M 893-7139 7

BEST

X GENESEE
NO #* **SC EAST SAT**
* 15 BUS

BEST 14006

658 XXXX
697 DIPASQUALE
704 XXXX
708 BLEY RICHAR
* 0 BUS

BEST 14075

189 GUSTEK EDW
268 XXXX
4770 LAPARE CHA
4779 CHIAVETTA
4786 GIER CARL
4812 JANOWSKI
4820 BLEECH MI
4825 WESOLEK E
4828 LONG GLEN
4836 HOCH J C
4845 SMITH AND
4846 SHAW M C
4854 DURNI PAU
4855 DIGGINS J
4866 PLATZ LAR
4876 FIERLE RA
4886 MILLER DO
4889 SCHMITT
4904 HINDERBE
4907 PINTO LO
4914 CALIGIURI
4917 MC GUINE
4922 WATKINS
4925 WARD AL
4932 BEMBIA J
4948 BOLAND
4949 DEPERTO
4956 HORNBE
4968 KRUG E
KRUG RO
4978 BARBER
* 0 BUS

BETHFORD BLASDELL

3148 XXXX
3278 MASON
3281 SWANN
3284 OSZUS
3288 DAINS
3289 HAAR
3293 FANDL
3294 GROSS
3299 CORDN
3300 SQUIR
3303 BALAS
3309 KOWA
3313 CROW
3316 QUINL
3329 CLOHE
3330 MEJIA
3334 BARGI
3335 DUKE
3340 XXXX
3346 SHAF
3347 RUI IV
3353 XXXX
3356 KOSC
3357 CUDD
3360 KENN
3363 DUKE
3364 SNYD
3367 HOOV
3371 COSI
3383 BISH
3387 HUG
3388 BRN
3393 CRO
3403 RAD
3407 FLIC
3408 ALV
3411 GRE
3412 XX
3418 TWA
3421 WIE
3430 JO
3431 PIA
3437 SH
3443 HE
3444 GU
3447 WO
3453 BA
3457 MC
3458 CA
3461 MC
3464 BR
3467 JE
3468 X
3472 M
3476 S
3480 S
3484 N
3485 P
3490 D
*

BETHL LACKA

X
8
11
15
16
18*
29
30
34
35
39
43
46
BETC HAM
31
56
59
61

1980 ELLICOTT ST

SOURCE: HAINES



ELLER AV 14211 CONT.

106 XXXX 00
109 DURKIN KENNETH 893-0068 9
110 JURKIW MICHL 896-6004
111 KRAFT ROBERT J 894-5899 5
114 PIATEK JOSEPH S 893-8447 5
115 SCHEUERLE H S 892-7030 6
119 SCHARMACH EDW 896-0436
120 BOCHENEK EDWIN M 892-8189
121 SZYMANKIEWICZ EDW 894-0527 1
126 XXXX 00
127 XXXX 00
129 HEITZ K A 892-0604 +0
133 GASSER ANNA-MRS 893-2140 +0
MOEHRLE PAUL 892-4178
134 HARTMAN MARY B 894-2057 +0
HARTMAN N 892-6149
137 BUTTS CLARENCE G 895-3592 3
139 SERCU SALOME 893-5659
STEINBACH CHARLOTT 896-5285 9
144 RUHLAND TED 892-9228
X GENESEE
★ 0 BUS 95 RES 10 NEW

ELLICOTT 14203 BUFFALO

X EXCHANGE
X CARROLL
X SENECA
74★ G&O MFG CO 852-2055 8
X DOUGLAS
75★ WOOLLEY L A INC 852-7700
76 XXXX 00
79★ ONONDGA LITHO SUPL 855-2022 9
83 XXXX 00
86★ ARTCRAFT BUROW PRNT 854-3241
★ BORK M M&SONS INC 854-7979 2
★ ELLICOTT PRESS 845-3241 8
★ RAUSCH&STOECKL CO 854-3241 6
★ WEYLER FRED 854-3241
87 XXXX 00
91 XXXX 00
X SWAN
121 XXXX 00
X SOUTH DIVISION RD
169 XXXX 00
X NORTH DIVISION RD
179 XXXX 00
181 BUILDING
★ BLUE BIRD COACH LNS 855-7511 8
★ BURGER KING G F M 856-0342+0
★ CANADA COACH LINES 855-7511 8
★ GENESEE BUS LINES 855-7511 8
★ GRAY COACH LNES LTD 855-7511 8
★ GREYHOUND BUS LINES 855-7526 8
★ GREYHOUND BUS LINES 855-7525 8
★ GREYHOUND BUS LINES 855-7520 8
★ GREYHOUND BUS LINES 855-7524 8
★ GREYHOUND POST HSES 852-4366 8
★ METRO BUS 855-7211 8
★ METRO CONSTR DIV 855-7363 9
★ NIAGARA FRNTR TRANS 855-7363+0
★ NIAGARA FRNTR TRANS 855-7345+0
★ NIAGARA FRNTR TRNST 855-7224+0
★ NIAGARA FRNTR TRNST 855-7211+0
★ NIAGRA FRNTR TRNST 855-7268 7
★ NIAGRA FRNTR TRNST 855-7222 7
★ NIAGRA FRNTR TRNST 855-7292 7
★ NIAGRA FRNTR TRSPRT 855-7211 7
★ NIAGRA FRNTR TRSPRT 855-7224 7
★ NIAGRA FRONTR TRNSP 855-7300 9
★ NIAGRA FRONTR TRNSP 856-2026 9
★ TRAILWAYS BUS SYST 852-1750 8
181
187 XXXX 00
189 XXXX 00
X EAGLE
210★ BEVAN JOHN H 854-3695
★ FRANKLIN COWAN PAPR 854-5954
★ KEX COPY PRODS INC 856-0450 7
X CLINTON
X BROADWAY
285★ STANFORD DSPLY STDS 852-8060
298★ B&G REFRIGRATN 856-9300
300★ HOTEL YORK 855-9847 8
301★ EMULSO CORP 854-2889
★ EMULSO PRODUCTS CO 854-2889
303★ ELLICOTT MOHAWK SV 855-9376 6
★ MATTIOLI PARKING 854-9864
X EAST MOHAWK
X HERSEE AL
321★ BALLOU PLMBNG SUPL 856-5944
332★ BUFFALO FIRE DEPT 842-1111 9
333★ FERGUSON ELEC CNSTR 852-2010
★ FERGUSON WHITWORTH 852-2010
★ WACHTEL CLARENCE P 852-2010
338★ HORTON COFFEE CO 854-1177
350★ GRAMSE PAUL A 852-2653 4
★ HEVENOR MAP CO 852-1655
★ HOOVER ROBT C 853-6860 3
X HURON
365★ ELLICOTT ELEC EQUPT 852-3357
THOMAS GEO N 852-3357 2
367★ BRUNNER SIMON ELEC 852-3824
★ HURONELL CORP 852-3824
★ METALLIZING CO 852-3824
★ SIMON BERT 852-3824
★ SIMON ELECTRIC CO 852-3824 9
★ WILBERT CONST CO 852-3824
369★ STERNS ELEC INC 854-0194
371★ HURONELL GARAGE 852-5168 3
381 XXXX 00
393★ BUFFALO WHOL GREENY 856-2227+0
395 XXXX 00
X GENESEE
X EAST CHIPPEWA
419 XXXX 00
423 XXXX 00
427 XXXX 00
431 XXXX 00
433★ NIGRELLIS FRUIT&VEG 852-7578 2
★ TOMS FRUIT&VEG MKT 852-7578 3
435 XXXX 00
437 LIPTAK KATHERINE 855-2673 5
439★ HASTINGS MKTG DVCES 852-6640+0
455 KERN M 849-0435 8
★ MCCLELLAND FRANK JR 852-8276 3
★ MCCLELLAND ROBT B 852-8276 5
★ MCCLELLAND VETRNRY 852-8276
★ PROWTEN A W 852-8276 2
461 XXXX 00
475★ WEHLE ELEC CO 854-3270
★ WEHLE ELECTRNCS INC 854-3270 1
477★ FINGERET BROS 847-6363 9
481★ FINGERET BROS INC 852-1300
501 ARLOTTA ANTHONY 852-6077
FRISCO JENNIE 847-6645 +0
511 XXXX 00
519★ STERLING SILVER WKS 852-2123 4
520 XXXX 00
X EAST TUPPER
567 AYLWARD JAMES 845-6170 9
NITZGER ALFRED 856-5095 8

ELLICOTT 14203 CONT.

587 XXXX 00
X GOODELL
X BURTON
674★ ULRICH RESTRNT 855-8409 6
X VIRGINIA
699 XXXX 00
X CARLTON
752 XXXX 00
760★ STJUDE CENTER 882-2987+0
ULASZESKI EDW J REV 882-2987
766★ AMER LUNG ASSN 886-4655 5
★ ASTHAM LUNG ASSN 886-4655 9
★ CHRISTMAS SEALS 886-4655 6
★ EMPHYSEMA LUNG ASSN 886-4655 5
770 XXXX 00
774 STERLING ROBERT 883-1416 9
782 MCDONNELL NORMAN 882-1818 4
X HIGH
X GOODRICH
854 XXXX 00
870 XXXX 00
876 XXXX 00
X E NORTH

ZIP CODE 14209

890 XXXX 00
X ST PAUL
X BEST
967★ P&R WIRE FORMING CO 883-6644 4
969 XXXX 00
980★ OSMOSE WOOD PRESERV 882-5905
★ POLE SPRAYERS INC 882-5905
★ SURDAM JOHN L 882-5905
X EDNA PL
991 DIXON J M 884-3961 5
JACOBS EUGENE 886-4503 1
996 XXXX 00
997 SHAW VERNON 885-1977
1000 XXXX 00
1001 XXXX 00
1002 XXXX 00
1007★ CALVARY C M E CH 886-8557
HADLEY JOHN D REV 886-5843 6
1010 XXXX 00
X DODGE
1040 XXXX 00
1042 BRESLIN WM P 883-8442
1044 ANDREWS HARRIS 882-3932 9
1047 XXXX 00
X COE PL
1050 XXXX 00
1054 XXXX 00
1056 XXXX 00
X SOUTHAMPTON
1061 GREEN MARY MRS 884-4633
1063 HENDRICKS CAROLYN 881-0257 4
JACKSON ARTHUR 882-8372 9
★ RHODES JOHN 886-8943
1066 WAIRE AARON 882-0073
1069 GRANT JOHN 883-4035 8
1070 CLARK LESSIE B 884-3883 8
1072 GRANT FANNIE V 883-2895 5
JACKSON S J 886-7946 9
1075 XXXX 00
X NORTHAMPTON
1094 MONTGOMERY DOROTHY 884-5277 +0
1097 JAMES YVONNE 886-5232 5
JOHNSON GLENDORA 886-4258 +0
1098 MONTGOMERY DOROTHY 884-3999
1101 SOLOMON A 881-4280 +0
1102 FLAGG COWAN DAVIS 886-2876 6
1109 WATSON LEE 883-8802 2
1113 WILLIAMS WILBERT 884-9319
1117 DURSHORDWE THOS G 883-0179
1121 XXXX 00
1123 DESJARDINS ESTHER M 884-0515
1131 GAINEY NATHANIEL JR 884-8155 +0
1135 SMITH THOS J 884-3769
1137 MARLEY L M 886-5946 9
MCKELLER M 886-8241 9
1141 FRAZIER LUCIOUS 885-4795
X RILEY
★ 85 BUS 79 RES 13 NEW

ELLICOTT 14006 ANGOLA

9545 BRACCO CARMELO JR 549-4382 5
9559 MURPHY RICHARD C 549-1629 +0
9583 PEZZIMENTI JOS F 549-0854
9608 LOPES FRANK 549-1056 +0
9637 MICHALSKI CASIMIR W 549-5392 +0
★ 0 BUS 5 RES 3 NEW

ELLICOTT N 14221 WILLIAMSVILLE

SEE NORTH ELLICOTT

ELLICOTT S 14221 WILLIAMSVILLE

SEE SOUTH ELLICOTT

ELLICOTT BLVD 14150 TONAWANDA

TOWN OF TONAWANDA AREA

10 WEBER KARL E 693-4008
15 REID HILMER A 694-2948
19 BRAUN A 693-9412 9
30 HAAS WM L 693-2345
★ 0 BUS 4 RES 0 NEW

ELLICOTT CT 14150 TONAWANDA

TOWN OF TONAWANDA AREA

4 BECKER ANNE B 693-8287
10 FOOTE DANL C 692-2445
16 MARTENE FRANKLIN 695-2443
17 SZUR JOHN J 694-8232 8
20 WAGAR D A 694-8073 +0
WAGAR DAVID A 694-4725 6
21 GRIFFITHS JOHN W 692-3689 2

ELLICOTT CT
24 XXXX
25 BESANT W
26 XXXX
★ 0 BUS

ELLICOTT P
DEPEW
8 POLCHLO
10 XXXX
14 GOLEMBIE
KRZYSIAK
MILLER D
SOSNOWS
16★ ELLICOTT
61 CYBULSKI
67 FRON BER
71 ZIEMBA A
77 SIERAGA
83 BELTZ E
DENLER P
85 PLECHA W
99 WOJCIK J
107 WOLSKI J
111 KEEM C E
115 STEMPKO
119 XXXX
125 KOBEL JA
131 LEGOCKI
★ 1 BUS

ELLICOTT
CHEEKTOW
40 XXXX
44 SMITH FR
58 XXXX
510★ ALL WEA
KADER E
520★ BOWLING
★ KINGPIN
556★ CERVI C
CERVI G
★ CERVI J&
★ 5 BUS

ELLICOTT
TONAWAN
501 BAUER L
★ 0 BUS

ELLICOTT
ORCHARD
4905 RAPPL E
4915 KALINO
4919★ KELLYS
4923★ BOND C
★ KELLOG
★ SALERN
4924 FISHER
4936★ BEEF&W
ECKL M
★ ECKLS
PEARCE
4939 SCHMER
4944 REESE
4949 XXXX
4956 DEHART
4957 RAPPL
4962 DIETSC
PAA ED
ZIRNHE
4970 XXXX
4990 XXXX
5004 HAUSE
5012 DIPIAN
5017 FLICK F
5033 MAHER
5042 MARKU
5050 ROSPU
5053 ROSS R
5060 GUTEK
5061 MARTIN
5068 CHLOS
5069 MCKAY
5075 MOIST
MOIST
5080 XXXX
5082 WENKE
5083 BIELER
5089 HABITZ
VANHO
5098 XXXX
5101 PHILLI
5111 OCONN
5112 STANK
5119 SLAGE
5120 HEBER
5128 XXXX
5135 HARAS
5154 XXXX
5196 BOCHE
5228 GERLI
5266 MURPH
5293 BOOT
LAMKE
5294 STRON
STRON
5323 AURES
STRAI
5338 STRON
5410 LUCH
5432 WALS
5460 PRAC
5473 PAZ J
5476 XXXX
5481 XXXX
5491 CLARI
7025 CURN
HAMM
WAIBL
7040★ WELL
★ WELL
7060 WELL
7079 PFAF
7081 TELF
7093 HOLM
7102 XXXX
7105 CLAR
7130 XXXX
7140 GNAU
7144★ ORCH
★ SCHW
7151 HOFF
7164 GEIT
7167 FITZ
FITZ
7179 CANF
7186 ENGA

& CO., INC. INFORMATION ON THIS PAGE MAY NOT BE KEYPUNCHED, ENTERED INTO A COMPUTER OR PHOTOCOPIED, IN ANY MANNER W

1980 GOODRICH ST

SOURCE: HAINES



GOODRICH 14203
BUFFALO

X MAIN
26 XXXX 00
X ELLICOTT
80★ CITIZEN COMM DEVLP 856-1727+0
★ COMNTY ACTION ORG 853-0350 8
112★ BUFFALO GEN HOSP 845-2895+0
DEDARIO K 842-2649 +0
WAGNER C 842-2645 +0
X ELM
★ 3 BUS 3 RES 4 NEW

1980 MICHIGAN AVE

SOURCE: HAINES



1980 NORTH ST E

SOURCE: HAINES



1976 BEST ST

SOURCE: HAINES



..BERWYN AVE 14215 CONT..
KINMARTIN SIMON F 833-4129
57 ANDERSON H E 838-3956+6
58 HANLEY S 834-3384
61 ROGERS JACK E 833-2514 5
62 GRIMM WALTER A 834-5921
63 STEPHAN FREDK F 832-2925
64 MARTIN A DONALD 835-8145 0
67 MINCHEN EDW J 834-2845
68 NUTTER C C 832-1348 4
69 BLINE C S 837-4259 1
WEBER E H 832-5763
72 ZIMMERMAN D 834-2645 8
73 MAULUCCI DANL P 835-0173
MAULUCCI PASQUALE 835-2107
74 BECK WAYNE C 833-8327 5
BRUNNER M 836-7120 4
DELLWARDT M 836-7120 4
77 WANAT ROSE 837-4267 1
WANAT STANLEY JR 834-0988
78 MOSLOW JANET 835-9056+6
ZIMMERMAN JANET 835-9527
79 HELLER FRED 833-1022
80 GRUBER JOSEPH 837-3320 5
83 ZELLER WALTER J 835-3677 8
84 SCHLAU NORMAN E 833-9658
88 JONES J B 833-5579
90 KUECHLE FRANK J 835-0595 5
93 POLLARD PAULINE MRS 835-2439 4
94 DRESCHER C J 833-5402
96 DRESCHER EDWIN H 832-7181
99 LYNCH EARL 835-7989 3
LYNCH JESS J 835-3801 2
100 BARTNIK JOHN R 832-3818 5
101 KLEIN CYRIL 833-1705
102 BELSCHER L M 837-7958 5
105 FOLMER M 834-4364+6
106 ROSINSKI EUGENE C 835-3807
109 RUBER FRED W 834-8075
110 SORRELLS U JAMES 837-5010 3
X BAILEY AVE
* 0 BUS 72 RES 7 NEW

BERYL DR 14225 CHEEKTOWAGA

14 MATHEWS STEPH 892-9328
WILLIAMS J 896-4579+6
24 KELLER WM E 893-8438
34 CIURA THOMAS J 892-6260+6
IGNASZAK DENNIS M 892-9091 4
46 XXXX 00
54 WAGNER K P 895-4208 0
66 WIATR ROBERT J 892-8261 2
79 MUCCI CARMEN 893-3707
85 GRUBER JOHN B 894-3368 2
125 PERESAN ALEX 893-5322 4
129 GANGLOFF RICHARD J 893-2668 5
HERRMANN MARGIT 895-9529 5
136 REIS G W 894-6837 5
140 BOGNAR JOS 892-5957
141 HIRSCHAUER MATHW 893-8093
145 SAULINO ANNIO 895-6286 8
149 PATCHILL CHAS 895-4570
150 PYTLEWSKI EUGENE F 892-7943 5
153 WILD JOHN L JR 896-7464
156 KOLLER EDW J 892-9748
159 MIRANDO SALVATORE T 895-3565
160 SNUSZKA ANTHONY 894-3478 9
163 XXXX 00
* 0 BUS 24 RES 2 NEW

BEST 14209 BUFFALO

NO #*OUR LDY LOURDES SCH 883-7885
4 ASHBROOK HENRY F 882-6080
BERNAS C 883-8452+6
DONOVAN ROBERT 886-7519+6
JENNINGS EUGENE W 886-1773
POWERS THOS J 884-6728
X ELLICOTT
68 HUBBARD ELIZABETH 886-6196 5
JACKSON M A 885-5674 5
69 XXXX 00
70 COLLINS G 883-0014+6
DICKSON MACK 881-1435 0
71 XXXX 00
72 CONNER HOWARD 885-8077+6
73 XXXX 00
74 XXXX 00
79 XXXX 00
86 LEFTWICH HARRY S 882-1864
MERRIWETHER LENA 881-2715 4
X WELMONT PL
88 COLEMAN RACHEL V 882-1173 3
93 XXXX 00
94 HENRY CHARLES E 886-0298 5
97 FAISON DONALD 884-5491 4
102 GUYTON DOROTHY 884-5204
103 XXXX 00
104 DANIELS HENRY 886-3486+6
105 XXXX 00
108 JONES J 882-3084 5
WOODS WINIFRED 881-6853+6
111 XXXX 00
112 MELSON DAVID 886-4845
113 XXXX 00
120 SLAUGHTER GERALDINE 885-2731
122 LANG EARLY 882-5729
ROBERSON WILLIE 882-5033
X ELM
126 XXXX 00
129 XXXX 00
130 XXXX 00
131 XXXX 00
134 ELDRIDGE ALBERT 885-5149 5
136 CARR QUINCY 884-8893 1
139 XXXX 00
159 XXXX 00
160 XXXX 00
161 XXXX 00
162 LITTLE MERLE 881-5913 4

..BEST 14209 CONT..
163 XXXX 00
164 XXXX 00
165 XXXX 00
166 GUESS S N 886-4838 5
167 XXXX 00
174 XXXX 00
178 STANFORD WM P 885-5398
190 SUMLER STEPHEN 886-5699 3
192 HARPER HUBERT 886-5798 1
196 ROBINSON WILLIE 884-2710
WILLIAMS CLEVELAND 884-2746
200 JONES JAMES W 883-7826 5
202 MCCRAY MARIE 884-8326 5
SHOWERS ROOSEVELT 884-3094+6
206 HOGG R O S 884-3253 0
208 FOSTER KAISER L 886-6479+6
FOWLER ELOISE MRS 885-1177
210 PIERCE WILLIE C 884-9237
212 CALLAHAN SALLIE M 885-4150
216 BUCHANAN EUGENE 882-1848
THOMAS JOHNNIE M 885-1410 2
218 BAILEY RAYMOND 881-1700 4
222 XXXX 00

ZIP CODE 14204

X MASTEN AVE
X PEACH
329 FRASIER MAMIE L 886-5056 9
JOHNSON JOHNNY 886-5521 1
331 MIMS HORACE 886-4077+6
339 AGEE HELEN E 886-3863 1
341 ADAMS WILLIE 886-8186 0
345 PATTERSON LOLA 886-2157 9
347 JELKS FRANK 885-6028
X RAPE
357 MOSLEY MOZELL 884-3419 9
SCOTT EDWARD 883-0658 3
361 XXXX 00
363 ROBINSON ETHEL 884-2638 3
369 CHISM ELVIE 881-1972 0
DREHER J 882-8229+6
370 XXXX 00
X JEFFERSON AVE

ZIP CODE 14208

399 XXXX 00
401 THOMAS PETER 882-4946
WAFFORD L MRS 886-0606
403 SKINNER IDA M MRS 882-6675
409*STADIUM LIQ STORE 882-1838
410*HOLDERS WASH O MAT 886-9271+6
413*TRI ME BEAUTY BAR 886-9316
419 XXXX 00
427 BURROUGHS JOHN H 882-1803 2
BYRD JIMMIE R 885-8499+6
GILBERT D E 885-5379 5
429 WARDLAW EMMA 885-2328 2
433 WATTS LUTHER 882-0253 2
435*LINDE&GRAY HTG CO 883-0533 0
REGER C C 883-5167 4
445 XXXX 00
453 XXXX 00
457 HARDY ARTHUR W 882-2708
458 FLETCHER JOSEPHINE 886-3785+6
460 TILLMAN HOWARD 883-3518
461 WALKER JAS 883-9528
464 XXXX 00
465 BRYANT MITCHELL 881-3869 5
*GREENS DELICATESSEN 885-1899+6
466 ANDREWS E 884-4823+6
469 XXXX 00
470 HALL WM JR 883-4410 8
472 XXXX 00
473 JONES K C 886-2679+6
PARMER LUETHEL 883-2617 2
476 HOWARD CARRIE 885-6379+6
477 AUSTIN HILDRATH 884-3442 1
480 GURGANIOUS ALTON 883-8427
485*NY ST DRUG ABS CMSN 886-1425 5
X TIMON
488 CLARK IDA 886-4173 2
492 CLARK JOHN 886-7658
494 MURPHY DOSHIA 886-1624 5
WOODRUFF FRANK J 885-3128 8
496 BASKIN C 883-5347+6
HESTER B 886-1980+6
498 HALL W 886-7564 1
500 DAVIS HATTIE 885-2980 9
502 HILL COLUMBUS MRS 886-3578
518 COLEMAN G 886-1646 5
522 COIT THELMA MRS 883-3865+6
SATCHER ALFONZO 884-1872 2
528 KELLEY ALBERT E MRS 886-3538
530 FLIERL RAYMOND C 884-3300
*NIAGR FRT SEWG MACH 884-3300 3
534 BRUCE ROBT W 884-3205
GROH RICHD 885-1485
MAYLE HERMAN F 885-1485
536 DURANT BERTHA 882-3897 2
537 XXXX 00
541 EDMUNDS U M 884-1573 0
543 XXXX 00
548 XXXX 00
550 PAULDING MARY MRS 886-1443 2
551 MCCARY ANZO 886-4375 4
553 CAPPS BRAIS S 885-8634 2
CAPPS INEZ B 885-6840

1976 ELLICOTT ST

SOURCE: HAINES



..ELLICOTT 14203 CONT..
*SCHNEIDER HERB 854-1395
*WEYLER FRED 854-3241
87 XXXX 00
91 XXXX 00
X SWAN
121....POST OFFICE BLDG
*US POSTAL SV 842-2803 5
*US PSTL SV CONTRACT 842-3572 3
121.....
X SOUTH DIVISION RD
169 XXXX 00
X NORTH DIVISION RD
179 XXXX 00
187 XXXX 00
189 XXXX 00
X EAGLE
210*BEVAN JOHN H 854-3695
*COWAN HAROLD L 854-5954
*FRANKLIN COWAN PAPR 854-5954
X CLINTON
X BROADWAY
285*STANFORD DSPLY STDS 852-8060
298*B&G REFRIGRATN 856-9300
300*YORK HOTEL 854-9021
301*EMULSO CORP 854-2889 8
*EMULSO PRODUCTS CO 854-2889
303*ELLICOTT MOHAWK SV 855-9376+6
*MATTIOLI PARKING 854-9864
X EAST MOHAWK
X HERSEE AL
321*BALLOU PLMBNG SUPL 856-5944
332*ERIE CO FIRE COORD 856-1155
333*FERGUSON ELEC CNSTR 852-2010
*FERGUSON WHITWORTH 852-2010
*WACHTEL CLARENCE P 852-2010
338*HORTON COFFEE CO 854-1177
*WHITEHILL RICHD K 854-1177
350 GRAMSE PAUL A 852-2653 4
*HEVENOR MAP CO 852-1655
*HOOVER ROBT C 853-6860 3
X HURON
365*ELLICOTT ELEC EQUPT 852-3357
THOMAS GEO N 852-3357 2
367*BRUNNER SIMON ELEC 852-3824
*HURONELL CORP 852-3824
*METALLIZING CO 852-3824
SIMON BERT 853-9515
*SIMON BERT 852-3824
*SIMON ELEC CO INC 852-3824
*WILBERT CONST CO 852-3824
369*STERNS ELEC INC 854-0194 8
371*HURONELL GARAGE 852-5168 3
381*FRONTIER WHOL FLRST 852-5737 9
395*JOHNNYS ELLCTT GRLL 855-8894+6
WEISS JOHN J 852-1652
X GENESEE
X EAST CHIPPEWA
419 XXXX 00
423 XXXX 00
427 XXXX 00
431 XXXX 00
433*NIGRELLIS FRUIT&VEG 852-7578 2
*TOMS FRUIT&VEG MKT 852-7578 3
435*EVER READY TV SVCE 854-8685 5
KOPACK WESLEY C 854-8685+6
WOLENTARSKI LOUISE 842-0054 5
437 LIPTAK KATHERINE 855-2673 5
439*HASTINGS MRKNG DEVC 852-6640 2
455 MCCLELLAND FRANK JR 852-8276 3
*MCCLELLAND ROBT B 852-8276 5
*MCCLELLAND VETRNRY 852-8276
PROWTEN A W 852-8276 2
461 XXXX 00
475*WEHLE ELEC CO 854-3270
*WEHLE ELECTRNCS INC 854-3270 1
477*FINGERET BROS INC 853-3340 9
481*FINGERET BROS INC 852-1300
501 ARLOTTA ANTHONY 852-6077
DAWSON E W 856-8331+6
FRISCO JENNIE 853-1416 2
KNIBBS RAYMOND E 854-6881
NOWAK EDWARD B 856-8331+6
511 XXXX 00
519*STERLING SILVER WKS 852-2123 4
520*BUDD DISTRIBUTORS 854-3830
X EAST TUPPER
567 AYLWARD JAMES 853-9526+6
587 XXXX 00
X GOODELL
X BURTON
674 DALEY JAMES F 856-8873 3
*ULRICH RESTRNT 855-8409+6
X VIRGINIA
699 XXXX 00
X CARLTON
752 XXXX 00
760 ULASZESKI EDW J REV 882-2987 0
766*AMER LUNG ASSN W NY 886-4655 5
*CHRISTMAS SEALS 886-4655+6
*EMPHYSEMA LUNG ASSN 886-4655 5
770 XXXX 00
774 LINDNER HENRY J 883-1416 2
782 MCDONNELL NORMAN 882-1818 4
X HIGH
X GOODRICH
854 XXXX 00
870 XXXX 00
876 XXXX 00
X E NORTH

ZIP CODE 14209

886 PICKENS LOUISE 885-7276 3
PICKENS NORA 885-6969+6
890 CHURCH OF GOD PRSNG 884-2328 3
892 XXXX 00
894 XXXX 00
898 MOLLENKAMP C C 883-4127 4
900 XXXX 00
903 XXXX 00
X ST PAUL
935 XXXX 00
938 XXXX 00

..ELLICOTT 14209 CONT..
X BEST
967*PER WIRE FORMING CO 883-6644 4
969 XXXX 00
980*ANIMAL REPELLENTS 882-5905
*OSMOSE WOOD PRESERV 882-5905
*POLE SPRAYERS INC 882-5905
*SURDAM JOHN L 882-5905
X EDNA PL
991 DIXON J M 884-3961 5
JACOBS EUGENE 886-4503 1
996 WHITE MAGNOLIA 886-0519 0
997 SHAW VERNON 885-1977 9
1000 XXXX 00
1001 COEFIELD JOHN 881-1164+6
WILEY RUBY MRS 884-2249 2
1002 JONES CAROLYN 881-5027+6
1007*CALVARY CME CHURCH 886-8557 0
*HADLEY JOHN D REV 886-5843+6
1010 XXXX 00
X DODGE
1042 BRESLIN WM P 883-8442
1044 LOVELACE E J 882-3932 5
1047 XXXX 00
X COE PL
1050 KIRKLAND KATHERINE 884-3573 3
1054 BRICE M L 881-6711+6
JOHNSON CHAS A 886-8265 8
1056 TACKETT JESSIE 885-1828+6
X SOUTHAMPTON
1059 JACKSON DENISE 884-9145+6
1061 GREEN MARY MRS 884-4633
1063 HENDRICKS CAROLYN 881-0257 4
MATHIES LYDIA 885-7765+6
*RHODES JOHN 886-8943
1066 WAIRE AARON 882-0073
1069 GREEN EDDIE 886-4337 5
POPE HAROLD SR 885-7399+6
1070 MAUERMAN ROBT E 884-7148
1072 GRANT FANNIE F 883-2895 5
1075 XXXX 00
X NORTHAMPTON
1094 SISTER MARY C 884-5277 4
*SISTERS OF ST MARY 886-1913
1097 JAMES YVONNE 886-5232 5
1098 MONTGOMERY DOROTHY 884-3999
1101 COMER JOHN W 884-7817+6
ELLIS HENRY 882-6758+6
NELSON WILLIAM H 881-0871 4
WHITT DORIS 881-4284+6
1102 FLAGG JOHN DAVIS 886-2876+6
1109 WATSON LEE 883-8802 2
1113 WILLIAMS WILBERT 884-9319
1117 DURSHORDWE THOS G 883-0179
SUVER J A 884-3022 8
1121 XXXX 00
1123 DESJARDINS ESTHER M 884-0515
1131 JAMES B E 886-0715+6
REAVES DOUGLAS 882-5582 2
1135 SMITH THOS J 884-3769
1137 BATTS LESTER 882-4298
1141 FRAZIER LUCIOUS 885-4795
X RILEY
* 71 BUS 98 RES 25 NEW

ELLICOTT 14006 ANGOLA

9545 BRACCO CARMELO JR 549-4382 5
9583 PEZZIMENTI JOS F 549-0854 0
* 0 BUS 2 RES 0 NEW

ELLICOTT N 14221 WILLIAMSVILLE

SEE NORTH ELLICOTT

ELLICOTT S 14221 WILLIAMSVILLE

SEE SOUTH ELLICOTT

ELLICOTT BLVD 14150 TONAWANDA

TOWN OF TONAWANDA
AREA

10 WEBER KARL E 693-4008
15 REID HILMER A 694-2948
19 MURAWSKI EDMUND 694-8221+6
30 HAAS WM L 693-2345
* 0 BUS 4 RES 1 NEW

ELLICOTT CT 14150 TONAWANDA

TOWN OF TONAWANDA
AREA

4 BECKER ANNE B 693-8287
10 FOOTE DANL C 692-2445
16 MARTENE FRANKLIN 695-2443
17 SZUR JOHN J 694-8232+6
20 WAGAR DAVID A 694-4725+6
21 GRIFFITHS JOHN W 692-3669 2
24 LOFTUS ROBERT W 694-5621 3
25 BESANT WILLARD F 693-4174 5
26 XXXX 00
* 0 BUS 9 RES 2 NEW

ELLICOTT PL 14043 DEPEW

8 POLCHLOPEK THOMAS 684-8730 4

1976 GOODRICH ST

SOURCE: HAINES

GOODRICH 14203 BUFFALO

X MAIN

26 XXXX 00

X ELLICOTT

80*BUF GNRL HOSP EMER 845-4102 5

*BUF GNRL HOSP MNTL 845-4125 4

*BUFF GENERAL HOSP 845-4135+6

*LEARNING FOUNDATION 856-1727+6

*PROJECT RETURN INC 856-0440+6

112*BUFF GENERAL HOSP 856-1350+6

X ELM

* 6 BUS 1 RES 4 NEW

1976 MICHIGAN AVE

SOURCE: HAINES

..MICHIGAN AV 14203 CONT..

638 COOPER MOSES 856-1150 5
646*WARNER EDW L 852-6666
*WARNER JWLRY CASE 852-6666 0
647 XXXX 00
653 CLEMMONS OPHELIA O 856-9334
LANEY MARY 856-8199
MCNEAR CLARENCE 852-5993 5
REESE LILY 856-9334
WILLIAMS JOSEPHINE 852-3970 2
654*ORLINS BTY SUPPLY 854-3692 9
655*PILGRIM BAPT CHURCH 855-8614+6
X GENESEE
692*ANTHONE FURN CO INC 852-4662
715 XXXX 00
X E TUPPER
723 XXXX 00
X CHERRY
788 XXXX 00
X GOODELL
804 XXXX 00
808 XXXX 00
812 XXXX 00
813 PITTORF WM F SR 853-8123
X BURTON
833 XXXX 00
851 SHAPIRO JACOB M 852-1096
861 WALKER JANIE M 854-6511 4
862 XXXX 00
866 GADDY ALICE M 853-7549 8
869 XXXX 00
870 XXXX 00
873 XXXX 00
874 XXXX 00
875 DALE ROBBIE LEE 853-4117 9
DIXON E 856-4324+6
876 XXXX 00
877 XXXX 00
880 XXXX 00
881 REED ELREY 855-1694 5
882 XXXX 00
883 XXXX 00
X VIRGINIA
885*RUMPH MVG&LGHT HLNG 855-3406+6
889 YOUNG MCKINLEY 855-2950 4
891 XXXX 00
899 XXXX 00
901 XXXX 00
907 KEMPKER WM 856-8355
909 MITCHELL ANNIE 853-4398
913 PALMORE MARY 842-1285+6
915 CRAIG ALFRED 847-2689+6
917 GIBSON JAS E 856-1878
921 BANKS ELAINE 854-1469 0
JACKSON EDW 854-4415
MYERS G 855-3484+6
925 WOOD W 842-0187 5
927 XXXX 00
939 XXXX 00
X CARLTON
955*ROSWELL PK MMRL EMP 845-2330 3
*ROSWELL PRSNL INF 845-2320 1
975 XXXX 00
977 REED MAMIE 884-0760 0
983 WILLIAMS JAMMIE L 881-5459 5
985 THOMPSON JAS 882-1323
987 XXXX 00
989 THOMPSON FRANK 884-1122 3
WILLIAM M 884-0984+6
993 MERRILL G A 883-8545+6
ROSS SAMUEL 884-1810 2
997 XXXX 00
1001 XXXX 00
X HIGH
1027 XXXX 00
1029 BLANCK C M 884-2550 3
1031 MACKIE ARTHUR J 882-2480
MURRAY ELLA M 885-6937 1
1033 STRAUGHTER V 885-7289 5
THOMAS D D 882-7540+6
1035 XXXX 00
1039 KIRKWOOD FRANK C 886-0423
1043 PATTERSON M P 881-2528 4
X GOODRICH
1045 JOHNSON ALLIE 886-3595
WOODS HERBERT JR 882-3888
1049 XXXX 00
1053 LONG ELEANOR MRS 885-5393
1057 CORONER ALZIN 885-4892+6
TRIPLETT CARROLL M 882-7181 5
1059 RIES JOS W 882-3131
1061 WASHINGTON BETTY J 881-2360 5
1065 TRAUTMAN GERTRUDE 883-9349
1069 SCOTT HENRY 886-2820+6
X E NORTH

ZIP CODE 14209

1098 XXXX 00
X BEST
1137 XXXX 00
1144*MOYNIHANS COLLISION 881-1957 2
1145 WARD EDDIE MARY 883-0779
1148*TUTTON ELEC CO 884-7686
1149 GAINER ESTELLA 881-6410 5
STITT MANUEL 884-2918 2
1151 XXXX 00
1155 FOSTER MARGARET 885-7469
REED EMMITT 886-4372 3
1157 COOLEY EXCELL 881-2581 5
COOLEY HATTIE M 881-2581 5
X EDNA PL
1164*MES AUTO SVCE 886-8666+6
1165 XXXX 00
1166 XXXX 00
1167 SMILEY JOHN 882-9279 9
1170 NEAL AUSTIN 883-0461 3
1171 HUNTER L 886-6756 5
1172 BOND ANDREW J 886-3541 2
1173 GARRY LOUISE 884-9252 9
SMITH DOROTHY 883-6138 0
1174 BROWN SAM 883-1217

..MICHIGAN AV 14209 CONT..

1175 ROWE DONALD 881-2215+6
WIDEMAN MILDRED I 883-3735 9
1176 XXXX 00
1183 XXXX 00
1187 BALDWIN LITA 881-2885 5
1188 MOKARICAS GEO 883-8731
1189*EARNEST&CARRIES MKT 884-8442 5
X DODGE
1199 BURNEY ROBERT 886-1375+6
1200 XXXX 00
1202 XXXX 00
1203 XXXX 00
1206 DOCKETT GERTRUDE 886-1434 9
DOCKETT JACQUELINE 886-5162 5
JORDAN ROBERT M 886-7321+6
1207 FRITZ ROBERT L 883-1418 3
1208 SALTER LOUISE M 885-3917
1209 XXXX 00
1210 XXXX 00
1212 MCNETT JESSE 884-0004
1213 XXXX 00
1214 XXXX 00
1215 BLAND P A 881-4392+6
GREENE RAY 882-1312 3
1217 XXXX 00
1218 BENSON CHAS 886-2222
WILLIAMS DAVE 882-0741
1220 KING MAMIE 883-2331
1221*ST MARKS CH OF GOD 881-3097 5
1233*FREDDIES BARBECUE 883-0552 2
X SOUTHAMPTON
1236 DIXON MCKINLEY M 882-3945 0
1237 HARRIS D 886-8313 3
JOHNSON LILLIE 882-9543
1239 JONES MILTON M 881-4027 4
1241 JONES VERTONIA 884-6940
1242 XXXX 00
1243 XXXX 00
1244 MCMILLAN CURTIS A 881-6491 4
MOORE CAROL 884-9486+6
1245 XXXX 00
1249 HOPKINS CHEYENNE B 881-0397+6
1250 FORD WILLIE L 884-4233 5
1253 XXXX 00
1257 XXXX 00
1260 XXXX 00
1261 XXXX 00
X NORTHAMPTON
1263*COOKES LIQUORS 886-8577 5
1265*RUBYS BEAUTY LOUNGE 886-8573 1
VEASLEY SIDNEY 881-0808 5
1266 XXXX 00
1267 EVANS DOROTHY 883-5529 4
KENNON DOROTHY 886-3536+6
1268 XXXX 00
1269 WILSON MARION 883-5217 1
1270 XXXX 00
1272 DAHL HOWARD J 883-4665 5
1273 XXXX 00
1275 WILLIS ARLANA 881-6346+6
1279 BUTLER FLOYD 882-7052
DIXON N 886-2633+6
1280 XXXX 00
1281 DOCKERY JAMES A REV 884-3964 4
1284 XXXX 00
1288 XXXX 00
1292 BLUE JAS 885-0716
1296 QUARLES JENNEAR 884-7211 2
QUARLES LILLION 884-0113
X EATON
1297*STARLITE DELI 886-8946 4
1298 CAGGINS DESSIE 883-0381 5
TONEY TERRY LEE 884-4721+6
1301 XXXX 00
1302 BURTON JOHNIE 881-5579+6
1303 BARNES MARY R 884-1170
BARNES NATHL 884-1170
1304 WYATT THELMA 883-1253
1311 BATEMAN BETTY SUE 886-5803 9
1312 XXXX 00
1314 JENKINS CORRINE 883-3317 4
1315 NUNN VANESSA 882-6438+6
1316 DAVIS JOEL L 881-2840 5
1318 HUDSON ALLEN E 885-0976
1319 XXXX 00
1321 XXXX 00
1323*MGR DRY CLEANERS 886-8678 3
PUGH WADE 885-3859
1325*MICHIGAN&RILEY 886-9034+6
1327*CARY AUTO SVCE 886-9312 2
X RILEY
1331 XXXX 00
1337 KILLEBREW JOHN L 886-2068 1
1339 BOWE WILSON 881-4268 5
1341 DAVIS MARION 883-8235
X LAUREL
1363 XXXX 00
1364 HANNON ALEX 885-6068 1
MADISON EUGENIA 882-8526
1365 ALLEN JANICE 882-0720+6
1366 BROWN JESSE 885-1650 0
NORMENT R 884-3006 5
1368 BAILEY L 882-2748
JONES S 885-7127+6
THORNTON ANNIE MAE 886-0425 4
1370 BEDFORD WILSON M 882-1116
1371 BAKER MARY ALICE 886-3867
1372 COLEMAN ANNIE 886-3523
HALL GEORGE 886-4179 2
1373 XXXX 00
1375 HALSELL E 882-5014 9
MARION THOS 885-0103
1377 XXXX 00
1380*POHLES AUTO SVCE 884-7194 2

1976 NORTH ST E

SOURCE: HAINES



..EAST MORRIS AV 14214 CONT..

152 RIEMAN CARL A 833-4751 8
153 DOLAN L 838-3484+6
QUITT BENJ A 834-4852
156 REESE MARY K 836-2878
157 FORBES DAVID R 836-5256 9
MECCA GRACE MRS 837-2738 4
160 MECCA DAN 835-1211
161 XXXX 00
164 GOLDBERG EDITH B 832-6184
165 BRUNDO JACOB E JR 835-9096
BRUNDO MELINDA A 835-0016 5
SUTTON J C 836-6686+6
170 DUERR JOHN MRS 834-3861
171 CORDES HENRY 832-4825
175 XXXX 00
176 SCHERER J E 832-4013
179 XXXX 00
183 GILBERT ALBERT V 835-9812
X MERCER AVE
189 COLANGELO ANGELO 834-8402
ELSAESSER IDA W 833-3083
193*KOCH ROBT J 835-7474
* 4 BUS 125 RES 21 NEW

EAST NORTH 14203 BUFFALO

X MAIN
X ELLICOTT
72 KENDALL WM 886-0480 1
76 XXXX 00
86 XXXX 00
X WELMONT PL
X ELM
148 XXXX 00

ZIP CODE 14204

X MICHIGAN AVE
177 SUMLING ROBERT 886-3621 2
182 XXXX 00
X MAPLE
199 XXXX 00
207 KING ANDREW LEE 881-1866 0
215 XXXX 00
X MULBERRY
223 TRAYLOR LEWIS 884-2457 3
225 XXXX 00
237*MACEDONIA BAPT CH 886-3489 5
MERRIWETHER T J REV886-3489 5
X MASTEN AVE
X LOCUST
249 TOELLNER E W REV 884-2644
253 DITTRICH BERTHA 885-5828 2
257 SMITH M L 885-1475 5
261 HOLLEY ERNEST 884-8069 5
HULLIE EFFIE 882-5072 9
263 HAWZE JAMES E 882-1827+6
265 BOOKER HERBERT H 881-7094+6
FAULKNER EDGAR 885-7329+6
X LEMON
275 BELL PAUL W 882-3360+6
THOMAS FRANKLIN 883-8009
277 EATMAN JAMES 881-2688 2
283 ARNOLD LUCY 884-5795 9
285 PACE JASPER 884-6738
287 KERSHAW GWENDOLYN 882-5095 0
291 COLES EDWARD I 884-9453 9
X ORANGE
303 XXXX 00
309 PETERS JAS B 886-4003 9
314 BRANCH JOHN MRS 884-1083
316 XXXX 00
320*VILINE BEAUTY SALON886-9435 2
WOOD VILINE 882-4396
322 XXXX 00
X PEACH
332 XXXX 00
336 XXXX 00
342 XXXX 00
343*BETHLEHEM BAPTST CH882-1446 2
346 XXXX 00
350 XXXX 00
353 XXXX 00
356 MASON TECORA 884-6428 4
X GRAPE
358 CLARK DARRYL 881-6470+6
361 BARRETT EDW 886-2547
362 COLE L M 883-9405+6
363 HARRISON JOHN R REV886-3466 9
*TRUEVINE BPTST CH 885-8778 1
368 XXXX 00
370 XXXX 00
X ROSE
X JEFFERSON AVE

ZIP CODE 14211

X TIMON
505 LOWMACK EMMA 886-1088+6
SCAIFE KAREN 886-2601+6
509 FUQUA ELISHA 883-0231 8
JONES LOUISE 883-6364+6
511 XXXX 00
513 ADAMS E D 885-3092+6
X JOHNSON
542 MYLES ALBERT 885-2384
RUSSELL VERNON 881-0123 4
THOMPSON MARSHALL 886-8266+6
543 GASKIN FRED 881-0817 0
WHITAKER MARTHA MRS884-4563
545 XXXX 00
546 PITTMAN WAYNE 885-1092
548 XXXX 00

..EAST NORTH 14211 CONT..

549 CONLEY ROBERT H 886-4117 3
550 HOWARD WILLIS 881-1354 2
551 XXXX 00
553 XXXX 00
X SHERMAN
587 XXXX 00
589 HARRIS ANDREW 892-1088
591 MOZEE JOSEPHINE MRS897-1967 8
MOZEE YVONNE 891-8211+6
600*PATCHED UMBRELLA 896-9315 5
*PRIDE W N Y 1502 896-9420 5
X FOX
608 ROBINSON PEARL 897-4429+6
611 HILL C 893-0191+6
614 XXXX 00
616 XXXX 00
617 TAYLOR WILLIE 891-4084 5
618 STEVENS ALONZIA L 894-7496 9
620 HILL CHARLIE C 896-0119 0
628 CRAY BEAUFORD 891-8608+6
630 XXXX 00
634 DICKENS L 892-1970+6
X HERMAN
* 6 BUS 83 RES 14 NEW

EAST OAKWOOD PL 14214 BUFFALO

X MAIN
8 KENNEDY P 835-9874+6
11 HUFF ALWOOD 832-5835 0
14 SCHABEL M R 832-5520
15 SNYDER ANNA C 833-0842
WILLIAMS ROSE MRS 832-6667 0
17 JACKSON D 836-6583 5
18 HITZEL ELMER C 836-3541 4
MEYER H 835-0024 1
19 DEWAAL IAN 837-3585+6
MAIL BARBARA 837-3585 5
22 JORDAN DIANE 838-6387+6
LOWERY MAY A 832-0168+6
24 BURDETT ORANGE 834-4046 5
25 XXXX 00
28 FROMM RICHARD 837-0089+6
SCHWACH PAUL P 837-8393 5
29 XXXX 00
32 XXXX 00
39 XXXX 00
40 ZEIGLER MICHAEL 835-3761+6
41 XXXX 00
42 BROWN DEBORAH M 835-9694 2
45 XXXX 00
46 HIDALGO LUIS 836-4371 4
HIDALGO MAXIMINO 836-0655
49 XXXX 00
50 MARTIN P 837-1079+6
53 XXXX 00
54 JACKSON ROSETTA 837-2374 2
55 XXXX 00
56 XXXX 00
57 JACKSON PERCY R 836-8098 2
58 XXXX 00
64 BENTON DEBORAH 834-5774 3
65 XXXX 00
66 XXXX 00
70 RICHARDSON LEWIS 837-5625
71 XXXX 00
74 JOHNSON ROBT L 834-0699
75 XXXX 00
76 ALTING SIBERG REG 834-7364+6
77 XXXX 00
78 STALEY MORRIS 832-7143+6
80 LANG ANNA 835-2243
81 XXXX 00
82 FRITZ KENNETH H 837-8716 5
* 0 BUS 46 RES 9 NEW

EASTON 14043 DEPEW

270 XXXX 00
279 WINEGAR OLIVER F 683-8106 0
280 BANDY ANDREW 683-2423
HUGHES JAMES T 684-6981 3
282 NAGY MICHL A SR 684-3764
THUMAN D L 681-3210+6
285 SKRIP FRED 684-1072
286 VENTURA ELEANOR H 683-4621
288 KORNACKI SCOTT 681-2461+6
320 SKULSKI JEROME W 684-8698
326 SHARPE MILTON 681-0427 2
328 BOORUM RICHARD D 683-4280 2
330 SHARPE ORVILLE L 683-2171
334 SHEEHY JAMES F 683-3492 5
336 NORBERG GEO B 681-0670 2
340 GRAVER CHARLES W 683-1302 5
PARKS K R 681-2247 5
342 SINGER A MICHAEL 681-2324 2
344 HAPEMAN ROBERT B 684-5838 2
348 WOJCIECHOWSKI W 683-5009
* 0 BUS 20 RES 2 NEW

EASTON AV 14215 BUFFALO

X BAILEY AVE
19 ARBER NORBERT 894-5856 3
20 DAVIS M E 893-9590+6
SCHROEDER EDW C 895-8633
24 BUSCH ALFRED J 892-7952
25 XXXX 00
26 BANAS HENRY R 897-0912 3
DENTICO SAML 892-6837
29 KOLODZIEJSKI J 893-0637+6
30 MUELLER GEO 893-2811
31 MORAN M E 894-1182 5
34 ROUSH JESS A 895-6642 8
37 XXXX 00
38 ROMANO ROBT A 892-2911
41 XXXX 00
42 HANS AUGUST 895-7118

1971 BEST ST

SOURCE: HAINES



..BERYL DR 14225 CONT..

140 BOGNAR JOS 892-5957
141 HIRSCHAUER MATHW 893-8093
145 SAULINO ANNIO 895-6286 8
149 PATCHILL CHAS 895-4570
150 MURAWSKI RAYMOND 896-5496
153 WILD JOHN L JR 896-7464
156 KOLLER EDW J 892-9748
159 MIRANDO D R 895-1260+1
MIRANDO SALVATORE T895-3565
160 SNUSZKA ANTHONY 894-3478 9
163 EDERER EUGENE JR 895-4247
* 0 BUS 24 RES 3 NEW

BEST 14209 BUFFALO

NO #*OUR LDY LOURDES SCH883-7885
4 ANDERSON ARTHUR 883-4809+1
ASHBROOK HENRY F 882-6080
GRUPP A 884-1090
HAHN HENRY MRS 885-5259+1
JENNINGS EUGENE W 886-1773
KAROLICK STACY 884-9264 9
POWERS THOS J 884-6728
RANSIER EDSON C 884-2908 8
SCOTT RALPH E 883-8436+1
22 HARRIS JOHN G 882-0373
33 GONZALZ ROLAND 886-4352+1
SIMMONS CATHERINE 882-4869 8
35 FLOWERS THURSTON 882-9384 0
MCCLOUD L B 882-8597 0
41 LOGEL EDW W 884-2084
44 HOLLAND J 885-1126+1
46 COOPER JASPER C 885-1240
50 DRAKES HEDLEY V 882-8844
52 HARVEY J W 886-4084
53*CLUB 53 RESTRNT 886-9881
SOBUS ELLIAGGIA 885-7644
56*FRANS DELICATESSEN 886-9669 0
X ELLICOTT
65*CATHEYS CAROUSEL C8886-9658
67 JONES JOANAN MRS 882-9563
68 SMITH L B 882-5674 9
69 CRUTCHER ROBT 882-2376 0
70 DICKSON MACK 881-1435 0
KRAFT ARTHUR F 882-4798
71 WATKINS MARBLE 885-0541 0
73 GIBBS EDNA M 884-2646
74 ROSEBOROUGH MATTIE 883-2419
79*MASTEN CMTY WORKSHP885-5838 0
86 LEFTWICH HARRY S 882-1864
SOUTHALL R L SR REV882-6662 9
X WELMONT PL
93 DIXON LEILA J 882-1078+1
QUARLES MARY JEAN 885-4594
QUARLES STARR 885-4596
94 SEALEY GEO E 882-2265 9
97 COLLETT HAROLD E 884-4967
SCHMIDT EDW W MRS 884-2648
102 GUYTON DOROTHY 884-5204
TURNER WILLIE B 883-8344 9
103 WAGNER CHAS B 885-4983
104 ERDMAN D P 883-6601+1
SIMMONS EDW 884-6104
SIMMONS LILLIE M 884-6104 9
105 ALBERTI FRANK 883-3026
108 SCHWARZ HARRY G 884-4917
SCHWARZ JOANN 884-4917
111 LOWE KENNETH R 885-6531 0
112 MELSON DAVID 886-4845
113 VADEN LILLIE M 886-2216
WHITFIELD JERRY 885-7270 0
115 FARRIS ELOISE 885-3003 9
JONES ROOSEVELT 885-0108
120 SLAUGHTER GERALDINE885-2731
122 LANG EARLY 882-5729
ROBERSON WILLIE 882-5033
X ELM
125*VONCILE REED DELCTS886-9323
126 NELMS PATRICIA 884-4913 9
129 CORNELIUS WILLIE 881-2143 0
131 SWEENEY ALBERT 883-7706 9
134 JOHNSON LARRY 883-5131 0
RILEY SHARON J 881-0946+1
136 CARR QUINCY 884-8893+1
139 MOORE MAYBELLE 886-0712
150*TAYLORS MOBILE SVCE886-8576 8
159 WILLIAMS ERNEST 886-4113+1
161*BEST G I LIQUOR STR882-1330
*GI LIQUOR STORE 882-1330 9
*JOHNSON HORACE C 882-1330 9
163 HUNLEY SIMON L 882-0470 8
THOMPSON J REV 886-8277 9
164 HUBBARD WM 886-6196
166 SNEED JOEL 885-5356 0
167 PEAY THOS 886-6576+1
174 ESTES ANNIE 884-0260 0
178 STANFORD WM P 885-5398
190 BROWN SYLVIA J 886-5021+1
192 HARPER HUBERT 886-5798+1
196 ROBINSON WILLIE 884-2710
WILLIAMS CLEVELAND 884-2746
200 JEMISON SAMUEL J 885-4540+1
206 HOGG R D S 884-3253 0
208 FOWLER ELOISE MRS 885-1177
210 PIERCE WILLIE C 884-9237
212 CALLAHAN SALLIE M 885-4150
SMITH SALLIE M 882-7889 8
216 BUCHANAN EUGENE 882-1848
DAVIS JANET 883-8847+1
222 WRIGHT IRVIN 883-4025+1
X MASTEN AVE

ZIP CODE 14204

X PEACH
329 FRASIER MAMIE L 886-5056 9
JOHNSON JOHNNY 886-5521+1
ROBINSON T 884-1272+1
339 AGEE HELEN E 886-3863+1
341 ADAMS WILLIE 886-8186 0
345 PATTERSON LOLA 886-2157 9
347 JELKS FRANK 885-6028
WALTERS RUDINE 885-4542+1
X RAPE
357 GUESS JUANITA 884-3399+1

..BEST 14209 CONT..

MOSLEY MOZELL 884-3419 9
363 REED ABBIE M 885-1044 8
SANDERS JOHN 884-7036 9
369 CHISM ELVIE 881-1972 0
GREEN WILLIE MAE 883-9527+1
UNDERWOOD WILLIE 882-7536+1
X JEFFERSON AVE

ZIP CODE 14208

401 THOMAS PETER 882-4946
WAFFORD L MRS 886-0606
403 MACK FERDINAND 886-4322
SKINNER IDA M MRS 882-6675
SKINNER LORENZO 882-6675
409*STADIUM LIQ STORE 882-1838
410*HOLDERS WASH O MAT 886-4015+1
413 COTHRAN BESSIE L 882-4833+1
*TRI ME BEAUTY BAR 886-9316
419 OVERTON JOHN G 882-3726
427 BURROUGHS JOHN H 883-6952 0
HARDY MAGGIE 884-1078+1
429 LINA THEO C SR 884-4922
433 GRABP JOS 885-8087
HARPER J J 886-0916 0
435*LINDEGGRAY HTG CO 883-0533 0
REGER CLARA MRS 883-5167
445 MCCARY ROSETTA 883-5826+1
453 CHAMBERS HUEY A 886-4183
*WORTHS LOUNGE 886-8706+1
457 HARDY ARTHUR W 882-2708
458 MARSHALL DURHAM S 883-1402
DIXON ELIZABETH 884-0066+1
460 TILLMAN HOWARD 883-3518
461 WALKER JAS 883-9528
464 MITCHELL ALLIE MRS 886-3426
OWENS DELORES MRS 886-7874
465 GRANT WINSTON 886-4120 0
*GREENS DELICATESSEN886-8640 0
SEASE ALTON L 882-7366 9
466 ANDREWS ELIZ A 884-4823
WILLIAMS EARLENE 885-2607 0
469 TURNER COLONEL 882-7572
470 HALL WM JR 883-4410 8
JONES CHAS 884-3483
472 BARBOUR DOROTHY 881-2090 0
473 MEADOWS L J 883-4971+1
476 JACKSON ANNIE 885-6609
477 AUSTIN HILDRATH 884-3442+1
480 GURGANIOUS ALTON 883-8427
485*BLACHOWICZ ROBERT 881-0642+1
*NY ST NARCTC ADDCTN886-1425+1
X TIMON
488 THORNTON FRANK N 886-5371 8
492 CLARK JOHN 886-7658
WATTS LUTHER 882-0253
494 FANT ROSA MAE 884-1257 9
WOODRUFF FRANK J 885-3128 8
496 HALE BARBARA 886-5193+1
498 HALL W 886-7564+1
500 DAVIS HATTIE 885-2980 9
502 HILL COLUMBUS MRS 886-3578
518 FUNK A L MD 883-0965
528 KELLEY ALBERT E MRS886-3538
530 FLIERL ALEXNDR W 886-5911
*FLIERL RAYMOND C 884-3300
*NIGRA SEWNG MCH SLS884-3300
534 BRUCE ROBT W 884-3205
GROH RICHD 885-1485
MAYLE HERMAN F 885-1485
537 JOHNSON LONNIE A 885-9647
541 EDMUNDS U M 884-1573 0
543 HENDERSON S M 883-6592 0
PISKORSKI JOHN 882-3696+1
548 CORAM LEVI L MRS 886-7308 0
*DARRMICH BUILDERS 884-8041+1
*MILLOUGHBY LUKE S 884-8041
553 CAPPS INEZ B 885-6840
MONTGOMERY C W JR 885-0225
555*BEST BARBRGBTY SHOP883-5935
*GAMBACORTA MARIANO 883-5935
556 CLINTON LEE 883-7279 8
HUMES EMANUEL I 882-7756
557 BRYANT MARION L 884-5327 9
LAPETINA ALBERT DDS886-4430
563*HALPERN PHARMACY 885-7690
SCHWEIGERT NORBERT 886-6837
X SHERMAN
571*SAXON&MERRIWEATHER S886-8809+1

ZIP CODE 14211

X FOX
623*PILGRIM ST JAMES CH892-0985 9
X HERMAN
X WEST PARADE AVE
643*GOOD SHEPHRD EUB CH896-7276
LITTLEJOHN M L REV 896-7276
653 VANDERBUSH FRANCES 892-8610
657 WATTS V J 895-2889 0
661 CIESLA THEO F MD 896-7138
X GUILFORD
673 POE JOS A 893-8748
675 ROTHBALLER OTTO MRS895-5502
681 DUKE WALTER F 897-2983 0
683*CMNTY MSNRY BAPT CH896-7857 0
HOLLEY W JR REV 896-7857 0
685 TOWER LESLIE G 895-8072+1
687*LULU BELLE RESTRNT 896-9579
X RICH
697 DEE HENRY W 895-0040
MUELLER GEO J 894-3275
699 HARDRICK CURTISS 896-7033 0
ZUREK RUDOLF 894-6754
701 FINSEL GEO 892-3705
703 REED DORIS 896-1550+1
711 ADKINS THOMAS V 897-2735 0
EICKNER HELEN C 894-9057
713 CHEATOM GEORGE R 896-7459+1
PETERS ELAINE 897-0384 0

1971 ELLICOTT ST

SOURCE: HAINES



..ELLICOTT 14203 CONT..

455*HEACOCK NOEL A VET 852-8276 0
*MCCLELLAND F JR VET 852-8276
*MCCLELLAND R B VET 852-8276
*MCCLELLAND VETRNRY 852-8276
461*LANG G MTSGPROVSNS 852-8350
475*WEHLE ELEC CO 854-3270
*WEHLE ELECTRNCS INC 854-3270+1
477*FINGERET BROS INC 853-3340 9
481*FINGERET BROS INC 852-1300
501 ARLOTTA ANTHONY 852-6077
*EVER READY TV SVCE 854-8685
FOSTER JOHN R 856-1084+1
FRISCO JENNIE 853-1416
KNIBBS RAYMOND E 854-6881
*KOPACK WESLEY C 854-8685
NOWAK EDW B 856-8331
513 MOORE CLARA 853-8847+1
RICHARDSON E JR 852-6376+1
515 SHAW JAMES J 856-5675+1
WATT FRED L 853-5904 8
519*STERLING WKS INC 852-2123
520*BUDD DISTRIBUTORS 854-3830
X EAST TUPPER
587 CURTIS A J 852-2919 9
DOLL C F 852-2919
X GOODELL
X BURTON
674 DALEY JAMES F 856-8873 0
*ULRICH RESTRNT 854-9575
X VIRGINIA
682 FISHER JOHN H 852-6867 0
686 PLATE VICTOR 853-0215
687 FAULKNER MARLINE 853-6588 0
690 WILD JOHN H MRS 852-1518
691 KENNEDY DAVID A 852-3886
WEEKS FRANK C 852-4145
693*MAYORS HUMN REHBLTN 852-4145
*SIX NINETY THREE 852-9697
694 RAO RAGHAVENDRA C 853-0263+1
SIEMIENOWSKI LUCINA 853-8829
699 STEVENS JAS 854-4841
703 KNAPP EDITH 854-2793
704 BOYLE SARAH J 852-6739 0
708 DUBICKI KAROL 852-1287
MIKULSKI ANDRZEJ 854-3745 0
SOBIECH PAULETTE 854-7703 9
709 POMPILI H R 854-3158 0
710 ANTONELLOS JAS 852-1215
711 SIGAREW ALLA 854-8278
715 KOEHLER FRANK 854-2433
717 NOSTADT HELEN MRS 854-7461
720 KUBIK ANNA 853-0758 0
SCALE JAMES 853-5720+1
721 BOYCE GEO 853-3590
723 CALOS ANTHONY 854-1839
724 NITZER ALFRED 853-2749
WAGNER MARGARET A 853-0835 0
728 GANDY JOHN A SR 856-3751
731 LEBER JOS A 853-3738
732 COLLINS LOUIS H 853-4729+1
KIRKLAND MAE 854-0304+1
735 BOZZE MARTHA G 854-6691
KARN MARIE 853-0595
738 COLEMAN IKE JR 852-7144+1
739*BUFLO CTY RELOCATN 853-8590 0
X CARLTON
752 BIANCHINI LOUIS 884-4752
SWAN CLAYTON C 882-4511
756 CORDNER ROBERT D 882-2015+1
760 ULASZESKI EDW J REV 882-2987 0
766*CHRISTMAS SEALS TB 886-4655 0
*EMPHYSEMA TB ASSN 886-4655+1
*SALLAK V J 886-4655
*TUBERCULOSIS HEALTH 886-4655
770 ABELLA JOS 883-7158
774*RELIABLE RADO SLS SV 883-1416
782 POTTS CATHERINE 883-8556+1
783 HEINRICH ALFRED C 884-3551
788 DABROWSKI ALBIN B 884-8426
MAXWELL EDW J 883-1623
792 PARAVALOS JOHN 885-1899
PARAVALOS LOLA MRS 885-5307
797 EDDY ARTHUR 886-6797
802 RAMSEY ELIZABETH 883-6167+1
TRAUTMAN ELEANOR M 886-2243
X HIGH
X GOODRICH
854 BROWN HYACINTH 884-2863+1
COMBS MARGARET C 886-7222
866 WISTNER THEO 884-8369
870 YAHLE FRED V 882-3495
872 KONDRASCHOW TANJA 882-2496+1
876 NOVITZKI WM 886-1124
878 SHELTON WALTER W 882-1947
X E NORTH

ZIP CODE 14209

890 WELCH JUANITA 883-7040
894 GEIGER TIMOTHY REV 883-1613
HARRISON JOHN 883-5274 9
898 KOHLBRENNER RUTH E 885-3461
MCCARTHY M E RN 883-2654
900 HARRISON WALTER 882-6813
903 MOYE ANNIE 886-6468 8
905 FARRIS BETTY 885-5792 9
913 MOLLENKAMP C C 883-4127
X ST PAUL
935*AAA WINDOW CLEANING 884-1715
*MAIN BLDG MAINTNCE 884-1715
*MAIN WINDOW CLEANNG 884-1715
938*EMPIRE CUTNG TL SRV 884-6919
X BEST
967*P R WIRE FORMING CO 883-6644+1
969 EDWARDS M 886-3212+1
JOHNSON OSCAR LEE 884-8458
971 COMMODORE BONITA 886-7883 0
980*ANIMAL REPELLENTS 882-5905
*OSMOSE WOOD PRESERV 882-5905
*POLE SPRAYERS INC 882-5905
*R W MAINTENANCE SV 882-5905
*SURDAM JOHN L 882-5905
X EDNA PI

..ELLICOTT 14209 CONT..

991 DIXON WM 884-3961
JACOBS EUGENE 886-4503+1
996 WHITE MAGNOLIA 886-0519 0
997 SHAW VERNON 885-1977 9
1002 OPOKA SILVESTRO O 883-5263 9
REED MARY E 883-1671 9
SAMMON V D 882-1987
SAMUEL MIKE T 885-0282 8
1007*CALVARY CME CHURCH 886-8557 0
LIGHTSEY JOS H REV 886-5843+1
1010 WALKER JIM D 882-1280 8
X DODGE
1042 BRESLIN WM P 883-8442
1044 SMITH WILLIE 885-3570 9
X COE PL
1050 CALHOUN A 886-5773+1
STEVENSON JUNIUS 883-6764+1
1054 JOHNSON CHAS A 886-8265 8
1056 WILSON JESSIE 881-0358+1
X SOUTHAMPTON
1059 SIMON B 883-6190 9
1061 GREEN MARY MRS 884-4633
1063*RHODES JOHN 886-8943
1066 WAIRE AARON 882-0073
1069 GRANT FANNIE F 883-2895
1070 MAUERMAN ROBT E 884-7148
1075 GIRTON LEON 884-5781+1
X NORTHAMPTON
1094 SISTER MARIE J 884-5277 0
*SISTERS OF ST MARY 886-1913
1097 GIBSON CEDRIC 882-9655+1
1098 MONTGOMERY DOROTHY 884-3999
1101 JOHNSON WALTER 884-5654
MYLES LIVINGSTON 886-3706 0
WRIGHT WILLIAM F 884-7622 0
1102 CARR A MRS 883-5336+1
FLAGG JOHN DAVIS 886-8261
1113 WILLIAMS WILBERT 884-9319
WOODS VIOLA 886-7947 0
1117 DURSHORDWE THOS G 883-0179
SUVER J A 884-3022 8
1121 HAIRSTON GLADYS 882-3850+1
1123 DESJARDINS ESTHER M 884-0515
1131 NELSON KATHLEEN 883-4586
NORMAN RUTH REV 883-0397
1135 SMITH THOS J 884-3769
1137 BATTS LESTER 882-4298
1141 FRAZIER LUCIOUS 885-4795
X RILEY
* 154 BUS 122 RES 38 NEW

ELLICOTT 14006 ANGOLA

9583 PEZZIMENTI JOS F 549-0854 0
* 0 BUS 1 RES 0 NEW

ELLICOTT N 14221 WILLIAMSVILLE

SEE NORTH ELLICOTT

ELLICOTT S 14221 WILLIAMSVILLE

SEE SOUTH ELLICOTT

ELLICOTT BLVD 14150 TWN OF TON
P.O. ADDRESS TONAWANDA, N.Y.

10 WEBER KARL E 693-4008
15 REID HILMER A 694-2948
30 HAAS WM L 693-2345
* 0 BUS 3 RES 0 NEW

ELLICOTT CT 14150 TWN OF TON
P.O. ADDRESS TONAWANDA, N.Y.

4 BECKER ANNE B 693-8287
10 FOOTE DANL C 692-2445
16 MARTENE FRANKLIN 695-2443
17 HENRY DONALD B 695-3470 9
20 BEAN RUSL G 693-0926
21 GRIFFITHS JOHN 692-3669 8
24 LANGER PAUL H 693-0158
* 0 BUS 7 RES 0 NEW

ELLICOTT PL 14043 DEPEW

14 MCAFEE M B 683-2707
SOSNOWSKI RONALD A 684-0398+1
16*DANIELS RESTRNT 683-9605 0
*ELLICOTT MANOR 683-9605 9
61 CYBULSKI CASIMER JR 683-4960
71 ZIEMBA ANTHONY J 683-5570
77 SIERAGA JOHN 683-1034
83 KRAWCZYK SOPHIE 684-6987
PALICKI PETER C 684-8591
85 FREDERICKS D M 685-1311 8
PLECHA WALTER 683-5181
99 SANDERS WILEY F 683-7640
107 KUPKA LOUISE 684-2052
111 SCHEIDWELLER JOHN 684-9510+1
115 STEMPKOWSKI LEO M 684-9276 0
119 KALIETA JOHN 683-8840
125 PARYSZ EDW 683-9271
131 LEGOCKI JOS 683-5825
* 2 BUS 16 RES 2 NEW

1971 GOODRICH ST

SOURCE: HAINES

GOODRICH 14203 BUFFALO

X MAIN
26*ALEMITE OF BUFFALO 883-5440
X ELLICOTT
112*BUFLO HOSP NRS RES 883-1324+1
ILYKO MARYANN 882-0966+1
OTT L E 883-2140+1
SOTTILE B 884-5669+1
X ELM
* 2 BUS 3 RES 4 NEW

Report ID: 23022300643 - 03/01/2023
www.erisinfo.com

1971 MICHIGAN AVE

SOURCE: HAINES



..MICHIGAN AV 14203 CONT..
842 GOER HASKEL 852-5121
845 COOK BERNARD 856-0145 0
WILLIAMS NORMA H 856-2573 0
846 HOWARD FRED D 852-4264
PARISI FRANCES 853-2954
847 BARKSDALE FRED 854-4836
NOLAN DENNIS 852-2248
851 SHAPIRO JACOB M 852-1096
854 PAYNZ WM 852-2079
855 HICKS ETHEL 853-5659+1
856 KNIGHT MITTIE 854-4682 8
860 JOHNSON KEITH R 852-6277+1
SIMMONS ESSIE M 856-9792
861 BLACK HARRY 854-3253
JOHNSON JESSE 852-7511
862 MORRISON M 854-7666+1
UNDERWOOD OTIS 856-3928+1
866 GADDY ALICE M 853-7549 8
869 PARKS CYRUS 854-0337
870 PARISIEN FRANK 853-7854
873 HOWARD BERT S SR 852-2246
STEARNS L 856-0263 8
874 THOMAS CARNELL 852-6548
875 DALE ROBBIE LEE 853-4117 9
IVY NADINE 853-3471 8
LEE OTHA R 853-8953 9
WARE JESSIE L 853-8168 0
876 WEBSTER ROGER B 853-4867 0
877 JASINSKI WM 853-5198
879 SPEARMAN HELEN MRS 852-7693+1
WESTBROOK ALBERTA 856-5062
880 ANDERSON DORIS A 852-3653 0
883 HOLMES GEO 853-9332
X VIRGINIA
889*MR BENS BARBER SHOP854-9769
899 WHITE JOHN MRS 852-3225
901 BRYANT LLOYD H 854-0379 9
905 BITTLES ANNIE 852-8199
907 KEMPKER WM 856-8355
909 MITCHELL ANNIE 853-4398
913 JOHNSON MARGARET 854-8540+1
917 GIBSON JAS E 856-1878
REESE M C 854-2495+1
921 BANKS ELAINE 854-1469 0
JACKSON EDW 854-4415
X CARLTON
955*ROSWELL INST EMP 845-2330+1
*ROSWELL PRSNL INF 845-2320+1
975 JAMES LORENE 886-4980+1
977 REED MAMIE 884-0760 0
983 GARNETT THELMA A 883-3260
STEWART WILLIE 882-5931
985 THOMPSON JAS 882-1323
987 HEROD MARY L MRS 886-0053 8
989 THOMPSON FRANK 884-7943
993 POPE JERRY D 885-4653 8
997 ANDERSON LOLA M 884-0265 9
1001 VARN SUSAN MISS 884-8738
1007*HIGH ST PRESCRIPTN 885-5717+1
X HIGH
NO #*RESS GULF SVCE 886-9641
1027 BINK JOHN H 885-1249+1
1029 MORAN M T 882-7010
WANSART EDW M 884-2550
1031 MACKIE ARTHUR J 882-2480
MURRAY ELLA M 885-6937+1
1033 NICHOLS ROBERT LEE 886-2198 0
SHAW JEWELL 886-0679
1035 SMITH MICHAEL 883-6149 0
1039 KIRKWOOD FRANK C 886-0423
1043 DAVIS ANNA 882-6497
DAVIS FRANK 882-6497
JACKSON HARRY 884-8960+1
X GOODRICH
1045 JOHNSON ALLIE 886-3595
SMITH WALTER JR 886-7080+1
WOODS HERBERT JR 882-3888
1049 COSTON EUGENE 886-5028 0
CURRY PAULINE 886-7207 0
1053 LONG ELEANOR MRS 885-5393
1057 SCHIESEL EDW 885-2437
1059 RIES JOS W 882-3131
1065 TRAUTMAN GERTRUDE 883-9349
1069 SCOTT HENRY 882-5257
X E NORTH

..MICHIGAN AV 14209 CONT..
1167 SMILEY JOHN 882-9279 9
1171 HUNTER ELZER 886-2177
1173 GARRY LOUISE 884-9252 9
JACKSON CAROL A 883-5604+1
REED EMMITT 886-4940 8
SMITH DOROTHY 883-6138 0
1174 BROWN SAM 883-1217
MOORE EDDIE 886-2889
1175 WIDEMAN MILDRED I 883-3735 9
1176 WILLIAMS VIOLA 882-8507+1
1184*IMPERIAL CYCLE SLS 884-2040
KEHE AUGUST J 884-2040
KEYS MARY A 882-4738
1188 MOKARICAS GEO 883-8731
1189*SEL ECT SUPER MKT 884-8442
X DODGE
1199 BONNER ALBERTA 882-2510 0
WOLFE MARIE B 884-1582 8
1200 GREENE RAY 882-1312+1
HALL ALTHEA O 883-2742+1
JONES EMANUEL F 883-2677+1
1202 CHAMBERLAIN RONALD 886-2221+1
1206 DOCKETT GERTRUDE 886-1434 9
MARTIN GEO 882-2142 0
1207*FRITZS DELCTESN 883-1418
1208 SALTER LOUISE M 885-3917
1209 LITTLES MELVIN E 883-5712+1
1210 HARRIS DEMETRIA A 886-6677+1
HARRIS DOROTHY MRS 885-0783 0
1212 MCNETT JESSE 884-0004
1213 BROOKS AGNES 884-5873+1
JOHNSON ELZATA 886-0879
1214 KELLAM HAROLD F 883-2974
1215*ELZATA BEAUTY SALON886-9383
1217 CAGGINS DESSIE 883-0381+1
1218 BENSON CHAS 886-2222
WILLIAMS DAVE 882-0741
1220 KING MAMIE 883-2331
RUDOLPH FREDDIE 885-6360
1221*PARKER FABRIC CORP 884-4080
*PARKER NELSON T 884-4080
1233*THIRTY GRAND RSTRNT886-9524 9
X SOUTHAMPTON
1236 DIXON MCKINLEY M 882-3945 0
1237 JOHNSON LILLIE 882-9543
1239 GORDON SAML 882-6709+1
1241 JONES VERTONIA 884-6940
TURNER MARY 885-7051+1
1242 ROGERS HEBRON 882-1672+1
1243 PELLOW RICHD A 883-6278
WEEKLEY SADIE MRS 885-1431+1
WEEKLY SADIE MRS 885-1431
1244 ANDREWS ELIZABETH 883-0569 9
HALL EVA T 882-2146
LEWIS GWENDOLYN 883-0569 9
MURPHY ELOREDGE 884-7365
1249 PRENATT LORETTA MRS886-0260
1250*FLAMINGO LOUNGE 886-9456
SIMPSON MAE 881-0365 0
1257*TWENTY GRAND 886-9578
1261*STARLITE DELICATESN886-8946 0
X NORTHAMPTON
1262*PETS LAUNDRAMAT 885-2252
1263*COOKES LIQUOR STORE885-8123 0
1265*RUBYS BEAUTY LOUNGE886-8573+1
1266 ROBINSON GEORGE 886-2999+1
1267 WEIRCH ADOLF 884-0677
1269 WILSON MARION 883-5217+1
1270 RICHERSON MABLE 886-8350+1
1272 DAHL HOWARD J 883-4665
1275 WASHINGTON SADIE 882-1716 8
1279 BUTLER FLOYD 882-7052
SCOTT JOHN W 883-9257
1280 ROBERSON EQULA MAE 886-1299 0
WALTON ALBERT 886-8237 9
1281 DOCKERY WM M REV 884-3964
FOSTER LILLY 886-2872 0
1284 DANAHY RAYMOND MRS 883-3874+1
1288 DAVIS WILLIE 885-0760
RODRIGUEZ LEOLA 882-4281 0
1292 BLAKE BERTHA 883-0372 8
BLUE JAS 885-0716
BLUE JERRY 884-2649+1
1296 QUARLES LILLION 884-0113
X EATON
1298 GRESHAM LEE 885-0433
1302 BURTON JOHNIE 884-2318
1303 BARNES MARY R 884-1170
BARNES NATHL 884-1170
THOMAS WILLIAM 883-7048 0
1304 WYATT THELMA 883-1253
1311 BATEMAN BETTY SUE 886-5803 9
1312 ROBINSON SUSIE MRS 883-9166 9
1315 DUDLEY B 883-9334+1
GRAY ROBERT L 881-1137 0
1318 HUDSON ALLEN E 885-0976
1319 WINTERS JENNELL E 883-8967+1
1320 HATTEN A M 885-7528+1
1323 PUGH WADE 885-3859
*SAMS COIN LAUNDRY 886-8678
1325*RADIGANS DELCTSN 886-9034
1327*CARYS AUTO SVCE&CO 886-9312+1
X RILEY
1331 MILLER MICHL 886-6699 9
1337 KILLEBREW JOHN L 886-2068+1
1339 BOWE WILSON 884-9154+1
1341 DAVIS MARION 883-8235
X LAUREL
1364 HANNON ALEX 885-6068+1
MADISON EUGENIA 882-8526
1365 ROBINSON JOHN R 882-5172
1366 BROWN JESSE 885-1650 0
NORMENT R MRS LPN 884-3006
1368 BAILEY L 882-2748
SMITH EDNA 886-5502 9
1370 BEDFORD WILSON M 882-1116
1371 BAKER MARY ALICE 886-3867
1372 COLEMAN ANNIE 886-3523
HALL GEO 886-4179
1373 ALLEN MARY 886-0895+1
BROWN C 886-0534+1
1375 HALSELL E 882-5014 9
MARION THOS 885-0103
1377 BARBER ALICE C 886-1823

ZIP CODE 14209

1083 WILLIAMS J 885-7845+1
1086 GARRETT ROGER F 884-0724+1
1091 MASON CLERMONT B 885-3988
1095 DUGE M D 883-5491
1096 HEFFNER BEN J 883-9497
1098*LYLES JOHN F D REV 886-1279
1100 SCOTT SARAH L 884-4742 8
1104 ELLIOTT JOHN 886-1879
1107 SANDERS ROBT 886-0558
SCARVER HUEY 882-6674+1
1111 ORTH FRANK MRS 884-4347
1112 GARRISON EDITH F 886-0058
JONES JEREMIAH 882-2451 9
1114 COTTRELL SARAH J 884-4065 9
1116 DAVIS JOS 883-4143
1117 HILL PEARL 883-4311+1
SCOTT ESSIE L 882-4473+1
1119 BORON ANTHONY 882-5139 9
X BEST
1137 ATKINS JANIE 886-1684+1
POUMPEY JOHN 883-5973+1
1141 ALEXANDER JAMES 881-1685+1
1144*MOYNIHANS COLLSN SV886-9655
1145 JOHNSON BRENDA J 883-0779+1
WARD EDDIE MARY 883-0779
1148*TUTTON ELEC CO 884-7686
1149 ELLINGTON JOHN R 884-2577 9
1155 FOSTER MARGARET 885-7469
MURPHY ANN 883-7471+1
1157 TODD WILFORD 886-4602
X EDNA PL
1164*COUNTY PEST CONTROL883-2538 9
GAMEL L A 883-2538 9
1166 COOK ODIS 882-9540

..EAST MORRIS AV 14214 CONT..
MILLER EDITH I MRS 836-7350 9
SWAMY V C 832-0132+1
WAY ERNEST N 837-9825 9
37 BRENNAN A M 836-1762+1
HALLINAN JOS O 834-4086
HERMANN L 833-7005+1
IOVIERO D P 836-5972 8
LEBOVITZ E L 836-2099+1
TRAISE H M 835-3163+1
WISE JEAN SOLLE 832-3123
X HOLDEN
47 JOERGER P S 836-0003 9
SZOKA EDW V 832-8248
51 DREHER EUGENE C 834-5622
KRANTZ LEONARD 834-4576
52 DURKIN JOHN MRS 834-7189
MCCAFFERY ALEENE 834-7189
55 JACOBSON JOS 835-2241
SELLERS BERTHA 834-1643
59 DARE MILDRED H MRS 837-1479+1
DEAL C ROBT 836-8497
63 ALFF C 833-0312
66 GUGINO ANTHONY DDS 834-7658
67 LEMOINE PHYLLIS 837-2475+1
ROSE JAMES P 837-2634+1
STOLL KAREN 837-2475+1
71 BATT ANGELA M 836-3481 8
SCATCHERD M W 833-5068
75 CARUSO LAURA MRS 834-5015
KELLER EDWARD M 832-8457+1
78 KAESSER ORTON 834-4642
79 CHITTENDEN DAVID M 833-4348
STEUERNAGEL J MRS 834-2129
83 RUMSEY THOS L 834-4899 0
SEYMOUR LAWRENCE D 837-8463+1
87 PHELPS HARRY B 834-2930
WILPERT LEON W 837-6302
91 BRETT LESTER W 833-8704
DAVENPORT ORMUS W 833-5381
X BENWOOD AVE
95 CURRAN JOHN E 833-4976+1
96 OHARA EDW J MRS 832-9685
99 LYONS JEROME J 835-4590
SCHNELL WALTER W 836-5878
100 FREEDMAN WM 832-8443
*GOLDMAN J L AGCY 834-7811 8
GOLDMAN ROSE 836-0599
105 CLEMENTE WM M 833-2949
MEAD GAYLORD P 835-9263 0
106 HORNE M C 832-0811 9
LEE RICHARD T 838-2382+1
107 ARNO MICHAEL J 832-6609+1
CONNERS DAVID R 837-1233+1
110 PIDGEON REX E 833-0287
111 HENRY A W 833-1704
115 CUTRONE JOHN 835-0975
MORGANTE MICHL 833-9389
118 PIDGEON V 834-8955+1
119 DIJAMES DANL J DDS 834-7029
NUGENT PIERCE E JR 835-8123
123 KRUSHEL WM 832-6844
127*FIRE FIGHTERS SV EQ837-9115 0
SCHUPP GEO J 835-7504
*VACCARELLI CARML FR837-9115
137 LESSWING THOS P 832-9192
SCACCIA FRANK 832-9192
X HILL
141 THURBER HOWARD E 834-0852
WINTERMANTEL A F 833-8595
145 BRENDEL JOHN M MRS 834-4321
NOLLER DAVID C 834-4321
148 BEUCHE FRED J 834-9885 0
HENZLER E 837-8338 0
149 BAKER JOS J 833-6814
152 DICKEY HOWARD W 833-2322+1
RIEMAN CARL A 833-4751 8
153 BEHRENS B C 834-3242
QUITT BENJ A 834-4852
156 REESE MARY K 836-2878
157 FORBES DAVID R 836-5256 9
GRADY L H 836-1711 0
160 MECCA DAN 835-1211
161 FIELD JAS 833-2459
164 GOLDBERG EDITH B 832-6184
165 BRUNDO JACOB E JR 835-9096
JUSKUS P M 834-0649 0
170 DUERR JOHN MRS 834-3861
171 CORDES HENRY 832-4825
175 MATTHEWS CHAS H 833-4557
176 BARNES JACK 833-7341+1
MARSHALL RICHD J 833-7341 0
SCHERER J E 832-4013
179 WIECZOREK J S MRS 832-3402+1
183 GILBERT ALBERT V 835-9812
X MERCER AVE
189 COLANGELO ANGELO 834-8402
ELSAESSER IDA W 833-3083
193*KOCH ROBT J 835-7474
* 4 BUS 140 RES 26 NEW

EAST NORTH 14203 BUFFALO

X MAIN
23 MEYERS JOHANNA 882-6694 9
POLING L J 885-6777
25 WENDEL N L 884-0232
27 JONES M 884-2535
35 CONRAD EDGAR 885-1377
39 BILES DAWN 886-0087 0
41 HOBBS H D 885-2638+1
PARKER M 883-8327 9
54*ELLICOTT GARAGE 884-8582
*NORTH ELLICOTT GARG884-8582
X ELLICOTT
68 TRAYLOR ZACK 886-6081 8
70 COUNTS JUNE L 886-6920 0
HARRIS BENNIE 881-1491 0
JAGADOWSKI SADIE 883-4703
72 HENDERSON ESSIE 886-5041 0
KENDALL STEPHEN D 885-2757+1
KENDALL WM 886-0480+1
76 OWENS EARL L 883-8168+1

EAST NORTH 14203 CONT..
80 BROWN GEORGE 883-1874 0
86*NELSON D CLLSN&PNTG883-7050 0
94 WILSON WILLIE LEE 882-3861 9
96 BELL WARDEEN 882-1524+1
X WELMONT PL
108 REED HAZEL JR 886-1268+1
110 DIXON JANET MRS 883-0506+1
DUKES M J 885-8661+1
*VERDELL L BTY SALON885-9115 8
114 SMITH M A 886-0588 0
118 CARLTON SAM JR 886-7475 0
WINGARD JAS C 884-4783
120 MOORE ROBERTA 886-0821+1
124 MAJORS CLARICE MRS 885-6648+1
132 GRANDILLO JOHN 886-4229
X ELM
140 STURM ANN 886-5269
148 MATTESON CEIL 882-3222
150 SAWDAY ALBERT 886-1909
152 NOON ANN 885-5785 0
156 HATCHERSON C JR 881-1958 0
158 MOSELEY CLEOPHUS 883-1323
STOVALL D J 884-2733 0

ZIP CODE 14204

X MICHIGAN AVE
182 GUYTON WILLIE 883-0463
MORROW FRANCES MRS 885-8079
MORROW SIDNEY 885-8079
X MAPLE
197 JORDAN ROSIE LEE 882-8397+1
KING SIDNEY 882-2117+1
207 KING ANDREW LEE 881-1866 0
215 MCCLAIN ALBERTA MRS884-2836+1
*STRLGHT CFESODA 886-8540
X MULBERRY
223 ALEXANDER JAMES 882-1876+1
225 PEOPLES CARRIE 883-6566+1
VANOY RICHARD 883-0543+1
237*DALLMAN M H REV 883-1605
*MASTEN PK BAPT CH 883-1605
SHAW ISHMAEL L REV 883-1605 0
X MASTEN AVE
X LOCUST
249 TOELLNER E W REV 884-2644
257 SMITH JAS 885-1475 0
261 HOLLEY LENORA 882-3021 9
HOLLIE EFFIE 882-5072 9
265 BOOKER HERBERT H 883-4297+1
X LEMON
275 THOMAS FRANKLIN 883-8009
283 ARNOLD LUCY 884-5795 9
285 PACE JASPER 884-6738
287 CLARK D 881-0712+1
KERSHAW GWENDOLYN 882-5095 0
291 COLES EDWARD I 884-9453 9
X ORANGE
309 PETERS JAS B 886-4003 9
314 BRANCH JOHN MRS 884-1083
316 JONES JAMES 883-6795+1
320 GUESS SHELLIE N 885-5945+1
*VILINE BEUTY SALON 886-9435
WOOD VILINE 882-4396
322 MCNAB ERNEST A 884-4336+1
STEWARD LENWOOD 884-7846+1
WILLIAMS CORNELIOUS883-3852
X PEACH
330 WILSON JAS 886-3755 8
332 ANDERSON D L 883-4743+1
FOUNTAINE LUCY 884-8139 8
336 BENEFIELD SAM JR 884-0736+1
342 PRIMM HENRY L 884-3193+1
WHITE EDGAR L 884-1469
343 WILLIAMS A REV 885-8520 0
346 STEWART EDNA 884-6267+1
356 MASON TECORA 884-4058 9
X GRAPE
361 BARRETT EDW 886-2547
363 HARRISON JOHN R REV886-3466 9
*TRUEVINE BPTST CH 885-8778+1
X ROSE
X JEFFERSON AVE

ZIP CODE 14211

X TIMON
505 ENGLISH LESSIE 881-1345 0
GREENE JAMES 886-3143 0
507 PEGGUES C A 884-2502
509 FUQUA ELISHA 883-0231 8
511 OLSZEWSKI FREDK 885-6006
513 NEUROHR JOS G 883-8367
STEINKIRCHNER L 882-0168
515 BURTON TROY A 881-1358+1
PATILLO E J 885-9317
X JOHNSON
542 MYLES ALBERT 885-2384
543 GASKIN FRED 881-0817 0
WHITAKER MARTHA MRS884-4563
545 LOWE LESLIE MAE 886-2291+1
546 PITTMAN JAS 885-1092
PITTMAN WAYNE 885-1092
549 RIVERS WILLIE 885-8869
551 BURKES GENEVA 886-2812
553 GASKIN N 885-7023
X SHERMAN
587 HALL VONDALYN J 895-4963+1
589 HARRIS ANDREW 892-1088
PEOPLES ALICE 893-8124 0
591 MOZEE JOSEPHINE MRS897-1967 8
593 LEWIS ANN 896-3829+1
600*BROWNIES UPPER TRR896-9426+1
601*CLOVER FARM STORES 896-9258
*SCHNIDR CLVR FRM ST896-9258
X FOX
608 PERINE ALBERT 896-0365
611 LEWIS WILLIE R 893-8159 0
WARD RAYMOND 895-4384 9
614 EDGERTON I Y 894-1375+1

1971 NORTH ST E

SOURCE: HAINES



BEST—From 1119 Main east
Zone 9
4-16 Best Apts
1 Cleversley Eddie
2 Roberts Amelia
3 Bernard Ann Mrs
4 Knight Donald M TT4-1090
5 Fitzpatrick Leonard
11 O'Hara Florence M TT2-8532
12 Sellig Dorothy Mrs
14 Dannebrock Richd H TT6-6366
15 Overmire E G
18 Schweigert Florence B TT4-6253
20 Ashbrook Henry F TT2-6080
22 McMahon Frank TT6-4459
23 Bernas Charlotte B TT4-6032
24 Brumb Louis L Mrs TT3-5436
25 Vacant
26 Larrin Vincent
27 Tomasleli Norma
28 Brenzel Mildred C Mrs
29 Saxon Myrtle

30 Powers Thomas J TT4-6728
32 Loughney Thomas W TT3-9276
33 Pitass Dorothy TT4-3955
34 Weber Edw
35 Sommers Kate Mrs TT5-7829
36 Jennings Eugene W 886-1773
37 Buja Anna
38 Gamrath Lillian A
39 Linderman Esther A
Street continued
22 Keough Daniel 888-8399
Harris John G ◎ TT2-0373
25 Stevens Morris A
rear Smith Sam A ◎ 886-1465
Gathers Wm
26 Glover Josephine
Holmes Sarah E ◎
30 Burdett Clarence P TT4-7818
31 Vacant
32 Collin Helen Mrs TT6-7226
McDavis Bertha Mrs ◎ TT6-7226
rear Little Gladys Mrs
33 Vaden Hattie Mrs
Smith Phyllis J TT2-2764
35 Robinson Sophia Mrs
Jordan Willie L
36 Jefferies Mathew 885-3144
Johnson John L TT2-8281
rear Bush Barbara J 884-3649
38 Calhoun Willie Mae
Johnson Annie Mrs
44 Ali Nourooz TT5-7721
Carter Janah Mrs 885-7721
44½ No Return
45 Niagara-Mohawk Power Corp (sub sta) TL6-2424 ext 407
46 Cooper JasperC 885-1240
50 Drakes Hedley V ◎ TT2-8844
Morton John
52 Harvey Johnson W ◎ 886-4084
53 Sobus Elliaggia TT6-9881
Club Fifty-Three restr TT6-9881
56 Ray Edmund
Ellicott intersects
65 Cathey Carousel Club
67 Melson David jr ◎ 886-4845
68 Redmond J Patrick TT4-3279
69 Johnson M C 884-8232
70 Kraft Lily Mrs ◎ TT2-4798
Nyberg Kenneth 884-7190
71 Cofield John
72 Connors Howard
73 Swain Berry TT3-1036
Gibbs Edna M ◎ TT4-2646
74 Cox Mattie R Mrs ◎ TT2-7978
Sanford Rudolph
75 Stesiak Chester ◎
76 Weatherspoon Elmo
79 Blake Window Cl Co Inc TT6-5430
Baumgarten Mary TT3-2269
Welmont pl ends
80 Stevenson Calvin
86 Leftwich Harry S TT2-1864
Milligan Hattie E Rev ◎ TT2-1042
88 Jones Robert L 886-1577
VanBuren Matti TT6-6076
90 Erwin Clarence J ◎ TT2-6509
93 Quarles Mary J Mrs ◎ TT5-4594
94 Moore Ruth Mrs ◎ TT6-8075
Alston Barbara J Mrs
95 Thompson Donald
96 Dreissen Josephine D ◎ TT5-5683
97 Collett Harold E ◎ TT4-4967
Schmidt Grace E Mrs TT4-2648
98 Nevins Geo jr ◎ TT6-8404
rear Sanders Alberta
102 Guyton Dorothy TT4-5204
Turner William B 883-2209
103 Beach Ellsworth A ◎ TT4-8569
Wagner Anna J ◎ TT5-4983
104 Wright Lawrence M
Simmons Lillie M Mrs 884-6104
rear Erdman Doris E TT3-6601
105 Alberti Frank S ◎ TT3-3026
rear Vacant
108 Schwarz Harry G ◎ TT4-4917
Schwarz Harry G Welding TT4-4917
Stankovich Joseph J
111 Crutcher Harold G TT2-0542

EOPLE CLEANERS 834-6100

BEST—Contd
112 Dye Wesley S ◎ 885-5533
113 Barr Ida TT2-8971
Vaden Lillie M Mrs TT6-2216
115 Jones Roosevelt ◎ TT5-1620
Jenifer Lillian TT3-2834
116 Austin Leroy 883-8804
117 Nailor Radie Mrs TT4-0758
Jenifer Pearlena Mrs ◎ TT2-3101
118 Reed Spencer ◎ 886-1259
120 No Return
Elm ends
122 Lang Early ◎ TT2-5729
Roberson Willie TT2-5033
125 Reed's Delicatessen TT6-9323
126 Bess Kenneth J TT2-1063
127 White James L TT2-1390
Adams Irving
rear Jenkins Genobia
129 Cornelius Willie ◎
130 McBride Obie
131 Sweeney Albert D ◎ TT3-7706
133 Colbert Lemmie Mrs TT5-4310
rear Carpenter Beatrice
134 Garnder Herman F TT2-9230
rear Purdue Beverly J TT4-6041
135 Ashley Wm J
rear Haskins Katherine Mrs TT2-8536
136 Vacant
138 Vacant
rear Arida Raymond K ◎ TT2-8507
139 Hayes Laura E Mrs TT6-0712
rear Terrell Sarah Mrs
145 Emser Ray Texaco Service gas sta TT6-2936
150 Walker Wm H ◎ TT2-0655
Michigan av intersects
159 Sailer Albert C uphol TT3-2116
Harkins Lawrence J
161 Best G I Liquor Store TT2-1330
162 Mamie L's Beauty Shop TT6-9473
163 Hunley Simoa L
rear Pankratz Ora L
164 Adams Julius
Hubbard Wm TT6-6196
165 Herrera Pancho
Lopez Marcelino
166 Ray Willie TT6-0746
rear Northington Perlie TT3-9297
167 Peay Thos TT6-4968
Gibson Robt L
174 Jones Joseph 883-6875
176 Strasner Christiana Mrs TT3-3433
178 Hogg Gilbert M ◎ TT6-0357
184 Brown Render L ◎ 882-8925
186 Angel Quinton ◎ TT6-6432
190 Davis Roscoe TT6-5021
192 Vacant
196 Kenndy Alice F
Williams Cleveland TT4-2746
200 Martin Louis jr 886-3711
202 Rudolph Willie jr TT5-8249
Willis Fred D 886-5934
204 Fraiser Charles A 886-5390
206 Hogg Philip TT4-3253
208 Fowler Eloise Mrs ◎ TT5-1177
Little Robert
210 Pierce Willie C ◎ TT4-9237
212 Callahan Archie ◎ TT5-4150
Ashford Annie Mrs TT3-5558
216 Foster Chester E TT2-4453
Buchanan Eugene ◎ 882-1848
218 Heard Ruth M Mrs TT2-4323
222 Swafford Diane C Mrs ◎ TT2-0554

Masten av intersects
Zone 4
311-15-21 Vacant
323 Vacant
Peach ends
329 Finch Margaret Mrs TT6-5099
Edmunds Undine Mrs TT4-1830
331 Ogden John O ◎ TT5-8512
Sanders Delwarence 886-2246
337 White James H ◎
339 Walker Harold jr
Lane Roy 882-4983
341 Handel Frederick C ◎ TT3-2139
345 Jones Lola Mrs ◎
347 Curry Fred TT4-9138
Jelks Frank TT5-6028
Hodge Rebecca B
rear Hodge Rebecca B Mrs TT5-1364
Grape ends
357 Bravo Porfinio ◎ TT3-6241
Andrus Stanley TT2-5037
359 Jones Doris
361 Henry Rose L Mrs ◎ 884-2597

1965 ELLICOTT ST
SOURCE: POLKS

686 Plate Sophie S Mrs TL3-0215
Goscinska Dorothy Mrs ◎
687 Eusanio Thos P ◎ TL2-4364
Snyder Jean
691 Kennedy David J 852-3886
693 Mayor's Committee on Human Rehabilitation TL2-9697
694 Siemienowski Lucy Mrs ◎ TL3-8829
Heckman Paul
Rocfevej Algustan
Frediak Rose
699 Stevens Edith L Mrs ◎ furn rms TL4-4841
700 Hanna Walter E
Zimmerman Gordon
703 Knapp Edith S Mrs ◎ TL4-2793
704 Dombrowski Alex TL3-7106
705 Wojtaszek Jessie Mrs ◎
708 Dubicki Karol ◎ TL2-1287
709 Mathers Harry J ◎ TL2-7834
710 Antonellos Dimitrious ◎ TL2-1215
711 Cole Fred L TL3-8266
714 Vacant
715 Koehler Frank G ◎ TL4-2433
Kuras Eugenia Mrs TL3-7867
717 Nostadt Rudolph ◎ TL4-7461
720 Kubik Anna Mrs furn rms TL3-9617
721 Boyce Geo E ◎ TL3-3590
723 Calos Anthony ◎ TL4-1839
Shearer Laura Mrs ◎ TL2-4999
724 Nitzer Alma ◎ furn rms TL3-2749
Bayliss Donald W TL6-1296
728 Gandy John A TL6-3751
731 Leber Jos A ◎ paper hanger TL3-3738
Haynes Agnes TL4-7122
732 Hale Loretta Mrs 856-7420
Cornwell Jeff TL2-3591
Brown Nellie M Mrs 852-6233
735 Massarut Frank TL3-4142
Karn Marie F TL3-0595
Bozze Martha 854-6691
Scherm Louise 853-8562
738 Nygard Rita 852-8376
739 Nenno Mary H furn rooms 853-4291
741 McCoy Ellsworth

Carlton intersects

752 Swan Clayton C TT2-4511
Bianchini Louis ◎ TT4-4752
756 Cordner Robt D ◎ TT5-5451
760 Hock Marguerite T Mrs ◎ TT3-6657
766 Bflo & Erie County Tuberculosis & Health Assn Inc TT6-4055
770 Abella Jos ◎ TT3-7158
Sofuni Toshio 884-1781
774 Lindner Henry P TT3-5526
Compton Howard H ◎ TT3-5526
Lockwood Alton F TT5-3885
Linver Janet M
782 Beer Louis H ◎ TT5-0173
783 Vacant
rear Vacant
788 Nelson Geo O pntr
Maxwell Edw J ◎ TT3-1623
rear Reimer Alta Mrs
792 Paravalos John S ◎ TT5-1899
796 Vacant
797 Eddy Arth R ◎ TT6-6797
798 Vacant
802 Trouton Ollie Mrs ◎ TT6-2243
rear Matlasz Louis F
806 Dan-Dee Pizza 886-8838

High intersects

841 Vacant
843 Vacant
845 Vacant

Goodrich intersects

854 Tefferroa Margt Mrs
Hall Edith
860 Baecher Chas K ◎ TT4-4890
863 Tuschl Jennie TT3-0432
864 Watson John
Wallasch Clara L ◎ TT5-7048
866 Wistner Theo ◎ TT4-8369
867 Corbin Sylvester N ◎ TT5-3495
870 Yahle Fred V ◎ TT2-3495
871 Shaffer Saml
Wampach Mildred A Mrs TT2-2130
Hall Sim
rear Rundberg H C
872 Michaels Arth R
876 Vacant
878 Becker's restr 886-8972
Shelton Walter W TT2-1947

E North intersects
Zone 9

886 Guldner Martha M Mrs ◎ TT5-7426
Sharrer Pearl Z Mrs TT5-7234
890 Johnson Eliz ◎ 886-5383
892 Evans Frank M
894 Montgomery James F
Davis M Clark
898 Kohlbernner Anthony J ◎ TT5-3461
900 Harrison Walter T ◎ TT2-4813
903 Blackman Mary TT6-3016
Robinson Irene
905 Vacant
909 Parisi Danl F ◎ TT2-5043
Morgan Evelyn Mrs TT2-5487
913 Battaglia Wm J ◎ TL6-6403

St Paul intersects

932 House Jacob & Sons flavoring mfrs
935 Main Window Cleaning Co Inc TT4-1715
Main Building Maintenance Co TT4-1715
938 May Frank R Inc coml htg 882-6427

146

Best intersects

961 Vacant
966 Vacant
967 G & M Garage auto repr 886-8777
969 Johnson Oscar L TT4-8458
Smith Cynthia Mrs
rear Williams John W
971 Vacant
973 Nelligan Bert ◎
977 Scarvey Lorraine Mrs TT2-3372
979 Whitthorne Floyd L TT2-8979

Edna pl begins

980 Osmose Realty Corp TT2-5905
Pole Sprayers Inc contr TT2-5905
Osmose Wood Preserving Co of Am Inc TT2-5905
990 Crawford Nellie B Mrs 886-5181
991 Booth Mary
Dixon Wm TT4-3961
Chapman Steven
993 Lee Donald R ◎ TT6-3350
Williams James T TT5-0815
994 Sawyer Cleo Mrs TT4-1695
Murphy Joseph
rear McShee Rosie Mrs
996 Gay Isiah
Lovelace Eula
997 Shaw Vernon ◎ TT4-2210
998 Potter Jules H TT3-3427
Jackson John W
1000 Fisher Josephine M TT3-3941
Block Geo L TT4-4240
Deters Adelaide Mrs 884-0298
1001 Strother Roger
Roberts Wm E TT4-2484
rear Ziecker Freeman
1002 Apartments
1 Ingersoll Sterling TT5-4386
2 Hauber Cath TT4-7978
3 Sammon Joseph B
4 Kaiser Alf M
5 Agne Louis M TT4-3983
6 Donahue Mary C TT3-0985

Street continued

1006 Patom Inc real est
H & V Mtce bldg TT3-6346
1007 Calvary Christian M E Ch TT2-9885
Delaney Henry R Rev 886-8440
1010 Clifford J Edw TT2-5620

Dodge intersects

1031 Vacant
1032 Hettrich Electric Serv Inc auto repr TT4-7602
1034 Powell Sylvester TT4-5347
1036 McGhee James TT6-7831
Hawkins Vester RR3-8373
1037 Baff Arth
1040 Higgins Roy H ◎ TT2-7451
1041 Freeney Dock
Albridge David L 884-2733

1965 GOODRICH ST
SOURCE: POLKS

140

GOODRICH—From 1005 Main east
Zone 3

26-28 Alemite of Bflo Inc lubricants 883-5440
30 Vacant
34 Trans Cabt & Display Co Inc 884-0535
40 Vacant
44 Anderson Ann E TT2-8819
48 Haberl Mildred M TT3-7665

Ellicott intersects

66 Greco Marty
68 Vacant
74 Galioto Lucy Mrs ◎ TT4-6159
rear Vacant
82 Paolucci Mary Mrs TT3-8619
82½ Furlani Edw J ◎ TT5-1286
112 Bflo Genl Hosp (Hamlin House) TT3-1324

136

Elm intersects

134 Normandale John E ◎ TT3-8892
Allard Dorothy Mrs 884-6794
140 Raczka John jr ◎ TT2-1278
142 Lachte Donald E ◎ 886-0960
144 Johnson Leroy 886-0190
148 Mattulke Wm ◎ TT4-1796
152 Bickelman Florence Mrs ◎ TT3-2210
Hudson Dorothy A Mrs TT6-2346
154 DeMille Wm F TT6-7136
156 Vacant
158 Hudson Edw TT4-7646

Michigan av intersects

862 Mack John TL4-0616
King Danl W TL2-7775
865 Green Margt A Mrs
Parker Tommy C
866 Vacant
869 Park Cyrus ® TL4-0337
870 Parisien Frank ® TL3-7854
872 Wilson Luethel Mrs
873 Howard Bert S ® TL2-2246
874 Thomas Carnell ® TL2-6548
Ford Bertha Mrs TL6-9498
875 LoCastro John ® TL2-4698
Reynolds Willie L
DeVoe Carolyn TL4-2685
876 Wilson Alam Mrs TL6-4585
877 Jasinski Wm B ®
879 Ware Jimmie Mrs TL4-7363
Bloomer Hiner L TL2-6437
rear Walker Fronie Mrs 856-5062
880 Vacant
881 Lang Grace M Mrs ® TL2-4817
882 Bob's Market gro TL2-0064
883 Holmes Geo ® TL3-9332

Virginia intersects

889 Mr Ben's barber TE4-9297
Cadet Cleaners
Young McKinley
Witherspoon Benj G jr
891 Vacant
893 Daniels Theodore
895 Bell Juanita Mrs
899 White Jessie Mrs ® TL2-3225
Fenty Norman A TL2-0355
901 Komrek Steve
Alexander May Mrs TL4-5448
905 Bittles Annie C
Moore Bernice Mrs TL6-0658
907 Kempker Wm G TL3-0764
909 Davis Howard TL6-8975
Mitchell Annie Mrs 853-4398
913 Holden Walter R TL3-9313
Thompson Dallas J 856-1471
915 Henderson Estella J TL2-1664
Anderson Ted
917 Reese Mary C Mrs TL3-2794
Gibson James E TL6-1878
921 Hairston Eliz Mrs TL4-4415
925 Carton Elisha 853-3119
927 Wright John ® TL4-3769
Taylor Virginia TL2-2075
931 Vacant
rear Vacant
933 Anderson Manfield ® TL6-4566
937 Jeter Marion
939 Fernandez Willie J 854-3196
Childs Lottie Mrs 856-8440
rear Vacant
943 Vacant

Carlton intersects

955-57 Health Research Inc (Division
Roswell Park Hospital)
TT4-4200
967 Jeanette Victor ®
975 Wright Georgia Mrs TT3-6392
Dorsey Cenolia Mrs
rear Vacant
977 Pfohman Jacob P ®
Pfohman Jos J ® TT2-7034
979 Jones Lena M Mrs TT4-3786
rear Parker Lee
983 Stewart Wm TT2-5931
Gainett James TT3-3260
985 Thompson Jas E ® TT2-1323
987 Herod Jame s O
Long Edith Mrs TT4-5976
989 Dumme Janie M Mrs
Gibson Vera Mrs TT4-7943
993 Merrill Beatrice ® TT3-5682
McEachern John Rev TT6-7274
rear Rosenthal Jane TT2-5345
995 Allen Robt 882-5891
997 Vacant
1001 Susan's Beauty Studio TT4-3738
Varn Susan F ® TT4-8738
1009 Vacant

High intersects

1021 Vacant
1023 Vacant
1027 Snyder Cecil T ® TT6-0118
1029 Wansart Edw M TT4-2550
Blanck Clara ® TT4-2550
Richards Irene A TT5-7090
1031 Mackie Arth J ® TT2-2480
Murray Ella Mrs ® TT5-0524
1033 B & K Carting Co TT2-5587
Shaw John L TT6-0679
1035 Harp Roslyn J TT3-7518
1039 Kirkwood Frank C ® TT6-0423
Kirkwood Willie J 883-9683
1041 Lotempio Anthony ® TT2-5633

Goodrich ends

1043 Davis Frank ® TT3-6497
Whiting Eliz Mrs TT6-5077
1044 Vacant
1045 White Alberta E Mrs TT3-5449
Woods Herbert TT2-3888
Van Delanor
Johnson Allie Mrs TT6-3595
1046 Vacant
1048 Watkins James TT3-0514
1049 Webb Wm
Radford Maisie M Mrs TL6-2606
1052 Farnham John Phillip & Co x-ray
equip TT3-3096
Farnham Eben T lwyr TT3-3096
1053 Crosier Geo G ® TT5-5393
1054 Ingram Lester TT3-2537
1056 Avant Sara M Mrs ® TT6-4726
Davis Dorothy Mrs 882-5793
Council Geo
1057 Schiesel Edw TT5-2437
Heckler Geo TT3-6249
1059 Ries Rose Mrs ® TT2-3131
1060 Velazquez Norbert ® TT6-1846
Reyes Felipe V
1061 Anderson Wm H TT4-3215
1062 Johnson Wilmer ®
1064 Reed Wm TT6-2990
1065 Trautman Gertrude Mrs ® TT3-9349
1066 County Pest Control Inc TT3-2538
1069 Scott Henry ®
1071 Broadway Ernest S TT6-2491
Johnson Henry ® TT4-1097

North intersects
Zone 9

1080 Vacant
1082 Vacant
1083 Rickard Winona C TT5-7521
1084 Vacant
1086 Hardy Ulysses TT6-3258
Sanders Buddy TT2-7688
Elliott Johnnie Mae
rear No Return
1089 Klauk John ® TT3-1863
1091 Mason Claremont B ® TT5-3988
Baumler Frank J TT2-5309
1092 Nachtrieb Edw W ® TT2-7297
1095 Duge Marie D ® TT3-5491
1096 Collins Yvonne TT2-6948
Heffner Ben
1098 . pewell Baptist Church TT6-1297
1099 Elliott Eddie
rear Martin Morma
1100 Small Carolyn 885-5135
James Eliz Mrs
1102 McKinney John ® TT6-0558
Moore Lawrence
1103 Rieger Adeline R Mrs ®
1104 Holloway Willie ® TT6-5673
Elliott John ® TT6-1879
1105 Pratt Raymond J TT3-7769
Griffin Martha Mrs ® TT2-6030
1106 Vacant
1107 Stocker Wm S ® 884-8870
1111 DeHos Florence Mrs 886-7472
Orth Pauline A Mrs ® TT4-4347
1112 Kelly Irene
Lipford Ethel Mrs
rear Garrison Edith Mrs TT6-0058
1113 Powell Crawford
1114 Harris Barbara Mrs ®
Cottrell Sarah J 884-4065
rear Watts Eliz
1115 Barrso Alfred B ®
1116 Beckham Kath TT3-2920
Davis Connie Mrs TT3-4143
1117 Foster Edith J Mrs ® TT5-8213
Kobernuss Evelyn Mrs TT5-0922

MICHIGAN AV—Contd
1119 Boron Anthony F

Best intersects

1137 Robinson Lawrence L 883-6805
Holley's Lounge & Bar 886-8799
Holley Ernest
1141 Andrews Ricky
1144 Roberts & Rice Co auto repr
TR6-9655
1145 Ward Eddie Mary Mrs TT3-0779
1148 Tutton Electric Co auto repr
TT4-7686
1149 Finkley Annie L Mts TT5-6658
Ellington John R
1151 Murphy Titus
1152 Vacant
1155 Foster Margt Mrs 884-6131
Goodman Beulah Mrs 885-7682
1157 Todd Wilford ® 886-4602

Edna pl intersects

1163 Fidelity Cleaners 886-9116
Bailey Wilson 886-9116
1166 Cook Otis 882-9540
1167 Johnson Evelyn
Conyer Jay B 886-3608
1170 Cooper Richd L 882-6117
Walker Chas
1171 Hunter Elzer ® 886-2177
Parks James R 885-5587
rear Anderson Gloria Mrs 885-6415
Martin Beverly Ann 886-2059
1172 Wilson Dorothy TT5-6914
Holmes Theodis
Primm Oravae Mrs 883-8051
1173 Richardson John
Williams Gladys Mrs 885-4079
rear Jones James
1174 Brown Sam ® TT3-1217
1175 Butler Mildred TT2-1900
Green Andrew 885-8491
rear Vacant
1176 Bell Eliz G Mrs ® TT3-5458
1177 Farley Harry 883-0260
1178 Imperial Refrigeration Sales &
Service TT4-2040
Imperial Cycle Sales & Service
TT4-2040
Keys Marguerite Mrs ® TT2-4738
1183 Nieghbors Mamie
Becote Andrew jr
1184 Kehe Aug J TT4-2040
1187 Melvin Jas R ® TT2-2526
1188 Mokaricas Geo A ® TT3-8731

1965 NORTH ST E

SOURCE: POLKS



495

Sisters of Mercy convent TT4-5656
304 Smith Grace R TT4-0137
309 Cerebral Palsy Assn of Western NY TT6-3474
Co-operative Pre-School Center TT6-3474
The Circle intersects

140

NORTH E—From 1039 Main east
Zone 3
3 Bowers Mildred E 886-5498
5 Pike LeVere C ® mason contr 885-6963
Judge Timothy J
7 Griffin Eva E TT4-7958
Heintz Chas
9 Younger Hilda E 886-6943
Zimmermann Alvin TT5-5576
11 Pender Leo
13 Novitzski Wm TT6-1124
Hohensee Jennie C
14 Anchor Bar (parking lot)
20 Auto Paint Shop
23 Poling Leroy J ® TT5-6777
Pratt Wm 883-8763
25 Wendel Nathalie L ® TT4-0232
26 Vacant
27 McMillon Irene Mrs
Jones Mattie Mrs TT4-2535
30 No Return
31 Vacant
33 No Return
35 Conrad Edgar C TT5-1377
36 Hill Albert W TT3-4311
Smith Herman
37 Vacant
39 Ruddy Harlowe W TT5-3430
41-43 Apartments
1 Gavigan Isabelle W TT5-9129
2 Ouzeir Mouemin 883-1135
3 Walker Viola
4 Britton Clarence B TT2-9596
52-54 North Ellicott Garage Inc 884-8582
Ellicott intersects
61 Carnevale Anthony J ® TT6-3284
63 Morris Albert J TT2-1108
Roberts Edythe K Mrs TT5-1971
Jenkins Virginia
68 Guenther Dorothy M ® TT5-4790
Cullinan Dorothea Mrs TT5-4399
69 Croom Walter TT5-8849
Richards John TT5-9059
70 Morse Ruth E Mrs TT4-0870
Kramer Marlin 882-1640
Jagadowski Sadie TT3-4703
Fodor Jos TT6-8384
71 Danforth Willard J ® chiropractor TT4-4653
72 Kendall Jean S ® TT6-4019
Henderson Fred TT6-1686
76 Owens Earl TT3-9430
Mickel Dorthy Mrs
80 Vacant
82 Brown Geo E 885-3557
Scott Geraldine Mrs TT5-6698
90 Johnson Mary 884-1230
94 Wilson Willie L TT4-7560
Fields Kath 882-4438
96 Gamble Willie TT4-0338
Welmont pl begins
108 Banks Clayborn TT5-4305
110 JoLaine's Hair Modes
Apartments
1 Haynes Helen A TT3-2238
2 Jones Lillie Mrs TT4-4339
3 Butler Mae R Mrs
4 Jarrett Alean
5 Hunter John 883-7685
112 Wing Anita H Mrs ® TT5-0591
114 Coston Essie TT6-5473
Bevill Kath Mrs 883-7438
rear Valentine Henry TT6-5837
116 Bennett Jas N TT3-1068
Lennox Mary L
118 Wingard Jas C TT4-7783
rear Sartor Sylvia
120 Davis Eddie
124 Keller Isabelle Mrs TT3-2164
Fleming Kath Mrs
rear Dickinson Henry
126 Hambert Norman T
MacDonald Maude E Mrs ® TT4-6269
128 Lewis Adeline Mrs 883-0950
Phillips Lillie Mrs TT4-0329
132 Sally Ann Mkt TT3-9393
Grandillo John F ®

136

Elm intersects
135 Simon Geo W ® TT4-5543
137 LaHood Ramsey Mrs ®
Noon Mary M TT3-6111
rear Noon Anthony
140 Schaefer Henry J ® TT6-5269
Simmins Ann
141 Noon Chas C ® TT6-3085
Sommerville Jewell Mrs
142 Velazquez Miguel J jr ® TT5-1836
145 Smith Paul TT4-5182
Smith Frank ® 885-6539
146 Tolbert Lillian Mrs TT3-4220
148 Matteson Geo ® TT2-3222
149 Cryan Michl J ® TT3-4439
Erhardt Grace L Mrs TT3-2383
150 Sawday Albert E ® TT6-1909
152 Scobell Geo B ®
Klonowski Anthony J 884-5210
153 Rohs Clara ® TT5-5328
Karnitz Albert G
156 Golden Nora F ® TT3-9058
157 Thomas Daniel 883-2372
Hill Francis L Mrs TT2-4965
158 Robinson Carmen Mrs
Moseley Cleophus TT3-1323
160 Brown Billy ®
164 Morrow Wm TT5 8079
MtZion F B Holiness Church
Michigan av intersects
Zone 4
172 Kiyo Club social 882-6616
177 Sumling Robt ® TT6-4814
178 Vacant
Maple ends
179 Thuerck Kath Mrs ® TT5-4318
180 Vacant
189 Guyton Willie TT3-0463
Frank Ruby Mrs
197 Haywood Thos J 883-9068
Raulhac Barbara Mrs
199 Jones Linwood
205 Spiler Mamie Mrs
Allen Martha Mrs
207 Neuner Edw F TT4-5995
209 Wistner Ernest E ® TT4-6353
213 Marshall Sarah
215 Collins Lois Mrs
Mulberry ends
223 Feney Vincent TT3-5995
Maclin Gloria J Mrs
Taylor Louis
Fenty Vincent TT3-5995
225 Linder Dalina 886-6373
McClendon Luvada 886-6373
227 Terrell Eleanor L
nw cor Fosdick-Masten Vocational High Sch TT3-7860
ns Masten Park
237 Masten Park Bapt Ch TT3-9086

134

Locust ends
Masten av begins
249 Toellners Coal Dealers TT4-2644
Toellner Elmer W ® TT4-2644
253 Penz Ernest ® TT3-7693
Liegl Maria TT3-4995
257 Bromley Clinton T TT6-0446
Sharrer Pearl Mrs TT5-7234
261 Grass Ida Mrs ® TT5-2649
Grass Curt E TT4-4985
263 Koch Mary M ® TT5-5206
Hanlon Cecelia M Mrs TT4-3002
265 Grace Bapt Ch 882-7582
Lemon ends
275 Thomas Franklin L ® TT3-8009
Dunston Bernard
277 Eatmon Jas ®
283 Jackson Otis TT5-2579
Armstrong Calvin ®
285 Pace Jasper ® 884-6738
287 Cochran Louisa Mrs
Bryant Fannie L Mrs TT6-8403
291 Green Eug TT4-6620
Brown Carrie Mrs ® TT3-7817
Orange ends
301 Green Ernest T ® TT5-7070
Sheppard Thos TT3-0028
307 Dancy Willie ® TT2-5674
Ingram Lawrence
309 Wilke Anna A Mrs ® TT6-1627
314 Branch Doris Mrs
316 Brooks Mary Mrs TT4-0360
320 Smith Thos
Gooden Frank TT5-2785
322 Hill's Delicatessen
Hill Jos E ®

1960 BEST ST

SOURCE: POLKS



BERWYN AV—Contd
106△Schneider Jack
△Rosinski Eug C ®
109△Ruber Fredk W ®
110△Glass Margt E Mrs ®
Bailey av intersects

BESSMER — From 281 Chicago east 1 block

146

BEST—From 1119 Main to Genesee
4-16 Best Apts
1△Williams Edna M Mrs
2△McKee Harry S
3△Borman Carl
4△Wagner Jos
5△Barnes Walter
11 Perley Harvey
12 Quigley Danl E
14△Newton Alice
15 Klaus Dolores C
18△McElwee H Vincent
20△Ashbrook Henry F
21△Politis Geo
22△Goggin Kath D Mrs
23△Curtis Carlton
24△Drumb Louis Mrs
25△Browne Doris M
26△Larrin Vincent
27 Zombeck Aeleline
28△Ohlwater Frank J
29△Sapon Myrtle
△Burdette Orange
30△Bakos Emmanuel
31△Kersburg Ann L Mrs
32 Vacant
33 Dispenza Jos
34 Gray Anna C Mrs
35△Sommers Cath Mrs
36△Kell Frank E
37△Powers Thos J
38 Gamrath Lillian A
39△Schmidt Chester J
Street continued
22△Harris John G ®
△Weldeman Genestere Mrs
25△Novak Edw
△Schultz Wm
26△Holmes Sarah Mrs ®
29△Hamilton Marie Mrs
△Jones Clara
30△Burdett Clarence
△Smiley Odessa L
31 Vacant
32△Singleton Albert A Rev
△Dean John
McDavis John jr
rear McDavis Bertha Mrs ®
33△Miller Julius ®
△Somers Thos J
35△Burdick Milton P
36△Lancer Willie J
Henderson Henry
rear Vacant
38△Allen Clarence T ®
Woodward Ransom
41△Logel Herbert W
44△Beresford Vera M Mrs ®
△World Jas L
44½Vacant
45 Niagara-Mohawk Power Co (sub sta)
46△Duquin Lillian Mrs ®
50△Drakes Hedley V ®
52△Anthony Anthony F ®
53 Sobus Elliaggia
△Club Fifty-Three restr
56△Watkins Clinton U ®
delicatessen
Ellicott intersects
65△Liptak Dorothy Mrs ®
restr
67△Stevens Sarah E Mrs ®
68 No return
69△Braymiller Donald
△McKay Kenneth H
70△Kraft Lily Mrs
71 Vacant
72△Meiser Raymond A ®
73△Gibbs Edna M ®
74△Melchor Alf
△Martin Mary Mrs
Colognino Grlew
75△Stesiak Chester ®
76△Bruce Robt J
78 Vacant
79△Baumgarten Mary Mrs
Welmont pl ends
80 Vacant
86△Leftwich Harry S
△Milligan John ®
88△Beckett Rose Mrs ®
△Romaster Robt W
90△Aschbacher Walter C ®
93△Thie Marie A Mrs ®
94△Moore Ruth Mrs ®
Mitchell Luther
95△Winter Anna B ®
96△Dreissen Josephine D ®
△Schlee Agnes Mrs
97△Collett Harold E ®
98△Kubik Chas J
△Ackerly Robt E ®
102△Lombardo Peter jr
△Martin Nellie Mrs
103△Beach Ellsworth A ®
△Wagner Anna J ®
104△Malecki Jos
Heymann Friedhelm
rear△Trapp Jos ®
105 Schmidt Emilie Mrs ®
△Schultz Norman
rear Vacant
108△Schwarz Harry jr
Schwarz Harry G ®
111△Crutcher Harold G
112△Pokolm Florence A Mrs ®

BEST—Contd
113 Boling Maurice Wm
△Togrant Julius
115△Jones Roosevelt ®
△Cathey Margt
116△Peard Anna G Mrs
117 Vacant
118△Fee Lawrence C
120△Jackson Wm ®
Elm ends
122△Lang Early ®
△Roberson Willie
125 Lorrozo John
delicatessen
126△Nelms Austin ®
127△Mulvaugh Francis H
Vrenna Chas
Cronnin Gene T
rear△Kelly Lawrence J
129△Grady Maude E
130△Walker Wm H ®
△McBride Obie
131△Newton Fanny Mrs ®
133△Macknight Douglas H
rear△Brown David A
134△Benson Laura
Bingeman Jennie B Mrs
△Lambert Norman T
△Weis John P
rear△Jonas Marcus
135△Meyer Edw ®
△Vanderlinden Amelia
136△Gueth Marian O ®
138△Friedl Robt J
△Smith Arth J
rear△Godlewski Henry C
△Arida Raymond K
139 Vacant
rear△Boyer Fred
145△Emser Ray Texaco Service
150△Berti Louis P gas sta
Michigan av intersects
159 Sailer Albert C uphol
Harkins Lawrence J
160△Lamm Susanne Mrs ®
restr
Erie Josephine
161△Hogg Gerald W liquors
162△Olivia's Beauty Shop
△Dillard Olivia Mrs ®
163 Healy Pearl Mrs ®
rear△Stoerkel Frank M
164△Shropshire Robt
△Edwards Claudine Mrs
Hubbard Wm
△Palmer Tommie L Mrs
165 Bursie Irene Mrs
166 Northington Perly
Hunley Simon L
167△Comtois Lucien ®
168 Vacant
172 Barnes Mary A ®
174△Thur Geo W
176△Mumm Caroline A Mrs ®
△Gerhardt Clara
178△Hogg Gilbert M
184△Wetter Wilhelmina ®
186△Angel Qlinton ®
190△Thornhill Jos C
192△Sattle Melvin
Horner Howard
196△Williams Dan ®
Robinson Willie Mrs
200△Varnado Arth ®
202△Celms Wm P ®
△Willis Fred D
△Mednis Otomars
204 Jennings Robt
206△Bass General G ®
Hohn Edw
208△Fowler Irving ®
△Lewis Willie O Mrs
210△Pierce Willie ®
212△Callahan Archie ®
△Ashley Evelyn Mrs
216△Foster Chester E
△Buchanan Eug ®
218 No return
222△Ott Arth ®
△Twardokens Jerzy

132

Masten av intersects
311△Staub Eleanore M Mrs
315△McQueen Matilda
321 Pitrzrontak Bertha M Mrs
Bailey Verlon L Mrs
323△Cavallaro Tony
Peach ends
329△DiMino Emanuel C ®
△DiMino Rose Mrs
331△Catalfamo Frank J ®
337△Vroman Cora W Mrs ®
339△Klemenz Eug
341△Handel Fred A
345△Fabiano Sami ®
△McCormack Edna Mrs
△Miller Florence A Mrs
Grape ends
357△Bravo Porfinio ®
△Andrus Stanley
359△Henry Victor C ®
Key Celestine Mrs
rear Vacant
361△Palmisano John ®
363△Mosier Loretta Mrs
△Ferro Jos
rear△Ellsworth Frank M
△Scheffler Fredk W
△Glowinski Edwin W
369 Slay Wm L
Henderson Jas
△Stutz Wm N
rea△Cark Francis F
Krischner Herbert E
371△nw cor △ Buffalo Civic Stadium

128

Jefferson av intersects
400△Lang's Creamery Inc
△Wick Carting
Bueschen Milk Serv
Howard's Exp Inc
△James Mary G Mrs
401△Porter Otis

1960 ELLICOTT ST

SOURCE: POLKS

582 Kubik Anna K Mrs
583 Zelle Anton
Gibbs Lean
584 Hehir Steve H
587 Doll Olive E
590 Sheik Cafe
Karam Nicholas M
596 Powers Fred W
Klee Andrew
601 Maurice Motorist Motel
602 Loesch Emma S Mrs
Fuchs Wm F
Goddell intersects
Burton intersects
670 Trico Products Corp
(Part of Plant No 1)
674 Ulrich Restr
Hoare James F
Virginia intersects
682 Fisher John H
686 Rombach Helen Mrs
beauty shop
Wood Grace M
687 Eusanio Thos
690 Wild John H phys
691 Martin Lillian C
693 Ellicott Clinic and Hospital Inc
694 Siemienowski Joseph
Han Yong Hyon
699 Stevens Edith L Mrs
700 Ricks Raymond
Townsend Leta
703 Knapp Edith S Mrs
McCormick Everett
704 Charsky Lena Mrs
705 Wojtaszek Lawrence Mrs
Dilazquez Felipe
708 Dubicka Karol
709 Mathers Harry J
710 Antonellos Jas
711 Cole Fred L
Raymond Marie
714 Metcalf Riehd E
MacKay J Andrew
King Raymond P
715 Koehler Frank G
Mysker Mildred Mrs
717 Nostadt Rudolph
720 Wilger Mae C
721 Boyce Geo E
723 Calos Anthony
Shearer Laura Mrs
724 Schulz Max
Bayliss Donald W
727 Modica Anna T Mrs
Polenz Anna Mrs
728 Grandy John A
731 Leber Jos A
Kim In Hwan
732 Leonard Eliz Mrs
Strong Lillian E
Cunningham Booker T
735 Massarut Frank
Fredriksen Carl H
Lyons Beatrice H Mrs
Karn Marie
Bisone Martin
738 Brady Chas P
Boldinski John
Law Chas
739 Hilliker Norma Mrs
741 Mason Walter E
Carlton intersects
751 Parisi Joseph E
752 Swan Clayton C
Bianchini Louis
755 Parisi Carmelina Mrs
Wolf Henry
756 Cordner Robt D
759 Dewes P Paul
760 Hock Wm L
763 Nitzer Alf
766 Bflo & Erie County Tuberculosis & Health Assn
769 Devlin John T
Clecand Robt W
770 Abella Jos
Woolsey Geo
Wojnowski Donald
771 Hamele Sally
773 Crittenden Bertha Mrs
774 Lindner Henry J
Lockwood Alton
Zebold Lavina N
Farrell Emma Mrs
Compton Howard H
782 Beer Louis H
783 Gaetz Veterinary Hosp
Gaetz Hiram T
Gaetz Leonard H
Funeral Home
Gaetz Leonard H
785 Lennartz Fred W
Hilliker Robt O
Duncan Carl S
788 Kessler Geo C
Maxwell Edw J
rear Reimer Melvin M
789 Waugh Alf
Scott Lucille Mrs
792 Paravalos John
Paravalos Peter J
793 Newton Richd
Kenneth Harry
Ende Eug
796 Vacant
797 Eddy Arth R
798 Vacant
802 Trouton Ollie Mrs
Matlasz Louis F
rear Nenno Mary
806 Frank's Launders & Cleaners Inc
High intersects
820 Gray Kenneth
Sisson Joseph
822 Vacant
824 Seekins Fred K
826 Seibert Wm J
830 Ellis Ethel M
Burke John J
834 Hamilton Carlton W
Lukas Agnes
836 Jacobs Albert
Estrellado Romeo E
Ditcher Helen
rear Benedict Walter E
840 Belk Hiawatha
Burgess Joseph
Tigner Milton
842 Laney Edw
Whitfield Cath Mrs
Goodrich intersects
854 Tefferron John D
Pardoe A Mrs
Haberl Mildred M
860 Baecher Chas K
863 Finch Albert M
Tuschl Jennie
864 McGee John R jr
Wallasch Clara L
866 Wistner Theo
867 Savage Mary C Mrs
Marshall Shirley L
Cobin Sylvester W
870 Yahle Fred V
Warner Angeline M
871 Wampach Mildred A Mrs
Travers Cath
Wistner Frank M jr
rear Lochte Elmer C
872 Johnson John A
Price Antoinette
876 Connelly John
878 Shelton Walter W
E North intersects
886 Guldner John H
Sees Albert J
890 Lubo Frank
Desenroth Robt
Driscoll Frank W
892 Anderson Alfred
Gruber John A
894 Adam Robt A
898 Kohlbrenner Anthony J
Becker Fredk C restr
McCarthy Marguerite
900 Harrison Walter T
Barrante Robt
903 Fisher Ida Mrs
Asselin Chas L
905 Vacant
908 North Ellicott Garage
909 Parisi Dani
913 Fuss Flora F Mrs
Battaglia Wm J
StPaul intersects
931-35 Main Window Cleaning Co
Main Building Maintenance Co
932 House Jacob & Sons extracts
938 May Frank R Inc refgr
146
Best intersects
961 Morgan Piston Ring & Parts Inc whol auto parts
966 Grimm Carl C (whse)
967 Nebrich & Co auto reprs
969 Reichelt Wm A
970 McDowel Claude
Bruce John W
971 Kelly Irene A Mrs
Pratt Wm J
972 Brown Jesse
973 Lannon Margt
977 Sherrell Calvin
978 Kelly Letter Service Inc
979 Martin Hilda Mrs
rear LoCascio Vincent
Edna pl begins
980 Osmose Realty Corp
Pole Sprayers Inc contr
Osmose Wood Preserving Co of Am
990 Thompson Rudell Mrs
991 Sillaway Mildred E Mrs
Brown Genevieve M Mrs
993 Kreller Helen Mrs
Liebel Rose A Mrs
994 Ballard Harold E
rear Lewis Adeline Mrs
996 Reed Emmitt
997 Amann Raymond T
998 Potter Jules H
1000 **Apartments**
1 Fisher Anne C
2 Cream Betty C
3 Deters Adelaide
Street continued
1001 Hickey Anna L Mrs
rear Molina Ernest P
1002 **Apartments**
Paul Barbara M Mrs
1 Ingersoll Sterling
2 Hauber John H
3 No return
4 No return
5 Agne Louis
6 Donahue Mary C
Street continued
1006 LoCascio Vincent barber
1007 Calvary AME Church
1010 Brown Herbert B
Dodge intersects
1031 Denton Willlemae Mrs
Arrington Luther
1032 Hettrich Electric Service Inc auto repr
1033 Ford Earl
1034 Turner Willie
1035 Benefield Altha
1036 Cooper Edna
1037 Santiago Reinaldo
1040 Higgins Roy H
1041 Crockett Ernest
1042 Breslin Wm P
1044 Weber Anna Mrs
Coe pl ends
1045 Marsh Alice
1047 Davis Leola Mrs
Southampton begins
1050 Hunniford John
1054 Cronin Alice M
1056 Smith Wm

1960 GOODRICH ST

SOURCE: POLKS

77 Artistic Weaving Co
Wile M & Co Inc
clo mfrs
Amram Henry J mfrs agt
Norton pl begins
N Oak intersects
107 Anns Lunch
108 Rejnat Jos
Good Oak Lunch
Bill's Paints & Hdw
Strachnik J P jr
111 LeBar Geo L barber
Dziwulski Walter J
112 J & M Tires
113 Ballistrea Salvatore A
Loernz Genevieve Mrs
rear Vacant
114 Schwalb Edmund G
Magro John S
Syracuse Chas
116 Sklerczynski Leon W
Harrison Aubrey B
116½ Scharf Danl
117 Iacona Anthony
Mann Richd P
118 Panasci Anthony
Nino's Restaurant
Gentile Delores T
119 Heining John M
Hartman Edwin
124 Lux & Sons funeral directors
Lux Raymond P
Bartlett Cath L Mrs
Demond pl intersects
129 B & C Auto Serv
130 Dice Barbara Mrs
132 Tom & Len's Grill
133 Modernway Realty
Harrison Auto Parts
Apartments
1 Klemens Wm
2 Walton Olga Mrs
3 McKinnon Wm J
4 Filarecki Walter
5 Stanley Mary L
6 Murphy Ann
Street continued
134 Martyn Walter J
tailor
Bell Wm B
Veily Ruth D Mrs
135 Syracuse Pasquale J gro
136 Staff Cecile M
Kaiser Mary Mrs
136
Elm intersects
143 Havana Casino restr
145 Reynolds Wm E
146 Silver Elm Grill
147 Skibinski Josephine E
Iluk Roman
148 Selle Arth J plmb
149 Josephine's Dress Shop
Mare Antonia Mrs
151 O'Neil Charlotte M
152 Niagara Piston Ring Works
153 Smith Irene
Hayes Dennis G
Fudale Richd
Schuman John T
Elliott Louis
154 Draffin Willie J
Werrick pl begins
157 Weber Hattie A
Gori Julio
159 No return
Edwin pl ends
165 Lillians Beauty Shop
Daniels Alice
166 StPhilip's Episcopal Church
Curry Kenneth S Rev
167 Wilfrom James A
Foegen Bernard J
168 Pax Irene M beauty shop
170 Valazza Cleaners
170 Momant Willie
172 Ghafoor Nora
Michigan av intersects
180 Bflo Assn for the Blind
Marasi Lillie Mrs
Diehl Ell J
rear Cook Sara
Gold Harold
184 Rehabilitation Training Center
185 Patti Philip M
Bflo Assn for the Blind (work shop)
187 Patti Angelo J
Menard Geo
191 Hinton Addison
Amerson Jas
197 Berry Cecil
Rice Colie jr
rear Gibson James E
rear Pittman Ronald
Maple intersects
205 Mohr Horst A
McGraw Wm J
Johnson Gustave A
Bradley Geo
Reynolds Theresa Mrs
206 Wild's Grocery delicatessen
207 Lenau Otto
Putt Herbert V
208 Jackson Paul
211 Esposito Ralph
213 Sturdivant Prudence V Mrs
213½ Virby Arth
214 Grayson Jas
215 Dudley Jason
Johnson Fred
Johnson Fred jr
219 Armstrong Roosvelt
Picarda Reganalda
223 Wiltberger Henry gas sta
Mulberry intersects
Cherry intersects

50
GOODLIFF — From Hopkins east ½ block, 3 north of Marilla

140
GOODRICH—From 1005 Main east to 1044 Michigan av
20-28 Alemite of Bflo Inc lubricants
Stewart Warner Sls (ofc)
30 Health Research Inc cancer clinic
Burke Window Mfg Co Inc
40 Nealy Ray
Moore John H
41 Tru Ade Bottling Co
Squirt Beverage Co
44 Durham Odis
Suver Josephine A Mrs
Ellicott intersects
66 Rowley Robt K
68 Smith Glenn M
Manfredini Anna M Mrs
70 O'Neil Agnes F
72 Maxson Herbert B
Gembala Leo A
74 Silvis M Grace Mrs
Galioto Saml J
Smith Francis
Roberts Mary
82 Paolucci Emanuel
Kauffmann Geo H
82½ Furiant Edw
Hickey Henry
100 Harrington House (Bflo Genl Hosp Nurses Home)
112 Hamlin House (Bflo Genl Hosp Nurses' Home)
136
Elm intersects
134 Normandale John E jr
Allard Dorothy
140 Raczka John jr
142 Fries Raymond H
144 Spoor Easter C
148 Meyer Caroline Mrs
148 Mattulke Wm
152 DeMille Wm
rear Bickelman Albert G
154 DeMill Leonard
156 Vacant
158 Stearns Jos W
Michigan av intersects

98
GOODYEAR AV — From 1430 Broadway north to E Ferry
12 Reggie Garage
16 Boryszewski Casper J
17 Wisniewski Jos V
Wisniewski Eug
Heverly Helen M Mrs
18 Przybyszewski Edw J
19 Chodkowski John
Mazurek Victoria
rear Cichocki Walter S
22 Kryszak Jos H
23 Szablewski John
Penke Ervin
24 Jagielski Stella Mrs
rear Strychalski Geo
25 Stanski Frances Mrs
Rosinski Eleanor Mrs
28 Krakowiak John A
rear Wigdor Leo P
29 Zaganiaczyk Stanley J
31 Rothfuss Kazmiera Mrs
32 Zgoda Cecelia Mrs
Wydro Matthew
33 Barczykowski Ray
34 Nowak Walter
Kledrowski Victor
35 Haberer Anna
Pietraszak Rose Mrs
36 Dembinski Dorothy P
Wolanski Victoria Mrs
39 Kurzel Bernard M
40 Kropski Henry
Andrzejewski Frank
41 Wolicki Stefan
Keane Raymond
42 Twitchell Geo B
43 Witkowski Frances Mrs
46 Sobkowiak John
48 Prusak Frank
49 Szostak Chester
Florczak Jos B
52 Slusarski Mary Mrs
Karla Wm G
53 Kryczko Walter
Kryczko Mathew
54 Kornaszewski Mamie Mrs
55 Herzog Bernard L
Jurus Richd J
57 Lokrynski Geo F
58 Cieslak Pearl Mrs
Lewandowski Edw
59 Shine Donald
Empire intersects
83 Hallett Roger
rear Banas Andrew J
88 Symonds Joseph
rear Rosinski Thad
89 Pokora Jacob P
90 Brzyski Stanley F
rear Brzyski John
92 Barczak Bronisława Mrs
93 Drzewiecki Hattie
Hoinacki Henry A
98 Szymanski Chester
Przywuski Harry J
Lyczynski Victoria Mrs
99 Krakowiak Julia Mrs
Krakowiak Robt R
101 Pawlak Edw
102 Tomaszewski Raymond
Bittner Sophie Mrs
Knesma Agnes
Zgoda Harry A
103 Jedi Henry H
rear Karolk Frances F Mrs
104 Kaslewicz Frances Mrs
Dobrzynski Casimer
rear Mazurkiewicz Louise Mrs
106 Dolka Steph
107 Zielinski Frank J
Chalecki Jos P
108 Zaremba Adela F
109 Jakubik Jennie Mrs
Gabrzezak Stanley F
111 Orzechowski Bernard
113 Nowacek Cecilia
Zulewski Valentine
114 Aleles John
rear Banasiak Florian F
116 Szubinski Frank R

GOODYEAR A
119 Zalikow
Kozlows
120 Drzewie
Blinda J
Muehlbe
Gluszak
122 Ratka
125 Gabryk
Mrs
126 Iwanow
Kazmie
127 Arent
128 Barrzyc
131 Babin
132 Rebisz
133 Wollen
mill
134 Krawcz
Chudot
158 Szram
Szram
160 Kowal
Pilark
164 Kocol
Kocol
Tulis
Erbes
170 Biedr
Samu
171 Owsi
Czarn
172 Ramp
Skub
173 Mruk
174 Beck
Nien
rear Wilu
175 War
Won
Gron
177 Arm
Kasp
178 Grze
Maz
181 Mat
Lari
182 Kay
Dzi
183 Sty
184 Jure
Free
185 Szcz
Pen
187 Skr
Kle
188 Iek
Iek
189 Wal
Wa
190 Jar
rear Mru
191 Oke
194 Lu
196 Dor
Ste
199 Zie
Szy
200 Szc
201 Ra
Le
202 Pi
Jol
205 Ja
Da
206 Fo
Zy
207 By
208 Ga
Ob
211 Ko
212 Ki
Ki
213 Br
Kl
214 Ni
217 Cz
Cz
218 Le
Za
219 M
Cz
220 Ki
St
223 De
Ki
224 Sz
Le
225 Ol
Ar
226 Ju
Gi
228 Cz
229 Ki
Ka
230 Ja
Ja
231 Ro
Mi
234 Po
Po
235 Ro
241 Ke
Za
243 Mi
Ol
285 Fi
286 Bl
287 St
288 Br
290 So
292 Ca
294 Ar
298 Wi
Ru
299 Ka
Ig
300 Ka
301 Ko
302 Py
303 Ro
307 Le
Ba
308 Pi

1960 MICHIGAN AVE-A

SOURCE: POLKS

841 Jenkins Troy L
rear Saxon Clara Mrs
842△Goer Haskel ⓘ
845△Battaglia Geo A
△Terryberry Ethel Mrs
Hall Bertha Mrs
846△Parisi Thos
Howard Fred
847△Barksdale Fred D ⓘ
△Nolan Dennis
848 Forman Willie
△Bradshaw Timothy E
△Bildy Jas
851△Shapiro Philip ⓘ
△Kosta Geo
△Harper Florence
Vinson Wm
852△Jones Della O Mrs ⓘ
△Hunnicutt Noland A
854△Paynz Wm
△Guadagno Anthony D ⓘ
855△Kirkwood Jas L
△Flunder Vira Mrs
856△Knight Jas ⓘ
857△Abramo Angelo ⓘ
859△Russo Frank
860△Simmons Ernst S ⓘ
Robinson Clarence
△Johnson Frank
861△Spencer Hattie Mrs ⓘ
△Black Harry H
△Johnson Jesse
Glen Jas
862△King Danl W
△Pritchett Jas W
865△Slattery Henrietta Mrs
△Parker Tommy C
866△Parisien Frank ⓘ
△Montana Jos
869△Tomizzi Antoinette Mrs
ⓘ
870△Pfatschbacher Heinrich
ⓘ
872 DuBore Joshaway
△Wilson Jas E
873 Mallan Mary Mrs
△Howard Bert S ⓘ
874△Thomas Carnell ⓘ
875△LoCastro John ⓘ
△LoCastro Thos S
DeVoe Carrie
876△Wilson Ward
877△Jasinski Wm ⓘ
879△Schimmer Elsie E Mrs ⓘ
△Geise Veronica Mrs
rear△Brummer Catharina Mrs
880 Brown Jas T
Allen Robt
881△Lang Grace M Mrs ⓘ
882△Young Harry L pet shop
Collins Theo
883△Hayes Josie E Mrs ⓘ
Witherspoon Benj G jr
Virginia intersects
884△Capitol Market
△Goetz Carl ⓘ
Wahl John jr
885 Cadet Cleaners
886△Hancock Donald B
△Baker Elmer J
888 Thompson Wm
△Pierce Olga Mrs
889△Gladden and Tidwell
beauty shop
891 Mathews Jas
Sanders Elijah M ⓘ
892 Lewis Wm H ⓘ
893△Barnes Ruth Mrs ⓘ
△Timmons Hattie Mrs
△Bailey Walter
894 O'Brien John S
△Ruch Chas G
895 Green John
898△Jenkins Clarence A
△McClamb Martha Mrs
899△White Jessie Mrs ⓘ
△Fenty Norman
△Givens Estelle R
900△Tyson Walter L ⓘ
△Dixon Maggie Mrs
901 Komrek Steve
904 Stone Anna Mrs
△Volk Edw A
905△Johnson Adolph
Bittles Annie C
906△Scruggs Earl
△Gyton Willie
907△Kempker Wm G
908 Waldmann Nelson P
909△Noether Mary Mrs
△Lodge May Mrs
Vogt Donald F
Blatchley Ethel Mrs
912△Geigle Margt M Mrs ⓘ
△Rickard Ralph
Heath Geo
913△Everett Lillian
△Holden Walter R
△Partello Geo W
rear Millard Clarence
914△Eberly Steven S ⓘ
△Stiver Ray B jr
915 Glen Julius J
△Preston Baldwin
917 Hearon Faye
Reese Mary
918 Davis Prentiss
Perkins Eliz
Nelson Thos
Minneci Mary Mrs
Young Eliz Mrs

MICHIGAN AV—Contd
920△Clinton Doris Mrs
△Adams Evelyn Mrs
921△Buono Louis L ⓘ
[illegible] Morrie
△Edwards Annie P Mrs
922△Cooper Pauline
△McCullough Martha Mrs
Mrs
△Thomas Agnes Mrs
924△Johnson Bernard ⓘ
△Sheldon Fletcher E
△Middlebrook Saml
925△Dowdy Percy R
927△Wright John ⓘ
△Kienberger Michl
928 Johnson Ruth Mrs ⓘ
930 Chillis Ureese ⓘ
931△Heiss Herbert H
Jones Florence
933△Haefner Mary E Mrs ⓘ
934△Thomas Chas F
(antiques)
△Kanehl Bert
936△Williams Josephine Mrs
ⓘ
937 Jackson Margt
Mays Saml
939△Love Beulah
△McWilson Benj ⓘ
△Fryer Murray
Love Beulah
940△Manley Herman
△Sudduth Barbara A Mrs
942 Allen Speed Wash Indry
943△Edmonds Barnie J
Carlton intersects
946△Hunter Garland B gro
△Tuuri Eino E
948 Saari Olga Mrs
StMarks Ch of God &
Christ
948½Kippes Anthony barber
950△Nurmi Manda Mrs
Kuhnhaeuser Reinhard
952△Lewis Timothy C ⓘ
△Berry Richd
Taylor Phillip O
△Mitchell Willie F
955-57△Batt Co Inc plmb &
htg
958△Powell Owen
Spate Colemor
rear△Klouses Geo N ⓘ
959△Romano Jos ⓘ
Zalecki Mary Mrs
960△Benson Anthony B Rev
△Worthery Fannie
961△Smith Thos J
△Mays Ora Mrs
962△Saunders Edw jr ⓘ
965△Murray Ardella Mrs
△Saxon Jas
966△Berry Jas jr ⓘ
967 Jeanette Victor ⓘ
968 Oliver Hargis
972 Vacant
974△Johnson Jessie J
975△Jackson Marshall
△Wright Georgia Mrs
Lesh Helen Mrs
977△Pfohman Jacob P ⓘ
△Pfohman Jos J ⓘ
978 Rogers Johnnie L
△Harris Raymond
979 Smith Frank
△Smith Eddie C
△Rattley Louise Mrs
982△Thomas Annie Mrs
983△Paramount Beauty Salon
ⓘ
△Barnwell Clementina Mrs
△Garnett Jas
984 Schneider Sophie Mrs ⓘ
△Schneider Herman R
985△Thompson Jas E ⓘ
rear Sloane Art
986 Maxon Leo
Patterson Guy
987△Hopkins Dora Mrs
△Schneider Carl L
989△Wisniewski Steph S
△Oelschlaeger Robt F
990△Small Evelyn Mrs
△Elias Sadie Mrs ⓘ
993△Walter Edmund
△Merrill Beatrice ⓘ
994△Clark Gertrude B Mrs
△Davidson Edmund
995△Bobo Adam
△Harmon Archibald
△Jones Mary Mrs
996△Hargrave Jas
△White Noah E
998△Nestel Norman J
△Kirkpatrick Wm F
1001△Varn Susan F beauty
shop ⓘ
1009△Stegner Allen E drugs
High intersects
1021△Bowen John R
1023△Brock Florence M Mrs
ⓘ
1027△Snyder Cecil T ⓘ
1029△Wansart Edw M
△Blanck Clara ⓘ
△Richards Irene
1031△Mackie Arth ⓘ
△Murray Ella Mrs ⓘ
1033△B & K Cartage Co
△Ouzeir Mouemin
1035△Dupree David

1960 MICHIGAN AVE-B

SOURCE: POLKS

MICHIGAN AV—Contd
1039△Kirkwood Frank C ⓘ
△Kirkwood Willie J
1041△Lotempio Anthony ⓘ
Lotempio John A
Goodrich ends
1043 Davis Frank ⓘ
△Howse Homer S
1044 No return
1045△Manno Lawrence ⓘ
real est
△Brown John J
Sigrist Wm J
1046 No return
1048△Ferguson Alex E
1049△Munro Irving S ⓘ
Keller Eug
1052△Farnham John Philip &
Co x-ray equip
△Farnham Eben T lwyr
1053△Crosier Geo G ⓘ
1054 Vacant
1056△Avant Arth ⓘ
Collins Lois Mrs
1057△Schiesel Edw ⓘ
△Heckler Geo
1059 Gross Fredk
Ries Rose
1060△Velazquez Norbert
1061 Boyd Helene Mrs
1062 No return
1064△Malloy Theresa M Mrs
ⓘ
△Reed Wm
1065△Trautman Gertrude Mrs
ⓘ
1066△County Pest Control
1069 Scott Henry ⓘ
1071△Broadway Ernest S
North intersects
1083 Durham Jesse
Jeffries Mathew jr
1084 Vacant
1086 Williams Roland
1089 Klauk John ⓘ
△Murphy Sidney
1091△Mason Claremont B ⓘ
△Baumler Frank J
1092△Nachtrieb Edw W ⓘ
△Duge Marie D
1096 Pressley Clara E Mrs
Nailor Radie Mrs
1098△Hughey Robt B
Marcus Herbert R
1099△Carroll Lettie Mrs
Sanders Birdie
1100 Heilman Mary L Mrs
1102△Lotz Richd ⓘ
△Lotz Harriette Mrs ⓘ
1103△Rieger Peter C ⓘ
1104 Holloway Willie ⓘ
△Gregg Mickey
1105△Pratt Raymond J
Griffin Martha Mrs
1106 Scott Saml
△Martin Jas O
△Truedale Walter M
1107△Stocker Wm S ⓘ
△Cole Louise Mrs
△O'Brien John J
1111△Orth Pauline A Mrs ⓘ
△DeHos Jos
1112△Pohle John D ⓘ
Fogle Ralph W
△Pohle John C
1113△Brewer Wm C
1114△Harris Barbara Mrs ⓘ
Watts Eliz Mrs
1115△Meissner Walter H ⓘ
1116△Winzenried Lester
△Krueger Rose Mrs
1117△Foster Edith J Mrs ⓘ
△Kobermuss Harry A
1119△Donaldson Winifred
146
Best intersects
1137△Lamm Susanne Mrs
1139 Vacant
1141△DeWyer Melvin T ⓘ
1144△Roberts & Rice Co auto
reprs
1145△West Maurice A
△Johnson Jas
1148△Tutton Elec Co auto
repr
1149 Finkley Loretha Mrs
△Smith Louis C
1151△Finkley Geo L
1152△Custom Auto Upholstering
△Scott Claude L
1153△Brown Willie
Matthews Robt
1157△Todd Wilford ⓘ
Edna pl intersects
1163△Blaine Augustus gro
1165 Owens Kermit B
1166△Sullivan Franklin R
1167 Johnson Isaac
△Super Dora
1170△Sacca Stefano ⓘ
1171△Davis Clarence
rear Baylor Ideal
1172△Sweeney Jos F
△Wilson Dorothy
△Eckert Edw J
1173△Wright Albert E
Lewis Mary
△Barleant Realty Co
1174△Brown Sam ⓘ
1175△Keener Olin jr ⓘ
rear Henderson Geo
1176△Bell Eliz Mrs ⓘ
1177△Tigg Robt
rear Reed Jas
1178△Knittel Emil A ⓘ
1183 Vacant
1184△Imperial Refrigeration
Sales & Service
△Imperial Cycle Sls &
Serv
△Keys Marguerite Mrs
△Keho August J
1187△Melvin Jas R
1188△Mokaricas Geo A ⓘ
△Bondreas Ruth Mrs
1189△Select Super Mkt gro
Dodge intersects
1199△Town & Country Clean-
ers
△Smith Loretta
1200△Atlas Bedding Co
△Lee Lillian Mrs
△Gittere Lena Mrs
△Rathwell Helen Mrs
1201 Vacant
1202△Farris Kath Mrs
△Davis John D
1203△Britt Eliz ⓘ
Lofton Ann Mrs
Conyer Jay
1206 Vacant
1207△Fritz's Delicatessen gro
△Fritz Robt L ⓘ
1208△Salter Louise Mrs ⓘ
1209△Hettlinger John C ⓘ
contr
1210△Harris Willie ⓘ
Smith Ledell
1212△McNett Jack ⓘ
1213△Goodwin Otis B
△Pitts Robt L
1214△Kellam Frank H ⓘ
1215△Lawandus John J ⓘ
shoes
rear Heard Willie J
1217△Parker Fabric Corp
△Parker Nelson T ⓘ
1218△Benson Chas
Tigg Chas R
1220 Smith Chas
Southampton intersects
1233△Perkins Pharmacy
1236△Brown Leola Mrs
△Smith Gloria
1237△Hawkins Mozella Mrs
△Dorsey Cenolia Mrs
1238△Smith Ida L Mrs
1239△Zimmerman Rosemary ⓘ
1241△Jones Dennis L ⓘ
△Bramley Frank L
1242△Rogers Hebron ⓘ
1243 Weekley Sadie Mrs
△Pellow Alf R
1244△Malzer Mildred
△Roberts Rose Mrs
1245 Evans Bessie Mrs
Hinson Mary E Mrs
Phillips Ernest
1248△Childres Thos
1249△Prenatt Loretta Mrs ⓘ
△Reid Thos C
1250△Club 1250 tavern
1252△Early Alf E
1253△Smoot Seymour ⓘ
1257△Lorries Restaurant
Northampton intersects
1260△Ebony Soda and
Snack Bar
△Preston Audrey Mrs
△Byrd Geo
Thomas Van C
1261 Cadet Cleaners
△Black Geo L
1262 Pet Laundrmat
1263△Aquiline Chas Liquor
Store
1264△Echols Bros Cleaners &
Pressers
△Lawandus Millinery
1265△Lawndus Mary L
△Wright Arth
1266△Jefferson Clarence
△Tibbs Morgan
△Dudley Ernest
1267 Glover Annie Mrs
△Weirich Adolph
△Williams Albert
1268 Vacant
1269 Candlo Robt J
1270△Parker Elma Mrs
△White Allen D
1272 Dahl Howard J ⓘ
1273△Hilliard John T ⓘ
△Harris Alf
1274 Vacant
1275△Hodgkins Elmer S ⓘ
△Routh Margt Mrs
1276 Vacant
1279△Scott John W ⓘ
Ellis John L
1280 Pieree Jos
△Williams Chas A
1281△Dockery Wm M Rev ⓘ
Davis Wilbert
1284△Zapf H Morton ⓘ
1285 Vacant
Eaton begins
1288△Davis Willie ⓘ
Eccles Jas L
1292△Blue Jas ⓘ
1296△Washington Wm
△Quarels Fannie ⓘ

1960 NORTH ST E

SOURCE: POLKS



D7 Vacant
D8 Donovan John C jr
D9 Verstraaten Mary E
D10 Collins Vincent P
D11 Sweeney Jill
198 **One Ninety Eight North North St Apts**
Cline Clinton S
208 Oldak Chester F furn rms
220 First Church of Christ Scientist
221 Vacant
Elmwood av intersects
226-30 **Ransom Apartments**
O'Connor Wm R
Hermanson Elinor A
Northcott Bettie
Tinto Edw N
Phillips Eliz B
Henk Madeline R
West Ethel M Mrs
Junge Olive A
Manimana Dominic R
Boltes Vicenta M
Loswick Ann
Colwell Alex
Knapp Josephine M
Seyse Lillian M Mrs
Norton Gilbertine C Mrs
O'Hern Mildred K Mrs
Moore Rhea S Mrs
Silverman Howard D
Wakeman Charlotte
Wood Jean R Mrs
Snowden Cath A
235 Service Systems Corp vending machines
Food Operations Inc caterers
Retail Credit Co
Royal Glove Ins Group
Mariner ends
245 YWCA (residence)
249 Reed Mildred M
Young Ester M Mrs real est
252 Reinecke Ottomar W
Burrows Helen Mrs
Elston Elsie
256 O'Brian Roland L
Messner Norma S Mrs
Jones Ruth N Mrs
College ends
267 Ransom Realty Co
Ransom Philip W
268 **Apartments**
1 Kearney Jas E
2 Fenno Laura M Mrs
3 Desmond Mabel Mrs
4 Flaherty Julia M
5 Huff Anne M
6 Wilson Ruth
8 Cowles Chauncey D jr
Street continued
274 Will Lillie C Mrs
279 Corcoran Mary G nursing home
282 **North Gables Apt**
MacLeod Duncan
Jenkins Stanley S
Brindle Gertrude
290 **Two-Ninety North Apt**
1 Mullen Florence R
2 Ryan Fredk G
3 Moore Rudolph J
4 Miller Mary A
5 Smering Janey R Mrs
6 Nelson Hazel Mrs
7 Kamm Victor F
8 Steul Ada R Mrs
9 Reilly Margt Mrs
10 Anthony Margt M Mrs
11 Alfred Helena R
12 Burkhardt Margt M
13 Barnett Norman
14 Eustace Ella M Mrs
15 Kassmann Robt J
Ace Alarm Co
Street continued
291 Franciscan Sisters of the Immaculate Conception
Nazareth Home for Convalescents
292 Olive Mathilda Mrs furn rms
Arlington pl ends
303 Casa Misericordia Convent
304 Smith Gertrude R Mrs
309 Cerebral Palsy Association of Western New York
Co-operative Pre-School Center
The Circle intersects

140
NORTH E—From 1039 Main east to Herman av (not open between Jefferson av and Timon)
5 Zimmermann Alvin
Donnelly Mary Mrs
7 Griffin Eva E
Cechmann Herma Mrs
9 Henry Mabel
Younger Hilda E
11 Uebelhoer Kathryn
13 Worley Florence C Mrs
Novitzke Wm J
14 Anchor Bar (parking lot)
20 Automotive Bin Services Co Inc
23 Poling Wilson pntr
25 Wendel Nathalie L
26 Pepsi Cola Bottling Co (whse)
27 Holt Cleveland
Taylor Betty Mrs
30 Standard Die Set Co die mkrs
31 Banks M Irene Mrs
33 Martin Naomi
Bell James E
35 Conrad Edgar C
36 Smith Arlene M Mrs
39 Rose Amy
Ruske Kurt E
41-43 **Apartments**
1 Gavigan Isabelle W
2 Gabel Herbert N
3 Walker Viola A Mrs
4 Beswick Florence L
Street continued
52-54 Pepsi-Cola Buffalo Bottling Co
Ellicott intersects
61 Carnevale Anthony J gro
63 Roberts Edythe Mrs
Ehmke Marie Mrs
Tell-Puleo Nicholas
68 Cullinan Edw D
Guenther Dorothy
69 Rodriguez Jose A
Dudley Kenneth J
70 Hornung Roy
Stutts Robt
Hobler Tibor
Garvey Philip J
71 Danforth Willard J chiropractor
Bornheimer Alf W
72 Hunter Annie L
73 Schlifke Conrad A
Dolinski Jack
Prochl Edna C
rear Bohn John H
76 Hawkins Clarence
77 Cook E A Body Co auto body mfrs
80 Restivo Mathew C
Butterbow Ward
82 Lewis Travis W
Turley Ulysses
86 Garvey P J Carting & Storage Inc
Gaudy Mary Mrs
90 Beardsley Chas
93 Clark Martha Mrs
Maloney Mary Mrs
94 Lyons Bertha E Mrs
Gillis Peter M
96 Kennedy Helen B Mrs
Hall Geo C
Welmont pl begins
99 Wolfs Delicatessen
Wolf Marion J Mrs
101 Jagadowski Sadie Mrs
Byam Chas
Horrigan Arlene
rear DeMarzo Jos
108 Banks Clayborn
110 **Apartments**
1 Poppenberg Cecelia A Mrs
2 Bailey Gordon R
3 Dupree Julius
4 Vacant
112 Keller Leo
114 Dunlap Adolph
Highsmith Marshall
Croom Walter
rear Verser Ernestine Mrs
116 Hackett Wm
Dolan Kath Mrs
118 Weigand Louise Mrs
rear Taylor Lloyd B
119 Jones Fred M
Kirby Wm J
120 Koniarczyk Walter
124 Fleming Kath Mrs
Keller Isabelle Mrs
rear Wallace Carolyn
126 LaBarge Marion M Mrs
Moran Robt E
MacDonald Maud E Mrs
128 Britton Edgar C
Sweeney John J
132 Grandillo Food Mkt
Hansen Hans

136
Elm intersects
135 Simon Geo W
137 Noon Mary M
LaHood Gabriel
Noon Isaac
140 Schaefer Henry
Kirby Clarence
141 Noon Chas C
Mosley Otis
142 Grafley John W
145 Smith Frank
Smith Paul
146 Musial Rita E
148 Mattson Geo
149 Erhardt Grace L
Cryan Michl J
150 Sawday Albert E
152 Scobell Geo B
Swartzlager Anne Mrs
153 Rohs Mary
Karnitz Albert G
156 Golden Nora F
DelNuovo Vincent
158 Hannon Alice G
Herbolsheimer Rudolf
Robinson Frank C
164 Vacant
Michigan av intersects
172 Duch Cath Mrs
restr
177 Sumling Robt
178 Vacant
Maple ends
179 Thuerck Edw
180 Brown Ruth Mrs
182 Maul Hulda P
Tolentino Ernesto
191 Huling Melvin
197 Croxie Lester
199 Holmes Nellie
205 Farmer Willie
207 Neuner Edw F
209 Wistner Ernest E
213 Bryant Louise Mrs
215 Wainwright Martha R
Mulberry ends
223 Sauger A
Schmeizle
225 Moon Wm
Evans Th
227 Stoll Chr
Sulkowski
nw cor Fosdick-
Vocati
as Masten P
237 Masten P
Church
249 Toellner
lee an
253 Penz Ern
Penz Ern
257 Bromley
Sharrer
261 Grass Ed
Grass Cu
263 Koch Ma
Staebell
265 Ingeborg
Hammer
Smith H
273 Thomas
Clark E
277 Eatman
283 Wollenb
Conners
Zirnheld
285 Dietsch
287 Laugste
Fisher
291 Brown
301 Green E
Evans
307 Kinsem
Taylor
309 Wilke
314 Roetzer
316 Kreuge
320 Bryant
cins
Webste
322 Hill's
Wiley
William
330 Kersel
Latona
332 Seibett
Glowar
333 Collier
336 Seale
341 Advanc
343 Devine
Nazare
Chu
Henry
346 Russ
Stuff
348 Randle
Reed
350 Mirabe
353 Muell
355 Pape
356 McCom
Willia
358 Labart
359 Burket
Talleht
360 Sturge
Cole C
361 Dirnbe
Human
Meiser
362 Endres
Nusste
363 North
nacl
Rowsw
368 Kreinb
Oehler
Kenlin
370 Nicker
Ohmne
372 Steven
Harmo
383 Eckert
Szczdr
(Not op
505 Wald
Jones
Lee Ch
rear Price
507 Foye J
Ingram
rear Warre
509 Weiss
Weiss
nur
511 Olczew
rear Baston
513 Neuroh
Steink
Green
Emerso
542 Ray B
Yates
Briggs
543 Schlia
Delerl
dell
545 Snyder
truc
Snyder
546 Schmi
Stahlb

1955 BEST ST-A

SOURCE: POLKS



427 Block Dale
430 Dietschler Edwin J
Feldman Edw W
432 Marcus Warner C
Guinther Edw J
436 Maloney Ira F
Tixler Wm J
437 Nuessle Albert E
Kelley Pearl Mrs
440 Dieter Josephine Mrs
Dieter Geo J
441 Schenk Eleanor I Mrs
442 Fix Otto J
Fiellet Wm D
443 Erb Albert H
444 Schalck Jacob A
447 Dunning Chas F
448 Haas Frank B
449 Schindler Henry M
450 Sedler Harry I
Scudder Stanley J
452 Banse Henry J
Dahlfors Ernest
453 Pearles Fredk C
455 Bauza Wm N
Bauza Wm C
456 Block Leonard H
Goepfert Albert electn
459 Hill Louella M Mrs
Robinson Mary H Mrs
460 Farrell Jos P
461 Frantz Jos P
462 Freund Chas F
Freund Chas F jr
465 Anderschott Jos J
466 Feglitti Orezo
471 Bostock John H confr
Suffolk intersects
475 Kensington Gospel Hall
478 Houghton Richd jr
484 Sinclair John T
488 Sawyer Chas H
Wittmer Carl J
480 Granata Saml
490 Seltz Eug F
Schmurstein Chas
492 Olsen Geo C
493 Andruschat Frank A
495 Rabenstein Edw M
496 Rug Norbert F
499 Horton Della L Mrs
500 Dahl Edw
Warner Merle
501 Ferguson Jos J
502 Kirst Eliz M Mrs
Lindner John
505 May Alf E
506 Spence Richd E
Harrison Harriet M
508 Sullivan Wm J refrig repr
512 Miller Richd F
514 Horn Earl
515 Nelson Florence D Mrs
518 Dundon Robt J
522 Theisz Fred H
526 Smith Geo E
530 Niederpreuem Jos M
534 Emery Chas D
536 Smith Fredk W
538 Koehler Lawrence H
542 DeWald Emery
Westminster av intersects

284
BERRICK ALLEY—From 142 Seneca north to Swan
(No houses)
Swan intersects

48
BERTHA — From 1300 South Park av north to Buffalo Creek
1 Carroll Roy
3 Block Howard F
5 Knauss Carl F
7 Bruckman Geo J
Bruckman Moving & Raising Co Inc
9 Schuster Edith Mrs coal
11 Kuzmich Nicholas
13 Bongiovanni Philip A
Rautenstrauch Wm A
15 McIver Wm
Blaszak Chester
17 McIver Jos W
rear Matwiko Frances Mrs
Buffalo Creek

180
BERWYN AV — From 384 Olympic av east to Bailey av
11 Archer Wm
14 Lord Willis T jr
15 Gosney Arth R
16 Winans Stanley
19 Lambour Chas X
20 Lipp Millard V
21 Ess Alb J
22 Repman Earl L
25 Handley Victor C
26 Gassman Leo P
29 Hagg Helen Mrs
30 Dickinson Wm F
31 Evers Wm V
32 Douglas Joyce
35 Miller Edw G
36 Hauk Florence K Mrs
38 Wlodarczak Frank J
39 Meinke Carl
41 Raab Albert A
42 Hannon John J
45 Knittel Harold D
46 Coveney John S
47 Thompson Harrison
50 Pauley Glenn G
51 Foley Agnes Mrs
Hollstein Herman J
52 Lacey Albert G
Beaty Lawrence
53 O'Brian Jos V
54 Kinmartin Madeline Mrs
57 Rachow John H
Rachow Kenneth J
58 Hale Marie A Mrs
Lee Howard L
61 Hise Alf G
62 Grimm Walter A
63 Stephen Fredk F
64 Robert Leroy H
67 Schlau Peter N
68 Herman Albert
69 Weber Edw H
72 Zimmerman Dorothy

BERWYN AV—Contd
73 Maulucci Pasquale
Maulucci Dani
74 Weiss Orville F
Michael Geo
77 Rambuss Fred H
78 O'Neil Florence Mrs
79 Heller Fredk
80 Matt Wm J
83 Zeller Walter W
84 Schieder Wm E elec motor repr
85 Haberstock Jos L
88 Jones Alton A
89 Walter Jos G
90 Fial Alex
93 Matthews Alex
Muellerschoen Robt
94 Drescher Casper J plmbr
95 Cook Gilbert G
96 Drescher Edwin H
99 Case Geo
Elyea Albert W
100 Genet John G
101 Klein Cyril A
102 Demerly Ben trucking
105 Folmer Andrew J
106 Schneider Jack
Rosinski Eug C
109 Ruber Fred W
110 Glass Margt E Mrs
Bailey av intersects

6
BESSEMER—From 281 Chicago east 1 block
(No houses)

146
BEST—From 1119 Main east to Genesee
4-16 **Best Apts**
bsmt Haun Frank R
1 Williams Edna M Mrs
2 McKee Harry S
3 Rocklin Edw S
4 Leary Wm L
5 Avey Morris F
11 Miller Chas G
12 Quigley Danl E
14 Kirchner Henry L
15 Grevish Ruby A
18 McElwee Vincent H
20 Hoen Alice M
21 Politis Geo
22 No return
23 Birch Harry
24 Drumb Louise
25 Browne Doris M
26 Larrin Vincent
27 Titus Marie Mrs
28 Ohlwater Frank J
29 Fredlin Herman B
30 Bakos Emmanuel
31 Kersburg Benj
32 Hanley Andrew J
33 Robinson John
34 Devlin Jas E
35 Nash Harry N
36 Nelson Harry R
37 Powers Thos J
38 Gamrath Lillian A
39 Sahner Florence
Street continued
22 Harris John G
Weideman Genevieve Mrs
25 Gannon Richd P
Bell Robt
26 LoCascio Vincent
Buehl Martha
29 Pohlman Donald
Shamp Bertha Mrs
30 O'Connell Eliz G Mrs
Lauer Cath
31 Powell Percy G
32 Hearn Wm
rear Flumerfeldt Ivan H patr
Somers Thos J
33 Seereiter Louise A
Reilly Paul F
35 Miller Julius B patr
Bieganski Jos
36 Haefner Frank
Duquin Wm G
Wagner Fred E
Gregory Norman
38 Wright Edwin H
Allen Clarence T
41 Logel Elmer A
44 Beresford Vera M Mrs
44½ Williams Vincent J
45 Niagara-Mohawk Power Co (sub sta)
46 DuQuin Arnold J
50 Drakes Hedley V
Drakes Jos H
rear Burdick Milton P
52 Anthony Anthony F
53 Club Fifty-Three restr
56 Kalib Zack T delicatessen
Ellicott intersects
65 Liptak Dorothy Mrs restr
67 Stevens Sarah E Mrs
68 Marz Carl W
Kane Frank
Miller John G
69 McKay Kenneth H
Hollederer Irving G
70 Weast Louis
Kraft Lily Mrs
71 Neal Leo
Barnes Marie Mrs
72 Melser Raymond A
73 Vacant
74 Syracuse Salvatore
Colognino Salvatore
Trombly Norman
75 Stesiak Chester
76 Williams Richd
79 Ciucas Geo D Inc plmbr
Baumgarten Mary Mrs
Welmont pl ends
80 Steller's Bakery Inc
86 Marth Rudolph
Weber Kenneth
88 Beckett Rose Mrs
Bowers Wm
90 Aschbacher Walter C
Kelly Walter
93 Beckerle Jos
Beckerle Francis X radio repr
Schiffer Henry H jr
Johnson Fannie W

1955 BEST ST-B

SOURCE: POLKS



BEST—Contd
95 Winter Anna B ⓦ
96△Dreissen Josephine D ⓦ
97△Collett Harold E ⓦ
△Schmidt Edw W
98 Kubik Chas J
△Ackerly Robt E ⓦ
102 Crocker Lewis S
△Steck Frank
103△Beach Ellsworth A ⓦ
△Wagner Anna J
104△Malecki Jos
Heymann Freidhelm
rear Trapp Jos
105 Schmidt Millie Mrs ⓦ
rear No return
108△Schwarz Harry G ⓦ
pntr
△Wilson John R jr
111△Schaller Richd P ⓦ
112△Pokolm Kurt J ⓦ
113△Pelow Gert Mrs
115△Barone Salvatore ⓦ
△Shaver Lee
116△Peard Anna G Mrs
117 Green Geo
△Clare Henry P ⓦ
118△Fee Lawrence C
120△Warner Ida E Mrs ⓦ
△Jackson Wm
Lowry Ralph
Elm ends
122△Ahlheim Saml G ⓦ
Ravenos Julius
125△Simmons Cath Mrs delicatessen
126△Coppola Dominic ⓦ
△Lenau Hugo
127△Turner Merline L
Gauger Fred
rear DeBon John J
129 Grady Maude E
130△Mortok Albert L ⓦ pntr
△Boncaldo Jos S
△Boncaldo Frank
131△Mason Wm
△Newton Fanny
133 Pfeffer Theo H
rear△Evert Erwin F
134 Rysman Myrna
Lirak Alex
△Weiss John P
rear△Geddes Araleen C
135 Richardson Walter P
rear△Smith Sadie E
136△Gueth Marian O ⓦ
138△Arida Raymond K ⓦ
△Sarkis Kath
△Smith Arth J
139△Neal Chas A ⓦ
145△Blatner Norman gas sta
150△Berti Louis E gas sta
Michigan av intersects
159 Terray's Delicatessen
Sukora Frank
△Michael Lillian R
rear△Terray Wm R
160△Lamm Susanne Mrs ⓦ
restr
161△Hogg Gerald W liquors
162△Jarvis Jas J delicatessen
163△Healy Francis ⓦ
Leslie Norman
164 Edwards Claudine Mrs
165△Dewitt Jas
166△O'Connor Wm I
△Hill Harry
167△Comtors Lucian
168△Wilcox Frank C
174△Thur Geo W paperhngr
176△Mumm Caroline A Mrs ⓦ
178△Beck Henry J ⓦ
184 Wetter Wilhelmina
186△Fletcher John H
190△Smith Leslie E ⓦ
192 Frank Richd I
△Pierce Wm C
△Goodwin John T
196△Incorvaia Raymond
△Gehl Steph J ⓦ
200△Schmidt Wm ⓦ
202△Sarikas Theo ⓦ
Athanasiou Angelo
206△Hogg Phillip ⓦ
Hogg Gilbert
△Knappert John W
208△Fowler Eloise Mrs
210△Craik Alex L
212△Baldwin Chas V ⓦ
216△Carl Oscar A
△Zimmerman Richd A ⓦ
218△Beeny Lauretta E
222△Ott Arth ⓦ
△Meseches Kenneth S
132
Masten av intersects
311△Staub Arth C
315△Widelski Leo
321△Kulick Louis
△Michalowski Edw jr
323△McCarty John J
△Hopkins Earl N
Peach ends
329△Dimino Rose Mrs
△Agnello Silvio B
△Dimino Emanuel C ⓦ
331△Catalfamo Frank J ⓦ
△Catalfamo Carmen F
337△Vroman Cora C Mrs ⓦ
339△Kelmenz Louise Mrs ⓦ
△Klemenz Eug
341△Handel Fred A
345△Fabiano Saml ⓦ
347△Lageman Bertha S Mrs ⓦ
△Kilgore Jas F
△Thomson Thos C
Grape ends
357△Bravo Porfirio ⓦ
△Andrus Stanley
359△Small Clara L
△Atwell Harold J
rear Mooney Norman E
361 Palmisano John ⓦ
363△Mosier Loretta Mrs
Palmisano Peter
rear△Ellsworth Frank M
△Scheffler Fredk W
369△Storms Robt S
△Espow Isadore A
Werner Fred H
△Heanney Margt Mrs
△Stutz Wm N
△Rote Burnetta M Mrs
Kirchner Herbert
371△Baby Health Institute furn
nw cor△Buffalo Civic Stadium
128
Jefferson av intersects
400-20△Langs Creamery Inc
△Lang's Plaza Inc real est
Wick Carting
401△Coon Frank
△Decker Delmor ⓦ
403△Schaedel Earl V ⓦ
△Morehouse Ella M Mrs
407 Cooper Mildred B
△Sullivan Kathleen Mrs ⓦ
409△Stadium Liquor Store
rear Gravewelle Donald
410△Loblaw Inc gros
411△Siffling Theo J
Youngman Milton H
rear Winzenried Albert
413△Opel John
Earl pl ends
419△Georgian Beauty Salon
△Chamberlain Phyllis H
Dash Francis H
421△Engine Co No 21 BFD
423△Hook and Ladder Co No 6 BFD
427△Guppenberger John
△Hochhauser Fredk ⓦ
△Rasch Clara E
Smith Harry
429 Lina Theo C
433△Lina Rose Mrs ⓦ
△Koch Ella
435 Reger John B ⓦ
△Boll Edwin J
rear Reger's Auto Glass Shop
439 Niagara Mohawk Power Corp (sub sta)
445△Gates Jos D ⓦ
Pershing av intersects (ns not open)
453△Rath Edna Mrs
△Highfield Jas ⓦ restr
△Jevens John W
457△Adamczak Chester A chiro
458△MacDonald Holford T
△Klein Emily Mrs
458½△Kennedy David J
460△Fleming Jas
△Keller Fredk ⓦ
461△Buchbinder Alois B ⓦ
464△Fries Earl G
△Fries Florence L Mrs ⓦ
465△Hug Frank J jr ⓦ delicatessen
△Herman Edw
466 Cierlicki Stanley S
△Andrzejewski Frank ⓦ
469△Vogelsang Edw funeral dir
△Duge Arth
470 Johler Jacob
△Casper Marie Mrs ⓦ
472 DeAngiolis Peter ⓦ
△Sceusa Mary Mrs
473 Binger Geo E ⓦ
476△Holzworth Albert ⓦ
Backes Kenneth
477△Banas Jos A ⓦ
△Osuch Chester
480 Simon Agnes A
△Pliss Nathan ⓦ
Timon intersects
485△Asylum of Our Lady of Refuge
△Sisters of the Good Shepherd Convent
488 Schillo Rose Mrs
Hausbeck Anthony J
492△Bachhofer Wm C ⓦ
494△Fruth Matthew R
△Busch Wm
△Brucker Mathias
496△August Geo C
△Hotheins Norman G ⓦ
498△Weber Eliz S Mrs ⓦ
500 Cox Margt
502△Hoeppner Martin J Rev
Roehrer av begins
518△Funk Arth L ⓦ phys
522△Ludwig Howard J ⓦ
△Becker Clara B Mrs
528△Panziea Anthony G
△Lake Clarence C
530△Flierl Alex W
△Flierl Raymond C sewing mach repr
534 Mayle Herman F
126
Johnson ends
536△Harper Jerome J
Gambacorta Jos A
Wohlers av begins
537 Krempa Casimer F
△Fisher Frank J ⓦ
541△Prong Harry E
△Fogg Leonard H ⓦ
543△Kempf Robt A
△Piskorski John ⓦ
548△Guderian Fredk W
△Prince Harry ⓦ
550△Angermyer Elsie B Mrs
△Guenther Henry ⓦ
551△Richert Beatrice R ⓦ
△Martin Geo O
553 Thielke Allen A
△Heubusch Paul H ⓦ
555△Best Barber & Beauty Shop
△Gambacorta Mario J ⓦ
556 Elliott Laura
△Fass Chas ⓦ
557△Gambacorta Jos A dentist
△Fernetti Ferucclo ⓦ
△Heintzman Edwin C
561△Pauly Urban ⓦ
Mann Philip B
△Costello Geo
563△Halpern Julius ⓦ drugs
Kellogg Birdsell jr
Norway Park begins
Sherman ends
571△Jim & Em's Restaurant
△Cataldo Jas
575△Ken's Little Super Mkt
△Schmitt Steph R
△Winkler Jos J ⓦ
577 Gambacorta Louis barber
579△B
583△K
585△S
587△J
△A
△L
591△H
△B
593△B
△M
△B
W
rear△W
597△B
△E
△L
Z
600△L
605 B
B
△E
607△K
△J
613△C
615△C
616△C
△E
617△E
618 V
620△I
623△I
643△
653△
657△
659△
661△
669△
673
675
679△
681△
683△
687△
697△
699
701
703△
711△
rear
713△
717△
723△
727△
729
rear
733△
737△
739△
743
747
753
755
759
761
765
775
781
783
785
791
793
797
799
801
805
807
809
811
BEV
1
P

1955 ELLICOTT ST-A

SOURCE: POLKS



425 Vacant
427△Nigrelli Thos D prod
429△Oswald Bros meats whol
431△Dante's Restr
433△Schinas Candy Co
435△Bockstahler Henry W florist
437△New Market Inn
△Liptak Geo
439 Schwegler Furn Co (whse)
441△Thomas Printing Serv
443-45△Steinhauser Meat & Provision Co
rear△Wilson L C Div of Hygrade Food Products Corp whol meats
447-49△Buffalo Poultry Supply Co
455△McClelland Veterinary Hosp
Williams Benj R
457 Dechert Wm M restr
461-63△Lang Gerhard Meats & Provisions Inc
StMichael pl ends
465-69△Cy & Ken Market Garage
471△Dorriess F & Sons fdry
473-75△Wehle Electric Co Inc elec equip
481△Fingeret Bros prod
487-89 Bell Robt
491△Leeb Sign Co
501 Depaolis Gaston
△Carpenter Madeline Mrs
△Kopack Wesley L radio repr
503 Barbarno Ralph
505 Flanders LeRoy
507△Palmer Lloyd R
△Hancock Jos J
509△Burns Allen Co
△Sturner and Rovall Inc
511 Stoddard Earl
513△Comtais Antoinette ⓦ
515 Miller Walter
△Stoddard Geo E
517△Preston Elec Co contr
519△Sterling Silver Plating Works Inc
520△Frey The Wheel Man Inc auto wheels
522△Loomis-Root Inc auto accessories
523△Barnhart Frank E gas sta
530 Goretto Camillo
Redeye Julian
140
E Tupper intersects
538△Dowser Oliver A
Bill and Erm's restr
539 No return
540△T-Bone Restaurant
543△Queen City Welding Co
544△Kaiser Hamilton
Hilliker Oscar
545△Garlock Mary Mrs
546△Gallineau Ruth Mrs ⓦ
Lenius Alf G
548△Dewey Geo ⓦ
Steinmetz ——
Boppel Jos
549△Berti Edw ⓦ
△Komas Andrew
552 Sauriol Lucien
553△Herbold Printing Co
rear△Rhoe Isabelle Mrs
Young Geo J
554 Stemler Geo L
555 Todd Douglas C ⓦ
556 Long Louis W
Kelso Maybelle Mrs ⓦ
559△Interchemical Corp-Prntg Ink Div
△Henneman F W & Sons
560 LoCastro Alf G ⓦ
562△Oestereich Max
563△LaPlaca Jos H ⓦ podiatrist
Greco Mary
Pineino Frank
564 StPaul's & StMark's United Evangelical & Reformed Church
567 Donaghy Myrtle Mrs ⓦ
571△Marracino Albert ⓦ
△Burke Jessie M
Warren Charlotte E Mrs drsmkr
△Oliver John J
574△Buffalo Dental Laby
△Smith Reuben J
Busch Chas E
577△Thomas Mamie ⓦ
578 Lucas Thos M
△Alvord Elsie G Mrs ⓦ
△Miller Geo L
Armond Geo
582 Kubik Anna Mrs
583 Zeile Anton ⓦ
△Ostrovskis Donats
Viguos Donats
Ceplitis Janis
584 No return
587△Doll Olive E ⓦ
590△Queen's Daughters Working Girls' Home
596△Hackenberry Harry
601△Maurice Hotel
△French Quarters Lounge restr
602 Vacant
Goodell intersects
Burton intersects
648-54 Trico Products (whse)
674△Ulrich Restr
Virginia intersects
682△Yax Rose G Mrs ⓦ
686△Rombach Helen Mrs beauty shop
△Wood Grace M
687△Eusanio Thos ⓦ
690△Wild John ⓦ phys
691 Bauman Eleanor E Mrs
△Marten Lillian C
693△Ellicott Clinic and Hospital Inc
694△Butler Robt O

ELLICOTT—Contd
699 Curry N Chas
Stevens Jas
Everbert Gene
700△Mercurio Antonina Mrs
703 Knapp Edith S Mrs
704△Kam Ottilia Mrs ⓦ
705△Stoesen Jessie R Mrs ⓦ
△Hulin Albert L
708△Buffalo & Erie County Tuberculosis Assn Inc
709△Mathers Harry J ⓦ
710△Tsilimos Anna Mrs ⓦ
711△Gronowski Walter F
714△Metcalf Richd E ⓦ
△Crary R Ralph
715△Koehler Frank G ⓦ
△Mysker Mildred Mrs
717△Edwards Alvine E Mrs ⓦ
720△Nissenson Wm Rev ⓦ
721△Moersbfelder Louise M ⓦ
723△Calos Anthony
△Shearer Laura Mrs
724△Werkley Howard ⓦ
Bayliss Donald
727△Modica Anna T Mrs
728 Vacant
731△Leber Jos A ⓦ
732△Lenew Mary E
△DelBello Anthony
Dickman David A
735 Whitney Clare W
△Fredriksen Carl H ⓦ
△Lyons Frank
△Pluto Chester
738△Brady Chas P
Boldinski John
739△Nenno Mary Mrs ⓦ
741 Vacant
Carlton intersects
751△Parisi Jos ⓦ
752 Brawn Geo W
755△Perner Cecilia M ⓦ
756△Cordner Robt D ⓦ
759△Dewes Gertrude T Mrs ⓦ
760△Hock Wm L ⓦ
763△Baker Jas T jr
Baker Chas
766△Graesser Anna J Mrs ⓦ
769△Devlin Mabel A Mrs ⓦ
770△Berta Jos ⓦ
△Abella Jos ⓦ
Kingsland Fredk G
771△Hamele John ⓦ
773△Crittenden Bertha Mrs ⓦ
774△Lindner Henry P ⓦ
△Schindler Thos
Lockwood Alton
△Zebold Clarence Mrs
Fairell Emma
Zimpfer E C
△Compton Howard H
782△Speyser Louis T ⓦ
△Beer Louis H
783△Gaetz Veterinary Hosp
△Gaetz Hiram T ⓦ
△Gaetz Leonard H Funeral Home
△Gaetz Leonard H
783△Potts Henry R
788△Kessler Geo C
△Bell Lucy Mrs
△Maxwell Frank A
789△Heft LeRoy T
△Scott Lucille Mrs
792△Paravalos John ⓦ
793△Newton Richd
Warner John
796 No return
797△Eddy Arth R ⓦ
798△Murray Grace Mrs
802 Trouton Ollie Mrs
806 Vacant
High intersects
822△Simpson Willard F ⓦ
823 Sullivan Robt N
824 Delebart Danl
△Hynes Sarah Mrs ⓦ
826△Miller Anna Mrs ⓦ
830 Ellis Thos
Burke John J
834 Campbell Wallace
△Ryan Wm F
△Huegel Betty
836 Paananen Shirley
△Stinson Lloyd E
Blackwell Marion Mrs
Williams Henry G
839 Buffalo Genl Hosp (dormitory)
840△Roberts John T
△Rich Donald P
842△Laney Edw
843 No return
845 No return
Goodrich intersects
854△Haberl Mildred M
△Williams Ellen J Mrs
860△Baecher Chas K ⓦ
863 Finch Albert M ⓦ
△Tuschl Jennie
864△McGee John R jr
△Wallasch Clara L ⓦ
866△Bricka Della Mrs ⓦ
867△Neubeck Marjorie
△Curry Grace Mrs ⓦ
870△Yahle Fred V
△Warne Angeline M
871△Wampach Mildred B Mrs
△Lippi Wm J
rear△Reisch Caroline A Mrs
872△Smith Mary A ⓦ
△Hurley Wm J
876△Hagen Jack barber
rear△Green Mary Mrs
878△Shelton Walter W
△Becker Fredk C restr
E North intersects
886△Guldner John H ⓦ
△Sees, Albert J
890△Atwood Kenneth
△Desenrath Esther M Mrs
892△O'Connell Danl
Letke Theo
894△Schingeck Cornelia K Mrs
Schingeck Geo W

1955 ELLICOTT ST-B

SOURCE: POLKS

ELLICOTT—Contd
898 Kohlbrenner Anthony J
Barden John J
900 Klass Herbert F
Klass Kenneth J
903 Fisher Ida Mrs
Asselin Chas L
905 O'Connor Gregory
Seymour Eliz Mrs
908 North Ellicott Service Garage
909 Krombein Walter H
913 Fuss Flora F Mrs
Battaglia Wm
StPaul intersects
931-35 Main Window Cleaning Co
Main Building Maintenance
938 Warco Machinery Corp
Warco Products Corp mach parts
Daniels C R Inc canvas gds
Auto-Bar Systems bar supplies
United States Guage
146
Best intersects
961 Morgan Piston Ring & Parts Inc auto access
967 Nebrich & Co auto reprs
969 Gillmore Jas J
Biggie Henry H
Merkel Irene S
970 Apfel Walter H clo cln
Sheesan Nelson F
Adamczak Henry J
971 Kelly Irene A Mrs
Pratt Wm J
972 Vacant
rear Crean Martin F
973 Roper Abram A
Spink Gertrude A
977 Kingman Warren E
978 Kelly Letter Service
979 Koch Frank P
rear Steep Norman F
Edna pl begins
980-86 R W Maintenance Corp
Tree Care Inc
Osmose Wood Preserving Co of America Inc
990 Seames Margt Mrs
991 Stellaway Mildred E
Brown Genevieve M Mrs
993 Kreller Helen Mrs
Liebel Harold G
994 Bachman Anna M Mrs
Ness Marshall T
996 Moody Grace
Garrido Geo
997 Amann Raymond T
998 Potter Jules H
Balentine Gertrude
rear Bruce Robt J
1000 **Apartments**
1 Fisher Anne C
2 Crean Margt M
3 Costello Margt A
1001 Hickey Anna
Ebnet John int dec
Paul Barbara Mrs
1002 **Apartments**
1 Ingersoll Sterling
2 Vastola Jos C
3 Vastola Anthony
4 Juliano Jos J
5 Agne Louis M
6 Evans Anna S Mrs
1006 LoCascio Vincent barber
1007 Calvary Evan Lutheran Church
Dodge intersects
1031 Novitzki Wm
Sheehan Michl
1032 Hettrich Electric Service auto reprs
1033 Aaron Jack E
1034 O'Malley Jerome
1035 Birbeck John
1036 Burge Mabel
Mellener Louis W
Reiss Frank H
1037 Zarbo Lawrence
1040 Higgins Roy H
1041 Rick Edw A
Rick Edw A jr
1042 Breslin Wm P
1044 Weber Elmer W
Coe pl ends
1045 Bishop Frank H
Zakrzewski Alex
1047 Fisher Albert D
Martin Marjorie Mrs
Southampton begins
1050 Hunniford John
1054 Boore Ada Mrs
1056 Smith Wm
1059 Wilson Alex
McGranahan John B
1060 Boore Chas H
1061 Gross John
1062 Smith Wm H
1063 Bugman Dorothy M Mrs
1066 Lannen Sadie M Mrs
1067 Delzoppo Orlando
Lee Harold K
Stevenson Violet L
Herl Albert J
1069 Nichols Elmer C
1070 Mauerman Robt E
1072 Hamister Edwin
Schuelling Rose Mrs
1075 Whitmeyer Beatrice M
Northampton intersects
1094 Rueckwald Martin C chiropractor
Haier Geo H
1097 Forbes Clara
Cook Leighton
Allen John
1098 Grimm Rose Mrs
1101 Huntley Clinton
Guenther Harry V
Fedora Anthony
Evers Everett
Schmoyer Morse
Knell Roxey
1102 Hardick Paul G
1105 Lonca Jos
Golownik Jos
1106 Anderson Laura Mrs
1109 Reimondo Sylvia M Mrs
1110 Jehle Grover A
1113 Durshordwe Albert
1117 Durshordwe Gerard W
1121 Goins Ellen M Mrs
1123 DesJardins Edwin E
1127 Goldsmith Llewellyn L
1131 Bernard Edw
Hartman Geo
Paulus Stanley
Courtly Mary
1135 LaMacchi Carl
1137 Baumann Edwin J
1138 StVincent dePaul Female Orphan Asylum
1141 Schlickemrieder Minnie E
McCann Marie A Mrs
Riley intersects
2B-7
ELM—From 124 Swan north to Best
11 Vacant
15 Vacant
Booth al intersects
17-21 **Gutman Building**
Bates Jackson & Co steel engrs
Schwartz Jewelry Co Inc mfg jwlrs
South Division intersects
38 Freire Emilio billiards
41-43 Dynamo and Motor Exchange Inc
2B-9
North Division intersects
70 Pinta's Serv Sta gas sta
Akron al ends
2B-12
Eagle intersects
94-96 Vacant
95-97 Jordan Supply Co Inc refgrs
101 Worthington Pump & machy Corp (whse)
102 Public School No 35
120 Fox & Fox Inc lithograph fnshr
Clinton intersects
141 Hager E M & Sons Co millwork
150 Tillman Eliz
Edoweese Aameen
154 Araya Gustavo
William intersects
161 Reo Motors Inc (br)
161-71 Chretein Storage Warehouse Inc
162 Goodrich Pearl beauty shop
164 Gedley Thos
168 Dickinson Matthew
170 Davis Mary Mrs
Gilbert Barbara A Mrs
173-75 Case W A & Son Mfg Co (Sackett Elec Supply Br)
176 Newman Robt J
Boen Rodulphus
Willeughby Jessie
177-79 Chretien Storage Warehouse Inc
Am Red Ball Transit Inc
178 Steininger Chas
181 Schmidt Chester J
185 Kalogeres Alex restr
187 Vacant
189 Elm Lounge restr
Turner Blanche B
2B-14
Broadway intersects
210 Menifee Chas R
212 Kre Kre Oriental Restr
Agathos Geo K
214 Meyer Body Co Inc truck body mfrs
234 General Ice Cream Corp (shops)
236 Vacant
237-53 Dwelle-Kaiser Co whol paints
240 Podskohem Napoleon
242 Hill Jas
Benford Alex
246 Jones Kenneth I
248 Vacant
259 Jackson Charlotte Mrs
267 Smitty's Laundry Serv
Littlejohn Broadus G
Smith Cleveland
Sycamore intersects
280 Wisniewski Edw F
Ellis Jas C
284 Green Wm H
286-308 Monarch Storage Co
289 Pilarz Walter A
Sullivan Ruth Mrs
291-97 Taber Pump Co Inc pump mfrs
294 Nestles Co Inc
303 Eastwood Wm
309 Vacant
311 Saraceno Dominick
312 Radio Equipment Co (whse)
Morrison Isabelle B
Kast Frank W
Morgan Leo
318 Tredo Clyde A
319 Greene Essie Mrs
320 Leis Chas W
326 Progress Distr Corp elec appliances whol
327-29 Harvey & Carey Inc (ofc and whse) drugs
328 McDowell Henry
Gibson Charlena
330 **Apartments**
1 Griffin Allen
2 Elmore Mattie R Mrs
3 Warner John
4 Brown Elnola
335 Vacant
337 Buffalo Radio Exch
2B-15
Genesee intersects
350 Morgan Lee
352-54
1 Jan
2 Sen
3 Sw
4 Wo
5 Ha
6 Mo
7 O'
8 Bu
356-60
Am
361 Des
368 Ha
Ha
Be
374 Ba
Br
375 Ka
Cla
377 Pi
Pi
378 Fe
380 Tr
rear Ko
381 Sh
382 Sch
385 Ho
386-92
No
387 Su
Sch
389 Sk
391 Li
Li
393 M
394 La
399 K
La
400 R
402 B
403 So
404 Sc
Ko
405 St
Sc
M
406 W
W
409 Su
Bl
410-12
E
419 Sl
Jo
A
Sa
420 M
C
S
421 F
K
423 S
C
427 S
428 C
429 B
B
430 K
A
433 M
P
434 C
G
435 P
S
L
436 S
437 V
F
rear P
C
438 E
C
rear S
E
439 E
F
440 V
441 A
442 F
445 E
S
I
446 C
447 A
448 I
450 I
451 A
452 A
A
453 A
A
454
457
459 A
A
rear I
460
462 A
463 A
464 A
465 A
467 A
468
469 A
470
471 A
475 A
476

1955 GOODRICH ST

SOURCE: POLKS

GOODELL—Contd
147 Porter Harriet Mrs
Cosentino Gerald J
148 Selle Arth J plmb Bingemann Flora Mrs
149 Josephine's Dress Shop
O'Neil Charlotte Mrs
Moore Antionette Mrs
Stinson Joan
151 Indelicato Benj gro
152 Niagara Piston Ring Works
153 Smith Irene
Sardes Lawrence H
rear Hayes Wm M
Bailey Geo T
Elliott Louis
154 New York Painting Co
Hodgson Lester
rear Psaros Nicholas
Pappas Jas L
Werrick pl begins
157 Weber Hattie A
Gebensleben Laura J Mrs
Mack Irene J Mrs
Foegen Bernard
159 Messina Jos shoe repr
Gori Giulio
Edwin pl ends
165 Smith Lillian beauty shop
Stolla Pauline Mrs
166 StPhilip's Episcopal Church
Brown Osmond H Rev
167 Abbatoy Cora
Bosnalis Eliz Mrs
168 Pax Irene M beauty shop
Pax Henry
170 Valazza clo cln
172 Nazarene Spiritualist Church
Henry Rowland A Rev
Michigan av intersects
180 Bflo Assn for the Blind
Ulrey Thelma G
Olsen Andrew
184 Vacant
185 Stumpf Ellsworth A
186 Vacant
187 Patti Angelo televi repr
Nehrbass Julia Mrs
191 Hinton Addison
Amerson Jas
197 Schuler Leonard F
Parks Hubert S
rear Martin Robt E
Maple intersects
205 Mohr Horst
McGraw Wm J
Johnson Gustav A
Reynold Theresa Mrs
206 Vacant
rear Bobo Clara Mrs
207 Lohman Vincent J
Putt Herbert V
208 Owens Harold
210 Zillig Christine
Wabick Edw A
211 Fuligni Mario
Esposito Ralph
212 Pixley Ira J
Roth Saml P
213 Schenk Henry A
Sturdivant Prudence V Mrs
213 ½ Webb Wm P
214 Knott Stanley
215 Dudley Jason
Watson Anna Mrs
216 McCallum Hallie Mrs
Yates Frank C
219 Amigone Frank C
Fitzner Chas
Coobaugh Theo
rear Hart Thos A jr
220 Petruso Jos D
222 Levine Richd
Beyser Geo J
223 Matt Jos M gas sta
224 Minklein Richd J
Siejak Richie
Mulberry intersects
232 Knab Albert F liquors
234 Fuerter Fredk A barber
238 Puccio Frank T delicatessen
Incavo Francesco
240 Paoletti Amedeo
244 Miller Jacob filling sta
Cherry intersects
50
GOODLIFF — From Hopkins east ½ block, 3 north of Marilla
(No houses)
140
GOODRICH — From 1005 Main east to 1044 Michigan av
20-22 Veterans Administration (side ent)
26-28 Alemite Sls Co of Buffalo Inc lubricant equip
27 Vacant
30 Vacant
40 Barron Chas
41 Squirt Beverage Co
42 Smith Wm
43 Norris Francis A Mrs drsmkr
44 Abrams Jas S
Germaine Anatole K
48 Cook Bryant
Souter John
Habrel Millie Mrs
Ellicott intersects
66 Rowley Robt K
68 Smith Glenn
Manfredini Anna Mrs
70 O'Neil Agnes F
Yale Donald
782 Maxson Herbert B
Hutchinson Haldon C
74 Silvis M Grace Mrs
Galioto Lucy
Galioto Saml J
82 Paolucci Emanuel
Kauffmann Geo
82½ Furlani Edw
84 Vacant
86 Walker Wm
Johnson Theo R
88 Roberts John E
Yaiser Jack
90 Hoops Caroline Mrs
Clere Marie Mrs
92 Armstrong Bessie J Mrs
100 Harrington House (Bflo Genl Hosp Nurses Home)
112 Hamlin House (Bflo Genl Hosp Nurses' Home)
136
Elm intersects
131 General Hosp (storage)
134 McKee Z Pearl Mrs
Smith Kath J
140 Raczka John
142 Fries Raymond H
144 Spoor Easter C
148 No return
152 Rodenbuecher Wm
rear Bickelman Albert G
Bickelman Albert G jr
158 Stearns Jos W
Michigan av intersects
98
GOODYEAR AV—From 1430 Broadway north to E Ferry
16 Boryszewski Casper
17 Wisniewski Jos V
Burek Stanley
Heverly Helen M Mrs
18 Przybyszewski John F int dec
19 Chodkowski John
Cichocki Walter S
Lotys Wladyslawa
22 Kryszak Jos H
23 Szablewski John
Penke Ervin
24 Jiagielski Stella Mrs
Konieczny Bernard
25 Stanski Frances Mrs
Szmania Bernard
28 Krakowiak John A
rear Wigdorski Leo F
29 Zaganiaczyk Stanley J
31 Sliwiecicki Stanley
32 Zogoda Cecelia Mrs
33 Barczykowski Raymond
34 Kazmierczak Rose Mrs
35 Pietraszak Rose Mrs
Andrzejewski John B
36 Dembinski Dorothy P
39 Kurzel Bernard M
40 Wojnowski Leo A
Andrzejewski Frank
41 Nadolinski Edw
Hartshorn Ivor
42 Twitchell Geo B
45 Witkowski Frances Mrs
46 Kozurkiewicz Chester W
Sobkowiak John
48 Prusak Frank
49 Zagora Stanley T
Florczak Jos B
52 Buchorski Simon
Karla Wm G
53 Kryczko Walter
Kryczko Mathew
54 Kornaszewski Mamie Mrs
55 Herzog Bernard L
Jurus Mary Mrs
57 Lokcynski Geo F
58 Witkowski Leonard
59 Shine Donald
Empire intersects
85 Baty Wm E
Banas Andrew
Sudlik Chester
89 Pokora Jacob
90 Rybarczyk Thaddeus
Brzyski Stanley F
92 Bartczak Bronislawa Mrs
95 Hojnacki Bros house movers
98 Szymanski Chester
Kijek Arth J
Lyczynski Leo
99 Krakowiak Julia Mrs
Krakowiak Walter E
101 Nasilowski John
delicatessen
102 Bittner Sophia Mrs
Zgoda Harry
rear Rados Raymond
103 Karpik, Frank W
Jedrzejewski Henry G
104 Kasiewicz Jos
Mazurkiewicz Louis
Dobrzynski Casimer
106 Dolka Steph
Grochocki Jos E
107 Zielinski Frank J
Halecki Jos P
108 Zaremba Adele E
109 Jakubik Jennie Mrs
Gabryszak Stanley F
111 Orzechowski Bernard
113 Wiluk Angeline Mrs
Zulawski Valentine
114 Lisica John
116 Szubinski Frank
119 Zalikowski Vincent
Schultz Florence
120 Drzewiecki Frank
Binda Jas
121 Wojdylak John F
rear Guszak Steph
122 Ratka Michl
125 Gabrykiewicz Stanley
126 Iwanowski Wm
Zgoda Eug
127 Arent Boleslaw
128 Barzyeki Chester L
Kubiak Anthony M
131 Babin Fred
132 Rebisz John
133 Wollenberg Bros feed mill
134
158
160
164
168
170
171
172
173
174
rear
175
177
178
181
182
183
184
185
187
188
189
190
191
194
196
199
200
201
202
203
205
206
207
208
211
213
214
215
220
222
224
225
226
227
228
229
230
231
234
235
236
237
238
239
240
241
243
244
245
247
248
249
250
251
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292

1955 MICHIGAN AVE

SOURCE: POLKS



939 Sorel Jos
△Pollino Frank F
rear Pollino Jos
940△Dello Chas tailor
△Nehl Francis N
942△Carlton Grill
943 Vacant
Carlton intersects
946△Cole Gladys Mrs gro
△Scherrer John V
948△Ellicott Realty Corp
948½ Kippes Anthony barber
950 Nurmi Manda Mrs
Kuhnhaeuser Reinhard
952△Lewis Timothy
rear△Klouses Geo N
Cody Leon
953-57△Batt Co Inc plmbs
958△Ball Albert
△Hammer Esther Mrs
959△Romano Jos
△Romano Salvatore V
960△Green Otis
Worthery Fannie
961△Holden Thos
△Twiner Amos
△Mays Ora Mrs
962△Saunders Edw
965△Murray Ardella Mrs
△Sardina Mary
△Sardina Josephine Mrs
966△Berry Jas
967△Jeanette Victor
968△Caito Rose M Mrs
972△Clark Edw D
△Bobo Ada
974△Anchor Printing & Engraving
△Mays Benj
△Hall Chas L
△Johnson Frank
975△Dimitri Mary K Mrs
△Erler Jas S
rear Wood Winifred V Mrs
977△Pfohman Jacob P
△Pfohman Jos J
978 Harter Florence Mrs
△Harris Raymond
979△Parker Raymond Smith Frank
rear Bortells Sophia Mrs
982△Hunter Carnell
rear△Franklin O'Dell
△Lester Julius
983△Paramount Beauty Salon Barnwell Clementine Mrs
△Barnwell Hushell Anderson David L
△Grisby Jazz Mrs
984△Schneider Sophie M
rear Haueise Robt C
985△Thompson Jas E
Harris Jas
986△Hanley Hugh P
△O'Grady Geo
987△Hopkins Dora Mrs
△Schneider Carl L
989△Wisniewski Steph S
△Oelschlaeger Robt
990△Small Evelyn Mrs
△Elias Sadie Mrs
993△Wieland Christina Mrs Reinhardt Rita Mrs
△Megrill Beatrice
994△Clark Gertrude B Mrs
△Davidson Edmund
995△Smith Rosetta E Mrs
△Smith Walter G
996△Pike Wm E
△Bonaparte Mamie Mrs
997△Nestel Norman J
Kammerer Mary
1001△Varn Susan F beauty shop
△Monfluetho Anthony
1009△Stegner Allen E drugs
High intersects
1021△McWilliams Patricia J
Hahn Henry H
1023△Brock Loren E coal
1027△Snyder Cecil T
1029 Blank Cath Mrs
△Richards Julia Mrs
1031△Garnett Jas
△Murray Ella Mrs
1033△Gibbs John
△Markley Edwin C trucking
1035△Taylor Thos
△Morgan J Jas
1039 Sonier Lewis E
△Manno Calogero
1041△Lotempio Anthony
Lotempio John A
Goodrich ends
1043△Vallone Jos
1044 Mehrtens Fred W
1045△Manno Lawrence real est
△Brown John J
Sugrist Wm
1046△Mehrtens Fred W whol toilet preparations
Mitterer Alois barber
1048△Larke Elfriede K Mrs
1049△Munro Irving F
Munro Ethel Mrs
1052△Farnham John P & Co x-ray equip
△Farnham Eben T lwyr
1053△Crosier Geo G
1054△Wood Geo W
△Holfelder Jeanette
1056△Green Albert jr
△Hoellig Earl A
Reen John
1057△Schlessel Edw
△Heckler Geo
1059△Ries Jos W
Gross Fredk
1060△Horn Robt J
△Russell Elaine E
1061△Waite Neal M
1062△Weaver Nora Mrs
1064△Malloy Theresa M Mrs
△Sercu John A
1065 Trautman Gertrude Mrs
1066△Swift Bldrs Inc genl contrs
1069△Flanders Wm L
1071△Johnson Henry
△Dukesbury Sarah E Mrs
North intersects
1080△Curley Top Beauty Salon
1082△Speedway Auto Service
1086△Swartz Jos S
△Gabriel Ernest J
△Hughes Ruth M
1089△Klauk John
1091△Mason Claremont B
△Baumler Frank
1092 Nachtrieb Edw W
1095△Quigley Frank J
△Miller Lillian Mrs
1096 Holslag Frank
△Heximer Oliver W
1098 Ozolins Antons
Sivba Juris
1099△Visiting Nursing Assn (br)
△Ryan Jas W
△Swanz Kath
1100△Ukins Wladyslaw
1102△Strasser Henry
Haskell John C
1103△Rieger Peter C
1104△DeBon Henry T
△Alexander Andrew C
1105△LaCrout Arth B
1106△Hartwanger Geo
△Williams Clayton
△Caplick Jos L
rear Boyd Anna A Mrs
1107△Stocker Wm S
△O'Brien John J
△Hoffere Chas E
1111△Orth Pauline A Mrs Ironmonger Louise Mrs
1112 Pohle John C
△Pohle John D
△Sykes John R
1113 No return
1114△Bingeman Geo A
Horn Louis F
rear△Casper Mary L Mrs
1115△Meissner Walter H
1116△Winzenried Louise C
1117△Foster Jack
△Nellson John
1119 Sikora Frank
146
Best intersects
1137 Prem Albert F
1141 DeWyer Melvin T
1144 Roberts & Rice Co auto reprs
1145△Haskins Peter P
1148△Tutton Chas H auto repr
1149△Fitzgerald John J
1151 Haehn Frank W
1152△Frontier Oil Service gas sta
1155△Brennan Michl
O'Keefe Mary
1157△Todd Wilford
Edna pl intersects
1163△Blaine Augustus gro
1166△Sullivan John A
1167△Clayton Florence L
McNeil Jas
1170△Sacca Stefano
Iapichino Jos
1171 Peabody Raymond
△Greggo John T
rear△Parkes Henry L
Bowman Gilbert
1172 Sweeney Jos F
Durkee Leonard
△Aiken Robt C
1173△Berleant Bernard B real est
Hawkins Lawrence J
Cavanaugh Margt Mrs
1174 Vacant
1175△Keener Olin jr
△Prince Jas
1176△Smith Coe
△Bell Eliz
1177 Lewis Helen Mrs
△Lewis Helen I
rear Sullivan Ralph
1178△Knittel Emil A barber
1183△Anderson John
1184△Imperial Refrigeration Sales & Service
△Kehe Marguerite
△Tolan Richd
1187 No return
1188△Ruppert Peter C
1189△Tabone Michl J gro
Dodge intersects
1199△Town & Country Cleaners
Koch Mary M Mrs
1200△Carpenter Jas M
△Newman Herbert J
△Beck Geo beauty salon
Jones Earl W
△Kuhnke Louise B Mrs
1201△Marella Louis
1202△Laskowski Walter J delicatessen
1203△Eaton Elvina Mrs
△McEneny Rose A
1206 Harper Edith Mrs
△Baker Dogald
1207△Fi
△Fr
1208△Ho
1209△He
1210△Fr
Ha
1212△Mc
1213△Mu
Wy
1214 Em
△Fi
Ba
1215△La
1217△Pa
1218△Be
△Tu
1219-21
1220△Ge
△Ta
1233△Ev
△La
1236△Al
△Br
1237△Sy
△Sy
1238△W
1239△Zi
1241△Jo
△Br
1242△Du
1243 Sc
So
1244△Sc
△Va
Va
△Ri
1245△Le
Co
△Ta
Le
1248△M
1249 Pr
He
1250△Sc
1252△Le
Ke
1253 M
Sa
△Cl
1257△Ri
1260△Le
1261△G
Ki
Bu
△M
△Ri
1262 St
1263△S
K
1265△V
△L
Li
△T
1266 T
M
△S
△T
1267△W
1268 H
1269 M
△S
1270△B
△P
1272△D
1273△H
△K
△K
1274△H
1275△H
△R
1276 C
1279△S
△S
Sc
1280△W
△G
1281△D
Jo
1284△Z
1285 V
1288 S
A
1292△E
1296△C
M
1297△M
△E
1298△M
△E
1301△E
1302△E
F
1303△C
△E
1303½
1304△
1305△
1308△E
△E
△E
1309△C
△S
1311 E
1312 S
rear△E
1314 I
1315△



North Court Apts—Contd
C6△Hutchinson Mae Mrs
C7△Hauser Angelina M
C8△Daly Sarah
C9△Goodrich Gertrude
C10 No return
C11△Donato Cath M
D1 Miller Agnes M
D2 Cassata V B
D3△Ulmer Betty Jane
D4△Kleinschmidt Anna C
D5△Gick Wm A
D6△Hailey Martin
D7 Vacant
D8△Burkhardt Margt M
D9△Verstraaten Mary E
D10 Perkins S M
D11△Kaplin Alice J
Street continued
198△Cline Clinton S
208△Abt Clara A Mrs
220 First Church of Christ Scientist
221△Radder Chas S
Elmwood av intersects
226-30 **North Apartments**
△Nicks Walter E supt
△Clifton Sarah D
△Holt Isabel K
Breen M Frances
Davis Eliz Mrs
Colwell Alex H jr
Crawford M Eloise
Gonye Ladislaus
Howrene A Maurine
△Severns Emma
△Grove Raymond E
O'Brien Harriett Mrs nurse
Barth Marie J
Jarvis David M
△Knapp Josephine M
Kyle Willia Mrs
Massoth Leona E
Norton Gilbertine C Mrs
Smith Leah F Mrs
Cursons Stewart L
△O'Hern Mildred K Mrs
△Scully Jas N
△Sparfield Elsa L
△Yock Nell B nurse
Walsh John A
Mahoney Florence
Beckley Jane
△Thompson Mary E Mrs
△Wood Jean Mrs
△Goidstein Lena C Mrs
233△Holland-Wegman Productions
234△Ransom Realty Co
237△Diocese of Western NY Episcopal Church Mission of Help (Social Dept)
△Richardson John R Rev
Mariner ends
245△YWCA (residence)
252△Rokita Anna Mrs
△Reinecke Ottomar W
△Burrows Helen Mrs
△Cohen Rebecca
△Morey David W
256△O'Brian Roland L
△Mesner Norma S Mrs
Jones Ruth N Mrs
College ends
267△Stewart Woodford T Estate of
rear△Lorenz Otto
268 **Apartments**
1 No return
2△Fenno Laura M Mrs
3 Robison Florence E
4△Flaherty Julia M
5△Huff Ann M
6△Wilson Ruth
7△Doerr Hazel C Mrs
8△DeWitt June M
274△Will Lillie C Mrs
CSP
279△Corcoran Mary G nurse
282△**North Gables Apts**
△MacLeod Duncan
290 **Two-Ninety North Apts**
11△Mullen Florence R
12 Ryan Fredk G
13△Moore Rudolph J
14△Miller Mary A
21△Smering Janey R Mrs
22△Nelson Cornelius J
23 Kamm Victor F
24△Cushman Gertrude M Mrs
31△Mielcarek Adam J
32△Reilly Margt Mrs
33△Anthony Margt M Mrs
34△Alford Helena B
41△Hunseke Eliz Mrs
42△Rolland Walter phys
43△Eustace Ella M Mrs
44△Josett Lorraine J Mrs
291△Grancisian Sisters of the Immaculate Conception Nazareth Home for Convalescents
292△Olive Matilda Mrs
Swetland Kath nurse
Arlington pl ends
303△Casa Misericordia Convent
304△Smith Gertrude R Mrs
309△Cerebral Palsy Association of Western New York Co-operative Pre-School Center
310△Coplon Rosa Jewish Old Folks Home
The Circle intersects
140
NORTH E—From 1039 Main east to Herman av (not open between Jefferson av and Timon)
3 King Parker C
5 Zimmermann Alvin Schadenfroh Geo J
7 Griffin Eva E
9 Smith Frank

NORTH E—Contd
11△Uebelhoer Kathryn Kilgore Grace
13 Thiel Raymond Keller Henry K
14 Frank & Teresa's Anchor Bar (parking lot)
23△Poling Wilson pntr
△Sturm Francis W
25△Wendel Nathalie L
26△Buffalo Surplus Co hdw
27△Wittholz Otto C plmb
30△Jempson Machine Shop
△Cellophane Bag Co
31 Banks M Irene Mrs
33 Vacant
rear△Brown Max
35△Conrad Edgar C
36 Smith Arlene M Mrs
△Chase Carol B Mrs
37 No return
39△Conn Geo
41-43 **Apartments**
1△Herald Alex
2△Gabel Herbert N
3 Walker Viola A
4△Beswick Florence L
52-54△Pepsi-Cola Buffalo Bottling Corp
Ellicott intersects
61△Carnevale Anthony J gro
63△Mueller Harold J
△Holm John
68△Cullinan Edw G
△Guenther Dorothy
69△Biersbach Louise Mrs Dudley Kenneth J
70△Garvey Cyril P
rear Hornung Roy
71△Danforth Willard J chiropractor
△Bornheimer Alf
72△Kemp Francis J Newman Peter V
75 Armstrong Wm C Bohn John H
△Schlifke Conrad A
76△Noel Hedwick Mrs Owens Earl
77△Cook E A Body Co auto body mfrs
80△Restivo Mathew
△Jones Levi
82△Bixen Robt S
△DeToy Eugenia D Mrs
83△Vella Angilla Mrs
△D'Amico Martin
rear△Pribula John S
84△Erskine Robt H
△Dexter Harry
86△Garvey P J Carting & Storage Inc
△Frier Edwin A
87 Hontz Lillian
△Burton Irene E Mrs
rear△Emerick Eug F
89△Mattina Angelo
△Wood John
90 Beardsley Chas M
93△Katz Hyman
Evon John R
94△Glair Wm J
△Snyder Frank B
96△Kennedy Helen B Mrs
Welmont pl begins
99△Wolf John E delicatessen
Dzielski Stanley
101△Salamon Frank tailor
Troutman Chas W
105△Hughes Oliver H
△Hayhurst Vernon H
108 Winch Raymond A
109△Campanella Chas J
110 Kallos Gustav variety store
Poppenberg Cecelia
Yerke Frank
△Bailey Gordon R
Breer Lois I Mrs
111△Dolan Mary C
rear Loesch Anna Mrs
112△Bateman Harry C
114△Berger Mary D
△Lyon Claud L
rear Signer Dennis P
115△Lindeman Fred H
116 Hirschberger Louis Dolan Kath
117△Johnston Isabelle A Mrs
118△Taylor Lloyd Weigand Louise Mrs
119△Fredericks Christine W Mrs
△Otto Wm E
120△Koniarczyk Walter
124 Fleming Geo
△Proehl Erwin C
rear△Proehl Robt E
126△LaBarge Marian M
△Moran Robt
△MacDonald Maud E Mrs
128△Britton Edgar C
△Sweeney John J
132△Miller Carl delicatessen
136
Elm intersects
135△Simon Geo W
137△Noon Mary M
△LaHood Gabriel
rear△Noon Isaac
140△Schaefer Henry
141△Noon Chas C
Noon Anthony
142 Grafley John W
145△Gianiodis Michl
△Boubaris Nicholas
146 Clairmont Cath Mrs
148△Haas Margt Mrs
149△Erhardt Lillian L Mrs
△Cryan Michl J
150△Sawday Albert
152△Burkhardt Ida B Mrs
△Burkhardt Howard M
153△Rohs Mary
Karnitz Albert G
156△Golden Nora F
157△Lauer Amelia Mrs nurse

1955 NORTH ST E-A

SOURCE: POLKS

1955 NORTH ST E-B

SOURCE: POLKS



NORTH E—Contd
158 Hannon Alice
Herbolsheimer Rudolf
160 Sonnenberger Andrew L
164 Schaefer Norbert B phys
Michigan av intersects
172 Duch Stanley restr
177 Cook Robt J
178 Vogelsang Cath B drsmkr
179 Thuerck Edw
Maple ends
180 Menzele Gunther L
Kostka Seyfried
182 Maul Hulda P
Sculischezsky Paul
197 Gibbons Alvah
Grundner Melvin J
199 Kamman Donald
Banks Robt
205 Culp Lee L
Davis Arth E
207 Neuner Edw F
209 Wistner Ernest E
213 Bryant Louise Mrs
215 Ries Dorothy delicatessen
Saint Jos H
Wainwright Martha Mrs
Mulberry ends
223 Willard Hugh
Cain Lucy B
Lopez Gonzalo
Selzler Blanche J
225 Bishop Edw J
Lignos Gust
227 Stoll Albert A
229 Ulrich Johanna Mrs
Hall Lillian Mrs
rear DiPasquale Chas
nw cor Fosdick-Masten Park High Sch
ns Masten Park
237 Masten Park Baptist Church
134
Locust ends
Masten av begins
249 Toellner Elmer W ice and fuel
253 Cryan Wm
Penz Ernest
257 Bromley Clinton T
Edgley Wm
261 Schultz Morris
Grass Edw M
Grass Curt E
263 Koch Mary M
Staebell Emily H
265 Anthony Gertrude Mrs
Webb Dana J
Zamojski Walter J
Lemon ends
275 Altenoeder Anthony S
Volkert Gertrude Mrs
277 Dentinger Philip J jr
283 Wollenberg John
285 Dietsch Mary Mrs
287 Charrette Frank V
291 Diefenbach Wm C
Hetzendorfer Paul F
Orange ends
301 Kilmer Walter J
307 Kinneman Dora Mrs
Taylor Emma Mrs
rear Gibson Bertha D Mrs
309 Wilke Anna A Mrs
314 Roetzer Jos M
316 Young Vincent
Kane Steph
320 Vacant store
322 Hoffman Jennie Mrs
VanBuskirk Gertrude
Tropaquara tropical fish
Hovey Chas R
Peach intersects
330 Scibetta Jas J delicatessen
Apartments
1 Clark Wm
2 Latona Leonard
3 Manguso Jas H
332 Scibetta Carrie Mrs
333 Collier Sherman B
336 Foster Orville
338 Hamilton Barrett E
341 Advance Telev Laby
342 Tschampel Richd R
Rink Paul J
343 Anthony's Delicatessen
Anthony Wm
346 Russ Jos
Stuff Howard
348 Gross Magdaline M
Wolf Edw A
350 Mirabelli Frank
Grape intersects
353 Diehl Oscar W
355 Clark Asa G
356 Vario Dominic
358 Zamojski Jacob R
359 Featherstone Ronald A
Cribar Frank S
360 Sturges John J
361 Dirnberger Cath M
Human Clara
Meiser Nina A Mrs
362 Endres Henry C
363 North St Gospel Tabernacle
Rose ends
368 Kreinbring Chas
Oehler Geo F
Riebeth Vola L
370 Batterson Ethel M Mrs
Smith Gilbert F
372 Todd Roy E
383 Eckert John J
Bozze Martha

128
Jefferson av intersects (Not open between Jefferson av and Timon)
Timon intersects
505 Staber Carl G
Engelhardt Edw
rear Price Lorraine Mrs
507 Hale Warren
rear Row Louis
509 Schwartz Jos A
Weiss Rose Mrs nurse
511 Fuchs Walburga Mrs
Fuchs Jos
513 Neurohr Jos G
Steinkirchner Louis A
515 Emerson Ira
Green Marie J
517 Vacant
126
Johnson intersects
542 Koerber Jas C
Schlager Louis meats
Yates Frank
543 Schlia Kath A Mrs
Deieri Marie S Mrs delicatessen
545 Snyder Victor C
Potteiger Harry
546 Schmidt Geo J
rear Iwachiaw Michl
547 Bader Robt H
O'Conner Nicholas
rear Tobin Florence Mrs
548 Raab John
Vohwinkel Walter
549 Huber Helen
Gruber John
550 Diederich Carl J
551 Redenbach Johanna Mrs
Redenbach Lester
Deth Donald N
552 Maier Jos T
Wright Harley
Maher Wm C
Maher Jos J
553 Buss Robt
Koeth John
554 Schoen Geo W
Danner Otto
555 Leisner Ernest J
Rehel Theresa Mrs
556 Lane Rudolph S
557 Tschaepe Frank R
Kramer Fred jr
558 Hattenberger Aloysius J
559 Aman Edw J
Halland John M
560 Schmand Fred
567 Abrams Grant
Nagel Henry S
Sherman intersects
576 Schiesl Martin C
577 Welker Forest
578 Meyer Clara Mrs
Murschel Harry G
580 Christian Everett
Resetarits Rudolph
rear Brunner Robt
581 Norris Hugh F
Meyer Jos G
rear Bidell Richd C
Erhardt Richd
583 Habicht Emil
584 Baumgartner Edw J
585 Maisel Julia Mrs
586 Vogt Geo
587 Wetter Charlotte C
588 Rink Henry
Ludwig Anna Mrs
589 Strobl Geo A
Hall Donald A
590 Haas Alf R
591 Schlenker Harold H
Pellnat Robt
593 Wetter Harry J
Dirschedl Karl J
596 Wylie Ray J
Zlaikowski Alf C
Benzel Anna Mrs
Klein Norman
600 Herbart Hugo P restr
601 Pawlak Henry J delicatessen
Pawlak Michl
rear Hale Thos
Fox intersects
606 Rimas Roble
Urbaniak Wm
Husner Emma S Mrs
VanDusen Raymond T furnace repr
607 Herbart Hugo P
608 Stengel Edw I
Goodrich Reginald S
611 Kopp Pauline Mrs
Smithmeyer Louis J
614 Esposito Ignatius H
Nowak Benedict J
rear Laufer Jos W
Esposito Jos
615 Salamone Jas V
616 Begin Donald N
Strom Allan
617 Steinhart Dora Mrs
Bevilacqua John
rear Lang Susan Mrs
618 Fifagrowicz Geo
Czaikowski John J
619 Wohlert Arth B
620 Buss Margt
621 Kamionska Tony
Donovan Jas N jr
628 Ball Alf W
630 Springholtz Barbara D
Elmer Frieda Mrs

634 Se
Ki
Pe
Sa
NORTH
333 M
8
9
10 Ch
11 Bi
12 Va
15 Ol
16 Ge
17 Va
20-22
29
35-37
41
45
1st fl
2d fl
3d fl
4th fl
5th fl
6th fl
58
60
62
64
66
69-1
72
73
74
75
81-8
102
104-1
110-1
124
136
141
142
143
153
168
169
170
172
173
286-9
287
289
291
293
294
296
297
298
299

1950 BEST ST-A

SOURCE: POLKS



180
BERWYN AV — From 384 Olympic av east to Bailey av
11 Archer Wm
14 Lord Willis T jr ice
15 Gosney Arth R
16 Winans Stanley
19 Lambour Chas X
20 Kraft Herbert
21 Ess Clara Mrs
22 Repman Earl L
25 Handley Victor C
26 Gassman Leo P
29 Hagg Thos A
30 Dickinson Wm F
31 Evers Wm V
32 Joyce Douglas
35 Miller Edw G
36 Hauk Vitus G
38 Wlodarczak Frank J
39 Meinke Carl
41 Kumpf Lewis G
42 Hannon John J
45 Cothard Harry W
46 Coveney John S
47 Thompson Harrison
50 Pauley Glenn G
51 Foley Eug F
Maefs Clifford A
52 Ulrich Eliza Mrs
Beaty Lawrence
53 O'Brian Jos V
54 Kinmartin Madeline Mrs
57 Rachow John H
Jaeger Richd W
58 Lee Howard L
Conklin Fredk W
Conklin Marion E Mrs drsmkr
61 Hise Alf G
62 Grimm Walter A
63 Stephen Fredk F
64 Robert Leroy H
67 Schlau Peter N
68 Herman Albert
69 Bellgard Anna W Mrs
Weber Edw H
72 Zimmerman John
73 Bowen Herbert R
Scanlon Mary C Mrs
74 Weiss Orville F
77 Rambuss Fred H
78 O'Neil Florence Mrs
79 Heller Fredk
80 Matt Wm J
83 Zeller Walter W
84 Schieder Wm E elec motor repr
85 Scully Wm C
D'Addario Paul
88 Jones Alton A
89 Walter Jos G
90 Sparks Jos W
93 Muther Frances E Mrs Hafner Edw
94 Drescher Casper J plmbr
95 Cook Gilbert G
96 Drescher Edwin H
99 Case Geo
Elyea Albert
100 McElroy Clara A Mrs
101 Klein Cyril A
102 Demerly Benj trucking
105 Folmer Andrew J
106 Snyder Jack
109 Ruber Fred W
110 Glass Margt E Mrs
Bailey av intersects
6
BESSEMER—From 281 Chicago east 1 block
(No houses)
146
BEST—From 1119 Main east to Genesee
4-16 Best Apts
bsmt Haun Frank
1 Jackus A M
2 Nawrocki Della
3 Shaffer Theresa A
4 Sahner Wm
5 Kaeppel Martin
11 Holtz Walter
12 Stanton Dorothy E
14 Rinkle Clyde
15 Gravish Ruby A
18 McElwee Vincent H
20 Hoen Alice
21 Politis Geo
22 Schaub Francis A
23 Birtch Harry
24 Kape Jack
25 Scott John N
26 Dunn Jas
27 No return
28 Connally Mary M
29 Fredin Herman
30 Bakos Emanuel
31 Kersburg Benj
32 Doerr Stella
33 No return
34 Dunn Robt
35 Nash Harry N
36 Knapp Margt A
37 Valler Phyllis M
38 Gamrath Lillian A
39 Sahner Florence
Street continued
22 Weiderman Genevieve Mrs
22 Harris John G
25 Barry Raymond
Woodward Thos S
Ritter John M
Hoppe Edw
Elmer Edw J
26 LoCascio Vincent
29 Flier Paul R
Shamp Bertha Mrs
30 O'Connell Jas T
31 Powell Percy G
32 Armstrong Matthew
Hearn Wm C
rear Flumelfeld Ivan H pntr
Zielinski John
33 Seereiter Louise A
Reilly Paul F
35 Miller Julius B pntr
Joyce Patk
36 Gorman Warren
Ross Martha S Mrs
38 Wright Edwin H
Allen Clarence T
41 Logel Edw W
44 Beresford John
44½ Clarke Dora F Mrs
45 Niagara-Hudson Power Co (sub sta)
46 DuQuin Arnold J
50 Drakes Hedley V
Drakes Jos H
rear Duquin Wm G
52 Anthony Anthony F
53 Brennan Anna Mrs restr
56 Salamy Geo T delicatessen
Ellicott intersects
65 Liptak Dorothy Mrs restr
67 Stevens Sarah E Mrs
68 Marz Carl W
69 McKay Kenneth H
70 Weeast Louis
Kraft Lily Mrs
71 Deuter Mary E
Harrison Herbert
72 Riley Frank
73 Meiser Raymond A
Schmidt Edw J
74 MacAndrus Martin
Richardson Harry M
75 Stesiak Chester
76 Goodman Chester F
79 Clucas Geo D Inc plmbr
Baumgarten Mary Mrs
Welmont pl ends
80 Steller's Bakery Inc
Steller Anna Mrs
86 Chesney Stella
Martha Rudolph
88 Beckett David
Bowers Wm
90 Winter Henry G
James Donald
93 Beckerle Jos A tailor
94 Scheffler Henry H
Johnson Fred A
95 Winter Anna B
96 Dreissen Josephine D
Towlson Bertram
97 Collett Harold E
Schmidt Edw W
98 Martin Saml
Jenson Emily C Mrs
102 Dickey Jas W Crocker Lewis S
103 Beach Ellsworth A
Wagner Anna S Mrs
104 Downey Kath T Mrs Roemer Alf F
rear Trapp Jos
105 Schmidt Millie Mrs Schroeder John J
rear Fitzgerald Gerald J
108 Schwarz Harry G
Borsberry Lee
111 Shuller Richd P
112 Pokolm Kurt J
113 Pogrant Julius A
Steck Louise C Mrs
115 Barone Salvatore
Shaver Lee
116 Peard Anna G Mrs
117 Green Geo
Clare Alf J
Clare Henry P
118 Fee Lawrence
120 Warner Ida F Mrs
Elm ends
122 Ahlheim Saml G
122 Russell Theo
125 Lowe Ray D gro
126 Coppola Dominic
Pritchard Walter W
127 LaBart Fredk R Snell Raymond
rear DeBon John J
129 Grady Maude E
130 Morlock Albert L pntr
131 Ford Wm H
133 Pfeffer Theo H
Lafferty Richd
rear Evert Erwin F
134 Pettway Wm H
Weiss John P
rear Wesley Floyd J
135 Richardson Walter P
136 Gueth Marian O
138 Arida Raymond K
Yunke Aug W gro
rear Folga Vincent
139 No return
rear No return
141 Book Fred S
145 Blatner Norman gas sta
150 Schuesler Jas S filling sta
Michigan av intersects
159 Danahy-Faxon Stores Inc (br) gros
Sukora Frank
Snyder Gerald E
160 Lamm Restr
161 Hogg Gerald W liquors
162 Grimm Evelyn variety store
Grimm John
163 McBride Alex
Prouty Mortimer C
King Minnie
rear Prouty Mortimer J
164 Barnes Marie Mrs

1950 BEST ST-B

SOURCE: POLKS

31 Powell Percy G
32 Armstrong Matthew
Hearn Wm C
rear Flumelfeld Ivan H pntr
Zielinski John
33 Seereiter Louise A
Reilly Paul F
35 Miller Julius B pntr
Joyce Patk
36 Gorman Warren
Ross Martha S Mrs
38 Wright Edwin H
Allen Clarence T
41 Logel Edw W
44 Beresford John
44½ Clarke Dora F Mrs
45 Niagara-Hudson Power Co (sub sta)
46 DuQuin Arnold J
50 Drakes Hedley V
Drakes Jos H
rear Duquin Wm G
52 Anthony Anthony F
53 Brennan Anna Mrs restr
56 Salamy Geo T delicatessen

Ellicott intersects

65 Liptak Dorothy Mrs restr
67 Stevens Sarah E Mrs
68 Marz Carl W
69 McKay Kenneth H
70 Weeast Louis Kraft Lily Mrs
71 Deuter Mary E
Harrison Herbert
72 Riley Frank
73 Meiser Raymond A
Schmidt Edw J
74 MacAndrus Martin
Richardson Harry M
75 Stesiak Chester
76 Goodman Chester F
79 Clucas Geo D Inc plmbr
Baumgarten Mary Mrs

Welmont pl ends

80 Steller's Bakery Inc
Steller Anna Mrs
86 Chesney Stella
Martha Rudolph
88 Beckett David
Bowers Wm
90 Winter Henry G
James Donald
93 Beckerle Jos A tailor
94 Scheffler Henry H
Johnson Fred A
95 Winter Anna B
96 Dreissen Josephine D
Towlson Bertram
97 Collett Harold E
Schmidt Edw W
98 Martin Saml
Jenson Emily C Mrs
102 Dickey Jas W Crocker Lewis S
103 Beach Ellsworth A
Wagner Anna S Mrs
104 Downey Kath T Mrs Roemer Alf F
rear Trapp Jos
105 Schmidt Millie Mrs Schroeder John J
rear Fitzgerald Gerald J
108 Schwarz Harry G
Borsberry Lee
111 Shuller Richd P
112 Pokolm Kurt J
113 Pogrant Julius A
Steck Louise C Mrs
115 Barone Salvatore
Shaver Lee
116 Peard Anna G Mrs
117 Green Geo
Clare Alf J
Clare Henry P
118 Fee Lawrence
120 Warner Ida F Mrs

Elm ends

122 Ahlheim Saml G
122 Russell Theo
125 Lowe Ray D gro
126 Coppola Dominic
Pritchard Walter W
127 LaBart Fredk R Snell Raymond
rear DeBon John J
129 Grady Maude E
130 Morlock Albert L pntr
131 Ford Wm H
133 Pfeffer Theo H Lafferty Richd
rear Evert Erwin F
134 Pettway Wm H
Weiss John P
rear Wesley Floyd J
135 Richardson Walter P
136 Gueth Marian O
138 Arida Raymond K
Yunke Aug W gro
rear Folga Vincent
139 No return
rear No return
141 Book Fred S
145 Blatner Norman gas sta
150 Schuesler Jas S filling sta

Michigan av intersects

159 Danahy-Faxon Stores Inc (br) gros Sukora Frank
Snyder Gerald E
160 Lamm Restr
161 Hogg Gerald W liquors
162 Grimm Evelyn variety store
Grimm John
163 McBride Alex Prouty Mortimer C
King Minnie
rear Prouty Mortimer J
164 Barnes Marie Mrs

165 Comtois Lucien
166 Kordas John P
rear Hill Harry M
Greenberg Herman
167 Vetter Cath L Deisser Wm G
168 Reger Aubrey L
174 Thur Geo W paperhngr
176 Mumm Caroline A Mrs
178 Beck Henry J
184 Wetter Emma W
186 Vacanti Vincent J
190 Smith Leslie E
192 Frank Lydia Mrs Frank Richd I
196 Hughes Ruth M Gehl Steph
200 Schmidt Wm
202 Sarikas Theo
Nicolaides Paul
206 Hogg Phillip
Chatley John
208 Koeppel Edwin W LaPatia Lewis E
210 Blake Howard C
212 Evans J Donald
Baldwin Chas V
216 Carl Oscar A
Zimmerman Richd A
218 Adbender Gladys A
222 Ott Arth

132

Masten av intersects

311 Staub Arth C
315 Widelski Leo
321 Green John R Stemen Mary M Mrs
Blake Edw
323 Rosar Wm McCarty John J

Peach ends

329 Manning Thos J
Agnello Silvio B
331 Catalfamo Frank J Catalfamo Carmen F
337 Walter Cora C Mrs
339 Klemenz Louise Mrs Klemenz Eug
341 Handel Fred A
345 Fabiano Saml
347 Lageman Bertha S Mrs Thomson Thos C Palmisano Peter

Grape ends

357 Andrus Stanley
Gillies Margt
359 Small Clara E
Schler Anna E
rear Mooney Norman E
361 Palmisano John
363 McGurty Cath Mrs
Vetter Chas
Ellsworth Frank M
rear Scheffler Fredk W
369 Espow Isadore A Werner Fred H Kaufman Alton J
Wagner Frank
rear Clark Francis
nw cor Buffalo Civic Stadium

128

Jefferson av intersects

399 Frieh Louis W auto glass
400 Hyan Dry Beverages
Langs Bakery Inc
Langs Creamery Inc
401 Gold Arth M
Momjian Saml
403 Storms Nelson R
Morehouse Ella M Mrs
407 Cooper Mildred B
Sullivan Thos C
409 Olsen Sophus
411 Siffling Theo J
Winzenried Albert J Youngman Milton H
413 Opel John confr

Earl pl ends

419 Georgian Beauty Salon
Chamberlain Phyllis H Dash Francis H
421 Engine Co 21 BFD
423 Hook and Ladder Co No 6 BFD
427 Hochhauser Julius M Altman Aug M
Hochhauser Fred
Rasch Clara E
429 Lina Theo C
433 Lina Rose Mrs
Koch Ella E
435 Moest Howard O R
rear Reger's Monarch Auto Glass Shop Reger John B
439 Buffalo Niagara Electric Corp (sub sta)
445 Maecker Louis C

Pershing av intersects (ns not open)

453 Carver Clifford
Rath Edw restr
457 Adamczak Chester A chiropractor
458 MacDonald Holford
Klein Frank
458½ Kennedy David J
460 Keller Fredk jr
Nussbaum Norman J
461 Buchbinder Alois B
464 Fries Earl G
Fries Florence L Mrs
465 Hug Frank J jr delicatessen
Prem Clarence
466 Andrzewski Frank Cierlicki Stanley S
469 Schwander Willert
Vogelsang Edw funeral dir

BEST-

1950 ELLICOTT ST

SOURCE: POLKS

824 Murphy Geo Hynes Sarah
826 Miller Jos P
830 Ellis Thos Burke John J
831 Stevens Jas
Angus Harold J
834 Curry Grace Mrs Eckam Russell
835 Hayn Geo M
836 Snyder Cath L
Schweitzer Chas
Vastola Jos Hirsch Vincent R
839-43 Buffalo Genl Hosp (dormitory)
840 Farley Leo
Matzak Martha Mrs
842 Laney Edw Whitfield Jas
843 Denny Lillian J Mrs
845 Liebau Harry C

Goodrich intersects

854 Cook Briant F
Meno Frank G
Haberl Mildred M
860 Baecher Chas K
863 Finch Albert M
Tuschl Jennie
864 McGee John R jr
Wallasch Clara L
866 Nix Anna M Mrs Hill Jas R
867 Yochum Margt L Pearl Viola
870 Yahle Fred U
Hooker Morris
871 Bamberg Danl
Wampach Anthony J
rear Killian Eliz M Mrs
Reisch Caroline A Mrs
872 Smith Mary A Reichlin Chas J Hurley Wm J
876 Hagen Jack barber
rear Green Thos J
878 Shelton Walter W
Becker Fredk C restr

E North intersects

886 Guldner John H
Sees Albert J
890 Atwood Kenneth
Early Kath
892 Schilling Chas J
894 Schingeck Wm H
898 Kohlbrenner Anthony J
Barden John J
900 Klass Herbert F
903 Fisher Ida Mrs
Asselin Chas L
905 O'Connor Gregory
908 North Ellicott Service Garage
909 Krombein Walter H
913 Fuss Flora F Mrs

StPaul intersects

931-35 Pepsi Cola Bottling Corp (garage)
938 Kevra Frank atuo repr

146

Best intersects

961 Simplex Motor Parts auto accessories
967 Nebrich & Co auto reprs
969 Schultz John J
Biggie Henry H
Merkel Ernest F
970 Apfel Walter H clo clnr
rear Adamczak Henry J
971 Sturm John C
Pratt Wm J
972 Charrett Frank V
rear Crean Martin F jr
973 Roper Abram A Davis Susan Mrs
976 Barone Gasper
977 Kingman Warren E
978 Katoll Marie L florist
979 Koch Francis P
rear Steep Norman F

Edna pl begins

980-86 Engineers Specialties (Div of Universal Engraving & Color Plate Co Inc)
Empire State Metal Sch
988 Tradition Sigmund Pochron mfrs
990 Seames Margt Mrs
991 Clark Fredk A
Brown Genevieve M Mrs
Sillaway Chas H
993 Kreller Edw H
Evans Chas W
Ingersoll Sterling
994 Richter John Barlette Thos Askey Leland E Bartlemus Grace Mrs
996 Nicholson Wm Bruce Robt
Anderson Theo E
997 Amann Raymond T
998 Potter Jules H
rear Valentine Mary E Mrs
1000 **Apartments**
1 Fisher Anne
2 Crean Margt M
3 Costello Margt A

Street continued

1001 Paul Minnie Mrs Paul Barbara Mrs
1002 **Apartments**
1 Lee Roland F
2 Bartlett Grace
3 Vastola Anthony
4 Juliano Jos J
5 Agne Louis M
6 Evans Anna S Mrs

Apartments—Contd
7 Fritz Peter
8 Grillo Frank

Street continued

1006 LoCascio Vincent barber
1007 Calvary Evan Lutheran Church

Dodge intersects

1031 Novitzki Wm
Lewis Harold J
1032 Hettrich Electric Service auto reprs
1033 Aaron Jack E
1034 McDonald Ann Mrs
1035 O'brien Jos J
1036 Garvey Geo E
Reiss Frank H
1037 Black Robt
1040 Schubert Clement P
1041 Rick Edw A
1042 Schubert Rose Mrs
1044 Weber Elmer W

Coe pl ends

1045 Bishop Frank H
1047 Cecchini Lena Mrs Martin Wm

Southampton begins

1050 Wallace Albert
1054 Boore Ada Mrs
1056 Smith Wm
1059 Wilson Wm A
McGranahan John B
1060 Boore Chas H
1061 Gross John
1062 Smith Wm H
1063 Bugman Dorothy M
1066 Lannen Eug J
1067 Jones Earl Weber Kenneth
Stevenson Viola Mrs
1069 Nichols Elmer C
1070 Mauerman Robt E
1072 Running Richd E
Scott Lucille Mrs
1075 Rothschild Helen

Northampton intersects

1094 Good Clyde E chiropractor
Haier Geo H
1097 Griswold Helen
Forbes Clara Cook Leighton
1098 Grimm Rose Mrs
1101 Huntley Clinton
Guenther Harry V Hassett Dennis J Knell Roxey
rear Ebnet John pntr
1102 Bartlett Grace Mrs
1105 Allen Kenneth J
1106 Anderson Merle
1109 Reimondo Sylvia M Mrs
Reimondo Gerald A
1110 Jehle Grover A
1113 Cameron Geo S
Durshordive Albert
1117 Hondell Ila Mrs
1121 Goins Ellen M Mrs
1123 DesJardins Edwin E
1127 Bennett Wm
1131 LaMacchia Carl
Curran Josephine M Mrs Crean Hubert Henderson Thos
1135 Seitz Geo W phys
1137 Baumann Edwin J
1138 StVincent de Paul Female Orphan Asylum
1141 Schlieckenreider Minnie E
McIntyre Johanna Mrs
McCann Marie A Mrs

Riley intersects

2 B-7

ELM — From 124 Swan north to Best

11 Holt Robt A

Booth al intersects

15 Hoesel Jos B auto repr
17-21 **Gutman Building**
Bates-Jackson & Co engrs
Schwartz Jewelry Co mfg jwlrs

South Division intersects

38 Freire Emilio billiards
43 Dynamo & Motor Exchange Inc

2 B-9

North Division intersects

68-72 Bove Anthony fill sta

Akron al ends

2 B-12

Eagle intersects

94-96 Bergman Norge Co refrigerators
95-97 Jordan Supply Co Inc refrigerators
99 Rupert Nancy Snow Philip
rear Velasquez Cecario Hoak Lloyd
101 Worthington Pump & Machy Corp (whse)
102 Public School No 35
120 Fox & Fox Inc lithograph fnshrs
133 Gambacorta Jos P

Clinton intersects

141 Hager E M & Sons Co millwork
150 Aameen Karaamah Mrs
154 Araya Gustova

William intersects

161-71 Stewart Motor Corp whol parts

1950 GOODRICH ST

SOURCE: POLKS

1950 MICHIGAN AVE

SOURCE: POLKS



140

GOODRICH — From 1005 Main east to 1044 Michigan av

20-22 Veterans Administration
25△University of Buffalo School of Dentistry
26-28△Alemite Co of Buffalo Inc lubricant equip
27△Malzer Anna E Mrs
30△Brace-McGuire & Co (rear entrance)
33△Phelps Albert
△Leonard Edwin J
40△Baker John H
△Minklein Elmer N
Johnson Gladys
41△Squirt Beverage Co
43 Norris Frances A Mrs
drsmkr
44△Plastas Geo E
△Zitrin Israel
△Ryan Jas J
Taber Walter

Ellicott intersects

66 Rowley Robt K ◎
68△Smith Glenn
△Manfredini Anna Mrs ◎
rear Gross Fred
70△O'Neil Agnes F ◎
71△Henry Eunice L
72△Maxon Herbert B
△Hutchinson Haldon C
74△Kreutzer Rose P Mrs
rear Felle Alex
82△Wood John H ◎
△Tague John C
82½△Blum Robt
rear△Bean Cameron A
84△Peck Anna ◎
86△Walker Wm
△Murphy John
88△Roberts John E ◎
Doty Thos O
90△Hoops Caroline Mrs ◎
△Clerc Marie Mrs
92△Armstrong Bessie J Mrs ◎
100 Harrington Bldg (Div of Bflo General Hospital) (maternity)
112 Buffalo Genl Hosp Nurses' Home

136

Elm intersects

131 General Hosp (storage)
134 McKee Z Pearl Mrs
△Smith Kath J ◎
140 Frank Edw W
142△Fries Raymond H ◎
144 Vogl John W
148△Meyer Caroline A ◎
152 Valentine Richd H
rear△Bickelman Albert G
Hudson Clarence C
158 Stearns Jos W

Michigan av intersects

98

MICHIGAN AV—Contd

907△Sims Edmund ◎
908 Waldmann Nelson P
909△Scharlau W Clifford
Blakely Richd A
Murphy Thos P
Becker Geo M
912△Burau Louise Mrs
△Cropp Harvey L
rear Kenny Albert M
913 Smith Ralph J
Heusinger Ann K Mrs
Metz Cath O
914△Eberly Steven
△Hull Chas W
915△Smith Kath Mrs ◎
△Elsie Arth
917△Hirsch Harry H
△Schneider Walter J ◎
918△Zupa Angelo A
△Palmisano Bros concrete contrs
△Palmisano Saml J contr
rear Costello Jos A
Trinca Chas
920 Perna Rosalie Mrs ◎
△Perna Thos J
921△Scherer Wm ◎
△White Muriel R
Bourne Pearl M Mrs
922△Perna Jack J
924△Atkinson Russell
△Groner Ralph
925△Schaefer Alois H ◎
927 Schrembs Michl
Pursel Clayton B
928△Carlson Louis
930△Heiss Valentine jr
931 Rupprucht LaVerne
rear Numan Chas
933△Haefner Mary E Mrs ◎
934△Henry Jean E
936 Marsh Mina K Mrs
937△Fanaro Chas ◎
△Stone Rose
rear Polito Anthony L
939△Castiglia Pasquale
Pollino Jos ◎
rear Pollino Frank F ◎
940△Dello Chas tailor
Vogel Richd
942 Goldstone Barney restr
943△Rice Chas J ◎ antiques
Schieve Hubert

Carlton intersects

946△Harris Florence gro
△Scherer John V
948 Marasco Louis T clo clnr
948½ Kipps Anthony barber
950 Nurmi Henry
Kuhnhaeuser Reinhard
952△Cassube Teresa Mrs
△Saari Olga Mrs
rear Roininan Kaarlo
955-57△Batt Co Inc plmbrs
958△Ball Albert
Hammer Glenn
Kiouses Geo N
959△Romano Jos ◎
Mackey Jas R
960 Haueise Howard F
△Zimmerman Aug F
961 Holden Thos
△McKnight Herbert
962△Rehm Chas A ◎
965△Johnson Chas R
Whitman Arth J
966△Berry Jas ◎
Lucas Archie
967△Jeanette Victor ◎
968△Johnson Edw
Caito Rose M Mrs
972△Clark Edw D ◎
974 Mitterers Alois barber
△Boss Aug
975△Dimitri Mary K Mrs
Wood Wm D
rear Cummings Eva Mrs
977 Pfohman Jacob P
△Pfohman Jos J ◎
978 Harter David
△Davey Geo E ◎
979 Weller Clara ◎
△Griesbaum Raymond
rear Bortells Sophia Mrs
982△Pennario Jack
△Schroeder Elmer
983△King Chas M ◎
△Davis Johnson
rear Walker Wm
984△Schneider Fredk H ◎ carp
△Schneider Herman R
rear△Haueise Robt C
985 Bowers Edw J ◎
986△Cary Wm D
Sailor Clarence
△Lewis Raymond F
Meegan Edw C
△Popp Geo W
987 Hopkins Dora
△Knapp Anthony G
989△Haverty Edna L Mrs
△Baker Agnes B Mrs
990△Small Wm
△Nestel Fred W
993△Wieland Christina Mrs
△Merrill Grace
rear△Walter Edmund G
994△Evans Geo
△Davidson Edmund
995△Smith Rosetta E Mrs
△Smith Walter G ◎
996△Morganstern Julia C Mrs ◎
997△Nestel Norman J
Artmeier Mary Mrs
1001△Goldin John V
△Monfuletto Anthony ◎ gro
1009△Stegner Allen E drugs

High intersects

1021△Sutton Mary A Mrs
Hahn Henry H
1023△Brock Loren E ◎ coal
1027 Snyder Cecil T ◎
1029△Blank Clara Mrs ◎
Blank Cath Mrs
△Lavin Leo J
1031 McKnight Ernie
1033△Markey Edwin C trucking
1035 Sorci Salvatore
Taylor Zack
1039△Manno Chas ◎
△Newton Chas B
1041△Ott Jos W ◎

Goodrich ends

1043△Vallone Jos ◎
Uhlinger Edw C
1044△Ortolano Maria gro
1045△Tanno Lawrence ◎ real est
△Brown John J
1046 Reichard Jeannette Mrs restr
1048△Shepard Louis C
1049△Munro Irving
Munro Geo
1052△Holm John E ◎
1053△Crosier Geo G ◎
1054△Wood Geo W
△Holfelder Jeanette ◎
1056△Hoellig Howard M ◎
△Hoellig Earl A ◎
1057△Schiesel Edw ◎
△Heinike Henry H
1059 Ries Jos W ◎
1060△Koch Ida O Mrs ◎
1061 Waite Neal M ◎
1062△Weaver Nora Mrs ◎
1064 Bauer Ronald
△Emoles Henry R
1065△Trautman Gertrude Mrs ◎
1066 Winfield J H & Co (whse)
1069△Hickey Henry J
△Flanders Wm L ◎
1071 Karnitz Albert G
△Dukesbury Sarah E Mrs

North intersects

1080△Curley Top Beauty Shoppe
1082 Vacant
1083 Wehr John J
1086 Meyer John M tailor
△Gabriel Ernest J
1089△Murphy Louise Mrs ◎
1091△Mason Claremont B ◎
△Baumler Frank
1092 Nachtrieb Edw W ◎
1095△Quigley Frank J ◎
Miller Lillian Mrs
1096 Holslag Frank
Heximer Oliver W ◎
1098 Tiede Louise
1099△Visiting Nursing Assn (br)
Spencer Lulu V Mrs
△Hume Herbert
1100△Boergers Clarence
△Lucurcio Lawrence J
1102△Strasser Henry ◎
1103△Rieger Peter C ◎
1104△DeBon Henry T ◎
△Alexander Andrew C
1105 Gettum Richd
1106△Caplick Jos L
Wilson Chas G
Boyd Annie A Mrs
1107△Stocker Wm S ◎
rear△O'Brien John J
Cecy Louis P
1111△Orth Pauline A Mrs
△Ebert Clair
1112 Pohle John C
△Pohle John D ◎
Sykes John R
1113△Parry Melvin C ◎
1114△Bingeman Geo A ◎
Horn Louis F
rear△Casper Mary L Mrs
1115△Meissner Walter H ◎
1116△Honecker Louise C Mrs ◎
Winzenried Louise C
1117 Foster Jack
△Neilson John
1119△Wilcocks Grace A Mrs

146

Best intersects

1137 Prem Albert F ◎
△Lamm Susan Mrs
1141△Trushel Chas P
1144 Roberts & Rice Co auto reprs
1145△Haskins Peter P
1148△Tutton Chas H auto repr
1149 Fitzgerald John J
Freeman Chas E
1151 Haehn Frank W
1152-60△Grant & Lux heating contr
△Frontier Oil Service (filling sta)
△Scott Claude
1155△McKimmie Danl J
O'Keefe Mary
1157△Donohue Anna M Mrs ◎

Edna pl intersects

1163△Barnes Harvey gro
1165 Lumia Frank
1167△Clayton Florence
1170△Sacca Stefono
△Iapichino Jos
1171 Peabody Raymond
△Greggo John T ◎
rear△Parks Henry L
1172 Marr Sidney A
△Lindbeck Harry
rear Myreng Almar E
1173△Jordan Grant heating contr
Oakley Ernest
rear Hawkins Lawrence

1950 NORTH ST E-A

SOURCE: POLKS



NORTH—Contd
220 First Church of Christ Scientist
221 Badder Chas S
Elmwood av intersects
226-30 North Apartments
bsmt Nicks Walter E supt
Arrigo Thos J
Clifton Sarah D
Daugherty Roger M
Davis Cameron Rt Rev
DeLyden Albert P
Ellis Walter H
Fields Lillian M
Franklin Jas
Fridell Elsie A
Gaul Chas C
Goodhue Alice F Mrs
Hutton Glenn E
Grove Raymond E
Hodges Harry J mfrs agt
Mahan Jack M
McCombs Enid
Meeker Joan
Moffat Mildred
Nye Virginia
O'Hern Mildred K Mrs
Scully Jas N
Sparfeld Elsa L
Stevenson Margt L
Thompson Mary E Mrs
Traverse Clifton G
Twamley Edgar H
Wood Jean Mrs
234 Ransom Realty Co
237 Protestant Episcopal Diocese of Western NY
Church Mission of Help
Herriott Wm I
sw cor Universalist Church
Mariner ends
245 YWCA (residence)
249 Conover Garrett R
252 Rokita Anna Mrs
Harriman Lewis G
Reinecke Ottomar W
255 Ostrander Carl Pfeiffer Clayton H
256 O'Brian Roland L
Burns Lawrence C
Hale Dorothy Mrs Angell Richd C
259 Vacant
rear Riehman Jerauld C
College ends
267 Stewart Woodford T
268 Apartments
1 Osborne Wm F
2 Fenno Laura M Mrs
3 Robeson Florence E
4 Flaherty Julia M
5 Huff Ann M
6 Wilson Ruth
7 Doerr Hazel C Mrs
8 Peabody Robt V
Street continued
274 Will Wm E
279 Corcoran Mary G nurse
282 North Gables Apts
MacLeod Duncan
290 Two-Ninety North Apts
11 Mullen Florence R
12 Moriarity Veronica M Mrs
13 Moore Rudolph J
14 Miller Mary A
21 Smering Janey R Mrs
22 Nelson Cornelius J
23 Murch Carlton J
24 Cushman Geo A
31 Mielcarek Adam J
32 Reilly John F
33 Anthony Wm H
34 Alford Helena B
41 Hunseke Eliz Mrs
42 Kimball Robt
43 Kamm Victor F
44 Szymanski Thaddeus
Street continued
291 Franciscan Sisters of the Immaculate Conception Nazareth Home for Convalescents
292 Olive Matilda Mrs
Arlington pl ends
303 Casa Misericordia (boarding)
304 Smith Gertrude R Mrs
309 Children's Hosp Cerebral Palsy Dept
310 Coplon Rosa Jewish Old Folks Home Inc
The Circle intersects
140
NORTH E—From 1039 Main east to Herman av (not open between Jefferson av and Timon)
3 King Parker C
5 Zimmermann Alvin Schadenfroh Geo J
7 Griffin Eva E
9 Smith Frank
11 Uebelhoer Kathryn
13 Lange Fred W Keller Henry K
14 No return
23 Poling Wilson pntr Sturm Francis W
25 Huttenlocker Dora C Wendel Nathalie L
26 Buffalo Surplus Co hdw
27 Wittholz Otto C plmbr
30 Jempson Machine Shop Cellophane Bag Co
31 Banks Irene Mrs
33 Koerner Chas Boyer Andrew
35 Conrad Edgar E
36 Smith Arlene M Mrs Chase Carol B Mrs
37 Exelsior Window Clng Co
39 Conn Geo
39 Crandall Eug O
41-43 Apartments
1 Schultz John G
2 Gabel Herbert N
3 Walker Viola A
4 Beswick Florence
Street continued
52-54 Pepsi-Cola Buffalo Bottling Corp
Ellicott intersects
61 Carnevale Anthony J gro
63 Mueller Harold J Fleischauer Wm G
68 Cullinan Edw B
69 Burgard Geo A Dudley Kenneth J
70 Garvey Cyril P Garvey Mary A Mrs
rear Wittmer Franklin
71 Danforth Willard J chiropractor
72 Kemp Francis J Newman Peter V
75 Armstrong Wm C Bohn John H Davis Geo C Schlifke Conrad
76 Richardson Anna Mrs delicatessen Flading Howard
77 Cook E A Body Co auto body mfrs
80 Meyers Henry G
82 Bixen Robt S DeToy Eugenia D Mrs
rear Vacant
83 Ingersoll Sterling M
84 Allen Hattie Erskine Robt H
86 Garvey P J Carting & Storage Inc Murray Hugh
87 Tutt Marion G Mrs
rear Johnson Frank Carrese Angelo D
89 Mattina Angelo Lang Robt J Wood John
90 Beardsley Chas M
93 Daley Jos Wilkinson Glenden R
94 Glair Wm J Snyder Frank B
96 Fix Earl
96 Kennedy John E delicatessen Dzielski Stanley
Welmont pl begins
101 Goellner Henrietta
rear Egger Fredk M Hartman Floyd T
105 Hughes Oliver H Hughes Oliver H jr
108 Sullivan Frank
109 Campanella Chas J
110 Simmons Anna M Mrs Poppenberg Cecelia Koniarezyk Walter Yerke Frank
111 Dolan Mary C
rear Loesch Anna Mrs Wolford Wm E
112 Schwaegler Chas
114 Berger Mary D Lyon Claud L
rear Signer Dennis P
115 Lindeman Fred H
116 Hirschberger Louis Dolan Kath
117 Johnston Isabelle A Mrs
118 Taylor Lloyd Weigand Louise Mrs
119 Fredericks Christine W Mrs
119 Otto Wm E
120 Grossopf Edw H
rear No return
121 Huston Henry Bateman Henry C
124 Fleming Geo Proehl Erwin C
rear Moran Robt
126 Ford Ruth K Mrs MacDonald Maud E Mrs
128 Britton Edgar C Hare Margt
132 Miller Louis A delicatessen
136
Elm intersects
135 Simon Geo W
137 Noon Jos
rear Noon Isaac
140 Skaggs Ross
141 Youakim Jos F Lahood Mary Mrs
142 Vacant
143 Grafly John W
145 Gianiodis John Boubaris Nicholas
146 Purcker Wm J
148 Haas Margt Mrs
149 Erhart Lillian E Cryan Michl J
150 Sawday Albert
152 Burkhardt John C Spriagel Louise Mrs
153 Rohs Mary Chretien Harold W
157 Gillott Anna S Mrs Lauer Amelia Mrs
158 Herbolsheimer Rudolf Milne Jas
160 Sonnenberger Andrew L

1950 NORTH ST E-B

SOURCE: POLKS



36 Smith Arlene M Mrs Chase Carol B Mrs
37 Exelsior Window Clng Co
39 Conn Geo
39 Crandall Eug O
41-43 Apartments
1 Schultz John G
2 Gabel Herbert N
3 Walker Viola A
4 Beswick Florence
Street continued
52-54 Pepsi-Cola Buffalo Bottling Corp
Ellicott intersects
61 Carnevale Anthony J gro
63 Mueller Harold J Fleischauer Wm G
68 Cullinan Edw B
69 Burgard Geo A Dudley Kenneth J
70 Garvey Cyril P Garvey Mary A Mrs
rear Wittmer Franklin
71 Danforth Willard J chiropractor
72 Kemp Francis J Newman Peter V
75 Armstrong Wm C Bohn John H Davis Geo C Schlifke Conrad
76 Richardson Anna Mrs delicatessen Flading Howard
77 Cook E A Body Co auto body mfrs
80 Meyers Henry G
82 Bixen Robt S DeToy Eugenia D Mrs
rear Vacant
83 Ingersoll Sterling M
84 Allen Hattie Erskine Robt H
86 Garvey P J Carting & Storage Inc Murray Hugh
87 Tutt Marion G Mrs
rear Johnson Frank Carrese Angelo D
89 Mattina Angelo Lang Robt J Wood John
90 Beardsley Chas M
93 Daley Jos Wilkinson Glenden R
94 Glair Wm J Snyder Frank B
96 Fix Earl
96 Kennedy John E delicatessen Dzielski Stanley
Welmont pl begins
101 Goellner Henrietta
rear Egger Fredk M Hartman Floyd T
105 Hughes Oliver H Hughes Oliver H jr
108 Sullivan Frank
109 Campanella Chas J
110 Simmons Anna M Mrs Poppenberg Cecelia Koniarezyk Walter Yerke Frank
111 Dolan Mary C
rear Loesch Anna Mrs Wolford Wm E
112 Schwaegler Chas
114 Berger Mary D Lyon Claud L
rear Signer Dennis P
115 Lindeman Fred H
116 Hirschberger Louis Dolan Kath
117 Johnston Isabelle A Mrs
118 Taylor Lloyd Weigand Louise Mrs
119 Fredericks Christine W Mrs
119 Otto Wm E
120 Grossopf Edw H
rear No return
121 Huston Henry Bateman Henry C
124 Fleming Geo Proehl Erwin C
rear Moran Robt
126 Ford Ruth K Mrs MacDonald Maud E Mrs
128 Britton Edgar C Hare Margt
132 Miller Louis A delicatessen
136
Elm intersects
135 Simon Geo W
137 Noon Jos
rear Noon Isaac
140 Skaggs Ross
141 Youakim Jos F Lahood Mary Mrs
142 Vacant
143 Grafly John W
145 Gianiodis John Boubaris Nicholas
146 Purcker Wm J
148 Haas Margt Mrs
149 Erhart Lillian E Cryan Michl J
150 Sawday Albert
152 Burkhardt John C Spriagel Louise Mrs
153 Rohs Mary Chretien Harold W
157 Gillott Anna S Mrs Lauer Amelia Mrs
158 Herbolsheimer Rudolf Milne Jas
160 Sonnenberger Andrew L
164 Blight E Bertram drugs
Jauch Edwin C dentist
Schaefer Norbert B phys
Michigan av intersects
172 Duch Stanley restr
177 Westcott Wm M
178 Vogelsang Cath B drsmkr
179 Burk Edw J
Maple ends
180 Teetsell Violet E Mrs
182 Maul Hulda P
Pedrick Lee
197 Abell Roscoe C
Crawford Matthew J
199 Diehl Wm
Crosby Robt H
Archer Fred
Roehback Evelyn Mrs
205 Moritz Gregory A
207 Neuner Edw F
209 Wistner Ernest E
213 Bryant Louise Mrs
215 Smith Frances delicatessen
Wainwright Martha Mrs
rear Mumm Wm M jr
Mulberry ends
223 Willard Hugh
Sellers Blanche J
225 Bishop Edw J
Lignos Gust
227 Stoll Albert A
rear Hinman Edw
229 Ulrich Johanna Mrs
rear Moris Lizzie Mrs
nw cor Fosdick-Masten Park High Sch
ns Masten Park
237 Masten Park Baptist Church
134
Locust ends
Masten av begins
249 Toellnerf Elmer W Rev
253 Smith Edw H
257 Bromley Clinton T
Edgley Wm
261 Schultz Morris
Grass Edw M
263 Koch Josephine W Mrs
Staebell Emily H
265 Samples Jas F
Anthony Hippocrates
Perez Francis C
Durabilt Inc vending machs
Lemon ends
275 Altenoeder Anthony S
Volkert Gertrude Mrs
277 Dentinger Philip J jr
283 Heckathorne Ralph
Wollenberg John
285 Pfrang Cath Mrs
287 Benke Robt F
Oehler Wm A
291 Storm Emma E Mrs
Diefenbach Wm C
Orange ends
301 O'Brien Wm L
Kilmer Walter J
307 Mueller John
Taylor Emma
rear Hayden Clara F Mrs
309 Wilke Gustave
314 Roetzer Jos M
316 Kane Steph
Solo Mildred M Mrs
320 Hamilton Lawrence S
Schroth Chas F
Gorman Patk
322 Hoffman Jennie Mrs
VanBuskirk Gertrude
Schwartz Edw delicatessen
Peach intersects
330 Scibetta Jas J confr
Apartments
1 Scibetta Chas
2 Latona Leonard
3 Manguso Jas H
4 Dennis Pauline Mrs
5 Littleboy Robt
Street continued
333 Collier Sherman B
336 Cooper Chas W
338 Hamilton Barrett E
341-43 Hes & Schwab gro
342 Johnston Kenneth B Tschampel Richd R
343 Schwab Herbert
346 Russ Jos
Stuff Howard
348 Gross Magdaline M
Wolf Edw A
Haderer Michl F
350 Mirabelli Frank
Grape intersects
353 Mueller Allene M
Diehl Oscar W
355 Clark Asa G
356 Vario Nicholas
358 Zamojski Jacob
359 Bensching Florence E Dreher Arth W
360 Sturges John J
361 Dirnberger Cath M Human Caroline
362 Endres Henry C
363 North St Gospel Tabernacle
Rose ends
368 Kreinbring Chas Oehler Geo F
370 Batterson Ethel Mrs Smith Gilbert F
372 Steinke Anna M Mrs Todd Roy E
383 Eckert John J Bozze Martha

1946 BEST ST-A

SOURCE: POLKS

489 Granata Saml
Lepine Edw H
492△Celsner Theo O ◎
493△Andruschat Frank A ◎
495△Rabenstein Edw M
496△Quackenbusch Geo A
499 Horton Edmund J ◎
500△Dahl Edw ◎
△Hemflink Lawrence G jr
501△Ferguson Jos J
502△Kirst John F
Hurley Mary Mrs
505 May Alf E
506△Spence Richd E ◎
Harrison Harriet M
508△Sullivan Wm J ◎
512△Herbold Florence A Mrs ◎
△Bonnett Wm
514△Horn Earl ◎
515△Tel Nelson John S
518△Dundon Robt J ◎
522 Theisz Fred H ◎
526△Ammer Walter W
530△Niederpruem Jos M ◎
534△Emery Chas D ◎
536△Dusac Jos J
538 Koehler Lawrence H ◎
542△Helwig Chas ◎
Westminster av intersects

13

BERRICK ALLEY — From 142 Seneca north to Swan
(No houses)
Swan intersects

48

BERTHA—From 1300 South Park av north to Buffalo Creek
△Carroll Roy
3△Wahl Aug
△Moon Wm B
7△Bruckman Geo J
△Bruckman Moving & Raising Co Inc
9△Schuster Henry J coal
11 Pitonak Andrew
13 Lopez Manuel
15△McIvor Wm
Blaszak Chester
17△Matwijko Anna
△Matwijko Frances Mrs ◎
Buffalo Creek

180

BERWYN AV — From 384 Olympic av east to Bailey av
11△Archer Wm ◎
14 Bilz Geo C ◎
15△Gosney Arth R ◎
16△Winans Stanley ◎
19△Lambour Chas X ◎
20 Kraft Herbert ◎
21△MacKellar Danl carp
22 Repman Earl L ◎
25△Gillen Wm J
26 Gassman Leo P ◎
29△Kline Chas J ◎
30△Dickinson Wm F ◎
31△Evers Wm V ◎
32 Douglas Joyce ◎
35△Miller Edw G ◎
36△Hauk Vitus C ◎
38△Wlodarczak Frank J
39△Meinke Carl ◎
41△Kumpf Lewis G ◎
42△Wilson Clara Mrs
45△Cothard Harry W ◎
46△Coveney John S ◎
47 Thompson Harrison
50△Pauley Glenn G ◎
51△Foley Eug F ◎
52△Banhalzl Marjorie J Mrs ◎
Sweet Wallace
53△O'Brian Jos V ◎
54△Kinmartin Madeline Mrs ◎
57△Rachow John H ◎
△Jaeger Richd W
58△Lee Howard L ◎
△Conklin Fredk W
△Conklin Marion E Mrs drsmkr
61△Hise Alf G ◎
62△Grimm Walter A ◎
63△Stephan Fredk F ◎
64△Robert Leroy H ◎
67△Schlau Peter M ◎
68 Herman Albert ◎
69 Beilgard Anna W Mrs ◎
△Weber Edw H
72△Zimmerman Irva J ◎
73△Weber Eug B
△Scanlon Mary C Mrs
74△Weiss Orville F ◎
77△Rambuss Fred H
78△O'Neil Wm C ◎
79△Heller Fredk ◎
80 Matt Wm J ◎
83 Foisset Jos E ◎
84△Schieder Wm E ◎
elec motor repr
85△Zimmerman Norman R ◎
88△Jones Alton A ◎
89△Walter Jos F
90 Grimm Wm ◎
93△Muther Frances E Mrs ◎
Hafner Edw
94△Drescher Casper J ◎
plmbr
95 Cook Gilbert G ◎
96 Drescher Edwin H ◎
99△Case Geo ◎
△McGuire Walter H
100△McElroy John A ◎
101△Coon Benj H ◎
Klein Cyril A
102 Demerly Benj
105△Folmer Andrew J ◎
106△Klingelmeier Henry E ◎
109△Ruber Fred W ◎
110△Glass Margt E Mrs ◎
Bailey av intersects

6

BESSEMER—From 281 Chicago east 1 block
(No houses)

144

BEST—From 1119 Main east to Genesee
4-16 Best Apts
Apartments:
1 Williams Edna M Mrs
2 Nawrocki Della
3 Shaffer Theresa A
4△Patton Victor A mgr
5 Groves Verna M
11△Morgan Harry
12 Stanton Dorothy E
14 Corwin Louis H
15 Grevish Ruby A
18 McElwell Vincent H
20△Hoen Alice Mrs
21 Politis Geo
22 Terwilliger Raymond
23 Rosenblatt Dinah R
24 Werstine Eleanor P
25△Scott John M
26 Lynch Kath
27 Keller Ronald
28 Connally Mary
29 Groth Genevieve A
30△Seerelter Peter P
31 Kersberg Benj
32 Brazzel Valentine
33 Kruger Gertrude L
34 Martin J Nelson
35△Nash Harry N
36 Knapp Margt A
37△Munroe Thos G
38 Gamrath Lillian A
39 Devine Vincent T
Street continued
18 (Reinagel Gerard C
△Farry Thos F
22△Strasser Geo A ◎
Bross Paul
25 Barry Raymond
Ritter John M
Uschold Marguerite
Ermer Edw
26 Prevost Wilfred J
LoCascio Vincent
29 March Alice Mrs
Shamp Bertha Mrs
30 O'Connell Jas
△Reynolds Frank J
31 Powell Percy G
32△Armstrong Matthew
Hearn Wm C
rear Flumerfelt Ivan H
33△Seerelter Louise A ◎
△Reilly Paul F
35△Miller Julius B ◎
Aschbarker Kenneth J
36△Vego Marion R
Maquin Albert J
38 Wright Edwin H
Allen Clarence T ◎
41△Lozel Edw W ◎
44 Ritting John ◎
44½ Forster Eug C
45 Niagara-Hudson Power Co (sub sta)
46 DuQuin Arnold J ◎
50 Drake Hedley V ◎
Hess Geo
rear△Grant John A
52 Anthony Anthony F
53 Andriatch & Bielski restr
Owen Wm
56△Salamy Geo T delicatessen
Ellicott intersects
65△Liptak Dorothy Mrs ◎ restr
67△Stevens Sarah E Mrs ◎
68△Marz Carl W
Cuddy Jane Mrs
Matheson John
Pawlak Edw F
△Kane Frank
Hubbard John P
Kruse Herbert
69 Holledeger Geo J ◎
McKay Kenneth H
70 Wecast Louis
Morris Albert A
71 Deuter Mary E ◎
72△Helfrich Geo M ◎
73 Meiser Raymond A
△Schmidt Edw J ◎
MacDonald Virgil
△Richardson Harry M
Hunter Herbert F ◎
Willison Willard
75 Rauber Helen E
Gannon Rosa M Mrs drsmkr
76 Goodman Chester F
79△Clucas Geo D Inc plmbr
Baumgarten Mary
Welmont pl ends
80△Steller's Bakery Inc
△Steller Anna Mrs
86 Bernhard Anthony F
Martha Rudolph
88 Herr Edw
Bowers Wm
90△Winter Henry G ◎
93 Beckerle Jos A ◎ tailor
Beckerle Francis X
94△Scheffler Henry H ◎
△Johnson Fred A
95 Winter Anna ◎
96△Dreissen Josephine D ◎
△Sloan Eva M
97△Schmidt Edw W
98△Martin Saml
△Jenson Emily C Mrs
99 Wagner Anna S Mrs ◎
102 Dickey Jas W
Crocker Lewis S
103△Beach Ellsworth A ◎
△Collett Harold E
104△Downey Kath T
Roemer Alf F
rear Trapp Jos
105 Schmidt Gustav ◎
Schroeder John J
rear Kistner Gerard F

1946 BEST ST-B

SOURCE: POLKS

BEST—Contd
108△McAlpine Claire S
△Schuh Christina Mrs
111△Rockett Reginald
112△Harris Morris
113△Pogrant Julius A
△Steck Louise Mrs
115 Koch Fredk ◎
△Dundow Edw A
116 Peard Anna G Mrs
△Duncan Edw A
117△Macgregor Arth S
△Clare Henry P
Elm ends
118 Fee Lawrence
120△Warner Ida F Mrs ◎
122△Ahlheim Carrie Mrs ◎
△Ahlheim Saml G
125 Neuse Wm
△Ziegelmaier June M delicatessen
125△Beckett David W
Pritchard Walter W
127△LaBart Fredk R
Darrow Sarah V Mrs
rear DeBon John J
129 Grady Maude E ◎
130△Eisenberger Philip
△Morlock Albert L ◎ pntr
131△Ford Wm H
133 Leclair David J
Pfeffer Theo H
rear Evert Erwin F
134 Pettway Wm H
△Weis John P
rear Evans Florence E Mrs
135△Bingemann Kath ◎
136△Gueth Margt Mrs ◎
138△Arida Raymond K ◎ gro
Smith Henry
Brennan Dorothy Mrs
Folga Vincent
139 Hopkins Jos
rear△Carver Geo L
141△Landgraf Phillip A
Munro Geo G
145△Blatner Norman filling sta
150△Schueslee Jas S filling sta
Michigan av intersects
159 Danahy-Faxon Stores Inc (br) gros
Sikora Frank
160 Vacant
161△LaMode Permanent Wave Corp (br)
△Malone Frank W
162 Littlefield Chas ◎
△Hoag Gerald W liquor
163△Speiman Chas H
163 King Minnie
Freeman Chas
164 Bundt Irving G
Boltz John A
165 Book Fredk D
166△Laughlin Frances L Mrs needlework
△Kordas John P
Hill Harry M
Lucas Eliz Mrs
167△Vetter Cath L Mrs
Deisser Wm G
168△DeBoldt Clarence
174 Thur Geo W
176△Mumm Caroline A Mrs ◎
178△Beck Henry ◎
184△Wetter Emma ◎
186 Vacant
190△Griffin Donald L
192△Frank Richd ◎
196△Hughes Ruth M
200 Schmidt Wm
202 Vacant
202△Niederpruem Helen M Mrs
Winzenried Adolph
206 Hogg Gerald W
△Eckert John A
208△Koeppel Edwin W
LaPatia Lewis E
210△Blake Howard C ◎
212 Vacant
216△Merritt Earl W
Zimmerman Richd A ◎
218 Adbender Gladys A
222△Jahraus Kenneth G ◎ phys
132
Masten av intersects
311 Staub Arth C
315 Post Robt
321 Green John R
Stemen Mary M Mrs
323△Dirschberger Harold E
△McCarthy John J
Peach ends
329△Wurm Arth W
Manning Thos J
Lowe Raymond D
331 Catalfamo Frank J ◎
Catalfamo Carmen F
537△Walter Cora C Mrs ◎
339△Klemenz Louise Mrs ◎
Klemenz Eug
341△Handel Fred A
345△Fabiano Saml ◎
347△Lageman Bertha Mrs ◎
Thomson Thos C
Zanke Anna Mrs
Grape ends
357△Doris Mary Mrs ◎
△Gillies Margt
Pries Fred C
359 Small Clara L
△Schier Geo W ◎
rear Mooney Norman E
361 Palmisano John ◎
363 McGurty Frank
△Vetter Chas
rear△Scheffler Fredk W
Rogge Eliz
369 Espow Isadore A
Werner Fred H
Kaufman Alton J
Simko Peter jr
rear Ball Edith Mrs
△Clark Frank F

371 Queen City Printing Co ◎
nw cor△Buffalo Civic Stadium
Jefferson av intersects
399△Frieh Louis W auto glass
400△Lang Gerhard Brewery
△Langs Bakery Inc
△Langs Creamery Inc
401△Gold Arth M
△Momjian Saml
403△Storms Nelson R
△Morehouse Ella Mrs
407 Cooper Fred W
409△Olsen Sophus
411△Winzenried Albert J
Stiffling Theo J
Youngman Milton H
413△Opel John
Earl pl ends
419 Zeznick Genevieve
△Georgian Beauty Salon
△Chamberlain Phyllis H
Dash Francis H
421 Engine Co 21 BFD
423 Hook and Ladder Co No 6 BFD
427 Hochhauser Julius M ◎
Altmann Aug
Guppenberger John
Hochhauser Fred ◎
Rasch Clara E
429 Lina Theo C
433△Lina Rose Mrs ◎
△Koch Ella E
435△Moest Howard R
rear△Reger's Monarch Auto Glass Shop
Reger John B
439 Buffalo Niagara Electric Corp (sub sta)
445△Maecker Louis C
Pershing av intersects (ns not open)
453△Rath Edw ◎ restr
△Adamczak Chester A chiropractor
458△Hudson Wm H
MacDonald Holford
458½ △Kennedy David J
460△Keller Fredk jr ◎
△Nussbaum Norman J
461△Buchbinder Alois B ◎
464△Fries Florence L Mrs ◎
△Knapp Harry J
465△Hug Frank J jr ◎ delicatessen
△Prem Clarence
466△Andrzewski Frank
Schenk Edgar ◎
469△Mols Jos P ◎ physiotherapist
470△Weber Harvey W ◎
△Kohlback Chester B
472 Miskey Jos
△Koch Fred ◎
473△Anderson Emil A
Binger Geo
476 Dorsheimer Geo P
477 Banas Jos
Osuch Chester
480 Benstead Lawrence
△Pliss Nathan A
Timon intersects
485 Asylum of Our Lady of Refuge
Sisters of the Good Shepherd Convent
488△Haffa Kate Mrs ◎
Thompson Bertha Mrs
492△Giese Albert W
Giese Henry L
494△Garft Jaas M
△Lewis Robt
496 August Geo C
△Hofheins Norman G ◎
498△Weber Eliz S Mrs
500 Gollwitzer Geo C ◎
502△Hoeppner Martin J Rev
Roehrer av begins
518△Funk Arth L ◎ phys
522△Ludwig Howard J ◎
△Becker Clara B Mrs
528△Panzica Anthony G
△Lake Clarence C
530△Flierl Alex W
Flierl Raymond C
534△Wyant Albert
△Paddock Daisy E
Johnson ends
536△Wisner Walter H
△Harper Jerome J
Wohlers av begins
537 Wright Miles E
△Hesse Wm A
538 Prong Harry E
541△Fogg Leonard H ◎
543 Weber Ludwig C
Lindner Frank
548 Bonavida Arnold P
△Prince Harry I ◎
550△Honecker Elmer W
△Guenther Henry ◎
551△Richert Beatrice R ◎
△Martin Geo O
553△Lang Matthew
Heubusch Paul H
555△Vesper Edw L
556 Elliott Laura
△Fass Chas ◎
557△Best Barber & Beauty Shop
△Gambacorta Mario J ◎
561△Pauly Urban ◎
Turski Michl A
563△Halpern Julius ◎ drugs
Bauernfeind Ruth Mrs
Norway Park begins
Sherman ends
571△Schlipper Christ H restr
575 Danahy-Faxon Stores Inc (br) gros
△Winkler Jos J ◎
577 Gambacorta Louis barber
Wangler Edw
579△Staebell Aug B ret liquor
583△Valtin Henry L

1946 **ELLICOTT ST**

SOURCE: POLKS



Ample Free Parking

770ΔBerta Jos ⓞ
Edwards Frank
ΔAbella Jos ⓞ
771 Denny Geo H
773ΔCrittenden Albert ⓞ
Wilson Eliz Mrs
774ΔLindner Henry P ⓞ
Merkle Chas A
Mondoux Henry A
Lindsey Andrew
ΔCompton Howard T
Nawrot Harry A
782ΔSpeyser Louis T ⓞ
ΔBeer Louis H
783ΔGaetz Veterinary Hosp
ΔGaetz Hiram T ⓞ
veterinarian
Gaetz Richd H
veterinarian
ΔGaetz Leonard H
funeral director
785 Bartlemus Arth H
Askey Leland E
788ΔLanaris Ernest D
ΔKessler Geo C
789ΔCooper Lucille E nurse
ΔPotts Henry R
Langworthy Myrtle Mrs
792ΔBrogan Wm J
ΔKleber Gertrude I ⓞ
793ΔWelch Chas ⓞ
Caranaugh Jas
Wilcox Cora
796 **Engineers Hall**
Unity Spiritualist Church
Stationery Engineers Local No 907
Long Tent No 63 Knights of the Maccabees
797ΔHarrington Francis ⓞ
798ΔDahlquist Lillian Mrs
802 Trouton Ollie
806ΔSullivan Bros filling sta
High intersects
822ΔSimpson Willert
823 Nehns Jos
ΔHynes Sarah
824 Horton Wm
826 Paquette Yvonne
830 Ellis Thos
Burke John J
831ΔWelch Chas L
ΔAngus Harold J
Hirsch Lenert R
834ΔCurry Grace Mrs ⓞ
ΔFisher Jack
835ΔHayn Geo M ⓞ
836ΔSnyder Cath
Gudgel Edw F
ΔBergman Eug A
ΔSnyder Cath L
ΔDwyer John
840 Hurd Raymond P
Malley Cora Mrs
841ΔDeery Emma L Mrs
842 Findon John W
Doyle Mary F Mrs
843ΔStevens Jas M
845ΔWeaver Nora G Mrs
Geodrich intersects
854ΔWeaver Emerson E
ΔCook Brian T
Fetzek Andrew
860ΔWarren Gertrude
863 Finch Albert M ⓞ
ΔTuschl Jennie
864ΔWallasch Clara L ⓞ
ΔFuller Lester
Trombley Francis J
ΔHaaland Vincent S
866ΔNix Arth M
867 Pearl Agnes
Martin Clara
Gill Grace
870 Yahle Fred V ⓞ
ΔBarrett Jas J
871ΔBamberg Danl ⓞ
ΔWampach Anthony J
rear Killian Eliz Mrs
Prem Carl J
872 Reichlin Chas J
Hurley Wm J
873 Vacant
876ΔGreen Thos J
878ΔBecker Fredk C restr
E North intersects
886ΔGuldner John H ⓞ
ΔSees Albert J
890ΔEarly Kath ⓞ
ΔTorrence Earl M
892ΔCrotty Patk H
ΔSchilling Chas J
894ΔDouleas Clarence
898ΔKohlbrenner Anthony J
Barden John J
900 Klass Herbert F
903 Fisher Ida Mrs ⓞ
ΔAsselin Chas L
905ΔO'Connor Gregory
908ΔNorth Ellicott Service Garage
909ΔKroombein Walter H
913ΔGreen John J
ΔFuss Flora Mrs
StPaul intersects
931-35 Pepsi Cola Bottling Corp
938ΔKevra Frank auto repr
144
Best intersects
961ΔSimplex Motor Parts auto accessories
963 Vacant
966ΔArk Plumbing Supplies
967ΔNebrich & Co auto electns
969 Veith Martin E
Biggie Henry
ΔMerkel Ernest
970ΔApfel Walter H clo clnr
rear Adamczak Henry J
971ΔKelly Irene A Mrs
ΔPratt Wm J
972 Charrette Frank V
rear Cream Martin F jr
973ΔRoper Alonzo A
Davis Susan Mrs
976 Katoll Marie L ⓞ
977ΔKingman Warren E
978ΔKatoll Marie L florist
979 Miller Nettie Mrs ⓞ
Richardson Walter O
Edna pl begins

980-86ΔAmphibian Car Corp auto boat mfrs
988ΔRichardson Norman W
ΔBisonite Co pnt mfrs
990 Parent Susie Mrs
991ΔClark Fredk A ⓞ
ΔBrown Genevieve M Mrs
ΔSilaway Chas H
993 Kreller Edw H ⓞ
ΔEvans Chas W
994 Baker Walter F
Franklin Kenneth C
rear McIntosh Cath H ⓞ
996 Vetter John P
Heat Robt C
997 Amann Raymond T ⓞ
998ΔBuxton Luther D
Potter Jules H
rear Valentine Mary E Mrs
ΔHofheins Roger auto mfg
1000 **Apartments**
1ΔWagner Robt A
2ΔCrean Margt M
3 Kinsella Wm
Street continued
1001ΔPaul Minnie Mrs ⓞ
Paul Barbara ⓞ
rear Ebnet John
1002 **Apartments**
1 Lee Roland F
2 Roth Albert
3 Vastola Anthony
4ΔEvans Anna S
5ΔJulian Jos J
6ΔAcone Louis M
Street continued
1006 LoCascio Vincent barber
1007 Calvary Evan Lutheran Church
Dodge intersects
1031 Novitzki Wm
Mohammed Allie
1032ΔHettrich Electric Service auto reprs
1033 Knox John S
1034ΔKayler Wm G
1035 O'Brian Jos J
1036 Gastel Mae Mrs
Garvey Geo E
ΔReiss Frank H ⓞ
1037 Black Robt
1040ΔSchubert Clement P
1041ΔRick Edw A ⓞ
McFarlane Carlton C
1042 Schubert Rose ⓞ
1044ΔWeber Elmer W
Coe pl ends
1045ΔBishop Frank H
Miller John M
1047ΔCecchini Lena Mrs
Ford Helen Mrs
Cronin Alice M
Southampton begins
1050ΔWallace Albert ⓞ
1054ΔBoore Ada Mrs ⓞ
1056ΔSmith Wm
1059 Wilson Wm A
Larson Wm A
1060ΔBoore Edw B
1061ΔKemp Steph B ⓞ
1062ΔSmith Wm H ⓞ
1063ΔGallaghee John J ⓞ
1066ΔLannen Eug J
1067 Vacant
1069 Nichols Elmer C
Franklin Mabel Mrs nurse
1070ΔMauerman Robt E ⓞ
1072 Carson Frank J
ΔScott Lucille Mrs ⓞ
1075ΔRothschild Helen
146
Northampton intersects
1094 Duquin Richd
ΔGood Clyde E chiropractor
ΔHaier Geo H ⓞ
1097 Helnecki Edw
1098ΔGrimm Rose Mrs ⓞ
1101ΔGuentner Harry V
Hassett Dennis J ⓞ
Cope J Raymond
Knnell Roxey
Holstien Wm
1102ΔDolan Henry T ⓞ
Thompson Donald E
1105ΔAllen Kenneth J
ΔZimmermann Edw J ⓞ
1106ΔFishman Ruth Mrs
ΔGambert Agnes P
ΔIteimondo Sylvia M Mrs ⓞ
1110ΔJehle Grover A
1113 Cameron Geo S ⓞ
1117ΔHondell Ila Mrs
1121ΔGoins Bilton W
1123 Vacant
1127ΔGebhard Caroline A
1131ΔLaMacchia Carl
ΔCurran Josephine Mrs
1135ΔSeitz Geo W ⓞ phys
1137 Baumann Edwin J
1138 StVincent dePaul Female Orphan Asylum (rear ent)
1141 Schlieckenreider Minnie E ⓞ
ΔMcIntyre Johanna Mrs
ΔMcCann Marie A ⓞ
Riley intersects
B
ELM—From 124 Swan north to Best
11 Lee Spencer
12 Vacant
Booth al intersects
15 Hoesel Jos auto repr
17-21 **Gutman Building**
ΔBates-Jackson & Co engrs
ΔSchwartz Jewelry Co mfg jwlrs
ΔKorn Wm & Co store displays
South Division intersects
38 Freire Emilio billiards
41-45ΔDynamo & Motor Exchange Inc
51 Brown Jas
North Division intersects

ELM—Contd
68-72 Bov
sta
77 Sanders
94-96ΔBer
95ΔNation
Dist
ΔAcme
Dist
97 Handic
Indu
99 Rupert
Snow
rear Velasqu
Zwipf
Hoak
101 Worthi
Mac
102ΔHutchi
(am
120ΔFox &
grap
141ΔHager
mill
150 Tillma
Aame
154 Araya
161-71ΔSt
who
162 Reeves
164 Vacant
168ΔReeve
170 Vacant
172 Watley
Archib
173-75ΔCa
Mfg
Div
174 Jackso
176 Stein
177-79ΔCh
Wa
178ΔStenin
181 Snow
Bonap
185ΔNews
ΔSynan
Baker
187 Munte
(ga
189ΔBell
Young
ΔBell
Hillar
B
210ΔHardi
woo
212-20ΔM
ref
222-34 Ge
Co
235ΔGener
(W
Gener
(H
236 McCu
rear Bartz
237-53ΔD
Th
240 Podsk
242 Jones
Wood
246 Willi
Jones
248 Goodw
Gorm
259 Jacks
267ΔSmit
Little
Smith
280ΔMetz
Sorg
ΔWisn
284 Lodge
ΔSider
286-308Δ
Co
289 Wills
291-97ΔT
pu
294ΔLam
ag
303 East
309ΔStoke
rear Mills
Lee
311 Willi
rear Sage
312 Lafk
Weld
Morg
315 Vaca
318-20 L
fu
319 Gree
321 Gris
Dow
rear Whit
rear Lath
323 Brew
Holl
326ΔArro
327-29Δ
dr
328 Vaca
330 Elm
Grif
Wan
Brou
rear Vaca
333 Vaca
335 Vaca
337ΔRad
350 Kell
ΔSutt
352-54
1 Tess
2 Senk
3 Was
4 O'B
5 Haw
6 Sobi
7 O'R
8ΔGar
Street conti
356-60Δ
I
361 Hox
Web



140
GOODRICH — From 1005 Main east to 1044 Michigan av
20 Mullet Edw H auto repr
20-22ΔTutton Electric Co auto reprs
25ΔUniversity of Buffalo School of Dentistry
26-28ΔCottrell Wheel & Brake Service
27ΔMalzer Anna E Mrs
30ΔBrace-McGuire & Co
33 Hagen Wm
ΔLeonard Edwin J
35 Vacant
40 Baker John H
ΔSeal Jas D
ΔMicklein Elmer N
rear Coon Robt G
41ΔSquirt Beverage Co
43 Norris Frances A Mrs drsmkr
44ΔDurante Anthony
Ellicott intersects
66 Rowley Robt K
68ΔMaxson Herbert B
O'Rourke Margt
rear Kennedy Mary
Gunn Fred
70ΔO'Neil Agnes F ⓞ
Smith Herman
71ΔHenry Eunice L
72 O'Donnell Kath
ΔHutchinson Haldon C
73 Vacant
74ΔKreutzer Rose P
Curtis Celery D
rearΔMilburn Jas G
75 Walker John
82ΔWood John H ⓞ
ΔTague John C
82½ Serviss Edwin Z
rearΔBean Cameron A
84ΔPech Anna ⓞ
86 Wolf Matilda M
ΔFrost Eliz ⓞ
88 Apsey Geo
Morris Leroy S
90ΔHoops Caroline Mrs ⓞ
Brossman Chas C
92ΔArmstrong Bessie Mrs ⓞ
100ΔHarrington Hosp for Children
112 Buffalo Genl Hosp Nurses' Home
Elm intersects
142
131ΔCoddington Eliz Mrs
134 McKee Z Pearl
ΔSmith Kath J ⓞ
140 Frank Edw W
142ΔFries Raymond H ⓞ
144 Vogl John W
148ΔMeyer Caroline A ⓞ
Koeppen Anna K
152 Valentine Richd H
Scanlan Rose M
rearΔBickelman Albert G
Hudson Clarence C
158 Stearns Jos W
Michigan av intersects

1946 MICHIGAN AVE-A

SOURCE: POLKS

861△Spencer Jos H ⓞ
Black Harry H
rear△Johnson Jessie L
862△Tulipane Dominick ⓞ
△McClelland M Edw
Syracuse Saml J
865 Slattery Henrietta Mrs
△Witsil Jack D
rear Neubert Marie
866△Burk Martin ⓞ
Tower Lawrence G
869△Buddenhagen Louise Mrs ⓞ
△Hummel Herbert J
870 Barner Marjorie Mrs
872△Limpantis Geo
Miller Ida
873△Wood Wm J ⓞ
Stegner Wm J
874 Argiro Jos
Haggert Florence Mrs
875 Massa Jos
Battaglia Geo A
Wecker Frieda
Sloan Lena Mrs
876 Wickham Wm C
Lalayanis Peter
877 Buffun Eliz Mrs
△Loary Eug sch supplies whol
879 Schimmer Frank J
△Geise John B
△Urshel Anna Mrs ⓞ
rear△Brummer Cath Mrs
880△Backus Rollie G
Grote Shirley L coml artist
LeFountain Saml
881△Lang Grace M Mrs ⓞ
882 Everett Raymond W
LePrell Lawrence E
fill sta
882△Young Harry L pet shop
△StMartin Cath
883 Tiede Margt Mrs ⓞ

Virginia intersects

884△Theiss Howard meats
△Goetz Carl
885△Danahy-Faxon Stores Inc (br) gros
886△Gnann Olive G Mrs
△Hines Frank E
888△Hasselbeck Mary Mrs
Archambault Thos A
889 Llotti Paul shoe repr
Roberts Laura A Mrs
△Stone Anna Mrs
891△Croakman Arth W
Klavoon Geo
892△Taylor Geo E ⓞ
893△Geisenhof Adele ⓞ
894 Linneman Frank J
Barber Raymond L
△Ruch Chas G
rear Mattison Rose Mrs
Buechner Geo C
895 MacPeek Nelson
898 Streich Rudolph
Lemley Anna Mrs
Schroth Frank ⓞ
899 Buckenroth Albert
Plasari Christy
900 Zwetsch Chas W
Kacko Rose Mrs
901 Boyd Minnie E Mrs
904 Willert Frank
△Kammerer Herbert J ⓞ
905△Grano Louis
Benaquist Louis L
906△Britton Frank H ⓞ
Bitterman Jos C
907△Sims Edmund ⓞ
908 Walter Alf E
909△Eisenhardt Georgena E
△Scharlau Grace A
Murphy Thos P
Becker Geo M
912 Fuller Harold F
Stiver Margt Mrs
△Burau Louise Mrs
913△Heusinger Aug J
Wesnor Robt E
Madison Robt G
914 Fuller Harold
△Wyman Jas
915△Smith Kath Mrs ⓞ
Elsie Arth
Jackson Arth
917 Wexler Pincus
Schneider Walter J ⓞ
918 Zupa Angelo A
△Beers Mina
rear Jones Franklin M
Buono Louis L
920 Cusimano Michl
921△Scherer Wm ⓞ
White Orpha E Mrs
Bourne Pearl M
922△Perma John
△Inge Edw
924 Atkinson Russell
△Groner Ralph
925△Schaefer Alois H ⓞ
927 Schrembs Michl
Schrembs Lillian A Mrs
Clark Wiley
928 Zobrift Geo W
930△Heiss Valentine
931 Rupprucht Ruth
Haneise Howard
rear Numan Chas
933△Haefner Geo J ⓞ
934 Miller Ogillan
Lesaar Fred
Newman Chas E
△Robinson Wm T antiques
△Anger Arth W pntr
936△Jochim Chas P ⓞ

MICHIGAN AV—Contd

937 Fanaro Chas
△Seibert Philip G
rear Polito Anthony L
939△Castiglia Pasquale
Pollino Jos ⓞ
Camuza Anthony G
Sweet Elmer D
rear Pollino Frank F ⓞ
940△Dello Chas tailor
942 Vacant
943 Bantelman Albert R
△Weigand Emma ⓞ

142

Carlton intersects

946△Kiefer John A ⓞ
△Tulipane Richd gro
948△Beilman Henry F meats
948½ Kipps Anthony barber
950△Kiefer Clara
Kuhnhaeuser Reinhard
952 Nurmi Henry
△Kassube Tessie Mrs ⓞ
rear Ranta Victor F
955-57△Batt Co Inc plmbrs
958 Ball Albertt
Hammer Glenn
958½ Klouses Geo N
959 Romano Crucian
Romano Jos ⓒ
960 Sawday Albert E
△Zimmerman Aug F
961 Holden Thos
McKnight Herbert
962△Rehm Chas A ⓞ
963 Trotter Richd
965 Johnson Chas R
Lain Harry E
966 Ehlert Wm G
967△Smith Leo S
968△Poehlmann Christ
972 Gerlach Wm
Mitterers Alois barber
974 Boss Aug
975 Dimitri Mary K Mrs
Wood Wm D
rear Cummings Eva
Lang Jennie M Mrs
977 Pfohman Jacob P
Pfohman Jos J ⓞ
978 Harter David
△Davey Geo E ⓞ
979 Weller Clara ⓞ
Greisbaum Raymond
rear Bortells Sophia Mrs
982△Pennario Jack
rear Price Frances M Mrs
O'Byrne Lawrence
983 King Chas M ⓞ
rear Walker Wm
Davis Johnson
984△Schneider Fredk H ⓞ carp
Schneider Herman R
△McLaughlin Harold
rear Haueise Robt C
985 Binner Leo J
rear Vacant
986△Scherrer John V
Sailor Clarence
Handly Howard
Ranney Jos H
987 Wolf Jos J
Meicht Mary A Mrs
989 Haverty Edna L
Palm Hjalmer L
△Baker Agnes B Mrs
990 Small Wm
△Nestel Fred W
993 Wieland Christina Mrs
△Merrill Grace
rear Walter Edmund
994 Evans Geo W
Davidson Edmund
995 Smith Rosetta E Mrs
996△Morganstern Julia C Mrs ⓞ
Pike Wm E
Morganstern Wm A
997△Nestel Norman J
Artmeier Mary A Mrs
1001 Cole Edna
△Monfuletho Anthony ⓞ gro
Oelschlaeger Robt
1009△Stegner Allen E drugs

High intersects

1021 Sutton Mary A Mrs
Hahn Henry
1023△Brock Loren L ⓞ
1027 Snyder Cecil T
1029△Blanck Clara Mrs ⓞ
Blanck Aug C
rear Gottstein Mary H ⓞ
Cole Irene
1031 Sarika Peter
Boubaris Nicholas M
1033△Markey Edwin C trucking
△Gutschow Robt
1035 Sorci Salvatore
Riboldazzi Lawrence
1039 Manno Chas
△Newton Chas
1041 VanLear Wm

Goodrich ends

1043△Engel Jos F
Uhlinger Edw C
1044△Windisch Chas ⓞ gro
1045 Manno Lawrence ⓞ
Brown John J
Frick Kathryn
1048△Shepard Louis C
1049△Munro Irving
1052△Holm John E
1053 Morrison Geo G
△Kahle Theo J
1054△Wood Geo W
△Holfelder Jeannette ⓞ

1946 MICHIGAN AVE-B

SOURCE: POLKS

MICHIGAN AV—Contd

1056 Hoellig Howard M ⓞ
△Hoellig Earl A ⓞ
1057△Schiesel Edw ⓞ
Heinike Henry H
1059 Gross Fredk
Ries Jos W sr ⓞ
Seelbach Richd
1060△Koch Ida O Mrs ⓞ
1061△Waite Neal M ⓞ
1062△Leupold John G ⓞ
1064 Bauer Ronald
1065△Trautman Walter ⓞ
1066 Balmer Ross
△Ross Upholstering Co
1069△Hickey Henry J
Flanders Wm L
1071 Karnitz Albert G
△Dukesbury Sarah E

North intersects

1080△Curley Top Beauty Shoppe
1082△Marshall Geo coal
1083 Wehr John J
1086 Meyer John M tailor
McGavern Ada E drsmkr
Gabriel Ernest J
1089△Murphy Louise Mrs ⓞ
1091 Mason Claremont ⓞ
△Baumler Frank
1092 Nachtrieb Edw W ⓞ
1095△Metzger Andrew A
Miller Lillian
1096 Holslag Frank
Heximer Oliver W
1098 Boergers Clarence H
1099△Visiting Nursing Assn
Spencer Lulu V Mrs
△Hume Herbert
1100 Tiede Louise ⓞ
△Horlein Louise M
1102 Moria Lizzie Mrs
△Hillebrand Amelia ⓞ
1103 Urban Clara A Mrs
1104△DeBon Henry T ⓞ
1105△Griffin Martha Mrs
1106 Annable Wm H
Gangeloff Barbara
rear Hartwanger Conrad P
Boyd Annie A Mrs
1107△Schwegler Emil A ⓞ
rear△O'Brien John J
McDermott Margt
Hehir Steph
1111△Orth Frank V ⓞ
△Davies Emma Mrs
1112△Wagner Ed L
△Fleming Jas
rear Sykes John R
1113△Vastola Patk A
1114△Bingeman Geo A ⓞ
Horn Lewis F
rear△Casper Mary L Mrs
1115△Meissner Walter H sr ⓞ
1116△Honecker Louise C Mrs ⓞ
Winzenried Louise C
1117△Annable Wm H
△Neilson John
1119 Wilcox Frank
Sikora Frank
1122 Balter Norman gas sta

144

Best intersects

1137 Prem Albert F ⓞ
△Lamm Susan Mrs restr (side ent)
1141 Trushel Chas
1144 Robertson & Rice Co auto reprs
1145 Haskins Peter P
1149 Fitzgerald John J
Nosbisch Otto
1151 Haehn Frank W
Franklin Albert
1152 Carlson Danny (filling sta)
Rau Louis tailor
1155 McKimmie David J
1157△Donohue Anna M Mrs ⓞ

Eden pl intersects

1160 Terrin Edith
1163△Lumia Frank delicatessen
1165 Cole Raymond
1166△Taylor Jos J
rear Vacant
1167△Clayton Florence
1170△Condon Edmund
△Danichine Jos
1171 Neal Gilbert G
Matter Cornelius
rear△Parks Henry L
Boeham Richd
1172 Marr Sietney
Griener Hartwell W
Harrington Lloyd
rear Myreng Almar E
1173 Lux Chas ⓞ
rear Hawkins Lawrence
1174 Maue Ella W Mrs
Wagner Albert E
1175 Mitchell Silas V
Post Andrew
1176 Burnett Geo H
Banck Edwin H
1177△Ager Albert C ⓞ
Black Edw
rear Wilson Maurice
1178 Knittel Emil A barber
1182 Deneby Jerry F
1183△Sullivan Ralph E
1184△Keys Marguerite
Orth Frank V meats
1187 Cisco Carl W
1188△Firestone John H auto repr
△Chmelewski Edw J
1189△Smithmeyer Jos J gro

Dodge intersects

1199 Mingo Thos shoe repr
Cook Mary M Mrs
1200△Carpenter Jas M
△Leege Albert J elec store
1201△Habitzruther Pauline Mrs ⓞ
1202△Knobloch Clifford confr
Seligman Harry E
1203 O'Brien Frank J
Eaton Alvina Mrs ⓞ
1206 Seefeldt Mary
Seefeldt Alvin J
1207△Benzino Chas hdw store
1208 Hoyler Ursula Mrs ⓞ
1209△Hettinger John C interior dec
1210 Lamm Henry G
Mullins Loretta Mrs
1212△Barnes Marie Mrs
1213△Johnson Chas V
△Smith Josephine
Marthia Alvin M
△Mattheis Walter C
1214 Emerson Herman
rear△Frost Harvey F
Ream Edw W
1215△Lawandus John J ⓞ shoe repr
Phillips Jas F
Oliver Chas G
Alexander Andrew C
1217△Parker Fabric Co auto trimmers
△Parker Nelson T ⓞ
1218△Weast Robt L
△Harrington Norman
1220 Haynes Bertha B

Southampton intersects

1233△Evans Chas pharmacy
△Lang Oscar A dentist
1236 Seager Geo A
1237 Miller Mary E Mrs
△Shandraw Arth
1238△Barry Elwood L ⓞ
1239△Zimmerman Louis A ⓞ
1241 Greenwood Wm S
1242△Herlan Geo W ⓞ
1243 Scarlett Fannie B Mrs ⓞ
Soles Walter
△Schweigel Albert P
△Fisher Alex S
Runco Pasquale
Werick Cornelius
1245 Smith Orwien P
Eigbrett Frank C
Taylor Lily Mrs
Anderson Selma K
Cook Jeanette Mrs
1248 Snyder Ralph A
1249 Vacanti Jas ⓞ
Michell Howard
1250 Vacant
1252 Vacanti Frank F jr
Mingo Jos
1253 Lithgow Robt G
1254 Red and White Food Stores (br)
1255 Vacant
1257 McGrath Teresa restr

146

Northampton intersects

1260△Smith Grace P
Costello Thos
Pleger Ernest J
1261 Danahy-Faxon Stores Inc (br) gros
Dean Walter H
Maedl John E
1262△Smith Herbert F
△Vacante Jas mach shop
△Riley Wm A liquors
1266△VanBuskirk Frank
rear Amann Richd M
△Telfair Mary L Mrs
Muth Paul J ⓞ
Reedy Annette I
△Four Hour Clnrs
1267△Weirich Adolf
Stanton Fredk H
1268 Siragusea tailor
1269 Maue John E
1270 Stearns Jos
△Parker Elma Mrs
White Allen D nurse
Brooks Hazel B Mrs
1272△Dahl Wm ⓞ
1273△White Jas S
Brennan Margt
1274△Anger Ernest
1275 Sully Jas
Hodgkins Elmer
1276 Schumacher John J
1279 Uebelhoer Geo J ⓞ
△McDonald Jas J
1280 Alfrod Chester B
Hilroy Harold W
1281△Frangoeles Chas D
1284△Zapf H Morton ⓞ
1285△Reliable Window Cling Co
△Gaulin Bros elec contrs

Eaton begins

1288 Power Edw
1292△Stengel Christopher ⓞ
△Noeltner Cath
1296△Witzig Albert J ⓞ
1297 Barhyte Wm F hat clnr
△Meyer John H
1298△Ludlow Wm ⓞ plmbr
Collar Gilbert N
Falkos Christ D
1301△Bender Philip
1302△Wilson Louis
1303 Gallagher Frank
Kendrick Judson D
1303½ Barbarie Pearl V Mrs
1304△Kumpf Alice A ⓞ
Hoernschmeyer Magdalene Mrs
Baur Pearl M Mrs
1305 Kresenfels Fred
1308△Demopoulos Geo
Alexiou John
1309△Wolff Clara L ⓞ
△Hall Ralph D
1311△Baxter Jas E
Uloth Myrtle E
1312△Dechert Florence M ⓞ
△Styn Aug J
rear△Styn A J & Co carpet clnrs
1314 Buchan Robt
1315△Hughes Wesley J
1316△Wischerath Lucille M ⓞ
1317 Brown Jos J
△Mankoff Morris
1318△Caplin Grace Mrs ⓞ
1319 Lee Wm ⓞ

1946 NORTH ST E-A

SOURCE: POLKS



North Court Apts—Contd
D9 Verstraaten Mary E
D10 Paxon Jas E
D11 Brady Freda E
Street continued
198 Fairhurst Stella Mrs
200 Coghill Kenneth
208 Abt Clara Mrs
Elmwood av intersects
220 First Church of Christ Scientist
221 Radder Chas S
226-30 North Apartments
bsmt Nicks Walter E supt
A1 Stouten John B
A2 Franklin Jas
A3 Kent Charlotte M
Snelgrove Mary E nurse
A4 Clifton Sarah
A5 Hill Ernest M
A6 Adams Caroline
B1 Vacant
B2 Eby Adam F
B3 Templeton Donald K
B4 Strong Edw C
B5 Ryan Raymond V
C1 Dunbar Davis T
C2 Fichtner Chas C
C3 Ellis Ethel K
C4 Paterson Thos W
C5 Curtis Montgomery J
Street continued
237 Protestant Episcopal Diocese of Western N Y
Church Mission of Help
Herriott Wm I
Mariner ends
245 YWCA (residence)
249 Kahle Cora A
rear Crookes Spencer
252 Rice Fred J
Rokita Anna
Parmiter Arth H
rear Russo Albert
255 McGuiness Eliz
256 O'Brian Roland L
Hale Robt H
Stillman Manning E
Selkirk Gerald H
259 Thines Karl
rear Dwyer Wm jr
College ends
267 Vines Walter E
Stewart Woodford T
268 Apartments
1 Palmer Ruth
2 Fenno Laura M Mrs
3 Robeson Florence
4 Flaherty Julia M
5 Huff Ann M
6 Wilson Ruth
7 Doerr Hazel C
8 Myers F Eunice nurse
Nagle Eleanor nurse
Street continued
274 Will Wm E CS
279 Corcoran Mary G nurse
Mankell Natalie K Mrs phys
282 North Gables Apts
MacLeod Duncan
290 Two-Ninety North Apts
Apartments:
11 Mullen Florence R
12 Moriarity Veronica Mrs
13 Moore Rudolph J
14 Miller Mary A
21 Smering Janey R Mrs
22 Nelson Cornelius J
23 Murch Carlton J
24 Cushman Geo A
31 Mielcarek R A J
32 Reilly John F
Vodpetti Edw A
33 Price Fredk K
34 Alford Helena B
41 Hunsche Eliz Mrs
42 Johnson Julius R
43 Kamm Victor F
44 Walker Ellis A
Street continued
291 Vacant
rear Vacant
292 Olive Matilda
Arlington pl ends
303 Casa Misericordia (boarding)
304 Smith Gertrude R Mrs
309 Cerebral Palsy Br Children's Hosp
310 Coplon Rosa Jewish Old Folks Home
Pearlman Simon
The Circle intersects
140
NORTH E—From 1039 Main east to Herman av (not open between Jefferson av and Timon)
3 Kellogg Clarence
5 Zimmermann Alvin
Schadenfroh Geo J
7 Carmody Patk J
Kranse Hortense A M
Griffin Eva E
9 Macklem Susan Mrs
Smith Josephine
11 Krause Grace B
13 Lange Fred W
Keller Henry K
14 Ruehl Geo barber
16 Vacant
22 Vacant
23 Poling Wilson pntr
Sturm Francis W
25 Wendel Nathalie L
Huttenlocker Dora
26 Buffalo Surplus Co hdw
27 Wittholz Otto C plmbr
Nakatani Riyo
Coester Wilhelmina W Mrs
30 Benzler Wm auto repr
Jempson Machine Shop
31 Banks Irene Mrs
33 Keeler Raymond D
35 Conrad Edgar E
36 Smith Arlene M Mrs
Chase Carol B Mrs
37 Metz V J & Son bldg contrs
39 Crandall Eug O
Mace Edw G
40 Woody Frank E
Gorman Jas B
41-43 Apartments
1 Schultz John G
2 Katska Clarence W
3 Walker Viola
4 Vogel Harry H
Beswick Florence
Street continued
42 Desenroth Robt A
52-54 Pepsi-Cola Buffalo Bottling Corp
Ellicott intersects
61 Carnevale Anthony J gro and meats
68 Guenther Chas
Cullinan Edw D
69 Burgard Geo A
Dudley Kenneth J
70 Garvey Cyril P
Garvey Mary A
rear Ellis Gordon E
Merkt Wm T
71 Danforth Willard J chiropractor
72 Kemp Francis J
Newman Peter V
75 Armstrong Clarence J
Schlifke Alma M Mrs
Warnick Albert
Davis Geo C
76 Minkel Frances M delicatessen
Crowe Alf C
Sonnenberger Mary F
May Margt
77 Cook E A Body Co auto body mfrs
80 Stevens Lawrence D
82 Bixen Robt S
DeToy Peter
rear Distler John
83 Storck Chas A
Ingersoll Sterling M
84 Slorf Fred W
Erskine Robt H
86 Garvey P J Carting & Storage Inc
Murray Hugh J
rear Borland Glenn K
87 VanValkenburg Dana
LaPointe Raymond R
rear Tutt Leonard C
89 Mattina Angelo
Gaeta Mary Mrs
90 Beardsley Chas M
93 Daley Jos
Woods John
94 Glair Wm J
Synder Frank B int dec
96 Kennedy Helen B
99 Wolf John E confr
Welmont pl begins
101 Apelt Chas O
Dieckman Minna Mrs
Reiman Walter J
rear Exger Fredk M
Hartman Floyd T
105 Hayhurst Vernon H
Hughes Oliver H
108 Sullivan Frank
109 Donohue Edw J
110 Vogel Henry H
Simmons Anna M Mrs
Arcadipane Chas barber
Poppenberger Celia Mrs
Yerke Frank
111 Dolan Mary C
rear Loesch Anna Mrs
Wolford Wm E
112 Schwaegler Chas
114 LeCocq Alf C
Berger Alphonso M
Lyon Claud L
rear Signer Dennis P
115 Lindeman Fred H
116 Butler Pauline Mrs
Hirschberger Louis
117 Davis Elmer P
Johnston Isabelle
118 Weigand Albert
rear Weigand Edw W
119 Fredericks Christine W Mrs
Evans Guy J
120 Grosskopf Edw H
rear Limburg Frank J
121 Ahmler Anna
Fors Julius F jr
Manhardt Raymond A
124 Fleming Geo
Proehl Erwin C
125 Berliner Gustave J tailor
126 Ford Ruth K Mrs
Moran Robt E
MacDonald Maud E Mrs
Madden Helen M
127 DiMarco Saml gro
Johnson Jessie M Mrs
128 Weber Edw
Miller Walter P
132 Miller Louis A delicatessen
Ehlers Fredk J
142
Elm intersects
135 Simon Geo W
137 Keith Elmer
Noon Jos
rear Faber Florence Mrs nurse
140 Chiaramonte Jos C
Mitchell Norman G
Wallace Mary
141 Erbacher Christine
Lahood Mary billiards
142 Pezold Anna J Mrs
145 Green Victoria L Mrs
Clements Harry E
146 Volker Harold F radio repr
148 Haas Fredk
149 Erhart Lillian E
Cryan Michl J
150 Haas Norman G
152 Burkhardt John C
Sprigael Louise Mrs
153 Rohs Mary
Chretien Harold W
157 Gillott Arth J
Quigley Frank J
158 Herbolsheimer Rudolf
Milne Jas
160 Sonnenberger Andrew L
164 Blight E Bertram drugs
Jauch Edwin C dentist
Schaefer Norbert B phys
Michigan av intersects
172 Duch Stanley restr
177 Westcott Wm M
178 Vogelsang Cath B drsmkr
179 Burk Edw J
Maple ends
180 Teetsell Violet E Mrs
182 Maul Hulda P
Stoltman Chester J
197 Abell Roscoe C
Crawford Matthew J
199 Diehl Wm
Crosby Robt H
205 Moritz Gregory A
Riley Cyril E
207 LaRosa Anthony A
209 Wistner Ernest E
213 Bryant Louise Mrs
215 Scott Maude M Mrs
Wainwright Geo M
rear Mumm Wm M jr
223 Willard Hugh
Selzler Blanche J
225 Nagel Raymond H
Sousa Christopher J radio repr
227 Stoll Albert A
rear Hinman Edw
229 Ulrich Johanna Mrs
Eberhardt Bertha Mrs
rear Scheur Wm
nw cor Fosdick-Masten Park High Sch
ns Masten Park
237 Masten Park Baptist Church
134
Locust ends
Masten av begins
249 Miller Arth L
253 Graziadei Frank
Smith Edw H
257 Bromley Clinton T
Edgley Wm
261 Elsaesser Edw J
Grass Edw M
263 Koch Josephine W Mrs
Staebell Emily H
265 Samples Jas F
Anthony Hipocrates
Perez Francis C
Lemon ends
275 Altenoeder Anthony
Molyneux Donald W
277 Dentinger Philip J jr
283 Wollenberg Bertha
Wollenberg John
285 Pfrang Cath Mrs
287 Constantinos Christ D
Stetter Henry F
291 Storm Emma Mrs
Wheeler Walter H
Diefenbach Wm C
Orange ends
301 O'Brien Wm L
Kilmer Walter J
LeVine Leo H
307 Mueller John
Miller Emma
rear Hayden Clara F
309 Wilke Gustave
314 Roetzer Jos M
316 Solo Mildred Mrs
Hendershot Elmer J
320 Vacant store
Schroth Chas F
McDonough Wm R
Sievert Erna Mrs
Swiatowy Edw
322 Hoffman Jennie Mrs
VanBuskirk Gertrude
Schwartz Edw delicatessen
Peach intersects
330 Sciberta Jas J confr
Apartments
1 Sciberta Chas
2 Latona Leonard
3 Manguso Jas H
4 Dennis Pauline Mrs
5 Littleboy Robt
Street continued
333 Russo Leonard A
Gibbons Mary B
336 Cooper Chas W
338 Hamilton Barrett E
341-43 Bogumil Henry R gro and meats
342 Ellsworth Frank M
Tschampel Richd R
346 Russ Jos
Stuff Howard
348 Gross Magdaline M
Wolf Edw A
Haderer Michl
350 Mirabelli Frank
Grape intersects
353 Mueller Allene M
Diehl Oscar W
355 Clark Asa G
356 Vario Nicholas
358 Zamojski Jacob
359 Wilson Rex
rear Dreher Arth
360 Sturges John J
361 Dirnberger Cath M
Human Caroline
362 Endres Henry C
363 North St Gospel Tabernacle
Rose ends
368 Kreinbring Chas
Oehler Geo F
Hennig Paul M
370 Batterson Ethel Mrs
Smith Gilbert F

1946 NORTH ST E-B

SOURCE: POLKS



Contd
E
Mrs
intersects
Christ
supt
E nurse
K
Western
of Help
ends
ce)
L
E
ends
T
Mrs
Apts
Mrs
nurse
Mrs
Old
ects
140
Main
open
and
M
36 Smith Arlene M Mrs
Chase Carol B Mrs
37 Metz V J & Son bldg contrs
39 Crandall Eug O
Mace Edw G
40 Woody Frank E
Gorman Jas B
41-43 Apartments
1 Schultz John G
2 Katska Clarence W
3 Walker Viola
4 Vogel Harry H
Beswick Florence
Street continued
42 Desenroth Robt A
52-54 Pepsi-Cola Buffalo Bottling Corp
Ellicott intersects
61 Carnevale Anthony J gro and meats
68 Guenther Chas
Cullinan Edw D
69 Burgard Geo A
Dudley Kenneth J
70 Garvey Cyril P
Garvey Mary A
rear Ellis Gordon E
Merkt Wm T
71 Danforth Willard J chiropractor
72 Kemp Francis J
Newman Peter V
75 Armstrong Clarence J
Schlifke Alma M Mrs
Warnick Albert
Davis Geo C
76 Minkel Frances M delicatessen
Crowe Alf C
Sonnenberger Mary F
May Margt
77 Cook E A Body Co auto body mfrs
80 Stevens Lawrence D
82 Bixen Robt S
DeToy Peter
rear Distler John
83 Storck Chas A
Ingersoll Sterling M
84 Slorf Fred W
Erskine Robt H
86 Garvey P J Carting & Storage Inc
Murray Hugh J
rear Borland Glenn K
87 VanValkenburg Dana
LaPointe Raymond R
rear Tutt Leonard C
89 Mattina Angelo
Gaeta Mary Mrs
90 Beardsley Chas M
93 Daley Jos
Woods John
94 Glair Wm J
Synder Frank B int dec
96 Kennedy Helen B
99 Wolf John E confr
Welmont pl begins
101 Apelt Chas O
Dieckman Minna Mrs
Reiman Walter J
rear Exger Fredk M
Hartman Floyd T
105 Hayhurst Vernon H
Hughes Oliver H
108 Sullivan Frank
109 Donohue Edw J
110 Vogel Henry H
Simmons Anna M Mrs
Arcadipane Chas barber
Poppenberger Celia Mrs
Yerke Frank
111 Dolan Mary C
rear Loesch Anna Mrs
Wolford Wm E
112 Schwaegler Chas
114 LeCocq Alf C
Berger Alphonso M
Lyon Claud L
rear Signer Dennis P
115 Lindeman Fred H
116 Butler Pauline Mrs
Hirschberger Louis
117 Davis Elmer P
Johnston Isabelle
118 Weigand Albert
rear Weigand Edw W
119 Fredericks Christine W Mrs
Evans Guy J
120 Grosskopf Edw H
rear Limburg Frank J
121 Ahmler Anna
Fors Julius F jr
Manhardt Raymond A
124 Fleming Geo
Proehl Erwin C
125 Berliner Gustave J tailor
126 Ford Ruth K Mrs
Moran Robt E
MacDonald Maud E Mrs
Madden Helen M
127 DiMarco Saml gro
Johnson Jessie M Mrs
128 Weber Edw
Miller Walter P
132 Miller Louis A delicatessen
Ehlers Fredk J
142
Elm intersects
135 Simon Geo W
137 Keith Elmer
Noon Jos
rear Faber Florence Mrs nurse
140 Chiaramonte Jos C
Mitchell Norman G
Wallace Mary
141 Erbacher Christine
Lahood Mary billiards
142 Pezold Anna J Mrs
145 Green Victoria L Mrs
Clements Harry E
146 Volker Harold F radio repr
148 Haas Fredk
149 Erhart Lillian E
Cryan Michl J
150 Haas Norman G
152 Burkhardt John C
Sprigael Louise Mrs
153 Rohs Mary
Chretien Harold W
157 Gillott Arth J
Quigley Frank J
158 Herbolsheimer Rudolf
Milne Jas
160 Sonnenberger Andrew L
164 Blight E Bertram drugs
Jauch Edwin C dentist
Schaefer Norbert B phys
Michigan av intersects
172 Duch Stanley restr
177 Westcott Wm M
178 Vogelsang Cath B drsmkr
179 Burk Edw J
Maple ends
180 Teetsell Violet E Mrs
182 Maul Hulda P
Stoltman Chester J
197 Abell Roscoe C
Crawford Matthew J
199 Diehl Wm
Crosby Robt H
205 Moritz Gregory A
Riley Cyril E
207 LaRosa Anthony A
209 Wistner Ernest E
213 Bryant Louise Mrs
215 Scott Maude M Mrs
Wainwright Geo M
rear Mumm Wm M jr
223 Willard Hugh
Selzler Blanche J
225 Nagel Raymond H
Sousa Christopher J radio repr
227 Stoll Albert A
rear Hinman Edw
229 Ulrich Johanna Mrs
Eberhardt Bertha Mrs
rear Scheur Wm
nw cor Fosdick-Masten Park High Sch
ns Masten Park
237 Masten Park Baptist Church
134
Locust ends
Masten av begins
249 Miller Arth L
253 Graziadei Frank
Smith Edw H
257 Bromley Clinton T
Edgley Wm
261 Elsaesser Edw J
Grass Edw M
263 Koch Josephine W Mrs
Staebell Emily H
265 Samples Jas F
Anthony Hipocrates
Perez Francis C
Lemon ends
275 Altenoeder Anthony
Molyneux Donald W
277 Dentinger Philip J jr
283 Wollenberg Bertha
Wollenberg John
285 Pfrang Cath Mrs
287 Constantinos Christ D
Stetter Henry F
291 Storm Emma Mrs
Wheeler Walter H
Diefenbach Wm C
Orange ends
301 O'Brien Wm L
Kilmer Walter J
LeVine Leo H
307 Mueller John
Miller Emma
rear Hayden Clara F
309 Wilke Gustave
314 Roetzer Jos M
316 Solo Mildred Mrs
Hendershot Elmer J
320 Vacant store
Schroth Chas F
McDonough Wm R
Sievert Erna Mrs
Swiatowy Edw
322 Hoffman Jennie Mrs
VanBuskirk Gertrude
Schwartz Edw delicatessen
Peach intersects
330 Sciberta Jas J confr
Apartments
1 Sciberta Chas
2 Latona Leonard
3 Manguso Jas H
4 Dennis Pauline Mrs
5 Littleboy Robt
Street continued
333 Russo Leonard A
Gibbons Mary B
336 Cooper Chas W
338 Hamilton Barrett E
341-43 Bogumil Henry R gro and meats
342 Ellsworth Frank M
Tschampel Richd R
346 Russ Jos
Stuff Howard
348 Gross Magdaline M
Wolf Edw A
Haderer Michl
350 Mirabelli Frank
Grape intersects
353 Mueller Allene M
Diehl Oscar W
355 Clark Asa G
356 Vario Nicholas
358 Zamojski Jacob
359 Wilson Rex
rear Dreher Arth
360 Sturges John J
361 Dirnberger Cath M
Human Caroline
362 Endres Henry C
363 North St Gospel Tabernacle
Rose ends
368 Kreinbring Chas
Oehler Geo F
Hennig Paul M
370 Batterson Ethel Mrs
Smith Gilbert F

1940 BEST ST

SOURCE: POLKS



BERWYN AV—Contd
89 Walter Jos G 5 ⓞ
90△Werner Edgar C 4
93 Muther Frances E Mrs 3 ⓞ
94△Drescher Casper J 3 ⓞ
plmbr
95 Cook Gilbert G 5 ⓞ
96 Drescher Edwin H 2 ⓞ
99△Scott Orlando P 4 ⓞ
100△McElroy John A 2 ⓞ
101△Coon Benj H 4 ⓞ
102 Herlofson Thos C 2 ⓞ
105 Folmer Andrew J 3 ⓞ
106 Klingelmeier Henry E 3 ⓞ
109△Dunning Frank J 3 ⓞ
110△Glass Eug V 5 ⓞ
Bailey av intersects

BESSEMER—From 281 Chicago east one block
(No houses)

BEST—From 1119 Main east to Genesee
4-16 Best Apartments
Apartments:
1 Vacant
2 Nawroky Clara 1
3 Vacant
4△Patton Victor A 2 mgr
5 Grotes Verna M 1
11△Torbenson Allen P 2
12 Vacant
14 Lee Roland 2
15 Grevish Ruby A 1
18 Morgan Harry 1
20 Hayn Carl E 2
21△Stroman Jean 1
22 Porter Inez 1
23 Rosenblatt Dinah R 1
24 McGuigan John C 1
25△Scott John M 2
26 Vacant
27 Vacant
28 Vacant
29 Riley Gertrude 1
30 Vacant
31 DeWitt Thos 2
32 Vacant
33 Rosette Jeanette 1
34 Martin J Nelson 2
35 Nash Harry N 2
36△Habel Ann C 1
37 Clark Bobby 1
38 Gamrath Lillian A 1
39 Sheehan Timothy P 2
Street continued
18 Reinagel Gerard C 4
22△Strasser Geo A 4 ⓞ
Youngs Edwin B 2
25 Jones Bernadette M Mrs 1
26△Witter Sheridan L 5
29△Shea Walter V 2
March John 3
30 Murphy Harry 6
Burse Orval A 5
Nelson Elsie M nurse
31 Powell Percy G 4
32 Hearn Wm C 2
△Charlton Wallace 2
rear Gore Christopher 5
Opfel Walter H 3
33△Seereiter Cath Mrs 2 ⓞ
△Reilly Paul F 5
35△Miller Julius B 7 ⓞ
△Miller Kath Mrs 2
36 Wolf Anna M Mrs 2 ⓞ
38 Wright Edwin H 6
McDonell Geo F 6
41△Logel Edw W 4 ⓞ
44 Rittling John J 2 ⓞ
Forster Eug O 2
44½△O'Brien John D 4
45 Niagara-Hudson Power Co (sub sta)
46 Duquin Arnold J 8 ⓞ
50 Taylor Alex 1 ⓞ
Dennebey Timothy J 2
rear Metz Frank W 2
52 McGinnis Arth 7
Sippel Geo 1
53 Vacant
56△Radel Frank 2 gro
Ellicott intersects
65△Liptak Paul 5 ⓞ restr
67△Stevens Sarah E Mrs 2 ⓞ
68 Marz Carl W 2
Pawlak Edw F 2
△Simpson Edith Mrs 3
69 Hollederer Geo J 3 ⓞ
McKay Kenneth H 4
70 Weeast Louis 2
Gerace Thos 3
71 Deuter Mary E 1 ⓞ
Rekers Richd 2
72△Helfrich Geo M 4 ⓞ
73 Schmidt Edw J 2 ⓞ
Dalton Peter 2
74△Klein Kath M Mrs 3
Hunter Herbert F 2 ⓞ
75△McAllister John A 2 ⓞ
Gannon Rosa M Mrs 1
76 Goodman Chester F 2
79△Frank & Miller Inc plmbrs
Doyle Gertrude E Mrs 5
Welmont pl ends
80△Steller's Bakery Inc
Steller Anna Mrs
86△Davis Geo C 2
△Smith Ida Mrs 2
Smith Harriette A nurse
88△McCliment Jas F 2
Beck Henry B 4
90△Winter Marion T Mrs 1 ⓞ
93 Beckerle Jos A 2 ⓞ
tailor
Beckerle Francis X 4
94△Scheffler Henry H 3 ⓞ
Johnson Fred 2
95 Winter Anna 2 ⓞ
96△Dreissen Josephine D 2 ⓞ
97△Collett Harold E 2
△Schmidt Edw W 2
98△Jenson Emily C Mrs 3
Berggren Elmer E 3
102 Dains Delbert A 4
Dickey Jas W 2
103△Taylor Jesse M 2
△Wagner Anna Mrs 5 ⓞ
104 Meehan Mary 1
Roemer Alf F 4
rear Trapp Jos 2
105 Schmidt Gustav 3 ⓞ pntr
Herr Edw P 3
rear Anderson Edw H 3
108 Pries Fred C 2
111△Rockett Reginald 3
112△Bray Daisy M Mrs 3 ⓞ
113△Pogrant Julius A 2
115 Koch Fredk 2 ⓞ
△Oehler Grace Mrs 3
116 Peard Anna G Mrs 3
117△Berryman Elsa Mrs 3
△Clare Henry P 3
Elm ends
118 Fee Lawrence 4
120△Warner Ida E Mrs 8 ⓞ
122△Ahlheim Carrie Mrs 3 ⓞ
△Ahlheim Saml G 3
125△Zielkowski Wm 2 gro
126△Beckett David J 7 ⓞ
Pritchard Walter W 2
127△Labart Fred 2
Aschbacker Harry O 2
rear DeBon John B 4
129 Grady Maude E 1 ⓞ drsmkr
130△Eisenberger Phillip 3
△Morlock Albert L 2 ⓞ pntr
131△Ford Wm K 2
133 Leclair David J 2
Pfeffer Theo H 2
rear Humphreys Stanley L 6
134 Pettway Wm H 3
△Weis John P 4
135△Bingemann Kath 1 ⓞ
Carr Amelia E Mrs 2
136△Gueth Emil 4 ⓞ
138△Boldt Eliz Mrs 2 gro
rear Kautz Henrietta J Mrs 1
139 Vacant
rear Quiel Ida W Mrs 3 ⓞ
141△Landgraf Phillip A 7
Day Theo R 2
Haynes Constance Mrs 1
142 Precision Research Laboratories
145△Ostrom Gerald E filling sta
150△Wilcox Frank C filling sta
Michigan av intersects
159 Danahy-Faxon Stores Inc (br) gros
Sikora Frank 2
△Johnson Jas T ⓞ coal
160 Malone Frank W 2
△Lamm Susan Mrs 3 restr
161△LaMode Permanent Wave Corp (br) beauty shop
162 Schwind Clarence A 5 confr
163△Spelman Chas H 4
△King Mildred H 2
rear Aykroyd Aust H 2
164 Bundt Irving G 4
Boltz John A 4
165 Bogue Ivan 5
166 Greenberg Herman 2 ⓞ
rear Soergel Louise D 1
Martin Earl O 5
167 Vetter Jos W 3
Babcock Wayne N 5
168 Klemp Clarence J 4
174 Thur Geo W 2
176△Mumm Caroline A Mrs 1 ⓞ
178 Orr Henry H 2 ⓞ
184△Wetter Henry S 6 ⓞ
186 Heusinger Edw J 3
190 Spencer Clarence 4
192△Frank Richd V 3 ⓞ
Huebsch Norman 3
196△Gehl Steven J 4 ⓞ
Wander Henry J 2
Popadick Wm P 3
200△Seereiter Frank J 4
202 Gleiser Raymond A 4
Zermentsch Kath Mrs 1 ⓞ
△Niederpruem Helen M Mrs 3
Zermentsch Kath Mrs 1 ⓞ
206△Hoag Lewis H 5
△Singleton Wm J 2
208△Fitzpatrick Edw F 2 ⓞ
210 Tracey John E 3
212△Steiger Geo C 4 ⓞ
216△Syner Fredk W 2 ⓞ
Zimmerman Richd A 2 ⓞ
Pettit Jennie M Mrs 2

1940 ELLICOTT ST

SOURCE: POLKS



677△Dobmeier Augusta F Mrs 5 ⓞ
Virginia intersects
682△Yax Geo J 2 ⓞ
686△Diener Frank H 3
687 Fisher John G 3
690△Wild John H 4 ⓞ phys
691△Marten Bertha M Mrs 2
693△Charity Eye Ear & Throat Hosp of Erie County
△Kessel Fred J 2
694△Beyer Geo F 2 ⓞ
699△Fisher Jas 7 ⓞ
700△Wright Fanny E 5 ⓞ
703 Vacant
704 Kam Jos 2 ⓞ
705△Stoesen Lars E 4 ⓞ
Layton Edw W 3
708△Buffalo Tuberculosis Assn of Erie County
709 Mathers Harry J 3 ⓞ
△Sochen Max M 2
710△Sippel Julia M 5 ⓞ
711△Reisch Frank L 3 ⓞ
△Rogers Norman B 3
714△Shaw John E 10
715△Koehler Margt T Mrs 6 ⓞ
△LeVasseur Walter H 3
717△Edwards John 2 ⓞ
720△Nissenson Wm 11
721△Moersheifelder Louis F 4 ⓞ
723△Konnert Geo 4
Calos Anthony A 6
724△Weber Elmer W 4
727△Schweigert Eliz Mrs 2 ⓞ
728△Fildes Vincent J 5 ⓞ
731△Dieta Eugenie 1 ⓞ
732△Fortunato Thos 3
Kowalinski Frances Mrs 3
735△Fredriksen Carl H 3 ⓞ
Ahl Erie W 3
△Fleming Wm C 3
738△Kurvera Stanley J 7
Burgess Jane L 1
739△Ross Kathelyn F Mrs 1 ⓞ
741△Kronenwetter Ferd S 1 ⓞ
Frank Alice G Mrs 5
Carlton intersects
751△Parisi Jos 6 ⓞ
752 Brawn Geo W 7 ⓞ
755△Perner Cecelia M 4 ⓞ
756 Alger Flossie G Mrs 12
759△Dewes Gertrude M Mrs 6 ⓞ
760△Paul Eliz U Mrs 1 ⓞ
Paul Clayton used cars
763 Tranchell Amy L Mrs 3
766△Graesser Chas F 3 ⓞ
769△Devlin John T 3 ⓞ
770△Berta Jos 5 ⓞ
Kessler Geo C 5
771△Gehm Evelyn R Mrs 2 nurse
773△Crittenden Albert 3 ⓞ
Wilson Eliz Mrs 1
774△Lindner Henry P 5 ⓞ
△Sanford Robt L 2
782△Speyser Louis T 2 ⓞ
△Beer Louis H 5
783△Gaetz Veterinary Hosp
△Gaetz Hiram T 4 veterinarian
Gaetz Richd H veterinarian
△Gaetz Leonard H funeral director
785 Bartlemus Arth 4
788 Lanaris Ernest D 4
△Sidoni Angelo 3
rear△Bell Saml J 2
△Lockwood Julia E 1
789△Sullivan Eug A 4
△Cooper Myrtle Mrs 5
792△Kleber Louise Mrs 2 ⓞ
△Brogan Wm J 5
793 D'Andrea Jos P 5
796△Engineers Hall
Maccabees Assn (Long Tent)
Engineers Auxiliary No 1
Railway Mail Clerks Auxiliary
Engineers Club (Natl Assn Power Engineers No 16)
Railway Mail Clerks Assn
Unity Spiritualist Church
Stationery Engineers Local No 907
Ladies Auxiliary Buffalo Hive of Maccabees
Frontier Court Foresters of America
Nation Assn Power Engineers No 16
White Rose Foresters of America
School Engineers Local Amalgamated Assn of Meats Cutters Local No 224
797 Wingerter Leo P 10
798△Dahlquist Lillian Mrs 2
802△Touton Ollie Mrs 8
806△Sullivan Bros filling sta
High intersects
823△Nenno Jos A 6
824 Levins Frank P 2
Ludes Magdalene Mrs 3
826△Shaw Cath Mrs 7
830△Ellis Thos 3
Burke John 4
831 Beatty Clinton 3
834△Curry Grace Mrs 6 ⓞ
Mingus Cora Mrs 2
835△Hayn Geo M 6 ⓞ
836 Snyder Cath 1
839 Dwyer John J 5
840 Hurd Ray P 2
Malley Cora Mrs 4 drsmkr
841△Deery John P 4
842 Findon John W 2
Doyle Mary 1
843△Stevens Jas 2
845△Weaver Nora G Mrs 7
Goodrich intersects
854△Weaver Emerson E 3
△Stowell Donald 3
860△Britton Emma Mrs 8
863 Finch Bert 2 ⓞ
△Tuschl Jennie 1
864△Wallasch Clara L 1 ⓞ
Shelton Walter H 5
866△Nix Arth 4
867 Shaw Albert D 2
870△Gentilhomme Edw J 6 ⓞ
Nassos Thos
871△Bamburg Chas J 2 ⓞ
Wampach Anthony J 4
rear Killian Eliz Mrs 3
Keyes Gertrude E nurse
872 Reichlin Chas J 3
Hurley Wm J 4
873 Vacant
876 Vacant
878△Becker Fredk C 4 ⓞ restr
E North intersects
886△Guldner John H 3 ⓞ
△Sees Albert J 5
890△Early Kath 3 ⓞ
△Torrence Earl M 2
892△Hutchinson Wm B 3
Crotty Patk H 2
894△Winter Andrew J 5 ⓞ
Douleas Cleanthes 3
898 Kohlbrenner Anthony J 7
Barden John 5
900 Klass Herbert F 3
Gowin Amelia Mrs 3
903 Fisher Oliver L
Young Floria Mrs 5
905 Seymore Eliz Mrs 1
O'Connor Wm 2
908△Bolt Alf J auto repr
909△Krombein Henry 3 ⓞ
913 Green John J 6
917 Vacant
StPaul intersects
931-35△StPaul Auto Repair Shop
△Nebrich & Co auto elec reprs
938△Kevra Bros auto reprs
Best intersects
961△Simplex Products Corp auto accessories
963 Pan Optics Mfg Co optical goods mfrs
964△Vacant store
966△Schwab Fred O
△Schwab's Collision Service
967△F & J Auto Service
969 Dodd Peter D 3
Simon Geo 4
970△McMahon Wilford M clo clnr
rear Evert Erwin F 5
971△Kelly Irene A Mrs 1
△Pratt Wm J 5
972 Charrette Frank V 5
rear Crean Martin F jr 3
973△Bartlett Grace H Mrs 3
△Spink Gertrude 2
976 Katoll Marie L 1 ⓞ
977 Pugh Fred H 5
978△Katoll Marie L 1 florist
979 Miller Nettie Mrs 1 ⓞ
Morgan Alberta Mrs 1
Edna pl begins
980-86△Brunn & Co Inc auto body mfrs
988 Fischer Henry 2
990 Parent Susie Mrs 1
991△Clark Fredk A 1 ⓞ
△Brown Genevieve M Mrs 2
△Sillaway Chas H 2
993 Kreller Edw H 3 ⓞ
△Evans Chas W 2
△Evans Estelle R Mrs nurse
994 Baker Walter F 3
Lucas Eliz Mrs 4
rear McIntosh Cath H 1 ⓞ
996 Vetter John P 8
Klinger Eug 3
997 Amann Raymond T 3 ⓞ
998△Buxton Luther D 2
Potter Jules H 4
rear Valentine Mary E Mrs 4
1000 Apartments
1△Jensen Chas A
2△Crean Margt M 2
3△Barnes Geo K 2
Street continued
1001△Paul Frank L 5 ⓞ
Paul Harry G 2 ⓞ
rear Malke Wm 2
1002 Apartments
1 Berlin Lucille 1
2 Delaney Marjorie Mrs
3△Ferraro Matthew 3
4△Stains J Roy 4
5 Stollmeier Theo 2
6△Evans Frank K 2
Street continued
1006 Vacant
1007 Calvary Evan Lutheran Church
Dodge intersects
1031 Rose Margt Mrs 3
Mohammed Allie 1
1032△Hettrich Peter Auto Electric Service auto reprs
1033 Knox John S 4
1034△Kayler Wm G 4
1035 Smith Josephine C 3
1036△Reiss Frank H 4 ⓞ
1037△Ullmer Fred E 5 ⓞ
1040△Schubert Clement P 3
1041△Rick Edw A 7 ⓞ
Deuel Walton C 2
1042 Schubert Frank C 2 ⓞ
1044 Gastel Mary C Mrs 2 ⓞ
Coe pl ends
1045 Holtham Thos W 4
1047 Cecchini Lena Mrs 2
Ford Helen Mrs 2
Harrison Herbert J 3
Southampton begins
1050 Vacant
1054△Roore Ada Mrs 4 ⓞ
1056△Warren Gertrude 8

1940 GOODRICH ST

SOURCE: POLKS



MAIN AND COURT STREETS

143△Havana Casino ◎ restr
145 Cecola Jos 3
146△Maloy Barbara Mrs restr
147 Colazzi Anthony M 3
Syracuse Jos 3
Syracuse Pasquale 3
148△Selle Arth J 2 ◎ plmbr
△Wiekum Robt C 3
149 Mitterer Alois barber
Logan Hannah 1
151 Indelicato Jos gro and meats
152△Buxton Mach & Tool Co
Wilson Frank M 4
153 Jones Florence Mrs 1
Fralick Melvin 2
Schuck Mary Mrs 2
Bauer Alvin 3
rear Modenbach Aug P 2
Hayes Wm M 2
154△Chretien Philomena M Mrs 4 ◎
Werrick pl begins
157△Visman Frank A 3
△Cecala Geo 2 ◎
159 Messina Jos shoe repr
Cassata Josephine Mrs 1
Schindler Margt 1
Edwin pl ends
165 Stolla Frank J 2 ◎
Nicastro Chas
△Smith Lillian Mrs 1
beauty shop
166 St Philip's Episcopal Ch
△Brown Osmond H Rev
167 Kourkounis Jas 4
Ecker Clarence R 4
168△Pax Irene M beauty shop
170 Minklein Adolph 7
172 Lux Michl J 2 ◎
funeral director
Michigan av intersects
180△Bflo Assn for the Blind
183 Vacant
184△Czasek Alois E 3
185 Iacana Anthony 3
187 Dietzel Henry A 2 ◎
Duchman Geo H 2
189 Vacant
191 Rooney David D 5
Conway Grover C 3
197△White Albert 4
Mommertz Marguerite H 1
Carducci Concetta Mrs 2
Wilson Wm 5
Maple intersects
205 Domedion Geo 5
206△Stoesser Geo F gro
207△Gerlach Wm H 2 ◎
△Demerly Wm A 2
208△Wendling Frank E 3
210 Zillig Mathew 2 ◎
Steinmetz Carlton L 3
211△Wesley Olive C mus tchr
Wirges Anna M Mrs 1
213△Beyer John M 2
Doedema Jas J 3
213½ △Webb Wm P 3 ◎
214 LeBuff Harold F 5
Obermiller Chas 2
rear Raisch Pearl Mrs 3
215 Mallan Jos 2
Stroud Wm 3
rear VonDobschuetz Helen Mrs 3
216 Airgoode Anna Mrs
McCallum Edgar P 2
219 Manner Rose A Mrs 1
△Geise John B 2
220 Kempker Henry J 4
DiLiberto Jas 3
Magee Florence Mrs 1
222 Levine Richd 2
Paoletti Armand B 3
223△Wischerath Service Sta
224 Morrison Isabella Mrs 4
△Huber Vincent P 2
Mulberry intersects
232 Vacant store
234 Brunn Marie beauty shop
238 Sperrazza John 3
△Gilbert Isabella Mrs 2
delicatessen
rear Pfohl Hilda Mrs 1
240△Matthews Clarence G 5
244△Miller Jacob 6 filling sta
Funk Christiana Mrs 2
Cherry intersects

GOODLIFF — From Hopkins east ½ block, 3 north of Marilla
(No houses)

GOODRICH — From 1005 Main east to 1044 Michigan av
15 Vacant
20 Mullet Edw H auto repr
20-22△Tutton Electric Co
25△University of Buffalo School of Dentistry
26-28 Vacant
27 Malzer Ann Mrs 6
30△Peerless Laundry Corp
33 Hagen Wm 2
△Leonard Edwin J 2
35 Vacant
40 Carr Harry J 4
Stein Jas 2
rear Baker Frank H 3
41 Vacant
43 Norris Frances A Mrs 1
44△Mingen Frank J 1
Bishop Harry J 3
McDermott Edw 2
Ellicott intersects
66 Rowley Robt K 1
68△Maxson Herbert B 1
O'Rourke Margt 3
rear Irwin Maude Mrs 1
70△O'Neil Agnes F 2 ◎
△Bork Eliz Mrs 2
71△Henry Eunice L 2
72 O'Donnell Kath 1
Hutchinson Haldon 4
73 Booth Frank 4
Manko Dorothea Mrs 4
74 Bampton Henry 5
Ehlers Fred J 3
rear Milburn Jas G 5
75 Walker John 2
81 Weimer Francis 5

GOODRICH—Contd
82△Wood John H 3 ◎
Goltz Alex 2
82½ Precquer Robt 3
Bassett Chas 3
83 Ortner Jos L 9
Remick Lloyd S 4
84△Pech Josephine Mrs 3 ◎
86 Wolf Matilda M 1
△Frost Eliz 3 ◎
88 Vacant
90△Hoops Wm B 2 ◎
Brossman Chas C 2
92 Armstrong John R 4 ◎
100△Harrington Hosp for Children
112△Buffalo Genl Hosp Nurses' Home
Elm intersects
131 Coddington Eliz Mrs 4
134△Smith Abbie 2 ◎
Blair Gladys 2
140 Redlich Ida R Mrs 3 ◎
142△Fries Raymond H 4 ◎
144 Vogl John W 2
148 Meyer Caroline A 2 ◎
Koeppen Anna K Mrs 1
151 Vacant
152△Bickelman Geo 7 ◎
Bickelman John E radio repr
Peters Harvey 2
rear Hoffman Geo 2
Meindl Siegfried 3
Michigan av intersects

GOODYEAR AV — From 1430 Broadway north to E Ferry
12△Ryba Vincent ◎ sausage mfr
16 Boryszewski Casper 6 ◎
17 Wisniewski Jos V 5 ◎
△Retke Jos 3
18 Nataline Sophie Mrs 1
19 Brodzinski Julia Mrs 2
Olejniczak Lawrence F 4
Kowalczyk Alex 5
22 Grezlikowski John 5 ◎
23 Kopryanski Louis 5
Kraemer Chas P 5
24 Muchowski Geo 7 ◎
25 Gawryszewski Leo A 7
Szuba Geo 5
28 Koperski Jos E 5 ◎
Czolgosz Thos 2
29 Zaganiaczyk Stanley J 6 ◎
31 Swiecicki Stanley 3 ◎
32 Myszkiewicz Mary Mrs 4 ◎
Zgoda Frank 4
33 Barczykowski Raymond 5 ◎
34 Tomaszewski Valentine 3
Kryczka Walter 6 ◎
35 Pietraszak Steph 5 ◎
36 Dembinski Theresa Mrs 5 ◎
Wolanski Thos A 3
39 Bartel Mary Mrs 2 ◎
40 Skrok Anthony 7 ◎
Andrzejewski Frank 5
41 Ptak Jos 2 ◎
Sokolowski Edw J 3
42 Twitchell Geo B 3 ◎
45 Witkowski Frances Mrs 4 ◎
46 Ogniewski Julia Mrs 1 ◎
Lasota Ignatius 10
48 Prusak Frank 6 ◎
49 Jendrasiak Mary Mrs 3 ◎
Jendrasiak Bernard 2
52 Matuszewski Anthony 3
Kaczmarek Maryan 1
Karla Wm G 2
53 Lewandowski Bronislaus 3
Dubiel John 3
54△Huebner Bertha 3 ◎
55 Branlecki Anthony J 3
Kruzicki Thaddeus 3
57 Lokcynski Jos 4 ◎
58 Kornaszewski Stanley 8
Rusch Valentine A 3
59 Gostomski Felix P 4
barber
Empire intersects
85 Przybycien Walter 4
88 Marcinkowski Mary Mrs 4 ◎
Borucki Stanley 3
89 Pokora Jacob 4
90 Meyers Albert A 5
Brzyski Stanley F 2
92 Bartczak Bronislawa Mrs 4 ◎
95 Hojnacki Mary Mrs 2 ◎
Hojnacki Leonard J 3
△Hojnacki Bros house movers
98 Wrona Matthew 2
Lyczynski Leo J 4
Jablonski Jos 6
99 Krakowiak Michl 6
101 Nasilowski John 5 ◎
Nasilowski Helen Mrs gro
102 Bittner Sophia Mrs 3 ◎
Zimmerman Peter 3
rear Miller Florian 2
103 Gorka Frank J 3
Grzechowiak Steven 5
104 Wujek Bernard 2
Stobnicki Edw 1
Wojciechowski John 4
106 Dolka Steph 8 ◎
Grochocki Jos E 3
107 Dabek John 7
Klamborowski Constantine 5
108 Zaremba Edmund J 5 ◎
109 Jakubik Bronislaus 7 ◎
Garczynski Kath Mrs 4
111 Orzechowski Stanislaus 3 ◎
113 Wilk Edw 4
Zulawski Valentine 4 ◎
114 Lisica John 5 ◎
Budny Louis 2
116 Slazak Jos J 6
Puchalski Stanley 2

1940 MICHIGAN AVE

SOURCE: POLKS



MICHIGAN AV—Contd
909△Schariau Grace A 1
Murphy Thos L 2
Desimone Michl 3
Becker Arth
912 Fuller Harold F 4
△Stiver Ray R 3
△Burau Wm E 3
913△Metz Kath 1 ◎
Peppe Pasho 2
Heusinger Aug J 2
914 Gentile Jos 5
△Cochanides Mello G 4
915△Smith Kath Mrs 1 ◎
Scarpace Leo 2
Hare Margt Mrs 3
917 Helm Henry J 2
Schneider Walter J 3 ◎
918 Zupa Angelo A 2
Barrett Lucy C Mrs 2
mus tchr
rear Jones Franklin M 6
Buono Louis L 3
920△Perna John J 4
Cusimano Michl 3
921△Scherer Aug C 4 ◎
Reckerle Anna E 1
White Orpha E Mrs 2
Newman Chas E 2
922 Puerner Margt Mrs 2
Papadikis Geo G 8
924 Shosho Anthony I 4
Groner Ralph 2
925△Schaefer Aloys H 4 ◎
927△Renz Ernest J 4
Eilsinghorst Charlotte 1
Castiglia Pasquale 3
928 Imhof Anna Mrs 3
930△Heiss Valentine 4
931 Albrecht Gottlieb F 2 ◎
Erhardt Eug W 2
rear Erhardt Harold C 4
933△Haefner Geo J 4 ◎
934 Williams Jas B 3
Dello Chas 2 tailor
rear Parritt Chas T 2
Anger Arth W 2 pntr
△Shephard Chas P
936 Jochim Chas P 4 ◎
937 Fanaro Chas 3
△Seibert Philip G 3
rear Tarano Fred 3
939 Camuza Anthony G 6
Castiglia Thos J 2
rear Pollino Jos 2 ◎
Pollino Frank F pntr
Kessler Robt J 2
940△Pearce Jos J 7
942 Conley Irving F 2
Hagan Jos P 2
General Coin Machine Co
943 Bantelman Albert R 2
△Longendorfer Eliz Mrs 3
Carlton intersects
946△Kiefer John A 3 ◎ gro
948△Beilman Henry F meats
Harrington Norman 2
948½ Kippes Anthony 2
barber
950△Kiefer Clara 1
Ulmer Fred J 2
952 Pude Richd A 4
△Cassube Theresa Mrs 1 ◎
Pude Hazel beauty shop
rear Feist May Mrs 3
Payne Harold C 2
955-57△Batt Co Inc plmbrs
958 Ball Albert 5
rear Webster Robt B 4
Baker Genevieve Mrs 6
959 Romano John 7 ◎
Romano Jos 7 ◎
960△Zimmerman Aug F 6
Klentzel Anne Mrs 3
961 Clark Rufus 4
Dahn Richd W 5
962△Rehm Chas A 1 ◎
963 McElligott Edw 3
965 Pettengill Clyde G 7
Eckel Jos M 3
966 Waterman Ralph M 5
967 Smith Leo S 3
968 Gessner Arth C 6
972△Bennick Rudolph G 3 ◎
Hively Ross K 2
974△Am Cigarette Machine Co
Hopkins Dora S Mrs 1
Mason Geo H 6
975 Bauries Julius 3
Dimitri Mary Mrs 6
rear Homer Warren B 3
Bishop Mary Mrs 2
977 Pfohman Jacob 5
Strohauer Carrie Mrs 3
978 Moscato Jos J 3
McBride Paul G 2
979 Weller Clara J ◎
Pempsell Albertina Mrs 2
rear Ruppert John C 2
982 Vacant
rear Price Frances M Mrs 3
Stephenson John D 4
983 King Chas M 5 ◎
Davis Wm 2
rear Vacant
984 Schneider Fredk H 4 ◎
carp
Schneider Herman R 2
Thomas Wm J 4
985 Binner Leo J 6
Oger Aug G 2
986△Scherrer John V 2
MacLaughlin Harold V 2
Horan Gordon A 5
pntr
Wilson Harold 1
987 Sperber Wm H 1 ◎
Wolf Jos J 1
989 Artmeier Mary M Mrs 1
△Baker Agnes B Mrs 2
990 Small Wm 4
△Nestel Fred W 5
993 Wieland John J 4
△Merrill Chas F 3
rear Reinehardt Warren F 3
994 Evans Geo W 4
Thomas Thos 4
995 Meight Mary 1
Smith Rosetta E Mrs 5
996△Morganstern Julia C Mrs 2 ◎
Pike Wm E 3
997△Nestel Wm F 2
Everitt Albert E 2
1001△Thomsen Helen Mrs gro
Klemp Jos H 1
1009△Stegner Allen E drugs
High intersects
1021 Sutton Geo E 2 ◎
Marshall Andrew 2
1023△Brock Loren E 3 ◎
coal
1027 Hart Cale W 4
1029△Blanck Clara Mrs 2 ◎
Blanck Aug C 3
rear Gottstein Mary 1 ◎
1031 Andromidas Geo L 6
Diako Klay L 5
1033△Markey Edwin C 1
trucking
1035 Dietrich Jos F 3 ◎
Sorci Theresa M 4
1039 LaMacchia Carl 5
Griffin Martha Mrs 2
1041 Kuhn Geo 4 ◎
Goodrich ends
1043 Laurien John F 5
Kotz Wm P 3
1044△Windisch Chas 4 ◎ gro
Stearns Jos W 3
1045 Strauss Irving D 2
Manno Lawrence 3
△Manno Cologero 2 ◎
Dickerson Wm B 2
1048△Shepard Louis C 2
1049△Mason Clermont B 3
Thur Susan Mrs 3
1052 Helm John E 4
cabtmkr
1053△Ruehl Carl R 3
Morrison Geo G 3
1054△Hollifelder Christine Mrs 2 ◎
Wood Geo W 3
1056 Hoellig Howard M 3 ◎
Kirsch Frank 4
Hoellig Earl A 3 ◎
1057△Schiesel Edw 2 ◎
Heinike Henry H 2
1059 Newton Chas B 4
Gross Fredk 2
Ries Jos W 7 ◎
1060△Koch Ida O Mrs 3 ◎
1061 Limner Esther Mrs 2
Washer Theo L 3
1062△Leupold John G 4 ◎
1064 Bauer Laura H Mrs 2
Koenig Edw J 2
1065 Trautman Walter 7 ◎
1066△Lechner Geo L filling sta
1069 Fisher Anna Mrs 1 ◎
Hickey Henry J 3
1071 Lonz Grace Mrs 2
△Penton Paul 2
North intersects
1080 Hagan John P barber
1082△Taylor Albert J ice and coal
1083 Wehr John J 2
Vogelsang Mary Mrs 1 ◎
1086 Meyer John M tailor
McGavern Frank W 3
McGavern Ada E drsmkr
Snell Russell G 2
1089△Meyers Henry G 2
1091 Erion Kath Mrs 2
1092 Nachtrieb Edw W 2 ◎
1095 Griswold Ida beauty shop
Judd Richd W 3
1096 Holslag Frank 2
Heximer Oliver W 4
1098 Biersbach Frank I 5
1099△Visiting Nursing Assn
Spencer Lulu Mrs 1
Dawson Edw 3
1100 Tiede Minnie 2 ◎
Horlein Louise 1
1102 Moris Lizzie Mrs 3
1103△Beck Walter C 7
paperhngr
1104 DeBon Henry T 3
△Quigel Hamil E 2
1105 Fleming Geo A 3
1106 McCaluso Anthony 3
Rosen Nellie G Mrs 3
rear Hartwanger Conrad P 2
Boyd Robt 3
1107 McDermott Peter 2
△Schwegler Emiel 1 ◎
rear O'Brien John J 6
1111△Orth Frank V 3 ◎
△Davies Emma Mrs 1
1112△Wagner Edw L 3
Leary Geo J 2
rear Sykes Jos 5
1113△Vastola Patk A 2
1114△Bingeman Geo A 4 ◎
Horn Louis 2
rear Casper Frank J 2
1115 Meissner Walter H 3 ◎
1116 Honecker Louise C Mrs 1 ◎
Winzenried Louise C 5
1117△Annable Wm H 3
Neilson John 3
1122 Ostrom Gerald E filling sta
Best intersects
1137△Lamm Susan Mrs restr (side ent)
1141 Lamm Henry G 5
1145 Moritz J Albert 5
1149 Fitzgerald John J 5
Bensman Arth W 5
1151 McLean Jas 4
Weather Wm 5
1152△Dixon & Adams tires
Hughes Caroline F Mrs 4
1155 Fox S Perry 3
Mirman Ell 4
1157△Donohue Anna M Mrs 6 ◎
Eden pl intersects

1940 NORTH ST E-A

SOURCE: POLKS

1940 NORTH ST E-B

SOURCE: POLKS



NORTH—Contd
North Court Apts—Contd
C11 Hauser Angie 2
D1 Gorman Clifford H 1
D2 Vacant
D3 Vacant
D4 △Kleinschmidt Anna C 1
D5 Vacant
D6 △Bingham Walter O 2
D7 △Driscoll Ellen C 1
D8 △Hamlin Chas A 2
D9 △Verstraaten Mary E 2
D10 Vacant
D11 Vacant
Street continued
198 △Richtarsic Agnes 15 nurse
Carroll Helen 1 nurse
200 △Babbitt L Rex 2
208 △Abt Clara Mrs 8
Elmwood av intersects
220 First Church of Christ Scientist
221 △Huitfeldt May 15 furn rms
226-30 North Apartments
bsmt △Tong Harold A 2
Apartments:
A1 △Goodyear Grace Mrs 2
A2 △Hale Arth R 4
A3 △Kent Charlotte M 2
A4 △Clifton Sarah 2
A5 △Hill Ernest M 3
A6 △Bruton Phillip G 3
B1 △Lattimer Geo E 2
B2 Vacant
B3 △Anderson Walter E 3
B4 △Strong Edw C 3
B5 △Ryan Raymond V 2
C1 △Clements David H 2
C2 △Kurtz Howard W 3
C3 △Schneidau W Keith 5
C4 △Paterson Thos W 3
C5 Lee Garnett O jr 2
Street continued
237 △Protestant Episcopal Diocese of Western N Y
△Church Mission of Help
Herriott Wm 3
Mariner ends
sw cor Church of the Messiah
245 △YWCA (residence)
249 △Meyer Alex C 4 ⓓ
rear Whalen Geo A 5
252 △Evans Margt E Mrs 2 ⓓ
255 △Young Erwin A 10 furn rms
rear Bohlen Frank A 2
256 △O'Brian Roland L 5 ⓓ
259 △Lacaille Geo L 7 ⓓ
rear Mercer Everett 3
College ends
267 △Stewart Woodford T 6 ⓓ
268 Apartments
1 △Palmer Ruth 1
2 △Fenno Laura M Mrs 1
3 △Robison Margt Mrs 2
4 Briggs Margt 2
5 △Huff Ann M 1
6 △Wilson Ruth 1
7 △Allen Cora S 1
8 △Myers F Eunice 2
Street continued
274 △Will Wm E 3 ⓓ CS pract
Willis Lillie Mrs CS pract
279 △Corcoran Mary G 4 nurse
282 △North Gables Apts
△Jenkins Stanley S 3 ⓓ
MacLeod Duncan 2
290 Two-Ninety North Apts
Apartments:
11 △Mullen Florence R 1
12 △Oliver Jules S 2
13 △Moore Rudolph J 2
14 △Dawson Simms 2
21 Meyer Emma 1
22 △Snyder Jessie A 1 nurse
23 △Fitts Florence 2
24 △Morris Geo W 3
31 Jameson Maude M 2
32 △Reilly John F 2
33 △Anthony Wm H 3
34 △Alford Helena B 1
41 △Burns Jos E 2
42 △Craig Marjorie F nurse
43 △Philbrick Mae C 1
44 Vacant
Street continued
291 △Dean Sarah Mrs 18 ⓓ furn rms
LaVally Tally nurse
rear Halligan Thos 4
292 △Hotel Wardman 15
△Riequit Realty Corp
Arlington pl ends
303 △Casa Misericordia (boarding)
304 △Smith Gertrude R Mrs 7 ⓓ
309 △Rogers Wm A 3 ⓓ
310 △Coplon Rosa Jewish Old Folks Home
△Pearlman Simon 2
The Circle intersects

NORTH E—From 1039 Main east to Herman av (Not open between Jefferson av and Timon)
3 Cameron Chas 3
5 Timmons Agnes Mrs 1
6 Vacant
7 Carmody Patk J 2
Kranse Hortense A M 1
9 Miller Rosanna Mrs 1
Verona Frank 2
11 Sturm Francis W 3
Krause Grace Mrs 3
13 Lange Fred W
Keller Henry K 3
14 Ruehl Geo barber
16 △Hoerbelt & Bush antiques
22 Vacant
23 △Poling Wilson 2 pntr
Desenroth Herbert J 3
25 △Wendel Nathalie L 2 ⓓ
26 △Brown Motor Sales used cars
△Winter-Reisch auto pntrs
27 △Wittholz Otto C 3 ⓓ plmbr
Nakatani Riyo 3
28 Vacant
30 △Roberts Wm H auto repr
Jempson Machine Shop
31 Kinsella Jas 1
33 Popp Edwin 4
McCormick Geo 3
35 △Featherly Albert 5
36 △Smith Marvin R 2 taxi service
△Chase Carol B Mrs 1
37 △Metz V J & Son bldg contrs
39 O'Connor Cath 2
40 Gorman Jas P 4
△Woody Frank E 2
41-43 Apartments
1 Schultz John G 3
2 Bell Henry A 1
3 Brose Paul O F 3
4 △DesChene Erma V Mrs 2
Street continued
42 Winter Geo J 6
Jablon Walter 3
52-54 △Pepsi-Cola Buffalo Bottling Corp
Ellicott intersects
61 North St Mkt meats
68 △Guenther Chas 4 ⓓ
△Herold Geo 3
69 Burgard Geo A 3
Callopy Earl 2
70 Garvey Patk J 2 ⓓ
△Garvey Cyril P 9
Zimmerman Harold H 2
Amann Edw F 2
71 △Danforth Willard J 2 ⓓ chiropractor
72 △Kemp Francis J 3
Newman Peter V 4 ⓓ
75 Armstrong Clarence J 2 ⓓ
Bohn John 2
Davies Fred R 3
Warnick Albert 2
76 △Sonnenberger Mary Mrs 2 gro
77 △Cook E A Body Co auto body mfrs
80 Klose Susan M Mrs 1
Burley Kermit M 4
82 Bixen Robt S 2
May Margt 3
rear Distler John 2
83 VanDyke Fredk G 2
Greiner Hartwell 2
84 △Hesch Mildred E Mrs 3 beauty shop
Wales John H 2
86 △Garvey P J Carting & Storage Inc
Klopf Louise Mrs 2
rear Borland Glenn 3
87 Droney Mary 3
Regian John 3
rear Hilliker Sadie Mrs 4
89 Mattina Angelo 4
Berlin Lawrence 9
90 Beardsley Chas M 3
93 Hendricks Wm 5
94 Glair Wm J 2
LaBelle Bert 4
96 Taylor Earl 2
Kennedy Helen Mrs 2
99 △Wolf John E 7 ⓓ confr
Wolf Jerome M 2 ice and coal
Welmont pl begins
101 Apelt Chas O 2 ⓓ
Dockhorn Erich R 2
rear Hirschberger Louis H 5
105 Weinman Pauline Mrs 2 ⓓ
Kobernuss Harry A 3
108 Germano Nicholas shoe repr
109 △Donohue Edw J 5 ⓓ
110 Vogel Henry 2
Simmons John C 2
Arcadipane Chas barber
Poppenberg Jas F 5
111 Dolan Mary C 2 drsmkr
Kohler Stella Mrs 4
rear Loesch Anna Mrs 1
112 Schwaegler Jessie M Mrs 1
114 △Meyer John E jr 2 ⓓ
△Winegar Edith Mrs 1
rear Signer Dennis 3
115 △Lindeman Fredk H 2 ⓓ
116 Butler Benj 2
Werner Cordelia Mrs 1 ⓓ
117 Davis Elmer P 2
△Johnston Isabelle 2
118 Weigand Albert 2 ⓓ
rear △Weigand Edw 4
119 △Fredericks Christine W Mrs 2 ⓓ
Jones Oliver P 4
120 Grosskopf Edw 3
121 Ahmler Anna 1 ⓓ drsmkr
△Manhardt Clarence E 3
Fox Arth R 4
124 Frank Jos P 7
Barrow Robt 2
rear Limburg Frank 2
125 Vacant
126 △Horner Sarah E Mrs 1 ⓓ
Miller Arth E 3
Ford Ruth Mrs 1
Anderson Wm H 2
127 △DiMarco Enrico 2 gro
128 Vacant
132 Vacant store
△Becker John H 1
Elm intersects
135 △Simon Geo W 6 ⓓ
137 △Sweeney Eliz Mrs 2 ⓓ
△Schweiger Wm J 4 ⓓ
rear Faber Frank 2
Mason Jos N 2
141 △Meisreimer Edw A 2 ⓓ
LeCocq Bertha Mrs 3
142 Pezold Anna J Mrs 3
145 △Green Victoria L Mrs 1 ⓓ
Shamp Bertha Mrs 2
146 △Volker Harold F 5
148 Haas Fredk 2 ⓓ
149 △Groeschel Wm L 2 ⓓ
△Cryan Michl 2 ⓓ
150 △Haas Norman G 3 ⓓ
152 △Burkhardt John C 3
153 △Rohs Mary 2 ⓓ
Spriegel Louise Mrs 2
157 Gillott Arth J 2 ⓓ
Quigley Frank J 2
158 Herbolsheimer Rudolph 4 ⓓ
160 Rohrbach Conrad 2 ⓓ
Kreps Henry S 2
164 △Bilght E Bertram drugs
△Jauch Edwin C dentist
△Schaefer Norbert B phys
Michigan av intersects
172 △Duch Stanley 1 restr
177 Westcott Wm M 2 ⓓ
178 △Vogelsang Cath 2 ⓓ drsmkr
Mason Geo C 2
179 △Burk Edw J 2
Maple ends
180 Keller Margt Mrs 3 ⓓ
182 △Maul Florence Mrs 5 ⓓ
197 Crawford Matthew J 5
△Abell Roscoe C 2
199 △Diehl Carrie Mrs 5
Dugan Clara Mrs 4
205 Moritz Gregory A 2
Derschug Valentine J 3
207 Mayer Leonard J 5
209 Tague John C 3
213 Bryant Louise Mrs 1
215 △Crawford Amelia Mrs delicatessen
△Crawford Jesse 2
Mumm Wm J jr 2
Spohrs Carl 2
Mauer Theo
Mulberry ends
223 Martin Chas G 2
Putman Levret S 2
225 △Nagel Raymond H 4 ⓓ
Schworm Wm 3
227 △Stoll Albert A 2 ⓓ
Ippolito Chas F 3
229 Ulrich Michl J 4 ⓓ
rear Erskine Harry 2
nw cor Fosdick-Masten Park High Sch
ns Masten Park
237 Masten Park Baptist Church
Locust ends
Masten av begins
249 Lehman Jacob 2
253 Grigidei Rocco 3
Smith Edw 2
257 △Batt Minnie Mrs 2 ⓓ
Duringer Jos M 4
261 △Young Irene Mrs 2 ice
Miller Anna Mrs 5
263 △Koch Mary M 2 ⓓ
Roetzer Anna 2
265 Vacant store
Perez Francis C 4 ⓓ
Stafford Richd L 4
Gibbons Edw R 4
Gibbons Alva F 4
Lemon ends
275 Barenthaler Frank L 2
△Eller Roman 2
277 △Dentinger Philip J jr 1 ⓓ
283 △Wollenberg Bertha 1
△Wollenberg John 2 ⓓ
285 △Pfrang Cath 1 ⓓ
Dietsch Robt J 4
287 △Rosche Henry J 2 ⓓ
291 △Schabtach Albert J 2 ⓓ
△Diefenbach Wm C 4
Orange ends
301 △Weichsel John 2 ⓓ
Kilmer Walter J 3
Grant Edw H 4
307 Mueller John 2 ⓓ
Smith Rosanna Mrs 2
Shaw Margt L Mrs 1
309 Wilke Gustave 3 ⓓ
314 △Roetzer Jos M 2 ⓓ
316 Solo Mildred Mrs 3
Praetzel Mildred 2
320 Vacant store
Miller Anna Mrs 1
Conway Henry A 2
Scott Eunice Mrs 1
322 △Kuebler Pauline Mrs delicatessen
△Kuebler Albert 3
△Sickler Willard C 3
Peach intersects
330 △Seibetta Chas 7 confr
332 Apartments
1 Littleboy Robt 8
2 Carbone Jos F 3
3 Manguso Jas H 2
4 Vacant
5 Seibetta Jas A 4
Street continued
333 Fischer Geo J 2 ⓓ
336 △Cooper Chas W 2 ⓓ
338 △Moritz Agnes Mrs 2 ⓓ
341-43 △Koch Jacob J 2 ⓓ gro
342 △Desmond Chas F 3 ⓓ
△Schnell Wm J 2
346 △Russ Jos 3 ⓓ
Schmidt Kenneth 3
348 Gross Edw J 3 ⓓ
△Wolf Edw A 6
350 △Mirabelli Frank 3 ⓓ
Grape intersects
353 Hooper Jas W 2
Bailey Millard 3
355 Clark Asa G 3 ⓓ
356 Clark Cath Mrs 3
Schultz Fred E 3
△Vario Nicholas 2 ⓓ

1935 BEST ST-A

SOURCE: POLKS

BERWYN AV—From 391 Olympic av, east to Bailey av

11△Merritt Stanley pntr
14 Bils Geo C
15△Gosney Jos R
16△Winans Stanley
19△Lambour Chas X
20 Fullington G Lucene
21△Corrigall Alex B
22 Mullen Hugh C
25△Keenan Patk A
26 Gassman Leo P
29△Kline Chas J
30 Dickinson Wm F
31△Luippold Howard J
32 Douglas Joyce
35 Schaller Peter F
36 Hauk Vitus C
38 Kuechle Fredk J
39△Meinke Carl
41 Kumpf Lewis G
42 Cramer Albert R
45△Cothard Harry W
46△Coveney John S
47 Thompson Harrison
50 Calkins Saml R
51△Foley Eug F trucking
52△Banhalzl Andrew L
53 O'Brian Jos V
54△Kinmartin Simon F
57△Radkow John H
58△Lee Howard L
61△Hise Alf G
62△Conrad Harry S
63△Ott Harry F
64 Roberts LeRoy H
67 Schlau Peter M
68 Herman Albert
69 Bellgard Jos
72 Zimmerman Irvs J
73 Blank Anthony
△Bosetel Carl J
74△Weiss Orville F
77 Rambuss Fredk H
78 Gibson Chas
79△Heller Fredk
80 Vacant
83 Foisset Jos E
84 Gross Carl L
85 Zimmerman Norman R
88△Jones Alton A
89 Walter Jos G
90△Sullivan Wm C
93 Muther Anthony A
94△Drescher Casper J plmbr
95 Cook Gilbert G
96 Drescher Edwin H
99△Scott Orlando P
100△McElroy John A
101△Conn Benj H
102 Herlofson Thos R
105 Folmer Andrew J
106 Klingelmeier Henry E
109△Dunning Frank J
110△Taylor Arth H

BEST — From 1119 Main, east to 1132 Genesee

4-16 Best Apartments
Apartments:
1 Clockenberg Geo B
2 Rabion Gladys S
3 Ostheim Mary Mrs
4△Sloat Richd D
5 Archer Ernest
11△Connors Eleanor M
12 Underwood Frank
13△Snyder Hilda W
14△King Margt B Mrs
15 Grevish Ruby A
20 Adams Wm
21△Williams John C
22△Bernard Ione E
23 Rosenblatt D R
24△Long Maude Mrs
25△Lafan Marcia M
26 Lowe E J
27 DeLong F G
28 Blackburn Thos B
29△Riley Gertrude Mrs
30 Demming Jos J
31 Vacant
32 Chester I
33 Bush Gladys A
34△Burd Helen M
Carrish Margt Mrs
35 Carr Amelia E Mrs
36 Rumbold L
37 McClure Marjorie H
38 Simpson A O
39 Mingo Jos S

Street continued

17△Jones Bernadette
18△Williams Albert F
Thomas Tom
22 Strasser Geo A
Robinson Fannie Mrs
25△Haggerty Jas E
Trimm Thos E
26 Burke Martha Mrs
△Neely Chas C
△Burke Martha Mrs
Lipp Arth
29△Zavitz Robt D
Geise Harry A
30 Murphy Harry
31 Hess Henrietta Mrs
32△Huenniger Fred H contr
rear△McMahon John
Green Geo E
33△Secreiter Clath Mrs
△Reilly Paul F
35△Miller Julius B
△Miller Kath Mrs
36 Wolf Anna M Mrs
Macauley John C
38 Wittman Bernard J
△Ward Eusebius C trucking
41△Logel Edw W
43 Rennie John
44 Rittling John J
Forster Eug C
44½△O'Brien John D
45 Massey Richd R
46 Duquin Arnold J
50 Taylor Alex
Colin Anna Mrs
rear Metz Frank W
51-53 Ruddy Arnold restr
rear Vacant
52 McGinnis Arth
Sippel Geo
56△Radel Frank gro

Ellicott intersects

65△Liptak Paul
67△Stevens John H
68 Marz Carl W
Fisher Roy
Graser Geo R
Cannon Wm H
69 Holledarer Geo J
McKay Kenneth R
70 Zimmer Frank A
Preissing Wm A
71 Deuter Mary E
Haynes Chas F
72△Helfrich Geo M
73△Schmidt Edw J
Deigelman Anna Mrs
74△Klein Kath M Mrs
△Roach Wm H
75△Aquist Andrew D
Rose Margt Mrs
76 Herrmann Fritz W

Wehmont intersects

79△Frank & Miller Inc
plmbrs
△Baumgarten Mary
80△Steller Conrad baker
86 McKernan John H
Murphy Chas F
88 Helbling John P
△McClimont Jas F
90△Winter Henry A
93 Beckerle Jos A tailor

Wehmont pl intersects

94△Scheffler Henry H
△Prunotto Minnie Mrs
95 Winter Anna Mrs
96 Cope Gerald H
△Dreissen Josephine D
97△Collett Harold E
△Schmidt Edw W
98△Bergren Elmer E
Bergren Mabel Mrs beauty shop
102 Rahn Fred W
△Alfonsecs Phyllis Mrs
103△Taylor Jesse M
△Wagner Chas B
104 Meehan Mary
rear Trapp Jos
105 Schmidt Gustav pntr
Roth Frank T
rear Stevens Roger W
108 Pries Fred C
Quinn Edwin T
111△Monroe Floyd D
112△Bray Daisy Mrs
113△Burg Marie
△Pogrant Julius A
115△Clare Henry P
Clare Alf J
Koch Fredk
116 Peard Richd T
117 Fleming Seymour N
△Berryman Elsa Mrs

Elm intersects

118 Taylor John H
120△Warner Ida E Mrs
122△Ahlheim Currie Mrs
Ahlheim Saml G
125 Brooks Leila grp
126△Beckett David J
△Montagna Angelo J
127 Shomers Lulu Mrs
Darrow Sarah V Mrs
rear DeHon John B
129 Grady Maude E
130 Taynton Roy L
△Morlock Albert L pntr
131△Ford Wm H
133△Barry John G
Leclair David J
rear Carroll Geo W
134△Grauman Martha M Mrs
Wygant Edwin S
Ryzowski Severyn
135△Bingemann Ern
rear△Weis Barbara Mrs
136△Gueth Fred
138△Boldt Chas J gro
Reis John
Dolan Ella
rear Kautz Henrietta Mrs
139 Quiel Ida Mrs
rear Vacant
141△Landgraf Philip A
Day Theo R
Cloutier Louis B
142 Besser Wm J
Besser Helen Mrs pets
145 Goodyear-Wende Oil Corp filling sta
150△Socony-Vacuum Oil Co filling sta

Michigan av intersects

159 Danahy-Faxon Stores Inc (br) gros
Sikora Frank
△Johnson Jas G exsl
160△Orth Frank V meats
161△Curly Top Beauty Shoppe

1935 BEST ST-B

SOURCE: POLKS

38 Wittman Bernard J
△Ward Eusebius C trucking
41△Logel Edw W
43 Rennie John
44 Rittling John J
Forster Eug C
44½△O'Brien John D
45 Massey Richd R
46 Duquin Arnold J
50 Taylor Alex
Colin Anna Mrs
rear Metz Frank W
51-53 Ruddy Arnold restr
rear Vacant
52 McGinnis Arth
Sippel Geo
56△Radel Frank gro

Ellicott intersects

65△Liptak Paul
67△Stevens John H
68 Marz Carl W
Fisher Roy
Graser Geo R
Cannon Wm H
69 Holledarer Geo J
McKay Kenneth R
70 Zimmer Frank A
Preissing Wm A
71 Deuter Mary E
Haynes Chas F
72△Helfrich Geo M
73△Schmidt Edw J
Deigelman Anna Mrs
74△Klein Kath M Mrs
△Roach Wm H
75△Aquist Andrew D
Rose Margt Mrs
76 Herrmann Fritz W

Wehmont intersects

79△Frank & Miller Inc
plmbrs
△Baumgarten Mary
80△Steller Conrad baker
86 McKernan John H
Murphy Chas F
88 Helbling John P
△McClimont Jas F
90△Winter Henry A
93 Beckerle Jos A tailor

Wehmont pl intersects

94△Scheffler Henry H
△Prunotto Minnie Mrs
95 Winter Anna Mrs
96 Cope Gerald H
△Dreissen Josephine D
97△Collett Harold E
△Schmidt Edw W
98△Bergren Elmer E
Bergren Mabel Mrs beauty shop
102 Rahn Fred W
△Alfonsecs Phyllis Mrs
103△Taylor Jesse M
△Wagner Chas B
104 Meehan Mary
rear Trapp Jos
105 Schmidt Gustav pntr
Roth Frank T
rear Stevens Roger W
108 Pries Fred C
Quinn Edwin T
111△Monroe Floyd D
112△Bray Daisy Mrs
113△Burg Marie
△Pogrant Julius A
115△Clare Henry P
Clare Alf J
Koch Fredk
116 Peard Richd T
117 Fleming Seymour N
△Berryman Elsa Mrs

Elm intersects

118 Taylor John H
120△Warner Ida E Mrs
122△Ahlheim Currie Mrs
Ahlheim Saml G
125 Brooks Leila grp
126△Beckett David J
△Montagna Angelo J
127 Shomers Lulu Mrs
Darrow Sarah V Mrs
rear DeHon John B
129 Grady Maude E
130 Taynton Roy L
△Morlock Albert L pntr
131△Ford Wm H
133△Barry John G
Leclair David J
rear Carroll Geo W
134△Grauman Martha M Mrs
Wygant Edwin S
Ryzowski Severyn
135△Bingemann Ern
rear△Weis Barbara Mrs
136△Gueth Fred
138△Boldt Chas J gro
Reis John
Dolan Ella
rear Kautz Henrietta Mrs
139 Quiel Ida Mrs
rear Vacant
141△Landgraf Philip A
Day Theo R
Cloutier Louis B
142 Besser Wm J
Besser Helen Mrs pets
145 Goodyear-Wende Oil Corp filling sta
150△Socony-Vacuum Oil Co filling sta

Michigan av intersects

159 Danahy-Faxon Stores Inc (br) gros
Sikora Frank
△Johnson Jas G exsl
160△Orth Frank V meats
161△Curly Top Beauty Shoppe

162 Schwind Clarence A confr
163△Spelman Chas H
△King Robt T
rear Bishop Frank H
164△Batt Frank P
△Batt Irving P
165 Woodward Mildred R
166△Orouse Irving I phys
Greenberg Herman
rear Hulme Ralph J
Soergel Adolf G
167 Geary Clifford paperhngr
Yetter Henry
168 Klemp Clarence J
174△Lynex Alf J
176△Mumm Caroline A Mrs
178 Orr Henry H
184△Wetter Henry S
186 Heusinger Edw J
190 Hildebrand Caroline Mrs
192 Frank Richd V
Cahill Michl B
Keating John J
196 Gehl Steph
Goodwillie Robt
Wiegand Harvey O
200△Seereiter Frank J
202 Zermentsch Frank
Harris Mose
△Niederprue Helen M Mrs
206△Smith Norman T
Grubaugh Ada C Mrs
208△Fitzpatrick Edw F
Deering Geo P
210 Carter Elmer W
212△Steiger Geo C
216 Symer Fredk W
△Tanton Jesse
△Zimmerman Richd A
218 Yager Aug W
222△Jahraus Kenneth G phys
ne cor Prospect Reservoir

Maston av intersects

311 Kopff Mary Mrs
313 Zink Henry C
321 Costello Helen Mrs
Mason Geo H
323 VanRemmen Frances E Mrs

Peach intersects

329△Kuas Ernest C
American Coffee Co
Schneggenburger Albert M
331△Primiano John
337△Walter Cora C Mrs
339△Klemensz Louise Mrs
Klemensz Eug
341 Paepke John
343 Bethmann Sophia Mrs
347△Fuchs Frank
Thomson Thos
△Lageman Chas J

Grape intersects

357 Dorio Frank
359 Small Clara L
△Sehler Geo W
rear Mace Jos N
361 Aquist Andrew D
Jones Ralph
363 Fitzner Jos L
Causmanto Michl
rear Schlegel Otto F
Malak John J
369 Paslett John P
Stoos Edw W
Esenwein Chester A
Hammer John C
rear Solo John
Greulich Aug
Greulich Karl
371 Gerace Jos B barber

Jefferson intersects

392△Deco Restaurants Inc (br)
400△Lang Gerhard Brewery
△Langs Bakery Inc
△Langs Creamery Inc
401 Lina Theo C
Eckert Wm C
403△Karrer Wm G
Weirich Peter L
407 Schlegel Alf W
Simbritz Walter
409 Bowes Lena A Mrs
411 Siffling Chas
Winzenried Albert J
Litwin Louis
413 Ditzel Clarence V news dlr
Mohr Rose Mrs

Earl pl intersects

419△Tiede Edw A confr
421 Engine Co 21 BFD
423 Hook and Ladder Co No 6 BFD
427 Hochhauser Julius M
Gallinger Jos
Guppenberger John
Felschow Peter F
429△Lina Geo
433 Fillinger Margt Mrs
△Moest Howard O
439 Buffalo Genl Electric Co (sub sta)
445 Derr Elis Mrs
Derr Maud dressmkr

Pershing intersects

453△Rath Edw J restr
Raulis Margt
457△Durrenberger Alf J
458△Durr Louis M Mrs
△Goldsmith Reuben J mason contr
Chandler Ernest W
458½ Reger John B
Reger Clara Mrs mus tchr
460△Keller Fredk jr
△Nesper Elmer H
461 Buchbinder Alois B

1935 ELLICOTT ST

SOURCE: POLKS

671△Hariach Wm J
Heinrich Wm
674△Ulrich Michl ⓞ restr
675△Walsh Cath Mrs
677△Dobmeier Augusta F Mrs ⓞ
Virginia intersects
682△Yax Geo J ⓞ
686△Diener Frank H
687△Martin Bertha Mrs
△Plant Willard L
690△Seeger Eliz Mrs ⓞ
691-93△Charity Eye Ear & Throat Hosp of Erie County
△Kessel Fred J ⓞ
694△Beyer Geo F ⓞ
699△Nelson Arth
△Fisher Jas ⓞ
700△Wright Fanny E ⓞ
703△Frone Magdalena Mrs ⓞ
704△Kam Jos J ⓞ
705△Stoesep Lar E ⓞ
708△Buffalo Tuberculosis Assn
709 Mathers Harry J ⓞ
△Meiagari Elva L Mrs
710△Sippel Julia M ⓞ
711△Reisch Frank L ⓞ
Archambault Mary A
714 Garvey Michl J ⓞ
715△Koehler Margt T Mrs ⓞ
△LeVasseur Walter H
717△Chandler Alvina E Mrs ⓞ
720△Nissenson Wm Rev
721△Moerschfeider Louis F ⓞ
723△Dobbins Henrietta C
Calos Anthony
724△Weber Elmer W
727△Schweigert Andrew ⓞ
728△Evans Lillian E Mrs
731△Dietz Eugenia ⓞ
732 Clark Bessie M Mrs
Johnidas Gergory
735△Frederiksen Carl H ⓞ
Geiss Ernest J
Baltz Helen F
738△Klein Louis
739△Ross Wellington M ⓞ phys
△McPherson Colin A phys
741△Kronenwetter Fred S ⓞ
Carlton intersects
751 Parisi Jos ⓞ
752 Brawn Geo W ⓞ
755 Perner Mary U Mrs ⓞ
756 Alger Ekra D ⓞ
759△Dewes Gertrude M Mrs ⓞ
760△Paul Eliz U Mrs ⓞ
763 King Elia Mrs
Donovan John
766△Graesser Chas F ⓞ
769△Devlin John T ⓞ
770△Berta Jos ⓞ
Kessler Geo C
771 Seyfried Louis
773△Crittenen Albert ⓞ
△Wilson Geo W
774△Lindner Henry P ⓞ
782△Speyser Ernestine Mrs ⓞ
Beer Louis H
783△Gaeta Hiram T vet
785△Bartlemus Herman J ⓞ
788 Gaudet Zoel A
Osterhoudt Emma Mrs
rear△Beli Sami J
789△Sullivan Eug A
792△Kleber Louise Mrs ⓞ
Forster Freda E Mrs
793△Stemen Mary Mrs
796 **Engineers Hall**
Commodore Perry Lodge IOOF
Niagara Lodge No 25 IOOF
Mabel Rebekah Lodge No 192 IOOF
Engineers Club Natl Assn
Power Engineers No 16
Railway Mail Clerks Assn
Unity Spiritualist Church
797 Wingerter Leo P
798△Dahlquist Lillian Mrs
802△Delta Sigma Delta Frat House
806△Sullivan Bros filling sta
High intersects
823△Nenno Jos A
824 Morse Mary Mrs
826△Meudt Frank
830 Castle Geo H musical instrument repr
831△Whalen Leo F
834 Bergalias Geo
△Curry Grace Mrs ⓞ
Reed Emily S
835△Hayn Geo M ⓞ
Gallagher Margt
836 DeLacy Jos C
839△Rogers Geo W
Perry Mabel M nurse
840△Valentine Mary E Mrs music tchr
Malley Cora Mrs
841△Deery John P
842 Findon John W
Howland Clyde H
843△Henderson Jas M
845△Weaver Nora G Mrs
Goodrich intersects
854 Boyle Llewellyn
Weaver Emerson E
860△Britton Emma Mrs
863△Tuchi Jennie ⓞ
864△Wallasch Clara L ⓞ
△Jenkins Ida L Mrs
866△McCabe Bernard
Quinlan John H
867 Curry Wm
870△Gentilhomme Edw J
871△Bamberg Chas J ⓞ
Wampach Anthony J
rear Wilson Helen W Mrs
872△Reichlin Chas J
876△Hoffman Albert G gro

ELLICOTT—Contd
878△Becker Fredk C ⓞ restr
882 Blair Clarence J auto indry
886△Guidner John H ⓞ
△Sees Albert J
E North intersects
890△Sandberg Albert
△Early Kath ⓞ
892 Radert A Mary Mrs
Nelson Peter
894 Winter Andrew J ⓞ
△Hutchinson Wm B
898 Kohlbrenner Anthony J
△Seymour Eliz M Mrs
900 Klass Herbert F
△Kessel Rose Mrs
903△Beck Henry J
Lanaris Ernest
△McMartin Josephine
905 Eri Jos
908△Bolt Alf J garage
△Fike Theo N auto repr
△Morrison Auto Hospital
△Winter & Reisch Co auto repr
Ryan Louis
909△Krombein Henry ⓞ
913△Green John J
△Fuss Flora Mrs
917△Eckert Mfg Co aluminum ware mfrs
StPaul intersects
931-35△StPaul Auto Repair Shop
938 Kevra Bros auto reprs
Best intersects
961△Simplex Huntley Motor Parts Co
963△Standard Auto Top Co
△Kemp Equitable Co auto accessories
Will Bee Dry Cleaners
964 Hauck Windshield Equip Co
965 Vacant store
966△Schwab Fred O auto repr
Materbofer Paul sheet metal
969△Gates Mary Mrs
Parsons Ray O
970△McNamara Jos
rear Steinbrenner Ida Mrs
Barber Nancy Mrs
971 Adamberger Jos F
972 Charrette Frank V
rear Horton Jote N Mrs
973△Bartlett Fred P
△Davis Susan Mrs
976 Katoll Marie L
977 Lebart Fred R
978△Katoli Marie L ⓞ florist
979 Miller John G ⓞ
Edna pl intersects
980-86△Brunn & Co Inc body mfrs
988 Striker John F
990 Perrin Chas
991△Clark Fredk A ⓞ
△Hooley Josephine Mrs
993 Kreller Edw H ⓞ
△Meicht Harold
994 Lippert Simon
Norton Paul A
rear△Hoffmann Paul ⓞ
996 Vacant
997 Amann Raymond T ⓞ
998△Buxton Luther D
Potter Jules
rear Cronk Howard E
1000 **Apartments**
1 Vacant
2△Crean Margt M
3△Jones Maude M
Street continued
1001△Paul Frank L ⓞ
Paul Harry G ⓞ
rear Johns Gerald
1002 **Apartments**
1△Heltzhaus Sara J Mrs
2△Limbury Eliz Mrs
3 Vacant
4△Hardesty Faustus P
5 Swift Salome E
6△Evans Frank K
Street continued
1006 Biesinger Frank G barber
1007 Calvary Evang Lutheran Church
1010△Parks John A
Dodge intersects
1031 Hanner Amelia M Mrs
Donnelly John H
1032△Hettrich Auto Electric Service
1033 Knox John S
1034 Vacant
1035 Smith Josephine F
1036 Hanna Chas S
Reiss Frank H ⓞ
1037△Ulmer Henry A music tchr
1040 Schubert Clement P ⓞ
1041△Rick Edw A
Wischerath Lottie Mrs
1042 Schubert Frank C ⓞ
1044 Gastel John ⓞ
Coe pl intersects
1045△McCracken Walter J
△Poling Leroy J pntr
1047 Harrison Herbert J
△Gepp Harold C
Greene Earl J
Southampton intersects
1050△Steele Amos E ⓞ
1054△Boore Ada Mrs ⓞ
Carey Harriet M nurse
Boland Carrie M nurse
1056 Buckley John J ⓞ
1059△Peckham Glenn E
△Boore Edw B
1060△Holch Cath W Mrs ⓞ
1061△Marley Mary ⓞ
△Sullivan Michl J ⓞ
1062 Lane Jas L

1935 GOODRICH ST

SOURCE: POLKS



GOODELL—Contd
187 Dietzel Henry A ⓞ
△Kuhn Roland E
189 Schwarze Henry
191 Rooney David
Kaufman Abr
197△White Jas D
△White Albert
Mommertz Marguerite
Nestel Julia drsmkr
White Eliz E Mrs ⓞ
Maple intersects
205 Patrizi Olga Mrs
McGraw Wm
Domedion Geo
Wennemann Mary Mrs
206△Stoesser Geo F gro
207△Gerlach Wm C
Demerly Wm A
208 Wendling Frank E
210 Zillig Mathew M ⓞ
Herzog Anna Mrs
211 Wesley Mina Mrs
Wesley Olive mus tchr
Fries Chas J
213△Beyer John M
Boyle Laura Mrs
213½ Webb Wm P ⓞ
214△Huber Adolph E ⓞ
rear Zuber Bertram G
215 Mallan Jos
Lubick Albert
rear VonDobschuetz Helen Mrs
216 Schultheis Mathilda C Mrs
McCallum Edgar P
219 Manner Rose A Mrs
△Geise John B
220 Kempker Henry J
Benten Wilhelmina Mrs
McGee Geo
Bennett Geo E
222 Geiger Frank F
Evans Louis
223△Wischerath Albert P
filling sta
224△Goodell Tavern
Mulberry intersects
232 Silver Jos A
238 Coveny Anna M confr
△Coveny Chas J
rear Erler Jas
240 Vacant
242△Miller Jacob filling sta
244 Tubbs Nellie
Miller Jacob
LaPlante Eug

GOODLIFFE—From 69 Hopkins east to inner lot

GOODRICH — From 1006 Main east to 1044 Michigan av
15 Mullett Edw H auto repr
20-22 Miller Walter P auto repr
25△University of Buffalo School of Dentistry
26 Buffalo Wilbert Vault Works Inc
27 Vacant
28 Vacant
30△Peerless Laundry Corp
33 Hagen Wm
Leonard Edwin J
35 Vacant
40 Vacant
rear Marlin Walter E
41 Wipperman & Hoffmeyer batteries
Turner Hiram L radio service
43 Norris Frances A Mrs
44△Mingen Frank J
Bishop Harry J
Elliott intersects
66 Rowley Anna C Mrs ⓞ
68 Maxson Herbert B
O'Rourke Margt
rear Burton Leora J Mrs
70△O'Neil Agnes F ⓞ
△Bork Frank R
71 Henry Louise
72 O'Donnell Kath
Galloway Jane L Mrs
73 Nachtrieb Lillian M ⓞ
Dietrick Jos J
Galivan Wm
74 Fox Arth R
Mash Rose
rear Milburn Jas G
75 Walker John
81 Armstrong John R
82△Wood John H ⓞ
Goltz Alex
82½ Shafto Alice G Mrs
Miller Walter P
83△Simonds Cortes V
McMahon John A
84△Pech Josephine Mrs ⓞ
86 Wolf Matilda M Mrs
△Frost Eliz ⓞ
88 Kiefer Anna M ⓞ
90 Hoops Wm B ⓞ
Brossman Chas C
92 Dreger Emma L ⓞ
Gollan Donald S
100 Harrington Hosp for Children
112 Buffalo Genl Hosp Nurses Home
Elm intersects
131 Coddington Adelbert
134△Smith Chas O ⓞ
△Smythe John
140 Redlich Ida R Mrs ⓞ
142 Fries Raymond H
144 Vogl John W
148 Meyer Caroline A ⓞ
Koeppen Anna K Mrs
152△Bickelman Geo ⓞ
Peters Harvey
rear Hoffman Geo

GOODYEAR AV — From 1432 Broadway north to 1123 E Ferry
12△Ryba Vincent sausage mfr
16 Boryszewski Casper ⓞ
17 Ruminski Casmer
Cwiklinski John A
18 Nataline Sophie Mrs
19 Flisowski Thos
Brodzinski Adam ⓞ
Olejniczak Lawrence F
22 Greklikowski John ⓞ
23 Kopryanski Louis
Kramer Chas P
24 Muchowski Geo ⓞ
25 Anuslewicz John ⓞ
Gawryszewski Leo N
Rogacki Felix F
28 Koperski Jos E ⓞ
Kasmark Wm
29 Zaganiaczyk Stanley ⓞ
31 Swiecicki Stanley ⓞ
32 Myszkiewicz Mary Mrs ⓞ
33 Barczykowski Raymond ⓞ
34 Kryczka Walter ⓞ
Sierocinski Pauline Mrs
35 Pietraszak Steph ⓞ
36 Dembinski Theresa Mrs ⓞ
39 Bartel Mary A Mrs ⓞ
Bartel Stanley
40 Skrok Anthony ⓞ
Andrzejewski Frank
41 Ptak Jos ⓞ
Westover Wm E
42 Twitchell Geo B ⓞ
45 Witkowski Frances Mrs ⓞ
Zielinski Pearl Mrs
46 Ognlewski Walter ⓞ
48 Prusak Frank ⓞ
49 Jendrasiak Mary Mrs ⓞ
Wojtusiak Vincent
52 Jasinski Frank ⓞ barber
Muszynski Martin
53 Dubiel Anna Mrs
Glowacki Teofil
54△Huebner Bertha ⓞ
55 Marszalewski Teofila Mrs
Cholasinski Louis
Bronicki Anthony J ⓞ
57 Lokcynski Jos ⓞ
58 Vacant store
△Lica Stanley J paperhngr
59 Laszcz Stanley barber
Empire intersects
85 Bucholtz Steph A
87 Kurek Boleslaw B
88 Marcinkowski Mary Mrs ⓞ
Jeroszewski Stanley
90 Wujek Bronislaus T ⓞ
92 Bartczak Stanley ⓞ
95 Hojnacki Mary Mrs ⓞ
98 Lyszynski Leon J
Pokora Jacob
Kurowski Jos
99 Kurowski Josephine Mrs ⓞ
Browarek Henry O
101 Nasilowski John ⓞ gro
102 Bittner Sophia Mrs ⓞ
Walczak Walter O
rear Zakrzewski Stanley S
103 Krayna Valentine
104 Foldt Louis J
Markwa Jos
Stobnicki Anna ⓞ
106 Dolka Steph ⓞ
Puchalski Stanley
107 Basinski Wm
Klamborowski Constantine
108 Zaremba Edmund J ⓞ
109 Jakubik Bronislaus ⓞ
111 Orzechowski Stanley ⓞ
113 Zulawski Valentine ⓞ
Felski Veronica Mrs ⓞ
114 Lisiea John ⓞ
Budny Ludwig
116 Utecht Anthony
Surdam Howard L
119 Muszynski Stella Mrs ⓞ
120 Cuzner Fredk
Drzewiecki Frank
121 Pilarski Frank M ⓞ
Pinlarski Frank
122△Stapf Eliz Mrs ⓞ
△Stapf Emil
125 Gabrykiewicz Agnes Mrs ⓞ
Kruszynski Anthony
126 Ruteski Jos A ⓞ
Wisniewski Jos V
127 Arent Boleslaus ⓞ
128 Bartycki Frances Mrs ⓞ
Michalek John
131 Biedrzycki Frank
132 Ziolkowski Julia ⓞ
Utecht Frank J
133 Bensching Chas N
134 Misnik Adam B
Maciejewski Max H
West Shore RR crosses
158△Zrams Lawrence J ⓞ
Jakubowski John
160 Czarnecki Theo ⓞ
Jurewicz Frank
164 Kocol Anthony ⓞ
Brzyski Stanley
168 Klein Wm J
Tuliszewski Frances Mrs ⓞ
170 Siejakowski Casimer
Olszewski Stanley ⓞ
171 Owczarkowski Frank ⓞ
Matuszewski Steph
172 Skubinski Casimir
173 Mruk Cath Mrs ⓞ
Neumeister Paul A

1935 MICHIGAN AVE

SOURCE: POLKS



917△Sherlock Eug J
918 Buono Louis J
Llacos Theo
rear Pierce John J
Skinner Jas E
920 Perna John J
Del Bosco Rose Mrs
921△Scherer Aug C Ⓓ
Beckerle Anna
Stelley Robt
O'Shea Jos
922△Puerner Marst R Mrs
Hoshal Chas R
924 Haverty John
925△Schaefer Al H Ⓓ
927 Elsinghorst Frances M Ⓓ
Wahlenmaver Mina Mrs
928 Imhof Anna Mrs
930△Heiss Valentine
931 Albrecht Gottlieb G Ⓓ
Erhardt Harold C
rear Vacant
933△Haefner Geo J Ⓓ
934 Delta Chas tailor
Williams Jas V
Romanello Jos R
rear Handley Howard
Love Marst Mrs
McCarthy Jos P
936 Jochim Chas P
937 Fanaro Chas
△Seibert Philip
Bianchi Biagio
939 Camuza Anthony
McDermott Raymond E
rear Schaefer Howard J
Pollino Jos
940△Chandler Kath R Mrs Ⓓ
942△Ronk Linoleum Mfg Co
Panzer Frank J
Cook Jas
943△Weirand Wm G Ⓓ
Carlton intersects
946△Kiefer John A Ⓓ gro
948△Albrecht Gottlieb G meats
Kiefer John
948½ Kinnes Anthony barber
950 Kiefer Clara
Ulmer Fred J
952 Pude Richd A
△Cassube Theresa Mrs Ⓓ
rear Feist Mav Mrs
Schneider Walter J
955-57△Batt Co Inc plmbrs
958 Richeal Clifford R
Horton John E
rear Rauth Eva Mrs
959 Romano John Ⓓ
Romano Jos
960 Meyer John N Ⓓ
Zimmerman Aug F
961 Greinwald John
△Mason Allen L
962△Rohm Chas A Ⓓ
963 Vacant
965 Harper Clarence A
966△Wiese Maximilian G Ⓓ phys
Wiese Maximilian C
967 Thomson Walter W
968△Scheda Frank M
972△Bennick Rudolph Ⓓ
Marshall Robt
rear Hively Ross K
974△Hurst Pearl M Mrs wall paper
Hopkins Dora S Mrs
975 Kramer Marie Mrs Ⓓ
Kelley Jas L
rear Hippele Marst
Bishop Mary Mrs
Stauber Frank L
977 Wolff Erminie Ⓓ
Martorana Carl H
978 Woodcock Richd F
Small Ethel Mrs
979 Weller Clara Ⓓ
Molser Harry T
rear Haas Minnie Mrs
982 Cochran John confr
rear Hasenstab Herman
Gee Wm G
983 King Chas
Reickert Jos C
rear Ansteth Henry
984 Schneider Fredk H Ⓓ
Haueise Walter G
985 Binner Leo J
rear Ozer Aug G
986 Russo Carmello barber
Caverly Richd
Smith Danl
Mullen Dominick P
Smith Mary
987 Sperber Wm H Ⓓ
Wolf Jos J
989 Artmeier Mary M Mrs
Moreno Thos
990 Sailor Louise Mrs
Nestel Fred W
993 Cole Sarah Mrs
Merrill Chas F
rear Wimmer Revelon M
994 May Saml A
995 Weite Fred E
Everitt Albert
996 Evans Geo W
△Morzenstern Fred H Ⓓ
997△Nestel Louis J Ⓓ
Kremer Mary J Mrs
1001△White Oroba E Mrs confr
Klemp Jos H
1007 Boeckman John restr
1009△Stegner's Pharmacy
High intersects
1021 Sutton Geo E
Maynard Arth R
1023△Brock Loren E Ⓓ coal
1027 Putsbach Leonard P
1029 Blanck Clara Mrs Ⓓ
Wansart Edw M
rear Gottstein Mary
1031 Natchuras Saml
Andromidas Geo
1033△Markey Edwin C trucking
1035 Dietrich Martin Ⓓ
Adams Lawrence
1039 Eichelberger Eug
Pappas John L
1041 Kuhn Geo Ⓓ
Goodrich intersects
1043 Windisch John Ⓓ
Kline Alvin F
1044△Windisch Chas Ⓓ gro
Schack Fred G
1045 Hauck Edmund C
Colos Jas
1048 Shepard Louis
1049 Mason Claremont
Thur Chas A
1052△Holm Carl P Ⓓ
rear Holm C P & Son antique reproduction
1053 Luke Louisa Mrs Ⓓ
Ruehl Carl
1054△Holifelder Christine Mrs Ⓓ
Niemela Arvid T
1056 Hoellig Josephine Mrs Ⓓ
Burns Irene M Mrs
Sprlegel Louise Mrs
1057△Schliesel Edw Ⓓ
Heinike Henry H
1059 Ries Jos W Ⓓ
Newton Chas B
Gross Fred
1060 Koch Ida O Mrs Ⓓ
1061 Hickey Henry Ⓓ
Jackson Nellie H Mrs
1062△Leupold John G Ⓓ
1064 Kick Barbara M Mrs
Dettman Albert J
1065 Marshall Robt P pntr
1066△Lechner Geo P filling sta
1069 Fisher Anna Mrs Ⓓ
Cole Mary Mrs
1071 Row Jas E
Elleboudt Ray
North intersects
1080 Hazan John H barber
1082 Taylor Albert J ice
1083△Vogelsang Henry C Ⓓ
Weber John J
1086 Meyer John M tailor
△Wilson Geo R
Schwabe Edw
1089 Meyers Henry G
1091△Acosta Jose
△Wander Florence Mrs
1092 Nachtrieb Edw Ⓓ
1095△Levitan S Albert Ⓓ phys
1096 Heximer Eliz Mrs Ⓓ
Benbatzel Norman M
1098 Biersbach Frank
1099 Leupold Magdalene Mrs Ⓓ
△Well Baby Clinic
1100 Tiede Minnie Ⓓ
1102 Bearch Harry W
McCarthy Mary Mrs
1103△Beck Walter C
1104 DeBon Henry
△Quizel Hamil E
1105 Fleming Geo A
1106 Frank Louis Ⓓ
1107△Schwekler Anna B Mrs Ⓓ
McDermott Peter
rear O'Brien John J
1111△Funk Christine A Mrs Ⓓ
Mauer Cath Mrs
1112 Wagner Edw
Lamb Edw B
rear Chinco Geraldine M
1113 Worth Lydia A Ⓓ
1114△Rinzeman Geo A Ⓓ
Horn Louis
rear Brooks Walter L
1115 Meissner Walter H Ⓓ
1116 Honecker Louise Mrs Ⓓ
Winzenried Louise C
1117 Schlarter Norman G
△Brann Theo A
1119 Vacant
1122△Goodyear-Wende Oil Corp filling sta
Best intersects
1135 Vacant
1137△Lamm Frank restr
1137½ Lamm Frank
1139 Vacant
1141 Kuhefus Elmer J
1145△Lienert Frank J Ⓓ
1149 Springer Anna Mrs
1151 Shuman Marst
McLean Jas
1152△Dixon & Adams auto reprs
Edna pl intersects
1155 Craft Chas P
1157 Donohue Anna
1163△Fritz Eliz Mrs confr
1164 Vacant
1165△Guenther Raymond amusement devices
1166 Anker Martha M Mrs
1167 Mitchell Mattie Mrs
△Clayton Mary Mrs Ⓓ
1170△Toenfer Conrad F Ⓓ mus tchr
Schoenle Marie Mrs
1171 Archibald Chas A
Archibald Jennie Mrs
rear Hart Mary Mrs
Avery Edwin B
1172 Havens John B
Torgeson Frieda Mrs
Torgeson Alice Mrs
Zangle Jos

1935 NORTH ST E-A

SOURCE: POLKS



NORTH—Contd
North Apts—Contd
A6△Pierce R Vaughn
B1△Lehrbach Kath Mrs
B2 Thompson Andrew
B3△Peck Emerson P
B4△Georger Mary G Mrs
B5△Mallon Florence W
C1 Daniels Goodyear
C2 Vacant
C3△Breinig Granville M
C4△Patterson Thos W
Black John T interior decorator
Street continued
233 DeLancey Divinity School
237△Protestant Episcopal Diocese of Western N Y
△Church Mission of Help
Church Extension Society (Protestant Episcopal)
Meister Jacob
Mariner intersects
sw cor Church of the Messiah
245△Y W C A (residence)
249△Meyer Jennie M Mrs Ⓓ
rear Whalen Geo A
252△Evans Marst E Mrs Ⓓ
255△Young Mary R Mrs
rear Smith Virginia
Vacant
256△O'Brien Roland L
259 Osborn Adelaide M
rear Perry Leslie W
College intersects
267△Stewart Woodford T Ⓓ
268△Corcoran Mary G sanitarium
274△Will Wm E Ⓓ OS pract
Will Lillie Mrs OS pract
279△Underhill Augustus P
282△North Gables Apartments
△Jenkins Stanley S
290 Two-Ninety North Apartments
Apartments:
11 Mullen Florence R
12△LaRowe Frank F
13 Moore Robt J
14△Chambers M Eliz nurse
21 Meyer Emma
22 Snyder Jessie A nurse
23△Fitts Florence
24 Deck Barbara E Mrs
31 Vacant
32△Valaer Jean
33△Oliver Frank J
34△Raffauf Ella C
41△Werner Geo W
42△Campbell Edw O
43△Hanlon Donald F
44 Wilson Vela A Mrs
Street continued
291△Navlon Henry M Ⓓ
Murray Wm J
292△Hotel Wardman
Ward Clara Mrs
Arlington pl intersects
303△Sisters of Mercy
304 Smith Gertrude Mrs
309△Rogers Wm A Ⓓ
310△Coolon Rosa Jewish Old Folks Home
Perlman Simon
NORTH E—From 1039 Main east to 354 Herman av
3 Vacant
5 Schad Chas W
6 Haefner Elmer
△Haefner Frank N
7 Buscarlia Santo shoe repr
Carmody Patk J
Krause Hortense A M
9 Schroeder Eliz Mrs
11 Vetter John P
Sturm Francis W
13 Lange Herman C contr
Lange Fred W contr
Keller Henry K
14 Rushl Geo barber
16 Hoerbelt & Bush antiques
22△Boucher Frank P
23△Poling Wilson
Kilzore Mae
25△Wendel Martha H Mrs Ⓓ
26 Vacant
27△Wittholz Otto C Ⓓ
Nakatani Riyo
28 Fisher John G auto pntr
△Roberts Nash Service
△Buffalo Cylinder Grinding Co
31 Featherly Albert J
33 Doyle Anna nurse
Kerseaou Wm
35 Pratt Lena Mrs
36△Smith Marvin R taxi service
△Chase Carrie B Mrs
37 Metz V J & Son bldg contrs
39 O'Connor Cath
40△Gorman Jas P
41-43 Apartments
1 Hughes Thos J
2 Bell Henry A
3 Clement Leopold
4△DerChene Erma V Mrs
Street continued
42 Harrington Michl F
Winter Geo J
48-50 Vacant
Ellicott intersects
52-54△Winter Bros Co bottlers
Oxford Process Corp
Oldham F B Co
61 Lehman's Meat Market
68△Guenther Chas Ⓓ
△Herold Geo
69 Zieler Otto H
Williams Annabelle Mrs
70 Strauch Edw P
Garvey Patk J Ⓓ
Muckler Andrew
Taylor Alf
71△Danforth Willard J Ⓓ chiro
Barber Fred
72△Kemp Francis J
Newman Peter Ⓓ
Welmont pl intersects
75 Armstrong Clarence J Ⓓ
Bedeska Leo E
Boyd Edw J
Derrick Robt L
76 Munro Gordon gro
Klose Susan Mrs
77△Cook E A Body Corp
80 Allen Montague
81△Brogan Wm J
Black Frances W Mrs
82 Bixon Robt S
May Margt
rear Tistler Anna K Mrs
83△Bennett Daisy V Mrs
VanDyke Fredk G
84 Knopf Chas M
△Spriegel Eug A
86△Garvey Cyril P
△Garvey P J Carting & Stge Inc
Lindstrom Harold O
87 Wegferth Geo H
rear Griese Albert E
Fernandez Dora Mrs Ⓓ
89 Bising Gertrude Mrs Ⓓ
Hanley Jas K
90 Beardsley Chas M
93△Wolf Marie G Mrs Ⓓ
94 Dill Mary E Mrs
Brunner Bertha Mrs
French Fredk B
Welmont pl begins
99 Bohn John
Greene Everett J
101 Apelt Chas O Ⓓ
Brennan Margt M Mrs
rear Vanderlaan Haayo
105 Weinman Pauline Mrs Ⓓ
Kobernuss Harry A
108 Wolf John E delicatessen
Wolf Jerome M coal & ice
109△Donohue Edw J Ⓓ
110 Vacant store
Grant Leola E Mrs
Pray Earl L
Fagan Albert G
Simmons John C
111 Dolan Mary C drsmkr
Rang Henry
rear Loesch Anna Mrs
112 Schwaegler Jessie Mrs
114△Meyer John jr Ⓓ
Flynn Jane Mrs
Winegar Shirrell C
rear Beers Cath Mrs
115 Lindeman Fredk H Ⓓ
116 Butler Pauline Mrs
Werner Cordelia Mrs Ⓓ
117△Helbig Wm C Ⓓ
Nye Ethel nurse
Davis Elmer printer
118 Weigand Albert Ⓓ
rear Foley Kath
119△Fredericks Christine W Mrs Ⓓ nurse
△Hague Harriet Mrs
120 Grosskopf Chas H Ⓓ
121 Ahmler Anna Ⓓ drsmkr
△Schutz Geo L
124 Frank Jos P
Gazley Jas F
rear Tronolone Florence M Mrs
125△Pickelman Caroline Mrs florist
126△Horner Sarah E Mrs Ⓓ
Miller Arth E
127 Vacant
Elm intersects
128 Chapman Lucinda Mrs
Burr Emma
132△Becker John H Ⓓ baker
135△Simon Geo W Ⓓ
137△Sweeney Eliz Mrs Ⓓ
△Schweiger Wm J
rear Faber Frank
140△Chiaramonte Jos C
Mason Jos N
141△Meisreimer Edw A Ⓓ
△Diller Emma B Mrs
142 Pezolt Anna J Mrs Ⓓ
145△Green Victoria L Mrs Ⓓ
146 Volker Wm A tailor
148 Haas Fredk
149△Groeschel Wm L Ⓓ
△Weber Chas F
150△Haas Norman G Ⓓ
152△Burkhardt John C
153 Rohs Mary Ⓓ
△Tripp Ira J
157 Gillott Arth J Ⓓ
Quigley Frank J
158 Hanna Elmo T
Barrow Robt J
160 Rohrbach Conrad Ⓓ
Kreps Henry S
164 Blight E Bertram drugs
△Jauch Edwin C dentist
△Schaefer Norbert B phys
Michigan av intersects
174△Guenther Wm restr
177 Westcott Wm M Ⓓ
178△Vogelsang Gregory Ⓓ
179 Waters Arth M
Maple ends
180 Keller Marst Mrs Ⓓ
182△Maul Andrew A Ⓓ
197 Crawford Matthew J
Abell Roscoe C
199△Pestell Florence Mrs
△Diehl Carrie Mrs

1935 **NORTH ST E-B**

SOURCE: POLKS



70 Strauch Edw P
Garvey Patk J ⓓ
Muckler Andrew
Taylor Alf
71△Danforth Willard J ⓓ chiro
Barber Fred
72△Kemp Francis J
Newman Peter ⓓ
Welmont pl intersects
73 Armstrong Clarence J ⓓ
Bedeska Leo E
Boyd Edw J
Derrick Robt L
76 Munro Gordon gro
Klose Susan Mrs
77△Cook E A Body Corp
80 Allen Montague
81△Brogan Wm J
Black Frances W Mrs
82 Bixin Robt S
May Margt
rear Tistler Anna K Mrs
83△Bennett Daisy V Mrs
VanDyke Fredk G
84 Knopf Chas M
△Spriegel Eug A
86△Garvey Cyril P
△Garvey P J Carting & Stge Inc
Lindstrom Harold O
87 Wegferth Geo H
rear Griese Albert E
Fernandez Dora Mrs ⓓ
89 Bissing Gertrude Mrs ⓓ
Hanley Jas K
90 Beardsley Chas M
93△Wolf Marie G Mrs ⓓ
94 Dill Mary E Mrs
Brunner Bertha Mrs
French Fredk B
Welmont pl begins
99 Bohn John
Greene Everett J
101 Apelt Chas O ⓓ
Brennan Margt M Mrs
rear Vanderlaan Haayo
105 Weinman Pauline Mrs ⓓ
Kobernuss Harry A
108 Wolf John E delicatessen
Wolf Jerome M coal & ice
109△Donohue Edw J ⓓ
110 Vacant store
Grant Leola E Mrs
Pray Earl L
Fagan Albert G
Simmons John O
111 Dolan Mary C drsmkr
Rang Henry
rear Loesch Anna Mrs
112 Schwaegler Jessie Mrs
114△Meyer John jr ⓓ
Flynn Jane Mrs
Winegar Shirrell C
rear Beers Cath Mrs
115 Lindeman Fredk H ⓓ
116 Butler Pauline Mrs
Warner Cordelia Mrs ⓓ
117△Helbig Wm C ⓓ
Nye Ethel nurse
Davis Elmer printer
118 Weigand Albert ⓓ
rear Foley Kath
119△Fredericks Christine W Mrs ⓓ nurse
△Hague Harriet Mrs
120 Grosskopf Chas H ⓓ
121 Ahmler Anna ⓓ drsmkr
△Schutz Geo L
124 Frank Jos P
Gazley Jas F
rear Trondone Florence M Mrs
125△Pickelman Caroline Mrs florist
126△Horner Sarah E Mrs ⓓ
Miller Arth E
127 Vacant
Elm intersects
128 Chapman Lucinda Mrs
Burr Emma
132△Becker John H ⓓ baker
135△Simon Geo W ⓓ
137△Sweeney Eliz Mrs ⓓ
△Schweiger Wm J
rear Faber Frank
140△Chiaramonte Jos C
Mason Jos N
141△Meisreimer Edw A ⓓ
△Diller Emma B Mrs
142 Pezolt Anna J Mrs ⓓ
145△Green Victoria L Mrs ⓓ
146 Volker Wm A tailor
148 Haas Fredk
149△Groeschel Wm L ⓓ
△Weber Chas F
150△Haas Norman G ⓓ
152△Burkhardt John C
153 Rohs Mary ⓓ
△Tripp Ira J
157 Gillott Arth J ⓓ
Quigley Frank J
158 Hanna Elmo T
Barrow Robt J
160 Rohrbach Conrad ⓓ
Kreps Henry S
164 Blight E Bertram drugs
△Jauch Edwin C dentist
△Schaefer Norbert B phys
Michigan av intersects
174△Guenther Wm restr
177 Westcott Wm M ⓓ
178△Vogelsang Gregory ⓓ
179 Waters Arth M
Maple ends
180 Keller Margt Mrs ⓓ
182△Maul Andrew A ⓓ
197 Crawford Matthew J
Abell Roscoe C
199△Pestell Florence Mrs
△Diehl Carrie Mrs
203 Moritz Gregory A
Derschug Valentine J
207 Mayer Leonard J
209 Tague John C
213 Gauger Wm ice
215△Kramer Walter D delicatessen
Izydorczak Helen Mrs
Mulberry ends
223△Snabon Michl
Casper Marvin P
225△Nagel Raymond H ⓓ
Arhart Charlotte M Mrs
227△Stoll Albert A ⓓ
229 Ulrich Michl J ⓓ
Broderick Jos V
rear△Lange Henry G
cor Fosdick-Masten Park High School
Masten Park
Masten intersects
237 Masten Park Baptist Church
Locust ends
249 Vogel Anthony
253△Oswald Mary Mrs
Sauer Esther I Mrs
257△Batt Minnie Mrs ⓓ
Dukesbury Chas A
261 Monroe Jas G
△Young Geo J coal
263△Koch John P ⓓ
265 Vacant store
Alonzo Ralph R
Stevenson Geo H
Vereeck Martha Mrs
Doellinger Peter J
Lemon ends
275 Hayslip Geo A
Barenbaler Frank L
277△Dentinger Philip J jr ⓓ
283 Wollenberg John ⓓ
285△Pfrang Kath ⓓ
Dietsch Robt J
287△Rosche Henry J ⓓ
291△Schabtach Albert J ⓓ
△Diefenbach Wm C
Orange ends
301△Welchsel John ⓓ
Grant Edw H
307 Mueller John ⓓ & Mrs
Smith Rosanna Mrs
Shaw Margt L Mrs
309 Wilke Gustave ⓓ
314△Roetzer Jos M ⓓ
316 Neubeck Chauncey
320 Vacant store
Miller Anna Mrs
Schalk Aubrey W
Conway Henry A
322 Scibetta Jas A
Pusateri Nicholas
Cook Josephine Mrs
Peach intersects
330△Mefligan Thos confr
332 **Apartments**
1 Scibetta Chas
2 Wassinger Jos W
3 **Vacant**
4 Beigel Anna C Mrs
5 Scibetta Jas
Street continued
333 Fischer Wm F ⓓ
336△Cooper Chas W ⓓ
338 Moritz Agnes Mrs ⓓ
341-43 Koch Jacob ⓓ gro
342 Desmond Chas
△Schnell Wm J
343 Milbrandt Jos J
346△Russ Jos ⓓ
Moeller Kenneth
348 Gross Edw J ⓓ
Wolf Edw
350 Mirabelli Frank milk
Grape intersects
353 Hooper Jas W
Pagel Henry M
355△Clark Asa G ⓓ
356 Vacant store
Sampson John G
△Vario Nicholas ⓓ
358 Welham Percy H ⓓ
359 Burgard Mary Mrs
Griesbaum Mary Mrs
360 Sturges John J ⓓ
361△Dirnberger Cath M ⓓ
Human Caroline
362 Endres Henry C ⓓ
363-65 Ulrich & Co metal polishes
Rose intersects
368△Kreinbring Chas ⓓ
Oehler Geo F
Sengbusch Herbert
370 Reitz Albert F
372 Mersdorf Chas E
Steinka Anna Mrs
383 Backus Jacob P
Spiegel Henry
Jefferson intersects
Unopened to Timon
Timon intersects
505 Nichen Eugenia Mrs
Holmes Andrew R
rear Timmons Edw
507 Pichtel Jos
Walter Otto
509△Mohr Martin B ⓓ
Miller Kath A
511 Haitzman Mary A Mrs ⓓ
Mugle Otto
513 Neurhor Jos G
Steinkirchner Louis A
515 Ross Helen Mrs
Hirsch Dominic ⓓ
Johnson intersects
542△Schlager Louis meats
Reichert Alf W
Brown Grace P

1930 **BEST ST-A**

SOURCE: POLKS

BERKSHIRE AV—Contd
538 Koehler Lawrence H ⓓ
542 Lysitt Maybelle Mrs ⓓ
Westminster intersects

BERRICK ALLEY—From 142 Seneca, north to Swan
(No houses)

BERTHA—From 640 Abbott rd, north to Buffalo Creek
1 Wisniewski Frank ⓓ
3 Wahl Aug
5 Bis Walter
7 Bruckman Geo
9 Schuster Matthew house mover
Gilner Frank
11 Heck Albert ⓓ
15 Bondaruk Thos
17 Matwiikow Nicholas ⓓ
Buffalo Creek crosses

BERWYN AV—From 391 Olympic av, east to Bailey av
11 Farber Raymond N
14 Bilz Geo ⓓ
15 Gosney Jos R ⓓ
16 Winans Stanley ⓓ
19 Lambour Chas X ⓓ
20 Fullington G Lucene ⓓ
21 Dorscheid Jacob ⓓ
22 Beuthel Edw J ⓓ
25 Keenan Patk A
26 Andrew Thos ⓓ
29 Kline Chas J ⓓ
30 Cook Jas C ⓓ
31 Jennings Minnie Mrs ⓓ
32 Douglas Joyce
35 Goehm Fredk
36 Kogler Emil C ⓓ
38 Kuechle Fredk J ⓓ
39 Meinke Carl ⓓ
41 Kumpf Lewis G ⓓ
42 Cramer Albert R ⓓ
45 Cothard Harry W ⓓ
46 Braun Philip ⓓ
47 Thompson Harrison ⓓ
50 Calkins Sami R ⓓ
51 Foley Eug F ⓓ trucking
52 Banhalzl Andrew L ⓓ
53 O'Brian Jos V ⓓ
54 Kinmartin Simon F ⓓ
57 Rachow John H ⓓ
58 Lee Howard L ⓓ trucking
61 Hise Alf G ⓓ
62 Conrad Harry S ⓓ
63 Ott Harry F ⓓ
64 Munt Edgar E ⓓ
67 Schlau Peter M ⓓ
68 Herman Albert ⓓ
69 Beilzard Jos ⓓ
72 Zimmerman Irva ⓓ
73 Haslow Raymond G
Fechter Eug G
Brophy Jas A
74 Weiss Orville F ⓓ
77 Morrison Wm E ⓓ
78 Gibson Chas ⓓ
79 Heller Fredk ⓓ
80 Euller Geo M
83 Foisset Jos E ⓓ
84 Schlazer Geo
85 Zimmerman Norman R ⓓ
88 Jones Alton A ⓓ
89 Walter Jos G ⓓ
90 Lesso Albert J
93 Muther Anthony A
94 Drescher Casper J ⓓ
95 Cook Chas W ⓓ elec contr
96 Drescher Edwin H ⓓ
99 Scott Orlando P ⓓ
100 McElroy John A ⓓ
101 Coon Benj H ⓓ
102 Heriofson Thos ⓓ
105 Folmer Andrew J ⓓ
106 Klinzelmeier Henry E ⓓ
109 Dunning Frank J ⓓ
110 Taylor Arth H ⓓ

BEST—From 1119 Main, east to 1132 Genesee
4-16 Best Apartments
Apartments:
1 Vacant
2 Baker Margt
3 Vacant
4 Vacant
5 Vacant
11 Brossman Martha E nurse
12 Dwyer Alice E
13 Teausaw Laura
14 Watson Willard H
15 Rice Mae
20 Calts Lucille
21 Froel Mary Mrs
22 Ferguson Margt
23 Crane Dorothy
24 Alborg Mary
25 Vacant
26 Bouzas Geo H
27 Hill Harry J
28 Wheeler Edw F
29 Fenno Bertha
30 Vacant
31 Kiefer Gerald L
32 McFarland Anna
33 McCabe Florence
34 Burd Helen
35 Vacant
36 Devlin Fred J
37 Vacant
38 Vacant
39 McFoul Wm
Street continued
17 Romer Jos
18 Williams Albert F
19 Kelow Thos J
21 Groh Fred J
rear Norris Frances Mrs
22 Strasser Geo A ⓓ
25 Koehler Geo B
Downs Thos
26 Burke Martha Mrs ⓓ
Steller Danl L
29 Stecher Fred
Reimann Benj ⓓ
Zavits Robt
30 Furst Marie Mrs
Smith Chas
31 Sanders Irvin
32 Lang Francis J
McVicker Margt
rear Leary Margt ⓓ
Spang Arth
Spang Gertrude Mrs nurse
33 Seereiter Cath Mrs ⓓ
35 Miller Julius B
36 Decker Jennie Mrs
Wolf Henry ⓓ
38 Ward Eusebius C exp
O'Gara John
41 Logel Edw W
43 Klein Mary Mrs ⓓ
44 Rittling John J ⓓ
Forester Eug
rear Woodward Orin L
45 Brann Wm
46 Duquin Arnold J
Miller Fred
50 Taylor Alex ⓓ
Colin Jas E
rear Metz Frank W
51 Loos Walter
52 Walker Frieda Mrs
53 Casper Martin soft drinks
Jacobs Harriet Mrs
56 Radel Frank gro
Ellicott intersects
65 Szak Dorothy Mrs restr
67 Stevens John H
68 Wynot Louis W clo clnr
Michalski Frank
69 Chaplin John P
70 Zimmer Frank A
71 LaRusch John
Wagner Anna Mrs
72 Helfrich Geo M ⓓ
73 Schmidt Edw
74 Klein Kath Mrs
Griffin Francis E
75 Saabye Wigo H
Garbe Harry H
76 Vacant
Welmont intersects
79 Frank & Miller Inc plmbrs
Baumgarten Anna M Mrs
80 Steller Conrad baker
86 Casper Frank J
McClimont Jas F
88 Helbing John P
Woodall Helena Mrs
90 Winter Henry A ⓓ
93 Beckerle Jos A
Welmont pl intersects
94 Scheffler Henry H ⓓ
95 Winter Anna Mrs
96 Diersen Josephine ⓓ
97 Collett Harold E
Schmidt Edw W
98 Crocker Frank
Garbutt Elmer
Shisler A C
102 Fisher Margt Mrs
Rahn Augusta ⓓ
103 Taylor Jesse M
Wagner Chas B
104 Kauta Henrietta
Porter Harry H
rear Trapp Jos
105 Schmidt Gustav contr
Seebald Margt
rear Trautman Walter
108 Irr Elis Mrs
Shaddock Wm E
111 Gilroy Wm J
112 Bray Wm F ⓓ
113 Burg Marie
115 Clare Gertrude Mrs beauty shop
Clare Henry P
Stidinger Karl
116 Peard Richd T
117 Fleming Seymour N
Reazan John J
Gerlach Caroline Mrs
Elm intersects

1930 BEST ST-B

SOURCE: POLKS

29 Fenno Bertha
30 Vacant
31 Kiefer Gerald L
32 McFarland Anna
33 McCabe Florence
34 Burd Helen
35 Vacant
36 Devlin Fred J
37 Vacant
38 Vacant
39 McFoul Wm
Street continued
17 Romer Jos
18 Williams Albert F
19 Kelow Thos J
21 Groh Fred J
rear Norris Frances Mrs
22 Strasser Geo A
25 Koehler Geo B
Downs Thos
26 Burke Martha Mrs
Steller Danl L
29 Stecher Fred
Reimann Benj
Zavitz Robt
30 Furst Marie Mrs
Smith Chas
31 Sanders Irvin
32 Lang Francis J
McVicker Margt
rear Leary Margt
Spang Arth
Spang Gertrude Mrs nurse
33 Seereiter Cath Mrs
35 Miller Julius B
36 Decker Jennie Mrs
Wolf Henry
38 Ward Eusebius C exp
O'Gara John
41 Logel Edw W
43 Klein Mary Mrs
44 Rittling John J
Forester Eug
rear Woodward Orin L
45 Brann Wm
46 Duquin Arnold J
Miller Fred
50 Taylor Alex
Colin Jas E
rear Metz Frank W
51 Loos Walter
52 Walker Frieda Mrs
53 Casper Martin soft drinks
Jacobs Harriet Mrs
56 Radel Frank gro
Ellicott intersects
65 Szak Dorothy Mrs restr
67 Stevens John H
68 Wynot Louis W clo cinr
Michalski Frank
69 Chaplin John P
70 Zimmer Frank A
71 LaRusch John
Wagner Anna Mrs
72 Helfrich Geo M
73 Schmidt Edw
74 Klein Kath Mrs
Griffin Francis E
75 Saabye Wiggo H
Garbe Harry H
76 Vacant
Wetmont intersects
79 Frank & Miller Inc plmbrs
Baumgarten Anna M Mrs
80 Steller Conrad baker
86 Casper Frank J
McClIment Jas F
88 Helbing John P
Woodall Helena Mrs
90 Winter Henry A
93 Beckerle Jos A
Wetmont pl intersects
94 Scheffler Henry H
95 Winter Anna Mrs
96 Diersen Josephine
97 Collett Harold E
Schmidt Edw W
98 Crocker Frank
Garbutt Elmer
Shisler A C
102 Fisher Margt Mrs
Rahn Augusta
103 Taylor Jesse M
Wagner Chas B
104 Kautz Henrietta
Porter Harry H
rear Trapp Jos
105 Schmidt Gustav contr
Seebald Margt
rear Trautman Walter
108 Irr Eliz Mrs
Shaddock Wm E
111 Gilroy Wm J
112 Bray Wm F
113 Burz Marie
115 Clare Gertrude Mrs beauty shop
Clare Henry P
Stidinger Karl
116 Peard Richd T
117 Fleming Seymour N
Reagan John J
Gerlach Caroline Mrs
Elm intersects
118 Taylor John H
120 Warner Ida Mrs
122 Ahlheim Carrie Mrs
Ahlheim Saml G
125 Commins John E gro
126 Beckett David J
127 Darrow Sarah Mrs
Dill Mary Mrs
Walters Edw
rear DeBon John coal
129 Ryan Cath Mrs
Ryan Danl L
130 Morlock Albert
Roebbig Leopold
131 Whitwell Mary
133 Wilcock Robt
LeClair David J
rear Clapp Sara M Mrs
134 Grauman Berthold
Hoffmeister Florence Mrs
135 Weis Wm H
Bingemann Eva
136 Gueth Emil
138 Boldt Chas J gro
Davis Austin
rear Cash May M Mrs
139 Quiel Ida Mrs
rear O'Hara Chas E
141 Landgraf Philip A
Kinskey Chas E
142 Mingo Thos shoe repr
144 Schwartz Chas
145 Day Thos R
147 McDonald Jos J
McDonald Marie Mrs confr
Price Albert
150 Reichlin Bros fill sta
Michigan av intersects
159 Danahy-Faxon Stores Inc gros
Johnson Jas
Sikora Frank
160 Lamm Frank F meats
161 Spaznola Jennie beauty shop
162 Bielak Helen confr
163 Drescher Luke E
King Robt T
rear Bishop Frank H
164 Batt Frank P
Batt Irving P
165 VanPatten Lester N
166 Greenberg Herman
Spoeri Frank L
rear Sydow Otto C H
Colby Wm R
167 Finkelstein Meyer
Korzie Albert L
168 Klemp Jos H
176 Ballschmeider Carl L
Mumm Fredk J
178 Orr Henry H
184 Wetter Henry S
186 Heusinger Edw J
190 Hildebrand Caroline Mrs
192 Frank Richd V
Reinig Francis
196 Balz Karl
Gehl Steph
200 Seereiter Frank J
202 Fischer John
Zernentsch Frank
Zernentsch Peter
206 Froby Harry G
Kirchner Kate Mrs
208 Fitzpatrick Edw F
Staples Mayme E Mrs
210 Dingler John H
212 Kramer Geo
216 Smyer Fredk W
Zimmerman Richd
218 Leonard Harvey
222 Kreiss Jesse G W
Schlageter Sarah Mrs
nw cor Fosdick Masten Park High Sch
Masten av intersects
311 Kooff Chas F
315 Vacant
323 Cuddeford Rhoda Mrs
Peach intersects
329 Kuss Ernest C
American Coffee Co The
Greenfield Saml
331 Dorio Nicholas
Primiano John
337 Crocoll Geo I
339 Klemenz Henry
341 Paenke John
345 Bethman Sophia Mrs
347 Fuchs Frank
Thomson Thos
Grape intersects
357 Dorio Frank
Reichert Geo
359 Schier Geo
rear Weston Clayton E
361 Dangler Cath
363 Dietzel Otto J
Glastetter John J
rear Derion Henry
Gerritz Anna Mrs
369 Horner Peter A
Werner Fred
Weihmueller John
rear Greulich Albert

1930 ELLICOTT ST

SOURCE: POLKS

ELLICOTT—Contd
731 Dietz Eug
732 Boyd Frank
Weston Wm
735 Fredericksen Carl H
rear Ritzel Frank
739 Ross Wellington M phys
741 Kronenwetter Fred
Harris Elmer
Papoas Jas
751 Parisi Jos
752 Brawn Geo W
755 Perner Mary Mrs
756 Alger Ezra D furn rms
759 Dewes Gertrude M Mrs
760 Paul Eliz U Mrs
763 Starr Inc coml photogs
Starr Walter B
766 Graesser Chas F
769 Devlin John
770 Berta Jos
Fausone Peter
771 Seyfried Louis
773 Crittenden Albert
Wilson Geo W
774 Lindner Henry P
Baker Arth
782 Beer Louis H
Speyser Ernestine Mrs
783 Wieland & Gaetz vet surgeons
Gaetz Hiram T
Robinson Eug furn rms
785 Bartlemus Herman J
788 Chaltas Thos
Deming Chas G
rear Spoth Albert A
789 Sullivan Eug
792 Kleber Louise Mrs
Walker John S
793 Turski John
Ducharme Albert
796-98 National Assn of Power Engineers
Unity Spiritualist Ch
797 Haffa Oscar J
798 Dahlquist Lillian Mrs
802 Miller Mary A Mrs
High intersects
806 Sullivan Eug fill sta
825 Nenno Jos
824 Dustin Walter
McCoy Fred
826 Froney Eliz Mrs
830 Black Frances Mrs
821 Corbin Sylvester N
834 Haefner Mary Mrs
Carver Arth
835 Gallagher Margt
Prince Ernest C
836 Pfennig Frank L
839 Vacant
840 Davis Ralph
Kelly Mary Mrs
841 Deery John P
842 Bishop Harry J
843 Aubry Jos
845 Bragg Sylvester
Goodrich intersects
854 Schlageter Alphonse M mus tchr
860 Britton Emma Mrs
863 Tuchl Mary Mrs
864 Wallasch Clara L
866 McCabe Bernard
867 Curry Grace Mrs
870 Gentilhomme Ruth M Mrs beauty shop
Gentilhomme Edw J
871 Wampach Anthony J
872 Herrick Emma Mrs
Reichlin Chas J
876 Hoffman Albert J gro
878 Garbe Chas restr
E North intersects
886 Guldner John H
Hoffmeyer Clarence W
890 Busch Edw
Early Kath S Mrs
892 Rees May Mrs
894 Guenther Wm G
Winter Andrew J
898 Keim Geo A
Knoof Chas M
Lamm Jos N
900 Hall Harriet J
Keller Jos
903 Bach R Herbert
Beck Henry J
Fisher Margt Mrs
905 Longmore Mary Mrs
Post Russell D
908 Bolt Alf J garage
Lilley Frank auto indry
Pike Theo auto repr
909 Cromwell Walter phys
913 Green John
Kirby Flora Mrs
917-19 Eckert W A Mfg Co aluminum specialties
StPaul intersects
931-35 StPaul Auto Repair Shop
938 Kerra Bros auto repr
Best intersects
963 Standard Auto Top Co
Lownie & Co tires
964 Hauck Edmund C auto accessories
966 Schwab Fred sheet metalwks
969 Gates Mary Mrs
970 McNamara Jos
rear Etheridge Mary Mrs
971 Faxon Roy
McCoy Harry J
972 Charrette Frank
rear Weimer Francis
973 Bartlett Fred P
Davis Suzanne Mrs
976 Katoll Arth O
977 Shea Anna
978 Katoll Arth O florist
979 Tonge John W
Edna pl intersects
980-86 Brunn & Co auto bodies
990 Parent Chas
991 Clark Fredk A
Clark Wm E
Sillaway Chas
993 Kreller Edw H
Batt Clarence C
994 Allox Mary Mrs
DeMarie Michl
rear Hoffmann Paul
996 Machbolz John
Morrison Frank A
997 Amann Raymond T
998 Buxton Luther D
Potter Jules H
rear Jacobs Geo D
1000 **Apartments**
1 McFarland Geo
2 Suter Edw C
3 Meyer Caroline M Mrs
Street continued
1001 Paul Frank L
Paul Harry F
Spergel Adolph G
Hickey Nelson M
1002 **Apartments**
1 Mulligan Martin
2 Trent Harry C
3 Bundy Ralph A
4 Rano Laura Mrs
5 Welshofer Chas L
6 Evans Frank R
Street continued
1006 Biesinger Frank G barber
1007 Calvary Evang Lutheran Ch
1010 Gaskill Varney E
Dodge intersects
1031 Mueller Oscar
1032 Hettrich Auto Electric Service
1033 Knox John S
1034 Clark Isaac
1035 Hauk Oscar
1036 Reiss Frank H
Heinike Henry H
1037 Ullmer Henry A mus tchr
1040 Schubert Clement P
1041 Rick Edw A
Wischerath Henry M
1042 Schubert Frank C
1044 Gastel John
Coe pl intersects
1045 Norton Geo E
Pettis Earl H
1047 Foster Christina Mrs
Gepp Harold C
Southampton intersects
1050 Steel Amos W
1054 Boore Ada Mrs
1056 Buckley John J
1059 Peckham Glenn E
Boore Ida Mrs
1060 Holch Cath Mrs
1061 Marley Mary
Sullivan Michl J
1062 Minsterman Frank A
1063 McCarthy John
Flaherty Margt nurse
1066 Diebolt Andrew G
1067 Knoll John G MD
Strong Lyman J MD
1069 Klein Henry L
1070 Mauerman Theo H
Jacus Allen
Williams Edna Mrs
Northampton intersects
1072 Vacant
1093 Orr Clifford R phys
1094 Good Clyde E chiro
Guenther Fredk C
1097 Ritter Chas J
1098 Grimm Rose Mrs
1101 Guenther Harry V
MacArthur Frank B
1102 Dolan Henry T
1105 Marchand Clara M Mrs
Hedstrom Raymond F
1106 Batt Anthony
Reid Robt B
1109 Reimondo Sylvia Mrs
1110 Jehle Fred W
1113 Cameron Geo S
1114 Bergtold Helen E nurse
Rourke Fannie M Mrs

1930 GOODRICH ST

SOURCE: POLKS

168 Pax Frances Mrs
Pax Irene beauty shop
170 Pax Henry wall paper
172 Lux Michl J undtkr
Michigan av intersects
180 Buffalo Assn for the Blind
184 Kobernuss Barbara Mrs
185 Stott Chas
187 Dietzel Henry A
Kuhn E Roland
189 Fenton Kath Mrs
191 Miles Albert W
Blencowe Alf
197 White Albert
White Jas D
Ossing Herman
Maple intersects
205 Neuman Alex
Allgrim Louis C
Yax Rose Mrs
Simon Wm
206 Stoesser Geo F gro
207 Gerlach Wm C
Demerly Wm A
208 Wendling Frank E
210 Zillig Matthew
Hubbard Leonard
211 Fries Chas J
Bolton Mary Mrs
213 Beyer John M
Howard May
Howard Lorene nurse
rear Webb Wm P
214 Huber Adolph E
rear Zuber G Bertrand
215 Sauter Geo A
rear VonDobschuetz Kurt
216 Kaiser Chas
219 Shields Wm
Weiss Emma Mrs dancing tchr
220 Kempker Henry J
rear Matt Jacob
222 Janulewicz Martha Mrs
Fitzgibbon Wm
223 Wischerath Albert P fill sta
224 Arhart Charlotte confr
Arhart Edw N
Sheele Edw M
Mulberry intersects
232 Stanton Hattie Mrs
Meyers Wm
238 Marx Anna Mrs delicatessen
Johnson Harry
rear McNerney Howard E
240 Brauer Chas R
242 Vacant
244 Miller Jacob fill sta
Burke Albert

GOODLIFFE—From 69 Hopkins east to inner lot

GOODRICH — From 1005 Main east to 1044 Michigan av
15 Mullett Edw auto repr
25 University of Buffalo School of Dentistry
26-28 Sturtzer & Co Inc auto reprs
Triplex Safety Glass Co of Buffalo
27 Roddy Jos furn rms
30 Peerless Laundry
33 Howley Mary C
Leonard Edwin
35 Deckop Bros Inc service sta equipment
40 Johnson Jessie Mrs
rear Lynex Alf J
41 Wipperman & Hoffmeyer batteries
43 Harris Harriet J Mrs
44 Mingen Frank
Williams Lloyd massage
Ellicott intersects
66 Rowley Anna C Mrs
68 Murphy Michl
Coumont Leopold
Stuart Bertha
70 Bork Frank R
O'Neil Agnes
71 Burkard Eliz Mrs furn rms
72 Jones Howard W
Howe Albert R polish mfr
73 Nachtrieb Lillian M
Dittman Albert
rear Kiesel Amelia nurse
74 Kilgore Mae
Potter Hattie E Mrs
rear Vacant
75 Hoffmann Jos
81 Armstrong John
82 Wood John H
Goltz Anna Mrs
82½ Shafto Alice G Mrs
Grant Wm A
83 Coddington Adelbert
Simonds Cortes V
84 Pech Josephine Mrs
86 Frost Eliz
Scholz Geo
88 Kiefer Anna
90 Leuze Evangeline mus tchr
Leuze Henry
Hoops Wm B
92 Dreger Mary Mrs
Duly Lily nurse
100 Harrington Hosp for Children
112 Buffalo Genl Hosp Nurses Home
Elm intersects
131 Stewart Margt Mrs
Roberts Iva nurse
McKinnon Lillian nurse
Stratton Marion nurse
134 Smith Chas O
Schlabitz Fred jr
140 Frank Ida Mrs
142 Vogl John
144 Fries Raymond
148 Meyer John
Koeppen Anna Mrs
152 Bickelman Geo
Fix Chas A
154 Bickelman John E radio sets
Zittel Albert

GOODYEAR AV — From 1432 Broadway north to 1123 E Ferry
12 Ryba Vincent meats
16 Boroszewski Casper
17 Stranc Frank
Rutkowski Anthony
18 Nataline Saml
19 Brodzinski Adam
Olejniczak Lawrence F
22 Grezijkowski John
23 Nowak Stanley
Schultz Andrew
24 Muchowski Adalbert
25 Anusiewicz Benedicta Mrs
Gabryszewski Leon
28 Dobrzynski Mary Mrs
Doberstein Frank
29 Zaganiaczyk Stanley
31 Kozerski Ignatz
32 Glowacki Mary Mrs
Zgoda Frank
33 Smolarek Jos
34 Kryczka Walter
Rieger Edw
35 Pietraszak Steph
36 Dembinski Teresa Mrs
39 Bartel Louis
40 Skrok Anthony
Raczynski Andrew
41 Pokora Jacob
Ptak Jos
42 Twitchell Geo
45 Witkowski Frances Mrs
Zielinski Thos
46 Ogniewski Walter
48 Prusak Frank
49 Jedrasiak Mary Mrs
52 Jasinski Frank
Dorociak John
53 Dubiel John
Szeluga Anthony
Klein Frank
54 Huebner Bertha T
55 Marszelewski Tillie Mrs
Braniecki Anthony
57 Lokcynski Jos
58 Niech Michl gro
Jackowski Anthony
59 Golebiewski Felix C barber
Empire intersects
85 Frankowski Felix
88 Marcinkowski Mary Mrs
Grominski Michl
89 Kurek Bolesiaus B
90 Wujek Bronislaus
Mortek John
92 Bartczak Stanley
95 Hojnacki Mary Mrs
Smol Frank X
98 Lyczynski Leon
Jarzyniecki John
Balczerzak Steph
99 Kurowski Josephine Mrs
101 Nasilowski John gro
102 Walczak Walter
Bittner Sophie Mrs
103 Mikstacki Frank
Switala Leonard A
104 Stobnicki Anna Mrs
Glowacki Thaddeus
Kawalerowski John
106 Dolka Steph
Grzechowiak Steph
107 Nowakowski Wm
Gorski Thos
108 Zaremba Edmund J
109 Jakubik Bronislaus
111 Orzechowski Stanley
113 Zulawski Valentine
Jazdzewski Frank
114 Lisica John
Nowicki Adam J
116 Darlak Frank
Utecht Frank
119 Muszynski Stella Mrs
Muszynski Vincent
120 Kozlowski Walter
Kotlarek Wm

1930 MICHIGAN AVE-A

SOURCE: POLKS

866 Burk Martin
Burk Elsie Mrs music tchr
Brumm Aug C
869 Buddenhagen Edw H
VanAllen Wm W
870 Vacant
872 Tartaglino Angelo
Xigges Gustav
873 Wood Wm J
874 Gohn Lloyd trucking
Wirges Anna Mrs
875 DiDio Oresto tailor
Blando Carmine
Alessi Chas
Mayer Marie Mrs
876 Ball Henry J
Smith Frank
877 Graff John confr
879 Ursbel John
Schimmer Frank
rear Coggins Bert
880 Matthew Perry E
May Guy
881 Lang Grace M Mrs
882 Lauer Eug V tire repr
Vlasich Vincent
Kadi Jos soft drinks
Virginia intersects
883 Tiede Wm
884 Zier Geo A meats
885 Danahy-Faxon Stores Inc
886 Alford Eliz
Anderson Alf J
888 Burgstahler Louise Mrs
Hasselbeck Mary Mrs dressmkr
889 Liotti Paul shoe repr
Dolan Dani
Roberts Stanley
891 Clergy Steph J
Croakman Fred
892 Taylor Geo E
893 Geisenhof Adela
894 Bentz Henry G phys
895 Moest Wm
898 Graham T Martin
Brown David J
899 Baum Sylvester
Lally Thos J
900 Hilin Grover
Dobmeier Carl
901 Boyd Minnie Mrs
904 Cressy Chester L
Bates Ray B
905 Nicastro Anthony
Trainer Mary Mrs
906 Bitterman Jos C
Britton Frank H
907 Sims Edmund
908 Waldman John M
McDonald Anne Mrs
Bourie Wm
909 Blando Jos
Scholl Ursula Mrs
912 Burau Louise Mrs
Brown Frank R
George Fred
913 Metz Kath
Sonnekalb Chas
914 Grampp Fred
McFaul Thos
Carney John G
917 Bennett Leo S
918 Schultz Robt
Stendts Fred
920 Biegel Anna C Mrs
Delbosco Rose Mrs
921 Scherer Aug
rear O'Shea John J
Beckerle Anna E
Webster Danl
922 Perna Frank jr fruits
Perna Rose V Mrs
924 Pappas Geo
Russell Percy
925 Schaefer Aloys H
927 Elsinghorst Anthon
Vanderlinden Geo
928 Wolf Matilda
930 Harman Robt
931 Albrecht Gottlieb
rear Erhardt Harold
933 Haefner Geo J
934 Denny Mildred Mrs beauty shop
rear Roykouff Otto
Lindemann Richd
Hauber Carl
Komrek Steph
936 Jochim Chas P
937 Castiglia Biagio
Castiglia Chas
Seibert Philip
939 MacDermott Raymond E
rear Pollino Jos
940 Chandler Kathryn Mrs
Chandler Mabel E mus tchr
942 Vacant
943 Weigand Wm G
Carlton intersects
946 Kiefer & Weckerle gros
Kiefer John A
948 Albrecht Gottlieb meats
Kippes Anthony barber
950 Liebrecht Carl
Ulmer Fred
952 Cassube Theresa Mrs
Weber Louis
rear Feist May B Mrs
Garry Michl
955-57 Batt Co Inc plmbrs
958 Kennedy Francis
Anderson Geo C
rear Rauth Bernard
959 Romano John
Romano Jos
960 Meyer John N
Zimmerman Aug F
961 Smitherman Andrew J
Smith Orville R
962 Rehm Chas A
965 Berback Melvin
DeLong Edw
rear Marshall Robt P
966 Wiese Maxmilian C
967 Thiel Ray
968 Frank Theresa Mrs
972 Bennick Rudolph
rear Brook John
974 Tresch Clarence confr
Hopkins Edgar
975 Kramer Mary Mrs
Winter Johanna Mrs
rear Schmid Estella Mrs
Bishop Mary Mrs
977 Wolff Erminie
978 Duncan Chester
Hoffmeyer Josephine
979 Weller Clara
Molser Harry
rear Haas Minnie Mrs
982 Hasenstab Bernhard
Hasenstab Herman
rear Binner Leo
983 Kriegbaum Albert H
Reickert Jos
rear Ansteth Henry
984 Schneider Fred
Haueise Walter
985 Vielgut Fred
Ghiesen Chas
987 Sperber Wm H
Wolf Jos
989 Barrow Robt J
Klausman Wm L
990 Manno Chas J
Riedhammer Matthew
993 Johnson Wahle Electric Co
Merrill Agnes
Pfeiffer J Adam
rear Scharf Donald
994 May Saml A
Wieland Frank
995 Welte Fred
Franz Rose Mrs
996 Dreher Geo T
Morgenstern Fred H
997 Nestel Louis
Kremer Mary J Mrs
1001 White Walter C confr
1005 Hoefner John
1009 Kiefer's Pharmacy
High intersects
1021 Sutton Geo E
Blakeney Rodney M
1023 Brock Loren E
1027 Nelson Anna Mrs
1029 Blanck Aug W
rear Gottstein John P
1031 Natchuras Soterios
Alexander Steph
1033 Markey Edwin C trucking
1035 Dietrich Martin
Kaufmann Geo H
1039 Liotti Anthony
McMillan John J
1041 Kuhn Geo
Goodrich intersects
1043 Windisch John
Kline Alvin E
1044 Windisch Chas gro
Windisch Mary Mrs
Kenovan Wm K J
1045 McGuire Mary Mrs
McGuire Marguerite nurse
Schilling Henry C
1048 Schlenker Edw
1049 Koopman Laurence
Zimmer Jas E
1052 Holm Chas P antiques
Holm John E
1053 Luke Louisa Mrs
Ruehl Carl
1054 Hollfelder Christine Mrs
Niemela Arvid
1056 Hoellig Andrew
Spriegel Louise Mrs
Schryver Albert L
1057 Schiesel Edw
Schiesel Josephine Mrs
1059 Ries Jos
Lempke Agnes Mrs
1060 Koch Ida Mrs
Koch Albert E mus tchr
1061 Hickey Henry
1062 Leupold John G
1064 [illegible] Barbara Mrs
Wasmuth Anna Mrs

1930 **MICHIGAN AVE-B**

SOURCE: POLKS

MICHIGAN AV—Contd
1065 Schnick Julius
1066 Firestone Service Stores Inc (br) auto tires
1069 Fisher Anna Mrs
Singer Fred J
1071 Carberry Cath Mrs
Long Geo
North intersects
1080 Hagan John P barber
1083 Vogelsang Henry C
Wehr John J
1086 Meyer John M tailor
rear Dorshied Lawrence
1089 Meyers Henry G
1091 Ball Jacob
Schuh Emanuel
1092 Nachtrieb Edw W
1095 Probst John A
1096 Heximer Eliz Mrs
1098 French Rudolph
1099 Buffalo City Hosp Baby Clinic
Luippold Magdalena Mrs
1100 Little Thos
Tiede Mary
1102 Bearsh Augusta Mrs
Pedersen Wm
1103 Wright John
1104 Levitan Albert phys
Pederson Wm
1105 Ackerman Earl W
1106 Frank Louis
1107 Jones Ralph
Schwegler Anna B Mrs
rear O'Brien John
1111 Carrick Margt
Funk Geo
1112 Koch Ralph H
Lawson Fredk
rear Woodward Henry
1113 Worth M Lydia
1114 Bingeman Geo A
Wagner Edw L
rear Kuhefus Elmer J
1115 Meissner Geo
1116 Honecker Louise Mrs
Winzenried G Adolph
1117 Fleming Wm R
Schlagter Norman G
1118 Walke Buster
1119 Johnson Jas
Sommersdorf Julius
Best intersects
1139 Bauer Albert J auto repr
1141 MacLauchlan Edw
1145 Lienert Frank J
1149 Bradley Edw T
Parker Robt
1151 Mead Wm A
1152 Dixon & Adams auto supplies
Edna pl intersects
1155 Shelley Margt Mrs
1157 Donohue Anna Mrs
Lockwood Ada E mus tchr
1163 Cottrell Henrietta confr
Cottrell Lawrence
1164 Holtzer Jack auto repr
1165 Ringer Walter V
1166 Holzer John F fill sta
1167 Clayton Mary Mrs
Willert Mary nurse
1170 Winter Johanna Mrs
1171 Schoenwald Albert C
Smith Jennie Mrs
rear Rice Gertrude Mrs
Hassel Jas
1172 Torgeson Alice Mrs
Torgeson Frieda Mrs
1173 McFarlane Pearl Mrs
Stone Paul B
rear Opel Gustave A
1174 Heinemann Oscar H
Hauser Magdalene Mrs
1175 Brooks Walter L
Herold Geo
rear Cumming Ethel Mrs
1176 Flickinger Fred E
Winchester Wm E
1177 Ager Albert C
Baehr Robt
rear Kleinhans Geo W
1178 Knittel Emil A barber
1183 Hagen Chas E
1184 Feuerstein John H auto repr
1187 Wingerter Leo
1188 Galloway Mary Mrs, confr
Rau Louis tailor
Galloway Geo S
1189 Gt A & P Tea Co gros
Dodge intersects
1199 Vertalius Nicholas beauty shop
1200 Neuman Jacob H soft drinks
1201 Habitzruther Eug J
1202 Schaefer Carlton A art gds
1205 Eaton Geo G
Ellman Margt Mrs
1206 King Clara L
1207 Rug Henry C hdw
1208 Hoyler Ernest C
1209 Wagner Eliz
1210 Versch Wm
Brimm Peter J
1212 Castin Lawrence N heating
1213 Marthia Anna E Mrs
Griffin Ella Mrs
rear Reifeld Fred
1214 Italiano Jerome
rear Sallis Geo E
1215 Lawandus John J shoes
Hawayek Monsour M
1217 Parker Nelson T auto seat covers
1218 Reissig Francis W
1219 Hawayek Monsour M shoe repr
Chesser Frank
1220 Berry Wallace
Tierney Jas W
Wolflein Eliz Mrs
1221 Wilson Hattie B Mrs confr
Southampton intersects
1233 Perkins Jas L drugs
Barnes Harry T
1236 Wild Alois C
rear Nichols Klaus
1237 Zimmerman Magdaline drsmkr
1238 Stewart David W
1239 Zimmerman Louis A
1241 Scarlet Fanny Mrs
1242 Harlan Emma Mrs
1243 Forbes John G
Nagel Jos
1244 Schuman Valentine
Sorgar Mitchl
1245 Fitzpatrick Harry
1249 Helfman Wm
Maul Hannah
1250 Vacanti Frank soft drinks
1252 Vacanti Frank
1253 Myles Fredk W
1254 Foegen Jos J meats
1255 Oehler Raymond barber
1257 Dunn Wm G soft drinks
Northampton intersects
1260 Sexton Jas A confr
Mavis Selma Mrs
Pleger Louise Mrs
1261 Larkin Co Inc gros
Johnston Goldie E
Place Melvin
1262 Ludlow Wm plmbr
1263 Walter Geo P meats
1265 Schneider & Lenz fruits
VanBuskirk Frank J
rear Nichter Norbert
1266 Muth Paul J dry gds
Muth Jacob
1267 Doenitz Fredk F
Doenitz Herta C nurse
Camus Alex L
Jung Dani phys
1268 Kavanaugh Jas E
1269 Maue John E
Schrader Edw W
Behrader Minnie M Mrs
1270 Fries Arth W
1272 Dahl Wm coal
1273 Navel Robt N
Curculis Theo P
1274 Weinsheimer Edw
1275 Page Leslie A.
1276 Winkler Arth
1279 Uebelhoer Geo J
Rowan Martin S
1280 Adams Henry E
1281 Cotton Adria Mrs
Fisher Minnie Mrs
1284 Zapf H Morton milk dlr
1285 Behringer Chas malt
Eaton begins
1288 Farrell John J
1292 Stengel Christ J
Noeltner Kath
1296 Witzig Albert J
1297 Barhyte Wm F hat clnr
Meyer John H
1298 Ludlow Wm
Gartside Arth F
1301 Walter Louis C
1302 Lawandus John J
1303 Day Elmer F
Lautz Bernard
rear Barbarie Wm
1304 Kumpf Rose Mrs
Buchholz Chas C
1305 Hall Harry A
1308 Anderson John W
Gebhard Frank R
1309 Long Louise Mrs
Norman John D
1311 Vass S H
1312 Dechert Florence M
Cook Jos carpet clnr
1314 McMurray Wm
1315 Hogle Ward
1316 Sanders Mary
1317 Robbins Lena Mrs
1318 Caplin Anthony
1319 Lee Wm C
1320 Boland Nellie Mrs
1321 Todd Nyrum J
1323 Chertoff Israel gro
1325 Galle Harry J meats
Riley intersects
1331 Meyer Anthony G auto repr

1930 **NORTH ST E**

SOURCE: POLKS

290 **Two-Ninety-North Apts**
Apartments:
11 Coates Florence M mgr
12 LaRowe F
13 Campbell Wm
14 Wells Robt H
21 Dennison John D jr
22 Stacy E Lyon
23 Deck Barbara E Mrs
24 Miller Hugh
31 Kibler Roy A
32 Jordan J Edwin
33 Robertson Jas D
34 Hubbard Wm P
41 Danihy Anne B
42 Snyder Jessie A nurse
43 Wilson Chas K
44 Coats Colin C
Street continued
291 Navion Henry M
rear Diehl Eliz J
292 Hotel Wardman
Arlington pl intersects
303 Sisters of Mercy
Casa Misericordia Home
304 Smidt Gertrude Mrs
309 Rogers Wm A
310 Conlon Rosa Jewish Old Folks Home

NORTH E—From 1039 Main east to 354 Herman av
3 Roach Harry
5 Doctor Chas
6 Haefner Elmer G
7 Buscaglia Santo shoe repr
Krauss Hortense
9 Cohnie Julia
Schroeder Eliz Mrs
11 Conner Edw L
Ferguson Margt Mrs
13 Caron Stella Mrs
Park Esther Mrs
14 Ruehl Geo barber
16 Vacant
22 Nakatani Riyo
23 Ford Chas H
25 Wendel Martha M Mrs
26 Morrison's Auto Hospital
Winter & Reisch Co Inc auto pntrs
27 Black Wm B
Coester Wilhelmina Mrs
28 Fisher John G auto pntr
30 Buffalo Cylinder Grinding Inc
31 Taylor Roy O
33 Daley Olive F nurse
Daley Saml C
Achey Rose Mrs
35 Kompalla Elsa Mrs
36 Meicht Ralph L auto repr
37 Metz V J & Son contrs
39 Jones Clayton W
O'Connor Edw A
40 Senefelder Henry E
Schweizel Chas W
41-43 **Apartments**
1 Schregleman Geo
2 Bell Henry A
3 Finn Cath Mrs
4 **VanDyke Fredk**
Street continued
42 Burnett Almon W
Edwards Ruby nurse
Winter Geo J
46 Wheeler-Nowak Electroplating Corp
Ellicott intersects
52-54 Reif-Rexoll Inc
Winter Bros bottlers
rear Babcock Testing Laboratory
52 Buffalo Sugar Sales Co
61 Ehlert & Gloss gros
68 Guenther Chas
Hitzel Edw L
69 Helbig Wm C
Ziehm Otto
70 Baker Chas G
McLean Mary
Garvey Patk J
Shuart Jos W
71 Danforth Willard J chiropractor
Haber Robt C
72 Kemp Francis J
Newman Magdalene T Mrs
Welmont pl intersects
75 Armstrong Clarence J
Smith John J
76 Klose Sarah Mrs
Schock G Adolph gro
77-81 Cook E A Body Corp
Brozan Wm J
Deschene Erma Mrs
80 Klose Benj H
82 Bohn John
May Margt
rear Kaun Martha Mrs
83 Storck Frances Mrs
84 Alexander Roy
Detman Chas
86 Garvey Cyril P
Garvey P J Carting & Storage
Johnson Alf
87 Fernandez John M
rear George Frank N
89 Bissing Gertrude Mrs
Geer Farrell
90 Beardsley Chas M
93 Wolf Marie Mrs
94 McPherson Eug
Detman Chas M
96 Proudley Chas E trucking
Schroeder Maude Mrs
Welmont pl begins

NORTH E—Contd
99 Wagoner Herbert L
Bendola Jack T
100 Vacant store
Dimick Richd
Remington Geo
101 Pfeffer Mehlon J
rear Vanderlean Haayo
105 Kobernuss Harry A
Weinman Pauline Mrs
109 Miller Chas
110 Wolf John confr
Dimick Richd
111 Reilley Thos
Dolan Mary drsmkr
rear King Albert J
112 Schwaegler Jessie Mrs
114 Hutchinson Wm B
Meyer John jr
rear Vacant
115 Lindeman Fred H
116 Butler Pauline Mrs
Werner Cordelia Mrs
117 Newman Dani S
Nye Ethel nurse
Smith Frances N Mrs
118 Weigand Albert
rear Nestell Fred
119 Fredericks Christine W Mrs
Hague Harriet Mrs
120 Groswkoof Chas H
121 Ahmler Anna drsmkr
Cusick Mary
Schutz Geo L
124 O'Rourke Cath
Thomas Geo J
rear Eaton Wayne H
125 Pickelman John G florist
126 Horner Sarah Mrs
Simones Norman
127 Domm Claire M Mrs gro
Domm Wm G
Elm intersects
128 Buhr Emma
132 Becker Bros bakers
Becker John H
135 Simon Geo W
137 Nelly Chas C
Sweeney Eliz Mrs
rear Baker Edw
Baker Ina nurse
140 Chiaramonte Jos C
Fleming Geo L
141 Meisreimer Edw A
Walpole Harry K
142 Pezold Anna
145 Green Wm D
Thum Raymond C
146 Volker Harold H
148 Haas Fredk
149 Groeschel Wm L
Weber Chas F
150 Haas Norman G
152 Burkhardt John C
153 Rohs Matilda
Tripp Ira J
154 Leupold Kate
157 Gillott Arth J
Hettrich Christine Mrs
158 Miller Ira F
160 Rhode Clara E Mrs
Rohrback Conrad
164 Blight E Bertram drugs
Jauch Edwin C dentist
Schaefer Norbert B phys
Michigan av intersects
172 Guenther & Guenther restr
174-76 Vacant
177 Westcott Wm M
179 Aaron Geo
Maple ends
180 Keller Margt Mrs
182 Maul Andrew
197 Moriarty Maurice J
Rupert Wereley A
199 Abell Roscoe C
Diehl Carrie Mrs
205 Eichel Rose
207 Marsden Jas H
209 Tague John C
211 Vacant
213 Tappe Wm
215 Meyer Martin M confr
Mulberry ends
223 Cole Lester C
Teetsell Benj A
225 Nazel Martha Mrs
Dole Lawrence
227 Stoll Albert A
229 Ulrich Michl J
rear Weishaupl John
233 Weeks Clayton
Black Nelson E
235 Clare Sophia Mrs
Kuehe Frieda Mrs
Masten intersects
239 Redlein Roy C
241 Clift Wm W
Locust ends
249 Weeks Ray
253 Sauer Carl W
Evans Gerald D

O'BRIA
INSURAN
210 Ellicott Square

1" equals approx. 200 ft.

1959 aerial photograph
USDA (1959-05-08 - 1959-05-18)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

1963 aerial photograph
USGS (1963-04-22 - 1963-10-02)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

1966 aerial photograph
USDA (1966-06-12 - 1966-07-16)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

1974 aerial photograph
US Geological Survery (Unknown - 1974-04-17)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

1985 aerial photograph
USDA NHAP85 (1985-04-23 - 1985-05-03)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

1995 aerial photograph
USGS DOQQ (1995-03-27 - 1995-04-16)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.



1" equals approx. 200 ft.

2005 aerial photograph
USGS Hi-Res Orthoimagery (2005-04-01 - 2005-04-30)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

2008 aerial photograph

USGS Hi Res via NYS Digital Ortho-imagery Program (NYSDOP) (2008-05-01 - 2008-05-30)
USDA (2008-05-24 - 2008-10-12)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

2011 aerial photograph
USGS Hi Res Ortho Imagery (2011-04-01 - 2011-04-30)
USDA (2011-05-01 - 2011-10-06)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

1" equals approx. 200 ft.

2015 aerial photograph
USDA (2015-05-06 - 2015-09-23)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.



1" equals approx. 200 ft.

2019 aerial photograph
USDA (2019-07-13 - 2019-10-11)

prepared March 22, 2023 -- Historic Aerial imagery © 2023 , NETRonline, LLC.

LaBella
Powered by partnership.

Owner/Operator Questionnaire

Privileged and Confidential

LaBella
Powered by partnership.

Project No._____ Date of Interview: March 16, 2023 Conducted by: Chris Finn

Address (tax # if undeveloped): 903 and 951 Ellicott Street Buffalo NY

Interviewee & Relationship to Site: Samantha Scavulli How long affiliated with Site: 1.5 years

Title/Position/Relationship to Site ☐Owner ☐Owner Representative ☐Former Owner ☐Occupant
☐Former Occupant ☐Neighbor ☐Purchaser ☐Seller ☐Real estate agent
☒Property Manager ☐Other (explain):

Additional Contacts:_____

1. What is the purpose of this assessment? ☐Selling the property ☐Purchasing the property
☐Construction loan ☐Re-financing the property ☐Other (explain):

2. Do you have a PROPERTY SURVEY MAP or OTHER MAPPING of the Site available?
☑No ☐Yes ☐Unknown (if Yes, please provide if possible)

3. Number of building(s): Total sq. ft. of building(s):
Acreage of Site: ☐Unknown ☐NA

Building #1/location: Sq. ft. Construction Date:
Building #2/location: Sq. ft. Construction Date:
Building #3/location: Sq. ft. Construction Date:
Building #4/location: Sq. ft. Construction Date:

4. What is the CURRENT USE(S) of the Site (and/or Site Buildings if applicable) and DATES, if known? ☐Unknown
apartments three buildings total of 17 units

5. What are the PAST USE(S) of the Site (and/or Site Buildings if applicable)and DATES of occupancy, if known? ☐Unknown
apartments

6. Have any buildings been BURNED or DEMOLISHED on the Site? ☒No ☐Yes ☐Unknown
Explain:

Was the Debris:
Burned on Site ☐No ☐Yes ☐Unknown Buried on Site ☐No ☐Yes ☐Unknown
Removed from Site ☐No ☐Yes ☐Unknown
Explain:

Has the Site ever been developed with a residential structure? ☐No ☐Yes ☐Unknown

7. Is the SITE or any ADJOINING PROPERTY CURRENTLY or PREVIOUSLY utilized as any of the following?

Dry Cleaning Facility ■No ☐Yes ☐Unknown ☐Site ☐Adjoining Property to the _____
Dates and Explain:

X-ray or Film Developing ■No ☐Yes ☐Unknown ☐Site ☐Adjoining Property to the _____
Dates and Explain:

Is there a Metal Recovery System in Place? ☐No ☐Yes ☐Unknown
Explain:

Car Repair Shop: ■No ☐Yes ☐Unknown ☐Site ☐Adjoining Property to the _____
Dates and Explain:

Paint/Body Shop: ■No ☐Yes ☐Unknown ☐Site ☐Adjoining Property to the _____
Dates and Explain:

Gasoline Station: ■No ☐Yes ☐Unknown ☐Site ☐Adjoining Property to the _____
Dates and Explain:

Industrial Property: ☐No ☐Yes ☐Unknown ☐Site ☐Adjoining Property to the _____
Dates and Explain:

8. What are the CURRENT and PREVIOUS USE(S) of the ADJOINING PROPERTIES?

Direction	Current Use/Occupant	Past Uses/Occupant
North:		
South:		
East:		
West:		

9. Is SANITARY WASTE WATER CURRENTLY or was PREVIOUSLY Generated and how is/was it Disposed of?

☐No ☐Yes ☐Unknown Discharge Point: ■Public System ☐Private System ☐Unknown
☐Other (explain):

If PRIVATE SYSTEM where is the leach field currently located?

Is NON-SANITARY WASTE WATER CURRENTLY or was PREVIOUSLY Generated and how is/was it Disposed of?

☐No ☐Yes ☐Unknown Discharge Point: ■Public System ☐Private System ☐Unknown
☐Other (explain):

If PRIVATE SYSTEM where is the discharge point currently located? basements

Are any of the following CURRENTLY or PREVIOUSLY located at the Site?

SEPTIC TANK: ☑No ☐Yes ☐Unknown Location:
Dates of Usage:
LEACHFIELD: ☑No ☐Yes ☐Unknown Location:
Dates of Usage:
INJECTION WELL: ☑No ☐Yes ☐Unknown Location:
Dates of Usage:
DRY WELL: ☑No ☐Yes ☐Unknown Location:
Dates of Usage:

Are any of the following CURRENTLY or PREVIOUSLY located at the Site?

FLOOR DRAINS: ☐No ☑Yes ☐Unknown Location: basements
Discharge Point:
TRENCH DRAINS: ☑No ☐Yes ☐Unknown Location:
Discharge Point:
SUMP PUMPS: ☐No ☑Yes ☐Unknown Location: Sumps are in end units
Discharge Point:
STORM DRAINS: ☑No ☐Yes ☐Unknown Location:
Discharge Point:
OTHER: ☑No ☐Yes ☐Unknown Location:
Discharge Point:

Are any FLOOR DRAINS, TRENCH DRAINS, or SUMPS connected to an OIL/WATER SEPERATOR?
■No ☐Yes ☐Unknown ☐NA

Dates of Usage:

Location:

Have any drains been closed in place or sealed over? ☐No ☐Yes ☐Unknown
If YES, date:
Location and explain:

10. Is the Site serviced with PUBLIC or PRIVATE WATER SYSTEMS and DATES of Connection, if known?

Type	Date of Connection/Usage	
■Public		☐Unknown
☐ Well		☐NA

Are there, or were there ever any OBSERVATION or MONITORING WELLS located on-Site?
☐No ☐Yes ☐Unknown ☐NA

Location: Purpose: Dates of Usage/Installation:

11. Are ANY of the FOLLOWING located ON or ADJACENT TO the SITE? (Choose all that apply):

Type:	**Location:**	**Type:**	**Location:**
☐Surface water		☐Pits	
☐Ponds		☐Lagoons	
☐Creek		☐Drainage Ditch	
☐Rivers		☐Lakes	
☐Unknown		■No	

12. What type of heating does this property CURRENTLY have, if any?
Choose all that apply and identify the associated building(s) and dates of connection if applicable.

Type	**Date(s) of Connection/Usage**	**Type**	**Date(s) of Connection/Usage**
■Natural Gas		☐Oil	
☐Propane		☐Radiant	
☐Coal		☐Hot Water	
☐Not Heated		☐Unknown	
☐Other (explain)			

If oil: How is/was the oil stored ☐above ground storage tank ☐underground storage tank (see Question 20)
Location:

What type of heating does this property PREVIOUSLY have, if any?
Choose all that apply and identify the associated building(s) and dates of connection if applicable.

Type	Date(s) of Connection/Usage	Type	Date(s) of Connection/Usage
■ Natural Gas		☐ Oil	
☐ Propane		☐ Radiant	
☐ Coal		☐ Hot Water	
☐ Not Heated		☐ Unknown	
☐ Other (explain)			

If oil: How is/was the oil stored ☐ above ground storage tank ☐ underground storage tank (see Question 20)
Location:

13. Who Supplies ELECTRIC SERVICE to the Site?
☐ RG&E ■ National Grid ☐ NYSEG ☐ Unknown ☐ NA
☐ Other:

14. What is the nature of SOLID WASTE Generated at the Site and Disposed of from the Site (including hazardous)?

Type of Waste?	How is it stored?	Who collects the waste and when?
general waste from apartments		

15. To the best of your knowledge, have you ever GENERATED or TRANSPORTED HAZARDOUS WASTE from the Site?
■ No ☐ Yes ☐ Unknown (if Yes, please provide Manifests)
Explain:

16. Do you TREAT or DISPOSE of any WASTE MATERIALS on-Site? (i.e., land filling, neutralization, incineration)
■ No ☐ Yes ☐ Unknown
Explain:

17. Has any OTHER ENTITY ever been allowed to DUMP, STORE, DISPOSE, TRANSPORT, BURY, INCINERATE, OR LANDFILL any materials at the Site? ■ No ☐ Yes ☐ Unknown

Who?	What?	When?	Location:

18. Has FILL DIRT been brought onto the Site from an UNKNOWN ORIGIN OR CONTAMINATED SITE?
■ No ☐ Yes ☐ Unknown
Explain:

19. Are there areas of the Site in which the any of the following were or are located? ☐ Unknown ■ No

Type:	Location:	Type:	Location:
☐ Gravel		☐ Debris	
☐ Construction Materials		☐ Tree/Brush	
☐ Other (explain):			

20. Are there CURRENTLY or PREVIOUSLY any ABOVE (AST) or UNDERGROUND (UST) STORAGE TANKS located at the Site? ■ No
☐ Yes ☐ Unknown Are they REGISTERED with the NYSDEC? ☐ No ☐ Yes ☐ Unknown

Tank Type (AST/UST)	Capacity (Gallons)	Product	Installation Date	Removal/Closure Date
1.				

2.

3.

4.

5.

Are there any LEAK DETECTION DEVICES in place? ☐No ☐Yes ☐Unknown
Explain:

Have any TANKS been: ☐Unknown ☐No Date(s):

☐REMOVED from the Site
Explain:
Location:

☐CLOSED in place at the Site
Explain:
Location:

Is **Documentation/Closure Reports /Analytical Data** Available? ☐No ☐Yes ☐Unknown
(Please provide copy)

Has any CONTAMINATION been identified or REMEDIATION been required at the Site; related to CURRENT OR PRIOR TANKS?
☐No ☐Yes ☐Unknown
Explain:

Has any CONTAMINATION been identified or REMEDIATION been required at a neighboring property; related to CURRENT OR PRIOR TANKS? ☐No ☐Yes ☐Unknown
Explain:

21. What type of CHEMICALS are CURRENTLY or have PREVIOUSLY been STORED or UTILIZED on Site?

Type:	Usage:	Storage Container/Capacity:	Disposal Method:
none			

Are MSDS sheets readily available for these chemicals? ☐No ☐Yes ☐Unknown (if Yes, please provide copies)

22. Have there been any SPILLS, UNPERMITTED DISCHARGES, or RELEASES of HAZARDOUS or CONTAMINATED MATERIALS or PETROLEUM PRODUCTS at or in the vicinity of the Site? ☒No ☐Yes ☐Unknown

What?	When?	Location:

23. Are you AWARE if the SITE is listed as any of the following –Check all that Apply: ☐No
(please provide information for 'yes' responses)
Regulatory Listing: Explain:
☐National Priority or Delisted Priority List
☐CERLCIS Site
☐CERCLIS NFRAP Site
☐RCRA Generator Facility
☐RCRA Treatment/Storage/Disposal Facility

☐ State or Local Landfill
☐ National Response Site
☐ NYSDEC Spill Site
☐ Hazardous Waste Disposal Site
☒ Brownfield or Voluntary Cleanup Site
☐ Institutional or Environmental Control Site
☐ Hazardous Substance Site

24. To the best of your knowledge, do you have any FEDERAL, STATE, or LOCAL PERMITS for the following?
☒ None ☐ Air Emissions ☐ SPDES (waste water discharge)
Explain:

25. Has the Site ever been the subject of an ENFORCEMENT ACTION by any FEDERAL, STATE, or LOCAL agency regarding ENVIRONMENTAL ISSUES? ☒ No ☐ Yes ☐ Unknown
Explain and provide DATES and any Documentation:

26. Is the Site presently under any FEDERAL, STATE, or LOCAL CONSENT ORDERS, DECREES, or CAUSE of ACTION?
☒ No ☐ Yes ☐ Unknown
Explain and provide DATES and any Documentation:

27. Are you aware of any ENVIRONMENTAL LIENS on the Site? ☒ No ☐ Yes ☐ Unknown
Explain:

28. Are you aware of any LAND USE or ACTIVITY LIMITATIONS that are in place on the Site or have been FILED or RECORDED in a registry? ☐ No ☐ Yes ☐ Unknown
Explain:

29. Are you aware of any KNOWLEDGE or INDICATORS related to the Site that point to the PRESENCE or LIKELY PRESENCE of CONTAMINATION? ☒ No ☐ Yes ☐ Unknown
Explain:

30. Are you aware if the PURCHASE PRICE of this Site reasonably reflects the fair market value of the property?
☐ No ☐ Yes ☒ Unknown ☐ NA (Site is not being sold at this time)
Explain:

31. Has there ever been PREVIOUS Phase I Environmental Site Assessments or environmental audits performed for the Site?
☒ No ☐ Yes ☐ Unknown (if Yes, please provide copies if possible)
If yes, by Whom? Date?
Concerns identified: ☐ No ☐ Yes ☐ Unknown
Explain:

32. Is the ABSTRACT OF TITLE for the Site available? ☒ No ☐ Yes ☐ Unknown
(If Yes, please provide if possible or provide name and contact information for attorney that may have report)

33. Do you have any additional information or specialized knowledge or experience regarding the Site?
☒ No ☐ Yes ☐ Unknown
Explain:

34. Do you have any information related to the future use of the Site? ☒ No ☐ Yes ☐ Unknown
Explain:

35. Has the Site ever been utilized agriculturally? ☒No ☐Yes ☐Unknown
If so, when?:
Explain:

LaBella
Powered by partnership.

Municipal Information

Tax ID	Owner	Print Key	
100.710-0003-001.10000	PILGRIM VILLAGE	100.71-3-1.1	
Street Address	**Co Owner**	**Municipality**	**SWIS CODE**
903 ELLICOTT NF2022		CITY OF BUFFALO	140200
Mailing Address	**Subdivision / Cross Street**	**Property Description**	
91 NORA LN BUFFALO, NY 14209	BEST	**Use Code**	

Year Built	1980	**Heat**	**# of Bedrooms**	0.0	**Sq. Footage** 66,063	**# of Stories**	1
House Type		**Fuel**	**# of Baths**	0.0	**1st Floor SQFT** 0	**# Res. Units**	0
Basement		**Water**			**2nd Floor SQFT** 0	**# of Buildings**	1
Exterior		**Sewer** NONE	**# of Fireplaces**	0	**Base SQFT** 0	**# of Garages**	0
		Central Air				**Story Height**	0

Assessment	1,400,000	**School**		**North**	1057875
Land Value	$225,700	**School Tax**	$0.00	**East**	1072832
Equalization Value 100%	$0			**Latitude**	42.9030632
Account #	4093810	**County Tax**	$0.00	**Longitude**	-78.864985

Improvements

	Improvement Type	Dimensions	SQ. Feet	Year		Improvement Type	Dimensions	SQ. Feet	Year
# 1		0 X 0	0		**# 3**		0 X 0	0	
# 2		0 X 0	0		**# 4**		0 X 0	0	

Land Characteristics

Total Acres	9.05	**Land SQ FT**	394,218	**Lot Size**	614 X 642

Sales History

Grantor	Sale Price	Sale Date	Deed Book	Deed Page	Deed Valid	Deed Type	ARMS Length
		/ /					

Notes

Buffalo Property Record Card

103256
903 Ellicott Buffalo 14209

McGuire PV Holding LP

Total Assessed Value
$2,241,200

KEY INFORMATION

SWIS #	**140200**
SBL #	**100.71-3-1.12**
Account #	**04093820**
Owner/s	**McGuire PV Holding LP**
Property Address	**903 Ellicott Buffalo 14209**
Mailing Address	**455 Cayuga Rd Buffalo NY 14225**
Type	**Vacant Land**
Use	**330 - COMMERCIAL VACANT LAND**
Ownership Code	**-**
Zoning	**D-R - Campus-Resident**
School District	**Buffalo School District 140200**
NBHD Code	**4500**
Cenus Tract	**0031004**
Council	**EL**

ASSESSMENT INFORMATION

Total Assessed Value	**$2,241,200**
Total Land	**$2,241,200**
County Taxable	**$2,241,200**
Town Taxable	**$2,241,200**
School Taxable	**$2,241,200**
Village Taxable	**$0**
Equalization Rate (2023)	**70%**
Level of Assessment (2023)	**70%**
Full Market Value	**$3,201,714**

Assessment Values displayed represent the **2023 Final Assessment Roll**

EXEMPTIONS

No data to display

LAND

SITE #	LAND TYPE	ACRES	FRONT	DEPTH	SQFT
1	01 - Primary	3.43	0.00	0.00	149411.00

BUILDINGS

ADDITIONAL IMPROVEMENTS

No data to display

TRANSFER HISTORY

No data to display

Data last updated: 03/21/2023

LANDMAX

Main Record

03/22/2023

Tax ID	Owner	Print Key	
100.710-0003-001.11000	MCGUIRE PV HOLDING LP	100.71-3-1.11	
Street Address	**Co Owner**	**Municipality**	**SWIS CODE**
951 ELLICOTT		CITY OF BUFFALO	140200
Mailing Address	**Subdivision / Cross Street**	**Property Description**	
455 CAYUGA RD		APARTMENT	
BUFFALO, NY 14225		**Use Code** 411	

Year Built	1980	**Heat**	**# of Bedrooms**	0.0	**Sq. Footage**	42,110	**# of Stories** 1
House Type		**Fuel**	**# of Baths**	0.0	**1st Floor SQFT**	0	**# Res. Units** 0
Basement		**Water** PUBLIC			**2nd Floor SQFT**	0	**# of Buildings** 1
Exterior		**Sewer** PUBLIC	**# of Fireplaces**	0	**Base SQFT**	0	**# of Garages** 0
		Central Air					**Story Height** 14

Assessment	4,496,000	**School**	BUF CITY	**North**	1057873
Land Value	3,568,900	**School Tax**	$0.00	**East**	1073015
Equalization Value 100%	5,764,100			**Latitude**	
Account #	4093900	**County Tax**	$0.00	**Longitude**	

Improvements

	Improvement Type	Dimensions	SQ. Feet	Year		Improvement Type	Dimensions	SQ. Feet	Year
# 1	PAVNG,ASPHLT	2600 X 4	10400	1988	**# 3**		0 X 0	0	
# 2		0 X 0	0		**# 4**		0 X 0	0	

Land Characteristics

Total Acres	5.63	Land SQ FT	245,242	Lot Size	0 X 0

Sales History

Grantor	Sale Price	Sale Date	Deed Book	Deed Page	Deed Valid	Deed Type	ARMS Length
SENIOR HOUSING DEV	2,236,185	12/16/2021	11392	9689			N
		/ /					

Notes

Buffalo Property Record Card

103255
951 Ellicott Buffalo 14209

McGuire PV Holding LP

Total Assessed Value
-

KEY INFORMATION

SWIS #	**140200**
SBL #	**100.71-3-1.11**
Account #	**04093900**
Owner/s	**McGuire PV Holding LP**
Property Address	**951 Ellicott Buffalo 14209**
Mailing Address	**455 Cayuga Rd Buffalo NY 14225**
Type	**Commercial**
Use	**411 - APARTMENT**
Ownership Code	**-**
Zoning	**D-R - Campus-Resident**
School District	**-**
NBHD Code	**4500**
Cenus Tract	**0031004**
Council	**EL**

ASSESSMENT INFORMATION

Total Assessed Value	**-**
Total Land	**-**
County Taxable	**-**
Town Taxable	**-**
School Taxable	**-**
Village Taxable	**-**
Equalization Rate (2023)	**70%**
Level of Assessment (2023)	**70%**
Full Market Value	**-**

Assessment Values displayed represent the **2023 Final Assessment Roll**

EXEMPTIONS

No data to display

LAND

SITE #	LAND TYPE	ACRES	FRONT	DEPTH	SQFT
1	01 - Primary	0.00	0.00	0.00	245243.00

BUILDINGS

COMMERCIAL BUILDING DETAILS

COMMERCIAL BUILDING SITE #(1), BUILDING #(1), SECTION #(1)

Building #	**1**	Section #	**1**
Boeck #	**0110**	Gross Floor Area	**4,374**
Construction Quality	**2.0**	Building Perimeter	**470**
Number of Stories	**2.0**	Basement Perimeter	**0**
Story Height	**9**	Basement SQFT	**0**
Year Built	**1980**	Number of Elevators	**0**
Effective Year Built	**1980**	Air Conditioning %	**0**
Condition	**3 - Normal**	Sprinkler %	**100**

COMMERCIAL BUILDING SITE #(1), BUILDING #(2), SECTION #(1)

Building #	**2**	Section #	**1**
Boeck #	**0110**	Gross Floor Area	**6,155**
Construction Quality	**2.0**	Building Perimeter	**654**
Number of Stories	**2.0**	Basement Perimeter	**0**
Story Height	**9**	Basement SQFT	**0**
Year Built	**1980**	Number of Elevators	**0**
Effective Year Built	**1980**	Air Conditioning %	**0**
Condition	**3 - Normal**	Sprinkler %	**100**

COMMERCIAL BUILDING SITE #(1), BUILDING #(3), SECTION #(1)

Building #	**3**	Section #	**1**
Boeck #	**0109**	Gross Floor Area	**2,083**
Construction Quality	**2.0**	Building Perimeter	**231**
Number of Stories	**1.0**	Basement Perimeter	**0**
Story Height	**9**	Basement SQFT	**0**
Year Built	**1980**	Number of Elevators	**0**
Effective Year Built	**1980**	Air Conditioning %	**0**
Condition	**3 - Normal**	Sprinkler %	**100**

COMMERCIAL BUILDING SITE #(1), BUILDING #(4), SECTION #(1)

Building #	**4**	Section #	**1**
Boeck #	**0109**	Gross Floor Area	**3,150**
Construction Quality	**2.0**	Building Perimeter	**330**
Number of Stories	**1.0**	Basement Perimeter	**0**
Story Height	**9**	Basement SQFT	**0**
Year Built	**1980**	Number of Elevators	**0**
Effective Year Built	**1980**	Air Conditioning %	**0**
Condition	**3 - Normal**	Sprinkler %	**100**

COMMERCIAL BUILDING SITE #(1), BUILDING #(5), SECTION #(1)

Building #	**5**	Section #	**1**
Boeck #	**0855**	Gross Floor Area	**1,218**

Construction Quality	**2.0**	Building Perimeter	**142**
Number of Stories	**1.0**	Basement Perimeter	**0**
Story Height	**14**	Basement SQFT	**0**
Year Built	**1980**	Number of Elevators	**0**
Effective Year Built	**1980**	Air Conditioning %	**0**
Condition	**3 - Normal**	Sprinkler %	**0**

COMMERCIAL SITE USES

SITE #	USE #	COMMERCIAL USE	TOTAL UNITS	TOTAL RENTABLE AREA SQFT
1	1	A03 - Garden apt	17	13,679
1	1	A03 - Garden apt	73	64,845
1	2	F05 - Row storage	1	1,218

ADDITIONAL IMPROVEMENTS

SITE #	DESCRIPTION	QUANTITY	CONDITION	YEAR BUILT	SQFT	DIMENSIONS
1	LP4 - Paving, asphalt	1.00	3 - Normal	1988	0.00	2600.00x4.00

TRANSFER HISTORY

SALE DATE	SALE PRICE	USEABLE SALE	ARMS LENGTH	PRIOR OWNER	DEED BOOK	DEED PAGE	DEED DATE
11/13/2019	$2,821,029	0	0	Pilgrim Village,	11352	6572	11/13/2019

Data last updated: 03/21/2023

CITY OF BUFFALO

FREEDOM OF INFORMATION LAW RECORDS REQUEST FORM

MAYOR
BYRON W. BROWN

Under the provisions of Article 6, Sections 84 -90, of the New York State Public Officers Law entitled, the FREEDOM OF INFORMATION LAW (FOIL), I hereby request the records or portions thereof that I have reasonably described in Part "B" of this form.

PART A - APPLICANT INFORMATION

1. Name of Applicant: Christopher Finn

2. Company Name: LaBella Associates, D.P.C.

3. Type of Business:
   - ❑ Government Entity
   - ❑ Law Firm
   - ❑ Media
   - ❑ Other _____

4. Address: 300 Pearl Street, Suite 130 City: Buffalo State: NY Zip Code: 14202

5. Telephone Number: 716.907.0596 Fax Number: _____

6. E-Mail: cfinn@labellapc.com

PART B – INFORMATION REQUESTED

Describe the records that you are requesting in the space provided below. Please include as much detail as possible such as the respective department having possession of the records, dates, titles, or any other information that may assist us in locating the record(s) you are seeking.

-Assessment Records (current and/or historical property cards)

-Building Inspection/Code Enforcement Records (records of tank installation, permits, removals, or closures, construction/demolition permits)

-Records of Environmental Concerns, issues, or violation (if available)

-Fire Marshal Records (records of fires or spills at the Site)

-Records of soil or groundwater contamination/cleanup or on-Site remediation (if available)

Address: 903 and 951 Ellicott Street Buffalo NY

Tax ID: 100.71-3-1.12, 100.71-3-1.11

Owner: MCGUIRE PV HOLDING LP

PART C – METHODS OF REVIEW

- ☐ I would like to schedule a time to review the records that I am requesting. I understand that access to the requested records will be provided in accordance with Section 87 of New York State Public Officers Law. I understand that copies may not be immediately available.
- ☐ I would like the requested documents mailed to me. I understand that access to the requested records will be provided in accordance with Public Officers Law §87. I understand that any fees associated with my obtaining copies of the requested records must be received by the City before the records are disclosed.
- ☐ I would like the requested records sent to the following e-mail address: _____

PART D – FEES

Should you desire copies of records, fees shall apply in accordance with Section 87(1) of the Public Officers Law. Advanced payment is required before records will be released. Please make check or money orders payable to the **City of Buffalo**.

FEES FOR PHOTOCOPIES: *Pages up to 9" x 14"are $.25 ea.* or *the actual cost of reproducing any other record.*

The fee for reproducing a record may include the actual cost of the storage device or media; actual cost for engaging outside professional service to reproduce record; hourly salary for employee time used in reproducing the record.

PART E – SUBMISSION OF REQUEST

After you have reasonably described the records you wish to inspect or obtain, please sign this form and return it to the appropriate City department that maintains the records you seek. Requests may be sent via electronic mail, regular US mail, or hand delivery.

I hereby affirm that the information I have provided on this request form is correct.

Signature: Christopher Finn **Print Name:** Christopher Finn **Date:** February 23, 2023

..86 E. NORTH

86 E. North

BUREAU OF FIRE PREVENTION

Date 11-20-72
Time Entered Building
Time Left

Construction Hvrb Stories 1 Area

VIOLATIONS AND FLOOR FOUND ON

Aisles, insufficnt or blocked
Ashes in wooden boxes, etc.
Bulk, dangerous, not placarded
Baled papers, storing too much of
Chimney defective
Celluloid improperly stored
Concealed spaces
Doors or windows, blocked or nailed
Are there sufficient exits?
No sink under stoves, etc.
No hood or vent over ranges, etc.
No metal cans for oily rags, etc.
No metal bins for excelsior, etc.
Ovens, etc., not properly protected
Partitions, too near stoves, etc.
Rubbish in yard or building
Rubber hose on gas appliances
Smoke pipes too near woodwork
Steam pipes, too near woodwork or stock
Storing explosives contrary to law
Ventilators full of grease, dust, etc.
Windows to fire escapes, out of order

QUESTIONS — Yes or No

Did you examine behind machines, ranges, shelves, benches, under stairs, dressing rooms, lockers, etc., for litter and fire hazards? Is boiler room kept clean, cut off?

Are there any loose electric wires?
Do they use paper shades on electric lights, or tie up wires on nails, pipes, etc.?
Do they use any oil or electric appliances which would be likely to cause a fire?
Do they use any substance which would be detrimental to firemen in case of fire? If so, what is it, where is it stored and what amount is carried in stock?

Name of Occupant in Violation and Floor Found On

Owner Paul Stapp Address
Occupant David Milton Address 2 Minetown Rds N.Y.
Occupancy Rapair Garage No. Tenants
Sprinklers: Wet ☐ Dry ☐ Condition none Supply
Location, Shut-off Valves
Standpipe No. Location none Siamese Conn. Location
Condition Water Supply
Portable Fire Apparatus—No. & Kind on each floor carried Condition out of date

Fire Appliance Recommended: Kind none
Location
Stairways: Number & Location none Enclosed

Fire Escapes: Number - Location - Type none

Elevators: Number - Location - How Enclosed none

Do Elevator Gates Work Properly? N/A Condition of Pit
Has building fire doors? No Condition
Will they work? N/A If not automatic, are they kept closed?
Are openings through fire walls protected? No
Are floors overloaded? No What floors
What conditions are skylights in? none
Is there a ladder to scuttle in roof of building? No Condition
Are all openings in floors protected? No
Heating system: Type carried Fuel Gas
Fuel Oil Tank: Capacity none Location

Volatile liquids—Oils or Acids none Quantity
Where kept?
Main Shut-off: Gas 1st Floor Electric 1st Floor
Any Violations of Laws or Ordinances? (see letter)

Condition of Building poor Premises poor
Re-inspected
Whom interviewed Sean Lake
Inspector Lt. P. Colvin Company Officer

Batt. Chief

Use other side for Recommendations, Remarks and Sketches

November 28, 1972

Mr. Daniel Nelson
86 East North Street
Buffalo, New York 14203

Re: 86 East North Street

Dear Sir:

Subsequent to an inspection of the above noted premises by a member of the Fire Prevention Bureau, be advised of the following.

1) You are presently licensed for a Repair Garage only. This means that you cannot apply flammable spray and therefore, your present painting operation is illegal. If you wish to continue this painting operation, you must apply for a flammable spray license which license will be issued after the regulations in the enclosed excerpt are complied with.

2) Remove the clock from in front of your "No Smoking" sign.

3) Change all fuses to 15 amp.

4) Remove the present kerosene floor heater from the premises. An approved overhead heater is allowed if it is at least 8' off the floor.

5) Clean up the garage interior and dispose of unnecessary combustibles. Stack that which is necessary in a neat and orderly fashion.

6) Clean up all oil and grease deposits from the floor and keep it clean in the future.

7) Recharge and hang extinguishers not more than 5' off the floor.

A re-inspection will be made on or about December 29, 1972 to determine compliance.

DEPARTMENT OF FIRE

City of Buffalo

INTER DEPARTMENTAL CORRESPONDENCE

If you have any further questions regarding this matter, please contact Lt. P. Colson at 856-4200, Ext. 498 between 8:30 and 9:00 A. M. or 3:30 and 4:30 P. M. weekdays.

Very truly yours

Paul J. Zalewski, Chief
BUREAU OF FIRE PREVENTION

P. Colson, Lt.

PC:RC
CC: Lt. Louis J. Spitzer
Ladder #1--2nd Platoon

F-8

DEPARTMENT OF FIRE

City of Buffalo

INTER DEPARTMENTAL CORRESPONDENCE

TO Fire Prevention Bureau

DATE Nov 7, 1972

SUBJECT Inspection of 86 E. Nor... a repair garage

FROM H + L #1

DEAR SIR:

While inspecting a repair garage for a license renewal, the David Nelson Co at 86 E. North I found a flor kerosene heater being used. One of the workers stated the owner would repair the orignal system. Poor housekeeping and evidence of spraying without a booth was also present. I advised the worker of the unsafe conditions and told him the garage would be reinspected. Please inspect this building, your recommendations and notification to the owner may facilitate a more rapid response

Edson Hardling

RESPECTFULLY,

Lt. L. J. Spitzer Jr.

BUREAU OF FIRE PREVENTION

Date 3-9-70
Time Entered Building
Time Left

Construction Block - wood roof Stories 1 Area

Owner Peter Gorky Address —
Occupant David Nelson Address 2 Dupont
Occupancy repair garage No. Tenants
Sprinklers: Wet ☐ Dry ☐ Condition none Supply
Location, Shut-off Valves
Standpipe No. Location none Siamese Conn. Location
Condition Water Supply
Portable Fire Apparatus—No. & Kind on each floor 1-10# A, B, C, Condition out of charge

Fire Appliance Recommended: Kind none
Location
Stairways: Number & Location 1- rear to corkloft Enclosed

Fire Escapes: Number - Location - Type none

Elevators: Number - Location - How Enclosed none

Do Elevator Gates Work Properly? Condition of Pit
Has building fire doors? no Condition
Will they work? If not automatic, are they kept closed?
Are openings through fire walls protected?
Are floors overloaded? What floors.
What conditions are skylights in?
Is there a ladder to scuttle in roof of building? Condition
Are all openings in floors protected?
Heating system: Type Overhead Fuel gas
Fuel Oil Tank: Capacity Location

Volatile liquids—Oils or Acids Quantity
Where kept?
Main Shut-off: Gas 1st floor Electric some
Any Violations of Laws or Ordinances? yes - all listed

Condition of Building fair Premises poor
Whom interviewed Cleveland Jenkins Re-inspected
Inspector Lt. P. Cohen Company Officer

Batt. Chief

Use other side for Recommendations, Remarks and Sketches

...CES AND FLOOR FOUND ON

...ct or blocked
...wooden boxes, etc.
...dangerous, not plastered
...il papers, storing too much of
...chinery defective
Celluloid improperly stored
Concealed spaces
Doors or windows, blocked or nailed
Are there sufficient exits?
No zinc under stoves, etc.
No hood or vent over ranges, etc.
No metal cans for oily rags, etc.
No metal bins for excelsior, etc.
Ovens, etc., not properly protected
Partitions, too near stoves, etc.
Rubbish in yard or building
Rubber hose on gas appliances
Smoke pipes too near woodwork
Steam pipes, too near woodwork or stock
Storing explosives contrary to law
Ventilators full of grease, dust, etc.
Windows to fire escapes, out of order

QUESTIONS	Yes or No
Did you examine behind machines, ranges, shelves, benches, under stairs, dressing rooms, lockers, etc., for litter and fire hazards?	
Is boiler room kept clean, cut off?	
Are there any loose electric wires?	
Do they use paper shades on electric lights, or tie up wires on nails, pipes, etc.?	
Do they use any oil or electric appliances which would be likely to cause a fire?	
Do they use any substance which would be detrimental to firemen in case of fire? If so, what is it, where is it stored and what quantity is carried in stock?	

Name of Occupant in Violation and Floor Found On

March 25, 1970

Mr. Peter Garby
86 E. North Street
Buffalo, New York 14203

Re: 86 E. North Street

Dear Sir:

Subsequent to an inspection of the above noted premises by a member of the Fire Prevention Bureau, be advised of the following.

a) Place two (2) "No Smoking" signs in conspicuous places within the garage interior. Signs shall be at least 18" long and 12" high with said lettering on white background, said lettering at least 2½" high saying:

"Smoking Prohibited"
Under Penalty of a Fine
Section 18:12 Fire Prevention
Code by orders of the
Fire Prevention Bureau

OK

b) Re-charge the 2½-gallon soda and acid extinguisher. OK

c) Clean up and remove all unnecessary combustibles from the garage interior and exterior. That which is necessary stack in a neat and orderly fashion. OK

d) If spray painting operations are to continue, all provisions of Article XX which is enclosed must be complied with.

A re-inspection will be made on or about April 20, 1970 and compliance is expected.

If you have any further questions regarding this matter, please contact Lt. P. Colson at 856-4200, Ext. 498 between 9:00 A. M. and 10:00 A. M. weekdays.

Very truly yours

Paul J. Zalewski, Chief
BUREAU OF FIRE PREVENTION

PC:RC
Enc. 1

P. Colson, Lt.

BUREAU OF FIRE PREVENTION

Date 10-7-67

Time Entered Building

Time Left

Construction Cinder Block Stories 1 Area

Address

Owner

Occupant David Nelson Address

Occupancy Nelson Collision & Painting No. Tenants

Sprinklers: Wet ☐ Dry ☐ Condition Supply

Location, Shut-off Valves Siamese Conn. Location

Standpipe No. Location

Condition Water Supply

Portable Fire Apparatus—No. & Kind on each floor Condition

Fire Appliance Recommended: Kind

Location

Stairways: Number & Location Enclosed

Fire Escapes: Number - Location - Type

Elevators: Number - Location - How Enclosed

Do Elevator Gates Work Properly? Condition of Pit

Has building fire doors? Condition

Will they work? If not automatic, are they kept closed?

Are openings through fire walls protected?

Are floors overloaded? What floors.

What conditions are skylights in? Condition

Is there a ladder to scuttle in roof of building?

Are all openings in floors protected?

Heating system: Type Fuel

Fuel Oil Tank: Capacity Location

Volatile liquids—Oils or Acids Quantity

Where kept?

Main Shut-off: Gas Electric

Any Violations of Laws or Ordinances?

Condition of Building Premises

Re-inspected

Whom interviewed

Inspector Lt. Jos. Ward Company Officer

(SEE OVER)

Batt. Chief

Use other side for Recommendations, Remarks and Sketches

...S AND FLOOR FOUND ON

...t or blocked

...den boxes, etc.

...gerous, not placarded

...papers, storing too much of

...imney defective

Celluloid improperly stored

Concealed spaces

Doors or windows, blocked or nailed

Are there sufficient exits?

No zinc under stoves, etc.

No hood or vent over ranges, etc.

No metal cans for oily rags, etc.

No metal bins for excelsior, etc.

Ovens, etc., not properly protected

Partitions, too near stoves, etc.

Rubbish in yard or building

Rubber hose on gas appliances

Smoke pipes too near woodwork

Steam pipes, too near woodwork or stock

Storing explosives contrary to law

Ventilators full of grease, dust, etc.

Windows to fire escapes, out of order

QUESTIONS	Yes or No
Did you examine behind machines, ranges, shelves, benches, under stairs, dressing rooms, lockers, etc., for litter and fire hazards? Is boiler room kept clean, cut off?	
Are there any loose electric wires?	
Do they use paper shades on electric lights, or tie up wires on nails, pipes, etc.?	
Do they use any oil or electric appliances which would be likely to cause a fire?	
Do they use any substance which would be detrimental to firemen in case of fire? If so, what is it, where is it stored and what amount is carried in stock?	

Name of Occupant in Violation and Floor Found On

F.8

DEPARTMENT OF FIRE

City of Buffalo

INTER DEPARTMENTAL CORRESPONDENCE

TO Fire Prevention Bureau DATE February 12, 196

SUBJECT "Out of Business" Ch

FROM Ladder Co #1 - 3rd Platoon

DEAR SIR: I wish to report that the P. J. Garvey Co. at 86 E North St has moved and the private gas pump has been removed.

Please remove this inspection location from your records.

Mail 3/15/66

RESPECTFULLY,

Lt. Robert Wright

TANKS--Removed, Watered, or Slushed

Location 86 East North St

Removed ___ Make sure vent is removed.

Slushed ___ Make sure vent is removed at grade or below.

Watered ✓ If it is expected to be watered for 3 years, be sure pump is removed and suction and vent capped.

Number of Tanks 1 Sizes 4000

Owner of Premises P. O. Garvey Co.

Present or Former Operator Same

Brand Name of Gasoline Gulf.

Owner of Tank Gulf oil

Address

Contractor J Leichman Service

Address 74 Skillen St.

Draw sketch of approximate location on property on reverse side. Also, any other pertinent information.

INSTRUCTIONS BELOW THIS LINE FOR OFFICE USE ONLY.

See Over

If station had flammable liquid license, notify the Battalion Chief to have company remove from files. If station is still in business, make note on Form 29 of which tank or tanks have been removed, slushed, or watered and date of same.

PZ:RC
5/28/63

Location 86 East North St.

Date June 23, 65

FLEISCHMANN SERVICE CO

74 SKILLEN STREET • BUFFALO, N. Y. 14207 • PHONE TR 3-49

June 21, 1965

Fire Prevention Bureau
Buffalo, N.Y.

Attn: F. Shaller

Gentlemen:

This is to verify that on May 10, 1965 we filled 1-4000 gal. tank with water at P. J. Garvey 86 E. North St. for Gulf Oil Corp.

We removed the pump, capped all lines and disconnected elec service to pump.

Very truly yours,

FLEISCHMANN SERVICE CORP.

L. Fleischmann

L. Fleischmann, Pres.

TANKS--Removed, Watered, or Slushed

Location 86 E. North St.

Removed ✓ Make sure vent is removed.

Slushed ___ Make sure vent is removed at grade or below.

Watered ___ If it is expected to be watered for 3 years, be sure pump is removed and suction and vent capped.

Number of Tanks 1 Sizes 4000 gal.

Owner of Premises P. J. Garvey Casting

Present or Former Operator

Brand Name of Gasoline Gulf

Owner of Tank

Address River Rd. Tonawanda N.Y.

Contractor Iggo Tank

Address 15 Lafayette

Draw sketch of approximate location on property on reverse side. Also, any other pertinent information.

INSTRUCTIONS BELOW THIS LINE FOR OFFICE USE ONLY.

Witnessed by Lt. James J. Rhine

If station had flammable liquid license, notify the Battalion Chief to have company remove from files. If station is still in business, make note on Form 29 of which tank or tanks have been removed, slushed, or watered and date of same.

PZ:RC
5/28/63

Location 86 E. North St.

Date 7-3-68

F29 (Revised 6/56) — BUFFALO FIRE DEPARTMENT
FLAMMABLE LIQUID ORDINANCE CHAP. XXIX
STORAGE AND USE

FILLED W/ WATER MAY '65

BATTALION
COMPANY
DATE 5-6-65

APPLICATION INSTALLATION SURVEY [A]

GASOLINE — TYPE OF LIQUID — I — CLASS

COMMISSIONER OF FIRE:

LOCATION 866 NORTH ST

NAME P J HARVEY

PURPOSE OF USE: COMMERCIAL (PRIVATE) Date:

APPLICATION NO. Date:

PERMIT NO. Date:

CITY PROPERTY (CURB) [ ]
PRIVATE PROPERTY [X]
ZONED USE DISTRICT

IS LICENSE REQUIRED? YES

CONTRACTOR ELMWOOD ELECTRIC

ADDRESS

TANKS:
Number of 1
Capacity of Each 4000
Capacity Total 4000
Above Ground NO
Feet Underground 3'
Ft. from Property Line 10'
Ft. from Street Line (Min. 10 ft.) 10'
Ft. from Cellar or Bldg. 10'
U. L. Label Numbers E 27152 2

Public Assemblage Bldg. within 300 ft.? NO (Sec. 82)
Less than 50 ft. from RR & docks? (Sec. 16, Chap. LXX) NO

VENT PIPE:
Number of 1
Size 2"
Terminates Outside YES
Ft. above Fill Pipe 15'
Ft. from Bldg. Opening 10'
Weatherproof hood YES
Flame Arrester YES

PUMPS:
Number of Pumps 1
Ft. from Bldg. Line 15'
Ft. from Street Line (Min. 10 ft.) 10'
U. L. Label Numbers 756866
If inside bldg., are pumps protected as required by Sec. 148?

FILL PIPE:
Size 2"
Located Outside YES
Ft. from Bldg. Opening 30'
Protected against damage YES

TESTS:
(Sec. 91) APPROVED OK
DISAPPROVED

ALL TANKS, PUMPS AND PIPING, ~~WILL BE~~ ___, ARE ___, ~~ARE NOT~~ ___, INSTALLED IN ACCORDANCE WITH THE REQUIREMENTS OF THE CITY ORDINANCE, I THEREFORE, RECOMMEND

APPROVED [Y]
~~DISAPPROVED~~ [ ]

Martin L Holden TITLE Md Batt Chief

APPROVED Robert J. Zahm Jr. DATE 5-7-64

P.O. Pirie Deputy Comm

IMPORTANT: Include Remarks, Sketch of Tank and Pump Location on other side.
Forward copy to Bureau of Fire Prevention.


CONC BLOCK
1 STORY
TRUCK GARAGE
DOOR
FRAME HOUSE
FRAME DWELLING
NEW TANK 4000 GAL
PUMP
OLD TANK
FILL FOR NEW TANK
86 E NORTH ST
FILLED WITH CONC.
NEW TANK REPLACES OLD
Filling process written by Chief Inspector
and work done by Edmund O Flaherty
NORTH

YT 5-1880

ELMWOOD ELECTRIC & PUMP CORP.

Service to the Petroleum Industry
810 ELMWOOD AVENUE
BUFFALO 22, NEW YORK

February 13, 1964

City of Buffalo
Fire Prevention Bureau
City Hall Bldg.
Buffalo, New York

Attn: Chief Uhrich

Gentlemen:

Enclosed please find release as per your request from P. J. Garvey Carting & Storage Co. to Gulf Oil Corporation for filling one 1000 gallon tank with concrete.

Trusting you find our letter in order, we remain

Very truly yours,

ELMWOOD ELECTRIC & PUMP CORP.

Richard J. Hitchcock

RJH:ac
encl.

2-5-64
Permit # 25935 issued
to P.J. Garvey - 86 E. Mortimer St
to Install - 1-4000 gal concrete Tank

NT-582
35-1000

KNOW ALL MEN BY THESE PRESENTS:

That GULF OIL CORPORATION, for a valuable consideration paid to ~~it~~ the receipt whereof is hereby acknowledged, hereby sells and conveys to

F. J. Harvey Carting & Stevage Co., 86 E. North St., Buffalo, N. Y.

hereinafter called grantee, the following equipment:

1 - 1000 gallon U. S. Tank

installed on premises situated at 86 E. North St., Buffalo, N. Y.

TO HAVE AND TO HOLD the same unto the said grantee, forever.

This conveyance is made without warranty of any kind with respect to the condition or installation of said equipment.

Grantee, as part of the consideration for this conveyance, hereby fully releases and forever discharges said GULF OIL CORPORATION, its successors and assigns, from all liability for all damages and losses of every kind caused in any manner whatsoever by said equipment or the use thereof.

EXECUTED this 12th day of April, 1944.

provided said tank is made safe by filling with grout type cement.

WITNESS:

GULF OIL CORPORATION

BY W. L. Stenberg
Division Manager, Supply and Operation

Grantee

F29 (Revised 6/56)

BUFFALO FIRE DEPARTMENT
FLAMMABLE LIQUID ORDINANCE CHAP. XXIX
STORAGE AND USE

APPLICATION [X]
INSTALLATION [X]
SURVEY

GASOLINE — TYPE OF LIQUID

I — CLASS

BATT... COMP... DATE 11

COMMISSIONER OF FIRE:

LOCATION 86 E. North St

NAME C.P. Garvey Co.

PURPOSE OF USE: COMMERCIAL PRIVATE Date:

APPLICATION NO. Date:

PERMIT NO.

CITY PROPERTY (CURB) [X]
PRIVATE PROPERTY

ZONED USE DISTRICT M 1

IS LICENSE REQUIRED? YES

CONTRACTOR ELMWOOD ELECTRIC

ADDRESS 810 ELMWOOD AVE

TANKS:
Number of 1
Capacity of Each 4 000
Capacity Total 4 000
Above Ground
Feet Underground 5'
Ft. from Property Line 50'
Pt. from Street Line (Min. 10 ft.) 60'
Ft. from Cellar or Bldg. 25'
U. L. Label Numbers

Public Assemblage Bldg. within 300 ft.? No (Sec. 82)

Less than 50 ft. from RR & docks? (Sec. 16, Chap. LXX) No

VENT PIPE:
Number of
Size
Terminates Outside
Ft. above Fill Pipe
Ft. from Bldg. Opening
Weatherproof hood
Flame Arrester

PUMPS:
Number of Pumps 2 (PROPOSED)
Ft. from Bldg. Line 90'
Ft. from Street Line (Min. 10 ft.) 40
U. L. Label Numbers
If inside bldg., are pumps protected as required by Sec. 148?

FILL PIPE:
Size
Located Outside Yes
Ft. from Bldg. Opening 70'
Protected against damage

TESTS:
(Sec. 91) APPROVED
DISAPPROVED

ALL TANKS, PUMPS AND PIPING, WILL BE X, ARE ___, ARE NOT ___, INSTALLED IN ACCORDANCE WITH THE REQUIREMENTS OF THE CITY ORDINANCE, I THEREFORE, RECOMMEND

APPROVED [X]
DISAPPROVED [ ]

Charles T. Dietrich TITLE Batt. Chief 2nd.

APPROVED Robert V. Zahm Jr. DATE 1/27/64

IMPORTANT: Include Remarks, Sketch of Tank and Pump Location on other side. Forward copy to Bureau of Fire Prevention.

BUFFALO FIRE DEPARTMENT
VOLATILE FLAMMABLE LIQUID TANK STORAGE AND USE

FORM 89

Gasoline — KIND OF LIQUID — I — CLASS

BATTALION — COMPANY — DATE 7-24-47

APPLICATION [X]
INSTALLATION [ ]
SURVEY [ ]

COMMISSIONER OF FIRE: Joseph O. MacTurnan

LOCATION 86 East North St. — CITY PROPERTY (CURB) [X] PRIVATE PROPERTY [ ]

NAME C. P. Garvey — ZONED USE DISTRICT Business

PURPOSE OF USE: ~~COMMERCIAL FILLING STATION~~ PRIVATE FILLING STATION PRIVATE STORAGE 660 GAL. OR LESS

TYPE OF SYSTEM: PRESSURE [ ] SUCTION [X]

APPLICATION NUMBER ____ DATE 7-24-47

IS LICENSE REQUIRED No

PERMIT NUMBER ____ DATE ____

CONTRACTOR Elmwood Elec & Pump

INSTALLATION ____ DATE ____

ADDRESS 810 Elmwood Ave

86 EAST NORTH ST.

TANKS:

1 NUMBER OF
1,000 Gals CAPACITY OF EACH
1,000 Gals CAPACITY TOTAL
No ABOVE GROUND
____ FEET UNDERGROUND
____ FEET FROM BLDG. LINE
____ FEET FROM STREET LINE
____ FEET FROM CELLAR
____ UNDERWRITERS LAB. LABEL

VENT PIPE:

____ NUMBER OF
____ SIZE
____ TERMINATES OUTSIDE
____ FEET ABOVE FILL PIPE
____ FEET FROM BLDG. OPENING
____ WEATHERPROOF HOOD
____ FLAME ARRESTER

FILL PIPE:

____ LOCATED OUTSIDE
____ FEET FROM BLDG. OPENING
____ PROTECTED AGAINST DAMAGE

PUMPS

____ QUANITY
____ FEET FROM BLDG. LINE
____ FEET FROM STREET LINE
____ UNDERWRITERS LAB. LABEL

AS ALL TANKS, PUMPS AND PIPING ~~WILL BE~~ ARE INSTALLED IN ACCORDANCE WITH THE ~~ARE NOT~~ REQUIREMENTS OF THE CITY ORDIANCE AND STANDARDS OF THE NATIONAL BOARD OF FIRE UNDERWRITERS, I THEREFORE,

RECOMMEND APPROVAL [X] Arthur H. Bond TITLE 9th Batt. Chief

DISAPPROVAL [ ]

APPROVED Frank J. Masterson COMMISSIONER OF FIRE DATE ____

NOTE: INCLUDE REMARKS, SKETCH OF TANK AND PUMP LOCATION ON OTHER SIDE.

Note:
Also new Tank of 1000. GALS to Replace
existing 280 GAL TANK

EAST NORTH ST



22 E.North,822,830 Elm,66 Goodell, 937 Washington,
124 Goodell, 499-501 N.Oak, 108-114 Goodell,

BUILDING PERMIT # B 02503

804 Michigan, 168 Goodell, 130-132 Goodell

LOCATION _____ DATE Sept. 23, 1975

OWNER City of Bflo.Urban Renewal ADDRESS _____

CONTRACTOR Northern Demolition

DESCRIPTION OF WORK Dem.to gr.3-1½sty.fr.,2-1sty.fr.,
6-2½sty.fr.,2-2sty.fr.,1-3sty.fr.,1-1sty.conc.blk.
1-3sty.msry.,1-1sty.fr.&stone bldgs.(24 apts.)
CONDITIONS (various bldgs.) Fut.use-vacant.

VALUE ~~$~~ $21,700.00 FEE $230.00

APPLICATION # 143101 PLAN FILE # _____

LOCATION 68 E North
PERMIT NO. 65143 DATE May 20/21
OWNER Chas Guenther
DESCRIPTION 1 Story fr pr garage

LOCATION 70 E. North St
PERMIT NO. 60559 DATE MAR 1 9 1920
OWNER Patrick J. Garvey
DESCRIPTION alt + add 2 fr lite pr garage

LOCATION 70 E. North St.
PERMIT NO. 18975 B.O. DATE 2/27/24
OWNER P. J. Garvey
DESCRIPTION convert and later 2 story frame 4 family apartment

LOCATION 70 E. North
PERMIT NO. 18254 B.O. DATE 1/27/26
OWNER P. J. Garvey
DESCRIPTION enclose front porch

LOCATION 70 East North St.
PERMIT NO. BO26630 DATE August 27, 1937
OWNER Patrick J. Garvey
DESCRIPTION Alter frame tenement.

LOCATION 70 East North St.
PERMIT NO. BO 49413 DATE 10/13/50
OWNER C. Garvey
DESCRIPTION Enlarge cellar - frame two family dwelling.
$500

LOCATION 70 North St.
PERMIT NO. 62604 DATE 7-17-73
OWNER Urban Renewal (Demo of Buffalo)
DESCRIPTION Demo 1 fam 1½ sty fr dwelling
SEE CARD FOR OAK ST. REDEVELOPMENT

LOCATION 70 North St.
PERMIT NO. 62604 DATE 7-17-73
OWNER Urban Renewal (Demo of Buffalo)
DESCRIPTION Demo 1 fam 1 sty fr dwelling
SEE CARD FOR OAK ST. REDEVELOPMENT

LOCATION 70 North St.
PERMIT NO. 62604 DATE 7-17-73
OWNER Urban Renewal (Demo of Buffalo)
DESCRIPTION Demo 2 fam 2 sty fr dwelling
SEE CARD FOR OAK ST. REDEVELOPMENT

LOCATION- 72 E. North St

PERMIT No. 6651 DATE Feby 26 1926 PLAN FILE

OWNER M. Newman

DESCRIPTION- 2 STORY fr USE dwell-ad

PERMIT No. DATE 19 PLAN FILE

OWNER

DESCRIPTION- STORY USE

F. & W. Co., Buffalo

LOCATION 72 North St

PERMIT NO. 67139 DATE 9/21/21

OWNER Jos. B. Hoffner

DESCRIPTION 1 str. fr. pr. gar.

YAWMAN & ERBE MFG. CO., ROCHESTER AND BUFFALO

LOCATION 72 North

PERMIT NO. 65082 DATE 12/31/73

OWNER CITY OF BUFFALO - Northern Demolition

DESCRIPTION Demolish to grade 2 1/2 story frame building.

PWB-308

(aka North)

LOCATION 12,14,16,18,20 Jaktram DATE 10/3/80

OWNER Pilgrim Village Assoc.

ADDRESS P.O. Box 1435
Niagara Falls, NY 14035

CONTRACTOR A.F.O. Electric

DESCRIPTION OF WORK Twonhouses - Service (5) 100 A, lights & plugs, 5 ranges, 5 dryers, 5 exhaust fans.

CONDITIONS

VALUE

FEE $34.00 ck.

PLAN FILE #

ELECTRICAL PERMIT #E 14374

2, 4, ~~6~~, 8, 10 Jaktram Cr.

LOCATION ~~76, 78, 80, 82, 84~~ E. North DATE 8/26/80

OWNER Pilgrim Village Assoc.

ADDRESS P.O. Box 1435
NIagara FAlls, NY

CONTRACTOR A.F.O. Electric

DESCRIPTION OF WORK 2-2fam. town houses, 1-1 fam. res
Service (5) 100 amp, 5 ranges, 5 dryers, 5 exhaust fans, lights & plugs

CONDITIONS

VALUE

FEE $34.00 ck.

PLAN FILE #

ELECTRICAL PERMIT #E 14083

LOCATION 76 North

PERMIT NO. 65082 DATE 12/31/73

OWNER CITY OF BUFFALO - Northern Demolition

DESCRIPTION Demolish to grade 2 story frame building.

FWB-308

LOCATION 80 E. North

PERMIT NO. 51535 DATE May 8 1917

OWNER Mazie A. Winkler

DESCRIPTION 1 s.fr. gr. gar.

~1/3~

LOCATION 80 E. North

PERMIT NO. 63005 DATE 8/7/73

OWNER City of Buffalo, Urban Renewal

DESCRIPTION Dem. 1½ sty fr. dwlg.

PWB-308

LOCATION 80 E North

PERMIT NO. RO 54029 DATE July 12, 1954

OWNER Mrs. Sophie Restino

DESCRIPTION Alt & rep sun room 1st flr 2 fmly dwlg $100

PWB-308

LOCATION 80 E. North St.

PERMIT NO. RO 50624 DATE Oct. 19, 1951

OWNER Chas. Campanella

DESCRIPTION Conv. & alt. frame 1 to 2 fmly dwlg. $1000.

PWB-308

LOCATION- 82 E. North St

PERMIT No. 8299 DATE apl 6 5 1897. PLAN FILE

OWNER Barbara Miller

DESCRIPTION- 2 STORY fr . USE dwlg

PERMIT No. DATE 189 PLAN FILE

OWNER

DESCRIPTION- STORY . USE

W., Buffalo, N. Y.

LOCATION- 82 E. North St

PERMIT No. 8299 DATE apl 6 5 1897. PLAN FILE

OWNER Barbara Miller

DESCRIPTION- 2 STORY fr . USE dwlg

PERMIT No. DATE 189 PLAN FILE

OWNER

DESCRIPTION- STORY . USE

V. & W., Buffalo, N. Y.

LOCATION 82 North

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ sty 3 family frame dwelling.

See card for Oak St. Redevelopment

FWB-308

LOCATION 84 E. North St

PERMIT No. 6688 DATE Mar 4 19 6 PLAN FILE

OWNER E. M. Haberstroe

DESCRIPTION 2 STORY fr USE dwell

PERMIT No. DATE 19 PLAN FILE

OWNER

DESCRIPTION STORY USE

F. & W. Co., Buffalo

LOCATION 84 North St.

PERMIT NO. 7070 DATE MAY 24 1912

OWNER Henry Klauck

DESCRIPTION erect cellar wall

TUSTIN AND FAST MFG. CO. ROCHESTER AND BUFFALO

LOCATION 84-86 North

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ sty 2 family frame dwelling and garage.

See card for Oak St. Redevelopment

FWB-308

LOCATION 86 E. North

PERMIT NO. 4384 E DATE 9/28/26

OWNER Patrick J. Garvey

DESCRIPTION concrt block garage storage, office & dwelling

LOCATION 86 E. North St.

PERMIT NO. 6010 DATE 3/10/27

OWNER Patrick J. Garvey

DESCRIPTION stucco frame porch

C-129

LOCATION 86 E. North St.

PERMIT NO. 30951 DATE 11/7/46

OWNER P. J. Garvey, Inc.

DESCRIPTION Enlarge masonry building for storage. $5000.

FMB-208

LOCATION 86 E. North St.

PERMIT NO. 40361 DATE 10/2/47

OWNER C. P. Garvey

DESCRIPTION Place 1-1000 gal. steel tank for private gasoline storage. $200.

FMB-208

LOCATION 86 E. North

PERMIT NO. 53950 DATE 7-6-55

OWNER P.J. Garvey

DESCRIPTION Alter, enlarge fr. offices 20' x 10' x 13' $3500.

FMB-208

LOCATION 86 East North

PERMIT NO. BP 55922 DATE 10/31/55

OWNER P. J. Garvey

DESCRIPTION Demolish to grade, frame 2 fmly. dwlg. $600

FMB-208

ADDRESS 86 E. North St.,

OWNER C. P. Garvey

ADDRESS 86 E. North St.,

CONTRACTOR Elmwood Elec. & Pump Corp.,

ADDRESS 810 Elmwood Ave.,

DATE 8/5/46 19 APPLICATION NO. 24703

Place & Use (1) 1000 gal. Steel Gasoline Storage Tank, Lot 37.5' x 140'

PLAN FILE NO. $500.00

No. A 25935

ADDRESS 86 E. North St.,

OWNER P. J. Garvey

ADDRESS 465 Cornwall Ave.,

CONTRACTOR Same

ADDRESS -

DATE 9/15/66 19 APPLICATION NO. 33683

Use 2 sty. Mary. Bldg. - Auto Repair Shop Lot 37.5' x 140' Use 77.30' x 37.50' = 2,

PLAN FILE NO. ----

No. A 33683

LOCATION 86 North Drive DATE 11/3/80

OWNER Joseph Darnat

ADDRESS Same

CONTRACTOR Owner

DESCRIPTION OF WORK 1 fam. res. - 13 lights & plugs

CONDITIONS

VALUE FEE $7.00 ea.

PLAN FILE #

ELECTRICAL PERMIT # E 14619

90-96 North (6-14 Welmont)

63516 DATE 9-10-73

City of Buffalo - Northern Demolition

Dem to grade 2½ sty 15 fam dwlgs.
2 bldgs.

See card for Oak St. Redevelopment

LOCATION 90 E. North

PERMIT NO. 63005 DATE 8/7/73

OWNER City of Buffalo, Nrban renewal

DESCRIPTION Dem. 2 sty fr dwlg.

PWB-308

ADDRESS 108-110 E. North St.,

OWNER Irving Rubin

ADDRESS 612 Brisbane Bldg.

CONTRACTOR Owner

ADDRESS

DATE 1/25/67 19__ APPLICATION NO. 100996

Alt.exist. 3 sty. Fr. 6-fam Cl. Tenmt & Stores erected in 1887 & apprvd. under plans filed in Hlth Dept. 1929 to comply w/HBO. Case 31,769 Hst. Appl. withdrawn. Plans to be filed. Work to be done in accd. w/ltr/ 2/10/66 from Supv. of Rehab. & Conser $800.00

PLAN FILE NO.

No. A 34990 C. of O. #1986 - 1/26/67

LOCATION 110 E North

PERMIT NO. 57294 DATE 4/4/72

OWNER See card for Oak St. Development

DESCRIPTION

PWB-308

LOCATION 114 North

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ sty 3 family frame dwlg. and 1 story frame cottage.

See card for Oak St. Redevelopment

FWS-308

LOCATION 116 East North [illegible]

PERMIT NO. 3723 DATE June 6 19 54 PLAN FILE

OWNER Rosa Dodds

DESCRIPTION One STORY Frame USE Dwelling

PERMIT NO. DATE 19 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 116 E. North Street

PERMIT NO. 55276 DATE 8/4/71

OWNER City of Buffalo

DESCRIPTION Dem to gr. 2½ sty fr. 2 fmly dwelling. Under Elm-Oak Redev. N. Y. R. 197 Phase 11

FWS-308

ADDRESS 116 E. North Street

OWNER Catherine E. Dolan

ADDRESS 116 E. North Street

CONTRACTOR Raitt Builders, Inc.

ADDRESS 268 Voorhees

APPLICATION

DATE June 13, 19 58 NO. 76195

Repr 2 fmly fr dwlg-Rear Shed
No struct'l. chgs. $400

PLAN FILE NO.

PERMIT No. A 8040

CATION 118 North

MIT NO. 63516 DATE 9-10-73

ER City of Buffalo - Northern Demolition

RIPTION Dem to grade 2 - 1½ story 2 family frame dwellings.

See cardfor Oak St. Redevelopment

-308

LOCATION 120 E. North

PERMIT NO. 57294 DATE 4/4/72

OWNER See card for Oak St. Development

DESCRIPTION

PWB-308

LOCATION 124 E. North St

PERMIT NO. 5135 DATE 1/17/89 190 PLAN FILE

OWNER Walbridge Schifferle Enlarge

DESCRIPTION 1 STORY fr USE dwlg

PERMIT NO. DATE 190 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 124 E North St.

PERMIT NO. 56743 DATE APR 21 1919

OWNER Walberga Schifferle

DESCRIPTION 1-1 S. fr. chicken coop.

LOCATION 124 - East North St

PERMIT NO. 2671 DATE June 18 08 PLAN FILE Enlarge

OWNER Bertha H. Schifferle

DESCRIPTION 2 STORY fr USE dwell K

PERMIT NO. DATE 190 PLAN FILE

OWNER

DESCRIPTION STORY USE

K

LOCATION 124. E. North st

PERMIT NO. 23475 DATE Nov 13 26 PLAN FILE Enlarge

OWNER Walbergia Schifferle

DESCRIPTION 2 STORY fr USE dwelling

PERMIT NO. DATE 189 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 124-126 E. North (800 Elm)

PERMIT NO. A 54393 DATE 5/25/71

OWNER City of Buffalo

DESCRIPTION Dem.to gr. (2) 2½sty. & (1) 1½ sty. fr. 8-fm.dwlgs. under Elm-Oak Redev. Proj. NYR 197 Phase I

(see application for entire list of bldgs.covered by this Phase)

PMB-306

LOCATION 126 E North
PERMIT NO. 61064 DATE APR 30 1920
OWNER Mrs Sarah Horner
DESCRIPTION 1 s. fr. pr. garage

LOCATION Rear 126 E North St
PERMIT No. 18811 DATE Oct 21 1926 PLAN FILE
OWNER Minnie Timmons
DESCRIPTION— 1 STORY fr USE Hen Coops
PERMIT No. DATE PLAN FILE
OWNER
DESCRIPTION— STORY USE

LOCATION 126 E. North St
PERMIT NO. 14567 R.O. DATE 7/17/22
OWNER Horner
DESCRIPTION build cellar under fr. 1 fam. dwlg.

LOCATION 126 E. North St.
PERMIT No. R023280 DATE May 16, 1932
OWNER Sarah Horner
DESCRIPTION Repair open porch.

LOCATION 126 E. North St.
PERMIT No. 24110 DATE August 6, 1932
OWNER Saraha Honer
DESCRIPTION Enlarge frame building bedroom addition.

LOCATION 126 E. North St.
PERMIT No. 24200 DATE August 24, 1932
OWNER Sarah Horner
DESCRIPTION Raise roof and frame addition to dwelling.

I-163

LOCATION 126 E. North
PERMIT No. DATE 6/17/33.
OWNER Sarah Horner
DESCRIPTION Convert ④ fmly Tenement

LOCATION 126 E. North St.
PERMIT No. R024382 DATE June 30, 1933
OWNER Sara Horner
DESCRIPTION Build dormer in roof of frame dwelling.

LOCATION 128 E. North Street

PERMIT NO. 61087 DATE 4/3/24

OWNER John O. Kibler

DESCRIPTION 1 story frame private garage

LOCATION 128 E. North

PERMIT NO. 4553 DATE May 6 '08 PLAN FILE

OWNER Edward Dreg-
Alb. Miller

DESCRIPTION 2 STORY fr USE dwell

PERMIT NO. DATE PLAN FILE

OWNER

DESCRIPTION STORY USE

1K

LOCATION 128 North

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ sty 2 family frame dwlg

See card for Oak St. Redevelopment

FWB-308

LOCATION 132 E. North St.

PERMIT NO. RO 43719 DATE 12/16/46

OWNER Louis Miller

DESCRIPTION Build part cellar - frame store and two family dwelling. $700.

LOCATION 132 E. North St.

PERMIT NO. 77118 DATE 5/28/23

OWNER John H. Bedrer

DESCRIPTION 1 str. conc. bl. pr. garage

LOCATION 132 North

PERMIT NO. 63516 DATE 9-10-73

OWNER city of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ story 2 family frame dwelling and store

See card for Oak St. Redevelopment

FWB-308

LOCATION 57-65 Holloway DATE 6/25/81
OWNER Pilgrim Village Assoc.
ADDRESS P.O. Box 1435
Niagara falls, NY
CONTRACTOR National Energy Action
DESCRIPTION OF WORK 1 fam. res.'s - Service (5) 100 amp. lights & plugs, 5 ranges, 5 dryers, 5 exhaust fans.
CONDITIONS
VALUE FEE $50.00 ck.
PLAN FILE #

ELECTRICAL PERMIT # E 16305

LOCATION 34 Halloway Blvd. DATE 6/25/81
OWNER Pilgrim Village Assoc.
ADDRESS P.O. Box 1435
Niagara Falls, NY
CONTRACTOR National Energy Action
DESCRIPTION OF WORK Storage shed - Wiring for shed - not in excess of 5000 W
CONDITIONS
VALUE FEE $7.50 ck.
PLAN FILE #

ELECTRICAL PERMIT # E 16303

LOCATION 36 Hollaway DATE 12/18/81
OWNER Pilgrim Village
ADDRESS
CONTRACTOR Dobson Electric
DESCRIPTION OF WORK Res. - Service 30 A, 2 lights & plugs, meter @ bldg. 18, services, exterior lights and sump pumps for bldgs. 4,5,6,18
CONDITIONS
VALUE FEE $7.50 ck. & ca.
PLAN FILE #

ELECTRICAL PERMIT # E 17905

LOCATION 20 Holloway DATE 12/18/81
OWNER Dobson Electric
ADDRESS
CONTRACTOR Dobson Electric
DESCRIPTION OF WORK Housing - Mater @ Bldg. #7, service exterior lighting and sump pumps for bldgs. 7,8,9 - 16
CONDITIONS
VALUE FEE $7.50 ck. & ca.
PLAN FILE #

ELECTRICAL PERMIT # E 17901

LOCATION 35-47 Holloway DATE 6/25/81
OWNER Piligirm Village
ADDRESS P.O. Box 1435
Niagara Falls, NY
CONTRACTOR National Energy Action
DESCRIPTION OF WORK 1 fam. res.s' - Service (7) 100 A lights & plugs, 7 ranges, 7 dryers, 7 exhaust fans.
CONDITIONS
VALUE FEE $70.00 ck.
PLAN FILE #

ELECTRICAL PERMIT # E 16304

LOCATION 2,4,6,8,10 Holloway DATE 8/26/80
OWNER Pilgrim Village Assoc.
ADDRESS P.O. Box 1435
Niagara Falls, NY 14305
CONTRACTOR A.F.O. Electrical
DESCRIPTION OF WORK 2-2 fam., 1-1 fam. res. - Service (5) 100 amp, lights & plugs, 5 ranges, 5 dryers, 5 exhaust fans.
CONDITIONS
VALUE FEE $34.00 ck.
PLAN FILE #

ELECTRICAL PERMIT # E 14082

LOCATION 20-28 Holloway Blvd DATE 3/6/81
OWNER Pilgrim Village Assoc.
ADDRESS P.O. Box 1435
Niagara Falls, NY 14305
CONTRACTOR National Engrgy
DESCRIPTION OF WORK 2 fam. res. - Service (5) 100 A, lights & plugs, 5 dryers, 5 exhuast fans
CONDITIONS
VALUE FEE $34.00 ck.
PLAN FILE #

ELECTRICAL PERMIT # E 15384

LOCATION 15 Holloway Alley DATE May 14, 1976
OWNER James D. DiLapo Sr.
ADDRESS 166 Rumsey Road
Bflo. N.Y.
CONTRACTOR owner X
DESCRIPTION OF WORK Rep.lstry.msry.gar. restore & repl. exist. gar.w/msry.materials
CONDITIONS
VALUE $3000.00 FEE $30.00
APPLICATION # 145541 PLAN FILE #

BUILDING PERMIT # B04717

ADDRESS 69 St. Paul St.,
OWNER Joseph Battaglia
ADDRESS 69 St, Paul St.,
CONTRACTOR A.C.E. Genl. Contr.
ADDRESS 150 W. Utica St.
DATE 7/31/63 19 APPLICATION NO. 93379
Rep. 2 sty. 2-fam. Frame Dwelling
Repair damage to front of dwelling, interior & exterior. NO structural changes. $200.00
PLAN FILE NO.

No. A 24301

LOCATION 69 St.Paul St.
PERMIT NO. 9584 DATE 10/21/69
OWNER F.T. Catalano
DESCRIPTION

FWB-306

ADDRESS 72 St. Paul St.,
OWNER Willie J. Berry
ADDRESS 72 St. Paul St.,
CONTRACTOR Owner
ADDRESS
DATE 7/9/62 19 APPLICATION NO. 89001
Rep. 1½ sty. 1-fam. Frame Dwlg.
General repairs to frame bldg. NO str. chgs.
PLAN FILE NO. $800.00

No. A 20463

LOCATION 71 St. Paul St.
PERMIT NO. 55276 DATE 8/4/71
OWNER City of Buffalo
DESCRIPTION Dem to gr. 2 sty fr. 2 fmly dwelling. Under Eln-Oak Redelvelpoment Project N. Y. R. 197 Phase 11

FWB-306

ADDRESS 72 St. Paul Street
OWNER Willie J. Berry
ADDRESS 72 St. Paul Street
CONTRACTOR Owner
ADDRESS Same
DATE 10-19-66 19 APPLICATION NO. 101188
Alt. & Rep. 1½sty.1-family frame dwelling. Repair & remodel int. & add two dormers. NO str.chgs.
PLAN FILE NO. $1,000.00

No. A 34159

LOCATION 72 St. Paul
PERMIT NO. 84331 DATE 5/13/24
OWNER John F. Gralis
DESCRIPTION 1 story frame private garage

LOCATION 73 St. Paul

PERMIT No. DATE 5/16/38

OWNER Maude Barrett

DESCRIPTION Convert Rooming House

LOCATION 73 Saint Paul St.

PERMIT No. 20252 R.O. DATE 6/20/28

OWNER J. C. Barrett

DESCRIPTION Build dormer.

LOCATION 73 St. Paul

PERMIT NO. 30832 DATE 11/1/23

OWNER Maude E. Barrett

DESCRIPTION 1 str. br. pr. garage

LOCATION- 73 St Paul St

PERMIT No. 17199 DATE Feby 29 1924 PLAN FILE

OWNER Christian Flierl (remodel)

DESCRIPTION- 1½ STORY frame USE dwelling

PERMIT No. DATE 19 PLAN FILE

OWNER

DESCRIPTION- STORY USE

No. 73 St. Paul St.

PLAN NO.	PLUMBER	FILED	FINAL
6156	P.K. Montgomery	4-8-40	done
1299	P.J. Donovan	5-28-53	✓

P.W.B. 510

BR

No. 8 WELMONT St.

PLAN NO.	PLUMBER	FILED	FINAL
38886	FIORELLA	9-8-50	

LOCATION 6-14 Welmont (90-96 North)

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ sty 15 family frame dwlgs. 2 bldgs.

See Oak St. Redevelopment

FWB-308

LOCATION 9 Welmont St.

PERMIT NO. 62604 DATE 7-17-73

OWNER Urban Renewal (Demo of Buffalo)

DESCRIPTION Demo 2 fam 2½ sty frame dwelling

SEE CARD FOR OAK ST. REDEVELOPMENT

FWB-308

LOCATION 9 Welmont St.

PERMIT NO. 62604 DATE 7-17-73

OWNER Urban Renewal (Demo of Buffalo)

DESCRIPTION Demo 1 sty fr garage

SEE CARD FOR OAK ST. REDEVELOPMENT

FWB-308

ADDRESS 9 Welmont St..

OWNER Angelo Rodrigues

ADDRESS 9 Welmont St..

CONTRACTOR S.S.S G. Const. Co..

ADDRESS 1006 Prudential Bldg.

DATE 4/14/65 19 APPLICATION NO. 9834

Repair, Alter 1½ sty. 1-fam. Frame Dwelling Repair fire damage. NO structural changes.

PLAN FILE NO. $600.00

No. A 29439

ADDRESS 9 Welmont Place

OWNER Wm. Rodrickris

ADDRESS 9 Welmont Place

CONTRACTOR Ken Thomas Const.

ADDRESS 483 Loretta Avenue

DATE April 2 19 59 NO. 78660

Repr 1 fmly fr dwlg. Gen repra.

PLAN FILE NO. $320

RMIT A 10468

ADDRESS 9 Welmont Pl.

OWNER Angelo Rodrigues

ADDRESS Same

CONTRACTOR Same

ADDRESS

DATE 8-14-57 19 APPLICATION NO. 78337

Repr. fr. 1 fmly. dwlg.,rebuild fr.shed. $800.

PLAN FILE NO.

PERMIT No. A 4279

P.W.B. 510

No. 10 Welmont St.

PLAN NO.	PLUMBER	FILED	FINAL
29328	A Fiorilla	11-20-50	✓

LOCATION 13 Welmant St.

PERMIT NO. 62604 DATE 7-17-73

OWNER Urban Renewal (Demo of Buffalo)

DESCRIPTION Demo 1 fam 1½ sty fr dwelling

SEE CARD FOR OAK ST. REDEVELOPMENT

PMB-308

LOCATION 13 Welmont

PERMIT NO. 87998 DATE 10/30/24

OWNER Albert Windesch

DESCRIPTION 1 story frame private garage

LOCATION 13 Wellmont Pl.

PERMIT NO. 8483 DATE 10-11-60

OWNER Fred Tuhl & Sons.

DESCRIPTION

PMB-308

ADDRESS 16 Welmont Pl.,

OWNER Betty Miano DEMOLISHED

ADDRESS 1753 Bertel Ave.,

CONTRACTOR Owner

ADDRESS -

DATE 12/13/66 19 APPLICATION NO. 103798

Demolish to grade, 1½ sty. Frame 2-family Bldg. future use - vacant. (By owner only) Sewer & water connections cut off as per code.

PLAN FILE NO. $800.00

No. A 34715

LOCATION 16 Welmont Place

PERMIT NO. 7250 DATE Jan 19-1906 PLAN FILE

OWNER Eugene P. Dewitt Eulogy & Mon

DESCRIPTION 1 STORY Fr USE dwelling

PERMIT NO. DATE 189 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 17 Welmont

PERMIT NO. 65082 DATE 12/31/73

OWNER CITY OF BFLO. - Northern Demolition

DESCRIPTION Demolish to grade a 1 1/2 story frame building.

PMB-308

LOCATION 17 Welmont Pl.

PERMIT NO. R037100 DATE March 30, 1942

OWNER Karl Winter

DESCRIPTION Repair frame dwelling.

LOCATION 19 Welmont Pl.
PERMIT NO. 35463 DATE 8/3/43
OWNER C. Ayres
DESCRIPTION Frame addition to dwelling.
12x14x7.

LOCATION 19 Welmont
PERMIT NO. A 54393 DATE 5/25/71
OWNER City of Buffalo
DESCRIPTION Dem.to gr. 1½sty.fr.2-fm.dwlg.under Elm-Oak Redev.Proj. NYR 197 Phase I
(see application for entire list of bldgs.covered by this Phase)
FWB-308

LOCATION 21 Welmont
PERMIT NO. 59085 DATE 9/1/72
OWNER See card for Oak St. Redevelpment
DESCRIPTION
FWB-308

LOCATION 21 Welmont Pl.
PERMIT NO. 18997 R.O. DATE 10/5/26
OWNER George F. Streigel
DESCRIPTION cut dormer windows & make necessary repairs

LOCATION 22 Welmont Pl.
PERMIT NO. 55276 DATE 8/4/71
OWNER City of Buffalo
DESCRIPTION
Dem to gr. 1½ sty fr. 1 fmly dwelling
Under Elm-Oak Redev. Project N. Y. R.
197 Phase II
FWB-308

ADDRESS 22 We lmont Pl.
OWNER George & Esther Ward
ADDRESS 22 Welmont Pl.
CONTRACTOR Same
ADDRESS Same
DATE June 24, 19 58 APPLICATION NO. 76351
Repr. 1 fmly. fr. dwlg.
No structural changes $150
PLAN FILE NO.
PERMIT No. A 8168

LOCATION 22 Welmont Pl.
PERMIT No. R037587 DATE 6/17/42
OWNER Ivan Flemerfeldt
DESCRIPTION Alter frame dwelling.

LOCATION 23 Welmont Pl
PERMIT NO. RG 12231 DATE SEP 17 1919
OWNER Mary Nussbaum
DESCRIPTION 1 s fr add 1 fam dwlg

~183~

LOCATION 23 Welmont Street
PERMIT NO. 62942 DATE 8/1/73
OWNER Urban Renewal Northern Demo
DESCRIPTION See card for Oak St. Redevelopment

PWB-308

LOCATION 24-26 Welmont
PERMIT NO. 59085 DATE 9/1/72
OWNER See card for Oak St. Redeveopment
DESCRIPTION

PWB-308

LOCATION 24-26 Welmont Place
PERMIT NO. R038399 DATE 1/18/43
OWNER Sarah E. Miller Estate
DESCRIPTION Alter and convert frame tenement. 8-10.

LOCATION 24-26 Welmont Pl.
PERMIT NO. R036839 DATE January 15, 1942
OWNER Sl.t E. Miller Est.
DESCRIPTION Alter and convert for a tenement.

New LOCATION 26 Welmont.
PERMIT NO. 52431 DATE Aug. 2-1917
OWNER Ernest Miller.
DESCRIPTION 1 Story frame
Private Garage.

~183~

LOCATION 24-26 Welmont Place
PERMIT NO. 2794 DATE Nov 24 68 BD PLAN FILE
OWNER Chas F. Miller
DESCRIPTION 2 STORY Fr 4 Fam tenement
PERMIT NO. DATE BD PLAN FILE
OWNER
DESCRIPTION STORY USE

K

LOCATION 27 Welmont

PERMIT NO. 57497 DATE

OWNER Mrs Catherine Cooper

DESCRIPTION Add 1 s. fr. kitchen

LOCATION 27,27½ Welmont

PERMIT NO. 58422 DATE 7/6/72

OWNER Urban Renewal

DESCRIPTION Dem. 2 ½ story 2 fam. fr. dwlgs
Oak Street Development

FHB-308

LOCATION 30 Welmont Pl.

PERMIT NO. 55276 DATE 8/4/71

OWNER City of Buffalo

DESCRIPTION Dem to gr. 2½ sty fr. 3 fmly dwelling.
Under Elm-Oak Redev. Project N. Y. R.
197 Phase II

FHB-308

ADDRESS 30 Welmont St.

OWNER Harry Simmons

ADDRESS 39 Kingsley Ave.

CONTRACTOR Kenwood Bldrs.

ADDRESS 280 Delaware Ave.

DATE 3/15/43 19 APPLICATION NO. 91037

Rep. 2½ sty. 2-fam. frame dwlg.
Replace open front porch. Ex str. chgs.

PLAN FILE NO. 2905.00

No. A 22360

LOCATION 30 Welmont

PERMIT NO. 7[illegible]8 DATE 8/18/23

OWNER Mrs. Ida Schultz

DESCRIPTION 1 str. br. pr. garage

LOCATION 31 Welmont Pl.

PERMIT NO. 73236 DATE 10/8/32

OWNER Conrad Medler

DESCRIPTION 1 str. fr. pr. garage

LOCATION 31 Welmont

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ story 2 family frame dwelling

See card for Oak St Redevelopment

FHB-308

LOCATION 31 Welmont Pl.

PERMIT NO. 8030802 DATE April 17th, 1939

OWNER Conrad Medler Estate

DESCRIPTION alter frame dwelling

TENEMENT HOUSE
No. 31 Welmont St.

PLAN NO.	PLUMBER	FILED	FINALED
C1C141	Chas Bellit	11/4/38 P	[illegible]
5721-C	" "	4-11-39	[illegible]
2365	A Wilcox	2-8-54	✓

LOCATION 32 Welmont

PERMIT NO. 58422 DATE 7/6/72

OWNER Urban Renewal

DESCRIPTION Dem 2 sty 2 fam. fr. dwlg
Oak Street Development

FWB-308

LOCATION 32 Welmont St.

PERMIT NO. RO 45062 DATE 10/30/47

OWNER Jos. Harrington

DESCRIPTION New open front porch - frame
two family dwelling. $500.

FWB-308

LOCATION 32 Welmont Pl.

PERMIT NO. RO37663 DATE 6/30/42

OWNER Rev. Joseph Harrington

DESCRIPTION Build upper deck

LOCATION 32 Welmont Place

PERMIT NO. 7198 DATE Feby 29 1924 PLAN FILE

OWNER Christian Fleet

DESCRIPTION 2 STORY Frame USE dwelling (2 fam)

PERMIT NO. DATE 19 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 33 Welmont Pl

PERMIT NO. RS 4842 DATE NOV 14 1908 PLAN FILE

OWNER Joseph Leinart

DESCRIPTION Repair Cellar Wall & Shed

PERMIT NO. DATE 19 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 37 Welmont St.

PERMIT NO. 14688 DATE 6/25/71

OWNER Simon Elec. Co.

DESCRIPTION

FWB-308

LOCATION 37 Welmont

PERMIT NO. 60336 DATE 12/14/72

OWNER Oak St. Redev.

DESCRIPTION

LOCATION 41 Welmont
PERMIT NO. 76358 DATE 5/4/23
OWNER Otto Schmitt
DESCRIPTION enl. 1 str. fr. priv. garage

near
LOCATION 41 Welmont Pl.
PERMIT NO. 57135 DATE MAY 17 1919
OWNER Otto Schmuck
DESCRIPTION 1 1/2 fr. Pr. Garage

LOCATION 42 Welmont
PERMIT NO. 60336 DATE 12/14/72
OWNER Oak St. Redev.
DESCRIPTION

FWB-308

LOCATION 42 Welmont
PERMIT NO. 73335 DATE 10/6/22
OWNER Wm. J. Chapman
DESCRIPTION 1 str.fr. pr. garage

LOCATION 43 Welmont
PERMIT NO. 65082 DATE 12/31/73
OWNER CITY OF BFLO. - Northern Demolition
DESCRIPTION Demolish to grade a 2 1/2 story frame & 1 1/2 story frame buildings.

FWB-308

LOCATION 43 Welmont
PERMIT NO. 17640 R.O. DATE 6/13/25
OWNER Otto Schmidt
DESCRIPTION encloseveranda front frame 1 family dwelling

LOCATION 43 Welmont Pl
PERMIT NO. R.O. 12957 DATE AUG 4 1920
OWNER Otto Smith
DESCRIPTION 1 s. fr. addition

LOCATION 43 Welmont Place
PERMIT NO. 29018 DATE 6/8/09 19[illegible] PLAN FILE
OWNER Otto Quick
DESCRIPTION 2 STORY Fr USE Dwell
& Barn Frame House & Barn 1/2 Brick
PERMIT NO. DATE 19[illegible] PLAN FILE
OWNER
DESCRIPTION STORY USE
2

ADDRESS 44 Welmont St.
OWNER Elaine Kesterson
ADDRESS 44 Welmont
CONTRACTOR Welts Tree Serv.
ADDRESS 69 Cemetery Rd., Lanc.
DATE 1/6/71 19__ APPLICATION NO. 123084
Dem. to gr. 1½sty.2-fa.br.&fr.dwlg. Fut.use-vac.
PLAN FILE NO. $1,099.00
No. A 53065

LOCATION 145 Helmont Pl
PERMIT No. 9137 DATE Dec 13 1917 PLAN FILE
OWNER Sophia Mayers
DESCRIPTION 1½ STORY fra USE dwell
PERMIT No. DATE PLAN FILE
OWNER
DESCRIPTION STORY USE

LOCATION 145 Helmont Place
PERMIT No. 14376 DATE June 20 1922 PLAN FILE
OWNER Mary Mayers (addn)
DESCRIPTION 1½ STORY frame USE dwelling & garage
PERMIT No. DATE PLAN FILE
OWNER
DESCRIPTION STORY USE

LOCATION 45 Welmont
PERMIT NO. 65082 DATE 12/31/73
OWNER CITY OF BFLO. - Northern Demolition
DESCRIPTION Demolish to grade a 2 story frame building.
PWB-208

LOCATION 46 Welmont
PERMIT NO. 63516 DATE 9-10-73
OWNER City of Buffalo - Northern Demolition
DESCRIPTION Dem to grade 2½ story 2 family frame dwelling
See card for Oak St. Redevelopment
PWB-208

ADDRESS 46 Welmont St.-rear
OWNER Ada Upson & Mrs. James Porter
ADDRESS 100 Oakland Pl.
CONTRACTOR Amber Trucking Inc.
ADDRESS 177 Gruner Rd., Cheektowaga, N.Y.
DATE 3/31/66 19__ APPLICATION NO. 100324
Demolish to grade 1½ sty. 1 fam. Frame Dwlg.
Future use- vacant. $170.00
PLAN FILE NO.
No. A 31839

LOCATION 46 Welmont St
PERMIT NO. 36602 DATE 4-20-45
OWNER Est. Conrad Hedler
DESCRIPTION Use part 1-st. fr. bldg. beauty shop

LOCATION 46 Welmont Pl.
PERMIT No. R037800 DATE 7/23/42
OWNER C. Hedler Estate
DESCRIPTION Repair frame dwelling.

LOCATION 46 Welmont

PERMIT NO. 317 DATE 11/21/56

OWNER Albert Wilson

DESCRIPTION

FMB-308

LOCATION 46 Welmont Pl

PERMIT NO. 19616 DATE Apl 11 19 0 PLAN FILE

OWNER Jno Hyrchko

DESCRIPTION 2 STORY frame USE dwell. &c

PERMIT NO. DATE 19 PLAN FILE

OWNER

DESCRIPTION STORY USE

New LOCATION 46 Welmont

PERMIT NO. 57546 DATE

OWNER Conrad Nedler

DESCRIPTION 1 S. fr. 1 fam. dwlg.

LOCATION 47 Welmont

PERMIT NO. 64306 DATE Apr. 8-1921

OWNER Chas. J. J. Miller.

DESCRIPTION 1 story Brick fr. Garage.

LOCATION 47 Welmont

PERMIT NO. 51612 DATE MAY 14 1917

OWNER Charles J. J. Miller

DESCRIPTION 1 s. brick fr. gar.

LOCATION 47 Welmont Pl

PERMIT NO. 19307 DATE Feby 16 19 0 PLAN FILE

OWNER Chas J Miller (and

DESCRIPTION 2 STORY frame USE dwell

PERMIT NO. DATE 19 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 49 Welmont Place

PERMIT NO. 10544 DATE Nov 7 19 3 PLAN FILE

OWNER Charles J. Weller

DESCRIPTION 1 STORY frame USE wood shed

PERMIT NO. DATE 19 PLAN FILE

OWNER

DESCRIPTION STORY USE

LOCATION 47 Welmont

PERMIT NO. 65082 DATE 12/31/73

OWNER CITY OF BFLO. - Northern Demolition

DESCRIPTION Demolish to grade a 2 story frame building.

FMB-308

LOCATION 33 Welmont St.

PERMIT NO. A 54393 DATE 5/25/71

OWNER City of Buffalo

DESCRIPTION Dem.to gr. 1½sty.fr.1-fm.dwlg. under
Elm-Oak Redev. Proj. ~~XXX~~ NYR 197 Phase I

(see application for entire list of
bldgs.covered by this phase)

PWB-308

LOCATION 48 Welmont Pl.,

PERMIT NO. 13544 DATE 12/5/63

OWNER A. Wilson

DESCRIPTION

PWB-308

LOCATION 48 Welmont

PERMIT NO. 8049 DATE 7-18-60

OWNER Corby Plbg. & Htg. Co.

DESCRIPTION

PWB-308

LOCATION 48 Welmont

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 1½ story 1 family frame dwelling

See card for Oak St. Redevelopment

PWB-308

LOCATION 48 Welmont Pl.

PERMIT NO. 4192 DATE 1/8/68

OWNER Simon Electric

DESCRIPTION

PWB-308

ADDRESS Oak St. Redevelopment N.Y.R. (Various addresses)
OWNER City of Buffalo, Urban Renewal
ADDRESS 920 City Hall, Bflo. N.Y.
CONTRACTOR Lehis Contracting Corporation
ADDRESS 261 Massachusetts
DATE August 7, 19[illegible] APPLICATION NO. 132404
Dem. to grade 22 buildings Urban renewal
PLAN FILE NO. $29,900.00
No. 63005

ADDRESS N.Y.R. 197 Oak Street Redevelopment
OWNER Urban Renewal, City of Buffalo
ADDRESS 920 City Hall
CONTRACTOR Northern Demolition
ADDRESS P.O. Box 192 West Seneca
DATE Dec. 14, 1972 APPLICATION NO. 127006
Dem. 8 various building Future use re-development
PLAN FILE NO. $14,650.00
No. 60336

ADDRESS Oak St Redevelopment N.Y.R. 197 Phase II
OWNER Urban Renewal-City of Buffalo
ADDRESS 920 City Hall
CONTRACTOR Albert Ellis Bldg. Co.
ADDRESS P.O. Box 196-Niagara Falls, N.Y.
DATE August 4, 1971 19 APPLICATION NO. 125460
emolish to grade-various Buildings. for Oak st. edevelopment Project. Insurance Approved through rban Renewal Dept. Water & Sewer to be approved y Urban Renewal Dept. PLAN FILE NO. $[illegible],800.00
No. 55276 Rodent Control will approve w/Urban renewal Dept. See attchd. ltr.

ADDRESS Oak St. Redevelopment Urban Renewal Various Streets
OWNER City of Buffalo
ADDRES:
CONTRACTOR Ellis Contracting
ADDRESS 261 Massachusetts Ave.
DATE Sept. 16, 19[illegible] APPLICATION NO. 130451
em. to gr. Oak Street Redevelopment
opwi insurance filed
ruture land use vacant
PLAN FILE NO. $ 29,100.00
68403

ADDRESS Oak Street Redevelopment
OWNER Urban Renewal
ADDRESS 920 City Hall
CONTRACTOR G. N. T. Demolition
ADDRESS 1205 Delaware Avenue
DATE September 1, 1972 APPLICATION NO. 129133
Dem. 14 bldgs. for Oak St Redevelopment
PLAN FILE NO. $29,775.00
No. 59085

ADDRESS Oak Street Development
OWNER Urban Renewal, City of Buffalo
ADDRESS 920 City Hall
CONTRACTOR G. N. T. Demolition
ADDRESS 1205 Delaware Avenue
DATE July 17, 1972 APPLICATION NO. 128624
Dem 6 buildings of Oak St. Redevelopment
PLAN FILE NO. $11,879.00
No. 58522
Oak Street Redevelopment Project

ADDRESS Oak Street Redevelopment NYR 197 Various Addresses
OWNER City of Buffalo, Urban Renewal
ADDRESS 920 City Hall
CONTRACTOR Northern Demolition
ADDRESS P. O. Box 192 West Seneca
DATE August 1, 19[illegible] APPLICATION NO. 130542
o grade 27 parcels for Oak St. Redevelopment
PLAN FILE NO. $30,300.00
2942

ADDRESS Oak Street Redevelopment NYR197-21
OWNER Urban Renewal
ADDRESS 920 City Hall
CONTRACTOR Northern Demolition
ADDRESS P. O. Box 192 West Seneca
DATE Dec. 14, 1972 APPLICATION NO. 129782
Dem. to grade 22 bldgs. Oak Street Project
PLAN FILE NO. $29,386.00
No. 60337

ADDRESS Oak St. Redevelopment NYR 197 various addresses
OWNER Urban Renewal
ADDRESS 920 City Hall
CONTRACTOR G.N.T. Demolition Inc.
ADDRESS 1205 Delaware Avenue, Bflo, NY
DATE April 4, 1972 19 APPLICATION NO. 127318
Demolish to grade Various addresses.
Oak St. Redevelopment NYR 197. see copy att
PLAN FILE NO. $22,190.00
No. 57294

No. 60312

ELECTRICAL PERMIT # E 14086

69,71,73,75,
77,79,81 Best St. 6/26/69
Pilgrim Village Assoc.
P.O. Box 1435
Niagara Falls, NY
A.F.C. Electric
3-2 fam. res., 1-1 fam. res. -
Service (7) 100 amp. lights & power.
7 ranges, 7 dryers, 7 exhaust fans

$60.00 ck.

69 Best St.
13168 8/1/28
S. Benlerem
Frame private garage.

69 Best
66135 5/9/74
City of Buffalo
Northern Demolition
Dem to grade 2½ sty 2 fam & garage

71 Best
63516 9-10-73
City of Buffalo, Northern Demolition
Dem to grade 1½ story 1 family frame dwelling
See card for Oak St. Redevelopment

73 Best St
95429 10/26/22
Mrs. L. Reinhiser
1 str. fr. pr. garage

73 Best
65082 12/31/73
CITY OF BFLO. - Northern Demolition
Demolish to grade a 2 1/2 story frame building.

73 Best St.
2586 June 9, 1930
Ed. Schmidt
frame enclosed porch to dwelling.

75 Best Street
62902 8/1/73
Urban Renewal Northern Demo
See card for Oak St. Redevelopment

93 Best St
2832 9/17/69
Henry Hueler
2 story fr dwlg

93 Best St.
B005113 May 17, 1934
J. A. Beckerle
Build new foundations and repair frame porch.

79 Best Street
60337 12/14/72
Oak Street Redevelopment Project

93 Best St.
13451 9/6/28
Jos. A. Beckerle
Frame private garage.

93 Best
63516 9-10-73
City of Buffalo
Contractor - Northern Demolition
Dem to grade 1½ sty 1 family frame dwelling.
See card for Oak St. Redevelopment



LOCATION 800 Elm
PERMIT NO. A SW393 DATE 5/25/71
OWNER City of Buffalo
DESCRIPTION see card filed under 124-126 E. North for Elm-Oak Redev.Proj. NYR 197 Phase I

LOCATION 804 Elm
PERMIT NO. 63005 DATE 8/7/73
OWNER City of Buffalo, Urban Renewal
DESCRIPTION Demolish, future use, vacant 1½ sty fr dwlg.

LOCATION 806 Elm
PERMIT NO. 63005 DATE 8/7/73
OWNER City of Buffalo, Urban Renewal
DESCRIPTION Demolish, future use, vacant 1½ sty fr dwlg.

LOCATION 806 Elm St..
PERMIT NO. 19994 DATE $1P L- 1920
OWNER Harry Deskel
DESCRIPTION Frame addition to rear shed

LOCATION 808 Elm
PERMIT NO. 63005 DATE 8/7/73
OWNER City of Buffalo, Urban Renewal
DESCRIPTION Demolish, future use, vacant 1½ sty fr dwlg.

LOCATION 808 Elm St.
PERMIT NO. A SW393 DATE 5/25/71
OWNER City of Buffalo
DESCRIPTION Dem.to gr. 2½sty.fr.2-fm.dwlg. under Elm-Oak R.dev.Proj. NYR 197 Phase I
(see application for entire list of bldgs.covered by this Phase)

LOCATION 808 Elm
PERMIT NO. 31764 DATE January 6, 1940
OWNER B. F. Schaller
DESCRIPTION frame addition to dwlg.

LOCATION 810 Elm
PERMIT NO. 66135 DATE 5/8/74
OWNER City of Buffalo
Urban Demolition
DESCRIPTION Dem to grade 2½ sty 3 fam dwlg.

LOCATION 810 Elm St
PERMIT NO. 1879 DATE Aug 2
OWNER Elizabeth Gunnerson
DESCRIPTION 3 story frame dwelling

LOCATION 810 Elm St
PERMIT NO. 4327 DATE Oct 12
OWNER Elizabeth Gunnerson
DESCRIPTION 2½ story frame dwelling

LOCATION 810 Elm St.
PERMIT NO. 17294 B.O. DATE 9/10/25
OWNER Leonard Klefer
DESCRIPTION alter frame 1 family dwelling

LOCATION 810 Elm St.
PERMIT NO. 126928 DATE August 15, 1935
OWNER Leonard Klefer
DESCRIPTION to alter and convert 2½ story bldg.

LOCATION 810 Elm St..
PERMIT NO. 15162 DATE 11/13/64
OWNER A. Wilson
DESCRIPTION

LOCATION 933 Ellicott

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ story 2 family frame dwelling.

See card for Oak St. Redevelopment

LOCATION 903-905 Ellicott

PERMIT NO. 65082 DATE 12/31/73

OWNER CITY OF BFLO. - Northern demolition

DESCRIPTION Demolish to grade a 2 story frame & a 2 1/2 story frame buildings.

LOCATION 917 Ellicott St.

PERMIT NO. R054458 DATE November 27, 1940

OWNER Penn Mut. Life

DESCRIPTION demolish r. factory

LOCATION 901,903,905, 907,909 Ellicott DATE 8/26/80

OWNER Pilgrim Village Assoc.

ADDRESS P.O. Box 1435 Niagara Falls, NY

CONTRACTOR A.F.O. Electric

DESCRIPTION OF WORK 2-2 fam. res. - 1-1 fam. res. - Service (5) 100 amp. lights & plugs, 5 ranges, 5 dryers, 5 exhaust fans.

CONDITIONS

VALUE FEE $34.00 ck.

PLAN FILE #

ELECTRICAL PERMIT # E 14084

LOCATION 937 Ellicott St.

PERMIT NO. 24457 DATE October 25, 1932

OWNER Paul Liptak

DESCRIPTION Use brick building for radio service on autos.

LOCATION 903 Ellicott

PERMIT NO. 63516 DATE 9-10-73

OWNER City of Buffalo - Northern Demolition

DESCRIPTION Dem to grade 2½ story 2 family frame dwelling.

See card for Oak St. Redevelopment

LOCATION 931 Ellicott St.

PERMIT NO. R037057 DATE 3/23/42

OWNER Pepsi Cola Co.

DESCRIPTION Alter brick garage.

LOCATION 931 Ellicott (64 St. Paul) UR

PERMIT NO. 64403 DATE 9/16/74

OWNER City of Buffalo Lebis Contracting

DESCRIPTION Dem 1 story brick commerical bldg.

On same permit # of various bldgs demolished by Oak St. Redevelopment)

186-127

LOCATION 929,931,933, 935, 937 Ellicott DATE 8/26/80

OWNER Pilgrim Village Assoc.

ADDRESS P.O. Box 1435 Niagara Falls, NY

CONTRACTOR A.F.O. Electric

DESCRIPTION OF WORK 2-2 fam. res. , 1 -1 fam. res. - Service (5) 100 amp. lights & plugs, 5 ranges, 5 dryers, 5 exhaust fans.

CONDITIONS

VALUE FEE $34.00 ck.

PLAN FILE #

ELECTRICAL PERMIT # E 14085

LOCATION 909 Ellicott

PERMIT NO. 60337 DATE 12/14/72

OWNER Oak St. Redev.

DESCRIPTION

LOCATION 937 Ellicott St.

PERMIT NO. 25459 DATE September 11, 1933

OWNER Paul Liptak

DESCRIPTION Use brick building for a public garage.

LOCATION 919 Ellicott St.

PERMIT NO. 65341 DATE 4/20/76

OWNER Th. J. Schaut

DESCRIPTION erect 1 story frame 2 car garage

FORM 29

BUFFALO FIRE DEPARTMENT
VOLATILE FLAMMABLE LIQUID
TANK STORAGE AND USE

Gasoline & Alcohol
KIND OF LIQUID - GLASS

APPLICATION [ ]
INSTALLATION [ ]
SURVEY [X]

BATTALION 9th
COMPANY 21
DATE 5/17/45.

COMMISSIONER OF FIRE: John J. Tubridy:

LOCATION 933 Ellicott St.
CITY PROPERTY (curb) [X]
PRIVATE PROPERTY [ ]

NAME Pensicola Co. Garage
ZONED USE DISTRICT

PURPOSE OF USE: Commercial Filling Station
Private Filling Station -x
Private Storage 280 Gal. or less

TYPE OF SYSTEM
PRESSURE [ ]
SUCTION [X]

933 Ellicott

APPLICATION NUMBER DATE
IS LICENSE REQUIRED? ?

PERMIT NUMBER DATE

INSTALLATION: DATE

CONTRACTOR
ADDRESS

TANKS:

one	NUMBER OF
550	CAPACITY OF EACH
550	CAPACITY TOTAL
No	ABOVE GROUND
?	FEET UNDERGROUND
?	FEET FROM BUILDING LINE
?	FEET FROM STREET LINE
?	FEET FROM CELLAR
yes	UNDERWRITERS LABORATORY LABEL

VENT PIPE:

one	NUMBER OF
1"	SIZE
yes	TERMINATES OUTSIDE
12'	FEET ABOVE FILL PIPE
4	FEET FROM BUILDING OPENING
yes	WEATHERPROOF HOOD
yes	FLAME ARRESTER

FILL PIPE:

yes	LOCATED OUTSIDE
15	FEET FROM BUILDING OPENING
yes	PROTECTED AGAINST DAMAGE

PUMPS:

one	QUANITY
17	FEET FROM BUILDING LINE
1 1/2	FEET FROM STREET LINE
yes	UNDERWRITERS LAB. LABEL

As all tanks, pumps and piping are installed in accordance with the requirements of the City Ordiance and Standards of the National Board of Fire Underwriters, I therefore,

recommend APPROVAL [X]
DISAPPROVAL [ ]

James J. Maloney TITLE Jr. Captain

APPROVED _____ DATE _____
COMMISSIONER OF FIRE

NOTE: INCLUDE REMARKS AND SKETCH OF TANK AND PUMP LOCATION ON OTHER SIDE.

F.B.

DEPARTMENT OF FIRE

City of Buffalo

2nd Batt

INTER DEPARTMENTAL CORRESPONDENCE

TO Fire prevention Bureau DATE Oct 8 1973

SUBJECT underground gasoline tank

FROM ENG Co # 16 4

DEAR SIR:

Abandoned Bld. @ St. Paul + Elliott has a cart pump, underground gasoline tank has probable not been made safe.

about 931-935 Elliott

main Window cleaning

Texaco

10-24-73

owner: according to Erie City Records

931 Elliott Inc.

931 Elliott St. 854-1715

RESPECTFULLY.

Capt Walter Coakley

November 9, 1973

Mr. Robert Moore
920 City Hall
Buffalo, New York

Dear Sir:

It has been brought to the attention of this office that an abandoned gasoline tank is located at 931-935 Ellicott Street

This was formerly the Main Window Cleaning Company which, in the past had a private service station license. It is located on city property and may be bonded by the City. Chapter 29 of the City Ordinance provides for removal of flammable liquid tanks which are not in use.

Please inform the undersigned what action is anticipated by Urban Renewal.

If any further information is desired, please contact Lt. F. J. Schaller at Ext. 498.

Very truly yours

Paul J. Zalewski, Chief
BUREAU OF FIRE PREVENTION

FJS:RC

F. J. Schaller, Lt.

931-35 ELLICOTT ST.

933 ELLICOTT

TANKS--Removed, Watered, or Slushed

Location 931-35 Ellicott St

Removed ✓ Make sure vent is removed.

Slushed ___ Make sure vent is removed at grade or below.

Watered ___ If it is expected to be watered for 3 years, be sure pump is removed and suction and vent capped.

Number of Tanks 1 Sizes 550

Owner of Premises CITY OF BUFFALO

Present or Former Operator Main Window Cleaning ?

Brand Name of Gasoline

Owner of Tank CITY OF BUFFALO

Address CITY HALL

Contractor LEBBIS CONTRACTORS

Address TONY BODOMI 883-0183

Location

Draw sketch of approximate location on property on reverse side. Also, any other pertinent information.

Date Oct 16 - 74

INSTRUCTIONS BELOW THIS LINE FOR OFFICE USE ONLY.

If station had flammable liquid license, notify the Battalion Chief to have company remove from files. If station is still in business, make note on Form 29 of which tank or tanks have been removed, slushed, or watered and date of same.

PZ:RC
5/28/63

Schaller

1760

Byron W. Brown, Mayor

DEMOLITION PERMIT

Department of Permit & Inspection Services

65 Niagara Sq Rm. 301
Buffalo, NY 14202

Department of Permit & Inspection Services

. . . . Building a Better Buffalo

Application Type: Demolition Application

You must contact the Inspector at or at the number listed below prior to starting any work

Application/Permit No.: **219562**

Location: **903 ELLICOTT**

Applicant: EMPIRE BUILDING DIAGNOSTICS INC

SBL No.: 1007100003001100

Land Use:

Census Track: 31.00

Inspector: NONE

Issue Date: 08/31/2015

Processed By: FRANK DIGENNARO

Expire Date:

Fees: $550.00

License No.: DM311-517408

License Type: DEMOLITION GRADE 1

Value: $49,800.00

Plans: No

Description of Work: DEMO 5 2 STORY FRAME MULTIPLE DWELLINGS (BUILDINGS 1,2,3,4 AND 6) IN THE PILGRAM VILLAGE HOUSING COMPLEX. AKA 38 HOLLOWWAY BLVD. *ASBESTOS SURVEY SCANNED*

YOU MUST CONTACT YOUR INSPECTOR PRIOR TO STARTING ANY WORK

CONTRACTOR MUST CONTACT INSPECTOR FOR BASEMENT INSPECTIONS AND FINAL INSPECTIONS

Commissioner, Permit & Inspection Services

Thank you for investing in the City of Buffalo

AND AS SHOWN ON APPLICATION NUMBERED ABOVE. WHICH APPLICATION IS MADE PART OF THIS PERMIT.
*** ALL GENERAL CONTRACTORS AND SUB-CONTRACTORS MUST CARRY A CITY LICENSE ***
ALL WORK PERFORMED AND ANY ASSOCIATED PLANS SUBMITTED FOR THE ISSUANCE OF THIS PERMIT, SHALL COMPLY WITH ALL APPLICABLE STATE AND LOCAL CODES, ORDINANCES AND REGULATIONS.
THIS PERMIT IS VOID IF FOUND TO BE ISSUED IN VIOLATION OF ANY LAW OR ORDINANCE AND CONDITIONS STATED ABOVE.

THIS PERMIT MUST BE DISPLAYED WHERE IT IS VISIBLE FROM THE STREET

Signature of Contact/Contractor _____ Date: 2/27/2023

CITY OF BUFFALO
DEPARTMENT OF
PERMIT & INSPECTION SERVICES

BYRON W. BROWN
Mayor

Catherine Amdur
Commissioner

February 27, 2023

Chris Finn
LaBella Associates | Environmental Analyst
300 Pearl St, Suite 130
Buffalo, NY 14202

RE- Freedom of Information Act Request (FOIA): 903 and 951 Ellicott

Dear Chris,

The Department of Permit & Inspection Services has performed an electronic search of the records and files within the department that pertain to the above-mentioned address.

The department's findings are as follows:

- There are no Demolition/Construction permits on file for 951 Ellicott
- There are no Construction permits on file for 903 Ellicott
- There are no Tank installation/removal permits on file
- Contact the NYSDEC regarding environmental concerns

Please be advised that the electronic search may not have produced all departmental records for the aforementioned address. If you wish to conduct a physical search of our records, please contact our office to schedule an appointment.

If you have questions or comments concerning this matter, please feel free to contact our office at (716) 851-4921.

Very truly yours,

Ron Draffin, Senior Clerk
Permit & Inspection Services

STATE OF NEW YORK
DEPARTMENT OF HEALTH

2364 Corning Tower Governor Nelson A. Rockefeller Empire State Plaza Albany, New York 12237

1. TO THE NEW YORK STATE DEPARTMENT OF HEALTH:

I hereby apply to **Inspect** □ or **Receive Copies** ☒ of the following records (use additional sheets as needed and attach)

All environmental records of concern—examples: violations, spills, leaks, fires, clean-ups, remediation, records of solid/ chemical/ hazardous substance usage, and / or disposal for the following Address: 903 and 951 Ellicott Street Buffalo NY Tax ID: 100.71-3-1.12, 100.71-3-1.11 Owner: MCGUIRE PV HOLDING LP

NAME: Christopher Finn PHONE: ( ) 716-907-0596 EMAIL: cfinn@labellapc.com

FIRM: LaBella Associates DPC

ADDRESS: 300 Pearl Street, Suite 130, Buffalo, New York 14202

SIGNATURE: **Christopher Finn** DATE: 2.23.23

2. TO THE APPLICANT:

-Records Provided

☐ The reproduction costs for the records are $_____. Please forward a check payable to the New York State Department of Health to the address listed above. If we do not receive your payment within **60** days, we will assume that you no longer wish to receive the materials, and they will be sent back to the originating unit. Accordingly, any future requests for information will require an initial deposit before processing.

☐ Records have been (partially, fully) provided. (If not fully provided, date when records are expected to be fully provided:_____).

-Records Not Available

☐ Records cannot be found after a diligent search.

☐ The Department does not maintain records indicated, please contact:_____

-Records Denied or Redacted

I hereby certify that access to the records—or part of the records—have been denied to the applicant for the reason(s) checked below (You may appeal this denial of access in writing within 30 days to the Records Access Appeals Officer, Empire State Plaza, 1455 Corning Tower, Albany New York 12237):

☐ Specifically exempt by other statute(s).

☐ Unwarranted invasion of personal privacy.

☐ Would impair present or imminent contract awards or collective bargaining negotiations.

☐ Are examination questions or answers.
Are inter-agency or intra-agency materials that are not: -statistical or factual tabulations or data
-instructions to staff that affect the public
-final agency policy or determinations; or
-external audits, including but not limited to audits performed by the comptroller and the federal government.

☐ Are trade secrets.

☐ Could, if disclosed endanger the life of any person.

☐ Are compiled for law enforcement purposes and which, if disclosed would:
-interfere with law enforcement investigations or judicial proceedings
-deprive a person of the right to a fair trial or impartial adjudication
-identify a confidential source or disclose confidential information relating to a criminal investigation, or
-reveal criminal investigative techniques and procedures

☐ Would jeopardize an agency's capacity to guarantee the security of its information technology assets, such assets encompassing both electronic information systems and infrastructures.

Department Representative_____ Date:_____

W112579-022323 - Freedom of Information Law Request

Message History (2)

On 2/23/2023 3:33:54 PM, New York DEC FOIL Center wrote:

Dear Christopher:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 2/23/2023 and given the reference number FOIL #W112579-022323 for tracking purposes. You may expect the Department's response to your request no later than **3/23/2023**.

Record Requested: **Environmental enforcement, environmental permits, environmental remediation, hazardous materials, solid materials, land use restrictions including and/or engineering controls, law enforcement/ investigation, legal, water, and air, spills/ PBS, BCP, and VCP programs for the following property:**

Address: 903 and 951 Ellicott Street Buffalo NY
Tax ID: 100.71-3-1.12, 100.71-3-1.11
Owner: MCGUIRE PV HOLDING LP

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

Click here to login to the FOIL Center.

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at:
https://newyorkdec.govqa.us/WEBAPP//_rs/RequestEdit.aspx?rid=112579

On 2/23/2023 3:33:53 PM, Christopher Finn wrote:

Request Created on Public Portal

Regulatory Information

DATABASE REPORT

Project Property:	*2231229: Phase I: Pilgrim Village, Sublots 3, 4 & 5, 903 & 951 Ellicott St., Buffalo* *903 and 951 Ellicott Street* *Buffalo NY 14209*
Project No:	*2231229*
Report Type:	*Database Report*
Order No:	*23022300643*
Requested by:	*LaBella Associates*
Date Completed:	*February 24, 2023*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....8
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary by Data Source.....34
Map.....63
Aerial.....66
Topographic Map.....67
Detail Report.....68
Unplottable Summary.....602
Unplottable Report.....606
Appendix: Database Descriptions.....643
Definitions.....658

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*2231229: Phase I: Pilgrim Village, Sublots 3, 4 & 5, 903 & 951 Ellicott St., Buffalo 903 and 951 Ellicott Street Buffalo NY 14209*
Project No:	*2231229*

Coordinates:

Latitude:	*42.90295935*
Longitude:	*-78.86528268*
UTM Northing:	*4,752,249.33*
UTM Easting:	*674,273.88*
UTM Zone:	*UTM Zone 17T*

Elevation: *644 FT*

Order Information:

Order No:	*23022300643*
Date Requested:	*February 23, 2023*
Requested by:	*LaBella Associates*
Report Type:	*Database Report*

Historicals/Products:

City Directory Search	*CD - 2 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Vapor Screening Tool	*Vapor Screening Tool*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
DOE FUSRAP	Y	1	0	0	0	0	0	0
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	**1**	0	**1**
RCRA TSD	Y	0.5	0	0	0	**2**	-	**2**
RCRA LQG	Y	0.25	0	**6**	**2**	-	-	**8**
RCRA SQG	Y	0.25	0	**3**	**1**	-	-	**4**
RCRA VSQG	Y	0.25	0	**1**	**2**	-	-	**3**
RCRA NON GEN	Y	0.25	0	**8**	**11**	-	-	**19**
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
FRP	Y	0.25	0	0	0	-	-	0
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
SHWS	Y	1	0	**1**	0	0	**3**	**4**
DELISTED SHWS	Y	1	0	0	0	0	0	0
HSWDS	Y	1	0	0	0	0	0	0
VAPOR	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	0	**2**	0	-	**2**
LANDFILL INACTIVE	Y	0.5	0	0	0	0	-	0
WASTE TIRE	Y	0.5	0	0	0	0	-	0
RECYCLING	Y	0.5	0	0	0	0	-	0
LST	Y	0.5	0	**10**	**11**	**21**	-	**42**
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	**3**	**3**	-	-	**6**
AST	Y	0.25	0	**4**	**3**	-	-	**7**
TANKS	Y	0.25	0	0	0	-	-	0
MOSF	Y	0.5	0	0	0	0	-	0
CBS	Y	0.25	0	0	0	-	-	0
DELISTED TANKS	Y	0.25	0	**1**	0	-	-	**1**
DELISTED COUNTY	Y	0.25	0	0	0	-	-	0
ENG	Y	0.5	0	**1**	0	**1**	-	**2**
INST	Y	0.5	0	**2**	0	**1**	-	**3**
VCP	Y	0.5	0	0	0	0	-	0
ERP	Y	0.5	0	0	0	**1**	-	**1**
BROWNFIELDS	Y	0.5	**1**	**6**	**2**	**2**	-	**11**
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0
County	***No County databases were selected to be included in the search.***							
Additional Environmental Records								
Federal								
FINDS/FRS	Y	PO	0	**2**	-	-	-	**2**
TRIS	Y	PO	0	-	-	-	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
ERNS PFAS	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	**2**	-	-	-	**2**
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	**1**	**1**
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	**23**	0	-	-	**23**
CONSENT DECREES	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
AFS	Y	PO	0	-	-	-	-	0
SSTS	Y	0.25	0	**2**	0	-	-	**2**
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	**1**	-	**1**
State								
UIC	Y	PO	0	-	-	-	-	0
MGP	Y	1	0	0	0	0	0	0
NY SPILLS	Y	0.5	0	**24**	**21**	**73**	-	**118**
PFAS CONTAM	Y	0.5	0	0	0	0	-	0
PFAS	Y	0.5	0	0	0	0	-	0
PFAS LANDFILL	Y	0.5	0	0	0	0	-	0
DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
NY MANIFEST	Y	0.125	0	**1**	-	-	-	**1**
REC MANIFEST	Y	0.25	0	0	0	-	-	0
GEN MANIFEST	Y	0.125	0	**16**	-	-	-	**16**
E DESIGNATION	Y	0.125	0	0	-	-	-	0
COOLING TOWERS	Y	0.125	0	**11**	-	-	-	**11**
TIER 2	Y	0.125	0	**15**	-	-	-	**15**
PROJECTS	Y	0.25	0	0	0	-	-	0
AIR PERMITS	Y	0.25	0	**3**	**2**	-	-	**5**
LIEN	Y	PO	0	-	-	-	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							
County	***No County additional environmental record sources available for this State.***							
	Total:		***1***	***145***	***60***	***103***	***4***	***313***

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	BROWNFIELDS	Pilgrim Village Redevelopment/Campus Square	903 Ellicott Street Buffalo NY 14209	WNW	0.00 / 0.00	-2	68

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
2	FINDS/FRS	NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT BUFFALO NY 14209 ***Registry ID:*** 110066947380	NW	0.01 / 31.43	-6	70
2	RCRA NON GEN	NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT MH 61ST ST BUFFALO NY 14209 ***EPA Handler ID:*** NYP000972208	NW	0.01 / 31.43	-6	71
2	RCRA NON GEN	NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT ST MH 87TH BUFFALO NY 14209 ***EPA Handler ID:*** NYP000972182	NW	0.01 / 31.43	-6	72
2	GEN MANIFEST	NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT MH @ 61ST ST BUFFALO NY 14209	NW	0.01 / 31.43	-6	73
2	GEN MANIFEST	NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT ST MH @ 87TH BUFFALO NY 14209	NW	0.01 / 31.43	-6	74
3	NY SPILLS	BLD SITE OF GENERAL HOSPITAL	CORNER NORTH ST AND ELLICOTT ST BUFFALO NY ***Spill No | Close Date:*** 0910563 | 2010-02-01 00:00:00	WSW	0.01 / 48.91	3	74
4	GEN MANIFEST	NIAGARA MOHAWK	STATION 49 BEST ST BUFFALO NY 14209	NW	0.01 / 60.10	-5	75
5	BROWNFIELDS	Former Pilgrim Village Senior Apartments	951 Ellicott Street Buffalo NY 14209	NNW	0.01 / 71.96	-6	75
6	NY SPILLS	BUFFALO GENERAL HOSPITAL	GOODRICH BUFFALO NY ***Spill No | Close Date:*** 0751355 | 2008-05-09 00:00:00	SW	0.02 / 92.34	3	78
6	LST	BUFFALO GENERAL HOSPITAL	NORTH STREET BUFFALO NY ***Spill No | Close Date:*** 9310029 | 1994-12-16 00:00:00	SW	0.02 / 92.34	3	79
6	FINDS/FRS	UNIVERSITY AT BUFFALO - CTRC	875 ELLICOTT ST BUFFALO NY 14203 ***Registry ID:*** 110046400774	SW	0.02 / 92.34	3	80
6	GEN MANIFEST	UNIVERSITY AT BUFFALO - CTRC	875 ELLICOTT ST BUFFALO NY 14203	SW	0.02 / 92.34	3	80

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
6	RCRA LQG	UNIVERSITY AT BUFFALO - CTRC	875 ELLICOTT ST BUFFALO NY 14203 ***EPA Handler ID:*** NYR000195461	SW	0.02 / 92.34	3	84
7	BROWNFIELDS	Buffalo City Mission (E. North St & Michigan Ave)	150 East North Street Buffalo NY 14203-1029	ESE	0.03 / 164.91	11	88
7	COOLING TOWERS		150 E North St Buffalo NY 14203	ESE	0.03 / 164.91	11	89
8	RCRA NON GEN	STATION 49	45 BEST ST BUFFALO NY 14209-2301 ***EPA Handler ID:*** NYD980783229	WNW	0.03 / 182.83	-4	89
8	NY SPILLS	NIAGARA MOHAWK	45 BEST STREET BUFFALO NY ***Spill No | Close Date:*** 9303440 | 1995-10-12 00:00:00	WNW	0.03 / 182.83	-4	91
8	NY SPILLS	NIAGARA MOHAWK	45 BEST STREET BUFFALO NY ***Spill No | Close Date:*** 8603091 | 1986-10-16 00:00:00	WNW	0.03 / 182.83	-4	92
8	RCRA NON GEN	NIAGARA MOHAWK A NATIONAL GRID CO	45 BEST ST & OLD BEST ST BUFFALO NY 14209 ***EPA Handler ID:*** NYP000974236	WNW	0.03 / 182.83	-4	93
8	NY MANIFEST	NIAGARA MOHAWK A NATIONAL GRID CO	45 BEST ST & OLD BEST ST BUFFALO NY 14209	WNW	0.03 / 182.83	-4	94
8	TIER 2	STATION #49 Substation	45 BEST STREET BETWEEN MAIN STREET AND ELLICOTT ROAD BUFFALO Buffalo NY 14209	WNW	0.03 / 182.83	-4	95
9	COOLING TOWERS		50 E North St Buffalo NY 14203	WSW	0.04 / 191.29	4	95
10	RCRA LQG	NATIONAL GRID MANHOLE 119 BEST BUFFALO	119 BEST ST BUFFALO NY 14209 ***EPA Handler ID:*** NYP000967299	NE	0.04 / 226.66	-2	95
10	GEN MANIFEST	NIAGARA MOHAWK A NATIONAL GRID CO	119 BEST ST. BUFFALO NY 14209	NE	0.04 / 226.66	-2	97

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
11	RCRA NON GEN	DEGUSSA CORP	980 ELLICOTT ST - WAREHOUSE BUFFALO NY 14209 ***EPA Handler ID:*** NYR000045112	NNW	0.06 / 291.10	-6	97
11	RCRA LQG	OSMOSE INC	980 ELLICOTT ST BUFFALO NY 14209 ***EPA Handler ID:*** NYD002112944	NNW	0.06 / 291.10	-6	99
11	AST	OSMOSE INC	980 ELLICOTT ST Buffalo NY 14209 ***Site ID*** **|** ***Site Status:*** 52006 | Active	NNW	0.06 / 291.10	-6	109
11	UST	OSMOSE INC	980 ELLICOTT ST Buffalo NY 14209 ***Site ID*** **|** ***Site Status:*** 52006 | Active	NNW	0.06 / 291.10	-6	111
11	SHWS	Osmose Wood Preserving	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	-6	117
11	INST	Osmose Wood Preserving	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	-6	120
11	NY SPILLS	NOCO ENERGY-980 ELLICOTT	980 ELLICOTT STREET BUFFALO NY ***Spill No*** **|** ***Close Date:*** 9505668 | 1995-08-11 00:00:00	NNW	0.06 / 291.10	-6	124
11	NY SPILLS	OSMOSE	980 ELLICOTT ST Buffalo NY 14209 ***Spill No*** **|** ***Close Date:*** 0750740 | 2007-08-24 00:00:00	NNW	0.06 / 291.10	-6	125
11	NY SPILLS	OSMOSE WOOD	980 ELLICOTT STREET BUFFALO NY ***Spill No*** **|** ***Close Date:*** 9608362 | 1996-10-11 00:00:00	NNW	0.06 / 291.10	-6	126
11	NY SPILLS	OSMOSE PRODUCT RELEASE	980 ELLICOTT ST Buffalo NY 14209 ***Spill No*** **|** ***Close Date:*** 0750741 | 2008-01-15 00:00:00	NNW	0.06 / 291.10	-6	127
11	LST	OSMOSE WOOD PRESERVATIVE	980 ELLICOTT STREET BUFFALO NY ***Spill No*** **|** ***Close Date:*** 8903194 | 1989-09-12 00:00:00	NNW	0.06 / 291.10	-6	129
11	LST	OSMOSE WOOD PRESERVING	980 ELLICOTT STREET BUFFALO NY ***Spill No*** **|** ***Close Date:*** 9975243 | 1999-08-17 00:00:00	NNW	0.06 / 291.10	-6	130
11	AST	OSMOSE INC.	980 Ellicott Street Buffalo NY 14209 ***Site ID*** **|** ***Site Status:*** 339349 | Unregulated/Closed	NNW	0.06 / 291.10	-6	131

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
11	UST	OSMOSE INC.	980 Ellicott Street Buffalo NY 14209 ***Site ID* | *Site Status:*** 339349 | Unregulated/Closed	NNW	0.06 / 291.10	-6	132
11	DELISTED TANKS	OSMOSE INC.	980 ELLICOTT STREET BUFFALO NY 14209	NNW	0.06 / 291.10	-6	133
11	SSTS	OSMOSE UTILITIES SERVICES, INC.	980 ELLICOTT ST - BUFFALO NY 14209 ***Establishment No:*** 75341-NY-1	NNW	0.06 / 291.10	-6	133
11	SSTS	OSMOSE INC	980 ELLICOTT ST - BUFFALO NY 14209 ***Establishment No:*** 3008-NY-1	NNW	0.06 / 291.10	-6	134
11	BROWNFIELDS	980 Ellicott Street Site	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	-6	134
11	GEN MANIFEST	OSMOSE WOOD PRESERVING INC	980 ELLICOTT ST BUFFALO NY 14209	NNW	0.06 / 291.10	-6	136
11	TIER 2	Osmose, Inc.	980 Ellicott St. Buffalo NY 14209	NNW	0.06 / 291.10	-6	152
11	TIER 2	Osmose, Inc.	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	-6	153
11	TIER 2	Osmose Inc; 980 Ellicott Street, Buffalo, NY 14209	NY	NNW	0.06 / 291.10	-6	153
12	NY SPILLS	PHASE II	1100 MICHIGAN AVE. BUFFALO NY 14202 ***Spill No* | *Close Date:*** 1508707 | 2015-11-23 00:00:00	E	0.06 / 322.34	3	153
12	BROWNFIELDS	Former Pilgrim Village Family Apartments	1100 Michigan Avenue Buffalo NY 14209	E	0.06 / 322.34	3	154
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 8	854 Ellicott St Buffalo NY 14203 ***ID:*** 162228	WSW	0.06 / 327.34	7	157
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 3	854 Ellicott St Buffalo NY 14203 ***ID:*** 180119	WSW	0.06 / 327.34	7	157

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 9	854 Ellicott St Buffalo NY 14203 **ID:** 180116	WSW	0.06 / 327.34	7	158
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 5	854 Ellicott St Buffalo NY 14203 **ID:** 180112	WSW	0.06 / 327.34	7	158
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 6	854 Ellicott St Buffalo NY 14203 **ID:** 180113	WSW	0.06 / 327.34	7	159
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 2	854 Ellicott St Buffalo NY 14203 **ID:** 180117	WSW	0.06 / 327.34	7	160
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 11	854 Ellicott St Buffalo NY 14203 **ID:** 180114	WSW	0.06 / 327.34	7	160
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 1	854 Ellicott St Buffalo NY 14203 **ID:** 180122	WSW	0.06 / 327.34	7	161
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 7	854 Ellicott St Buffalo NY 14203 **ID:** 180121	WSW	0.06 / 327.34	7	161
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 4	854 Ellicott St Buffalo NY 14203 **ID:** 180118	WSW	0.06 / 327.34	7	162
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 12	854 Ellicott St Buffalo NY 14203 **ID:** 180115	WSW	0.06 / 327.34	7	162
13	ALT FUELS	854ELLICOTT 854 ELLICOTT 10	854 Ellicott St Buffalo NY 14203 **ID:** 180120	WSW	0.06 / 327.34	7	163
14	RCRA NON GEN	DEL-RICH PROPERTIES	35 EDNA PL BUFFALO NY 14209 **EPA Handler ID:** NYR000087031	NNE	0.07 / 348.66	-6	163
15	NY SPILLS	BUFFALO GENERAL HOSPITAL	112 GOODRICH AVENUE BUFFALO NY **Spill No | Close Date:** 9502029 | 1995-05-18 00:00:00	SSE	0.07 / 358.41	18	165
16	NY SPILLS	BUFFALO GENERAL HOSPITAL	GOODRICH ST/ELLICOTT ST C/BUFFALO NY **Spill No | Close Date:** 0705383 | 2007-09-13 00:00:00	SW	0.07 / 385.77	10	166

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
17	COOLING TOWERS		1031 Michigan Ave Buffalo NY 14204	SE	0.10 / 507.39	25	167
18	NY SPILLS	ABANDONED MEDICAL WASTE	1003 ELLICOTT STREET BUFFALO NY	N	0.10 / 537.43	-5	167
			***Spill No*	*Close Date:*** 9910017 | 1999-11-18 00:00:00			
19	RCRA LQG	NYSDOT-WB	RTE I-86 OVER RTE 60 ELLICOTT NY 14701	S	0.10 / 538.47	18	168
			EPA Handler ID: NYD986973444				
19	RCRA LQG	BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	18	172
			EPA Handler ID: NYD074042292				
19	RCRA SQG	MULTILAB - FIRST FLOOR	100 HIGH ST ROOM 122 BUFFALO NY 14203-1154	S	0.10 / 538.47	18	185
			EPA Handler ID: NYR000144576				
19	AST	BUFFALO GENERAL HOSPITAL	100 HIGH ST Buffalo NY 14203	S	0.10 / 538.47	18	187
			***Site ID*	*Site Status:*** 54488 | Active			
19	UST	BUFFALO GENERAL HOSPITAL	100 HIGH ST Buffalo NY 14203	S	0.10 / 538.47	18	206
			***Site ID*	*Site Status:*** 54488 | Active			
19	NY SPILLS	BUFFALO GENERAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	18	215
			***Spill No*	*Close Date:*** 0109330 | 2001-12-21 00:00:00			
19	NY SPILLS	BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	18	216
			***Spill No*	*Close Date:*** 9408004 | 1994-09-14 00:00:00			
19	LST	BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	18	217
			***Spill No*	*Close Date:*** 0075587 | 2001-02-27 00:00:00			
19	LST	BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	18	218
			***Spill No*	*Close Date:*** 8909904 | 1990-07-10 00:00:00			
19	HMIRS		100 HIGH ST BUFFALO NY	S	0.10 / 538.47	18	219
19	GEN MANIFEST	MULTILAB - FIRST FLOOR	100 HIGH ST ROOM 122 BUFFALO NY 14203	S	0.10 / 538.47	18	221

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
19	GEN MANIFEST	BUFFALO GENERAL HOSPITAL	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	18	226
19	NY SPILLS	BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY 14203 ***Spill No* | *Close Date:*** 1905674 | 2019-10-30 00:00:00	S	0.10 / 538.47	18	246
19	HMIRS		100 HIGH ST BUFFALO NY	S	0.10 / 538.47	18	246
19	AIR PERMITS	BUFFALO GENERAL MEDICAL CENTER	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	18	248
19	AIR PERMITS	BUFFALO GENERAL MEDICAL CENTER	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	18	248
19	AIR PERMITS	BUFFALO GENERAL MEDICAL CENTER	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	18	249
19	COOLING TOWERS		100 High St. Buffalo NY 14203	S	0.10 / 538.47	18	249
19	COOLING TOWERS		100 High St. Buffalo NY 14203	S	0.10 / 538.47	18	249
19	COOLING TOWERS		100 High St. Buffalo NY 14203	S	0.10 / 538.47	18	250
19	COOLING TOWERS		100 High St. Buffalo NY 14203	S	0.10 / 538.47	18	250
19	COOLING TOWERS		100 High St. Buffalo NY 14203	S	0.10 / 538.47	18	250
19	COOLING TOWERS		100 High St. Buffalo NY 14203	S	0.10 / 538.47	18	251
19	TIER 2	Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY 14203	S	0.10 / 538.47	18	251

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
19	TIER 2	Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY 14203	S	0.10 / 538.47	18	251
19	LST	HOSPITAL	100 HIGH ST BUFFALO NY ***Spill No* | *Close Date:*** 2203688 | 2022-07-28 00:00:00	S	0.10 / 538.47	18	251
19	NY SPILLS	BUFFALO GENERAL HOSPITAL	100 HIGH ST BUFFALO NY ***Spill No* | *Close Date:*** 2203342 |	S	0.10 / 538.47	18	252
19	TIER 2	Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY NY	S	0.10 / 538.47	18	253
19	TIER 2	Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY Erie	S	0.10 / 538.47	18	254
20	NY SPILLS	NIAGARA MOHAWK TRANSFORME	1031 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 9406282 | 1994-09-07 00:00:00	WSW	0.11 / 586.54	11	254
20	NY SPILLS	PARKING LOT	1031 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 1311101 | 2016-10-11 00:00:00	WSW	0.11 / 586.54	11	255
21	RCRA NON GEN	PATH-BIO-RESEARCH LABORATORY	50 HIGH ST BUFFALO NY 14203-1008 ***EPA Handler ID:*** NYD982179434	SW	0.11 / 594.21	16	256
21	NY SPILLS	KALEIDA HEALTH	50 HIGH STREET BUFFALO NY ***Spill No* | *Close Date:*** 1201711 | 2012-08-24 00:00:00	SW	0.11 / 594.21	16	258
21	LST	BUFFALO GENERAL HOSP	50 HIGH STREET BUFFALO NY ***Spill No* | *Close Date:*** 0705382 | 2007-09-13 00:00:00	SW	0.11 / 594.21	16	259
21	GEN MANIFEST	TRESCO DISTRIBUTION CORPORATION	820 ELLICOTT SQUARE BLDG BUFFALO NY 14203	SW	0.11 / 594.21	16	260
21	GEN MANIFEST	CMX LABORATORIES	50 HIGH STREET BUFFALO NY 14203	SW	0.11 / 594.21	16	260
22	NY SPILLS	TRANSFORMER PAD MOUNT	24R FOSDICK AVE BUFFALO NY ***Spill No* | *Close Date:*** 1503405 | 2015-06-29 00:00:00	E	0.11 / 597.94	22	261

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
23	ALT FUELS	854ELLICOTT 134 HIGH ST 10	134 High St Buffalo NY 14203 ***ID:*** 169910	SSE	0.12 / 610.22	21	262
23	ALT FUELS	854ELLICOTT 134 HIGH ST 6	134 High St Buffalo NY 14203 ***ID:*** 169908	SSE	0.12 / 610.22	21	262
23	ALT FUELS	854ELLICOTT 134 HIGH ST 3	134 High St Buffalo NY 14203 ***ID:*** 169909	SSE	0.12 / 610.22	21	263
23	ALT FUELS	854ELLICOTT 134 HIGH ST 5	134 High St Buffalo NY 14203 ***ID:*** 181843	SSE	0.12 / 610.22	21	263
23	ALT FUELS	854ELLICOTT 134 HIGH ST 4	134 High St Buffalo NY 14203 ***ID:*** 181846	SSE	0.12 / 610.22	21	264
23	ALT FUELS	854ELLICOTT 134 HIGH ST 9	134 High St Buffalo NY 14203 ***ID:*** 181848	SSE	0.12 / 610.22	21	264
23	ALT FUELS	854ELLICOTT 134 HIGH ST 7	134 High St Buffalo NY 14203 ***ID:*** 181847	SSE	0.12 / 610.22	21	265
23	ALT FUELS	854ELLICOTT 134 HIGH ST 1	134 High St Buffalo NY 14203 ***ID:*** 181845	SSE	0.12 / 610.22	21	265
23	ALT FUELS	854ELLICOTT 134 HIGH ST 8	134 High St Buffalo NY 14203 ***ID:*** 181849	SSE	0.12 / 610.22	21	266
23	ALT FUELS	854ELLICOTT 134 HIGH ST 2	134 High St Buffalo NY 14203 ***ID:*** 181844	SSE	0.12 / 610.22	21	267
24	BROWNFIELDS	Michigan-Best Development	1145 Michigan Avenue Buffalo NY 14209	ENE	0.12 / 616.23	-5	267
25	RCRA NON GEN	ERIE CO PUBLIC HEALTH LAB	1021 MAIN ST - 5TH FL BUFFALO NY 14203 ***EPA Handler ID:*** NYD986985448	WSW	0.12 / 620.50	14	270
25	RCRA VSQG	RESEARCH INSTITUTE ADDICTIONS	1021 MAIN ST BUFFALO NY 14203-1016 ***EPA Handler ID:*** NYD982722076	WSW	0.12 / 620.50	14	273

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
25	NY SPILLS	PARKING LOT	1021 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 1311100 | 2016-10-11 00:00:00	WSW	0.12 / 620.50	14	275
25	GEN MANIFEST	RESEARCH INSTITUTE ADDICTIONS	1021 MAIN ST BUFFALO NY 14203	WSW	0.12 / 620.50	14	276
25	GEN MANIFEST	RESEARCH INSTITUTE OF ALCHOLISM	1021 MAIN STREET BUFFALO NY 14203	WSW	0.12 / 620.50	14	277
25	GEN MANIFEST	ERIE COUNTY PUBLIC HEALTH LAB	1021 MAIN ST BUFFALO NY 14203	WSW	0.12 / 620.50	14	281
26	TIER 2	Kaleida Health - Highpointe	1023 Michigan Buffalo NY 14203	SE	0.12 / 637.81	24	284
26	TIER 2	Kaleida Health - Highpointe	1023 Michigan Buffalo NY 14203	SE	0.12 / 637.81	24	284
26	TIER 2	Kaleida Health - Highpointe	1023 Michigan Buffalo NY NY	SE	0.12 / 637.81	24	284
26	TIER 2	Kaleida Health - Highpointe	1023 Michigan Buffalo NY Erie	SE	0.12 / 637.81	24	285
27	BROWNFIELDS	Former Mobil Service Station 99-MST	979 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	16	285
27	NY SPILLS	BUFFALO GENERAL HOSPITAL	999 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 9508300 | 1995-10-30 00:00:00	WSW	0.12 / 641.48	16	289
27	NY SPILLS	OIL AT HIGH STREET	999 MAIN AND 24 HIGH BUFFALO NY ***Spill No* | *Close Date:*** 9500234 | 2015-09-15 00:00:00	WSW	0.12 / 641.48	16	290
27	LST	PHYSICANS IMAGING	979 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 8806781 | 1989-01-25 00:00:00	WSW	0.12 / 641.48	16	293
27	RCRA SQG	MOBIL SERVICE STATION 99 - MST FORMERLY	1001 MAIN ST BUFFALO NY 14203 ***EPA Handler ID:*** NYR000215533	WSW	0.12 / 641.48	16	294

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
27	RCRA LQG	CURIA GLOBAL INC – MAIN ST	1001 MAIN ST STE 700 BUFFALO NY 14203 ***EPA Handler ID:*** NYR000218347	WSW	0.12 / 641.48	16	296
27	INST	Former Mobil Service Station 99-MST	979 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	16	302
27	ENG	Former Mobil Service Station 99-MST	979 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	16	306
27	AST	CONVENTUS BUILDING	1001 MAIN STREET BUFFALO NY 14203 ***Site ID	Site Status:*** 563710 | Active	WSW	0.12 / 641.48	16	310
27	RCRA SQG	ATHENEX INC	1001 MAIN ST STE 600 CONVENTUS BUILDING BUFFALO NY 14203 ***EPA Handler ID:*** NYR000234906	WSW	0.12 / 641.48	16	318
27	GEN MANIFEST	ATHENEX INC	1001 MAIN ST SUITE 600 CONVENTUS BUILDING BUFFALO NY 14203	WSW	0.12 / 641.48	16	320
27	GEN MANIFEST	MOBIL SERVICE STATION 99-MST FORMER	1001 MAIN ST BUFFALO NY 14203	WSW	0.12 / 641.48	16	323
27	GEN MANIFEST	CURIA GLOBAL INC - MAIN ST	1001 MAIN ST STE 700 BUFFALO NY 14203	WSW	0.12 / 641.48	16	323
27	TIER 2	Albany Molecular Research, Inc.	1001 Main St, Suite 110 Buffalo NY 14203	WSW	0.12 / 641.48	16	327
27	ALT FUELS	CONVENTUS CONVENTUS	1001 Main Street Buffalo NY 14203 ***ID:*** 165111	WSW	0.12 / 641.48	16	327
27	COOLING TOWERS		1001 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	16	327
27	COOLING TOWERS		1001 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	16	328
27	TIER 2	Albany Molecular Research, Inc.	1001 Main St, Suite 110 Buffalo NY NY	WSW	0.12 / 641.48	16	328

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
27	TIER 2	Albany Molecular Research, Inc.	1001 Main St, Suite 110 Buffalo NY Erie	WSW	0.12 / 641.48	16	328
28	LST	MAIN - SUMMER CORPORATION	MAIN & SUMMER STREETS BUFFALO NY	WNW	0.12 / 641.59	4	328
			Spill No* | *Close Date: 8908322 | 1990-04-02 00:00:00				
29	NY SPILLS	WENDY,S	MAIN AND NORTH STREETS BUFFALO NY	WSW	0.12 / 655.66	11	329
			Spill No* | *Close Date: 8911108 | 1990-03-12 00:00:00				
29	LST	A.R.G. TRUCKING CO.	MAIN AND NORTH ST. BUFFALO NY	WSW	0.12 / 655.66	11	330
			Spill No* | *Close Date: 8607168 | 1987-02-24 00:00:00				
30	NY SPILLS	OIL IN STREET	336 MAPLE BUFFALO NY	ESE	0.13 / 685.33	25	331
			Spill No* | *Close Date: 0750965 | 2007-10-17 00:00:00				
31	BROWNFIELDS	1155 Main Street	1155 Main Street Buffalo NY 14209	NW	0.13 / 691.54	6	332
32	AST	CITY HONORS SCHOOL NO. 195	186 E. NORTH STREET Buffalo NY 14209	E	0.13 / 705.71	26	336
			Site ID* | *Site Status: 55323 | Active				
33	NY SPILLS	PARKING LOT - HOSPITAL	CARLTON & OAK / HIGH ST. BUFFALO NY	SSW	0.13 / 708.44	18	340
			Spill No* | *Close Date: 1810147 | 2019-01-08 00:00:00				
34	RCRA VSQG	HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI	HIGH STREET BUFFALO NY 14203	SSW	0.13 / 712.17	18	341
			EPA Handler ID: NYR000130849				
35	RCRA NON GEN	WORLD AUTO PAINT SHOPS OF BUFFALO INC	1114 MAIN ST BUFFALO NY 14209	WNW	0.13 / 712.68	4	347
			EPA Handler ID: NYD013780267				
36	NY SPILLS	ON SITE	1091 MAIN ST BUFFALO NY	W	0.14 / 715.44	6	349
			Spill No* | *Close Date: 1802722 | 2018-08-16 00:00:00				
37	NY SPILLS	NIAGARAMO/BRYANT STRATON	1028 MAIN STREET BUFFALO NY	WSW	0.14 / 745.66	14	350
			Spill No* | *Close Date: 9705897 | 1997-10-09 00:00:00				
38	NY SPILLS	ROSWELL PARK CANCER INSTI	MICHIGAN AT HIGH BUFFALO NY	SE	0.14 / 752.03	20	351

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 9875088 | 2000-03-08 00:00:00			
38	NY SPILLS	ROSWELL PARK	MICHIGAN & HIGH STREETS BUFFALO NY ***Spill No* | *Close Date:*** 9504945 | 1995-07-27 00:00:00	SE	0.14 / 752.03	20	352
38	LST	ROSWELL PARK	MICHIGAN AND HIGH BUFFALO NY ***Spill No* | *Close Date:*** 9875428 | 1999-03-01 00:00:00	SE	0.14 / 752.03	20	353
38	LST	ROSWELL PARK #6 OIL	HIGH & MICHIGAN AVENUES BUFFALO NY ***Spill No* | *Close Date:*** 8907884 | 1989-12-12 00:00:00	SE	0.14 / 752.03	20	354
38	LST	ROSWELL PARK CANCER INST.	MICHIGAN AND HIGH STREETS BUFFALO NY ***Spill No* | *Close Date:*** 9504008 | 1996-07-01 00:00:00	SE	0.14 / 752.03	20	355
38	NY SPILLS	SIDEWALK	HIGH ST AND MICHIGAN AVE BUFFALO NY ***Spill No* | *Close Date:*** 1609890 | 2017-01-27 00:00:00	SE	0.14 / 752.03	20	357
39	UST	PROPERTY	174 HIGH ST BUFFALO NY 14203 ***Site ID* | *Site Status:*** 443109 | Unregulated/Closed	SE	0.15 / 771.75	20	357
39	NY SPILLS	174 HIGH PROJECT	174 HIGH STREET BUFFALO NY 14210 ***Spill No* | *Close Date:*** 0912618 | 2010-05-04 00:00:00	SE	0.15 / 771.75	20	359
40	SWF/LF	Olmsted Center For Sight	1170 Main Street Buffalo NY 14209	NW	0.15 / 789.54	7	360
41	RCRA LQG	SCHUELE PAINT CO	12 SUMMER ST BUFFALO NY 14209 ***EPA Handler ID:*** NYR000165506	WNW	0.16 / 836.96	5	360
42	BROWNFIELDS	19 North Street	19 North Street Buffalo NY 14202	W	0.16 / 841.09	14	362
43	RCRA NON GEN	GULF SERVICE STATION #176476	1038 MAIN ST BUFFALO NY 14202 ***EPA Handler ID:*** NYR000033134	WSW	0.16 / 844.61	14	365
43	UST	CUMBERLAND FARMS #176476	1038 MAIN ST Buffalo NY 14202 ***Site ID* | *Site Status:*** 53097 | Unregulated/Closed	WSW	0.16 / 844.61	14	367
43	NY SPILLS	CUMBERLAND FARMS/GULF	1038 MAIN STREET BUFFALO NY	WSW	0.16 / 844.61	14	371

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			Spill No* | *Close Date: 9311640 | 1994-07-01 00:00:00				
43	NY SPILLS	CUMBERLAND FARMS	1038 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 9613078 | 1997-03-17 00:00:00	WSW	0.16 / 844.61	14	372
43	LST	ARG TRUCKING	1038 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 8803956 | 1988-08-08 00:00:00	WSW	0.16 / 844.61	14	373
43	LST	NIRELLI'S GULF STATION	1038 MAIN & NORTH BUFFALO NY ***Spill No* | *Close Date:*** 8808014 | 1989-10-02 00:00:00	WSW	0.16 / 844.61	14	374
44	RCRA NON GEN	PRECISION ABRASIVES CORP	11 SUMMER ST BUFFALO NY 14209 ***EPA Handler ID:*** NYD986930584	WNW	0.17 / 875.14	7	375
45	RCRA NON GEN	NORTHEAST TOWER INC	23 HIGH ST BUFFALO NY 14203 ***EPA Handler ID:*** NYD982539645	SW	0.17 / 920.40	18	377
46	NY SPILLS	BEHIND VACANT HOUSES	204 HIGH ST BUFFALO NY ***Spill No* | *Close Date:*** 0108495 | 2001-11-23 00:00:00	SE	0.18 / 938.11	16	379
47	NY SPILLS	VACANT LOT FORMERLY 33 HIGH STREET APTS	960 WASHINGTON NY ***Spill No* | *Close Date:*** 1204448 | 2014-04-29 00:00:00	SW	0.19 / 989.58	18	380
48	RCRA NON GEN	AUTOPIA INC	1176 MAIN ST BUFFALO NY 14203 ***EPA Handler ID:*** NYD987012838	NW	0.19 / 1,010.67	9	381
49	RCRA NON GEN	CITIBANK	1008 MAIN ST BUFFALO NY 14202-1102 ***EPA Handler ID:*** NYR000084129	WSW	0.19 / 1,021.94	17	383
50	RCRA SQG	SALVATION ARMY THE	984 MAIN ST BUFFALO NY 14202-1102 ***EPA Handler ID:*** NYR000133009	WSW	0.20 / 1,077.57	18	385
51	RCRA NON GEN	DMNA STATE OF NEW YORK OMS #2	27 MASTEN AVE BUFFALO NY 14204 ***EPA Handler ID:*** NYD981561673	E	0.21 / 1,083.89	33	387
51	RCRA VSQG	NYS DMNA - FMS #1	27 MASTEN AVE BUFFALO NY 14204-1097 ***EPA Handler ID:*** NYD981561665	E	0.21 / 1,083.89	33	390
51	AST	MASTEN AVENUE ARMORY	27 MASTEN AVE Buffalo NY 14204	E	0.21 / 1,083.89	33	394

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Site ID*	*Site Status:*** 53860 | Unregulated/Closed			
51	UST	MASTEN AVENUE ARMORY	27 MASTEN AVE Buffalo NY 14204	E	0.21 / 1,083.89	33	398
			Site ID* | *Site Status: 53860 | Unregulated/Closed				
51	NY SPILLS	NYS NATIONAL GUARD	27 MASTEN AVENUE BUFFALO NY	E	0.21 / 1,083.89	33	404
			Spill No* | *Close Date: 9907527 | 1999-09-24 00:00:00				
51	NY SPILLS	NATIONAL GUARD BUILDING	27 MASTEN AVE BUFFALO NY	E	0.21 / 1,083.89	33	405
			Spill No* | *Close Date: 9708830 | 1997-10-31 00:00:00				
51	LST	MASTEN AVENUE ARMORY	27 MASTEN AVENUE BUFFALO NY	E	0.21 / 1,083.89	33	406
			Spill No* | *Close Date: 8904853 | 1990-11-14 00:00:00				
51	LST	NYS ARMORY	27 MASTEN STREET BUFFALO NY	E	0.21 / 1,083.89	33	407
			Spill No* | *Close Date: 9709636 | 1998-03-30 00:00:00				
51	LST	MASTEN AVENUE ARMORY	27 MASTEN AVENUE BUFFALO NY	E	0.21 / 1,083.89	33	408
			Spill No* | *Close Date: 9305872 | 1993-08-27 00:00:00				
52	RCRA NON GEN	CITY HONORS SCHOOL	MASTEN AVE & NORTH BUFFALO NY 14204	E	0.21 / 1,090.40	33	410
			EPA Handler ID: NYD986940328				
53	RCRA NON GEN	BISHOP LESLIE	1059 ELLICOTT ST BUFFALO NY 14209	N	0.21 / 1,091.38	0	412
			EPA Handler ID: NYR000060442				
54	NY SPILLS	ARTSPACE	1219-1233 MAIN STREET BUFFALO NY	NNW	0.21 / 1,094.56	5	414
			Spill No* | *Close Date: 0600379 | 2006-10-26 00:00:00				
54	NY SPILLS	FORMER SARA BETH BUILDING	1219-1233 MAIN STREET BUFFALO NY	NNW	0.21 / 1,094.56	5	415
			Spill No* | *Close Date: 0485354 | 2005-01-27 00:00:00				
55	NY SPILLS	BFI TRUCK	33 LINWOOD AVENUE BUFFALO NY	W	0.22 / 1,159.45	15	416
			Spill No* | *Close Date: 9975353 | 1999-08-12 00:00:00				
56	NY SPILLS	M J GRASS SCREW MACHINE	1233 MAIN STREET BUFFALO NY	NNW	0.23 / 1,206.26	5	417
			Spill No* | *Close Date: 8807560 | 1990-10-22 00:00:00				
56	NY SPILLS	G&E MANAGEMENT	1233 MAIN ST BUFFALO NY	NNW	0.23 / 1,206.26	5	418

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 9100320 | 1991-04-10 00:00:00			
57	RCRA NON GEN	NIAGARA MOHAWK A NATIONAL GRID CO	1229 MAIN ST BUFFALO NY 14209	NNW	0.23 / 1,227.57	6	419
			EPA Handler ID: NYP000968909				
58	NY SPILLS	CAO DART	1237 MAIN STREET BUFFALO NY	NNW	0.24 / 1,258.75	5	420
			***Spill No*	*Close Date:*** 0175280 | 2001-08-24 00:00:00			
59	NY SPILLS	CITY OF BUFFALO PARKS	29 NORTH HAMPTON BUFFALO NY	N	0.24 / 1,261.85	3	421
			***Spill No*	*Close Date:*** 9913377 | 2000-04-10 00:00:00			
60	RCRA NON GEN	MIDCITY OFFICE EQUIPMENT INC	1220 MAIN ST BUFFALO NY 14209	NNW	0.24 / 1,278.62	7	422
			EPA Handler ID: NYR000046102				
60	LST	MID CITY OFFICE EQUIPMENT	1220 MAIN STREET BUFFALO NY	NNW	0.24 / 1,278.62	7	424
			***Spill No*	*Close Date:*** 9707872 | 1997-11-28 00:00:00			
61	LST	AGASSIZ HOLDINGS INC	1235 - 1245 MAIN STREET BUFFALO NY	NNW	0.24 / 1,288.80	5	426
			***Spill No*	*Close Date:*** 0500859 | 2006-03-21 00:00:00			
62	RCRA LQG	UNIVERSITY AT BUFFALO-JSMBS	955 MAIN ST BUFFALO NY 14203	SW	0.25 / 1,296.56	12	427
			EPA Handler ID: NYR000233718				
62	AST	SUNY AT BUFFALO JSMBS	955 MAIN ST. Buffalo NY 14203	SW	0.25 / 1,296.56	12	432
			***Site ID*	*Site Status:*** 579178 | Active			
62	SWF/LF	University at Buffalo (SUNY) Downtown Campus	955 Main Street Buffalo NY 14203	SW	0.25 / 1,296.56	12	436
63	LST	NYNEX	645 FRANKLIN STREET BUFFALO NY	W	0.25 / 1,297.40	23	436
			***Spill No*	*Close Date:*** 9315172 | 1994-12-15 00:00:00			
64	AIR PERMITS	ROSWELL PARK CANCER INSTITUTE	666 ELM & CARLTON STS BUFFALO NY 14263	S	0.25 / 1,308.86	2	437
64	AIR PERMITS	ROSWELL PARK CANCER INSTITUTE	666 ELM & CARLTON STS BUFFALO NY 14263	S	0.25 / 1,308.86	2	437
65	RCRA TSD	ROSWELL PARK CANCER INSTITUTE	ELM & CARLTON STREETS BUFFALO NY 14263	S	0.26 / 1,361.98	1	438

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			EPA Handler ID: NYD083534115				
65	NY SPILLS	ROSWELL	ELM AND CARLTON ST BUFFALO NY ***Spill No | Close Date:*** 1203400 | 2012-07-11 00:00:00	S	0.26 / 1,361.98	1	466
65	LST	NYSDOH ROSWELL LOADING DK	ELM & CARLTON BUFFALO NY ***Spill No | Close Date:*** 9206876 | 1995-02-06 00:00:00	S	0.26 / 1,361.98	1	467
65	LST	NYSDOH ROSWELL PARK	ELM AND CARLTON STREETS BUFFALO NY ***Spill No | Close Date:*** 9402510 | 1995-02-06 00:00:00	S	0.26 / 1,361.98	1	468
65	LST	ROSWELL CANCER INSTITUTE	ELM AND CARLTON STREETS BUFFALO NY ***Spill No | Close Date:*** 9301132 | 1993-08-18 00:00:00	S	0.26 / 1,361.98	1	469
65	LST	ROSWELL PARK	ELM AT CARLTON BUFFALO NY ***Spill No | Close Date:*** 0750760 | 2007-11-15 00:00:00	S	0.26 / 1,361.98	1	470
66	NY SPILLS	IN DITCH LINE	CORNER OF MICHIGAN AVE AND CARLTON ST BUFFALO NY ***Spill No | Close Date:*** 1003048 | 2011-09-19 00:00:00	SSE	0.26 / 1,368.63	1	471
67	NY SPILLS	A & J DISTRIBUTORS	36 NORTHAMPTON STREET BUFFALO NY ***Spill No | Close Date:*** 8603602 | 1987-05-06 00:00:00	N	0.26 / 1,368.83	4	473
68	LST	UST @ ROSWELL PRKG GARAGE	CARLTON STREET B/T ELM-MICHIGAN STS BUFFALO NY ***Spill No | Close Date:*** 0651376 | 2007-05-15 00:00:00	SSE	0.26 / 1,373.20	1	474
69	NY SPILLS	IHRIG RESIDENCE	71 NORTH STREET BUFFALO NY ***Spill No | Close Date:*** 9503436 | 1995-06-20 00:00:00	W	0.26 / 1,397.10	22	475
70	NY SPILLS	TRANSFORMER	80 NORTH HAMPTON BUFFALO NY ***Spill No | Close Date:*** 1907809 | 2019-11-04 00:00:00	NNE	0.27 / 1,425.31	-1	476
71	LST	SINCLAIR RADIO OF BUFFALO	695 DELAWARE AVENUE BUFFALO NY ***Spill No | Close Date:*** 9709172 | 1998-12-02 00:00:00	W	0.28 / 1,482.28	23	477
72	NY SPILLS	NATIONAL FUEL GAS	CARLTON AND WASHINGTON ST BUFFALO NY ***Spill No | Close Date:*** 8905988 | 1990-03-14 00:00:00	SW	0.29 / 1,518.57	3	478
73	LST	WESTBROOK 675 DELAWARE	675 DELAWARE AVENUE BUFFALO NY	W	0.29 / 1,519.32	25	479

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Spill No*	*Close Date:*** 9308986 | 1994-04-20 00:00:00			
74	NY SPILLS	TANK ROOM	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	8	480
			***Spill No*	*Close Date:*** 0809396 | 2008-11-28 00:00:00			
74	NY SPILLS	DELTASONIC	1264 MAIN STREET BUFFALO NY	NNW	0.30 / 1,573.13	8	481
			***Spill No*	*Close Date:*** 9204557 | 1992-07-22 00:00:00			
74	NY SPILLS	DELTA SONIC	1264 MAIN STREET BUFFALO NY	NNW	0.30 / 1,573.13	8	482
			***Spill No*	*Close Date:*** 9906970 | 1999-09-14 00:00:00			
74	NY SPILLS	DELTA SONIC CAR WASH	1264 MAIN STREET BUFFALO NY 14203	NNW	0.30 / 1,573.13	8	483
			***Spill No*	*Close Date:*** 1407257 | 2014-10-14 00:00:00			
74	NY SPILLS	FRONT YARD	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	8	484
			***Spill No*	*Close Date:*** 1707510 | 2018-03-06 00:00:00			
74	NY SPILLS	DELTA SONIC CAR WASH	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	8	485
			***Spill No*	*Close Date:*** 1911365 | 2020-03-12 00:00:00			
74	NY SPILLS	COMMERICAL	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	8	486
			***Spill No*	*Close Date:*** 2002296 | 2020-06-29 00:00:00			
74	NY SPILLS	COMMERCIAL	1264 MAIN ST BUFFALO NY 14209	NNW	0.30 / 1,573.13	8	487
			***Spill No*	*Close Date:*** 2008396 | 2021-02-11 00:00:00			
75	NY SPILLS	NATIONAL GRID	153 NORTH HAMPTON STREET BUFFALO NY 14203 ***Spill No*	*Close Date:*** 1109000 | 2012-01-25 00:00:00	NE	0.30 / 1,591.91	-7	488
76	NY SPILLS	J & I DISPOSAL	666 ELM STREET BUFFALO NY	S	0.30 / 1,600.72	-5	489
			***Spill No*	*Close Date:*** 8902159 | 1989-06-13 00:00:00			
76	NY SPILLS	ROSWELL PARK	666 ELM STREET BUFFALO NY	S	0.30 / 1,600.72	-5	489
			***Spill No*	*Close Date:*** 8706549 | 1987-11-18 00:00:00			
76	LST	ROSWELL PARK	666 ELM STREET BUFFALO NY	S	0.30 / 1,600.72	-5	490
			***Spill No*	*Close Date:*** 8905775 | 1989-11-22 00:00:00			
77	NY SPILLS	POLE 173	173 MULBERRY ST BUFFALO NY	SE	0.31 / 1,613.76	-7	491
			***Spill No*	*Close Date:*** 0805954 | 2008-08-27 00:00:00			

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
78	NY SPILLS	FAIRFAX APTS.	715 DELAWARE AVE. BUFFALO NY ***Spill No* | *Close Date:*** 0550371 | 2005-06-09 00:00:00	W	0.31 / 1,646.25	23	492
79	NY SPILLS	CITY OF BUFFALO	MAIN AND CARLTON STREETS BUFFALO NY ***Spill No* | *Close Date:*** 8907967 | 1993-01-25 00:00:00	SW	0.32 / 1,671.54	3	493
80	NY SPILLS	COMMERCIAL BUILDINGS	1269 THRU 1285 MAIN ST BUFFALO NY ***Spill No* | *Close Date:*** 1408808 | 2014-12-31 00:00:00	NNW	0.32 / 1,675.64	8	494
81	NY SPILLS	DEMOLITION SITE	289 HIGH STREET BUFFALO NY ***Spill No* | *Close Date:*** 0275036 | 2002-04-23 00:00:00	ESE	0.32 / 1,708.41	10	496
81	LST	FORMER GAS STATION	289 HIGH STREET BUFFALO NY ***Spill No* | *Close Date:*** 0275035 | 2002-08-30 00:00:00	ESE	0.32 / 1,708.41	10	496
82	LST	KULBACK CONSTRUCTION	DELAWARE AT NORTH BUFFALO NY ***Spill No* | *Close Date:*** 9403219 | 1994-10-04 00:00:00	W	0.33 / 1,745.61	24	498
83	NY SPILLS	ROAD SIDE	82 NORTH PEARL BUFFALO NY ***Spill No* | *Close Date:*** 1708175 | 2017-11-29 00:00:00	WSW	0.33 / 1,748.63	2	499
84	NY SPILLS	NATIONAL GRID COMMERCIAL	72 NORTH PEARL ST BUFFALO NY ***Spill No* | *Close Date:*** 2207913 |	SW	0.35 / 1,834.23	1	500
85	NY SPILLS	SAINT VINCENT DEPAUL	1298 MAIN ST AT BRYANT BUFFALO NY ***Spill No* | *Close Date:*** 9603069 | 1996-06-05 00:00:00	NNW	0.35 / 1,864.38	10	501
85	NY SPILLS	GARY LOWD PROPERTY	1298 MAIN STREET BUFFALO NY ***Spill No* | *Close Date:*** 9106713 | 1991-09-23 00:00:00	NNW	0.35 / 1,864.38	10	502
86	NY SPILLS	MEDICAL WASTE/UNITED FUND	742 DELAWARE AVENUE BUFFALO NY ***Spill No* | *Close Date:*** 9710273 | 1997-12-10 00:00:00	W	0.36 / 1,886.75	18	503
87	NY SPILLS	COMMERCIAL	888 MAIN ST BUFFALO NY ***Spill No* | *Close Date:*** 1704513 | 2017-08-15 00:00:00	SW	0.36 / 1,888.96	-1	504
88	NY SPILLS	COMPUTER TASK GROUP	700 DELAWARE AVE BUFFALO NY ***Spill No* | *Close Date:*** 0507232 | 2006-02-01 00:00:00	W	0.36 / 1,891.59	23	505

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
89	LST	AMERICAN RED CROSS TANK	786 DELAWARE AVENUE BUFFALO NY	WNW	0.36 / 1,924.29	16	506
			Spill No* | *Close Date: 9404334 | 1995-12-12 00:00:00				
90	NY SPILLS	ROSWELL PARKING RAMP	ELM & VIRGINIA STREETS BUFFALO NY	S	0.37 / 1,939.69	-10	507
			Spill No* | *Close Date: 9108647 | 1992-01-03 00:00:00				
91	LST	GREYHOUND	ELLICOTT & OAK STREETS BUFFALO NY	SSW	0.37 / 1,977.40	-6	508
			Spill No* | *Close Date: 8912297 | 1990-03-29 00:00:00				
92	NY SPILLS	ROADSIDE	65 RILEY @ HOLLAND BUFFALO NY	NNE	0.38 / 1,998.39	-2	509
			Spill No* | *Close Date: 0375482 | 2004-12-13 00:00:00				
93	NY SPILLS	SOIL	215 PEACH ST BUFFALO NY	ESE	0.38 / 2,008.70	14	510
			Spill No* | *Close Date: 2007371 | 2020-11-17 00:00:00				
94	NY SPILLS	HOLIDAY INN	620 DELAWARE AVENUE BUFFALO NY	WSW	0.38 / 2,019.95	11	511
			Spill No* | *Close Date: 8806417 | 1988-11-04 00:00:00				
94	NY SPILLS	TOUR BUS	620 DELAWARE AVENUE BUFFALO NY	WSW	0.38 / 2,019.95	11	512
			Spill No* | *Close Date: 8704229 | 1987-08-24 00:00:00				
94	NY SPILLS	AMHERST DISPOSAL	620 DELAWARE AVENUE BUFFALO NY	WSW	0.38 / 2,019.95	11	513
			Spill No* | *Close Date: 8703944 | 1987-09-30 00:00:00				
95	BROWNFIELDS	Ellicott and Oak Streets Site	324, 328, and 334 North Oak St and 441 Ellicott St Bufalo NY 14203	SSW	0.39 / 2,047.16	-7	514
96	NY SPILLS	TRI-GRAPHICS	78 ALLEN OR 99 VIRGINIA BUFFALO NY	WSW	0.39 / 2,055.99	0	516
			Spill No* | *Close Date: 0275050 | 2002-05-17 00:00:00				
97	NY SPILLS	ROSWELL PARK CANER INSTIT	VIRGINIA ST/ELLICOTT ST BUFFALO NY	SSW	0.39 / 2,059.77	-7	517
			Spill No* | *Close Date: 0207429 | 2002-11-22 00:00:00				
98	NY SPILLS	LEAKING FIRE DEPT VEHICLE	289 DODGE BUFFALO NY	ENE	0.39 / 2,069.26	12	518
			Spill No* | *Close Date: 1503811 | 2015-07-09 00:00:00				
99	NY SPILLS	POLE #152	MULBERRY & VIRGINIA BUFFALO NY	SSE	0.39 / 2,069.66	-16	519
			Spill No* | *Close Date: 0711466 | 2008-03-14 00:00:00				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
100	NY SPILLS	CONCRETE	888 DELAWARE AVE BUFFALO NY	NW	0.39 / 2,072.55	14	520
			Spill No* | *Close Date: 2105781 | 2021-09-17 00:00:00				
101	NY SPILLS	BENDERSON #2	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	520
			Spill No* | *Close Date: 8910055 | 1990-03-07 00:00:00				
101	NY SPILLS	NYSDEC - BUFFALO GAS PUMP	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	521
			Spill No* | *Close Date: 9004957 | 1990-08-06 00:00:00				
101	NY SPILLS	ARMBRUST GASOLINE SPILL	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	522
			Spill No* | *Close Date: 8912037 | 1990-03-20 00:00:00				
101	NY SPILLS	BENDERSON DEVELOPMENT	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	523
			Spill No* | *Close Date: 8900461 | 1991-07-03 00:00:00				
101	NY SPILLS	MODERN DISPOSAL	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	524
			Spill No* | *Close Date: 9002580 | 1990-06-06 00:00:00				
101	NY SPILLS	LASALLE AMBULANCE	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	525
			Spill No* | *Close Date: 9509971 | 1995-11-13 00:00:00				
101	NY SPILLS	NYS DEPT. OF ENV. CONS.	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	526
			Spill No* | *Close Date: 8608020 | 1987-03-26 00:00:00				
101	LST	BENDERSON 600 DELAWARE	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	527
			Spill No* | *Close Date: 9404468 | 1994-08-15 00:00:00				
101	LST	BENDERSON DEVELOPMENT	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	7	528
			Spill No* | *Close Date: 9503691 | 1998-05-07 00:00:00				
102	LST	WESTMINSTER PRESBYTERIAN	724 DELAWARE AVENUE BUFFALO NY	W	0.40 / 2,127.33	19	530
			Spill No* | *Close Date: 8805542 | 1988-11-10 00:00:00				
103	LST	BENDERSON DEVELOPMENT	584 DELAWARE AVENUE BUFFALO NY	WSW	0.41 / 2,157.42	3	531
			Spill No* | *Close Date: 8808966 | 1989-11-10 00:00:00				
103	NY SPILLS	VAULT #16-109	584 DELAWARE AVE BUFFALO NY	WSW	0.41 / 2,157.42	3	532
			Spill No* | *Close Date: 1606362 | 2016-09-27 00:00:00				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
104	NY SPILLS	APT COMPLEX IN PARKING LOT	2 ALICE COURT BUFFALO NY	S	0.41 / 2,166.27	-13	533
			Spill No* | *Close Date: 2201549 | 2022-05-20 00:00:00				
105	LST	ALLENTOWN TRADING COMPANY	553 DELAWARE AVENUE BUFFALO NY	WSW	0.41 / 2,172.28	-2	534
			Spill No* | *Close Date: 9306552 | 2007-11-15 00:00:00				
105	LST	BRADLEY SUNOCO	553 DELAWARE AVENUE BUFFALO NY	WSW	0.41 / 2,172.28	-2	536
			Spill No* | *Close Date: 8902410 | 1989-08-01 00:00:00				
106	LST	TANKS AT APARTMENT COMPLE	905 DELAWARE AVENUE BUFFALO NY	NW	0.41 / 2,173.62	15	537
			Spill No* | *Close Date: 0075007 | 2000-06-22 00:00:00				
107	NY SPILLS	ST. JOHNS TOWERS	865 MICHGAN AVE. BUFFALO NY	S	0.42 / 2,219.64	-17	538
			Spill No* | *Close Date: 0275453 | 2002-12-18 00:00:00				
108	NY SPILLS	ST. JOHNS HOSPICE SITE	113 MAPLE BUFFALO NY	SSE	0.42 / 2,232.56	-16	539
			Spill No* | *Close Date: 0550592 | 2008-12-23 00:00:00				
109	NY SPILLS	FUMES IN HOUSE	51 IRVING STREET BUFFALO NY	WSW	0.43 / 2,265.94	5	540
			Spill No* | *Close Date: 8709670 | 1988-10-20 00:00:00				
110	NY SPILLS	SOIL	644 ELLICOT ST BUFFALO NY	SSW	0.43 / 2,267.12	-8	542
			Spill No* | *Close Date: 2104166 | 2021-08-02 00:00:00				
111	NY SPILLS	SEWAGE BACKUP AT BUILDING	560 DELAWARE AVENUE BUFFALO NY	WSW	0.43 / 2,294.82	-2	543
			Spill No* | *Close Date: 9702249 | 1997-05-22 00:00:00				
112	LST	925 DELAWARE AVENUE INC	925 DELAWARE AVENUE BUFFALO NY 14209	NW	0.44 / 2,300.20	15	543
			Spill No* | *Close Date: 0906378 | 2010-01-06 00:00:00				
113	NY SPILLS	ROADWAY	245 NORTHHAMPTON ST BUFFALO NY	ENE	0.44 / 2,309.21	-4	544
			Spill No* | *Close Date: 1405197 | 2014-08-20 00:00:00				
114	NY SPILLS	NATIONAL GRID ABOVE GROUND VAULT	916 DELWARE AVE BUFFALO NY	NW	0.44 / 2,314.90	14	545
			Spill No* | *Close Date: 2109996 | 2022-07-15 00:00:00				
115	NY SPILLS	MASTEN SALES & SERVICES	247 MASTEN AVE. BUFFALO NY	NE	0.44 / 2,343.26	-5	546
			Spill No* | *Close Date: 0813761 | 2009-03-23 00:00:00				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
115	LST	MASTEN-RILEY STATION	247 MASTEN AVENUE BUFFALO NY ***Spill No*	*Close Date:*** 9601741 | 1996-05-03 00:00:00	NE	0.44 / 2,343.26	-5	548
116	NY SPILLS	TRANSFORMER (PAD MOUNT)	641 ELLICOTT ST BUFFALO NY ***Spill No*	*Close Date:*** 1107814 | 2011-09-20 00:00:00	SSW	0.45 / 2,368.37	-10	549
117	NY SPILLS	NATURAL GAS AT RESIDENCE	MICHIGAN & LAUREL STREET BUFFALO NY ***Spill No*	*Close Date:*** 9875375 | 1999-02-02 00:00:00	NNE	0.45 / 2,377.99	-7	549
118	NY SPILLS	VACANT LOT	CORNER OF RILEY @ MASTON BUFFALO NY ***Spill No*	*Close Date:*** 1507590 | 2015-10-21 00:00:00	NE	0.46 / 2,445.09	-6	550
119	RCRA TSD	CENTURY CENTRE I	817 WASHINGTON ST BUFFALO NY 14203 ***EPA Handler ID:*** NYD002107399		SSW	0.47 / 2,476.66	-9	551
119	RCRA CORRACTS	CENTURY CENTRE I	817 WASHINGTON ST BUFFALO NY 14203 ***EPA Handler ID:*** NYD002107399		SSW	0.47 / 2,476.66	-9	559
119	NY SPILLS	TRICO	817 WASHINGTON STREET BUFFALO NY ***Spill No*	*Close Date:*** 9212975 | 1993-02-19 00:00:00	SSW	0.47 / 2,476.66	-9	568
119	PCB	TRICO PRODUCTS CORP.	817 WASHINGTON STREET BUFFALO NY 14203 ***Site ID:*** NYD002107399		SSW	0.47 / 2,476.66	-9	569
119	ERP	Century Centre I	817 Washington Street Buffalo NY 14203		SSW	0.47 / 2,476.66	-9	570
120	NY SPILLS	KLENK RESIDENCE	293 LINWOOD AVENUE BUFFALO NY ***Spill No*	*Close Date:*** 9975538 | 2000-10-20 00:00:00	NNW	0.47 / 2,488.69	15	571
121	NY SPILLS	FLYNN'S BAR AND GRILL	815 MAIN STREET BUFFALO NY ***Spill No*	*Close Date:*** 8803675 | 1989-10-02 00:00:00	SW	0.48 / 2,513.30	-8	572
122	NY SPILLS	NATIONAL FUEL GAS	73 MULBERRY STREET BUFFALO NY ***Spill No*	*Close Date:*** 9200310 | 1992-04-08 00:00:00	SSE	0.48 / 2,520.67	-22	573
123	NY SPILLS	AMBASSADOR APTS TANK	175 NORTH STREET BUFFALO NY ***Spill No*	*Close Date:*** 9607625 | 2001-01-11 00:00:00	W	0.49 / 2,564.59	16	574

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
123	NY SPILLS	KISSLING INTERESTS LLC	175 NORTH BUFFALO NY	W	0.49 / 2,564.59	16	575
			Spill No* | *Close Date: 2006097 | 2020-10-06 00:00:00				
124	NY SPILLS	NATIONAL GRID	301 LINWOOD AVE BUFFALO NY	NNW	0.49 / 2,571.77	15	576
			Spill No* | *Close Date: 0605499 | 2006-08-11 00:00:00				
125	BROWNFIELDS	Former Trico Plant	791 Washington Street Buffalo NY 14203	SSW	0.49 / 2,574.88	-11	577
125	INST	Former Trico Plant	791 Washington Street Buffalo NY 14203	SSW	0.49 / 2,574.88	-11	581
125	ENG	Former Trico Plant	791 Washington Street Buffalo NY 14203	SSW	0.49 / 2,574.88	-11	585
126	NY SPILLS	FORMER RESIDENCE	1022 JEFFERSON AVE BUFFALO NY	E	0.49 / 2,599.98	22	588
			Spill No* | *Close Date: 0175376 | 2001-11-13 00:00:00				
127	NY SPILLS	PAVEMENT	13 HODGE AVE BUFFALO NY	NW	0.49 / 2,601.93	15	589
			Spill No* | *Close Date: 1903061 | 2019-06-25 00:00:00				
128	NY SPILLS	ROADWAY	147 ALLEN ST BUFFALO NY	WSW	0.49 / 2,605.14	-5	590
			Spill No* | *Close Date: 1808242 | 2018-11-02 00:00:00				
129	NY SPILLS	ODOR AT 499 DELAWARE	499 DELAWARE AVENUE BUFFALO NY	WSW	0.50 / 2,624.67	-12	591
			Spill No* | *Close Date: 9004148 | 1990-07-14 00:00:00				
130	NY SPILLS	UNDERGROUND CABLE/MANHOLE 1056	1056 JEFFERSON AVE BUFFALO NY	E	0.50 / 2,631.04	17	592
			Spill No* | *Close Date: 1305900 | 2013-09-05 00:00:00				
131	NY SPILLS	G&J AUTOMOTIVE	1049 JEFFERSON BUFFALO NY	E	0.50 / 2,636.89	22	593
			Spill No* | *Close Date: 0904802 | 2009-12-15 00:00:00				
132	SHWS	Former Pendrick Laundry Site	1200 Jefferson Avenue Buffalo NY 14203	ENE	0.58 / 3,055.05	-5	594
133	SHWS	Diarsenol Co., Kingsley Park	Kingsley Street Buffalo NY 14208	ENE	0.77 / 4,065.45	-5	596

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
134	SHWS	1542 Main Street	1542 Main Street Buffalo NY 14209	N	0.80 / 4,223.15	-12	599
135	MRDS	BUFFALO PERLITE PLANT	ERIE COUNTY BUFFALO NY 14222 ***Dep ID:*** 10297233	NW	0.99 / 5,206.29	-2	600

Executive Summary: Summary by Data Source

Standard

Federal

RCRA CORRACTS - RCRA CORRACTS-Corrective Action

A search of the RCRA CORRACTS database, dated Nov 7, 2022 has found that there are 1 RCRA CORRACTS site(s) within approximately 1.00 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CENTURY CENTRE I	817 WASHINGTON ST BUFFALO NY 14203 ***EPA Handler ID**: NYD002107399*	SSW	0.47 / 2,476.66	119

RCRA TSD - RCRA non-CORRACTS TSD Facilities

A search of the RCRA TSD database, dated Nov 7, 2022 has found that there are 2 RCRA TSD site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ROSWELL PARK CANCER INSTITUTE	ELM & CARLTON STREETS BUFFALO NY 14263 ***EPA Handler ID**: NYD083534115*	S	0.26 / 1,361.98	65

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CENTURY CENTRE I	817 WASHINGTON ST BUFFALO NY 14203 ***EPA Handler ID**: NYD002107399*	SSW	0.47 / 2,476.66	119

RCRA LQG - RCRA Generator List

A search of the RCRA LQG database, dated Nov 7, 2022 has found that there are 8 RCRA LQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
UNIVERSITY AT BUFFALO - CTRC	875 ELLICOTT ST BUFFALO NY 14203 ***EPA Handler ID**: NYR000195461*	SW	0.02 / 92.34	6
NYSDOT-WB	RTE I-86 OVER RTE 60 ELLICOTT NY 14701 ***EPA Handler ID**: NYD986973444*	S	0.10 / 538.47	19
BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH	100 HIGH ST BUFFALO NY 14203 ***EPA Handler ID**: NYD074042292*	S	0.10 / 538.47	19

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CURIA GLOBAL INC – MAIN ST	1001 MAIN ST STE 700 BUFFALO NY 14203 ***EPA Handler ID**: NYR000218347*	WSW	0.12 / 641.48	27
SCHUELE PAINT CO	12 SUMMER ST BUFFALO NY 14209 ***EPA Handler ID**: NYR000165506*	WNW	0.16 / 836.96	41
UNIVERSITY AT BUFFALO-JSMBS	955 MAIN ST BUFFALO NY 14203 ***EPA Handler ID**: NYR000233718*	SW	0.25 / 1,296.56	62

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NATIONAL GRID MANHOLE 119 BEST BUFFALO	119 BEST ST BUFFALO NY 14209 ***EPA Handler ID**: NYP000967299*	NE	0.04 / 226.66	10
OSMOSE INC	980 ELLICOTT ST BUFFALO NY 14209 ***EPA Handler ID**: NYD002112944*	NNW	0.06 / 291.10	11

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Nov 7, 2022 has found that there are 4 RCRA SQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MULTILAB - FIRST FLOOR	100 HIGH ST ROOM 122 BUFFALO NY 14203-1154 ***EPA Handler ID**: NYR000144576*	S	0.10 / 538.47	19
MOBIL SERVICE STATION 99 - MST FORMERLY	1001 MAIN ST BUFFALO NY 14203 ***EPA Handler ID**: NYR000215533*	WSW	0.12 / 641.48	27
ATHENEX INC	1001 MAIN ST STE 600 CONVENTUS BUILDING BUFFALO NY 14203 ***EPA Handler ID**: NYR000234906*	WSW	0.12 / 641.48	27
SALVATION ARMY THE	984 MAIN ST BUFFALO NY 14202-1102 ***EPA Handler ID**: NYR000133009*	WSW	0.20 / 1,077.57	50

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Nov 7, 2022 has found that there are 3 RCRA VSQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
RESEARCH INSTITUTE ADDICTIONS	1021 MAIN ST BUFFALO NY 14203-1016 ***EPA Handler ID**: NYD982722076*	WSW	0.12 / 620.50	25
HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI	HIGH STREET BUFFALO NY 14203 ***EPA Handler ID**: NYR000130849*	SSW	0.13 / 712.17	34
NYS DMNA - FMS #1	27 MASTEN AVE BUFFALO NY 14204-1097 ***EPA Handler ID**: NYD981561665*	E	0.21 / 1,083.89	51

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Nov 7, 2022 has found that there are 19 RCRA NON GEN site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PATH-BIO-RESEARCH LABORATORY	50 HIGH ST BUFFALO NY 14203-1008 ***EPA Handler ID**: NYD982179434*	SW	0.11 / 594.21	21
ERIE CO PUBLIC HEALTH LAB	1021 MAIN ST - 5TH FL BUFFALO NY 14203 ***EPA Handler ID**: NYD986985448*	WSW	0.12 / 620.50	25
WORLD AUTO PAINT SHOPS OF BUFFALO INC	1114 MAIN ST BUFFALO NY 14209 ***EPA Handler ID**: NYD013780267*	WNW	0.13 / 712.68	35
GULF SERVICE STATION #176476	1038 MAIN ST BUFFALO NY 14202 ***EPA Handler ID**: NYR000033134*	WSW	0.16 / 844.61	43
PRECISION ABRASIVES CORP	11 SUMMER ST BUFFALO NY 14209 ***EPA Handler ID**: NYD986930584*	WNW	0.17 / 875.14	44
NORTHEAST TOWER INC	23 HIGH ST BUFFALO NY 14203 ***EPA Handler ID**: NYD982539645*	SW	0.17 / 920.40	45
AUTOPIA INC	1176 MAIN ST BUFFALO NY 14203 ***EPA Handler ID**: NYD987012838*	NW	0.19 / 1,010.67	48
CITIBANK	1008 MAIN ST BUFFALO NY 14202-1102 ***EPA Handler ID**: NYR000084129*	WSW	0.19 / 1,021.94	49
DMNA STATE OF NEW YORK OMS #2	27 MASTEN AVE BUFFALO NY 14204	E	0.21 / 1,083.89	51

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID**: NYD981561673*			
CITY HONORS SCHOOL	MASTEN AVE & NORTH BUFFALO NY 14204	E	0.21 / 1,090.40	52
	***EPA Handler ID**: NYD986940328*			
NIAGARA MOHAWK A NATIONAL GRID CO	1229 MAIN ST BUFFALO NY 14209	NNW	0.23 / 1,227.57	57
	***EPA Handler ID**: NYP000968909*			
MIDCITY OFFICE EQUIPMENT INC	1220 MAIN ST BUFFALO NY 14209	NNW	0.24 / 1,278.62	60
	***EPA Handler ID**: NYR000046102*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT ST MH 87TH BUFFALO NY 14209	NW	0.01 / 31.43	2
	***EPA Handler ID**: NYP000972182*			
NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT MH 61ST ST BUFFALO NY 14209	NW	0.01 / 31.43	2
	***EPA Handler ID**: NYP000972208*			
NIAGARA MOHAWK A NATIONAL GRID CO	45 BEST ST & OLD BEST ST BUFFALO NY 14209	WNW	0.03 / 182.83	8
	***EPA Handler ID**: NYP000974236*			
STATION 49	45 BEST ST BUFFALO NY 14209-2301	WNW	0.03 / 182.83	8
	***EPA Handler ID**: NYD980783229*			
DEGUSSA CORP	980 ELLICOTT ST - WAREHOUSE BUFFALO NY 14209	NNW	0.06 / 291.10	11
	***EPA Handler ID**: NYR000045112*			
DEL-RICH PROPERTIES	35 EDNA PL BUFFALO NY 14209	NNE	0.07 / 348.66	14
	***EPA Handler ID**: NYR000087031*			
BISHOP LESLIE	1059 ELLICOTT ST BUFFALO NY 14209	N	0.21 / 1,091.38	53
	***EPA Handler ID**: NYR000060442*			

State

SHWS - Registry of Inactive Hazardous Waste Disposal Sites in New York State

A search of the SHWS database, dated Jan 3, 2023 has found that there are 4 SHWS site(s) within approximately 1.00 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Osmose Wood Preserving	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	11
Former Pendrick Laundry Site	1200 Jefferson Avenue Buffalo NY 14203	ENE	0.58 / 3,055.05	132
Diarsenol Co., Kingsley Park	Kingsley Street Buffalo NY 14208	ENE	0.77 / 4,065.45	133
1542 Main Street	1542 Main Street Buffalo NY 14209	N	0.80 / 4,223.15	134

SWF/LF - Solid Waste Facilities and Landfills

A search of the SWF/LF database, dated Dec 22, 2021 has found that there are 2 SWF/LF site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Olmsted Center For Sight	1170 Main Street Buffalo NY 14209	NW	0.15 / 789.54	40
University at Buffalo (SUNY) Downtown Campus	955 Main Street Buffalo NY 14203	SW	0.25 / 1,296.56	62

LST - Leaking Storage Tanks

A search of the LST database, dated Jan 6, 2023 has found that there are 42 LST site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO GENERAL HOSPITAL	NORTH STREET BUFFALO NY	SW	0.02 / 92.34	6
	Spill No* | *Close Date: *9310029* | *1994-12-16 00:00:00*			
BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	19
	Spill No* | *Close Date: *0075587* | *2001-02-27 00:00:00*			
BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	19
	Spill No* | *Close Date: *8909904* | *1990-07-10 00:00:00*			
HOSPITAL	100 HIGH ST BUFFALO NY	S	0.10 / 538.47	19
	Spill No* | *Close Date: *2203688* | *2022-07-28 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO GENERAL HOSP	50 HIGH STREET BUFFALO NY	SW	0.11 / 594.21	21
	Spill No* | *Close Date: *0705382* | *2007-09-13 00:00:00*			
PHYSICANS IMAGING	979 MAIN STREET BUFFALO NY	WSW	0.12 / 641.48	27
	Spill No* | *Close Date: *8806781* | *1989-01-25 00:00:00*			
MAIN - SUMMER CORPORATION	MAIN & SUMMER STREETS BUFFALO NY	WNW	0.12 / 641.59	28
	Spill No* | *Close Date: *8908322* | *1990-04-02 00:00:00*			
A.R.G. TRUCKING CO.	MAIN AND NORTH ST. BUFFALO NY	WSW	0.12 / 655.66	29
	Spill No* | *Close Date: *8607168* | *1987-02-24 00:00:00*			
ROSWELL PARK CANCER INST.	MICHIGAN AND HIGH STREETS BUFFALO NY	SE	0.14 / 752.03	38
	Spill No* | *Close Date: *9504008* | *1996-07-01 00:00:00*			
ROSWELL PARK #6 OIL	HIGH & MICHIGAN AVENUES BUFFALO NY	SE	0.14 / 752.03	38
	Spill No* | *Close Date: *8907884* | *1989-12-12 00:00:00*			
ROSWELL PARK	MICHIGAN AND HIGH BUFFALO NY	SE	0.14 / 752.03	38
	Spill No* | *Close Date: *9875428* | *1999-03-01 00:00:00*			
NIRELLI'S GULF STATION	1038 MAIN & NORTH BUFFALO NY	WSW	0.16 / 844.61	43
	Spill No* | *Close Date: *8808014* | *1989-10-02 00:00:00*			
ARG TRUCKING	1038 MAIN STREET BUFFALO NY	WSW	0.16 / 844.61	43
	Spill No* | *Close Date: *8803956* | *1988-08-08 00:00:00*			
MASTEN AVENUE ARMORY	27 MASTEN AVENUE BUFFALO NY	E	0.21 / 1,083.89	51
	Spill No* | *Close Date: *9305872* | *1993-08-27 00:00:00*			
NYS ARMORY	27 MASTEN STREET BUFFALO NY	E	0.21 / 1,083.89	51
	Spill No* | *Close Date: *9709636* | *1998-03-30 00:00:00*			
MASTEN AVENUE ARMORY	27 MASTEN AVENUE BUFFALO NY	E	0.21 / 1,083.89	51
	Spill No* | *Close Date: *8904853* | *1990-11-14 00:00:00*			
MID CITY OFFICE EQUIPMENT	1220 MAIN STREET BUFFALO NY	NNW	0.24 / 1,278.62	60
	Spill No* | *Close Date: *9707872* | *1997-11-28 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
AGASSIZ HOLDINGS INC	1235 - 1245 MAIN STREET BUFFALO NY	NNW	0.24 / 1,288.80	61
	Spill No* | *Close Date: *0500859* | *2006-03-21 00:00:00*			
NYNEX	645 FRANKLIN STREET BUFFALO NY	W	0.25 / 1,297.40	63
	Spill No* | *Close Date: *9315172* | *1994-12-15 00:00:00*			
NYSDOH ROSWELL LOADING DK	ELM & CARLTON BUFFALO NY	S	0.26 / 1,361.98	65
	Spill No* | *Close Date: *9206876* | *1995-02-06 00:00:00*			
NYSDOH ROSWELL PARK	ELM AND CARLTON STREETS BUFFALO NY	S	0.26 / 1,361.98	65
	Spill No* | *Close Date: *9402510* | *1995-02-06 00:00:00*			
ROSWELL CANCER INSTITUTE	ELM AND CARLTON STREETS BUFFALO NY	S	0.26 / 1,361.98	65
	Spill No* | *Close Date: *9301132* | *1993-08-18 00:00:00*			
ROSWELL PARK	ELM AT CARLTON BUFFALO NY	S	0.26 / 1,361.98	65
	Spill No* | *Close Date: *0750760* | *2007-11-15 00:00:00*			
UST @ ROSWELL PRKG GARAGE	CARLTON STREET B/T ELM-MICHIGAN STS BUFFALO NY	SSE	0.26 / 1,373.20	68
	Spill No* | *Close Date: *0651376* | *2007-05-15 00:00:00*			
SINCLAIR RADIO OF BUFFALO	695 DELAWARE AVENUE BUFFALO NY	W	0.28 / 1,482.28	71
	Spill No* | *Close Date: *9709172* | *1998-12-02 00:00:00*			
WESTBROOK 675 DELAWARE	675 DELAWARE AVENUE BUFFALO NY	W	0.29 / 1,519.32	73
	Spill No* | *Close Date: *9308986* | *1994-04-20 00:00:00*			
FORMER GAS STATION	289 HIGH STREET BUFFALO NY	ESE	0.32 / 1,708.41	81
	Spill No* | *Close Date: *0275035* | *2002-08-30 00:00:00*			
KULBACK CONSTRUCTION	DELAWARE AT NORTH BUFFALO NY	W	0.33 / 1,745.61	82
	Spill No* | *Close Date: *9403219* | *1994-10-04 00:00:00*			
AMERICAN RED CROSS TANK	786 DELAWARE AVENUE BUFFALO NY	WNW	0.36 / 1,924.29	89
	Spill No* | *Close Date: *9404334* | *1995-12-12 00:00:00*			
BENDERSON 600 DELAWARE	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *9404468* | *1994-08-15 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BENDERSON DEVELOPMENT	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *9503691* | *1998-05-07 00:00:00*			
WESTMINSTER PRESBYTERIAN	724 DELAWARE AVENUE BUFFALO NY	W	0.40 / 2,127.33	102
	Spill No* | *Close Date: *8805542* | *1988-11-10 00:00:00*			
BENDERSON DEVELOPMENT	584 DELAWARE AVENUE BUFFALO NY	WSW	0.41 / 2,157.42	103
	Spill No* | *Close Date: *8808966* | *1989-11-10 00:00:00*			
TANKS AT APARTMENT COMPLE	905 DELAWARE AVENUE BUFFALO NY	NW	0.41 / 2,173.62	106
	Spill No* | *Close Date: *0075007* | *2000-06-22 00:00:00*			
925 DELAWARE AVENUE INC	925 DELAWARE AVENUE BUFFALO NY 14209	NW	0.44 / 2,300.20	112
	Spill No* | *Close Date: *0906378* | *2010-01-06 00:00:00*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OSMOSE WOOD PRESERVATIVE	980 ELLICOTT STREET BUFFALO NY	NNW	0.06 / 291.10	11
	Spill No* | *Close Date: *8903194* | *1989-09-12 00:00:00*			
OSMOSE WOOD PRESERVING	980 ELLICOTT STREET BUFFALO NY	NNW	0.06 / 291.10	11
	Spill No* | *Close Date: *9975243* | *1999-08-17 00:00:00*			
ROSWELL PARK	666 ELM STREET BUFFALO NY	S	0.30 / 1,600.72	76
	Spill No* | *Close Date: *8905775* | *1989-11-22 00:00:00*			
GREYHOUND	ELLICOTT & OAK STREETS BUFFALO NY	SSW	0.37 / 1,977.40	91
	Spill No* | *Close Date: *8912297* | *1990-03-29 00:00:00*			
ALLENTOWN TRADING COMPANY	553 DELAWARE AVENUE BUFFALO NY	WSW	0.41 / 2,172.28	105
	Spill No* | *Close Date: *9306552* | *2007-11-15 00:00:00*			
BRADLEY SUNOCO	553 DELAWARE AVENUE BUFFALO NY	WSW	0.41 / 2,172.28	105
	Spill No* | *Close Date: *8902410* | *1989-08-01 00:00:00*			
MASTEN-RILEY STATION	247 MASTEN AVENUE BUFFALO NY	NE	0.44 / 2,343.26	115
	Spill No* | *Close Date: *9601741* | *1996-05-03 00:00:00*			

UST - Underground Storage Tanks- UST-Petroleum Bulk Storage (PBS)

A search of the UST database, dated Nov 21, 2022 has found that there are 6 UST site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO GENERAL HOSPITAL	100 HIGH ST Buffalo NY 14203	S	0.10 / 538.47	19
	Site ID* | *Site Status: *54488* | *Active*			
PROPERTY	174 HIGH ST BUFFALO NY 14203	SE	0.15 / 771.75	39
	Site ID* | *Site Status: *443109* | *Unregulated/Closed*			
CUMBERLAND FARMS #176476	1038 MAIN ST Buffalo NY 14202	WSW	0.16 / 844.61	43
	Site ID* | *Site Status: *53097* | *Unregulated/Closed*			
MASTEN AVENUE ARMORY	27 MASTEN AVE Buffalo NY 14204	E	0.21 / 1,083.89	51
	Site ID* | *Site Status: *53860* | *Unregulated/Closed*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OSMOSE INC	980 ELLICOTT ST Buffalo NY 14209	NNW	0.06 / 291.10	11
	Site ID* | *Site Status: *52006* | *Active*			
OSMOSE INC.	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	11
	Site ID* | *Site Status: *339349* | *Unregulated/Closed*			

AST - The Bulk Storage Program Database - AST

A search of the AST database, dated Nov 21, 2022 has found that there are 7 AST site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO GENERAL HOSPITAL	100 HIGH ST Buffalo NY 14203	S	0.10 / 538.47	19
	Site ID* | *Site Status: *54488* | *Active*			
CONVENTUS BUILDING	1001 MAIN STREET BUFFALO NY 14203	WSW	0.12 / 641.48	27
	Site ID* | *Site Status: *563710* | *Active*			
CITY HONORS SCHOOL NO. 195	186 E. NORTH STREET Buffalo NY 14209	E	0.13 / 705.71	32
	Site ID* | *Site Status: *55323* | *Active*			
MASTEN AVENUE ARMORY	27 MASTEN AVE Buffalo NY 14204	E	0.21 / 1,083.89	51
	Site ID* | *Site Status: *53860* | *Unregulated/Closed*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SUNY AT BUFFALO JSMBS	955 MAIN ST. Buffalo NY 14203	SW	0.25 / 1,296.56	62
	Site ID* | *Site Status: *579178* | *Active*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OSMOSE INC	980 ELLICOTT ST Buffalo NY 14209	NNW	0.06 / 291.10	11
	Site ID* | *Site Status: *52006* | *Active*			
OSMOSE INC.	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	11
	Site ID* | *Site Status: *339349* | *Unregulated/Closed*			

DELISTED TANKS - Delisted Storage Tanks

A search of the DELISTED TANKS database, dated Nov 21, 2022 has found that there are 1 DELISTED TANKS site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OSMOSE INC.	980 ELLICOTT STREET BUFFALO NY 14209	NNW	0.06 / 291.10	11

ENG - Registry of Engineering Controls in New York State

A search of the ENG database, dated Jan 3, 2023 has found that there are 2 ENG site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Former Mobil Service Station 99-MST	979 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	27

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Former Trico Plant	791 Washington Street Buffalo NY 14203	SSW	0.49 / 2,574.88	125

INST - Registry of Institutional Controls in New York State

A search of the INST database, dated Jan 3, 2023 has found that there are 3 INST site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Former Mobil Service Station 99-MST	979 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	27

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Osmose Wood Preserving	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	11
Former Trico Plant	791 Washington Street Buffalo NY 14203	SSW	0.49 / 2,574.88	125

ERP - Environmental Restoration Program Listing

A search of the ERP database, dated Jan 3, 2023 has found that there are 1 ERP site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Century Centre I	817 Washington Street Buffalo NY 14203	SSW	0.47 / 2,476.66	119

BROWNFIELDS - Brownfields Site List (Subset of Site Remediation)

A search of the BROWNFIELDS database, dated Jan 3, 2023 has found that there are 11 BROWNFIELDS site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Buffalo City Mission (E. North St & Michigan Ave)	150 East North Street Buffalo NY 14203-1029	ESE	0.03 / 164.91	7
Former Pilgrim Village Family Apartments	1100 Michigan Avenue Buffalo NY 14209	E	0.06 / 322.34	12
Former Mobil Service Station 99-MST	979 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	27
1155 Main Street	1155 Main Street Buffalo NY 14209	NW	0.13 / 691.54	31
19 North Street	19 North Street Buffalo NY 14202	W	0.16 / 841.09	42

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Pilgrim Village Redevelopment/Campus Square	903 Ellicott Street Buffalo NY 14209	WNW	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Former Pilgrim Village Senior Apartments	951 Ellicott Street Buffalo NY 14209	NNW	0.01 / 71.96	5
980 Ellicott Street Site	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	11
Michigan-Best Development	1145 Michigan Avenue Buffalo NY 14209	ENE	0.12 / 616.23	24
Ellicott and Oak Streets Site	324, 328, and 334 North Oak St and 441 Ellicott St Bufalo NY 14203	SSW	0.39 / 2,047.16	95
Former Trico Plant	791 Washington Street Buffalo NY 14203	SSW	0.49 / 2,574.88	125

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Nov 2, 2020 has found that there are 2 FINDS/FRS site(s) within approximately 0.02 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
UNIVERSITY AT BUFFALO - CTRC	875 ELLICOTT ST BUFFALO NY 14203 ***Registry ID**: 110046400774*	SW	0.02 / 92.34	6

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT BUFFALO NY 14209 ***Registry ID**: 110066947380*	NW	0.01 / 31.43	2

HMIRS - Hazardous Materials Information Reporting System

A search of the HMIRS database, dated Sep 1, 2020 has found that there are 2 HMIRS site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	100 HIGH ST BUFFALO NY	S	0.10 / 538.47	19

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	100 HIGH ST BUFFALO NY	S	0.10 / 538.47	19

MRDS - Mineral Resource Data System

A search of the MRDS database, dated Mar 15, 2016 has found that there are 1 MRDS site(s) within approximately 1.00 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO PERLITE PLANT	ERIE COUNTY BUFFALO NY 14222 ***Dep ID**: 10297233*	NW	0.99 / 5,206.29	135

ALT FUELS - Alternative Fueling Stations

A search of the ALT FUELS database, dated Jan 3, 2023 has found that there are 23 ALT FUELS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
854ELLICOTT 854 ELLICOTT 10	854 Ellicott St Buffalo NY 14203 ***ID**: 180120*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 12	854 Ellicott St Buffalo NY 14203 ***ID**: 180115*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 8	854 Ellicott St Buffalo NY 14203 ***ID**: 162228*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 3	854 Ellicott St Buffalo NY 14203 ***ID**: 180119*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 9	854 Ellicott St Buffalo NY 14203 ***ID**: 180116*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 5	854 Ellicott St Buffalo NY 14203 ***ID**: 180112*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 6	854 Ellicott St Buffalo NY 14203 ***ID**: 180113*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 2	854 Ellicott St Buffalo NY 14203 ***ID**: 180117*	WSW	0.06 / 327.34	13

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
854ELLICOTT 854 ELLICOTT 11	854 Ellicott St Buffalo NY 14203 ***ID**: 180114*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 1	854 Ellicott St Buffalo NY 14203 ***ID**: 180122*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 7	854 Ellicott St Buffalo NY 14203 ***ID**: 180121*	WSW	0.06 / 327.34	13
854ELLICOTT 854 ELLICOTT 4	854 Ellicott St Buffalo NY 14203 ***ID**: 180118*	WSW	0.06 / 327.34	13
854ELLICOTT 134 HIGH ST 10	134 High St Buffalo NY 14203 ***ID**: 169910*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 5	134 High St Buffalo NY 14203 ***ID**: 181843*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 4	134 High St Buffalo NY 14203 ***ID**: 181846*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 9	134 High St Buffalo NY 14203 ***ID**: 181848*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 7	134 High St Buffalo NY 14203 ***ID**: 181847*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 1	134 High St Buffalo NY 14203 ***ID**: 181845*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 8	134 High St Buffalo NY 14203 ***ID**: 181849*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 2	134 High St Buffalo NY 14203 ***ID**: 181844*	SSE	0.12 / 610.22	23
854ELLICOTT 134 HIGH ST 6	134 High St Buffalo NY 14203 ***ID**: 169908*	SSE	0.12 / 610.22	23

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
854ELLICOTT 134 HIGH ST 3	134 High St Buffalo NY 14203 ***ID**: 169909*	SSE	0.12 / 610.22	23
CONVENTUS CONVENTUS	1001 Main Street Buffalo NY 14203 ***ID**: 165111*	WSW	0.12 / 641.48	27

SSTS - Registered Pesticide Establishments

A search of the SSTS database, dated Mar 30, 2022 has found that there are 2 SSTS site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
OSMOSE UTILITIES SERVICES, INC.	980 ELLICOTT ST - BUFFALO NY 14209 ***Establishment No**: 75341-NY-1*	NNW	0.06 / 291.10	11
OSMOSE INC	980 ELLICOTT ST - BUFFALO NY 14209 ***Establishment No**: 3008-NY-1*	NNW	0.06 / 291.10	11

PCB - Polychlorinated Biphenyl (PCB) Notifiers

A search of the PCB database, dated Nov 3, 2022 has found that there are 1 PCB site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TRICO PRODUCTS CORP.	817 WASHINGTON STREET BUFFALO NY 14203 ***Site ID**: NYD002107399*	SSW	0.47 / 2,476.66	119

State

NY SPILLS - Spill Incidents Database

A search of the NY SPILLS database, dated Jan 6, 2023 has found that there are 118 NY SPILLS site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BLD SITE OF GENERAL HOSPITAL	CORNER NORTH ST AND ELLICOTT ST BUFFALO NY ***Spill No**	**Close Date**: 0910563 | 2010-02-01 00:00:00*	WSW	0.01 / 48.91	3
BUFFALO GENERAL HOSPITAL	GOODRICH BUFFALO NY ***Spill No**	**Close Date**: 0751355 | 2008-05-09 00:00:00*	SW	0.02 / 92.34	6
PHASE II	1100 MICHIGAN AVE. BUFFALO NY 14202 ***Spill No**	**Close Date**: 1508707 | 2015-11-23 00:00:00*	E	0.06 / 322.34	12

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO GENERAL HOSPITAL	112 GOODRICH AVENUE BUFFALO NY	SSE	0.07 / 358.41	15
	Spill No* | *Close Date: *9502029* | *1995-05-18 00:00:00*			
BUFFALO GENERAL HOSPITAL	GOODRICH ST/ELLICOTT ST C/BUFFALO NY	SW	0.07 / 385.77	16
	Spill No* | *Close Date: *0705383* | *2007-09-13 00:00:00*			
BUFFALO GENERAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	19
	Spill No* | *Close Date: *0109330* | *2001-12-21 00:00:00*			
BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY	S	0.10 / 538.47	19
	Spill No* | *Close Date: *9408004* | *1994-09-14 00:00:00*			
BUFFALO GENERAL HOSPITAL	100 HIGH STREET BUFFALO NY 14203	S	0.10 / 538.47	19
	Spill No* | *Close Date: *1905674* | *2019-10-30 00:00:00*			
BUFFALO GENERAL HOSPITAL	100 HIGH ST BUFFALO NY	S	0.10 / 538.47	19
	Spill No* | *Close Date: *2203342* |			
NIAGARA MOHAWK TRANSFORME	1031 MAIN STREET BUFFALO NY	WSW	0.11 / 586.54	20
	Spill No* | *Close Date: *9406282* | *1994-09-07 00:00:00*			
PARKING LOT	1031 MAIN STREET BUFFALO NY	WSW	0.11 / 586.54	20
	Spill No* | *Close Date: *1311101* | *2016-10-11 00:00:00*			
KALEIDA HEALTH	50 HIGH STREET BUFFALO NY	SW	0.11 / 594.21	21
	Spill No* | *Close Date: *1201711* | *2012-08-24 00:00:00*			
TRANSFORMER PAD MOUNT	24R FOSDICK AVE BUFFALO NY	E	0.11 / 597.94	22
	Spill No* | *Close Date: *1503405* | *2015-06-29 00:00:00*			
PARKING LOT	1021 MAIN STREET BUFFALO NY	WSW	0.12 / 620.50	25
	Spill No* | *Close Date: *1311100* | *2016-10-11 00:00:00*			
BUFFALO GENERAL HOSPITAL	999 MAIN STREET BUFFALO NY	WSW	0.12 / 641.48	27
	Spill No* | *Close Date: *9508300* | *1995-10-30 00:00:00*			
OIL AT HIGH STREET	999 MAIN AND 24 HIGH BUFFALO NY	WSW	0.12 / 641.48	27
	Spill No* | *Close Date: *9500234* | *2015-09-15 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
WENDY,S	MAIN AND NORTH STREETS BUFFALO NY	WSW	0.12 / 655.66	29
	Spill No* | *Close Date: *8911108* | *1990-03-12 00:00:00*			
OIL IN STREET	336 MAPLE BUFFALO NY	ESE	0.13 / 685.33	30
	Spill No* | *Close Date: *0750965* | *2007-10-17 00:00:00*			
PARKING LOT - HOSPITAL	CARLTON & OAK / HIGH ST. BUFFALO NY	SSW	0.13 / 708.44	33
	Spill No* | *Close Date: *1810147* | *2019-01-08 00:00:00*			
ON SITE	1091 MAIN ST BUFFALO NY	W	0.14 / 715.44	36
	Spill No* | *Close Date: *1802722* | *2018-08-16 00:00:00*			
NIAGARAMO/BRYANT STRATON	1028 MAIN STREET BUFFALO NY	WSW	0.14 / 745.66	37
	Spill No* | *Close Date: *9705897* | *1997-10-09 00:00:00*			
ROSWELL PARK CANCER INSTI	MICHIGAN AT HIGH BUFFALO NY	SE	0.14 / 752.03	38
	Spill No* | *Close Date: *9875088* | *2000-03-08 00:00:00*			
ROSWELL PARK	MICHIGAN & HIGH STREETS BUFFALO NY	SE	0.14 / 752.03	38
	Spill No* | *Close Date: *9504945* | *1995-07-27 00:00:00*			
SIDEWALK	HIGH ST AND MICHIGAN AVE BUFFALO NY	SE	0.14 / 752.03	38
	Spill No* | *Close Date: *1609890* | *2017-01-27 00:00:00*			
174 HIGH PROJECT	174 HIGH STREET BUFFALO NY 14210	SE	0.15 / 771.75	39
	Spill No* | *Close Date: *0912618* | *2010-05-04 00:00:00*			
CUMBERLAND FARMS/GULF	1038 MAIN STREET BUFFALO NY	WSW	0.16 / 844.61	43
	Spill No* | *Close Date: *9311640* | *1994-07-01 00:00:00*			
CUMBERLAND FARMS	1038 MAIN STREET BUFFALO NY	WSW	0.16 / 844.61	43
	Spill No* | *Close Date: *9613078* | *1997-03-17 00:00:00*			
BEHIND VACANT HOUSES	204 HIGH ST BUFFALO NY	SE	0.18 / 938.11	46
	Spill No* | *Close Date: *0108495* | *2001-11-23 00:00:00*			
VACANT LOT FORMERLY 33 HIGH STREET APTS	960 WASHINGTON NY	SW	0.19 / 989.58	47
	Spill No* | *Close Date: *1204448* | *2014-04-29 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NYS NATIONAL GUARD	27 MASTEN AVENUE BUFFALO NY	E	0.21 / 1,083.89	51
	Spill No* | *Close Date: *9907527* | *1999-09-24 00:00:00*			
NATIONAL GUARD BUILDING	27 MASTEN AVE BUFFALO NY	E	0.21 / 1,083.89	51
	Spill No* | *Close Date: *9708830* | *1997-10-31 00:00:00*			
ARTSPACE	1219-1233 MAIN STREET BUFFALO NY	NNW	0.21 / 1,094.56	54
	Spill No* | *Close Date: *0600379* | *2006-10-26 00:00:00*			
FORMER SARA BETH BUILDING	1219-1233 MAIN STREET BUFFALO NY	NNW	0.21 / 1,094.56	54
	Spill No* | *Close Date: *0485354* | *2005-01-27 00:00:00*			
BFI TRUCK	33 LINWOOD AVENUE BUFFALO NY	W	0.22 / 1,159.45	55
	Spill No* | *Close Date: *9975353* | *1999-08-12 00:00:00*			
M J GRASS SCREW MACHINE	1233 MAIN STREET BUFFALO NY	NNW	0.23 / 1,206.26	56
	Spill No* | *Close Date: *8807560* | *1990-10-22 00:00:00*			
G&E MANAGEMENT	1233 MAIN ST BUFFALO NY	NNW	0.23 / 1,206.26	56
	Spill No* | *Close Date: *9100320* | *1991-04-10 00:00:00*			
CAO DART	1237 MAIN STREET BUFFALO NY	NNW	0.24 / 1,258.75	58
	Spill No* | *Close Date: *0175280* | *2001-08-24 00:00:00*			
CITY OF BUFFALO PARKS	29 NORTH HAMPTON BUFFALO NY	N	0.24 / 1,261.85	59
	Spill No* | *Close Date: *9913377* | *2000-04-10 00:00:00*			
ROSWELL	ELM AND CARLTON ST BUFFALO NY	S	0.26 / 1,361.98	65
	Spill No* | *Close Date: *1203400* | *2012-07-11 00:00:00*			
IN DITCH LINE	CORNER OF MICHIGAN AVE AND CARLTON ST BUFFALO NY ***Spill No* | *Close Date***: *1003048* | *2011-09-19 00:00:00*	SSE	0.26 / 1,368.63	66
A & J DISTRIBUTORS	36 NORTHAMPTON STREET BUFFALO NY	N	0.26 / 1,368.83	67
	Spill No* | *Close Date: *8603602* | *1987-05-06 00:00:00*			
IHRIG RESIDENCE	71 NORTH STREET BUFFALO NY	W	0.26 / 1,397.10	69
	Spill No* | *Close Date: *9503436* | *1995-06-20 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NATIONAL FUEL GAS	CARLTON AND WASHINGTON ST BUFFALO NY	SW	0.29 / 1,518.57	72
	Spill No* | *Close Date: *8905988* | *1990-03-14 00:00:00*			
TANK ROOM	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *0809396* | *2008-11-28 00:00:00*			
DELTASONIC	1264 MAIN STREET BUFFALO NY	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *9204557* | *1992-07-22 00:00:00*			
DELTA SONIC	1264 MAIN STREET BUFFALO NY	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *9906970* | *1999-09-14 00:00:00*			
DELTA SONIC CAR WASH	1264 MAIN STREET BUFFALO NY 14203	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *1407257* | *2014-10-14 00:00:00*			
FRONT YARD	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *1707510* | *2018-03-06 00:00:00*			
DELTA SONIC CAR WASH	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *1911365* | *2020-03-12 00:00:00*			
COMMERICAL	1264 MAIN ST BUFFALO NY	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *2002296* | *2020-06-29 00:00:00*			
COMMERCIAL	1264 MAIN ST BUFFALO NY 14209	NNW	0.30 / 1,573.13	74
	Spill No* | *Close Date: *2008396* | *2021-02-11 00:00:00*			
FAIRFAX APTS.	715 DELAWARE AVE. BUFFALO NY	W	0.31 / 1,646.25	78
	Spill No* | *Close Date: *0550371* | *2005-06-09 00:00:00*			
CITY OF BUFFALO	MAIN AND CARLTON STREETS BUFFALO NY	SW	0.32 / 1,671.54	79
	Spill No* | *Close Date: *8907967* | *1993-01-25 00:00:00*			
COMMERCIAL BUILDINGS	1269 THRU 1285 MAIN ST BUFFALO NY	NNW	0.32 / 1,675.64	80
	Spill No* | *Close Date: *1408808* | *2014-12-31 00:00:00*			
DEMOLITION SITE	289 HIGH STREET BUFFALO NY	ESE	0.32 / 1,708.41	81
	Spill No* | *Close Date: *0275036* | *2002-04-23 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ROAD SIDE	82 NORTH PEARL BUFFALO NY	WSW	0.33 / 1,748.63	83
	Spill No* | *Close Date: *1708175* | *2017-11-29 00:00:00*			
NATIONAL GRID COMMERCIAL	72 NORTH PEARL ST BUFFALO NY	SW	0.35 / 1,834.23	84
	Spill No* | *Close Date: *2207913* |			
SAINT VINCENT DEPAUL	1298 MAIN ST AT BRYANT BUFFALO NY	NNW	0.35 / 1,864.38	85
	Spill No* | *Close Date: *9603069* | *1996-06-05 00:00:00*			
GARY LOWD PROPERTY	1298 MAIN STREET BUFFALO NY	NNW	0.35 / 1,864.38	85
	Spill No* | *Close Date: *9106713* | *1991-09-23 00:00:00*			
MEDICAL WASTE/UNITED FUND	742 DELAWARE AVENUE BUFFALO NY	W	0.36 / 1,886.75	86
	Spill No* | *Close Date: *9710273* | *1997-12-10 00:00:00*			
COMPUTER TASK GROUP	700 DELAWARE AVE BUFFALO NY	W	0.36 / 1,891.59	88
	Spill No* | *Close Date: *0507232* | *2006-02-01 00:00:00*			
SOIL	215 PEACH ST BUFFALO NY	ESE	0.38 / 2,008.70	93
	Spill No* | *Close Date: *2007371* | *2020-11-17 00:00:00*			
HOLIDAY INN	620 DELAWARE AVENUE BUFFALO NY	WSW	0.38 / 2,019.95	94
	Spill No* | *Close Date: *8806417* | *1988-11-04 00:00:00*			
TOUR BUS	620 DELAWARE AVENUE BUFFALO NY	WSW	0.38 / 2,019.95	94
	Spill No* | *Close Date: *8704229* | *1987-08-24 00:00:00*			
AMHERST DISPOSAL	620 DELAWARE AVENUE BUFFALO NY	WSW	0.38 / 2,019.95	94
	Spill No* | *Close Date: *8703944* | *1987-09-30 00:00:00*			
LEAKING FIRE DEPT VEHICLE	289 DODGE BUFFALO NY	ENE	0.39 / 2,069.26	98
	Spill No* | *Close Date: *1503811* | *2015-07-09 00:00:00*			
CONCRETE	888 DELAWARE AVE BUFFALO NY	NW	0.39 / 2,072.55	100
	Spill No* | *Close Date: *2105781* | *2021-09-17 00:00:00*			
BENDERSON #2	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *8910055* | *1990-03-07 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NYSDEC - BUFFALO GAS PUMP	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *9004957* | *1990-08-06 00:00:00*			
ARMBRUST GASOLINE SPILL	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *8912037* | *1990-03-20 00:00:00*			
BENDERSON DEVELOPMENT	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *8900461* | *1991-07-03 00:00:00*			
MODERN DISPOSAL	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *9002580* | *1990-06-06 00:00:00*			
LASALLE AMBULANCE	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *9509971* | *1995-11-13 00:00:00*			
NYS DEPT. OF ENV. CONS.	600 DELAWARE AVENUE BUFFALO NY	WSW	0.40 / 2,111.59	101
	Spill No* | *Close Date: *8608020* | *1987-03-26 00:00:00*			
VAULT #16-109	584 DELAWARE AVE BUFFALO NY	WSW	0.41 / 2,157.42	103
	Spill No* | *Close Date: *1606362* | *2016-09-27 00:00:00*			
FUMES IN HOUSE	51 IRVING STREET BUFFALO NY	WSW	0.43 / 2,265.94	109
	Spill No* | *Close Date: *8709670* | *1988-10-20 00:00:00*			
NATIONAL GRID ABOVE GROUND VAULT	916 DELWARE AVE BUFFALO NY	NW	0.44 / 2,314.90	114
	Spill No* | *Close Date: *2109996* | *2022-07-15 00:00:00*			
KLENK RESIDENCE	293 LINWOOD AVENUE BUFFALO NY	NNW	0.47 / 2,488.69	120
	Spill No* | *Close Date: *9975538* | *2000-10-20 00:00:00*			
AMBASSADOR APTS TANK	175 NORTH STREET BUFFALO NY	W	0.49 / 2,564.59	123
	Spill No* | *Close Date: *9607625* | *2001-01-11 00:00:00*			
KISSLING INTERESTS LLC	175 NORTH BUFFALO NY	W	0.49 / 2,564.59	123
	Spill No* | *Close Date: *2006097* | *2020-10-06 00:00:00*			
NATIONAL GRID	301 LINWOOD AVE BUFFALO NY	NNW	0.49 / 2,571.77	124
	Spill No* | *Close Date: *0605499* | *2006-08-11 00:00:00*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FORMER RESIDENCE	1022 JEFFERSON AVE BUFFALO NY	E	0.49 / 2,599.98	126
	Spill No* | *Close Date: *0175376* | *2001-11-13 00:00:00*			
PAVEMENT	13 HODGE AVE BUFFALO NY	NW	0.49 / 2,601.93	127
	Spill No* | *Close Date: *1903061* | *2019-06-25 00:00:00*			
UNDERGROUND CABLE/MANHOLE 1056	1056 JEFFERSON AVE BUFFALO NY	E	0.50 / 2,631.04	130
	Spill No* | *Close Date: *1305900* | *2013-09-05 00:00:00*			
G&J AUTOMOTIVE	1049 JEFFERSON BUFFALO NY	E	0.50 / 2,636.89	131
	Spill No* | *Close Date: *0904802* | *2009-12-15 00:00:00*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NIAGARA MOHAWK	45 BEST STREET BUFFALO NY	WNW	0.03 / 182.83	8
	Spill No* | *Close Date: *9303440* | *1995-10-12 00:00:00*			
NIAGARA MOHAWK	45 BEST STREET BUFFALO NY	WNW	0.03 / 182.83	8
	Spill No* | *Close Date: *8603091* | *1986-10-16 00:00:00*			
OSMOSE	980 ELLICOTT ST Buffalo NY 14209	NNW	0.06 / 291.10	11
	Spill No* | *Close Date: *0750740* | *2007-08-24 00:00:00*			
OSMOSE WOOD	980 ELLICOTT STREET BUFFALO NY	NNW	0.06 / 291.10	11
	Spill No* | *Close Date: *9608362* | *1996-10-11 00:00:00*			
OSMOSE PRODUCT RELEASE	980 ELLICOTT ST Buffalo NY 14209	NNW	0.06 / 291.10	11
	Spill No* | *Close Date: *0750741* | *2008-01-15 00:00:00*			
NOCO ENERGY-980 ELLICOTT	980 ELLICOTT STREET BUFFALO NY	NNW	0.06 / 291.10	11
	Spill No* | *Close Date: *9505668* | *1995-08-11 00:00:00*			
ABANDONED MEDICAL WASTE	1003 ELLICOTT STREET BUFFALO NY	N	0.10 / 537.43	18
	Spill No* | *Close Date: *9910017* | *1999-11-18 00:00:00*			
TRANSFORMER	80 NORTH HAMPTON BUFFALO NY	NNE	0.27 / 1,425.31	70
	Spill No* | *Close Date: *1907809* | *2019-11-04 00:00:00*			
NATIONAL GRID	153 NORTH HAMPTON STREET BUFFALO NY 14203	NE	0.30 / 1,591.91	75

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Spill No* | *Close Date: *1109000* | *2012-01-25 00:00:00*			
J & I DISPOSAL	666 ELM STREET BUFFALO NY	S	0.30 / 1,600.72	76
	Spill No* | *Close Date: *8902159* | *1989-06-13 00:00:00*			
ROSWELL PARK	666 ELM STREET BUFFALO NY	S	0.30 / 1,600.72	76
	Spill No* | *Close Date: *8706549* | *1987-11-18 00:00:00*			
POLE 173	173 MULBERRY ST BUFFALO NY	SE	0.31 / 1,613.76	77
	Spill No* | *Close Date: *0805954* | *2008-08-27 00:00:00*			
COMMERCIAL	888 MAIN ST BUFFALO NY	SW	0.36 / 1,888.96	87
	Spill No* | *Close Date: *1704513* | *2017-08-15 00:00:00*			
ROSWELL PARKING RAMP	ELM & VIRGINIA STREETS BUFFALO NY	S	0.37 / 1,939.69	90
	Spill No* | *Close Date: *9108647* | *1992-01-03 00:00:00*			
ROADSIDE	65 RILEY @ HOLLAND BUFFALO NY	NNE	0.38 / 1,998.39	92
	Spill No* | *Close Date: *0375482* | *2004-12-13 00:00:00*			
TRI-GRAPHICS	78 ALLEN OR 99 VIRGINIA BUFFALO NY	WSW	0.39 / 2,055.99	96
	Spill No* | *Close Date: *0275050* | *2002-05-17 00:00:00*			
ROSWELL PARK CANER INSTIT	VIRGINIA ST/ELLICOTT ST BUFFALO NY	SSW	0.39 / 2,059.77	97
	Spill No* | *Close Date: *0207429* | *2002-11-22 00:00:00*			
POLE #152	MULBERRY & VIRGINIA BUFFALO NY	SSE	0.39 / 2,069.66	99
	Spill No* | *Close Date: *0711466* | *2008-03-14 00:00:00*			
APT COMPLEX IN PARKING LOT	2 ALICE COURT BUFFALO NY	S	0.41 / 2,166.27	104
	Spill No* | *Close Date: *2201549* | *2022-05-20 00:00:00*			
ST. JOHNS TOWERS	865 MICHGAN AVE. BUFFALO NY	S	0.42 / 2,219.64	107
	Spill No* | *Close Date: *0275453* | *2002-12-18 00:00:00*			
ST. JOHNS HOSPICE SITE	113 MAPLE BUFFALO NY	SSE	0.42 / 2,232.56	108
	Spill No* | *Close Date: *0550592* | *2008-12-23 00:00:00*			
SOIL	644 ELLICOT ST BUFFALO NY	SSW	0.43 / 2,267.12	110

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Spill No* | *Close Date: *2104166* | *2021-08-02 00:00:00*			
SEWAGE BACKUP AT BUILDING	560 DELAWARE AVENUE BUFFALO NY	WSW	0.43 / 2,294.82	111
	Spill No* | *Close Date: *9702249* | *1997-05-22 00:00:00*			
ROADWAY	245 NORTHHAMPTON ST BUFFALO NY	ENE	0.44 / 2,309.21	113
	Spill No* | *Close Date: *1405197* | *2014-08-20 00:00:00*			
MASTEN SALES & SERVICES	247 MASTEN AVE. BUFFALO NY	NE	0.44 / 2,343.26	115
	Spill No* | *Close Date: *0813761* | *2009-03-23 00:00:00*			
TRANSFORMER (PAD MOUNT)	641 ELLICOTT ST BUFFALO NY	SSW	0.45 / 2,368.37	116
	Spill No* | *Close Date: *1107814* | *2011-09-20 00:00:00*			
NATURAL GAS AT RESIDENCE	MICHIGAN & LAUREL STREET BUFFALO NY	NNE	0.45 / 2,377.99	117
	Spill No* | *Close Date: *9875375* | *1999-02-02 00:00:00*			
VACANT LOT	CORNER OF RILEY @ MASTON BUFFALO NY	NE	0.46 / 2,445.09	118
	Spill No* | *Close Date: *1507590* | *2015-10-21 00:00:00*			
TRICO	817 WASHINGTON STREET BUFFALO NY	SSW	0.47 / 2,476.66	119
	Spill No* | *Close Date: *9212975* | *1993-02-19 00:00:00*			
FLYNN'S BAR AND GRILL	815 MAIN STREET BUFFALO NY	SW	0.48 / 2,513.30	121
	Spill No* | *Close Date: *8803675* | *1989-10-02 00:00:00*			
NATIONAL FUEL GAS	73 MULBERRY STREET BUFFALO NY	SSE	0.48 / 2,520.67	122
	Spill No* | *Close Date: *9200310* | *1992-04-08 00:00:00*			
ROADWAY	147 ALLEN ST BUFFALO NY	WSW	0.49 / 2,605.14	128
	Spill No* | *Close Date: *1808242* | *2018-11-02 00:00:00*			
ODOR AT 499 DELAWARE	499 DELAWARE AVENUE BUFFALO NY	WSW	0.50 / 2,624.67	129
	Spill No* | *Close Date: *9004148* | *1990-07-14 00:00:00*			

NY MANIFEST - Hazardous Waste Manifest - Facilities

A search of the NY MANIFEST database, dated Dec 15, 2022 has found that there are 1 NY MANIFEST site(s) within approximately 0.12 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NIAGARA MOHAWK A NATIONAL GRID CO	45 BEST ST & OLD BEST ST BUFFALO NY 14209	WNW	0.03 / 182.83	8

GEN MANIFEST - Generators from Hazardous Waste Manifests

A search of the GEN MANIFEST database, dated Dec 15, 2022 has found that there are 16 GEN MANIFEST site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
UNIVERSITY AT BUFFALO - CTRC	875 ELLICOTT ST BUFFALO NY 14203	SW	0.02 / 92.34	6
BUFFALO GENERAL HOSPITAL	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	19
MULTILAB - FIRST FLOOR	100 HIGH ST ROOM 122 BUFFALO NY 14203	S	0.10 / 538.47	19
TRESCO DISTRIBUTION CORPORATION	820 ELLICOTT SQUARE BLDG BUFFALO NY 14203	SW	0.11 / 594.21	21
CMX LABORATORIES	50 HIGH STREET BUFFALO NY 14203	SW	0.11 / 594.21	21
ERIE COUNTY PUBLIC HEALTH LAB	1021 MAIN ST BUFFALO NY 14203	WSW	0.12 / 620.50	25
RESEARCH INSTITUTE OF ALCHOLISM	1021 MAIN STREET BUFFALO NY 14203	WSW	0.12 / 620.50	25
RESEARCH INSTITUTE ADDICTIONS	1021 MAIN ST BUFFALO NY 14203	WSW	0.12 / 620.50	25
CURIA GLOBAL INC - MAIN ST	1001 MAIN ST STE 700 BUFFALO NY 14203	WSW	0.12 / 641.48	27
MOBIL SERVICE STATION 99-MST FORMER	1001 MAIN ST BUFFALO NY 14203	WSW	0.12 / 641.48	27
ATHENEX INC	1001 MAIN ST SUITE 600 CONVENTUS BUILDING BUFFALO NY 14203	WSW	0.12 / 641.48	27

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT ST MH @ 87TH BUFFALO NY 14209	NW	0.01 / 31.43	2
NIAGARA MOHAWK A NATIONAL GRID CO	BEST ST & ELLICOTT MH @ 61ST ST BUFFALO NY 14209	NW	0.01 / 31.43	2
NIAGARA MOHAWK	STATION 49 BEST ST BUFFALO NY 14209	NW	0.01 / 60.10	4
NIAGARA MOHAWK A NATIONAL GRID CO	119 BEST ST. BUFFALO NY 14209	NE	0.04 / 226.66	10
OSMOSE WOOD PRESERVING INC	980 ELLICOTT ST BUFFALO NY 14209	NNW	0.06 / 291.10	11

COOLING TOWERS - Registered Cooling Towers

A search of the COOLING TOWERS database, dated Aug 2, 2022 has found that there are 11 COOLING TOWERS site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	150 E North St Buffalo NY 14203	ESE	0.03 / 164.91	7
	50 E North St Buffalo NY 14203	WSW	0.04 / 191.29	9
	1031 Michigan Ave Buffalo NY 14204	SE	0.10 / 507.39	17
	100 High St. Buffalo NY 14203	S	0.10 / 538.47	19
	100 High St. Buffalo NY 14203	S	0.10 / 538.47	19
	100 High St. Buffalo NY 14203	S	0.10 / 538.47	19

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	100 High St. Buffalo NY 14203	S	0.10 / 538.47	19
	100 High St. Buffalo NY 14203	S	0.10 / 538.47	19
	100 High St. Buffalo NY 14203	S	0.10 / 538.47	19
	1001 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	27
	1001 Main Street Buffalo NY 14203	WSW	0.12 / 641.48	27

TIER 2 - Tier 2 Report

A search of the TIER 2 database, dated Sep 28, 2022 has found that there are 15 TIER 2 site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY 14203	S	0.10 / 538.47	19
Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY 14203	S	0.10 / 538.47	19
Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY NY	S	0.10 / 538.47	19
Kaleida Health - Buffalo General Hospital	100 High Street Buffalo NY Erie	S	0.10 / 538.47	19
Kaleida Health - Highpointe	1023 Michigan Buffalo NY 14203	SE	0.12 / 637.81	26
Kaleida Health - Highpointe	1023 Michigan Buffalo NY 14203	SE	0.12 / 637.81	26

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Kaleida Health - Highpointe	1023 Michigan Buffalo NY NY	SE	0.12 / 637.81	26
Kaleida Health - Highpointe	1023 Michigan Buffalo NY Erie	SE	0.12 / 637.81	26
Albany Molecular Research, Inc.	1001 Main St, Suite 110 Buffalo NY 14203	WSW	0.12 / 641.48	27
Albany Molecular Research, Inc.	1001 Main St, Suite 110 Buffalo NY NY	WSW	0.12 / 641.48	27
Albany Molecular Research, Inc.	1001 Main St, Suite 110 Buffalo NY Erie	WSW	0.12 / 641.48	27

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
STATION #49 Substation	45 BEST STREET BETWEEN MAIN STREET AND ELLICOTT ROAD BUFFALO Buffalo NY 14209	WNW	0.03 / 182.83	8
Osmose, Inc.	980 Ellicott St. Buffalo NY 14209	NNW	0.06 / 291.10	11
Osmose, Inc.	980 Ellicott Street Buffalo NY 14209	NNW	0.06 / 291.10	11
Osmose Inc; 980 Ellicott Street, Buffalo, NY 14209	NY	NNW	0.06 / 291.10	11

AIR PERMITS - Air Permitted Facilities

A search of the AIR PERMITS database, dated Dec 30, 2022 has found that there are 5 AIR PERMITS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO GENERAL MEDICAL CENTER	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	19
BUFFALO GENERAL MEDICAL CENTER	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	19

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUFFALO GENERAL MEDICAL CENTER	100 HIGH ST BUFFALO NY 14203	S	0.10 / 538.47	19
ROSWELL PARK CANCER INSTITUTE	666 ELM & CARLTON STS BUFFALO NY 14263	S	0.25 / 1,308.86	64
ROSWELL PARK CANCER INSTITUTE	666 ELM & CARLTON STS BUFFALO NY 14263	S	0.25 / 1,308.86	64



Map: 1.0 Mile Radius

Order Number: 23022300643

Address: 903 and 951 Ellicott Street, Buffalo, NY

ERIS

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius

Order Number: 23022300643

Address: 903 and 951 Ellicott Street, Buffalo, NY

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 23022300643

Address: 903 and 951 Ellicott Street, Buffalo, NY

ERIS

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- Plume
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Aerial **Year: 2022**

Order Number: 23022300643

Address: 903 and 951 Ellicott Street, Buffalo, NY

Source: ESRI World Imagery

© ERIS Information Inc.



Topographic Map **Year: 2016**

Order Number: 23022300643

Address: 903 and 951 Ellicott Street, NY

Quadrangle(s): Buffalo SE OE W, NY; Buffalo NW, NY; Buffalo NE, NY; Buffalo SE, NY

© ERIS Information Inc.

Source: USGS Topographic Map

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 1	WNW	0.00 / 0.00	642.42 / -2	Pilgrim Village Redevelopment/Campus Square 903 Ellicott Street Buffalo NY 14209	BROWNFIELDS

Site Code:	504533
HW Code:	C915294
Program:	BCP
Site Class:	A
Site Name:	Pilgrim Village Redevelopment/Campus Square
Site Address:	903 Ellicott Street
City:	Buffalo
Zip:	14209
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.902361111
Longitude:	-78.866194444
SWIS:	1502
Acres:	3.430
Record Added:	2015-02-10 14:23:00
Record Update:	2021-04-07 12:54:00
Updated by:	AECAPRIO
Site Code (Web):	C915294
Program Type (Web):	BCP
Site Name (Web):	Pilgrim Village Redevelopment/Campus Square
Site Class (Web):	A
Address1 (Web):	903 Ellicott Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209
County (Web):	Erie
Longitude (Web):	-78.866194444
Latitude (Web):	42.902361111
Site Code (GIS):	C915294
Site Name (GIS):	Pilgrim Village Redevelopment/Campus Square
Program (GIS):	BCP
Site Class (GIS):	A
Address1 (GIS):	903 Ellicott Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14209
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Description:

Location: The Pilgrim Village Redevelopment/Campus Square site is an approximately 3.43-acre site located in an urban area at 903 Ellicott St. in the City of Buffalo, Erie County. The site is bordered by North Street, Michigan Avenue, Best Street, and Ellicott Street. Residential properties are located to the north, east and west with health care facilities located to the southwest. Site Features: The site is generally flat and is bisected by Halloway Boulevard. It contains a mix of buildings consisting of multi-family apartments/town homes, asphalt parking/driveway areas, sidewalks, and landscaped lawn areas. Current Zoning and Land Use: The site is currently used for multi-residential purposes and is zoned residential/commercial. The surrounding parcels are currently used for a combination of commercial, residential, light industrial, and utility right-of-ways. Past Use of the Site: The W.A. Eckert Manufacturing Company was located inside the northwest corner of the site from approximately 1884 to at about 1925 and produced aluminum, brass, and copper specialties. An auto repair shop operated just off the northwestern edge of the site from approximately 1931 to 1968. A gas tank is shown in

historical records for that auto repair shop, but there are no records of a tank removal. Site Geology and Hydrogeology: Subsurface conditions consist of approximately 4 to 7 feet of sand and silt fill materials overlying native soils. The native soils include silty clays, sands and silts.

Assessment:

Nature and Extent of Contamination: During the Remedial Investigation (RI), analytical samples were collected from soil and groundwater and analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigations conducted to date, the primary contaminants of concern include SVOCs, cadmium and trichloroethene (TCE). Soil: Polycyclic aromatic hydrocarbons (PAHs) were detected in 6 out of 15 surface soil samples. Benzo(a)anthracene (up to 12 parts per million (ppm)), benzo(a) pyrene (up to 11 ppm), benzo(b)fluoranthene (up to 16 ppm), and dibenzo(a,h)anthracene (up to 2.7 ppm) all exceeded industrial SCOs. Ideno(1,2,3-cd) pyrene (up to 7 ppm) exceeded the commercial SCO of 5.6 ppm, and benzo(k)fluoranthene (up to 8.3 ppm) and chrysene (up to 11 ppm) both exceeded restricted residential SCOs. Subsurface soil samples were taken of the urban fill up to 8 feet below ground surface (bgs). VOCs, including acetone, benzene, methylene chloride, toluene and 1,4-dioxane were detected at concentration exceeding unrestricted use SCOs. SVOCs, mainly PAHs, were detected mainly at concentrations exceeding restricted residential SCOs, but industrial SCOs were exceeded in two of the samples. Pesticides and PCB-1254 were detected at concentrations above unrestricted use SCOs. Metals, including arsenic, lead, mercury, nickel and zinc were detected at concentrations exceeding unrestricted use SCOs in all 20 samples, and arsenic exceeded industrial use SCOs in two of the samples. Native soil samples taken at varying depths from 7.5 to 12.5 feet bgs all met unrestricted use SCOs. Perimeter soil samples collected to investigate off-site conditions contained methylene chloride at a concentration exceeding unrestricted use SCOs. Seven of the samples contained benzo(a)pyrene at concentrations exceeding industrial SCOs, and several PAHs exceeded restricted residential SCOs. Metals, including lead, mercury, and zinc were detected above unrestricted use SCOs in 29 samples. Two samples contained chromium at concentrations exceeding residential SCOs, and arsenic exceeded industrial SCOs in one sample. Groundwater generally contained the same contaminants as the fill materials on the site. Acetone was the only volatile organic compound (VOC) detected in the groundwater. It was detected during both sampling events; however, it was only detected at concentrations above groundwater standards during the second sampling event. Two SVOCs, phenanthrene and pentachlorophenol, were each detected during at least one of the sampling events at concentrations above NYSDEC groundwater standards and guidance values. Pesticides were detected above standards and guidance values in the first sampling event but were not detected above NYSDEC groundwater standards and guidance values during the second sampling event. There were no PCBs detected in any of the samples for the first sampling event. PCB-1248 was detected above groundwater standard concentrations during the second sampling event. Aluminum, sodium, iron, magnesium, manganese, lead and chromium were all detected at concentrations above NYSDEC groundwater standards and guidance values during at least one of the sampling events.

Owner Information

Owner Op: 06
Sub Type: P03
Owner Name: Jeffrey Lehrbach
Owner Company: Campus Square LLC
Owner Street: 560 delaware avenue
Owner Street 2: Suite 300
Owner City: buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name:
Owner Company: North-Ellicott Management, Inc.
Owner Street: 91 Nora Lane
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14209
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Carol Ann Batt
Owner Company: Buffalo & Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: c/o Mark H. Trammell
Owner Company: North-Ellicott Management, Inc.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Street: 570 LeBrun Road
Owner Street 2:
Owner City: Amherst
Owner State: NY
Owner Zip: 14226
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Mark Trammell
Owner Company: North-Ellicott Management, Inc.
Owner Street: 570 LeBrun Road
Owner Street 2:
Owner City: amherst
Owner State: NY
Owner Zip: 14226
Country: United States of America

HW Extra Information

Dump:	False	**Record Added:**	2017-04-19 13:57:00
Structure:	False	**Record Updated:**	2017-04-19 13:57:00
Lagoon:	False	**Disposal Start:**	
Landfill:	False	**Disposal Terminate:**	
Pond:	False	**Latitude:**	
Dell:		**Longitude:**	
Updated By:	ALLOPES		

Environmental Remediation

Operable Unit: 01
Contaminants:

2	1 of 5	NW	0.01 / 31.43	638.77 / -6	NIAGARA MOHAWK A NATIONAL GRID CO BEST ST & ELLICOTT BUFFALO NY 14209	FINDS/FRS

Registry ID: 110066947380
FIPS Code: 36029
HUC Code: 04120104
Site Type Name: STATIONARY
Location Description:
Supplemental Location: MH @ 61ST ST
Create Date: 25-NOV-15
Update Date: 25-NOV-15
Interest Types: UNSPECIFIED UNIVERSE
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 28
Census Block Code: 360290031004001
EPA Region Code: 02
County Name: ERIE
US/Mexico Border Ind:
Latitude: 42.90398
Longitude: -78.86608
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-NEAREST INTERSECTION
Accuracy Value: 200

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110066947380
Program Acronyms:

RCRAINFO:NYP000972182, RCRAINFO:NYP000972208

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	2 of 5	NW	0.01 / 31.43	638.77 / -6	NIAGARA MOHAWK A NATIONAL GRID CO BEST ST & ELLICOTT MH 61ST ST BUFFALO NY 14209	RCRA NON GEN

EPA Handler ID: NYP000972208
Gen Status Universe: No Report
Contact Name: LENNY DELVECCHIO
Contact Address: 300, ERIE BLVD W, SYRACUSE, NY, 13202, US
Contact Phone No and Ext: 315-428-6670
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type:
Receive Date: 20160411
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150922
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO
Source Type: Emergency
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20160411
Handler Name:	NIAGARA MOHAWK A NATIONAL GRID CO
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Historical Handler Details

Receive Dt:	20150922
Generator Code Description:	Large Quantity Generator
Handler Name:	NIAGARA MOHAWK A NATIONAL GRID CO

2	***3 of 5***	***NW***	***0.01 / 31.43***	***638.77 / -6***	***NIAGARA MOHAWK A NATIONAL GRID CO BEST ST & ELLICOTT ST MH 87TH BUFFALO NY 14209***	***RCRA NON GEN***

EPA Handler ID:	NYP000972182
Gen Status Universe:	No Report
Contact Name:	LENNY DELVECCHIO
Contact Address:	300, ERIE BLVD W, SYRACUSE, NY, 13202, US
Contact Phone No and Ext:	315-428-6670
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	
Receive Date:	20160407
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20160407
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150921
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO
Source Type: Emergency
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Historical Handler Details

Receive Dt: 20150921
Generator Code Description: Large Quantity Generator
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO

2	4 of 5	NW	0.01 / 31.43	638.77 / -6	NIAGARA MOHAWK A NATIONAL GRID CO BEST ST & ELLICOTT MH @ 61ST ST BUFFALO NY 14209	GEN MANIFEST

RCRA ID: NYP000972208
District Name: NIAGARA MOHAWK A NATIONAL GRID CO
Contact Name: L MONTESANO
Business Phone No: 7168317209
Mailing Street 1: 144 KENSINGTON AVE
Mailing Street 2:
Mailing City: BUFFALO
Mailing State: NY
Mailing ZIP: 14214
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: ERIE

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 100 Pounds; 165 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	5 of 5	NW	0.01 / 31.43	638.77 / -6	NIAGARA MOHAWK A NATIONAL GRID CO BEST ST & ELLICOTT ST MH @ 87TH BUFFALO NY 14209	GEN MANIFEST

RCRA ID:	NYP000972182	**Mailing State:**	NY
District Name:	NIAGARA MOHAWK A NATIONAL GRID CO	**Mailing ZIP:**	14214
Contact Name:	L MONTESANO	**Mailing ZIP Ext:**	
Business Phone No:	7168317209	**Mailing Country:**	USA
Mailing Street 1:	144 KENSINGTON AVE	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	BUFFALO	**Location County:**	ERIE

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 100 Pounds; 110 Gallons

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of 1	WSW	0.01 / 48.91	647.21 / 3	BLD SITE OF GENERAL HOSPITAL CORNER NORTH ST AND ELLICOTT ST BUFFALO NY	NY SPILLS

Spill No:	0910563	**UST Trust:**	False
Site ID:	423324	**Spill Date:**	2009-12-28 08:00:00
DER Facility ID:	372217	**Received Date:**	2009-12-28 08:58:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2010-02-01 00:00:00
Water Body:		**Create Date:**	2009-12-28 09:01:00
Class:		**Update Date:**	2010-02-01 15:53:22.517000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CLEAN UP IN PROGRESS."

DEC Remark:

"12/28/09 TDJ CONSTRUCTION MACHINERY BEING USED AT GENERAL HOSPITAL PROJECT BROKE HYDRAULIC LINE CAUSING APPROX. 50 GALLONS OF FLUID TO COLLECT IN A DEPRESSION ON GROUND. PINTO CONSTRUCTION WAS CONTACTED BY HERB DARLING TO COLLECT AND DISPOSE OF LIQUID AND SOIL. SMALL PUMP WILL COLLECT STANDING LIQUID AND MACHINE WILL DIG CONTAMINATED SOIL. NO WATER OR DRAINS WERE AFFECTED. DISPOSAL RECEIPT WILL BE SENT WHEN COMPLETE. 2/1/10 TDJ DISPOSAL RECEIPTS FOR SPILL WERE RECEIVED. EP&S COLLECTED AND DISPOSED OF 906 GALLONS OF OIL/WATER MIXTURE. PINTO CONSTRUCTION COLLECTED AND REMOVED 18.37 TONS OF SOIL TO NIAGARA FALLS LANDFILL TAKEN BY ALLIED WASTE. NO FURTHER ACTION FILE CLOSED"

Material Information

OP Unit ID:	1179137	**Med Ind Air:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU:	01	**Med GW:**	False
Material ID:	2172710	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	55.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	HERB DARLING
Spiller Company:	DARLING CONSTRUCTION
Spiller Address:	131 CALIFORNIA DR
Spiller City:	WILLIAMSVILLE
Spiller State:	NY
Spiller Zip:	14221
Spiller Country:	999
Contact Name:	HERB DARLING
Contact Phone:	(716) 983-0188
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	1 of 1	NW	0.01 / 60.10	638.95 / -5	NIAGARA MOHAWK STATION 49 BEST ST BUFFALO NY 14209	GEN MANIFEST

RCRA ID:	NYD980783229	**Mailing State:**	NY
District Name:	NIAGARA MOHAWK	**Mailing ZIP:**	14214
Contact Name:	FRANK J GRABOWSKI	**Mailing ZIP Ext:**	
Business Phone No:	7168317426	**Mailing Country:**	USA
Mailing Street 1:	144 KENSINGTON AVE	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	BUFFALO	**Location County:**	ERIE

Manifest Information

Waste Code(s):

B002: (Wastes containing polychlorinated biphenyls (PCBs)) Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers, and cable.

Waste Amounts By Year:

1993: 3196 Kilograms; 7738 Kilograms; 4668 Kilograms

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	1 of 1	NNW	0.01 / 71.96	638.23 / -6	Former Pilgrim Village Senior Apartments 951 Ellicott Street Buffalo NY 14209	BROWNFIELDS

Site Code:	605812
HW Code:	C915363
Program:	BCP
Site Class:	C
Site Name:	Former Pilgrim Village Senior Apartments
Site Address:	951 Ellicott Street
City:	Buffalo
Zip:	14209
County:	Erie

Region:	9
Town:	Buffalo (c)
Latitude:	42.903619444
Longitude:	-78.864197222
SWIS:	1502
Acres:	1.860
Record Added:	2020-05-21 12:52:00
Record Update:	2022-12-27 15:37:00
Updated by:	BJMCPHER
Site Code (Web):	C915363
Program Type (Web):	BCP
Site Name (Web):	Former Pilgrim Village Senior Apartments
Site Class (Web):	C
Address1 (Web):	951 Ellicott Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209
County (Web):	Erie
Longitude (Web):	-78.864197222
Latitude (Web):	42.903619444
Site Code (GIS):	C915363
Site Name (GIS):	Former Pilgrim Village Senior Apartments
Program (GIS):	BCP
Site Class (GIS):	C
Address1 (GIS):	951 Ellicott Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14209
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Direct contact with contaminants in the soil is unlikely because the site is currently covered with buildings, pavement, and vegetation. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination.

Description:

Location: The 1.86-acre Former Pilgrim Village Senior Apartments site is located in a mixed residential/commercial area south of Best Street and east of Michigan Avenue in the City of Buffalo, Erie County. Site Features: The site is currently under development as affordable housing. Much of the site consists of the multi-storied building footprint surrounded by open area used for construction access. Non-building areas are planned to be used as parking or open vegetated areas. Current Zoning and Land Use: The site is currently zoned D-R Residential Campus. Future use of the site will be for multi-family residential. Past Use of the Site: From the late 1800s through the mid-1970s the site was occupied by dense residential housing with several small shops. In the 1970s the site was developed into the Pilgrim Village Apartment complex. The Pilgrim Village Apartments operated until 2021/2022. Site Geology and Hydrogeology: The sub-surface consists of urban fill which is predominantly sand, silt, crushed rock, asphalt, and brick from the ground surface to approximately 2 to 6 feet below ground surface. The fill is underlain by native soil consisting of sand, gravel, silty clay to clayey silt. Groundwater flow during the investigation was to the north or northwest. Groundwater flow direction may change as a result of the remedy and on-site development. Regional groundwater flow is west toward Lake Erie.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were semi-volatile organic compounds (SVOCs), arsenic, barium, copper, lead, mercury, and zinc in soil. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use.

Materials Information

Waste Name:	lead
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name: copper
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: NNN
Owner Name: J. Mascaro
Owner Company: Pilgrim Village Senior Housing Development Fund Company, Inc
Owner Street: 1408 Sweet Home Road, #8
Owner Street 2:
Owner City: Amherst
Owner State: NY
Owner Zip: 14228
Country: United States of America

Owner Op: 01
Sub Type: NNN
Owner Name: David Alexander
Owner Company: SAA EVI MC SENIOR, LLC
Owner Street: 150 SE 2nd Avenue, Suite 300
Owner Street 2:
Owner City: Miami
Owner State: FL
Owner Zip: 33131
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: David Alexander
Owner Company: SAA EVI MC SENIOR, LLC
Owner Street: 150 SE 2nd Avenue, Suite 300
Owner Street 2:
Owner City: Miami
Owner State: FL
Owner Zip: 33131
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Buffalo & Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: JSWALIA

Record Added: 2021-02-17 13:50:00
Record Updated: 2021-02-17 14:59:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Projects Information

Project Code:	02
Project Desc:	Remedial Investigation
Project Refer Name:	
End Date:	2021-05-10 00:00:00
End Status:	ACT
Operable Unit ID:	1352965
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Investigation

Environmental Remediation

Operable Unit:	00
Contaminants:	copper, lead, mercury, zinc
Operable Unit:	01
Contaminants:	copper, lead, mercury, zinc

6	*1 of 5*	*SW*	*0.02 / 92.34*	*647.65 / 3*	***BUFFALO GENERAL HOSPITAL GOODRICH BUFFALO NY***	***NY SPILLS***

Spill No:	0751355	***UST Trust:***	
Site ID:	392389	***Spill Date:***	2008-01-17 09:00:00
DER Facility ID:	341986	***Received Date:***	2008-01-17 10:00:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	2008-01-17 00:00:00
SWIS Code:	1502	***Close Date:***	2008-05-09 00:00:00
Water Body:		***Create Date:***	2008-01-17 10:00:00
Class:	D3	***Update Date:***	2008-05-09 08:49:30.273000000
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	jfotto
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"gauge blew on boiler tank spilling 40 gallons to the ground. safety kleen hired to clean up."

DEC Remark:

"01/17/08 JFO ON SITE MET WITH MR PETER MURPHY AND MR DOUG ROBINSON SUPERVISOR FOR BUFFALO GENERAL HOSPITAL. THE SPILL IS TO THE EQUIPMENT, WALLS AND CONCRETE FLOOR. NO OIL REACHED THE SUMP. THEY ARE CLEANING UP WITH PADS AND RAGS. HE WILL CALL WHEN COMPLETE. 01/22/08 JFO TELCON WITH MR ROBINSON. THE SPILL IS CLEANED FROM THE FLOOR, WALLS AND THE PIPING. THERE IS INSULATION ON SOME OF THE PIPING. 03/18/08 JFO CALL TO DOUG ROBINSON. HE WILL CONTACT MODERN LANDFILL FOR THE RECEIPTS AND FAX TO THIS OFFICE. 05/09/08 JFO RECEIVED THE DISPOSAL RECEIPT FOR THE CLEANUP MATERIAL. NO FURTHER ACTION REQUIRED. CLOSED"

Material Information

OP Unit ID:	1149397	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2139922	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	40.00	***Med Surf:***	True
Units:	G	***Med Subway:***	False
Recovered:	40.00	***Med Utility:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Soil:	False	**Oxygenate:**	False
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spill Data

Material Name:	#2 fuel oil
Material Family:	Petroleum
Quantity:	40
Units:	Gallons
Recovered:	40

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	2 of 5	SW	0.02 / 92.34	647.65 / 3	BUFFALO GENERAL HOSPITAL NORTH STREET BUFFALO NY	LST

Spill No:	9310029	**REM Phase:**	0
Site ID:	116252	**UST Trust:**	False
DER Facility ID:	101186	**Spill Date:**	1993-11-17 09:00:00
CID:		**Rcvd Date:**	1993-11-17 10:40:00
Program Type:	ER	**CAC Date:**	1994-12-16 00:00:00
SWIS Code:	1502	**Insp Date:**	1993-11-17 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	1994-12-16 00:00:00
Water Body:		**Create Date:**	1993-11-19 00:00:00
Class:	C3	**Update Date:**	1994-12-22 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	SORGI
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Citizen		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CITIZEN OBSERVED OIL RUNNING DOWN SIDEWALK INTO STREET."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 11/17/93: MJS SITE INSPECT. WEATHER RAINING. HEAVY SHEEN ON WATER RUNNING DOWN STREET. PRODUCT CAME OUT VENT PIPE DURING FILLING OF TANK. MET W/ MR KERLING - DEBRIS MUST BE DISPOSED. 09/08/94: MJS REVIEW FILE. NO RECEIPTS OR ANALYTICAL FOR CONT DEBRIS. LETTER TO RP REQUESTING DOCUMENTATION. RESPONSE DUE 10/1/94. 10/12/94: MJS TELECON FROM RP. HE WILL FORWARD DOCUMENTATION ASAP FOR CLOSURE OF FILE. 12/16/94: RECEICED DISPOSAL DOCUMENTATION FROM RP. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "

Material Information

OP Unit ID:	991734	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	392667	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Company: BUFFALO GENERAL HOSPITAL
Spiller Address: 100 HIGH STREET
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14203
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.887419993
Longitude: -78.877900023

---

6 | **3 of 5** | **SW** | **0.02 / 92.34** | **647.65 / 3** | **UNIVERSITY AT BUFFALO - CTRC**
875 ELLICOTT ST
BUFFALO NY 14203 | **FINDS/FRS**

Registry ID: 110046400774
FIPS Code: 36029
HUC Code: 04120104
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 27-AUG-12
Update Date: 28-MAR-14
Interest Types: SQG
SIC Codes:
SIC Code Descriptions:
NAICS Codes: 541711, 541712
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 28
Census Block Code: 360290031004004
EPA Region Code: 02
County Name: ERIE
US/Mexico Border Ind:
Latitude: 42.90196
Longitude: -78.8667
Reference Point: CENTER OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110046400774
Program Acronyms:

RCRAINFO:NYR000195461

---

6 | **4 of 5** | **SW** | **0.02 / 92.34** | **647.65 / 3** | **UNIVERSITY AT BUFFALO - CTRC**
875 ELLICOTT ST
BUFFALO NY 14203 | **GEN MANIFEST**

RCRA ID: NYR000195461
District Name: UNIVERSITY AT BUFFALO - CTRC
Contact Name: TONY OSWALD
Business Phone No: 7168293301
Mailing Street 1: 220 WINSPEAR AVE
Mailing Street 2:
Mailing City: BUFFALO
Mailing State: NY
Mailing ZIP: 14215
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: ERIE

Manifest Information

Waste Code(s):

D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 4 Pounds; 4 Pounds
2017: 40 Pounds

Manifest Information

Waste Code(s):

D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
U188: (108-95-2) Phenol

Waste Amounts By Year:

2017: 34 Pounds

Manifest Information

Waste Code(s):

P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2016: 4 Pounds

Manifest Information

Waste Code(s):

U007: (79-06-1) 2-Propenamide

Waste Amounts By Year:

2017: 18 Pounds

Manifest Information

Waste Code(s):

U188: (108-95-2) Phenol

Waste Amounts By Year:

2018: 177 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 20 Pounds; 23 Pounds
2014: 10 Pounds; 8 Pounds; 17 Pounds; 52 Pounds

2015: 18 Pounds; 6 Pounds; 6 Pounds
2016: 15 Pounds; 20 Pounds; 34 Pounds; 7 Pounds; 3 Pounds; 90 Pounds; 5 Pounds
2017: 81 Pounds; 12 Pounds; 89 Pounds; 12 Pounds; 142 Pounds; 17 Pounds; 5 Pounds; 24 Pounds; 8 Pounds
2018: 12 Pounds; 101 Pounds; 32 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2016: 12 Pounds; 3 Pounds
2017: 5 Pounds; 124 Pounds; 3 Pounds; 4 Pounds; 28 Pounds; 7 Pounds; 14 Pounds; 177 Pounds
2018: 3 Pounds; 3 Pounds; 3 Pounds; 7 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 6 Pounds; 3 Pounds; 55 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U003: (75-05-8) Acetonitrile (I,T)

Waste Amounts By Year:

2018: 30 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 2 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 2 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 2 Pounds
2018: 2 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)
U151: (7439-97-6) Mercury

Waste Amounts By Year:

2014: 11 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 11 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 3 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 30 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 64 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U122: (50-00-0) Formaldehyde

Waste Amounts By Year:

2018: 59 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 99 Pounds; 117 Pounds; 79 Pounds
2014: 42 Pounds; 33 Pounds; 7 Pounds; 60 Pounds; 4 Pounds; 60 Pounds; 4 Pounds
2015: 4 Pounds
2016: 15 Pounds; 83 Pounds; 7 Pounds; 3 Pounds; 9 Pounds; 2 Pounds
2017: 3 Pounds; 6 Pounds; 5 Pounds; 15 Pounds; 4 Pounds; 3 Pounds; 13 Pounds; 180 Pounds; 8 Pounds; 5 Pounds; 5 Pounds; 43 Pounds
2018: 25 Pounds; 15 Pounds; 60 Pounds; 2 Pounds; 10 Pounds; 3 Pounds; 64 Pounds

Manifest Information

Waste Code(s):

D019: CARBON TETRACHLORIDE (Waste Code Description from EPA Hazardous Waste Identification)
D020: CHLORDANE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
D028: 1,2-DICHLOROETHANE (Waste Code Description from EPA Hazardous Waste Identification)
D039: TETRACHLOROETHYLENE (Waste Code Description from EPA Hazardous Waste Identification)
D040: TRICHLORETHYLENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2014: 4 Pounds

6	5 of 5	SW	0.02 / 92.34	647.65 / 3	UNIVERSITY AT BUFFALO - CTRC 875 ELLICOTT ST BUFFALO NY 14203	RCRA LQG

EPA Handler ID:	NYR000195461
Gen Status Universe:	Large Quantity Generator
Contact Name:	JOSHUA SNYDER
Contact Address:	220, WINSPEAR AVE, BUFFALO, NY, 14215, US
Contact Phone No and Ext:	716-829-5829
Contact Email:	JSNYDER8@BUFFALO.EDU
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	State

Receive Date:	20220224
Location Latitude:	42.891917
Location Longitude:	-78.870007

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date:	20200903
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State

Evaluation Start Date:	20141126
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20220224
Handler Name:	UNIVERSITY AT BUFFALO - CTRC
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	D022
Waste Code Description:	CHLOROFORM

Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE

Hazardous Waste Code:	F005
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS

LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: D028
Waste Code Description: 1,2-DICHLOROETHANE

Hazardous Waste Code: D029
Waste Code Description: 1,1-DICHLOROETHYLENE

Hazardous Waste Code: U003
Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20120711
Handler Name: UNIVERSITY AT BUFFALO - CTRC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D029

Waste Code Description: 1,1-DICHLOROETHYLENE

Hazardous Waste Code: D028
Waste Code Description: 1,2-DICHLOROETHANE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: U003
Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	State	***Street 1:***	CAPER HALL
Name:	UNIVERSITY AT BUFFALO	***Street 2:***	
Date Became Current:	20120701	***City:***	AMHERST
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	14260

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	State	***Street 1:***	220 WINSPEAR AVE
Name:	JOSHUA SNYDER	***Street 2:***	
Date Became Current:	20210501	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-829-5829	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14215

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	State	***Street 1:***	
Name:	ANTHONY OSWALD	***Street 2:***	
Date Became Current:	20120701	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	State	***Street 1:***	CAPER HALL
Name:	UNIVERSITY AT BUFFALO	***Street 2:***	
Date Became Current:	20120701	***City:***	AMHERST
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14260

Historical Handler Details

Receive Dt: 20120711
Generator Code Description: Small Quantity Generator
Handler Name: UNIVERSITY AT BUFFALO - CTRC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	1 of 2	ESE	0.03 / 164.91	655.43 / 11	Buffalo City Mission (E. North St & Michigan Ave) 150 East North Street Buffalo NY 14203-1029	BROWNFIELDS

Site Code: 337121
HW Code: C915190
Program: BCP
Site Class: N
Site Name: Buffalo City Mission (E. North St & Michigan Ave)
Site Address: 150 East North Street
City: Buffalo
Zip: 14203-1029
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.902226730
Longitude: -78.863007915
SWIS: 1502
Acres: 1.530
Record Added: 2005-02-04 16:01:00
Record Update: 2013-02-19 14:56:00
Updated by: MLDOSTER
Site Code (Web): C915190
Program Type (Web): BCP
Site Name (Web): Buffalo City Mission (E. North St & Michigan Ave)
Site Class (Web): N
Address1 (Web): 150 East North Street
Address2 (Web):
Locality (Web): Buffalo
Zip Code (Web): 14203-1029
County (Web): Erie
Longitude (Web): -78.863007915
Latitude (Web): 42.902226730
Site Code (GIS): C915190
Site Name (GIS): Buffalo City Mission (E. North St & Michigan Ave)
Program (GIS): BCP
Site Class (GIS): N
Address1 (GIS): 150 East North Street
Address2 (GIS):
Locality (GIS): Buffalo
Zip Code (GIS): 14203-1029
County (GIS): Erie
Site Class Desc:
Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH:
Description:

A BCP application was received in early 2005 for the investigation of vacant land in support of the construction of a new housing facility. The application included an assessment conducted in 2004 which revealed no evidence of recognized environmental conditions in connection with the subject property. According to the 1951-1952 Polk Directory, the portion of the subject property historically addressed at 1082 Michigan Avenue was identified as a vehicle service facility. This facility was apparently not present in 1948 or in 1957, suggesting this operation was short-lived. No other records were discovered identifying this potential historic on-site operation of environmental concern. A building permit, dated 1954, relative to the installation of one

220-gallon fuel oil tank within a former on-site residence basement, historically addressed at 142 East North Street, is on file for the subject property. As this tank was located within the basement of this structure, it was likely an aboveground storage tank (AST) that was removed from the subject property at the time of building demolition. This project was denied entry into the BCP.

Assessment:

No environmental problems have been defined for this site.

Owner Information

Owner Op: 01
Sub Type: NNN
Owner Name:
Owner Company: CITY OF BUFFALO, BUFFALO URBAN RENEWAL AGENCY
Owner Street: 920 CITY HALL
Owner Street 2: 65 NIAGARA SQUARE
Owner City: BUFFALO
Owner State: NY
Owner Zip: 14202-3376
Country: United States of America

Owner Op: 06
Sub Type: NNN
Owner Name: THOMAS J. MCLAUGHLIN
Owner Company: CORNERSTONE MANOR L.P./CITY MISSION INC.
Owner Street: 100 EAST TUPPER STREET
Owner Street 2:
Owner City: BUFFALO
Owner State: NY
Owner Zip: 14203-1315
Country: United States of America

Environmental Remediation

Operable Unit: 01
Contaminants:

---

7 | ***2 of 2*** | ***ESE*** | ***0.03 / 164.91*** | ***655.43 / 11*** | ***150 E North St Buffalo NY 14203*** | ***COOLING TOWERS***

Equip Unique ID: 8445
Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: Baltimore Aircoil Company
Model: VF1-027-41K
Bacteriological Sample Dt: 05/13/2022
Legionella Sample Coll Dt: 05/13/2022
Last Legionella Sample Result: no
Street Address: 150 E North St
New Georeferenced Column: 150 E North St
Buffalo, ny 14203
(42.902159, -78.863266)

Cooling Capacity: 220
Cool Capacity Unit: Tonnage
Commissioned Dt: 07/16/2006
Inspection Dt: 05/13/2022

---

8 | ***1 of 6*** | ***WNW*** | ***0.03 / 182.83*** | ***640.47 / -4*** | ***STATION 49 45 BEST ST BUFFALO NY 14209-2301*** | ***RCRA NON GEN***

EPA Handler ID: NYD980783229
Gen Status Universe: No Report
Contact Name:
Contact Address: 300, ERIE BLVD W, SYRACUSE, NY, 13202, US

Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 42.903794
Location Longitude: -78.866592

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: STATION 49
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: STATION 49
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: STATION 49
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sequence No: 1
Receive Date: 19841120
Handler Name: STATION 49
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: X002
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country:
Zip Code: 99999

Owner/Operator Ind: Current Operator
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Historical Handler Details

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: STATION 49

Receive Dt: 19841120
Generator Code Description: Large Quantity Generator
Handler Name: STATION 49

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: STATION 49

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	2 of 6	WNW	0.03 / 182.83	640.47 / -4	NIAGARA MOHAWK 45 BEST STREET BUFFALO NY	NY SPILLS

Spill No: 9303440
Site ID: 308284
DER Facility ID: 248974
CID:
Program Type: ER
SWIS Code: 1502
UST Trust: False
Spill Date: 1993-06-15 23:15:00
Received Date: 1993-06-16 02:22:00
CAC Date: 1995-10-12 00:00:00
Insp Date:
Close Date: 1995-10-12 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Body:		**Create Date:**	1993-08-13 00:00:00
Class:	D4	**Update Date:**	1995-10-16 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	SORGI
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TRANSFORMER BURNED UP CAUSING OIL TO BOIL OVER."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 10/12/95: MJS REVIEW FILE. NO INSPECTION DUE TO INCORRECT STREET NAME. MJS TELECON TO LENNY FIUME(NIMO) AND HE STATED STATION #49 IS ON BEST ST AND NOT BETH STREET. MJS CORRECTED FILE. NO INSPECTION REQUIRED AT THIS TIME. NO RECEIPTS REQUIRED - MINOR QUANTITY. MJS CLOSE FILE."

Material Information

OP Unit ID:	985320	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	397015	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0017A		
Material Name:	PCB oil		

Spiller Information

Spiller Name:	
Spiller Company:	NIAGARA MOHAWK
Spiller Address:	535 WASHINGTON STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.903960020
Longitude:	-78.866668290

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	3 of 6	WNW	0.03 / 182.83	640.47 / -4	NIAGARA MOHAWK 45 BEST STREET BUFFALO NY	NY SPILLS

Spill No:	8603091	**UST Trust:**	False
Site ID:	308283	**Spill Date:**	1986-08-08 13:00:00
DER Facility ID:	248974	**Received Date:**	1986-08-08 14:19:00
CID:		**CAC Date:**	1986-10-16 00:00:00
Program Type:	ER	**Insp Date:**	1986-08-11 00:00:00
SWIS Code:	1502	**Close Date:**	1986-10-16 00:00:00
Water Body:		**Create Date:**	1986-08-08 00:00:00
Class:		**Update Date:**	1986-10-28 00:00:00
Meets Std:	True	**DEC Region:**	9

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Penalty: False
Lead DEC: LEARY
REM Phase: 0
After Hours: False
County: Erie
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"TRANSFORMER FAILURE"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL / / : CONTAINED BY CONCRETE BERM, CLEANED UP BY NIGARA MOHAWK CREW. / / : SITE INSPECTION 08/08/86, CLEANUP REQUIRED AND AGREED TO BY SPILLER; SITE INSPECTION 08/11/86, CLEANUP COMPLETE AND SATISFACTORY. / / : TELECON 8/8/86. / / : TELECONS 08/28/86 TO 09/17/86, SAMPLING RESULTS OF DRIVEWAY NEEDED. / / : TELECONS 08/28/86 TO 09/17/86, SAMPLING RESULTS OF DRIVEWAY NEEDED; LETTER 10/16/86 RECEIVED, SAMPLING RESULTS OK, COMPLETE. "

Material Information

OP Unit ID: 899986
OU: 01
Material ID: 475928
CAS No:
Material Family: Petroleum
Quantity: 15.00
Units: G
Recovered: 15.00
Med Soil: True
Med Air: False
Material Code: 0017A
Material Name: PCB oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NIAGARA MOHAWK
Spiller Address:
Spiller City:
Spiller State: ZZ
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.903960020
Longitude: -78.866668290

8	4 of 6	WNW	0.03 / 182.83	640.47 / -4	NIAGARA MOHAWK A NATIONAL GRID CO 45 BEST ST & OLD BEST ST BUFFALO NY 14209	RCRA NON GEN

EPA Handler ID: NYP000974236
Gen Status Universe: No Report
Contact Name: LENNY DELVECCHIO
Contact Address: 300, ERIE BLVD WEST, SYRACUSE, NY, 13202, US
Contact Phone No and Ext: 315-428-6670
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02

Land Type:
Receive Date: 20180912
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180329
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO
Source Type: Emergency
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180912
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Historical Handler Details

Receive Dt: 20180329
Generator Code Description: Large Quantity Generator
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO

8	***5 of 6***	***WNW***	***0.03 / 182.83***	***640.47 / -4***	***NIAGARA MOHAWK A NATIONAL GRID CO 45 BEST ST & OLD BEST ST BUFFALO NY 14209***	***NY MANIFEST***

RCRA ID: NYP000974236
District Name: NIAGARA MOHAWK A NATIONAL GRID CO
Business Phone No: 3154286670
Contact Name: LEONARD DELVECCHIO
Location ZIP Ext:

Mailing Street 1: 300 ERIE BLVD W
Mailing Street 2:
Mailing City: SYRACUSE
Mailing State: NY
Mailing ZIP: 13202

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Location County: ERIE
Location Country: USA
Mailing ZIP Ext:
Mailing Country: USA

---

8 | **6 of 6** | **WNW** | **0.03 / 182.83** | **640.47 / -4**

STATION #49 Substation
45 BEST STREET BETWEEN MAIN STREET AND ELLICOTT ROAD
BUFFALO
Buffalo NY 14209

TIER 2

Company Name: National Grid
DUN Bradstreet Cd: 00-695-2628
County: Erie
Latitude: 42.9027
Longitude: -78.8833
Report Method: Reported Online

---

9 | **1 of 1** | **WSW** | **0.04 / 191.29** | **648.35 / 4**

50 E North St
Buffalo NY 14203

COOLING TOWERS

Equip Unique ID: 7961
Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: BAC
Model: VTL-079-KXR
Bacteriological Sample Dt: 05/11/2022
Legionella Sample Coll Dt: 05/11/2022
Last Legionella Sample Result: no
Street Address: 50 E North St
New Georeferenced Column: 50 E North St
Buffalo, ny 14203
(42.902189, -78.867216)

Cooling Capacity:
Cool Capacity Unit: BTU
Commissioned Dt: 05/18/1995
Inspection Dt: 05/06/2022

---

10 | **1 of 2** | **NE** | **0.04 / 226.66** | **642.59 / -2**

NATIONAL GRID MANHOLE 119
BEST BUFFALO
119 BEST ST
BUFFALO NY 14209

RCRA LQG

EPA Handler ID: NYP000967299
Gen Status Universe: Large Quantity Generator
Contact Name: STEPHEN P HALLER
Contact Address: 300, ERIE BLVD W A-3, SYRACUSE, NY, 13202, US
Contact Phone No and Ext: 315-428-5206
Contact Email: STEPHEN.HALLER@US.NGRID.COM
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20120302
Location Latitude: 42.903798
Location Longitude: -78.849874

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20110502
Handler Name:	NIAGARA MOHAWK A NATIONAL GRID CO
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Emergency

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20120302
Handler Name:	NATIONAL GRID MANHOLE 119 BEST BUFFALO
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20110602
Handler Name:	NIAGARA MOHAWK A NATIONAL GRID CO
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	300
Type:	Private	***Street 1:***	ERIE BLVD W
Name:	NATIONAL GRID	***Street 2:***	
Date Became Current:	19791231	***City:***	SYRACUSE
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	13202

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	NIAGARA MOHAWK POWER CORP	***Street 2:***	
Date Became Current:	19791231	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type: Annual/Biennial Report update with Notification **Zip Code:**

Historical Handler Details

Receive Dt: 20110502
Generator Code Description: Small Quantity Generator
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO

Receive Dt: 20110602
Generator Code Description: Not a Generator, Verified
Handler Name: NIAGARA MOHAWK A NATIONAL GRID CO

10	2 of 2	NE	0.04 / 226.66	642.59 / -2	NIAGARA MOHAWK A NATIONAL GRID CO 119 BEST ST. BUFFALO NY 14209	GEN MANIFEST

RCRA ID: NYP000967299
District Name: NIAGARA MOHAWK A NATIONAL GRID CO
Contact Name: MIKE MORROW
Business Phone No: 7168317428
Mailing Street 1: 144 KENSINGTON AVE
Mailing Street 2:
Mailing City: BUFFALO
Mailing State: NY
Mailing ZIP: 14214
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: ERIE

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2011: 300 Pounds; 330 Gallons

11	1 of 22	NNW	0.06 / 291.10	637.97 / -6	DEGUSSA CORP 980 ELLICOTT ST - WAREHOUSE BUFFALO NY 14209	RCRA NON GEN

EPA Handler ID: NYR000045112
Gen Status Universe: No Report
Contact Name: CONNIE TWIFORD
Contact Address: PO BOX 606, THEODORE, NY, 36590, US
Contact Phone No and Ext: 334-443-4427
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20070101
Location Latitude: 42.904777
Location Longitude: -78.866374

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No

Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: DEGUSSA CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19970923
Handler Name: DEGUSSA CORP
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: DEGUSSA CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: OSMOSE INC
Date Became Current:
Date Ended Current:
Phone: 716-882-5905
Source Type: Notification
Street No:
Street 1: 980 ELLICOTT ST
Street 2:
City: BUFFALO
State: NY
Country:
Zip Code: 14209

Owner/Operator Ind: Current Owner
Type: Private
Name: OSMOSE INC
Date Became Current:
Street No:
Street 1: 980 ELLICOTT ST
Street 2:
City: BUFFALO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Ended Current:		**State:**	NY
Phone:	716-882-5905	**Country:**	US
Source Type:	Implementer	**Zip Code:**	14209
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	980 ELLICOTT ST
Name:	OSMOSE INC	**Street 2:**	
Date Became Current:		**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-882-5905	**Country:**	US
Source Type:	Implementer	**Zip Code:**	14209

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	DEGUSSA CORP
Receive Dt:	19970923
Generator Code Description:	Very Small Quantity Generator
Handler Name:	DEGUSSA CORP

11	*2 of 22*	*NNW*	*0.06 / 291.10*	*637.97 / -6*	***OSMOSE INC 980 ELLICOTT ST BUFFALO NY 14209***	***RCRA LQG***

EPA Handler ID:	NYD002112944
Gen Status Universe:	Large Quantity Generator
Contact Name:	EDWIN J GOETZ
Contact Address:	980, ELLICOTT ST, BUFFALO, NY, 14209, US
Contact Phone No and Ext:	716-882-5905 3443
Contact Email:	EGOETZ@OSMOSE.COM
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	Private
Receive Date:	20140210
Location Latitude:	42.90587
Location Longitude:	-78.865499

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation:	Yes
Citation:	
Violation Short Description:	Generators - Pre-transport
Violation Type:	262.C
Violation Determined Date:	20090113
Scheduled Compliance Date:	
Return to Compliance:	Documented
Actual Return to Compl:	20090203
Violation Responsible Agency:	State

Enforcement Details

Enforcement Type:	120
Enforcement Type Description:	WRITTEN INFORMAL
Enforcement Action Date:	20090113
Enf Disposition Status:	ACTION SATISFIED (CASE CLOSED)

Disposition Status Date: 20090212
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19980210
Scheduled Compliance Date: 19980808
Return to Compliance: Observed
Actual Return to Compl: 19980820
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 310
Enforcement Type Description: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date: 19980708
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount: 1200
Paid Amount: 1200

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19980210
Scheduled Compliance Date:
Return to Compliance: Observed
Actual Return to Compl: 19980820
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 210
Enforcement Type Description: INITIAL 3008(A) COMPLIANCE
Enforcement Action Date: 19980325
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount: 1600
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Universal Waste - Small Quantity Handlers
Violation Type: 273.B
Violation Determined Date: 20090113
Scheduled Compliance Date:
Return to Compliance: Documented

Actual Return to Compl: 20090203
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20090113
Enf Disposition Status: ACTION SATISFIED (CASE CLOSED)
Disposition Status Date: 20090212
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20170126
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19980820
Evaluation Type Description: NOT A SIGNIFICANT NON-COMPLIER
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19890510
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20140109
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20090113
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - Pre-transport
Return to Compliance Date: 20090203
Evaluation Agency: State

Evaluation Start Date: 20010322
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA Contractor/Grantee

Evaluation Start Date: 20020118
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20050831
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19980210
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

Violation Short Description: Generators - General
Return to Compliance Date: 19980820
Evaluation Agency: State

Evaluation Start Date: 19960725
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 20110111
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19910819
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19991208
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20030828
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19980210
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20090113
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Universal Waste - Small Quantity Handlers
Return to Compliance Date: 20090203
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1

Receive Date: 19800818
Handler Name: OSMOSE WOOD PRESERVING INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F004
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U081
Waste Code Description: 2,4-DICHLOROPHENOL (OR) PHENOL, 2,4-DICHLORO-

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140210
Handler Name: OSMOSE INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: U051
Waste Code Description: CREOSOTE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: OSMOSE, INC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060117
Handler Name: OSMOSE, INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20010101
Handler Name: OSMOSE INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900301
Handler Name: OSMOSE WD PG AA
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19920227
Handler Name: OSMOSE WOOD PRESERVING
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20040219
Handler Name: OSMOSE INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D020
Waste Code Description: CHLORDANE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D021
Waste Code Description: CHLOROBENZENE

Hazardous Waste Code: D013
Waste Code Description: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

Hazardous Waste Code: F034
Waste Code Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE CREOSOTE FORMULATIONS. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: P013
Waste Code Description: BARIUM CYANIDE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20020220
Handler Name: OSMOSE INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19940329
Handler Name: OSMOSE WOOD PRESERVING, INC.
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 19980225
Handler Name: OSMOSE WOOD PRESERVING, INC.
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19960322
Handler Name: OSMOSE WOOD PRESERVING INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20060118
Handler Name: OSMOSE, INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: P119
Waste Code Description: AMMONIUM VANADATE (OR) VANADIC ACID, AMMONIUM SALT

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: F034

Waste Code Description:	WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE CREOSOTE FORMULATIONS. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.
Hazardous Waste Code:	U051
Waste Code Description:	CREOSOTE
Hazardous Waste Code:	D006
Waste Code Description:	CADMIUM
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D007
Waste Code Description:	CHROMIUM

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	ELLICOTT ST
Name:	OSMOSE, INC.	***Street 2:***	
Date Became Current:	19511101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	14209
Owner/Operator Ind:	Current Operator	***Street No:***	980
Type:	Private	***Street 1:***	ELLICOTT ST
Name:	OSMOSE INC	***Street 2:***	
Date Became Current:	19511101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14209
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	ELLICOTT ST
Name:	OSMOSE INC	***Street 2:***	
Date Became Current:	19791231	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	14209
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	ELLICOTT ST
Name:	OSMOSE, INC.	***Street 2:***	
Date Became Current:	19511101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	14209
Owner/Operator Ind:	Current Owner	***Street No:***	980
Type:	Private	***Street 1:***	ELLICOTT ST
Name:	OSMOSE INC	***Street 2:***	
Date Became Current:	19511101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14209
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	ELLICOTT ST
Name:	OSMOSE INC	***Street 2:***	
Date Became Current:	19791231	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	14209

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	OSMOSE, INC.	***Street 2:***	
Date Became Current:	19511101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	NOT REQUIRED
Name:	PRIVATE CORP	***Street 2:***	
Date Became Current:		***City:***	NOT REQUIRED
Date Ended Current:		***State:***	WY
Phone:	212-555-1212	***Country:***	
Source Type:	Notification	***Zip Code:***	99999

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	ELLICOTT ST
Name:	OSMOSE INC	***Street 2:***	
Date Became Current:	19791231	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	14209

Historical Handler Details

Receive Dt:	20060117
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE, INC

Receive Dt:	20040219
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE INC

Receive Dt:	20060118
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE, INC

Receive Dt:	19980225
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE WOOD PRESERVING, INC.

Receive Dt:	19960322
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE WOOD PRESERVING INC

Receive Dt:	19800818
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE WOOD PRESERVING INC

Receive Dt:	19940329
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE WOOD PRESERVING, INC.

Receive Dt:	20010101
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE INC

Receive Dt:	20020220
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE INC

Receive Dt:	19900301
Generator Code Description:	Large Quantity Generator
Handler Name:	OSMOSE WD PG AA

Receive Dt:	20070101
Generator Code Description:	Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: OSMOSE, INC

Receive Dt: 19920227
Generator Code Description: Large Quantity Generator
Handler Name: OSMOSE WOOD PRESERVING

---

11 | **3 of 22** | **NNW** | **0.06 / 291.10** | **637.97 / -6** | **OSMOSE INC**
980 ELLICOTT ST
Buffalo NY 14209 | **AST**

Site ID: 52006
Site Status: Active
Program No: 9-014583
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Manufacturing (Other than Chemical)/Processing

Expiry: 2016/09/02
County: Erie
UTM X: 184382.11741
UTM Y: 4757494.96758

Tank Information

Prog No: 9-014583
Tank ID: 160442
Tank No: 5
Tank Status: 1
Tank Status Desc: In Service
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 08/01/1989
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 12000
Registered: True
Tank Model:
Pipe Model:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Class A Operator:
Class B Operator:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: E02
Code Name: Vault (with Access)
Type: Piping Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: K99
Code Name: Other
Type: Spill Prevention

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: OSMOSE INC
Contact Title: PLANT MANAGER
Contact Name: EDWIN GOETZ
Address1: 980 ELLICOTT ST
Address2:
City: BUFFALO
State: NY
Zip Code: 14209
Country Code: 001
Phone: (716) 882-5905
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: OSMOSE INC
Contact Title: PLANT MANAGER
Contact Name: EDWIN GOETZ
Address1: 980 ELLICOTT ST
Address2:
City: BUFFALO
State: NY
Zip Code: 14209
Country Code: 001
Phone: (716) 882-5905

Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: OSMOSE INC
Contact Title:
Contact Name: EDWIN GOETZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (716) 882-5905
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: OSMOSE INC
Contact Title:
Contact Name: EDWIN GOETZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (716) 882-5905
Phone Ext:
Email:
Fax:

11	*4 of 22*	*NNW*	*0.06 / 291.10*	*637.97 / -6*	***OSMOSE INC*** ***980 ELLICOTT ST*** ***Buffalo NY 14209***	***UST***

Site ID: 52006
Site Status: Active
Program No: 9-014583
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Manufacturing (Other than Chemical)/Processing
Expiry: 09/02/2016
County: Erie
UTM X: 184382.11741
UTM Y: 4757494.96758

Tank Information

Prog No: 9-014583
Tank ID: 160440
Tank No: 2
Tank Status: 6
Tank Status Desc: Closed Prior to 03/1991
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 04/01/1954
Close Date:
Tk Out of Serv Dt:
Capacity (Gal): 12000
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: NN
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	9-014583	***UDC Ind:***	1
Tank ID:	174892	***Red Tag Start Date:***	
Tank No:	4	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	04	***Test Method:***	NN
Tank Type Desc:	Fiberglass Coated Steel	***Date Tested:***	
Install Date:	10/09/2003	***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	12000	***Line Test Method:***	

Registered: True
Modified by: MJGRIFFI
Tank Model:
Last Modified: 05/09/2022
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 3
Subpart Desc: Subpart 3 contains requirements for USTs subject to just DEC requirements (primary example is tanks storing heating oil for on-premises consumption).
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: K99
Code Name: Other
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: E04
Code Name: Double walled UG
Type: Piping Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: F04
Code Name: Fiberglass
Type: Pipe External Protection

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: I02

Code Name: High Level Alarm
Type: Overfill

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Tank Information

Prog No:	9-014583	***UDC Ind:***	1
Tank ID:	160439	***Red Tag Start Date:***	
Tank No:	1	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	04/01/1954	***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	10000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	9-014583	***UDC Ind:***	1
Tank ID:	160441	***Red Tag Start Date:***	
Tank No:	3	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	08/01/1962	***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	12000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: OSMOSE INC
Contact Title:
Contact Name: EDWIN GOETZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (716) 882-5905
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: OSMOSE INC
Contact Title: PLANT MANAGER
Contact Name: EDWIN GOETZ
Address1: 980 ELLICOTT ST
Address2:
City: BUFFALO
State: NY
Zip Code: 14209
Country Code: 001
Phone: (716) 882-5905
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: OSMOSE INC
Contact Title:
Contact Name: EDWIN GOETZ
Address1:
Address2:
City:
State: NN
Zip Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Country Code:	999
Phone:	(716) 882-5905
Phone Ext:	
Email:	
Fax:	
Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	OSMOSE INC
Contact Title:	PLANT MANAGER
Contact Name:	EDWIN GOETZ
Address1:	980 ELLICOTT ST
Address2:	
City:	BUFFALO
State:	NY
Zip Code:	14209
Country Code:	001
Phone:	(716) 882-5905
Phone Ext:	
Email:	
Fax:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	5 of 22	NNW	0.06 / 291.10	637.97 / -6	Osmose Wood Preserving 980 Ellicott Street Buffalo NY 14209	SHWS

Site Code:	56635
HW Code:	915143
Program:	HW
Site Class:	04
Site Name:	Osmose Wood Preserving
Site Address:	980 Ellicott Street
City:	Buffalo
Zip:	14209
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.904453460
Longitude:	-78.866454220
SWIS:	1502
Acres:	0.533
Record Added:	1999-11-18 12:00:00
Record Update:	2022-02-22 13:43:00
Updated by:	AECAPRIO
Site Code (Web):	915143
Program Type (Web):	HW
Site Name (Web):	Osmose Wood Preserving
Site Class (Web):	04
Address1 (Web):	980 Ellicott Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209
County (Web):	Erie
Longitude (Web):	-78.866454220
Latitude (Web):	42.904453460
Site Code (GIS):	915143
Site Name (GIS):	Osmose Wood Preserving
Program (GIS):	HW
Site Class (GIS):	04
Address1 (GIS):	980 Ellicott Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14209
County (GIS):	Erie
Site Class Desc:	This classification is assigned to a site that has been properly closed but that requires continued site management consisting of operation, maintenance and/or monitoring. Class 4 is appropriate for a site where remedial construction actions have been completed for all operable units, but the site has not necessarily been brought into

compliance with standards, criteria, or guidance (e.g., a groundwater extraction and treatment system has been installed and is operating properly but groundwater standards have not been achieved yet). The Record of Decision should define the remedial action objectives that need to be achieved during site management. If a Certificate of Completion (CoC) is to be issued for a site, the CoC is issued concurrently with the reclassification.

Site Class Desc (Web): This classification is assigned to a site that has been properly closed but that requires continued site management consisting of operation, maintenance and/or monitoring. Class 4 is appropriate for a site where remedial construction actions have been completed for all operable units, but the site has not necessarily been brought into compliance with standards, criteria, or guidance (e.g., a groundwater extraction and treatment system has been installed and is operating properly but groundwater standards have not been achieved yet). The Record of Decision should define the remedial action objectives that need to be achieved during site management. If a Certificate of Completion (CoC) is to be issued for a site, the CoC is issued concurrently with the reclassification.

Assess DOH: Exposures via drinking water are not expected because homes in the area are served by public water and no known private wells exist in the immediate area. Direct contact exposure to site-related contaminants by community members is not expected because the remaining contaminants are located below a paved parking lot and public access to the site is restricted by security guards. A deed restriction is in place to control future digging on the site.

Description:

Location: The Osmose Wood Preserving site is an approximately 0.533-acre site located in a mixed commercial and residential area at 980 Ellicott Street in the City of Buffalo, Erie County. Site Features: The site contains multiple buildings and asphalt parking areas. Current Zoning and Land Use: This site is zoned for industrial manufacturing use and is currently unoccupied. Past Use of the Site: In 1989, underground storage tanks (USTs)at the site used for storage of creosote, No.2 Fuel Oil and other chemicals were found to be leaking. Soil surrounding the tanks was contaminated as a result. Site Geology and Hydrology: The site geology consists of approximately 60 feet of unconsolidated clay, silt, sand and gravel deposits, which is underlain by the Onondaga limestone bedrock. Fill mixed with silt and clay varies up to 5 feet below ground surface (fbgs), followed by low permeability silty clay from 7 to 12 fbgs. This is followed by highly permeable strata of sands and a mix of sands and gravel down to the bedrock. Depth to groundwater varies across the property and with the seasons. The groundwater at the site flows east toward Ellicott Street.

Assessment:

Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polycyclic aromatic hydrocarbons (PAHs) and petroleum hydrocarbons in soil and groundwater. Remedial activities have successfully achieved soil cleanup objectives for commercial use. Residual contamination in soil and groundwater is being managed under a Site Management Plan.

Materials Information

Waste Name: CREOSOTE (U051)
Waste Quantity: > 1000 GALLONS
Waste Code:

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 04
Sub Type: E
Owner Name: C/O David V. L. Bradley, Esq.
Owner Company: Osmose Realty Corporation
Owner Street: 980 ELLICOTT ST.
Owner Street 2:
Owner City: BUFFALO
Owner State: NY
Owner Zip: 14209
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Jon M. Williams
Owner Company: 780 Ellicott Street, LLC
Owner Street: 140 Lee Street
Owner Street 2: Suite 200
Owner City: Buffalo
Owner State: NY
Owner Zip: 14210
Country: United States of America

HW Extra Information

Dump:	False	***Record Added:***	1999-11-18 12:00:00
Structure:	False	***Record Updated:***	2018-11-02 09:58:00
Lagoon:	False	***Disposal Start:***	unknown
Landfill:	False	***Disposal Terminate:***	1990
Pond:	False	***Latitude:***	42:54:16:0
Dell:	False	***Longitude:***	78:52:00:0
Updated By:	JSWALIA		

Projects Information

Project Code:	05
Project Desc:	Remedial Action
Project Refer Name:	
End Date:	2000-02-01 00:00:00
End Status:	ACT
Operable Unit ID:	3152
Operable Unit:	01
Operable Unit Desc:	REMEDIAL PROGRAM
Code Name:	Remedial Action

Project Code:	04
Project Desc:	Remedial Design
Project Refer Name:	
End Date:	1999-03-01 00:00:00
End Status:	ACT
Operable Unit ID:	3152
Operable Unit:	01
Operable Unit Desc:	REMEDIAL PROGRAM
Code Name:	Remedial Design

Project Code:	05
Project Desc:	Remedial Action
Project Refer Name:	
End Date:	2000-05-01 00:00:00
End Status:	ACT
Operable Unit ID:	3155
Operable Unit:	02
Operable Unit Desc:	IRM - Ozonation Treatment of Soils
Code Name:	Remedial Action

Project Code:	02
Project Desc:	Remedial Investigation
Project Refer Name:	
End Date:	1997-01-01 00:00:00
End Status:	ACT
Operable Unit ID:	3152
Operable Unit:	01
Operable Unit Desc:	REMEDIAL PROGRAM
Code Name:	Remedial Investigation

Project Code:	25
Project Desc:	
Project Refer Name:	
End Date:	2019-09-03 00:00:00
End Status:	ACT
Operable Unit ID:	3152
Operable Unit:	01
Operable Unit Desc:	REMEDIAL PROGRAM
Code Name:	Certificate of Completion

Project Code:	05
Project Desc:	Remedial Action
Project Refer Name:	
End Date:	1990-10-01 00:00:00
End Status:	ACT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit ID: 3153
Operable Unit: 01A
Operable Unit Desc: IRM - Bioremediation of Soils
Code Name: Remedial Action

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 1995-07-01 00:00:00
End Status: ACT
Operable Unit ID: 3154
Operable Unit: 01B
Operable Unit Desc: IRM - LNAPL Recovery Wells
Code Name: Remedial Action

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 1994-08-01 00:00:00
End Status: ACT
Operable Unit ID: 3152
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Site Characterization

Environmental Remediation

Operable Unit: 00
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 01A
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 02
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 01B
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 01
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	6 of 22	NNW	0.06 / 291.10	637.97 / -6	Osmose Wood Preserving 980 Ellicott Street Buffalo NY 14209	INST

Site Code: 56635
HW Code: 915143
Control Type: INST
Program: HW
Site Class: 04
Site Name: Osmose Wood Preserving
Site Address: 980 Ellicott Street
City: Buffalo
Zip: 14209
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.904453460
Longitude: -78.866454220
SWIS: 1502
Acres: 0.533
Record Added: 1999-11-18 12:00:00
Record Updated: 2022-02-22 13:43:00
Updated By: AECAPRIO
Site Code (Web): 915143
Program Type (Web): HW

Site Class (Web):	04
Site Name (Web):	Osmose Wood Preserving
Address1 (Web):	980 Ellicott Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209
County (Web):	Erie
Longitude (Web):	-78.866454220
Latitude (Web):	42.904453460
Site Code (GIS):	915143
Program (GIS):	HW
Site Class (GIS):	04
Site Name (GIS):	Osmose Wood Preserving
Address 1 (GIS):	980 Ellicott Street
Address 2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14209
County (GIS):	Erie
Latitude (GIS):	
Longitude (GIS):	
Site Class Desc:	This classification is assigned to a site that has been properly closed but that requires continued site management consisting of operation, maintenance and/or monitoring. Class 4 is appropriate for a site where remedial construction actions have been completed for all operable units, but the site has not necessarily been brought into compliance with standards, criteria, or guidance (e.g., a groundwater extraction and treatment system has been installed and is operating properly but groundwater standards have not been achieved yet). The Record of Decision should define the remedial action objectives that need to be achieved during site management. If a Certificate of Completion (CoC) is to be issued for a site, the CoC is issued concurrently with the reclassification.
Site Class Desc (Web):	This classification is assigned to a site that has been properly closed but that requires continued site management consisting of operation, maintenance and/or monitoring. Class 4 is appropriate for a site where remedial construction actions have been completed for all operable units, but the site has not necessarily been brought into compliance with standards, criteria, or guidance (e.g., a groundwater extraction and treatment system has been installed and is operating properly but groundwater standards have not been achieved yet). The Record of Decision should define the remedial action objectives that need to be achieved during site management. If a Certificate of Completion (CoC) is to be issued for a site, the CoC is issued concurrently with the reclassification.
Assess DOH:	Exposures via drinking water are not expected because homes in the area are served by public water and no known private wells exist in the immediate area. Direct contact exposure to site-related contaminants by community members is not expected because the remaining contaminants are located below a paved parking lot and public access to the site is restricted by security guards. A deed restriction is in place to control future digging on the site.

Description:

Location: The Osmose Wood Preserving site is an approximately 0.533-acre site located in a mixed commercial and residential area at 980 Ellicott Street in the City of Buffalo, Erie County. Site Features: The site contains multiple buildings and asphalt parking areas. Current Zoning and Land Use: This site is zoned for industrial manufacturing use and is currently unoccupied. Past Use of the Site: In 1989, underground storage tanks (USTs)at the site used for storage of creosote, No.2 Fuel Oil and other chemicals were found to be leaking. Soil surrounding the tanks was contaminated as a result. Site Geology and Hydrology: The site geology consists of approximately 60 feet of unconsolidated clay, silt, sand and gravel deposits, which is underlain by the Onondaga limestone bedrock. Fill mixed with silt and clay varies up to 5 feet below ground surface (fbgs), followed by low permeability silty clay from 7 to 12 fbgs. This is followed by highly permeable strata of sands and a mix of sands and gravel down to the bedrock. Depth to groundwater varies across the property and with the seasons. The groundwater at the site flows east toward Ellicott Street.

Assessment:

Remediation at the site is complete. Prior to remediation the primary contaminants of concern were polycyclic aromatic hydrocarbons (PAHs) and petroleum hydrocarbons in soil and groundwater. Remedial activities have successfully achieved soil cleanup objectives for commercial use. Residual contamination in soil and groundwater is being managed under a Site Management Plan.

Controls Information

Control Code:	32	***Record Added Date:***	2007-06-18 10:29:00
Control Name:	Site Management Plan	***Record Updated Dt:***	2022-06-07 11:47:59.353000000
Control Type:	INST	***In Place Date:***	2019-07-29 00:00:00
Updated By:	TJMONNIN		
Control Code:	25	***Record Added Date:***	2007-06-18 10:29:00
Control Name:	Landuse Restriction	***Record Updated Dt:***	2022-06-07 11:47:59.353000000
Control Type:	INST	***In Place Date:***	2019-07-29 00:00:00
Updated By:	TJMONNIN		
Control Code:	J	***Record Added Date:***	2007-06-18 10:29:00

Control Name:	Environmental Easement	**Record Updated Dt:**	2022-06-07 11:47:59.353000000
Control Type:	INST	**In Place Date:**	2019-07-29 00:00:00
Updated By:	TJMONNIN		
Control Code:	34	**Record Added Date:**	2007-06-18 10:29:00
Control Name:	IC/EC Plan	**Record Updated Dt:**	2022-06-07 11:47:59.353000000
Control Type:	INST	**In Place Date:**	2019-07-29 00:00:00
Updated By:	TJMONNIN		
Control Code:	31	**Record Added Date:**	2007-06-18 10:29:00
Control Name:	Monitoring Plan	**Record Updated Dt:**	2022-06-07 11:47:59.353000000
Control Type:	INST	**In Place Date:**	2019-07-29 00:00:00
Updated By:	TJMONNIN		
Control Code:	08	**Record Added Date:**	2007-06-18 10:29:00
Control Name:	Ground Water Use Restriction	**Record Updated Dt:**	2022-06-07 11:47:59.353000000
Control Type:	INST	**In Place Date:**	2019-07-29 00:00:00
Updated By:	TJMONNIN		

Materials Information

Waste Name:	polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity:	UNKNOWN
Waste Code:	
Waste Name:	CREOSOTE (U051)
Waste Quantity:	> 1000 GALLONS
Waste Code:	

Owner Information

Owner Op:	04
Sub Type:	E
Owner Name:	C/O David V. L. Bradley, Esq.
Owner Company:	Osmose Realty Corporation
Owner Street:	980 ELLICOTT ST.
Owner Street 2:	
Owner City:	BUFFALO
Owner State:	NY
Owner Zip:	14209
Country:	United States of America
Owner Op:	01
Sub Type:	E
Owner Name:	Jon M. Williams
Owner Company:	780 Ellicott Street, LLC
Owner Street:	140 Lee Street
Owner Street 2:	Suite 200
Owner City:	Buffalo
Owner State:	NY
Owner Zip:	14210
Country:	United States of America

HW Extra Information

Dump:	False	**Dell:**	False
Structure:	False	**Updated By:**	JSWALIA
Lagoon:	False	**Record Added:**	1999-11-18 12:00:00
Landfill:	False	**Record Updated:**	2018-11-02 09:58:00
Pond:	False	**Latitude:**	42:54:16:0
Disposal Start:	unknown	**Longitude:**	78:52:00:0
Disposal Terminate:	1990		

Projects Information

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 1990-10-01 00:00:00
End Status: ACT
Operable Unit ID: 3153
Operable Unit: 01A
Operable Unit Desc: IRM - Bioremediation of Soils
Code Name: Remedial Action

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 1995-07-01 00:00:00
End Status: ACT
Operable Unit ID: 3154
Operable Unit: 01B
Operable Unit Desc: IRM - LNAPL Recovery Wells
Code Name: Remedial Action

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2000-02-01 00:00:00
End Status: ACT
Operable Unit ID: 3152
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Remedial Action

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 1994-08-01 00:00:00
End Status: ACT
Operable Unit ID: 3152
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Site Characterization

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2019-09-03 00:00:00
End Status: ACT
Operable Unit ID: 3152
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Certificate of Completion

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 1997-01-01 00:00:00
End Status: ACT
Operable Unit ID: 3152
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 1999-03-01 00:00:00
End Status: ACT
Operable Unit ID: 3152
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM

Code Name: Remedial Design

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2000-05-01 00:00:00
End Status: ACT
Operable Unit ID: 3155
Operable Unit: 02
Operable Unit Desc: IRM - Ozonation Treatment of Soils
Code Name: Remedial Action

Environmental Remediation

Operable Unit: 01
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 02
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 00
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 01B
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

Operable Unit: 01A
Contaminants: polycyclic aromatic hydrocarbons (PAHS), total

---

11 | **7 of 22** | **NNW** | **0.06 / 291.10** | **637.97 / -6** | **NOCO ENERGY-980 ELLICOTT**
980 ELLICOTT STREET
BUFFALO NY | **NY SPILLS**

Spill No: 9505668
Site ID: 114686
DER Facility ID: 100016
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: C3
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Affected Persons
Referred to:
Source: Tank Truck
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 1995-08-07 12:30:00
Received Date: 1995-08-07 14:00:00
CAC Date: 1995-08-11 00:00:00
Insp Date: 1995-08-11 00:00:00
Close Date: 1995-08-11 00:00:00
Create Date: 1995-08-06 00:00:00
Update Date: 2002-03-19 00:00:00
DEC Region: 9
Lead DEC: RMCROSSE
After Hours: False

Caller Remark:

"HOSE FAILED ON TANKER TRUCK SPILL ON LAND"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 08/07/95: RMC/SITE CLEAN UP NEAR COMPLETE, SEVERAL DRUMS FOR DISPOSAL, SPILLED ON PARKING LOT AND INTO CONTAINMENT SUMP, DISPOSAL DUE 9/15/95. 08/11/95: RMC/SITE ROESCH/PHONE CLEAN UP COMPLETE,4 DRUMS SPEEDY DRY ONBIO-CELL AT NOCO,AMOUNT SPILLED ADJUSTED DOWN FROM INITIAL EST AS DEBRIS GENERATED SUPPORT ONLY 100 GALLON SPILL, CLOSE OUT. "

Material Information

OP Unit ID: 1016553
Med Ind Air: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU:	01	**Med GW:**	False
Material ID:	363661	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	100.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	95.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	NOCO ENERGY
Spiller Address:	700 GRAND ISLAND BLVD
Spiller City:	TONAWANDA
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.904730960
Longitude:	-78.865969430

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	8 of 22	NNW	0.06 / 291.10	637.97 / -6	OSMOSE 980 ELLICOTT ST Buffalo NY 14209	NY SPILLS

Spill No:	0750740	**UST Trust:**	False
Site ID:	386213	**Spill Date:**	2007-08-17 12:00:00
DER Facility ID:	51197	**Received Date:**	2007-08-21 00:00:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2007-08-24 00:00:00
Water Body:		**Create Date:**	2007-08-22 07:50:00
Class:	A3	**Update Date:**	2007-08-24 08:52:55.273000000
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	cgmckenz
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Non Major Facility > 1,100 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SAL STATES TO DKK THAT THE BUFFALO NEWS POSTED AN ARTICLE IN THE PAPER REGARDING THE UNREPORTED RELEASE."

DEC Remark:

"8/21/07: DKK/FILE...HAZ SUBSTANCE SPILL NOTIFICATION TO LOCAL MUNICIPALITY IS NOT NECESSARY IN THIS CASE. SPILL OCCURRED SOMETIME DURING THE WEEKEND OF 8/17-19/07. HOWEVER DEC DID NOT LEARN OF THE RELEASE UNTIL THE MORNING OF 8/21/07 VIA A NEWS PAPER ARTICLE. BY THAT TIME THE RELEASE WAS ALREADY PUBLIC INFORMATION. ALSO, RELEASE WAS TO A SECONDARY CONTAINMENT SYSTEM AND REMEDIAL EFFORTS TO REMOVE THE SPILLED PRODUCT WERE ALREADY UNDERWAY. 8/24/07 FILE DUPLICATE OF SPILL #0750741. THIS SPILL CLOSED. ELECTRONIC FILE COPY ONLY."

Material Information

OP Unit ID:	1143458	**Med Ind Air:**	False
OU:	01	**Med GW:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material ID:	2133735	**Med SW:**	False
CAS No:	07440508	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0161A		
Material Name:	copper		

Spiller Information

Spiller Name:	ED GOETZ
Spiller Company:	OSMOSE
Spiller Address:	980 ELLICOTT
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14209
Spiller Country:	999
Contact Name:	ED GOETZ
Contact Phone:	(716) 882-5905
Contact Ext:	
Latitude:	42.904791475
Longitude:	-78.866386787

---

11 | ***9 of 22*** | ***NNW*** | ***0.06 / 291.10*** | ***637.97 / -6*** | ***OSMOSE WOOD 980 ELLICOTT STREET BUFFALO NY*** | ***NY SPILLS***

Spill No:	9608362	**UST Trust:**	False
Site ID:	114687	**Spill Date:**	1996-10-04 11:40:00
DER Facility ID:	100016	**Received Date:**	1996-10-04 11:45:00
CID:	196	**CAC Date:**	1996-10-11 00:00:00
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1996-10-11 00:00:00
Water Body:		**Create Date:**	1996-10-04 00:00:00
Class:	E5	**Update Date:**	1999-10-08 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Police Department		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"LEAKING PROPANE CYLINDER."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 10/4/96 CONTACTED OSMOSE. CYLINDER WAS A GAS GRILL TYPE. OSMOSE CLOSED THE VALVE. THE CYLINDER WAS DUMPED ON THEIR PROPERTY AND THEY JUST NOTICED IT. 10/4/96 HENRY SANDONATO W/DAR SAID TO DRAIN TANK & PUT IN GARBAGE. 10/4/96 CHERYL WEBSTER W/SOLID WASTE SAID IT IS OK TO DUMP IN GARBAGE IF EMPTY. 10/4/96 CONTACTED OSMOSE & TOLD THEM IT IS OK TO DISCHARGE CONTENTS THEN THROW IN GARBAGE. NO FURTHER ACTION IS REQUIRED. SITE CAN BE CLOSED."

Material Information

OP Unit ID:	1039409	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	344098	**Med SW:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	True		
Material Code:	2617A		
Material Name:	propane gas		

Spiller Information

Spiller Name:	
Spiller Company:	NONE
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	CARLOS GONZALEZ
Contact Phone:	(716) 882-5905
Contact Ext:	
Latitude:	42.904730960
Longitude:	-78.865969430

---

11 | ***10 of 22*** | ***NNW*** | ***0.06 / 291.10*** | ***637.97 / -6*** | ***OSMOSE PRODUCT RELEASE***
980 ELLICOTT ST
Buffalo NY 14209 | ***NY SPILLS***

Spill No:	0750741	**UST Trust:**	False
Site ID:	386215	**Spill Date:**	2007-08-17 12:01:00
DER Facility ID:	51197	**Received Date:**	2007-08-21 08:00:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2008-01-15 00:00:00
Water Body:		**Create Date:**	2007-08-22 08:02:00
Class:	A3	**Update Date:**	2008-10-23 14:58:40.673000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	fxgalleg
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Non Major Facility > 1,100 gal		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SAL STATES TO DKK THAT THE BUFFALO NEWS HAD AN ARTICLE IN THE PAPER THIS MORNING REGARDING THE UNREPORTED RELEASE OF 2000-3000 GALLONS OF PRODUCT (OIL/COPPER NAPHTHENATE MIXTURE) AT OSMOSE. THE ARTICLE STATES MOST OF THE 180 WORKERS WERE SENT HOME ON MONDAY MORNING AFTER FINDING THE OIL LEAK AT ITS PLANT, LEAK DIDN'T POSE AN EXPOSURE THREAT TO WORKS OR THE NEIGHBORHOOD AND WAS CONTAINED WITHIN THE PLANT, WORKERS WERE SENT HOME BECAUSE OF THE POTENTIAL FIRE RISK AND OILY ODOR. THE MIXTURE CONTAINS FUEL OIL AND A FUNGICIDE CALLED COPPER NAPHTHENATE USED AS A WOOD PRESERVATIVE USED ON TELEPHONE POLES AND RAILROAD TIES."

DEC Remark:

"8/21/07 CGM ON SITE W/ ED GOETZ. ED STATES THE DISCOVERY WAS MADE BY EMPLOYEE, RICH RILEY, AT 6AM MONDAY MORNING UPON SMELLING ODORS OUTSIDE THE BUILDING. ODOR WAS TRACED BACK TO AREA OF TWO 12000 GAL STORAGE TANKS (#2 FUEL OIL AND OIL/ COPPER MIXTURE) INSIDE AN ENCLOSED ROOM. IT IS UNKNOWN WHEN THE RELEASE OCCURRED BETWEEN FRIDAY AT 4: 30PM (LAST KNOWN OBSERVATION OF TANK SYSTEM AREA) AND THE MONDAY 6AM DISCOVERY. FACILITY STATES CAUSE IS UNKNOWN, BUT PIPING IS SUSPECTED DUE TO STAIN SPRAY ALONG WALL ABOVE PUMP AREA. OPTECH WAS CALLED IN MONDAY AND TUESDAY FOR CLEANUP. PRODUCT WAS PUMPED OUT OF ROOM INTO A TANKER OUTSIDE THE BUILDING IN AN ALCOVE OF THE PARKING LOT, REMAINING WASHWATER/ SPEEDI-DRI WAS DRUMMED (~12 DRUMS GENERATED). CONCRETE BLOCK ROOM CONTAINING TWO TANKS IS A SUNKIN BASEMENT WITH 4' OF STAIRS INTO THE ROOM. THIS AREA SERVED AS A SECONDARY CONTAINMENT. REMAINING STAINING ALONG WALLS OF ROOM INDICATE LEVEL PRODUCT REACHED. CALCULATED ROOM SIZE AND PRODUCT DEPTH INDICATE A POSSIBLE RELEASE OF 7540 GALLONS. FACILITY STATES A 2% MIXTURE OF COPPER EQUATES TO 151 GALLONS OF COPPER AND 7389 GAL OF OIL

RELEASED TO ROOM. A SUMP WAS OBSERVED IN THE FLOOR OF THE ROOM. THIS SUMP HAS PIPING CONNECTED TO THE ALCOVE PARKING LOT DRAIN. A VALVE IS STATED TO EXIST IN THE DRAIN WHICH WAS INACCESSIBLE DUE TO FLUID CONTENTS. LOT DRAIN/ SUMP AREA IS SUSPECT SINCE FACILITY HAS REPEATEDLY OBSERVED WATER INFILTRATION INTO THE SECONDARY CONTAINMENT. MINOR CRACKS OBSERVED IN THE FLOOR ALSO MAY INDICATE THE CONTAINMENT IS NOT TIGHT. DEPT REVIEWED MSDS SHEETS, SPILL RESPONSE, SPCC PLANS. PLAN LISTS EMERGENCY NUMBER NOTIFICATIONS TO FIRE, POLICE, MEDICAL, NRC, DEC, ERIE COUNTY EMERGENCY SERVS, DOT, BUFFALO SEWER AUTHORITY. THE REASON STATED FOR NO NOTIFICATIONS MADE IS THE COPPER NAPHTHENATE MSDS STATES THE MATERIAL DOES NOT CONTAIN SUBSTANCES WITH REPORTABLE QUANTITIES. DEPT REVIEWED REPORTING REQUIREMENTS FOR PBS AND CBS PROGRAMS THAT REGULATE THEIR FACILITY AND REQUIRED THEM TO REPORT THE RELEASE. OBSERVATIONS OF EQUIPMENT, PROCEDURES, DOCUMENTATION INDICATION DEFICIENCIES IN CBS COMPLIANCE; CBS INSPECTION MAY BE CONDUCTED. FACILITY WILL SUBMIT TO DEPARTMENT REQUIRED CBS DOCUMENTATION, IDENTIFY SOURCE OF LEAK, MAKE NECESSARY REPAIRS, REPLACEMENT, UPGRADE TANK SYSTEMS WHERE REGULATORILY DEFICIENT. IF CONTAINMENT IS TESTED AND FOUND TO LEAK, ADDITIONAL REMEDIAL ACTIVITY WILL PROCEED TO DETERMINE EXTENT OF IMPACT TO ENVIRONMENT. 8/21/07: DKK/FILE...HAZ SUBSTANCE SPILL NOTIFICATION TO LOCAL MUNICIPALITY IS NOT NECESSARY IN THIS CASE. SPILL OCCURRED SOMETIME DURING THE WEEKEND OF 8/17-19/07. HOWEVER DEC DID NOT LEARN OF THE RELEASE UNTIL THE MORNING OF 8/21/07 VIA A NEWS PAPER ARTICLE. BY THAT TIME THE RELEASE WAS ALREADY PUBLIC INFORMATION. ALSO, RELEASE WAS TO A SECONDARY CONTAINMENT SYSTEM AND REMEDIAL EFFORTS TO REMOVE THE SPILLED PRODUCT WERE ALREADY UNDERWAY. 8/22/07 FACILITY FAXED TANK#6 FIVE-YEAR INSPECTION REPORT. UPON REVIEW, CBS INSPECTION RECOMMENDED. 8/23/07 ED GOETZ T/C W/CGM. STATES FACILITY LOCATED TANK HOLE AS LEAK SOURCE. OPTECH CALLED BACK IN TO CLEAN UP SECONDARY CONTAINMENT AND CLEAN OUT TANK CONTENTS. HIRED ENGINEER TO ASSESS NEED FOR TANK FOR CURRENT PROCESS USE AND REQUIRED REPAIRS/ REPLACEMENT DEEMED NECESSARY. WILL SEND WRITTEN CONFIRMATION AND FOLLOWUP REPORT BY 9/5/07. CGM/JOSPOL REVIEW OF ONGOING REMEDIATION ACTIVITY. CLOSEST MWS TO SPILL AND SUMP-DRAIN AREA ARE MWS 24,26. LOCATION OF WELLS AND SOIL TYPES MAY NOT DISCLOSE ANY IMPACTS. 8/24/07 FACILITY EMAIL DOCUMENTING CURRENT STATUS NOTED ABOVE. 8/31/07 RECEIVED OSMOSE INVESTIATION/ CAP REPORT CONFIRMING SPILL EVENTS. ROOM QUARANTINED TO ASSESS SITUATION, CLOSED PLANT, OPTECH HIRED FOR CLEANUP, AST #6 TANK/ EQUIPMENT INSPECTIONS PERFORMED, SPILL OCCURRED DUE TO A HOLE IN THE TANK BOTTOM. INVESTIGATION CONCLUDES WATER/ SLUDGE INTRODUCED DURING RE-CIRCULATION REACTED UNFAVORABLY W/STEEL TANK. CORRECTIVE ACTIONS STATED TO BE DECIDE ON FUTURE USE OF FAILED TANK (REPAIR, REPLACE), CONTACT RAW MATERIALS SUPPLIERS FOR ADDITIONAL INFO ON CHEM COMPOSITION OF PRODUCT, INSPECT/REPAIR SECONDARY CONTAINMENT FOR INTEGRITY, AST#5 TO BE DRAINED, REVIEW EMERGENCY PLANS AND MAKE NECESSARY CHANGES. 9/4/07 ED GEOTZ EM TO DEPT STATING INVESTIGATION REPORT SUBMITTED ON 8/31 WAS PRELIMINARY REPORT. UPDATE TO BE PROVIDED SOON. 9/7/07 UPDATED INVESTIGATION REPORT SUBMITTED. CHANGES TO ABOVE REPORT INCLUDE: INSPECTION OF SECONDARY CONTAINMENT CONFIRMS NO ENV IMPACT OCCURRED, BUT WAS CONTAINED, ALL RELEASED MATERIAL RECOVERED, NO INJURIES OCCURRED. NO PIPING/ANCILLARY EQIUPMENT DEFICIENCIES FOUND BY QUALITY INSPECTION SERVICES INC, MINOR RPIPING REPAIRS NOTED AND REPAIRED. INTERNAL AST INSPECTION SHOWS TANK FAILED FOR EXCESSIVE RUST AND CORROSION AND PLACED OUT OF SERVICE. CAUSE OF CORROSION UNDER INVESTIGATION SINCE APRIL 2006 INSPECTION STATE VESSEL WAS IN GOOD CONDITION. INTRODUCTION OF SECOND PHASE WATER SUSPECTED THROUGH RAW MATERIALS OR ATMOSPHERIC CONDENSATION. AST #5 CONVERTED TO CUNAP-8 BLEND. BOTTOM DRAIN INCORPORATED TO INSURE AGITATION, SAMPLING FOR MOISTURE MONTHLY PART OF REVISED SPCC PLAN, UPGRADING SECONDARY CONTAINMENT PLANNED, AST #5 DRAINED. 9/28/07 CGM ON SITE W/ED GOETZ FOR INSPECTION AFTER CLEANUP. WALLS AND PORTION OF FLOOR SEALANT ADDED. AST #6 TANK TAKEN OUT OF SERVICE PERMANENTLY, PRODUCT FROM TANKER AND RESIDUAL IN TANK SWITCHED TO TOTES, HEATING OIL REMAINS IN OTHER TANK INSIDE SECONDARY CONTAINMENT. DEPT REQUESTED FOLLOWUP EVIDENCE OF CHANGES ONCE MADE INFERENCED IN LAST REPORT (STATING IMPROVEMENTS INTENDED). DEPT REQUESTED TEST SHOWING SECONDARY CONTAINMENT TESTED TIGHT AS REPORT STATES. GEOTZ STATES HE WILL LOCATE WORK PERFORMED TO DATE. HE DOES NOT THINK SUMP WAS INCLUDED IN SECONDARY CONTAINMENT TESTING. GOETZ STATES HE REVISED CBS APPLICATION TO SHOW TANK CLOSED AND IS NO LONGER CBS REGULATED. DEPT REQUESTS DISPOSAL RCPTS SUBMITTED FOR CLEANUP MATERIAL. 10/1/07 DEPT RECEIVED AST #6 INTERNAL EXPECTION REPORT DATED 9/7/07. REPORT STATES TANK IS NOT FIT FOR CONTINUED SERVICE DUE TO EXTENSIVE REPAIRS REQUIRED. SEVERAL HOLES LOCATED IN BOTTOM SECTION OF TANK BELOW DIP PIPE. SEVERELY CORRODED AREA IS APPROXIMATELY 5' WIDE AND COVERS ENTIRE LENGTH OF TANK. SEVERE PITTING ON TANK ENDS/HEADS BETWEEN 1/8 -3/16 DEEP. 10/2/07 OSMOSE FAXED DISPOSAL RECEIPTS SHOWING 10,990 POUNDS TAKEN TO ASHLAND BINGHAMTON FACILITY. 10/5/07 DEPT RECEIVES GOETZ EM DATED 10/4/07 WITH PICS SHOWING AST6 STENCILED W/PERMANENTLY CLOSED. 10/09/07 HARD COPY OF STATUS OF CORRECTIVE ACTIONS REPORT RECEIVED BY CGM. REPORT STATES AST#5 CONVERTED TO STORE FUEL OIL BLEND W/BOTTOM DRAIN (NEED TO CONFIRM, CONFLICTS W 9/28 INSPECTION USE OF TOTES), RAW MATERIALS SUPPLIERS STATE ADDING WATER AND SULFER USE INCREASED CORROSION OF STEEL CAUSING TANK TO FAIL, SECONDARY CONTAINMENT EPOXY ADDED TO WALL/FLOOR JUNCTION FORMULATED FOR THESE CHEMICALS, SUMP HOLE HYDROSTATICALLY TESTED FOR 48 HOURS TO DETERMINE LEACHING-NONE FOUND, NO LONGER REGULATED UNDER CBS-SPR REMOVED FROM SPCC PLAN. 1/15/08 SECONDARY CONTAINMENT SHOWN NOT TO HAVE BEEN BREACHED. DISPOSAL RECEIPTS PROVIDED AND TANK USED FOR PRODUCT NOT REGULATED BY CBS. NO FURTHER WORK IS REQUIRED. THE SITE IS CLOSED."

Material Information

OP Unit ID:	1143460	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2133738	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	7389.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0001A
Material Name: #2 fuel oil

OP Unit ID: 1143460
OU: 01
Material ID: 2133737
CAS No: 07440508
Material Family: Hazardous Material
Quantity: 151.00
Units: G
Recovered:
Med Soil: True
Med Air: False
Material Code: 0161A
Material Name: copper

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: ED
Spiller Company: OS
Spiller Address: 980 ELLICOTT
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14209
Spiller Country: 999
Contact Name: ED GOETZ
Contact Phone: (716) 851-5905
Contact Ext:
Latitude: 42.904791475
Longitude: -78.866386787

11	11 of 22	NNW	0.06 / 291.10	637.97 / -6	OSMOSE WOOD PRESERVATIVE 980 ELLICOTT STREET BUFFALO NY	LST

Spill No: 8903194
Site ID: 114685
DER Facility ID: 100016
CID:
Program Type: ER
SWIS Code: 1502
Contribute Factor: Tank Overfill
Water Body:
Class:
Meets Std: True
Penalty: False
County: Erie
Referred to:
Reported by: Responsible Party
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 1989-06-26 12:00:00
Rcvd Date: 1989-06-26 14:00:00
CAC Date: 1989-09-12 00:00:00
Insp Date: 1989-08-22 00:00:00
Close Date: 1989-09-12 00:00:00
Create Date: 1989-06-27 00:00:00
Update Date: 2002-03-19 00:00:00
DEC Region: 9
Lead DEC: ROSS
After Hours: False

Caller Remark:

"1-10000,2-12000 TANKS TO BE REMOVED"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR 06/26/89: LQR TELCON W/ SPILLER TANKS EMPTIED,AND TO BE REMOVED. 07/17/89: RLL TELCON W/ SPILLER MW'S INDICATED READINGS OF CONTAMINATION. 08/14/89: LQR TELCON W/ SPILLER PRODUCT IN MW,S TANKS TO BE EMPTIED ASAP. 08/16/89: LQR TELCON W/ SPILLER PRODUCT IN MW,S TANKS TO BE EMPTIED ASAP, TANKSTO BE PULLED 8/21-23/89. 08/21/89: LQR TELCON W/ SPILLER TANKS TO BE PULLED 8/22/89. 09/05/89: LQR TELCON W/ SPILLER CONTRACTOR TO BUG SOIL. 09/11/89: LQR TELCON W/ SPILLER REFERED TO HW UNIT TO REVIEW RESULTS. 09/12/89: REFERED TO HW UNIT. "

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Information

OP Unit ID:	930695	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	447306	***Med SW:***	False
CAS No:	08001589	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0180A		
Material Name:	creosote		

Spiller Information

Spiller Name:	
Spiller Company:	OSSOMOS
Spiller Address:	980 ELLICOTT STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14209
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.904730960
Longitude:	-78.865969430

11	***12 of 22***	***NNW***	***0.06 / 291.10***	***637.97 / -6***	***OSMOSE WOOD PRESERVING 980 ELLICOTT STREET BUFFALO NY***	***LST***

Spill No:	9975243	***REM Phase:***	0
Site ID:	114688	***UST Trust:***	False
DER Facility ID:	100016	***Spill Date:***	1999-06-28 10:50:00
CID:		***Rcvd Date:***	1999-06-28 11:00:00
Program Type:	ER	***CAC Date:***	
SWIS Code:	1502	***Insp Date:***	1999-06-28 00:00:00
Contribute Factor:	Tank Failure	***Close Date:***	1999-08-17 00:00:00
Water Body:		***Create Date:***	1999-06-28 11:09:00
Class:	C3	***Update Date:***	2002-03-19 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	JFOTTO
County:	Erie	***After Hours:***	False
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"WHILE REMOVING A 4,000 GALLON TANK, CONTAMINATED SOIL WAS DISCOVERED"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 06/28/99: JFO CALL FROM GREG WILLEY OF MAPLE TREE CONTACTORS. ONE ROLLOFF OF CONTAMINATED SOIL HAS BEEN EXCAVATED SO FAR. WILL VISIT SITE LATER TODAY. 06/28/99: JFO ON SITE, MET WITH GREG WILLEY. TANK WAS AN ABOVEGROUND TANK, THE BOTTOM WAS ABOUT 3-4 BELOW GRADE. THE EXCAVATION (25'X6'X5') LOOKS CLEAN. I TOLD GREG TO SAMPLE SIDEWALLS AND BOTTOM AND ANALYZE FOR 8021 AND 8270 STARS. ANALYTICAL AND DISPOSAL RECEIPTS TO FOLLOW. 08/02/99: JFO TELECON GREG WILLEY. HE WILL FORWARD ANALYTICAL AND DISPOSAL RECEIPTS. 08/17/99: JFO RECEIVED DISPOSAL RECEIPTS AND ANALYTICAL. NO FURTHER ACTION REQUIRED. CLOSED"

Material Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	1093750	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	291757	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	OSMOSE WOOD PRESERVING
Spiller Address:	980 ELLICOTT STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.904730960
Longitude:	-78.865969430

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	13 of 22	NNW	0.06 / 291.10	637.97 / -6	OSMOSE INC. 980 Ellicott Street Buffalo NY 14209	AST

Site ID:	339349	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Erie
Program No:	9-000268	**UTM X:**	184354.14073
Program Type Code:	CBS	**UTM Y:**	4757496.49503
Program Type Desc:	Chemical Bulk Storage		
Site Type:	Manufacturing (Other than Chemical)/Processing		

Tank Information

Prog No:	9-000268	**UDC Ind:**	1
Tank ID:	196183	**Red Tag Start Date:**	
Tank No:	6-A	**Red Tag End Date:**	
Tank Status:	4	**Tank Last Test:**	
Tank Status Desc:	Closed - In Place	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	08/01/1989	**Next Line Test Due:**	
Close Date:	10/01/1998	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	12000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	3		
Tank Location Desc:	Aboveground on saddles, legs, stilts, rack or cradle		
Category:	2		
Category Desc:	Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015		
Subpart:			
Subpart Desc:			
Tank Owner Name:			
Tank Owner Address:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Information

Prog No:	9-000268	***UDC Ind:***	1
Tank ID:	196182	***Red Tag Start Date:***	
Tank No:	6	***Red Tag End Date:***	
Tank Status:	4	***Tank Last Test:***	
Tank Status Desc:	Closed - In Place	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	08/01/1989	***Next Line Test Due:***	
Close Date:	09/04/2007	***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	12000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	14 of 22	NNW	0.06 / 291.10	637.97 / -6	OSMOSE INC. 980 Ellicott Street Buffalo NY 14209	UST

Site ID:	339349	***Expiry:***	N/A
Site Status:	Unregulated/Closed	***County:***	Erie
Program No:	9-000268	***UTM X:***	184354.14073
Program Type Code:	CBS	***UTM Y:***	4757496.49503
Program Type Desc:	Chemical Bulk Storage		
Site Type:	Manufacturing (Other than Chemical)/Processing		

Tank Information

Prog No:	9-000268	***UDC Ind:***	1
Tank ID:	196180	***Red Tag Start Date:***	
Tank No:	4	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	04	***Test Method:***	NN
Tank Type Desc:	Fiberglass Coated Steel	***Date Tested:***	
Install Date:	01/01/1980	***Next Test:***	
Close Date:	10/01/1998	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	12000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Tank Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Prog No:	9-000268	**UDC Ind:**	1
Tank ID:	196181	**Red Tag Start Date:**	
Tank No:	4-A	**Red Tag End Date:**	
Tank Status:	5	**Tank Last Test:**	
Tank Status Desc:	Tank Converted to Non-Regulated Use	**Tank Next Test Due:**	
Tank Type:	09	**Test Method:**	NN
Tank Type Desc:	Concrete	**Date Tested:**	
Install Date:	10/01/1998	**Next Test:**	
Close Date:	10/01/2003	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	12000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

11	15 of 22	NNW	0.06 / 291.10	637.97 / -6	OSMOSE INC. 980 ELLICOTT STREET BUFFALO NY 14209	DELISTED TANKS

Delisted Storage Tanks

Program No:	9-000268	**DEC Region:**	9
Site ID:	339349	**County:**	Erie
Site Status:	Unregulated	**UTM X:**	184354.14073
Program Type:	Chemical Bulk Storage	**UTM Y:**	4757496.49503
Program Type Code:	CBS	**Original Source:**	CBS
Expiry:	N/A	**Record Date:**	28-AUG-2013

Site Type: Manufacturing (Other than Chemical)/Processing

11	16 of 22	NNW	0.06 / 291.10	637.97 / -6	OSMOSE UTILITIES SERVICES, INC. 980 ELLICOTT ST - BUFFALO NY 14209	SSTS

EPA Region: 2
Establishment No: 75341-NY-1
Est Create Update Date:
Est Site County: Erie
Est Site Country: USA
Est Mailing Address: 980 ELLICOTT ST
Est Mailing Address Line 2: -
Est Mail City: BUFFALO
Est Mail State: NY
Est Mail Zip: 14209
Est Mail Country:
Company Name: OSMOSE UTILITIES SERVICES, INC.
Co Site Address Line 1: 215 GREENCASTLE ROAD
Co Site Address Line 2: -
Co Site City: TYRONE
Co Site State: GA
Co Site Zip: 30290
Co Site Country: USA
Co Mailing Address Line 1: 215 GREENCASTLE ROAD
Co Mail Address Line 2: -
Co Mail City: TYRONE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Co Mail State:	GA
Co Mail Zip:	30290
Co Mail Country:	USA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	17 of 22	NNW	0.06 / 291.10	637.97 / -6	OSMOSE INC 980 ELLICOTT ST - BUFFALO NY 14209	SSTS

EPA Region:	2
Establishment No:	3008-NY-1
Est Create Update Date:	
Est Site County:	Erie
Est Site Country:	USA
Est Mailing Address:	980 ELLICOTT ST
Est Mailing Address Line 2:	-
Est Mail City:	BUFFALO
Est Mail State:	NY
Est Mail Zip:	14209
Est Mail Country:	
Company Name:	KOPPERS PERFORMANCE CHEMICALS, INC.
Co Site Address Line 1:	1016 EVEREE INN ROAD
Co Site Address Line 2:	-
Co Site City:	GRIFFIN
Co Site State:	GA
Co Site Zip:	30224
Co Site Country:	USA
Co Mailing Address Line 1:	1016 EVEREE INN ROAD
Co Mail Address Line 2:	-
Co Mail City:	GRIFFIN
Co Mail State:	GA
Co Mail Zip:	30224
Co Mail Country:	USA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	18 of 22	NNW	0.06 / 291.10	637.97 / -6	980 Ellicott Street Site 980 Ellicott Street Buffalo NY 14209	BROWNFIELDS

Site Code:	544725
HW Code:	C915143
Program:	BCP
Site Class:	N
Site Name:	980 Ellicott Street Site
Site Address:	980 Ellicott Street
City:	Buffalo
Zip:	14209
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.904830556
Longitude:	-78.866541667
SWIS:	1502
Acres:	1.350
Record Added:	2017-04-05 10:43:00
Record Update:	2018-01-02 11:11:00
Updated by:	BXANDERS
Site Code (Web):	C915143
Program Type (Web):	BCP
Site Name (Web):	980 Ellicott Street Site
Site Class (Web):	N
Address1 (Web):	980 Ellicott Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209
County (Web):	Erie
Longitude (Web):	-78.866541667

Latitude (Web): 42.904830556
Site Code (GIS): C915143
Site Name (GIS): 980 Ellicott Street Site
Program (GIS): BCP
Site Class (GIS): N
Address1 (GIS): 980 Ellicott Street
Address2 (GIS):
Locality (GIS): Buffalo
Zip Code (GIS): 14209
County (GIS): Erie
Site Class Desc:
Site Class Desc (Web): No Further Action at this Time: Sites are given a classification of "N" when:

a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program;

b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Description:

Location: The Site is located in an urban area in the City of Buffalo. The Site is located on Ellicott Street midway between Dodge Street (north) and Best Street (south). The Niagara River is approximately 1.8 miles west of the Site. Site Features: The Site itself is currently a vacant facility composed of multiple structures and asphalt parking areas. Current Zoning and Land Use: The Site is currently vacant and zoned commercial and residential; more specifically, CM – General Commercial District and R3 – Dwelling District. Current zoning for the surrounding parcels similarly includes CM General Commercial District, R3 – Dwelling District, and TS – Transit Station. Past Use of the Site: The Site is part of a greater complex formerly owned and operated by Osmose Wood Preserving, Inc., which manufactured a variety of preservatives used in the treatment of lumber and wood products since 1951. As early as 1910, the property was developed with residential and automotive facilities. From at least 1910 to 1950, several automotive repair shops were listed on Ellicott Street located between the northern end of the subject property and Best Street. Additional operations, either on or bordering the Site, included a florist (1930-1940), a sheet metal works operation (1930s), a plumbing supplier (1946), a letter service company (1950-1960), and residential properties (up to 1970). Site Geology and Hydrogeology: The surface of the Site is primarily hardscape with multiple structures and asphalt parking areas and is underlain by approximately 63 feet of unconsolidated clay, silt, sand, and gravel deposits. These deposits are fairly typical of glacial deposits of the area, and exhibit varied permeability. A clay and silt layer approximately 5 feet below grade presented the least permeable zone observed. This clay and silt unit, composed primarily of extremely low permeability glacial lake deposits, ranged in thickness from approximately 7 to 12 feet. The water table in the vicinity of Ellicott Street appears to be locally affected by the storm sewer system and/or other subsurface artifacts. Local groundwater flow, however, may also be influenced by subsurface features, such as excavations, utilities, and localized fill-conditions. The hydrogeologic evaluation indicates a complex aquifer system exists beneath the Site. Groundwater levels in the upper portion of the overburden aquifer range from 5 to 10 fbgs whereas groundwater in the deep portion of the overburden aquifer range from 20.50 fbgs to 26.68 fbgs. Variances between depth to shallow and deep groundwater indicate a steep downward vertical gradient exists within this unit. Deep groundwater elevations also indicate a significant horizontal gradient toward the west (more consistent with regional groundwater) compared to an easterly direction in the shallow overburden. Shallow and deep overburden groundwater differ significantly in both direction and gradient. Bedrock mirrors the land surface by dipping gently toward the east. BCP application withdrawn by applicant's attorney via email on 06/14/17.

Assessment:

Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.

Owner Information

Owner Op: 01
Sub Type: E
Owner Name: Jon Williams
Owner Company: 780 Ellicott Street, LLC
Owner Street: 333 Ganson Street
Owner Street 2:

Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Jon Williams
Owner Company: 780 Ellicott Street, LLC
Owner Street: 333 Ganson Street
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Buffalo & Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Environmental Remediation

Operable Unit: 01
Contaminants:

11	*19 of 22*	*NNW*	*0.06 / 291.10*	*637.97 / -6*	***OSMOSE WOOD PRESERVING INC 980 ELLICOTT ST BUFFALO NY 14209***	***GEN MANIFEST***

RCRA ID: NYD002112944
District Name: OSMOSE WOOD PRESERVING INC
Contact Name: MICHAEL RIDER PLNT MGR
Business Phone No: 7168825905
Mailing Street 1: 980 ELLICOTT ST
Mailing Street 2:
Mailing City: BUFFALO
Mailing State: NY
Mailing ZIP: 14209
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: ERIE

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 77 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2003: 10 Pounds; 10 Pounds
2009: 231 Pounds
2010: 1 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P030: Cyanides (soluble cyanide salts), not otherwise specified

Waste Amounts By Year:

2010: 4 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1982: 55 Gallons
1987: 1950 Pounds; 650 Pounds; 1650 Pounds
1991: 440 Gallons
1995: 2700 Pounds
2001: 497 Pounds; 763 Pounds
2002: 125 Pounds; 75 Pounds
2003: 10 Pounds; 60 Pounds; 482 Pounds; 400 Pounds; 320 Pounds
2004: 88 Pounds; 780 Pounds; 180 Pounds **Note: data in the [Waste Amounts By Year] field for some records is truncated from the source.

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
P010: (7778-39-4) Arsenic acid H3AsO4

Waste Amounts By Year:

2010: 7 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2005: 19 Pounds; 17 Pounds

Manifest Information

Waste Code(s):

D000: DESCRIPTION (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1982: 110 Gallons; 110 Gallons

Manifest Information

Waste Code(s):

D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1985: 1260 Pounds
1987: 2300 Pounds
1988: 2800 Pounds; 100 Pounds; 5000 Pounds
1989: 2700 Pounds
1990: 5200 Pounds
1991: 5200 Pounds; 7200 Pounds
1992: 900 Pounds; 4500 Pounds; 2400 Pounds
1993: 2400 Pounds; 3250 Pounds; 600 Pounds; 660 Pounds; 4000 Pounds
1994: 750 Pounds; 950 Pounds; 1000 Pounds; 1550 Pounds; 2575 Pounds
1995: 300 Pounds; 1750 Pounds; 2040 Pounds; 600 Pounds; 2100 Pounds; 700 Pounds
1996: 600 Pounds; 3890 Pounds; 600 Pounds; 3790 Pounds
1997: 490 Pounds; 1830 Pounds; 2447 Pounds; 300 Pounds
1998: 686 Pounds; 985 Pounds; 3567 Pounds; 644 Pounds; 2400 Pounds; 1150 Pounds; 549 Pounds
1999: 1556 Pounds; 735 Pounds; 1090 Pounds
2000: 1403 Pounds; 864 Pounds; 748 Pounds; 1019 Pounds
2001: 792 Pounds; 2089 Pounds; 1001 Pounds; 2495 Pounds; 1212 Pounds; 1025 Pounds
2002: 1244 Pounds; 542 Pounds; 4472 Pounds; 758 Pounds; 1058 Pounds; 1041 Pounds
2003: 1884 Pounds; 845 Pounds; 474 Pounds; 950 Pounds; 870 Pounds
2004: 857 Pounds; 1121 Pounds; 1428 Pounds; 1258 Pounds; 953 Pounds
2005: 289 Pounds; 1662 Pounds; 109 Pounds; 1039 Pounds; 220 Pounds; 528 Pounds; 1494 Pounds
2006: 902 Pounds; 931 Pounds; 1953 Pounds; 638 Pounds
2007: 1009 Pounds; 805 Pounds; 1521 Pounds; 751 Pounds; 569 Pounds; 818 Pounds; 1916 Pounds; 1361 Pounds
2008: 2051 Pounds; 812 Pounds; 1034 Pounds; 941 Pounds; 1171 Pounds; 1691 Pounds; 1298 Pounds; 2127 Pounds; 818 Pounds

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 133 Pounds
2009: 314 Pounds
2010: 174 Pounds

Manifest Information

Waste Code(s):

D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2003: 2200 Pounds; 800 Pounds; 550 Pounds
2010: 6 Pounds

Manifest Information

Waste Code(s):

D020: CHLORDANE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2003: 10 Pounds

Manifest Information

Waste Code(s):

D026: CRESOL (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1998: 1567 Pounds; 498 Pounds
1999: 1787 Pounds

Manifest Information

Waste Code(s):

D026: CRESOL (Waste Code Description from EPA Hazardous Waste Identification)
U052: (1319-77-3) Phenol, methyl-

Waste Amounts By Year:

2013: 1737 Pounds

Manifest Information

Waste Code(s):

D028: 1,2-DICHLOROETHANE (Waste Code Description from EPA Hazardous Waste Identification)
U051: Creosote

Waste Amounts By Year:

2010: 2176 Pounds
2014: 198 Pounds

Manifest Information

Waste Code(s):

D037: PENTACHLOROPHENOL (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2001: 173 Pounds; 5 Gallons

Manifest Information

Waste Code(s):

F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

1982: 440 Gallons; 935 Gallons
2002: 250 Pounds

Manifest Information

Waste Code(s):

F007: (Generic) Spent cyanide plating bath solutions from electroplating operations. (R,T)

Waste Amounts By Year:

1988: 1376 Pounds

Manifest Information

Waste Code(s):

P012: (1327-53-3) Arsenic oxide As2 O3

Waste Amounts By Year:

2003: 50 Pounds; 250 Pounds

Manifest Information

Waste Code(s):

P022: (75-15-0) Carbon disulfide

Waste Amounts By Year:

2001: 305 Pounds

Manifest Information

Waste Code(s):

P048: (51-28-5) 2,4-Dinitrophenol

Waste Amounts By Year:

1992: 185 Liters

Manifest Information

Waste Code(s):

P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2003: 10 Pounds

Manifest Information

Waste Code(s):

P106: (143-33-9) Sodium cyanide

Waste Amounts By Year:

2002: 5 Pounds

Manifest Information

Waste Code(s):

U129: (58-89-9) Lindane

Waste Amounts By Year:

2002: 300 Pounds
2003: 250 Pounds

Manifest Information

Waste Code(s):

U135: (7783-06-4) Hydrogen sulfide

Waste Amounts By Year:

2002: 10 Pounds

Manifest Information

Waste Code(s):

U168: (91-59-8) 2-Naphthalenamine

Waste Amounts By Year:

2001: 7 Pounds

Manifest Information

Waste Code(s):

U188: (108-95-2) Phenol

Waste Amounts By Year:

2005: 4 Pounds

Manifest Information

Waste Code(s):

U201: (108-46-3) Resorcinol

Waste Amounts By Year:

2001: 763 Pounds

Manifest Information

Waste Code(s):

U220: (108-88-3) Benzene, methyl-

Waste Amounts By Year:

2001: 763 Pounds

Manifest Information

Waste Code(s):

U226: (71-55-6) Methyl chloroform

Waste Amounts By Year:

2001: 305 Pounds

Manifest Information

Waste Code(s):

U242: Not Listed In 6 CRR-NY 371.4 or EPA Hazardous Waste Identification

Waste Amounts By Year:

1980/1981: 330 Gallons; 275 Gallons
1982: 665 Gallons; 550 Gallons
1983: 450 Pounds

Manifest Information

Waste Code(s):

U404: (121-44-8) Ethanamine, N,N-diethyl-

Waste Amounts By Year:

2001: 763 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1982: 440 Gallons
1984: 4250 Pounds; 2500 Pounds; 4750 Pounds
1985: 2300 Pounds; 480 Pounds
1987: 400 Pounds
1988: 3150 Pounds
1991: 400 Pounds; 1800 Pounds
1995: 750 Pounds
1998: 586 Pounds
1999: 626 Pounds
2000: 841 Pounds; 1190 Pounds; 30 Gallons
2001: 127 Pounds; 1092 Pounds; 196 Pounds; 146 Pounds; 205 Pounds; 689 Pounds; 214 Pounds; 2015 Pounds
2002: 12863 Pounds; 1000 Pounds; 30 Pounds; 5 Pounds; 310 Pounds; 55 Gallons; 500 Pounds; 678 Pounds; 5 Gallons; 5523 Pounds
2003: 25 Pounds; 10 Pounds; 200 Pounds; 10 Pounds; 5 Pounds; 10 Pounds; 10 Pounds; 10 Pounds; 50 Pounds; 10 Pounds; 10 Pounds; 461 Pounds; 2163 Pounds; 10 Pounds
2004: 2204 Pounds; 404 Pounds; 537 Pounds
2005: 1024 Pounds; 63 Pounds; 29 Pounds; 7 Pounds; 20 Pounds; 44 Pounds; 807 Pounds; 325 Pounds; 116 Pounds; 934 Pounds
2006: 745 Pounds

2008: 640 Pounds; 424 Pounds
2009: 284 Pounds; 415 Pounds; 214 Pounds
2010: 294 Pounds; 380 Pounds; 1 Pounds; 141 Pounds; 4 Pounds; 270 Pounds
2011: 1832 Pounds; 130 Pounds
2014: 336 Pounds
2015: 270 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2009: 333 Pounds
2010: 1 Pounds; 1 Pounds; 302 Pounds
2013: 743 Pounds
2015: 63 Pounds; 307 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 37 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U002: (67-64-1) 2-Propanone (I)

Waste Amounts By Year:

2010: 77 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U003: (75-05-8) Acetonitrile (I,T)
U164: (56-04-2) Mitomycin C
U213: (109-99-9) Furan, tetrahydro-(I)
U220: (108-88-3) Benzene, methyl-

Waste Amounts By Year:

2010: 77 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U051: Creosote

Waste Amounts By Year:

2006: 1070 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 17 Pounds; 2 Pounds; 47 Pounds

Manifest Information

Waste Code(s):

P119: (7803-55-6) Vanadic acid, ammonium salt

Waste Amounts By Year:

2005: 5 Pounds
2010: 1 Pounds

Manifest Information

Waste Code(s):

U012: (62-53-3) Aniline (I,T)

Waste Amounts By Year:

2003: 10 Pounds

Manifest Information

Waste Code(s):

U051: Creosote

Waste Amounts By Year:

1980/1981: 3575 Gallons
1982: 1210 Gallons; 495 Gallons; 440 Gallons; 825 Gallons
1983: 15340 Pounds; 9000 Pounds
1985: 10890 Pounds
1987: 3200 Pounds; 7790 Pounds; 1600 Pounds; 9020 Pounds; 3690 Pounds
1990: 11200 Pounds
1991: 793 Pounds; 1000 Pounds
1992: 4200 Pounds; 278 Pounds
1993: 17100 Pounds; 300 Pounds; 6750 Pounds
1994: 200 Pounds; 1045 Gallons; 29600 Pounds
1995: 240 Pounds; 9900 Pounds; 2400 Pounds; 4240 Pounds; 315 Pounds
1997: 1964 Pounds; 350 Pounds; 1700 Pounds; 1935 Pounds; 585 Pounds; 260 Pounds
1998: 459 Pounds; 55 Gallons; 2779 Pounds; 1250 Pounds; 300 Pounds; 537 Pounds; 958 Pounds
1999: 30000 Pounds; 1274 Pounds; 734 Pounds; 30020 Pounds; 30000 Pounds; 36500 Pounds; 3422 Pounds; 30000 Pounds; 18300 Pounds; 273

Pounds; 445 Pounds
2000: 1293 Pounds; 2103 Pounds; 1929 Pounds; 545 Pounds; 523 Pounds; 132 Pounds; 2150 Pounds; 620 Pounds; 5224 Pounds
2001: 1418 Pounds; 970 Pounds; 253 Pounds; 2043 Pounds; 1010 Pounds; 1109 Pounds; 1004 Pounds
2002: 2899 Pounds; 1500 Pounds; 1039 Pounds; 1065 Pounds; 1167 Pounds; 733 Pounds; 200 Pounds; 1098 Pounds; 1024 Pounds
2003: 4900 Pounds; 351 Pounds; 3150 Gallons; 2325 Pounds; 201 Pounds; 2052 Pounds; 2195 Pounds; 3944 Pounds
2004: 2614 Pounds; 94 Pounds; 700 Pounds; 2176 Pounds; 2595 Pounds; 2160 Pounds; 270 Pounds; 930 Pounds
2005: 2116 Pounds; 225 Pounds; 2177 Pounds; 3174 Pounds; 325 Pounds; 177 Pounds; 517 Pounds; 270 Pounds; 300 Pounds; 928 Pounds; 246 Pounds
2006: 1976 Pounds; 377 Pounds; 205 Pounds; 241 Pounds; 1984 Pounds
2007: 253 Pounds; 309 Pounds
2008: 209 Pounds
2009: 198 Pounds; 1380 Pounds; 465 Pounds
2010: 172 Pounds

Manifest Information

Waste Code(s):

U108: (123-91-1) 1,4-Diethyleneoxide

Waste Amounts By Year:

2002: 75 Pounds

Manifest Information

Waste Code(s):

D026: CRESOL (Waste Code Description from EPA Hazardous Waste Identification)
U051: Creosote

Waste Amounts By Year:

2007: 569 Pounds; 2000 Pounds
2008: 1784 Pounds; 2100 Pounds; 2072 Pounds
2009: 1796 Pounds; 2036 Pounds; 1908 Pounds
2010: 1988 Pounds; 1816 Pounds
2011: 1988 Pounds; 2280 Pounds
2012: 2132 Pounds; 846 Pounds; 2028 Pounds; 1600 Pounds
2013: 291 Pounds; 579 Pounds; 2268 Pounds; 2156 Pounds; 2160 Pounds
2014: 2044 Pounds; 2200 Pounds; 203 Pounds; 2044 Pounds
2015: 1960 Pounds; 2164 Pounds
2016: 2000 Pounds

Manifest Information

Waste Code(s):

D037: PENTACHLOROPHENOL (Waste Code Description from EPA Hazardous Waste Identification)
D042: 2,4,6-TRICHLOROPHENOL (Waste Code Description from EPA Hazardous Waste Identification)
F027: (Generic) Discarded unused formulations containing tri-, tetra-, or pentachlorophenol or discarded unused formulation containing compounds derived from these chlorophenols. (This listing does not include formulations containing hexachlorophene synthesized from prepurified 2,4,5-trichlorophenol as the sole component.) (H)

Waste Amounts By Year:

2010: 47 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2010: 770 Pounds; 170 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1982: 55 Gallons; 385 Gallons
2001: 47 Pounds; 25 Pounds; 370 Pounds; 187 Pounds
2002: 75 Pounds; 10 Pounds; 10 Pounds; 75 Pounds; 5 Gallons
2003: 50 Pounds; 2658 Pounds; 10 Pounds
2005: 13 Pounds; 13 Pounds
2007: 1964 Pounds
2008: 154 Pounds; 952 Pounds
2009: 352 Pounds; 487 Pounds; 150 Pounds; 234 Pounds
2010: 205 Pounds
2017: 10 Gallons

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 77 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2010: 53 Pounds

Manifest Information

Waste Code(s):

F001: (Generic) The following spent halogenated solvents used in degreasing: tetrachloroethylene, trichloroethylene, methylene chloride, 1,1, 1-trichloroethane, carbon tetrachloride, and chlorinated fluorocarbons; all spent solvent mixtures/blends used in degreasing containing, before use, total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those solvents listed in F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)
U002: (67-64-1) 2-Propanone (I)
U112: (141-78-6) Acetic acid ethyl ester (I)
U154: (67-56-1) Methanol (I)
U159: (78-93-3) Methyl ethyl ketone (MEK) (I,T)

Waste Amounts By Year:

2010: 77 Pounds

Manifest Information

Waste Code(s):

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

1998: 458 Pounds
2001: 275 Gallons
2002: 250 Pounds
2004: 413 Pounds

Manifest Information

Waste Code(s):

F004: (Generic) The following spent nonhalogenated solvents: cresols and cresylic acid, and nitrobenzene; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

1994: 1000 Pounds
2001: 614 Pounds

Manifest Information

Waste Code(s):

F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

1982: 495 Gallons

Manifest Information

Waste Code(s):

F024: (Generic) Process wastes, including but not limited to, distillation residues, heavy ends, tars, and reactor clean-out wastes, from the production of certain chlorinated aliphatic hydrocarbons by free radical catalyzed processes. These chlorinated aliphatic hydrocarbons are those having carbon chain

lengths ranging from one to and including five, with varying amounts and positions of chlorine substitution. (This listing does not include wastewaters, wastewater treatment sludges, spent catalysts, and wastes listed in subdivision [b] or [c] of this section.) (T)

Waste Amounts By Year:

2001: 492 Pounds

Manifest Information

Waste Code(s):

F027: (Generic) Discarded unused formulations containing tri-, tetra-, or pentachlorophenol or discarded unused formulation containing compounds derived from these chlorophenols. (This listing does not include formulations containing hexachlorophene synthesized from prepurified 2,4,5-trichlorophenol as the sole component.) (H)

Waste Amounts By Year:

1988: 14525 Pounds; 550 Pounds; 4236 Pounds; 400 Pounds; 28240 Pounds; 11050 Pounds; 3320 Pounds; 13760 Pounds; 1500 Pounds; 3600 Pounds; 1376 Pounds; 24004 Pounds; 375 Pounds; 630 Pounds
1990: 2510 Pounds; 8973 Pounds; 4487 Pounds; 8625 Pounds
2004: 58 Pounds

Manifest Information

Waste Code(s):

F034: (Generic) Wastewaters (except those that have not come into contact with process contaminants), process residuals, preservative drippage, and spent formulations from wood preserving processes generated at plants that use creosote formulations. This listing does not include K001 bottom sediment sludge from the treatment of wastewater from wood preserving processes that use creosote and/or pentachlorophenol. (T)

Waste Amounts By Year:

1994: 4000 Pounds
1995: 1200 Pounds; 1750 Pounds; 1600 Pounds; 1750 Pounds; 540 Pounds; 1200 Pounds
1996: 1211 Pounds; 1804 Pounds; 380 Pounds; 630 Pounds
1997: 1100 Pounds; 1790 Pounds; 1301 Pounds
1998: 448 Pounds; 500 Pounds; 590 Pounds; 500 Pounds; 1549 Pounds; 1382 Pounds
1999: 441 Pounds; 1024 Pounds; 473 Pounds; 896 Pounds
2000: 386 Pounds; 513 Pounds; 479 Pounds; 489 Pounds
2001: 560 Pounds; 599 Pounds; 428 Pounds; 520 Pounds; 514 Pounds
2002: 4418 Pounds; 1955 Pounds; 1463 Pounds; 628 Pounds; 476 Pounds; 548 Pounds; 1137 Pounds; 632 Pounds; 1104 Pounds; 773 Pounds
2003: 550 Pounds; 1049 Pounds; 627 Pounds; 456 Pounds; 339 Pounds
2004: 220 Pounds; 128 Pounds
2005: 839 Pounds; 139 Pounds; 771 Pounds; 413 Pounds
2006: 485 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
P011: (1303-28-2) Arsenic oxide As2O5
P012: (1327-53-3) Arsenic oxide As2 O3

Waste Amounts By Year:

2010: 3 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)
U044: (67-66-3) Methane, trichloro-
U211: (56-23-5) Methane, tetrachloro-
U372: (10605-21-7) Carbamic acid, 1H-benzimidazol-2-yl,methyl ester

Waste Amounts By Year:

2010: 214 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)
U372: (10605-21-7) Carbamic acid, 1H-benzimidazol-2-yl,methyl ester

Waste Amounts By Year:

2010: 177 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 27 Pounds; 77 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 70 Pounds

Manifest Information

Waste Code(s):

D012: ENDRIN (1,2,3,4,10,10-HEXACHLORO-1,7-EPOXY-1,4,4A,5,6,7,8,8A-OCTAHYDRO-1,4-ENDO, ENDO-5,8-DIMETH-ANO-NAPHTHALENE) (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 295 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)
U044: (67-66-3) Methane, trichloro-

U080: (75-09-2) Methane, dichloro-
U102: (131-11-3) 1,2-Benzenedicarboxylic acid, dimethyl ester
U219: (62-56-6) Thiourea

Waste Amounts By Year:

2010: 140 Pounds

Manifest Information

Waste Code(s):

D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
F034: (Generic) Wastewaters (except those that have not come into contact with process contaminants), process residuals, preservative drippage, and spent formulations from wood preserving processes generated at plants that use creosote formulations. This listing does not include K001 bottom sediment sludge from the treatment of wastewater from wood preserving processes that use creosote and/or pentachlorophenol. (T)

Waste Amounts By Year:

2006: 247 Pounds
2007: 247 Pounds
2008: 337 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2003: 15 Pounds; 10 Pounds
2010: 1 Pounds
2011: 151 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 22 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 903 Pounds; 925 Pounds
2008: 58 Pounds
2013: 94 Pounds; 378 Pounds; 323 Pounds
2015: 501 Pounds; 200 Pounds; 349 Pounds; 36 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 17 Gallons

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
U019: (71-43-2) Benzene (I,T)
U220: (108-88-3) Benzene, methyl-
U239: (1330-20-7) Benzene, dimethyl-(I)

Waste Amounts By Year:

2010: 70 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D038: PYRIDINE (Waste Code Description from EPA Hazardous Waste Identification)
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)
U196: (110-86-1) Pyridine

Waste Amounts By Year:

2010: 47 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2006: 492 Pounds
2007: 416 Pounds
2008: 35 Pounds; 260 Pounds; 424 Pounds
2009: 439 Pounds; 432 Pounds; 159 Pounds
2010: 236 Pounds; 84 Pounds
2011: 2045 Pounds; 810 Pounds; 66 Pounds
2012: 239 Pounds
2013: 472 Pounds
2014: 42 Pounds; 508 Pounds

2015: 865 Pounds; 481 Pounds; 448 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U057: (108-94-1) Cyclohexanone (I)

Waste Amounts By Year:

2010: 114 Pounds

Manifest Information

Waste Code(s):

D021: CHLOROBENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2003: 1735 Pounds

Manifest Information

Waste Code(s):

D024: M-CRESOL (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2003: 376 Pounds

Manifest Information

Waste Code(s):

D026: CRESOL (Waste Code Description from EPA Hazardous Waste Identification)
D031: HEPTACHLOR (AND ITS EPOXIDE) (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 1820 Pounds

Manifest Information

Waste Code(s):

D026: CRESOL (Waste Code Description from EPA Hazardous Waste Identification)
U031: (71-36-3) 1-Butanol (I)

Waste Amounts By Year:

2011: 2100 Pounds

11	*20 of 22*	*NNW*	*0.06 / 291.10*	*637.97 / -6*	***Osmose, Inc.*** ***980 Ellicott St.*** ***Buffalo NY 14209***	*TIER 2*

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Company Name: Osmose, Inc.
DUN Bradstreet Cd: 00-211-2944
County: Erie
Latitude: 42.904758
Longitude: -78.865835
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	21 of 22	NNW	0.06 / 291.10	637.97 / -6	Osmose, Inc. 980 Ellicott Street Buffalo NY 14209	TIER 2

Company Name: Osmose, Inc.
DUN Bradstreet Cd: 00-211-2944
County: Erie
Latitude: 42.904758
Longitude: -78.865835
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	22 of 22	NNW	0.06 / 291.10	637.97 / -6	Osmose Inc; 980 Ellicott Street, Buffalo, NY 14209 NY	TIER 2

Company Name:
DUN Bradstreet Cd:
County:
Latitude:
Longitude:
Report Method: Reported via Mail

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	1 of 2	E	0.06 / 322.34	647.69 / 3	PHASE II 1100 MICHIGAN AVE. BUFFALO NY 14202	NY SPILLS

Spill No: 1508707
Site ID: 517281
DER Facility ID: 471632
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D3
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Unknown
Reported by: Affected Persons
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 2015-11-23 14:30:00
Received Date: 2015-11-23 14:30:00
CAC Date:
Insp Date:
Close Date: 2015-11-23 00:00:00
Create Date: 2015-11-23 14:41:00
Update Date: 2015-11-24 13:12:46.940000000
DEC Region: 9
Lead DEC: GPSUTTON
After Hours: False

Caller Remark:

"Consultant performing a Phase II at site and ran across petroleum odors in soil. Collected samples and indicated low levels of petroleum products slightly over unrestricted values. Will submit report with investigation information."

DEC Remark:

"11/23/2015 GPS: REC'D COPY OF PHASE II FROM 03/2015. REVIEWED REPORT AND ALTHOUGH SOME PETROLEUM ODORS WERE NOTED AND 3 VOCS WERE DETECTED SLIGHTLY ABOVE CP-51 SCOS DETERMINED NO FURTHER WORK IS NECESSARY. SPILL CLOSED."

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Information

OP Unit ID:	1266367	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2270247	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spill Data

Material Name:	unknown petroleum
Material Family:	Petroleum
Quantity:	0
Units:	
Recovered:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	2 of 2	E	0.06 / 322.34	647.69 / 3	Former Pilgrim Village Family Apartments 1100 Michigan Avenue Buffalo NY 14209	BROWNFIELDS

Site Code:	605803
HW Code:	C915362
Program:	BCP
Site Class:	C
Site Name:	Former Pilgrim Village Family Apartments
Site Address:	1100 Michigan Avenue
City:	Buffalo
Zip:	14209
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.903411111
Longitude:	-78.863238889
SWIS:	1502
Acres:	2.720
Record Added:	2020-05-21 10:16:00
Record Update:	2022-12-27 15:46:00
Updated by:	BJMCPHER
Site Code (Web):	C915362
Program Type (Web):	BCP
Site Name (Web):	Former Pilgrim Village Family Apartments
Site Class (Web):	C
Address1 (Web):	1100 MICHIGAN AVENUE
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209
County (Web):	Erie
Longitude (Web):	-78.863238889
Latitude (Web):	42.903411111
Site Code (GIS):	C915362
Site Name (GIS):	Former Pilgrim Village Family Apartments
Program (GIS):	BCP
Site Class (GIS):	C
Address1 (GIS):	1100 Michigan Avenue
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14209
County (GIS):	Erie
Site Class Desc:	

Site Class Desc (Web): Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).

Assess DOH: Direct contact with contaminants in the soil is unlikely because the site is currently covered with buildings, pavement, and vegetation. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the soil vapor (air spaces within the soil), may move into buildings and affect indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling indicates that soil vapor intrusion may be a concern for future redevelopment in the area of the former gasoline service station but does not indicate a concern for off-site locations.

Description:

Location: The 2.72- acre Former Pilgrim Village Family Apartments site is located in a mixed residential/commercial area at the southwest corner of Best Street and Michigan Avenue in the City of Buffalo, Erie County. Site Features: The site is currently under development as affordable housing. Much of the site consists of the multi-storied building footprint surrounded by open area used for construction access. Non-building areas are planned to be used as parking or open vegetated areas. Current Zoning and Land Use: The site is currently zoned D-R Residential Campus. Future use of the site will be for multi-family residential. Past Use of the Site: From the late 1800s through the mid-1970s the site was occupied by dense residential housing with several small shops. A gasoline filling station was located on the northeast corner parcel at Michigan and Best Streets from at least 1951 through at least the 1960s. In the 1970s the site was developed into the Pilgrim Village Apartment complex. The Pilgrim Village Apartments operated until 2021/2022. Site Geology and Hydrogeology: The sub-surface consists of urban fill which is predominantly sand, silt, crushed rock, asphalt, and brick from the ground surface to approximately 2 to 11 feet below ground surface. The fill is underlain by native soil consisting of sand, gravel, silty clay to clayey silt. Groundwater flow during the investigation was to the north or northwest. Groundwater flow direction may change as a result of the remedy and on-site development. Regional groundwater flow is west toward Lake Erie.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), arsenic, barium, lead, mercury, and zinc in soil. Petroleum related VOCs were present in groundwater in the northeast portion of the site. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use.

Materials Information

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: zinc
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: petroleum products
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Buffalo & Erie County Pubic Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: David Alexander
Owner Company: SAA EVI MC FAMILY, LLC
Owner Street: 150 SE 2nd Avenue, SUITE 300
Owner Street 2:
Owner City: Miami
Owner State: FL
Owner Zip: 33131
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: David Alexander
Owner Company: SAA EVI MC FAMILY, LLC
Owner Street: 150 SE 2nd Avenue, Suite 300
Owner Street 2:
Owner City: Miami
Owner State: FL
Owner Zip: 33131
Country: United States of America

Owner Op: 01
Sub Type: NNN
Owner Name: J. Mascaro
Owner Company: Pilgrim Village Family Housing Development Fund Company, Inc
Owner Street: 1408 Sweet Home Road, #8
Owner Street 2:
Owner City: Amherst
Owner State: NY
Owner Zip: 14228
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Conner Kenney
Owner Company: SAA EVI MC FAMILY, LLC
Owner Street: 150 SE 2nd Avenue, SUITE 300
Owner Street 2:
Owner City: Miami
Owner State: FL
Owner Zip: 33131
Country: United States of America

HW Extra Information

Dump:	False	***Record Added:***	2021-02-17 08:51:00
Structure:	False	***Record Updated:***	2021-02-17 15:00:00
Lagoon:	False	***Disposal Start:***	
Landfill:	False	***Disposal Terminate:***	
Pond:	False	***Latitude:***	
Dell:		***Longitude:***	
Updated By:	JSWALIA		

Projects Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2021-05-10 00:00:00
End Status: ACT
Operable Unit ID: 1352956
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 01
Contaminants: arsenic, barium, lead, mercury, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, zinc

Operable Unit: 00
Contaminants: arsenic, barium, lead, mercury, petroleum products, polycyclic aromatic hydrocarbons (PAHS), total, zinc

---

13 | ***1 of 12*** | ***WSW*** | ***0.06 / 327.34*** | ***651.59 / 7*** | ***854ELLICOTT 854 ELLICOTT 8
854 Ellicott St
Buffalo NY 14203*** | ***ALT FUELS***

Fuel Type Code: ELEC: Electric
Station Phone: 888-758-4389
Expected Date: 2022-11-13
BD Blends:
NG Fill Type Code:
NG PSI:
Federal Agency ID:
Open Date: 2020-06-12
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2023-01-02
Restricted Access:
Fed Agency Name:
Hydrogen Status Link:
Status: Temporarily unavailable: The station is temporarily unavailable. See the "Expected Date" field for an anticipated open date.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:

ID: 162228
Updated at: 2023-01-02 23:13:48 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 42.901641
Longitude: -78.867271

---

13 | ***2 of 12*** | ***WSW*** | ***0.06 / 327.34*** | ***651.59 / 7*** | ***854ELLICOTT 854 ELLICOTT 3
854 Ellicott St
Buffalo NY 14203*** | ***ALT FUELS***

Fuel Type Code: ELEC: Electric
Station Phone: 888-758-4389
Expected Date:
BD Blends:
NG Fill Type Code:
NG PSI:

ID: 180119
Updated at: 2023-01-02 23:13:48 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Federal Agency ID:
Open Date: 2021-01-27
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2023-01-02
Restricted Access:
Fed Agency Name:
Hydrogen Status Link:
Status: Open: The station is open.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 42.901754
Longitude: -78.867332

13	3 of 12	WSW	0.06 / 327.34	651.59 / 7	854ELLICOTT 854 ELLICOTT 9 854 Ellicott St Buffalo NY 14203	ALT FUELS

Fuel Type Code: ELEC: Electric
Station Phone: 888-758-4389
Expected Date: 2022-11-13
BD Blends:
NG Fill Type Code:
NG PSI:
Federal Agency ID:
Open Date: 2021-01-27
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2023-01-02
Restricted Access:
Fed Agency Name:
Hydrogen Status Link:
Status: Temporarily unavailable: The station is temporarily unavailable. See the "Expected Date" field for an anticipated open date.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:
ID: 180116
Updated at: 2023-01-02 23:13:48 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 42.901642
Longitude: -78.867333

13	4 of 12	WSW	0.06 / 327.34	651.59 / 7	854ELLICOTT 854 ELLICOTT 5 854 Ellicott St Buffalo NY 14203	ALT FUELS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fuel Type Code:	ELEC: Electric	**ID:**	180112
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:13:48 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901752
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867471
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
13	5 of 12	WSW	0.06 / 327.34	651.59 / 7	854ELLICOTT 854 ELLICOTT 6 854 Ellicott St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	180113
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:13:48 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901752
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867526
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
13	6 of 12	WSW	0.06 / 327.34	651.59 / 7	854ELLICOTT 854 ELLICOTT 2 854 Ellicott St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	180117
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:13:48 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901762
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867248
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
13	7 of 12	WSW	0.06 / 327.34	651.59 / 7	854ELLICOTT 854 ELLICOTT 11 854 Ellicott St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	180114
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:13:48 UTC
Expected Date:	2022-11-13	**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901631
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867483
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Temporarily unavailable: The station is temporarily unavailable. See the "Expected Date" field for an anticipated open date.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:

---

13 | **8 of 12** | **WSW** | **0.06 / 327.34** | **651.59 / 7** | **854ELLICOTT 854 ELLICOTT 1**
854 Ellicott St
Buffalo NY 14203
ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	180122
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:13:30 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.90175
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867178
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

---

13 | **9 of 12** | **WSW** | **0.06 / 327.34** | **651.59 / 7** | **854ELLICOTT 854 ELLICOTT 7**
854 Ellicott St
Buffalo NY 14203
ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	180121
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:13:30 UTC
Expected Date:	2022-11-13	**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901637
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867194
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Temporarily unavailable: The station is temporarily unavailable. See the "Expected Date" field for an anticipated open date.		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:

---

13 | **10 of 12** | **WSW** | **0.06 / 327.34** | **651.59 / 7** | **854ELLICOTT 854 ELLICOTT 4**
854 Ellicott St
Buffalo NY 14203
ALT FUELS

Fuel Type Code: ELEC: Electric
Station Phone: 888-758-4389
Expected Date:
BD Blends:
NG Fill Type Code:
NG PSI:
Federal Agency ID:
Open Date: 2021-01-27
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2023-01-02
Restricted Access:
Fed Agency Name:
Hydrogen Status Link:
Status: Open: The station is open.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:

ID: 180118
Updated at: 2023-01-02 23:13:48 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 42.901748
Longitude: -78.867401

---

13 | **11 of 12** | **WSW** | **0.06 / 327.34** | **651.59 / 7** | **854ELLICOTT 854 ELLICOTT 12**
854 Ellicott St
Buffalo NY 14203
ALT FUELS

Fuel Type Code: ELEC: Electric
Station Phone: 888-758-4389
Expected Date: 2022-11-13
BD Blends:
NG Fill Type Code:
NG PSI:
Federal Agency ID:
Open Date: 2021-01-27
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:

ID: 180115
Updated at: 2023-01-02 23:13:48 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 42.901631

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867552
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Temporarily unavailable: The station is temporarily unavailable. See the "Expected Date" field for an anticipated open date.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

13	12 of 12	WSW	0.06 / 327.34	651.59 / 7	854ELLICOTT 854 ELLICOTT 10 854 Ellicott St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	180120
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:13:48 UTC
Expected Date:	2022-11-13	**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901637
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.867398
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Temporarily unavailable: The station is temporarily unavailable. See the "Expected Date" field for an anticipated open date.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

14	1 of 1	NNE	0.07 / 348.66	638.45 / -6	DEL-RICH PROPERTIES 35 EDNA PL BUFFALO NY 14209	RCRA NON GEN

EPA Handler ID:	NYR000087031
Gen Status Universe:	No Report
Contact Name:	DWIGHT HILL
Contact Address:	96, SEYMORE AVE, TONAWANDA, NY, 14151, US
Contact Phone No and Ext:	716-884-8859
Contact Email:	
Contact Country:	US
County Name:	ERIE

EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 42.904608
Location Longitude: -78.864393

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: DEL-RICH PROPERTIES
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: DEL-RICH PROPERTIES
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20000614
Handler Name: DEL-RICH PROPERTIES
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	96 SEYMORE AVE
Name:	DEL-RICH PROPERTIES	***Street 2:***	
Date Became Current:		***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-835-5624	***Country:***	
Source Type:	Notification	***Zip Code:***	14151

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	96 SEYMORE AVE
Name:	DEL-RICH PROPERTIES	***Street 2:***	
Date Became Current:		***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-835-5624	***Country:***	US
Source Type:	Implementer	***Zip Code:***	14151

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	96 SEYMORE AVE
Name:	DEL-RICH PROPERTIES	***Street 2:***	
Date Became Current:		***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-835-5624	***Country:***	US
Source Type:	Implementer	***Zip Code:***	14151

Historical Handler Details

Receive Dt:	20000614
Generator Code Description:	Very Small Quantity Generator
Handler Name:	DEL-RICH PROPERTIES

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	DEL-RICH PROPERTIES

15	*1 of 1*	*SSE*	*0.07 / 358.41*	*662.79 / 18*	***BUFFALO GENERAL HOSPITAL*** ***112 GOODRICH AVENUE*** ***BUFFALO NY***	***NY SPILLS***

Spill No:	9502029	***UST Trust:***	False
Site ID:	141665	***Spill Date:***	1995-05-01 12:00:00
DER Facility ID:	120937	***Received Date:***	1995-05-18 09:30:00
CID:		***CAC Date:***	1995-05-18 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1995-05-18 00:00:00
Water Body:		***Create Date:***	1995-05-18 00:00:00
Class:	E5	***Update Date:***	1995-05-18 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	LEARY
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Citizen		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"LETTING FREON ESCAPE WHILE DISMANTLING AIR CONDITIONER."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 05/18/95: RNL GAVE COPY OF SPILL REPORT TO LARRY SITZMAN, DIVISION OF AIR RESOURCES FOR FOLLOW-UP. NO FURTHER ACTION BY SPILLS NECESSARY. "

Material Information

OP Unit ID:	1013104	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	367101	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	True		
Material Code:	0050A		
Material Name:	freon		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO GENERAL HOSPITAL
Spiller Address:	112 GOODRICH AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901308276
Longitude:	-78.865347445

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	1 of 1	SW	0.07 / 385.77	654.69 / 10	BUFFALO GENERAL HOSPITAL GOODRICH ST/ELLICOTT ST C/BUFFALO NY	NY SPILLS

Spill No:	0705383	***UST Trust:***	False
Site ID:	385684	***Spill Date:***	2007-08-10 06:37:00
DER Facility ID:	335066	***Received Date:***	2007-08-10 07:06:00
CID:	74	***CAC Date:***	
Program Type:	ER	***Insp Date:***	2007-08-10 00:00:00
SWIS Code:	1502	***Close Date:***	2007-09-13 00:00:00
Water Body:		***Create Date:***	2007-08-10 07:36:00
Class:	B3	***Update Date:***	2007-09-13 11:48:30.390000000
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	rmcrosse
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Citizen		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"100 gallon fuel tank on a tractor trailer - in front of the Buffalo General Hospital - ruptured saddle tank. Dyke it - Would like DEC REP to call back and speak to acting dispatcher Grice. "

DEC Remark:

"08/10/07 RMC/SITE. TRACTOR TRAILER JUST HAD NEW TANK PUT ON PASS. SIDE. MOUNTING BOLT PUT HOLE IN THE TANK. TRUCK DROVE AROUND THE BUILDING AND STOPPED ON GOODRIDGE JUST EAST OF THE EMERGENCY ROOM. SPILL CONTAINED BY BUFFALO FIRE AND CLEANED UP BY RUSINIAKS WHO WILL PROVIDE DISPOSAL RECEIPTS. RECEIPTS DUE 9/15/07. 09/13/07 RMC/FILE. DISPOSAL DOCUMENTS RECEIVED FOR 2 DRUMS, NO FURTHER ACTION REQUIRED. CLOSE OUT. "

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Information

OP Unit ID:	1142947	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2133194	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	True
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	False
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	CAPT THOMAS FITZPATRICK
Contact Phone:	(716) 851-3510
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	*1 of 1*	*SE*	*0.10 / 507.39*	*669.80 / 25*	***1031 Michigan Ave Buffalo NY 14204***	***COOLING TOWERS***

Equip Unique ID:	8342	***Cooling Capacity:***	440
Equipment County:	Erie	***Cool Capacity Unit:***	Tonnage
Equipment Borough:		***Commissioned Dt:***	04/01/2010
Intended Use:	Air Conditioning	***Inspection Dt:***	05/04/2022
Manufacturer:	Tower Tech		
Model:	TTXL-061950		
Bacteriological Sample Dt:	05/04/2022		
Legionella Sample Coll Dt:	05/04/2022		
Last Legionella Sample Result:	no		
Street Address:	1031 Michigan Ave		
New Georeferenced Column:	1031 Michigan Ave Buffalo, ny 14204 (42.900981, -78.8628)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	*1 of 1*	*N*	*0.10 / 537.43*	*639.09 / -5*	***ABANDONED MEDICAL WASTE 1003 ELLICOTT STREET BUFFALO NY***	***NY SPILLS***

Spill No:	9910017	***UST Trust:***	False
Site ID:	159831	***Spill Date:***	1999-11-18 07:23:00
DER Facility ID:	135005	***Received Date:***	1999-11-18 07:46:00
CID:	204	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1999-11-18 00:00:00
Water Body:		***Create Date:***	1999-11-18 00:00:00
Class:	B4	***Update Date:***	1999-11-22 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	JFOTTO
REM Phase:	0	***After Hours:***	True
County:	Erie		

Contributing Factor:	Deliberate
Reported by:	Fire Department
Referred to:	
Source:	Unknown
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"MEDICAL WASTE FOUND AT ABOVE LOCATION "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 11/18/99: JFO TELECON BUFFALO FIRE DISPATCHER PITTS. WASTE HAS BEEN CLEANED UP BY THE BUFFALO FIRE DEPARTMENT. A BLEACH COMPOUND IS BEING SPREAD ON THE AREA WHERE THE WASTE WAS DISCOVERED AND WILL BE BAGGED. BUFFALO GENERAL HOSPITAL WILL ACCEPT THE WASTE AND CLEANUP MATERIAL AND DISPOSE. NO ACTION NECESSARY. CLOSED"

Material Information

OP Unit ID:	1088708	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	299079	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0053A		
Material Name:	medical waste		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	FIRE DISPATCHER PITTS
Contact Phone:	(716) 851-5510
Contact Ext:	
Latitude:	42.905310640
Longitude:	-78.865601530

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	1 of 29	S	0.10 / 538.47	662.47 / 18	NYSDOT-WB RTE I-86 OVER RTE 60 ELLICOTT NY 14701	RCRA LQG

EPA Handler ID:	NYD986973444
Gen Status Universe:	Large Quantity Generator
Contact Name:	JANINE H SHEPHERD
Contact Address:	
Contact Phone No and Ext:	716-847-5080
Contact Email:	JSHEPHERD@DOT.STATE.NY.US
Contact Country:	
County Name:	CHAUTAUQUA
EPA Region:	02
Land Type:	State
Receive Date:	20100218
Location Latitude:	42.900796
Location Longitude:	-78.865658

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation: FR - 40 CFR 268.7(a)(b)
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19930204
Scheduled Compliance Date: 19940612
Return to Compliance: Observed
Actual Return to Compl: 19940612
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 110
Enforcement Type Description: VERBAL INFORMAL
Enforcement Action Date: 19940512
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation: FR - 40 CFR 262.40
Violation Short Description: Generators - Manifest
Violation Type: 262.B
Violation Determined Date: 19930204
Scheduled Compliance Date: 19940612
Return to Compliance: Observed
Actual Return to Compl: 19940612
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 110
Enforcement Type Description: VERBAL INFORMAL
Enforcement Action Date: 19940512
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 19930409
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19940612
Evaluation Agency: EPA Contractor/Grantee

Evaluation Start Date: 19930409

Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - Manifest
Return to Compliance Date: 19940612
Evaluation Agency: EPA Contractor/Grantee

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100218
Handler Name: NYSDOT-WB
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: NYSDOT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19910819
Handler Name: NYSDOT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: NYSDOT
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: State
Name: NYSDOT
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: UNKNOWN
Street 2:
City: UNKNOWN
State: NY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: State
Name: NYSDOT
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No: 125
Street 1: MAIN ST - GEN WJ DONOVAN
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14203

Owner/Operator Ind: Current Owner
Type: State
Name: NYSDOT
Date Became Current: 19730101
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No: 100
Street 1: SENECA ST
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14203

Owner/Operator Ind: Current Operator
Type: State
Name: NYSDOT
Date Became Current: 19730101
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No: 100
Street 1: SENECA ST
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14203

Owner/Operator Ind: Current Owner
Type: State
Name: NYSDOT
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: UNKNOWN
Street 2:
City: UNKNOWN
State: NY
Country: US
Zip Code: 99999

Historical Handler Details

Receive Dt: 20070101
Generator Code Description: Not a Generator, Verified
Handler Name: NYSDOT

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: NYSDOT

Receive Dt: 19910819
Generator Code Description: Not a Generator, Verified
Handler Name: NYSDOT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	2 of 29	S	0.10 / 538.47	662.47 / 18	BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH 100 HIGH ST BUFFALO NY 14203	RCRA LQG

EPA Handler ID: NYD074042292
Gen Status Universe: Large Quantity Generator
Contact Name: VINCENT C PERRI
Contact Address: 100, HIGH ST, BUFFALO, NY, 14203, US
Contact Phone No and Ext: 716-859-4597
Contact Email: VPERRI@KALEIDAHEALTH.ORG
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20220301
Location Latitude: 42.900329
Location Longitude: -78.864937

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19950619
Scheduled Compliance Date: 19950719
Return to Compliance: Observed
Actual Return to Compl: 19950623
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19950619
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Universal Waste - Small Quantity Handlers
Violation Type: 273.B
Violation Determined Date: 20140828
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20141006
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20140908
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: State Statute or Regulation
Violation Type: XXS
Violation Determined Date: 20140828
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20141006
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20140908
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - Pre-transport
Violation Type: 262.C
Violation Determined Date: 20160913
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20161014
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20160916
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:

Violation Short Description: Generators - Pre-transport
Violation Type: 262.C
Violation Determined Date: 20140828
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20141006
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20140908
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: TSD IS-Container Use and Management
Violation Type: 265.I
Violation Determined Date: 20140828
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20141006
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20140908
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20160913
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - Pre-transport
Return to Compliance Date: 20161014
Evaluation Agency: State

Evaluation Start Date: 20140828
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - Pre-transport
Return to Compliance Date: 20141006
Evaluation Agency: State

Evaluation Start Date: 19950608
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19950623
Evaluation Agency: State

Evaluation Start Date: 20140828
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: State Statute or Regulation
Return to Compliance Date: 20141006
Evaluation Agency: State

Evaluation Start Date: 20030827
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 20140828
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: TSD IS-Container Use and Management
Return to Compliance Date: 20141006
Evaluation Agency: State

Evaluation Start Date: 20111103
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20050301
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20030702
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19861101
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20020115
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20140828
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Universal Waste - Small Quantity Handlers
Return to Compliance Date: 20141006
Evaluation Agency: State

Evaluation Start Date: 20191120
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No

Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20160223
Handler Name:	BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code:	U129
Waste Code Description:	CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE
Hazardous Waste Code:	U035
Waste Code Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL
Hazardous Waste Code:	U010
Waste Code Description:	AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C
Hazardous Waste Code:	U002
Waste Code Description:	2-PROPANONE (I) (OR) ACETONE (I)
Hazardous Waste Code:	U080
Waste Code Description:	METHANE, DICHLORO- (OR) METHYLENE CHLORIDE
Hazardous Waste Code:	D011
Waste Code Description:	SILVER
Hazardous Waste Code:	D009
Waste Code Description:	MERCURY
Hazardous Waste Code:	U165
Waste Code Description:	NAPHTHALENE
Hazardous Waste Code:	U015
Waste Code Description:	AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)
Hazardous Waste Code:	U034
Waste Code Description:	ACETALDEHYDE, TRICHLORO- (OR) CHLORAL
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	F003
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20210302
Handler Name: BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D042
Waste Code Description: 2,4,6-TRICHLOROPHENOL

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P188
Waste Code Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: U058
Waste Code Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: BUFFALO GENERAL HOSPITAL THE
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19841211
Handler Name: BUFFALO GENERAL HOSPITAL THE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: X002
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960131
Handler Name: THE BUFFALO GENERAL HOSPITAL
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20180227
Handler Name: BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: U034
Waste Code Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Hazardous Waste Code: U015
Waste Code Description: AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)

Hazardous Waste Code: U035
Waste Code Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U129
Waste Code Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U080
Waste Code Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: BUFFALO GENERAL HOSPITAL THE
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20220301
Handler Name: BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH

Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: P188
Waste Code Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Code: D042
Waste Code Description: 2,4,6-TRICHLOROPHENOL

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: U058

Waste Code Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20010101
Handler Name: BUFFALO GENERAL HOSPITAL
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140131
Handler Name: BUFFALO GENERAL MEDICAL CTR - KALEIDA HEALTH
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: U155
Waste Code Description: 1,2-ETHANEDIAMINE, N,N-DIMETHYL-N'-2-PYRIDINYL-N'-(2-THIENYLMETHYL)- (OR) METHAPYRILENE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: U123
Waste Code Description: FORMIC ACID (C,T)

Hazardous Waste Code: U035
Waste Code Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U015
Waste Code Description: AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U034
Waste Code Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: U129
Waste Code Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Code: U080
Waste Code Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20200302
Handler Name: BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990714
Handler Name: BUFFALO GENERAL HOSPITAL THE
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	726
Type:	Private	***Street 1:***	EXCHANGE ST
Name:	KALEIDA HEALTH	***Street 2:***	
Date Became Current:	20010101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-859-2715	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14203

Owner/Operator Ind:	Current Operator	***Street No:***	100
Type:	Private	***Street 1:***	HIGH ST
Name:	TIMOTHY R BATT	***Street 2:***	
Date Became Current:	20010101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-859-2715	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14203

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	NOT REQUIRED
Name:	THE BUFFALO GENERAL HOSPITAL	***Street 2:***	
Date Became Current:		***City:***	NOT REQUIRED
Date Ended Current:		***State:***	WY
Phone:	212-555-1212	***Country:***	
Source Type:	Notification	***Zip Code:***	99999

Owner/Operator Ind:	Current Owner	***Street No:***	100
Type:	Private	***Street 1:***	HIGH ST
Name:	KALEIDA HEALTH	***Street 2:***	
Date Became Current:	20010101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-859-4597	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14203

Owner/Operator Ind:	Current Owner	**Street No:**	100
Type:	Private	**Street 1:**	HIGH ST
Name:	KALEIDA HEALTH	**Street 2:**	
Date Became Current:	20010101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-859-2715	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14203

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	THE BUFFALO GENERAL HOSPITAL	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	THE BUFFALO GENERAL HOSPITAL	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Owner/Operator Ind:	Current Operator	**Street No:**	100
Type:	Private	**Street 1:**	HIGH ST
Name:	VINCENT C. PERRI	**Street 2:**	
Date Became Current:	20010101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-859-4597	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14203

Owner/Operator Ind:	Current Operator	**Street No:**	726
Type:	Private	**Street 1:**	EXCHANGE ST
Name:	KALEIDA HEALTH	**Street 2:**	
Date Became Current:	20010101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14203

Historical Handler Details

Receive Dt:	20160223
Generator Code Description:	Large Quantity Generator
Handler Name:	BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH

Receive Dt:	20060101
Generator Code Description:	Small Quantity Generator
Handler Name:	BUFFALO GENERAL HOSPITAL THE

Receive Dt:	20210302
Generator Code Description:	Large Quantity Generator
Handler Name:	BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH

Receive Dt:	19841211
Generator Code Description:	Large Quantity Generator
Handler Name:	BUFFALO GENERAL HOSPITAL THE

Receive Dt:	20180227
Generator Code Description:	Large Quantity Generator
Handler Name:	BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH

Receive Dt:	20070101
Generator Code Description:	Small Quantity Generator
Handler Name:	BUFFALO GENERAL HOSPITAL THE

Receive Dt:	19960131

Generator Code Description: Large Quantity Generator
Handler Name: THE BUFFALO GENERAL HOSPITAL

Receive Dt: 19990714
Generator Code Description: Small Quantity Generator
Handler Name: BUFFALO GENERAL HOSPITAL THE

Receive Dt: 20140131
Generator Code Description: Large Quantity Generator
Handler Name: BUFFALO GENERAL MEDICAL CTR - KALEIDA HEALTH

Receive Dt: 20200302
Generator Code Description: Large Quantity Generator
Handler Name: BUFFALO GENERAL MEDICAL CENTER-KALEIDA HEALTH

Receive Dt: 20010101
Generator Code Description: Large Quantity Generator
Handler Name: BUFFALO GENERAL HOSPITAL

19	3 of 29	S	0.10 / 538.47	662.47 / 18	MULTILAB - FIRST FLOOR 100 HIGH ST ROOM 122 BUFFALO NY 14203-1154	RCRA SQG

EPA Handler ID: NYR000144576
Gen Status Universe: Small Quantity Generator
Contact Name: ANTHONY OSWALD
Contact Address: 200, WINSPEAR AVE, SUNY @ BUFFALO, BUFFALO, NY, 14215, US
Contact Phone No and Ext: 716-829-3301
Contact Email: AOSWALD@FACILITIES.BUFFALO.EDU
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Municipal
Receive Date: 20070222
Location Latitude: 42.900325
Location Longitude: -78.86631

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20070222
Handler Name: MULTILAB - FIRST FLOOR

Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070222
Handler Name: MULTILAB - FIRST FLOOR
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20070223
Handler Name: MULTILAB - FIRST FLOOR
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P087
Waste Code Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: U117
Waste Code Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Hazardous Waste Code: U136
Waste Code Description: ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID

Hazardous Waste Code: U239
Waste Code Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: U007
Waste Code Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Municipal	***Street 1:***	
Name:	BUFFALO GENERAL HOSPITAL	***Street 2:***	
Date Became Current:	20000101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Notification	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Municipal	***Street 1:***	
Name:	BUFFALO GENERAL HOSPITAL	***Street 2:***	
Date Became Current:	20000101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Notification	***Zip Code:***	

Historical Handler Details

Receive Dt: 20070222
Generator Code Description: Small Quantity Generator
Handler Name: MULTILAB - FIRST FLOOR

Receive Dt: 20070223
Generator Code Description: Small Quantity Generator
Handler Name: MULTILAB - FIRST FLOOR

19	*4 of 29*	*S*	*0.10 / 538.47*	*662.47 / 18*	***BUFFALO GENERAL HOSPITAL*** ***100 HIGH ST*** ***Buffalo NY 14203***	***AST***

Site ID:	54488	**Expiry:**	2023/07/28
Site Status:	Active	**County:**	Erie
Program No:	9-451320	**UTM X:**	184366.07848
Program Type Code:	PBS	**UTM Y:**	4757059.04328
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Hospital/Nursing Home/Health Care		

Tank Information

Prog No:	9-451320	**UDC Ind:**	0
Tank ID:	251480	**Red Tag Start Date:**	
Tank No:	3A-3	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	05/09/2011	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	500	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location:	3
Tank Location Desc:	Aboveground on saddles, legs, stilts, rack or cradle
Category:	2
Category Desc:	Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:	4
Subpart Desc:	Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:	DENNIS DEVORE
Tank Owner Address:	100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name:	diesel
Percent:	100.00

Equipment Information

Equipment:	G01
Code Name:	Diking (Aboveground)
Type:	Tank Secondary Containment
Equipment:	L09
Code Name:	Exempt Suction Piping
Type:	Piping Leak Detection
Equipment:	E00
Code Name:	None
Type:	Piping Secondary Containment
Equipment:	H00
Code Name:	None
Type:	Tank Leak Detection
Equipment:	C01
Code Name:	Aboveground
Type:	Pipe Location
Equipment:	B01
Code Name:	Painted/Asphalt Coating
Type:	Tank External Protection
Equipment:	F01
Code Name:	Painted/Asphalt Coating

Type: Pipe External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Tank Information

Prog No:	9-451320	**UDC Ind:**	0
Tank ID:	251478	**Red Tag Start Date:**	
Tank No:	3A-1	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	05/09/2011	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	500	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	178126	***Red Tag Start Date:***	
Tank No:	6	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	11/01/1997	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	250	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: waste oil/used oil
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J03
Code Name: Gravity
Type: Dispenser

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	248682	***Red Tag Start Date:***	
Tank No:	3A	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	05/09/2011	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	26000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: J05
Code Name: On Site Heating System (Supply/Return)
Type: Dispenser

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: G12
Code Name: Double-Walled (AG only)
Type: Tank Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: B09
Code Name: Urethane
Type: Tank External Protection

Equipment: E12
Code Name: Double-Walled (AG only)
Type: Piping Secondary Containment

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	251491	***Red Tag Start Date:***	
Tank No:	8-5	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	10/01/1998	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	100	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI

Tank Model: ***Last Modified:*** 05/09/2022
Pipe Model:
Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Tank Information

Prog No:	9-451320	***UDC Ind:***	1
Tank ID:	178129	***Red Tag Start Date:***	
Tank No:	7-A	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:		***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	3000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 6
Tank Location Desc: Aboveground in Subterranean Vault w/ access for inspections
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: J02
Code Name: Suction Dispenser

Type: Dispenser

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	251485	***Red Tag Start Date:***	
Tank No:	8-3	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	10/01/1998	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	200	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	265033	***Red Tag Start Date:***	
Tank No:	9A	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	10/01/2015	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	500	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	9-451320	***UDC Ind:***	1
Tank ID:	178127	***Red Tag Start Date:***	
Tank No:	6-A	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:		***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	3000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 6
Tank Location Desc: Aboveground in Subterranean Vault w/ access for inspections
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: G03

Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	251484	***Red Tag Start Date:***	
Tank No:	8-2	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	10/01/1998	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	200	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	251479	***Red Tag Start Date:***	
Tank No:	3A-2	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	05/09/2011	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	500	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	3		

Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Tank Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Prog No:	9-451320	**UDC Ind:**	0
Tank ID:	251482	**Red Tag Start Date:**	
Tank No:	8-1	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	10/01/1998	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	200	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: F01

Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Tank Information

Prog No:	9-451320	**UDC Ind:**	0
Tank ID:	264579	**Red Tag Start Date:**	
Tank No:	9	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	-
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	10/01/2015	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	-
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	15000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: A01
Code Name: Epoxy Liner
Type: Tank Internal Protection

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: G12
Code Name: Double-Walled (AG only)

Type: Tank Secondary Containment

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Tank Information

Prog No:	9-451320	**UDC Ind:**	0
Tank ID:	251489	**Red Tag Start Date:**	
Tank No:	8-4	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	10/01/1998	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	200	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 3
Tank Location Desc: Aboveground on saddles, legs, stilts, rack or cradle
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	174947	***Red Tag Start Date:***	
Tank No:	09	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	12/20/1999	***Next Line Test Due:***	
Close Date:	10/01/2009	***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	1500	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	1		
Tank Location Desc:	Aboveground-contact w/ soil		
Category:	2		
Category Desc:	Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015		
Subpart:			
Subpart Desc:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: B05
Code Name: Jacketed
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J03
Code Name: Gravity
Type: Dispenser

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: F06
Code Name: Wrapped
Type: Pipe External Protection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: KALEDIA HEALTH
Contact Title:
Contact Name: JAMES A. BORTZ
Address1:
Address2:
City:
State: NY
Zip Code:
Country Code: 001
Phone: (716) 859-2818
Phone Ext:
Email:

Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: BUFFALO GENERAL HOSPITAL
Contact Title:
Contact Name: AARON JUDD
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (716) 859-5600
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: KALEIDA HEALTH
Contact Title: SR. DIRECTOR OF FACILITIES
Contact Name: JAMES A. BORTZ
Address1: 726 EXCHANGE STREET
Address2:
City: BUFFALO
State: NY
Zip Code: 14210
Country Code: 001
Phone: (716) 859-5600
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: BUFFALO GENERAL HOSPITAL
Contact Title: SR. DIRECTOR OF FACILITIES
Contact Name: JAMES A. BORTZ
Address1: 100 HIGH STREET
Address2:
City: BUFFALO
State: NY
Zip Code: 14203
Country Code: 001
Phone: (716) 859-2818
Phone Ext:
Email: JBORTZ@KALEIDAHEALTH.ORG
Fax:

19	***5 of 29***	***S***	***0.10 / 538.47***	***662.47 / 18***	***BUFFALO GENERAL HOSPITAL*** ***100 HIGH ST*** ***Buffalo NY 14203***	***UST***

Site ID: 54488
Site Status: Active
Program No: 9-451320
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: Hospital/Nursing Home/Health Care

Expiry: 07/28/2023
County: Erie
UTM X: 184366.07848
UTM Y: 4757059.04328

Tank Information

Prog No: 9-451320
UDC Ind: 1

Tank ID:	168013	**Red Tag Start Date:**	
Tank No:	5	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:		**Next Test:**	
Close Date:	10/01/1998	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	500	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G07
Code Name: Excavation Liner
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: B02
Code Name: Original Sacrificial Anode
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	168010	***Red Tag Start Date:***	
Tank No:	2	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	06/30/2003
Tank Status Desc:	In Service	***Tank Next Test Due:***	10/11/2016
Tank Type:	01	***Test Method:***	00
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	06/01/1967	***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	26000	***Line Test Method:***	-
Registered:	True	***Modified by:***	PTDIEZ
Tank Model:		***Last Modified:***	07/11/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 3
Subpart Desc: Subpart 3 contains requirements for USTs subject to just DEC requirements (primary example is tanks storing heating oil for on-premises consumption).
Class A Operator:
Class B Operator:
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: #4 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No:	9-451320	**UDC Ind:**	0
Tank ID:	173262	**Red Tag Start Date:**	
Tank No:	8	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	06/30/2003
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	06	**Test Method:**	21
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	**Date Tested:**	
Install Date:	10/01/1998	**Next Test:**	
Close Date:		**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	20000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 2
Subpart Desc: Subpart 2 contains requirements for USTs (underground storage tanks) subject to EPA UST regulations and DEC requirements.
Class A Operator: AARON JUDD
Class B Operator: AARON JUDD
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: H05
Code Name: In-Tank System (ATG)
Type: Tank Leak Detection

Equipment: I03
Code Name: Automatic Shut-Off

Type: Overfill

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: D08
Code Name: Equivalent Technology
Type: Pipe Type

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: F99
Code Name: Other
Type: Pipe External Protection

Tank Information

Prog No:	9-451320	***UDC Ind:***	0
Tank ID:	168009	***Red Tag Start Date:***	
Tank No:	1	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	07/26/2022
Tank Status Desc:	In Service	***Tank Next Test Due:***	07/26/2023
Tank Type:	01	***Test Method:***	34
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	06/01/1967	***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	26000	***Line Test Method:***	-
Registered:	True	***Modified by:***	PTDIEZ
Tank Model:		***Last Modified:***	08/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart: 3
Subpart Desc: Subpart 3 contains requirements for USTs subject to just DEC requirements (primary example is tanks storing heating oil for on-premises consumption).
Class A Operator:
Class B Operator:
Tank Owner Name: DENNIS DEVORE
Tank Owner Address: 100 HIGH ST BUFFALO, NY. 14203

Material Information

Material Name: #4 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: G03
Code Name: Vault (w/o access)
Type: Tank Secondary Containment

Equipment: L09

Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Tank Information

Prog No:	9-451320	***UDC Ind:***	1
Tank ID:	168012	***Red Tag Start Date:***	
Tank No:	4	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	NN
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:	02/01/1984	***Next Test:***	
Close Date:	10/01/1998	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	10000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: G07
Code Name: Excavation Liner
Type: Tank Secondary Containment

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Tank Information

Prog No:	9-451320	***UDC Ind:***	1
Tank ID:	168011	***Red Tag Start Date:***	
Tank No:	3	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	03/01/1995
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	06	***Test Method:***	03
Tank Type Desc:	Fiberglass Reinforced Plastic (FRP)	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	10/01/1998	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	5000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: G07
Code Name: Excavation Liner
Type: Tank Secondary Containment

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: A03
Code Name: Fiberglass Liner (FRP)
Type: Tank Internal Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Equipment: B04
Code Name: Fiberglass
Type: Tank External Protection

Tank Information

Prog No: 9-451320
Tank ID: 178128
Tank No: 7
Tank Status: 3
Tank Status Desc: Closed - Removed
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
Install Date: 10/01/1998
Close Date: 05/13/2010
Tk Out of Serv Dt:
Capacity (Gal): 500
Registered: True
Tank Model:
Pipe Model:
Tank Location: 5
Tank Location Desc: Underground
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart:
Subpart Desc:
Class A Operator:

UDC Ind: 1
Red Tag Start Date:
Red Tag End Date:
Tank Last Test: 07/30/2003
Tank Next Test Due:
Test Method: 21
Date Tested:
Next Test:
Line Last Test Due:
Next Line Test Due:
Line Test Method:
Modified by: MJGRIFFI
Last Modified: 05/09/2022

Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: F99
Code Name: Other
Type: Pipe External Protection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: D08
Code Name: Equivalent Technology
Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I03
Code Name: Automatic Shut-Off
Type: Overfill

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: C02
Code Name: Underground/On-ground
Type: Pipe Location

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: BUFFALO GENERAL HOSPITAL
Contact Title:
Contact Name: AARON JUDD
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone: (716) 859-5600
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: BUFFALO GENERAL HOSPITAL
Contact Title: SR. DIRECTOR OF FACILITIES
Contact Name: JAMES A. BORTZ
Address1: 100 HIGH STREET
Address2:
City: BUFFALO
State: NY
Zip Code: 14203
Country Code: 001
Phone: (716) 859-2818
Phone Ext:
Email: JBORTZ@KALEIDAHEALTH.ORG
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: KALEIDA HEALTH
Contact Title: SR. DIRECTOR OF FACILITIES
Contact Name: JAMES A. BORTZ
Address1: 726 EXCHANGE STREET
Address2:
City: BUFFALO
State: NY
Zip Code: 14210
Country Code: 001
Phone: (716) 859-5600
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: KALEDIA HEALTH
Contact Title:
Contact Name: JAMES A. BORTZ
Address1:
Address2:
City:
State: NY
Zip Code:
Country Code: 001
Phone: (716) 859-2818
Phone Ext:
Email:
Fax:

19	6 of 29	S	0.10 / 538.47	662.47 / 18	BUFFALO GENERAL 100 HIGH STREET BUFFALO NY	NY SPILLS

Spill No: 0109330
Site ID: 138919
DER Facility ID: 118777
CID: 196
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D4

UST Trust: False
Spill Date: 2001-12-20 20:15:00
Received Date: 2001-12-20 21:45:00
CAC Date:
Insp Date:
Close Date: 2001-12-21 00:00:00
Create Date: 2001-12-20 00:00:00
Update Date: 2002-01-04 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	BRENNAN
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER STATES THAT A MATERIAL NAMED NATURALYTE THAT IS USED FOR A DIALISAS MACHINE SPILLED 1 QUART IN A ELEVATOR MATERIAL HAS BEEN CLEANED UP. UNKNOWN WHO SPILLED THE PRODUCT. CHEMICAL HAS BEEN CLEANED UP BY THE HOSPITAL CHEMICAL TEAM. PUT IN BIO HAZMAT BAGS AND WILL BE DISPOSED."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KAB 12/21/01: KAB RECEIVED AFTER-HOURS REPORT OF SPILLAGE AT BUFFALO GENERAL HOSPITAL. NO RESPONDER CALLED OUT AT TIME OF INCIDENT. MINOR SPILLAGE CLEANED UP BY RP AND DISPOSED WITH HOSPITAL'S REGULAR HAZMAT DISPOSAL. NO FURTHER ACTION NECESSARY. CLOSE OUT. *****NO PAPER FILE EXISTS FOR THIS SPILL*****"

Material Information

OP Unit ID:	846677	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	530537	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	1.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO GENERAL HOSPITAL
Spiller Address:	100 HIGH STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	SGT COLLEGE
Contact Phone:	(716) 859-4520
Contact Ext:	
Latitude:	42.900349120
Longitude:	-78.865082900

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	7 of 29	S	0.10 / 538.47	662.47 / 18	BUFFALO GENERAL HOSPITAL 100 HIGH STREET BUFFALO NY	NY SPILLS

Spill No:	9408004	**UST Trust:**	False
Site ID:	138921	**Spill Date:**	1994-09-14 08:00:00
DER Facility ID:	118777	**Received Date:**	1994-09-14 09:00:00
CID:		**CAC Date:**	1994-09-14 00:00:00
Program Type:	ER	**Insp Date:**	1994-09-14 00:00:00
SWIS Code:	1502	**Close Date:**	1994-09-14 00:00:00
Water Body:		**Create Date:**	1994-09-15 00:00:00
Class:	D3	**Update Date:**	1994-10-07 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HYDRAULIC LINE FAILURE ON TRUCK"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/14/94: RMC/KERLING/PHONE RMC/SITE MATERIAL CLEANED UP W/ SPEEDY DRY AND PUT IN DUMPSTER, NO FURTHE ACTION REQUIRED, CLOSEOUT. "

Material Information

OP Unit ID:	1005715	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	377457	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	5.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO GENERAL
Spiller Address:	100 HIGH STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900349120
Longitude:	-78.865082900

19	***8 of 29***	***S***	***0.10 / 538.47***	***662.47 / 18***	***BUFFALO GENERAL HOSPITAL 100 HIGH STREET BUFFALO NY***	***LST***

Spill No:	0075587	**REM Phase:**	0
Site ID:	138918	**UST Trust:**	False
DER Facility ID:	118777	**Spill Date:**	2001-01-30 08:30:00
CID:		**Rcvd Date:**	2001-01-30 08:30:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	2001-01-30 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	2001-02-27 00:00:00
Water Body:		**Create Date:**	2001-01-30 08:35:00
Class:	C3	**Update Date:**	2002-03-12 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
County:	Erie	**After Hours:**	False

Referred to:
Reported by: Responsible Party
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CALLER SAID THAT THY HAD A #6 FUEL OIL SPILL(50 GAL),ALL IN THEIR SECONDARY CONTANIMENT AREA,BUT A SMALL AMOUNT GOT INTO THE SEWER,DUE TO THE RAIN...THEY HAVE PUT ABSORBANT BOOMS/PADS ALL OVER AND HAVE CONTAINED ABOUT 49 GALS."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 01/30/01: FG SITE INSPECTION. BUFFALO GENERAL WAS CLEANING UP SPILL WHEN I ARRIVED. IT WAS RAINING AND THEY HAD BUILT A DAM TO PREVENT THE SHEEN OFF THE PARKING LOT FROM ENTERING THE STORM DRAIN. THE CAUSE OF THE SPILL IS AN OVERFILL INTO CONTAINMENT. APPROXIMATELY 1 GALLON SPILLED OUT OF THE SECONDARY CONTAINMENT ONTO THE PARKING LOT. BUFFALO GENERAL HIRED THE ENVIRONMENTAL SERVICE GROUP TO COMPLETE THE CLEANUP AND DISPOSAL OF THE SPILLED MATERIAL. THEY WILL PUMP THE PRODUCT OUT OF THE SECONDARY CONTAINMENT. ESG IS EXPECTED TO BE ON SITE SHORTLY. 02/02/01: FG SPOKE TO DAVE MENDEL WITH THE ENVIRONMENTAL SERVICE GROUP. HE SAID BUFFALO GENERAL GENERATED 15 DRUMS OF DEBRIS, TWO OF THOSE ARE FUEL OIL RECOVERED, THE REST ARE PADS, BOOMS, SPEEDI DRY. ESG WILL BE HANDLING THE DISPOSAL OF THE MATERIAL AND WILL SEND ME A DISPOSAL RECEIPT. 02/27/01: FG RECEIVED DISPOSAL RECPT. NO FURTHER WORK IS REQUIRED. SITE CAN BE CLOSED."

Material Information

OP Unit ID:	838457	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	539165	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	50.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	49.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	LARRY HEANEY
Spiller Company:	BUFFALO GENERAL HOSPITAL
Spiller Address:	100 HIGH STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14203-
Spiller Country:	001
Contact Name:	LARRY HEANEY
Contact Phone:	(716) 859-2613
Contact Ext:	
Latitude:	42.900349120
Longitude:	-78.865082900

19	***9 of 29***	***S***	***0.10 / 538.47***	***662.47 / 18***	***BUFFALO GENERAL HOSPITAL 100 HIGH STREET BUFFALO NY***	***LST***

Spill No:	8909904	***REM Phase:***	0
Site ID:	138920	***UST Trust:***	True
DER Facility ID:	118777	***Spill Date:***	1990-01-15 12:00:00
CID:		***Rcvd Date:***	1990-01-16 09:30:00
Program Type:	ER	***CAC Date:***	1990-07-10 00:00:00
SWIS Code:	1502	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	1990-07-10 00:00:00
Water Body:		***Create Date:***	1990-01-29 00:00:00
Class:		***Update Date:***	1990-07-11 00:00:00

Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"5,000 GAL. UST FAILED SYSTEM TEST"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 01/24/90: 1/24/90 LETTER TO FLANIGAN, OPTION TO RETEST OR REMOVE TANK. 07/10/90: 7/10/90 MNP REVIEW OF FILE TANK RETEST RECEIVED 1/31/90. TANK TEST RESULTS SATISFACTORY, TANK & PIPING TESTED TIGHT, COMPLETE. "

Material Information

OP Unit ID:	935004	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	443045	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO GENERAL HOSPITAL
Spiller Address:	100 HIGH STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14203
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900349120
Longitude:	-78.865082900

Tank Test Information

Spill Tank ID:	1536684	**Source:**	
Tank No:		**Leak Rate:**	.00
Tank SIze:	0	**Gross Fail:**	
Material:	0008	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	00
Cause:			
Alt Test Method:	Unknown		

19	***10 of 29***	***S***	***0.10 / 538.47***	***662.47 / 18***	***100 HIGH ST BUFFALO NY***	***HMIRS***

Incident County: ERIE

HMIR Historical Reports

Report No:	I-2006010653	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	11/02/2005	***Report Submit Src:***	Paper
Time of Incident:	1025	***Inc Multiple Rows:***	No
Haz Class Code:	5.2	***Inc Non US State:***	
Hazardous Class:	ORGANIC PEROXIDE	***Mode Transport:***	Highway
Commodity Short Nm:	ORGANIC PEROXIDE TYPE E	***Transport Phase:***	IN TRANSIT
Commodity Long Nm:	ORGANIC PEROXIDE TYPE E LIQUID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3107	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	UPS GROUND FREIGHT INC.
Qty Released:	0.0625	***CR Street Name:***	1000 SEMMES AVE
Unit of Measure:	Liquid - Gallon	***CR City:***	RICHMOND
What Failed:	103	***CR State:***	VA
What Failed Desc:	Basic Material	***CR Postal Code:***	23224-2246
How Failed Code:	305	***CR Non US State:***	
How Failed Desc:	Crushed	***CR Fed DOT ID:***	121058
Failure Cause Code:	519	***CR Hazmat Reg ID:***	051303004015LN
Failure Cause Desc:	Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:	STERIS - S2000	***Shipper Name:***	STERIS CORPORATION
Cont1 Pkging Type:	Box	***Shipper Street Name:***	6100 HEISLEY RD
Cont1 Const Mat:	Fiberboard	***Shipper City:***	MENTOR
Cont1 Head Type:		***Shipper State:***	OH
Cont1 Pkg Capacity:	1.75	***Shipper Postal:***	44060-1838
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	1.75	***Shipper Country:***	US
C1 Pkg Amt UOM:	LGA	***Shipper Waybill:***	970 525 754
Cont1 Pkg No:	15	***Ship Hazmat Reg ID:***	051705550046N
C1 Pkg NO Failed:	1	***Origin City:***	MENTOR
Cont1 Pkg Mnfctr:		***Origin State:***	OHIO
Cont1 Pkg Mnfct Dt:		***Origin Postal:***	44060
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:		***Origin Country:***	US
C1 Test Const Mat:	Fiberboard	***Destination City:***	BUFFALO
C1 Pkg Dsign Pres.:		***Destination State:***	NEW YORK
C1 Dsign Press UOM:		***Destination Postal:***	14203
C1 Pkg Shell Thick:		***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:		***Cont2 Package Type:***	Box
C1 Head Thick UOM:		***Cont2 Const Mat:***	Fiberboard or cardboard
C1 Pkg Srvc Pres.:		***Cont2 Pkg Capacity:***	
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	
C1 Device Model:		***Cont2 Pkg No Failed:***	
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	0
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	0
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:		***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	Yes	**Contact Name:**	MARCIE PRAUT
Damage > 500:	No	**Contact Title:**	OS&D CLERK
Material Loss:	0	**Contact Business:**	OVERNITE
Carrier Damage:	0	**Contact Street:**	2580 KENMORE AVE
Property Damage:	0	**Contact City:**	TONAWANDA
Response Cost:	0	**Contact State:**	NY
Remediation Cost:	0	**Contact Postal:**	14150
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: OUT FOR CITY DELIVERY DISCOVERED ONE BOX CRESTED AND LEAKING DUE TO IMPROPER LOADING BLOCKING AND BRACING. PROPER DISPOSAL STEPS HAVE BEEN FOLLOWED.

Recommend Actions Taken: BETTER USE OF DUNNAGE TO BLOCK / BRACE LOAD

19	11 of 29	S	0.10 / 538.47	662.47 / 18	MULTILAB - FIRST FLOOR 100 HIGH ST ROOM 122 BUFFALO NY 14203	GEN MANIFEST

RCRA ID:	NYR000144576	**Mailing State:**	NY
District Name:	MULTILAB - FIRST FLOOR	**Mailing ZIP:**	14203
Contact Name:	MULTILAB - FIRST FLOOR	**Mailing ZIP Ext:**	
Business Phone No:	7167545400	**Mailing Country:**	USA
Mailing Street 1:	100 HIGH ST	**Location ZIP Ext:**	
Mailing Street 2:	ROOM 122	**Location Country:**	USA
Mailing City:	BUFFALO	**Location County:**	ERIE

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2007: 3 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 10 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 13 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2007: 679 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
U239: (1330-20-7) Benzene, dimethyl-(I)

Waste Amounts By Year:

2007: 77 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U117: (60-29-7) Ethane, 1,1?-oxybis-(I)

Waste Amounts By Year:

2007: 8 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 26 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 8 Pounds; 8 Pounds; 3 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 4 Pounds; 5 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 10 Pounds; 8 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 6 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2007: 6 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification) **Note: data in the [Waste Code(s)] field for some records is truncated from the source.

Waste Amounts By Year:

2007: 4 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P030: Cyanides (soluble cyanide salts), not otherwise specified

Waste Amounts By Year:

2007: 10 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 11 Pounds

Manifest Information

Waste Code(s):

P087: (20816-12-0) Osmium oxide OsO4, (T-4)-

Waste Amounts By Year:

2007: 16 Pounds

Manifest Information

Waste Code(s):

U007: (79-06-1) 2-Propenamide

Waste Amounts By Year:

2007: 9 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)
U136: (75-60-5) Arsinic acid, dimethyl-

Waste Amounts By Year:

2007: 4 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U122: (50-00-0) Formaldehyde

Waste Amounts By Year:

2007: 77 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 9 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 9 Pounds; 36 Pounds; 262 Pounds; 14 Pounds; 13 Pounds; 62 Pounds; 44 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P098: (151-50-8) Potassium cyanide

Waste Amounts By Year:

2007: 7 Pounds

Manifest Information

Waste Code(s):

D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2007: 2 Pounds

Manifest Information

Waste Code(s):

P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2007: 4 Pounds

Manifest Information

Waste Code(s):

U188: (108-95-2) Phenol

Waste Amounts By Year:

2007: 16 Pounds; 6 Pounds

19	12 of 29	S	0.10 / 538.47	662.47 / 18	BUFFALO GENERAL HOSPITAL 100 HIGH ST BUFFALO NY 14203	GEN MANIFEST

RCRA ID:	NYD074042292	***Mailing State:***	NY
District Name:	BUFFALO GENERAL HOSPITAL	***Mailing ZIP:***	14203
Contact Name:	WILLIAM E BAMBERG	***Mailing ZIP Ext:***	
Business Phone No:	7168451602	***Mailing Country:***	USA
Mailing Street 1:	100 HIGH STREET	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 1 Pounds
2010: 7 Pounds; 3 Pounds; 1 Pounds
2011: 1 Pounds; 1 Pounds

2013: 1 Pounds
2014: 1 Pounds
2016: 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 30 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)
D024: M-CRESOL (Waste Code Description from EPA Hazardous Waste Identification)
P001: (181-81-2) Warfarin, & salts, when present at concentrations greater than 0.3 percent
P075: (154-11-5) Pyridine, 3-(1-methyl- 2-pyrrolidinyl)-, (S)-, & salts

Waste Amounts By Year:

2017: 1000 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 1 Pounds
2016: 154 Pounds

Manifest Information

Waste Code(s):

U031: (71-36-3) 1-Butanol (I)

Waste Amounts By Year:

2005: 1 Gallons

Manifest Information

Waste Code(s):

U044: (67-66-3) Methane, trichloro-

Waste Amounts By Year:

1993: 100 Pounds
2001: 4 Gallons
2002: 1 Gallons

Manifest Information

Waste Code(s):

U058: (50-18-0) 2H-1,3,2-Oxazaphosphorin- 2-amine, N,N-bis (2-chloroethyl) tetrahydro-, 2-oxide

Waste Amounts By Year:

2001: 15 Gallons

Manifest Information

Waste Code(s):

U069: (84-74-2) 1,2-Benzenedicarboxylic acid, dibutyl ester

Waste Amounts By Year:

1998: 55 Gallons

Manifest Information

Waste Code(s):

U080: (75-09-2) Methane, dichloro-
U129: (58-89-9) Lindane
U154: (67-56-1) Methanol (I)
U165: (91-20-3) Naphthalene
U205: (7488-56-4) Selenium sulfide

Waste Amounts By Year:

2013: 66 Pounds
2014: 400 Pounds

Manifest Information

Waste Code(s):

U112: (141-78-6) Acetic acid ethyl ester (I)

Waste Amounts By Year:

2006: 200 Pounds

Manifest Information

Waste Code(s):

U117: (60-29-7) Ethane, 1,1?-oxybis-(I)

Waste Amounts By Year:

1995: 1 Pounds
2002: 18 Gallons

Manifest Information

Waste Code(s):

U122: (50-00-0) Formaldehyde

Waste Amounts By Year:

2002: 55 Gallons; 55 Gallons
2013: 20 Pounds
2016: 400 Pounds

Manifest Information

Waste Code(s):

U133: (302-01-2) Hydrazine (R,T)

Waste Amounts By Year:

2001: 5 Pounds

Manifest Information

Waste Code(s):

U151: (7439-97-6) Mercury

Waste Amounts By Year:

2002: 100 Pounds

Manifest Information

Waste Code(s):

U188: (108-95-2) Phenol

Waste Amounts By Year:

1993: 10 Pounds
2016: 11 Pounds; 10 Pounds

Manifest Information

Waste Code(s):

U211: (56-23-5) Methane, tetrachloro-

Waste Amounts By Year:

2006: 30 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U003: (75-05-8) Acetonitrile (I,T)
U031: (71-36-3) 1-Butanol (I)
U122: (50-00-0) Formaldehyde
U154: (67-56-1) Methanol (I)

Waste Amounts By Year:

2010: 200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U031: (71-36-3) 1-Butanol (I)
U117: (60-29-7) Ethane, 1,1?-oxybis-(I)
U121: (75-69-4) Methane, trichlorofluoro-
U154: (67-56-1) Methanol (I)

Waste Amounts By Year:

2008: 200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U080: (75-09-2) Methane, dichloro-
U129: (58-89-9) Lindane
U154: (67-56-1) Methanol (I)
U165: (91-20-3) Naphthalene
U205: (7488-56-4) Selenium sulfide

Waste Amounts By Year:

2014: 200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U122: (50-00-0) Formaldehyde

Waste Amounts By Year:

2007: 20 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U188: (108-95-2) Phenol

Waste Amounts By Year:

2013: 16 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U201: (108-46-3) Resorcinol

Waste Amounts By Year:

2016: 5 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1990: 55 Gallons; 110 Gallons
1991: 35 Gallons
1993: 10 Pounds
1995: 500 Pounds; 10 Pounds; 5 Pounds
1996: 240 Gallons
1997: 5 Gallons; 55 Gallons
1998: 55 Gallons
1999: 4 Gallons; 4 Gallons; 2 Gallons
2001: 9 Pounds; 55 Pounds; 1 Gallons; 7 Pounds
2003: 3 Gallons
2004: 3 Pounds
2005: 3 Gallons; 1 Gallons; 8 Gallons; 1 Gallons; 5 Gallons
2007: 120 Pounds; 120 Pounds
2008: 55 Gallons; 1 Pounds; 200 Pounds; 40 Gallons; 12 Pounds; 50 Gallons
2009: 20 Pounds
2010: 3 Pounds
2011: 5 Pounds; 41 Pounds; 200 Pounds
2013: 40 Pounds
2016: 9 Pounds; 13 Pounds
2017: 18 Pounds; 77 Pounds; 3 Pounds; 4 Pounds; 1 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 8 Pounds
2010: 2 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 20 Pounds
2011: 2 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 175 Pounds
2014: 6 Pounds
2017: 4 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D010: SELENIUM (Waste Code Description from EPA Hazardous Waste Identification)
D015: TOXAPHENE (C10 H10 CL8, TECHNICAL CHLORINATED CAMPHENE, 67-69 PERCENT CHLORINE) (Waste Code Description from EPA Hazardous Waste Identification)
D034: HEXACHLOROETHANE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 553 Pounds; 170 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U123: (64-18-6) Formic acid (C,T)

Waste Amounts By Year:

2010: 7 Pounds
2013: 35 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P106: (143-33-9) Sodium cyanide

Waste Amounts By Year:

2008: 1 Pounds

Manifest Information

Waste Code(s):

B001: (Wastes containing polychlorinated biphenyls (PCBs)) PCB oil (concentrated) from transformers, capacitors, etc.

Waste Amounts By Year:

1984: 2450 Pounds
1987: 250 Pounds; 250 Pounds

Manifest Information

Waste Code(s):

B006: (Wastes containing polychlorinated biphenyls (PCBs)) PCB transformers. PCB transformers means any transformer that contains 500 ppm PCB or greater.

Waste Amounts By Year:

1987: 9700 Kilograms; 250 Pounds
1992: 2039 Kilograms

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
P012: (1327-53-3) Arsenic oxide As2 O3

Waste Amounts By Year:

2009: 1 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1993: 40 Pounds
2002: 12 Pounds

Manifest Information

Waste Code(s):

D006: CADMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1993: 150 Pounds
1995: 500 Pounds

Manifest Information

Waste Code(s):

D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 1 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1993: 25 Pounds; 25 Pounds
1995: 1 Pounds
1998: 5 Gallons
2001: 1 Pounds
2002: 5 Pounds
2004: 1 Pounds
2010: 1 Pounds
2014: 150 Pounds
2015: 20 Pounds
2016: 20 Pounds; 11 Pounds; 3 Pounds
2018: 1 Pounds

Manifest Information

Waste Code(s):

D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2006: 596 Pounds
2007: 50 Pounds; 5 Gallons; 30 Pounds; 5 Gallons; 30 Pounds
2008: 5 Gallons; 5 Gallons; 5 Gallons
2009: 5 Gallons; 5 Gallons
2010: 42 Pounds; 40 Pounds; 40 Pounds
2011: 50 Pounds; 42 Pounds; 90 Pounds
2012: 40 Pounds; 25 Pounds; 20 Pounds
2013: 100 Pounds; 50 Pounds; 50 Pounds
2014: 50 Pounds; 90 Pounds; 40 Pounds; 40 Pounds; 40 Pounds
2015: 350 Pounds; 800 Pounds; 300 Pounds; 50 Pounds; 40 Pounds; 200 Pounds; 300 Pounds; 250 Pounds; 350 Pounds; 150 Pounds; 400 Pounds
2016: 600 Pounds; 550 Pounds; 500 Pounds; 650 Pounds; 500 Pounds; 500 Pounds; 350 Pounds; 350 Pounds; 400 Pounds; 650 Pounds; 300 Pounds; 400 Pounds
2017: 400 Pounds; 800 Pounds; 800 Pounds; 400 Pounds; 400 Pounds; 450 Pounds; 45 Pounds; 500 Pounds; 400 Pounds; 412 Pounds; 450 Pounds; 409 Pounds; 300 Pounds
2018: 425 Pounds; 425 Pounds; 409 Pounds; 400 Pounds; 425 Pounds; 425 Pounds

Manifest Information

Waste Code(s):

F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

1990: 165 Gallons
2006: 165 Gallons

Manifest Information

Waste Code(s):

P048: (51-28-5) 2,4-Dinitrophenol

Waste Amounts By Year:

1999: 2 Gallons

2001: 1 Pounds
2002: 12 Pounds

Manifest Information

Waste Code(s):

P077: (100-01-6) Benzenamine, 4-nitro-

Waste Amounts By Year:

2008: 1 Pounds

Manifest Information

Waste Code(s):

P087: (20816-12-0) Osmium oxide OsO4, (T-4)-

Waste Amounts By Year:

1999: 1 Gallons
2005: 1 Pounds
2014: 1 Pounds

Manifest Information

Waste Code(s):

P098: (151-50-8) Potassium cyanide

Waste Amounts By Year:

1993: 10 Pounds
1999: 1 Gallons

Manifest Information

Waste Code(s):

P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2001: 11 Pounds
2013: .88 Pounds

Manifest Information

Waste Code(s):

U001: (75-07-0) Acetaldehyde (I)

Waste Amounts By Year:

1993: 40 Pounds

Manifest Information

Waste Code(s):

U006: (75-36-5) Acetyl chloride (C,R,T)

Waste Amounts By Year:

2001: 1 Pounds

Manifest Information

Waste Code(s):

U007: (79-06-1) 2-Propenamide

Waste Amounts By Year:

1999: 5 Pounds
2017: 4 Pounds

Manifest Information

Waste Code(s):

P043: (55-91-4) Phosphorofluoridic acid, bis(1-methylethyl) ester

Waste Amounts By Year:

1995: 200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1993: 10 Pounds; 10 Pounds
1994: 110 Gallons
1995: 2 Pounds; 10 Pounds; 75 Pounds; 10 Pounds; 5 Pounds
1996: 110 Gallons
1997: 5 Gallons; 55 Gallons
1998: 5 Gallons; 5 Gallons
1999: 3 Gallons; 1 Gallons; 5 Gallons; 5 Gallons; 5 Gallons; 5 Gallons; 5 Gallons; 5 Gallons; 5 Gallons; 1 Gallons; 5 Pounds; 5 Pounds; 1 Pounds; 1 Gallons; 1 Gallons; 1 Pounds; 1 Gallons; 2 Gallons; 2 Gallons
2001: 2 Pounds; 10 Pounds
2002: 8 Gallons; 1 Pounds; 12 Pounds; 15 Pounds; 1 Pounds; 1 Pounds; 1 Pounds; 8 Pounds; 2 Pounds
2003: 40 Gallons
2004: 55 Gallons; 110 Gallons; 55 Gallons
2005: 2 Gallons; 1 Pounds; 1 Gallons
2006: 50 Pounds; 2 Pounds
2009: 1 Pounds; 145 Pounds; 3 Pounds
2010: 5 Pounds; 20 Pounds
2011: 24 Pounds; 20 Pounds; 20 Pounds; 14 Pounds; 18 Pounds; 2 Pounds
2012: 32 Pounds; 628 Pounds; 37 Pounds; 65 Pounds
2013: 150 Pounds; 30 Pounds; 88 Pounds; 100 Pounds
2014: 40 Pounds; 2 Pounds; 125 Pounds; 125 Pounds; 40 Pounds; 125 Pounds
2015: 200 Pounds; 200 Pounds; 125 Pounds
2016: 1 Pounds; 4 Pounds; 1 Pounds; 42 Pounds; 1 Pounds; 200 Pounds
2017: 3 Pounds; 34 Pounds; 16 Pounds; 62 Pounds; 24 Pounds; 900 Pounds; 48 Pounds; 1 Pounds; 96 Pounds; 50 Pounds; 2 Pounds
2018: 52 Pounds; 38 Pounds; 1 Pounds; 56 Pounds; 58 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2008: 3 Pounds; 300 Pounds
2010: 90 Pounds; 4 Pounds; 12 Pounds
2011: 1 Pounds
2016: 7 Pounds; 15 Pounds
2017: 2 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2016: 1 Pounds
2017: 1 Pounds

Manifest Information

Waste Code(s):

D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2013: 253 Gallons

Manifest Information

Waste Code(s):

D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
U044: (67-66-3) Methane, trichloro-

Waste Amounts By Year:

2009: 6 Pounds

Manifest Information

Waste Code(s):

D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)
U002: (67-64-1) 2-Propanone (I)
U010: (50-07-7) Azirino [2?,3?: 3,4]pyrrolo[1,2-a]indole-4,7-dione, 6-amino- 8-[[(aminocarbonyl) oxy] methyl] -1,1a,2,8a,8b-hexahydro- 8a- methoxy-5-methyl-, [1aS- (1aalpha, 8beta, 8aalpha,8balpha)]-
U015: (115-02-6) L-Serine, diazoacetate (ester)
U034: (75-87-6) Acetaldehyde, trichloro-

Waste Amounts By Year:

2013: 300 Pounds

Manifest Information

Waste Code(s):

F001: (Generic) The following spent halogenated solvents used in degreasing: tetrachloroethylene, trichloroethylene, methylene chloride, 1,1, 1-trichloroethane, carbon tetrachloride, and chlorinated fluorocarbons; all spent solvent mixtures/blends used in degreasing containing, before use, total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those solvents listed in F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

1995: 1500 Pounds

Manifest Information

Waste Code(s):

F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

1993: 10 Pounds
1995: 10 Pounds

Manifest Information

Waste Code(s):

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

1990: 55 Gallons; 55 Gallons; 165 Gallons
1991: 55 Gallons
1992: 52 Gallons
1993: 55 Gallons; 55 Gallons; 110 Gallons; 400 Pounds; 100 Pounds
1995: 1600 Pounds
2004: 110 Gallons; 55 Gallons; 55 Gallons; 100 Pounds; 55 Gallons; 110 Gallons; 55 Gallons
2005: 110 Gallons; 110 Gallons; 110 Gallons; 110 Gallons; 110 Gallons; 110 Gallons; 110 Gallons; 110 Gallons
2006: 165 Gallons; 110 Gallons; 110 Gallons; 110 Gallons; 110 Gallons

Manifest Information

Waste Code(s):

P001: (181-81-2) Warfarin, & salts, when present at concentrations greater than 0.3 percent
P012: (1327-53-3) Arsenic oxide As2 O3
P042: (51-43-4) 1,2-Benzenediol, 4-[1-hydroxy-2-(methylamino) ethyl]-, (R)-
P075: (154-11-5) Pyridine, 3-(1-methyl- 2-pyrrolidinyl)-, (S)-, & salts
U002: (67-64-1) 2-Propanone (I)

Waste Amounts By Year:

2015: 800 Pounds

Manifest Information

Waste Code(s):

U002: (67-64-1) 2-Propanone (I)
U010: (50-07-7) Azirino [2?,3?: 3,4]pyrrolo[1,2-a]indole-4,7-dione, 6-amino- 8-[[(aminocarbonyl) oxy] methyl] -1,1a,2,8a,8b-hexahydro- 8a- methoxy-5-methyl-, [1aS- (1aalpha, 8beta, 8aalpha,8balpha)]-
U015: (115-02-6) L-Serine, diazoacetate (ester)
U034: (75-87-6) Acetaldehyde, trichloro-

Waste Amounts By Year:

2014: 750 Pounds

Manifest Information

Waste Code(s):

U002: (67-64-1) 2-Propanone (I)
U010: (50-07-7) Azirino [2?,3?: 3,4]pyrrolo[1,2-a]indole-4,7-dione, 6-amino- 8-[[(aminocarbonyl) oxy] methyl] -1,1a,2,8a,8b-hexahydro- 8a- methoxy-5-methyl-, [1aS- (1aalpha, 8beta, 8aalpha,8balpha)]-
U015: (115-02-6) L-Serine, diazoacetate (ester)
U034: (75-87-6) Acetaldehyde, trichloro-
U035: (305-03-3) Benzenebutanoic acid, 4-[bis (2- chloroethyl) amino] -

Waste Amounts By Year:

2011: 484 Pounds; 775 Pounds; 641 Pounds; 731 Pounds; 475 Pounds
2012: 1017 Pounds; 375 Pounds; 321 Pounds; 770 Pounds; 533 Pounds
2013: 800 Pounds; 200 Pounds; 1155 Pounds; 600 Pounds
2014: 1000 Pounds; 1000 Pounds; 200 Pounds; 1000 Pounds; 600 Pounds
2015: 600 Pounds; 800 Pounds; 1000 Pounds; 300 Pounds; 350 Pounds; 900 Pounds; 200 Pounds
2016: 600 Pounds; 750 Pounds; 2000 Pounds

Manifest Information

Waste Code(s):

P048: (51-28-5) 2,4-Dinitrophenol
P077: (100-01-6) Benzenamine, 4-nitro-
P087: (20816-12-0) Osmium oxide OsO4, (T-4)-
P105: (26628-22-8) Sodium azide
P116: (79-19-6) Thiosemicarbazide

Waste Amounts By Year:

2010: 1 Pounds

Manifest Information

Waste Code(s):

P106: (143-33-9) Sodium cyanide

Waste Amounts By Year:

2002: 5 Pounds

Manifest Information

Waste Code(s):

U002: (67-64-1) 2-Propanone (I)

Waste Amounts By Year:

2003: 2 Gallons

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1999: 120 Pounds
2000: 200 Pounds
2004: 12000 Pounds
2007: 400 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)
U151: (7439-97-6) Mercury

Waste Amounts By Year:

2008: 1 Pounds
2010: 3 Pounds
2011: 3 Pounds
2013: 1 Pounds
2018: 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2006: 110 Gallons; 110 Gallons; 110 Gallons
2007: 110 Gallons; 55 Gallons; 55 Gallons; 55 Gallons; 110 Gallons; 110 Gallons; 55 Gallons; 55 Gallons; 55 Gallons; 52 Gallons; 55 Gallons; 110 Gallons
2008: 55 Gallons; 55 Gallons; 500 Pounds; 369 Pounds; 369 Pounds; 369 Pounds; 55 Gallons; 55 Gallons; 357 Pounds; 55 Gallons; 55 Gallons; 55 Gallons; 363 Pounds; 55 Gallons; 55 Gallons
2009: 369 Pounds; 420 Pounds; 738 Pounds; 738 Pounds; 740 Pounds; 740 Pounds; 760 Pounds; 720 Pounds; 55 Gallons
2010: 738 Pounds; 1600 Pounds; 2000 Pounds; 1200 Pounds; 1400 Pounds

2011: 1500 Pounds; 110 Gallons; 600 Pounds; 800 Pounds; 1200 Pounds; 2000 Pounds; 860 Pounds; 450 Pounds; 660 Pounds; 2010 Pounds
2012: 600 Pounds; 800 Pounds; 400 Pounds; 900 Pounds; 1600 Pounds; 400 Pounds; 800 Pounds; 850 Pounds; 800 Pounds; 430 Pounds; 900 Pounds; 400 Pounds; 1200 Pounds
2013: 165 Gallons; 900 Pounds; 700 Pounds; 804 Pounds; 1107 Pounds; 450 Pounds; 900 Pounds; 800 Pounds; 1200 Pounds; 800 Pounds; 1200 Pounds; 1200 Pounds
2014: 900 Pounds; 1400 Pounds; 900 Pounds; 1200 Pounds; 1200 Pounds; 900 Pounds; 800 Pounds; 1200 Pounds; 1600 Pounds; 1600 Pounds; 1500 Pounds; 800 Pounds; 1200 Pounds
2015: 2000 Pounds; 900 Pounds; 900 Pounds; 800 Pounds; 1600 Pounds; 1600 Pounds; 800 Pounds; 1200 Pounds; 1200 Pounds; 900 Pounds; 900 Pounds; 900 Pounds; 1200 Pounds; 1200 Pounds
2016: 826 Pounds; 2100 Pounds; 1800 Pounds; 2100 Pounds; 1200 Pounds; 2000 Pounds; 1300 Pounds; 1800 Pounds; 1260 Pounds; 1200 Pounds; 3200 Pounds; 1600 Pounds; 2000 Pounds
2017: 2100 Pounds; 1750 Pounds; 1050 Pounds; 1800 Pounds; 2160 Pounds; 1950 Pounds; 2100 Pounds; 2200 Pounds; 1800 Pounds; 1750 Pounds; 2100 Pounds; 1400 Pounds; 1400 Pounds
2018: 1050 Pounds; 210 Pounds; 1750 Pounds; 1750 Pounds; 1400 Pounds; 1800 Pounds; 1750 Pounds; 1750 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
P010: (7778-39-4) Arsenic acid H3AsO4
P012: (1327-53-3) Arsenic oxide As2 O3

Waste Amounts By Year:

2010: 2 Pounds

Manifest Information

Waste Code(s):

U154: (67-56-1) Methanol (I)

Waste Amounts By Year:

1998: 55 Gallons

Manifest Information

Waste Code(s):

U196: (110-86-1) Pyridine

Waste Amounts By Year:

2001: 2 Gallons

Manifest Information

Waste Code(s):

U239: (1330-20-7) Benzene, dimethyl-(I)

Waste Amounts By Year:

2002: 20 Gallons
2011: 40 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2016: 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)
D010: SELENIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)
D013: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER) (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 600 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D010: SELENIUM (Waste Code Description from EPA Hazardous Waste Identification)
U204: (7783-00-8) Selenious acid

Waste Amounts By Year:

2012: 7 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2011: 200 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1991: 10 Pounds
1999: 1 Gallons; 1 Gallons
2001: 2 Pounds
2002: 10 Pounds
2009: 2 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P098: (151-50-8) Potassium cyanide
P106: (143-33-9) Sodium cyanide

Waste Amounts By Year:

2010: 3 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)
D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)
D006: CADMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 40 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
D024: M-CRESOL (Waste Code Description from EPA Hazardous Waste Identification)
D038: PYRIDINE (Waste Code Description from EPA Hazardous Waste Identification)
U003: (75-05-8) Acetonitrile (I,T)

Waste Amounts By Year:

2010: 175 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
U002: (67-64-1) 2-Propanone (I)
U003: (75-05-8) Acetonitrile (I,T)
U031: (71-36-3) 1-Butanol (I)

Waste Amounts By Year:

2010: 200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
U044: (67-66-3) Methane, trichloro-
U122: (50-00-0) Formaldehyde

Waste Amounts By Year:

2016: 75 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D035: METHYL ETHYL KETONE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)
U154: (67-56-1) Methanol (I)

Waste Amounts By Year:

2008: 200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2010: 2090 Pounds; 1254 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)
D010: SELENIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)
D013: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER) (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2016: 1000 Pounds
2017: 800 Pounds; 630 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

D010: SELENIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2016: 1032 Pounds
2017: 1155 Pounds; 550 Pounds; 1400 Pounds; 640 Pounds; 1200 Pounds; 1200 Pounds; 1200 Pounds; 600 Pounds; 1400 Pounds
2018: 1320 Pounds; 2070 Pounds; 2200 Pounds; 2100 Pounds; 1360 Pounds; 1980 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2011: 4 Pounds
2012: 4 Pounds; 4 Pounds
2016: 15 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)
D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)
D010: SELENIUM (Waste Code Description from EPA Hazardous Waste Identification)
D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 2200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
U019: (71-43-2) Benzene (I,T)

Waste Amounts By Year:

2010: 5 Pounds

Manifest Information

Waste Code(s):

B007: (Wastes containing polychlorinated biphenyls (PCBs)) Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Waste Amounts By Year:

1987: 250 Pounds

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	13 of 29	S	0.10 / 538.47	662.47 / 18	BUFFALO GENERAL HOSPITAL 100 HIGH STREET BUFFALO NY 14203	NY SPILLS

Spill No:	1905674	**UST Trust:**	
Site ID:	593719	**Spill Date:**	2019-08-08 08:30:00
DER Facility ID:	543695	**Received Date:**	2019-08-19 08:30:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2019-10-30 00:00:00
Water Body:		**Create Date:**	2019-08-30 11:39:00
Class:	D4	**Update Date:**	2020-01-16 13:10:57.400000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PTDIEZ
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

""

DEC Remark:

"- Received Pump Doctor spill bucket testing report from Vince Perri via email on 8/19/19. Testing completed on 8/8/19, spill bucket failed. See 9-451320 NOV in D2. PTD 1/16/2020. Received email from Vince Perri on 12/27/19 containing spill bucket replacement and passing test records. Records dated 10/30/19. Spill closed, see D2 for records. PTD"

Material Information

OP Unit ID:	1341296	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2351155	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	2731		
Material Name:	Diesel (E-Gen)		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	
Contact Phone:	(716) 859-4597
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	14 of 29	S	0.10 / 538.47	662.47 / 18	100 HIGH ST	HMIRS

Incident County: ERIE

HMIR Incident Reports

Report No:	I-2006010653	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2005-11-02	**Report Submit Src:**	Paper
Time of Incident:	1025	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	5.2	**Mode Transport:**	Highway
Commodity Short Nm:	ORGANIC PEROXIDE TYPE E,	**Transport Phase:**	In Transit
Commodity Long Nm:	ORGANIC PEROXIDE TYPE E, LIQUID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3107	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	OVERNITE TRANSPORTATION COMPANY
Qty Released:	0.0625	**CR Street Name:**	1000 SEMMES AVENUE
Unit of Measure:	Liquid - Gallon	**CR City:**	RICHMOND
What Failed:	103	**CR State:**	VA
What Failed Desc:	Basic Material	**CR Postal Code:**	23224
How Failed Code:	305	**CR Non US State:**	
How Failed Desc:	Crushed	**CR Fed DOT ID:**	121058
Failure Cause Code:	519	**CR Hazmat Reg ID:**	051303004015LN
Failure Cause Desc:	Inadequate Blocking and Bracing	**CR Country:**	US
Ident. Markings:	STERIS - S2000	**Shipper Name:**	STERIS CORP
Cont1 Pkging Type:	Box	**Shipper Street Name:**	6100 HEISLEY RD
Cont1 Const Mat:	Fiberboard	**Shipper City:**	MENTOR
Cont1 Head Type:		**Shipper State:**	OH
Cont1 Pkg Capacity:	1.75	**Shipper Postal:**	44060
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	1.75	**Shipper Country:**	US
C1 Pkg Amt UOM:	LGA	**Shipper Waybill:**	970 525 754
Cont1 Pkg No:	15	**Ship Hazmat Reg ID:**	051705550046N
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	BUFFALO
C1 Pkg Dsign Pres.:	0	**Destination State:**	NEW YORK
C1 Dsign Press UOM:		**Destination Postal:**	14203
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Box
C1 Head Thick UOM:		**Cont2 Const Mat:**	Fiberboard or cardboard
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	Yes	**Contact Name:**	MARCIE PRAUT
Damage > 500:	No	**Contact Title:**	OS&D CLERK
Material Loss:	0	**Contact Business:**	OVERNITE
Carrier Damage:	0	**Contact Street:**	2580 KENMORE AVE
Property Damage:	0	**Contact City:**	TONAWANDA
Response Cost:	0	**Contact State:**	NY
Remediation Cost:	0	**Contact Postal:**	14150
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: OUT FOR CITY DELIVERY DISCOVERED ONE BOX CRESTED AND LEAKING DUE TO IMPROPER LOADING, BLOCKING, AND BRACING. PROPER DISPOSAL STEPS HAVE BEEN FOLLOWED.

Recommend Actions Taken: BETTER USE OF DUNNAGE TO BLOCK / BRACE LOAD

19	15 of 29	S	0.10 / 538.47	662.47 / 18	**BUFFALO GENERAL MEDICAL CENTER** **100 HIGH ST** **BUFFALO NY 14203**	AIR PERMITS

Permit ID: 914020008900009
County:
Source: Air Title V

Title V Details

Permit Type:	ATV	**Modification No:**	0
Status:	Expired	**Issue Date:**	4/13/1999
Renewal No:	0	**Exp Date:**	4/13/2004
Url Permit:			

19	16 of 29	S	0.10 / 538.47	662.47 / 18	**BUFFALO GENERAL MEDICAL CENTER** **100 HIGH ST** **BUFFALO NY 14203**	AIR PERMITS

Permit ID: 914020008900011
County:
Source: Air Permitted Facilities

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Details

Permit Type:	ASF	***Modification No:***	2
Status:	Expired	***Issue Date:***	12/30/2013
Renewal No:	0	***Exp Date:***	
Url Permit:			
Permit Type:	ASF	***Modification No:***	1
Status:	Expired	***Issue Date:***	4/5/2004
Renewal No:	0	***Exp Date:***	
Url Permit:			
Permit Type:	ASF	***Modification No:***	0
Status:	Expired	***Issue Date:***	
Renewal No:	0	***Exp Date:***	12/30/2013
Url Permit:			

19	***17 of 29***	***S***	***0.10 / 538.47***	***662.47 / 18***	***BUFFALO GENERAL MEDICAL CENTER 100 HIGH ST BUFFALO NY 14203***	***AIR PERMITS***

Permit ID:	914020008900014
County:	
Source:	Air Permitted Facilities

Facility Details

Permit Type:	ASF	***Modification No:***	0
Status:	Expired	***Issue Date:***	4/5/2004
Renewal No:	0	***Exp Date:***	1/27/2020
Url Permit:			
Permit Type:	ASF	***Modification No:***	0
Status:	Issued	***Issue Date:***	3/10/2020
Renewal No:	1	***Exp Date:***	3/9/2030
Url Permit:	https://www.dec.ny.gov/dardata/boss/afs/issued_asf.html		

19	***18 of 29***	***S***	***0.10 / 538.47***	***662.47 / 18***	***100 High St. Buffalo NY 14203***	***COOLING TOWERS***

Equip Unique ID:	8348	***Cooling Capacity:***	1400
Equipment County:	Erie	***Cool Capacity Unit:***	Tonnage
Equipment Borough:		***Commissioned Dt:***	04/01/1997
Intended Use:	Air Conditioning	***Inspection Dt:***	06/01/2022
Manufacturer:	Baltimore Air Coil		
Model:	3707-2NMX		
Bacteriological Sample Dt:	07/25/2022		
Legionella Sample Coll Dt:	06/07/2022		
Last Legionella Sample Result:	no		
Street Address:	100 High St.		
New Georeferenced Column:	100 High St. Buffalo, ny 14203 (42.900342, -78.865983)		

19	***19 of 29***	***S***	***0.10 / 538.47***	***662.47 / 18***	***100 High St. Buffalo NY 14203***	***COOLING TOWERS***

Equip Unique ID:	8350	***Cooling Capacity:***	1875
Equipment County:	Erie	***Cool Capacity Unit:***	Tonnage
Equipment Borough:		***Commissioned Dt:***	03/07/1990

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Intended Use: Air Conditioning
Manufacturer: Marley
Model: 220
Bacteriological Sample Dt: 07/25/2022
Legionella Sample Coll Dt: 06/07/2022
Last Legionella Sample Result: no
Street Address: 100 High St.
New Georeferenced Column: 100 High St.
Buffalo, ny 14203
(42.900342, -78.865983)
Inspection Dt: 06/01/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	20 of 29	S	0.10 / 538.47	662.47 / 18	100 High St. Buffalo NY 14203	COOLING TOWERS

Equip Unique ID: 8352
Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: Tower Tech
Model: TTXL-101975
Bacteriological Sample Dt: 07/25/2022
Legionella Sample Coll Dt: 05/02/2022
Last Legionella Sample Result: no
Street Address: 100 High St.
New Georeferenced Column: 100 High St.
Buffalo, ny 14203
(42.900342, -78.865983)
Cooling Capacity: 750
Cool Capacity Unit: Tonnage
Commissioned Dt: 06/24/2010
Inspection Dt: 05/02/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	21 of 29	S	0.10 / 538.47	662.47 / 18	100 High St. Buffalo NY 14203	COOLING TOWERS

Equip Unique ID: 8356
Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: Tower Tech
Model: TTXL-101975
Bacteriological Sample Dt: 07/25/2022
Legionella Sample Coll Dt: 05/02/2022
Last Legionella Sample Result: no
Street Address: 100 High St.
New Georeferenced Column: 100 High St.
Buffalo, ny 14203
(42.900342, -78.865983)
Cooling Capacity: 750
Cool Capacity Unit: Tonnage
Commissioned Dt: 06/24/2010
Inspection Dt: 05/02/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	22 of 29	S	0.10 / 538.47	662.47 / 18	100 High St. Buffalo NY 14203	COOLING TOWERS

Equip Unique ID: 8355
Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: Tower Tech
Model: TTXL-101975
Bacteriological Sample Dt: 07/25/2022
Legionella Sample Coll Dt: 05/02/2022
Last Legionella Sample Result: no
Street Address: 100 High St.
New Georeferenced Column: 100 High St.
Buffalo, ny 14203
(42.900342, -78.865983)
Cooling Capacity: 750
Cool Capacity Unit: Tonnage
Commissioned Dt: 06/24/2010
Inspection Dt: 05/02/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	23 of 29	S	0.10 / 538.47	662.47 / 18	100 High St. Buffalo NY 14203	COOLING TOWERS

Equip Unique ID: 8351
Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: Baltimore Air Coil
Model: T2-2430FCRM
Bacteriological Sample Dt: 07/25/2022
Legionella Sample Coll Dt: 06/07/2022
Last Legionella Sample Result: no
Street Address: 100 High St.
New Georeferenced Column: 100 High St.
Buffalo, ny 14203
(42.900342, -78.865983)

Cooling Capacity: 1600
Cool Capacity Unit: Tonnage
Commissioned Dt: 04/01/1983
Inspection Dt: 06/01/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	24 of 29	S	0.10 / 538.47	662.47 / 18	Kaleida Health - Buffalo General Hospital 100 High Street Buffalo NY 14203	TIER 2

Company Name: Kaleida Health
DUN Bradstreet Cd: 620301556
County: Erie
Latitude: 42.900795
Longitude: -78.865657
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	25 of 29	S	0.10 / 538.47	662.47 / 18	Kaleida Health - Buffalo General Hospital 100 High Street Buffalo NY 14203	TIER 2

Company Name: Kaleida Health
DUN Bradstreet Cd:
County: Erie
Latitude: 42.900795
Longitude: -78.865657
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	26 of 29	S	0.10 / 538.47	662.47 / 18	HOSPITAL 100 HIGH ST BUFFALO NY	LST

Spill No: 2203688
Site ID: 639802
DER Facility ID: 586020
CID:
Program Type: ER
SWIS Code: 1502
Contribute Factor: Tank Test Failure
Water Body:
Class: C4
Meets Std: False
Penalty: False
County: Erie
Referred to:
Reported by: Other
Source: Institutional, Educational, Gov., Other

REM Phase: 0
UST Trust: False
Spill Date: 2022-07-27 15:30:00
Rcvd Date: 2022-07-27 17:14:00
CAC Date:
Insp Date:
Close Date: 2022-07-28 00:00:00
Create Date: 2022-07-27 17:16:00
Update Date: 2022-07-28 09:27:14.417000000
DEC Region: 9
Lead DEC: TDJOHNSO
After Hours: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"REPORTED FAILED TANK TEST-NO DISCHARGE OF PRODUCT"

Dec Remark:

"07/28/22 TDJ SMALL AMOUNT OF FUEL OIL FROM TANK TEST FAILURE. THIS FUEL WILL BE TRANSFERRED TO ANOTER TANK ONSITE AND ANY FURTHER WORK WILL BE NOTED UNDER OPEN SPILL #2203342. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1386854	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2401747	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	JAMES BORTZ
Spiller Company:	CALIDA HEALTH
Spiller Address:	100 HIGH ST
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JAMES BORTZ
Contact Phone:	(716) 861-6461
Contact Ext:	
Latitude:	
Longitude:	

19	27 of 29	S	0.10 / 538.47	662.47 / 18	**BUFFALO GENERAL HOSPITAL** **100 HIGH ST** **BUFFALO NY**	NY SPILLS

Spill No:	2203342	**UST Trust:**	
Site ID:	639447	**Spill Date:**	2022-07-12 12:00:00
DER Facility ID:	586020	**Received Date:**	2022-07-18 13:15:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	
Water Body:		**Create Date:**	2022-07-18 14:07:00
Class:		**Update Date:**	2023-01-04 07:47:08.587000000
Meets Std:	False	**DEC Region:**	9
Penalty:		**Lead DEC:**	FXGALLEG
REM Phase:	1	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	DEC		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"9-451320 While Leak Detection Systems was conducting a tightness test, they found that multiple tank top fittings were not tight and therefore a vacuum test would not be possible until those fittings are repaired. tanks affected include tanks 1 south & 2 north both 26k gal #4 fuel oil."

DEC Remark:

"7/27/22 The Pump Doctor Nicholas Ball provided an update: attached testing report from Leak Detection Systems for the tightness test on UST's 1 and 2 performed on 07/26/2022 at Buffalo General Hospital PBS# 9-451320. As you can see tank 1 passed the test but tank 2 failed indicating a leak from the bottom of the tank, so we will need to open a spill number for this location. The Pump Doctor, Inc. 2706 Hemlock Road Eden, NY 14057 716-992-3181 (phone) 716-992-3186 (fax) 7/27/22 James Bortz with Kaleida Health 716-861-6461 called another spill report in for the same failed tank 2203688. 2203688 has been closed as a duplicate. Mr. Bortz has moved the product from the failed tank to another onsite tank so it is now empty. He will let me know what he plans to do with the tank. 7/28/22 Bob Broomfield with Pinto called and said that the tank currently has 3000 gallons of #4 fuel oil in it which will be pumped out today. The tank will be cleaned out and then filled with flowable fill due to its location adjacent to the generator and foundation. 3 samples will be collected from holes drilled through the bottom of the tank for analysis. 7/29/22 Update from Nicholas Ball with the Pump Doctor: the hospital is working with Pinto Construction on pumping those tanks out and filling them in place. I'm not positive if we will be further involved or not but if you need any information from them, you can reach Bob at rbroomfield@pintocs.com, Cell (716) 622-8412, Office (716) 825-6666. 8/5/22 Pinto submitted a tank closure report. FG provided the following comments: Bob, Thank you for the submission of the workplan for the closure in place of the 26000 gallon fuel oil tank located at Buffalo General Hospital. I have the following comments: You need to collect 5 excavation samples. One from each sidewall and a bottom sample. Those samples must be analyzed for 8260 and 8270 STARS list. You need to confirm that the entire system will be removed/filled (piping in addition to the tank). And, you need to submit a closure report including the disposal receipts, a site map with sampling locations, and the analytical results. Patrick Diez and Veronica Kreutzer will also review the workplan and may provide additional comments next week. Please submit a revised workplan 8/8/22 Pinto submitted a revised workplan with the requested changes. They will notify the Department when work begins. 10/11/22 Bob Broomfield provided the closure report. The excavation samples all had extremely elevated levels of toluene with very elevated detection limits for all other 8260 STARS list analytes. The closure report provided all disposal receipts. FG met Bob Broomfield on site to decide on additional sampling locations surrounding the filled in place tank. 4 locations around the ust were chosen. Mr. Broomfield will provide a workplan for Department approval. 11/21/22 FG requested an update on the sampling plan status. 12/27/22 Bob Broomfield said he would notify the Department in the next several days if he will be able to provide a workplan to complete the subsurface investigation. 1/2/23 Bob Broomfield provided a sampling plan. The Department requested a resubmission to include a sampling plan, discreet sample collection, continuous sampling until no contamination identified, clarification of sampling method."

Material Information

OP Unit ID:	1386497	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2401267	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0002A		
Material Name:	#4 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	buffalo general hospital
Spiller Address:	100 high st
Spiller City:	buffalo
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	28 of 29	S	0.10 / 538.47	662.47 / 18	Kaleida Health - Buffalo General Hospital 100 High Street Buffalo NY NY	TIER 2

Company Name:	Kaleida Health
DUN Bradstreet Cd:	620301556

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County: Erie
Latitude: 42.900795
Longitude: -78.865657
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	29 of 29	S	0.10 / 538.47	662.47 / 18	Kaleida Health - Buffalo General Hospital 100 High Street Buffalo NY Erie	TIER 2

Company Name: Kaleida Health
DUN Bradstreet Cd: 620301556
County: NY
Latitude: 42.900795
Longitude: -78.865657
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	1 of 2	WSW	0.11 / 586.54	655.91 / 11	NIAGARA MOHAWK TRANSFORME 1031 MAIN STREET BUFFALO NY	NY SPILLS

Spill No: 9406282
Site ID: 310372
DER Facility ID: 250524
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: C3
Meets Std: True
Penalty: False
REM Phase: 0
UST Trust: False
Spill Date: 1994-08-08 18:00:00
Received Date: 1994-08-08 20:20:00
CAC Date: 1994-09-07 00:00:00
Insp Date: 1994-08-10 00:00:00
Close Date: 1994-09-07 00:00:00
Create Date: 1994-08-09 00:00:00
Update Date: 1994-10-17 00:00:00
DEC Region: 9
Lead DEC: SORGI
After Hours: True
County: Erie
Contributing Factor: Human Error
Reported by: Affected Persons
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"ADF EXCAVATED SECONDARY LINE. PULLED ON CABLES - RIPPED BUSHING FROM TRANSFORMER"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 08/10/94: MJS SITE INSPECT. CLEANUP SATISFACTORY. NO FURTHER ACTION REQUIRED. 09/14/94: RECEIVED ANALYTICAL RESULTS AND DISPOSAL RECEIPT. DEBRIS DISPOSED AT LAKEVIEW LANDFILL. NO FRUTHER ACTION REQUIRED. MJS CLOSE FILE. "

Material Information

OP Unit ID: 1000433
OU: 01
Material ID: 379331
CAS No:
Material Family: Petroleum
Quantity: 4.00
Units: G
Recovered: 4.00
Med Soil: True
Med Air: False
Material Code: 0016A
Material Name: non PCB oil
Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	1000433	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	379332	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	
Spiller Company:	ADF CONSTRUCTION COMPANY
Spiller Address:	455 COMMERCE DRIVE
Spiller City:	AMHERST
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901934550
Longitude:	-78.869052190

20	2 of 2	WSW	0.11 / 586.54	655.91 / 11	PARKING LOT 1031 MAIN STREET BUFFALO NY	NY SPILLS

Spill No:	1311101	**UST Trust:**	
Site ID:	491984	**Spill Date:**	2014-02-25 09:00:00
DER Facility ID:	250524	**Received Date:**	2014-02-25 10:00:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2016-10-11 00:00:00
Water Body:		**Create Date:**	2014-02-25 10:34:00
Class:		**Update Date:**	2016-10-11 10:57:18.043000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"During Phase II study elevated levels of contaminants were found in soil borings. Report will be submitted when complete."

DEC Remark:

"During Phase II work soil borings found Benzene at levells above restricted use levels. Brownfield site is adjacent to property which had contamination which may have led to elevated levels. 06/02/15 TDJ RECEIVED PHASE II REPORT SHOWING BORING LOGS AND SOIL SAMPLING RESULTS. BENZENE WAS FOUND AT DEPTHS BELOW 30' ABOVE CP-51 LIMITS. 11/30/15 TDJ SPOKE WITH JOE DORETY OF FISHER ASSOC. WHO WILL TELL THE STATE REPS. WHO OWN SITE THAT DEC REQUIRES GW SAMPLING TO DETERMINE CLASS OF SITE. 10/11/16 TDJ SPOKE WITH JOE DORETY WHOM SPOKE WITH OWNERS OF PROPERTY ABOUT STATUS OF SITE. OWNERS AGREED ALONG WITH DEC SITE MANAGER THAT AN INACTIVE STATUS OF THE SITE IS ACCEPTABLE. LETTER WILL BE SENT TO OWNER FOR INACTIVE STAUS AND NO FURTHER WORK. NO FURTEHR WORK SITE CLOSED AS INACTIVE"

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City:
Spiller State:
Spiller Zip:
Spiller Country:
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.902001479
Longitude: -78.868476803

21	1 of 5	SW	0.11 / 594.21	660.50 / 16	PATH-BIO-RESEARCH LABORATORY 50 HIGH ST BUFFALO NY 14203-1008	RCRA NON GEN

EPA Handler ID: NYD982179434
Gen Status Universe: No Report
Contact Name:
Contact Address: 50, HIGH ST, BUFFALO, NY, 14203, US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 42.900358
Location Longitude: -78.867438

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: PATH-BIO-RESEARCH LABORATORY
Source Type: Implementer
Federal Waste Generator Code: N

Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: PATH-BIO-RESEARCH LABORATORY
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990708
Handler Name: PATH-BIO-RESEARCH LABORATORY
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19870309
Handler Name: PATH-BIO-RESEARCH LABORATORY
Source Type: Notification
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: CHESHIRE MANAGEMENT
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country:
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: CHESHIRE MANAGEMENT
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Operator
Type: Private
Name: CHESHIRE MANAGEMENT
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Historical Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 19870309
Generator Code Description: Small Quantity Generator
Handler Name: PATH-BIO-RESEARCH LABORATORY

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: PATH-BIO-RESEARCH LABORATORY

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: PATH-BIO-RESEARCH LABORATORY

---

21 | **2 of 5** | **SW** | **0.11 / 594.21** | **660.50 / 16** | **KALEIDA HEALTH 50 HIGH STREET BUFFALO NY** | **NY SPILLS**

Spill No: 1201711
Site ID: 464436
DER Facility ID: 335065
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: C3
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Other
Reported by: DEC
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 2012-05-01 12:00:00
Received Date: 2012-05-15 12:00:00
CAC Date:
Insp Date:
Close Date: 2012-08-24 00:00:00
Create Date: 2012-05-22 11:17:00
Update Date: 2012-08-24 10:39:06.450000000
DEC Region: 9
Lead DEC: jswalia
After Hours: False

Caller Remark:

"another Spill for the eastern portion of the property covered under Spill #9500234 is being created to separate the two spill sites."

DEC Remark:

"05/22/12 JSW/File. As per request from C&S Companies (letter dated 5/15/2012), the spill # 9500234 was split into two spills. The spill #9500234 will pertain to the western portion of the block and would be addressed under the BCP site # C915260. The eastern portion of the block (830 Ellicott Street and 40 High Street) is the intended location of Kaleida's new WCHOB. The eastern portion of the block also known as 50 High Street would be the property of spill # 1201711. 08/24/12 JSW/File: This following reports and sampling data were reviewed: • Phase I Report, dated March 2011 and Phase II Investigation Report, dated August 2011, for 50 High Street property, both prepared by American Consulting Professionals • Site Monitoring Report for Spill # 9500234, dated March, 2012, prepared by Groundwater and Environmental Services • Soil Borings Results - April 2012, submitted by C&S Engineers. The results show exceedances of New York State groundwater standards for VOCs and phthalates in on-site monitoring wells. However, based upon site conditions represented in the above referenced documents, the Department will not require any further work at this time. The site will have a status of "inactive". "

Material Information

OP Unit ID: 1214488
OU: 01
Material ID: 2212534
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0066A
Material Name: unknown petroleum

Med Ind Air: False
Med GW: True
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:
Spiller Company: Kaleida health
Spiller Address:
Spiller City: buffalo
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: A. KRUGER
Contact Phone:
Contact Ext:
Latitude: 42.900397375
Longitude: -78.867407134

21	3 of 5	SW	0.11 / 594.21	660.50 / 16	BUFFALO GENERAL HOSP 50 HIGH STREET BUFFALO NY	LST

Spill No: 0705382
Site ID: 385683
DER Facility ID: 335065
CID: 76
Program Type: ER
SWIS Code: 1502
Contribute Factor: Tank Failure
Water Body:
Class: D3
Meets Std: True
Penalty: False
County: Erie
Referred to: DUPLICATE OF 0705383
Reported by: Other
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: True
Spill Date: 2007-08-10 06:25:00
Rcvd Date: 2007-08-10 07:02:00
CAC Date:
Insp Date: 2007-08-10 00:00:00
Close Date: 2007-09-13 00:00:00
Create Date: 2007-08-10 07:20:00
Update Date: 2007-09-13 11:46:44.250000000
DEC Region: 9
Lead DEC: rmcrosse
After Hours: True

Caller Remark:

"25-30 GALLONS SPILL. IN PROCESS OF CONTAINMENT. FIRE DEPT O/S. "

Dec Remark:

"DUPLICATE OF 0705383"

Material Information

OP Unit ID: 1142946
OU: 01
Material ID: 2133193
CAS No:
Material Family: Petroleum
Quantity: 30.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0008
Material Name: diesel

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: DAVE HANNAHAK
Spiller Company: US FOOD SERVICE
Spiller Address: 125 GARDENVILLE PKWY
Spiller City: BUFFALO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller State: NY
Spiller Zip: 14224
Spiller Country: 001
Contact Name: LARRY SNYDER
Contact Phone: (716) 824-2245
Contact Ext:
Latitude: 42.900397375
Longitude: -78.867407134

---

21 | 4 of 5 | SW | 0.11 / 594.21 | 660.50 / 16 | TRESCO DISTRIBUTION CORPORATION
820 ELLICOTT SQUARE BLDG
BUFFALO NY 14203 | GEN MANIFEST

RCRA ID: NYD986912970
District Name: TRESCO DISTRIBUTION CORPORATION
Contact Name: RONALD DROZDOWSKI
Business Phone No: 7168568257
Mailing Street 1: 820 ELLICOTT SQUARE BLDG
Mailing Street 2:
Mailing City: BUFFALO
Mailing State: NY
Mailing ZIP: 14203
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: ERIE

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1990: 220 Gallons; 110 Gallons

Manifest Information

Waste Code(s):

U210: (127-18-4) Ethene, tetrachloro-

Waste Amounts By Year:

1990: 165 Gallons

---

21 | 5 of 5 | SW | 0.11 / 594.21 | 660.50 / 16 | CMX LABORATORIES
50 HIGH STREET
BUFFALO NY 14203 | GEN MANIFEST

RCRA ID: NYD982179434
District Name: CMX LABORATORIES
Contact Name: CMX LABORATORIES
Business Phone No: 7166897555
Mailing Street 1: 50 HIGH STREET
Mailing Street 2:
Mailing City: BUFFALO
Mailing State: NY
Mailing ZIP: 14203
Mailing ZIP Ext:
Mailing Country: USA
Location ZIP Ext:
Location Country: USA
Location County: ERIE

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1988: 110 Gallons

1992: 25 Gallons

Manifest Information

Waste Code(s):

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

1987: 70 Gallons

---

22 | ***1 of 1*** | ***E*** | ***0.11 / 597.94*** | ***666.40 / 22*** | ***TRANSFORMER PAD MOUNT 24R FOSDICK AVE BUFFALO NY*** | ***NY SPILLS***

Spill No:	1503405	***UST Trust:***	False
Site ID:	509707	***Spill Date:***	2015-06-26 18:40:00
DER Facility ID:	464325	***Received Date:***	2015-06-26 20:22:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2015-06-29 00:00:00
Water Body:		***Create Date:***	2015-06-26 20:25:00
Class:		***Update Date:***	2015-06-29 09:12:00.797000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	TDJOHNSO
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Traffic Accident		
Reported by:	Responsible Party		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Spilled to the soil around the pad. Cleanup pending OpTech arrival."

DEC Remark:

"06/29/15 TDJ MINOR SPILL OF NON-PCB OIL CLEANED BY CONTRACTOR NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1258987	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2262222	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0016A		
Material Name:	non PCB oil		

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	24R FOSDICK AVE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA MONTESANO
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	1 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 10 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	169910
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:04 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2020-12-04	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901008
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863625
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	2 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 6 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	169908
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:04 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2020-12-04	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Type:		**Latitude:**	42.901003
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863841
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	3 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 3 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	169909
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:05 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2020-12-04	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.900863
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.86391
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	4 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 5 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	181843
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:05 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.900856
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863837
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	5 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 4 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	181846
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:03 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.90086
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863637
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	6 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 9 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	181848
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:03 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901006
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863905
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	7 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 7 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	181847
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:03 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901007
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863771
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	8 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 1 134 High St Buffalo NY 14203	ALT FUELS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fuel Type Code:	ELEC: Electric	**ID:**	181845
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:03 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.90086
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863704
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	9 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 8 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	181849
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:03 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.901008
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863697
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	10 of 10	SSE	0.12 / 610.22	665.84 / 21	854ELLICOTT 134 HIGH ST 2 134 High St Buffalo NY 14203	ALT FUELS

Fuel Type Code:	ELEC: Electric	**ID:**	181844
Station Phone:	888-758-4389	**Updated at:**	2023-01-02 23:27:03 UTC
Expected Date:		**CNG Dispenser No:**	
BD Blends:		**CNG Site Renew Src:**	
NG Fill Type Code:		**CNG Tot Compr Cap:**	
NG PSI:		**CNG Storage Cap:**	
Federal Agency ID:		**CNG Fill Type Code:**	
Open Date:	2021-01-27	**CNG PSI:**	
NG Vehicle Class:		**CNG Vehicle Class:**	
LPG Primary:		**LNG Site Renew Src:**	
E85 Blender Pump:		**LNG Vehicle Class:**	
NG Fill Type Desc:		**LPG Nozzle Types:**	
Hydrogen is Retail:		**Hydrogen Pressures:**	
Federal Agency:		**Hydrogen Standards:**	
Facility Type:		**Latitude:**	42.900864
Dt Last Confirmed:	2023-01-02	**Longitude:**	-78.863776
Restricted Access:			
Fed Agency Name:			
Hydrogen Status Link:			
Status:	Open: The station is open.		
Owner Type Desc:			
E85 Blender Pump Desc:			
NG Vehicle Class Desc:			
Geocode Status Desc:	The location is from a real GPS readout at the station.		
LPG Primary Desc:			
E85 Other Ethanol Blends:			
EV Pricing:			
EV Pricing French:			
EV on Site Renewable Source:			
Intersection Directions:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	1 of 1	ENE	0.12 / 616.23	639.74 / -5	Michigan-Best Development 1145 Michigan Avenue Buffalo NY 14209	BROWNFIELDS

Site Code:	617382
HW Code:	C915375
Program:	BCP
Site Class:	A
Site Name:	Michigan-Best Development
Site Address:	1145 Michigan Avenue
City:	Buffalo
Zip:	14209
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.904319444
Longitude:	-78.862152778
SWIS:	1502
Acres:	0.736
Record Added:	2021-03-24 09:57:00
Record Update:	2022-12-29 13:43:00
Updated by:	AECAPRIO
Site Code (Web):	C915375
Program Type (Web):	BCP
Site Name (Web):	Michigan-Best Development
Site Class (Web):	A
Address1 (Web):	1145 Michigan Avenue
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209

County (Web):	Erie
Longitude (Web):	-78.862152778
Latitude (Web):	42.904319444
Site Code (GIS):	C915375
Site Name (GIS):	Michigan-Best Development
Program (GIS):	BCP
Site Class (GIS):	A
Address1 (GIS):	1145 Michigan Avenue
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14209
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.
Assess DOH:	Remedial actions taken at the site have eliminated the potential for contact with contaminated soil. The area is served by a public water source and as per local code, all water use must be from the public water mains.

Description:

Location: The Michigan-Best Development site is an approximately 0.736-acre site located in a highly developed residential/commercial area on the northeast corner of Michigan Avenue and Best Street in the City of Buffalo, Erie County. The site is bordered by Edna Place to the north, Michigan Avenue to the west, Best Street to the south and residential and vacant properties to the east. Site Features: The site consists of one vacant lot that historically had residential and/or commercial structures. The site surface generally consists of a mixed vegetative cover with grass, brush, and small trees. The site is currently being developed into multi-family residential housing. Zoning and Land Use: The current zoning for the site and the adjacent properties is N-2R, which is Residential (predominantly residential area with a variety of housing options, occasional civic structures, and mixed-use buildings on corner lots). The site is currently vacant. Planned reuse of the site as a residential development is consistent with the City of Buffalo zoning for the area. Past Use of the Site: Prior to a recent parcel consolidation, the site formerly included seven vacant lots that were developed with several former residential and commercial buildings. Portions of site were historically used for automotive repair purposes from at least 1919 through at least 1930. Additional on-site commercial operations were identified as a beauty shop, storefronts, and a restaurant. A previous investigation identified fill material underlying the site impacted by semi-volatile organic compounds (SVOCs) and metals exceeding 6 NYCRR Part 375 Soil Cleanup Objectives (SCOs). Site Geology and Hydrogeology: The site is located within the Lake Erie-Niagara River major drainage basin, which is typified by little topographic relief that gently slopes westward towards Lake Erie and the Niagara River, except in the immediate vicinity of major drainage ways. According to the United States Department of Agriculture (USDA) Web soil survey, site soils are characterized as Urban Land-Odessa Complex (Ut) and Urban Land-Colonie Complex (UnB). Soils within the City of Buffalo are characterized as urban land (Ud) with surface covered by asphalt, concrete, buildings, or other impervious structures, typical of an urban environment. The Urban Land-Odessa Complex is described as gently sloping areas of urban land and silty/clayey, somewhat poorly drained Odessa soils. The Urban Land-Colonie complex is described as gently sloping areas of urban land and sandy, somewhat excessively drained to well drained Colonie soils. The subsurface conditions of the site consist of varying types of fill materials ranging in depth from 0 to 7 feet below ground surface (fbgs). Fill materials were found at all test pit locations with the exception of TP-6 and TP-14. Native soil was encountered and consists of reddish brown sandy lean clay at depths ranging from 2 to 7 fbgs. Native soils were encountered at shallower depths in the north and western portions of the site. Native soils elsewhere on the site, averaged 4 to 5 fbgs. Regional groundwater flows in the northwesterly direction, consistent with topography in the vicinity of the site.

Assessment:

The Remedial Investigation (RI) was conducted in 2021 and included sampling of surface soil, subsurface soil/fill, groundwater, and soil vapor. The data collected during the RI identified metals, volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), herbicides/pesticides and emerging contaminants above unrestricted soil clean up objectives (USCOs) as follows. Surface soils: Surface soils were sampled from 0-2 inches bgs and analyzed for SVOCs, metals, PCBs, herbicides/pesticides, and emerging contaminants. SVOCs detected in surface soil samples included benzo(a) anthracene at concentrations up to 1.8 parts per million (ppm) (USCO 1 ppm), benzo(a)pyrene at concentrations up to 1.8 ppm (USCO 1 ppm), benzo(b) fluoranthene at concentrations up to 2.4 ppm (USCO 1 ppm), benzo(k)fluoranthene at concentrations up to 0.82 ppm (USCO 0.8 ppm), chrysene at concentrations up to 1.8 ppm (USCO 1 ppm) and indeno(1,2,3-cd)pyrene at concentrations up to 1.3 ppm (USCO 0.5 ppm). Metals detected in surface soil samples included lead at concentrations up to 708 ppm (USCO 63 ppm), mercury at concentrations up to 0.182 ppm (USCO 0.18 ppm) and zinc at concentrations up to 399 ppm (USCO 109 ppm). Total PCBs were detected at concentrations below its USCO of 0.1 ppm at all surface soil locations. The emerging contaminant perfluorooctanesulfonic acid (PFOS) was detected in surface soil samples at concentrations up to 3.06 ppm (USCO 0.88 ppm). Pesticides and herbicides detected in surface soil samples include 4,4'-DDD at concentrations up to 0.0174 ppm (USCO 0.0033 ppm), 4,4'-DDE at concentrations up to 0.257 ppm (USCO 0.0033 ppm), 4,4-DDT at concentrations up to 0.199 ppm (USCO 0.0033 ppm) and dieldrin at concentrations up to 0.0118 ppm (USCO 0.005 ppm). Subsurface soils: Subsurface samples were analyzed for VOCs, SVOCs, metals, herbicides/pesticides, PCBs and emergent contaminants. There were no exceedances of USCOs for PCBs identified in these samples. The VOC acetone was detected at up to 0.1 ppm (USCO 0.5 ppm) in surface soil samples. SVOCs detected in subsurface samples included benzo(a)anthracene at concentrations up to 1.8 ppm (USCO 1 ppm), benzo(a)pyrene at concentrations up to 1.3 ppm (USCO 1 ppm), benzo(b)fluoranthene at concentrations up to 1.6 ppm (USCO 1 ppm), chrysene at concentrations up to 1.7 ppm (USCO 1 ppm) and indeno(1,2,3-cd)pyrene at concentrations up to 0.79 ppm (USCO 0.5 ppm). Metals detected in subsurface soil included arsenic at 19.2 ppm (USCO), barium at 353 ppm (USCO), copper at concentrations up to 551 ppm (USCO 50 ppm), lead at concentrations up to 57,100 ppm (USCO 63 ppm), mercury at concentrations up to 1.77 ppm (USCO 0.18 ppm), nickel at concentrations up to 61.8 ppm (USCO 30 ppm) and zinc at concentrations up to 4,330 ppm (USCO 109 ppm). Pesticides/herbicides detected in subsurface soil included 4,4'-DDD at concentrations up to 0.0327 ppm (USCO 0.0033 ppm), 4,4'-DDE at concentrations up to 0.0643 ppm (USCO 0.0033 ppm) and 4,4'-DDT at concentrations up to 0.0089 ppm (USCO 0.0033 ppm). Emerging contaminants detected in subsurface soil included perfluorooctanoic acid (PFOA) at concentrations up to 0.661 ppm (USCO 0.66 ppm) and perfluorooctanesulfonic acid (PFOS) at concentrations up to 1.76 ppm (USCO 0.88 ppm). Groundwater: Groundwater samples were analyzed for VOCs, SVOCs, metals, pesticides/herbicides, PCBs, and emergent contaminants. Samples were evaluated against the NYS Groundwater Quality Standards (GWQS). No exceedances of GWQS for VOCs, herbicides/pesticides,

emerging contaminants, or PCBs were identified. SVOCs detected in groundwater included benzo(a)pyrene at concentrations up to 0.02 ppt (GWQS ND), benzo(b)fluoranthene at concentrations up to 0.02 ppt (GWQS 0.002 ppt), benzo(k)fluoranthene at concentrations up to 0.01 ppt (GWQS 0.002 ppt), chrysene at concentrations up to 0.01 ppt (GWQS 0.002 ppt) and indeno(1,2,3-cd)pyrene at concentrations up to 0.03 ppt (GWQS 0.002 ppt). Metals detected above GWQS included antimony at 5.55 ppt (GWQS 3 ppt). Naturally occurring metals were also detected in groundwater including magnesium at concentrations up to 50,200 ppt (GWQS 35,000 ppt) and sodium at concentrations up to 656,000 ppt (GWQS 20,000 ppt). These metals are naturally occurring minerals and are not considered contaminants of concern for this site. Soil Vapor: Soil vapor studies included the collection and testing of soil vapor samples from two locations within the site boundary. Samples were analyzed for VOCs. Soil vapor sampling results did not indicate a level of concern for potential soil vapor intrusion. The subsequent IRM excavation removed all impacted soil and fill materials on-site. Laboratory analysis of post-excavation samples concluded that within the site boundary, unrestricted SCOs have been achieved and no potential future environmental impacts are presented by the site following the IRM excavation of impacted soil/fill material.

Materials Information

Waste Name: antimony
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DDE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(k)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: zinc
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DDT
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DDD
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: NNN
Owner Name: Dr. Fadi Dagher
Owner Company: Michigan & Best LLC
Owner Street: 50 lakefront Blvd.
Owner Street 2: Suite 103
Owner City: buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name:
Owner Company: Buffalo & Erie County Library-Frank E. Merriweather JrBranch
Owner Street: 1324 Jefferson Avenue
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14208
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Dr. Fadi Dagher
Owner Company: Michigan & Best LLC
Owner Street: 50 Lakefront Boulevard, Suite 103
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: AECAPRIO

Record Added: 2021-08-31 13:19:00
Record Updated: 2022-12-21 14:24:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Environmental Remediation

Operable Unit: 01
Contaminants: DDD, DDE, DDT, antimony, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, indeno(1,2,3-cd)pyrene, lead, mercury, zinc

Operable Unit: 01A
Contaminants: DDD, DDE, DDT, antimony, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, indeno(1,2,3-cd)pyrene, lead, mercury, zinc

Operable Unit: 00
Contaminants: DDD, DDE, DDT, antimony, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, indeno(1,2,3-cd)pyrene, lead, mercury, zinc

25	1 of 6	WSW	0.12 / 620.50	658.01 / 14	ERIE CO PUBLIC HEALTH LAB 1021 MAIN ST - 5TH FL BUFFALO NY 14203	RCRA NON GEN

EPA Handler ID: NYD986985448
Gen Status Universe: No Report
Contact Name:
Contact Address: 1021, MAIN ST - 5TH FL, BUFFALO, NY, 14203, US

Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	
Receive Date:	20070101
Location Latitude:	42.901573
Location Longitude:	-78.868781

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19911010
Handler Name:	ERIE CO PUBLIC HEALTH LAB
Source Type:	Notification
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Waste Code Details

Hazardous Waste Code:	F003
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19990708
Handler Name:	ERIE CO PUBLIC HEALTH LAB
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20070101
Handler Name: ERIE CO PUBLIC HEALTH LAB
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20060101
Handler Name: ERIE CO PUBLIC HEALTH LAB
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20000222
Handler Name: ERIE CO PUBLIC HEALTH LAB
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: County
Name: ERIE COUNTY
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: NY
Country:
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: County
Name: ERIE COUNTY
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: NY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Operator
Type: County
Name: ERIE COUNTY
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: NY
Country: US
Zip Code: 99999

Historical Handler Details

Receive Dt: 20000222
Generator Code Description: Not a Generator, Verified
Handler Name: ERIE CO PUBLIC HEALTH LAB

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: ERIE CO PUBLIC HEALTH LAB

Receive Dt: 19911010

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Large Quantity Generator
Handler Name: ERIE CO PUBLIC HEALTH LAB

Receive Dt: 19990708
Generator Code Description: Not a Generator, Verified
Handler Name: ERIE CO PUBLIC HEALTH LAB

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	2 of 6	WSW	0.12 / 620.50	658.01 / 14	RESEARCH INSTITUTE ADDICTIONS 1021 MAIN ST BUFFALO NY 14203-1016	RCRA VSQG

EPA Handler ID: NYD982722076
Gen Status Universe: VSG
Contact Name: JAMES KRYGIER
Contact Address: 1021, MAIN ST, BUFFALO, NY, 14203-1016, US
Contact Phone No and Ext: 716-887-2590
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: State
Receive Date: 20070101
Location Latitude: 42.888601
Location Longitude: -78.87342

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: RESEARCH INSTITUTE ADDICTIONS
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20000523
Handler Name: RESEARCH INSTITUTE ADDICTIONS

Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: RESEARCH INSTITUTE ADDICTIONS
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1

Receive Date:	19990708
Handler Name:	RESEARCH INSTITUTE ADDICTIONS
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	State	**Street 1:**	STATE UNIVERSITY PLZ
Name:	STATE UNIVERSITY OF NEW YORK	**Street 2:**	
Date Became Current:		**City:**	ALBANY
Date Ended Current:		**State:**	NY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	14201-1946

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	STATE UNIVERSITY PLZ
Name:	STATE UNIVERSITY OF NEW YORK	**Street 2:**	
Date Became Current:		**City:**	ALBANY
Date Ended Current:		**State:**	NY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	14201-1946

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	STATE UNIVERSITY PLZ
Name:	STATE UNIVERSITY OF NEW YORK	**Street 2:**	
Date Became Current:		**City:**	ALBANY
Date Ended Current:		**State:**	NY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	14201-1946

Historical Handler Details

Receive Dt:	20000523
Generator Code Description:	Small Quantity Generator
Handler Name:	RESEARCH INSTITUTE ADDICTIONS

Receive Dt:	20060101
Generator Code Description:	Very Small Quantity Generator
Handler Name:	RESEARCH INSTITUTE ADDICTIONS

Receive Dt:	19990708
Generator Code Description:	Not a Generator, Verified
Handler Name:	RESEARCH INSTITUTE ADDICTIONS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	3 of 6	WSW	0.12 / 620.50	658.01 / 14	PARKING LOT 1021 MAIN STREET BUFFALO NY	NY SPILLS

Spill No:	1311100	**UST Trust:**	
Site ID:	491983	**Spill Date:**	2014-02-25 08:00:00
DER Facility ID:	446944	**Received Date:**	2014-02-25 09:00:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2016-10-11 00:00:00
Water Body:		**Create Date:**	2014-02-25 10:29:00
Class:		**Update Date:**	2016-10-11 10:54:01.687000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"During Phase II work gasoline constituent was found in boring samples. Site is located near Brownfield Site where large amount of contamination had been found. Report will be submitted when work is complete."

DEC Remark:

"During Phase II study for facility expansion soil borings showed elevated levels of benzene in sample. Report will be submitted when complete 06/02/15 TDJ RECEIVED PHASE II REPORT WHICH SHOWS BORING LOGS AND SOIL SAMPLING REULTS. BENZENE WAS FOUNDABOVE CP-51 LIMITS AT DEPTHS AT 30' AND BEYOND. 11/30/15 TDJ SPOKE WITH JOE DORETY OF FISHER ASSOC. WHO STATED THAT HE WOULD TELL THE STATE REPS. WHO OWN THE SITE THAT GW SAMPLING IS REQUIRED BY SPILL TO DECIDE CLASS OF SITE. 10/11/16 TDJ SPKE WIT HJOE DORETY WHOM SPOKE WIT OWNERS OF PROPERTY AND THEY DECIDED TO MAKE SITE INACTIVE WITH CONTAMINATION IN GROUNDWATER AT 30' DEPTH. DEC AGREED TO ALLOW INACTIVE STATUS. NO FURTHER WORK. LETTER WILL BE SENT TO SITE OWNER FOR INACTIVE STATUS. NO FURTEHR ACTION FILE CLOSED AS INACTIVE."

Material Information

OP Unit ID:	1241524	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2241968	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	1038A		
Material Name:	gasoline constituent		

Spiller Information

Spiller Name:	
Spiller Company:	university of buffalo
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901653672
Longitude:	-78.869070639

25	***4 of 6***	***WSW***	***0.12 / 620.50***	***658.01 / 14***	***RESEARCH INSTITUTE ADDICTIONS 1021 MAIN ST BUFFALO NY 14203***	***GEN MANIFEST***

RCRA ID:	NYD982722078	***Mailing State:***	NY
District Name:	RESEARCH INSTITUTE ADDICTIONS	***Mailing ZIP:***	14203
Contact Name:	TONY OSWALD	***Mailing ZIP Ext:***	
Business Phone No:	7168293301	***Mailing Country:***	USA
Mailing Street 1:	1021 MAIN ST	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 30 Pounds
2018: 141 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2013: 84 Pounds
2015: 17 Pounds; 178 Pounds
2018: 50 Pounds; 70 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 6 Pounds

25	5 of 6	WSW	0.12 / 620.50	658.01 / 14	RESEARCH INSTITUTE OF ALCHOLISM 1021 MAIN STREET BUFFALO NY 14203	GEN MANIFEST

RCRA ID:	NYD982722076	***Mailing State:***	NY
District Name:	RESEARCH INSTITUTE OF ALCHOLISM	***Mailing ZIP:***	14203
Contact Name:	RESEARCH INSTITUTE OF ALCHOLISM	***Mailing ZIP Ext:***	
Business Phone No:	7168872566	***Mailing Country:***	USA
Mailing Street 1:	1021 MAIN STREET	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1989: 121 Pounds; 7 Pounds
2000: 10 Pounds; 10 Pounds; 100 Pounds; 10 Pounds; 10 Pounds; 10 Pounds
2004: 10 Pounds; 200 Pounds; 10 Pounds
2009: 65 Pounds
2010: 43 Pounds
2011: 175 Pounds

Manifest Information

Waste Code(s):

D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2004: 10 Pounds

Manifest Information

Waste Code(s):

P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2004: 10 Pounds

Manifest Information

Waste Code(s):

U031: (71-36-3) 1-Butanol (I)

Waste Amounts By Year:

2000: 200 Pounds

Manifest Information

Waste Code(s):

U170: (100-02-7) p-Nitrophenol

Waste Amounts By Year:

2000: 10 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1989: 163 Pounds
2000: 200 Pounds
2004: 10 Pounds; 10 Pounds; 10 Pounds
2006: 10 Pounds
2010: 21 Pounds; 20 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1989: 9 Pounds
2004: 10 Pounds

Manifest Information

Waste Code(s):

D007: CHROMIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 100 Pounds

Manifest Information

Waste Code(s):

U219: (62-56-6) Thiourea

Waste Amounts By Year:

2000: 100 Pounds

Manifest Information

Waste Code(s):

U154: (67-56-1) Methanol (I)

Waste Amounts By Year:

2000: 200 Pounds

Manifest Information

Waste Code(s):

U188: (108-95-2) Phenol

Waste Amounts By Year:

2004: 10 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2010: 54 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl

alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2007: 171 Pounds; 226 Pounds
2008: 182 Pounds
2009: 100 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2010: 103 Pounds

Manifest Information

Waste Code(s):

D004: ARSENIC (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2004: 10 Pounds

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 40 Pounds
2004: 75 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1989: 6 Pounds
2000: 3 Pounds

Manifest Information

Waste Code(s):

D011: SILVER (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2004: 10 Pounds

Manifest Information

Waste Code(s):

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2006: 200 Pounds

Manifest Information

Waste Code(s):

P106: (143-33-9) Sodium cyanide

Waste Amounts By Year:

2000: 5 Pounds

Manifest Information

Waste Code(s):

U002: (67-64-1) 2-Propanone (I)

Waste Amounts By Year:

2000: 200 Pounds; 200 Pounds

25	6 of 6	WSW	0.12 / 620.50	658.01 / 14	ERIE COUNTY PUBLIC HEALTH LAB 1021 MAIN ST BUFFALO NY 14203	GEN MANIFEST

RCRA ID:	NYD986985448	***Mailing State:***	NY
District Name:	ERIE COUNTY PUBLIC HEALTH LAB	***Mailing ZIP:***	14203
Contact Name:	GERHARD PALUCA	***Mailing ZIP Ext:***	
Business Phone No:	7168817295	***Mailing Country:***	USA
Mailing Street 1:	1021 MAIN ST	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 2 Gallons; 1 Gallons; 1 Gallons

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 10 Pounds; 26 Pounds

Manifest Information

Waste Code(s):

P004: (309-00-2) Aldrin

Waste Amounts By Year:

2000: 20 Gallons

Manifest Information

Waste Code(s):

P098: (151-50-8) Potassium cyanide

Waste Amounts By Year:

2000: 9 Pounds

Manifest Information

Waste Code(s):

U021: (92-87-5) Benzidine

Waste Amounts By Year:

2000: 2 Gallons

Manifest Information

Waste Code(s):

U220: (108-88-3) Benzene, methyl-

Waste Amounts By Year:

2000: 5 Gallons

Manifest Information

Waste Code(s):

F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

1999: 55 Gallons

Manifest Information

Waste Code(s):

F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

1999: 55 Gallons

Manifest Information

Waste Code(s):

P011: (1303-28-2) Arsenic oxide As2O5

Waste Amounts By Year:

2000: 200 Pounds

Manifest Information

Waste Code(s):

P105: (26628-22-8) Sodium azide

Waste Amounts By Year:

2000: 5 Pounds; 2 Pounds

Manifest Information

Waste Code(s):

U133: (302-01-2) Hydrazine (R,T)

Waste Amounts By Year:

2000: 1 Gallons

Manifest Information

Waste Code(s):

U246: (506-68-3) Cyanogen bromide (CN)Br

Waste Amounts By Year:

2000: 1 Gallons

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 7 Pounds; 1 Gallons; 1 Gallons; 20 Pounds; 20 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 1 Gallons

Manifest Information

Waste Code(s):

D005: BARIUM (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2000: 30 Pounds

26	*1 of 4*	*SE*	*0.12 / 637.81*	*668.72 / 24*	***Kaleida Health - Highpointe*** ***1023 Michigan*** ***Buffalo NY 14203***	*TIER 2*

Company Name: Kaleida health
DUN Bradstreet Cd: 064849020
County: Erie
Latitude: 42.9087047
Longitude: -78.844034
Report Method: Reported Online

26	*2 of 4*	*SE*	*0.12 / 637.81*	*668.72 / 24*	***Kaleida Health - Highpointe*** ***1023 Michigan*** ***Buffalo NY 14203***	*TIER 2*

Company Name: Kaleida health
DUN Bradstreet Cd:
County: Erie
Latitude: 42.9087047
Longitude: -78.844034
Report Method: Reported Online

26	*3 of 4*	*SE*	*0.12 / 637.81*	*668.72 / 24*	***Kaleida Health - Highpointe*** ***1023 Michigan***	*TIER 2*

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Buffalo NY NY	

Company Name: Kaleida health
DUN Bradstreet Cd: 064849020
County: Erie
Latitude: 42.9087047
Longitude: -78.844034
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
26	4 of 4	SE	0.12 / 637.81	668.72 / 24	**Kaleida Health - Highpointe** **1023 Michigan** **Buffalo NY Erie**	TIER 2

Company Name: Kaleida health
DUN Bradstreet Cd: 064849020
County: NY
Latitude: 42.9087047
Longitude: -78.844034
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	1 of 19	WSW	0.12 / 641.48	660.19 / 16	**Former Mobil Service Station 99-MST** **979 Main Street** **Buffalo NY 14203**	BROWNFIELDS

Site Code: 458395
HW Code: C915260
Program: BCP
Site Class: C
Site Name: Former Mobil Service Station 99-MST
Site Address: 979 Main Street
City: Buffalo
Zip: 14203
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.900858000
Longitude: -78.868792000
SWIS: 1502
Acres: 1.725
Record Added: 2011-11-28 14:06:00
Record Update: 2022-07-13 15:20:00
Updated by: AECAPRIO
Site Code (Web): C915260
Program Type (Web): BCP
Site Name (Web): Former Mobil Service Station 99-MST
Site Class (Web): C
Address1 (Web): 979 Main Street
Address2 (Web):
Locality (Web): Buffalo
Zip Code (Web): 14203
County (Web): Erie
Longitude (Web): -78.868792000
Latitude (Web): 42.900858000
Site Code (GIS): C915260
Site Name (GIS): Former Mobil Service Station 99-MST
Program (GIS): BCP
Site Class (GIS): C
Address1 (GIS): 979 Main Street
Address2 (GIS):
Locality (GIS): Buffalo
Zip Code (GIS): 14203
County (GIS): Erie
Site Class Desc:
Site Class Desc (Web): Complete: The classification used for sites where the Department has determined that remediation has been

satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).

Assess DOH: Measures are in place to control the potential for coming in contact with residual subsurface soil and groundwater contamination remaining on the site.

Description:

Location: The Former Mobil Service Station 99-MST site is an approximately 1.72-acre site located at 1001 Main Street (formerly 979 Main Street) in the City of Buffalo, Erie County. The site is bordered by Goodrich Street to the north, High Street to the south, a parking lot to the east and Main Street with an underground subway corridor below to the west. Site Features: This site consists of two parcels and has a medical office building and associated parking which was constructed in 2015. Current Zoning and land Use: The site is zoned for commercial use. Land use in the surrounding area is characterized as urban mixed use, primarily commercial and community services. The community services include public and private medical and hospital facilities. Past Use of the Site: Exxon/Mobil and its predecessors operated a gas station on the site from approximately 1950 to 1982. The gas station building was demolished in 1982 and four underground storage tanks (USTs) were removed between 1981 and 2007. Other previous operations at the site included an auto repair shop, University at Buffalo medical and dental departments, a restaurant and a motel. Site Geology and Hydrogeology: Overburden soils in the area consist primarily of fill material at the ground surface. Geotechnical boring logs collected from the site in 2010 indicate that fill material such as sand, gravel and bricks varies in thickness from 2 to 10 feet across the site. Soil underlying the fill is comprised of interbedded sands and silt that are brown to olive - brown in color. Overburden soils are underlain by the Onondaga Limestone (bedrock), which is at approximately 100 feet below ground surface (fbgs). The groundwater is approximately 32 fbgs and flows towards northeast.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum hydrocarbons in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in soil and groundwater is being managed under a Site Management Plan. Note: Off-site contamination in the Main Street Right-of-Way, between the subway line and sheet piles along the site border, is being managed under Spill number 9500234.

Materials Information

Waste Name: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: TOLUENE
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: NNN
Owner Name: Robert W. Bragg
Owner Company: Kaleida Health
Owner Street: 726 Exchange Street
Owner Street 2:
Owner City: Buffao
Owner State: NY

Owner Zip:	14210
Country:	United States of America
Owner Op:	06
Sub Type:	P03
Owner Name:	Malika Basheer
Owner Company:	Seavest Core Buffalo Coventus, LLC
Owner Street:	707 Westchester Avenue
Owner Street 2:	Suite 401
Owner City:	White Plains
Owner State:	NY
Owner Zip:	10604
Country:	United States of America
Owner Op:	01
Sub Type:	P03
Owner Name:	malika basheer
Owner Company:	seavest core buffalo conventus, llc
Owner Street:	707 westchester avenue
Owner Street 2:	Suite 401
Owner City:	white plains
Owner State:	NY
Owner Zip:	10604
Country:	United States of America
Owner Op:	06
Sub Type:	P03
Owner Name:	Paul Ciminelli
Owner Company:	Ciminelli Real Estate Corporation
Owner Street:	50 Fountain Plaza
Owner Street 2:	Suite 500
Owner City:	Buffalo
Owner State:	NY
Owner Zip:	14202
Country:	United States of America
Owner Op:	19
Sub Type:	NNN
Owner Name:	Reference Librarian
Owner Company:	Buffalo and Erie County Public Library
Owner Street:	1 Lafayette Square
Owner Street 2:	
Owner City:	Buffalo
Owner State:	NY
Owner Zip:	14203-1887
Country:	United States of America
Owner Op:	06
Sub Type:	P03
Owner Name:	Robert Bragg
Owner Company:	kaleida health
Owner Street:	726 exchange street
Owner Street 2:	
Owner City:	buffalo
Owner State:	NY
Owner Zip:	14210
Country:	United States of America
Owner Op:	06
Sub Type:	P03
Owner Name:	Robert bragg
Owner Company:	kaleida properties, inc.
Owner Street:	726 exchange street
Owner Street 2:	
Owner City:	buffalo
Owner State:	NY
Owner Zip:	14210
Country:	United States of America

Owner Op:	04
Sub Type:	NNN
Owner Name:	Malika Basheer
Owner Company:	Seavest Core Buffalo Coventus, LLC
Owner Street:	707 Westchester Avenue
Owner Street 2:	Suite 101
Owner City:	White Plains
Owner State:	NY
Owner Zip:	10604
Country:	United States of America

HW Extra Information

Dump:	False	**Record Added:**	2011-11-28 14:58:00
Structure:	False	**Record Updated:**	2014-12-11 15:56:00
Lagoon:	False	**Disposal Start:**	
Landfill:	False	**Disposal Terminate:**	
Pond:	False	**Latitude:**	
Dell:		**Longitude:**	
Updated By:	jswalia		

Projects Information

Project Code:	02
Project Desc:	Remedial Investigation
Project Refer Name:	
End Date:	2014-12-16 00:00:00
End Status:	ACT
Operable Unit ID:	1208514
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Investigation

Project Code:	25
Project Desc:	
Project Refer Name:	
End Date:	2014-12-23 00:00:00
End Status:	ACT
Operable Unit ID:	1208514
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Certificate of Completion

Project Code:	04
Project Desc:	Remedial Design
Project Refer Name:	IRM
End Date:	2012-12-19 00:00:00
End Status:	ACT
Operable Unit ID:	1213770
Operable Unit:	01A
Operable Unit Desc:	Excavation of Contaminated Soils:
Code Name:	Remedial Design

Project Code:	05
Project Desc:	Remedial Action
Project Refer Name:	
End Date:	2014-12-23 00:00:00
End Status:	ACT
Operable Unit ID:	1213770
Operable Unit:	01A
Operable Unit Desc:	Excavation of Contaminated Soils:
Code Name:	Remedial Action

Environmental Remediation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit: 01A
Contaminants: 1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

Operable Unit: 01
Contaminants: 1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

Operable Unit: 00
Contaminants: 1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

27	2 of 19	WSW	0.12 / 641.48	660.19 / 16	BUFFALO GENERAL HOSPITAL 999 MAIN STREET BUFFALO NY	NY SPILLS

Spill No: 9508300
Site ID: 90966
DER Facility ID: 82050
CID: 365
Program Type: ER
SWIS Code: 1502
Water Body:
Class: E5
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 1995-10-01 12:00:00
Received Date: 1995-10-05 12:00:00
CAC Date:
Insp Date:
Close Date: 1995-10-30 00:00:00
Create Date: 1995-10-06 00:00:00
Update Date: 1995-11-01 00:00:00
DEC Region: 9
Lead DEC: RMCROSSE
After Hours: False

Caller Remark:

"LETTER RECEIVED FROM TVGA NOTIFYING DEC OF DEMOLITION / CONSTRUCTION ACTIVITIES ON-SITE. NO SPILLAGE NOTED"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC RMC/FILE DUPLICATE FILE SEE 9500234 CLOSE OUT "

Material Information

OP Unit ID: 1019029
OU: 01
Material ID: 362780
CAS No:
Material Family: Other
Quantity: .00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0064A
Material Name: unknown material

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NONE
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Ext:						
Latitude:		42.900951993				
Longitude:		-78.869370023				

27	3 of 19	WSW	0.12 / 641.48	660.19 / 16	OIL AT HIGH STREET 999 MAIN AND 24 HIGH BUFFALO NY	NY SPILLS

Spill No:	9500234	**UST Trust:**	True
Site ID:	204696	**Spill Date:**	1995-04-01 12:00:00
DER Facility ID:	170158	**Received Date:**	1995-04-03 11:00:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	2006-01-16 00:00:00
SWIS Code:	1502	**Close Date:**	2015-09-15 00:00:00
Water Body:		**Create Date:**	1995-04-10 00:00:00
Class:	B2	**Update Date:**	2015-09-15 11:13:36.117000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:	BCP C915260		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"PHASE II SHOWS CONTAMINATION"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 04/07/95: RMC/SITE DEMME/PHONE. NO OVERT SOURCE NOTED , SITE WAS USE AS GAS STATION YEARS AGO, CONSULTANT TO FILE ALL REPORTS DONE W/STATE, DUE 4/30/95. 06/30/95: RMC/FILE. SPILL BEING REVIEWED BY TED UPDATE 7/21/95. . 11/1/95 RMC/FILE. BEING REVIEWED BY RNL AND PJB, UPDATE 12/1/95 01/09/96 RMC/FILE. NO DECISION BY RNL AND SAC REGARDING APPROACH, UPDATE 2/1/96 01/10/96 RMC/FILE. LETTER TO RP FROM RNL, RESPONSE DUE 1/30/96 01/26/96 RMC/RNL/CARMICHAEL/MEETING. WENT OVER REQUIRMENTS AND OPTIONS, RP PLANS TO RESAMPLE FOR TCLP, LETTER,RESULTS DUE 3/30/96 03/12/96 RMC/FILE. RECEIVED RETEST RESULTS ON BORING, DONE DIRECT NOT TCLP, RNL CONFIRED WITH CONSULTANT, CALL BACK FROM CONSULTANT WITH PRELIMINARY PLAN DUE 3/20/96 05/21/96 RMC/CARMICHAEL/PHONE. RMC INQUIRING IF RESAMPLE DONEON TCLP, MR CARMICHAEL UNAWARE THAT RESULTS NOT PERFORMED THAT WAY IN THE FIRST PLACE, HE WILL LOOK INTO AND CALL BACK, UPDATE 6/1/96 06/19/96 RMC/RNL/MEETING. REMEDIATION WILL BE REQUIRED AS FOUND FREE PRODUCT IN DRILLING, RMC TO ADVISE RP 07/01/96 RMC/FILE. LETTER ON REMEDIATION REQUIRMENTS, RESPONSE DUE 8/15/96 08/13/96 RMC/CARMICHAEL/MEETING. WENT OVER OPTIONS AND TYPE OF CONTRACTOR REQUIRED, WORK PLAN DUE 9/30/96 10/22/96 RMC/FILE. LEFT MESSAGE TO CALL, CALL DUE 11/1/96 10/24/96 RMC/FILE. RECEIVED MESSAGE THAT WORK WAS BEING PLANNED AND CONTRACTOR CHOICE WAS DUE SOON, UPDATE 11/30/96 12/26/96 RMC/FILE. CONTRACTOR CHOICE YET TO BE MADE, UPDATE 1/30/97 02/26/97 RMC/CARMICHAEL/PHONE. GOING OVER PROPOSALS, RESPONSE DUE 3/15/97 03/19/97 RMC/CARMICHAEL/PHONE. WENT OVER PROPOSALS RMC ADVISED THAT EITHER ONE IS ACCEPTABLE FOR PHASE ONE AS THEY ARE ESSENTIALLY SIMILIAR, DECISION DUE 4/15/97 06/02/97 RMC/FILE. REVEIVED REPORT FROM WELL INSTALLATION, SIGNIFICANT EXCEEDANCES IN SOIL AND WATER, TO SCHEDULE MEETING, DUE 6/30/97 06/19/97 RMC/RNL/CARMICHAEL/KERLING/MEETING. FURTHER WORK IS REQUIRD, HOSPITAL TO WAY OPTIONS, LETTER 06/25/97 RMC/FILE. RECEIVED LETTER WITH SIGNED ROE AND PHASE ONE REPORT, TO REVIEW AND HIRE CONTRACTOR. 08/25/97 RMC/COULTER,EPS/SITE. REVIEWED WORK TO DATE, DEC REQUESTED EPS TO TEST ALL WELLS FOR STARS GASOLINE PLUS 31013 AND INSTALL TWO ADDITIONAL WELLS TO THE NORTH, UPDATE 9/15/97 9/97 RMC/RNL/SITE. CHECKED TWO WELLS INSTALLED BY DEC CONTRACTOR, ONE TO THE WEST HAS 2 FEET OF PRODUCT, OTHER JUST ODOR, REQUESTED CONTRACTOR PLAN AND INSTALL ADDITIONAL WELLS TO DETERMINE SOURCE AND AREA OF IMPACT, DUE 10/30/97, REVISED TO 11/15/97 11/21/97 RMC/VREELAND/SITE. WALKED PROPERTY CHECKING AGAINST REPORT 11/24/97 RMC/RNL/MEETING. EPS REPORT REWIEW, FREE PRODUCT PLUME NEEDS BETTER DEFFINITION, AUTHORIZED 5 ADDITIONAL WELLS. UPDATE 12/30/97 12/9/97 RMC/SITE. WELL BEGAN PROBLEM WITH PLACEMENT DUE TO UTILITIES 12/10/97 RMC/COULTER/RNL/SITE. WENT OVER WELL PLACEMENT, EPS TO HAVE SURVEYED ASAP, 12/15/97 RMC/COULTER/PHONE. WELLS INSTALLED, REPORT DUE 1/15/98 02/06/97 RMC/FILE. RECEIVED AND REVIEWED REPORT FROM EPS, REVIEWED FILE, SIGNIFICANT CONTAMINATION EXISTS ON PROPERTY, ESTIMATES AT 10 TO 20K GASOILINE 30 FEET BG, SOURCE BELIEVED TO BE 979 MAIN STREET FORMER SERVICE STATION, RMC REQUESTED THE FOLLOWING FROM EPS 1. ADDITIONAL WORK TO DETERMINE PROPERTY OWNERSHIP THROUGHOUT HISTORY OF 979 MAIN. 2. COST TO DO HIGH VAC AND PUMP AND TREAT TEST. 3. COST TO INSTALL VR UNIT AND COST PER GALLON RECOVERY ON FORMER SITE, GENEVA. 4. LOOK INTO SALVAGING OLD EQUIPMENT AND COSTS FROM OLD DEC SITES. ESTIMATES DUE 2/15/98 2/06/98 RMC/THOMAS CHARMICAL, 843-7521 843-7486 FAX/PHONE. RMC UPDATED PROPERTY OWNER OF FINDINGS, PLAN TO MEET AS SOON AS WE HAVE PLAN FOR SITE, CHARMICAL REQUESTED THAT WE NOTIFY DICK KERLING AT 859-2818 THE DAY BEFORE WE WORK ON SITE. 02/17/98 RMC/FILE. RECEIVED PROPOSAL FOR HIGH VAC AND PUMP AND TREAT TEST, REVIEWED WITH RNL, TO GO WITH BOTH AND DISPOSE OF WATER WITH AIR STRIPPER AT BROADWAY AN NASH, UPDATE 2/28/98 02/23/98 RMC/WILDER/PHONE. HIGH VAC TEST UNDERWAY,INITIAL RESULTS GOOD 3/16/98 RMC/RNL/FILE. RECEIVED HIGH VAC/PUMP AND TREAT TEST REPORT. HIGH VAC APPEARS TO BE THE BEST OPTION, RMC ADVISED EPS TO GET PRICE AND PROPOSAL TOGETHER, DUE 3/30/98 03/31/98 RMC/RNL/EPS/MEETING. WENT OVER WORK

TO DATE, COVERED COSTS AND PLANS FOR REMEDIATION, RECEIVED TITLE SEARCH OF 979 MAIN, EPS BELIEVES THAT PROPERTY IS THE SOURCE, RMC TO SEND LETTER TO PRP, EPS TO SEND OUT SAMPLE OF PRODUCT TO SEE IF IT CAN BE FURTHER IDED, EPS TO INSTALL PIPING AND WELLS FOR HIGH VAC NOW AS OWNER OF LOT WANT TO PAVE IT ASAP, RMC CONTACTED BUFFALO GENERAL, CHARMICAL WANTS PLANS FOR SYSTEM AND MEETING TO DISCUSS LAYOUT OF LOT, RMC ADVISED EPS, UPDATE 5/1 05/01/98 RMC/FILE. RECEIVED LETTER FROM MOBIL ADVISING THAT THEY WERE GOING TO LOOK INTO 05/06/98 RMC/TIM MCARTELL, EPS/MEETING. OVER DRILLING OF 2 INCH WELLS AND PLACEMENT OF ADDITIONAL WELLS BEING DONE TODAY AND TOM., EPS WORKING WITH HOSPITAL ON PLACEMENT OF CURB BOXES, WELLS, PIPING AND SYSTEM, REPORT DUE 6/1/98 06/01/98 RMC/OVERHOLDT/PHONE. WORK UNDERWAY ON TRENCHES AND PIPING, EPS HAS 15 LOADS OF NON CONTAMINATED SOIL FOR FILL, MATERIAL WAS TESTED TO MAKE SURE, EPS DOES NOT HAVE A PLACE FOR IT RUSS SAVAGE HAS A HOLE AT 12866 BROADWAY WHICH NEEDS FILL, EPS AND RUSS TO WORK OUT DETAILS OF TRANSFER, RMC ALSO ASKED EPS FOR LAY OUT OF SYSTEM TO DETERMINE THE NEEDS OF A TRAILOR. UPDATE 6/20/98 06/16/98 RMC/RNL/BRIAN CARY,GES/RICHARD CICCOTELLI, MOBIL/PHONE. MOBIL YET TO MAKE A DETERMINATION, NEED OT REVIEW SPILL HISTORY, RNL ADVISED THAT DEC WORK TO CONTINUE. 09/23/98 RMC/FILE. NOTES SINCE 6/16/98 LOST IN COMPUTER PROBLEM 09/23/98 RMC/FILE. UPDATE RMC AND RNL MET SEVERAL TIMES ON SITE, IN WARSAW AND AT THE DEC OFFICE TO DISCUSS SITE, DEC AUTHORIZED EPS OT REMEDIATE SITE, TOTAL COST APPROACHES 150K INITIAL YEAR. HIGH VAC CHOOSEN METHOD, PURCHASED TWO TRAILORS TO PUT SYSTEM IN, EPS HAS UNITS 50 PERCENT COMPLETE, RMC/RNL TO INSPECT UNITS THIS WEEK, UPDATE 10/98 09/25/98 RMC/WILDER/MCARDELL/SYRACUSE OFFICE. EPS REVIEWED SPILL FILE AND COST, ON BUDGET, SYSTEM 50+ PERCENT COMPLETE, REQUESTED FEW MINOR CHANGES, UNIT TO BE SHIPPED IN TWO WEEKS, UPDATE 11/98 10/7/98 RMC/SCOTT O/EPS/PHONE. ELECTRIC IN, SOIL FROM TRENCHING OT DEAL WITH, NO ODOR, NO VISUAL CONTAMINATION NOTED,RMC ADVISED TO HAVE IT ANALYIZED PRIOR TO SHIPPIN GOUT AS FILL, UPDATE 11/98 10/22/98 RMC/SAC/MJS/EPS/SITE. ONE TRAILOR DELIVERED, NEXT ONE DUE 10/23 11/16/98: PROCESSED PAY PACKAGE-EPS NO.14 FOR $28821.27, TOTAL COST $215366.14, WORK PERIOD 10/1/98-10/30/98. 11/27/98:PROCESSED PAY PACKAGE-ENV.LAB SERV. NO.11 FOR $270.00, TOTAL COST $9180.00, WORK PERIOD 11/13/98-11/17/98. 12/1/98:PROCESSED PAY PACKAGE-ENV.LAB SERV. NO.12 FOR $1190.00, TOTAL COST $10370, WORK PERIOD 11/13/98-11/25/98. 12/14/98:PROCESSED PAYPACKAGE FROM EPS NO.15 FOR $15550.13, TOTAL COST $230,916.27, INVOICE NO.003869, WORK PERIOD IS 10/13/98- 11/25/98. 12/14/98 RMC/FILE. SEVERAL SITE VISITS, SYSTEM OPERATING FOR MONTH, REMOVED 6 TO 7 THOUSAND GALLONS PRODUCT SO FAR, REPORT DUE 12/99 12/15/98 RMC/MOBIL MEETING, RMC ADVISED THAT DEC HAS RECEIVED NO RESPONSE FROM MOBIL, RESPONSE DUE 1/99 12/28/98: PROCESSED 2 PAYPACKAGES FROM ENV. LAB SERV. NOS.13 & 14, FOR $270.OO INVOICE NO.110935, WORK PERIOD 12/1/98 - 12/4/98 & FOR $204.00 INVOICE NO. 111118, WORK PERIOD 12/8/98 - 12/22/98. 1/8/99:PROCESSED PAYPACKAGE NO. 14 FROM ENV.LAB SERV. FOR $204.00 INVOICE NO. 111175, WORK PERIOD FROM 12/16/98-12/28/98, TOTAL COST OF $11048.00. 1/15/99:PROCESSED PAYPACKAGE FROM EPS NO.16 FOR $7818.36, TOTAL COST $238734.63, WORK PERIOD 11/30/98 TO 12/29/98, INVOICE NO. 004570. 12/28/98 RMC/FILE. RECEIVED MONTHLY REPORTFOR NOVEMBER 98, REMOVED 5800 GALLONS TO DATE, IMPLEMENTED EPS RECCOMENDATIONS, NEXT REPORT DUE 1/20/98. 03/08/99 RMC/FILE. RECEIVED REPORT FOR 1/99, TOTAL PRODUCT RECOVERY TO DATE 8500 GALLONS, NEXT REPORT DUE 5/1/99 04/01/99 RMC/SITE. NOTED A FEW OPERATIONAL PROBLEMS, ADVISED EPS. 04/19/99 RMC/FILE. RECEIVED 2/99 SYSTEM REPORT 10K GALLONS RECOVERED SO FAR, NEXT ROUD DUE 5/30 05/24/99 RMC/SITE. FENCE HAS DAMAGE, REQUESTED EPS FIX, SYSTEM OPERATIONAL, RECEIVED REPROTS FOR MARCH AND APRIL 10K RECOVERED TO DATE, UPDATE 6/30 07/07/99 RMC/FILE. RECEIVED QUATERLY REPORT, 10K REMOVED TO DATE, SYSTEM OPERATING, NEXT REPORT DUE 9/30 11/4/99 RMC/RJJ/SITE. PERFORMED SITE CHECK, SYSTEM DOWN, ADVISED EPS, 11/09/99 RMC/RNL/RJJ/MOBILE MEETING. MOBIL TO PROVIDE A RESPONSE TO OUR LETTER OF 1998, DUE 12/30 11/23/99 RMC/FILE. RECEIVED QUARTERLY REPORT, RECOVERY HAS DROPPED SIGNIFICANTLY, SYSTEM OPERATIONAL PERCENTAGE IS 57%, THIS IS DUE TO CALCIFICATION OF PUMPS, RMC REQUESTED THAT EPS LOOK INTO ANOTHER TYPE OF TRANSFER PUMP WHICH IS THE WEAK LINK, ALSO RMC REQUESTED THAT THE CONTROLER BE CHANGED SO THAT THE LIQUID RING WILL START AGAIN ON LOW LOW. UPDATE 12/30 04/05/00 RMC/FILE. INSPECTED SEVERAL TIMES, SYSTEM OPERATIONAL, REPORTS ARE BEIG SUBMITTED BY CONTRACTOR, UPDATE 6/1 06/02/00 RMC/FILE. REVIEWED REPORTS, HARD WATER CONTINUES TO CAUSE A CONSTANT MAINTENCE PROBLEM, THIS HAS CAUSED SIGNIFICANT MAINTENCE COST AND DOWN TIME, RMC AUTHORIZED A SYSTEM BE INSTALLED TO ALLEVIATE THE PROBLEM, ADVISED SCOTT O, AT EPS, UPDATE 7/1 06/21/00 RMC/FILE. MOBIL MEETING, NO RESPONSE TO OUR LETTER OVER A YEAR AGO, MOBIL WILL RESPOND, RESPONSE DUE 7/30 06/28/00 RMC/FILE. RECEIVED SAMPLE RESULTS FROM WELLS, LEVELS IMPROVED, NOTE WELLS ARE RECOVERY WELLS AND SYSTEM IS RUNNING SO DATA MAY BE DIFFERENT THAN ACTUAL RESULTS, UPDATE 8/30 08/15/00 RMC/FILE. RECEIVED REPORT, SYSTEM HAS BEEN DOWN FOR REPAIRS, FIRST THE HV MOTOR, THEN THE PUMP ITSELF, LEVELS NOT IMPROVED THIS ROUND, TO DISCUSS ADDTIONAL WORK IF ANY WITH RNL AND PJB, UPDATE 9/1 09/20/00 RMC/FILE. RNL REVIEWED REPORTS TO DATE, RNL DECIDED NOT TO MODIFY SYSTEM WITH AIR SPARGE AT THIS TIME, HE WILL AGAIN REVIEW SAMPLE TRENDS IN 6 MONTHS, UPDATE 11/1/00 09/00 RMC/SAC/RNL/MEETING. TO TRANSFER SITE TO SAC. 07/02/01 SAC/FILE. REVIEWED OPERATIONAL REPORTS, EXCEEDANCES CONTINUE, SYSTEM OPERATIONAL, NOTED SPIKES IN A PERIMETER WELL, HIRED NWECC TO TRACK DOWN INFORMATION IN RESPONSE TO AG REQUEST, UPDATE 8/30/01 08/16/01 RMC/JACOB SCHU, DIRECTOR FACILITIES MANAGEMENT, KALEIDA HEALTH, 859-3465/PHONE HE IS NEW CONTACT FOR HOSPITAL, 1/24/02:SAC TELECON RANDY KLOSKO, BEARING FAILURE CAUSED PUMP TO BREAK DOWN, REPAIR WILL COST AROUND $2100 AND A NEW PUMP WOULD COST JUST OVER $4045, ALTHOUGH THIS IS THE 2ND TIME THIS HAS HAPPENED IN A LITTLE OVER A YEAR THERE IS NO GUARANTEE THAT THE NEW PUMP WOULD NOT HAVE THE SAME PROBLEM, REPAIR WILL BE DONE, MR. KLOSKO BELIEVES THE PROBLEM MAY BE BECAUSE THE CONCENTRATION OF THE GASOLINE MAY BE CAUSING A BREAKDOWN OF THE GREASE AND OIL FOR THE BEARINGS, THEREFORE HE WILL HAVE TO CHANGE OIL A LITTLE MORE FREQUENTLY. 3/5/04:SAC, RMC MET W/DFK AND DAN DAVID - REGION 9 REMEDIAL ENGINEER TO DISCUSS THE AIR SPARGING PROPOSAL, HIGH VACUUM EXTRACTION HAS REMOVED PRODUCT, NOW SPARGING IS PROPOSED TO REMOVE DISSOLVED LEVELS, DAN DAVID GAVE HIS APPROVAL FOR THE AIR SPARGING PROPOSAL. 02/02/05 SAC/RMC/MEETING. SPARGE IN PLACE, NEED SPARGE COMPRESSORS TO COMPLETE INSTALLATION. RMC TO PICK UP UNIT THAT CAME FORM ORCHARD PARK AND RIDGE ROAD TAKE TO C+W TO SEE IF IT CAN BE USED. 7/6/05:SAC MET W/DKK. C&W ENV. UNABLE TO UTILIZE COMPRESSOR FROM ORCHARD PARK & RIDGE. RANDY KLOSKO PRICED USED MODEL AT ABOUT $3000 PLUS SHIPPING. DKK GAVE APPROVAL TO ORDER THE UNIT. SAC TELECON RANDY KLOSKO GIVING GO AHEAD. 12/27/05 RMC/FILE. CHECKED SITE FOR SAC. SYSTEM RUNNING. 12/30/05 FILE. SITE TO BE TRANSFERRED TO EMPIRE GEO. AUTHORIZATION TO PROCEED COMPLETED. LETTER OF COMPLETION TO PREVIOUS CONTRACTOR. 01/16/06 RMC/ART, CHUCK, AND TIM, EMPIRE GEO/SITE. SITE REASSIGNED TO RMC. REPLACED LOCKS WITH KEY MASTER 3232. HIGH VAC DOWN UPON ARRIVIAL. TRANSFER PUMP FROM KNOCK OUT TANK TO STRIPPER IS APART, UNKNOWN PROBLEM. HEATERS RUNNING AND NOTHING APPEARS FROZEN. AIR SPARGE SYSTEM NEARLY COMPLETED, NEED TO RUN TRUNK LINE TO HEAD, INSTALL SYSTEM CONTROLS, INSTALL EFFLUENT LINE FROM COOLING TANK, AND WATER LINE FROM STRIPPER TO COOLING TANK. RMC REQUESTED A SURFACE AQUASTATE BE INSTALLED WITH A RELAY TO SHUT DOWN THE AIR SPARGE IF TEMP. ABOVE 130 DEGREES F. IN ORDER TO KEEP SPARGE AIR TEMP. DOWN.... MAY NEED TO TIE INTO CONTROL FOR HIGH VAC. IE SPARGE ONLY ENABLED IF HIGH VAC IS RUNNING. EMPIRE GEO TO REVIEW FILE THIS WEEK, TO

PROVIDED COMPREHENSIVE SUMMARY REPORT, TO GET HIGH VAC RUNNING, TO FINISH AIR SPARGE SYSTEM, CLEAN UP SITE INSIDE AND OUT, TO PICK UP TWO HITCHES AND FOUR TIRES FROM C AND W. 01/21/06 RMC/FILE. MAILED COPIES OF OLD REPORTS TO EMPIRE GEO. 03/01/06 RMC/FILE. CALLED CHUCK GUZZETTA COLLECTED SAMPLES. REDEVELOPLED WELLS. TODAY ARE COLLECTING SAMPLES SOME FREE PRODUCT FOUND. REPORTS WILL FOLLOW. HI VAC IS NOW OPERATIONAL. UPDATE 3/30/06. 06/20/06 RMC/FILE. CONTACTED CHUCK GUZZETTA AND REQUESTED REPORT ASAP. 06/21/06 RMC/FILE. RECIEVED A CALL FROM KALIDA HEALTH ON FENCE REQUEST. RMC DISCUSSED WITH DKK TO MEET ON SITE WHEN THEY KNOW MORE. UPDATE 6/30/06. 06/29/06 RMC/CHUCK GUZZETTA/MEETING. COMPREHENSIVE SUMMARY AND PILOT TEST REPORTS OVERDUE. WILL SEND ASAP. 07/12/06 RMC/FILE. MET WITH KALIDA. DKK ATTENDED. LETTER WENT OUT. RMC THEN MET ON SITE WITH EMPIRE GEO. THEY WILL FIX UP THE AREA AND GET SLAT SAMPLES. REPORTS WILL BE SUBMITTED ASAP. UPDATE 7/30/06. 08/14/06 RMC/AL KRUGER KALIDA/SITE. KALIDA CHOOSE BLACK FOR FENCE COLOR. RMC ADVISED EMPIRE GEO. EMPIRE GEO WILL CALL WITH SCHEDULE. 08/15/06 RMC/FILE. DISCUSSED SITE WITH DKK, SENT NOTE TO ALBANY 08/30/06 RMC/SITE. FENCE COMPANY WORKING ON REPLACING SLATS AND REPAIRING REST OF THE FENCE. MET WITH RUSS SAVAGE ON SITE LAST WEEK, NWECC TO TAKE OVER THE SITE. 09/05/06 RMC/CHUCK GUZZETTA/MEETING. DELIVERED COMP. SUMMARY REPORT. 09/08/06 RMC/SITE. FENCE WORK STARTED BUT NOT FINISHED. 09/13/06 RMC/CHUCK GUZZETTA/PHONE. RMC ADVISED WORK NOT COMPLETED. HE WILL LOOK INTO AND GET BACK TO ME. 09/14/06 RMC/FILE. TALKED WITH AL KRUGER. HE IS CONCERNED WITH PROGRESS ON FENCE. RMC ADVISED THAT CONTRACTOR REPORTED THAT THE HAD TO ORDER ADDITIONAL MATERIAL CAUSING THE DELAY. THAT THEY WERE THERE 9/13 WORKING ON IT AND THAT RMC WOULD INSPECT IT TOM. 09/15/06 RMC/SITE. LEFT MESSAGE THAT WOULD BE ON SITE AT 9AM. SLATS DONE. PIPE REMOVAL AND FENCE ITSELF IS ON COMPLETED. 09/26/06 RMC/SITE. THE FENCE WORK IS ESENTIALLY COMPLETED. THEY LEFT ONE UNUSED POST STANDING, REASON UNKNOWN. THE STACK STILL NEEDS TO BE STRAIGHTENED. UPDATE 10/15/06. 09/29/06 RMC/RUSS SAVAGE/PHONE. NWECC WITH CUT OFF LAST POST, STRAIGHTEN STACK, FILL IN FENCE HOLES, AND PERFORM SOME MORE CLEANUP AROUND THE FENCE. 12/29/06 RMC/FILE. HAVE HAD SEVERAL SITE VISITS AND DISCUSSIONS WITH NWECC. THEY CONTINUE UPDATING THE SITE AND GETTING UP TO SPEED ON THE REMEDIATION. UPDATE 1/10/07. . 01/07/07 RMC/SITE. SYSTEM DOWN FOR MAINTENANCE. NWECC TO GET THAT AND AIR SPARGE ON LINE. 01/09/07 RMC/FILE. CONTACED NWECC AND ADVISED THEY ARE OVERDUE ON REQUIRMENTS IN AUTHORIZATION TO PROCEED. REPORT OVER DUE AND SYSTEM NOT OPTIMIZED. REPORT OVERDUE AND NOW DUE 1/30/07. 06/18/07 RMC/FILE. VISITED SITE SEVERAL TIMES. BUILDING NEXT DOOR WAS IMPLODED WHICH REQUIRED SYSTEM TO LOOSE POWER FOR A WEEK OR SO. NWECC WORING WITH THE SITE CONTRACTOR TO GET SYSTEM UP. 10/22/07 RMC/TONY K./ MATT MANCUSO, ARCHITECTURAL RESOURCES, 570-3190/SITE. FOUND A 1K UST 200 FEET EAST OF THE TRAILERS. TANK CRUSHED DOWN BY SITE CONTRACTOR WHO STATED THAT THE TANKS END WAS ALREADY CUT OFF. SLIGHT GASOLINE ODOR IN THE UST. DUG TO 8 FEET IN THE TANK PIT. NO INDICATION OF CONTAMINATION. TOOK ONE BOTTOM SAMPLE. AIR SPARGE PUMP SHAFT SHEARED OFF. NWECC TO FIX OR GET A NEW PUMP. PARKING LOT BEING REDONE, NWECC TO COORDINATE CURB BOX WORK. 10/25/07 RMC/TOM HELLERT/SITE. CONTRACTOR PUTTING IN STORM SEWERS BROKE SOME AIR SPARGE AND HVE LINES 10 FEET SOUTH OF THE FENCE ENTRANCE. CALLED NWECC AND LEFT MESSAGE. COULD NOT LOCATE ALL THE MW POINTS. 10/26/07 RMC/FILE. TOM HELLER LEFT MESSAGE THAT SEVERAL OF THE MWS AND RECOVERY WELLS WERE BROKEN AND PARTIALLY FILLED IN. RMC CONTACTED NWECC TO GET THEM SURVEYED AND REPLACED. 10/29/07 RMC/FILE. RECIEVED MESSAGE THAT TOM HELLERT IS SICK AND WILL BE OUT FOR A WHILE. RMC CONTACTED NWECC TO CHECK ON PROGRESS IN GETTING WELLS REPAIRED/REPLACED. 10/30/07 RMC/FILE. RECEIVED SOILS ANALYSIS FOR THE EXCAVATION BOTTOM OF THE ORPHAN 1K UST. ALL ND EXCEPT MINOR HIT ON NAPTHLENE 4.8 PPB. 11/08/07 RMC/SITE. NWECC INSTALLING RECOVERY AND MWS THAT WERE DAMAGED, ALSO INSTALLING RECOVERY WELL BY THE STREET AND REINSTALLING SPARGER POINTS THAT WERE DAMAGED IN GRADING. 11/14/07 RMC/SITE. NWECC HAS FINISHED RE-INSTALLING WELLS. DISCUSSED WITH GREG WEBER, NWECC, THEY ARE WORKING TOWARDS GETTING ALL HOOKED UP TO VAC OR SPARGE BY NEXT WEEK WHEN THE CURBS ARE SET TO GO IN. 11/15/07 RMC/FILE. RECIEVED SAMPLE RESULTS FROM THE ORFHAN TANK EXCAVATION. MEETS STARS. 11/21/07 RMC/CORY, NWECC/SITE. WORK CONTINUES. ANOTHER MW WAS HIT AND NEEDS TO BE REPLACED. NWE RECOVERY POINT NEAR THE ROAD NEEDS TO BE HOOKED UP. AIR SPARGE POINTS NEED TO BE LOWERED. FINAL GRADING NEXT WEEK. 11/26/07 RMC/GREG WEBER/PHONE. THEY HAVE 4 ON SITE TODAY. NEARING BLACK TOP. 12/10/07 RMC/SITE. BINDER IN. FINISH NEXT SPRING. NWECC ON SITE SETTING CURB BOXES. UPDATE 12/30/07. 12/17/07 RMC/FILE. INSPECTED 12/13, NWECC WORKING ON CURB BOXES. SYSTEM WILL BE PUT BACK INTO OPERATION NEXT WEEK. UPDATE 12/30/07. 12/18/07 RMC/SITE. WORK CONTINUES. AG INFORMS NEGOTIATION ON COST RECOVERY MAY BE COMPLETED SOON AND THAT EXXONMOBIL MAY TAKE OVER REMEDIATION. 12/31/07 RMC/FILE. RECEIVED CALL FROM THE AG. THEY HAVE AGEEED TO TERMS WITH EXXONMOBLIL THEY WILL BE TAKING OVER THE SITE. SYSTEM START UP NEXT WEEK. 1/3/08 RMC/TONY K, NWECC/PHONE. SYSTEM IS UP AND RUNNING. UPDATE 1/15/08. 02/21/08 RMC/FILE. CALLED GREG WEBER AND REQUESTED A SITE REPORT. DUE 3/15/08. 03/05/08 RMC/AMY HEWSON/PHONE. STILL WORKING ON ACCESS. 03/05/08 RMC/FILE. TRANSFER PUMP DOWN. REPAIRS WILL TAKE 7 WEEKS. RMC ADVISES TO GET NEW PUMP. $977 VS $1300. UPDATE 3/15/08 04/23/08 RMC/FILE. SYSTEM OPERATIONAL. PROCESSED NWI PAY PACKAGE 13. 07/01/08 RMC/GES/NWECC/SITE. SYSTEM OPERATIONAL. GES PREPARING TO TAKE OVER OPERATION. NEED TO GET SEWER PERMIT FIRST. UPDATE 7/30/08 07/21/08 RMC/DAN KING/MEETING. HE RECEIVED CALL FROM MOBIL. WANT TO SHUT DOWN SYSTEM. START SOMETHING AGAIN IN MID 2009. RMC TO DISCUSS WITH MOBIL. NEED SOLID PLAN FIRST. 08/27/08 RMC/FILE. RECEIVED LETTER FROM GES. SYSTEM SHUT DOWN 7/23/08 FOR MW INSTALLATION AND SAMPLING. NOT YET TURNED BACK ON. RMC LEFT MESSAGE REQUESTING MWS BE DEVELOPED AND SAMPLED SO UNIT CAN BE TURNED BACK ON. ADDITIONAL SOIL BORINGS PLANNED. SYSTEM DOES NOT REQUIRE SHUT DOWN FOR SOIL SAMPLING. LEFT MESSAGE, CALL DUE 8/30/08 08/30/08 RMC/AMY HEWSEN/PHONE. ADDITIONAL WATER WELLS ARE PLANNED FOR NEXT WEEK. WELLS WILL BE DEVELOPED AND SAMPLED SOON AFTER. RMC ADVISED SYSTEM MUST RESTARTED. UPDATED DKK. UPDATE 9/15/08. 11/17/08 RMC/FILE. GES ADVISED INVESTIGATION WORK COMPLETED AND OK TO START SYSTEM. RMC SENT NWECC OUT TO LOOK AT SYSTEM TO SEE WHAT NEEDS TO BE DONE. PROCESSED ELECTRIC PAY PACKAGE. UPDATE 12/1/08 03/19/09 RMC/DKK/AL KRUGER/MEETING. KALIDA HAS NOT FINALIZED PLANS FOR THE SITE AS OF YET. RMC TO SEND COPY OF MOST RECENT REPORTS TO AL KRUGER. UPDATE 4/1/09 05/01/09 RMC/FILE. HAD CONFERENCE CALL 4/20. LOOKING AT OPTIONS. PHONE CONTACT WITH AMY HEWSON 5/1/09. ELECTRIC BILL SWITCHED INTO GES NAME NOW. THEY HAVE DONE ADDITIONAL TESTING ON SITE. MAY WORK OUT PUBLIC/PRIVATE WORK ARRANGEMENT. TO TALK AGAIN 5/8/09. 06/05/09 RMC/FILE. DISCUSSED OPERATION OF REMEDIATION SYSTEM WITH NWECC SEVERAL TIMES. RECEIVED SMR. RECOVERED 55 GALLONS PRODUCT VIA VAC EX EVENTS FROM MW23 AND MW11. UPDATE 6/30/09 08/20/09 RMC/FILE. MET EARLIER IN THE MONTH WITH KALIDA TO GET UPDATE ON PLANS. TALED WITH GES AND DOUG DUGGAN, EXXON/MOBILE. PILOT TEST NOT YET DONE. TO HAVE PLAN BY 8/20/09. 09/01/09 RMC/FILE. RECEIVED PILOT TEST PLAN, DISCUSSED WITH STEVE LEITTEN AND DKK. DEC CONCERNED THAT THE TIME LINE SINCE GES TOOK OVER IS TOO SLOW. THEY WILL START THE TESTS ASAP. 09/02/09 RMC/FILE. KALEIDA CONTACTE INFORMATION. ALBERT KRUGER, RPA, DIRECTOR OF CORPORATE REAL ESTATE LARKIN BUILDING 726 EXCHANGE STREET BUFFALON 14210-1484 7168598552 09/04/09 RMC/FILE. RECEVEIVED SMR. CONSISTENT WITH PREVIOUS GW NUMBERS. 11/25/09 RMC/FILE. MET WITH KALIDA LAST WEEK TO UPDATE ON SITE PROGRESS. RECEIVED SUBMITALS

FROM EPS VT RE CONTINUED TESTING REMEDIAL OPTIONS. UPDATE 1/1/10 11/30/09 RMC/FILE. RECEIVED A NOTICE FROM GES THAT THEY ARE GOING TO DO MORE PILOT TESTING THE WEEK OF 12/7/09. NEXT REPORT DUE 1/1/10 01/26/10 RMC/FILE. RECEIVED SMR. NO ACTION PLAN YET. CONTINUED TESTING, RMC CONTACTED STEVE LEITTEN, RAP BY 3/30/10. 02/24/10 RMC/FILE. DEC RECEIVED SMR. EXCEEDANCES CONTINUE. NO RAP. 03/02/10 RMC/FILE. DEC HAS BEEN CONTACED BY KALIDA. THEY ARE PLANNING ON GOING FORWARD WITH BUILDING ON THE SITE. SUTTON IS DISCUSSING VARIOUS OPTIONS WITH KRUGER. UPDATE 4/30/10. 06/15/10 RMC/FILE. UPDATE. NO NE INFORMATION. GES REPORTS THAT THEY WILL BE REMOVING THE OLD SYSTEM SOON AND STATE THEY WILL BE SENDING A RAP. UPDATE 9/30/10. 07/30/10 RMC/FILE. GES SUBMITTED PRODUCT REMOVAL RAP. OKED TO GO FORWARD. LETTER. UPDATE 9/30/10. 10/06/10 RMC/FILE. MET WITH EXXON MOBIL AND KALIDA AT DIFFERENT TIMES. DEVELOPEMENT WILL PROCEED. PARTIES ARE WORKING OUT DETAILS. UPDATE 11/30/10 05/17/11 RMC/FILE. RECEIVED 1ST 2011 REPORT. EXCEEDANCES CONTINUE. PRP CONTINUES TO NEGOTIATE WITH OWNER. UPDATE 6/1/11. 11/28/11 RMC/FILE. RECEIVED ANOTHER SMR. SITE IS POTENTIAL BROWNFIELD. WORK IS PROGRESSING ON THAT FRONT. UPDATE 3/30/12. 05/22/12 JSW/File. As per request from C&S Companies (letter dated 5/15/2012), this spil was split into two spills. The spill #9500234 will pertain to the western portion of the block and would be addressed under the BCP site # C915260. The eastern portion of the block (830 Ellicott Street and 40 High Street) is the intended location of Kaleida's new WCHOB. The address for WCHOB would be 818 Ellicott Street, Buffalo, NY. The eastern portion of the block would be addressed under spill # 1201711. 01/16/13 RMC/FILE. PER JW AND GS SPILL TRANSFERRED TO JW FOR FOLLOW UP. 09/15/15 RMC/FILE. THIS SPILL IS BEING HANDLED UNDER THE BCP PROGRAM, C915260, 7/18/12, AG COLLECTED FUNDS OWED TO THE SPILL FUND, THE AG CLOSED DATE IS 6/8/12. THIS SITE TO BE CLOSED AS A SPILLS ISSUE, ANY FOLLOW UP IS BEING TRACKED UNDER THE BCP PROGRAM. "

Material Information

OP Unit ID:	1011005	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	368843	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	30000.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	15000.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	RICHARD CICCOTELLI
Spiller Company:	MOBIL OIL/BUSINESS RESOUR
Spiller Address:	464 DOUGHTY BLVD.100 HIGH
Spiller City:	INWOOD
Spiller State:	NY
Spiller Zip:	11096-1342
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900954993
Longitude:	-78.869370023

27	***4 of 19***	***WSW***	***0.12 / 641.48***	***660.19 / 16***	***PHYSICANS IMAGING 979 MAIN STREET BUFFALO NY***	***LST***

Spill No:	8806781	***REM Phase:***	0
Site ID:	146808	***UST Trust:***	True
DER Facility ID:	124995	***Spill Date:***	1988-11-01 12:00:00
CID:		***Rcvd Date:***	1988-11-14 11:00:00
Program Type:	ER	***CAC Date:***	1989-01-25 00:00:00
SWIS Code:	1502	***Insp Date:***	1989-01-23 00:00:00
Contribute Factor:	Tank Failure	***Close Date:***	1989-01-25 00:00:00
Water Body:		***Create Date:***	1988-11-17 00:00:00
Class:		***Update Date:***	2001-07-02 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	MXFRANKS
County:	Erie	***After Hours:***	False
Referred to:			

Reported by: Other
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CONTRACTOR CALLED IN SHEEN IN MW, SITE IS AN OLD MOBIL STATION."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 11/14/88: MF TELECON VARIOUS PARTIES TO GET OWNERS NAME. 11/18/88: MF TELECON JIM KELLY TO GET ENVIRONMENTAL REPORT. NOT IN TO RETURN CALL. 11/28/88: MF TELECON JIM KELLEY FOR COPY OF EMPIRE SOIL'S REPORT. HE CLAIMED HE WILL SEND IT RIGHT OUT. 12/12/88: MF TELECON RAVI CHOPRA,I ASKED FOR A COPY OF THE REPORT FROM EMPIRE SOILS HE CLAIMED HE DIDN'T GET A COPY AS YET, & AS SONN AS HE DOES HE WILL SEND ME A COPY. 12/30/88: MF JIM KELLY TELECON, HE WANTED TO KNOW IF I HAD A COPY OF REPORT AS HE DIDN'T. HE WILL SET UP SITE MEETING WITH ESI ASAP. 01/23/89: MF RECEIVED COPY OF SITE SURVEY. SITE VISIT/EMPIRE SOILS & JIM KELLY (LAWYER) WELLS BAILED & CHECKED FOR SHEEN. NO SHEEN NOTICED, 1 WELL NO LIQUID. NO FUTHER ACTION NECESSARY. "

Material Information

OP Unit ID:	923617	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	455124	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0064A
Material Name: unknown material

Spiller Information

Spiller Name:
Spiller Company: PHYSICIANS IMAGING CENTER
Spiller Address: ONE CAMBRIDGE SQUARE
Spiller City: MERRIVILLE
Spiller State: IN
Spiller Zip: 46410
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.832678993
Longitude: -78.738992018

27	5 of 19	WSW	0.12 / 641.48	660.19 / 16	MOBIL SERVICE STATION 99 - MST FORMERLY 1001 MAIN ST BUFFALO NY 14203	RCRA SQG

EPA Handler ID: NYR000215533
Gen Status Universe: Small Quantity Generator
Contact Name: DENISE JURON-BORGESE
Contact Address: 350, ESSJAY RD, WILLIAMSVILLE, NY, 14221, US
Contact Phone No and Ext: 716-631-8000
Contact Email: DJURON-BORGESE@CIMINELLI.COM
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20141205
Location Latitude: 42.888601

Location Longitude: -78.87342

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20141205
Handler Name: MOBIL SERVICE STATION 99 - MST FORMERLY
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: CONVENTUS PARTNERS LLC
Date Became Current: 20130731
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Owner/Operator Ind: Current Owner
Street No: 726

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street 1:**	EXCHANGE ST SUITE 200
Name:	KALEIDA PROPERTIES	**Street 2:**	
Date Became Current:	20120319	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-859-8552	**Country:**	US
Source Type:	Notification	**Zip Code:**	14210

27	6 of 19	WSW	0.12 / 641.48	660.19 / 16	**CURIA GLOBAL INC – MAIN ST** **1001 MAIN ST STE 700** **BUFFALO NY 14203**	RCRA LQG

EPA Handler ID:	NYR000218347
Gen Status Universe:	Large Quantity Generator
Contact Name:	JASON R NICHOLS
Contact Address:	26, CORPORATE CIR, ALBANY, NY, 12203, US
Contact Phone No and Ext:	518-512-2000 x2545
Contact Email:	JASON.NICHOLS@AMRIGLOBAL.COM
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	Private
Receive Date:	20220225
Location Latitude:	42.888601
Location Longitude:	-78.87342

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date:	20210901
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20220225
Handler Name:	CURIA GLOBAL INC – MAIN ST
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: B
Waste Code Description: Incineration, heat recovery, burning. Waste management method code to be used on e-manifests only.

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: U067
Waste Code Description: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U194
Waste Code Description: 1-PROPANAMINE (I,T) (OR) N-PROPYLAMINE (I,T)

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P028
Waste Code Description: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

Hazardous Waste Code: P087
Waste Code Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Hazardous Waste Code: P121
Waste Code Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Hazardous Waste Code: U156
Waste Code Description: CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D002

Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20210225
Handler Name: ALBANY MOLECULAR RESEARCH INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: P087
Waste Code Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: P028
Waste Code Description: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: U067
Waste Code Description: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

Hazardous Waste Code: U156
Waste Code Description: CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)

Hazardous Waste Code: P121
Waste Code Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Hazardous Waste Code: U194
Waste Code Description: 1-PROPANAMINE (I,T) (OR) N-PROPYLAMINE (I,T)

Hazardous Waste Code: B
Waste Code Description: Incineration, heat recovery, burning. Waste management method code to be used on e-manifests only.

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150331
Handler Name: ALBANY MOLECULAR RESEARCH INC
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20210715
Handler Name: CURIA GLOBAL INC – MAIN ST
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: P028
Waste Code Description: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: U067
Waste Code Description: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

Hazardous Waste Code: P121
Waste Code Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: B
Waste Code Description: Incineration, heat recovery, burning. Waste management method code to be used on e-manifests only.

Hazardous Waste Code: P087
Waste Code Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U156
Waste Code Description: CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING,

BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U194
Waste Code Description: 1-PROPANAMINE (I,T) (OR) N-PROPYLAMINE (I,T)

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	State	***Street 1:***	PO BOX 100
Name:	FORT SCHUYLER TRIBAL MUNICIPAL	***Street 2:***	
Date Became Current:	20150128	***City:***	UTICA
Date Ended Current:		***State:***	NY
Phone:	518-437-8686	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	13502
Owner/Operator Ind:	Current Operator	***Street No:***	1001
Type:	State	***Street 1:***	MAIN ST STE 700
Name:	CIMINELLI REAL ESTATE CORP FOR CONVENTUS	***Street 2:***	
Date Became Current:	20120514	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	14203
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	State	***Street 1:***	PO BOX 100 SEYMOUR RD
Name:	FORT SCHUYLER TRIBAL MUNICIPAL	***Street 2:***	
Date Became Current:	20150128	***City:***	UTICA
Date Ended Current:		***State:***	NY
Phone:	518-437-8686	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	13502
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	State	***Street 1:***	
Name:	CIMINELLI REAL ESTATE CORP FOR CONVENTUS	***Street 2:***	
Date Became Current:	20120514	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	State	***Street 1:***	
Name:	CIMINELLI REAL ESTATE CORP FOR CONVENTUS	***Street 2:***	
Date Became Current:	20120514	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	
Owner/Operator Ind:	Current Operator	***Street No:***	1001
Type:	State	***Street 1:***	MAIN ST STE 700
Name:	CIMINELLI REAL ESTATE CORP FOR CONVENTUS	***Street 2:***	
Date Became Current:	20120514	***City:***	BUFFALO
Date Ended Current:		***State:***	NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14203
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	PO BOX 100 SEYMOUR RD
Name:	FORT SCHUYLER TRIBAL MUNICIPAL	**Street 2:**	
Date Became Current:	20150128	**City:**	UTICA
Date Ended Current:		**State:**	NY
Phone:	518-437-8686	**Country:**	US
Source Type:	Notification	**Zip Code:**	13502
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	PO BOX 100
Name:	FORT SCHUYLER TRIBAL MUNICIPAL	**Street 2:**	
Date Became Current:	20150128	**City:**	UTICA
Date Ended Current:		**State:**	NY
Phone:	518-437-8686	**Country:**	US
Source Type:	Notification	**Zip Code:**	13502

Historical Handler Details

Receive Dt:	20150331
Generator Code Description:	Large Quantity Generator
Handler Name:	ALBANY MOLECULAR RESEARCH INC
Receive Dt:	20210715
Generator Code Description:	Large Quantity Generator
Handler Name:	CURIA GLOBAL INC – MAIN ST
Receive Dt:	20210225
Generator Code Description:	Large Quantity Generator
Handler Name:	ALBANY MOLECULAR RESEARCH INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	7 of 19	WSW	0.12 / 641.48	660.19 / 16	Former Mobil Service Station 99-MST 979 Main Street Buffalo NY 14203	INST

Site Code:	458395
HW Code:	C915260
Control Type:	INST
Program:	BCP
Site Class:	C
Site Name:	Former Mobil Service Station 99-MST
Site Address:	979 Main Street
City:	Buffalo
Zip:	14203
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.900858000
Longitude:	-78.868792000
SWIS:	1502
Acres:	1.725
Record Added:	2011-11-28 14:06:00
Record Updated:	2022-07-13 15:20:00
Updated By:	AECAPRIO
Site Code (Web):	C915260
Program Type (Web):	BCP
Site Class (Web):	C
Site Name (Web):	Former Mobil Service Station 99-MST
Address1 (Web):	979 Main Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14203
County (Web):	Erie
Longitude (Web):	-78.868792000

Latitude (Web):	42.900858000
Site Code (GIS):	C915260
Program (GIS):	BCP
Site Class (GIS):	C
Site Name (GIS):	Former Mobil Service Station 99-MST
Address 1 (GIS):	979 Main Street
Address 2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14203
County (GIS):	Erie
Latitude (GIS):	
Longitude (GIS):	
Site Class Desc:	
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Measures are in place to control the potential for coming in contact with residual subsurface soil and groundwater contamination remaining on the site.

Description:

Location: The Former Mobil Service Station 99-MST site is an approximately 1.72-acre site located at 1001 Main Street (formerly 979 Main Street) in the City of Buffalo, Erie County. The site is bordered by Goodrich Street to the north, High Street to the south, a parking lot to the east and Main Street with an underground subway corridor below to the west. Site Features: This site consists of two parcels and has a medical office building and associated parking which was constructed in 2015. Current Zoning and land Use: The site is zoned for commercial use. Land use in the surrounding area is characterized as urban mixed use, primarily commercial and community services. The community services include public and private medical and hospital facilities. Past Use of the Site: Exxon/Mobil and its predecessors operated a gas station on the site from approximately 1950 to 1982. The gas station building was demolished in 1982 and four underground storage tanks (USTs) were removed between 1981 and 2007. Other previous operations at the site included an auto repair shop, University at Buffalo medical and dental departments, a restaurant and a motel. Site Geology and Hydrogeology: Overburden soils in the area consist primarily of fill material at the ground surface. Geotechnical boring logs collected from the site in 2010 indicate that fill material such as sand, gravel and bricks varies in thickness from 2 to 10 feet across the site. Soil underlying the fill is comprised of interbedded sands and silt that are brown to olive - brown in color. Overburden soils are underlain by the Onondaga Limestone (bedrock), which is at approximately 100 feet below ground surface (fbgs). The groundwater is approximately 32 fbgs and flows towards northeast.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum hydrocarbons in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in soil and groundwater is being managed under a Site Management Plan. Note: Off-site contamination in the Main Street Right-of-Way, between the subway line and sheet piles along the site border, is being managed under Spill number 9500234.

Controls Information

Control Code:	31	***Record Added Date:***	2020-11-05 09:45:37.237000000
Control Name:	Monitoring Plan	***Record Updated Dt:***	2022-04-08 14:12:36.253000000
Control Type:	INST	***In Place Date:***	2014-12-02 00:00:00
Updated By:	MEKUCZKA		
Control Code:	34	***Record Added Date:***	2020-11-05 09:45:37.237000000
Control Name:	IC/EC Plan	***Record Updated Dt:***	2022-04-08 14:12:36.253000000
Control Type:	INST	***In Place Date:***	2014-12-02 00:00:00
Updated By:	MEKUCZKA		
Control Code:	32	***Record Added Date:***	2020-11-05 09:45:37.237000000
Control Name:	Site Management Plan	***Record Updated Dt:***	2022-04-08 14:12:36.253000000
Control Type:	INST	***In Place Date:***	2014-12-02 00:00:00
Updated By:	MEKUCZKA		
Control Code:	25	***Record Added Date:***	2020-11-05 09:45:37.237000000
Control Name:	Landuse Restriction	***Record Updated Dt:***	2022-04-08 14:12:36.253000000
Control Type:	INST	***In Place Date:***	2014-12-02 00:00:00
Updated By:	MEKUCZKA		
Control Code:	08	***Record Added Date:***	2020-11-05 09:45:37.237000000

Control Name: Ground Water Use Restriction
Control Type: INST
Updated By: MEKUCZKA
Record Updated Dt: 2022-04-08 14:12:36.253000000
In Place Date: 2014-12-02 00:00:00

Control Code: 14
Control Name: Soil Management Plan
Control Type: INST
Updated By: MEKUCZKA
Record Added Date: 2020-11-05 09:45:37.237000000
Record Updated Dt: 2022-04-08 14:12:36.253000000
In Place Date: 2014-12-02 00:00:00

Control Code: J
Control Name: Environmental Easement
Control Type: INST
Updated By: MEKUCZKA
Record Added Date: 2020-11-05 09:45:37.237000000
Record Updated Dt: 2022-04-08 14:12:36.253000000
In Place Date: 2014-12-02 00:00:00

Materials Information

Waste Name: TOLUENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: NNN
Owner Name: Robert W. Bragg
Owner Company: Kaleida Health
Owner Street: 726 Exchange Street
Owner Street 2:
Owner City: Buffao
Owner State: NY
Owner Zip: 14210
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Buffalo and Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203-1887
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Robert Bragg

Owner Company: kaleida health
Owner Street: 726 exchange street
Owner Street 2:
Owner City: buffalo
Owner State: NY
Owner Zip: 14210
Country: United States of America

Owner Op: 04
Sub Type: NNN
Owner Name: Malika Basheer
Owner Company: Seavest Core Buffalo Coventus, LLC
Owner Street: 707 Westchester Avenue
Owner Street 2: Suite 101
Owner City: White Plains
Owner State: NY
Owner Zip: 10604
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Robert bragg
Owner Company: kaleida properties, inc.
Owner Street: 726 exchange street
Owner Street 2:
Owner City: buffalo
Owner State: NY
Owner Zip: 14210
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: malika basheer
Owner Company: seavest core buffalo conventus, llc
Owner Street: 707 westchester avenue
Owner Street 2: Suite 401
Owner City: white plains
Owner State: NY
Owner Zip: 10604
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Malika Basheer
Owner Company: Seavest Core Buffalo Coventus, LLC
Owner Street: 707 Westchester Avenue
Owner Street 2: Suite 401
Owner City: White Plains
Owner State: NY
Owner Zip: 10604
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Paul Ciminelli
Owner Company: Ciminelli Real Estate Corporation
Owner Street: 50 Fountain Plaza
Owner Street 2: Suite 500
Owner City: Buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

HW Extra Information

Dump:	False	***Dell:***	
Structure:	False	***Updated By:***	jswalia
Lagoon:	False	***Record Added:***	2011-11-28 14:58:00

Landfill: False
Pond: False
Disposal Start:
Disposal Terminate:
Record Updated: 2014-12-11 15:56:00
Latitude:
Longitude:

Projects Information

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2014-12-23 00:00:00
End Status: ACT
Operable Unit ID: 1213770
Operable Unit: 01A
Operable Unit Desc: Excavation of Contaminated Soils:
Code Name: Remedial Action

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2014-12-16 00:00:00
End Status: ACT
Operable Unit ID: 1208514
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2014-12-23 00:00:00
End Status: ACT
Operable Unit ID: 1208514
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Certificate of Completion

Project Code: 04
Project Desc: Remedial Design
Project Refer Name: IRM
End Date: 2012-12-19 00:00:00
End Status: ACT
Operable Unit ID: 1213770
Operable Unit: 01A
Operable Unit Desc: Excavation of Contaminated Soils:
Code Name: Remedial Design

Environmental Remediation

Operable Unit: 01A
Contaminants: 1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

Operable Unit: 01
Contaminants: 1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

Operable Unit: 00
Contaminants: 1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

27	8 of 19	WSW	0.12 / 641.48	660.19 / 16	**Former Mobil Service Station 99-MST** **979 Main Street** **Buffalo NY 14203**	ENG

Site Code: 458395
HW Code: C915260
Control Type: ENG

Program:	BCP
Site Class:	C
Site Name:	Former Mobil Service Station 99-MST
Site Address:	979 Main Street
City:	Buffalo
Zip:	14203
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.900858000
Longitude:	-78.868792000
SWIS:	1502
Acres:	1.725
Record Added:	2011-11-28 14:06:00
Record Updated:	2022-07-13 15:20:00
Updated By:	AECAPRIO
Site Code (Web):	C915260
Program Type (Web):	BCP
Site Class (Web):	C
Site Name (Web):	Former Mobil Service Station 99-MST
Address1 (Web):	979 Main Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14203
County (Web):	Erie
Longitude (Web):	-78.868792000
Latitude (Web):	42.900858000
Site Code (GIS):	C915260
Program (GIS):	BCP
Site Class (GIS):	C
Site Name (GIS):	Former Mobil Service Station 99-MST
Address 1 (GIS):	979 Main Street
Address 2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14203
County (GIS):	Erie
Latitude (GIS):	
Longitude (GIS):	
Site Class Desc:	
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Measures are in place to control the potential for coming in contact with residual subsurface soil and groundwater contamination remaining on the site.

Description:

Location: The Former Mobil Service Station 99-MST site is an approximately 1.72-acre site located at 1001 Main Street (formerly 979 Main Street) in the City of Buffalo, Erie County. The site is bordered by Goodrich Street to the north, High Street to the south, a parking lot to the east and Main Street with an underground subway corridor below to the west. Site Features: This site consists of two parcels and has a medical office building and associated parking which was constructed in 2015. Current Zoning and land Use: The site is zoned for commercial use. Land use in the surrounding area is characterized as urban mixed use, primarily commercial and community services. The community services include public and private medical and hospital facilities. Past Use of the Site: Exxon/Mobil and its predecessors operated a gas station on the site from approximately 1950 to 1982. The gas station building was demolished in 1982 and four underground storage tanks (USTs) were removed between 1981 and 2007. Other previous operations at the site included an auto repair shop, University at Buffalo medical and dental departments, a restaurant and a motel. Site Geology and Hydrogeology: Overburden soils in the area consist primarily of fill material at the ground surface. Geotechnical boring logs collected from the site in 2010 indicate that fill material such as sand, gravel and bricks varies in thickness from 2 to 10 feet across the site. Soil underlying the fill is comprised of interbedded sands and silt that are brown to olive - brown in color. Overburden soils are underlain by the Onondaga Limestone (bedrock), which is at approximately 100 feet below ground surface (fbgs). The groundwater is approximately 32 fbgs and flows towards northeast.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum hydrocarbons in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in soil and groundwater is being managed under a Site Management Plan. Note: Off-site contamination in the Main Street Right-of-Way, between the subway line and sheet piles along the site border, is being managed under Spill number 9500234.

Controls Information

Control Code:	12	***Record Added Date:***	2020-11-05 09:45:37.237000000
Control Name:	Groundwater Treatment System	***Record Updated Dt:***	2022-04-08 14:12:36.253000000
Control Type:	ENG	***In Place Date:***	2014-12-02 00:00:00
Updated By:	MEKUCZKA		

Materials Information

Waste Name: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: TOLUENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: BENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2,4-TRIMETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: NAPHTHALENE
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: P03
Owner Name: malika basheer
Owner Company: seavest core buffalo conventus, llc
Owner Street: 707 westchester avenue
Owner Street 2: Suite 401
Owner City: white plains
Owner State: NY
Owner Zip: 10604
Country: United States of America

Owner Op: 01
Sub Type: NNN
Owner Name: Robert W. Bragg
Owner Company: Kaleida Health
Owner Street: 726 Exchange Street
Owner Street 2:
Owner City: Buffao
Owner State: NY
Owner Zip: 14210
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Malika Basheer
Owner Company: Seavest Core Buffalo Coventus, LLC
Owner Street: 707 Westchester Avenue
Owner Street 2: Suite 401
Owner City: White Plains

Owner State: NY
Owner Zip: 10604
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Robert Bragg
Owner Company: kaleida health
Owner Street: 726 exchange street
Owner Street 2:
Owner City: buffalo
Owner State: NY
Owner Zip: 14210
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Robert bragg
Owner Company: kaleida properties, inc.
Owner Street: 726 exchange street
Owner Street 2:
Owner City: buffalo
Owner State: NY
Owner Zip: 14210
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Reference Librarian
Owner Company: Buffalo and Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203-1887
Country: United States of America

Owner Op: 04
Sub Type: NNN
Owner Name: Malika Basheer
Owner Company: Seavest Core Buffalo Coventus, LLC
Owner Street: 707 Westchester Avenue
Owner Street 2: Suite 101
Owner City: White Plains
Owner State: NY
Owner Zip: 10604
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Paul Ciminelli
Owner Company: Ciminelli Real Estate Corporation
Owner Street: 50 Fountain Plaza
Owner Street 2: Suite 500
Owner City: Buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disposal Start:
Disposal Terminate:
Dell:
Updated By: jswalia
Record Added: 2011-11-28 14:58:00
Record Updated: 2014-12-11 15:56:00
Latitude:
Longitude:

Projects Information

Project Code:	25
Project Desc:	
Project Refer Name:	
End Date:	2014-12-23 00:00:00
End Status:	ACT
Operable Unit ID:	1208514
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Certificate of Completion

Project Code:	02
Project Desc:	Remedial Investigation
Project Refer Name:	
End Date:	2014-12-16 00:00:00
End Status:	ACT
Operable Unit ID:	1208514
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Investigation

Project Code:	04
Project Desc:	Remedial Design
Project Refer Name:	IRM
End Date:	2012-12-19 00:00:00
End Status:	ACT
Operable Unit ID:	1213770
Operable Unit:	01A
Operable Unit Desc:	Excavation of Contaminated Soils:
Code Name:	Remedial Design

Project Code:	05
Project Desc:	Remedial Action
Project Refer Name:	
End Date:	2014-12-23 00:00:00
End Status:	ACT
Operable Unit ID:	1213770
Operable Unit:	01A
Operable Unit Desc:	Excavation of Contaminated Soils:
Code Name:	Remedial Action

Environmental Remediation

Operable Unit:	00
Contaminants:	1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

Operable Unit:	01A
Contaminants:	1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

Operable Unit:	01
Contaminants:	1,2,4-trimethylbenzene, benzene, ethylbenzene, naphthalene, toluene, xylene (mixed)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	9 of 19	WSW	0.12 / 641.48	660.19 / 16	CONVENTUS BUILDING 1001 MAIN STREET BUFFALO NY 14203	AST

Site ID:	563710	***Expiry:***	2023/02/12
Site Status:	Active	***County:***	Erie
Program No:	9-601759	***UTM X:***	
Program Type Code:	PBS	***UTM Y:***	
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Apartment Building/Office Building		

Tank Information

Prog No:	9-601759	***UDC Ind:***	0
Tank ID:	274177	***Red Tag Start Date:***	
Tank No:	A00052930	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	02/01/2014	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	150	***Class B Operator:***	
Registered:	True	***Modified by:***	PTDIEZ
Tank Model:		***Last Modified:***	09/09/2022
Pipe Model:			

Tank Location: 2
Tank Location Desc: Aboveground-contact w/ impervious barrier
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: ADAM VAN HISE
Tank Owner Address: 707 WESTCHESTER AVE. WHITE PLAINS, NY. 10604

Material Information

Material Name: Diesel (E-Gen)
Percent: 100.00

Equipment Information

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: L01
Code Name: Interstitial - Electronic Monitoring

Type: Piping Leak Detection

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Tank Information

Prog No:	9-601759	***UDC Ind:***	0
Tank ID:	278165	***Red Tag Start Date:***	
Tank No:	A00052929	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	02/01/2014	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	150	***Class B Operator:***	
Registered:	True	***Modified by:***	PTDIEZ
Tank Model:		***Last Modified:***	09/09/2022
Pipe Model:			

Tank Location: 2
Tank Location Desc: Aboveground-contact w/ impervious barrier
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: ADAM VAN HISE
Tank Owner Address: 707 WESTCHESTER AVE. WHITE PLAINS, NY. 10604

Material Information

Material Name: Diesel (E-Gen)
Percent: 100.00

Equipment Information

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Tank Information

Prog No:	9-601759	**UDC Ind:**	0
Tank ID:	274176	**Red Tag Start Date:**	
Tank No:	A00052928	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	-
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	02/01/2014	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	-
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	150	**Class B Operator:**	
Registered:	True	**Modified by:**	PTDIEZ
Tank Model:		**Last Modified:**	09/09/2022
Pipe Model:			

Tank Location: 2
Tank Location Desc: Aboveground-contact w/ impervious barrier
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: ADAM VAN HISE
Tank Owner Address: 707 WESTCHESTER AVE. WHITE PLAINS, NY. 10604

Material Information

Material Name: Diesel (E-Gen)
Percent: 100.00

Equipment Information

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Tank Information

Prog No:	9-601759	***UDC Ind:***	0
Tank ID:	274178	***Red Tag Start Date:***	
Tank No:	A00052963	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	
Tank Status Desc:	In Service	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	-
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	02/01/2014	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	150	***Class B Operator:***	
Registered:	True	***Modified by:***	PTDIEZ
Tank Model:		***Last Modified:***	09/09/2022
Pipe Model:			

Tank Location: 2
Tank Location Desc: Aboveground-contact w/ impervious barrier
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: ADAM VAN HISE
Tank Owner Address: 707 WESTCHESTER AVE. WHITE PLAINS, NY. 10604

Material Information

Material Name: Diesel (E-Gen)
Percent: 100.00

Equipment Information

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Tank Information

Prog No: 9-601759
Tank ID: 274175
Tank No: D94207
Tank Status: 1
Tank Status Desc: In Service
Tank Type: 01
Tank Type Desc: Steel/Carbon Steel/Iron
UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:
Tank Next Test Due:
Test Method: -
Line Last Test Due:

Install Date:	02/01/2014	***Next Line Test Due:***	
Close Date:		***Line Test Method:***	-
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	2000	***Class B Operator:***	
Registered:	True	***Modified by:***	PTDIEZ
Tank Model:		***Last Modified:***	09/09/2022
Pipe Model:			

Tank Location: 6
Tank Location Desc: Aboveground in Subterranean Vault w/ access for inspections
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: ADAM VAN HISE
Tank Owner Address: 707 WESTCHESTER AVE. WHITE PLAINS, NY. 10604

Material Information

Material Name: Diesel (E-Gen)
Percent: 100.00

Equipment Information

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: C03
Code Name: Aboveground/Underground Combination
Type: Pipe Location

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F05
Code Name: Jacketed
Type: Pipe External Protection

Equipment: D11
Code Name: Flexible Piping
Type: Pipe Type

Equipment: E00
Code Name: None
Type: Piping Secondary Containment

Equipment: G04
Code Name: Double-Walled (Underground)
Type: Tank Secondary Containment

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment:	L01
Code Name:	Interstitial - Electronic Monitoring
Type:	Piping Leak Detection

Affiliation Information

Affiliation Type:	11
Affiliation Name:	Emergency Contact
Affiliation Sub Type:	NNN
Company:	SEAVEST CORE BUFFALO CONVENTUS
Contact Title:	PROPERTY MANAGER
Contact Name:	ADAM VAN HISE
Address1:	
Address2:	
City:	
State:	NY
Zip Code:	
Country Code:	001
Phone:	(716) 336-2142
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	04
Affiliation Name:	Facility Operator
Affiliation Sub Type:	NNN
Company:	CONVENTUS BUILDING
Contact Title:	
Contact Name:	SK MEDICAL MANAGEMENT, AS AGENT FOR OWNER
Address1:	
Address2:	
City:	
State:	NY
Zip Code:	
Country Code:	001
Phone:	(716) 332-2142
Phone Ext:	
Email:	
Fax:	

Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	SEAVEST CORE BUFFALO CONVENTUS LLC C/O SK MEDICAL MANAGEMENT
Contact Title:	PROPERTY MANAGER, AS AGENT FOR OWNER
Contact Name:	ADAM VAN HISE
Address1:	101 W. BIG BEAVER ROAD
Address2:	SUITE 200
City:	TROY
State:	MI
Zip Code:	48084
Country Code:	001
Phone:	(716) 336-2142
Phone Ext:	
Email:	ADAMVANHISE@SKMEDICALMANAGEMENT.COM
Fax:	

Affiliation Type:	01
Affiliation Name:	Facility Owner
Affiliation Sub Type:	E
Company:	SEAVEST CORE BUFFALO CONVENTUS, LLC
Contact Title:	PROPERTY MANAGER, AS AGENT FOR OWNER
Contact Name:	ADAM VAN HISE
Address1:	707 WESTCHESTER AVE.
Address2:	
City:	WHITE PLAINS
State:	NY
Zip Code:	10604

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Country Code: 001
Phone: (914) 269-0910
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	10 of 19	WSW	0.12 / 641.48	660.19 / 16	ATHENEX INC 1001 MAIN ST STE 600 CONVENTUS BUILDING BUFFALO NY 14203	RCRA SQG

EPA Handler ID: NYR000234906
Gen Status Universe: Small Quantity Generator
Contact Name: JEFF CONTINO
Contact Address: 3805, LAKE SHORE DR EAST, DUNKIRK, NY, 14048, US
Contact Phone No and Ext: 716-363-2306
Contact Email: JCONTINO@ATHENEX.COM
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20210615
Location Latitude: 42.901153
Location Longitude: -78.86912

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date: 20210902
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20180207
Handler Name: ATHENEX INC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F004
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20210615
Handler Name: ATHENEX INC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Code: U197
Waste Code Description: 2,5-CYCLOHEXADIENE-1,4-DIONE (OR) P-BENZOQUINONE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	350
Type:	Private	**Street 1:**	ESSJAY RD
Name:	CONVENTUS PARTNERS LLC	**Street 2:**	
Date Became Current:	20150401	**City:**	WILLIAMSVILLE
Date Ended Current:		**State:**	NY
Phone:	716-631-8000	**Country:**	US
Source Type:	Notification	**Zip Code:**	14221

Owner/Operator Ind:	Current Operator	**Street No:**	1001
Type:	Other	**Street 1:**	MAIN ST SUITE 600
Name:	ATHENEX INC	**Street 2:**	CONVENTUS BUILDING
Date Became Current:	20151030	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-427-2950	**Country:**	US
Source Type:	Notification	**Zip Code:**	14203

Owner/Operator Ind:	Current Operator	**Street No:**	1001
Type:	Other	**Street 1:**	MAIN ST STE 600 CONVENTUS BUILDING
Name:	ATHENEX INC	**Street 2:**	
Date Became Current:	20151030	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-427-2950	**Country:**	US
Source Type:	Notification	**Zip Code:**	14203

Historical Handler Details

Receive Dt: 20180207
Generator Code Description: Small Quantity Generator
Handler Name: ATHENEX INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	11 of 19	WSW	0.12 / 641.48	660.19 / 16	ATHENEX INC 1001 MAIN ST SUITE 600 CONVENTUS BUILDING BUFFALO NY 14203	GEN MANIFEST

RCRA ID:	NYR000234906	**Mailing State:**	NY
District Name:	ATHENEX INC	**Mailing ZIP:**	14203
Contact Name:	ATHENEX INC	**Mailing ZIP Ext:**	
Business Phone No:		**Mailing Country:**	USA
Mailing Street 1:	1001 MAIN ST SUITE 600 CONVENTUS BUILDING	**Location ZIP Ext:**	
Mailing Street 2:		**Location Country:**	USA
Mailing City:	BUFFALO	**Location County:**	ERIE

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 7 Pounds; 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 2 Pounds
2018: 39 Pounds; 1 Pounds; 1 Pounds; 16 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2018: 14 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 480 Pounds; 50 Pounds; 2 Pounds; 480 Pounds; 300 Pounds
2018: 200 Pounds; 300 Pounds; 1 Pounds; 200 Pounds; 300 Pounds; 82 Pounds; 325 Pounds; 300 Pounds; 300 Pounds; 300 Pounds; 200 Pounds; 300 Pounds; 200 Pounds; 300 Pounds; 81 Pounds; 1 Pounds; 200 Pounds; 200 Pounds; 150 Pounds; 400 Pounds; 400 Pounds; 175 Pounds; 325 Pounds

Manifest Information

Waste Code(s):

D009: MERCURY (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 5 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D038: PYRIDINE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2017: 240 Pounds; 30 Pounds; 150 Pounds; 240 Pounds; 240 Pounds; 150 Pounds
2018: 100 Pounds; 200 Pounds; 220 Pounds; 140 Pounds; 75 Pounds; 200 Pounds; 240 Pounds; 100 Pounds; 50 Pounds; 150 Pounds; 200 Pounds; 150 Pounds; 200 Pounds; 175 Pounds; 240 Pounds; 240 Pounds; 240 Pounds; 80 Pounds; 200 Pounds; 200 Pounds; 125 Pounds; 125 Pounds; 240 Pounds; 40 Pounds; 200 Pounds; 200 Pounds; 240 Pounds; 200 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 6 Pounds; 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2017: 71 Pounds; 33 Pounds
2018: 36 Pounds; 50 Pounds; 48 Pounds; 21 Pounds; 87 Pounds; 60 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U123: (64-18-6) Formic acid (C,T)

Waste Amounts By Year:

2018: 1 Pounds

Manifest Information

Waste Code(s):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2018: 60 Pounds; 80 Pounds; 1 Pounds; 100 Pounds; 250 Pounds; 50 Pounds; 60 Pounds

---

27	12 of 19	WSW	0.12 / 641.48	660.19 / 16	MOBIL SERVICE STATION 99-MST FORMER 1001 MAIN ST BUFFALO NY 14203	GEN MANIFEST

RCRA ID:	NYR000215533	***Mailing State:***	NY
District Name:	MOBIL SERVICE STATION 99-MST FORMER	***Mailing ZIP:***	14203
Contact Name:	MOBIL SERVICE STATION 99-MST FORMER	***Mailing ZIP Ext:***	
Business Phone No:		***Mailing Country:***	USA
Mailing Street 1:	1001 MAIN ST	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2015: 165 Gallons; 800 Pounds

27	13 of 19	WSW	0.12 / 641.48	660.19 / 16	CURIA GLOBAL INC - MAIN ST 1001 MAIN ST STE 700 BUFFALO NY 14203	GEN MANIFEST

RCRA ID:	NYR000218347	***Mailing State:***	NY
District Name:	CURIA GLOBAL INC - MAIN ST	***Mailing ZIP:***	14203
Contact Name:	ALBANY MOLECULAR RESEARCH INC	***Mailing ZIP Ext:***	
Business Phone No:	5185122000	***Mailing Country:***	USA
Mailing Street 1:	1001 MAIN ST	***Location ZIP Ext:***	
Mailing Street 2:	STE 700	***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2017: 1 Pounds
2018: 2 Pounds; 1 Pounds; 1 Pounds; 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
P095: (75-44-5) Phosgene

Waste Amounts By Year:

2018: .25 Pounds

Manifest Information

Waste Code(s):

D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 1 Pounds; 1 Pounds

Manifest Information

Waste Code(s):

D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2016: 200 Pounds; 100 Pounds
2017: 50 Pounds; 50 Pounds; 60 Pounds; 40 Pounds; 50 Pounds; 50 Pounds; 50 Pounds; 100 Pounds
2018: 50 Pounds; 50 Pounds; 50 Pounds; 50 Pounds; 100 Pounds; 50 Pounds; 50 Pounds; 50 Pounds; 50 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*

Waste Amounts By Year:

2018: 15 Pounds

Manifest Information

Waste Code(s):

D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)

Waste Amounts By Year:

2016: 800 Pounds; 1200 Pounds; 450 Pounds; 400 Pounds
2017: 400 Pounds; 500 Pounds; 800 Pounds; 800 Pounds; 800 Pounds; 500 Pounds; 400 Pounds; 400 Pounds; 400 Pounds; 400 Pounds; 400 Pounds; 800 Pounds; 450 Pounds
2018: 400 Pounds; 800 Pounds; 400 Pounds; 800 Pounds; 400 Pounds; 400 Pounds; 400 Pounds; 400 Pounds; 400 Pounds; 200 Pounds

Manifest Information

Waste Code(s):

D022: CHLOROFORM (Waste Code Description from EPA Hazardous Waste Identification)
F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2016: 400 Pounds; 150 Pounds; 30 Pounds; 300 Pounds
2017: 400 Pounds; 400 Pounds; 400 Pounds; 400 Pounds; 350 Pounds; 400 Pounds; 400 Pounds; 420 Pounds; 400 Pounds; 400 Pounds
2018: 1400 Pounds; 350 Pounds; 350 Pounds; 700 Pounds; 350 Pounds; 350 Pounds; 350 Pounds; 700 Pounds; 350 Pounds; 350 Pounds; 700 Pounds

Manifest Information

Waste Code(s):

F002: (Generic) The following spent halogenated solvents: tetrachloro-ethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2- trifluoroethane, orthodichlorobenzene, trichlorofluoromethane and 1,1,2-trichloroethane; all spent solvent

mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004 or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (T)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume) of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2016: 150 Pounds; 100 Pounds; 100 Pounds; 100 Pounds
2017: 75 Pounds; 90 Pounds; 50 Pounds; 30 Pounds; 110 Pounds; 50 Pounds; 60 Pounds; 60 Pounds; 150 Pounds; 250 Pounds; 80 Pounds
2018: 150 Pounds; 100 Pounds; 100 Pounds; 50 Pounds; 50 Pounds; 50 Pounds; 50 Pounds; 50 Pounds; 50 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 1 Pounds; 1 Pounds; 1 Pounds; 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2018: 5 Pounds; 1 Pounds; 1 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D002: CORROSIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D003: REACTIVE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
U113: (140-88-5) 2-Propenoic acid, ethyl ester (I)

Waste Amounts By Year:

2018: 2 Pounds

Manifest Information

Waste Code(s):

D001: IGNITABLE WASTE (Waste Code Description from EPA Hazardous Waste Identification)
D018: BENZENE (Waste Code Description from EPA Hazardous Waste Identification)
F003: (Generic) The following spent nonhalogenated solvents: xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent nonhalogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above nonhalogenated solvents, and a total of 10 percent or more (by volume)

of one or more of those solvents listed in F001, F002, F004 and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I)*
F005: (Generic) The following spent nonhalogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, and pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of 10 percent or more (by volume) of one or more of the above nonhalogenated solvents or those solvents listed in F001, F002 or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures. (I,T)

Waste Amounts By Year:

2016: 300 Pounds; 400 Pounds; 400 Pounds; 400 Pounds
2017: 400 Pounds; 200 Pounds; 400 Pounds; 400 Pounds; 350 Pounds; 400 Pounds; 800 Pounds; 320 Pounds
2018: 350 Pounds; 350 Pounds; 400 Pounds; 350 Pounds; 400 Pounds

---

27	14 of 19	WSW	0.12 / 641.48	660.19 / 16	**Albany Molecular Research, Inc.** **1001 Main St, Suite 110** **Buffalo NY 14203**	TIER 2

Company Name: Albany Molecular Research, Inc.
DUN Bradstreet Cd: 78-779-3900
County: Erie
Latitude: 42.901090
Longitude: -78.868870
Report Method: Reported Online

27	15 of 19	WSW	0.12 / 641.48	660.19 / 16	**CONVENTUS CONVENTUS** **1001 Main Street** **Buffalo NY 14203**	ALT FUELS

Fuel Type Code: ELEC: Electric
Station Phone: 888-758-4389
Expected Date:
BD Blends:
NG Fill Type Code:
NG PSI:
Federal Agency ID:
Open Date: 2020-08-11
NG Vehicle Class:
LPG Primary:
E85 Blender Pump:
NG Fill Type Desc:
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2023-01-02
Restricted Access:
Fed Agency Name:
Hydrogen Status Link:
Status: Open: The station is open.
Owner Type Desc:
E85 Blender Pump Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
LPG Primary Desc:
E85 Other Ethanol Blends:
EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
Intersection Directions:

ID: 165111
Updated at: 2023-01-02 23:24:29 UTC
CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 42.900489
Longitude: -78.868369

27	16 of 19	WSW	0.12 / 641.48	660.19 / 16	**1001 Main Street** **Buffalo NY 14203**	COOLING TOWERS

Equip Unique ID: 14228
Cooling Capacity: 1085

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: Ecapco
Model: ECO-ATWB-24-5N40-R
Bacteriological Sample Dt: 06/14/2022
Legionella Sample Coll Dt: 05/10/2022
Last Legionella Sample Result: no
Street Address: 1001 Main Street
New Georeferenced Column: 1001 Main Street
Buffalo, ny 14203
(42.901168, -78.869315)

Cool Capacity Unit: Tonnage
Commissioned Dt: 04/01/2015
Inspection Dt: 05/10/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	17 of 19	WSW	0.12 / 641.48	660.19 / 16	1001 Main Street Buffalo NY 14203	COOLING TOWERS

Equip Unique ID: 14229
Equipment County: Erie
Equipment Borough:
Intended Use: Air Conditioning
Manufacturer: Evapco
Model: ECO-ATWB 24-5N40-R
Bacteriological Sample Dt: 06/14/2022
Legionella Sample Coll Dt: 05/10/2022
Last Legionella Sample Result: no
Street Address: 1001 Main Street
New Georeferenced Column: 1001 Main Street
Buffalo, ny 14203
(42.901168, -78.869315)

Cooling Capacity: 1085
Cool Capacity Unit: Tonnage
Commissioned Dt: 04/01/2015
Inspection Dt: 05/10/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	18 of 19	WSW	0.12 / 641.48	660.19 / 16	Albany Molecular Research, Inc. 1001 Main St, Suite 110 Buffalo NY NY	TIER 2

Company Name: Albany Molecular Research, Inc.
DUN Bradstreet Cd: 78-779-3900
County: Erie
Latitude: 42.901090
Longitude: -78.868870
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	19 of 19	WSW	0.12 / 641.48	660.19 / 16	Albany Molecular Research, Inc. 1001 Main St, Suite 110 Buffalo NY Erie	TIER 2

Company Name: Albany Molecular Research, Inc.
DUN Bradstreet Cd: 78-779-3900
County: NY
Latitude: 42.901090
Longitude: -78.868870
Report Method: Reported Online

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
28	1 of 1	WNW	0.12 / 641.59	648.82 / 4	MAIN - SUMMER CORPORATION MAIN & SUMMER STREETS BUFFALO NY	LST

Spill No: 8908322
Site ID: 197277
DER Facility ID: 164194
CID:
Program Type: ER

REM Phase: 0
UST Trust: False
Spill Date: 1989-11-20 10:00:00
Rcvd Date: 1989-11-20 12:10:00
CAC Date: 1990-02-12 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	1502	**Insp Date:**	1989-11-30 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1990-04-02 00:00:00
Water Body:		**Create Date:**	1989-11-22 00:00:00
Class:		**Update Date:**	1990-04-10 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	LYONS
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK FOUND AT MAIN AND SUMMER SITE WHILE DIGGING FOR FOOTER"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 11/20/89: MEL INSPECTON. TANK REMOVED FROM GROUND, NO CONTAMINATED SOIL OBSERVED IN EXCAVATION. TANK FILLED WITH SAND. TOLD MR. CORDES THAT TANK HAD TO BE CLEANED, AND SAND IN TANK PROPERLY DISPOSED. 12/11/89: RNL TELCON WITH DICK DALEY FROM ELMWOOD TANK. MR. DALEY NOTIFIED DEC THAT ELMWOOD TANK WAS TO DO CLEAN UP WORK. 03/07/90: MEL RECIEVED PROPER RECIEPTS FROM DISPOSAL OF CONTAMINATED MATERIALS. NO FURTHER ACTION NECESSARY, RECOMMEND FILE BE CLOSED. 11/30/90: MEL INSPECTION. TANK, AND SOIL IN TANK, STILL ON SITE. SPOKE WITH OWNER, WHO SAID THAT ELMWOOD TANK WOULD BE REMOVING TANK AND CONTAMINATED SOIL. TO SEND IN RECIEPTS. "

Material Information

OP Unit ID:	933377	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	445070	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	5.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	MAIN-SUMMER CORPORATION
Spiller Address:	25 SUMMER STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14209
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.904616994
Longitude:	-78.868166934

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
29	1 of 2	WSW	0.12 / 655.66	655.81 / 11	WENDY,S MAIN AND NORTH STREETS BUFFALO NY	NY SPILLS

Spill No:	8911108	**UST Trust:**	False
Site ID:	147439	**Spill Date:**	1990-02-17 12:00:00
DER Facility ID:	125509	**Received Date:**	1990-02-22 08:52:00
CID:		**CAC Date:**	1990-03-12 00:00:00
Program Type:	ER	**Insp Date:**	1990-03-05 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	1502	**Close Date:**	1990-03-12 00:00:00
Water Body:		**Create Date:**	1990-02-22 00:00:00
Class:		**Update Date:**	1990-03-26 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FIX
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"ON GOING SPILLAGE IN BACK OF WENDY,S DRAWING RATS.WENDY,S REFUSES TO RECOGNIZE PROBLEM WHEN CONFRONTED BY CALLER."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CAF 03/05/90: CAF SITE VISIT UNABLE TO FIND SPILL. 03/12/90: CAF TELCON WITH MS. MCCUDDEN SHE SAID SPILL WAS CLEANED UP THE DAY AFTER SHE CALLED IT IN.NO FURTHER ACTION PLANNED. 09/29/95: This is additional information about material spilled from the translation of the old spill file: GREASE FROM FRYER."

Material Information

OP Unit ID:	938093	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	440650	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0016A		
Material Name:	non PCB oil		

Spiller Information

Spiller Name:	
Spiller Company:	WENDY,S
Spiller Address:	
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902196961
Longitude:	-78.868970957

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
29	2 of 2	WSW	0.12 / 655.66	655.81 / 11	A.R.G. TRUCKING CO. MAIN AND NORTH ST. BUFFALO NY	LST

Spill No:	8607168	**REM Phase:**	0
Site ID:	193501	**UST Trust:**	False
DER Facility ID:	161329	**Spill Date:**	1987-02-24 10:00:00
CID:		**Rcvd Date:**	1987-02-24 16:19:00
Program Type:	ER	**CAC Date:**	1987-02-24 00:00:00
SWIS Code:	1502	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	1987-02-24 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Body:		**Create Date:**	2003-12-02 00:00:00
Class:		**Update Date:**	2003-12-02 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	ROSS
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Tank Truck		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SPILL OCCURED AND NSI GAS STATION"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR / / : F.D. FLSHED TO SEWER. "

Material Information

OP Unit ID:	903852	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	472690	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	True
Quantity:	30.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	A.R.G. TRUCKING CO.
Spiller Address:	
Spiller City:	TONAWANDA
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902196961
Longitude:	-78.868970957

30	1 of 1	ESE	0.13 / 685.33	669.63 / 25	OIL IN STREET 336 MAPLE BUFFALO NY	NY SPILLS

Spill No:	0750965	**UST Trust:**	
Site ID:	388438	**Spill Date:**	2007-10-01 12:00:00
DER Facility ID:	337945	**Received Date:**	2007-10-12 12:30:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2007-10-17 00:00:00
Water Body:		**Create Date:**	2007-10-12 12:34:00
Class:	D4	**Update Date:**	2007-10-17 08:32:51.177000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	fxgalleg
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Housekeeping		

Reported by: Other
Referred to:
Source: Passenger Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Passenger vehicle continues to spill oil all over the street and the city would like the Dept to enforce against the spiller. City will send a street sweeper to clean it up."

DEC Remark:

"10/17/07 FG SITE INSPECTION. FOUND ONLY A STAIN ON THE STREET. NO ACTION POSSIBLE. SPILL CLOSED. ELECTRONIC FILE ONLY. SPILL REFERRED TO LAW ENFORCEMENT PER CALLERS REQUEST."

Material Information

OP Unit ID:	1145612	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2135944	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	True
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	False
Med Air:	False		

Material Code: 0022
Material Name: waste oil/used oil

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City:
Spiller State:
Spiller Zip:
Spiller Country:
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.901264016
Longitude: -78.861766338

31	1 of 1	NW	0.13 / 691.54	650.56 / 6	1155 Main Street 1155 Main Street Buffalo NY 14209	BROWNFIELDS

Site Code: 579132
HW Code: C915341
Program: BCP
Site Class: C
Site Name: 1155 Main Street
Site Address: 1155 Main Street
City: Buffalo
Zip: 14209
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.905361111
Longitude: -78.867222222
SWIS: 1502
Acres: 1.551
Record Added: 2018-11-05 14:23:00

Record Update:	2022-04-01 08:27:00
Updated by:	AECAPRIO
Site Code (Web):	C915341
Program Type (Web):	BCP
Site Name (Web):	1155 Main Street
Site Class (Web):	C
Address1 (Web):	1155 Main Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14209
County (Web):	Erie
Longitude (Web):	-78.867222222
Latitude (Web):	42.905361111
Site Code (GIS):	C915341
Site Name (GIS):	1155 Main Street
Program (GIS):	BCP
Site Class (GIS):	C
Address1 (GIS):	1155 Main Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14209
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Actions taken at the site have eliminated the potential for exposure to contaminated soil. The area is served by a public water supply that is not affected by site contamination. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into nearby buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Soil vapor intrusion is not a current concern as the site is vacant.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were polycyclic aromatic hydrocarbons (PAHs), metals and pesticides in soil and chlorinated volatile organic compounds and metal in groundwater. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Residual contamination in groundwater is managed by municipal code which prohibits the use of groundwater in the City of Buffalo. A soil vapor assessment will be completed post building construction. If soil vapor requires mitigation, the mitigation system will be managed under the site management plan for the site.

Description:

Location: The 1155 Main Street site is an approximately 1.551-acre site located in a highly developed commercial/residential area at 1155 Main Street in the City of Buffalo, Erie County. The site is bordered by Dodge Street to the north, Main Street to the west, a parking lot and the Summer-Best Transit Station to the south and Osmose Utility Services to the east. Site Features: The site is currently being developed with construction of a mixed use commercial and residential building. Zoning and Land Use: The site is zoned N-1C, which is mixed use mid-rise development at the edge of downtown. Planned development is a mixed-use residential and commercial. Past Use of the Site: The site was used as a gasoline filling station from approximately 1924 until approximately 1947, a pre-owned automobile sales lot from the 1940s until the 1960s and as a motel from the 1950s until 2014. Other portions of the site were used for residential purposes until the 1950s. After the buildings were demolished, the site was used as a parking lot. Site Geology and Hydrogeology: Investigations have identified the site geology below the surface cover as urban fill (brick, ash, concrete, etc.)ranging in thickness from 1.0 to 9.0 feet below ground surface (fbgs), underlain by native soils consisting of silty fine sands and silty clay. Bedrock is estimated to be present at over 50 fbgs. The depth to groundwater ranges between 15.6 and 24.3 fbgs, with flow in a northwesterly direction, towards the Niagara River.

Materials Information

Waste Name:	yohimban-16-carboxylic acid,11,17-dimethoxy-18- [(3,4,5-trimethoxybenzoyl)oxy]-,methylester
Waste Quantity:	UNKNOWN
Waste Code:	
Waste Name:	sodium
Waste Quantity:	UNKNOWN
Waste Code:	

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: acetone
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: lead
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(b)fluoranthene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: iron
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DDE
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DDD
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: aldrin
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dibenz[a,h]anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: manganese
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: toluene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: DDT
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: indeno(1,2,3-CD)pyrene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: chrysene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(a)anthracene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: benzo(k)fluoranthene

Waste Quantity: UNKNOWN
Waste Code:

Waste Name: magnesium
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: P03
Owner Name: Dr. Fadi Dagher
Owner Company: Main & Dodge LLC
Owner Street: 50 Lakefront Boulevard, Suite 103
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: April Thompkins
Owner Company: Buffalo & Erie County Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Dr. Fadi Dagher
Owner Company: Main & Dodge LLC
Owner Street: 50 Lakefront Boulevard, Suite 103
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: SMQUANDT

Record Added: 2019-05-07 11:57:00
Record Updated: 2019-12-13 11:05:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2019-12-13 00:00:00
End Status: ACT
Operable Unit ID: 1326861
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 05

Project Desc: Remedial Action
Project Refer Name:
End Date: 2019-12-16 00:00:00
End Status: ACT
Operable Unit ID: 1326861
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 25
Project Desc:
Project Refer Name: Certificate of Completion (COC)
End Date: 2019-12-16 00:00:00
End Status: ACT
Operable Unit ID: 1346462
Operable Unit: 00
Operable Unit Desc: Site Management
Code Name: Certificate of Completion

Project Code: 05
Project Desc: Remedial Action
Project Refer Name: IRM - Urban Fill Removal
End Date: 2019-12-16 00:00:00
End Status: ACT
Operable Unit ID: 1326861
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Environmental Remediation

Operable Unit: 01A
Contaminants: DDD, DDE, DDT, acetone, aldrin, arsenic, benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz[a,h]anthracene, indeno(1,2,3-cd)pyrene, iron, lead, magnesium, manganese, mercury, sodium, tetrachloroethene (PCE), toluene, yohimban-16-carboxylic acid,11,17-dimethoxy-18- [(3,4,5-trimethoxybenzoyl)oxy] -,methylester

Operable Unit: 01
Contaminants: DDD, DDE, DDT, acetone, aldrin, arsenic, benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz[a,h]anthracene, indeno(1,2,3-cd)pyrene, iron, lead, magnesium, manganese, mercury, sodium, tetrachloroethene (PCE), toluene, yohimban-16-carboxylic acid,11,17-dimethoxy-18- [(3,4,5-trimethoxybenzoyl)oxy] -,methylester

Operable Unit: 00
Contaminants: DDD, DDE, DDT, acetone, aldrin, arsenic, benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, dibenz[a,h]anthracene, indeno(1,2,3-cd)pyrene, iron, lead, magnesium, manganese, mercury, sodium, tetrachloroethene (PCE), toluene, yohimban-16-carboxylic acid,11,17-dimethoxy-18- [(3,4,5-trimethoxybenzoyl)oxy] -,methylester

---

32	1 of 1	E	0.13 / 705.71	669.97 / 26	**CITY HONORS SCHOOL NO. 195** **186 E. NORTH STREET** **Buffalo NY 14209**	AST

Site ID: 55323
Site Status: Active
Program No: 9-600476
Program Type Code: PBS
Program Type Desc: Petroleum Bulk Storage Program
Site Type: School

Expiry: 2019/12/02
County: Erie
UTM X: 184762.24708
UTM Y: 4757276.56656

Tank Information

Prog No: 9-600476
Tank ID: 173797
Tank No: 1
Tank Status: 1

UDC Ind: 0
Red Tag Start Date:
Red Tag End Date:
Tank Last Test:

Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	12/01/1999	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	5100	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 6
Tank Location Desc: Aboveground in Subterranean Vault w/ access for inspections
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: G02
Code Name: Vault (w/access)
Type: Tank Secondary Containment

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: E02
Code Name: Vault (with Access)
Type: Piping Secondary Containment

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: F01

Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Tank Information

Prog No:	9-600476	**UDC Ind:**	0
Tank ID:	173798	**Red Tag Start Date:**	
Tank No:	2	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	12/01/1999	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	5100	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 6
Tank Location Desc: Aboveground in Subterranean Vault w/ access for inspections
Category: 2
Category Desc: Category 2 means a tank which was installed from December 27, 1986 through October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: L09
Code Name: Exempt Suction Piping
Type: Piping Leak Detection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: F01
Code Name: Painted/Asphalt Coating
Type: Pipe External Protection

Equipment: K00
Code Name: None
Type: Spill Prevention

Equipment: G02
Code Name: Vault (w/access)
Type: Tank Secondary Containment

Equipment: E02
Code Name: Vault (with Access)

Type: Piping Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: H99
Code Name: Other
Type: Tank Leak Detection

Equipment: D01
Code Name: Steel/Carbon Steel/Iron
Type: Pipe Type

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Affiliation Information

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: CITY HONORS SCHOOL NO. 195
Contact Title:
Contact Name: MIKE BENZ
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (716) 816-4230
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: CITY OF BUFFALO
Contact Title:
Contact Name: BARRY KIRKER JR.
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (716) 818-7822
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: C01
Company: CITY OF BUFFALO
Contact Title: EXECUTIVE DIRECTOR OF PLANT SERVICES
Contact Name: JOSEPH P. GIUSIANA
Address1: 65 NIAGARA SQUARE - ROOM 901
Address2:
City: BUFFALO
State: NY
Zip Code: 14202
Country Code: 001
Phone: (716) 851-5275
Phone Ext:

Email:
Fax:

Affiliation Type:	07
Affiliation Name:	Mail Contact
Affiliation Sub Type:	NNN
Company:	BUFFALO BOARD OF EDUCATION
Contact Title:	
Contact Name:	JOSEPH P. GIUSIANA
Address1:	RM 403 CITY HALL
Address2:	
City:	BUFFALO
State:	NY
Zip Code:	14202
Country Code:	001
Phone:	(716) 816-3652
Phone Ext:	
Email:	JGIUSIANA@BUFFALOSCHOOLS.ORG
Fax:	

33 ***1 of 1*** ***SSW*** ***0.13 / 708.44*** ***662.64 / 18*** ***PARKING LOT - HOSPITAL CARLTON & OAK / HIGH ST. BUFFALO NY*** ***NY SPILLS***

Spill No:	1810147	***UST Trust:***	False
Site ID:	581027	***Spill Date:***	2019-01-04 06:23:00
DER Facility ID:	533605	***Received Date:***	2019-01-04 06:35:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2019-01-08 00:00:00
Water Body:		***Create Date:***	2019-01-04 06:38:00
Class:		***Update Date:***	2019-01-08 09:35:45.503000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	TDJOHNSO
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"contained to paved parking lot clean up is in progress"

DEC Remark:

"01/04/19 TDJ WENT TO LOCATION WHERE SPEEDY DRY AND PADS WERE PLACED NEAR STORM RECEIVER. MODERN REP. STATED THAT APPROX. 10 GALLONS OF HYDRAULIC FLUID HAD REACED THE ASPHALT AND POSSIBLY 2 GALLONS REACHED THE RECEIVER. THE RECEIVER LED TO A HOLDING TANK IN THE YARD WHICH HAD LIGHT FILM. MODERN HAD A CREW COMING TO REMOVE SPEEDY DRY AND A VAC TRUCK TO PUMP OUT THE LINE AND HOLDING TANK. 01/05/19 TDJ RECEIVED PICTURES OF CLEANUP FROM MODERN REP. MATERIAL WAS SWEPT UP AND DISPOSED BY MODERN AT THEIR FACILITY. NO DISPOSAL RECEIPT WAS REQUESTED. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1328736	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2337755	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	20.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Code: 0010
Material Name: hydraulic oil

Spiller Information

Spiller Name: ERIC PRENTISS
Spiller Company: UNKNOWN
Spiller Address: CARLTON & OAK / HIGH ST.
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: ERIC PRENTISS
Contact Phone: (716) 851-5510
Contact Ext:
Latitude:
Longitude:

34	1 of 1	SSW	0.13 / 712.17	661.98 / 18	HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI HIGH STREET BUFFALO NY 14203	RCRA VSQG

EPA Handler ID: NYR000130849
Gen Status Universe: VSG
Contact Name: CARLEEN POPE
Contact Address: US
Contact Phone No and Ext: 716-898-8661 POPE
Contact Email: CPOPE@HWI.BUFFALO.EDU
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20070101
Location Latitude: 42.900325
Location Longitude: -78.86631

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2

Receive Date: 20070101
Handler Name: HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060223
Handler Name: HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20050222
Handler Name: HAUPTMAN - WOODWARD MEDICAL RESEARCH
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: P104
Waste Code Description: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: U070
Waste Code Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Hazardous Waste Code: U136
Waste Code Description: ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P010
Waste Code Description: ARSENIC ACID H3ASO4

Hazardous Waste Code: P029
Waste Code Description: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: P101
Waste Code Description: ETHYL CYANIDE (OR) PROPANENITRILE

Hazardous Waste Code: U007
Waste Code Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F004
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U022
Waste Code Description: BENZO[A]PYRENE

Hazardous Waste Code: U052
Waste Code Description: CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-

Hazardous Waste Code: U077
Waste Code Description: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: U187
Waste Code Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: U201
Waste Code Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Hazardous Waste Code: U246
Waste Code Description: CYANOGEN BROMIDE (CN)BR

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060224
Handler Name: HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: U196
Waste Code Description: PYRIDINE

Hazardous Waste Code: U201
Waste Code Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Hazardous Waste Code: U211
Waste Code Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Hazardous Waste Code: U217
Waste Code Description: NITRIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) NITRATE

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: U246
Waste Code Description: CYANOGEN BROMIDE (CN)BR

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: P098

Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: P101
Waste Code Description: ETHYL CYANIDE (OR) PROPANENITRILE

Hazardous Waste Code: P104
Waste Code Description: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U012
Waste Code Description: ANILINE (I,T) (OR) BENZENAMINE (I,T)

Hazardous Waste Code: U019
Waste Code Description: BENZENE (I,T)

Hazardous Waste Code: U022
Waste Code Description: BENZO[A]PYRENE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: U052
Waste Code Description: CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-

Hazardous Waste Code: U096
Waste Code Description: ALPHA,ALPHA-DIMETHYLBENZYLHYDROPEROXIDE (R) (OR) HYDROPEROXIDE, 1-METHYL-1-PHENYLETHYL- (R)

Hazardous Waste Code: U108
Waste Code Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Hazardous Waste Code: U136
Waste Code Description: ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: P014
Waste Code Description: BENZENETHIOL (OR) THIOPHENOL

Hazardous Waste Code: P018
Waste Code Description: BRUCINE (OR) STRYCHNIDIN-10-ONE, 2,3-DIMETHOXY-

Hazardous Waste Code: P029
Waste Code Description: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	
Name:	NO NAME FOUND	***Street 2:***	
Date Became Current:	19561101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	ELICOTT
Name:	HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI	***Street 2:***	
Date Became Current:	19561101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	14203

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI	***Street 2:***	
Date Became Current:	19561101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	
Name:	HAUPTMAN-WOODWARD MEDICAL RESEARCH	***Street 2:***	
Date Became Current:	19561101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	NO NAME FOUND	***Street 2:***	
Date Became Current:	19561101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	
Name:	HAUPTMAN-WOODWARD MEDICAL RESEARCH	***Street 2:***	
Date Became Current:	19561101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

Historical Handler Details

Receive Dt: 20050222
Generator Code Description: Small Quantity Generator
Handler Name: HAUPTMAN - WOODWARD MEDICAL RESEARCH

Receive Dt: 20060224

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Small Quantity Generator
Handler Name: HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI

Receive Dt: 20060223
Generator Code Description: Very Small Quantity Generator
Handler Name: HAUPTMAN-WOODWARD MEDICAL RESEARCH INSTI

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	1 of 1	WNW	0.13 / 712.68	648.77 / 4	WORLD AUTO PAINT SHOPS OF BUFFALO INC 1114 MAIN ST BUFFALO NY 14209	RCRA NON GEN

EPA Handler ID: NYD013780267
Gen Status Universe: No Report
Contact Name:
Contact Address: 1114, MAIN ST, BUFFALO, NY, 14209, US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 42.904164
Location Longitude: -78.869022

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date: 20100222
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990714
Handler Name: WORLD AUTO PAINT SHOPS OF BUFFALO INC
Source Type: Implementer

Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19880819
Handler Name: WORLD AUTO PAINT SHOPS OF BUFFALO INC
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: WORLD AUTO PAINT SHOPS OF BUFFALO INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101

Handler Name: WORLD AUTO PAINT SHOPS OF BUFFALO INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	ROBERT DUPREE	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	ROBERT DUPREE	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	ROBERT DUPREE	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Historical Handler Details

Receive Dt: 19880819
Generator Code Description: Large Quantity Generator
Handler Name: WORLD AUTO PAINT SHOPS OF BUFFALO INC

Receive Dt: 19990714
Generator Code Description: Small Quantity Generator
Handler Name: WORLD AUTO PAINT SHOPS OF BUFFALO INC

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: WORLD AUTO PAINT SHOPS OF BUFFALO INC

---

36 | ***1 of 1*** | ***W*** | ***0.14 / 715.44*** | ***650.11 / 6*** | ***ON SITE 1091 MAIN ST BUFFALO NY*** | ***NY SPILLS***

Spill No:	1802722	**UST Trust:**	False
Site ID:	571319	**Spill Date:**	2018-06-08 16:00:00
DER Facility ID:	524452	**Received Date:**	2018-06-08 17:10:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2018-08-16 00:00:00
Water Body:		**Create Date:**	2018-06-08 17:13:00
Class:		**Update Date:**	2018-08-16 15:46:46.087000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"found abandoned tank, contained and clean up is ongoing"

DEC Remark:

"6/8/18 FG spoke to Bryan Mayback with Benchmark. He said the RP discovered the tank during construction and need it removed ASAP. They will be removing the ust and contamination on 6/9/18. 6/11/18 TDJ contacted benchmark and they indicated the work had already been completed. A closure report will be provided. 08/06/18 TDJ RECEIVED FINAL REPORT FOR REMOVAL OF 1,000 GALLON TANK FROM SITE. TANK CLEANING GENERATED 590 GALLONS OF LIQUID/SLUDGE WHICH WAS DISPOSED AT AMERICAN RECYCLERS. APPROX. 20 TON OF CONTAMINATED SOLIDS WERE TAKEN TO WASTE MANAGEMENT/CHAFEE LANDFILL FOR DISPOSAL. CONFIRMATORY SAMPLING RESULTS WERE ALL BELOW CP-51 LIMITS WITH MOST ND. SITE WILL BE CLOSED AS NO FURTHER ACTION. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1319155	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2327123	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	PROPERTY OWNER
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	BRIAN MAVAK
Contact Phone:	(716) 844-1699
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
37	1 of 1	WSW	0.14 / 745.66	658.79 / 14	NIAGARAMO/BRYANT STRATON 1028 MAIN STREET BUFFALO NY	NY SPILLS

Spill No:	9705897	***UST Trust:***	False
Site ID:	265017	***Spill Date:***	1997-08-15 00:30:00
DER Facility ID:	215951	***Received Date:***	1997-08-15 04:10:00
CID:	201	***CAC Date:***	
Program Type:	ER	***Insp Date:***	1997-08-15 00:00:00
SWIS Code:	1502	***Close Date:***	1997-10-09 00:00:00
Water Body:		***Create Date:***	1997-08-15 00:00:00
Class:	C3	***Update Date:***	1997-11-10 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	JFOTTO
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Traffic Accident		
Reported by:	Local Agency		
Referred to:			
Source:	Commercial Vehicle		

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"PICK UP HIT DOWN GUY/CAUSING BANK OF TRANSFORMERS TO FALL TO GROUND CAUSING SPILL/NONE HAS BEEN CLEANED UP AT THIS TIME/SPILL IS CONTAINED BUT UNK AMOUNT (POSS 20 GLS) WENT INTO SEWER"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 08/15/97 JFO ON SITE MET W/FRANK STANCZEWSKI FORMAN FOR NIMO. SPILL CONTAINED, SPILL ON BLACKTOP APPROX 15'X 15'. FIRE DEPT SPREAD SPEEDY-DRY AND PLACED ABSORBANT PILLOWS O AREA. NIMO SENDING CREW TO CLEANUP. 20 GALLONS TO SEWER 30 GALLONS ON BLACKTOP. JOE JORDAN AND DENNIS YOUNG OF BFLO SEWER AUTH ALSO ON SITE. KEN JONES NIMO CLEANUP FORMAN ON SITE. THEY REMOVED APPROX 10-15 GALLONS. SPEEDY DRY PLACED IN DRUMS ALONG WITH OIL FROM SEWER (6-55 GALLON DRUMS). REINSPECTED SITE AT 12:30 CLEANUPO COMPLETED. SAMPLE RESULTS AND DISPOSAL RECEIPTS TO FOLLOW. LTR SENT TO RP 8/19/97, RESPONSE DATE 9/12/97 CC: NIMO 10/6/97 JFO TELCON W/FRANK GRABOWSKI, HE SENT DISPOSAL RECEIPTS AND SAMP RESULTS 10/09/97 JFO REC'D DISP RECEIPTS AND SAMP RESULTS. NO FURTHER ACTION REQUIRED. CLOSED"

Material Information

OP Unit ID:	1052069	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	331507	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	True
Quantity:	50.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	30.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	
Spiller Company:	PINKSTON/NIAGARA MOHAWK
Spiller Address:	306 HUDSON
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14201-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901774360
Longitude:	-78.869262600

38	***1 of 6***	***SE***	***0.14 / 752.03***	***664.46 / 20***	***ROSWELL PARK CANCER INSTI MICHIGAN AT HIGH BUFFALO NY***	***NY SPILLS***

Spill No:	9875088	***UST Trust:***	False
Site ID:	167391	***Spill Date:***	1998-10-05 14:01:00
DER Facility ID:	141035	***Received Date:***	1998-10-05 15:08:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	2000-03-08 00:00:00
SWIS Code:	1502	***Close Date:***	2000-03-08 00:00:00
Water Body:		***Create Date:***	1998-10-05 15:11:00
Class:	B4	***Update Date:***	2000-11-29 00:00:00
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RMCROSSE
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Unknown		

Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"FOUND PETROLEUM CONTAMINATION WHILE REMOVING TANK, TANK NUMBER 105, 570 GALLON DIESEL "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/05/98: RMC TELECON KEVIN CROMIN, GES, TANK BEING REMOVED OVER NEXT TWO DAYS, SOME CONTAMINATION FOUND 10/06/98: RMC TELECON KEVIN CRONIN, TANK REMOVED AND BACKFILLED DUE TO SAFETY REASONS, SOME ODORS REMAINED AFTER ALL THAT COULD BE WAS REMOVED, AREA VERY TIGHT WITH TRAFFIC AND UTILITIES, SAMPLE RESULTS AND DISPOSAL RECEIPTS DUE 12/98 12/16/98: RMC RECEIVED DISPOSAL RECEIPT DIRECTLY FROM OGS FOR 170 TONS. 03/01/99: RMC TELECON KEVIN CROMIN, REQUESTED SAMPLE REPORT, DUE 3/15/99 04/13/99: KAB TELECON JENNIFER RYAN, IT CORP., SHE IS SENDING REPORTS FOR TANK REMOVALS TODAY. WAS CALLING TO CONFIRM THAT ALL TANKS WERE BEING DEALT WITH UNDER THIS SPILL NUMBER. 08/01/99: RMC NOTE TO FILE, IT CORP TO PROVIDE GOOD LOCATION MAP, DUE 8/15 09/28/99: RMC FILE REVIEW, FILE REFLECTS TANK 105 ONLY, LEVELS HIGH, FURTHER ASSESSMENT REQUIRED, LETTER, RESPONSE DUE 1/1/00 10/15/99: RNL NOTE, SEE ALSO SPILL 9975436, REMOVAL OF A I000 GALLON DIESEL TANK, CLOSED 09/27/99, DISPOSAL UNDER THIS SPILL 01/21/00: RMC SENT NO RESPONSE LETTER, UPDATE 2/28/00 02/08/00: RMC TELECON JOHN HLOMQUEST, CAND S ENG, (315-455-2000) THEY DOING SITE ASSESSEMENT PREVIOUSLY AGREED UPON, REPORT DUE 3/30/00 03/08/00: RMC REVIEWED REPORT, ADDTIONAL BORINGS ADVANCED, TESTS SLIGHTLY ABOVE STARS, FURTHER WORK NOT PRACTICAL, NO FURTHER ACTION REQUIRED, INACTIVE, "

Material Information

OP Unit ID:	1078209	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	306671	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	AL G
Spiller Company:	ROSWELL PARK CANCER INST
Spiller Address:	ELM AND CARLTON
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14623-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

38	2 of 6	SE	0.14 / 752.03	664.46 / 20	ROSWELL PARK MICHIGAN & HIGH STREETS BUFFALO NY	NY SPILLS

Spill No:	9504945	**UST Trust:**	False
Site ID:	301544	**Spill Date:**	1995-07-20 14:10:00
DER Facility ID:	243677	**Received Date:**	1995-07-21 09:30:00
CID:		**CAC Date:**	1995-07-27 00:00:00
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1995-07-27 00:00:00
Water Body:		**Create Date:**	1995-07-27 00:00:00
Class:	E5	**Update Date:**	1995-08-04 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Housekeeping		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"POSSIBLE CONTAMINATED SOIL WHEN REMOVING SOIL SOUTH OF POWER PLANT"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 07/27/95: MF 7/21/95 TELECON DAVE COMENALE, ENG FIRM. POSSIBLE CONTAMINATION WHEN DIGGING IN PARKING AREA. SOIL TO BE TESTED FOR 8021 & 8270BN PER STARS. WILL FAX RESULTS TO ME. 07/27/95: MF 7/27/95 RECEIVED FAX OF SAMPLE RESULTS, NO STARS COMPOUNDS DETECTED IN SAMPLES. SOIL PILE 'CLEAN'. NO FURTHER ACTION NECESSARY. "

Material Information

OP Unit ID:	1015857	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	366474	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	NONE
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900295944
Longitude:	-78.863023888

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
38	3 of 6	SE	0.14 / 752.03	664.46 / 20	ROSWELL PARK MICHIGAN AND HIGH BUFFALO NY	LST

Spill No:	9875428	**REM Phase:**	0
Site ID:	309722	**UST Trust:**	True
DER Facility ID:	250034	**Spill Date:**	1999-02-01 12:00:00
CID:		**Rcvd Date:**	1999-03-01 09:19:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	
Contribute Factor:	Tank Overfill	**Close Date:**	1999-03-01 00:00:00
Water Body:		**Create Date:**	1999-03-01 09:25:00
Class:	D4	**Update Date:**	1999-03-31 00:00:00
Meets Std:	False	**DEC Region:**	9

Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SAMPLE RESULTS FROM 2500 GALLON TANK EXCAVATION SHOW MINOR EXCEEDANCE, NO VISUAL CONTAMINATION WAS NOTED AT THE TIME OF EXCAVATION BY THE CONTRACTOR"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 03/01/99: RMC TELECON WITH CRONIN, TANK CLOSURE REPORT SHOWS ONE MINOR EXCEEDANCE, NO FURTHER ACTION REQUIRED, INACTIVE"

Material Information

OP Unit ID:	1074849	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	307068	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	ROSWELL PARK
Spiller Address:	666 ELM STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14263
Spiller Country:	001
Contact Name:	OWEN BYRNE OGS
Contact Phone:	(716) 674-0437
Contact Ext:	
Latitude:	42.900295944
Longitude:	-78.863023888

38	***4 of 6***	***SE***	***0.14 / 752.03***	***664.46 / 20***	***ROSWELL PARK #6 OIL HIGH & MICHIGAN AVENUES BUFFALO NY***	***LST***

Spill No:	8907884	**REM Phase:**	0
Site ID:	286130	**UST Trust:**	False
DER Facility ID:	231904	**Spill Date:**	1989-11-08 23:00:00
CID:		**Rcvd Date:**	1989-11-09 00:13:00
Program Type:	ER	**CAC Date:**	1989-12-12 00:00:00
SWIS Code:	1502	**Insp Date:**	1989-12-04 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	1989-12-12 00:00:00
Water Body:		**Create Date:**	1989-11-09 00:00:00
Class:		**Update Date:**	1996-01-03 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
County:	Erie	**After Hours:**	True
Referred to:			
Reported by:	Affected Persons		

Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"DRIVER UNLOADED FUEL TO WRONG TANK; PRODUCT SPILLED ON STONE PARKING LOT, ALL CONTAINED."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 11/09/89: MF 1300 SITE VISIT, SPILLAGE ALL CONTAINED. SPILL AREA COVERED WITH PLASTIC. 0800 SITE VISIT, ELMWOOD TANK HIRED BY HOSPITAL TO REMEDIATE SPILL. 0930 ELMWOOD ON SITE. 11/17/89: MF 11/16/890 ELMWOOD TANK ON SITE REMEDIATING AREA. 11/17/89 ELMWOOD TANK ON SITE REMEDIATING AREA, WILL NOT BE COMPLEATED TODAY. ROSWELL WILL MONITOR MONDAY. (VACATION). 12/04/89: MF SITE VISIT WITH FRANK VALLONE. THE SPILL AREA HAS BEEN BACKFILLED. ROSWELL PARK IS SATISIFIED WITH THE CLEAN UP. TOLD FRANK OF THE NEED FOR DISPOSAL RECEIPTS. 12/12/89: MF RECEIVED COPY OF THE DISPOSAL RECEIPT. NO FUTHER ACTION NECESSARY BY SPILLS. "

Material Information

OP Unit ID:	935474	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	444659	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1000.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	990.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	NOCO ENERGY
Spiller Address:	700 GRAND ISLAND BLVD
Spiller City:	TONAWANDA
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

---

38 | ***5 of 6*** | ***SE*** | ***0.14 / 752.03*** | ***664.46 / 20*** | ***ROSWELL PARK CANCER INST. MICHIGAN AND HIGH STREETS BUFFALO NY*** | ***LST***

Spill No:	9504008	**REM Phase:**	0
Site ID:	116024	**UST Trust:**	False
DER Facility ID:	100997	**Spill Date:**	1995-07-03 07:00:00
CID:		**Rcvd Date:**	1995-07-03 10:11:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	1996-04-29 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	1996-07-01 00:00:00
Water Body:		**Create Date:**	1995-07-06 00:00:00
Class:	B1	**Update Date:**	1999-03-19 00:00:00
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Institutional, Educational, Gov., Other		

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"OVER FILLED 6 OIL TANK"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 07/03/95: RMC/RAY JONES/AL GUSTAFSON/EPS/SITE EPS GAVE ROSWELL ESTIMATE OF 10 K TO CLEAN UP ESTIMATED 50 GALLON SPILL AROUND CONTAINMENT MH,RMC ADVISED AUTHORIZATION TO CONTRACTOR BY ROSWELL COULD TAKE 6 WEEKS. 07/03/95: RMC/RAY JONES/AL GUSTAFSON/EPS/SITE AFTER TALKING WITH RNL.. DEC+ROSWELL AGREEED DEC TO DO CLEANUP AND BILL ROSWELL FOR COST LATER, ROE SIGNED, EPS AUTHORIZED TO BEGIN. 07/03/95: RMC/EPS/SITE TWO LOADS MATERIAL EXCAVATED,APPEARS SIGNIFICANTLY MORE PRODUCTS SPILLED THAN ORIGINALLY THOUGHT,NO ROOM TO STAGE ON SITE, SUMP DUG TO GIVE PRODUCT PLACE TO ACCUMULATE TILL WED AM. 07/03/95: RMC/FILE CONTACTED HENRY SANDONATO AND ADVISED OF SPILL AND SPACE PROBLEMS, HS AGREED THAT STAGING AT BIG K SITE NOT DESIRABLE BUT HAVE NO OTHER OPTION READILY AVAILABLE,RMC WROTE TRANSPORTER PERMIT. 07/05/95: RMC/SITE WORK UNDER WAY, EPS FOUND LIMITS OF SPILL, AND RECOVERED 300 + GALLONS PURE PRODUCT, FIVE LOADS CONTAMINATED SOIL EXCAVATED, EXCAVATION COMPLETE,. 07/06/95: RMC/SITE RESTORATION WORK BEGUN, CLAY REPLACEMENT COMPLETE, REPLACING STONE NOW, TO DRUM CONTENTS OF VAC TRUCK PENDING DISPOSAL,. 07/06/95: RMC/FILE AUTHORIZATION TO PROCEED AND RP LETTER SENT. 07/14/95: RMC/FILE DISPOSAL AND TESTING DUE 8/30/95. 08/02/95: RNL/EPS/ROSWELL/SITE FOUND ADDITIONAL MINOR SPILLAGE UNDER CONCRETE CURB, EPS TO REMEDIATE, DISPOSAL AND TESTING DUE 8/30/95. 08/10/95: RMC/ROSWELL/JERRY MILNE ENG 3157351960/PEG LAWRENCE ERM 6335920/SITE WENT OVER REQUIRMENT FOR UTILITY EXCAVATIONS,NO ACTION UNLESS FIND VISUAL CONTAMINATION,DISPOSAL DUE FOR SOIL SEGRATED DUE 9/15/95\. 08/11/95: RMC/SITE NO VISUAL CONTAMINATION NOTED IN NFG EXCAVATIONS OR WATER LINEEXCAVATIONS TO THE EAST OF 6 OIL TANKS WHERE RECENT OVERFILL HAPPENED, DISPOSAL BY RP FOR SOIL DUE 9/15/95 DISP+BILL DUE EPS 9/1. 02/09/96 RMC/GUSTAFSON/PHONE 6 OIL TANK REMOVALS ARE A YEAR A HEAD OF SCHEDUL, CONTRACT TO BE RELEASED TO OGS BY 3/1, THE DISPOSAL OF THE REMAINING LOAD OF SOIL WILL BE IN THE TANK REMOVAL PROJECT, CALL FROM OGS DUE 3/30/96 03/16/96 RMC/RECEIVED TANK CLOSURE NOTICE, REMOVALS TO PROCEED, 3/19/96 03/19/96 RMC/SITE NO WORK YET 03/20/96 RMC/BURN/PHONE REMOVALS PUT BACK TO NEXT WEEK , SITE CONTACT FOR OGS IS BOB MAYER 852-7437 04/17/96 RMC/FILE SAC INSPECTED SITE ON 4/10 AND 4/12/96 TWO TANKS REMOVED, CAN NOT IMMEDIATELY FIND 550 GALLON DIESEL TANK DUE TO SITE LIMITATIONS ON EXCAVATION 04/17/96 RMC/BOB MAYER/OWEN BURN/PHONE WATER IN EXCAVATION WILL BE PUMPED OUT THEN EXCAVATION OF CONTAMINATION WILL RESUME, FUTURE CONTRACT WILL COVER DIESEL AND OTHER TWO TANKS, TO REINSPECT 04/27/96 RMC/BURN/DENNIS MAHN PRINCIPAL UTILITIES ENG 845 5866/SITE TWO TANKS REMOVED AND SIGNIFICANT AMOUNTS OF CONTAMINATED SOIL AND WATER TO REMOVE REMAINING VISUAL CONTAMINATION AND TEST, THREE REMAINING TANKS TO BE REMOVED LATER THIS YEAR, TESTING AND DISPOSAL DUE 5/30/96 07/01/96 RMC/BOB MAYER/DENNIS MAHN/PHONE RMC WAS ADVISED THAT REMAINING TANKS WOULD BE TAKEN OUT OF SERVICE AND REMOVED LATE THIS YEAR OR EARLY NEXT YEAR, FILE NOTE THESE REMOVALS MAY RESULT IN ADDITIONAL SPILLAGE BEING FOUND, 07/01/96 RMC/FILE, MINOR EXCEEDANCES IN TANK PIT, SITE TO BE MADE INACTIVE"

Material Information

OP Unit ID:	1018472	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	365518	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	600.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	600.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	ROSWELL PARK CANCER INST.
Spiller Address:	ELM AND CARLTON STREETS
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14263
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900295944
Longitude:	-78.863023888

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
38	6 of 6	SE	0.14 / 752.03	664.46 / 20	SIDEWALK HIGH ST AND MICHIGAN AVE BUFFALO NY	NY SPILLS

Spill No:	1609890	**UST Trust:**	False
Site ID:	538702	**Spill Date:**	2017-01-20 11:00:00
DER Facility ID:	492499	**Received Date:**	2017-01-27 11:02:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2017-01-27 00:00:00
Water Body:		**Create Date:**	2017-01-27 11:06:00
Class:		**Update Date:**	2017-01-31 11:04:07.770000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"caller states that it was less than one cup of diesel, clean up is completed"

DEC Remark:

"1/27/17 THIS IS A MINOR SPILL THAT WAS CLEANED UP AND PROPERLY DISPOSED OF BY NOCO. NO FURTHER ACTION IS NECESSARY. THE SPILL IS CLOSED."

Material Information

OP Unit ID:	1287284	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2292988	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	NOCO ENERGY CORP
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	KEVIN GALLAS
Contact Phone:	(716) 435-7309
Contact Ext:	
Latitude:	
Longitude:	

39	1 of 2	SE	0.15 / 771.75	664.29 / 20	PROPERTY 174 HIGH ST	UST

BUFFALO NY 14203

Site ID:	443109	***Expiry:***	N/A
Site Status:	Unregulated/Closed	***County:***	Erie
Program No:	9-601232	***UTM X:***	184649.34680
Program Type Code:	PBS	***UTM Y:***	4756988.92881
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	9-601232	***UDC Ind:***	1
Tank ID:	237239	***Red Tag Start Date:***	
Tank No:	1	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	04/06/2010	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	gasoline
Percent:	100.00

Equipment Information

Equipment:	K00
Code Name:	None
Type:	Spill Prevention
Equipment:	J00
Code Name:	None
Type:	Dispenser
Equipment:	B01
Code Name:	Painted/Asphalt Coating
Type:	Tank External Protection
Equipment:	A00
Code Name:	None
Type:	Tank Internal Protection
Equipment:	H00
Code Name:	None
Type:	Tank Leak Detection
Equipment:	I00
Code Name:	None

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: NNN
Company: KALEIDA HEALTH
Contact Title:
Contact Name:
Address1: 726 EXCHANGE ST
Address2:
City: BUFFALO
State: NY
Zip Code: 14210
Country Code: 001
Phone:
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
39	2 of 2	SE	0.15 / 771.75	664.29 / 20	174 HIGH PROJECT 174 HIGH STREET BUFFALO NY 14210	NY SPILLS

Spill No: 0912618
Site ID: 425519
DER Facility ID: 374411
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: B3
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 2010-03-03 12:00:00
Received Date: 2010-03-04 10:19:00
CAC Date:
Insp Date: 2010-04-27 00:00:00
Close Date: 2010-05-04 00:00:00
Create Date: 2010-03-04 10:26:00
Update Date: 2010-05-04 12:39:05.470000000
DEC Region: 9
Lead DEC: RMCROSSE
After Hours: False

Caller Remark:

"contamination found during phase II, phase I and II reports to follow."

DEC Remark:

"03/26/10 RMC/FILE. AL KRUGER/PHONE. PHASE II IS READY FOR PICK UP. NWECC WAS LOW BID ON WORK AND WILL BE HIRED TO DO THE WORK. 03/31/10 RMC/SITE. SAC INSPECTED THE SITE WHILE USTS WERE BEING REMOVED. SITE IS CONTAMINATED AND THE IMPACTED SOILS WILL BE REMOVED NEXT WEEK WHEN THE SAMPLES COME BACK. 04/12/10 RMC/GREG WEBER/PHONE. ONE SAMPLE CAME BACK IGNITABLE. WILL STOCKPILE SOIL AND SAMPLE PILE. 04/22/10 RMC/FILE. VISITED SITE SEVERAL TIMES. EXCAVATED OUT ABOUT 1000 TONS FROM TWO AREAS. NUISSANCE CHARACTERISTICS REMAIN ALONG MICHIGAN. UP AGAINST UTILITIES AND CAN NOT DIG ANYMORE. REPORT DUE 5/30/10. 05/04/10 RMC/FILE. 1151 TONS IMPACTED SOILS DISPOSED OF AT CHAFFEE LANDFILL. POST EXCAVATION SAMPLES MEET TAGM EXCEPT FOR TWO SIDEWALL SAMPLES ALONG MICHIGAN AND 1 ALONG HIGH STREET ALL THE EXCEEDANCES WERE FOR VOC. DISCUSSED SITE WITH GS AND SAC. CONTACTED AL KRUGER. PROPOSED FUTURE US OF PROPERTY IN THAT AREA IS FOR A PARKING LOT. DUE TO THE TAGM EXCEEDANCES SITE TO BE MADE INACTIVE. LETTER. "

Material Information

OP Unit ID:	1181238	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2175308	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	AL KRUGER
Contact Phone:	(716)8598552
Contact Ext:	
Latitude:	42.900337323
Longitude:	-78.862481585

---

40 | ***1 of 1*** | ***NW*** | ***0.15 / 789.54*** | ***651.47 / 7*** | ***Olmsted Center For Sight 1170 Main Street Buffalo NY 14209*** | ***SWF/LF***

Active:	No	**Owner Address:**	1170 Main Street
Activity No:	[15M24]	**Owner Addr2:**	
Regltry Status:	Registration	**Owner City:**	Buffalo
Auth No:	15M24	**Owner State:**	NY
Auth Issue Dt:	24-Jul-2009 00:00:00	**Owner ZIP:**	14209
Expiration Date:		**Owner Email:**	
Operator Type:		**Owner Phone:**	7168821025
Operator Name:		**Contact Name:**	Daniel Genco
East Coord:	184216	**Contact Addr:**	
North Coord:	4757585	**Contact Addr2:**	
Accuracy Code:	4.2 - Utilization of GIS and existing spatial data	**Contact City:**	
County:	Erie	**Contact State:**	NY
Region:	9	**Contact ZIP:**	
Phone No:	7168821025	**Contact Email:**	dgenco@olmstedcenter.org
Owner Name:	Olmstead Center	**Contact Phone:**	7168821025
Owner Type:	Private	**DateofLastInspctn:**	
Activity Desc:	RHRF - registration		
Source:	SWMF - Inactive Facility Lists		
Waste Types:	Commingled Paper		
Georeference:			

---

41 | ***1 of 1*** | ***WNW*** | ***0.16 / 836.96*** | ***649.23 / 5*** | ***SCHUELE PAINT CO 12 SUMMER ST BUFFALO NY 14209*** | ***RCRA LQG***

EPA Handler ID:	NYR000165506
Gen Status Universe:	Large Quantity Generator
Contact Name:	PAUL R LEAHEY
Contact Address:	12, SUMMER ST, BUFFALO, NY, 14209, US
Contact Phone No and Ext:	716-884-3374
Contact Email:	PAUL.LEAHEY@SCHUELEPAINT.COM
Contact Country:	US
County Name:	ERIE

EPA Region: 02
Land Type: Private
Receive Date: 20140304
Location Latitude: 42.904683
Location Longitude: -78.870244

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date: 20170419
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140304
Handler Name: SCHUELE PAINT CO
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20090528
Handler Name: SCHUELE PAINT CO
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	SUMMER ST
Name:	SUMMER STREET ASSOC	***Street 2:***	
Date Became Current:	19000101	***City:***	BUFFALO
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	SCHUELE PAINT CO INC	***Street 2:***	
Date Became Current:	19940901	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Notification	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	12
Type:	Private	***Street 1:***	SUMMER ST
Name:	SUMMER STREET ASSOC	***Street 2:***	
Date Became Current:	19000101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-884-3374	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14209

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	
Name:	SUMMER ST ASSOCIATES	***Street 2:***	
Date Became Current:	20070101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Notification	***Zip Code:***	

Historical Handler Details

Receive Dt: 20090528
Generator Code Description: Small Quantity Generator
Handler Name: SCHUELE PAINT CO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
42	1 of 1	W	0.16 / 841.09	658.15 / 14	19 North Street 19 North Street Buffalo NY 14202	BROWNFIELDS

Site Code: 521040
HW Code: C915303
Program: BCP
Site Class: C
Site Name: 19 North Street
Site Address: 19 North Street
City: Buffalo
Zip: 14202
County: Erie

Region:	9
Town:	Buffalo (c)
Latitude:	42.902483333
Longitude:	-78.869961111
SWIS:	1502
Acres:	0.500
Record Added:	2016-01-21 08:10:00
Record Update:	2017-12-29 13:48:00
Updated by:	BXANDERS
Site Code (Web):	C915303
Program Type (Web):	BCP
Site Name (Web):	19 North Street
Site Class (Web):	C
Address1 (Web):	19 North Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14202
County (Web):	Erie
Longitude (Web):	-78.869961111
Latitude (Web):	42.902483333
Site Code (GIS):	C915303
Site Name (GIS):	19 North Street
Program (GIS):	BCP
Site Class (GIS):	C
Address1 (GIS):	19 North Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14202
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Remedial actions taken at the site has removed all site-related contamination. Therefore, no contact with site contaminants is expected.

Description:

Location: The 19 North St. BCP is a 0.5 acre site located in the City of Buffalo at the intersection of North Pearl Street and North Street, near to the Buffalo Niagara Medical Campus. The 19 North St site includes parcels located at 19 North St and 23 North St. Site Features: The Site is currently vacant which formally held a small parking area in the eastern portion of the Site with grass/soil area covering the remainder of the site. The Site fronts to North Street. Current Zoning and Land Use: The Site is currently zoned as general commercial district and classified as a commercial land use. The surrounding parcels are a mix of commercial, residential and transit station zoning districts. Surrounding parcels are also a mix of commercial, residential and community service land uses. Past Use of the Site: The Phase I Environmental Site Assessment (ESA)indicated that the BCP Site was occupied by residential dwellings. By 1951, the residence at 23 North Street had become a radio station. By 1981, the residence at 19 North Street had been removed and replaced with a radio tower. In 2014 the residence at 23 North Street was demolished and the basement area backfilled. Site Geology and Hydrogeology: The Site contains fill consisting of sand and gravel, clay, brick, concrete and traces of coal. Fill thickness ranges up to 13 feet. The fill is underlain by brown silty clay and silty sand. Groundwater was observed during site investigations to be approximately 16 - 24 feet below grade. Groundwater flow direction on the site is variable due to the nature of the urban setting but is generally in the northeast direction. Bedrock was not encountered at the site and is therefore greater than 24' below ground surface. A site location map is attached as Figure 1 and a Site map is attached as Figure 2.

Assessment:

Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs) and pesticides. Based upon the investigations performed, the primary contaminants include polycyclic aromatic hydrocarbons (PAHs), pesticides and several metals (lead, mercury, zinc and selenium) in soil/fill. Refer Table 1 for soil/fill concentration data. No VOCs or PCBs were detected in the soil/fill on the site. For groundwater, minor detections of Volatile Organic Compounds (VOCs) for 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene and p-Isopropyltoluene were detected above groundwater standards in one well on only one occasion. These compounds were non-detect on subsequent sampling events. No exceedances of groundwater standards were found on site for Semi-volatile Organic Compounds (SVOCs), PCBs or pesticides. Several metals were detected at various times above groundwater standards that included iron, magnesium, manganese and sodium. These metal concentrations are typical of local groundwater conditions and are not a site concern. The City of Buffalo prohibits the use of groundwater for drinking water purposes. Refer Table 2 for groundwater sampling data. The Remedial Investigation (RI) conducted on site identified approximately 6000 cy of soil contaminated with SVOCs and metals. An Interim Remedial Measure (IRM) work plan was developed that required the excavation of all contaminated soil to unrestricted soil cleanup objectives(SCOs). The IRM was begun in July 2017 and excavation was completed in October 2017. Excavation was performed to predetermined depths as identified in the RI and IRM work plan. Approximately 12,018 tons of

contaminated soil was removed and disposed off-site at a permitted facility. The site was backfilled with crushed stone meeting the requirements for unrestricted use.

Owner Information

Owner Op:	01
Sub Type:	P02
Owner Name:	Benjamin Obletz
Owner Company:	23 North Street LLC
Owner Street:	4508 Main Street
Owner Street 2:	
Owner City:	Amherst
Owner State:	NY
Owner Zip:	14226
Country:	United States of America

Owner Op:	06
Sub Type:	P03
Owner Name:	Benjamin Obletz
Owner Company:	23 North Street LLC
Owner Street:	4508 Main Street
Owner Street 2:	
Owner City:	Amherst
Owner State:	NY
Owner Zip:	14226
Country:	United States of America

Owner Op:	19
Sub Type:	NNN
Owner Name:	Carol Ann Batt
Owner Company:	Buffalo & Erie County Public Library -
Owner Street:	1 Lafayette Square
Owner Street 2:	
Owner City:	Buffalo
Owner State:	NY
Owner Zip:	14203
Country:	United States of America

HW Extra Information

Dump:	False	***Record Added:***	2016-06-08 12:29:00
Structure:	False	***Record Updated:***	2017-11-20 14:52:00
Lagoon:	False	***Disposal Start:***	
Landfill:	False	***Disposal Terminate:***	
Pond:	False	***Latitude:***	
Dell:		***Longitude:***	
Updated By:	MJHINTON		

Projects Information

Project Code:	02
Project Desc:	Remedial Investigation
Project Refer Name:	
End Date:	2017-12-28 00:00:00
End Status:	ACT
Operable Unit ID:	1270062
Operable Unit:	01
Operable Unit Desc:	Remedial Program
Code Name:	Remedial Investigation

Project Code:	05
Project Desc:	Remedial Action
Project Refer Name:	
End Date:	2017-12-28 00:00:00
End Status:	ACT

Operable Unit ID: 1270062
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2017-12-28 00:00:00
End Status: ACT
Operable Unit ID: 1270062
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Certificate of Completion

Environmental Remediation

Operable Unit: 01
Contaminants:

Operable Unit: 00
Contaminants:

43	1 of 6	WSW	0.16 / 844.61	658.51 / 14	GULF SERVICE STATION #176476 1038 MAIN ST BUFFALO NY 14202	RCRA NON GEN

EPA Handler ID: NYR000033134
Gen Status Universe: No Report
Contact Name: WILLIAM LOVELY
Contact Address: 777, DEDHAM ST, CANTON, NY, 02021-9118, US
Contact Phone No and Ext: 617-828-4900
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20070101
Location Latitude: 42.902078
Location Longitude: -78.869034

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: GULF SERVICE STATION #176476
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19961212
Handler Name: GULF SERVICE STATION #176476
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19980304
Handler Name: GULF SERVICE STATION #176476
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: GULF SERVICE STATION #176476
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: CUMBERLAND FARMS INC
Date Became Current:
Date Ended Current:
Phone: 617-828-4900
Source Type: Notification
Street No:
Street 1: 777 DEDHAM ST
Street 2:
City: CANTON
State: MA
Country:
Zip Code: 02021-9118

Owner/Operator Ind: Current Owner
Type: Private
Name: CUMBERLAND FARMS INC
Date Became Current:
Date Ended Current:
Phone: 617-828-4900
Source Type: Implementer
Street No:
Street 1: 777 DEDHAM ST
Street 2:
City: CANTON
State: MA
Country: US
Zip Code: 02021-9118

Owner/Operator Ind: Current Operator
Street No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street 1:**	777 DEDHAM ST
Name:	CUMBERLAND FARMS INC	**Street 2:**	
Date Became Current:		**City:**	CANTON
Date Ended Current:		**State:**	MA
Phone:	617-828-4900	**Country:**	US
Source Type:	Implementer	**Zip Code:**	02021-9118

Historical Handler Details

Receive Dt:	19980304
Generator Code Description:	Large Quantity Generator
Handler Name:	GULF SERVICE STATION #176476
Receive Dt:	19961212
Generator Code Description:	Very Small Quantity Generator
Handler Name:	GULF SERVICE STATION #176476
Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	GULF SERVICE STATION #176476

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
43	2 of 6	WSW	0.16 / 844.61	658.51 / 14	CUMBERLAND FARMS #176476 1038 MAIN ST Buffalo NY 14202	UST

Site ID:	53097	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Erie
Program No:	9-222690	**UTM X:**	184103.19061
Program Type Code:	PBS	**UTM Y:**	4757199.94531
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Retail Gasoline Sales		

Tank Information

Prog No:	9-222690	**UDC Ind:**	1
Tank ID:	164356	**Red Tag Start Date:**	
Tank No:	2	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	10/01/1994
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	14
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	04/01/1977	**Next Test:**	
Close Date:	02/01/1997	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	8000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	gasoline
Percent:	100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H03
Code Name: Vapor Well
Type: Tank Leak Detection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	9-222690	***UDC Ind:***	1
Tank ID:	164355	***Red Tag Start Date:***	
Tank No:	1	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	10/01/1994
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	14
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	04/01/1977	***Next Test:***	
Close Date:	01/01/1997	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	8000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: J01
Code Name: Pressurized Dispenser
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: H03
Code Name: Vapor Well
Type: Tank Leak Detection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B00
Code Name: None
Type: Tank External Protection

Tank Information

Prog No:	9-222690	***UDC Ind:***	1
Tank ID:	164357	***Red Tag Start Date:***	
Tank No:	3	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	10/01/1994
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	14
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:	04/01/1954	***Next Test:***	
Close Date:	02/01/1997	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	550	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:

Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: B00
Code Name: None
Type: Tank External Protection

Affiliation Information

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: CUMBERLAND FARMS INC
Contact Title:
Contact Name: LORAINE HIGGINS
Address1: 777 DEDHAM ST
Address2:
City: CANTON
State: MA
Zip Code: 02021
Country Code: 001
Phone: (617) 828-4900
Phone Ext:
Email:
Fax:

Affiliation Type: 01

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affiliation Name: Facility Owner
Affiliation Sub Type: E
Company: CUMBERLAND FARMS, INC.
Contact Title:
Contact Name:
Address1: 777 DEDHAM STREET
Address2:
City: CANTON
State: MA
Zip Code: 02021
Country Code: 001
Phone: (617) 828-4912
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: CUMBERLAND FARMS, INC.
Contact Title:
Contact Name: CUMBERLAND FARMS, INC.
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 999
Phone: (781) 828-4900
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: CUMBERLAND FARMS #176476
Contact Title:
Contact Name: MANAGER
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (716) 886-9043
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
43	3 of 6	WSW	0.16 / 844.61	658.51 / 14	CUMBERLAND FARMS/GULF 1038 MAIN STREET BUFFALO NY	NY SPILLS

Spill No: 9311640
Site ID: 71679
DER Facility ID: 67798
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D5
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Unknown
Reported by: Other

UST Trust: False
Spill Date: 1993-12-30 00:00:00
Received Date: 1993-12-30 09:04:00
CAC Date: 1994-07-01 00:00:00
Insp Date:
Close Date: 1994-07-01 00:00:00
Create Date: 1993-12-30 00:00:00
Update Date: 2000-09-28 00:00:00
DEC Region: 9
Lead DEC: SORGI
After Hours: False

Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"SOIL SAMPLING FOUND LEAD, NO BTEX"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 02/14/94: LETTER TO RP REQUESTING SUBSURFACE INVESTIGATION REPORT. 02/23/94: MJS/KEVIN MCCABE, CUMBERLAND FARMS/TELECON - HE STATES THAT NO FREE PRODUCT WAS FOUND IN BORINGS. HE WILL FORWARD A LETTER TO THAT EFFECT AND ANY FIELD DATA HE CAN OBTAIN. 04/06/94: MJS RECEIVED BORING LOGS AND SITE MAP FROM CONSULTANT. GW AT APPROX. 25' BELOW GRADE. LOW P.I.D. READINGS IN BORINGS #2, #3 JUST ABOVE WATER TABLE. 04/07/94: MJS SENT LETTER TO RP ADVISING THAT DEC REQUIRES GROUNDWATER SAMPLING. 06/01/94: RECEIVED REPORT FROM GES INC. NO BTEX FOUND IN WELLS. LEAD FOUND ABOVE GW STANDARDS. NO FURTHER ACTION BY SPILL UNIT REQUIRED. COPY OF REPORT TO BE PASSED ON TO DOW FOR FOLLOWUP ON LEAD PROBLEM. 07/01/94: RECEIVED REPORT FROM GES INC. NO BTEX FOUND IN WELLS. LEAD FOUND ABOVE GW STANDARDS. NO FURTHER ACTION BY SPILL UNIT REQUIRED. COPY OF REPORT TO BE PASSED ON TO DOW FOR FOLLOWUP ON LEAD PROBLEM. "

Material Information

OP Unit ID:	993656	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	390666	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	CUMBERLAND FARMS/GULF
Spiller Address:	777 DEDHAM STREET
Spiller City:	CANTON
Spiller State:	MA
Spiller Zip:	02021
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902002290
Longitude:	-78.869178900

43	***4 of 6***	***WSW***	***0.16 / 844.61***	***658.51 / 14***	***CUMBERLAND FARMS 1038 MAIN STREET BUFFALO NY***	***NY SPILLS***

Spill No:	9613078	***UST Trust:***	True
Site ID:	71680	***Spill Date:***	1997-02-04 12:00:00
DER Facility ID:	67798	***Received Date:***	1997-02-04 13:10:00
CID:	351	***CAC Date:***	1997-03-14 00:00:00
Program Type:	ER	***Insp Date:***	1997-02-07 00:00:00
SWIS Code:	1502	***Close Date:***	1997-03-17 00:00:00
Water Body:		***Create Date:***	1997-02-04 00:00:00
Class:	C3	***Update Date:***	1997-04-24 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	COOKE
REM Phase:	0	***After Hours:***	False

County:	Erie
Contributing Factor:	Equipment Failure
Reported by:	Tank Tester
Referred to:	
Source:	Gasoline Station or other PBS Facility
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"2 - 8K TANKS BEING REMOVED BY NATURE'S WAY BY CUMBERLAND THROUGH GESERVICES SOIL CONTAMINATION FOUND UNDER SERVICE ISLAND ALONG MAIN STREET SIDE. NO FREE PRODUCT FOUND. SPILL FAXED FROM REGION 9 ON 02/04/97"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 2/4/97: JDC ON SITE AND MET W/ BOB DRABOT, GES MINOR CONTAMINATION TO SERVICE ISLAND AREA ALONG MAIN STREET. NO FREE PRODUCT WAS OBSERVED IN ISLAND EXCAVATION. SOILS REMOVED AND STAGED ALONG BUILDING FOR DISPOSAL. 2/7/97: JDC ON SITE AND OBSERVED EXCAVATION ON WEST SIDE OF BUILDING WHERE WASTE OIL TANK WAS DISCOVERD FULL OF WASTE OILS. SAFETY CLEAN HIRED TO REMOVE WASTE OILS. CONTAMINATED SOILS WILL BE DISPOSED OF SEPARATELY. 3/17/97: REVIEWED CLOSURE REPORT AND FOUND POST TEST AND DISPOSAL INFORMATION SATISFACTORY. POST TEST INDICATED NO VIOLATIONS OF STARS, SITE WILL BE CLOSED, SENT LETTER STATING SAME. "

Material Information

OP Unit ID:	1040734	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	566737	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	BILL LOVELY
Spiller Company:	CUMBERLAND FARMS
Spiller Address:	727 DEDHAM STREET
Spiller City:	CANTON
Spiller State:	MA
Spiller Zip:	02021-9118
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902002290
Longitude:	-78.869178900

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
43	5 of 6	WSW	0.16 / 844.61	658.51 / 14	ARG TRUCKING 1038 MAIN STREET BUFFALO NY	LST

Spill No:	8803956	**REM Phase:**	0
Site ID:	71678	**UST Trust:**	True
DER Facility ID:	67798	**Spill Date:**	1988-08-04 18:00:00
CID:		**Rcvd Date:**	1988-08-04 18:21:00
Program Type:	ER	**CAC Date:**	1988-08-08 00:00:00
SWIS Code:	1502	**Insp Date:**	1988-08-04 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	1988-08-08 00:00:00
Water Body:		**Create Date:**	1988-08-30 00:00:00
Class:	C3	**Update Date:**	2000-07-26 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	LEARY
County:	Erie	**After Hours:**	True
Referred to:			
Reported by:	Citizen		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OVERFILLED TANK"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 08/04/88: RNL SITE INSP., GASOLINE SPILLED AND FLUSHED BY BUFFALO FD, FURTHER CLEANUP NOT POSSIBLE, SPILLER MADE NO ATTEMPT TO CLEANUP. 08/08/88: RNL LETTER 08/08/88 TO SPILLER, REQUIRES CLEANUP FOR FUTURE SPILLS. "

Material Information

OP Unit ID:	921125	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	459476	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	50.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	25.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	ARG TRUCKING
Spiller Address:	122 COOPER AVENUE
Spiller City:	TONAWANDA
Spiller State:	NY
Spiller Zip:	14150
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902002290
Longitude:	-78.869178900

43	***6 of 6***	***WSW***	***0.16 / 844.61***	***658.51 / 14***	***NIRELLI'S GULF STATION 1038 MAIN & NORTH BUFFALO NY***	***LST***

Spill No:	8808014	**REM Phase:**	0
Site ID:	168845	**UST Trust:**	True
DER Facility ID:	142195	**Spill Date:**	1989-01-03 12:00:00
CID:		**Rcvd Date:**	1989-01-05 12:03:00
Program Type:	ER	**CAC Date:**	1989-10-02 00:00:00
SWIS Code:	1502	**Insp Date:**	1989-06-08 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1989-10-02 00:00:00
Water Body:		**Create Date:**	1989-01-10 00:00:00
Class:		**Update Date:**	1989-10-05 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
County:	Erie	**After Hours:**	False
Referred to:			

Reported by: Affected Persons
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"LEAK AT GAS STATION CAUSED FUMES TO ENTER BASEMENT OF BRYANT & STRATTON SCHOOL"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 01/05/89: 1/5/89 MNP INSP. GASOLINE FUMES FOUND IN BASEMENT, GULF STATION TO TEST TANKS & EXCAVATE INTERCEPTION TRENCH TO STOP FUMES FROM ENTERING BUILDING. 10/02/89: 10/2/89 MNP REVIEW OF FILE, CLEANUP & DISPOSAL SATISFACTORY, COMPLETE. "

Material Information

OP Unit ID:	923499	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	559496	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	CUMBERLAND FARMS
Spiller Address:	777 DEDHAM
Spiller City:	CANTON
Spiller State:	OH
Spiller Zip:	02021
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902002290
Longitude:	-78.869178900

Tank Test Information

Spill Tank ID:	1535058	**Source:**	
Tank No:		**Leak Rate:**	.00
Tank SIze:	0	**Gross Fail:**	
Material:	0009	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	00
Cause:			
Alt Test Method:	Unknown		

44	1 of 1	WNW	0.17 / 875.14	650.94 / 7	PRECISION ABRASIVES CORP 11 SUMMER ST BUFFALO NY 14209	RCRA NON GEN

EPA Handler ID: NYD986930584
Gen Status Universe: No Report
Contact Name:
Contact Address: UNKNOWN, BUFFALO, NY, 14209, US
Contact Phone No and Ext:

Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 42.904907
Location Longitude: -78.86869

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date: 19900906
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: PRECISION ABRASIVES CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19791231
Handler Name: PRECISION ABRASIVES CORP
Source Type: Implementer
Federal Waste Generator Code:
Generator Code Description:

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: PRECISION ABRASIVES CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country:
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: OWNERNAME
Date Became Current:
Date Ended Current:
Phone: 212-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: WY
Country: US
Zip Code: 99999

Historical Handler Details

Receive Dt: 19791231
Generator Code Description:
Handler Name: PRECISION ABRASIVES CORP

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: PRECISION ABRASIVES CORP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
45	1 of 1	SW	0.17 / 920.40	661.92 / 18	NORTHEAST TOWER INC 23 HIGH ST BUFFALO NY 14203	RCRA NON GEN

EPA Handler ID: NYD982539645
Gen Status Universe: No Report
Contact Name:
Contact Address: PO BOX 436, BUFFALO, NY, 14209, US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude: 42.90034
Location Longitude: -78.868321

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	3
Receive Date:	20070101
Handler Name:	NORTHEAST TOWER INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19880718
Handler Name:	NORTHEAST TOWER INC
Source Type:	Notification
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Waste Code Details

Hazardous Waste Code:	X002
Waste Code Description:	DESCRIPTION

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20060101
Handler Name:	NORTHEAST TOWER INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19990708
Handler Name:	NORTHEAST TOWER INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner ***Street No:***

Type:	Private	**Street 1:**	NOT REQUIRED
Name:	NORTHEAST TOWER INC	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	NORTHEAST TOWER INC	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	NORTHEAST TOWER INC	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	NORTHEAST TOWER INC
Receive Dt:	19880718
Generator Code Description:	Small Quantity Generator
Handler Name:	NORTHEAST TOWER INC
Receive Dt:	19990708
Generator Code Description:	Not a Generator, Verified
Handler Name:	NORTHEAST TOWER INC

---

46 | ***1 of 1*** | ***SE*** | ***0.18 / 938.11*** | ***660.08 / 16*** | ***BEHIND VACANT HOUSES 204 HIGH ST BUFFALO NY*** | ***NY SPILLS***

Spill No:	0108495	**UST Trust:**	False
Site ID:	262527	**Spill Date:**	2001-11-22 02:31:00
DER Facility ID:	214332	**Received Date:**	2001-11-22 04:02:00
CID:	397	**CAC Date:**	
Program Type:	ER	**Insp Date:**	2001-11-23 00:00:00
SWIS Code:	1502	**Close Date:**	2001-11-23 00:00:00
Water Body:		**Create Date:**	2001-11-22 00:00:00
Class:	A3	**Update Date:**	2001-11-26 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RJJONAK
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Fire Department		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"fire dept responded to a vehicle fire which they suspect was arson and discovered a large amount of gas was used. the gas leaked into the ground would like a call back"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 11/23/2001: RJJ AT SITE AT 1000...A CAR WAS TOTALY BURNED BEHIND

VACANT HOUSES ON 11/22/01 AT 0230 IN THE MORNING...THE FIRE DEPT SAID THAT ARSON WAS THE CAUSE...ONLY THE BURNED CAR IS LEFT,ALL THE GASOLINE USED WAS ALSO BURNED IN THE FIRE...IT DOSN'T APPEAR THAT ANY FUEL IS IN THE GROUND,IT WAS USED TO START THE FIRE AND ALL BURNED UP...NO FURTHER ACTION NEEDED...SPILL CLOSED OUT."

Material Information

OP Unit ID:	846534	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	529743	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	UNK
Spiller Address:	UNK
Spiller City:	UNK
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	CALLER
Contact Phone:	
Contact Ext:	
Latitude:	42.900309960
Longitude:	-78.861712570

---

47 ***1 of 1*** ***SW*** ***0.19 / 989.58*** ***661.93 / 18*** ***VACANT LOT FORMERLY 33 HIGH STREET APTS 960 WASHINGTON NY*** ***NY SPILLS***

Spill No:	1204448	***UST Trust:***	
Site ID:	467335	***Spill Date:***	2012-08-03 12:00:00
DER Facility ID:	421656	***Received Date:***	2012-08-03 14:05:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2014-04-29 00:00:00
Water Body:		***Create Date:***	2012-08-03 13:49:00
Class:	B3	***Update Date:***	2015-09-04 11:21:35.543000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	TDJOHNSO
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTAMINATION FOUND IN PHASE II BORING RESULTS. PHASE I ALSO DONE. PHASE I AND II WILL BE SUBMITTED. SEEM TO BE ISOLATED PROBLEM."

DEC Remark:

"08/06/12 TDJ PHASE II REPORT WILL BE SUBMITTED FOR FUTURE WORK. 10/23/12 TDJ SPOKE WITH ROBERT RUGGERI,SENIOR

MANAGING COUNSEL FROM THE STATE UNIVERSITY OF NEW YORK WHO WAS INTERESTED IN DEPARTMENTS COMMENTS ON PHASE II REPORT. I STATED THAT I HAD NOT RECEIVED THE REPORT AS OF YET. HE E-MAILED A COPY AND I SPENT TIME REVIEWING THE BORING INFORMATION AND SAMPLING RESULTS. THE MAJORITY OF SITE IS CLEAN AS TO AREAS SAMPLED EXCEPT BORING #2 WHICH SHOWED CONTAMINATION AT 18' DEPTH. THE DATA IS SUSPECT THOUGH DUE TO BORING LOGS WHICH SHOW NO PID READING AT THE DEPTH AND A MONITORING WELL IN THE VICINITY SCREENED AT THAT DEPTH SHOWED NO HITS ASSOCIATED WITH THE SOIL CONTAMINATION. ACETONE SHOWED UP IN SOIL AND GROUNDWATER SAMPLES AT DIFFERENT LOCATIONS AROUND THE SITE WHICH IS ALSO SUSPECT. LAB CONTAMINATION IS SOMETIMES THE CAUSE OF THESE SPIKES. REPORT ALSO HAS LAB RESULTS IN ppb levels AND PUT INTO FINAL REPORT AS ppm levels FOR CONTAMINANTS. 10/24/12 TDJ OFFICE OF GENERAL COUNSEL FOR SUNY CALLED REQUESTING A CONFERENCE CALL ON 10/26. WILL SPEAK WITH BOB RUGGERI AND LAND AQUISITION SUPERVISOR. 12/5/12 TDJ EMAIL FROM JOE DORETY 04/29/14 TDJ RECEIVED FINAL REPORT DATED 4/23/14 FROM EMPIRE GEO SHOWING TEST BORINGS IN THE SUSPECT AREA OF THE SITE. ANALYTICAL REPORTS SHOWED SEMI VOLATILE CONTAMINANTS ABOVE CP-51 LIMITS BUT THESE WERE ATTRIBUTED TO FILL MATERIAL USED IN THE PAST. NO ODORS NOR PETROLEUM CONTAMINATION WAS ENCOUNTERED. FOR THIS REASON THE SITE WILL BE CLOSED AS NO FURTHER ACTION. 09/04/15 TDJ NO FURTHER ACTION LETTER SENT TO FISHER ASSOC. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1217291	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2215559	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	EVERGREEN REALESTATE
Spiller Address:	348 HARRIS HILL ROAD
Spiller City:	WILLIAMSVILLE
Spiller State:	NY
Spiller Zip:	14221
Spiller Country:	999
Contact Name:	EVERGREEN REALESTATE
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
48	1 of 1	NW	0.19 / 1,010.67	653.02 / 9	AUTOPIA INC 1176 MAIN ST BUFFALO NY 14203	RCRA NON GEN

EPA Handler ID:	NYD987012838
Gen Status Universe:	No Report
Contact Name:	MICHAEL FARNSWORTH
Contact Address:	1176, MAIN ST, BUFFALO, NY, 14203, US
Contact Phone No and Ext:	716-998-3052
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	Private
Receive Date:	20070101
Location Latitude:	42.905724
Location Longitude:	-78.868546

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date: 19970709
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19950620
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: AUTOPIA INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: AUTOPIA INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20000601
Handler Name: AUTOPIA INC
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: MRS SYLVIA WIESS
Date Became Current:
Date Ended Current:
Phone: 716-836-4320
Source Type: Implementer
Street No:
Street 1: 360 CLAREMONT ST
Street 2:
City: KENMORE
State: NY
Country: US
Zip Code: 14036

Owner/Operator Ind: Current Owner
Type: Private
Name: MRS SYLVIA WIESS
Date Became Current:
Date Ended Current:
Phone: 716-836-4320
Source Type: Notification
Street No:
Street 1: 360 CLAREMONT ST
Street 2:
City: KENMORE
State: NY
Country:
Zip Code: 14036

Owner/Operator Ind: Current Operator
Type: Private
Name: MRS SYLVIA WIESS
Date Became Current:
Date Ended Current:
Phone: 716-836-4320
Source Type: Implementer
Street No:
Street 1: 360 CLAREMONT ST
Street 2:
City: KENMORE
State: NY
Country: US
Zip Code: 14036

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: AUTOPIA INC

Receive Dt: 20000601
Generator Code Description: Very Small Quantity Generator
Handler Name: AUTOPIA INC

49	1 of 1	WSW	0.19 / 1,021.94	661.72 / 17	CITIBANK 1008 MAIN ST BUFFALO NY 14202-1102	RCRA NON GEN

EPA Handler ID: NYR000084129
Gen Status Universe: No Report

Contact Name:	ANITA JORDAN
Contact Address:	500, W MADISON 5TH FLOOR, CHICAGO, NY, 60661, US
Contact Phone No and Ext:	312-627-3609
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	Private
Receive Date:	20070101
Location Latitude:	42.901304
Location Longitude:	-78.869909

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20060101
Handler Name:	CITIBANK
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20070101
Handler Name:	CITIBANK
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20000202
Handler Name:	CITIBANK
Source Type:	Notification
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: CITIBANK NYS C-O CITIBANK FSB
Date Became Current:
Date Ended Current:
Phone: 312-627-3609
Source Type: Implementer
Street No:
Street 1: 500 W MADISON 5TH FLOOR
Street 2:
City: CHICAGO
State: IL
Country: US
Zip Code: 60661

Owner/Operator Ind: Current Owner
Type: Private
Name: CITIBANK NYS C-O CITIBANK FSB
Date Became Current:
Date Ended Current:
Phone: 312-627-3609
Source Type: Notification
Street No:
Street 1: 500 W MADISON 5TH FLOOR
Street 2:
City: CHICAGO
State: IL
Country:
Zip Code: 60661

Owner/Operator Ind: Current Operator
Type: Private
Name: CITIBANK NYS C-O CITIBANK FSB
Date Became Current:
Date Ended Current:
Phone: 312-627-3609
Source Type: Implementer
Street No:
Street 1: 500 W MADISON 5TH FLOOR
Street 2:
City: CHICAGO
State: IL
Country: US
Zip Code: 60661

Historical Handler Details

Receive Dt: 20000202
Generator Code Description: Small Quantity Generator
Handler Name: CITIBANK

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: CITIBANK

50	*1 of 1*	*WSW*	*0.20 / 1,077.57*	*662.78 / 18*	***SALVATION ARMY THE*** ***984 MAIN ST*** ***BUFFALO NY 14202-1102***	***RCRA SQG***

EPA Handler ID: NYR000133009
Gen Status Universe: Small Quantity Generator
Contact Name: DONALD W MATTESON
Contact Address: 960, MAIN ST, BUFFALO, NY, 14202, US
Contact Phone No and Ext: 716-883-9800 206
Contact Email: DMATTESON@USE.SALVATIONARMY.ORG
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20070101

Location Latitude: 42.888149
Location Longitude: -78.873574

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: SALVATION ARMY THE
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20050706
Handler Name: SALVATION ARMY THE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: SALVATION ARMY THE
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator ***Street No:***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street 1:**	
Name:	THE SALVATION ARMY	**Street 2:**	
Date Became Current:	19910904	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	NO NAME FOUND	**Street 2:**	
Date Became Current:	19910904	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	
Owner/Operator Ind:	Current Owner	**Street No:**	440
Type:	Private	**Street 1:**	W NYACK RD - PO BOX C-635
Name:	THE SALVATION ARMY	**Street 2:**	
Date Became Current:	19910904	**City:**	WEST NYACK
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Implementer	**Zip Code:**	10994-1739
Owner/Operator Ind:	Current Owner	**Street No:**	440
Type:	Private	**Street 1:**	W NYACK RD - PO BOX C-635
Name:	THE SALVATION ARMY	**Street 2:**	
Date Became Current:	19910904	**City:**	WEST NYACK
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	10994-1739

Historical Handler Details

Receive Dt:	20050706
Generator Code Description:	Large Quantity Generator
Handler Name:	SALVATION ARMY THE
Receive Dt:	20060101
Generator Code Description:	Small Quantity Generator
Handler Name:	SALVATION ARMY THE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	1 of 9	E	0.21 / 1,083.89	677.33 / 33	DMNA STATE OF NEW YORK OMS #2 27 MASTEN AVE BUFFALO NY 14204	RCRA NON GEN

EPA Handler ID:	NYD981561673
Gen Status Universe:	No Report
Contact Name:	
Contact Address:	27, MASTEN AVE, BUFFALO, NY, 14204, US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	
Receive Date:	20070101
Location Latitude:	42.90306
Location Longitude:	-78.859728

Violation/Evaluation Summary

Note:	VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation: FR - 40 cfr 262.40
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19931001
Scheduled Compliance Date: 19931129
Return to Compliance: Observed
Actual Return to Compl: 19931129
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19931018
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation: FR - 40 cfr 262.34
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19931001
Scheduled Compliance Date: 19931129
Return to Compliance: Observed
Actual Return to Compl: 19931129
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19931018
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 19920915
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19931129
Evaluation Agency: EPA Contractor/Grantee

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No

Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060101
Handler Name: DMNA STATE OF NEW YORK OMS #2
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070101
Handler Name: DMNA STATE OF NEW YORK OMS #2
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931220
Handler Name: DMNA STATE OF NEW YORK OMS #2
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: NONE
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19860925
Handler Name: DMNA STATE OF NEW YORK OMS #2
Source Type: Notification
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: X001
Waste Code Description: DESCRIPTION

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19920211

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: UNITED STATED MILITARY DMNA
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Federal	**Street 1:**	NOT REQUIRED
Name:	DMNA STATE OF NY	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Federal	**Street 1:**	NOT REQUIRED
Name:	DMNA STATE OF NY	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Federal	**Street 1:**	NOT REQUIRED
Name:	DMNA STATE OF NY	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: DMNA STATE OF NEW YORK OMS #2

Receive Dt: 19860925
Generator Code Description: Large Quantity Generator
Handler Name: DMNA STATE OF NEW YORK OMS #2

Receive Dt: 19920211
Generator Code Description: Large Quantity Generator
Handler Name: UNITED STATED MILITARY DMNA

Receive Dt: 19931220
Generator Code Description: Not a Generator, Verified
Handler Name: DMNA STATE OF NEW YORK OMS #2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	2 of 9	E	0.21 / 1,083.89	677.33 / 33	NYS DMNA - FMS #1 27 MASTEN AVE BUFFALO NY 14204-1097	RCRA VSQG

EPA Handler ID: NYD981561665
Gen Status Universe: VSG
Contact Name: HEIDI M UNWIN
Contact Address: 330, OLD NISKAYUNA RD, LATHAM, NY, 12110-2224, US
Contact Phone No and Ext: 518-786-4347
Contact Email: HEIDI.UNWIN@NY.NGB.ARMY.MIL
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: State
Receive Date: 20070101
Location Latitude: 42.903036
Location Longitude: -78.859766

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation: FR - 40 cfr 262.40
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19931001
Scheduled Compliance Date: 19931230
Return to Compliance: Unverifiable
Actual Return to Compl: 19930510
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19931203
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation: FR - 40 cfr 262.34
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19931001
Scheduled Compliance Date: 19931230
Return to Compliance: Unverifiable
Actual Return to Compl: 19930510
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19931203
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 19920916
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19930510
Evaluation Agency: EPA Contractor/Grantee

Evaluation Start Date: 19930510
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA Contractor/Grantee

Evaluation Start Date: 20040924
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19951120
Handler Name: NYS DIV MILITARY NAVAL AFFAIRS - OMS #1
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: X001
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060904
Handler Name: NYS DMNA - FMS #1
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20060905

Handler Name: NYS DMNA - FMS #1
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: NYS DMNA - FMS #1
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20040129
Handler Name: OMS #1
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: State
Name: NYS DIV MILITARY NAVAL AFFAIRS
Date Became Current:
Date Ended Current:
Phone: 518-786-4495
Source Type: Notification
Street No:
Street 1: 330 OLD NISKAYUNA RD
Street 2:
City: LATHAM
State: NY
Country:
Zip Code: 12110-2224

Owner/Operator Ind: Current Operator
Type: State
Name: NYS DIV OF MILITARY & NAVAL AFFAIRS
Date Became Current: 20060905
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Operator
Type: State
Name: NYS DIV MILITARY & NAVAL AFFAIRS
Date Became Current: 19791231
Date Ended Current:
Phone:
Street No:
Street 1: OLD NISKAYUNA RD
Street 2:
City: LATHAM
State: NY
Country: US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type:	Implementer	**Zip Code:**	12110-2224
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	330 OLD NISKAYUNA RD
Name:	NYS DIV MILITARY NAVAL AFFAIRS	**Street 2:**	
Date Became Current:		**City:**	LATHAM
Date Ended Current:		**State:**	NY
Phone:	518-786-4495	**Country:**	US
Source Type:	Implementer	**Zip Code:**	12110-2224
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	OLD NISKAYUNA RD
Name:	NYS DIV OF MILITARY & NAVAL AFFAIRS	**Street 2:**	
Date Became Current:	20060905	**City:**	LATHAM
Date Ended Current:		**State:**	NY
Phone:	518-786-4495	**Country:**	US
Source Type:	Notification	**Zip Code:**	12110-2224
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	State	**Street 1:**	OLD NISKAYUNA RD
Name:	NYS DIV MILITARY & NAVAL AFFAIRS	**Street 2:**	
Date Became Current:	19791231	**City:**	LATHAM
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	12110-2224
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	OLD NISKAYUNA RD
Name:	NYS DIVISION OF MILITARY & NAVAL AFFAIRS	**Street 2:**	
Date Became Current:	19791231	**City:**	LATHAM
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	12110-2224

Historical Handler Details

Receive Dt:	20040129
Generator Code Description:	Large Quantity Generator
Handler Name:	OMS #1
Receive Dt:	20060905
Generator Code Description:	Very Small Quantity Generator
Handler Name:	NYS DMNA - FMS #1
Receive Dt:	19951120
Generator Code Description:	Small Quantity Generator
Handler Name:	NYS DIV MILITARY NAVAL AFFAIRS - OMS #1
Receive Dt:	20060904
Generator Code Description:	Small Quantity Generator
Handler Name:	NYS DMNA - FMS #1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	3 of 9	E	0.21 / 1,083.89	677.33 / 33	MASTEN AVENUE ARMORY 27 MASTEN AVE Buffalo NY 14204	AST

Site ID:	53860	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Erie
Program No:	9-391514	**UTM X:**	184939.64704
Program Type Code:	PBS	**UTM Y:**	4757268.99294
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Prog No:	9-391514	**UDC Ind:**	1
Tank ID:	162854	**Red Tag Start Date:**	
Tank No:	5	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	09/01/1982	**Next Line Test Due:**	
Close Date:	10/01/1997	**Line Test Method:**	
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	2000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: I04
Code Name: Product Level Gauge (A/G)
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	9-391514	***UDC Ind:***	1
Tank ID:	162856	***Red Tag Start Date:***	
Tank No:	7	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Line Last Test Due:***	
Install Date:	12/01/1960	***Next Line Test Due:***	
Close Date:	06/01/1994	***Line Test Method:***	
Tk Out of Serv Dt:		***Class A Operator:***	
Capacity (Gal):	1000	***Class B Operator:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 1
Tank Location Desc: Aboveground-contact w/ soil
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I00
Code Name: None
Type: Overfill

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G00
Code Name: None

Type: Tank Secondary Containment

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: B14
Company: NYS DIV MILITARY NAVAL AFFAIRS
Contact Title:
Contact Name:
Address1: 330 OLD NISKAYUNA RD
Address2:
City: LATHAM
State: NY
Zip Code: 12110
Country Code: 001
Phone: (518) 786-4347
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: NYS DIV MILITARY NAVAL AFFAIRS
Contact Title:
Contact Name: MNFE-EC, HEIDI GABEL
Address1: 330 OLD NISKAYUNA RD
Address2:
City: LATHAM
State: NY
Zip Code: 12110-2224
Country Code: 001
Phone: (518) 786-4495
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: NYS DIV MILITARY NAVAL AFFAIRS
Contact Title:
Contact Name: MR. REGINALD HARRIS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (716) 881-7417
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: MASTEN AVENUE ARMORY
Contact Title:
Contact Name: MR. REGINALD HARRIS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (716) 881-7417

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Phone Ext:						
Email:						
Fax:						
51	4 of 9	E	0.21 / 1,083.89	677.33 / 33	MASTEN AVENUE ARMORY 27 MASTEN AVE Buffalo NY 14204	UST

Site ID:	53860	**Expiry:**	N/A
Site Status:	Unregulated/Closed	**County:**	Erie
Program No:	9-391514	**UTM X:**	184939.64704
Program Type Code:	PBS	**UTM Y:**	4757268.99294
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	Other		

Tank Information

Prog No:	9-391514	**UDC Ind:**	1
Tank ID:	162853	**Red Tag Start Date:**	
Tank No:	4	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	08/01/1995
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	02
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	05/01/1967	**Next Test:**	
Close Date:	10/01/1997	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	3000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	5		
Tank Location Desc:	Underground		
Category:	1		
Category Desc:	Category 1 means a tank which was installed before December 27, 1986		
Subpart:			
Subpart Desc:			
Class A Operator:			
Class B Operator:			
Tank Owner Name:			
Tank Owner Address:			

Material Information

Material Name:	#2 fuel oil (on-site consumption)
Percent:	100.00

Equipment Information

Equipment:	B01
Code Name:	Painted/Asphalt Coating
Type:	Tank External Protection
Equipment:	G00
Code Name:	None
Type:	Tank Secondary Containment
Equipment:	I05
Code Name:	Vent Whistle
Type:	Overfill
Equipment:	C02
Code Name:	Underground/On-ground
Type:	Pipe Location

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Tank Information

Prog No:	9-391514	**UDC Ind:**	1
Tank ID:	162851	**Red Tag Start Date:**	
Tank No:	2	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1972	**Next Test:**	
Close Date:	10/01/1990	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	800	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Tank Information

Prog No:	9-391514	**UDC Ind:**	1
Tank ID:	162850	**Red Tag Start Date:**	
Tank No:	1	**Red Tag End Date:**	
Tank Status:	3	**Tank Last Test:**	07/01/1988
Tank Status Desc:	Closed - Removed	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	05
Tank Type Desc:	Steel/Carbon Steel/Iron	**Date Tested:**	
Install Date:	12/01/1973	**Next Test:**	
Close Date:	10/01/1990	**Line Last Test Due:**	
Tk Out of Serv Dt:		**Next Line Test Due:**	
Capacity (Gal):	4000	**Line Test Method:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: gasoline
Percent: 100.00

Equipment Information

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: A00
Code Name: None

Type: Tank Internal Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Tank Information

Prog No:	9-391514	***UDC Ind:***	1
Tank ID:	162852	***Red Tag Start Date:***	
Tank No:	3	***Red Tag End Date:***	
Tank Status:	3	***Tank Last Test:***	
Tank Status Desc:	Closed - Removed	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:	11/01/1991	***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	1000	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: diesel
Percent: 100.00

Equipment Information

Equipment: J02

Code Name: Suction Dispenser
Type: Dispenser

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: I00
Code Name: None
Type: Overfill

Tank Information

Prog No:	9-391514	***UDC Ind:***	1
Tank ID:	162855	***Red Tag Start Date:***	
Tank No:	6	***Red Tag End Date:***	
Tank Status:	6	***Tank Last Test:***	
Tank Status Desc:	Closed Prior to 03/1991	***Tank Next Test Due:***	
Tank Type:	01	***Test Method:***	NN
Tank Type Desc:	Steel/Carbon Steel/Iron	***Date Tested:***	
Install Date:		***Next Test:***	
Close Date:		***Line Last Test Due:***	
Tk Out of Serv Dt:		***Next Line Test Due:***	
Capacity (Gal):	500	***Line Test Method:***	
Registered:	True	***Modified by:***	MJGRIFFI
Tank Model:		***Last Modified:***	05/09/2022
Pipe Model:			

Tank Location: 5
Tank Location Desc: Underground
Category: 1
Category Desc: Category 1 means a tank which was installed before December 27, 1986
Subpart:
Subpart Desc:
Class A Operator:
Class B Operator:
Tank Owner Name:
Tank Owner Address:

Material Information

Material Name: other
Percent: 100.00

Equipment Information

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Equipment: G00
Code Name: None
Type: Tank Secondary Containment

Equipment: H00
Code Name: None
Type: Tank Leak Detection

Equipment: I00
Code Name: None
Type: Overfill

Equipment: B00
Code Name: None
Type: Tank External Protection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Affiliation Information

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: B14
Company: NYS DIV MILITARY NAVAL AFFAIRS
Contact Title:
Contact Name:
Address1: 330 OLD NISKAYUNA RD
Address2:
City: LATHAM
State: NY
Zip Code: 12110
Country Code: 001
Phone: (518) 786-4347
Phone Ext:
Email:
Fax:

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: NYS DIV MILITARY NAVAL AFFAIRS
Contact Title:
Contact Name: MR. REGINALD HARRIS
Address1:
Address2:
City:
State: NN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Zip Code:
Country Code: 001
Phone: (716) 881-7417
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: NYS DIV MILITARY NAVAL AFFAIRS
Contact Title:
Contact Name: MNFE-EC, HEIDI GABEL
Address1: 330 OLD NISKAYUNA RD
Address2:
City: LATHAM
State: NY
Zip Code: 12110-2224
Country Code: 001
Phone: (518) 786-4495
Phone Ext:
Email:
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: MASTEN AVENUE ARMORY
Contact Title:
Contact Name: MR. REGINALD HARRIS
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (716) 881-7417
Phone Ext:
Email:
Fax:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	5 of 9	E	0.21 / 1,083.89	677.33 / 33	NYS NATIONAL GUARD 27 MASTEN AVENUE BUFFALO NY	NY SPILLS

Spill No: 9907527
Site ID: 219354
DER Facility ID: 181393
CID: 211
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D3
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 1999-09-22 14:10:00
Received Date: 1999-09-22 14:20:00
CAC Date:
Insp Date: 1999-09-23 00:00:00
Close Date: 1999-09-24 00:00:00
Create Date: 1999-09-22 00:00:00
Update Date: 1999-09-30 00:00:00
DEC Region: 9
Lead DEC: RMCROSSE
After Hours: False

Caller Remark:

"historical spill - waste products from vehicles - soil affected no clean up"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/23/99: RMC SITE INSPECTION, MET SGT IMAGNA AND HEIDE GABEL, 518-786-4347, SPILLAGE FROM VEHICLE, WHICH MUST HAVE MINOR HISTORICAL LEAKING PROBLEM, TO INSIDE OF STORAGE SHED ON GRAVEL WHERE PARKED, NOTED TRIANGULAR AREA 6 BY 10 BY 8 FEET IMPACTED WITH STAINED GRAVEL, RMC ADVISED TO BAG UP MINOR AMOUNT OF GRAVEL IMPACTED AND DISPOSE OF IN NORMAL WASTESTREAM, PROVIDED 6MILL GARBAGE BAGS, ALSO TO CHECK MACHINE FOR LEAKS AND REPAIR IF NECESSARY, CLOSE OUT "

Material Information

OP Unit ID:	1081806	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	300230	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0043A		
Material Name:	antifreeze		

OP Unit ID:	1081806	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	300229	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	ANTHONY IMAGNA
Spiller Company:	NYS NATIONAL GUARD
Spiller Address:	27 MASTEN AVENUE ARMORY
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902880370
Longitude:	-78.859717710

51	***6 of 9***	***E***	***0.21 / 1,083.89***	***677.33 / 33***	***NATIONAL GUARD BUILDING 27 MASTEN AVE BUFFALO NY***	***NY SPILLS***

Spill No:	9708830	***UST Trust:***	False
Site ID:	264237	***Spill Date:***	1997-10-28 11:00:00
DER Facility ID:	215366	***Received Date:***	1997-10-28 16:52:00
CID:	267	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1997-10-31 00:00:00
Water Body:		***Create Date:***	1997-10-28 00:00:00
Class:	D4	***Update Date:***	1997-11-12 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RMCROSSE
REM Phase:	0	***After Hours:***	True

County:	Erie
Contributing Factor:	Equipment Failure
Reported by:	Affected Persons
Referred to:	
Source:	Commercial Vehicle
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"FUEL LAEKING FROM AN M1 TANK INSIDE THE BUILDING ONTO THE BLACKTOP FLOOR CALLER WAS JUST ADVISED OF THIS AND WILL BE FOLLOWING UP TOMORROW AM UNKNOWN IF THIS IS A SPILL OR CAUSED BY THE HEAT OF THE TANK CALLER WILL UPDATE DEC TOMORROW"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/28/97 RMC/FILE LEFT MESSAGE FOR RP TO CALL 10/31/97 RMC/FILE KAH TOOK CALL FROM JAMES FREEHART, NATIONAL GUARD, WHO STATED THAT MINOR SPILL HAPPENED TOTALLY WITHIN BUILDING SOMETIME IN 1995, THEY JUST REALIZED THAT REPORTING WAS REQUIRED, SPILL WAS CLEANED UP WITH SPEEDY DRY, RMC VIEWED THIS AS A MINOR SPILL TO BEGIN WITH AND BEING CLEANED UP YEARS AGO, NO ACTION REQUIRED, CLOSE OUT "

Material Information

OP Unit ID:	1055265	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	330773	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	JAMES FREEHART
Spiller Company:	NYS NATIONAL GUARD
Spiller Address:	27 MASTEN AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14204-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902880370
Longitude:	-78.859717710

51	7 of 9	E	0.21 / 1,083.89	677.33 / 33	**MASTEN AVENUE ARMORY** **27 MASTEN AVENUE** **BUFFALO NY**	LST

Spill No:	8904853	**REM Phase:**	0
Site ID:	219352	**UST Trust:**	True
DER Facility ID:	181393	**Spill Date:**	1989-08-15 20:15:00
CID:		**Rcvd Date:**	1989-08-15 22:14:00
Program Type:	ER	**CAC Date:**	1990-11-14 00:00:00
SWIS Code:	1502	**Insp Date:**	1990-11-14 00:00:00
Contribute Factor:	Tank Test Failure	**Close Date:**	1990-11-14 00:00:00
Water Body:		**Create Date:**	1989-08-16 00:00:00
Class:		**Update Date:**	1990-12-18 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	LYONS

County: Erie
After Hours: True
Referred to:
Reported by: Tank Tester
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"4000 GAL LEAK RATE -O.37047 GPH"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 08/16/89: LQR TELCON W/ SPILLER RETEST BEING PREFORMED. 09/25/89: LQR TELCON W/ SPILLER TANK TO BE REMOVED LETTER TO SPILLER SENT. 11/17/89: LQR TELCON W/ SPILLER BIDS OUT TO REMOVE 2 TANKS. 01/30/90: LQR TELCON W/ SPILLER REMOVE 2 TANKS AFTER 04/01/90. 11/14/90: MEL INSP. TANKS REMOVED FROM GROUND, NO CONTAMINATION OBSERVED. NO FURTHER ACTION NECESSARY, RECOMMEND FILE BE CLOSED. 09/29/95: This is additional information about material spilled from the translation of the old spill file: UNKNOWN AMOUNT."

Material Information

OP Unit ID: 932603
OU: 01
Material ID: 448884
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0009
Material Name: gasoline

Med in Air: False
Med GW: True
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: MASTEN AVENUE ARMORY
Spiller Address: 27 MASTEN AVENUE
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.902880370
Longitude: -78.859717710

Tank Test Information

Spill Tank ID: 1535858
Tank No:
Tank SIze: 0
Material: 0009
EPA UST:
UST:
Cause:
Alt Test Method: Unknown

Source:
Leak Rate: .00
Gross Fail:
Modified by: Spills
Last Modified: 2004-10-01 04:00:45.140000000
Test Method: 00

51	8 of 9	E	0.21 / 1,083.89	677.33 / 33	NYS ARMORY 27 MASTEN STREET BUFFALO NY	LST

Spill No: 9709636
REM Phase: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site ID:	106039	**UST Trust:**	True
DER Facility ID:	93469	**Spill Date:**	1997-11-19 08:00:00
CID:	999	**Rcvd Date:**	1997-11-19 11:30:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	1997-11-20 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1998-03-30 00:00:00
Water Body:		**Create Date:**	1997-11-19 00:00:00
Class:	B3	**Update Date:**	1998-05-11 00:00:00
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"REMOVED 5000 GALLON TANK AND FOUND CONTAMINATION"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 11/19/97 AND 11/20/97: RMC/SITE, MET WITH MARSHALL KIMMONS, CONTAMINATION NOTED IN TANK PIT UPON REMOVAL, KIMMONS REMOVED APPROXIMATELY 200 TONS SOIL AND TOOK POST EXCAVATION SAMPLES, LETTER TO RP, SAMPLE RESULTS AND DISPOSAL RECEIPTS DUE 1/30/98 12/02/97: RMC/FILE, TANK WAS MIS-REPORTED AS A 5OOO GALLON TANK, ACTUAL TANK IS A 3000 GALLON FUEL OIL TANK 12/04/97: RMC/FILE, RECEIVED EXCAVATION SAMPLE REPORT, MINOR EXCEEDANCES, DISPOSAL DUE 1/30/98 01/15/98: RMC/HEIDI GABEL/PHONE, GABEL HAS BEEN UNABLE TO CONTACT KIMMONS, FAXED CONTRACTORS LIST, RESPONSE DUE 2/28/98 03/30/98: RMC/FILE, RECEIVED DISPOSAL DOCUMENTS, OK, SITE TO BE MADE INACTIVE PER RNL, LETTER, INACTIVE"

Material Information

OP Unit ID:	1052680	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	327972	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	HEIDI GABEL
Spiller Company:	NYS DIV MILITARY NAVAL AF
Spiller Address:	330 OLD NISKAYUNA ROAD
Spiller City:	LATHAM
Spiller State:	NY
Spiller Zip:	12210-2224
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902880370
Longitude:	-78.859717710

51	9 of 9	E	0.21 / 1,083.89	677.33 / 33	MASTEN AVENUE ARMORY 27 MASTEN AVENUE BUFFALO NY	LST

Spill No:	9305872	**REM Phase:**	0

Site ID:	219353	**UST Trust:**	False
DER Facility ID:	181393	**Spill Date:**	1993-08-11 12:00:00
CID:		**Rcvd Date:**	1993-08-12 15:15:00
Program Type:	ER	**CAC Date:**	1993-08-27 00:00:00
SWIS Code:	1502	**Insp Date:**	1993-08-27 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	1993-08-27 00:00:00
Water Body:		**Create Date:**	1993-08-13 00:00:00
Class:	C3	**Update Date:**	1993-08-31 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	DEC		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK #7 WAS OVERFILLED, NOTED DURING PBS INSPECTION."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 08/20/93: RMC/LESLIE FISHER SUPT OF MAINTENANCE/PHONE RP TO REMOVE CONTAMINATED SOIL, RMC TO INSPECT NEXT WEEK. 08/27/93: RMC/LESLIE FISHER SUPT OF MAINTENANCE/SITE CONTAMINATION REMOVED TO NORMAL DUMPSTER PICKUP, NO FURTHER ACTION REQUIRED, CLOSE OUT. "

Material Information

OP Unit ID:	987352	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	395775	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	MASTEN AVENUE ARMORY
Spiller Address:	27 MASTEN AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14203
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902880370
Longitude:	-78.859717710

Tank Test Information

Spill Tank ID:	1541872	**Source:**	
Tank No:	007	**Leak Rate:**	.00
Tank SIze:	0	**Gross Fail:**	
Material:	0022	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	00
Cause:	02		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Alt Test Method:		Unknown				
52	1 of 1	E	0.21 / 1,090.40	677.81 / 33	CITY HONORS SCHOOL MASTEN AVE & NORTH BUFFALO NY 14204	RCRA NON GEN

EPA Handler ID: NYD986940328
Gen Status Universe: No Report
Contact Name: MICHAEL ANELLI
Contact Address: MASTEN AVE & NORTH, BUFFALO, NY, 14204, US
Contact Phone No and Ext: 716-885-7279
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type:
Receive Date: 20070101
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation: SR - 371.1(f)
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 20050404
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20060526
Violation Responsible Agency: EPA

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 20060405
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: EPA
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20050404
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 20060526
Evaluation Agency: EPA

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19910212
Handler Name:	CITY HONORS SCHOOL
Source Type:	Notification
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code:	NONE
Waste Code Description:	DESCRIPTION

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20070101
Handler Name:	CITY HONORS SCHOOL
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20060101
Handler Name:	CITY HONORS SCHOOL
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Municipal	***Street 1:***	712 CITY HALL
Name:	BUFFALO BD OF ED	***Street 2:***	
Date Became Current:		***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-842-3166	***Country:***	
Source Type:	Notification	***Zip Code:***	14202

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Municipal	***Street 1:***	712 CITY HALL
Name:	BUFFALO BD OF ED	***Street 2:***	
Date Became Current:		***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-842-3166	***Country:***	US
Source Type:	Implementer	***Zip Code:***	14202

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Municipal	**Street 1:**	712 CITY HALL
Name:	BUFFALO BD OF ED	**Street 2:**	
Date Became Current:		**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-842-3166	**Country:**	US
Source Type:	Implementer	**Zip Code:**	14202

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Municipal	**Street 1:**	712 CITY HALL
Name:	BUFFALO BD OF ED	**Street 2:**	
Date Became Current:		**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-842-3166	**Country:**	
Source Type:	Notification	**Zip Code:**	14202

Historical Handler Details

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	CITY HONORS SCHOOL

Receive Dt:	19910212
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CITY HONORS SCHOOL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
53	1 of 1	N	0.21 / 1,091.38	644.09 / 0	BISHOP LESLIE 1059 ELLICOTT ST BUFFALO NY 14209	RCRA NON GEN

EPA Handler ID:	NYR000060442
Gen Status Universe:	No Report
Contact Name:	WILLIE ROBERSON
Contact Address:	1059, ELLICOTT ST, BUFFALO, NY, 14209, US
Contact Phone No and Ext:	212-555-1212
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	
Receive Date:	20070101
Location Latitude:	42.906839
Location Longitude:	-78.864774

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No

Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19980918
Handler Name: BISHOP LESLIE
Source Type: Notification
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: BISHOP LESLIE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: BISHOP LESLIE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: LESLIE BISHOP
Date Became Current:
Date Ended Current:
Phone: 716-888-8007
Source Type: Implementer
Street No:
Street 1: 1059 ELLICOTT ST
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14209

Owner/Operator Ind: Current Owner
Type: Private
Name: LESLIE BISHOP
Date Became Current:
Date Ended Current:
Phone: 716-888-8007
Source Type: Implementer
Street No:
Street 1: 1059 ELLICOTT ST
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14209

Owner/Operator Ind: Current Owner
Type: Private
Name: LESLIE BISHOP
Date Became Current:
Date Ended Current:
Phone: 716-888-8007
Source Type: Notification
Street No:
Street 1: 1059 ELLICOTT ST
Street 2:
City: BUFFALO
State: NY
Country:
Zip Code: 14209

Historical Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: BISHOP LESLIE

Receive Dt: 19980918
Generator Code Description: Very Small Quantity Generator
Handler Name: BISHOP LESLIE

---

54 | **1 of 2** | **NNW** | **0.21 / 1,094.56** | **649.15 / 5** | **ARTSPACE**
1219-1233 MAIN STREET
BUFFALO NY | **NY SPILLS**

Spill No:	0600379	**UST Trust:**	False
Site ID:	362362	**Spill Date:**	2006-04-11 09:04:00
DER Facility ID:	312616	**Received Date:**	2006-04-11 09:04:00
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	2006-09-15 00:00:00
SWIS Code:	1502	**Close Date:**	2006-10-26 00:00:00
Water Body:		**Create Date:**	2006-04-11 09:25:00
Class:	C3	**Update Date:**	2007-05-09 15:12:59.640000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	JFOTTO
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Other
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"WHILE DOING SOIL BORINGS FOUND CONTAMINATION:"

DEC Remark:

"04/11/06 JFO TELCON WITH JEFF RAWLEY WITH LCS. THEY DID A PHASE II ON THE PROPERTY. THIS SITE HAS AN INACTIVE STATUS. JEFF WILL SUBMIT THE RESULTS WHEN HE GETS APPROVAL. THE RESULTS WILL DETERMINE IF THE SITE CAN REMAIN INACTIVE. 04/21/06 JFO RECEIVED A COPY OF THE PHASE II AND DISCUSSED WITH SAC. WE AGREED THAT THERE ARE A COUPLE AREAS THAT NEED TO BE ADDRESSED. DOUG REID FROM LCS WANTS TO KNOW IF THEY CAN REMEDIATE WHEN THE CONSTRUCTION BEGINS. I CALLED DOUG AND GAVE A VERBAL APPROVAL. 04/25/06 JFO CALL FROM DOUG REID, HE NEEDS A LTR INDICATING THE CONTAMINATION CAN BE ADDRESSED WHEN THEY BEGIN CONSTRUCTION THIS SUMMER. LETTER SENT 05/16/06 JFO RECEIVED THE CORRECTIVE ACTION PLAN. REVIEWED AND APPROVED WHEN THEY ADD BH-7 INVESTIGATION. LTR SENT TO DOUG REID. CC'D CAMERON O'CONNOR DOH. 05/ /06 JFO RECEIVED A CALL FROM PETER GORTON WITH PAN AMERICAN ENV. THEY WILL BE DOING THE WORK AND WILL FOLLOW THE PLAN SUBMITTED BY LCS. 06/14/06 JFO ON SITE MET WITH PETER G. IN BH-1 THEY FOUND NO CONTAMINATION, A SAMPLE WAS COLLECTED. THEY HAVE DUG THE AREA NORTH OF BH-4 AND FOUND CONTAMINATE4ED SOIL. THEY ARE STAGING IT ON THE SOUTH SIDE OF THE PROPERTY. 06/22/06 JFO ON SITE MET WITH JUSTIN AND PETER G. THEY DISCOVERED A TANK IN THE AREA OF BH-11 THEY WILL REMOVE IT AND DIG TO CLEAN. SO FAR THEY HAVE DISPOSED OF APPROX 1500 TONS. 06/29/06 JFO ON SITE MET WITH JUSTIN. THE FIRST PIT IS BEING BACKFILLED. SAMPLES COLLECTED. THE SECOND PITIS CLEAN AT SOUTH END AND BOTTOM. THEY WILL KEEP DIGGING TO THE NORTH. 07/07/06 JFO ON SITE MET WITH PETE G. THEY HAVE DUG TO THE FENCE LINE ON THE EAST SIDE OF THE PROPERTY. 07/24/06 JFO ON SITE WITH PETE GORTON. EXCAVATION COMPLETE. SIDEWALLS AND BOTTOM SAMPLES COLLECTED. 12,000 TONS DISPOSED. 09/15/06 JFO AND FG ON SITE MET WITH PETE G AND ATTY: CRAIG SLATER. SAVARINO WAS INSTALLING A 48 SEWER LINE ON THE SOUTH SIDE OF THE PROPERTY AND DISCOVERED SOME DISCOLORED SOIL. A 3' AREA 12 THICK. THEY WILL SAMPLE. ALSO THEY DUG A TEST PIT (12 DEEP) IN THE AREA OF BH-7 AND BH-6. THEY FOUND NO CONTAMINATION OR ODORS. THEY SAMPLED BOTH PITS. 09/21/06 JFO RECEIVED THE RESULTS OF THE SAMPLES. 1 THE STORM SEWER MATERIAL IS SLIGHTLY OVER TAGMS ON ONE COMPOUND ONLY. BENZO(A)ANTHRACENE 320 PPB TAGMS 224 PPB 2 THE TEST PIT IS <TAGMS FOR SVOC AND VOC. 3 THE SOIL PILE IS OVER TAGMS OIN 5 COMPOUNDS AND WILL HAVE TO BE DISPOSED. JFO CALL TO PETE GORTON AND INFORMED HIM THAT THE SOIL PILE NEEDED TO BE DISPOSED. 10/02/06 JFO RECEIVED E-MAIL FROM CRAIG SLATER. HE SPOKE WITH MARK HANS WITH SOLID WASTE. MARK HAS NO PROBLEM REUSING THE SOIL UNDER THE BUD EXEMPTION SINCE IT IS ONLY SLIGHTLY ABOVE TAGMS FOR 5 COMPOUNDS. I DISCUSSED WITH FG AND AGREE. I SENT CRAIG AN E-MAIL INFORMING HIM THE SOIL CAN BE REUSED ON SITE. 10/26/06 JFO RECEIVED THE CLOSURE REPORT. FOR THE 2 MAIN EXCAVATIONS, ALL SAMPLE RESULTS ARE <TAGMS. STORM SEWER EXCAVATION SAMPLE IS ABOVE TAGMS FOR 1 COMPOUND BENZO(A)ANTHRACENE 320PPB LCS SOIL BORING BH-01 IS ABOVE TAGMS FOR 2 COMPOUNDS BENZO(A)PYRENE 220PPB AND DIBENZO(A)ANTHRACENE 50PPB THIS SITE WILL BE INACTIVE. NO FURTHER ACTION REQUIRED AT THIS TIME. CLOSED 05/09/07 JFO SENT INACTIVE LTR TO ATTY. CRAIG SLATER AT HIS REQUEST"

Material Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	1120463	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2109955	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

OP Unit ID:	1120463	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2109959	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	WILL LAW
Spiller Company:	ARTSPACE PROJECT
Spiller Address:	250 THIRD ST NORTH
Spiller City:	MINNEAPOLIS
Spiller State:	MN
Spiller Zip:	55401
Spiller Country:	001
Contact Name:	PETE GORTON
Contact Phone:	(716)308-8220
Contact Ext:	
Latitude:	42.906759000
Longitude:	-78.867427000

54	2 of 2	NNW	0.21 / 1,094.56	649.15 / 5	FORMER SARA BETH BUILDING 1219-1233 MAIN STREET BUFFALO NY	NY SPILLS

Spill No:	0485354	**UST Trust:**	False
Site ID:	335483	**Spill Date:**	2004-12-22 12:00:00
DER Facility ID:	312616	**Received Date:**	2004-12-22 12:00:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2005-01-27 00:00:00
Water Body:		**Create Date:**	2004-12-22 11:26:00
Class:		**Update Date:**	2005-01-27 11:17:32.140000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Contamination found while conducting subsurface investigation. Suspect former USTs. Contamination also found on adjoining City of Buffalo property."

DEC Remark:

"1/27/05 CLOSED OUT UNDER SPILL 0485478. PLEASE REFER TO THAT SPILL FOR CLOSURE DOCUMENTATION."

Material Information

OP Unit ID:	1097544	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	577530	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	False
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	MARK PAGANO
Contact Phone:	
Contact Ext:	
Latitude:	42.906762106
Longitude:	-78.867379869

55	***1 of 1***	***W***	***0.22 / 1,159.45***	***659.28 / 15***	***BFI TRUCK 33 LINWOOD AVENUE BUFFALO NY***	***NY SPILLS***

Spill No:	9975353	***UST Trust:***	False
Site ID:	327272	***Spill Date:***	1999-08-12 09:00:00
DER Facility ID:	263440	***Received Date:***	1999-08-12 09:50:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1999-08-12 00:00:00
Water Body:		***Create Date:***	1999-08-12 16:16:00
Class:	D4	***Update Date:***	1999-09-01 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	BRENNAN
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HYDRAULIC LINE RUPTURE ON BFI REFUSE TRUCK. OIL RAN INTO STORM SEWER. BFI WAS GOING TO SOAK UP OIL WITH BOOM. "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KAB 08/12/99: FRANK SHATTUCK TOOK REPORT AND PASSED ON TO KAB. KAB CONTACTED JIM CARUSO, BSA, AND ADVISED HIM THAT HYDRAULIC OIL WAS LEAKING DIRECTLY TO STORM SEWER. HE WILL SEND

SOMEONE OUT. NO FURTHER ACTION NECESSARY. CLOSE OUT."

Material Information

OP Unit ID:	1091508	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	291875	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	True
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	
Spiller Company:	BFI
Spiller Address:	2321 KENMORE AVENUE
Spiller City:	KENMORE
Spiller State:	NY
Spiller Zip:	14217-
Spiller Country:	001
Contact Name:	MIKE NEARY
Contact Phone:	(716) 614-3333
Contact Ext:	
Latitude:	42.903048993
Longitude:	-78.870689023

---

56 ***1 of 2*** ***NNW*** ***0.23 / 1,206.26*** ***649.77 / 5*** ***M J GRASS SCREW MACHINE 1233 MAIN STREET BUFFALO NY*** ***NY SPILLS***

Spill No:	8807560	***UST Trust:***	False
Site ID:	172756	***Spill Date:***	1988-10-12 12:00:00
DER Facility ID:	145383	***Received Date:***	1988-12-14 15:35:00
CID:		***CAC Date:***	1990-10-22 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1990-10-22 00:00:00
Water Body:		***Create Date:***	1989-01-26 00:00:00
Class:		***Update Date:***	1990-10-22 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	COOKE
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Affected Persons		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SPILLER IS ACCORDING TO CALLER DUMPING ACID IN SEWERS ON HIS PROPERTY."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 01/25/89: MNP CONTACTED CALLER AND JIM KRUSKA, BSA ABOUT THE MATTER. CALLER WILL BE SENDING A LETTER THAT OUTLINES THE SPILL OCCURANCES. JDC WILL MAKE SITE INSPECTION. 01/30/89: CONTACTED CALLER AND CONFIRMED SPILL INCIDENT 1/30/89. CALLER WILL BE FORWARDING EVIDENCE TO THE SAME TO AIDE IN THE INVESTIGATION. BSA IS ALSO INVESTIGATING. 02/16/89: JDC SPOKE W/ J GREOBE, BECI WHO WILL BE FOLLOWING UP W/ CALLER FOR INVESTIGATIVE PURPOSES. BSA INSPECTED SITE AND FOUND NO SPILLAGE. NO SPECIAL PERMITS HAVE BEEN ISSUED BY BSA FOR

DUMPING. "

Material Information

OP Unit ID:	923035	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	455893	***Med SW:***	False
CAS No:	07647010	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	True
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0029C		
Material Name:	hydrogen chloride		

Spiller Information

Spiller Name:	
Spiller Company:	MJ GRASS SCREW MACHINE CO
Spiller Address:	19 NORTH HAMPTON
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14209
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.907143680
Longitude:	-78.867308510

56	***2 of 2***	***NNW***	***0.23 / 1,206.26***	***649.77 / 5***	***G&E MANAGEMENT 1233 MAIN ST BUFFALO NY***	***NY SPILLS***

Spill No:	9100320	***UST Trust:***	False
Site ID:	120328	***Spill Date:***	1991-04-05 12:00:00
DER Facility ID:	104481	***Received Date:***	1991-04-08 10:00:00
CID:		***CAC Date:***	1991-04-10 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1991-04-10 00:00:00
Water Body:		***Create Date:***	2003-12-02 00:00:00
Class:		***Update Date:***	2003-12-02 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	MJHINTON
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Affected Persons		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"PRIVATE SEWER PLUGGED WITH CUTTING OIL AND METEL SHAVINGS"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH 04/10/91: BSA INSPECTED SITE FOUND NOTHING OF CONCERN PROBLEM IS A PRIVATE MATTER, FOLLOWUP REFERRED TO RAY HENNING RECRA FOR SITE INSPECTION NO ACTION BY SPILL UNIT NEEEDED. 09/29/95: This is additional information about material spilled from the translation of the old spill file: OILY SLUDGE."

Material Information

OP Unit ID:	951158	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	426528	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	True
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	M.J. GRESS
Spiller Address:	NORTH HAMPTON
Spiller City:	BUFFALO
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.907143680
Longitude:	-78.867308510

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
57	*1 of 1*	*NNW*	*0.23 / 1,227.57*	*650.27 / 6*	***NIAGARA MOHAWK A NATIONAL GRID CO*** ***1229 MAIN ST*** ***BUFFALO NY 14209***	***RCRA NON GEN***

EPA Handler ID:	NYP000968909
Gen Status Universe:	No Report
Contact Name:	MARGARET M CARD
Contact Address:	300, ERIE BLVD W, SYRACUSE, NY, 13202, US
Contact Phone No and Ext:	315-428-6670
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	
Receive Date:	20121206
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No

Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20121206
Handler Name:	NIAGARA MOHAWK A NATIONAL GRID CO
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20121012
Handler Name:	NIAGARA MOHAWK A NATIONAL GRID CO
Source Type:	Emergency
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Waste Code Details

Hazardous Waste Code:	D008
Waste Code Description:	LEAD

Historical Handler Details

Receive Dt:	20121012
Generator Code Description:	Large Quantity Generator
Handler Name:	NIAGARA MOHAWK A NATIONAL GRID CO

---

58 | ***1 of 1*** | ***NNW*** | ***0.24 / 1,258.75*** | ***649.78 / 5*** | ***CAO DART***
1237 MAIN STREET
BUFFALO NY | ***NY SPILLS***

Spill No:	0175280	**UST Trust:**	False
Site ID:	89514	**Spill Date:**	2001-08-23 09:00:00
DER Facility ID:	81757	**Received Date:**	2001-08-23 10:24:00
CID:		**CAC Date:**	2001-08-24 00:00:00
Program Type:	ER	**Insp Date:**	2001-08-23 00:00:00
SWIS Code:	1502	**Close Date:**	2001-08-24 00:00:00
Water Body:		**Create Date:**	2001-08-23 10:28:00
Class:	D6	**Update Date:**	2001-08-24 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Affected Persons		
Referred to:			
Source:	Unknown		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"SULFURLIKE ODORS OBSERVED INSIDE BUILDING IN DISPENSING ROOM"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 08/23/01: MF S/I/CYNTHIA DAWSON, BUILDING MAINTANANCE & MANAGER. AFTER A COMPLAINT OF A SULFUR ODOR IN METHODONE CLINIC DISPENSING ROOM. THEY DO NOT USE ANY LIQUIDS IN THIS ROOM OTHER THEN WATER. THERE ARE NO LEAKS IN THE SINK TRAP. THERE ARE NO FLOOR DRAINS. THE AIR CONDITIONING SYSTEM SERVICES THE ENTIRE BUILDING. THERE IS A SMALL CEILING FAN BETWEEN THE FALSE CEILING & THE ORIGINAL CEILING. THERE IS NO DUCT WORK FOR THIS FAN. THERE ARE NO SIGNS OF SPILLAGE ON THE CEILING TILES. THERE ARE NO OTHER COMPLAINTS IN THE BUILDING. THIS ROOM IS APPX 10' x 102'. RECOMMENDED DISCONNECTING THE FAN. ALSO TOLD THEM IF THE 2 EMPLOYEES CONTINUE TO COMPLAIN TO CALL THE FD OR OSHA OR BOTH. I DID NOT NOTICE ANY ODOR IN THE ROOM OR BUILDING NOR DID CYNTHIA OR ANY OTHER EMPLOYEES. THE ONLY COMPLAINT WAS FROM THE 2 EMPLOYEES WORKING IN THE DISPENSING ROOM. 08/24/01: MF T/C/CYNTHIA DAWSON, NO FURTHER COMPLAINTS. NO FURTHER ACTION POSSIBLE."

Material Information

OP Unit ID:	853037	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	524603	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	True		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	-
Spiller Country:	001
Contact Name:	CYNTHIA DAWSON - HD NURSE
Contact Phone:	(716) 884-9101
Contact Ext:	
Latitude:	42.907253150
Longitude:	-78.867266370

59	***1 of 1***	***N***	***0.24 / 1,261.85***	***647.15 / 3***	***CITY OF BUFFALO PARKS 29 NORTH HAMPTON BUFFALO NY***	***NY SPILLS***

Spill No:	9913377	**UST Trust:**	True
Site ID:	154621	**Spill Date:**	2000-02-25 12:00:00
DER Facility ID:	131078	**Received Date:**	2000-02-25 15:44:00
CID:	252	**CAC Date:**	
Program Type:	ER	**Insp Date:**	2000-02-28 00:00:00
SWIS Code:	1502	**Close Date:**	2000-04-10 00:00:00
Water Body:		**Create Date:**	2000-02-25 00:00:00
Class:	C3	**Update Date:**	2000-04-20 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RJJONAK
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		

Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"1000 GAL GASOLINE UNDERGROUND TANK WAS EXCAVATED - SOIL CONTAMINATION WAS DISCOVERED-TYREE IS WORKING WITH DEC AND CITY OF BUFFALO RE REMEDIATION."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 02/28/2000: RJJ SITE INSPECTION AT 0900...UST WAS ALREADY REMOVED AND EXCAVATION WAS BACKFILLED...CALLED PETE MERLO, CONTRACTOR, HE SAID THE TANK WAS REMOVED ABOUT SIX WEEKS AGO AND BACKFILLED... THEY ARE WAITING FOR THE ANALYTICAL RESULTS AND SOIL DISPOSAL RECEIPTS TO COME BACK... THEY WILL SEND ME ALL THE INFOMATION. 03/02/2000: RJJ RECEIVED THE UNDERGROUND STORAGE TANK CLOSURE REPORT FROM THE TYREE ORGANIZATION ON THE UST AT 29 NORTHAMPTON IN CITY OF BUFFALO...THE ANALYTICAL RESULTS WERE SLIGHTLY ABOVE THE ALTERNATIVE GUIDANCE VALUES, BUT SINCE THEY WERE ONLY SLIGHTLY HIGH, WE CAN MAKE THIS 'INACTIVE' AT THIS TIME...SINCE THEY USED THE EXCAVATED SOIL TO BACKFILL THE PIT, THERE ARE NO SOIL DISPOSAL RECEIPTS...I CAN NOW CLOSE OUT THIS SPILL.NO FURTHER REMEDIATION IS NEEDED AT THIS TIME. 04/17/2000: RJJ SENT 'INACTIVE' LETTER TO BOTH TYREE ORGANIZATION AND BOB O'HARA, CITY OF BUFFALO ARCHITECTURE DEPT, 616 CITY HALL, BUFFALO, NY 14202"

Material Information

OP Unit ID:	1091986	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	295229	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	DANIEL KOLKMANN
Spiller Company:	CITY OF BUFFALO
Spiller Address:	CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

60	***1 of 2***	***NNW***	***0.24 / 1,278.62***	***651.73 / 7***	***MIDCITY OFFICE EQUIPMENT INC 1220 MAIN ST BUFFALO NY 14209***	***RCRA NON GEN***

EPA Handler ID: NYR000046102
Gen Status Universe: No Report
Contact Name: BARRY COHEN
Contact Address: 1220, MAIN ST, BUFFALO, NY, 14209, US
Contact Phone No and Ext: 716-882-0666
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02

Land Type: Private
Receive Date: 20070101
Location Latitude: 42.906902
Location Longitude: -78.867435

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: MIDCITY OFFICE EQUIPMENT INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: MIDCITY OFFICE EQUIPMENT INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19980807
Handler Name: MID CITY OFFICE EQUIPMENT, INC.
Source Type: Annual/Biennial Report
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19971021
Handler Name: MIDCITY OFFICE EQUIPMENT INC
Source Type: Notification
Federal Waste Generator Code: 1

Generator Code Description: Large Quantity Generator

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: BARRY COHEN
Date Became Current:
Date Ended Current:
Phone: 716-882-0666
Source Type: Implementer
Street No:
Street 1: 1220 MAIN ST
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14209

Owner/Operator Ind: Current Operator
Type: Private
Name: BARRY COHEN
Date Became Current:
Date Ended Current:
Phone: 716-882-0666
Source Type: Implementer
Street No:
Street 1: 1220 MAIN ST
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14209

Owner/Operator Ind: Current Owner
Type: Private
Name: BARRY COHEN
Date Became Current:
Date Ended Current:
Phone: 716-882-0666
Source Type: Notification
Street No:
Street 1: 1220 MAIN ST
Street 2:
City: BUFFALO
State: NY
Country:
Zip Code: 14209

Historical Handler Details

Receive Dt: 20060101
Generator Code Description: Not a Generator, Verified
Handler Name: MIDCITY OFFICE EQUIPMENT INC

Receive Dt: 19980807
Generator Code Description: Large Quantity Generator
Handler Name: MID CITY OFFICE EQUIPMENT, INC.

Receive Dt: 19971021
Generator Code Description: Large Quantity Generator
Handler Name: MIDCITY OFFICE EQUIPMENT INC

---

60 | **2 of 2** | **NNW** | **0.24 / 1,278.62** | **651.73 / 7** | **MID CITY OFFICE EQUIPMENT**
1220 MAIN STREET
BUFFALO NY | **LST**

Spill No: 9707872
Site ID: 187292
DER Facility ID: 156482
CID: 999
Program Type: ER
REM Phase: 0
UST Trust: True
Spill Date: 1997-10-02 08:00:00
Rcvd Date: 1997-10-03 10:33:00
CAC Date:

SWIS Code:	1502	**Insp Date:**	1997-10-08 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1997-11-28 00:00:00
Water Body:		**Create Date:**	1997-10-03 00:00:00
Class:	B3	**Update Date:**	1997-12-12 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"contamination discovered during tank removal"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/08/97 RMC/SITE TWO EXCAVATIONS OPEN, APPEAR VISUAL CLEAN, ONE ROLL OFF AND 18 DRUMS STAGED ON SITE FOR DISPOSAL, SAMPLING AND DISPOSAL DUE 11/14/97 10/10/97 RMC/FILE RECEIVED SAMPLE RESULTS FOR FOUR SEPARATE EXCAVATIONS, ONE HAD TWO GASOLINE TANKS, NO EXCEEDANCES, DISPOSAL AND MAP SHOWING FORMER LOCATIONS DUE 11/30/97 11/28/97 RMC/FILE RECEIVED DISPOSAL RECEIPTS, OK, NO FURTHER ACTION REQUIRED, CLOSE OUT "

Material Information

OP Unit ID:	1054381	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	558161	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

OP Unit ID:	1054381	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	558160	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	BARRY COHEN
Spiller Company:	MID CITY OFFICE EQUIPMENT
Spiller Address:	1220 MAIN STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14209-2194
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.906956550
Longitude:	-78.867517260

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
61	1 of 1	NNW	0.24 / 1,288.80	649.87 / 5	AGASSIZ HOLDINGS INC 1235 - 1245 MAIN STREET BUFFALO NY	LST

Spill No:	0500859	**REM Phase:**	0
Site ID:	343953	**UST Trust:**	False
DER Facility ID:	290562	**Spill Date:**	2005-04-20 16:47:00
CID:	408	**Rcvd Date:**	2005-04-20 16:47:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	2006-01-25 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	2006-03-21 00:00:00
Water Body:		**Create Date:**	2005-04-20 17:08:00
Class:	C3	**Update Date:**	2006-03-24 13:00:46.513000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	JFOTTO
County:	Erie	**After Hours:**	True
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HAS NOT BEEN CLEANED UP. SOIL SAMPLES WERE TAKEN OF IMPACTED SOIL AND THE READINGS FAILED FOR TICKS."

Dec Remark:

"04/22/05 JFO TELCON WITH DOUG REID OF LCS. HE WILL FORWARD PHASE II REPORT. 10/17/06 JFO RECEIVED THE PHASE II. THERE ARE 2 AREAS THAT NEED TO BE ADDRESSED. BH-4 AND BH-10. SEND LTR 10/18/05 JFO SENT TREATMENT LTR TO AGASSIZ HOLDINGS INC. RESPONSE BY 11/10/05. 01/17/06 JFO MET IN OUR OFFICE WITH DOUG REID AND JEFF ROWLEY BOTH WITH LCS. THEY WILL BEGIN WORK ON JAN 23. THEY WILL DIG TO CLEAN. THEY WILL CALL FOR AN INSPECTION WHEN THE HOLES ARE CLEAN. ALSO DOUG R. GAVE ME A COPY OF THE MAGNETOMETER SURVEY AND SUPPLEMENTAL SUBSURFACE SOIL AND GROUNDWATER INVESTIGATION. 01/23/06 JFO ON SITE MET WITH JEFF R WITH LCS. THEY REMOVED THE STORAGE TANK (APPROX 500 GALLON)AND PUMPED OUT OILY WATER TO DRUMS. THEY WILL BEGIN DIGGING TO CLEAN TOMORROW. I WILL VISIT SITE TOMORROW FOR INSPECTION. THEY WILL THEN DIG OUT THE OTHER AREA NEAR THE BUILDING. 01/24/06 JFO ON SITE MET WITH JEFF. THE BOTTOM, NORTH, EAST AND SOUTH WALLS LOOK OK. THEY WILL FINISH THE WEST WALL TOMORROW. 01/25/06 JFO ON SITE WITH JEFF. THE WEST WALL IS CLEAN. SAMPLES WERE COLLECTED. THEY STARTED THE OTHER HOT SPOT NEAR THE BUILDING AND DISCOVERED ANOTHER TANK (APPROX 500 GALLON). THE EXCAV IS BETWEEN THE BUILDING AND A BSA MANHOLE. THEY ARE CONCERNED ABOUT DAMAGING THE SEWER SO THEY WILL DIG ON THE OTHER SIDE OF THE MANHOLE AND COLLECT A SAMPLE. I WILL CHECK SITE 1/27/06. 01/26/06 JFO TELCON WITH DOUG REID. THEY DUG OUT THE CONTAMINATION AND REMOVED THE SOIL AROUND THE MANHOLE. THEY BELIEVE THE GOT TO CLEAN. THEY SAMPLED BELOW THE MANHOLE ALONG WITH SIDEWALLS AND BOTTOM. RESULTS AND RECEIPTS TO FOLLOW. 02/01/06 JFO RECEIVED THE ANALYTICAL RESULTS. IN THE 1ST EXCAVATION BENZENE AT 72 PPB WAS FOUND IN THE EAST SIDEWALL ALL OTHER 8260 COMPOUNDS <STARS. IN THE 2ND EXCAVATION TOTAL XYLENES AT 3300 PPB WAS FOUND IN THE BOTTOM SAMPLE ALL OTHER 8260 COMPOUNDS <TAGMS. DISCUSSED RESULTS WITH SAC AND AGREED SITE WILL BE INACTIVE . NOTIFIED DOUG REID AND INFORMED HIM THAT WE NEED RECEIPTS TO CLOSE. 03/21/06 JFO RECEIVED THE FINAL REPORT FROM DOUG REID. INCLUDED ARE THE DISPOSAL RECEIPTS FOR THE CONTAMINATED SOIL. INACTIVE NO FURTHER ACTION REQUIRED AT THIS TIME. CLOSED"

Material Information

OP Unit ID:	1102612	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	582830	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name: MARK PAGANO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Company:	AGASSIZ HOLDINGS
Spiller Address:	40 AGASSIZ CIRCLE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14214
Spiller Country:	001
Contact Name:	JEFF ROWLEY
Contact Phone:	(716) 845-6145
Contact Ext:	
Latitude:	
Longitude:	

62	1 of 3	SW	0.25 / 1,296.56	656.48 / 12	UNIVERSITY AT BUFFALO-JSMBS 955 MAIN ST BUFFALO NY 14203	RCRA LQG

EPA Handler ID:	NYR000233718
Gen Status Universe:	Large Quantity Generator
Contact Name:	JOSHUA SNYDER
Contact Address:	220, WINSPEAR AVE, BUFFALO, NY, 14215, US
Contact Phone No and Ext:	716-829-5829
Contact Email:	JSNYDER8@BUFFALO.EDU
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	State
Receive Date:	20220224
Location Latitude:	42.89992
Location Longitude:	-78.869654

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Nov, 2022.

Evaluation Details

Evaluation Start Date:	20220223
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20220224
Handler Name: UNIVERSITY AT BUFFALO-JSMBS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D030
Waste Code Description: 2,4-DINITROTOLUENE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D029
Waste Code Description: 1,1-DICHLOROETHYLENE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: LABP
Waste Code Description: LAB PACK

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: P068
Waste Code Description: HYDRAZINE, METHYL- (OR) METHYL HYDRAZINE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20200221
Handler Name: UNIVERSITY AT BUFFALO-JSMBS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: P068
Waste Code Description: HYDRAZINE, METHYL- (OR) METHYL HYDRAZINE

Hazardous Waste Code: D029
Waste Code Description: 1,1-DICHLOROETHYLENE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: LABP
Waste Code Description: LAB PACK

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D030
Waste Code Description: 2,4-DINITROTOLUENE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20171025
Handler Name: UNIVERSITY AT BUFFALO - JSMBS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: U007
Waste Code Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: U019
Waste Code Description: BENZENE (I,T)

Hazardous Waste Code: U003
Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Hazardous Waste Code: U080
Waste Code Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: U106
Waste Code Description: 2,6-DINITROTOLUENE (OR) BENZENE, 2-METHYL-1,3-DINITRO-

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D028
Waste Code Description: 1,2-DICHLOROETHANE

Hazardous Waste Code: U181
Waste Code Description: 5-NITRO-O-TOLUIDINE (OR) BENZENAMINE, 2-METHYL-5-NITRO

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D029
Waste Code Description: 1,1-DICHLOROETHYLENE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D036
Waste Code Description: NITROBENZENE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	U154
Waste Code Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Hazardous Waste Code:	D026
Waste Code Description:	CRESOL
Hazardous Waste Code:	LABP
Waste Code Description:	LAB PACK
Hazardous Waste Code:	P005
Waste Code Description:	2-PROPEN-1-OL (OR) ALLYL ALCOHOL
Hazardous Waste Code:	P105
Waste Code Description:	SODIUM AZIDE
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D003
Waste Code Description:	REACTIVE WASTE
Hazardous Waste Code:	D011
Waste Code Description:	SILVER
Hazardous Waste Code:	D018
Waste Code Description:	BENZENE
Hazardous Waste Code:	D039
Waste Code Description:	TETRACHLOROETHYLENE
Hazardous Waste Code:	U031
Waste Code Description:	1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)
Hazardous Waste Code:	U138
Waste Code Description:	METHANE, IODO- (OR) METHYL IODIDE
Hazardous Waste Code:	U211
Waste Code Description:	CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	State	***Street 1:***	CAPEN HALL
Name:	UNIVERSITY AT BUFFALO	***Street 2:***	
Date Became Current:	20171001	***City:***	AMHERST
Date Ended Current:		***State:***	NY
Phone:	716-829-3301	***Country:***	US
Source Type:	Notification	***Zip Code:***	14260
Owner/Operator Ind:	Current Operator	***Street No:***	220
Type:	State	***Street 1:***	WINSPEAR AVE
Name:	JOSHUA SNYDER	***Street 2:***	
Date Became Current:	20210501	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-829-5829	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14215
Owner/Operator Ind:	Current Operator	***Street No:***	220
Type:	State	***Street 1:***	WINSPEAR AVE
Name:	UNIVERSITY AT BUFFALO	***Street 2:***	
Date Became Current:	20171001	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-829-3301	***Country:***	US
Source Type:	Notification	***Zip Code:***	14215

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	220
Type:	State	**Street 1:**	CAPEN HALL
Name:	STATE UNIVERSITY OF NEW YORK AT BUFFALO	**Street 2:**	
Date Became Current:	20171030	**City:**	AMHERST
Date Ended Current:		**State:**	NY
Phone:	716-829-5681	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14260

Owner/Operator Ind:	Current Operator	**Street No:**	220
Type:	State	**Street 1:**	WINSPEAR AVE
Name:	ANTHONY OSWALD	**Street 2:**	
Date Became Current:	20041201	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:	716-829-5681	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14215

Historical Handler Details

Receive Dt:	20200221
Generator Code Description:	Large Quantity Generator
Handler Name:	UNIVERSITY AT BUFFALO-JSMBS

Receive Dt:	20171025
Generator Code Description:	Large Quantity Generator
Handler Name:	UNIVERSITY AT BUFFALO - JSMBS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
62	2 of 3	SW	0.25 / 1,296.56	656.48 / 12	SUNY AT BUFFALO JSMBS 955 MAIN ST. Buffalo NY 14203	AST

Site ID:	579178	**Expiry:**	2023/02/08
Site Status:	Active	**County:**	Erie
Program No:	9-601804	**UTM X:**	
Program Type Code:	PBS	**UTM Y:**	
Program Type Desc:	Petroleum Bulk Storage Program		
Site Type:	School		

Tank Information

Prog No:	9-601804	**UDC Ind:**	0
Tank ID:	278330	**Red Tag Start Date:**	
Tank No:	1	**Red Tag End Date:**	
Tank Status:	1	**Tank Last Test:**	
Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	-
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	12/01/2017	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	-
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	5000	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			
Tank Location:	6		
Tank Location Desc:	Aboveground in Subterranean Vault w/ access for inspections		
Category:	3		
Category Desc:	Category 3 means a tank which was installed after October 11, 2015		
Subpart:	4		
Subpart Desc:	Subpart 4 contains requirements for ASTs (aboveground storage tanks).		
Tank Owner Name:	JOE RAAB		
Tank Owner Address:	STATE UNIVERSITY CENTRAL OFFICE ALBANY, NY. 12246		

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: G12
Code Name: Double-Walled (AG only)
Type: Tank Secondary Containment

Equipment: C01
Code Name: Aboveground
Type: Pipe Location

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: D02
Code Name: Galvanized Steel
Type: Pipe Type

Equipment: I01
Code Name: Float Vent Valve
Type: Overfill

Equipment: J02
Code Name: Suction Dispenser
Type: Dispenser

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: H01
Code Name: Interstitial - Electronic Monitoring
Type: Tank Leak Detection

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Equipment: E12
Code Name: Double-Walled (AG only)
Type: Piping Secondary Containment

Equipment: L01
Code Name: Interstitial - Electronic Monitoring
Type: Piping Leak Detection

Tank Information

Prog No:	9-601804	***UDC Ind:***	0
Tank ID:	278451	***Red Tag Start Date:***	
Tank No:	1D	***Red Tag End Date:***	
Tank Status:	1	***Tank Last Test:***	

Tank Status Desc:	In Service	**Tank Next Test Due:**	
Tank Type:	01	**Test Method:**	-
Tank Type Desc:	Steel/Carbon Steel/Iron	**Line Last Test Due:**	
Install Date:	12/01/2017	**Next Line Test Due:**	
Close Date:		**Line Test Method:**	-
Tk Out of Serv Dt:		**Class A Operator:**	
Capacity (Gal):	400	**Class B Operator:**	
Registered:	True	**Modified by:**	MJGRIFFI
Tank Model:		**Last Modified:**	05/09/2022
Pipe Model:			

Tank Location: 6
Tank Location Desc: Aboveground in Subterranean Vault w/ access for inspections
Category: 3
Category Desc: Category 3 means a tank which was installed after October 11, 2015
Subpart: 4
Subpart Desc: Subpart 4 contains requirements for ASTs (aboveground storage tanks).
Tank Owner Name: JOE RAAB
Tank Owner Address: STATE UNIVERSITY CENTRAL OFFICE ALBANY, NY. 12246

Material Information

Material Name: #2 fuel oil (on-site consumption)
Percent: 100.00

Equipment Information

Equipment: C00
Code Name: No Piping
Type: Pipe Location

Equipment: F00
Code Name: None
Type: Pipe External Protection

Equipment: L00
Code Name: None
Type: Piping Leak Detection

Equipment: K01
Code Name: Catch Basin
Type: Spill Prevention

Equipment: G01
Code Name: Diking (Aboveground)
Type: Tank Secondary Containment

Equipment: H06
Code Name: Impervious Barrier/Concrete Pad (A/G)
Type: Tank Leak Detection

Equipment: I02
Code Name: High Level Alarm
Type: Overfill

Equipment: B01
Code Name: Painted/Asphalt Coating
Type: Tank External Protection

Equipment: A00
Code Name: None
Type: Tank Internal Protection

Equipment: J00
Code Name: None
Type: Dispenser

Equipment: E00

Code Name: None
Type: Piping Secondary Containment

Equipment: D00
Code Name: No Piping
Type: Pipe Type

Affiliation Information

Affiliation Type: 11
Affiliation Name: Emergency Contact
Affiliation Sub Type: NNN
Company: STATE UNIVERSITY OF NEW YORK
Contact Title:
Contact Name: BRIAN FOTI
Address1:
Address2:
City:
State: NN
Zip Code:
Country Code: 001
Phone: (716) 829-3301
Phone Ext:
Email:
Fax:

Affiliation Type: 01
Affiliation Name: Facility Owner
Affiliation Sub Type: B06
Company: STATE UNIVERSITY OF NEW YORK
Contact Title: DIRECTOR EH&S
Contact Name: JOE RAAB
Address1: STATE UNIVERSITY CENTRAL OFFICE
Address2:
City: ALBANY
State: NY
Zip Code: 12246
Country Code: 001
Phone: (518) 473-4060
Phone Ext:
Email:
Fax:

Affiliation Type: 07
Affiliation Name: Mail Contact
Affiliation Sub Type: NNN
Company: UNIVERSITY AT BUFFALO
Contact Title:
Contact Name: BRIAN FOTI
Address1: 220 WINSPEAR AVE.
Address2:
City: BUFFALO
State: NY
Zip Code: 14217
Country Code: 001
Phone: (716) 829-3301
Phone Ext:
Email: BRIANF@BUFFALO.EDU
Fax:

Affiliation Type: 04
Affiliation Name: Facility Operator
Affiliation Sub Type: NNN
Company: SUNY AT BUFFALO JSMBS
Contact Title:
Contact Name: SUNY AT BUFFALO
Address1:
Address2:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City:
State: NN
Zip Code:
Country Code: 001
Phone: (999) 999-9999
Phone Ext:
Email:
Fax:

---

62 | 3 of 3 | SW | 0.25 / 1,296.56 | 656.48 / 12 | **University at Buffalo (SUNY)**
Downtown Campus
955 Main Street
Buffalo NY 14203 | SWF/LF

Active: Yes
Activity No: [15J20087]
Regltry Status: Registration
Auth No: 15J20087
Auth Issue Dt: 08-Jan-2021 00:00:00
Expiration Date: 08-Jan-2026 00:00:00
Operator Type: State
Operator Name: University at Buffalo (SUNY)
East Coord: 184079
North Coord: 4756955
Accuracy Code: 4.2 - Utilization of GIS and existing spatial data
County: Erie
Region: 9
Phone No: 7168295816
Owner Name: University at Buffalo (SUNY)
Owner Type: State
Activity Desc: RMW - treatment at the site of generation - registration
Source: SWMF - Active Facility Lists
Waste Types: Regulated Medical Waste
Georeference: 955 Main Street
Buffalo, NY 14203
(42.899983, -78.869704)

Owner Address: 220 Winspear Avenue
Owner Addr2:
Owner City: Buffalo
Owner State: NY
Owner ZIP: 14215
Owner Email: drp@buffalo.edu
Owner Phone: 7168293301
Contact Name:
Contact Addr:
Contact Addr2:
Contact City:
Contact State:
Contact ZIP:
Contact Email:
Contact Phone:
DateofLastInspctn:

---

63 | 1 of 1 | W | 0.25 / 1,297.40 | 667.21 / 23 | **NYNEX**
645 FRANKLIN STREET
BUFFALO NY | LST

Spill No: 9315172
Site ID: 123609
DER Facility ID: 107125
CID:
Program Type: ER
SWIS Code: 1502
Contribute Factor: Tank Failure
Water Body:
Class: C3
Meets Std: True
Penalty: False
County: Erie
Referred to:
Reported by: Responsible Party
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: True
Spill Date: 1994-03-25 07:05:00
Rcvd Date: 1994-03-25 08:37:00
CAC Date: 1994-12-15 00:00:00
Insp Date: 1994-03-25 00:00:00
Close Date: 1994-12-15 00:00:00
Create Date: 1994-03-25 00:00:00
Update Date: 1997-12-24 00:00:00
DEC Region: 9
Lead DEC: SORGI
After Hours: False

Caller Remark:

"LEAK IN GASOLINE TANK."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 03/25/94: MJS/SITE - MET W/EP & S AND NYNEX. FUEL LINE BROKE ON DUMP TRUCK. GASOLINE SPILLED TO PAVEMENT & SEWER. SEWER CLEANED OUT; NO MITIGATION OF PRODUCT. SAMPLES TAKEN; 2 DRUMS TO BE STAGED ON-SITE. 04/04/94: MJS SENT LETTER TO RP OUTLINING REQUIREMENTS. 12/15/94: MJS REVIEW FILE. NEED

DISPOSAL DOCUMENTATION FOR CLOSURE. MJS TELECON TO LINDA CARR. SHE WILL LOOK FOR INFO AND FAX IF FOUND. 12/15/94: MJS RECEIVED FAX OF DISPOSAL INFO FROM LINDA CARR. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE. "

Material Information

OP Unit ID:	993422	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	386939	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	20.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	20.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	NYNEX
Spiller Address:	645 FRANKLIN STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.988945990
Longitude:	-78.788428650

---

64 ***1 of 2*** ***S*** ***0.25 / 1,308.86*** ***646.58 / 2*** ***ROSWELL PARK CANCER INSTITUTE***
666 ELM & CARLTON STS
BUFFALO NY 14263 ***AIR PERMITS***

Permit ID:	914020040600007
County:	
Source:	Air Permitted Facilities

Facility Details

Permit Type:	ASF	***Modification No:***	0
Status:	Expired	***Issue Date:***	11/7/2005
Renewal No:	0	***Exp Date:***	6/8/2015
Url Permit:			
Permit Type:	ASF	***Modification No:***	0
Status:	Issued	***Issue Date:***	6/12/2015
Renewal No:	1	***Exp Date:***	6/11/2025
Url Permit:	https://www.dec.ny.gov/dardata/boss/afs/issued_asf.html		
Permit Type:	ASF	***Modification No:***	1
Status:	Expired	***Issue Date:***	7/10/2009
Renewal No:	0	***Exp Date:***	6/8/2015
Url Permit:			

---

64 ***2 of 2*** ***S*** ***0.25 / 1,308.86*** ***646.58 / 2*** ***ROSWELL PARK CANCER INSTITUTE***
666 ELM & CARLTON STS
BUFFALO NY 14263 ***AIR PERMITS***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Permit ID: 914020040600006
County:
Source: Air Permitted Facilities

Facility Details

Permit Type: ASF
Status: Expired
Renewal No: 0
Url Permit:
Modification No: 1
Issue Date: 12/30/2013
Exp Date:

Permit Type: ASF
Status: Expired
Renewal No: 0
Url Permit:
Modification No: 0
Issue Date:
Exp Date: 12/30/2013

65	1 of 6	S	0.26 / 1,361.98	645.84 / 1	ROSWELL PARK CANCER INSTITUTE ELM & CARLTON STREETS BUFFALO NY 14263	RCRA TSD

EPA Handler ID: NYD083534115
Gen Status Universe: Large Quantity Generator
Contact Name: JOSEPH W MOSLOW
Contact Address: ELM & CARLTON STREETS, BUFFALO, NY, 14263, US
Contact Phone No and Ext: 716-845-3874
Contact Email: JOE.MOSLOW@ROSWELLPARK.ORG
Contact Country: US
Land Type: Other
County Name: ERIE
EPA Region: 02
Receive Date: 20220218
Location Latitude: 42.89853
Location Longitude: -78.86522

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - Manifest
Violation Type: 262.B
Violation Determined Date: 19970224
Scheduled Compliance Date: 19970324
Return to Compliance: Observed
Actual Return to Compl: 19970708
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19970224
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - Records/Reporting
Violation Type: 262.D
Violation Determined Date: 19930430
Scheduled Compliance Date:
Return to Compliance: Observed
Actual Return to Compl: 19931019
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 210
Enforcement Type Description: INITIAL 3008(A) COMPLIANCE
Enforcement Action Date: 19930804
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount: 1200
Final Amount:
Paid Amount:

Enforcement Type: 310
Enforcement Type Description: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date: 19931019
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount: 1200
Paid Amount: 1200

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19970224
Scheduled Compliance Date: 19970324
Return to Compliance: Observed
Actual Return to Compl: 19970708
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19970224
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Violation Details

Found Violation: Yes
Citation:

Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19991221
Scheduled Compliance Date: 20000626
Return to Compliance: Observed
Actual Return to Compl: 20000606
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 310
Enforcement Type Description: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Action Date: 20000526
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount: 11500
Paid Amount: 11500

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 19860113
Scheduled Compliance Date: 19860515
Return to Compliance: Observed
Actual Return to Compl: 19860529
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19860414
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 20040116
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19970204
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19970708
Evaluation Agency: State

Evaluation Start Date: 19930430
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Violation Short Description: Generators - Records/Reporting
Return to Compliance Date: 19931019
Evaluation Agency: State

Evaluation Start Date: 20200203
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20020215
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20050201
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20121024
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19970204
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - Manifest
Return to Compliance Date: 19970708
Evaluation Agency: State

Evaluation Start Date: 19860113
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 19860529
Evaluation Agency: State

Evaluation Start Date: 20160223
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20100322
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19991221
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 20000606
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No

Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060227
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940610
Handler Name: ROSWELL PARK CANCER INSTITUTE NYSDH
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20040225
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: P010
Waste Code Description: ARSENIC ACID H3ASO4

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D010

Waste Code Description: SELENIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P011
Waste Code Description: ARSENIC OXIDE AS2O5 (OR) ARSENIC PENTOXIDE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19920430
Handler Name: NYSDOH ROSWELL PARK MEMORIAL INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20080226
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: P120
Waste Code Description: VANADIUM OXIDE V2O5 (OR) VANADIUM PENTOXIDE

Hazardous Waste Code: U404
Waste Code Description: ETHANAMINE, N,N-DIETHYL- (OR) TRIETHYLAMINE

Hazardous Waste Code: P048
Waste Code Description: 2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U003
Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: LABP
Waste Code Description: LAB PACK

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Hazardous Waste Code: F027
Waste Code Description: DISCARDED UNUSED FORMULATIONS CONTAINING TRI-, TETRA-, OR PENTACHLOROPHENOL OR DISCARDED UNUSED FORMULATIONS CONTAINING COMPOUNDS DERIVED FROM THESE CHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE FORMULATIONS CONTAINING HEXACHLOROPHENE SYNTHESIZED FROM PREPURIFIED 2,4,5-TRICHLOROPHENOL AS THE SOLE COMPONENT.)

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: U151
Waste Code Description: MERCURY

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: B004
Waste Code Description: PCB articles containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs, excluding small capacitors. This

includes oil-filled electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: U031
Waste Code Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D014
Waste Code Description: METHOXYCHLOR (1,1,1-TRICHLORO-2,2-BIS [P-METHOXYPHENYL] ETHANE)

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20160302
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN

PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20220218
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U123
Waste Code Description: FORMIC ACID (C,T)

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: U003
Waste Code Description: ACETONITRILE (I,T)

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U031
Waste Code Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U200
Waste Code Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL) OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Hazardous Waste Code: U119
Waste Code Description: ETHYL METHANESULFONATE (OR) METHANESULFONIC ACID, ETHYL ESTER

Hazardous Waste Code: U134
Waste Code Description: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

Hazardous Waste Code: U138
Waste Code Description: METHANE, IODO- (OR) METHYL IODIDE

Hazardous Waste Code: U150
Waste Code Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Hazardous Waste Code: P188
Waste Code Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Hazardous Waste Code: U096
Waste Code Description: ALPHA,ALPHA-DIMETHYLBENZYLHYDROPEROXIDE (R) (OR) HYDROPEROXIDE, 1-METHYL-1-PHENYLETHYL- (R)

Hazardous Waste Code: U213
Waste Code Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U001
Waste Code Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Hazardous Waste Code: P087
Waste Code Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: U196
Waste Code Description: PYRIDINE

Hazardous Waste Code: U237
Waste Code Description: 2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]- (OR) URACIL MUSTARD

Hazardous Waste Code: U206
Waste Code Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: P023
Waste Code Description: ACETALDEHYDE, CHLORO- (OR) CHLOROACETALDEHYDE

Hazardous Waste Code: P204
Waste Code Description: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: LABP
Waste Code Description: LAB PACK

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: U007
Waste Code Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: U136
Waste Code Description: ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID

Hazardous Waste Code: U248
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: U140
Waste Code Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Hazardous Waste Code: U201
Waste Code Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Hazardous Waste Code: U061
Waste Code Description: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDT

Hazardous Waste Code: U205
Waste Code Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19811211
Handler Name: ROSWELL PARK MEMORIAL INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F005

Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	U220
Waste Code Description:	BENZENE, METHYL- (OR) TOLUENE
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	U117
Waste Code Description:	ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)
Hazardous Waste Code:	D000
Waste Code Description:	DESCRIPTION
Hazardous Waste Code:	F002
Waste Code Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	U019
Waste Code Description:	BENZENE (I,T)
Hazardous Waste Code:	U239
Waste Code Description:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)
Hazardous Waste Code:	F001
Waste Code Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	F003
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	U154
Waste Code Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Hazardous Waste Code:	U211
Waste Code Description:	CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-
Hazardous Waste Code:	U226
Waste Code Description:	ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM
Hazardous Waste Code:	U034
Waste Code Description:	ACETALDEHYDE, TRICHLORO- (OR) CHLORAL
Hazardous Waste Code:	U112
Waste Code Description:	ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)
Hazardous Waste Code:	U044
Waste Code Description:	CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20010101
Handler Name: ROSWELL PARK CANCER INSTITUTE CORP.
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20210301
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: P204
Waste Code Description: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

Hazardous Waste Code: U007
Waste Code Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Hazardous Waste Code: U134
Waste Code Description: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Code: U196
Waste Code Description: PYRIDINE

Hazardous Waste Code: U248
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Hazardous Waste Code:	P001
Waste Code Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Hazardous Waste Code:	D010
Waste Code Description:	SELENIUM
Hazardous Waste Code:	U031
Waste Code Description:	1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)
Hazardous Waste Code:	D022
Waste Code Description:	CHLOROFORM
Hazardous Waste Code:	D006
Waste Code Description:	CADMIUM
Hazardous Waste Code:	P087
Waste Code Description:	OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE
Hazardous Waste Code:	D019
Waste Code Description:	CARBON TETRACHLORIDE
Hazardous Waste Code:	P046
Waste Code Description:	ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-
Hazardous Waste Code:	U188
Waste Code Description:	PHENOL
Hazardous Waste Code:	U206
Waste Code Description:	D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN
Hazardous Waste Code:	F003
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	U154
Waste Code Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Hazardous Waste Code:	U061
Waste Code Description:	BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDT
Hazardous Waste Code:	P023
Waste Code Description:	ACETALDEHYDE, CHLORO- (OR) CHLOROACETALDEHYDE
Hazardous Waste Code:	U096
Waste Code Description:	ALPHA,ALPHA-DIMETHYLBENZYLHYDROPEROXIDE (R) (OR) HYDROPEROXIDE, 1-METHYL-1-PHENYLETHYL- (R)
Hazardous Waste Code:	U002
Waste Code Description:	2-PROPANONE (I) (OR) ACETONE (I)
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	D007
Waste Code Description:	CHROMIUM
Hazardous Waste Code:	U138
Waste Code Description:	METHANE, IODO- (OR) METHYL IODIDE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Code:	U150
Waste Code Description:	L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN
Hazardous Waste Code:	P012
Waste Code Description:	ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE
Hazardous Waste Code:	U201
Waste Code Description:	1,3-BENZENEDIOL (OR) RESORCINOL
Hazardous Waste Code:	U205
Waste Code Description:	SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)
Hazardous Waste Code:	U213
Waste Code Description:	FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)
Hazardous Waste Code:	P188
Waste Code Description:	BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE
Hazardous Waste Code:	U136
Waste Code Description:	ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	F005
Waste Code Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	D038
Waste Code Description:	PYRIDINE
Hazardous Waste Code:	U003
Waste Code Description:	ACETONITRILE (I,T)
Hazardous Waste Code:	U200
Waste Code Description:	RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL) OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-
Hazardous Waste Code:	F002
Waste Code Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	D011
Waste Code Description:	SILVER
Hazardous Waste Code:	P105
Waste Code Description:	SODIUM AZIDE
Hazardous Waste Code:	U044
Waste Code Description:	CHLOROFORM (OR) METHANE, TRICHLORO-
Hazardous Waste Code:	U140
Waste Code Description:	1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)
Hazardous Waste Code:	U220
Waste Code Description:	BENZENE, METHYL- (OR) TOLUENE
Hazardous Waste Code:	D005

Waste Code Description: BARIUM

Hazardous Waste Code: U001
Waste Code Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Hazardous Waste Code: U123
Waste Code Description: FORMIC ACID (C,T)

Hazardous Waste Code: U237
Waste Code Description: 2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]- (OR) URACIL MUSTARD

Hazardous Waste Code: U119
Waste Code Description: ETHYL METHANESULFONATE (OR) METHANESULFONIC ACID, ETHYL ESTER

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20060228
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: U081
Waste Code Description: 2,4-DICHLOROPHENOL (OR) PHENOL, 2,4-DICHLORO-

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P048
Waste Code Description: 2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: P077
Waste Code Description: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20120305
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: LABP
Waste Code Description: LAB PACK

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P012

Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19960515
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20020205

Handler Name: ROSWELL PARK CANCER INSTITUTE CORP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100226
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: P064
Waste Code Description: METHANE, ISOCYANATO- (OR) METHYL ISOCYANATE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: LABP
Waste Code Description: LAB PACK

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P087
Waste Code Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20180228
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: P010
Waste Code Description: ARSENIC ACID H3ASO4

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: P048
Waste Code Description: 2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: P011
Waste Code Description: ARSENIC OXIDE AS2O5 (OR) ARSENIC PENTOXIDE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: B007
Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19980224
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20200302
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator

Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: P204
Waste Code Description: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: F002
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: U010
Waste Code Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A, 2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: P188
Waste Code Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: U200
Waste Code Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL) OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20140306
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D019
Waste Code Description: CARBON TETRACHLORIDE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: P042
Waste Code Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Hazardous Waste Code: D038
Waste Code Description: PYRIDINE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: B007

Waste Code Description: Other PCB wastes, including contaminated soil, solids, sludges, clothing, rags and dredge material.

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: P012
Waste Code Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: P105
Waste Code Description: SODIUM AZIDE

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: ROSWELL PARK CANCER INSTITUTE
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	
Name:	PUBLIC BENEFIT CORPORATION	***Street 2:***	
Date Became Current:	19000101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	ELM & CARLTON STS.
Name:	NYS DEPT. OF HEALTH	***Street 2:***	
Date Became Current:	19791231	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Implementer	***Zip Code:***	14263

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	ELM & CARLTON STREETS
Name:	NYS DEPT OF HEALTH	***Street 2:***	
Date Became Current:	19000101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	14263

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	ELM + CARLTON STREETS
Name:	ROSWELL PARK CANCER INSTITUTE	***Street 2:***	
Date Became Current:	19000101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	14263

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	
Name:	ROSWELL PARK CANCER INSTITUTE	***Street 2:***	
Date Became Current:	19000101	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	NOT REQUIRED
Name:	OWNERNAME	***Street 2:***	
Date Became Current:		***City:***	NOT REQUIRED
Date Ended Current:		***State:***	WY
Phone:	212-555-1212	***Country:***	
Source Type:	Notification	***Zip Code:***	99999

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	ELM & CARLTON STREETS
Name:	ROSWELL PARK CANCER INSTITUTE	***Street 2:***	
Date Became Current:	19000101	***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-845-2300	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip Code:***	14263

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	ELM & CARLTON STREETS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	PUBLIC BENEFIT CORPORATION	**Street 2:**	
Date Became Current:	19000101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14263
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	ELM & CARLTON STREETS
Name:	ROSWELL PARK CANCER INSTITUTE	**Street 2:**	
Date Became Current:	19791231	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14263
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	ELM & CARLTON STS.
Name:	NYS DEPT. OF HEALTH	**Street 2:**	
Date Became Current:	19791231	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	14263
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	OWNERNAME	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	WY
Phone:	212-555-1212	**Country:**	US
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	ELM & CARLTON STREETS
Name:	NEW YORK STATE DEPARTMENT OF HEALTH	**Street 2:**	
Date Became Current:	19791231	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14263
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	ELM & CALRON STREETS
Name:	PUBLIC BENEFIT CORPORATION	**Street 2:**	
Date Became Current:	19000101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14263
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	State	**Street 1:**	ELM + CARLTON STREETS
Name:	NYS DEPARTMENT OF HEALTH	**Street 2:**	
Date Became Current:	19000101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	14263
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	ELM & CARLTON ST
Name:	ROSWELL PARK CANCER INSTITUTE	**Street 2:**	
Date Became Current:	19000101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	14263
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	ELM & CARLTON STREETS
Name:	ROSWELL PARK CANCER INST	**Street 2:**	
Date Became Current:	19000101	**City:**	BUFFALO
Date Ended Current:		**State:**	NY
Phone:		**Country:**	US

Source Type: Annual/Biennial Report ***Zip Code:*** 14263

Historical Handler Details

Receive Dt: 20120305
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20070101
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20010101
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE CORP.

Receive Dt: 20020205
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE CORP

Receive Dt: 19960515
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 19980224
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20140306
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20180228
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20210301
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20060227
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 19940610
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE NYSDH

Receive Dt: 20200302
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20040225
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20060228
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 19811211
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK MEMORIAL INSTITUTE

Receive Dt: 20100226
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 20160302
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Receive Dt: 19920430
Generator Code Description: Large Quantity Generator
Handler Name: NYSDOH ROSWELL PARK MEMORIAL INSTITUTE

Receive Dt: 20080226
Generator Code Description: Large Quantity Generator
Handler Name: ROSWELL PARK CANCER INSTITUTE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
65	2 of 6	S	0.26 / 1,361.98	645.84 / 1	ROSWELL ELM AND CARLTON ST BUFFALO NY	NY SPILLS

Spill No: 1203400
Site ID: 466212
DER Facility ID: 420550
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D4
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2012-07-09 08:15:00
Received Date: 2012-07-09 08:15:00
CAC Date:
Insp Date:
Close Date: 2012-07-11 00:00:00
Create Date: 2012-07-09 08:18:00
Update Date: 2012-07-11 12:44:31.920000000
DEC Region: 9
Lead DEC: FXGALLEG
After Hours: True

Caller Remark:

"clean up and repairs underway"

DEC Remark:

"7/11/12 MINOR SPILL, CLEANED UP. NO FURTHER WORK REQUIRED. CLOSED ELECTRONIC FILE ONLY."

Material Information

OP Unit ID: 1216219
OU: 01
Material ID: 2214385
CAS No:
Material Family: Petroleum
Quantity: 2.00
Units: G
Recovered:
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: True
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: ROSWELL
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Country: 999
Contact Name: JOE MOSLOW
Contact Phone: 716-803-9250
Contact Ext:
Latitude: 42.898527002
Longitude: -78.865010976

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
65	3 of 6	S	0.26 / 1,361.98	645.84 / 1	NYSDOH ROSWELL LOADING DK ELM & CARLTON BUFFALO NY	LST

Spill No: 9206876
Site ID: 289314
DER Facility ID: 234282
CID:
Program Type: ER
SWIS Code: 1502
Contribute Factor: Tank Failure
Water Body:
Class: C3
Meets Std: False
Penalty: False
County: Erie
Referred to:
Reported by: Citizen
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: True
Spill Date: 1992-09-10 16:41:00
Rcvd Date: 1992-09-10 16:50:00
CAC Date: 1994-12-29 00:00:00
Insp Date:
Close Date: 1995-02-06 00:00:00
Create Date: 1992-09-24 00:00:00
Update Date: 1995-02-08 00:00:00
DEC Region: 9
Lead DEC: COOKE
After Hours: True

Caller Remark:

"EMPIRE SOILS PERFORMING SOIL BORINGS. ONE BORING PRODUCED PETROLEUM ODORS. SPILLS 8905775 AND 8907884 INDICATE PREVIOUS TANK FAILURE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 10/07/92: RECEIVED OUTLINE FOR REMEDIATION PLAN THAT IS ACCEPTABLE. WILL HOLD UNTIL TESTING IS COMPLETE. 04/02/93: JDC/DENNIS MAHN, ROSWELL/TELECON - STATED REMEDIAL PLAN WAS FINE W/ THE FOLLOWING EXCEPTIONS: CONFIRM DISCHARGE TO SEWERS W/BSA FROM TREATMENT SYSTEM; POST SAMPLING SHOULD BE EPA METHOD 8021 DIRECT. 04/08/93: JDC CRITIQUED REMEDIATION PLAN; RAISED QUESTIONS IN 3 AREAS. WAITINGFOR RESPONSE FROM DENNIS MAHN. 04/23/93: JDC MET W/MR. MAHN AND VISITED LOADING DOCK AREA TO IDENTIFY AREAS OF CONCERN AS THEY RELATE TO REMEDIATION PROJECT. WORK EXPECTED TO BEGIN SOON. 08/18/93: JDC LEFT MESSAGE FOR MR. MAHN TO RETURN CALL REGARDING CURRENT REMEDIATION STATUS. 10/25/93: JDC/DON ABRAMS, EMPIRE SOILS/TELECON - EMPIRE HIRED TO DO REMEDIAL WORK. CARBON FILTRATION SYSTEM OPERATING SINCE 8/93. DISCHARGE WATER TO SANITARY SEWER UNDER BSA AUTHORITY. 12/30/93: JDC REVIEWED OCTOBER '93 MONTHLY MONITORING REPORT AND FOUND INFORMATION SATISFACTORY. CARBON FILTER PUMP AND TREAT SYSTEM PROVIDING SATISFACTORY REMEDIATION. 02/14/94: JDC REVIEWED HUNTINGDON'S ANALYTICAL REPORT DATED 1/94 AND FOUND NO SIGNIFICANT CHANGE IN PRETREATMENT CONCENTRATIONS. WILL CONTINUE TO MONITOR CURRENT RECOVERY. 04/20/94: JDC REVIEW MARCH MONITORING REP[ORT AND FOUND DISCHARGE LIMITS BEING MET. WILL CONTINUE TO MONITOR REPORTS. 05/09/94: APRIL 94 REPORT, NO CHANGE SYSTEM OPERATION GOOD. BREAKTHROUGH BETWEEN FILTERS IN DEC. HAS BEEN CORRECTED. CONJTINUE TO MONITOR. 05/31/94: MAY REPORT CONTINUES TO SHOW GOOD FILTRATION, WILL CONTINUE TO MONITOR. 07/15/94: MAY REPORT CONTINUES TO SHOW GOOD FILTRATION, WILL CONTINUE TO MONITOR. 08/09/94: JDC ON SITE W/ K SHANAHAN, EMPIRE SOILS CONTAMINATED SOILS REMOVED FROM TANK AREA FOR DISPOSAL. COMPOSIT SOIL ANALYSIS FROM EXCAVATION TAKEN FOR CLEAN DETERMINATION. 11/28/94: JDC ON SITE AND OBSERVED TANK BEING FILLED W/ FLOWABLE FILL. SOIL SAMPLES COLLECTED THROUGH TANK WALL. 02/06/95: REVIEWD HUNTINGTO SITE REPORT AND FOUND SOILS ANALYSIS TO EXCEED GUIDANCE VALUES. SENT INACTIVE LETTER, NO FURTHER ACTION AT THIS TIME, ALL MW'S DESTROYED, SOURCE OF CONTAMINATION (SOIL) REMOVED. 02/06/95: REVIEWD HUNTINGTONS SITE REPORT AND FOUND SOILS ANALYSIS TO EXCEED GUIDANCE VALUES. SENT INACTIVE LETTER, NO FURTHER CLEANUP IS REQUIRED AT THIS TIME. 02/06/95: RECEIVED AND RESPONDED TO FOIL REQUEST BY SCOTT BURCHARD OF CIMINELLI COSTRUCTION.(SEE 2/6/95 REQUEST LETTER) FAXED SOIL ANALYSIS RESULTS. "

Material Information

OP Unit ID: 970663
OU: 01
Material ID: 407563
CAS No:
Material Family: Petroleum
Quantity: .00

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	ROSWELL PARK CANCER INST.
Spiller Address:	ELM & CARLTON
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14263
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.886649993
Longitude:	-78.867610023

65	4 of 6	S	0.26 / 1,361.98	645.84 / 1	**NYSDOH ROSWELL PARK** **ELM AND CARLTON STREETS** **BUFFALO NY**	LST

Spill No:	9402510	**REM Phase:**	0
Site ID:	324082	**UST Trust:**	False
DER Facility ID:	261055	**Spill Date:**	1994-05-18 12:00:00
CID:		**Rcvd Date:**	1994-05-19 14:50:00
Program Type:	ER	**CAC Date:**	1995-01-30 00:00:00
SWIS Code:	1502	**Insp Date:**	1994-11-28 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1995-02-06 00:00:00
Water Body:		**Create Date:**	1994-05-24 00:00:00
Class:	C3	**Update Date:**	1995-02-10 00:00:00
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	COOKE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BELOW GROUND TANK FOUND DURING GAS LINE EXCAVATION."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 05/19/94: JDC ON SITE AND FOUND EXCAVATION FILLED IN. TELCON W/ MS MAYNARD NYS DORM. AUTH. MAY BE CITY PROPERTY, SHE WILL INVESTIGATE. 05/19/94: JDC TELCON W/ MS KELLEY, DOH DISCUSSED DOH HAS NO FUNDS FOR TANK REMOVAL, THEY BELIEVE TANK BELONGS TO CITY OF BUFFALO. WILL SEND TANK REMOVAL LETTER DECLINING WORK AND RIGHT-OF-ENTRY TO MS KELLEY. 05/27/94: JDC SENT TANK REMOVAL LETTER TO DORMITORY AUTHORITY. CK BACK 6/30/94. 07/15/94: JDC TELCON W/ MS KELLEY, DECLINED TO SIGN ENTRY FORM, STATES PROPERTY BELONGS TO CITY ACCORDING TO SURVEY. DOH CONTACTED MIKE MURPHY, CITY OF BUFFALO AT 851-5636 TO DIFFER. WILL CONTACT MURPHY. 07/15/94: JDC TELCON W/ DAVE JAROS, CITY OF BFLO ENGINEER PUBLIC WORKS AT 851-5631. HE WILL FOLLOWUP WITH MURPHY AND CALL BACK ON MONDAY 7/18/94 TO DISCUSS REMOVAL REQUIREMENTS. 07/15/94: JDC TELCON W/ DAVE JAROS, CITY OF BFLO ENGINEER PUBLIC WORKS AT 851-5631. HE WILL FOLLOWUP WITH MURPHY AND CALL BACK ON MONDAY 7/18/94 TO DISCUSS TANK REMOVAL REQUIREMENTS. 07/20/94: RECEIVED LETTER FROM MS KELLEY, DOH SHOWING SITE DRAWING OF TANK ON CITY PROPERTY. JDC TELCON W/ MIKE MURPHY, CITY ENGINEER AND ADVISED HIM OF TANK REMOVAL REQUIREMENTS. CITY TO RESPONDE THIS WEEK. 07/27/94: JDC TELCON W/ MIKE MURPHY, CITY OWNS PROPERTY, WILL SEND STANDARD REMOVAL LETTER. CK BK 8/24/94. 10/25/94: JDC TELCON W/ JOHN DAY, CITY OF BFLO, ELMWOOD TANK HIRED TO DO TANK REMOVAL AT ROSEWELL. WORK TO BEGIN NEXT WEEK , REQUESTED ADVANCED NOTICE TO DO SITE INSPECTION. 11/23/94: JDC TELCON W/ DICK SIEFER, ELMWOOD TK. TANK WILL BE ABANDONED IN PLACE DUE TO UTILITIES IN THE AREA. WORK TO BEGIN 11/28/94. 02/06/95: RECIEVED TANK PIT SAMPLE RESULTS AND FOUND MINOR VIOLATIONS WITH METHOD 8270. WILL MAKE FILE INACTIVE, NO FURTHER ACTION AT THIS TIME. 11/28/95: JDC ON SITE AND OBSERVED BACKFILL OF TANK BY ELMWOOD TANK. SOIL SAMPLES COLLECTED THROUGH TANK SIDE WALL, CONCRETE PAD PREVENTED THROUGH THE BOTTOM SAMPLING. "

Material Information

OP Unit ID:	999629	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	382702	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	CITY OF BUFFALO
Spiller Address:	502 CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.898527002
Longitude:	-78.865010976

65	***5 of 6***	***S***	***0.26 / 1,361.98***	***645.84 / 1***	***ROSWELL CANCER INSTITUTE ELM AND CARLTON STREETS BUFFALO NY***	***LST***

Spill No:	9301132	***REM Phase:***	0
Site ID:	324081	***UST Trust:***	False
DER Facility ID:	261055	***Spill Date:***	1993-04-12 10:30:00
CID:		***Rcvd Date:***	1993-04-12 10:40:00
Program Type:	ER	***CAC Date:***	1993-08-18 00:00:00
SWIS Code:	1502	***Insp Date:***	1993-06-10 00:00:00
Contribute Factor:	Tank Test Failure	***Close Date:***	1993-08-18 00:00:00
Water Body:		***Create Date:***	1993-04-26 00:00:00
Class:	D3	***Update Date:***	1993-08-20 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	COOKE
County:	Erie	***After Hours:***	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK FAILED INITIAL TEST. WILL BE ISOLATED FOR RETEST."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 04/12/93: SAC/WAYNE LESS, SLC/TELECON - TIGHTNESS TESTED 1K FIBERGLASS TANK FOR THE EMERGENCY GENERATOR. TANK FAILED TEST. TWO MONITORING WELLS ON SIDE OF TNAK. NO SIGN OF PRODUCT. 04/15/93: SAC/WAYNE LESS, SLC/TELECON - TANK #118 AT ROSWELL WAS ISOLATED & FAILED RETEST AT LEAK RATE OF -0.170 GPH. ROSWELL REP. MAKING ARRANGEMENTS FOR REMOVAL OF FUEL FROM TANK. 04/23/93: JDC/DENNIS MAHN, ROSWELL/SITE - INSPECTED AREA AROUND FAILED TANK. EXPLAINED REMEDIATION REQUIREMENTS AND DOCUMENTATION NEEDED. 06/10/93: JDC/J. KLOC/SITE - FOUND EXCAVATION FREE OF ANY VISIBLY CONTAMINATION. FIBERGLASS TANK CUT OPEN AND CLEANED OUT. SOIL COMPOSITE OF EXCAVATION TO BE ANALYZED UNDER 8270. 08/18/93: JDC REVIEWED SAMPLE DATA FROM EXCAVATION COMPOSITE AND FOUND RESULTS SATISFACTORY. NO FURTHER ACTION REQUIRED. "

Material Information

OP Unit ID:	983035	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	401859	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	ROSWELL PARK CANCER INST.
Spiller Address:	ELM AND CARLTON STREETS
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14263
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.898527002
Longitude:	-78.865010976

Tank Test Information

Spill Tank ID:	1541447	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank Size:	0	***Gross Fail:***	
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

---

65 ***6 of 6*** ***S*** ***0.26 / 1,361.98*** ***645.84 / 1*** ***ROSWELL PARK ELM AT CARLTON BUFFALO NY*** ***LST***

Spill No:	0750760	***REM Phase:***	0
Site ID:	386342	***UST Trust:***	True
DER Facility ID:	335727	***Spill Date:***	2007-08-24 12:00:00
CID:		***Rcvd Date:***	2007-08-24 12:11:00
Program Type:	ER	***CAC Date:***	
SWIS Code:	1502	***Insp Date:***	
Contribute Factor:	Tank Test Failure	***Close Date:***	2007-11-15 00:00:00
Water Body:		***Create Date:***	2007-08-24 12:15:00
Class:	B3	***Update Date:***	2007-11-15 13:18:35.770000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	fxgalleg
County:	Erie	***After Hours:***	False
Referred to:			
Reported by:	Other		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"3 TEN K USTS FAILED TANK TEST. BELIEVE PROBLEM IS WITH THE VENT. TANKS FOR EMERGENCY GENERATORS. TANKS 126,123,122."

Dec Remark:

"8/27/07 FG SPOKE TO TERRY WATERS WITH ROSWELL. HE SAID THAT ROSWELL IS GETTING A PRICE QUOTE TO RETEST THE UST'S ASAP. HE WILL PROVIDE THE RESULTS AS SOON AS HE GETS THEM. 10/10/07 FG SPOKE TO TERRI WATERS WITH ROSWELL AND HE SAID ELMWOOD CAME BACK OUT BECAUSE THEY RAN THE ORIGINAL TEST IMPROPERLY. THEY CAPPED THE WRONG VENT LINE. ROSWELL WILL SUBMIT THE PASSED TEST WITHIN THE NEXT TWO WEEKS. THEY DO NOT HAVE A FAILED TEST BECAUSE OF THE ERROR IN RUNNING THE ORIGINAL TEST. 11/15/07 FG SPOKE TO TERRY WATERS WITH ROSWELL. HE SAID THAT THE UST'S PASSED THE RETEST. PBS IS SCHEDULED TO COMPLETE AN INSPECTION NEXT WEEK AND HE WILL GIVE THE FAILED AND PASSED TESTS TO THE DEC REPRESENTATIVE AT THAT TIME. PBS WILL KEEP THE TESTS IN THEIR FILE. NO FURTHER WORK IS REQUIRED. THE SITE IS CLOSED. ELECTRONIC FILE ONLY."

Material Information

OP Unit ID:	1143582	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2133853	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	False
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	ANTHONY PUTRELO
Contact Phone:	(716) 845-8171
Contact Ext:	
Latitude:	
Longitude:	

66	***1 of 1***	***SSE***	***0.26 / 1,368.63***	***645.07 / 1***	***IN DITCH LINE CORNER OF MICHIGAN AVE AND CARLTON ST BUFFALO NY***	***NY SPILLS***

Spill No:	1003048	***UST Trust:***	False
Site ID:	436251	***Spill Date:***	2010-06-17 12:45:00
DER Facility ID:	391186	***Received Date:***	2010-06-17 13:06:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2011-09-19 00:00:00
Water Body:		***Create Date:***	2010-06-17 13:10:00
Class:	C3	***Update Date:***	2011-09-19 10:51:01.060000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	TDJOHNSO
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"While excavating for new line contamination was found. DEC, Francine Galago, Nat Grid will manage ite clean up."

DEC Remark:

"6/17/10 FG SITE INSPECTION. OIL IN NATIONAL GRID EXCAVATION AT 4 FT DEEP. OP TECH ON SITE VACCED OUT OIL/WATER. NATIONAL GRID WILL DIG DEEPER TO INSTALL MANHOLE. NO EVIDENCE OF OIL STAINED SOIL AT LOCATION. OIL SHEEN APPEARS TO BE RUNNING FROM THE ADJACENT PROPERTY WITH WATER. DISPOSAL RECEIPTS TO BE PROVIDED. NATIONAL GRID WILL CONTINUE THEIR WORK. 12/29/10 FG CONTACTED LISA MONTESANO WITH NATIONAL GRID TO AGAIN REQUEST THE DISPOSAL RECEIPT FOR THIS SITE. SHE SAID SHE WILL PROVIDE IT AS SOON AS SHE CAN AND NOTED THAT THE SOIL WAS DISPOSED. 1/7/11 FG RECEIVED THE SIGNED RIGHT OF ENTRY FROM ROSWELL PARK. THEY ASKED TO BE NOTIFIED WHEN WE PLAN TO BEGIN WORK. 1/14/11 NATIONAL GRID SUBMITTED THE DISPOSAL RECEIPT FROM THE DISPOSAL OF THE CONTAMINATED SOILS THEY REMOVED FROM THE EXCAVATION WORK THEY COMPLETED. 1/26/11 TDJ CONTACTED STEVE LEITTEN OF GES TO SUBMIT A WORK PLAN WITH BIDDERS TO PERFORM A GPR STUDY AND A SUBSURFACE INVESTIGATION AT THE SITE. 3/1/11 TDJ RECEIVED PROPOSAL FROM GES FOR SITE INVESTIGATION. WORK PLAN WAS EXCESSIVE FOR WORK NEEDED SO DEC ASKED FOR RESUBMISSION WITH LESS TIME AND MANPOWER. 3/3/11 TDJ RECEIVED RESUBMITION WHICH IS MORE INLINE WITH DEC PLANS FOR SITE. WILL GIVE APPROVAL TO START PROJECT. 2/7/11 TDJ MET ERIC POPPKIN AT SITE TO DETERMINE EXTENT OF WORK AND SITE CONDITIONS. WILL NEED TO HAVE GPR SURVEY TEAM DETERMINE IF SNOW WILL BE PROBLEM. IF SO SNOW REMOVAL WILL BE NECESSARY. 3/14/11 TDJ WAS CONTACTED BY ERIC POPPKIN WITH START DATE FOR GPR OF 3/17/11. 3/17/11 TDJ MET THOMAS PALMER, GES AND AMEC GPR CREW JOHN LUTTINGER AND DAN MACKENNA. GRID WAS MAPPED ON SOIL IN A 60' X 70' AREA WHICH WAS CUT INTO 6' STRIPS WITH SAMPLES BEING TAKEN AT EVERY 3' INTERVAL. ARRIVED ONSITE AT 9:00 AM AND WORK WAS COMPLETE BY 10:30 AM. 3/29/11 TDJ MET TOM PALMER AND TREC CREW FOR SUBSURFACE INVESTIGATION. TREC HAND DUG TO FIND GAS LINE AT EDGE OF SIDEWALK THEN MOVED IN ~5'AWAY FROM SIDEWALK FOR BORINGS. THREE BORING WERE DUG TO 8-10' INTO A SANDY CLAY SOIL. A THICK CONFINING CLAY LAYER WAS AT 10'. A HIGH OF 0.3 PPM ON THE PID METER. NO STAINING NOR VISUAL CONTAMINATION WAS ENCOUNTERED. SINCE THE PETROLEUM STAINED SOIL WAS ENCOUNTERD BY NATIONAL GRID UNDER THE SIDEWALK WE DECIDED IF WE DID NOT ENCOUNTER ANY CONTAMINATION 5' AWAY IT WAS UNNECESSARY TO MOVE FARTHER AWAY FROM THE SIDEWALK. A COMPOSITE SAMPLE WAS TAKEN OF THE SIMILIAR SOIL DUG WHICH WAS TAKEN TO TEST AMERICA FOR CONFIRMATION TESTING. 5/10/11 TDJ RECEIVED FINAL REPORT FROM GES WHICH SHOWED TEST PITS DUG HAD MINIMAL CONTAMINATION BELOW THE CP-51 SOIL GUIDANCE CLEANUP LIMITS. NO FURTHER WORK WILL BE PERFORMED ON THIS SITE. 5/16/11 TDJ RECEIVED PAY PACKAGE FROMTEST AMERICA FOR CONFIRMATORY SAMPLES COLLECTED DURING TEST PIT WORK. 06/30/11 TDJ RECEIVED PAY PACKAGE FROM GES FOR SITE WORK PERFORMED. NO FURTHER ACTION FILE CLOSED "

Material Information

OP Unit ID:	1186953	***Med Ind Air:***	False
OU:	01	***Med GW:***	True
Material ID:	2181818	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA MONTICELLO
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
67	1 of 1	N	0.26 / 1,368.83	648.24 / 4	A & J DISTRIBUTORS 36 NORTHAMPTON STREET BUFFALO NY	NY SPILLS

Spill No:	8603602	**UST Trust:**	False
Site ID:	76118	**Spill Date:**	1986-08-29 12:00:00
DER Facility ID:	71201	**Received Date:**	1986-08-29 15:30:00
CID:		**CAC Date:**	1987-05-06 00:00:00
Program Type:	ER	**Insp Date:**	1986-11-13 00:00:00
SWIS Code:	1502	**Close Date:**	1987-05-06 00:00:00
Water Body:		**Create Date:**	1986-10-22 00:00:00
Class:	E6	**Update Date:**	1997-03-28 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	COOKE
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Equipment Failure
Reported by: Citizen
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"OVERFLOW FROM ABANDONED HYDRAULIC LIFT"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC / / : SITE INSPECTION 08/29/86, CLEANUP NEEDED AND AGREED TO BY SPILLER, SOURCE NOT KNOWN; SITE INSPECTION 10/02/86, HYDRAULIC LIFT IS SOURCE. / / : SITE INSPECTION 10/02/86, HYDRAULIC LIFT IS SOURCE; LETTER 09/04/86, NO REPLY DATE, SPILLER TO CLEANUP. / / : SITE INSPECTION 10/02/86, HYDRAULIC LIFT IS SOURCE; LETTER 09/04/86, NO REPLY DATE, SPILLER TO CLEANUP; SITE INSPECTION 11/13/86, NO CLEANUP. / / : TELECON 01/13/87, WILL CHECK IF OIL REMOVED. / / : TELCOM 02/24/87 W/ B HEIN, OIL NOT YET PUMPED OFF. HEIN WILL BE HIRING NEW CONTRACTOR TO DO WORK. HEIN WILL NOTIFY WHEN COMPLETE. / / : TELECON 05/06/87, SPILLER DISCONNECTED PIPELINE FROM LIFT, FURTHER LEAKAGE POSSIBLE, NO FURTHER ACTION REQUIRED. "

Material Information

OP Unit ID:	900848	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	476429	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0010
Material Name: hydraulic oil

Spiller Information

Spiller Name:
Spiller Company: A & J DISTRIBUTORS
Spiller Address: 36 NORTHAMPTON STREET
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14209
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.907683020
Longitude: -78.865737740

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
68	1 of 1	SSE	0.26 / 1,373.20	645.33 / 1	UST @ ROSWELL PRKG GARAGE CARLTON STREET B/T ELM-MICHIGAN STS BUFFALO NY	LST

Spill No:	0651376	**REM Phase:**	0
Site ID:	372445	**UST Trust:**	True
DER Facility ID:	326823	**Spill Date:**	2006-10-24 11:00:00
CID:		**Rcvd Date:**	2006-10-24 12:35:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	2007-05-15 00:00:00
Water Body:		**Create Date:**	2006-10-24 12:48:00
Class:	B3	**Update Date:**	2007-07-27 15:14:38.953000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	CGMCKENZ
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Local Agency		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"WHILE INSTALLING A CONDENSATE RETURN LINE, AN UNKNOWN ABANDONED UST WAS FOUND WITH WHAT APPEARS TO BE PETROEUM CONTAMINATION AROUND IT. TANK IS BETWEEN THE CURB AND THE SIDEWALK. DANFORTH IS DOING WORK FOR THE STEAMLINE. THEY ARE INTERVIEWING TONAWANDA TANK AND ELMWOOD TANK REGARDING REMOVAL OF THE TANK."

Dec Remark:

"10/24/6 SAC NOTIFIES PBS-BG THAT REGISTRATION OF TANK REQUIRED. 10/26/6 ON SITE W/ JOE, STEVE AND ANTHONY. UST TANK TOP UNCOVERED. MANHOLE OPENED, COULD SEE TANK WAS CLOSED IN PLACE W/SLURRY. MINOR FLUID W/STRONG PETROLEUM ODOR INSIDE. AREA FENCED FOR PROTECTION. THEY WILL CONTINUE W/UTILITY INSTALLATION. FEELS TANK BELONGS TO CITY SINCE TANK SITS INSIDE ROW. REQUESTED ABSTRACT/ DOCUMENTS REGARDING DISCOVERY OF TANK. 10/27/6 Nothing found in Sanborn search for tank history. Call PBS contacts, need updating. Requested SPCC plan identifying all tank locations. Called Buff Fire Dept on tank closures for this area. Joe Moslow researching records to see when Roswell knew of tank existence, when it was closed, by whom and if site assessment exists. 10/30/6 Ken-Buff Fire Dept (851-5707 x756) states nothing on file for Carlton, Michigan, Elm or old alley that was removed to build the parking garage. 11/3/6 City of Buff's contractor/Tom Forbes, Benchmark (864-1730) will do what has to be done w/tank. 11/16/6 Joe states City owns ROW where UST is. T/C with Darin Muglestein (843-5896) and Dennis Sutton. 11/17/6 MOSLOW FAXED URS TANK LOCATION MAP. 11/29/6 T/C W/JOE, RE RESEARCH FINDINGS? 11/30/6 TOM FORBES/ BENCHMARK FOR DAN KRUIZ OF CITY STATES THEY ARE PREPARED TO REMOVE TANK IF NO DATA IS LOCATED. 12/1/6 JOE FOUND ABSTRACT, WAS A VACANT LOT IN 1964. MOSLOW FAXED TITLE INSURANCE ABSTRACT SHOWING OWNERSHIP HISTORY OF TANK LOCATION/ PROPERTY. 12/4/6 TOM FORBES BIDDING OUT REMOVAL OF UST. NO DATA FOUND AT CITY. 12/6/6 MOSLOW FAXED 5/20/94 LTR FROOM LEHRER MCGOVERN BOVIS INC/ RUSSELL PROGRAM MANAGEMENT STATING UST WAS DISCOVERED. CONTAMINATED SOIL FOUND W/ PETROLEUM ODORS. LTR STATES NFG LOCATED TANK DURING GAS LINE INSTALLATION. CONTACTED NFG TO SEE WHAT INFORMATION THEY HAD ON TANK AND END RESULT OF CONTAMINATED SOILS REMOVED AT THAT TIME. NYSOGS CALLED TO RESEARCH FOR SITE ASSESSMENT PAPERS. DOH CALLED TO LOCATE SITE ASSESSMENT INFO. ALL FOUR AGENCIES HAVE NO INFORMATION. CALL CITY FIRE DEPARTMENT AND DPW FOR ASSESSMENT INFO/ REGISTRATION OF TANK. KURT KRUMPA/OGS A CONTACT REGARDING INFO ON UST CLOSURE IN 90s. REFERRED TO MARTIN DEPAULO (518-473-9369). 12/8/6 LIER-MCGOVERN-BOGUS LTR STATES PREVIOUS OWNER DOH CONTRACTED CONDENSATE LINE PRIOR TO ROSWELL OWNERSHIP. OGS FOUND TANK, WORKED AROUND IT. ROBERT GREY-DOH STATED NATIONAL FUEL FOUND TANK, CONTAMINATED SOIL FOUND/STAGED. T/C W/MARTY OGS TO FOLLOWUP ON DATA THEY HAVE. CGM T/C W/JOE FOUND ABSTRACT, BACKUP TANK IDENTIFIED FROM LETTER RE: UTILITY INSTALLATION PROJECT IN MAY 1994. 12/18/6 TOM FORBES FOR CITY, ROSWELL NOR FIRE DEPARTMENT CAN FIND ANY INFO DESPITE DIRECTION FROM LETTER PROVIDED BY ROSWELL. MARTY DIPAULO RE: PROJECT NUMBER FOR 1994. 12/19/6 TANYA ALEXANDER, NATIONAL FUEL GAS REGARDING CARLTON TANK WORK. 2/9/7 FORBES/BENCHMARK WAITING ON DEC FINDING INFO FROM ROSWELL REGARDING TANK. HOPEFULLY SOMETHING WILL COME UP. CITY WILL DO WHAT MUST BE DONE. KEEP THEM POSTED. LEFT MESSAGE FOR DAN CRUISE OF CITY. LEFT MSG FOR UPDATE FROM MOSLOW. 2/12/7 MIKE TURRI, URS (856-5636) CALLED REGARDING MAP MOSLOW SENT OVER SHOWING TANK LOCATION. ONCE TANK UNCOVERED DURING CONDENSATE LINE INSTALLATION, JOE REQUESTED MAP SURVEY OF ITS LOCATION. 2/13/7 MOSLOW FOUND AND RESUBMITTED 1994 LETTER TO SAL CALANDRA FROM MS. KELLEY OF ROSWELL RELATED TO SPILL REPORTS #9402510 AND #9206876. BOTH SHOW EXISTENCE OF TANK OWNED BY CITY OF BUFFALO DUE TO LOCATION WITHIN ROW. CITY HIRED ELMWOOD TANK AND PIPE TO CLOSE IN PLACE. SITE ASSESSMENT SHOWED EXCEEDANCES AND THOSE SPILLS MADE INACTIVE. DUE TO LOW LEVEL EXCEEDANCES, INACCESSIBILITY OF TANK DUE TO SEVERAL UTILITIES SURROUNDING/TOUCHING TANK, DEPARTMENT STANCE REMAINS THE SAME; IF CITY WISHES TO, THEY MAY REMOVE BUT NOT REQUIRED TO DO SO. MOSLOW CONFIRMS PBS APPL UPDATED W/ CORRECT CONTACTS AND MISSING TANK INFORMATION. 5/14/7 INACTIVE CLOSURE LETTER SUBMITTED TO ROSWELL COPIED TO CITY OF BUFFALO AND THEIR CONTRACTOR-BENCHMARK. NO FURTHER ACTION REQUIRED AT THIS TIME. SHOULD THE CONTAMINATION BE EXPOSED IN THE FUTURE, SPILL WILL BE REOPENED, REMEDIATION MAY BE REQUIRED. "

Material Information

OP Unit ID:	1130185	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2119855	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	DAN CRUISE
Spiller Company:	CITY OF BUFFALO DPW
Spiller Address:	CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	JOE MOSLOW
Contact Phone:	(716) 845-3874
Contact Ext:	
Latitude:	
Longitude:	

---

69 | ***1 of 1*** | ***W*** | ***0.26 / 1,397.10*** | ***666.25 / 22*** | ***IHRIG RESIDENCE 71 NORTH STREET BUFFALO NY*** | ***NY SPILLS***

Spill No:	9503436	***UST Trust:***	True
Site ID:	240579	***Spill Date:***	1995-06-01 12:00:00
DER Facility ID:	197853	***Received Date:***	1995-06-19 12:00:00
CID:		***CAC Date:***	1995-06-20 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1995-06-20 00:00:00
Water Body:		***Create Date:***	1995-06-20 00:00:00
Class:	C4	***Update Date:***	1995-06-23 00:00:00
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SACALAND
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONFIRMATORY SAMPLE RESULTS EXCEED GUIDANCE VALUES."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 06/20/95: ANALYTICAL RESULTS FOR EXCAVATION SAMPLES INDICATE LOW-LEVEL EXCEEDANCES,INACTIVE LETTER SENT. "

Material Information

OP Unit ID:	1014659	***Med Ind Air:***	False
OU:	01	***Med GW:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material ID:	364935	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	JOHN IHRIG
Spiller Address:	71 NORTH STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902245340
Longitude:	-78.871839520

---

70 | ***1 of 1*** | ***NNE*** | ***0.27 / 1,425.31*** | ***643.07 / -1*** | ***TRANSFORMER 80 NORTH HAMPTON BUFFALO NY*** | ***NY SPILLS***

Spill No:	1907809	**UST Trust:**	False
Site ID:	595951	**Spill Date:**	2019-11-02 14:05:00
DER Facility ID:	545756	**Received Date:**	2019-11-02 14:05:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2019-11-04 00:00:00
Water Body:		**Create Date:**	2019-11-02 14:07:00
Class:		**Update Date:**	2019-11-04 08:28:26.550000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Storm		
Reported by:	Other		
Referred to:			
Source:	Transformer		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"cleanup pending"

DEC Remark:

"11/4/19 This is a minor spill that has been properly cleaned up and disposed of by National Grid. No further action is necessary. The spill site is closed."

Material Information

OP Unit ID:	1343488	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2353669	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False

Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	
Spiller Company:	NATIONAL GRID
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA MONTISANO
Contact Phone:	(716) 831-7029
Contact Ext:	
Latitude:	
Longitude:	

---

71 | ***1 of 1*** | ***W*** | ***0.28 / 1,482.28*** | ***667.15 / 23*** | ***SINCLAIR RADIO OF BUFFALO
695 DELAWARE AVENUE
BUFFALO NY*** | ***LST***

Spill No:	9709172	**REM Phase:**	0
Site ID:	190349	**UST Trust:**	True
DER Facility ID:	158781	**Spill Date:**	1997-10-29 12:00:00
CID:	999	**Rcvd Date:**	1997-11-04 10:30:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	
Contribute Factor:	Tank Failure	**Close Date:**	1998-12-02 00:00:00
Water Body:		**Create Date:**	1997-11-06 00:00:00
Class:	D6	**Update Date:**	2001-12-05 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	COOKE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"MR ATKINS ADVISED HIS POST TEST RESULTS HAD LEVELS OF CONTAMINATION. AFTER REVIEW OF FAXED RESULTS FOUND MINOR VIOLATIONS, WILL CLOSE FILE AS INACTIVE. ADVISED MR MTKINS THAT HE COULD RESAMPLE FOR CLOSURE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 11/4/97: JDC TELCON W/ TOM ATKINS, FACILTY MGR FOR RADIO STATION. ADVISED HE FORWARD POST TEST RESULTS FOR OUR REVIEW. RECEIVED RESULTS AND FOUND LEVELS SATISFACTORY FOR 8021 DIRECT, HOWEVER 8270 RESULTS EXCEEDED. JDC CONTACTED MR ATKINS AND REQUESTED HE RESAMPLE UNDER TCLP CONDITIONS. HE AGREED, WILL DETERMINE STATUS BASED ON NEXT ROUND OF SAMPLING. 5/4/98: JDC TELCON W/ ANDY KASARICK, BFLO DRILLING AND ADVISED ON RESAMPLING REQUIREMENTS. 12/2/98: JDC LEFT MESSAGE FOR MR ATKINS TO RETURN MY CALL ON RESAMPLING STATUS. TELCON W/ ANDY KASARICK WHO SAID HE FAX OVER RESULTS. JDC RECEIVED TEST RESULTS FOR TCLP AND FOUND SATISFACTORY. NO FURTHER ACTION REQUIRED SITE CLOSED. WILL SEND CLOSURE LETTER."

Material Information

OP Unit ID:	1055557	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	331087	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	THOMAS ATKINS
Spiller Company:	SINCLAIR RADIO OF BUFFALO
Spiller Address:	695 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14209-
Spiller Country:	001
Contact Name:	TOM ATKINS
Contact Phone:	(716) 843-0269
Contact Ext:	
Latitude:	42.902942870
Longitude:	-78.872777290

72	1 of 1	SW	0.29 / 1,518.57	647.39 / 3	NATIONAL FUEL GAS CARLTON AND WASHINGTON ST BUFFALO NY	NY SPILLS

Spill No:	8905988	**UST Trust:**	False
Site ID:	189803	**Spill Date:**	1989-09-18 11:10:00
DER Facility ID:	158385	**Received Date:**	1989-09-18 11:25:00
CID:		**CAC Date:**	1990-03-14 00:00:00
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1990-03-14 00:00:00
Water Body:		**Create Date:**	1989-09-18 00:00:00
Class:		**Update Date:**	1990-03-26 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FIX
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FROM BACK OF TRUCK HOSE SPRAYED 24X2 FOOT AREA OF SOIL WITH HYDRAULIC OIL(RED APPEARANCE,SWEET SMELL)"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CAF 09/18/89: CAF SITE VISIT WITH FOREMAN RON WALSH,ADVISED RON OF CLEANUP REQUIREMENTS. 09/22/89: CAF SITE VISIT -OIL LADEN SOIL REMOVED,NEW SOIL IN ITS PLACE.SPOKE TO TANYA ALEXANDER RELATIVE TO SOIL DISPOSAL. 03/14/90: CAF RECEIVED SOIL RECEIPTS,NO FURTHER ACTION PLANNED. "

Material Information

OP Unit ID:	933628	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	570762	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	5.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Air: False
Material Code: 0010
Material Name: hydraulic oil

Spiller Information

Spiller Name:
Spiller Company: NATIONAL FUEL GAS
Spiller Address: 10 LAFAYETTE SQUARE
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14203
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.898563034
Longitude: -78.869085923

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
73	1 of 1	W	0.29 / 1,519.32	669.04 / 25	WESTBROOK 675 DELAWARE 675 DELAWARE AVENUE BUFFALO NY	LST

Spill No: 9308986
Site ID: 213036
DER Facility ID: 176488
CID:
Program Type: ER
SWIS Code: 1502
Contribute Factor: Tank Failure
Water Body:
Class: B3
Meets Std: True
Penalty: False
County: Erie
Referred to:
Reported by: Other
Source: Private Dwelling
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 1993-10-21 12:00:00
Rcvd Date: 1993-10-21 13:30:00
CAC Date: 1994-02-08 00:00:00
Insp Date: 1993-12-01 00:00:00
Close Date: 1994-04-20 00:00:00
Create Date: 1993-10-26 00:00:00
Update Date: 1994-04-21 00:00:00
DEC Region: 9
Lead DEC: RMCROSSE
After Hours: False

Caller Remark:

"CONTAMINATED SOIL DISCOVERED DURING REMOVAL OF 6K UST"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 10/22/93: RMC/JOE KLOC/SITE - 6K #6 OIL TANK; PLANNED TO CLOSE IN PLACE. ONCE CLEANED, OIL RAN INTO BOTTOM FROM OUTSIDE. REMOVAL PROBLEMATIC DUE TO BUILDING. REQUESTED WORK PLAN AND SCHEDULE BY 11/15/93. 11/01/93: RMC/RECEIVED WRITTEN WOK PLAN, OK. HOWEVER PLAN ALTERED TO COMPLETE REMOVAL, DUE TO AMOUNT OF CONTAMINATION FOUND, REMOVAL DUE 12/1/93. 12/01/93: RMC/FILE/SITE MET HITCHCOCK ON SITE, DATE UNKNOWN, TANK REMOVED, VERY MINOR CONTAMINATION NOTED AT NORTH END, 1 YARD TO REMOVE, DISPOSAL AND TESTING DUE 1/30/94. 03/07/94: RMC/NFC/PHONE TO FAX DISPOSAL AND ANALYITICAL. DUE 3/21/94. 03/10/94: RMC/RECEIVED SAMPLING RESULTS, NO EXCEEDANCES, DISPOSAL DUE 4/1/94. 04/20/94: RMC/RECEIVED DISPOSAL RECEIPT, OK SPILL COMPLETE, CLOSE OUT. "

Material Information

OP Unit ID: 990522
OU: 01
Material ID: 391662
CAS No:
Material Family: Petroleum
Quantity: .00
Units:
Recovered: .00
Med Soil: True

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Air: False
Material Code: 0003A
Material Name: #6 fuel oil

Spiller Information

Spiller Name:
Spiller Company: NIAGARA ASSET CORP.
Spiller Address: 60 LAKEFRONT BLVD.
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14202-4392
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.902460890
Longitude: -78.872918540

74	1 of 8	NNW	0.30 / 1,573.13	652.88 / 8	TANK ROOM 1264 MAIN ST BUFFALO NY	NY SPILLS

Spill No: 0809396
Site ID: 406855
DER Facility ID: 356111
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2008-11-19 09:00:00
Received Date: 2008-11-19 13:32:00
CAC Date:
Insp Date:
Close Date: 2008-11-28 00:00:00
Create Date: 2008-11-19 13:34:00
Update Date: 2008-11-28 13:39:56.317000000
DEC Region: 9
Lead DEC: TDJOHNSO
After Hours: False

Caller Remark:

"A waste oil heater valve was loose and leaked oil onto the concrete floor. Clean up is ongoing."

DEC Remark:

"11/19/08 TDJ VALVE ON WASTE OIL LINE LEAKED OIL ONTO CONCRETE VAULT IN BASEMENT OF DELTASONIC OIL CHANGE AREA. MANAGER WAS CLEANING UP WIYH SPEEDY DRY AND WILL HAVE SAFETY KLEEN DISPOSE OF MATERIAL. NO DRAINS IN FLOOR OF VAULT AND AREA WILL BE REINSPECTED WHEN WORK ISS COMPLETE. 11/28/08 TDJ RECEIVED DISPOSAL RECEIPT FOR SPEEDY DRY/WASTE OIL CLEANUP MATERIAL TAKEN AWAY FOR DISPOSAL BY SAFETY KLEEN SYSTEMS. ONE DRUM OF NON REGULATED WASTE WAS DISPOSED OF. NO FURTHER ACTION FILE CLOSED "

Material Information

OP Unit ID: 1163424
OU: 01
Material ID: 2154738
CAS No:
Material Family: Petroleum
Quantity: 30.00
Units: G
Recovered:
Med Soil: False
Med Air: False

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Code: 0022
Material Name: waste oil/used oil

Spiller Information

Spiller Name: JOHN RUSCH
Spiller Company: DELPASONIC
Spiller Address: 1264 MAIN ST
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: JOHN RUSCH
Contact Phone: (716) 289-2895
Contact Ext:
Latitude: 42.908258476
Longitude: -78.867035483

74	2 of 8	NNW	0.30 / 1,573.13	652.88 / 8	DELTASONIC 1264 MAIN STREET BUFFALO NY	NY SPILLS

Spill No: 9204557
Site ID: 62626
DER Facility ID: 60699
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: E6
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Other
Reported by: Affected Persons
Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 1992-07-08 12:00:00
Received Date: 1992-07-20 14:00:00
CAC Date: 1992-07-22 00:00:00
Insp Date:
Close Date: 1992-07-22 00:00:00
Create Date: 1992-07-22 00:00:00
Update Date: 2002-03-15 00:00:00
DEC Region: 9
Lead DEC: SORGI
After Hours: False

Caller Remark:

"CONSUMER SAID HE RECEIVED APPROX 25 GAL OF GAS, HALF OF WHICH WAS WATER"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 07/20/92: MDB TO INSPECT. HOLD FOR HIS REPORT. 07/22/92: MJS SPOKE WITH MDB. HE INSPECTED SITE AND FOUND NO VIOLATIONS. FILL CAP WAS LEFT OFF FILL PIPE AND RAINWATER ENTERED TANK. NO FURTHER ACTION BY SPILL UNIT. MJS TO CLOSE FILE. "

Material Information

OP Unit ID: 968225
OU: 01
Material ID: 412266
CAS No:
Material Family: Petroleum
Quantity: .00
Units: L
Recovered: .00
Med Soil: False
Med Air: False
Material Code: 0009
Material Name: gasoline

Med Ind Air: False
Med GW: True
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:	
Spiller Company:	NONE
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.907812270
Longitude:	-78.867240130

74	3 of 8	NNW	0.30 / 1,573.13	652.88 / 8	DELTA SONIC 1264 MAIN STREET BUFFALO NY	NY SPILLS

Spill No:	9906970	***UST Trust:***	False
Site ID:	62627	***Spill Date:***	1999-09-11 10:30:00
DER Facility ID:	60699	***Received Date:***	1999-09-11 10:45:00
CID:	351	***CAC Date:***	
Program Type:	ER	***Insp Date:***	1999-09-14 00:00:00
SWIS Code:	1502	***Close Date:***	1999-09-14 00:00:00
Water Body:		***Create Date:***	1999-09-11 00:00:00
Class:	C3	***Update Date:***	2002-03-15 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SACALAND
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Passenger Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DRIVER OF A VEHICLE WAS FILLING TANK AT GAS STATION & THE GAS TANK ON THE VEHICLE WAS LEAKING - FD ON SCENE WHO HAS CONTAINED THE SPILL"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 09/11/99: GERRY PALUMBO, DUTY OFFICER, SPOKE WITH FRANK SCHIABARRASI OF DELTA SONIC, ALTHOUGH ORIGINALLY REPORTED AS 15 GALLONS, 7.9 GALS OF PRODUCT SPILLED DUE TO BROKEN FUEL LINE, SPILL WAS CONTAINED WITH KITTY LITTER, NO SEWERS WERE IN THE AREA AND HIS STAFF COMPLETED THE CLEANUP. 09/14/99: SAC SITE INSPECTION, MET STORE MANAGER, DONNA, WHO SHOWED SAC LOCATION OF THE SPILL, SPILL WAS CLEANED UP, DONNA SAID THAT BRUCE NATALIZIA WAS ON-SCENE DURING THE INCIDENT SAC SPOKE TO DELTA SONIC EMPLOYEE JOHNNY MOORE WHO HELPED WITH THE CLEANUP, PER MR. NATALIZIA'S DIRECTION, ABSORBENTS WERE PLACED DOWN TO CLEAN UP THE SPILL, AND ALLOWED TO AERATE AND THEN PLACED IN PLASTIC BAG FOR DUMPSTER PICKUP."

Material Information

OP Unit ID:	1085403	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	299682	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	8.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	8.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		

Material Name: gasoline

Spiller Information

Spiller Name:
Spiller Company: UNKNOWN MOTORIST
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: FRANK SCHIABARRASI
Contact Phone: (716) 882-2941
Contact Ext:
Latitude: 42.907812270
Longitude: -78.867240130

---

74 | ***4 of 8*** | ***NNW*** | ***0.30 / 1,573.13*** | ***652.88 / 8*** | ***DELTA SONIC CAR WASH 1264 MAIN STREET BUFFALO NY 14203*** | ***NY SPILLS***

Spill No: 1407257
Site ID: 500765
DER Facility ID: 455768
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D4
Meets Std: True
Penalty:
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2014-10-11 13:00:00
Received Date: 2014-10-11 13:03:00
CAC Date:
Insp Date:
Close Date: 2014-10-14 00:00:00
Create Date: 2014-10-11 13:06:00
Update Date: 2014-10-14 10:09:14.133000000
DEC Region: 9
Lead DEC: RMCROSSE
After Hours: True

Caller Remark:

"caller reporting spill of gas, spill went to concret, no resources affected, clean up is done"

DEC Remark:

"10/11/14:SAC TELECON MIKE YOUNT - DELTA SONIC. SPILL HAPPENED WHEN NOZZLE FELL OFF THE HOSE. THEY WERE ABLE TO SHUT DOWN PUMP QUICKLY. THEY WERE ABLE TO CONTAIN AND CLEAN UP QUICKLY. NO DRAINS AFFECTED. THEY ARE REPLACING THE NOZZLE. 10/14/14 RMC/FILE. MINOR INCIDENT REPORTED TO HAVE BEEN CONTAINED AND CLEANED UP IMMEDIATELY BY RP. NO ACTION REQUIRED. CLOSE OUT."

Material Information

OP Unit ID: 1250161
OU: 01
Material ID: 2251842
CAS No:
Material Family: Petroleum
Quantity: 10.00
Units: G
Recovered: 10.00
Med Soil: False
Med Air: False
Material Code: 0009
Material Name: gasoline

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: True
Med Subway: False
Med Utility: False
Oxygenate:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:	MIKE YOUNT
Spiller Company:	DELTA SONIC
Spiller Address:	1264 MAIN STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	MIKE YOUNT
Contact Phone:	(716) 481-6898
Contact Ext:	
Latitude:	
Longitude:	

74	5 of 8	NNW	0.30 / 1,573.13	652.88 / 8	FRONT YARD 1264 MAIN ST BUFFALO NY	NY SPILLS

Spill No:	1707510	***UST Trust:***	False
Site ID:	563871	***Spill Date:***	2017-11-04 08:00:00
DER Facility ID:	356111	***Received Date:***	2017-11-04 08:33:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2018-03-06 00:00:00
Water Body:		***Create Date:***	2017-11-04 08:35:00
Class:		***Update Date:***	2018-03-06 14:22:05.420000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	FXGALLEG
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"contained to pavement and clean up is completed"

DEC Remark:

"11/4/17 FG spoke to Tom Forbes with Benchmark. He said they are the environmental contact for Delta Sonic now. A customer overfilled their gas tank and it was cleaned up right away. The cleanup debris was placed in a drum. Benchmark will provide a closure report. 2/14/18 FG requested an update from Tom Forbes. 3/5/18 FG received the disposal receipt for the cleanup debris which was disposed at Superior lubricants. 1 drum."

Material Information

OP Unit ID:	1311829	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2319023	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	10.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Name:
Spiller Company: DELTA SONIC CAR WASH SYSTEMS INC
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: THOMAS FORBES
Contact Phone: (716) 864-1730
Contact Ext:
Latitude:
Longitude:

74	6 of 8	NNW	0.30 / 1,573.13	652.88 / 8	DELTA SONIC CAR WASH 1264 MAIN ST BUFFALO NY	NY SPILLS

Spill No:	1911365	**UST Trust:**	False
Site ID:	602058	**Spill Date:**	2020-03-10 14:50:00
DER Facility ID:	356111	**Received Date:**	2020-03-10 15:27:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2020-03-12 00:00:00
Water Body:		**Create Date:**	2020-03-10 15:30:00
Class:		**Update Date:**	2020-03-12 08:19:44.007000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Unknown
Reported by: Responsible Party
Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"gasoline entered the catch basin, it's being checked to see if it went anywhere offsite, c/u in progress"

DEC Remark:

"03/11/20 TDJ CONTACTED DELTA SONIC REP.WHO STATED THAT APPROX 2 GALLONS OF GASOLINE WAS SPILLED BY CUSTOMER. SPEEDY DRY WAS PLACED AND BOOM WAS PLACED INTO STORM DRAIN AS PRECAUTION. RAIN CAUSED A SHEEN TO FLOW TOWARDS CATCH BASIN BUT MINIMAL ENTERED DRAIN. CONTAMINATED MATERIAL WAS COLLECTED FOR DISPOSAL INTO REGULARY PICKED UP WASTE LOCATION. SITE WAS CLEANED TO SATISFACTION OF DEC SITE MANAGER. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1349192	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2359780	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	True
Quantity:	3.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0009
Material Name: gasoline

Spiller Information

Spiller Name:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Company: UNK
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: TIM REEDY
Contact Phone: (716) 541-2332
Contact Ext:
Latitude:
Longitude:

---

74 | **7 of 8** | **NNW** | **0.30 / 1,573.13** | **652.88 / 8** | **COMMERICAL 1264 MAIN ST BUFFALO NY** | **NY SPILLS**

Spill No: 2002296
Site ID: 607976
DER Facility ID: 356111
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: C1
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2020-06-27 12:45:00
Received Date: 2020-06-27 12:58:00
CAC Date:
Insp Date:
Close Date: 2020-06-29 00:00:00
Create Date: 2020-06-27 13:00:00
Update Date: 2020-09-11 08:26:43.060000000
DEC Region: 9
Lead DEC: TDJOHNSO
After Hours: True

Caller Remark:

"clean up almost completed"

DEC Remark:

"06/28/20 TDJ CONTACTED JIM REIDY AT DELTA SONIC WHO STATED THAT A TRUCK FILLED UP WITH GASOLINE WITHOUT NOWING THAT THE TANK WAS LEAKING. APPROX. 10 GALLONS WAS LOST TO CONCRETE DRIVEWAY. SPEEDY DRY WAS USED TO CONTAIN THE SPILL. MATERIAL WAS SWEPT UP AND CONTAINED INTO DRUMS FOR DISPOSAL. NO FURTHER ACTION FIEL CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID: 1355134
OU: 01
Material ID: 2366203
CAS No:
Material Family: Petroleum
Quantity: 15.00
Units: G
Recovered:
Med Soil: True
Med Air: False
Material Code: 0009
Material Name: gasoline

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: (DELTA SONIC CAR WASH SYSTEMS)
Spiller Address:
Spiller City:

Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	TIM RIEDY
Contact Phone:	(716) 870-9752
Contact Ext:	
Latitude:	
Longitude:	

74 | **8 of 8** | **NNW** | **0.30 / 1,573.13** | **652.88 / 8** | **COMMERCIAL**
1264 MAIN ST
BUFFALO NY 14209 | **NY SPILLS**

Spill No:	2008396	**UST Trust:**	False
Site ID:	615332	**Spill Date:**	2020-12-28 11:45:00
DER Facility ID:	52495	**Received Date:**	2020-12-28 12:22:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2021-02-11 00:00:00
Water Body:		**Create Date:**	2020-12-28 12:24:00
Class:		**Update Date:**	2021-02-11 14:22:17.120000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"spill to pavement, clean up in progress"

DEC Remark:

"12/29/20 TDJ CONTACTED TIM REIDY FROM DELTA SONIC REGARDING GASOLINE SPILL. APPARENTLY A CUSTOMER PUT PUMP IN THE CAR AND SAT DOWN INSIDE. RELEASE ON PUMP DID NOT KICK OFF CAUSING A SPILL OF 15 GALLONS OF GASOLINE TO ASPHALT. WORKERS AT STATION PUT BOOM AROUND DRAIN BEFORE IT REACHED. SPEEDY DRY WAS USED TO ABSORB MATERIAL WHIC WAS PLACED INTO DRUM FOR DISPOSAL. NO GASOLINE REACHED DRAIN BUT BOOM WAS PLACED INSIDE TO COLLECT ANY RUNNOFF INTO SAME. DISPOSAL RECEIPT WILL BE GENERATED. 02/11/21 TDJ RECEIVED DISPOSAL INFO FOR SPILL CLEANUP. ONE DRUM OF CONTAMIATED SORBENT MATERIAL WAS SENT FOR DISPOSAL. SITE WAS CLEANED TO SATISFACTION OF DEC SITE MANAGER. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1362432	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2374508	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	15.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	DELTA SONIC CAR WASH
Spiller Address:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: TIMOTHY RIEDY
Contact Phone: (716) 541-2332
Contact Ext:
Latitude:
Longitude:

---

75 | **1 of 1** | **NE** | **0.30 / 1,591.91** | **637.64 / -7** | **NATIONAL GRID**
153 NORTH HAMPTON STREET
BUFFALO NY 14203 | **NY SPILLS**

Spill No: 1109000
Site ID: 456747
DER Facility ID: 411277
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D4
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2011-10-17 15:50:00
Received Date: 2011-10-17 16:03:00
CAC Date:
Insp Date:
Close Date: 2012-01-25 00:00:00
Create Date: 2011-10-17 16:08:00
Update Date: 2012-01-25 14:22:47.310000000
DEC Region: 9
Lead DEC: RMCROSSE
After Hours: False

Caller Remark:

"Cleanup in progress."

DEC Remark:

"01/25/12 RMC/FILE. MINOR SPILL REPORTED AS CLEAN UP IN PROGRESS. NO ACTION REQUIRED. CLOSE OUT. NO PAPER FILE. "

Material Information

OP Unit ID: 1206889
OU: 01
Material ID: 2204020
CAS No:
Material Family: Petroleum
Quantity: 1.00
Units: G
Recovered:
Med Soil: True
Med Air: False
Material Code: 0020A
Material Name: transformer oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: LISA MONTESANO
Spiller Company: NATIONAL GRID
Spiller Address: 144 KENSINGTON AVENUE
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14214
Spiller Country: 999
Contact Name: LISA MONTESANO

Contact Phone: (716) 479-5339
Contact Ext:
Latitude:
Longitude:

---

76 **1 of 3** **S** **0.30 / 1,600.72** **639.52 / -5** **J & I DISPOSAL**
666 ELM STREET
BUFFALO NY
NY SPILLS

Spill No:	8902159	**UST Trust:**	False
Site ID:	195811	**Spill Date:**	1989-06-02 06:00:00
DER Facility ID:	163129	**Received Date:**	1989-06-02 09:00:00
CID:		**CAC Date:**	1989-06-13 00:00:00
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1989-06-13 00:00:00
Water Body:		**Create Date:**	1989-06-02 00:00:00
Class:		**Update Date:**	1989-06-26 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	ROSS
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Other
Reported by: Fire Department
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"EXPLOSION IN A DUMP TRUCK"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR 06/02/89: MF FOR LQR CHEMICALS BURNED UP IN THE FIRE. FD TO CONTACT HOSPITAL TO FIND OUT WHY CHEMICALS WERE THROWN OUT & CONTAINERS NOT CLEANED. 06/13/89: NO RESPONSE FROM FD FOR FURTHER ASSISTANTS,NO FURTHER ACTION REQUIRED. 09/29/95: This is additional information about material spilled from the translation of the old spill file: HEXANE & THIOPHENE."

Spiller Information

Spiller Name:
Spiller Company: J & I TRUCKING CO
Spiller Address: 11372 MAIN STREET
Spiller City: CLARENCE
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.892799993
Longitude: -78.866730023

---

76 **2 of 3** **S** **0.30 / 1,600.72** **639.52 / -5** **ROSWELL PARK**
666 ELM STREET
BUFFALO NY
NY SPILLS

Spill No:	8706549	**UST Trust:**	False
Site ID:	195810	**Spill Date:**	1987-10-26 12:00:00
DER Facility ID:	163129	**Received Date:**	1987-11-02 18:15:00
CID:		**CAC Date:**	1987-11-18 00:00:00
Program Type:	ER	**Insp Date:**	1987-11-04 00:00:00
SWIS Code:	1502	**Close Date:**	1987-11-18 00:00:00
Water Body:		**Create Date:**	1987-11-04 00:00:00
Class:		**Update Date:**	1987-12-10 00:00:00
Meets Std:	True	**DEC Region:**	9

Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Other		
Reported by:	Citizen		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"NATIONAL FUEL GAS ON SCENE, TURNED OFF WATER HEATER & FURNACE. SUSPECT CO FUMES FROM FURNACE & HOT WATER HEATER."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF / / : MF 11/04/87 DEC TO INVESTIGATE. / / : 11/04/87 MF MET WITH AL GUSTAFSON (ROSWELL). LAST TIME DIGGING 2 WEEKS AGO, MICHIGAN & HIGH DID NOT NOTICE CONTAMINATION IN EXCAVATION. / / : MF 11/18/87 PAUL RODRIGEZE HAS NOT CONTACTED OFFICE APPEARENTLY COMPLAINT IS UNFOUNDED, HE WAS SCHEDULED TO CALL 11/4/87. "

Material Information

OP Unit ID:	910270	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	465558	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	True		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	ROSWELL PARK
Spiller Address:	666 ELM STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.892799993
Longitude:	-78.866730023

76	3 of 3	S	0.30 / 1,600.72	639.52 / -5	ROSWELL PARK 666 ELM STREET BUFFALO NY	LST

Spill No:	8905775	**REM Phase:**	0
Site ID:	195812	**UST Trust:**	True
DER Facility ID:	163129	**Spill Date:**	1989-09-07 15:00:00
CID:		**Rcvd Date:**	1989-09-08 15:30:00
Program Type:	ER	**CAC Date:**	1989-11-22 00:00:00
SWIS Code:	1502	**Insp Date:**	1989-10-26 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1989-11-22 00:00:00
Water Body:		**Create Date:**	1989-09-15 00:00:00
Class:		**Update Date:**	1989-12-08 00:00:00
Meets Std:	True	**DEC Region:**	9

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Penalty:	False	**Lead DEC:**	LYONS
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"1000 GALLON TANK WAS TAKING ON WATER AND FAILED AN AIR PRESSURE TEST."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MEL 09/14/89: MEL TELCON WITH DENNIS MAHN. TANK HAS BEEN EMPTIED, AND ARRANGEMENTS ARE BEING MADE TO REMOVE TANK FROM GROUND. 10/23/89: MEL TELCON WITH DON FRASER, OGS. TANKS ARE TO BE REMOVED ON 10/24/89. SENT LETTER OUTLINING REQUIREMENTS. 10/24/89: CAF INSPECTION. MET DON FRASER ON SITE. TWO 1000 GALLON TANKS REMOVED. NO PETROLEUM CONTAMINATED SOIL OBSERVED, PERMISSION TO BACKFILL GIVEN. ELMWOOD TANK TO CLEAN TANKS. 10/26/89: MEL INSPECTION. EXCAVATION BACKFILLED.ELMWOOD TANK ON SITE TO CLEAN TANKS. 11/20/89: MEL. NO CONTAMINATION OBSERVED, TANKS CLEANED BY ELMWOOD TANK. NO FURTHER ACTION NECESSARY, RECOMMEND FILE BE CLOSED AS PER RNL. "

Material Information

OP Unit ID:	930967	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	446178	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	ROSWELL PARK
Spiller Address:	666 ELM STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14263
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.892799993
Longitude:	-78.866730023

77	1 of 1	SE	0.31 / 1,613.76	637.66 / -7	POLE 173 173 MULBERRY ST BUFFALO NY	NY SPILLS

Spill No:	0805954	**UST Trust:**	
Site ID:	403171	**Spill Date:**	2008-08-25 19:00:00
DER Facility ID:	352370	**Received Date:**	2008-08-25 19:18:00
CID:	79	**CAC Date:**	
Program Type:	ER	**Insp Date:**	2008-08-26 00:00:00
SWIS Code:	1502	**Close Date:**	2008-08-27 00:00:00
Water Body:		**Create Date:**	2008-08-25 19:29:00
Class:	D3	**Update Date:**	2008-08-27 09:53:03.617000000
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	jfotto

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TRANSFORMER BLOWN. ON PAVEMENT AND GRASS. CLEANUP CREW EN ROUTE. UNK PCB."

DEC Remark:

"08/26/08 JFO ON SITE MET WITH NATIONAL GRID WORKER BILL SCHMIDT. THE SPILL HAS BEEN CLEANED UP. HE IS UNSURE IF OIL IS PCB. JFO CALL TO LISA MONTESANO. SHE RECEIVED THE RESULTS. OIL IS NON-PCB. NO FURTHER ACTION REQUIRED. CLOSED ELECTRONIC FILE"

Material Information

OP Unit ID:	1159890	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2151020	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	True
Units:	G	**Med Subway:**	False
Recovered:	1.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	LISA MONTSANO
Spiller Company:	NATIONAL GRID
Spiller Address:	173 MULBERRY ST
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	LISA MONTSANO
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	42.898091498
Longitude:	-78.861356812

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
78	1 of 1	W	0.31 / 1,646.25	667.13 / 23	FAIRFAX APTS. 715 DELAWARE AVE. BUFFALO NY	NY SPILLS

Spill No:	0550371	**UST Trust:**	False
Site ID:	346890	**Spill Date:**	2005-06-02 08:00:00
DER Facility ID:	293150	**Received Date:**	2005-06-02 08:30:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2005-06-09 00:00:00
Water Body:		**Create Date:**	2005-06-02 08:45:00
Class:	D5	**Update Date:**	2005-06-09 09:00:46.093000000
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	JFOTTO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Deliberate		

Reported by: Citizen
Referred to:
Source: Private Dwelling
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CALLER STATES THAT A PERSON HAS DUMPED AUTO FLUIDS BEHIND 715 DELAWARE AVE. ON THE GROUND...THE CAR IS LICENSE # BMS3157,GRAY BUICK...PERSON CALLED HIMSELF FRANK,BUT WANTS TO REMAIN ANONYMOUS."

DEC Remark:

"06/02/05 RJJ REFERRED THIS SPILL TO LAW ENFORCEMENT FOR FOLLOW UP. NO ACTION NECESSARY BY SPILLS. CLOSED THERE IS NO PAPER FILE FOR THIS SPILL"

Material Information

OP Unit ID:	1104646	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	584859	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	False
Med Air:	False		
Material Code:	0021		
Material Name:	transmission fluid		

Spiller Information

Spiller Name:
Spiller Company:
Spiller Address:
Spiller City:
Spiller State:
Spiller Zip:
Spiller Country:
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.903448741
Longitude: -78.872590412

---

79 | ***1 of 1*** | ***SW*** | ***0.32 / 1,671.54*** | ***647.79 / 3*** | ***CITY OF BUFFALO MAIN AND CARLTON STREETS BUFFALO NY*** | ***NY SPILLS***

Spill No:	8907967	**UST Trust:**	True
Site ID:	233116	**Spill Date:**	1989-11-01 12:00:00
DER Facility ID:	192072	**Received Date:**	1989-11-10 12:00:00
CID:		**CAC Date:**	1993-01-25 00:00:00
Program Type:	ER	**Insp Date:**	1992-02-26 00:00:00
SWIS Code:	1502	**Close Date:**	1993-01-25 00:00:00
Water Body:		**Create Date:**	1989-11-17 00:00:00
Class:	C6	**Update Date:**	2001-10-25 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	LEARY
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"SITE ASSESSMENT OF URBAN RENEWAL PROPERTY FOUND HYDROCARBONS - LEGAL REFERRAL"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 11/09/89: RNL RECEIVED LETTER DATED 11/09/89 AND REPORTS FROM GEORGE LUKASZEWICZ, SITE ASSESSMENT, REPLY REQUESTED OF DEC. 03/09/90: RNL LETTER DATED 03/09/90, REQUESTS ANSWER TO PREVIOUS LETTER. 07/24/90: RNL SITE INSP. 07/24/90, NO WORK AT SITE, MADE SKETCH OF SITE, FROM TELECON 03/12/90, CITY HAD HIRED EMPIRE SOILS TO INVESTIGATE SITE AND REPORT FINDINGS. 12/28/90: RNL LETTER TO CITY 12/10/90, REQUESTED UPDATE; RNL REC. REPORT FROM CITY 12/21/90, FOUND PETROLEUM; RNL LETTER TO CITY 12/28/90, REQUESTED CLEANUP OF AREA AROUND FORMER GAS PUMP ISLAND. 01/31/91: RNL REC. LETTER 01/30/91 FROM CITY, STATED HEALTH CARE PLAN RESPONSIBLE FOR CLEANUP; RNL LETTER TO HEALTH CARE PLAN 01/31/91, REQUESTED CLEANUP. 02/04/91: RNL INSP. 02/04/91, NO WORK AT SITE, LETTER HAS BEEN SENT TO HEALTH CARE PLAN. 04/10/91: RNL SECOND LETTER TO HEALTH CARE PLAN 04/10/91, REQUESTED WORK SCHEDULEE PLAN. 05/15/91: RNL MORE LETTERS TO HEALTH CARE PLAN 05/15/91 AND CITY OF BUFFALO 05/15/91, REQUESTED WORK SCHEDULE PLAN. 08/26/91: RNL INSP. 08/26/91, NO WORK; RNL LETTERS TO CITY AND HEALTH CARE, LEGAL REFERRAL TO BE STARTED DUE TO NO WORK. 09/25/91: RNL LEGAL REFERRAL TO PJB 09/25/91. 02/26/92: RNL SITE INSP. 02/26/92, CONSTRUCTION FENCING AROUND SITE AND TRAILERS ON SITE BUT NO WORK, INFORMED LEGAL, LEGAL REFERRAL HAS BEEN SENT OUT TO CITY. 01/25/93: RNL FILE REVIEW, CONSENT ORDER SIGNED, RECEIVED 01/25/93, FINE PAID, CLEANUP NOT POSSIBLE, CLOSEOUT. "

Material Information

OP Unit ID:	932896	***Med Ind Air:***	False
OU:	01	***Med GW:***	True
Material ID:	567840	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO URBAN RENEWAL AGE
Spiller Address:	920 CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-3376
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.886578000
Longitude:	-78.878941000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
80	1 of 1	NNW	0.32 / 1,675.64	652.22 / 8	COMMERCIAL BUILDINGS 1269 THRU 1285 MAIN ST BUFFALO NY	NY SPILLS

Spill No:	1408808	***UST Trust:***	False
Site ID:	502392	***Spill Date:***	2014-11-25 11:30:00
DER Facility ID:	457358	***Received Date:***	2014-11-28 12:10:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2014-12-31 00:00:00
Water Body:		***Create Date:***	2014-11-28 12:12:00
Class:		***Update Date:***	2014-12-31 14:16:51.707000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	FXGALLEG

REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"cleanup pending - awaiting approval of report to DEC"

DEC Remark:

"12/1/14 FG SPOKE TO MAGGIE POPEK WITH LCS. SHE SAID THERE WAS ONLY 1 BOREHOLE WITH IMPACTS AT THE FORMER SERVICE STATION. SHE WILL PROVIDE THE REPORT OF FINDINGS WITHIN TWO WEEKS. 12/22/14 LCS SUBMITTED THE Geophysical Survey and Limited and Focused Subsurface Soil Investigation 1285 Main, LLC 1269-1285 Main Street Buffalo, New York. The purpose of this study was to assess the recognized environmental conditions identified during a review of previous studies for the subject property completed by others (LCS summary dated November 20, 2014) (specifically, former on-site printing and automotive repair operations and historic USTs and pumps). Select soil samples were collected from the areas of the recognized environmental conditions and submitted for laboratory analysis. In addition, a geophysical survey was completed over readily accessible exterior areas of the subject property to better assess if historic UST(s) remain on-site. Geophysical Survey Based on the results of the geophysical survey, several anomalies were identified in a small area Of the Main Street parking lot. Utilities were also identified. Subsurface Investigation Field Observations Based on the field observations, PID measurements were above total ambient air background VOC concentrations (i.e., 0.0 parts per million, ppm) in 4 of the 63 soil samples collected. All of the elevated PID measurements occurred in soil samples collected from BH4. These elevated concentrations ranged from 10.0 parts per million (ppm) to 53.8 ppm (BH4, ~4-6 ft. bgs). Suspect petroleum-type odors were detected and suspect petroleum-type staining was observed in the soil samples collected from BH4 at depths of ~4-10.5 ft. bgs. No suspect solvent-type staining was observed and no suspect solvent-type odors were detected in the soil samples collected. In LCS' experience, the PID measurements and field observations suggest the presence of some petroleum impact proximate to test boring BH4. Due to the discovery of petroleum impact, as required by law, the New York State Department of Environmental Conservation (NYSDEC) was notified and spill number 1408808 assigned to the site. Ms. Francine Gallego has been assigned to the site as the spill investigator. Laboratory Test Results Based on the laboratory results, the VOC 1,2,4-Trimethylbenzene was detected at a concentration above the Final Commissioner Policy-51 (CP-51) list Soil Cleanup Levels in the soil sample collected and submitted for analysis from BH4 (~4-6 ft. bgs). No other analytes were detected at concentrations above commonly applied regulatory criteria for commercial sites in the soil samples collected and submitted for analysis. 12/31/14 FG SPOKE TO MAGGIE POPEK WITH LCS. SHE SAID THAT THE ANOMALIES DISCOVERED ARE INACCESSIBLE. NO ANOMALY WAS FOUND NEAR BH4 WHERE PETROLEUM IMPACTS WERE IDENTIFIED. ONLY 1 ANALYTE EXCEEDED CP51. NO FURTHER WORK IS REQUIRED. THE SITE IS INACTIVE DUE TO THE EXCEEDANCE OF CP51. "

Material Information

OP Unit ID:	1251763	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2253712	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	HISTORIC - UNK
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	MAGGIE POLPAK
Contact Phone:	(800) 474-6802
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
81	1 of 2	ESE	0.32 / 1,708.41	654.15 / 10	DEMOLITION SITE 289 HIGH STREET BUFFALO NY	NY SPILLS

Spill No:	0275036	**UST Trust:**	False
Site ID:	73217	**Spill Date:**	2002-04-23 12:00:00
DER Facility ID:	68964	**Received Date:**	2002-04-23 13:50:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2002-04-23 00:00:00
Water Body:		**Create Date:**	2002-04-23 15:58:00
Class:	E5	**Update Date:**	2002-04-23 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	JFOTTO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DURING BUILDING DEMOLITION, TANKS WERE ENCOUNTERED. IT IS NOT KNOWN AT THIS TIME WHETHER OR NOT THERE IS ANY CONTAMINATION OR SPILLAGE."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 04/23/02: THIS SPILL IS A DUPLICATE OF SPILL #0275035. NO ACTION UNDER THIS SPILL NUMBER. REFER TO #0275035 FOR FOLLOW-UP. ******NO PAPER FILE FOR THIS SPILL******"

Material Information

OP Unit ID:	865419	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	510970	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	DENNIS SUTTON
Spiller Company:	CITY OF BUFFALO
Spiller Address:	304 CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-
Spiller Country:	001
Contact Name:	DENNIS SUTTON
Contact Phone:	(716) 851-6587
Contact Ext:	
Latitude:	42.900175580
Longitude:	-78.858226080

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
81	2 of 2	ESE	0.32 / 1,708.41	654.15 / 10	FORMER GAS STATION 289 HIGH STREET	LST

Spill No:	0275035	**REM Phase:**	0
Site ID:	73216	**UST Trust:**	True
DER Facility ID:	68964	**Spill Date:**	2002-04-23 13:06:00
CID:		**Rcvd Date:**	2002-04-23 13:06:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	2002-06-05 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	2002-08-30 00:00:00
Water Body:		**Create Date:**	2002-04-23 13:08:00
Class:	B3	**Update Date:**	2002-08-30 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	JFOTTO
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FOUND CONTAMINATION WHEN USTS WERE UNCOVERED FOR SAMPLING. 9 USTS INVLOVED."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 04/23/02 JFO REC'D FAX FROM FRANK BODAMI OF LEBIS ENTERPRISES. LEBIS IS THE CONTRACTOR FOR THE CITY OF BUFFALO. THEY WILL NOTIFY US WHEN IT IS DETERMINED WHEN THE 9 TANKS WILL BE REMOVED. 05/06/02 JFO REC'D FAX FROM DENNIS SUTTON OF CITY HALL WITH THE RESULTS FOR THE TANK SAMPLES. THE RESULTS INDICATE SEVERAL DIFFERENT PRODUCTS. (ie, gas, diesel, lub oil, hydraulic oil). ALSO RECEIVED A SKETCH OF THE SITE AND TANK LOCATIONS. 05/23/02 JFO ON SITE THE TANKS ARE OUT OF THE GROUND. THERE IS WATER IN THE BOTTOM OF THE EXCAVATION. NO SHEEN. 05/31/02 JFO ON SITE MET WITH DON G. THEY ARE REMOVING SOIL AND DISPOSING. SOIL IS DISCOLORED IN THE SOUTH SIDE OF THE EXCAVATION AND THE SOIL IS REMOVE ON THE EAST SIDE TO THE STREET. THEY WILL CONTINUE TO DIG TO THE SOUTH. I EXPLAINED WHERE TO SAMPLE THE PIT TO FRANK BODAMI OF LEBIS. 06/05/02 JFO ON SITE MET WITH FRANK B AND DON G. SAMPLE RESULTS INDICATE THE SITE CAN BE INACTIVE BECAUSE THE SOUTHEAST CORNER IS SLIGHTLY ABOVE TAGMS. THE CITY WANTS A CLEAN CLOSURE SO THEY WILL REMOVE MORE SOIL AND RESAMPLE. RESULTS AND RECEIPTS TO FOLLOW. 08/22/02 JFO CALL TO DON G OF THE CITY OF BUFFALO. HE WILL FORWARD DISPOSAL RECEIPTS. 08/24/02 JFO REC'D THE DISPOSAL RECEIPTS (85 PAGES) FOR THE SOIL. NEED THE SAMPLE RESULTS FOR THE AREA THAT WAS RESAMPLED AFTER MORE SOIL WAS REMOVED. DON G WAS NOTIFIED 08/27/02 JFO RECEIVED THE SAMPLE RESULTS. NO FURTHER ACTION REQUIRED. CLOSED "

Material Information

OP Unit ID:	865417	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	510967	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

OP Unit ID:	865417	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	510968	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OP Unit ID:	865417	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	510969	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	LARRY SCHIVONE
Spiller Company:	CITY OF BUFFALO
Spiller Address:	304 CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900175580
Longitude:	-78.858226080

82	1 of 1	W	0.33 / 1,745.61	668.03 / 24	KULBACK CONSTRUCTION DELAWARE AT NORTH BUFFALO NY	LST

Spill No:	9403219	**REM Phase:**	0
Site ID:	221515	**UST Trust:**	False
DER Facility ID:	183195	**Spill Date:**	1994-06-01 15:00:00
CID:		**Rcvd Date:**	1994-06-02 15:00:00
Program Type:	ER	**CAC Date:**	1994-10-04 00:00:00
SWIS Code:	1502	**Insp Date:**	1994-06-13 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1994-10-04 00:00:00
Water Body:		**Create Date:**	1994-06-06 00:00:00
Class:	E6	**Update Date:**	1994-10-07 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FOUND 1000 GALLON TANK WHILE EXCAVATING FOR BUILDING"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 06/13/94: RMC/BRAD MEYERS/SITE TANK ,8K, REMOVED, NO VISUAL CONTAMINATION FOUND, BUFFALO DRILLING TOOK SAMPLES, RESULTS DUE 7/15/94. 07/22/94: RMC/RESULTS LETTER, RESPONSE DUE 8/1/94. 10/04/94: RMC/RECEIVED TEST RESULTS, NO EXCEEDANCE, NO INDICATION OF SPILL ASSOCIATED W/ THIS TANK, CLOSE OUT. "

Material Information

OP Unit ID:	997012	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	570081	**Med SW:**	False
CAS No:		**Med DW:**	False

Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	KULBACK CONSTRUCTION
Spiller Address:	6363 TRANSIT ROAD
Spiller City:	DEPEW
Spiller State:	NY
Spiller Zip:	14043
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

---

83 | ***1 of 1*** | ***WSW*** | ***0.33 / 1,748.63*** | ***646.86 / 2*** | ***ROAD SIDE 82 NORTH PEARL BUFFALO NY*** | ***NY SPILLS***

Spill No:	1708175	**UST Trust:**	
Site ID:	564571	**Spill Date:**	2017-11-29 10:28:00
DER Facility ID:	518138	**Received Date:**	2017-11-29 10:42:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2017-11-29 00:00:00
Water Body:		**Create Date:**	2017-11-29 10:43:00
Class:	D4	**Update Date:**	2017-11-29 10:46:01.763000000
Meets Std:	True	**DEC Region:**	9
Penalty:		**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"2 gallon spill from garbage truck. Cleaned up with speedy dry. Disposal back into the truck."

DEC Remark:

"11/29/17 RMC/FILE. NO SPILL ACTION REQUIRED. CLOSE OUT."

Material Information

OP Unit ID:	1312513	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2319820	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	2.00	**Med Surf:**	True
Units:	G	**Med Subway:**	False
Recovered:	2.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Med Air: False
Material Code: 0010
Material Name: hydraulic oil

Spiller Information

Spiller Name:
Spiller Company: city of buffalo
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude:
Longitude:

---

84 | **1 of 1** | **SW** | **0.35 / 1,834.23** | **645.63 / 1** | **NATIONAL GRID COMMERCIAL**
72 NORTH PEARL ST
BUFFALO NY | **NY SPILLS**

Spill No: 2207913
Site ID: 647204
DER Facility ID: 593399
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 1
County: Erie
Contributing Factor: Storm
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2022-12-23 11:54:00
Received Date: 2022-12-23 11:58:00
CAC Date:
Insp Date:
Close Date:
Create Date: 2022-12-23 12:03:00
Update Date: 2022-12-28 08:20:36.330000000
DEC Region: 9
Lead DEC: FXGALLEG
After Hours: False

Caller Remark:

"Loose bushing causing transformer oil to leak up. Cleanup pending. Contained to soil but blowing around due to wind and snow."

DEC Remark:

"12/23/22 This is a minor spill. National Grid will clean this release when the weather improves. Lisa Montesano said she hired Clean Harbors to inspect and clean up the .15 gallon release of mineral oil. 12/28/22 National Grid provided an update on the site: Clean Harbors cleaned up this spill today since we had access to the area. Security team reported the cause of the release below. - 15 gallons were released. - The transformer is a very new unit (manufactured by NETS in 2022) and therefore, manufactured certified non-PCB. - Clean Harbors is cleaning up the area including the two sprayed cars, as long as the owners are agreeable to that. We will also offer the owners the ability to have a professional car wash and they can file a claim with National Grid for reimbursement. Clean Harbors will dispose of the cleanup debris as nonhazardous waste. As the weather warms up and the snow recedes, we will perform additional site reconnaissance to confirm no additional cleanup is required. National Grid Security report: A poletop transformer removed from this location was found to have a bullet lodged in the sidewall. • Photos of the transformer and location from which it was removed are attached. The bullet is located to the right of and adjacent to the text: “75”. I am uncertain as to whether the bullet wound occurred before or after the start of the blizzard, but it appears to be the only portion of the transformer that is compromised (no other weeping or leaking locations). • On 12/23/2022 our overhead line crew noted that this transformer was releasing non-PCB mineral oil and we reported a spill to NYSDEC. The spill impacted the ground and two parked cars adjacent to the pole. • Clean Harbors has custody of the transformer and will transport it to the Dewey Transformer Shop in the near future. They cleaned up the spill."

Material Information

OP Unit ID: 1394179
OU: 01
Material ID: 2409716

Med Ind Air: False
Med GW: False
Med SW: False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.15	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	72 NORTH PEARL ST
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA MONTESANO
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	
Longitude:	

85	1 of 2	NNW	0.35 / 1,864.38	654.35 / 10	SAINT VINCENT DEPAUL 1298 MAIN ST AT BRYANT BUFFALO NY	NY SPILLS

Spill No:	9603069	**UST Trust:**	False
Site ID:	281730	**Spill Date:**	1996-06-01 12:00:00
DER Facility ID:	228738	**Received Date:**	1996-06-04 10:00:00
CID:	351	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1996-06-05 00:00:00
Water Body:		**Create Date:**	1996-06-04 00:00:00
Class:	D5	**Update Date:**	1996-07-02 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	BRENNAN
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"former employee stated hundreds of gallons of paint poured down basement access way outside building. paint also dumped near drive way by building. both locations capped with cement. paint dumped after osha inspections 5-6 years ago-spill faxed from reg 9 6/4/96"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KAH 6/5/96 - KAH REFERRED COMPLAINT TO WALLY CAIN, BECI, FOR INVESTIGATION. NO FURTHER ACTION BY SPILLS NECESSARY."

Material Information

OP Unit ID:	1034359	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	349307	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	100.00	**Med Surf:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0055A		
Material Name:	paint		

Spiller Information

Spiller Name:	
Spiller Company:	JOHN AND THOMAS STORM
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	CALLER
Contact Phone:	
Contact Ext:	
Latitude:	42.908990993
Longitude:	-78.866832023

85	2 of 2	NNW	0.35 / 1,864.38	654.35 / 10	GARY LOWD PROPERTY 1298 MAIN STREET BUFFALO NY	NY SPILLS

Spill No:	9106713	**UST Trust:**	False
Site ID:	314597	**Spill Date:**	1991-09-21 13:10:00
DER Facility ID:	253642	**Received Date:**	1991-09-21 14:22:00
CID:		**CAC Date:**	1991-09-23 00:00:00
Program Type:	ER	**Insp Date:**	1991-09-23 00:00:00
SWIS Code:	1502	**Close Date:**	1991-09-23 00:00:00
Water Body:		**Create Date:**	2003-12-02 00:00:00
Class:		**Update Date:**	2003-12-02 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	SORGI
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Citizen		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"MR LOWD FOUND BOTTLE ON HIS PROPERTY. BOTTLE TAKEN TO POLICE STATION AT 1444 MAIN STREET. BROWN BOTTLE LABELED HAZARDOUS WASTE."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 09/23/91: MJS PICKED UP BOTTLE AT POLICE DEPT. LOOKS LIKE A SPECIALIZED BOTTLE. KEVIN GLASER INSPECTED LIQUID. PH 3-4. TOM CORBETT RECOGNIZED ODOR AS FORMALIN. DISPOSED OF IN REGULAR WASTE STREAM. 09/29/95: This is additional information about material spilled from the translation of the old spill file: HAZARDOUS WASTE."

Material Information

OP Unit ID:	957059	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	422397	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	***Update***
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.908996410
Longitude:	-78.866836570

---

86 | ***1 of 1*** | ***W*** | ***0.36 / 1,886.75*** | ***662.80 / 18*** | ***MEDICAL WASTE/UNITED FUND 742 DELAWARE AVENUE BUFFALO NY*** | ***NY SPILLS***

Spill No:	9710273	**UST Trust:**	False
Site ID:	287289	**Spill Date:**	1997-12-08 07:00:00
DER Facility ID:	232721	**Received Date:**	1997-12-08 09:00:00
CID:	999	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1997-12-10 00:00:00
Water Body:		**Create Date:**	1997-12-08 00:00:00
Class:	E6	**Update Date:**	1999-10-08 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"MEDICAL WASTE - GLOVES, EXTRACTED TEETH BEING DUMPED."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 12/8/97 NOTIFIED ERIE COUNTY HEALTH DEPT., KEN FARRELL, THEY WERE ALREADY AWARE OF THE COMPLAINT. NOTIFIED NYSDOH, C. O'CONNOR. NOTIFIED ECO'S WHO ACCORDING TO OUR PROTOCOL ARE TO HANDLE THE INSPECTION. 12/8/97 SPOKE TO CAPTAIN SCHULTZ WHO SAID AN ECO INSPECTED THE SITE AND FOUND THAT THE MATERIAL WAS NOT MEDICAL WASTE. THEY TOLD THE RP TO DISPOSE AS GARBAGE WITH NO FURTHER ACTION REQUIRED. 12/10/97 SPOKE TO KEN FARRELL WHO SAID THAT HE SPOKE TO UNITED WAY AND BASED ON THE ECO DIRECTION, THE MATERIAL WAS PLACED IN THE GARBAGE. 12/10/97 NO FURTHER WORK REQUIRED. SITE CAN BE CLOSED."

Material Information

OP Unit ID:	1056661	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	328583	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False

Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0051A		
Material Name:	garbage		

Spiller Information

Spiller Name:	
Spiller Company:	NONE
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	DENNIS WALKER
Contact Phone:	(716) 887-2654
Contact Ext:	
Latitude:	42.904639993
Longitude:	-78.871340023

---

87 **1 of 1** **SW** **0.36 / 1,888.96** **643.69 / -1** **COMMERCIAL 888 MAIN ST BUFFALO NY** ***NY SPILLS***

Spill No:	1704513	**UST Trust:**	False
Site ID:	556759	**Spill Date:**	2017-08-05 17:00:00
DER Facility ID:	510303	**Received Date:**	2017-08-05 20:41:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2017-08-15 00:00:00
Water Body:		**Create Date:**	2017-08-05 20:44:00
Class:		**Update Date:**	2017-08-15 14:11:14.677000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"the spill is contained in a man hole.The cleanup is in progress"

DEC Remark:

"8/5/17 FG spoke to Lisa Montesano with National Grid. She said they found an unknown oil in the manhole. They hired OpTech to vac out the oil. They collected a sample for analysis. They will properly dispose of the oil. 8/8/17 FG spoke to Lisa Montesano with National Grid. She said that the observation of the collected material from the manhole does not appear to be oil, only water. Ms. Montesano is having the material analyzed. 8/13/17 National Grid reports that the material is not oil. Hello Francine. Analytical results are attached for the sludges (and suspect oil layer) removed from this manhole. The lab could not identify “oil” in the samples we provided, and therefore the floating material must be another substance that exhibited an oily/musty odor. We apologize for incorrectly reporting the presence of an oil spill. Nevertheless, the sludges and floating material do not have PCB concentrations (ND), which is good news. OPTECH will dispose of the material as nonhazardous waste. Lisa L. Montesano Lead Environmental Engineer, Western Division NY Compliance nationalgrid 144 Kensington Avenue Buffalo, NY 14214 No further work is required. The spill site is closed."

Material Information

OP Unit ID:	1304792	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2311459	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Quantity:	50.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	888 MAIN ST
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA MONTESANO
Contact Phone:	7164795339
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
88	1 of 1	W	0.36 / 1,891.59	667.21 / 23	COMPUTER TASK GROUP 700 DELAWARE AVE BUFFALO NY	NY SPILLS

Spill No:	0507232	**UST Trust:**	False
Site ID:	352601	**Spill Date:**	2005-09-15 11:54:00
DER Facility ID:	299900	**Received Date:**	2005-09-15 11:54:00
CID:	444	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2006-02-01 00:00:00
Water Body:		**Create Date:**	2005-09-15 12:20:00
Class:	C3	**Update Date:**	2006-02-07 07:24:46.700000000
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"LOST ALL OIL OUT OF THEIR ELEVATOR; CALLED OTIS IN TO EVALUATE: THEY NEED TO REMOVE SAHFT ETC."

DEC Remark:

"9/15/05 FG SPOKE TO PAT OXENHOLM WITH CTG. SHE SAID THAT WHEN THE ELEVATOR GETS REPAIRED THEY WILL TAKE CARE OF THE SPILL. THE ELEVATOR IS NOT OPERATING AND YOU CAN'T SEE ANYTHING IN THE SHAFT. SHE WILL CONTACT US WHEN THE WORK WILL BEGIN. 01/31/06: MF T/C PAT OXENHOLM. WORK COMPLETED MONTHS AGO BY SCHENDLER ELEVATOR OF WILLIAMSVILLE, CONTACT CARL KRUG, SCHENDLER ELEVATOR, 632-1463 x 31. T/C CARL KRUG, HE WILL FAX DISPOSAL INFORMATION. MODERN DID VACCING & DISPOSAL. ELEVATOR HAS BEEN REPAIRED & IS BACK IN OPERATION. 02/01/06: MF RECEIVED DISPOSAL INFORMATION FROM MODERN. NO FURTHER ACTION NECESSARY."

Spiller Information

Spiller Name:	KATHY OXENHOLM
Spiller Company:	COMPUTER TASK GROUP
Spiller Address:	700 DELEWARE AVE
Spiller City:	BUFFALO
Spiller State:	NY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Zip:
Spiller Country: 001
Contact Name: KATHY OXENHOLM
Contact Phone: (716) 887-7390
Contact Ext:
Latitude: 42.903321525
Longitude: -78.873426827

---

89 | **1 of 1** | **WNW** | **0.36 / 1,924.29** | **660.89 / 16** | **AMERICAN RED CROSS TANK**
786 DELAWARE AVENUE
BUFFALO NY | **LST**

Spill No: 9404334
Site ID: 141275
DER Facility ID: 120650
CID:
Program Type: ER
SWIS Code: 1502
Contribute Factor: Tank Test Failure
Water Body:
Class: C3
Meets Std: True
Penalty: False
County: Erie
Referred to:
Reported by: Tank Tester
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

REM Phase: 0
UST Trust: False
Spill Date: 1994-06-28 11:20:00
Rcvd Date: 1994-06-28 11:30:00
CAC Date:
Insp Date: 1994-06-28 00:00:00
Close Date: 1995-12-12 00:00:00
Create Date: 1994-06-28 00:00:00
Update Date: 1996-01-05 00:00:00
DEC Region: 9
Lead DEC: SORGI
After Hours: False

Caller Remark:

"TANK TEST FAILURE. TANK IN GARAGE IN CONCRETE VAULT."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 06/28/94: MJS TELECON W/ DENNIS CANNON. HE IS HIRING CONTRACTOR TO PLACE ALTERNATE TANK AND PUMP OUT LEAKING TANK. CONCRETE VAULT IS CONTAINING RELEASED PRODUCT. 06/28/94: MJS SITE INSPECT. MET W/ MR CANNON. TANKNOLOGY INC ON SITE. TANK IS APPROX 400 GALLONS AND ON SADDLES. SMALL AMOUNT OF PRODUCT ON BOTTOM OF VAULT. TANK MUST BE REMOVED. NO SAMPLE RESULTS REQUIRED. 05/25/95: MJS REVIEW FILE. NO INFO ON REMOVAL. LETTER TO RP REQUESTING UPDATE. 09/22/95: MJS TELECON FROM MIKE DAGGETT(RED CROSS). HE REPLACED MR CANNON AND IS RESPONDING TO 5/25/95 LETTER REGARDING UPDATE ON CLEANUP. TANK WAS REPLACED. HE WILL SEARCH FOR DOCUMENTATION AND DISPOSAL RECEIPT. 11/10/95: MJS TELECON TO MR DAGGETT AND LEFT MESSAGE FOR HIM TO CALL. 11/14/95: MJS TELECON FROM MR DAGGETT. HE HAS SPOKEN WITH ELMWOOD TANK AND PIPING AND FOUND THAT ONLY SMALL QUANTITY OF CONTAMINATED DEBRIS GENERATED AND DISPOSED IN REGULAR WASTE STREAM. 11/16/95: MJS TELECON WITH JOE KLOC FROM ELMWOOD. HE CONFIRMED ONLY MINOR QUANTITY GENERATED. 12/12/95: MJS REVIEW FILE. NO RECEIPTS REQUIRED. NO FURTHER ACTION NECESSARY. MJS CLOSE FILE. "

Material Information

OP Unit ID: 1001406
OU: 01
Material ID: 380946
CAS No:
Material Family: Petroleum
Quantity: .00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0001A
Material Name: #2 fuel oil

Med in Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: MIKE DAGGETT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Company:	AMERICAN RED CROSS
Spiller Address:	786 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14209-
Spiller Country:	001
Contact Name:	MIKE DAGGETT
Contact Phone:	(716) 886-7500
Contact Ext:	
Latitude:	42.905456460
Longitude:	-78.872200000

Tank Test Information

Spill Tank ID:	1542909	**Source:**	
Tank No:		**Leak Rate:**	.00
Tank SIze:	400	**Gross Fail:**	F
Material:	0001	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	14
Cause:			
Alt Test Method:	VacuTest		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
90	1 of 1	S	0.37 / 1,939.69	634.78 / -10	ROSWELL PARKING RAMP ELM & VIRGINIA STREETS BUFFALO NY	NY SPILLS

Spill No:	9108647	**UST Trust:**	False
Site ID:	160321	**Spill Date:**	1991-11-13 12:00:00
DER Facility ID:	135393	**Received Date:**	1991-11-14 12:20:00
CID:		**CAC Date:**	1992-01-03 00:00:00
Program Type:	ER	**Insp Date:**	1992-01-03 00:00:00
SWIS Code:	1502	**Close Date:**	1992-01-03 00:00:00
Water Body:		**Create Date:**	1991-11-22 00:00:00
Class:		**Update Date:**	1992-01-30 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HYDRAULIC OIL SPILL ON PAVED AREA & SIDEWALK OUTSIDE ON SOUTH SIDE OF PARKING RAMP."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 11/20/91: 11/20/91 MNP INSP. SPEEDY DRY ON SPILL AREA, BUT MORE CLEANUP NEEDED. SPILLER AGREED TO COMPLETE CLEANUP. 01/03/92: 1/3/92 MNP & RNL INSP. MOST OF SPILL CLEANED UP, NO MORE CLEANUP REQURED, COMPLETE. "

Material Information

OP Unit ID:	958935	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	420777	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False

Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		
OP Unit ID:	958935	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	420776	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	
Spiller Company:	RESTORATION EAST, INC.
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.896946953
Longitude:	-78.865525916

91	**1 of 1**	**SSW**	**0.37 / 1,977.40**	**638.51 / -6**	**GREYHOUND ELLICOTT & OAK STREETS BUFFALO NY**	**LST**

Spill No:	8912297	**REM Phase:**	0
Site ID:	279141	**UST Trust:**	False
DER Facility ID:	226663	**Spill Date:**	1990-03-27 09:45:00
CID:		**Rcvd Date:**	1990-03-27 09:50:00
Program Type:	ER	**CAC Date:**	1990-03-29 00:00:00
SWIS Code:	1502	**Insp Date:**	1990-03-29 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	1990-03-29 00:00:00
Water Body:		**Create Date:**	1990-03-27 00:00:00
Class:		**Update Date:**	1990-04-02 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FIX
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Citizen		
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BUS LEAKED DIESEL WHEN PULLING OUT FROM STATION,PROBABLY OVERFILLED, CITIZEN MAY BE A STRIKING EMPLOYEE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CAF 03/27/90: CAF SITE VISIT-FOUND SPILL AND INSTRUCTED SUPERVISOR HOW CLEANUP ANDDISPOSAL OF MATERIALS SHOULD BE HANDELED. 03/29/90: CAF SITE VISIT-CLEANUP COMPLETED,NO FURTHER ACTION PLANNED. "

Material Information

OP Unit ID:	937993	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	441767	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	10.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	GREYHOUND
Spiller Address:	181 ELLICOTT STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.897046000
Longitude:	-78.868305918

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
92	1 of 1	NNE	0.38 / 1,998.39	642.04 / -2	ROADSIDE 65 RILEY @ HOLLAND BUFFALO NY	NY SPILLS

Spill No:	0375482	**UST Trust:**	False
Site ID:	186134	**Spill Date:**	2004-02-26 13:51:00
DER Facility ID:	155617	**Received Date:**	2004-02-26 13:52:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	2004-05-24 00:00:00
SWIS Code:	1502	**Close Date:**	2004-12-13 00:00:00
Water Body:		**Create Date:**	2004-02-26 13:53:00
Class:	E6	**Update Date:**	2004-12-13 06:49:37.607000000
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RJJONAK
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"nfg uncovered ust while doning install. they rerouted their line. hole still open"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 2/26/2004: RJJ AT SITE AT 1450...IN FRONT OF 65 RILEY ST.,NATIONAL FUEL UNCOVERED AN UST NEXT TO THE BUILDING...IT APPEARS TO BE AN OLD SMALL FUEL OIL TANK,ABOUT 55 GAL,AND DOES NOT APPEAR TO BE LEAKING...I CONTACTED THE OWNER OF THE PROPERTY,THOMAS WALKER,AND TOLD HIM ABOUT THIS...HE WILL HIRE SOMEONE TO REMOVE THE UST AND KEEP ME INFORMED...PBS,AES,DRAFTED AND SEND THEIR TANK REMOVAL FORM...AT THIS TIME, THERE IS NO EVIDENCE OF ANY SPILL. 5/21/2004: RJJ LEFT MESSAGE FOR MR. WALKER TO CALL ME BACK. 5/24/2004: RJJ AT SITE AT 0230...THE TANK,(55 GAL FUEL OIL TANK) HAS BEEN REMOVED AND THERE IS NO EVIDENCE OF ANY SPILL. 8/10/2004: MR. WALKER TELECON RJJ,HE SAID THAT HE HAS SCRAPED THE TANK AND HE WILL SEND ME THE DISPOSAL RECEIPT. 12/13/2004: RECEIVED THE BILL OF LADING FOR THE FUEL OIL TANK WHICH WAS SCRAPED...THE TANK HAS BEEN REMOVED AND WAS INTACT AND NOT LEAKING... SINCE THERE WAS NO EVIDENCE OF ANY SPILL,NO FURTHER ACTION IS NEEDED...SPILL CLOSED OUT."

Material Information

OP Unit ID:	882292	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	494665	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	THOMAS WALKER
Spiller Company:	THOMAS WALKER
Spiller Address:	1255 EAST FERRY ST.
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14211-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.909457993
Longitude:	-78.864073023

93	***1 of 1***	***ESE***	***0.38 / 2,008.70***	***658.88 / 14***	***SOIL 215 PEACH ST BUFFALO NY***	***NY SPILLS***

Spill No:	2007371	***UST Trust:***	False
Site ID:	613260	***Spill Date:***	2020-11-16 13:40:00
DER Facility ID:	561281	***Received Date:***	2020-11-16 14:08:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2020-11-17 00:00:00
Water Body:		***Create Date:***	2020-11-16 14:09:00
Class:		***Update Date:***	2020-11-17 10:44:43.107000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	TDJOHNSO
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Storm		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"clean up is pending"

DEC Remark:

"11/17/20 TDJ MINOR SPILL OF APPROX. 1 GALLON OF MINERAL OIL CLEANED BY CONTRACTOR. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1360382	***Med Ind Air:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU:	01	**Med GW:**	False
Material ID:	2372358	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	2630		
Material Name:	mineral oil		

Spiller Information

Spiller Name:	J GIFT
Spiller Company:	NATIONAL GRID
Spiller Address:	215 PEACH ST
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	J GIFT
Contact Phone:	(716) 398-5308
Contact Ext:	
Latitude:	
Longitude:	

---

94 *1 of 3* *WSW* *0.38 / 2,019.95* *655.80 / 11* ***HOLIDAY INN 620 DELAWARE AVENUE BUFFALO NY*** ***NY SPILLS***

Spill No:	8806417	**UST Trust:**	False
Site ID:	140283	**Spill Date:**	1988-10-31 10:00:00
DER Facility ID:	119798	**Received Date:**	1988-10-31 12:30:00
CID:		**CAC Date:**	1988-11-04 00:00:00
Program Type:	ER	**Insp Date:**	1988-11-04 00:00:00
SWIS Code:	1502	**Close Date:**	1988-11-04 00:00:00
Water Body:		**Create Date:**	1988-11-01 00:00:00
Class:		**Update Date:**	1988-11-21 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	DEC		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SPILL NOTICED IN DRIVEWAY OF HOLIDAY INN BY DUMPSTER."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 10/31/88: MF 1400 AREA STILL NOT CLEANED. TELECON MR. LEISTNER (MANAGER). TOLD HIM IF IT WASN'T CLEANED ASAP THE STATE WILL HIRE A CONTRACTOR TO CLEAN. HE CLAIMED IT WILL BE CLEANED. 10/31/88: MF TELECON PAUL SZCZESEK, HE CLAIMED AMHERST DISPOSAL TRUCK BROKE HOSE, AND SPILL HAS BEEN CLEANED. I TOLD HIM THERE WAS MORE CLEANUP TO BE DONE & HE CLAIMED IT WILL BE DONE ASAP. 1230. 11/01/88: MF TELECON MR. LEISTNER HE CLAIMED THE SPEEDI DRI WILL BE REMOVED TODAY. 11/04/88: MF LETTER SENT TO SPILLER ALSO SPILL CLEANED. NO FUTHER ACTION NECESSARY. "

Material Information

OP Unit ID:	923243	**Med Ind Air:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OU:	01	**Med GW:**	False
Material ID:	454757	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	4.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	
Spiller Company:	AMHERST DISPOSAL
Spiller Address:	938 MAPLE ROAD
Spiller City:	WILLIAMSVILLE
Spiller State:	NY
Spiller Zip:	14221
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901162300
Longitude:	-78.873510720

94	2 of 3	WSW	0.38 / 2,019.95	655.80 / 11	TOUR BUS 620 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No:	8704229	**UST Trust:**	False
Site ID:	140282	**Spill Date:**	1987-08-21 08:00:00
DER Facility ID:	119798	**Received Date:**	1987-08-21 08:00:00
CID:		**CAC Date:**	1987-08-24 00:00:00
Program Type:	ER	**Insp Date:**	1987-08-24 00:00:00
SWIS Code:	1502	**Close Date:**	1987-08-24 00:00:00
Water Body:		**Create Date:**	1987-08-25 00:00:00
Class:		**Update Date:**	1987-09-01 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	DEC		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DIESEL FUEL LEAKING FROM BUS, TENNESSEE LIC. # MUS-030"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : 8/21/87 MNP & MJH INSP. NO CLEANUP BY SPILLER;8/24/87 NO CLEANUP POSSIBLE, COMPLETE. "

Material Information

OP Unit ID:	910710	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	466874	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Quantity:	2.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	DON ARKON
Spiller Address:	
Spiller City:	TENNESSEE
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901162300
Longitude:	-78.873510720

94	***3 of 3***	***WSW***	***0.38 / 2,019.95***	***655.80 / 11***	***AMHERST DISPOSAL 620 DELAWARE AVENUE BUFFALO NY***	***NY SPILLS***

Spill No:	8703944	**UST Trust:**	False
Site ID:	140281	**Spill Date:**	1987-08-12 07:00:00
DER Facility ID:	119798	**Received Date:**	1987-08-12 11:30:00
CID:		**CAC Date:**	1987-09-30 00:00:00
Program Type:	ER	**Insp Date:**	1987-09-30 00:00:00
SWIS Code:	1502	**Close Date:**	1987-09-30 00:00:00
Water Body:		**Create Date:**	1987-08-12 00:00:00
Class:		**Update Date:**	1987-10-02 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	DEC		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HYDRAULIC OIL FROM GARBAGE TRUCK SPILLED BETWEEN HOLIDAY INN & DEC OFFICE"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : MNP SITE INSP. 08/12/87, DEC PLACED SPEEDI-DRY PLACED ON SPILL; RNL TELECON 08/12/87, AMHERST DISPOSAL TO CHECK ON TRUCK, CALL BACK. / / : 8/24/87 MNP INSP. SPEEDY DRY REMAINS BY REAR DUMPSTER AREA OF HOLIDAY INN;MILLER TO BE CONTACTED. / / : 8/27/87 MNP TELECON W/MILLER, AGREED TO CLEANUP REMAINING SPEEDY DRY;9/30/87 MNP INSP. CLEANUP IN BOTH SPILL AREAS SATISFACTORY, COMPLETE. "

Material Information

OP Unit ID:	907830	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	470152	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Recovered: 5.00
Med Soil: True
Med Air: False
Material Code: 0022
Material Name: waste oil/used oil
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: AMHERST DISPOSAL
Spiller Address:
Spiller City: AMHERST
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.901162300
Longitude: -78.873510720

---

95 | ***1 of 1*** | ***SSW*** | ***0.39 / 2,047.16*** | ***637.77 / -7*** | ***Ellicott and Oak Streets Site 324, 328, and 334 North Oak St and 441 Ellicott St Bufalo NY 14203*** | ***BROWNFIELDS***

Site Code: 608889
HW Code: C915366
Program: BCP
Site Class: A
Site Name: Ellicott and Oak Streets Site
Site Address: 324, 328, and 334 North Oak St and 441 Ellicott St
City: Bufalo
Zip: 14203
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.890622222
Longitude: -78.869625000
SWIS: 1502
Acres: 1.269
Record Added: 2020-07-22 12:11:00
Record Update: 2022-08-22 09:37:00
Updated by: AECAPRIO
Site Code (Web): C915366
Program Type (Web): BCP
Site Name (Web): Ellicott and Oak Streets Site
Site Class (Web): A
Address1 (Web): 324, 328, and 334 North Oak St and 441 Ellicott St
Address2 (Web):
Locality (Web): Bufalo
Zip Code (Web): 14203
County (Web): Erie
Longitude (Web): -78.869625000
Latitude (Web): 42.890622222
Site Code (GIS): C915366
Site Name (GIS): Ellicott and Oak Streets Site
Program (GIS): BCP
Site Class (GIS): A
Address1 (GIS): 324, 328, and 334 North Oak St and 441 Ellicott St
Address2 (GIS):
Locality (GIS): Bufalo
Zip Code (GIS): 14203
County (GIS): Erie
Site Class Desc:
Site Class Desc (Web): Active: The classification assigned to a non-registry site in any remedial program where work is underway and not yet complete (i. e., Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program

and RCRA Corrective action Program sites). This may be used for Manufactured Gas Plant sites or those being remediated under an EPA Cooperative Agreement.

Assess DOH: Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.

Description:

Location: The Ellicott and Oak Streets site is an approximately 1.269-acre site located in a highly developed commercial and residential area at 324, 328 and 334 North Oak Street and 441 Ellicott Street in the City of Buffalo, Erie County. The site is bordered by commercial properties to the north and south, Ellicott Street to the west, and North Oak Street to the east. Site Features: The site is developed with three buildings. Building 2 at 441 Ellicott Street is 9,348 square feet, Building 3 at 328 North Oak Street is 6,854 square feet and Building 4 at 324 North Oak Street is 10,800 square feet. Building 1, located at 334 North Oak, was demolished in June 2022. Portions of the site that are not covered by buildings are currently vacant land that are either covered by asphalt paving, gravel, or vegetation. Zoning and Land Use: The site is zoned N-1C, mixed-use core and is currently used for equipment storage and a wholesale flower market. Several areas of the site are currently unoccupied. Proposed redevelopment includes a new residential structure at 334 North Oak Street. Past Use of the Site: The site was used for residential, commercial, and light industrial purposes from at least 1889 to the present. From at least 1889 until 1899, the southern portion of the site was occupied by a carpenter shop, elevators, a mill, flour storage, and warehousing and the northern portion was occupied by a furniture factory, residential properties, storefronts and saloons. From approximately 1925 to 1986, various operations utilized the southern portion of the site, including John Kamman Cold Storage, L.C. Wilson Packing Corporation, and Hygrade Food Products Corporation, and an auto storage and ignition service/garage existed on the northern portion of the site. An associated former gasoline tank is understood to have existed between 338 and 340 North Oak Street. Other operations at this time included furniture storage, a mattress manufacturer, two sausage factories, a restaurant, a printing operation, a pants manufacturer, at least two florists, and a wholesale radio and a television parts company. Stores, residences, and an office were also noted at the site during this time. A previous Phase II Environmental Investigation identified polycyclic aromatic hydrocarbons (PAHs) and metals in the soil/fill across the site. Site Geology and Hydrogeology: The site is located within the Erie-Ontario Lowlands, which is typified by little topographic relief, and gently slopes westward towards Lake Erie, except in the immediate vicinity of major drainage ways. The surficial geology of the Erie-Ontario Lowlands has developed from lacustrine deposits or till that may contain both limestone and shale. The overburden geology is generally described as urban fill consisting of cinders, ash, slag, wood, asphalt, concrete, glass, plastic, brick, metal, paint cans, and metal piping from the ground surface to depths ranging from 2 to 5 feet below ground surface (fbgs). Sandy lean clay was observed underlying the fill materials along the south end of the site and fine sand was observed underlying the fill along the north end. Subangular gravel was observed overlying the fill at the north end, and topsoil was observed in the southwestern portion of the site. Bedrock is comprised of a varying texture from coarse to very finely crystalline with a dark gray to tan color and chert and fossils within. The unit has an approximate thickness of 110 to 160 feet. Regional and local groundwater likely flows west towards Lake Erie. Local groundwater flow however may be influenced by subsurface features such as excavations, utilities, and localized fill conditions.

Assessment:

Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name: April Tompkins
Owner Company: Buffalo & Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Frank Chinnici
Owner Company: Main Gateway, L.P.
Owner Street: 810 Main Street
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14202
Country: United States of America

Owner Op: 01
Sub Type: P03
Owner Name: Frank Chinnici
Owner Company: Main Gateway, L.P.
Owner Street: 810 Main Street
Owner Street 2:
Owner City: Buffalo

Owner State: NY
Owner Zip: 14202
Country: United States of America

Environmental Remediation

Operable Unit: 01
Contaminants:

---

96 | **1 of 1** | **WSW** | **0.39 / 2,055.99** | **644.07 / 0** | **TRI-GRAPHICS 78 ALLEN OR 99 VIRGINIA BUFFALO NY** | **NY SPILLS**

Spill No:	0275050	**UST Trust:**	False
Site ID:	73746	**Spill Date:**	2002-04-01 12:00:00
DER Facility ID:	69381	**Received Date:**	2002-05-01 10:15:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2002-05-17 00:00:00
Water Body:		**Create Date:**	2002-05-01 10:24:00
Class:	D6	**Update Date:**	2003-10-30 00:00:00
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Gasoline Station or other PBS Facility
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"PHASE II SITE ASSESSMENT DONE BY DAY ENVIRONMENTAL SHOWS GROUNDWATER CONTAMINATION."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 05/15/02: MF RECEIVED 3/02 PHASE 2 REPORT DONE BY SLC. 9 TEST BORINGS ADVANCED ALONG VIRGINIA(6) & ALLEN(3) STS ALONG SIDE TRI-GRAPHICS BUILDING TO REFUSAL. VERY LOW PID READINGS, 1.8 PPM HIGHEST. BORINGS 4, 5 & 9 SAMPLED, ALL 8021 DIRECT PARAMETERS BDL, DL AT 10 PPB. 2 MW'S SAMPLED, HIGHEST PARAMETER, TOLUENE IN MW#2, 6.19 PPB & MTBE AT 15 PPB. 8260 NO DONE ON THE WATER SO ITS POSSIBLE MTBE IS A FALSE POSITIVE. BASED ON RADAR SURVEY, NO UST'S DETECTED. NOTHING IN THE REPORT TO REQUIRE ADDITIONAL INVESTIGATION. WILL MAKE SPILL 'I', DUE TO GW VIOLATIONS. NO FURTHER ACTION NECESSARY. LETTER SENT."

Material Information

OP Unit ID:	867800	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	510984	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 0009
Material Name: gasoline

Spiller Information

Spiller Name: LARRY GROHMAN
Spiller Company: TRI-GRAPHICS
Spiller Address: 99 VIRGINIA PLACE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-
Spiller Country:	001
Contact Name:	TOM HEWNER
Contact Phone:	(716) 856-3646
Contact Ext:	
Latitude:	42.899355907
Longitude:	-78.872810873

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
97	1 of 1	SSW	0.39 / 2,059.77	637.77 / -7	ROSWELL PARK CANER INSTIT VIRGINIA ST/ELLICOTT ST BUFFALO NY	NY SPILLS

Spill No:	0207429	**UST Trust:**	False
Site ID:	229572	**Spill Date:**	2002-10-10 12:00:00
DER Facility ID:	189247	**Received Date:**	2002-10-18 10:07:00
CID:	396	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2002-11-22 00:00:00
Water Body:		**Create Date:**	2002-10-18 00:00:00
Class:	E5	**Update Date:**	2003-10-08 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"soil samples were taken on 10/10 and 10/11 results back today show contamination...belives material may be decaying fuel oil. 30 to 40 years ago there were houses on the site. req call back."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 10/31/02: MF ASSIGNED SPILL. T/C DOUG HURLBUT, CME. THEY FOUND POSSIBLE CONTAMINATION AT 3 LOCATIONS. STV IS ENV CONSULTANT OUT OF NYC. THEY DID 10 TEST PITS 10/23/02, ANISTASI DID WORK. BURNT WOOD FOUND ALONG DECAYED F/O AT THE NE CORNER OF VIRGINA & ELLICOTT, OWNED BY ROSWELL, 8021 & 8270 BN'S ANALYTICAL DONE. WORKING WITH MICHELLE PARIS OF THE DORMITORY AUTHORITY IS THE CONTACT. 716-845-5758. STV INC REBECCA TUMMON, 212-505-4908.. JOHN GAVRAS IS ALSO WITH STV. OLD SANDBORNE MAP SHOWED RESIDENTIAL AREA. 11/05/02: MF T/C REBECCA, 8260, 3 VOC BELOW TAGM & STARS, 8270'S MIN DETECTION LIMIT 2 PPM. NOTHING ABOVE TAGM. 11/21/02: MF RECEIVED 11/18/02 REPORT WITH SAMPLE TAKEN FROM TP-9 (2.5-4' BG) AT THE AREA OF THE HIGHEST PID READING OF 70 PPB, RESULTS 8021, BELOW STARS & 8270 BN'S BDL'S. FO #2 DETECTED BY 310-13 AT 250 PPM. 26 BORINGS ADVANCED & SCREENED WITH PID. BASED ON DATA IN REPORT SPILL CAN BE 'C'. LETTER SENT. 12/20/02: MF CLOSURE LETTER NEVER RECEIVED. I DO NOT HAVE A FILE COPY. ANOTHER LETTER SENT. 10/08/03: MF T/C MICHELLE WHITMAN, GZA. THEY REMOVED SOIL IN THE SPILL AREA. APPX 500 TONS DUE TO ODOR. FIELD CONTACT KEN ABRAM, 570-7906."

Material Information

OP Unit ID:	860248	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	518018	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spiller Information

Spiller Name:	MICHELLE PARIS
Spiller Company:	NASNY C/O ROSWELL PARK
Spiller Address:	ELM & CARLTON STS
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14263-
Spiller Country:	001
Contact Name:	DOUGLAS HURLBUT
Contact Phone:	(315) 668-3868
Contact Ext:	
Latitude:	
Longitude:	

98	*1 of 1*	*ENE*	*0.39 / 2,069.26*	*656.89 / 12*	***LEAKING FIRE DEPT VEHICLE 289 DODGE BUFFALO NY***	***NY SPILLS***

Spill No:	1503811	***UST Trust:***	
Site ID:	510129	***Spill Date:***	2015-07-09 08:11:00
DER Facility ID:	464720	***Received Date:***	2015-07-09 08:35:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2015-07-09 00:00:00
Water Body:		***Create Date:***	2015-07-09 08:43:00
Class:	D4	***Update Date:***	2015-07-09 08:46:56.763000000
Meets Std:	False	***DEC Region:***	9
Penalty:		***Lead DEC:***	FXGALLEG
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Fire Department		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"hi lift broke a hydraulic line leaking 3 gallons. Fire Depat cleaned it up and disposed of debris."

DEC Remark:

"7/9/15 THE SPILL WAS CLEANED UP BY THE FIRE DEPT AND THE DEBRIS WAS PROPERLY DISPOSED. MINOR SPILL. CLOSED. ELECTRONIC FILE ONLY."

Material Information

OP Unit ID:	1259401	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2262699	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	3.00	***Med Surf:***	True
Units:	G	***Med Subway:***	False
Recovered:	3.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spill Data

Material Name:	hydraulic oil
Material Family:	Petroleum

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Quantity: 3
Units: Gallons
Recovered: 3

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
99	1 of 1	SSE	0.39 / 2,069.66	628.86 / -16	POLE #152 MULBERRY & VIRGINIA BUFFALO NY	NY SPILLS

Spill No: 0711466
Site ID: 392953
DER Facility ID: 342546
CID: 444
Program Type: ER
SWIS Code: 1502
Water Body:
Class: C3
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Other
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 2008-01-31 08:30:00
Received Date: 2008-01-31 08:51:00
CAC Date:
Insp Date: 2008-01-31 00:00:00
Close Date: 2008-03-14 00:00:00
Create Date: 2008-01-31 09:10:00
Update Date: 2008-03-19 10:52:09.387000000
DEC Region: 9
Lead DEC: jfotto
After Hours: False

Caller Remark:

"STORM RELATED AND CREW ENROUTE"

DEC Remark:

"01/31/08 JFO ON SITE, CREW STILL WORKING ON SITE. WILL INSP TOMORROW. 02/01/08 JFO ON SITE NOA. SPILL IS CLEANED UP. RECEIPTS TO FOLLOW. 03/14/08 JFO RECEIVED THE DISPOSAL RECEIPTS. NO FURTHER ACTION REQUIRED. CLOSED"

Material Information

OP Unit ID: 1149929
OU: 01
Material ID: 2140491
CAS No:
Material Family: Petroleum
Quantity: 30.00
Units: G
Recovered: .00
Med Soil: True
Med Air: False
Material Code: 0020A
Material Name: transformer oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: LISA MONTSANO
Spiller Company: POLE #152
Spiller Address: MULBERRY & VIRGINIA
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name: LISA MONTSANO
Contact Phone: (716) 479-5339
Contact Ext:
Latitude: 42.896727953
Longitude: -78.862142950

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
100	1 of 1	NW	0.39 / 2,072.55	658.65 / 14	CONCRETE 888 DELAWARE AVE BUFFALO NY	NY SPILLS

Spill No:	2105781	**UST Trust:**	False
Site ID:	624646	**Spill Date:**	2021-09-17 08:53:00
DER Facility ID:	571880	**Received Date:**	2021-09-17 08:53:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2021-09-17 00:00:00
Water Body:		**Create Date:**	2021-09-17 08:54:00
Class:		**Update Date:**	2021-09-17 10:29:57.293000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Transformer		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"non pcb clean up pending"

DEC Remark:

"09/17/21 TDJ MINOR SPILL CLEANED BY CONTRACTOR NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1371789	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2384993	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	2630		
Material Name:	mineral oil		

Spiller Information

Spiller Name:	LISA
Spiller Company:	NATIONAL GRID
Spiller Address:	888 DELAWARE AVE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
101	1 of 9	WSW	0.40 / 2,111.59	651.21 / 7	BENDERSON #2 600 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	8910055	**UST Trust:**	True
Site ID:	169889	**Spill Date:**	1990-01-01 12:00:00
DER Facility ID:	142956	**Received Date:**	1990-01-02 12:00:00
CID:		**CAC Date:**	1990-03-07 00:00:00
Program Type:	ER	**Insp Date:**	1990-02-28 00:00:00
SWIS Code:	1502	**Close Date:**	1990-03-07 00:00:00
Water Body:		**Create Date:**	1990-01-19 00:00:00
Class:		**Update Date:**	1990-03-08 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	DEC		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"GASOLINE DISPENSER LEAKS WHEN UNDER PRESSURE. PADS IN PLACE."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 01/19/90: MF TELECON BENDERSON, TO RETURN CALL. 02/28/90: MF 2/2/90 TELECON RENO (BENDERSON), HE CLAIMED HE WILL SEND ME REPAIR INVOICE. 02/28/90: MF 2/28/90 INSPECTED DISPENSOR, NEW UNIT IN PLACE, NO LEAKS NOTICED. NO REPORT FROM BENDERSON. 03/07/90: MF RECEIVED REPAIR BILL FROM BENDERSON. NO FUTHER WORK NECESSARY ON THIS SPILL. "

Material Information

OP Unit ID:	937070	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	443181	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	BENDERSON DEVELOPMENT
Spiller Address:	570 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

101	*2 of 9*	*WSW*	*0.40 / 2,111.59*	*651.21 / 7*	***NYSDEC - BUFFALO GAS PUMP 600 DELAWARE AVENUE BUFFALO NY***	***NY SPILLS***

Spill No:	9004957	**UST Trust:**	False
Site ID:	169892	**Spill Date:**	1990-08-03 14:15:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DER Facility ID:	142956	**Received Date:**	1990-08-03 14:25:00
CID:		**CAC Date:**	1990-08-06 00:00:00
Program Type:	ER	**Insp Date:**	1990-08-06 00:00:00
SWIS Code:	1502	**Close Date:**	1990-08-06 00:00:00
Water Body:		**Create Date:**	1990-08-07 00:00:00
Class:		**Update Date:**	1990-12-04 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Citizen		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"NOZZLE DID NOT SHUT OFF WHILE NYSDEC EMPLOYEE WAS FUELING STATE VEHICLE"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 08/06/90: 8/6/90 MNP INSP. SPEEDY DRY PICKED UP & DISPOSED, I PUT GASOLINE SOAKED SORBENT PADS IN DUMPSTER. NO FURTHER ACTION NEEDED, COMPLETE. "

Material Information

OP Unit ID:	942608	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	436030	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	15.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	15.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	NYSDEC
Spiller Address:	600 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
101	3 of 9	WSW	0.40 / 2,111.59	651.21 / 7	ARMBRUST GASOLINE SPILL 600 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No:	8912037	**UST Trust:**	True
Site ID:	169890	**Spill Date:**	1990-03-20 09:00:00
DER Facility ID:	142956	**Received Date:**	1990-03-20 09:05:00
CID:		**CAC Date:**	1990-03-20 00:00:00
Program Type:	ER	**Insp Date:**	1990-03-20 00:00:00
SWIS Code:	1502	**Close Date:**	1990-03-20 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Body:		**Create Date:**	1990-03-20 00:00:00
Class:		**Update Date:**	1990-03-26 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	ROSS
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OVER FILL TANK ON VEHICLE"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR 03/20/90: LQR AND CAF SPILL UNIT SPREAD SPEEDY DRY AND PADS, MECHANIC CLEANED UP. "

Material Information

OP Unit ID:	937794	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	441518	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	4.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	4.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	NYSDEC
Spiller Address:	600 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

101	4 of 9	WSW	0.40 / 2,111.59	651.21 / 7	BENDERSON DEVELOPMENT 600 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No:	8900461	**UST Trust:**	False
Site ID:	169888	**Spill Date:**	1989-04-14 12:00:00
DER Facility ID:	142956	**Received Date:**	1989-04-17 09:00:00
CID:		**CAC Date:**	1991-07-03 00:00:00
Program Type:	ER	**Insp Date:**	1989-04-17 00:00:00
SWIS Code:	1502	**Close Date:**	1991-07-03 00:00:00
Water Body:		**Create Date:**	1989-04-17 00:00:00
Class:		**Update Date:**	1991-07-03 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	LEARY

REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Affected Persons		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"MERCURY SPILL FROM MANOMETER FOUND IN AIR ROOM"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 04/17/89: RNL SITE INSP. 04/17/89 WITH R. MCCABE AND K. KISH, CLEANUP REQUIRED, RNL TO CONTACT BENDERSON FOR CLEANUP, J. MCMAHON AND P. BUECHI ALSON NOTIFIED. 04/17/89: 04/17/89, P. BUECHI STATED BENDERSON REFUSED TO CLEANUP AS THEY STATED THEY WERE NOT THE SPILLER, RNL CONTACTED E&E TO CLEANUP ROOM, THEY WILL DO SO 04/17/89, PM. 04/17/89: RNL SITE INSP. 04/17/89, E&E CLEANED UP ROOM OF FREE MURCURY, AIR MONITORING TO BE DONE 04/18/89. 04/18/89: E&E SAMPLED AIR IN ROOM, LEVELS OF MUNCURY WERE FOUND, VENTILATION DONE. 04/24/89: E&E AGAIN SAMPLED AIR IN ROOM, VIRTUALLY ALL READINGS WERE ZERO, CONTINUE TO VENTILATE. 06/01/89: RNL DISCUSSION WITH LESTER ABOUT POP DISPOSAL AND METHOD OF PAYMENT FOR HIS DAMAGES, TALKED TO E&E, S&HW, AND ADMINSTRATION, NO ANSWER TO DATE. 08/13/90: RNL DISCUSSION 08/13/90 WITH LESTER ABOUT POP DISPOSAL AND METHOD OF PAYMENT FOR HIS DAMAGES, STILL NO ANSWER TO DATE. 01/29/91: RNL DISCUSSION 01/29/91 WITH LESTER ABOUT POP DISPOSAL AND METHOD OF PAYMENT FOR HIS DAMAGES, HE WILL CHECK WITH ALBANY, NO PAYMENT TO DATE. 05/16/91: RNL REVIEW OF FILE, NO FURTHER SPILL UNIT INVOLVEMENT, LESTER NOT PURSUEING HIS COST RECOVERY, CLOSEOUT. "

Material Information

OP Unit ID:	926868	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	451795	**Med SW:**	False
CAS No:	07439976	**Med DW:**	False
Material Family:	Hazardous Material	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	1.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0031A		
Material Name:	mercury		

Spiller Information

Spiller Name:	
Spiller Company:	NYSDEC
Spiller Address:	DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

101	5 of 9	WSW	0.40 / 2,111.59	651.21 / 7	MODERN DISPOSAL 600 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No:	9002580	**UST Trust:**	False
Site ID:	169891	**Spill Date:**	1990-06-05 15:45:00
DER Facility ID:	142956	**Received Date:**	1990-06-05 16:00:00
CID:		**CAC Date:**	1990-06-06 00:00:00
Program Type:	ER	**Insp Date:**	1990-06-06 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	1502	**Close Date:**	1990-06-06 00:00:00
Water Body:		**Create Date:**	1990-06-06 00:00:00
Class:		**Update Date:**	1990-06-08 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FIX
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"MODERN DISPOSAL WILL SEND CREW TO CLEAN UO,BENDERSON CREWS STARTED CLEANUP BY APPLYING FLOOR DRY."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CAF / / : CAF SITE INSPECTION-REASONABLE CLEANUP,SOME SPEEDY DRY STILL ON SITENO FURTHER ACTION PLANNED,. "

Material Information

OP Unit ID:	940597	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	437321	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	2.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	2.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0016A		
Material Name:	non PCB oil		

Spiller Information

Spiller Name:	
Spiller Company:	MODERN DISPOSAL
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
101	6 of 9	WSW	0.40 / 2,111.59	651.21 / 7	LASALLE AMBULANCE 600 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No:	9509971	**UST Trust:**	False
Site ID:	169895	**Spill Date:**	1995-11-07 13:00:00
DER Facility ID:	142956	**Received Date:**	1995-11-10 14:29:00
CID:	312	**CAC Date:**	1995-11-13 00:00:00
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1995-11-13 00:00:00
Water Body:		**Create Date:**	1995-11-10 00:00:00
Class:	C5	**Update Date:**	2002-03-20 00:00:00
Meets Std:	True	**DEC Region:**	9

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Penalty:	False	**Lead DEC:**	COOKE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Health Department		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"NOZZLE FELL FEOM VEHICLE - PRODUCT HOSED DOWN INTO SEWER BY R.P."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 11/13/95: JDC TELCON W/ DAVE COLE, LASALLE - HEAVY RAIN WASHED SPILLED GASOLINE FROM OVERFILL SPILL TO PARKING LOT AT DISPENSER, CLAY SORB USED, NO RECOVERY POSSIBLE. ADVISED DAVE COLE TO CONTACT DEC ON FUTURE SPILLS. NO FURTHER ACTION REQUIRED."

Material Information

OP Unit ID:	1020400	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	360900	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	True
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	LASALLE AMBULANCE
Spiller Address:	600 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

101	7 of 9	WSW	0.40 / 2,111.59	651.21 / 7	NYS DEPT. OF ENV. CONS. 600 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No:	8608020	**UST Trust:**	False
Site ID:	169887	**Spill Date:**	1987-03-26 10:00:00
DER Facility ID:	142956	**Received Date:**	1987-03-03 14:00:00
CID:		**CAC Date:**	1987-03-26 00:00:00
Program Type:	ER	**Insp Date:**	1987-03-26 00:00:00
SWIS Code:	1502	**Close Date:**	1987-03-26 00:00:00
Water Body:		**Create Date:**	1987-03-31 00:00:00
Class:		**Update Date:**	1987-04-06 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	COOKE
REM Phase:	0	**After Hours:**	False
County:	Erie		

Contributing Factor: Equipment Failure
Reported by: Affected Persons
Referred to:
Source: Passenger Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

""

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC / / : JDC SITE INSP. 03/26/87, CLEANED UP BY DEC SPILL UNIT. "

Material Information

OP Unit ID:	904596	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	473508	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	5.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0009
Material Name: gasoline

Spiller Information

Spiller Name:
Spiller Company: NYS DEPT. OF ENV. CONS.
Spiller Address: 600 DELAWARE AVENUE
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14202
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.900652530
Longitude: -78.873674710

---

101 | ***8 of 9*** | ***WSW*** | ***0.40 / 2,111.59*** | ***651.21 / 7*** | ***BENDERSON 600 DELAWARE 600 DELAWARE AVENUE BUFFALO NY*** | ***LST***

Spill No:	9404468	**REM Phase:**	0
Site ID:	169893	**UST Trust:**	True
DER Facility ID:	142956	**Spill Date:**	1994-06-29 13:00:00
CID:		**Rcvd Date:**	1994-06-29 13:30:00
Program Type:	ER	**CAC Date:**	1994-08-15 00:00:00
SWIS Code:	1502	**Insp Date:**	
Contribute Factor:	Tank Test Failure	**Close Date:**	1994-08-15 00:00:00
Water Body:		**Create Date:**	1994-06-30 00:00:00
Class:	C4	**Update Date:**	2002-03-20 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False

Referred to:
Reported by: Tank Tester
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"LINES PASSED, TANK FAILED"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 06/30/94: RMC/LETTER RESPONSE DUE 7/30/94. 07/12/94: SAC BRUCE NATALIZIA BENDERSON/PHONE BENDERSON IS GOING TO RETEST, RESULTS DUE 8/18/94. 08/15/94: RMC/RECEIVED RETEST, PASSED, CLOSE OUT. "

Material Information

OP Unit ID:	1001539	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	553940	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	BENDERSON DELEVELOPMENT
Spiller Address:	570 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

Tank Test Information

Spill Tank ID:	1542915	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank SIze:	0	***Gross Fail:***	
Material:	0008	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

101	*9 of 9*	*WSW*	*0.40 / 2,111.59*	*651.21 / 7*	***BENDERSON DEVELOPMENT*** ***600 DELAWARE AVENUE*** ***BUFFALO NY***	***LST***

Spill No:	9503691	***REM Phase:***	0
Site ID:	169894	***UST Trust:***	True
DER Facility ID:	142956	***Spill Date:***	1995-06-01 12:00:00
CID:		***Rcvd Date:***	1995-06-23 14:00:00
Program Type:	ER	***CAC Date:***	
SWIS Code:	1502	***Insp Date:***	1998-03-04 00:00:00
Contribute Factor:	Tank Failure	***Close Date:***	1998-05-07 00:00:00
Water Body:		***Create Date:***	1995-06-30 00:00:00
Class:	B3	***Update Date:***	2002-03-20 00:00:00

Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTAMINATION FOUND IN CHEMICAL ANALYSIS"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 07/05/95: RMC/FILE, SENT LETTER REQUESTING SITE ASSESMENT , DUE 8/30/95. 09/20/95: RMC/FILE, SENT LETTER REQUESTING SITE ASSESMENT , DUE 8/30/95, REVISED TO 9/30/95. 11/2/95 RMC/FILE, NO RESPONSE LETTER, RESPONSE DUE 11/15/95 1/4/96 RMC/LAURIE CIRCELLI/PHONE, SITE CONTACT SHOULD BE JOHN GOULD, BENDERSON HAS HIRED BUFFALO DRILLING TO PREPARE A SITE ASSESSMENT, DUE 2/28/96 02/22/96 RMC/RECEIVED REPORT, RICK CROUCH/PHONE RNL/MEETING, REPORT SHOWS NO CONTAMINATION OUTSIDE TANK PIT, LEVELS IN HIGH PPM IN TANK PIT ITSELF BASED ON B AND D SAMPLING, TANK PIT REQUIRES FURTHER SITE ASSESSEMENT AND MAYBE REMEDIATION, CROUCH TO TALK WITH BENDERSON AND WORK OUT NEXT STEP, CALL BACK DUE 3/15/96 5/1/96 RMC/FILE, CONTRACTOR ADVISED THAT REPORT WILL BE SUBMITTED BY 6/1/96 07/05/96 RMC/LORI CIRCELLI/PHONE, RMC AGAIN ADVISED THAT FURTHER WORK IS REQUIRED, TO CALL BACK, CALL DUE 7/7/96 08/26/96 RMC/FILE, LETTER, RESPONSE DUE 9/6/96 09/09/96 RMC/RICK CROUCH, BUFFALO DRILLING/PHONE, TO PROPOSE VAC. EXTRACTION POINTS TO CLIENT AND GET BACK TO DEC, CALL DUE 9/15/96 10/21/96 RMC/RICK CROUCH/PHONE, WENT OVER PROPOSAL TO INSTALL SVE, RMC ADVISED THAT NEED TO HAVE SAMPLING IN PLAN ADEQUATE FOR CLOSURE DETERMINATION, TO DO BASELINE BORINGS IN TANK PIT AND RESUBMIT PLAN WITH MINOR CHANGES, DUE 11/30/96 12/31/96 RMC/RICK CROUCH/PHONE, SENT REWORKED PLAN TO BENDERSON, NOTHING HAS YET TO BE DECIDED BECAUSE GOULD LEFT COMPANY, CROUCH TO GET PLAN TO ME BY 1/30/97 02/25/97 RMC/FILE, LEFT MESSAGE FOR CROUCH TO CALL, CALL DUE 3/1/97 02/28/97 RMC/FILE, LEFT MESSAGE FOR TOM WUERCH TO CALL, CALL DUE 3/3/97 03/20/97 RMC/FILE, LEFT MESSAGE FOR RP TO CALL. CALL DUE 4/1/97 03/20/96 RMC/IVAN LOZINA, 878-9319/PHONE, RMC TO HAVE MEETING TO DISCUSS SITE APPROACH AFTER 4/8/96 06/03/97 RMC/FILE, LEFT MESSAGE FOR LOZINA TO CALL, CALL DUE 6/10/97 06/26/97 RMC/FILE, LEFT ANOTHER MESSAGE CALL DUE 6/27 07/21/97 RMC/FILE, LEFT ANOTHER MESSAGE CALL BACK 7/28 12/22/97 RMC/FILE, RETURNED LOZINAS CALL 12/24/97 RMC/LOZINA/PHONE, TO MEET 1/8/98 03/04/98 RMC/IVAN LOZINA/SITE, WENT OVER PREVIOUS WORK, SITE ASSESSMENT SHOWED CONTAMINATION CONFINED TO TANK PIT AREA, RMC REQUESTED THE TANK PIT BE RESAMPLED, FOR TCLP STARS TABLE 2, DUE 5/1/98 05/07/98 RMC/FILE, RECEIVED SUPPLEMENTAL REPORT FROM NWI, WORK REQUESTED AS ORIGINAL POST EXCAVATION SAMPLE BY B AND D IN 1995 PRIOR TO INSTALLING A NEW UST SHOWED EXCEEDANCES IN STARS, RMC REVIEWED FILE, NO PROBLEMS NOTED IN BUFFALO DRILLINGS INVESTIGATION OUTSIDE THE UST TANK PIT, NO EXCEEDANCES IN LATEST WORK BY NWI, NO ACTION REQUIRED, CLOSE OUT "

Material Information

OP Unit ID:	1018150	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	365199	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	JOHN GOULD
Spiller Company:	BENDERSON DEVELOPMENT
Spiller Address:	570 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.900652530
Longitude:	-78.873674710

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
102	1 of 1	W	0.40 / 2,127.33	662.97 / 19	WESTMINSTER PRESBYTERIAN 724 DELAWARE AVENUE BUFFALO NY	LST

Spill No:	8805542	**REM Phase:**	0
Site ID:	70639	**UST Trust:**	False
DER Facility ID:	67001	**Spill Date:**	1988-09-28 16:15:00
CID:		**Rcvd Date:**	1988-09-28 16:25:00
Program Type:	ER	**CAC Date:**	1988-11-10 00:00:00
SWIS Code:	1502	**Insp Date:**	1988-11-10 00:00:00
Contribute Factor:	Tank Test Failure	**Close Date:**	1988-11-10 00:00:00
Water Body:		**Create Date:**	1988-10-14 00:00:00
Class:		**Update Date:**	1988-11-21 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FIX
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Tank Tester		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"6000 FALLON TANK FAILURE RATE 0.084 GPH"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CAF / / : CAF SITE VISIT BACK FILLING COMPLETE,TANK CUT OPEN,CLEANED AND REMOVED NO FURTHER WORK ANTICIPATED. "

Material Information

OP Unit ID:	922523	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	457446	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	WESTMINSTER PREBYTERIAN
Spiller Address:	724 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.904639993
Longitude:	-78.871340023

Tank Test Information

Spill Tank ID:	1534698	**Source:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank No:		**Leak Rate:**	.00
Tank SIze:	0	**Gross Fail:**	
Material:	0001	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	00
Cause:			
Alt Test Method:	Unknown		

---

103 *1 of 2* *WSW* *0.41 / 2,157.42* *647.28 / 3* ***BENDERSON DEVELOPMENT***
584 DELAWARE AVENUE
BUFFALO NY ***LST***

Spill No:	8808966	**REM Phase:**	0
Site ID:	272336	**UST Trust:**	True
DER Facility ID:	221660	**Spill Date:**	1989-02-16 13:00:00
CID:		**Rcvd Date:**	1989-02-16 13:30:00
Program Type:	ER	**CAC Date:**	1989-11-10 00:00:00
SWIS Code:	1502	**Insp Date:**	1989-11-10 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1989-11-10 00:00:00
Water Body:		**Create Date:**	1989-02-23 00:00:00
Class:		**Update Date:**	1989-12-07 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	LEARY
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Fire Department		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FUMES DETECTED IN ELEVATOR SHAFT FROM LEAKING BENDERSON TANK"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 02/23/89: TANK TO BE TESTED BY OWNER, TANK OPERATED BY DEC R-9. 03/01/89: RNL SITE INSP. 03/01/89, FUMES NOTED ONLY IN SUMP PIT, FAN REMOVED, NO MONITORING WELLS. 03/09/89: RNL LETTER 03/03/89, REQUEST MW'S BY 03/07/89; RNL TELECON 03/08/89, NO ANSWER; RNL TELECON 03/09/89, NO ANSWER. 05/17/89: RNL CHECKED MW 04/05/89 AND 05/17/89, BOTH TIMES WELL WAS DRY, NO GASOLINE FUMES NOTED. 11/10/89: RNL CHECKED MW 08/15/89 AND 11/10/89, BOTH TIMES WELL WAS DRY, NO GASOLINE FUMES NOTED, CLOSEOUT SITE, NOTHING IN MW SINCE INSTALLATION. "

Material Information

OP Unit ID:	925281	**Med in Air:**	False
OU:	01	**Med GW:**	True
Material ID:	453722	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	BENDERSON DEVELOP. CORP.
Spiller Address:	570 DELAWARE AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001

Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.900251820
Longitude: -78.873808800

---

103 **2 of 2** **WSW** **0.41 / 2,157.42** **647.28 / 3** **VAULT #16-109**
584 DELAWARE AVE
BUFFALO NY
NY SPILLS

Spill No: 1606362
Site ID: 532972
DER Facility ID: 486948
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2016-09-27 10:25:00
Received Date: 2016-09-27 10:31:00
CAC Date:
Insp Date:
Close Date: 2016-09-27 00:00:00
Create Date: 2016-09-27 10:34:00
Update Date: 2016-09-27 12:45:04.190000000
DEC Region: 9
Lead DEC: FXGALLEG
After Hours: False

Caller Remark:

"spill contained to vault area/clean up pending crew"

DEC Remark:

"9/27/92 SPILL TO VAULT WHICH IS SECONDARY CONTAINMENT. CLEANUP IS COMPLETE AND WILL BE PROPERLY DISPOSED. NO FURTHER WORK IS NECESSARY. CLOSED."

Material Information

OP Unit ID: 1281706
OU: 01
Material ID: 2287011
CAS No:
Material Family: Petroleum
Quantity: 5.00
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 0016A
Material Name: non PCB oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: NAT GRID
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: LISA
Contact Phone: (716) 479-5339
Contact Ext:
Latitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Longitude:						
104	1 of 1	S	0.41 / 2,166.27	631.21 / -13	APT COMPLEX IN PARKING LOT 2 ALICE COURT BUFFALO NY	NY SPILLS

Spill No:	2201549	**UST Trust:**	False
Site ID:	636605	**Spill Date:**	2022-05-20 06:30:00
DER Facility ID:	583314	**Received Date:**	2022-05-20 08:52:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2022-05-20 00:00:00
Water Body:		**Create Date:**	2022-05-20 08:54:00
Class:		**Update Date:**	2022-06-30 12:29:13.960000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"cleanup in progress"

DEC Remark:

"05/20/22 TDJ CONTACTED STEVE WITH MODERN WHO STATED THAT THE SPILL WAS TO ASPHALT IN PARKING LOT AND WAS CLEANED WITH SORBRNT MATERIAL. NO WATERWAYS WERE AFFECTED AND MODERN WILL TAKE CONTAMINATED SORBENT FOR DISPOSAL. 05/24/22 TDJ RECEIVED DISPOSL INFORMATION FROM MODERN SHOWING .95 TON OF CONTAMINATED MATERIAL WAS PICKED UP FOR DISPOSAL. SITE WAS CLEANED TO SATISFACTION OF DEC SITE MANAGER. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1383674	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2398076	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	
Spiller Company:	MODERN DISPOSAL
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	STEVE MONTANEZ
Contact Phone:	(716) 377-4969
Contact Ext:	
Latitude:	
Longitude:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
105	1 of 2	WSW	0.41 / 2,172.28	642.89 / -2	ALLENTOWN TRADING COMPANY 553 DELAWARE AVENUE BUFFALO NY	LST

Spill No:	9306552	**REM Phase:**	0
Site ID:	128501	**UST Trust:**	True
DER Facility ID:	110861	**Spill Date:**	1993-08-28 13:30:00
CID:		**Rcvd Date:**	1993-08-28 15:21:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	2007-09-01 00:00:00
Contribute Factor:	Tank Test Failure	**Close Date:**	2007-11-15 00:00:00
Water Body:		**Create Date:**	1993-08-31 00:00:00
Class:	B3	**Update Date:**	2007-11-15 13:42:37.037000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
County:	Erie	**After Hours:**	True
Referred to:			
Reported by:	Tank Tester		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK TEST FAILURE."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/03/93: RMC/LOUIS PUDDU/PHONE - PLAN TO RETEST AND/OR SELL. TANKS ARE ALL PUMPED OUT. RESPONSE LETTER DUE BY 10/30/93. 11/23/93: RMC/REMINDER LETTER SENT, RESPONSE DUE 12/15/93. 11/24/93: RMC/SECOND REMINDER LETTER SENT, RESPONSE DUE 1/4/94. 01/12/94: SAC/AL DIPALO/PHONE HE HAS CONTRACT TO PULL TANK BY 2/15/94. 02/22/94: RMC/SITE WORK NO YET BEGUN. 02/25/94: MF/SITE TANKS REMOVED,CONTAMINATION FOUND, REMEDIATION LETTER, RESPONSE DUE 04/29/94. 05/17/94: RMC/LETTER RESPONSE DUE 6/7/94. 05/24/94: RMC/FILE SAC TALKED WITH ANDY K. OF BUFFALO DRILLING WHO IS WORKING ON PROJECT, WORK DUE 6/30/94. 05/27/94: RMC/LETTER SAMPLE RESULTS DUE 7/15/94. 06/06/94: RMC/ANDY K. BUFFALO DRILLING, WELLS WII BE TESTED, RESULTS DUE 7/30/94. 07/18/94: RMC/ANDY K. BUFFALO DRILLING/PHONE WELLS WILL BE TESTED,IF EXCAVATION IS DONE SPILLS WILL BE NOTIFIED FOR INSPECTION, RESULTS DUE 8/30/94. 08/11/94: RMC/ANDY K. BUFFALO DRILLING/MEETING PRELIMINARY WELL RESULTS HIGH, ADVISED WILL REQUIRE WORK, WORK PLAN DUE 9/30/94. 10/12/94: RMC/ANDY K. BUFFALO DRILLING/PHONE WORK TO BEGIN WEEK OF OCTOBER 17, INSPECT 10/30/94. 12/12/94: RMC/ANDY K. BUFFALO DRILLING/PHONE WORK BEGUN BUT NOT YET COMPLETED, SAMPLING 1/1, 4/1, 7/1, 10/1 AS BUILTS DUE 1/30/95. 02/10/95: RMC/ANDY K. BUFFALO DRILLING/PHONE WORK BEGUN BUT NOT YET COMPLETED, SAMPLING 1/1, 4/1, 7/1, 10/1 AS BUILTS DUE 1/30/95REVISED TO 2/28/95. 03/22/95: RMC/ANDY K. BUFFALO DRILLING/PHONE PHONE WORK COMPLETED, DOCUMENTATION TO TO FOLLOW ASAP, DUE 3/30/95. 03/27/95: RMC/RECEIVED AS BUILTS AND QUATERLY ANALYSIS, NEXT ROUND DUE 6/30/95. 05/30/95: RMC/ANDY K. BUFFALO DRILLING/PHONE - RMC ADVISED THAT MW SAMPLE RESULTS INDICATE THAT LEVELS ARE INCREASING. TO MEET WITH OWNERS OF PROPERTY 6/2/95 AT DEC OFFICE. 05/31/95: RMC/RECEIVED QUATERLY ANALYSIS, EXCEEDANCES, NEXT ROUND DUE 8/30/95. 06/02/95: RMC/SAC/PUDDU/CARL ELLICOTT DEVELOPEMENT/BUFFALO DRILLING/MEETING WENT OVER SITE HISTORY AND OPTIONS,RP TO SUBMIT LONG RANGE WORK PLAN FOR APPROVAL, DUE 6/30/95. 07/11/95: RMC/RECEIVED WORK PLAN, REVIEWED AND PROVIDED CHANGE REQUESTS TO BUFFALO DRILLING, REVISION DUE 8/30/95. 07/18/95: RMC/RECEIVED REVISED WORK PLAN, REVIEWED AND ACCEPTED, LETTER, SCHEDULE DUE 8/21/95. 08/17/95: RMC/RECEIVED SCHEDULE, OK, REINSPECT 9/15/95. 09/20/95: RMC/SITE SYSTEM NOT YET COMPLETE, REINSPECT 10/30/95. 11/06/95 RMC/ANDY K,BUFFALO DRILLING/PHONE SYSTEM UP AND RUNNING, QUATERLY SAMPLING TO BEGIN, ROUND DUE 12/30/95 01/19/96 RMC/FILE RECEIVED REPORT, OK, MAJOR EXCEEDANCES IN MWS PERSIST, NEXT ROUND DUE 4/30/96 05/10/96 RMC/FILE RECEIVED REPORT, MAJOR EXCEEDANCES CONTINUE, SYSTEM RUNNING, NEXT ROUND DUE 8/30/96 06/19/96 RMC/CARL PALADINO,852-8227/PHONE MR PALADINO WISHED TO EXLORE A VOL. CLEANUP OR REBCA AS HE CAN NOT GET FINANCING FOR DEVELOPEMENT COSTS OF SITE RMC TO CONFIR W/RNL AND PJB 07/3/96 RMC/PJB/ABBY SNYDER/CARL PALADINO/RICHARD SCHUECKLER/MEETING DISCUSSED CLEAN UP OBJECTIVES,CLOSURE AND LENDING INSTITUTION REQUIRMENTS, OPTIONS PRESENTED TO RP FOR REVIEW WITH LENDER, UPDATE 8/30/9 09/10/96 RMC/FILE RECEIVED SAMPLING REPORT, NO REAL IMPROVEMENT SEEN, NEXT ROUND DUE 12/30/96REVISED TO 1/31/97 03/12/97 RMC/FILE RECEIVED REPORT, EXCEEDANCE NOT DECREASING AS EXPECTED, RMC TO CAREFULLY REVIEW NEXT ROUND AS CURRENT TREATMENT MAY NOT BE ADEQATE, ROUND DUE 5/1/97 06/03/97 RMC/FILE LEFT MESSAGE FOR KUCSERIK TO CALL AS SAMPLE RESULTS OVERDUE, CALL DUE 6/10/97 06/06/97 RMC/ANDY K/PHONE WELLS TO BE SAMPLED TODAY, RESULTS DUE 7/15/97 08/18/97 RMC/FILE LETTER ON SAMPLING, RESPONSE DUE 9/12/97 08/25/97 RMC/FILE RECEIVED DISCHARGE SAMPLING, LETTER MW SAMPLING, REPORT DUE 10/30/97 09/02/97 RMC/FILE RECEIVE 6/97 AND7/97 MW SAMPLE RESULTS, VERY HIGH EXCEEDANCES, NEXT ROUND DUE 12/30/97 01/28/98 RMC/FILE RECEIVED REPORT, SIGNIFICANT EXCVEEDANCES CONTINUE, NEXT REPORT DUE 4/30/98 06/18/98 RMC/ANDY KUCSERIK/PHONE RECEIVED MW RESULTS HIGH EXCEEDANCES CONTINUE, RMC ADVISED THAT IF RESULTS DO NOT IMPROVE IN THE NEXT ROUND WE WILL REQUEST MORE AGRESSIVE REMEDIATION, NEXT ROUND DUE 10/30/98 11/12/98 RMC/FILE RECEIVED LETTER FROM BUFFALO DRILLING, RP PLANS FUTHER SITE INVESTIGATION, REPORT DUE 1/99 03/15/99 RMC/FILE LEFT MESSAGE FOR ANDY K. THAT REPORT OVERDUE, DUE 4/15/99 12/2/99 RMC/FILE NO RESPONSE FROM RECENT CALLS TO RP, LETTER, RESPONSE DUE 12/21/99 12/21/00 RMC/FILE RECVEIVED LETTER, LIMITED AMOUNT OF WORK WILL BE COMPLETED AND SUBMITTED FOR REVIEW BY 1/30/00 1/24/00 RMC/FILE RECEIVED FAX FORM BUFFALO DRILLING EXPOSURE ASSESSMENT IS BEING LOOKED AT AS A POTENTIAL, DUE 3/30/00 04/05/00 RMC/FILE LEFT MESSAGE FOR ANDY K. BUFFALO DRILLING REQUESTING REPORT. DUE 4/15 04/7/00 RMC/ANDY K./SITE NO WORK HAS BEEN AUTHORIZED BY RP,

DISCUSSED POTENTIAL EXPOSURE ASSESSMENT, LEVELS ARE TOO HIGH, LETTER RESPONSE DUE 5/1 04/24/00 RMC/FILE RECEIVED LETTER FROM ELLICOTT DEVELOPMENT, WORKING ON ALTERNATIVE REMEDIATION PLAN, DUE 6/10 07/10/00 RMC/FILE NO PLAN SUBMITTED, LETTER, PLAN DUE 7/30 08/2/00 RMC/FILE RECEIVED LETTER FROM BUFFALO DRILLING, PLAN TO INSTALL ORC, REPORT DUE 10/30/00 12/01/00 RMC/ANDY K./PHONE RMC REQUESTED REPORT, NO WORK WAS DONE DUE TO EQUIPMENT BREAKDOWN, PROMISED WORK WILL START IN 30 DAYS, REPORT DUE 1/15/00 02/13/01 RMC/FILE NO WORK YET, NO REPORT, LEFT MESSAGE FOR ANDY K. TO CALL, DUE 2/20/01 3/14/02 RMC/PAUL MORETTA/PHONE. HE HEARD THAT NEXT DOOR NEIGHBOR HAS A SPILL PROBLEM, RMC SEARCHED RECORED FOUND NOTHING FROM INFORMATION GIVEN, THEY PLAN TO START O2 INJECTION, REPORT DUE 4/30/01 09/04/02 RMC/FILE. NOTHING RECEIVED, CONTACTED PAUL MORETTA. HE WILL SEND A LETTER WITHIN A WEEK ON THE SITE, DUE 9/15/02 09/20/02 RMC/FILE. RECEIVED LETTER REQUESTING INACTIVE. REVIEWED FILE. NO TOTAL SOILS ANALYSIS EVER DONE. GW RESULTS IN 200 PPM RANGE. REMEDIATION REQUIRED. LETTER. RESPONSE DUE 11/1/02 10/03/02 RMC/FILE. RMC TALKED TO PAUL MORETTA AND ANDY K. BUFFALO DRILLING, RMC ADVISED THAT CONTAMINATION WAS NOTED IN 1993 BY INSPECTORS DURING THE UST REMOVALS. RMC ALSO NOTED THAT GW IN THE AREA IS HIGHLY CONTAMINATED. UPDATE 11/1/02 12/04/02 RMC/FILE. RECEIVED REPORT AND LETTER FROM HSE REQUESTING CLOSURE. REPORT SHOWS SOIL BORINGS. NO BORING LOGS, NOTED PETROLEUM TYPE ODORS IN SOME OF THE BORINGS. ANALYITICAL PROVIVED MEETS TAGM TABLES. SITE REQUIRES FURTHER WORK DUE TO GW CONTAMINATION AND PETROLUEM TYPE ODORS IN SOIL. SEE FILE. LEFT MESSAGE FOR CRAIG SLATER TO CALL. 12/04/02 RMC/CRAIG SLATER/PHONE. WANTS TO REVIEW FILE NEXT MONDAY A 2PM. NOTIFIED KAB. UPDATE 12/30/02, REVISED TO 1/15/03 02/21/03 RMC/FILE. LEFT MESSAGE FOR CRAIG SLATER TO CALL. CALL DUE 3/1/03 02/24/03 RMC/FILE. RECEIVED AND RETURNED SLATERS MESSAGE. UPDATE 3/1/03 03/06/03 RMC/SAC/SLATER/KUCSERIK/MORETTA/MEETING. RP REQUESTED STATUS CHANGE. DEC ADVISED THAT LEVELS ARE TOO HIGH, RP TO DO ADDITIONAL SAMPLING. UPDATE 4/15/03 06/13/03 RMC/FILE. NO REPSONSE FROM RP, LEFT MESSAGE FOR RPS CRAIG SLATER. UPDATE 6/30/03 06/13/03 RMC/CRAIG SLATER/PHONE. THEY ARE DOING SAMPLING, REPORT DUE 7/15/03 10/30/03 RMC/FILE. PRP IS NON RESPONSIVE TO REPEATED REQUESTS FOR WORK TO BE DONE ON THIS SITE FOR YEARS, LEGAL REFERAL, UPDATE 03/01/2004 06/16/04 RMC/FILE. REFERAL WENT TO LEGAL IN MARCH. NO WORD YET, UPDATE 9/1/04. 10/18/04 RMC/FILE. MESSAGE TO KING REQUESTING LEGAL UPDATE. SPILL ASSIGNED TO ANNETTE SANSONE. UPDATE 1/1/05. 05/14/05 RMC/FILE. RECEIVED COPY OF LETTER LEGAL SENT TO CRAIG SLATER. UPDATE 7/30/05. 05/31/05 RMC/DK/ANNETTE S/MEETING. PRP PROVIDED SAMPLING FROM 2003 WHICH SHOWS THAT LEVELS IN WELLS HAD DECREASED 10 TIMES SINCE LAST TESTS. TO SAMPLE TWO WELLS FOR NEXT THREE QUARTERS. AND MEET AGAIN. WE WILL LOOK INTO O2 UNIT. THEY WILL DO A FS. NEXT ROUND DUE 7/15/05. 06/02/05 RMC/FILE. RECEIVED EMAIL THAN A O2 UNIT MAY BE AVAILABLE IN REGION 5. PASSED ALONG INFORMATION TO CRAIG SLATER. 08/01/05 RMC/CRAIG SLATER/PHONE. RMC REMINDED OF REPORT DUE, DUE 8/30/05 08/30/05 RMC/FILE. NOTHING RECEIVED, REQUESTED ANNETTE S. FOLLOW UP WITH CRAIG SLATER. UPDATE 9/30/05. 10/03/05 RMC/FILE. NOTHING YET, ANNETTE SANSONE IS WORKING ON, UPDATE 10/30/05. 11/14/05 RMC/FILE. REVIEWED SAMPLE RESULTS, SIGNIFICANT EXCEEDANCES IN GW AT PROPERTY LINE IN MW14 100PPM AND GREATER EXCEEDANCES IN MW12 140PPM. DISCUSSED WITH DAN KING. REMEDIATION IS REQUIRED, CALLED CRAIG SLATER AND ADVISED NEED FOR REMEDIAITON, THEY ARE CONSIDERING SUB SURFACE REMEDIATION. RMC ADVISED THAT THIS WAS TRIED HERE AND IT DIDN'T WORK. RMC DRAFTED LETTER REQUESTING FURTHER ASSESSMENT AND RAP. UPDATE 12/22/05. 12/09/05 RMC/FILE. RECEIVED MESSAGE FROM DAN KING THAT THEY WOULD NOT BE READY BY 12/16/05. RMC CONTACTED CRAIG SLATER AND ANDY K. THAT THREE MORE WEEKS WOULD BE OK, RESPONSE DUE 1/22/06. 03/01/06 RMC/FILE. NOTHING RECEIVED. LEFT MESSAGE FOR CRAIG SLATER. CALL DUE 3/10/06. 03/02/06 RMC/CRAIG SLATER/PHONE. GETTING PRICES. PLAN DUE BY 4/1/06. 05/03/06 RMC/FILE. NOTHING RECEIVED. CALLED CRAIG SLATER, LEFT MESSAGE. BACK TO LEGAL IF NOTHING BY 5/15/06. 05/25/06 RMC/CRAIG SLATER/PHONE. CRAIG CALLED TO ADVISE THEY HAVE A WORK PLAN. WILL MEET ON SITE WITH THE CONTRACTOR NEXT WEEK. IF THE PLAN IS DEEMED FEASIBLE IT WILL BE SUBMITTED TO DEC WITHIN TWO WEEKS. DUE 6/15/06. 11/28/06 RMC/FILE. RMC INSPECTED SITE SEVERAL TIMES DURING EXCAVATION IN OCTOBER. EXCAVATED AN AREA 50 BY 30 BY 10 FEET DEEP. UP AGAINST THE ROAD AND SOUTH PROPERTY LINE. ALSO LIMITED BY BUILDING. RECEIVED EXCAVATION SOIL SAMPLE RESULTS. ALL MEET TAGM. RECEIVED DISPOSAL RECEIPTS FOR 590 TONS IMPACTED SOIL THAT WAS REMOVED. REVIEWED WITH SAC. NEED TO SAMPLE MW14 AGAIN. EMAILED CRAIG SLATER. UPDATE 1/30/07. 01/05/07 RMC/FILE. CRAIG SLATER AND SAC DISCUSSIONS. MW14 REQUIRES SAMPLING. DUE 2/28/07. 11/15/07 RMC/FILE. DKK AND RMC INSPECTED THE SITE IN 9/07. BAILED MW14. WELL HAD PETROLEUM ODOR. DKK REVIEWED THE FILE AND DETERMINED THAT REMOVAL OF ANY ADDITIONAL CONTAMINED SOILS NOT POSSIBLE. SITE TO BE MADE INACTIVE. LETTER. INACTIVE. "

Material Information

OP Unit ID:	984727	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	396412	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	True
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

OP Unit ID:	984727	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	573026	***Med SW:***	False
CAS No:	01634044	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	False
Quantity:		***Med Surf:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	True
Med Air:	False		
Material Code:	1213A		
Material Name:	MTBE (methyl-tert-butyl ether)		

Spiller Information

Spiller Name:	PAUL MORETTA/ JOE HANNON
Spiller Company:	ELLICOTT DEVELOPMENT CO.
Spiller Address:	210 ELLICOTT SQUARE BLDG
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14203-2545
Spiller Country:	001
Contact Name:	JOSEPH HANNON
Contact Phone:	(716) 854-0600
Contact Ext:	
Latitude:	42.899173540
Longitude:	-78.874010620

Tank Test Information

Spill Tank ID:	1541926	**Source:**	
Tank No:		**Leak Rate:**	.00
Tank SIze:	0	**Gross Fail:**	
Material:	1213A	**Modified by:**	Spills
EPA UST:		**Last Modified:**	2004-10-01 04:00:45.140000000
UST:		**Test Method:**	00
Cause:			
Alt Test Method:	Unknown		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
105	2 of 2	WSW	0.41 / 2,172.28	642.89 / -2	BRADLEY SUNOCO 553 DELAWARE AVENUE BUFFALO NY	LST

Spill No:	8902410	**REM Phase:**	0
Site ID:	128500	**UST Trust:**	True
DER Facility ID:	110861	**Spill Date:**	1989-06-07 18:00:00
CID:		**Rcvd Date:**	1989-06-08 08:00:00
Program Type:	ER	**CAC Date:**	1989-08-01 00:00:00
SWIS Code:	1502	**Insp Date:**	1989-07-11 00:00:00
Contribute Factor:	Tank Failure	**Close Date:**	1989-08-01 00:00:00
Water Body:		**Create Date:**	1989-06-08 00:00:00
Class:		**Update Date:**	1989-09-07 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	ROSS
County:	Erie	**After Hours:**	True
Referred to:			
Reported by:	Other		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FUMES IN NEW PLACED MW'S"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR 06/08/89: LQR AND MS ON SITE W/ SPILLER CONTRACTOR, MW'S CHECKED,FUMES FOUND. 07/11/89: LQR ON SITE W/ BUYER & CONTRACTOR, EXPLORIATORY PITS BEING DUG. 07/11/89: LQR ON SITE W/ BUYER,CONTRACTOR & SELLER,TANK FOUND FURTHER INVESTIGATION NEEDED. 07/13/89: LQR TELCON W/ BUYER,LETTER SENT ON TANK PULL NO FURTHER ACTION NECESSARY. 08/01/89: BUYER RETESTED TANK 08/01/89 INCONCLUSIVE TEST,TO RETEST. 08/09/89: BUYER RETESTED TANK 08/01/89 TESTED TIGHT. "

Material Information

OP Unit ID:	928135	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	450112	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	THE FIRST ELMWOOD MGT
Spiller Address:	5820 MAIN STREET
Spiller City:	WILLIAMSVILLE
Spiller State:	NY
Spiller Zip:	14221
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.899173540
Longitude:	-78.874010620

Tank Test Information

Spill Tank ID:	1535558	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank SIze:	0	***Gross Fail:***	
Material:	0009	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

---

106 ***1 of 1*** ***NW*** ***0.41 / 2,173.62*** ***658.96 / 15*** ***TANKS AT APARTMENT COMPLE 905 DELAWARE AVENUE BUFFALO NY*** ***LST***

Spill No:	0075007	***REM Phase:***	0
Site ID:	121438	***UST Trust:***	True
DER Facility ID:	105411	***Spill Date:***	2000-04-05 12:00:00
CID:		***Rcvd Date:***	2000-04-06 09:40:00
Program Type:	ER	***CAC Date:***	
SWIS Code:	1502	***Insp Date:***	2000-04-06 00:00:00
Contribute Factor:	Tank Failure	***Close Date:***	2000-06-22 00:00:00
Water Body:		***Create Date:***	2000-04-06 09:46:00
Class:	C3	***Update Date:***	2000-07-10 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RJJONAK
County:	Erie	***After Hours:***	False
Referred to:			
Reported by:	Citizen		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER OBSERVED UST REMOVAL IN PROCESS IN FRONT OF UNKNOWN APARTMENT BLDG. AND FELT THAT THERE WAS LIQUID LEAKING FROM TANKS AND WAS COVERED UP WITH DIRT."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 04/06/2000...RJJ SITE INSPECTION AT 1300...MEET WITH STEVE CROSS OF OKAR EQUIPMENT CO., THEY ARE PULLING 1-4000 AND 1-2000 GAL. FUEL OIL TANKS AT 905 DELAWARE AVE...THE EXCAVATION IS ABOUT 20X10X8',AND THE SOIL IS STAGED ON PLASTIC...PIT AREA LOOKS AND SMELLS CLEAN, NO VISIBLE STAINED SOIL...THEY WILL SEND ME THE ANALYTICAL RESULTS FROM THE 4 SIDES AND THE FLOOR AND THE SOIL DISPOSAL RECEIPTS...TANKS WERE CUT AND CLEANED PROPERLY...THEY PLAN TO BACKFILL THE PIT AREA TODAY ,WHEN THEY ARE DONE. 04/17/2000: RJJ RECEIVED ANALYTICAL DATA FOR THE TANK EXCAVATION AT 905 DELAWARE AVE....ALL SAMPLES SHOW NO CONTAMINATED LEVELS OF PRODUCT...WHEN THEY SEND THE SOIL DISPOSAL RECEIPTS, I WILL BE ABLE TO CLOSE OUT THIS SPILL. 06/22/2000: RJJ RECEIVED THE SOIL DISPOSAL RECEIPTS FRON OKAR EQUIPMENT,THEY REMOVED 5.03 TONS OF SOIL...ALL RECEIPTS ARE IN ORDER, I CAN NOW CLOSE OUT THIS SPILL...I WILL DRAFT AND SEND A CLOSURE LETTER...NO FURTHER ACTION NEEDED."

Material Information

OP Unit ID:	836373	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	568873	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	TONY PICCIONE
Spiller Company:	TONY PICCIONE
Spiller Address:	159 BYRANT STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.908545310
Longitude:	-78.871119790

---

107 ***1 of 1*** ***S*** ***0.42 / 2,219.64*** ***627.40 / -17*** ***ST. JOHNS TOWERS 865 MICHIGAN AVE. BUFFALO NY*** ***NY SPILLS***

Spill No:	0275453	***UST Trust:***	False
Site ID:	291763	***Spill Date:***	2002-12-18 09:10:00
DER Facility ID:	236220	***Received Date:***	2002-12-18 09:10:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2002-12-18 00:00:00
Water Body:		***Create Date:***	2002-12-18 09:12:00
Class:	C3	***Update Date:***	2002-12-18 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RJJONAK
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial Vehicle		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CALLER SAID THAT ONE OF THEIR TRUCKS BROKE A HYDRAULIC LINE,SPILLING 5 GAL OF OIL,ALL ON THE PAVEMENT."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 12/18/2002: BOB ENGELS,WASTE MANAGEMENT,TELECON RJJ,SAID THAT ONE OF THEIR TRUCKS BROKE A HYDRAULIC HOSE,SPILLING 5 GAL OF HYDRAULIC OIL,ALL ON THE PARKING LOT...THEY CLEANED UP THE OIL AND DISPOSED THE MATERIAL IN THEIR TRUCK FOR DISPOSAL...SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF. **** NOTE,THERE IS NO PAPER FILE FOR THIS SPILL ****"

Material Information

OP Unit ID:	868121	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	507821	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	5.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	5.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	BOB
Spiller Company:	WASTE MANAGEMENT
Spiller Address:	10890 OLEAN RD
Spiller City:	CHAFFEE
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BOB ENGELS
Contact Phone:	(716) 496-5000
Contact Ext:	231
Latitude:	42.896123190
Longitude:	-78.864377720

108	1 of 1	SSE	0.42 / 2,232.56	628.20 / -16	ST. JOHNS HOSPICE SITE 113 MAPLE BUFFALO NY	NY SPILLS

Spill No:	0550592	**UST Trust:**	False
Site ID:	348846	**Spill Date:**	2005-07-01 12:00:00
DER Facility ID:	295304	**Received Date:**	2005-07-07 16:26:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	2006-03-01 00:00:00
SWIS Code:	1502	**Close Date:**	2008-12-23 00:00:00
Water Body:		**Create Date:**	2005-07-07 16:30:00
Class:	B3	**Update Date:**	2008-12-23 11:22:52.590000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	fxgalleg
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Local Agency		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"partial phase ii shows a test pit with petroleum type odors, sampling data provided."

DEC Remark:

"7/12/05 FG CONTACTED DENNIS SUTTON WITH THE CITY OF BUFFALO AND LEFT A MESSAGE FOR HIM TO RETURN THE CALL. FG JFO SITE INSPECTION. THE PROPERTY IS A VACANT LOT. 12/7/05 FG SITE INSPECTION. MARK SWACHA WITH FOIT ALBERT ON SITE DIGGING OUT CONTAMINATION WHICH IS STAGED ON SITE ON PLASTIC. THE SOURCE IS A 6 INCH AND A 4 INCH SEWER LINE WHICH CONTAINS A PETROLEUM PRODUCT. FOIT ALBERT IS FOLLOWING THE LINES. DENNIS SUTTON WILL BE ON SITE TODAY AND IS LOOKING UP THE SEWER MAPS FOR ANY INFO. THEY WILL NOTIFY THIS OFFICE ABOUT WHERE THEY ENDED. 1/4/06 MUFFETT MAUCHE WITH FOIT ALBERT CALLED 856-3933. SHE SAID THAT ST JOHNS HOSPICE HAS STOPPED WORK TO ASK THE CITY TO CONTRIBUTE MONEY TO THE SITE WORK THAT IS NECESSARY SINCE THE CITY OWNS THE PROPERTY. SITE DEVELOPMENT IS SET TO START THIS SPRING. SHE EXPECTS TO HAVE THIS ISSUE RESOLVED BY NEXT WEEK AND WILL NOTIFY THIS OFFICE. I TOLD HER THAT NYSDEC DOES NOT CONSIDER ST JOHN'S THE RP BUT THE CITY. SHE UNDERSTANDS THIS. THE CITY IS RESPONSIBLE FOR THE WORK. THE EXCAVATED SOIL IS STAGED ON SITE AND THE EXCAVATION IS BACKFILLED. ADDITIONAL REMOVAL IS NECESSARY. 02/08/06 RMC/FILE. MR SUTTON FROM THE CITY CALLED. WANTED TO KNOW HOW LONG CONTAMINATED SOIL COULD STAY ON SITE ONCE EXCAVATED, TOLD HIM SW 360 REGULATIONS ARE 60 DAYS. 02/16/06: MF T/C DENNIS SUTTON, CITY OWNES PROPERTY. ST JOHN PAYING CONTRACTOR FOR INVESTIGATION & REMEDIATION. REV CHAPMAN, 184 GOODELL, BUFFALO 14204, 852-4540. IS THE LEAD FOR ST JOHNS. T/C MARIA SCINTA. 851-5720 SHE TOLD ME TO CALL MUFFETT M GEORGE 856-3933. T/C MMG, CONTRACTOR WILL BE ON SITE THE WEEK OF 2/27. CONTAMINTION LIMITED TO AREA OF CLAY TILES. 02/27/06: MF S/I/MARK SWACHA, FOIT ALBERT/DENNIS SUTTON, CITY OF BUFFALO/OP-TECH. DIGGING UP CLAY TILE DRAIN LINE ALONG WITH CONTAMINATED SOIL. SOIL BEING STOCKPILED ON SITE. DRAIN APPEARS TO BE SLOPED TOWARD THE BACK OF THE PROPERTY. ALL THE TILE TO BE REMOVED. 02/28/06: MF T/C MUFFETT M, RAN INTO SLAB APPX 18 BG. THEY WILL HAVE TO RAN HOE THRU IT. 03/01/06: MF S/I NOOS, AREA SNOW COVERED. TRENCH DUG TO THE BACK OF THE LOT. T/C MUFFETT, THEY FOLLOWED DRAIN PIPE AS FAR AS THEY COULD. SAMPLES TAKEN. THEY RUN OUT OF CONTAMINATION. 05/23/06 RMC/FILE. RECEIVED FAX SAMPLE RESULTS FOR STARS TABLE 2 COMPOUNDS. ALL MEET TAGM. CONTACTED MUFFETT MAUCHE GEORGE. SKETCH WILL BE SENT. SAMPLES WERE OBTAINED IN THE ORIGINAL EXCAVATION THAT WAS BACKFILLED. COMPREHENSIVE REPORT IS BEING COMPILED. DUE 6/30/06. 10/24/08 FG LEFT A MESSAGE FOR MUFFETT MAUCHE 856-3933 REQUESTING THAT SHE SUBMIT THE CLOSURE DOCUMENTATION. 12/23/08 DISPOSAL RECEIPTS RECEIVED. NO FURTHER WORK IS REQUIRED. THE SITE IS CLOSED."

Material Information

OP Unit ID:	1106489	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	1971409	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	DENNIS SUTTON
Contact Phone:	(716) 851-6587
Contact Ext:	
Latitude:	42.829197993
Longitude:	-78.820412021

109	***1 of 1***	***WSW***	***0.43 / 2,265.94***	***649.91 / 5***	***FUMES IN HOUSE 51 IRVING STREET BUFFALO NY***	***NY SPILLS***

Spill No:	8709670	***UST Trust:***	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site ID:	232837	**Spill Date:**	1988-02-01 12:00:00
DER Facility ID:	191836	**Received Date:**	1988-02-16 14:45:00
CID:		**CAC Date:**	1988-10-20 00:00:00
Program Type:	ER	**Insp Date:**	1988-10-20 00:00:00
SWIS Code:	1502	**Close Date:**	1988-10-20 00:00:00
Water Body:		**Create Date:**	1988-02-17 00:00:00
Class:		**Update Date:**	1988-10-25 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	MXFRANKS
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONSTANTINE ARE THE OWNERS 884-1010, MCCARTEN IS FURNACE CONTRACTOR, FUMES WERE NOTED IN SEWER. NOTICED PROBLEM ONCE BEFORE IN THE FALL."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 02/16/88: MF CHECKED ODOR BACK TO SEWER ON NORTH ST., UNABLE TO NOTICE ANY STORAGE TANKS IN AREA, WILL CHECK FUTHER 2/17/88. CHECKED WITH B.S.A. SEWER RUNS DOWN IRVING ST., PICKS UP A FEW LATERIALS ON NORTH. 02/17/88: MF OBTAINED MAP OF SEWERS, CHECKED MAN HOLES ON NORTH ST.(NO DEFINATE ODOR), B.S.A. CLEANED SEWERS ON IRVING ST. JOE JORDAN (BSA) SUSPECTS TRI-CLORO OR CLEANING FLUID. 02/19/88: MF MIKE MCCARTAN CALLED, HE NOTICED NY TELE WORKING IN MAN HOLE ON NORTH ST. PORTABLE HEATER WAS LEAKING F/O. ALSO INTAKE & EXHAUST FOR FURNACE WERE MOVED. 02/22/88: MF SITE VISIT/MIKE MCCARTEN, NO ODOR NOTICED AT 51 IRVING, TELECON NI-MO, THEY WERE WORKING PULLING CABLE ON IRVING, END OF JAN & FIRST 2 WEEKS IN FEB, THEY BROKE HYDRAULIC HOSE 1-22-88. 04/07/88: MF TELECON ALLEN INCORVAIA (GEN. MANAGER HOLIDAY INN) HE IS UNAWARE OF ANY PETROLEUM STORAGE TANKS AT THIS LOCATION. I TOLD HIM I WILL SEND HIM A LETTER TO THIS EFFECT. 04/13/88: MF VISIT/HOWARD JOHNSON'S (BOB CARON & JOHN TYCHINSKI). WE WERE UNABLE TO CONFIRM THE PRESENCE OF A UST AT THIS LOCATION. THEY WILL CONTINUE TO CHECK INTO THIS. 05/11/88: MF SITE VISIT, CHECKED SEWERS ON IRVING ST, DID NOT NOTICE ANY ODOR. TRIED TO VISIT 51 & 40 IRVING ST., NO LUCK, LEFT MESSAGE AT 51 IRVING TO CALL ME. 05/13/88: MF MIKE MCCARTAN TELECON, HE HASN'T NOTICED ANY ODOR PROBLEM SINCE THE MIDDLE OF FEBRUARY. 09/19/88: MF MARY BETH GANNON TELECON (WESTMINISTER CHURCH), SHE CLAIMED CHURCH WILL BE TESTING TANK, SHE SAID VENT LINE WAS BROKEN. ELMWOOD TANK TO DO THE WORK. 10/20/88: MF CHECKED SEWERS ON IRVING ST, NO SIGN OF PETROLEUM. NO FUTHER ACTION POSSIBLE. "

Material Information

OP Unit ID:	914714	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	461462	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	True
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Ext:
Latitude: 42.900835088
Longitude: -78.874973145

---

110 **1 of 1** **SSW** **0.43 / 2,267.12** **636.02 / -8** **SOIL**
644 ELLICOT ST
BUFFALO NY
NY SPILLS

Spill No:	2104166	**UST Trust:**	False
Site ID:	622965	**Spill Date:**	2021-08-02 09:18:00
DER Facility ID:	570342	**Received Date:**	2021-08-02 09:32:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2021-08-02 00:00:00
Water Body:		**Create Date:**	2021-08-02 09:33:00
Class:		**Update Date:**	2021-08-02 10:57:43.123000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Transformer
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"ONE QUART SPILLED CLEAN UP PENDING"

DEC Remark:

"8/2/21 This is a minor spill that has been cleaned up. Closed."

Material Information

OP Unit ID:	1370117	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2383122	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0020A
Material Name: transformer oil

Spiller Information

Spiller Name: LISA
Spiller Company: NATIONAL GRID
Spiller Address: 644 ELLICOT ST
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: COURTNEY ALLEN
Contact Phone: (716) 398-5307
Contact Ext:
Latitude:
Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
111	1 of 1	WSW	0.43 / 2,294.82	642.83 / -2	SEWAGE BACKUP AT BUILDING 560 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No:	9702249	**UST Trust:**	False
Site ID:	93165	**Spill Date:**	1997-05-19 12:00:00
DER Facility ID:	83547	**Received Date:**	1997-05-21 12:25:00
CID:	999	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1997-05-22 00:00:00
Water Body:		**Create Date:**	1997-05-21 00:00:00
Class:	D5	**Update Date:**	1997-05-30 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	SORGI
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SEWER BACKED UP TO DUE TO RAIN. RAW SEWAGE IN PARKING LOT"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 5/21/97 - 1240 HRS - MJS TELECON TO BSA. THEY WILL INSPECT. NO ACTION REQUIRED BY SPILLS UNIT. 5/22/97 - KAH UPDATED COMPUTER AND CLOSED FILE."

Material Information

OP Unit ID:	1044982	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	335190	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0062A		
Material Name:	raw sewage		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO SEWER AUTHORITY
Spiller Address:	FOOT OF WEST FERRY STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14213-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.899641570
Longitude:	-78.874015470

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
112	1 of 1	NW	0.44 / 2,300.20	659.63 / 15	925 DELAWARE AVENUE INC 925 DELAWARE AVENUE BUFFALO NY 14209	LST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	0906378	**REM Phase:**	0
Site ID:	418711	**UST Trust:**	
DER Facility ID:	367810	**Spill Date:**	2009-09-02 09:00:00
CID:		**Rcvd Date:**	2009-09-02 09:47:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	2009-12-08 00:00:00
Contribute Factor:	Tank Test Failure	**Close Date:**	2010-01-06 00:00:00
Water Body:		**Create Date:**	2009-09-02 09:51:00
Class:	B3	**Update Date:**	2010-01-06 12:13:15.123000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Other		
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"tank test failure. 8k fuel oil"

Dec Remark:

"will pull tank, will empty this week 9/15/09 FG SPOKE TO RP. SAID ELMWOOD REMOVED ALL FUEL. IS GETTING PROPOSAL FROM ELMWOOD TANK FOR A SUBSURFACE INVESTIGATION. FG SPOKE TO TOM PRITCHARD WITH 925 DELAWARE AVENUE INC. 885-9250. 12/08/09: MF S/V/ELMOOD TANK/GARY TOWNER/TOM PRITCHER. 8K #2FO UST REMOVED. NO HOLES NOTICED, NO CONTAMINATION NOTICED. SAMPLES TAKED, 8260 & 8270. 1/6/09 FG CONFIRMED WITH MIKE CLANCY WITH ELMWOOD TANK THAT NO SOIL WAS REMOVED DURING THE TANK REMOVAL. EXCAVATION ANALYTICAL PROVIDED FOR 8260 & 8270 STARS LIST AND ALL ARE BELOW DER 10 GUIDELINES. NO FURTHER WORK IS REQUIRED. THE SITE IS CLOSED."

Material Information

OP Unit ID:	1174877	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2167264	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	False
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	925 DELAWARE AVENUE INC
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	THOMAS G. PRITCHARD
Contact Phone:	(716) 885-9250
Contact Ext:	
Latitude:	42.909191465
Longitude:	-78.870526746

113	***1 of 1***	***ENE***	***0.44 / 2,309.21***	***640.48 / -4***	***ROADWAY 245 NORTHHAMPTON ST BUFFALO NY***	***NY SPILLS***

Spill No:	1405197	**UST Trust:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site ID:	498614	**Spill Date:**	2014-08-13 10:15:00
DER Facility ID:	453592	**Received Date:**	2014-08-13 10:34:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2014-08-20 00:00:00
Water Body:		**Create Date:**	2014-08-13 10:36:00
Class:		**Update Date:**	2014-08-20 08:26:31.810000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Fire Department		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Spilled onto roadway. FD on scene containing. DPW to continue cleanup."

DEC Remark:

"08/13/14 TDJ WENT TO LOCATION WHERE SPEEDY DRY HAD BEEN PLACED ONTO THE SPILL BY HE BUFFALO FIRE DEPT. AREA IN MIDDLE OF STREET WAS MOST AFFECTED. NO SOIL NOR DRAINS WERE REACHED. CONTACTED THE CITY OF BUFFALO WHO STATED THAT A STREET SWEEPER WAS CO ARRIVE ONSITE AFTER 1300 hrs. WILL SWEEP UP CONTAMINATION TO TAKE TO LANDFILL BY CITY GARBAGE TRUCK. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1248060	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2249440	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	10.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	BUFFALO FIRE DISPATCH
Spiller Company:	GARBAGE TRUCK
Spiller Address:	245 NORTHHAMPTON ST
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	BUFFALO FIRE DISPATCH
Contact Phone:	(716) 348-5380
Contact Ext:	
Latitude:	
Longitude:	

114	*1 of 1*	*NW*	*0.44 / 2,314.90*	*658.60 / 14*	***NATIONAL GRID ABOVE GROUND VAULT 916 DELWARE AVE BUFFALO NY***	***NY SPILLS***

Spill No:	2109996	**UST Trust:**	False
Site ID:	634027	**Spill Date:**	2022-02-25 15:50:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DER Facility ID:	580946	**Received Date:**	2022-02-25 16:09:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2022-07-15 00:00:00
Water Body:		**Create Date:**	2022-02-25 16:12:00
Class:		**Update Date:**	2022-07-15 10:50:00.453000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Transformer		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"2 cups mineral oil onto concrete floor clean up in progress slow leak possible"

DEC Remark:

"02/28/22 TDJ MINOR SPILL Lisa Montesano with National Grid notified the Department that they are not the owners of the transformers. They are owned by the property owner. They are very old and had a minor leak. It is unknown if they contain PCB's. The property owner will contact the Department with details on the cleanup. The environmental contractor is Turnkey Bryan Mayback. 07/14/22 TDJ SPOKE WITH BRYAN WHO STATED THAT JERREMY MITCHELL IS REP FOR OWNER (716)886-5300 OR (716)713-2934 AND WILL HAVE MORE INFORMATION ON PROJECT FOR VAULT SPILL. 07/14/22 TDJ MET OWNER OF COMPLEX AND FOUND X-FORMER SERVES (4) BLOCKS IN AREA AND THIS COMPANY LET THEM PUT THE VAULT IN THEIR BASEMENT, SMALL DRY STAIN WAS NOTED IN PICTURE DURING PHASE I WHICH NATIONAL GRID STATED WAS NOT A PROBLEM. NO FURTER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1381104	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2395082	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	2630		
Material Name:	mineral oil		

Spiller Information

Spiller Name:	LISA MONTESANO
Spiller Company:	NATIONAL GRID
Spiller Address:	916 DELWARE AVE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA MONTESANO
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	
Longitude:	

115	*1 of 2*	*NE*	*0.44 / 2,343.26*	*639.16 / -5*	***MASTEN SALES & SERVICES 247 MASTEN AVE. BUFFALO NY***	***NY SPILLS***

Spill No:	0813761	**UST Trust:**	

Site ID:	411459	**Spill Date:**	2009-03-20 12:00:00
DER Facility ID:	360677	**Received Date:**	2009-03-20 12:15:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2009-03-23 00:00:00
Water Body:		**Create Date:**	2009-03-20 12:28:00
Class:	D4	**Update Date:**	2009-03-23 08:45:47.027000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Deliberate		
Reported by:	Citizen		
Referred to:	LAW ENFORCEMENT		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER STATES THAT HE HAS SEEN EMPLOYEES DUMP ANT-FREZZE & TRANSMISSION FLUID IN A HOLE IN THE FLOOR,NEAR THE WASH BASINS."

DEC Remark:

"3/21/09 REFERRED SPILL REPORT TO THE DIVISION OF LAW ENFORCEMENT FOR FOLLOW UP. SPILL IS CLOSED. ELECTRONIC FILE ONLY."

Material Information

OP Unit ID:	1167935	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2159557	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0043A		
Material Name:	antifreeze		

OP Unit ID:	1167935	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2159558	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0021		
Material Name:	transmission fluid		

Spiller Information

Spiller Name:	
Spiller Company:	MASTEN SALES & SERVICES
Spiller Address:	247 MASTEN AVE.
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Ext:
Latitude: 42.909121453
Longitude: -78.859276778

---

115 **2 of 2** **NE** **0.44 / 2,343.26** **639.16 / -5** **MASTEN-RILEY STATION**
247 MASTEN AVENUE
BUFFALO NY **LST**

Spill No:	9601741	**REM Phase:**	0
Site ID:	205526	**UST Trust:**	True
DER Facility ID:	170654	**Spill Date:**	1996-05-03 09:15:00
CID:		**Rcvd Date:**	1996-05-03 10:53:00
Program Type:	ER	**CAC Date:**	
SWIS Code:	1502	**Insp Date:**	1996-05-03 00:00:00
Contribute Factor:	Tank Overfill	**Close Date:**	1996-05-03 00:00:00
Water Body:		**Create Date:**	1996-05-03 00:00:00
Class:	C3	**Update Date:**	2002-03-19 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
County:	Erie	**After Hours:**	False
Referred to:			
Reported by:	Responsible Party		
Source:	Gasoline Station or other PBS Facility		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"tank was being filled and petrolium gushed out at the end maybe a vent problem - stain on pavement - spill cleaned up using pads "

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 05/03/96: MNP INSP. SPOKE W/ STATION OWNER. SPILL CAUSED BY AIR LOCK IN VENT. KING PETROLEUM FINISHED DELIVERY WITHOUT ANY MORE PROBLEMS. AFTER INITIAL SPILL. ONLY STAINED BLACKTOP, NO DRAINS AFFECTED. CLEANUP USING SORBENT PADS SATISFACTORY.. NO FURTHER ACTION NEEDED, COMPLETE."

Material Information

OP Unit ID:	1033309	**Med in Air:**	False
OU:	01	**Med GW:**	False
Material ID:	351546	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	15.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	10.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	BILL ANDERSON
Spiller Company:	FRANCIS W KING PETROLEUM
Spiller Address:	370 ESSEX AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14207-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.908979980
Longitude:	-78.859596650

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
116	1 of 1	SSW	0.45 / 2,368.37	634.79 / -10	TRANSFORMER (PAD MOUNT) 641 ELLICOTT ST BUFFALO NY	NY SPILLS

Spill No:	1107814	**UST Trust:**	False
Site ID:	455525	**Spill Date:**	2011-09-20 08:30:00
DER Facility ID:	410100	**Received Date:**	2011-09-20 10:28:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2011-09-20 00:00:00
Water Body:		**Create Date:**	2011-09-20 10:31:00
Class:	D4	**Update Date:**	2011-09-20 11:02:30.353000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Spilled onto concrete pad. Cleanup pending per outage scheduling (could be 2 weeks)."

DEC Remark:

"9/20/11 MINOR SPILL. CLOSED. ELECTRONIC FILE ONLY."

Material Information

OP Unit ID:	1205673	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2202598	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0016A		
Material Name:	non PCB oil		

Spiller Information

Spiller Name:	LISA MONTESANTO
Spiller Company:	NATIONAL GRID
Spiller Address:	641 ELLICOTT ST
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA MONTESANTO
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	42.896412907
Longitude:	-78.868435232

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
117	1 of 1	NNE	0.45 / 2,377.99	637.91 / -7	NATURAL GAS AT RESIDENCE MICHIGAN & LAUREL STREET BUFFALO NY	NY SPILLS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Spill No:	9875375	**UST Trust:**	False
Site ID:	289514	**Spill Date:**	1999-01-25 12:00:00
DER Facility ID:	234445	**Received Date:**	1999-02-02 10:00:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1999-02-02 00:00:00
Water Body:		**Create Date:**	1999-02-02 10:03:00
Class:	E5	**Update Date:**	1999-10-08 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Citizen		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER SMELLS GAS FROM HOUSE AT MICHIGAN AND LAUREL."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 2/2/99 NOTIFIED NATIONAL FUEL OF THE REPORT. THEY WILL CALL MS. THOMAS AND LOOK INTO THE PROBLEM. NO FURTHER ACTION IS REQUIRED BY SPILLS. THE SITE CAN BE CLOSED."

Material Information

OP Unit ID:	1074806	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	307000	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	True		
Material Code:	0054A		
Material Name:	natural gas		

Spiller Information

Spiller Name:	
Spiller Company:	NONE
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.910225991
Longitude:	-78.862437940

118	1 of 1	NE	0.46 / 2,445.09	638.80 / -6	VACANT LOT CORNER OF RILEY @ MASTON BUFFALO NY	NY SPILLS

Spill No:	1507590	**UST Trust:**	
Site ID:	515084	**Spill Date:**	2015-10-20 13:00:00
DER Facility ID:	469515	**Received Date:**	2015-10-20 14:00:00
CID:		**CAC Date:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2015-10-21 00:00:00
Water Body:		**Create Date:**	2015-10-20 14:20:00
Class:		**Update Date:**	2015-10-21 13:07:02.040000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Housekeeping		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER STATES THAT THERE ARE NUMEROUS OLD CARS AND BUSSES PARKED ON VACANT LOT AND THERE IS A STRONG ODOR OF GASOLINE."

DEC Remark:

"10/21/15 TDJ REFERRED TO LAW ENFORCEMENT FOR INSPECTION, MET ECO PEINKOFER AT SITE WHICH IS AN OLD SERVICE STATION WHICH IS CURRENTLY OWNED AND USED AS A MECHANICAL SHOP. OLD VEHICLES ARE ON THE PAVED LOT WITH NO ODORS NOR STAINING FOUND. UST'S REMAIN ONSITE AND ARE CURRENT WITH STATE TESTING. SPOKE WITH OWNER WHO STATES THAT HE WORKS THERE ALONE. NO VIOLATIONS FOUND. TRIED TO CONTACT COMPLAINANT BUT WAS TOLD I HAD THE WRONG NUMBER. NO FURTHER ACTION FILE CLOSE TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1264253	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2268016	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	True		
Material Code:	0009		
Material Name:	gasoline		

Spill Data

Material Name:	gasoline
Material Family:	Petroleum
Quantity:	0
Units:	Gallons
Recovered:	0

119	*1 of 5*	*SSW*	*0.47 / 2,476.66*	*635.77 / -9*	***CENTURY CENTRE I 817 WASHINGTON ST BUFFALO NY 14203***	***RCRA TSD***

EPA Handler ID:	NYD002107399
Gen Status Universe:	VSG
Contact Name:	RON FARAVAUGH
Contact Address:	326, LOVELL PLACE, ERIE, PA, 16503, US
Contact Phone No and Ext:	814-392-4085
Contact Email:	
Contact Country:	US
Land Type:	Private
County Name:	ERIE
EPA Region:	02
Receive Date:	20170525

Location Latitude: 42.888145
Location Longitude: -78.872512

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: LDR - General
Violation Type: 268.A
Violation Determined Date: 19970127
Scheduled Compliance Date: 19970227
Return to Compliance: Observed
Actual Return to Compl: 19970211
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19970127
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 19980918
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 20030305
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19860312
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19991213
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19851114
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19860902
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20010131
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20010813
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19970110
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: LDR - General
Return to Compliance Date: 19970211
Evaluation Agency: State

Evaluation Start Date: 19850821
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19951106
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20011011
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070220
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator

Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801119
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Part A

Waste Code Details

Hazardous Waste Code: F008
Waste Code Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070221
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19920227
Handler Name: TRICO PRODUCTS CORP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19940517
Handler Name: TRICO PRODUCTS CORPORATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070220
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990714
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20170525
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19800818
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900301
Handler Name: TRICO PRODUCTS CORPORATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19960329
Handler Name: TRICO PRODUCTS CORPORATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20020320
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: U056
Waste Code Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Hazardous Waste Code: P029
Waste Code Description: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

Hazardous Waste Code: P121
Waste Code Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: B002
Waste Code Description: Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

Hazardous Waste Code: F007
Waste Code Description: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Hazardous Waste Code: U213
Waste Code Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Hazardous Waste Code:	F001
Waste Code Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Hazardous Waste Code:	F006
Waste Code Description:	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
Hazardous Waste Code:	U112
Waste Code Description:	ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	U228
Waste Code Description:	ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE
Hazardous Waste Code:	B006
Waste Code Description:	PCB transformers. PCB transformers means any transformer that contains 500 ppm PCB or greater.
Hazardous Waste Code:	F009
Waste Code Description:	SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.
Hazardous Waste Code:	F008
Waste Code Description:	PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.
Hazardous Waste Code:	P001
Waste Code Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Hazardous Waste Code:	D009
Waste Code Description:	MERCURY
Hazardous Waste Code:	U201
Waste Code Description:	1,3-BENZENEDIOL (OR) RESORCINOL
Hazardous Waste Code:	U239
Waste Code Description:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)
Hazardous Waste Code:	D000
Waste Code Description:	DESCRIPTION
Hazardous Waste Code:	U144
Waste Code Description:	ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE
Hazardous Waste Code:	U134
Waste Code Description:	HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)
Hazardous Waste Code:	U226
Waste Code Description:	ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM
Hazardous Waste Code:	U044
Waste Code Description:	CHLOROFORM (OR) METHANE, TRICHLORO-
Hazardous Waste Code:	U211
Waste Code Description:	CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-
Hazardous Waste Code:	B004
Waste Code Description:	PCB articles containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs, excluding small capacitors. This includes oil-filled electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers

and cable.

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: B005
Waste Code Description: PCB articles, other than transformers, that contain 500 ppm or greater of PCBs, excluding small capacitors.

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: U151
Waste Code Description: MERCURY

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	817 WASHINGTON ST
Name:	TRICO PRODUCTS CORPORATION	***Street 2:***	
Date Became Current:		***City:***	OPERCITY
Date Ended Current:		***State:***	NY
Phone:	716-852-5700	***Country:***	
Source Type:	Part A	***Zip Code:***	99999

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	1301 FRENCH ST
Name:	CENTURY CENTRE LTD PARTNERSHIP	***Street 2:***	
Date Became Current:		***City:***	ERIE
Date Ended Current:		***State:***	PA
Phone:	814-455-8717	***Country:***	
Source Type:	Notification	***Zip Code:***	16501

Historical Handler Details

Receive Dt: 19800818
Generator Code Description: Large Quantity Generator
Handler Name: CENTURY CENTRE I

Receive Dt: 19920227
Generator Code Description: Large Quantity Generator
Handler Name: TRICO PRODUCTS CORP

Receive Dt: 19940517
Generator Code Description: Large Quantity Generator
Handler Name: TRICO PRODUCTS CORPORATION

Receive Dt: 19801119
Generator Code Description: Not a Generator, Verified
Handler Name: CENTURY CENTRE I

Receive Dt: 20070220
Generator Code Description: Very Small Quantity Generator
Handler Name: CENTURY CENTRE I

Receive Dt: 20070221
Generator Code Description: Very Small Quantity Generator
Handler Name: CENTURY CENTRE I

Receive Dt: 19990714
Generator Code Description: Small Quantity Generator
Handler Name: CENTURY CENTRE I

Receive Dt: 20070220
Generator Code Description: Very Small Quantity Generator
Handler Name: CENTURY CENTRE I

Receive Dt: 19960329
Generator Code Description: Large Quantity Generator
Handler Name: TRICO PRODUCTS CORPORATION

Receive Dt: 19900301
Generator Code Description: Large Quantity Generator
Handler Name: TRICO PRODUCTS CORPORATION

Receive Dt: 20020320
Generator Code Description: Large Quantity Generator
Handler Name: CENTURY CENTRE I

119	2 of 5	SSW	0.47 / 2,476.66	635.77 / -9	CENTURY CENTRE I 817 WASHINGTON ST BUFFALO NY 14203	RCRA CORRACTS

EPA Handler ID: NYD002107399
Gen Status Universe: VSG
Contact Name: RON FARAVAUGH
Contact Address: 326, LOVELL PLACE, ERIE, PA, 16503, US
Contact Phone No and Ext: 814-392-4085
Contact Email:
Contact Country: US
County Name: ERIE
EPA Region: 02
Land Type: Private
Receive Date: 20170525
Location Latitude: 42.888145
Location Longitude: -78.872512

Event/Area Details

Area Name: SITEWIDE
Event Code: CA400
Corrective Action Event Descri: REMEDY DECISION
Actual Date of Event: 20170724
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20170724
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Area Name: SITEWIDE

Event Code:	CA999NF
Corrective Action Event Descri:	CA PROCESS IS TERMINATED-NO FURTHER ACTION
Actual Date of Event:	19881216
Orig Sched Event Date:	
New Sched Event Date:	
Best Date:	19881216
Groundwater Release Indicator:	
Soil Release Indicator:	
Air Release Indicator:	
Surface Waste Release Ind:	
Event Responsible Agency:	S

Area Name:	SITEWIDE
Event Code:	CA050
Corrective Action Event Descri:	RFA COMPLETED
Actual Date of Event:	19920922
Orig Sched Event Date:	
New Sched Event Date:	
Best Date:	19920922
Groundwater Release Indicator:	
Soil Release Indicator:	
Air Release Indicator:	
Surface Waste Release Ind:	
Event Responsible Agency:	E

Area Name:	SITEWIDE
Event Code:	CA070NO
Corrective Action Event Descri:	DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NOT NECESSARY
Actual Date of Event:	19881216
Orig Sched Event Date:	
New Sched Event Date:	
Best Date:	19881216
Groundwater Release Indicator:	
Soil Release Indicator:	
Air Release Indicator:	
Surface Waste Release Ind:	
Event Responsible Agency:	S

Area Name:	SITEWIDE
Event Code:	CA725YE
Corrective Action Event Descri:	HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Actual Date of Event:	20190920
Orig Sched Event Date:	
New Sched Event Date:	
Best Date:	20190920
Groundwater Release Indicator:	
Soil Release Indicator:	
Air Release Indicator:	
Surface Waste Release Ind:	
Event Responsible Agency:	S

Area Name:	SITEWIDE
Event Code:	CA070YE
Corrective Action Event Descri:	DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NECESSARY
Actual Date of Event:	19940719
Orig Sched Event Date:	
New Sched Event Date:	
Best Date:	19940719
Groundwater Release Indicator:	
Soil Release Indicator:	
Air Release Indicator:	
Surface Waste Release Ind:	
Event Responsible Agency:	E

Area Name:	SITEWIDE
Event Code:	CA050PA
Corrective Action Event Descri:	RFA COMPLETED-ASSESSMENT WAS A PA-PLUS
Actual Date of Event:	19881028
Orig Sched Event Date:	

New Sched Event Date:
Best Date: 19881028
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Area Name: SITEWIDE
Event Code: CA075LO
Corrective Action Event Descri: CA PRIORITIZATION-LOW CA PRIORITY
Actual Date of Event: 19940112
Orig Sched Event Date: 19940331
New Sched Event Date:
Best Date: 19940112
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: E

Area Name: SITEWIDE
Event Code: CA750YE
Corrective Action Event Descri: RELEASE TO GW CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Actual Date of Event: 20210607
Orig Sched Event Date:
New Sched Event Date:
Best Date: 20210607
Groundwater Release Indicator:
Soil Release Indicator:
Air Release Indicator:
Surface Waste Release Ind:
Event Responsible Agency: S

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov, 2022.

Violation Details

Found Violation: Yes
Citation:
Violation Short Description: LDR - General
Violation Type: 268.A
Violation Determined Date: 19970127
Scheduled Compliance Date: 19970227
Return to Compliance: Observed
Actual Return to Compl: 19970211
Violation Responsible Agency: State

Enforcement Details

Enforcement Type: 120
Enforcement Type Description: WRITTEN INFORMAL
Enforcement Action Date: 19970127
Enf Disposition Status:
Disposition Status Date:
Enforcement Lead Agency: State
Proposed Penalty Amount:
Final Amount:
Paid Amount:

Evaluation Details

Evaluation Start Date: 19970110
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: LDR - General
Return to Compliance Date: 19970211
Evaluation Agency: State

Evaluation Start Date: 19860902
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20011011
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20010813
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19991213
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19980918
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 20030305
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: EPA

Evaluation Start Date: 19860312
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19851114
Evaluation Type Description: NON-FINANCIAL RECORD REVIEW
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19951106
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20010131
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 19850821
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070221
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19940517
Handler Name: TRICO PRODUCTS CORPORATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19990714
Handler Name: CENTURY CENTRE I

Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20070220
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20170525
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Waste Code Details

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20020320
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F009
Waste Code Description: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Hazardous Waste Code: U226
Waste Code Description: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: P121
Waste Code Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Hazardous Waste Code: B004
Waste Code Description: PCB articles containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs, excluding small capacitors. This includes oil-filled electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: P029
Waste Code Description: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

Hazardous Waste Code: U144
Waste Code Description: ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE

Hazardous Waste Code: U239
Waste Code Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Code: B005
Waste Code Description: PCB articles, other than transformers, that contain 500 ppm or greater of PCBs, excluding small capacitors.

Hazardous Waste Code: F008
Waste Code Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Hazardous Waste Code: U044
Waste Code Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Hazardous Waste Code: P106
Waste Code Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: U201
Waste Code Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: B002
Waste Code Description: Petroleum oil or other liquid containing 50 ppm or greater of PCBs, but less than 500 ppm PCBs. This includes oil from electrical equipment whose PCB concentration is unknown, except for circuit breakers, reclosers and cable.

Hazardous Waste Code: B006
Waste Code Description: PCB transformers. PCB transformers means any transformer that contains 500 ppm PCB or greater.

Hazardous Waste Code: F006
Waste Code Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Hazardous Waste Code: P098
Waste Code Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Hazardous Waste Code: U211

Waste Code Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: P030
Waste Code Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Hazardous Waste Code: U056
Waste Code Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Hazardous Waste Code: U134
Waste Code Description: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: U228
Waste Code Description: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Hazardous Waste Code: F007
Waste Code Description: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: U112
Waste Code Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U151
Waste Code Description: MERCURY

Hazardous Waste Code: U213
Waste Code Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19920227
Handler Name: TRICO PRODUCTS CORP
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900301
Handler Name: TRICO PRODUCTS CORPORATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19801119
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Part A

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: F001
Waste Code Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F008
Waste Code Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070220
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19800818
Handler Name: CENTURY CENTRE I
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19960329
Handler Name: TRICO PRODUCTS CORPORATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	1301 FRENCH ST
Name:	CENTURY CENTRE LTD PARTNERSHIP	***Street 2:***	
Date Became Current:		***City:***	ERIE
Date Ended Current:		***State:***	PA
Phone:	814-455-8717	***Country:***	
Source Type:	Notification	***Zip Code:***	16501

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	817 WASHINGTON ST
Name:	TRICO PRODUCTS CORPORATION	***Street 2:***	
Date Became Current:		***City:***	OPERCITY
Date Ended Current:		***State:***	NY
Phone:	716-852-5700	***Country:***	
Source Type:	Part A	***Zip Code:***	99999

Historical Handler Details

Receive Dt:	20020320
Generator Code Description:	Large Quantity Generator
Handler Name:	CENTURY CENTRE I
Receive Dt:	20070221
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CENTURY CENTRE I
Receive Dt:	19801119
Generator Code Description:	Not a Generator, Verified
Handler Name:	CENTURY CENTRE I
Receive Dt:	19800818
Generator Code Description:	Large Quantity Generator
Handler Name:	CENTURY CENTRE I
Receive Dt:	20070220
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CENTURY CENTRE I
Receive Dt:	19920227
Generator Code Description:	Large Quantity Generator
Handler Name:	TRICO PRODUCTS CORP
Receive Dt:	19990714
Generator Code Description:	Small Quantity Generator
Handler Name:	CENTURY CENTRE I
Receive Dt:	19960329
Generator Code Description:	Large Quantity Generator
Handler Name:	TRICO PRODUCTS CORPORATION
Receive Dt:	19940517
Generator Code Description:	Large Quantity Generator
Handler Name:	TRICO PRODUCTS CORPORATION
Receive Dt:	19900301
Generator Code Description:	Large Quantity Generator
Handler Name:	TRICO PRODUCTS CORPORATION
Receive Dt:	20070220
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CENTURY CENTRE I

119	*3 of 5*	*SSW*	*0.47 / 2,476.66*	*635.77 / -9*	*TRICO 817 WASHINGTON STREET*	*NY SPILLS*

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					BUFFALO NY	

Spill No:	9212975	**UST Trust:**	False
Site ID:	230143	**Spill Date:**	1993-02-01 12:00:00
DER Facility ID:	189688	**Received Date:**	1993-02-17 12:30:00
CID:		**CAC Date:**	1993-02-19 00:00:00
Program Type:	ER	**Insp Date:**	1993-02-19 00:00:00
SWIS Code:	1502	**Close Date:**	1993-02-19 00:00:00
Water Body:		**Create Date:**	1993-02-22 00:00:00
Class:	A3	**Update Date:**	1993-02-23 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"PCB TRANSFORMERS LEAK. $500,000 CLEANUP PROJECT. 30,000 PPM PCB FROM SOME SAMPLES."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 02/19/93: RMC/KEVIN GLASER/RICHARD MELDRUM, TRICO/EVAN CASEY, OSEA/GARY BROWN,OSEA/SITE - INSPECTED TRANSFORMER AREAS. RP WILL SEND KEVIN G. WORK PLAN & SCHEDULE BY 2/26/93. NO LONGER SPILL ISSUE. CLOSE OUT. "

Material Information

OP Unit ID:	979976	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	402796	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		

Material Code: 0017A
Material Name: PCB oil

Spiller Information

Spiller Name:
Spiller Company: TRICO PRODUCTS
Spiller Address: 817 WASHINGTON STREET
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14203
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.895935510
Longitude: -78.869925640

119	4 of 5	SSW	0.47 / 2,476.66	635.77 / -9	TRICO PRODUCTS CORP. 817 WASHINGTON STREET BUFFALO NY 14203	PCB

Site ID:	NYD002107399	**Mail Address 1:**	817 WASHINGTON STREET

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Date:		**Mail Address 2:**	
Generator:	Yes	**Mail Street No:**	
Storer:	No	**Mail City:**	BUFFALO
Transporter:	No	**Mail State:**	NY
Disposer:	No	**Mail Zip:**	14203
Research:	No	**Mail Country:**	US
Smelter:	No	**Contact Name:**	TIM TOMPKINS
Cert Title:		**Contact Title:**	
Cert Date:	1/11/1994 12:00:00 AM	**Contact Phone:**	716-857-3052
Cert Name:		**Contact Phone Ext:**	
Location Country:	US	**Contact Email:**	
State Name:	NEW YORK	**Owner Name:**	TRICO PRODUCTS CORP.
Region:	02		

119	5 of 5	SSW	0.47 / 2,476.66	635.77 / -9	Century Centre I 817 Washington Street Buffalo NY 14203	ERP

Site Code:	446958
HW Code:	915249
Program:	RCRA
Site Class:	N
Site Name:	Century Centre I
Site Address:	817 Washington Street
City:	Buffalo
Zip:	14203
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.895806000
Longitude:	-78.869637000
SWIS:	1502
Acres:	
Record Added:	2011-03-22 11:16:00
Record Update:	2021-05-13 10:08:00
Updated by:	AECAPRIO
Site Code (Web):	915249
Program Type (Web):	RCRA
Site Name (Web):	Century Centre I
Site Class (Web):	N
Address1 (Web):	817 Washington Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14203
County (Web):	Erie
Longitude (Web):	-78.869637000
Latitude (Web):	42.895806000
Site Code (GIS):	915249
Site Name (GIS):	Century Centre I
Program (GIS):	RCRA
Site Class (GIS):	N
Address1 (GIS):	817 Washington Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14203
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to

Class A (active) to indicate that work has recommenced;

c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or

d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Site Location and Features: The Century Centre I site, better known as Trico Products Corporation?s Plant No. 1, is located at 817 Washington Street, Buffalo, Erie County, New York. It consists of several interconnected, multistory buildings covering 1-1/2 blocks. Manufacturing operations are carried out in the block bordered by Burton, Ellicottt, Goodell, and Washington Streets. Historical Uses: Trico manufactured windshield wiper components and assemblies in three plants in Buffalo; Plant No. 1 primarily manufactured components, including wiper arms, rubber blades and linkage systems. Plant No. 1 also made air pressure systems for heavy vehicles. Operations generating hazardous waste included: (1) plastic molding, (2) die casting (zinc alloy), and (3) metal finishing operations. Wastes included spent trichloroethene, ignitable solvents, Parcure Salt, asbestos (from pipe insulation renovation), spent solvents from degreasing, metal and cyanide-bearing sludges, and discarded PCB containing electrical components. The hazardous waste storage area was established by Trico Products Corporation in 1980 at Plant No. 1 for indoor storage of drummed hazardous waste. It was located on the first floor of a multi-story concrete and brick construction building, and was utilized to store spent solvent wastes and sludge wastes. Operations at the facility ceased in 1998 when the company moved its operations out west. Currently the build is undergoing renovation. The building was listed on the National Register of Historic Places in 2001.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs), including tetrachloroethene, trichloroethene, dichloroethenes, and vinyl chloride, PCBs, metals, including arsenic, barium, and mercury and polycyclic aromatic hydrocarbons (PAHs) in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in soil is being managed under a Site Management Plan. The certificate of completion for C915281 was issued in December 2019. The following activities took place during remedial action at C915281: 1) Removal and off-site disposal of approximately 171 tons of paint debris generated from hydro-blasting, 6 drums of various oils, and 51 oil-filled electrical equipment units. Additional removal actions included: • Removal and off-site disposal of 140,000 gallons of water and 10,682 tons of sludge from sub-basement and 7 drums of sediment from onsite sumps and sewer. • Removal and off-site disposal of crawl space sediments. • Removal of approximately 90 tons of asbestos. • Removal and off-site disposal of hydraulic lift parts, hydraulic oils and stained concrete. • Removal and off-site disposal of soil and concrete contaminated with polychlorinated bi-phenyls (PCBs). 2) Development of a Site Management Plan (SMP) for long-term management of residual contamination as required by the Environmental Easement, including plans for: (1) institutional and engineering controls (IC/ECs); (2) soil/fill management; (3) monitoring; and (4) reporting. 3) Recording of an Environmental Easement as an IC to prevent future exposure to any contamination remaining at the site and to ensure implementation of the SMP.

Environmental Remediation

Operable Unit: 02
Contaminants:

Operable Unit: 01
Contaminants:

120	1 of 1	NNW	0.47 / 2,488.69	659.62 / 15	KLENK RESIDENCE 293 LINWOOD AVENUE BUFFALO NY	NY SPILLS

Spill No:	9975538	***UST Trust:***	False
Site ID:	314267	***Spill Date:***	1999-11-19 23:00:00
DER Facility ID:	253403	***Received Date:***	1999-11-22 14:35:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2000-10-20 00:00:00
Water Body:		***Create Date:***	1999-11-22 14:43:00
Class:	D4	***Update Date:***	2000-11-29 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SORGI
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Traffic Accident		
Reported by:	Affected Persons		
Referred to:			
Source:	Passenger Vehicle		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CAR CRASHED THROUGH BACK YARD AND INTO CARS IN DRIVEWAY. ANTI-FREEZE AND MOTOR OIL IN YARD AND ON DRIVEWAY. COMPLAINANT CONCERNED ABOUT FATE OF HER PERENNIALS."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 11/22/99: MJS TELECON FROM CALLER. MJS ADVISED HER TO SCRAPE AWAY IMPACTED SOILS AND DISPOSED IN REGULAR WASTE STREAM. REIMBURSEMENT FOR DAMAGES SHOULD BE PURSUED THROUGH INSURANCE COMPANIES. 10/20/00: MJS REVIEW FILE. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE."

Material Information

OP Unit ID:	1093887	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	290062	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Other	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0043A		
Material Name:	antifreeze		

OP Unit ID:	1093887	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	290061	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN MOTORIST
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	PATRICIA KLENK
Contact Phone:	(716) 884-2649
Contact Ext:	
Latitude:	42.910338580
Longitude:	-78.868414960

121	1 of 1	SW	0.48 / 2,513.30	636.04 / -8	FLYNN'S BAR AND GRILL 815 MAIN STREET BUFFALO NY	NY SPILLS

Spill No:	8803675	**UST Trust:**	False
Site ID:	187489	**Spill Date:**	1988-07-27 18:00:00
DER Facility ID:	156645	**Received Date:**	1988-07-27 20:41:00
CID:		**CAC Date:**	1989-10-02 00:00:00
Program Type:	ER	**Insp Date:**	1989-07-27 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	1502	**Close Date:**	1989-10-02 00:00:00
Water Body:		**Create Date:**	1988-08-03 00:00:00
Class:		**Update Date:**	1989-11-08 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Fire Department		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"BUFFALO FIRE DEPT. CALLED TO 815 MAIN DUE GASOLINE FUMES IN BASEMENT"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : . / / : TEST HISTORY. 08/03/88: MNP SITE INSPECTION 7/28/88 HIGH READINGS ON HNU METER HIRED NEPCCO TO EXCAVATE HOLE ADJACENT TO BLDG TO RELIEVE VAPORS, VAPORS DETECTED IN EXCAVATION, 8/2/88 NO VAPORS DETECTED ANYWHERE AT SITE. 08/04/88: RNL SITE INSP. 08/04/88, SOIL STILL ON SITE, NO ODOR NOTED ON EXTERIOR OR FROM SOIL. 08/09/88: 8/9/88 RNL TELECON W/E&E , VERBAL SAMPLE RESULTS, NO PETRO. DETECTED, NON-IGNITABLE. 08/10/88: 8/10/88 MNP TELECON W/NEPCCO, THEY WILL START PAPERWORK FOR DISPOSAL, I WILL FORWARD SAMPLE RESULTS ASAP, HOLE TO BE BACKFILLED SOON. 08/11/88: 8/11/88 MNP TELECON W/DIOCESES, PROVIDED UPDATE;MNP INSP. NO ODORS OR READINGS ON HNU DETECTED IN BAR, 10-15 PPM IN PILE OF SOIL;MNP TELECON W/NEPCCO, DISPOSAL SET & HOLE TO BE BACKFILLED NEXT WEEK. 11/21/88: TEST # 2 EDITED. 11/21/88: TEST ADD HISTORY RECORD. 10/02/89: 10/2/89 MNP REVIEW OF FILE, FINAL PAYMENT PACKAGE COMPLETED 9/14/89, RNL TO SEND ISR TO ALBANY, COMPLETE. "

Material Information

OP Unit ID:	920843	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	459215	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.896145993
Longitude:	-78.870892023

122	1 of 1	SSE	0.48 / 2,520.67	622.80 / -22	NATIONAL FUEL GAS 73 MULBERRY STREET BUFFALO NY	NY SPILLS

Spill No:	9200310	**UST Trust:**	False
Site ID:	106887	**Spill Date:**	1992-04-08 13:50:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DER Facility ID:	94079	**Received Date:**	1992-04-08 14:23:00
CID:		**CAC Date:**	1992-04-08 00:00:00
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	1992-04-08 00:00:00
Water Body:		**Create Date:**	1992-04-08 00:00:00
Class:	D3	**Update Date:**	1992-08-06 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	PRINGLE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"HYDRAULIC FLUID SPILLED FROM HOSE OF BACKHOE ONTO STREET."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 04/02/92: 4/2/92 MNP RECEIVED REPORT, RESP. PARTY CLEANING UP, NO FURTHER ACTION BY DEC NEEDED, COMPLETE. 09/29/95: This is additional information about material spilled from the translation of the old spill file: HYDRAULIC FLUID."

Material Information

OP Unit ID:	964276	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	415117	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	3.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	3.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	NATIONAL FUEL GAS
Spiller Address:	LAYFAYETTE SQUARE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.895301340
Longitude:	-78.862587410

123	*1 of 2*	*W*	*0.49 / 2,564.59*	*660.28 / 16*	***AMBASSADOR APTS TANK 175 NORTH STREET BUFFALO NY***	***NY SPILLS***

Spill No:	9607625	**UST Trust:**	False
Site ID:	321361	**Spill Date:**	1996-09-17 16:10:00
DER Facility ID:	258883	**Received Date:**	1996-09-17 16:12:00
CID:	252	**CAC Date:**	
Program Type:	ER	**Insp Date:**	2001-01-11 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SWIS Code:	1502	**Close Date:**	2001-01-11 00:00:00
Water Body:		**Create Date:**	1996-09-17 00:00:00
Class:	E6	**Update Date:**	2002-03-12 00:00:00
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Citizen		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"tank in ground leaking into soil-tank has been there since 1929 and caller feels that due to its age it is now causing a problem "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/18/96: MJS TELECON TO CALLER (MR HERKEY). LEFT MESSAGE ON ANSWERING MACHINE. 09/26/96: MJS TELECON FROM MR HERKEY. HE STATED THAT HE USED TO WORK AT THE APARTMENT BUILDING. FILL PIPE IS COVERED WITH BLACKTOP. BOILER HAS NOT BEEN USED IN OVER FIVE YEARS. PRODUCT GAUGE INSIDE BUILDING IS DROPPING (TANK LOSING PRODUCT). ALSO, THERE IS AN ELECTRICAL ROOM ACROSS FROM BOILER ROOM WITH OLD LEAKING TRANSFORMERS (POSSIBLE PCB'S). 11/17/00 RMC/FILE - REVIEWED FILE AS MJS LEFT THE DEPT., COMPLAINT MORE THAN FOUR YEARS OLD, NO REASONABLE ACTION DUE TO THE PASSAGE OF TIME, CLOSE OUT 01/08/01: RNL FILE REVIEW, BELIEVES SITE NEEDS AN INSPECTION EVEN THOUGH FIVE YEARS LATE, REFERRED BACK TO RMC 01/11/01 RMC/SITE - MET HOUSEKEEPER WHO CONTACTED MARK STRAHIN, MAINTENANCE SUPERVISOR, 716-882-2787, VIA PHONE, STRAHIN KNOWS OF NO PROBLEM, RMC CHECKED BOILER ROOM, DUAL HEATING SYSTEM, OIL AND NATURAL GAS, UST ELEVATED ON TWO SIDES BY BASEMENT AND ADJACENT PROPERTY, NO OIL NOTED EITHER SPOT OR IN SUMPS, NO ACTION REQUIRED, CLOSE OUT "

Material Information

OP Unit ID:	1038784	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	346884	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	NONE
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JACQUELINE LAOUSSO
Contact Phone:	(716) 884-3913
Contact Ext:	
Latitude:	42.902275360
Longitude:	-78.875736020

123	2 of 2	W	0.49 / 2,564.59	660.28 / 16	KISSLING INTERESTS LLC 175 NORTH BUFFALO NY	NY SPILLS

Spill No:	2006097	**UST Trust:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site ID:	611918	**Spill Date:**	2020-10-01 12:00:00
DER Facility ID:	560032	**Received Date:**	2020-10-06 09:30:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2020-10-06 00:00:00
Water Body:		**Create Date:**	2020-10-06 10:07:00
Class:	D4	**Update Date:**	2020-10-08 12:10:11.547000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"Labella submitted a Phase II report with groundwater sample results slightly above groundwater standards at two locations near a closed in place 6000 gallon #6fuel oil ust."

DEC Remark:

"10/6/20 Labella submitted a Phase II report for the site. A 6000 gal #6 fuel oil ust is on site and had been previously closed in place. Borings were advanced on the property. The soil sample results were all below CP51. All groundwater sample results were below standards except at two locations near the fuel oil ust. The results exceed standards by a minor amount. No further action is required. The site is inactive."

Material Information

OP Unit ID:	1359062	**Med Ind Air:**	False
OU:	01	**Med GW:**	True
Material ID:	2370531	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	Kissling interests llc
Spiller Address:	298 Main St Suite 222
Spiller City:	buffalo
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

124	*1 of 1*	*NNW*	*0.49 / 2,571.77*	*659.61 / 15*	*NATIONAL GRID 301 LINWOOD AVE BUFFALO NY*	*NY SPILLS*

Spill No:	0605499	**UST Trust:**	False
Site ID:	368669	**Spill Date:**	2006-08-10 22:00:00
DER Facility ID:	318571	**Received Date:**	2006-08-10 22:41:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CID:	64	**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2006-08-11 00:00:00
Water Body:		**Create Date:**	2006-08-11 02:08:00
Class:	D4	**Update Date:**	2006-08-11 12:21:06.043000000
Meets Std:	True	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	RMCROSSE
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"1 Pint spilled. Clean up will be first thing in the morning. Non-PCB."

DEC Remark:

"08/11/06 RMC/FILE. MINOR SPILL NO ACTION REQUIRED, CLOSE OUT. NO PAPER FILE. "

Material Information

OP Unit ID:	1126536	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2116076	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	
Spiller Company:	NATIONAL GRID
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	LISA FREDERICKS
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	42.910661509
Longitude:	-78.867666802

125	*1 of 3*	***SSW***	***0.49 / 2,574.88***	***633.88 / -11***	***Former Trico Plant 791 Washington Street Buffalo NY 14203***	***BROWNFIELDS***

Site Code:	485846
HW Code:	C915281
Program:	BCP
Site Class:	C
Site Name:	Former Trico Plant
Site Address:	791 Washington Street
City:	Buffalo
Zip:	14203

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.895333333
Longitude:	-78.869666667
SWIS:	1502
Acres:	2.110
Record Added:	2013-08-15 13:32:00
Record Update:	2022-06-08 16:35:00
Updated by:	AECAPRIO
Site Code (Web):	C915281
Program Type (Web):	BCP
Site Name (Web):	Former Trico Plant
Site Class (Web):	C
Address1 (Web):	791 Washington Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14203
County (Web):	Erie
Longitude (Web):	-78.869666667
Latitude (Web):	42.895333333
Site Code (GIS):	C915281
Site Name (GIS):	Former Trico Plant
Program (GIS):	BCP
Site Class (GIS):	C
Address1 (GIS):	791 Washington Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14203
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH:	Measures are in place to address contact with residual groundwater and soil contaminants. As the site is currently vacant, no contact with contaminants in the concrete slab of the parking structure are expected. Volatile organic compounds in the contaminated groundwater or contaminated soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. While the building is unoccupied, no contact with site contaminants in indoor air is expected. However, a subslab depressurization systems (systems that ventilate/remove the air beneath the building) will be installed in onsite building prior to occupancy to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building.

Description:

Location: The Former Trico Plant site is an approximately 2.11-acre site located in a densely developed urban area at 791 Washington Street in the City of Buffalo, Erie County. The property is bounded by commercial and residential properties to the north, Ellicott Street and a parking lot to the east, Goodell Street and Eastman Machine Company to the south and Washington Street and commercial and residential properties to the west. Site Features: The site consists of a complex of five industrial buildings totaling 617,627 square feet and a small portion of the former Burton Street. Current Zoning and Land Use: The site is zoned for commercial use and is currently vacant. Past Use of the Site: The oldest of the five buildings was constructed circa 1890 as a portion of the Christian Weyand Brewery which operated at the site until the enactment of prohibition. The building was purchased in 1920 by Trico Products Corporation for the manufacturing of windshield wipers for the automotive industry. The remaining buildings were constructed from 1920 to 1954. The Trico Products Corporation operated at the site until 1990. Operations included electroplating, smelting, die-casting, rubber extrusion and metal fabrication. Site Geology and Hydrogeology: The site primarily consists of a building. Below the concrete building slab, there is a 2-3 inch layer of fill material consisting of black fine to course sand with ash. This is underlain with native soils generally consisting of a varying thickness and alternating layers of reddish-brown sandy lean clays and sandy silts to depths of 40 feet below the building floor. The bedrock consists of Onondaga Formation which has an approximate thickness of 110 to 160 feet. The depth to groundwater below the building basement floor is approximately 1.65 feet. Regional groundwater flow is estimated west toward Lake Erie.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs), including tetrachloroethene, trichloroethene, dichloroethenes, and vinyl chloride, PCBs, metals, including arsenic, barium, and mercury and polycyclic aromatic hydrocarbons (PAHs) in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in soil is being managed under a Site Management Plan.

Materials Information

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 06
Sub Type: P03
Owner Name: mike mcguigan
Owner Company: 791 Washington Street, LLC
Owner Street:
Owner Street 2: 4 centre drive
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Mary Jean Jakubowski
Owner Company: Buffalo and Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:

Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Peter Krog, Sr.
Owner Company: 791 Washington Street, LLC
Owner Street: 4 Centre Drive
Owner Street 2:
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Peter L. Krog, Sr.
Owner Company: 847 Main Street, LLC
Owner Street: 4 Centre Drive
Owner Street 2:
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Dell:
Updated By: JSWALIA
Record Added: 2013-08-15 14:21:00
Record Updated: 2019-12-09 09:51:00
Disposal Start:
Disposal Terminate:
Latitude:
Longitude:

Projects Information

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2019-12-26 00:00:00
End Status: ACT
Operable Unit ID: 1235503
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2017-07-24 00:00:00
End Status: ACT
Operable Unit ID: 1235503
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2019-12-26 00:00:00
End Status: ACT
Operable Unit ID: 1346820
Operable Unit: 00
Operable Unit Desc: Site Management Plan

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Code Name: Certificate of Completion

Environmental Remediation

Operable Unit: 01
Contaminants: arsenic, barium, dichloroethene (cis-1,2-), dichloroethene (trans-1,2-), mercury, polychlorinated biphenyls (PCB), polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

Operable Unit: 00
Contaminants: arsenic, barium, dichloroethene (cis-1,2-), dichloroethene (trans-1,2-), mercury, polychlorinated biphenyls (PCB), polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
125	2 of 3	SSW	0.49 / 2,574.88	633.88 / -11	Former Trico Plant 791 Washington Street Buffalo NY 14203	INST

Site Code: 485846
HW Code: C915281
Control Type: INST
Program: BCP
Site Class: C
Site Name: Former Trico Plant
Site Address: 791 Washington Street
City: Buffalo
Zip: 14203
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.895333333
Longitude: -78.869666667
SWIS: 1502
Acres: 2.110
Record Added: 2013-08-15 13:32:00
Record Updated: 2022-06-08 16:35:00
Updated By: AECAPRIO
Site Code (Web): C915281
Program Type (Web): BCP
Site Class (Web): C
Site Name (Web): Former Trico Plant
Address1 (Web): 791 Washington Street
Address2 (Web):
Locality (Web): Buffalo
Zip Code (Web): 14203
County (Web): Erie
Longitude (Web): -78.869666667
Latitude (Web): 42.895333333
Site Code (GIS): C915281
Program (GIS): BCP
Site Class (GIS): C
Site Name (GIS): Former Trico Plant
Address 1 (GIS): 791 Washington Street
Address 2 (GIS):
Locality (GIS): Buffalo
Zip Code (GIS): 14203
County (GIS): Erie
Latitude (GIS):
Longitude (GIS):
Site Class Desc:
Site Class Desc (Web): Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department. These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).
Assess DOH: Measures are in place to address contact with residual groundwater and soil contaminants. As the site is currently

vacant, no contact with contaminants in the concrete slab of the parking structure are expected. Volatile organic compounds in the contaminated groundwater or contaminated soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. While the building is unoccupied, no contact with site contaminants in indoor air is expected. However, a subslab depressurization systems (systems that ventilate/remove the air beneath the building) will be installed in onsite building prior to occupancy to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building.

Description:

Location: The Former Trico Plant site is an approximately 2.11-acre site located in a densely developed urban area at 791 Washington Street in the City of Buffalo, Erie County. The property is bounded by commercial and residential properties to the north, Ellicott Street and a parking lot to the east, Goodell Street and Eastman Machine Company to the south and Washington Street and commercial and residential properties to the west. Site Features: The site consists of a complex of five industrial buildings totaling 617,627 square feet and a small portion of the former Burton Street. Current Zoning and Land Use: The site is zoned for commercial use and is currently vacant. Past Use of the Site: The oldest of the five buildings was constructed circa 1890 as a portion of the Christian Weyand Brewery which operated at the site until the enactment of prohibition. The building was purchased in 1920 by Trico Products Corporation for the manufacturing of windshield wipers for the automotive industry. The remaining buildings were constructed from 1920 to 1954. The Trico Products Corporation operated at the site until 1990. Operations included electroplating, smelting, die-casting, rubber extrusion and metal fabrication. Site Geology and Hydrogeology: The site primarily consists of a building. Below the concrete building slab, there is a 2-3 inch layer of fill material consisting of black fine to course sand with ash. This is underlain with native soils generally consisting of a varying thickness and alternating layers of reddish-brown sandy lean clays and sandy silts to depths of 40 feet below the building floor. The bedrock consists of Onondaga Formation which has an approximate thickness of 110 to 160 feet. The depth to groundwater below the building basement floor is approximately 1.65 feet. Regional groundwater flow is estimated west toward Lake Erie.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs), including tetrachloroethene, trichloroethene, dichloroethenes, and vinyl chloride, PCBs, metals, including arsenic, barium, and mercury and polycyclic aromatic hydrocarbons (PAHs) in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in soil is being managed under a Site Management Plan.

Controls Information

Control Code:	25	***Record Added Date:***	2017-11-20 13:31:28.323000000
Control Name:	Landuse Restriction	***Record Updated Dt:***	2022-04-08 14:13:49.540000000
Control Type:	INST	***In Place Date:***	2019-10-31 00:00:00
Updated By:	MEKUCZKA		
Control Code:	08	***Record Added Date:***	2017-11-20 13:31:28.323000000
Control Name:	Ground Water Use Restriction	***Record Updated Dt:***	2022-04-08 14:13:49.540000000
Control Type:	INST	***In Place Date:***	2019-10-31 00:00:00
Updated By:	MEKUCZKA		
Control Code:	J	***Record Added Date:***	2017-11-20 13:31:28.323000000
Control Name:	Environmental Easement	***Record Updated Dt:***	2022-04-08 14:13:49.540000000
Control Type:	INST	***In Place Date:***	2019-10-31 00:00:00
Updated By:	MEKUCZKA		
Control Code:	32	***Record Added Date:***	2017-11-20 13:31:28.323000000
Control Name:	Site Management Plan	***Record Updated Dt:***	2022-04-08 14:13:49.540000000
Control Type:	INST	***In Place Date:***	2019-10-31 00:00:00
Updated By:	MEKUCZKA		
Control Code:	31	***Record Added Date:***	2017-11-20 13:31:28.323000000
Control Name:	Monitoring Plan	***Record Updated Dt:***	2022-04-08 14:13:49.540000000
Control Type:	INST	***In Place Date:***	2019-10-31 00:00:00
Updated By:	MEKUCZKA		
Control Code:	33	***Record Added Date:***	2017-11-20 13:31:28.323000000
Control Name:	O&M Plan	***Record Updated Dt:***	2022-04-08 14:13:49.540000000
Control Type:	INST	***In Place Date:***	2019-10-31 00:00:00
Updated By:	MEKUCZKA		
Control Code:	34	***Record Added Date:***	2017-11-20 13:31:28.323000000
Control Name:	IC/EC Plan	***Record Updated Dt:***	2022-04-08 14:13:49.540000000
Control Type:	INST	***In Place Date:***	2019-10-31 00:00:00
Updated By:	MEKUCZKA		

Control Code:	14	**Record Added Date:**	2017-11-20 13:31:28.323000000
Control Name:	Soil Management Plan	**Record Updated Dt:**	2022-04-08 14:13:49.540000000
Control Type:	INST	**In Place Date:**	2019-10-31 00:00:00
Updated By:	MEKUCZKA		

Materials Information

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 19
Sub Type: NNN
Owner Name: Mary Jean Jakubowski
Owner Company: Buffalo and Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14203
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Peter Krog, Sr.

Owner Company: 791 Washington Street, LLC
Owner Street: 4 Centre Drive
Owner Street 2:
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Peter L. Krog, Sr.
Owner Company: 847 Main Street, LLC
Owner Street: 4 Centre Drive
Owner Street 2:
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: mike mcguigan
Owner Company: 791 Washington Street, LLC
Owner Street:
Owner Street 2: 4 centre drive
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disposal Start:
Disposal Terminate:
Dell:
Updated By: JSWALIA
Record Added: 2013-08-15 14:21:00
Record Updated: 2019-12-09 09:51:00
Latitude:
Longitude:

Projects Information

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2019-12-26 00:00:00
End Status: ACT
Operable Unit ID: 1346820
Operable Unit: 00
Operable Unit Desc: Site Management Plan
Code Name: Certificate of Completion

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2017-07-24 00:00:00
End Status: ACT
Operable Unit ID: 1235503
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2019-12-26 00:00:00
End Status: ACT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operable Unit ID: 1235503
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Environmental Remediation

Operable Unit: 01
Contaminants: arsenic, barium, dichloroethene (cis-1,2-), dichloroethene (trans-1,2-), mercury, polychlorinated biphenyls (PCB), polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

Operable Unit: 00
Contaminants: arsenic, barium, dichloroethene (cis-1,2-), dichloroethene (trans-1,2-), mercury, polychlorinated biphenyls (PCB), polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

---

125	3 of 3	SSW	0.49 / 2,574.88	633.88 / -11	**Former Trico Plant** **791 Washington Street** **Buffalo NY 14203**	ENG

Site Code: 485846
HW Code: C915281
Control Type: ENG
Program: BCP
Site Class: C
Site Name: Former Trico Plant
Site Address: 791 Washington Street
City: Buffalo
Zip: 14203
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.895333333
Longitude: -78.869666667
SWIS: 1502
Acres: 2.110
Record Added: 2013-08-15 13:32:00
Record Updated: 2022-06-08 16:35:00
Updated By: AECAPRIO
Site Code (Web): C915281
Program Type (Web): BCP
Site Class (Web): C
Site Name (Web): Former Trico Plant
Address1 (Web): 791 Washington Street
Address2 (Web):
Locality (Web): Buffalo
Zip Code (Web): 14203
County (Web): Erie
Longitude (Web): -78.869666667
Latitude (Web): 42.895333333
Site Code (GIS): C915281
Program (GIS): BCP
Site Class (GIS): C
Site Name (GIS): Former Trico Plant
Address 1 (GIS): 791 Washington Street
Address 2 (GIS):
Locality (GIS): Buffalo
Zip Code (GIS): 14203
County (GIS): Erie
Latitude (GIS):
Longitude (GIS):
Site Class Desc:
Site Class Desc (Web): Complete: The classification used for sites where the Department has determined that remediation has been satisfactorily completed under a remedial program (i. e., State Superfund, Brownfield Cleanup Program, Environmental Restoration Program, Voluntary Cleanup Program, and RCRA Corrective Action Program). State Superfund (Registry) sites must have completed all active operation, maintenance, or monitoring requirements before they can be delisted and made class C. Non-registry sites may be made a class C after successful completion of all required construction or after a no further action remedy has been selected by the Department.

These sites will be issued a Certificate of Completion (COC), but may still require ongoing maintenance and periodic certification of institutional/engineering controls (IC/ECs).

Assess DOH: Measures are in place to address contact with residual groundwater and soil contaminants. As the site is currently vacant, no contact with contaminants in the concrete slab of the parking structure are expected. Volatile organic compounds in the contaminated groundwater or contaminated soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. While the building is unoccupied, no contact with site contaminants in indoor air is expected. However, a subslab depressurization systems (systems that ventilate/remove the air beneath the building) will be installed in onsite building prior to occupancy to prevent the indoor air quality from being affected by the contamination in soil vapor beneath the building.

Description:

Location: The Former Trico Plant site is an approximately 2.11-acre site located in a densely developed urban area at 791 Washington Street in the City of Buffalo, Erie County. The property is bounded by commercial and residential properties to the north, Ellicott Street and a parking lot to the east, Goodell Street and Eastman Machine Company to the south and Washington Street and commercial and residential properties to the west. Site Features: The site consists of a complex of five industrial buildings totaling 617,627 square feet and a small portion of the former Burton Street. Current Zoning and Land Use: The site is zoned for commercial use and is currently vacant. Past Use of the Site: The oldest of the five buildings was constructed circa 1890 as a portion of the Christian Weyand Brewery which operated at the site until the enactment of prohibition. The building was purchased in 1920 by Trico Products Corporation for the manufacturing of windshield wipers for the automotive industry. The remaining buildings were constructed from 1920 to 1954. The Trico Products Corporation operated at the site until 1990. Operations included electroplating, smelting, die-casting, rubber extrusion and metal fabrication. Site Geology and Hydrogeology: The site primarily consists of a building. Below the concrete building slab, there is a 2-3 inch layer of fill material consisting of black fine to course sand with ash. This is underlain with native soils generally consisting of a varying thickness and alternating layers of reddish-brown sandy lean clays and sandy silts to depths of 40 feet below the building floor. The bedrock consists of Onondaga Formation which has an approximate thickness of 110 to 160 feet. The depth to groundwater below the building basement floor is approximately 1.65 feet. Regional groundwater flow is estimated west toward Lake Erie.

Assessment:

Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were chlorinated volatile organic compounds (VOCs), including tetrachloroethene, trichloroethene, dichloroethenes, and vinyl chloride, PCBs, metals, including arsenic, barium, and mercury and polycyclic aromatic hydrocarbons (PAHs) in soil. Remedial actions have successfully achieved soil cleanup objectives for restricted residential use. Residual contamination in soil is being managed under a Site Management Plan.

Controls Information

Control Code: 13
Control Name: Vapor Mitigation
Control Type: ENG
Updated By: MEKUCZKA
Record Added Date: 2017-11-20 13:31:28.323000000
Record Updated Dt: 2022-04-08 14:13:49.540000000
In Place Date: 2019-10-31 00:00:00

Control Code: 15
Control Name: Cover System
Control Type: ENG
Updated By: MEKUCZKA
Record Added Date: 2017-11-20 13:31:28.323000000
Record Updated Dt: 2022-04-08 14:13:49.540000000
In Place Date: 2019-10-31 00:00:00

Materials Information

Waste Name: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dichloroethene (cis-1,2-)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polychlorinated biphenyls (PCB)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: mercury
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: arsenic
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: barium
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: polycyclic aromatic hydrocarbons (PAHS), total
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: dichloroethene (trans-1,2-)
Waste Quantity: UNKNOWN
Waste Code:

Waste Name: 1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 06
Sub Type: P03
Owner Name: mike mcguigan
Owner Company: 791 Washington Street, LLC
Owner Street:
Owner Street 2: 4 centre drive
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

Owner Op: 06
Sub Type: P03
Owner Name: Peter L. Krog, Sr.
Owner Company: 847 Main Street, LLC
Owner Street: 4 Centre Drive
Owner Street 2:
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

Owner Op: 01
Sub Type: E
Owner Name: Peter Krog, Sr.
Owner Company: 791 Washington Street, LLC
Owner Street: 4 Centre Drive
Owner Street 2:
Owner City: Orchard Park
Owner State: NY
Owner Zip: 14127
Country: United States of America

Owner Op: 19
Sub Type: NNN
Owner Name: Mary Jean Jakubowski
Owner Company: Buffalo and Erie County Public Library
Owner Street: 1 Lafayette Square
Owner Street 2:
Owner City: Buffalo
Owner State: NY

Owner Zip: 14203
Country: United States of America

HW Extra Information

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disposal Start:
Disposal Terminate:

Dell:
Updated By: JSWALIA
Record Added: 2013-08-15 14:21:00
Record Updated: 2019-12-09 09:51:00
Latitude:
Longitude:

Projects Information

Project Code: 25
Project Desc:
Project Refer Name:
End Date: 2019-12-26 00:00:00
End Status: ACT
Operable Unit ID: 1346820
Operable Unit: 00
Operable Unit Desc: Site Management Plan
Code Name: Certificate of Completion

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 2019-12-26 00:00:00
End Status: ACT
Operable Unit ID: 1235503
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Action

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 2017-07-24 00:00:00
End Status: ACT
Operable Unit ID: 1235503
Operable Unit: 01
Operable Unit Desc: Remedial Program
Code Name: Remedial Investigation

Environmental Remediation

Operable Unit: 00
Contaminants: arsenic, barium, dichloroethene (cis-1,2-), dichloroethene (trans-1,2-), mercury, polychlorinated biphenyls (PCB), polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

Operable Unit: 01
Contaminants: arsenic, barium, dichloroethene (cis-1,2-), dichloroethene (trans-1,2-), mercury, polychlorinated biphenyls (PCB), polycyclic aromatic hydrocarbons (PAHS), total, tetrachloroethene (PCE), trichloroethene (TCE), vinyl chloride

126	1 of 1	E	0.49 / 2,599.98	666.76 / 22	FORMER RESIDENCE 1022 JEFFERSON AVE BUFFALO NY	NY SPILLS

Spill No: 0175376
Site ID: 261371
DER Facility ID: 213459
CID:
Program Type: ER
SWIS Code: 1502

UST Trust: False
Spill Date: 2001-10-01 12:00:00
Received Date: 2001-10-16 10:00:00
CAC Date:
Insp Date: 2001-10-17 00:00:00
Close Date: 2001-11-13 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Body:		**Create Date:**	2001-10-16 10:04:00
Class:	C3	**Update Date:**	2001-11-26 00:00:00
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	JFOTTO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Local Agency		
Referred to:			
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER STATES HE DISCOVERED A HEATING OIL TANK (275 GALLON) WHILE DEMOLISHING A HOUSE FOR THE CITY OF BUFFALO. BISON OIL HAS BEEN CALLED TO REMOVE ANY PRODUCT IN THE TANK."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JFO 10/16/01 JFO SPOKE WITH CALLER. HE WILL CALL BACK AFTER BISON REMOVES THE PRODUCT AND HE UNCOVERS THE TANK. I EXPLAINED TO HIM HE MUST SAMPLE THE EXCAVATION. 10/17/01 JFO CALL FROM JASON HIBBARD. BISON WASTE OIL PUMPED OUT THE TANK AND REMOVED APPROX 25 GALLONS OF PRODUCT. JASON WILL REMOVE THE TANK AND PLACE ANY CONTAM SOIL ON PLASTIC AND COVER. I WILL INSPECT THE PIT AT NOON TODAY. JFO ON SITE MET WITH JASON H. THERE IS NO SPILLAGE. THE PIT LOOKS GOOD NO ODOR OR DISCOLORATION TO THE SOIL. A SAMPLE WILL BE COLLECTED FROM THE BOTTOM OF THE EXCAVATION ONLY. THEY WILL ANALYZE FOR 8021 AND 8270 STARS. THERE ARE 3 LARGE CYLINDERS AND 2 GRILL SIZE PROPANE TANKS ON SITE. (1-OXYGEN AND 2 POSSIBLE ACETYLENE). JASON H WILL CONTACT MODERN FOR DISPOSAL. 11/13/01 JFO REC'D DISPOSAL RECEIPTS FOR THE CYLINDERS, TANK AND OIL THAT WAS PUMPED FROM THE TANK. ALSO REC'D THE ANALYTICAL INDICATING THIS SITE WILL BE INACTIVE . BASE NEUTRALS ARE SLIGHTLY ABOVE STARS AND BENZO[A] PYRENE SLIGHTLY EXCEEDS TAGMS. NO FURTHER ACTION REQUIRED AT THIS TIME. SENT INACTIVE LETTER. CLOSED"

Material Information

OP Unit ID:	850740	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	524699	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	True	**Oxygenate:**	
Med Air:	False		
Material Code:	0002A		
Material Name:	#4 fuel oil		

Spiller Information

Spiller Name:	DON GRZEBIELUCHA
Spiller Company:	CITY OF BUFFALO
Spiller Address:	304 CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-
Spiller Country:	001
Contact Name:	JASON
Contact Phone:	(716) 628-6971
Contact Ext:	
Latitude:	42.902880960
Longitude:	-78.854096210

127	*1 of 1*	*NW*	*0.49 / 2,601.93*	*659.66 / 15*	***PAVEMENT 13 HODGE AVE BUFFALO NY***	***NY SPILLS***

Spill No:	1903061	**UST Trust:**	False

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site ID:	591009	**Spill Date:**	2019-06-25 10:00:00
DER Facility ID:	541189	**Received Date:**	2019-06-25 10:43:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2019-06-25 00:00:00
Water Body:		**Create Date:**	2019-06-25 10:44:00
Class:		**Update Date:**	2019-06-25 10:52:24.450000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	TDJOHNSO
REM Phase:	0	**After Hours:**	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"line break clean up is pending"

DEC Remark:

"06/25/19 TDJ MINOR HYDRAULIC SPILL CLEANED BY NATIONAL GRID NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID:	1338634	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2348138	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	1.00	**Med Surf:**	False
Units:	G	**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		
Material Code:	0010		
Material Name:	hydraulic oil		

Spiller Information

Spiller Name:	JAVONE GIFT
Spiller Company:	NATIONAL GRID
Spiller Address:	13 HODGE AVE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	JAVONE GIFT
Contact Phone:	(716) 398-5308
Contact Ext:	
Latitude:	
Longitude:	

128	1 of 1	WSW	0.49 / 2,605.14	639.42 / -5	ROADWAY 147 ALLEN ST BUFFALO NY	NY SPILLS

Spill No:	1808242	**UST Trust:**	False
Site ID:	579042	**Spill Date:**	2018-11-02 08:01:00
DER Facility ID:	531773	**Received Date:**	2018-11-02 08:09:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2018-11-02 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data
Create Date: 2018-11-02 08:11:00
Update Date: 2018-11-02 11:34:36.317000000
DEC Region: 9
Lead DEC: FXGALLEG
After Hours: True

Caller Remark:

"spill to paved roadway/containment underway"

DEC Remark:

"11/2/18 FG site inspection. Dale Bless with BFD haz mat and Larry Panaro with Buffalo Streets on scene. A hydraulic line broke on a City garbage truck spilling 20 gallons to the street in front of 147 Allen. Buffalo Police closed off the street to traffic. 17 bags of speedi dry were spread. The City of Buffalo Street sweeper swept up the speedi dry. The truck was towed away for repair. The cleanup was complete. No further action necessary. Closed."

Material Information

OP Unit ID: 1326770
OU: 01
Material ID: 2335593
CAS No:
Material Family: Petroleum
Quantity: 20.00
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 0010
Material Name: hydraulic oil
Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name:
Spiller Company: TRASH TRUCK
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: LAURA
Contact Phone:
Contact Ext:
Latitude:
Longitude:

129	1 of 1	WSW	0.50 / 2,624.67	632.38 / -12	ODOR AT 499 DELAWARE 499 DELAWARE AVENUE BUFFALO NY	NY SPILLS

Spill No: 9004148
Site ID: 282535
DER Facility ID: 229360
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class:
Meets Std: True
UST Trust: False
Spill Date: 1990-07-13 18:00:00
Received Date: 1990-07-14 18:00:00
CAC Date: 1990-07-14 00:00:00
Insp Date:
Close Date: 1990-07-14 00:00:00
Create Date: 1990-07-17 00:00:00
Update Date: 1990-12-04 00:00:00
DEC Region: 9

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Penalty:	False	**Lead DEC:**	ROSS
REM Phase:	0	**After Hours:**	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Affected Persons		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"WOOD BURNING ODORS"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was LQR 07/16/90: REFERED TO AIR RESOUCES. 09/29/95: This is additional information about material spilled from the translation of the old spill file: WOOD BURNING ODOR."

Material Information

OP Unit ID:	944349	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	557406	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:	.00	**Med Surf:**	False
Units:	L	**Med Subway:**	False
Recovered:	.00	**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	True		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.897790070
Longitude:	-78.874450470

130	1 of 1	E	0.50 / 2,631.04	661.90 / 17	UNDERGROUND CABLE/MANHOLE 1056 1056 JEFFERSON AVE BUFFALO NY	NY SPILLS

Spill No:	1305900	**UST Trust:**	False
Site ID:	486486	**Spill Date:**	2013-09-04 16:20:00
DER Facility ID:	441600	**Received Date:**	2013-09-04 16:26:00
CID:		**CAC Date:**	
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2013-09-05 00:00:00
Water Body:		**Create Date:**	2013-09-04 16:28:00
Class:	D4	**Update Date:**	2013-09-05 10:16:17.097000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	FXGALLEG
REM Phase:	0	**After Hours:**	False
County:	Erie		

Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Non PCB oil leaked, apx .25 gallon contained in manhole. Clean up pending."

DEC Remark:

"9/5/13 MINOR SPILL -- CLOSED. ELECTRONIC FILE ONLY."

Material Information

OP Unit ID:	1236135	**Med Ind Air:**	False
OU:	01	**Med GW:**	False
Material ID:	2235476	**Med SW:**	False
CAS No:		**Med DW:**	False
Material Family:	Petroleum	**Med Sewer:**	False
Quantity:		**Med Surf:**	False
Units:		**Med Subway:**	False
Recovered:		**Med Utility:**	False
Med Soil:	False	**Oxygenate:**	
Med Air:	False		

Material Code: 2630
Material Name: mineral oil

Spiller Information

Spiller Name:
Spiller Company: NAT GRID
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: LISA MONTESANO
Contact Phone: 7164795339
Contact Ext:
Latitude: 42.903684193
Longitude: -78.854051135

---

131 | ***1 of 1*** | ***E*** | ***0.50 / 2,636.89*** | ***666.52 / 22*** | ***G&J AUTOMOTIVE 1049 JEFFERSON BUFFALO NY*** | ***NY SPILLS***

Spill No:	0904802	**UST Trust:**	
Site ID:	417010	**Spill Date:**	2009-07-24 12:00:00
DER Facility ID:	366076	**Received Date:**	2009-07-24 12:00:00
CID:		**CAC Date:**	2009-12-15 00:00:00
Program Type:	ER	**Insp Date:**	
SWIS Code:	1502	**Close Date:**	2009-12-15 00:00:00
Water Body:		**Create Date:**	2009-07-24 14:14:00
Class:	C1	**Update Date:**	2009-12-15 11:24:46.323000000
Meets Std:	False	**DEC Region:**	9
Penalty:	False	**Lead DEC:**	DKKING
REM Phase:	0	**After Hours:**	False

County: Erie
Contributing Factor: Other
Reported by: DEC
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Former commercial facility with existing USTs and suspected subsurface spill(s). Facility has been listed as a potential Federal LUST Stimulus project requiring site investigation / remediation."

DEC Remark:

"12/16/09: DKK/FILE - THE SITE WAS FOUND NOT TO BE ELIGIBLE FOR FEDERAL STIMULUS PROGRAM DUE TO MUNICIPAL OWNERSHIP. AS SUCH THIS SPILL, OPENED IN ANTICIPATION OF A STIMULUS PROJECT, IS NOW CLOSED . THE SITE WILL BE RETAINED IN THE PBS TRACKING PROGRAM PENDING FUTURE OPPORTUNITIES FOR SITE INVESTIGATION."

Material Information

OP Unit ID:	1173268	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2165163	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.903396000
Longitude:	-78.853950000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
132	*1 of 1*	*ENE*	*0.58 / 3,055.05*	*639.60 / -5*	***Former Pendrick Laundry Site*** ***1200 Jefferson Avenue*** ***Buffalo NY 14203***	***SHWS***

Site Code:	598992
HW Code:	915346
Program:	HW
Site Class:	N
Site Name:	Former Pendrick Laundry Site
Site Address:	1200 Jefferson Avenue
City:	Buffalo
Zip:	14203
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.907735000
Longitude:	-78.854414000
SWIS:	1502
Acres:	0.406
Record Added:	2019-12-05 15:18:00
Record Update:	2020-07-14 10:33:00
Updated by:	AECAPRIO
Site Code (Web):	915346

Program Type (Web):	HW
Site Name (Web):	Former Pendrick Laundry Site
Site Class (Web):	N
Address1 (Web):	1200 Jefferson Avenue
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14203
County (Web):	Erie
Longitude (Web):	-78.854414000
Latitude (Web):	42.907735000
Site Code (GIS):	915346
Site Name (GIS):	Former Pendrick Laundry Site
Program (GIS):	HW
Site Class (GIS):	N
Address1 (GIS):	1200 Jefferson Avenue
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14203
County (GIS):	Erie
Site Class Desc:	
Site Class Desc (Web):	No Further Action at this Time: Sites are given a classification of "N" when: a. the investigation and evaluation of a Class P site results in a determination that contamination at the site does not warrant placing the site on the Registry or it is being addressed under a brownfield program; b. a site was in a brownfield program (BCP, ERP or VCP) or other non-Registry program, remediation was not completed, and the site did not otherwise qualify for listing on the Registry. As an example, this occurs when a volunteer begins a brownfield project and then for economic or other reasons, determines they cannot complete the work and the brownfield project is terminated. If the contamination at the brownfield site qualifies it for placement on the Registry, the Department acts to do so. If the site re-enters a brownfield program, it can be reclassified to Class A (active) to indicate that work has recommenced; c. a site was identified simply as the location(s) where a drum(s) or other discrete waste was at one time present and subsequently removed by DEC or others and, based on the resulting conditions, no need for additional work was apparent; or d. an application to the BCP, ERP or VCP was submitted, and was then withdrawn or terminated before any actions were taken to investigate or remediate the site.
Assess DOH:	As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Location: The Former Pendrick Laundry Site is a 0.406-acre site located in an urban area of the City of Buffalo. The site is bound by vacant properties and Eaton Street to the north, Jefferson Avenue to the east, Northampton Street to the south, and residential properties to the west. Site Features: The site currently consists a building, with asphalt-gravel parking surrounding the building on the south and west sides. Current Zoning and Land Use: The site has most recently been used for maintenance warehouse space, religious, transportation service and repair, and vacant commercial storefronts/office space. The site is zoned by the Buffalo Green Code (January 2017) as N-3E (mixed-use commercial) and N-3R (residential with existing commercial). The surrounding properties are a mix of commercial and residential uses, with residential areas immediately adjacent to the site. Past Use of the Site: The site has included numerous commercial operations from the late 1890s until the mid 2010s. The original portion of the existing building was built in 1926 and involved operations such as laundry/dry cleaning, from at least 1935 through at least 2010, and automotive service operations (repair, manufacturing/fabrication, and painting) from at least 1926 through at least 1950. Multiple underground storage tanks (USTs) have been located on-site. In 1993 during the removal of two USTs contaminated soil was encountered and removed under Spill 9305238. During this time spill records also indicate that an 8,000 gallon #6 fuel-oil UST was abandoned below the building by filling with concrete. A complete BCP application was submitted for the 1200 Jefferson Avenue Site (#C915346) site was submitted in June 2019. The application indicated that soil and groundwater are impacted with petroleum and tetrachloroethene contamination. The BCP application was withdrawn on November 7, 2019, and the DEC subsequently created this site to investigate the contamination identified in the BCP application. A new BCP application was submitted in March 2020 to investigate the impacts at the site. An agreement was signed in June 2020 and the full investigation of contamination at the site will be completed in the Brownfield Cleanup Program as site number C915346. Site Geology and Hydrogeology: Previous investigations have identified fill material on-site ranging in depth from 0-10 feet below ground surface (fbgs). Underlying soil is typically a red-brown to tan sandy clay. Regional groundwater appears to flow north towards Scajaquada Creek located approximately 1.10 miles from the site. Local groundwater flow, however, may be influenced by subsurface features, such as foundations and utilities, and localized fill conditions.

Assessment:

Information submitted with the June 2019 BCP application for 1200 Jefferson Avenue Site (#C915346) indicate that soil and groundwater on the 1200 Jefferson Avenue parcel are impacted with petroleum products and tetrachloroethene (and its breakdown products). A second BCP application was received in March 2020. Delineation of the nature and extent of contamination at the site will resume under the BCP, #C915346.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Information

Owner Op:	01
Sub Type:	01
Owner Name:	Nicholas Sinatra
Owner Company:	1200 Jefferson Properties, LLC
Owner Street:	617 Main Street
Owner Street 2:	Suite 200
Owner City:	Buffalo
Owner State:	NY
Owner Zip:	14203
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	petroleum products, tetrachloroethane

133	*1 of 1*	*ENE*	*0.77 / 4,065.45*	*638.93 / -5*	***Diarsenol Co., Kingsley Park*** ***Kingsley Street*** ***Buffalo NY 14208***	***SHWS***

Site Code:	56621
HW Code:	915124
Program:	HW
Site Class:	04
Site Name:	Diarsenol Co., Kingsley Park
Site Address:	Kingsley Street
City:	Buffalo
Zip:	14208
County:	Erie
Region:	9
Town:	Buffalo (c)
Latitude:	42.908860600
Longitude:	-78.850855980
SWIS:	1502
Acres:	2.216
Record Added:	1999-11-18 12:00:00
Record Update:	2022-02-07 09:39:00
Updated by:	AECAPRIO
Site Code (Web):	915124
Program Type (Web):	HW
Site Name (Web):	Diarsenol Co., Kingsley Park
Site Class (Web):	04
Address1 (Web):	Kingsley Street
Address2 (Web):	
Locality (Web):	Buffalo
Zip Code (Web):	14208
County (Web):	Erie
Longitude (Web):	-78.850855980
Latitude (Web):	42.908860600
Site Code (GIS):	915124
Site Name (GIS):	Diarsenol Co., Kingsley Park
Program (GIS):	HW
Site Class (GIS):	04
Address1 (GIS):	Kingsley Street
Address2 (GIS):	
Locality (GIS):	Buffalo
Zip Code (GIS):	14208
County (GIS):	Erie
Site Class Desc:	This classification is assigned to a site that has been properly closed but that requires continued site management consisting of operation, maintenance and/or monitoring. Class 4 is appropriate for a site where remedial construction actions have been completed for all operable units, but the site has not necessarily been brought into compliance with standards, criteria, or guidance (e.g., a groundwater extraction and treatment system has been installed and is operating properly but groundwater standards have not been achieved yet). The Record of Decision should define the remedial action objectives that need to be achieved during site management. If a Certificate of Completion (CoC) is to be issued for a site, the CoC is issued concurrently with the reclassification.

Site Class Desc (Web): This classification is assigned to a site that has been properly closed but that requires continued site management consisting of operation, maintenance and/or monitoring. Class 4 is appropriate for a site where remedial construction actions have been completed for all operable units, but the site has not necessarily been brought into compliance with standards, criteria, or guidance (e.g., a groundwater extraction and treatment system has been installed and is operating properly but groundwater standards have not been achieved yet). The Record of Decision should define the remedial action objectives that need to be achieved during site management. If a Certificate of Completion (CoC) is to be issued for a site, the CoC is issued concurrently with the reclassification.

Assess DOH: Remedial activities to address soil contamination conducted at the site and at some nearby off-site properties have effectively reduced the potential for exposure to site-related contaminants. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Assessment:

Remediation at the Site is complete. Prior to remediation, the primary contaminant of concern was arsenic in soil and groundwater. Remedial actions have successfully achieved soil cleanup objectives for restricted-residential use. Residual contamination in soil and groundwater is being managed under a Site Management Plan.

Description:

Location: The Diarsenol Co., Kingsley Park site is an approximately 2.216-acre site located in a residential neighborhood on Kingsley Street in the City of Buffalo, Erie County. Site Features: The site is a flat, grass covered lot with no buildings. Fencing surrounds much of the site. Current Zoning and Land Use: The site is currently a park owned by the City of Buffalo. Past Use of the Site: The Diarsenol Company occupied the property on Kingsley Street adjacent to the site starting in about 1900. Diarsenol manufactured medications containing arsenic at their facility from the early 1900s until the 1940s. They reportedly used this site for disposal of waste materials from their plant. The site was occupied by various owners from the 1940s until 1967, when it was acquired by the City of Buffalo. The site has been used as a public park and playground since 1972. Site Geology and Hydrology: The Site is currently covered with topsoil overlying clean fill and native clay. Minimal shallow-goundwater contamination is still present in an area proximal to the groundwater collection system.

Materials Information

Waste Name: ARSENIC
Waste Quantity: UNKNOWN
Waste Code:

Owner Information

Owner Op: 01
Sub Type: C01
Owner Name: Andrew Rabb
Owner Company: City of Buffalo Department of Parks and Recreation
Owner Street: 65 Niagara Square
Owner Street 2: Room 505
Owner City: BUFFALO
Owner State: NY
Owner Zip: 14202
Country: United States of America

Owner Op: 03
Sub Type: NNN
Owner Name:
Owner Company: DIARSENOL COMPANY
Owner Street:
Owner Street 2:
Owner City:
Owner State: ZZ
Owner Zip:
Country: United States of America

Owner Op: 04
Sub Type: NNN
Owner Name:
Owner Company: Diarsenol Company
Owner Street: 84 Kingsley Street
Owner Street 2:
Owner City: Buffalo
Owner State: NY
Owner Zip: 14208

Country: United States of America

HW Extra Information

Dump:	True	**Record Added:**	1999-11-18 12:00:00
Structure:	False	**Record Updated:**	1999-11-18 12:00:00
Lagoon:	False	**Disposal Start:**	unknown
Landfill:	False	**Disposal Terminate:**	1951
Pond:	False	**Latitude:**	42:54:32:0
Dell:	False	**Longitude:**	78:51:04:0
Updated By:	INITIAL		

Projects Information

Project Code: 01
Project Desc: Site Caracterization
Project Refer Name:
End Date: 1990-08-01 00:00:00
End Status: ACT
Operable Unit ID: 3119
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Site Characterization

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:
End Date: 1994-12-01 00:00:00
End Status: ACT
Operable Unit ID: 3119
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Remedial Action

Project Code: 02
Project Desc: Remedial Investigation
Project Refer Name:
End Date: 1994-03-01 00:00:00
End Status: ACT
Operable Unit ID: 3119
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Remedial Investigation

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 1994-09-01 00:00:00
End Status: ACT
Operable Unit ID: 3119
Operable Unit: 01
Operable Unit Desc: REMEDIAL PROGRAM
Code Name: Remedial Design

Project Code: 04
Project Desc: Remedial Design
Project Refer Name:
End Date: 1991-03-01 00:00:00
End Status: ACT
Operable Unit ID: 3120
Operable Unit: 01A
Operable Unit Desc: IRM - Soil Removal
Code Name: Remedial Design

Project Code: 05
Project Desc: Remedial Action
Project Refer Name:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

End Date: 1992-01-01 00:00:00
End Status: ACT
Operable Unit ID: 3120
Operable Unit: 01A
Operable Unit Desc: IRM - Soil Removal
Code Name: Remedial Action

Environmental Remediation

Operable Unit: 01
Contaminants: arsenic

Operable Unit: 01A
Contaminants: arsenic

Operable Unit: 00
Contaminants: arsenic

134	1 of 1	N	0.80 / 4,223.15	632.74 / -12	1542 Main Street 1542 Main Street Buffalo NY 14209	SHWS

Site Code: 482356
HW Code: 915278
Program: HW
Site Class: P
Site Name: 1542 Main Street
Site Address: 1542 Main Street
City: Buffalo
Zip: 14209
County: Erie
Region: 9
Town: Buffalo (c)
Latitude: 42.915524000
Longitude: -78.864944000
SWIS: 1502
Acres: 0.270
Record Added: 2013-05-24 15:42:00
Record Update: 2021-06-04 16:17:00
Updated by: AECAPRIO
Site Code (Web): 915278
Program Type (Web): HW
Site Name (Web): 1542 Main Street
Site Class (Web): P
Address1 (Web): 1542 Main Street
Address2 (Web):
Locality (Web): Buffalo
Zip Code (Web): 14209
County (Web): Erie
Longitude (Web): -78.864944000
Latitude (Web): 42.915524000
Site Code (GIS): 915278
Site Name (GIS): 1542 Main Street
Program (GIS): HW
Site Class (GIS): P
Address1 (GIS): 1542 Main Street
Address2 (GIS):
Locality (GIS): Buffalo
Zip Code (GIS): 14209
County (GIS): Erie
Site Class Desc:
Site Class Desc (Web): Potential: This classification is used for sites where preliminary information indicates that a site may have contamination that makes it eligible for consideration for placement on the Registry of Inactive Hazardous Waste Disposal Sites (commonly referred to as the list of State Superfund Sites). Further information and/or investigation, in the form of a site characterization, is needed to determine if a Class P site qualifies for listing of the site on the Registry. Generally, to qualify for placement on the Registry, there must be evidence that hazardous waste was disposed on the site and that any resulting contamination presents a significant threat (or reasonably foreseeable

threat) to public health or the environment. Class P sites are not listed on the Registry and many are eventually found to not qualify for Registry listing. Sites that do not qualify for listing are typically then reclassified to a "Class N" site.

Assess DOH: As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns.

Description:

Location: The 1542 Main Street site is an approximately 0.27-acre site located in an urban area at 1542 Main Street in the City of Buffalo, Erie County. It is at the intersection of Main and West Ferry Streets. Site Features: There were two adjoining buildings on the site consisting of two and three story brick, wood and concrete structures. The building were historically mixed commercial and residential use. The smaller building was demolished in 2012 and replaced with a new two story building that was connected to the renovated larger building. Current Zoning and Land Use: The site is located in an N-2C zone, as a "Mixed-Use Center", which allows for commercial use. The connected buildings are used for office space. The surrounding properties are predominately commercial to the north, east, and south with private residences to the west. Past Use of the Site: The demolished smaller building was historically addressed as 958-960 West Ferry Street and had been occupied by a dry-cleaning business. The dry cleaning operations are presumed to be the cause for the site contamination. Site Geology and Hydrogeology: The geology at the Site is generally described as fill materials overlying sandy lean clay and sandy silt. The fill materials consist of miscellaneous sand, intermixed with brick,concrete and cinders. Groundwater was encountered at approximately 6 fbgs during exterior installations and approximately 2 feet below grade surface during installation of the basement borings (i.e.,approximately 7 feet below street grade). Groundwater elevations surveyed in 2009 indicate groundwater flows in a general northeast direction across the Site.

Assessment:

Nature and Extent of Contamination: As part of a property transaction a series of Environmenal Assessments were conducted on the property from 2007 - 2012. Chlorinated Volatile Organic Compounds (cVOCs) were detected at very low concentrations in soil samples, with the majority of analytes detected at estimated concentrations below laboratory detection limits. No cVOCs were detected above Part 375 Unrestricted Use SCOs. On-site groundwater has been impacted by cVOCs, specifically perchloroethylene (PCE) and its chemical breakdown products. PCE is a common dry-cleaning solvent and the groundwater impacts are reasonably attributable to past use of a portion of the site as a dry-cleaning facility. The groundwater impacts were identified west of the buildings beneath an asphalt parking lot(monitoring wells MW-9 through -12), north of the buildings (MW-16) and beneath the buildings (MW-13 and -14). The highest concentration of cVOCs in groundwater was detected in MW-12 (7,845 ug/L total cVOCs), which is located on the southern boundary, west of the buildings. Additional groundwater samples were collected in October 2018 for the analyses of cVOCs. Monitoring wells MW-9, -10, -11 and -12,that had been installed in the asphalt parking lot, could not be found and were most likely paved over. The highest concentration of cVOCs found on site was west of the buildings in MW-17 (8,480 ug/L total cVOCs). Beneath the buildings, total cVOCs concentration was as high as 432 ug/L (MW-14). Remedial actions were taken in 2012, including: - in-situ enhanced bioremediation of VOC impacted groundwater; - implementation of a soil/fill management plan to address potentially impacted soil that may be encountered during Site redevelopment; and, - design and installation of an active sub-slab depressurization (ASD) system to protect the building from potential vapor intrusion of VOCs The potential for the off-site migration of cVOCs has not yet been evaluated.

Owner Information

Owner Op:	01
Sub Type:	06
Owner Name:	M. Deanna Eason
Owner Company:	HOUSING OPPORTUNITIES MADE EQUAL INC.
Owner Street:	1542 Main Street (at Ferry)
Owner Street 2:	
Owner City:	Buffalo
Owner State:	NY
Owner Zip:	14209
Country:	United States of America

Environmental Remediation

Operable Unit:	01
Contaminants:	

135	*1 of 1*	*NW*	*0.99 / 5,206.29*	*642.80 / -2*	***BUFFALO PERLITE PLANT ERIE COUNTY BUFFALO NY 14222***	*MRDS*

Dep ID:	10297233	***I1:***	20
Dev Status:	PLANT	***Latitude:***	42.916687
Code List:	PER	***Longitude:***	-78.874695
Url:	http://mrdata.usgs.gov/mrds/show-mrds.php?dep_id=10297233		

Commodity

I1:	16	***Line:***	1
Code:	PER	***Inserted By:***	MAS migration
Commodity:	Perlite	***Insert Date:***	29-OCT-2002 09:00:24
Commodity Type:	Non-metallic	***Updated By:***	USGS
Commodity Group:	Perlite	***Update Date:***	29-OCT-2002 09:02:33
Importance:	Primary		

Names

I1:	10	***Inserted By:***	MAS migration
Status:	Current	***Insert Date:***	29-OCT-02
Site Name:	Buffalo Perlite Plant	***Updated By:***	USGS
Line:	1	***Update Date:***	29-OCT-02

Unplottable Summary

Total: 39 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
GEN MANIFEST	NIAGARA MOHAWK POWER CORPORATION	MAIN ST	BUFFALO NY		874621305
GEN MANIFEST	M & T BANK	CORNER OF MAIN ST	BUFFALO NY	14203	874636011
LST	LIN-NOR APARTMENTS	LINWOOD AVENUE	BUFFALO NY		814025954
		Spill No* | *Close Date: 9405633 | 1994-07-22 00:00:00			
LST	BUFFALO FIRE DEPT	ELLICOTT STREET	BUFFALO NY		814027689
		Spill No* | *Close Date: 8707600 | 1988-01-11 00:00:00			
LST	BUFFALO FIRE HOUSE #1	ELLICOTT STREET	BUFFALO NY		814025064
		Spill No* | *Close Date: 9909990 | 2000-02-07 00:00:00			
NY SPILLS	BAD GASOLINE	MAIN STREET	BUFFALO NY		813657436
		Spill No* | *Close Date: 8904258 | 1989-07-29 00:00:00			
NY SPILLS	ROSWELL PARK	MICHIGAN STREET	BUFFALO NY		813655787
		Spill No* | *Close Date: 8808582 | 1989-02-13 00:00:00			
NY SPILLS	BUFFALO CEMENT COMPANY	MAIN STREET POLE # 242	BUFFALO NY		813823161
		Spill No* | *Close Date: 0608250 | 2007-01-26 00:00:00			
NY SPILLS	INTEGRATED WASTE TRUCK	MICHIGAN STREET	BUFFALO NY		813660518
		Spill No* | *Close Date: 9203605 | 1992-07-02 00:00:00			
NY SPILLS	ROSWELL PARK CANCER INST	CARLTON STREET	BUFFALO NY		813671307
		Spill No* | *Close Date: 9975436 | 1999-09-27 00:00:00			
NY SPILLS	ROSWELL PARK CANCER INST	CARLTON STREET	BUFFALO NY		813671308
		Spill No* | *Close Date: 9975440 | 2000-03-27 00:00:00			
NY SPILLS	SUNY AT BUFFALO	MAIN STREET	BUFFALO NY		813695469

		Spill No* | *Close Date: 8706241 | 1987-10-23 00:00:00		
NY SPILLS	DONAVAN OFFICE BLDG	MAIN STREET	BUFFALO NY	813652804
		Spill No* | *Close Date: 8901121 | 1989-05-05 00:00:00		
NY SPILLS	GOODYEAR REPAIR	MAIN STREET	BUFFALO NY	813650860
		Spill No* | *Close Date: 9110007 | 1993-05-12 00:00:00		
NY SPILLS	IN FRONT OF 1ST NIAGARA CENTER	MAIN ST	BUFFALO NY	895426708
		Spill No* | *Close Date: 2106683 | 2021-10-17 00:00:00		
NY SPILLS	STREET	MICHIGAN AVE	BUFFALO NY	882254824
		Spill No* | *Close Date: 1911697 | 2020-03-24 00:00:00		
NY SPILLS	UB SOUTH CAMPUS	MAIN ST	BUFFALO NY	875676954
		Spill No* | *Close Date: 1901415 | 2019-07-10 00:00:00		
NY SPILLS	GENERAL MILLS DOCK TO WATER	SOUTH MICHIGAN AVE	BUFFALO NY	858451437
		Spill No* | *Close Date: 1606604 | 2016-10-05 00:00:00		
NY SPILLS	GENERAL MILLS	MICHIGAN AVENUE	BUFFALO NY	813984250
		Spill No* | *Close Date: 9105790 | 1991-08-30 00:00:00		
NY SPILLS	IN ROAD	WASHINGTON	BUFFALO NY	813981232
		Spill No* | *Close Date: 0550698 | 2005-07-26 00:00:00		
NY SPILLS	NIMO VAULT	MAIN STREET	BUFFALO NY	813945021
		Spill No* | *Close Date: 0501616 | 2005-05-10 00:00:00		
NY SPILLS	IN STREET	ELLICOTT ST.	BUFFALO NY	813915798
		Spill No* | *Close Date: 0750398 | 2007-06-14 00:00:00		
NY SPILLS	BUFFALO FUEL TRUCK	ELMWOOD AVENUE	BUFFALO NY	813889976
		Spill No* | *Close Date: 9802486 | 1998-07-01 00:00:00		
NY SPILLS	AMERICANA	MAIN STREET	BUFFALO NY	813882544
		Spill No* | *Close Date: 9106228 | 1991-12-05 00:00:00		
NY SPILLS	SHEEN IN BUFFALO CANAL	MICHIGAN AVENUE	BUFFALO NY	813876827
		Spill No* | *Close Date: 9806584 | 1998-08-31 00:00:00		

NY SPILLS	BUFFALO NEWS	WASHINGTON STREET	BUFFALO NY		813866611
		Spill No* | *Close Date: 8605922 | 1986-12-18 00:00:00			
NY SPILLS	CANISTERS - NAVAL PARK	MAIN STREET	BUFFALO NY		813858084
		Spill No* | *Close Date: 9608221 | 1996-10-02 00:00:00			
NY SPILLS	BUFFALO NEWS	WASHINGTON STREET	BUFFALO NY		813854549
		Spill No* | *Close Date: 8708866 | 1988-01-27 00:00:00			
NY SPILLS	DUMPING AT NAVAL PARK	MAIN STREET	BUFFALO NY		813848496
		Spill No* | *Close Date: 9802175 | 1998-05-19 00:00:00			
NY SPILLS	MEMORIAL AUD	WASHINGTON STREET	BUFFALO NY		813847819
		Spill No* | *Close Date: 0275592 | 2003-11-17 00:00:00			
NY SPILLS	MEMORIAL AUDITORIUM	MAIN ST	BUFFALO NY		813823789
		Spill No* | *Close Date: 0902966 | 2009-07-02 00:00:00			
NY SPILLS	MEMORIAL AUD	MAIN STREET	BUFFALO NY		813814482
		Spill No* | *Close Date: 0812894 | 2009-03-25 00:00:00			
NY SPILLS	ELLICOTT SQUARE	ELLICOTT SQUARE BLDG	BUFFALO NY		813794292
		Spill No* | *Close Date: 9408628 | 1994-10-03 00:00:00			
NY SPILLS	BUFFALO AIRPORT	RT.33	BUFFALO NY		813774650
		Spill No* | *Close Date: 0200988 | 2002-07-26 00:00:00			
NY SPILLS	GENERAL MILLS	SOUTH MICHIGAN AVE	BUFFALO NY		813763951
		Spill No* | *Close Date: 0109857 | 2002-01-14 00:00:00			
NY SPILLS	WEBSTER BLOCK-PARKING LOT	WASHINGTON STREET	BUFFALO NY		813760398
		Spill No* | *Close Date: 0103210 | 2001-06-25 00:00:00			
NY SPILLS	ABANDONED DRUM	MICHIGAN STREET	BUFFALO NY		813736207
		Spill No* | *Close Date: 8900042 | 1989-04-06 00:00:00			
NY SPILLS	VICTOR'S MOTORS	MAIN STREET	BUFFALO NY		813724842
		Spill No* | *Close Date: 9300772 | 1993-04-21 00:00:00			
RCRA NON GEN	BUFFALO CITY OF MICHIGAN ST LIFT BRIDGE	MICHIGAN ST LAT N42 52 20 LONG E78 52 20	BUFFALO NY	14202	810391311

Unplottable Report

Site: ***NIAGARA MOHAWK POWER CORPORATION***
MAIN ST BUFFALO NY

GEN MANIFEST

RCRA ID:	NYP000964569	***Mailing State:***	NY
District Name:	NIAGARA MOHAWK POWER CORPORATION	***Mailing ZIP:***	14214
Contact Name:	M MORROW	***Mailing ZIP Ext:***	
Business Phone No:	7168317428	***Mailing Country:***	USA
Mailing Street 1:	144 KENSINGTON AVE	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

2009: 55 Gallons

Site: ***M & T BANK***
CORNER OF MAIN ST BUFFALO NY 14203

GEN MANIFEST

RCRA ID:	NYR000057208	***Mailing State:***	NY
District Name:	M & T BANK	***Mailing ZIP:***	14203
Contact Name:	ROBERT W VONLANGEN	***Mailing ZIP Ext:***	
Business Phone No:	7168483965	***Mailing Country:***	USA
Mailing Street 1:	MAIN ST & HURON ST	***Location ZIP Ext:***	
Mailing Street 2:		***Location Country:***	USA
Mailing City:	BUFFALO	***Location County:***	ERIE

Manifest Information

Waste Code(s):

D008: LEAD (Waste Code Description from EPA Hazardous Waste Identification)

Waste Amounts By Year:

1998: 4000 Pounds

Site: ***LIN-NOR APARTMENTS***
LINWOOD AVENUE BUFFALO NY

LST

Spill No:	9405633	***REM Phase:***	0
Site ID:	186397	***UST Trust:***	True
DER Facility ID:	155814	***Spill Date:***	1994-04-01 12:00:00
CID:		***Rcvd Date:***	1994-07-12 12:00:00
Program Type:	ER	***CAC Date:***	1994-07-22 00:00:00
SWIS Code:	1502	***Insp Date:***	1994-05-02 00:00:00
Contribute Factor:	Tank Failure	***Close Date:***	1994-07-22 00:00:00
Water Body:		***Create Date:***	1994-07-28 00:00:00
Class:	B3	***Update Date:***	1994-08-12 00:00:00
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SACALAND

County:	Erie	***After Hours:***	False
Referred to:			
Reported by:	Other		
Source:	Private Dwelling		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK REMOVAL INDICATED SOIL GUIDANCE EXCEEDANCES."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 07/19/94: SAC/JOHN OTTO, PBS - JOHN INSPECTED AND FOUND NO VISUAL CONTAMINATION. "

Material Information

OP Unit ID:	999943	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	382217	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	LIN-NOR APARTMENTS
Spiller Address:	LINWOOD AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.911249993
Longitude:	-78.869200023

Site: ***BUFFALO FIRE DEPT***
ELLICOTT STREET BUFFALO NY

LST

Spill No:	8707600	***REM Phase:***	0
Site ID:	230279	***UST Trust:***	False
DER Facility ID:	189792	***Spill Date:***	1987-12-04 14:00:00
CID:		***Rcvd Date:***	1987-12-04 14:04:00
Program Type:	ER	***CAC Date:***	1988-01-11 00:00:00
SWIS Code:	1502	***Insp Date:***	1988-01-11 00:00:00
Contribute Factor:	Tank Test Failure	***Close Date:***	1988-01-11 00:00:00
Water Body:		***Create Date:***	1987-12-04 00:00:00
Class:		***Update Date:***	1988-01-26 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	MXFRANKS
County:	Erie	***After Hours:***	False
Referred to:			
Reported by:	Tank Tester		
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"LEAKES IN VENT LINE"

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF / / : LINE REPAIRED 8CY CONTAMINATED SOIL REMOVED, LINES TO BE RETESTED. / / : MF 12/21/87 TELECON/BOB O'HARA, TAKING BIDS FOR REMOVAL. HE WILL CALL WHEN DATE IS FIRM. 851-5879. / / : MF 12/08/87 TELCON FRANK FABER, TANK WILL BE EMPTIED TODAY OR TOMORROW. TANK TO BE REMOVED IN THE NEXT FEW WEEKS- BOB O'HARA 851-5879. / / : MF 1/7/88 TELECON/DICK MIZE, BIDS WILL BE SENT OUT THE END OF THIS WEEK. (851-5670). / / : MF 1/11/88 SITE VISIT TANK REMOVAL, ELMWOOD TANK (DICK DAILY) NO GROUNDWATER OR SOIL CONTAMINATION NOTICED. "

Material Information

OP Unit ID:	913269	***Med in Air:***	False
OU:	01	***Med GW:***	True
Material ID:	466540	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO FIRE DEPT
Spiller Address:	ELLICOTT STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.902519993
Longitude:	-78.866550023

Tank Test Information

Spill Tank ID:	1532532	***Source:***	
Tank No:		***Leak Rate:***	.00
Tank SIze:	0	***Gross Fail:***	
Material:	0001	***Modified by:***	Spills
EPA UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
UST:		***Test Method:***	00
Cause:			
Alt Test Method:	Unknown		

Site: ***BUFFALO FIRE HOUSE #1***
ELLICOTT STREET BUFFALO NY

LST

Spill No:	9909990	***REM Phase:***	0
Site ID:	230280	***UST Trust:***	True
DER Facility ID:	189792	***Spill Date:***	1999-11-17 14:05:00
CID:	382	***Rcvd Date:***	1999-11-17 14:15:00
Program Type:	ER	***CAC Date:***	
SWIS Code:	1502	***Insp Date:***	1999-11-30 00:00:00
Contribute Factor:	Tank Failure	***Close Date:***	2000-02-07 00:00:00
Water Body:		***Create Date:***	1999-11-17 00:00:00
Class:	B3	***Update Date:***	2000-07-13 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SACALAND
County:	Erie	***After Hours:***	False
Referred to:			
Reported by:	Other		

Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CONTAMINATED SOIL FOUND DURING THE REMOVAL OF A 1000 GAL TANK. TANK WILL BE REMOVED AND SOIL EXCAVATED."

Dec Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 11/30/99: SAC TELECON DAVE HUTTON OF TYREE ORGANIZATION, WORK IS PROCEEDING TODAY ON LOADING OUT THE CONTAMINATED SOIL. 11/30/99: SAC SITE INSPECTION, TWICE WITHIN THREE HOURS, DAVE PARKER OF TYREE ORGANIZATION AT THE SITE REMOVING CONTAMINATED SOIL, EXCAVATION NEXT TO BUILDING, THEY WILL CONTINUE TO EXCAVATE WHERE THEY CAN BUT FURTHER EXCAVATION NEXT TO FOUNDATION MAY UNDERMINE THE BUILDING SO THEY WILL NOT CONTINUE TO DIG DEEPER NEXT TO THE BUILDING, THEY WILL ATTEMPT TO EXCAVATE ALONG THE BUILDING HOWEVER THEY NEED TO KEEP THE BAYS OPEN IN CASE OF EMERGENCY TO ALLOW EXIT FOR THE FIRE TRUCKS, THEY WILL BE INSTALLING A NEW TANK IN THE EXCAVATION. 11/30/99: SAC SITE INSPECTION, AT END OF THE DAY, ADDITIONAL CONTAMINATION REMOVED AND EXCAVATION APPEARED TO BE REDDISH SOIL, A VEIN OF MATERIAL ALONG THE FOUNDATION WAS NOT REMOVED, APPEARS THAT EXCAVATION IS CLOSE TO BEING COMPLETED. 12/01/99: SAC TELECON DAVE PARKER, HE IS NEARLY READY INSTALL THE TANK, SAC TOLD HIM TO TAKE HIS SAMPLES FROM THE EXCAVATION BEFORE INSTALLING THE TANK. 02/07/00: SAC RECEIVED TANK CLOSURE REPORT INCLUDING DISPOSAL RECEIPTS AND CONFIRMATORY SAMPLE RESULTS, 143.4 TONS OF SOIL DISPOSED, ALL PARAMETERS FOR ALL SAMPLES TAKEN WERE BELOW STARS GUIDANCE VALUES."

Material Information

OP Unit ID:	1088680	***Med in Air:***	False
OU:	01	***Med GW:***	False
Material ID:	299052	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	ROBERT O'HARA
Spiller Company:	CITY OF BUFFALO/CITY HALL
Spiller Address:	65 NIAGARA SQ - ROOM 616
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-
Spiller Country:	001
Contact Name:	DAN KOHKMAN
Contact Phone:	(716) 856-2142
Contact Ext:	
Latitude:	42.902519993
Longitude:	-78.866550023

Site: ***BAD GASOLINE***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	8904258	***UST Trust:***	False
Site ID:	263246	***Spill Date:***	1989-07-29 12:00:00
DER Facility ID:	359788	***Received Date:***	1989-07-29 12:22:00
CID:		***CAC Date:***	1989-07-29 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1989-07-29 00:00:00
Water Body:		***Create Date:***	1989-08-01 00:00:00
Class:	C1	***Update Date:***	2009-08-03 11:13:28.923000000
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	PRINGLE
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Other		

Reported by: Responsible Party
Referred to:
Source: Private Dwelling
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CALLER PURCHASED BAD GAS FROM GAS STATION APPROX. 6 GALS., HE WAS SEEKING ADVICE ON DISPOSAL OF WASTE GASOLINE, NOTHING SPILLED."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 07/29/89: 7/29/89 MNP TELECON W/DARIAGE, HE WAS ADVISED TO REUSE PRODUCT BY MIXING W/PREMIUM GAS OR ADDITIVES, OR TAKE BACK TO GAS STATION. "

Material Information

OP Unit ID:	931981	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	448312	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	
Spiller Company:	TOM DARIAGE
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.943809993
Longitude:	-78.839240022

Site: ***ROSWELL PARK***
MICHIGAN STREET BUFFALO NY

NY SPILLS

Spill No:	8808582	***UST Trust:***	False
Site ID:	73543	***Spill Date:***	1989-01-30 21:34:00
DER Facility ID:	69211	***Received Date:***	1989-01-30 23:14:00
CID:		***CAC Date:***	1989-02-13 00:00:00
Program Type:	ER	***Insp Date:***	1989-02-13 00:00:00
SWIS Code:	1502	***Close Date:***	1989-02-13 00:00:00
Water Body:		***Create Date:***	1989-02-07 00:00:00
Class:		***Update Date:***	1989-02-22 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	PRINGLE
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Responsible Party		
Referred to:			
Source:	Tank Truck		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"SUSPECT TANK OVERFILL DURING DELIVERY"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP 01/31/89: 1/31/89 MNP SPOKE W/ FACILITY PERSONNEL, SPILL CONTAINED AND WILL BE CLEANED UP. 02/13/89: 2/13/89 MNP & MEL INSP. CLEANUP SATISFACTORY, NO FURTHER WORK NEEDED, COMPLETE. "

Material Information

OP Unit ID:	924999	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	453342	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	5.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	5.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	CROSSET TRUCKING
Spiller Address:	
Spiller City:	FALCONER
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Tank Test Information

Spill Tank ID:	1535133	***Source:***	
Tank No:		***Test Method:***	00
Tank Size:	0	***Leak Rate:***	.00
Material:	0003	***Gross Fail:***	
EPA UST:		***Modified by:***	Spills
UST:		***Last Modified:***	2004-10-01 04:00:45.140000000
Cause:			
Alt Test Method:	Unknown		

Site: ***BUFFALO CEMENT COMPANY***
MAIN STREET POLE # 242 BUFFALO NY

NY SPILLS

Spill No:	0608250	***UST Trust:***	False
Site ID:	372159	***Spill Date:***	2006-10-18 14:00:00
DER Facility ID:	321891	***Received Date:***	2006-10-18 15:02:00
CID:	410	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2007-01-26 00:00:00
Water Body:		***Create Date:***	2006-10-18 15:26:00
Class:	D5	***Update Date:***	2007-01-26 09:52:15.780000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	JFOTTO
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Local Agency		
Referred to:			

Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"TRANSFORMER WAS FOUND UPSIDE DOWN DUE TO POLE SNAPPING DURING RECENT STORM: TRANSFORMER IS NOW IN UPRIGHT POSITION: CLEANUP CREW IN ROUTE:"

DEC Remark:

"national grid report indicates there was no apparent spill at this site. for more information see the report filed under spill #0607997. closed THERE IS NO PAPER FILE FOR THIS SPILL"

Material Information

OP Unit ID:	1129907	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2119565	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	LISA FREDERICKS
Spiller Company:	BUFFALO CEMENT COMPANY
Spiller Address:	MAIN STREET POLE # 242
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14214
Spiller Country:	001
Contact Name:	LISA FREDERICKS
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	
Longitude:	

Site: ***INTEGRATED WASTE TRUCK***
MICHIGAN STREET BUFFALO NY

NY SPILLS

Spill No:	9203605	***UST Trust:***	False
Site ID:	73545	***Spill Date:***	1992-06-26 12:00:00
DER Facility ID:	69211	***Received Date:***	1992-06-26 15:32:00
CID:		***CAC Date:***	1992-06-26 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1992-07-02 00:00:00
Water Body:		***Create Date:***	1992-07-02 00:00:00
Class:	D5	***Update Date:***	1992-11-16 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SORGI
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Human Error		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TRUCK HYDRAULIC LINES BROKE, SAME AS SPILL 9203667"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 06/26/92: MJS TELECON TO PAT KRANTZ. 6 BAGS SPEEDI DRI WERE USED. MJS ASKED MR KRANTZ. TO UNLOAD STREET SWEEPER AND DISPOSE IN REGULAR WASTE STREAM. NO FURTHER ACTION NECESSARY. MJS TO CLOSE FILE. 09/29/95: This is additional information about material spilled from the translation of the old spill file: HYDRAULIC FLUID."

Material Information

OP Unit ID:	967425	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	411392	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	50.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	50.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	INTEGRATED WASTE SYSTEMS
Spiller Address:	201 GANSON STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Site: ***ROSWELL PARK CANCER INST***
CARLTON STREET BUFFALO NY

NY SPILLS

Spill No:	9975436	***UST Trust:***	False
Site ID:	325430	***Spill Date:***	1998-10-02 12:00:00
DER Facility ID:	262142	***Received Date:***	1999-03-29 08:00:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1999-09-27 00:00:00
Water Body:		***Create Date:***	1999-09-27 10:43:00
Class:	B4	***Update Date:***	1999-10-15 00:00:00
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RMCROSSE
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTAMINATION NOTED DURING TANK REMOVAL, SPILL NOT NOTIFIED AT TIME OF REMOVAL. TANK #110, 1K DIESEL "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/27/99: RMC REVIEWED REPORT, TANK # 110 1K DIESEL, SPILL NOTED UPON REMOVAL, SPILLS NOT NOTIFIED, NO INSPECTION OF TANK EXCAVATION, REPORT STATES THAT TANK WAS REMOVED ALONG WITH 90 TONS CONTAMINATED SOILS, DISPOSAL FILED UNDER 9875088, LEVELS WITHIN INACTIVE GUIDANCE, SENT INACTIVE LETTER"

Material Information

OP Unit ID:	1091579	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	291964	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0008		
Material Name:	diesel		

Spiller Information

Spiller Name:	AL GUSTAFSON
Spiller Company:	ROSWELL PARK CANCER INST
Spiller Address:	ELM AND CARLTON STREETS
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14623-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.886649993
Longitude:	-78.867610023

Site: ***ROSWELL PARK CANCER INST***
CARLTON STREET BUFFALO NY

NY SPILLS

Spill No:	9975440	***UST Trust:***	False
Site ID:	325431	***Spill Date:***	1998-10-02 12:00:00
DER Facility ID:	262142	***Received Date:***	1999-04-16 08:00:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2000-03-27 00:00:00
Water Body:		***Create Date:***	1999-09-28 11:33:00
Class:	B4	***Update Date:***	2000-03-31 00:00:00
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RMCROSSE
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CONTAMINATION NOTED DURING TANK REMOVAL, SPILLS NOT NOTIFIED AT TIME OF REMOVAL, TANK NUMBER 107 "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/28/99: RMC REVIEWED REPORT, SPILLS NOT NOTIFIED AT TIME OF REMOVAL, UST NUMBER 107, RESULTS SHOW CONTAMINATION, REQUIRES FURTHER ASSESSMENT AND REMEDIATION, PLAN SUBMITTED, OK TO START, REPORT DUE 1/1/00 01/21/99: RMC TELECON RORY WOODMANSEE, CAND S 315-455-2000, ANOTHER CONSULTANT HAS BEEN HIRED BY OGS, RMC AGAIN WENT OVER ASSESSMENT REQUIREMENTS, REPORT DUE 2/28/00 03/27/00: RMC REVIEWED REPORT, EXTENSIVE SAMPLING DONE AROUND FORMER UST PIT, ONLY MINOR EXCEEDANCES FOUND, NO FURTHER ACTION REQUIRED, INACTIVE"

Material Information

OP Unit ID:	1093842	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	291971	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		

Material Code: 0008
Material Name: diesel

Spiller Information

Spiller Name: AL GUSTAFSON
Spiller Company: ROSWELL PARK CANCER INST
Spiller Address: ELM AND CARLTON
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14623-
Spiller Country: 001
Contact Name: AL GUSTAFSON
Contact Phone: (716) 845-5886
Contact Ext:
Latitude: 42.886649993
Longitude: -78.867610023

Site: ***SUNY AT BUFFALO***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	8706241	***UST Trust:***	False
Site ID:	263237	***Spill Date:***	1987-10-23 14:40:00
DER Facility ID:	282665	***Received Date:***	1987-01-23 15:10:00
CID:		***CAC Date:***	1987-10-23 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1987-10-23 00:00:00
Water Body:		***Create Date:***	1987-10-29 00:00:00
Class:		***Update Date:***	2004-09-30 21:28:29.950000000
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	LEARY
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Human Error
Reported by: Local Agency
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

""

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL / / : RNL TELECON NYSDOH 10/23/87, DOH, W. OBRIEN, ON SCENE, CONTAINED WITHIN BUILDING, UNDER CONTROL, NO FURTHER SPILL UNIT INVOLVEMENT. "

Material Information

OP Unit ID:	912276	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	465261	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False

Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	
Spiller Company:	SUNY AT BUFFALO
Spiller Address:	MAIN STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.943809993
Longitude:	-78.839240022

Site: ***DONAVAN OFFICE BLDG***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	8901121	***UST Trust:***	False
Site ID:	263243	***Spill Date:***	1989-05-04 08:00:00
DER Facility ID:	282665	***Received Date:***	1989-05-04 13:00:00
CID:		***CAC Date:***	1989-05-05 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1989-05-05 00:00:00
Water Body:		***Create Date:***	1989-05-08 00:00:00
Class:		***Update Date:***	2002-03-18 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	MJHINTON
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"TANK FILLED FOR TESTING OVERFLOWED DUE TO PRODUCT EXPANSION"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH 05/08/89: SPILL CLEANED UP W/ 1 BAG SPEEDY DRY DEBRIS PLACED WITH CONTAMINATED SOIL FROM GASOLINE TANK REMOVAL. "

Material Information

OP Unit ID:	927256	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	452429	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	1.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0002A		
Material Name:	#4 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	DONAVAN OFFICE BLDG
Spiller Address:	MAIN STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.943809993
Longitude:	-78.839240022

Site: ***GOODYEAR REPAIR***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	9110007	***UST Trust:***	False
Site ID:	263251	***Spill Date:***	1991-12-01 12:00:00
DER Facility ID:	282665	***Received Date:***	1991-12-13 15:20:00
CID:		***CAC Date:***	1993-05-12 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1993-05-12 00:00:00
Water Body:		***Create Date:***	1991-12-20 00:00:00
Class:	D6	***Update Date:***	1993-05-24 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SORGI
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Housekeeping		
Reported by:	Affected Persons		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"GOODYEAR WASHES DOWN CAR FLUIDS FROM REPAIRS"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 12/16/91: MJS/SITE - SOME RESIDUE FROM WASHING OPERATION. CLEANUP N0T WARRANTED. INFORMED GOODYEAR OF COMPLAINT. GOODYEAR WILL TRY TO CLEAN UP AS MUCH FLUID AS POSSIBLE BEFORE WASHING. 05/12/93: MJS REVIEWED FILE. NO FURTHER ACTION NECESSARY. MJS TO CLOSE FILE. "

Material Information

OP Unit ID:	963699	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	418585	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0043A		
Material Name:	antifreeze		

OP Unit ID:	963699	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	418584	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		

Material Code: 0022
Material Name: waste oil/used oil

Spiller Information

Spiller Name:
Spiller Company: GOODYEAR
Spiller Address: MAIN STREET
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.943809993
Longitude: -78.839240022

Site: ***IN FRONT OF 1ST NIAGARA CENTER MAIN ST BUFFALO NY***

NY SPILLS

Spill No: 2106683
Site ID: 625583
DER Facility ID: 364175
CID:
Program Type: ER
SWIS Code: 1502
Water Body: BUFFALO RIVER
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust: False
Spill Date: 2021-10-17 05:30:00
Received Date: 2021-10-17 05:59:00
CAC Date:
Insp Date:
Close Date: 2021-10-17 00:00:00
Create Date: 2021-10-17 06:03:00
Update Date: 2021-10-18 13:15:41.900000000
DEC Region: 9
Lead DEC: FXGALLEG
After Hours: True

Caller Remark:

"from boom truck. over the sewer. leads to Buffalo River. applied some absorbent, but not enough."

DEC Remark:

"10/17/21 FG spoke to Mike Nosbisch with the NFTA. He requested the Department's response to the scene. He said that Ferguson was on site doing work for the NFTA and a piece of equipment failed and a spill of 5 gal happened. Mr. Nosbisch is concerned that the cleanup completed by Ferguson is adequate and he is concerned that the release impacted the Buffalo River. FG site inspection. Ferguson was on site and had completed the cleanup. There was a stain on the road where the spill happened. No hydraulic oil made it to the storm sewer. Ferguson bagged up the speedi dry into a few bags which will be placed in the regular waste stream. No further action is possible. The site is closed."

Material Information

OP Unit ID: 1372724
OU: 01
Material ID: 2386068
CAS No:
Material Family: Petroleum
Quantity: 10.00
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 0010
Material Name: hydraulic oil

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: MIKE NOSBISCH
Spiller Company: FERGUSON ELECTRIC
Spiller Address: MAIN ST
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: MIKE NOSBISCH
Contact Phone: (716) 481-6101
Contact Ext:
Latitude:
Longitude:

Site: ***STREET***
MICHIGAN AVE BUFFALO NY

NY SPILLS

Spill No: 1911697
Site ID: 602402
DER Facility ID: 550947
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class:
Meets Std: False
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Equipment Failure
Reported by: DEC
Referred to:
Source: Commercial Vehicle
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 2020-03-24 09:00:00
Received Date: 2020-03-24 09:00:00
CAC Date:
Insp Date:
Close Date: 2020-03-24 00:00:00
Create Date: 2020-03-24 09:41:00
Update Date: 2020-03-24 09:45:27.370000000
DEC Region: 9
Lead DEC: TDJOHNSO
After Hours: False

Caller Remark:

"Republic Services released radiator fluid on Michigan Ave. and down DEC driveway."

DEC Remark:

"03/24/20 TDJ WENT INTO PARKING LOT WHERE SPILL HAD JUST OCCURED. REPUBLIC WORKERS BEGAN SPREADING SPEEDY DRY ONTO MICHIGAN AVE AND DEC DRIVE. MOST WAS A SPRAY ONTO ASPHALT AND WAS COVERED WITH SPEEDY DRY TO BE LEFT TO GRIND INTO SURFACE. TRUCK WAS REPAIRED AND SPILL WAS COMPLETED. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY"

Material Information

OP Unit ID: 1349545
OU: 01
Material ID: 2360165
CAS No:
Material Family: Other
Quantity: 7.00
Units: G
Recovered:
Med Soil: False
Med Air: False
Material Code: 1559A
Material Name: radiator fluid

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: False
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: larry manney
Spiller Company: Republic Services
Spiller Address: 2321 kenmore ave
Spiller City: buffalo
Spiller State: NY
Spiller Zip:

Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude:
Longitude:

Site: ***UB SOUTH CAMPUS***
MAIN ST BUFFALO NY

NY SPILLS

Spill No:	1901415	***UST Trust:***	
Site ID:	588290	***Spill Date:***	2019-05-09 12:00:00
DER Facility ID:	364175	***Received Date:***	2019-05-09 14:00:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2019-07-10 00:00:00
Water Body:		***Create Date:***	2019-05-09 14:30:00
Class:	C3	***Update Date:***	2019-09-12 09:12:51.420000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	CMMIKIDA
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Equipment Failure
Reported by: Other
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"AST tank test failure. Product in containment dike.2 to 3 inches. Slow leak. Call preston to get on site"

DEC Remark:

"PBS # 9-088668 tank #33 failed. 3000 gallon AST #2 fuel oil. 05/10/19 CMM site investigation. Arrived on site, met with Preston, and visually inspected AST #33. Tank has slow leak somewhere underneath and the containment dike has several inches of product collecting. Containment dike appears to be intact and product has no routes to escape. The dike is mostly covered and should not capture much rainwater. Preston has put in work order for vac truck to remove product from tank and dike. Product removed from tank will be reused and product from dike will be disposed of properly. Preston will advise me when that work is being completed and provide me with disposal receipts. Communicated with PBS that Brian Foti will be in charge of submitting paper work for tank replacement. 05/13/19 CMM email from Preston Monkelban. Preston stated that product was transferred from tank #33 to tank #39 and to a 1000 gallon rental tank that arrived on site. No product remains in tank #33, however there is still several inches of product in containment that needs to be disposed of properly. Advised Preston to complete disposal as soon as possible. Work order has been submitted for new tank. Will check back when further work has been completed. 05/29/19 CMM received phone call from Preston. He stated that containment dike is being pumped out and waste is being disposed of properly. Will receive disposal receipts. 07/10/19 CMM email from Brain Foti. Drums picked up during regular waste run. No further action. Spill closed. "

Material Information

OP Unit ID:	1335955	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2345292	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	20.00	***Med Surf:***	True
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code: 0001A
Material Name: #2 fuel oil

Spiller Information

Spiller Name: preston
Spiller Company: sunyat buffalo
Spiller Address:
Spiller City:
Spiller State: NY

Spiller Zip:
Spiller Country: 999
Contact Name: KEN MARTINO
Contact Phone: (716) 572-1144
Contact Ext:
Latitude:
Longitude:

Site: ***GENERAL MILLS DOCK TO WATER***
SOUTH MICHIGAN AVE BUFFALO NY

NY SPILLS

Spill No:	1606604	***UST Trust:***	False
Site ID:	533233	***Spill Date:***	2016-10-04 14:32:00
DER Facility ID:	210562	***Received Date:***	2016-10-04 14:41:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2016-10-05 00:00:00
Water Body:	BUFFALO RIVER	***Create Date:***	2016-10-04 14:44:00
Class:		***Update Date:***	2016-10-05 12:51:28.487000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	TDJOHNSO
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Unknown
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"unknown silvery 20x 12 ribbon sheen in the water."

DEC Remark:

"10/04/16 TDJ WENT TO LOCATION WHERE NO SHEEN WAS FOUND. NO FURTHER ACTION FILE CLOSED TO ELECTRONIC ONLY "

Material Information

OP Unit ID:	1281957	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2287265	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:		***Med Surf:***	False
Units:		***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		

Material Code: 0066A
Material Name: unknown petroleum

Spiller Information

Spiller Name: JEFF RUBINI
Spiller Company: UNKNOWN
Spiller Address: SOUTH MICHIGAN AVE
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name: JEFF RUBINI
Contact Phone: (856) 642-2091
Contact Ext:
Latitude:
Longitude:

Site: ***GENERAL MILLS***
MICHIGAN AVENUE BUFFALO NY

NY SPILLS

Spill No:	9105790	***UST Trust:***	False
Site ID:	170396	***Spill Date:***	1991-08-27 12:30:00
DER Facility ID:	143373	***Received Date:***	1991-08-27 13:00:00
CID:		***CAC Date:***	1991-08-30 00:00:00
Program Type:	ER	***Insp Date:***	1991-08-30 00:00:00
SWIS Code:	1502	***Close Date:***	1991-08-30 00:00:00
Water Body:		***Create Date:***	1991-08-28 00:00:00
Class:		***Update Date:***	1991-12-06 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	COOKE
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"FOOD COLORING SPILLED"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 08/27/91: BLUE FOOD COLORING DYE WASHED INTO STORM DRAIN AT DUMPSTER DURING ROUTINE GROUNDS MAINTENANCE. NO CLEANUP REQUIRED. 08/30/91: JDC INSPECTED REMEDIAL ACTION AND FOUND EFFORT SATISFACTORY. NO FURTHER ACTION WILL BE RQUIRED. "

Material Information

OP Unit ID:	956281	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	421565	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	GENERAL MILLS
Spiller Address:	54 SOUTH MICHIGAN AVENUE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14203
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901655993
Longitude:	-78.862680023

Site: ***IN ROAD***
WASHINGTON BUFFALO NY

NY SPILLS

Spill No:	0550698	***UST Trust:***	False
Site ID:	349892	***Spill Date:***	2005-07-25 12:00:00
DER Facility ID:	296315	***Received Date:***	2005-07-25 09:30:00
CID:		***CAC Date:***	

Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2005-07-26 00:00:00
Water Body:		***Create Date:***	2005-07-25 11:54:00
Class:		***Update Date:***	2005-07-26 13:43:50.297000000
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	FXGALLEG
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Unknown
Reported by: Affected Persons
Referred to:
Source: Unknown
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"UNKNOWN OIL IN ROAD WASHINTON NEAR ELLICOTTS BUILDING. MATERIAL IS ALL OVER THE ROAD."

DEC Remark:

"7/26/05 FG SITE INSPECTION. STAIN ON ROAD IN FRONT OF ELLICOTT SQUARE BLDG. SOURCE UNKNOWN. NO ACTION POSSIBLE BY SPILLS. SITE CLOSED. ELECTRONIC FILE ONLY."

Material Information

OP Unit ID:	1107480	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2097372	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:		***Med Surf:***	True
Units:	G	***Med Subway:***	False
Recovered:		***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	False
Med Air:	False		

Material Code: 0064A
Material Name: unknown material

Spill Data

Material Name: unknown material
Material Family: Other
Quantity: 0
Units: Gallons
Recovered: 0

Site: ***NIMO VAULT***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	0501616	***UST Trust:***	False
Site ID:	345803	***Spill Date:***	2005-05-10 11:45:00
DER Facility ID:	292042	***Received Date:***	2005-05-10 12:20:00
CID:	444	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1500	***Close Date:***	2005-05-10 00:00:00
Water Body:		***Create Date:***	2005-05-10 12:46:00
Class:		***Update Date:***	2005-05-10 13:38:27
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	FXGALLEG
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Institutional, Educational, Gov., Other
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CREW ENROUTE:"

DEC Remark:

"5/10/05 MINOR SPILL, CLOSED. ELECTRONIC FILE ONLY."

Material Information

OP Unit ID:	1103518	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	583737	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	3.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0020A		
Material Name:	transformer oil		

Spiller Information

Spiller Name:	LISA FREDERICKS
Spiller Company:	NIMO VAULT
Spiller Address:	MAIN STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	LISA FREDERICKS
Contact Phone:	(716) 479-5339
Contact Ext:	
Latitude:	
Longitude:	

Site: ***IN STREET***
ELLICOTT ST. BUFFALO NY

NY SPILLS

Spill No:	0750398	***UST Trust:***	
Site ID:	382908	***Spill Date:***	2007-06-14 07:30:00
DER Facility ID:	332358	***Received Date:***	2007-06-14 08:00:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2007-06-14 00:00:00
Water Body:		***Create Date:***	2007-06-14 08:55:00
Class:	C4	***Update Date:***	2007-06-14 08:55:10.577000000
Meets Std:	True	***DEC Region:***	9
Penalty:		***Lead DEC:***	rjjonak
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Fire Department		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"CALLER STATES THAT THERE IS A TRANSMISSION FLUID SLICK ON ELLICOTT ST. IN FRONT OF THE ERIE CO. LIBRARY...THE BUFFALO FIRE DEPT. SPREAD SPEED DRY AND WILL PICK UP THE MATERIAL."

DEC Remark:

"6/14/2007: TOMMY FITZPATRICK,BUFFALO FIRE DEPT. TELECON RJJ,HE SAID THAT THERE IS A TRANSMISSION FLUID(~1 GAL) SPILL (FROM AN UNKNOWN VEHICLE) ON ELLICOTT ST. IN FRONT OF THE ERIE CO. LIBRARY...THEY SPREAD SPEEDI-DRY ON THE SPILL, SWEEPED UP THE MATERIAL,AND WILL DISPOSE THE MATERIAL IN THEIR DUMPSTER...NONE OF THE FLUID REACHED ANY RECEIVERS

OR SOIL,IT WAS ALL RECOVERED...THE SPILL HAS BEEN CLEANED UP AND PROPERLY DISPOSED OF...NO FURTHER ACTION NEEDED... SPILL CLOSED OUT."

Material Information

OP Unit ID:	1140287	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2130351	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	True
Units:	G	***Med Subway:***	False
Recovered:	1.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	False
Med Air:	False		
Material Code:	0021		
Material Name:	transmission fluid		

Spiller Information

Spiller Name:	
Spiller Company:	
Spiller Address:	
Spiller City:	
Spiller State:	
Spiller Zip:	
Spiller Country:	
Contact Name:	TOMMY FITZPATRICK
Contact Phone:	(716) 864-9278
Contact Ext:	
Latitude:	
Longitude:	

Site: ***BUFFALO FUEL TRUCK***
ELMWOOD AVENUE BUFFALO NY

NY SPILLS

Spill No:	9802486	***UST Trust:***	False
Site ID:	330733	***Spill Date:***	1998-05-27 10:00:00
DER Facility ID:	266013	***Received Date:***	1998-05-27 11:45:00
CID:	999	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1998-07-01 00:00:00
Water Body:		***Create Date:***	1998-05-27 00:00:00
Class:	C4	***Update Date:***	1998-07-09 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SORGI
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial Vehicle		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"hydraulic line failure - spilled to soil"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 05/27/98: MJS TOOK REPORT FROM MR O'MALLEY. THEY WILL CLEAN SOILS TODAY. 06/30/98: MJS TELECON TO MR O'MALLEY AND LEFT MESSAGE FOR HIM TO CALL. 07/01/98: MJS RECEIVED FAX OF SOIL ANALYSIS AND DISPOSAL RECEIPT FROM MR O'MALLEY. NO FURTHER ACTION REQUIRED. MJS CLOSE FILE."

Material Information

OP Unit ID:	1063138	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	320814	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	50.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	50.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		

Material Code: 0010
Material Name: hydraulic oil

Spiller Information

Spiller Name:
Spiller Company: BUFFALO FUEL COMPANY
Spiller Address: 344 VULCAN STREET
Spiller City: BUFFALO
Spiller State: NY
Spiller Zip: 14207-
Spiller Country: 001
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.949989993
Longitude: -78.860480023

Site: ***AMERICANA***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	9106228	***UST Trust:***	False
Site ID:	263250	***Spill Date:***	1991-09-05 08:00:00
DER Facility ID:	282665	***Received Date:***	1991-09-05 11:00:00
CID:		***CAC Date:***	1991-12-05 00:00:00
Program Type:	ER	***Insp Date:***	1991-12-05 00:00:00
SWIS Code:	1502	***Close Date:***	1991-12-05 00:00:00
Water Body:	BUFFALO RIVER	***Create Date:***	1991-09-30 00:00:00
Class:		***Update Date:***	1992-01-27 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	MJHINTON
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Deliberate
Reported by: Citizen
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"15 DRUMS LEFT ON NFTA DOCK BY THE AMERICANA"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJH 09/30/91: NFTA TO ARRANGE FOR REMOVAL AND CLEANUP. 12/16/91: MJH SITE VISIT DRUMS OF WASTE OIL HAS BEEN REMOVED NO FURTHER ACTION NECESSARY. "

Material Information

OP Unit ID:	960557	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	421957	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False

Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	AMERICANA
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.943809993
Longitude:	-78.839240022

Site: ***SHEEN IN BUFFALO CANAL***
MICHIGAN AVENUE BUFFALO NY

NY SPILLS

Spill No:	9806584	***UST Trust:***	False
Site ID:	170397	***Spill Date:***	1998-08-19 08:15:00
DER Facility ID:	143373	***Received Date:***	1998-08-19 10:15:00
CID:	999	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1998-08-31 00:00:00
Water Body:	BUFFALO CANAL	***Create Date:***	1998-08-27 00:00:00
Class:	D6	***Update Date:***	1998-09-21 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SACALAND
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Citizen		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"OIL SLICK FOUND ON THE RIVER-SOURCE UNKNOWN."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAC 8/19/98:SAC CONTACTED COAST GUARD REGARDING REPORT,COAST GUARD AGREED TO INSPECT, COAST GUARD CALLED BACK AND FOUND SLIGHT SHEEN ON WATER BUT NO SOURCE,COAST GUARD BELIEVES IT PROBABLY CAME FROM RUN OFF DUE TO RAIN YESTERDAY,SAC TELECON ART DOMINO, ERIE CO. EMERGENCY SERVICES NOTIFYING HIM OF REPORT & FINDINGS."

Material Information

OP Unit ID:	1064198	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	317738	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0064A		
Material Name:	unknown material		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.901655993
Longitude:	-78.862680023

Site: ***BUFFALO NEWS***
WASHINGTON STREET BUFFALO NY

NY SPILLS

Spill No:	8605922	***UST Trust:***	False
Site ID:	190132	***Spill Date:***	1986-12-18 01:00:00
DER Facility ID:	158642	***Received Date:***	1986-12-18 08:55:00
CID:		***CAC Date:***	1986-12-18 00:00:00
Program Type:	ER	***Insp Date:***	1986-12-18 00:00:00
SWIS Code:	1502	***Close Date:***	1986-12-18 00:00:00
Water Body:		***Create Date:***	1987-01-30 00:00:00
Class:		***Update Date:***	2004-09-30 21:28:29.950000000
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	LEARY
REM Phase:	0	***After Hours:***	False

County:	Erie
Contributing Factor:	Equipment Failure
Reported by:	Responsible Party
Referred to:	
Source:	Tank Truck
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

""

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL / / : RNL SITE INSP. 12/18/86, CLEANUP UNDERWAY AND SATISFACTORY, DISPOSAL REMAINS; 12/18/86, SPILLER NOTIFIED OF DISPOSAL REQUIREMENTS, COMPLETE. "

Material Information

OP Unit ID:	902758	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	475065	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	True
Quantity:	30.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	20.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		

Material Code:	0582A
Material Name:	ink

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO NEWS
Spiller Address:	WASHINGTON STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202

Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.841589993
Longitude:	-78.756360019

Site: ***CANISTERS - NAVAL PARK***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	9608221	***UST Trust:***	False
Site ID:	263257	***Spill Date:***	1996-10-02 01:00:00
DER Facility ID:	282665	***Received Date:***	1996-10-02 01:21:00
CID:	216	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1996-10-02 00:00:00
Water Body:		***Create Date:***	1996-10-02 00:00:00
Class:	D4	***Update Date:***	1996-10-09 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	LEARY
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Other		
Reported by:	Police Department		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"after a concert above was confiscated from some subjects at the concert 8 canisters total unk how much in each canister "

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RNL 10/02/96: RNL RECEIVED FROM DUTY OFFICER, POLICE WANTED TO KNOW WHERE TO STORE CANISTERS 10/02/96:RNL CALLED CITY OF BUFFALO POLICE, THEY STORED CANISTERS AT THEIR POLICE SENECA GARAGE FOR POSSIBLE EVIDENCE, TOLD OFFICER ABOUT BSA OPTION FOR STORAGE, OK, NO FURTHER ACTION REQUIRED "

Material Information

OP Unit ID:	1036500	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	343962	***Med SW:***	False
CAS No:	10102439	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	1969A		
Material Name:	nitric oxide		

Spiller Information

Spiller Name:	
Spiller Company:	UNKNOWN
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.943809993
Longitude:	-78.839240022

Site: ***BUFFALO NEWS***
WASHINGTON STREET BUFFALO NY

NY SPILLS

Spill No:	8708866	***UST Trust:***	False
Site ID:	190133	***Spill Date:***	1988-01-18 14:30:00
DER Facility ID:	158642	***Received Date:***	1988-01-18 15:28:00
CID:		***CAC Date:***	1988-01-27 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	1988-01-27 00:00:00
Water Body:		***Create Date:***	1988-01-26 00:00:00
Class:		***Update Date:***	1988-01-29 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	PRINGLE
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Traffic Accident		
Reported by:	Responsible Party		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

""

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MNP / / : MNP TELECON 01/18/88, SPILL CLEANED UP BY SPILLER, TO INSPECT SITE. / / : MNP TELECON 01/18/88, SPILL CLEANED UP BY SPILLER, TO INSPECT SITE; MNP 01/27/88, INSPECTION NOT PERFORMED, NO LONGER NECESSARY, COMPLETE. "

Material Information

OP Unit ID:	914127	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	464223	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	5.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	5.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO NEWS
Spiller Address:	WASHINGTON STREET
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.841589993
Longitude:	-78.756360019

Site: ***DUMPING AT NAVAL PARK***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	9802175	***UST Trust:***	False
Site ID:	263259	***Spill Date:***	1998-04-25 11:00:00
DER Facility ID:	282665	***Received Date:***	1998-05-18 14:00:00

CID:	211	***CAC Date:***	
Program Type:	ER	***Insp Date:***	1998-05-19 00:00:00
SWIS Code:	1502	***Close Date:***	1998-05-19 00:00:00
Water Body:		***Create Date:***	1998-05-19 00:00:00
Class:	D6	***Update Date:***	1998-05-21 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	SORGI
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Deliberate
Reported by: Citizen
Referred to:
Source: Private Dwelling
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"BEC 1 UNIT RECEIVED WRITTEN COMPLAINT AND PHOTOS OF UNKNOWN PERSON DUMPING UNKNOWN SUBSTANCE ON GRASS AREA"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MJS 05/19/98: BECI UNIT RECEIVED WRITTEN COMPLAINT WITH PHOTOS. INCIDENT HAPPENNED THREE WEEKS AGO. MJS AND MR GROEBE INSPECTED SITE AND FOUND EXACT LOCATION OF ALLEDGED DUMPING FROM PHOTOS AND DETAILED DESCRIPTION IN LETTER. FOUND NO EVIDENCE OF OIL OR OTHER CONTAMINATION. NO STRESSED VEGETATION. NO FURTHER ACTION REQUIRED BY SPILL UNIT. MR GROEBE WILL CONTACT COMPLAINTANT. MJS CLOSE FILE."

Material Information

OP Unit ID:	1060214	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	320513	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		

Material Code: 0064A
Material Name: unknown material

Spiller Information

Spiller Name:
Spiller Company: UNKNOWN
Spiller Address:
Spiller City:
Spiller State: NY
Spiller Zip:
Spiller Country: 999
Contact Name:
Contact Phone:
Contact Ext:
Latitude: 42.943809993
Longitude: -78.839240022

Site: ***MEMORIAL AUD***
WASHINGTON STREET BUFFALO NY

NY SPILLS

Spill No:	0275592	***UST Trust:***	False
Site ID:	190131	***Spill Date:***	2003-03-27 13:25:00
DER Facility ID:	158642	***Received Date:***	2003-03-27 13:25:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	2003-03-31 00:00:00
SWIS Code:	1502	***Close Date:***	2003-11-17 00:00:00
Water Body:		***Create Date:***	2003-03-27 13:27:00
Class:	D3	***Update Date:***	2003-11-17 00:00:00

Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RMCROSSE
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Responsible Party		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"equipment failure, basement is flooded"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 03/27/03 RMC/DAVE HORNUNG/SITE. BASEMENT FLOODED, MILLION PLUS GALLONS, SCUM SHEEN ON TOP. SOME PETROLEUM SOURCES IN BASEMENT, RMC ADVIED TO CONTACT BSA TO SEE ABOUT PUTTING IN SANITART, RMC CALLED JORDAN AT BSA AND ADVISED OF THE PROBLEM, UPDATED PJB 03/28/03 RMC/FILE. MLD MEETING. RMC/SITE. MLD APPROVED DISCHARGE TO STORM SEWER, MAJORITY COMPLETED BY 730 PM ON 3/27. THEY THEN FOUND A SANITARY SEWER IN THE BUILDING, HORNUNG ADVISED THAT BSA WAS ON SITE SEVERAL TIMES. 04/03/03 RMC/FILE. FAXED OVER STATE CONTRACTOR LIST THE CITY REQUESTED UPDATE 4/30/03 11/17/03 RMC/FILE. WATER WAS ULTIMATEL DISCHARGED TO BSA. NO SPILL ACTION REQUIED, CLOSE OUT AS A SPILLS ISSUE. NO PAPER FILE. "

Material Information

OP Unit ID:	868191	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	507950	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	True
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	DAVE HORNUNG
Spiller Company:	CITY OF BUFFALO
Spiller Address:	616 CITY HALL
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14202-
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.841589993
Longitude:	-78.756360019

Site: ***MEMORIAL AUDITORIUM***
MAIN ST BUFFALO NY

NY SPILLS

Spill No:	0902966	***UST Trust:***	
Site ID:	415043	***Spill Date:***	2009-06-12 12:30:00
DER Facility ID:	364175	***Received Date:***	2009-06-12 13:00:00
CID:		***CAC Date:***	
Program Type:	ER	***Insp Date:***	2009-06-12 00:00:00
SWIS Code:	1502	***Close Date:***	2009-07-02 00:00:00
Water Body:		***Create Date:***	2009-06-12 13:11:00
Class:	D3	***Update Date:***	2009-07-02 14:44:17.070000000
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	JFOTTO
REM Phase:	0	***After Hours:***	False

County: Erie
Contributing Factor: Equipment Failure
Reported by: Responsible Party
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"Company was removing an ethylene glycol line they thought was empty. It was soaked up with speedy dry."

DEC Remark:

"06/12/09 JFO ON SITE MET WITH MIKE BYRNE & BOB KREUZER BOTH W/LIRO ENGINEERS. HE ESTIMATES THE SPILL AT 10 GALLONS. IT HAS BEEN CLEANED UP WITH SPEEDY DRY AND PLACED IN 3 DRUMS. RECEIPTS TO FOLLOW. 07/02/09 JFO RECEIVED THE RECEIPTS FOR THE 3 DRUMS. NO FURTHER ACTION REQUIRED. CLOSED"

Material Information

OP Unit ID: 1171404
OU: 01
Material ID: 2163206
CAS No: 00107211
Material Family: Hazardous Material
Quantity: 10.00
Units: G
Recovered: 10.00
Med Soil: False
Med Air: False
Material Code: 0028A
Material Name: ethylene glycol

Med Ind Air: False
Med GW: False
Med SW: False
Med DW: False
Med Sewer: False
Med Surf: True
Med Subway: False
Med Utility: False
Oxygenate:

Spiller Information

Spiller Name: MIKE BYRNE
Spiller Company: LIRO ENGINEERS
Spiller Address:
Spiller City:
Spiller State: NN
Spiller Zip:
Spiller Country: 999
Contact Name: MIKE BYRNE
Contact Phone: (716) 913-7953
Contact Ext:
Latitude:
Longitude:

Site: ***MEMORIAL AUD***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No: 0812894
Site ID: 410544
DER Facility ID: 359788
CID:
Program Type: ER
SWIS Code: 1502
Water Body:
Class: D3
Meets Std: True
Penalty: False
REM Phase: 0
County: Erie
Contributing Factor: Human Error
Reported by: Other
Referred to:
Source: Commercial/Industrial
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

UST Trust:
Spill Date: 2009-02-27 12:00:00
Received Date: 2009-02-27 13:22:00
CAC Date:
Insp Date: 2009-03-10 00:00:00
Close Date: 2009-03-25 00:00:00
Create Date: 2009-02-27 13:26:00
Update Date: 2009-03-25 10:26:50.117000000
DEC Region: 9
Lead DEC: JFOTTO
After Hours: False

Caller Remark:

"GLYCOL SPILL AT AUD HAPPENED WHEN REMOVING EQUIPMENT, ALL CLEANED UP WITH SPEEDY DRY"

DEC Remark:

"02/27/09 JFO ON SITE MET WITH BOB KREUZER. SEVERAL PLASTIC COILS CONTAINING GLYCOL WERE PLACED OUTSIDE THE BLDG. SOME MINOR SPILLAGE WAS DISCOVERED. A BERM, WITH SPEEDY DRY AND BOOMS, WAS PLACED AROUND THE THE STAGED COILS. THE SPILLAGE IS CONTAINED AND WILL BE ADDRESSED MONDAY. 03/02/09 JFO ON SITE MET WITH MIKE BYRNE. THEY REMOVED THE GLYCOL FROM 2 COILS. 100 GALLONS OF WATER AND GLYCOL WERE DRUMED. 03/12/09 CALL FROM MIKE BYRNE. THEY HAVE RECOVERED APPROX 1600 GALLONS OF WATER AND GLYCOL TOTAL. HE WILL SEND RECEIPTS. 03/13/09 JFO E-MAIL FROM MIKE BYRNE. HE WILL SUBMIT ALL RECEIPTS NEXT WEEK WHEN THE CLEANUP MATERIAL IS DISPOSED. 03/25/09 JFO RECEIVED THE CLOSURE LETTER ALONG WITH THE DISPOSAL RECEIPTS FOR 1600 GALLONS OF ETHYLENE GLYCOL-WATER MIXTURE AND 4 DRUMS OF SOLIDS. NO FURTHER ACTION REQUIRED. CLOSED"

Material Information

OP Unit ID:	1167028	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	2158551	***Med SW:***	False
CAS No:	00107211	***Med DW:***	False
Material Family:	Hazardous Material	***Med Sewer:***	False
Quantity:	1.00	***Med Surf:***	True
Units:	G	***Med Subway:***	False
Recovered:	1.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0028A		
Material Name:	ethylene glycol		

Spiller Information

Spiller Name:	MIKE BYRNE
Spiller Company:	LIRO ENGINEERS
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	BOB KREUZER
Contact Phone:	(646) 772-1312
Contact Ext:	
Latitude:	
Longitude:	

Site: ***ELLICOTT SQUARE***
ELLICOTT SQUARE BLDG BUFFALO NY

NY SPILLS

Spill No:	9408628	***UST Trust:***	False
Site ID:	328936	***Spill Date:***	1994-09-20 12:00:00
DER Facility ID:	264728	***Received Date:***	1994-09-27 09:10:00
CID:		***CAC Date:***	1994-10-03 00:00:00
Program Type:	ER	***Insp Date:***	1994-09-27 00:00:00
SWIS Code:	1502	***Close Date:***	1994-10-03 00:00:00
Water Body:		***Create Date:***	1994-10-01 00:00:00
Class:	D3	***Update Date:***	1994-10-07 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RMCROSSE
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Other		
Reported by:	Affected Persons		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"STRONG FUEL OIL ODOR IN BLDG FOR PAST WEEK, FANS DRAW AIR IN THROUGH EXHAUST STACK"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RMC 09/27/94: RMC/HANNON/ SEINKIEWICZ ECDOH/SITE ODOR IN SEVERAL OFFICES ON FIRST AND SECOND FLOORS, INSPECTED FUEL HANDLING, NO PROBLEMS FOUND, WORKERS VERY CONCERNED, ECDOH TO TAKE LEAD AS NO SPILLAGE FOUND. 09/27/94: RMC/HANNON/PHONE HAD SYSTEM INSPECTED, NO PROBLEMS FOUND, HEATED UP STACK TO PUT NEGATIVE PRESSURE ON BLDG, PROBLEM STOPED, NO FURTHER ACTION REQUIRED, CLOSEOUT. "

Material Information

OP Unit ID:	1006323	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	378060	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0003A		
Material Name:	#6 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	CARL PALADINO
Spiller Address:	210 ELLICOTT SQUARE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14203
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.878863993
Longitude:	-78.876522023

Site: ***BUFFALO AIRPORT***
RT.33 BUFFALO NY

NY SPILLS

Spill No:	0200988	***UST Trust:***	False
Site ID:	213136	***Spill Date:***	2002-04-26 09:00:00
DER Facility ID:	176581	***Received Date:***	2002-04-26 09:29:00
CID:	257	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2002-07-26 00:00:00
Water Body:		***Create Date:***	2002-04-26 00:00:00
Class:	B3	***Update Date:***	2002-09-09 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	RJJONAK
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Equipment Failure		
Reported by:	Other		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"line was tested and found to be leaking"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was RJJ 4/26/02:SAC TELECON RICK ESHENOUR - HERTZ RENTAL CAR, MR. ESHENOUR WAS AWARE OF THE PROBLEM BUT TOLD SAC IT WAS NATIONAL CAR RENTAL'S TANK THAT HAD THE PROBLEM AND IT WAS

THE TANK THAT IS ON THE AIRPORT PROPERTY, MR. ESHENOURIS GOING TO A MEETING PRESENTLY TO DISCUSS THE LEAKING TANK AND WILL HAVE THE REPRESENTATIVE FROM NATIONAL CAR RENTAL CONTACT SAC. 4/26/02:SAC TELECON BOB PAPIA - NATIONAL CAR RENTAL, MR. PAPIA IS AWARE OF THE LEAK, AND IS WORKING ON DEALING WITH THE LEAK, HE IS GOING TO CONTACT A VENDOR TO REMOVE AND VACUUM OUT THE PRODUCT FROM THE TANK, HE WILL THEN HIRE A CONTRACTOR TO DETERMINE WHERE THE LEAK IS POSSIBLY USING A HELIUM TEST TO FIND THE PROBLEM, ONCE THEY DETERMINE WHERE IT IS THEY WILL BE EXCAVATING TO REMOVE THE CONTAMINATION FOUND AND THE EXPOSE THE LINE TO REPAIR IT, MR. PAPIA ASKED IF SAC HAD KNOWLEDGE OF ANY VENDORS THAT COULD REMOVE THE PRODUCT FORM THE TANK, SAC FAXED A COPY OF THE CONTRACTOR LIST TO MR. PAPIA. 4/26/02:SAC GAVE COPY OF SPILL REPORT TO AES, SAC ALSO e-MAILED AES REGARDING WHICH TANK HAD THE LINE LEAK. 4/26/2002: RJJ DRAFTED AND SENT A 'RP' LETTER TO NATIONAL CAR RENTAL. 5/8/2002: BOBBIE BARKMAN,ATTORNEY FOR NATIONAL CAR RENTAL,TELECON RJJ SAID THAT THEY RE-TESTED THE LINE AND IT PASSED,AND THAT THE SMALL AMOUNT OF PRODUCT WHICH LEAKED,LEAKED FROM THE PIPING INTO AN ACCESS MANHOLE AND WAS ALL CLEANED UP...THE CONTRACTOR,TANK KNOWLEDGE, WILL SEND ME THE REPORT... BOBBIE'S ADDRESS IS PAUL,HASTINGS,JANOFSKY,&WALKER LAW FIRM 1299 PENNSYLVANIA AVE. N.W. WASHINGTON,DC. 20004 THOMAS MOUNTEER IS THE PERSON AT THE LAW FIRM WORKING FOR NATIONAL. 5/13/2002: RECEIVED THE TANK TEST SITE SUMMARY REPORT FROM TANKNOLOGY,WHICH SHOWS THAT THE LINE TEST FAILED FOR TANK #1. 6/27/2002: RECEIVED A LETTER FROM ROBERTA BARKMAN,ATTORNEY FOR NATIONAL CAR RENTAL,EXPLAINING WHAT HAD HAPPENED...THEY HIRED C&W TO VAC UP BOTH SUMPS, WHERE THE GASOLINE LEAKED INTO, AND PERFORMED A LINE TEST...THEY DISCOVERED THAT THE UNION COLLOR CONNECTION WAS LOOSE,WHICH CAUSED THE FUEL LEAK...C&W REPAIRED THE LINE AND PERFORMED A LINE TEST AND IT PASSED. 7/26/2002: RECEIVED THE REPORT FROM C&W ENVIRONMENTAL INDICATING THAT THE LINE WAS RE-TESTED AND PASSED...SINCE THE LEAK WAS REPAIRED AND THE LINE TEST PASSED,NO FURTHER ACTION IS NEEDED...SPILL CLOSED OUT. 9/6/2002: DRAFTED AND SENT A 'CLOSURE' LETTER TO NATIONAL CAR RENTAL,AS PER THEIR REQUEST."

Material Information

OP Unit ID:	851987	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	522414	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0009		
Material Name:	gasoline		

Spiller Information

Spiller Name:	JAMES LINDVALL
Spiller Company:	NATIONAL CAR RENTAL SYSTE
Spiller Address:	7700 FRANCE AVENUE SOUTH
Spiller City:	MINNEAPOLIS
Spiller State:	MN
Spiller Zip:	55435-
Spiller Country:	001
Contact Name:	BOB PAPIA
Contact Phone:	(716) 570-4812
Contact Ext:	
Latitude:	
Longitude:	

Site: ***GENERAL MILLS***
SOUTH MICHIGAN AVE BUFFALO NY

NY SPILLS

Spill No:	0109857	***UST Trust:***	False
Site ID:	257164	***Spill Date:***	2002-01-11 16:30:00
DER Facility ID:	210562	***Received Date:***	2002-01-11 18:22:00
CID:	196	***CAC Date:***	2002-01-14 00:00:00
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2002-01-14 00:00:00
Water Body:		***Create Date:***	2002-01-11 00:00:00
Class:	D4	***Update Date:***	2002-01-14 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	MXFRANKS
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Unknown		
Reported by:	Responsible Party		

Referred to:
Source: Non Major Facility > 1,100 gal
Source File: NYSDEC - Environmental Remediation Data Files - Spill Data

Caller Remark:

"CALLER STATES THAT ABOUT 55 GALLONS OF BEET JUICE SOME HOW GOT INTO THE SEWER SYSTEM. REQUEST TO CALL DON NORTON AT CELL NUMBER 570-1776."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MF 01/12/02: MF T/C/DON NORTON, GEN MILLS, PROCESS VAT CONTAINING BEET JUICE WASHED TO SEWER IN THE PROCESS ROOM. SEWER ON MICHIGAN ST BACKED UP THRU MANWAY. SOME JUICE RESIDUE GOT INTO STORM SEWER. SEWERS MAY BE COMBINED IN THIS AREA. BSA AWARE OF PROBLEM. LARRY SITZMAN WAS IN CONTACT WITH RP YESTERDAY. NO FURTHER ACTION POSSIBLE.**********COMPUTER FILE ONLY**********"

Material Information

OP Unit ID:	846992	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	527501	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	True
Quantity:	55.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	53.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	1013A		
Material Name:	food dye		

Spiller Information

Spiller Name:	DON NORTON
Spiller Company:	GENERAL MILLS OPERATIONS
Spiller Address:	54 SOUTH MICHIGAN AVE
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	14203-
Spiller Country:	001
Contact Name:	DON NORTON
Contact Phone:	(716) 857-3573
Contact Ext:	
Latitude:	42.869779993
Longitude:	-78.878779024

Site: ***WEBSTER BLOCK-PARKING LOT***
WASHINGTON STREET BUFFALO NY

NY SPILLS

Spill No:	0103210	***UST Trust:***	False
Site ID:	129434	***Spill Date:***	2001-06-23 10:00:00
DER Facility ID:	158642	***Received Date:***	2001-06-23 10:36:00
CID:	297	***CAC Date:***	
Program Type:	ER	***Insp Date:***	
SWIS Code:	1502	***Close Date:***	2001-06-25 00:00:00
Water Body:		***Create Date:***	2001-06-23 00:00:00
Class:	B3	***Update Date:***	2001-11-14 00:00:00
Meets Std:	False	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	FXGALLEG
REM Phase:	0	***After Hours:***	True
County:	Erie		
Contributing Factor:	Housekeeping		
Reported by:	Other		
Referred to:			
Source:	Institutional, Educational, Gov., Other		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"COMPS COMPANY HIRED TO PERFORM SOME SOIL TESTING AND DISCOVERED A UNDERGROUND TANK THAT WAS NOT REPORTED TO BE THERE - CALLER STATES THEY CAN SMELL AN OIL ODOR COMING FROM THE SURROUNDING SOIL - CALLERS CELL PHONE 716-864-1730"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FG 6/25/01 THIS IS A DUPLICATE OF SPILL 0075529. ALL FURTHER ACTION WILL BE REFERRED TO THIS SPILL. THIS SPILL SITE CAN BE CLOSED."

Material Information

OP Unit ID:	839967	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	535303	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0001A		
Material Name:	#2 fuel oil		

Spiller Information

Spiller Name:	
Spiller Company:	BUFFALO URBAN RENEWAL
Spiller Address:	
Spiller City:	
Spiller State:	ZZ
Spiller Zip:	
Spiller Country:	001
Contact Name:	THOMAS FORBES
Contact Phone:	(716) 856-0599
Contact Ext:	
Latitude:	42.841589993
Longitude:	-78.756360019

Site: ***ABANDONED DRUM***
MICHIGAN STREET BUFFALO NY

NY SPILLS

Spill No:	8900042	***UST Trust:***	False
Site ID:	73544	***Spill Date:***	1989-04-03 14:00:00
DER Facility ID:	69211	***Received Date:***	1989-04-03 14:00:00
CID:		***CAC Date:***	1989-04-06 00:00:00
Program Type:	ER	***Insp Date:***	1989-04-06 00:00:00
SWIS Code:	1502	***Close Date:***	1989-04-06 00:00:00
Water Body:	BUFFALO RIVER	***Create Date:***	1989-05-10 00:00:00
Class:		***Update Date:***	1989-06-05 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	COOKE
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Abandoned Drums		
Reported by:	Federal Government		
Referred to:			
Source:	Unknown		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"DRUM FLOATING IN BUFFALO, KENDALL OIL LABELED ON DRUM"

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 04/04/89: JDC MET COAST GUARD ON SITE AND OBSERVED DRUM TO BE

FILLED W/ LAKE WATER TAINTED W/ A SHEEN. NO PETROLEUM PRODUCT WAS VISIABLE. CONTACTED PAM FARLEY, KEN OIL-THEY WILL BE SENDING TRUCK TO COLLECT DRUM. 04/06/89: JDC MET W/ COAST GUARD AND KENDAL OIL TO RECOVER DRUM. DRUM REMOVED AND LOADED ON BOX TRUCK FOR TRANSPORT TO KENDAL FACILITY. NO FUTHER ACTION WILL BE REQUIRED. 04/06/89: JDC MET COAST GUARD AND KENDALL EMPLOYEE ON SITE AND REMOVED DRUM FROM RIVER TO BOX TRUCK OWNED BY KENDALL. NO FURTHER ACTION WILLBE REQUIRED BY THIS UNIT. "

Material Information

OP Unit ID:	926448	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	451406	***Med SW:***	True
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	G	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	False	***Oxygenate:***	
Med Air:	False		
Material Code:	0066A		
Material Name:	unknown petroleum		

Spiller Information

Spiller Name:	
Spiller Company:	KENDALL REFINING
Spiller Address:	
Spiller City:	BUFFALO
Spiller State:	NY
Spiller Zip:	
Spiller Country:	001
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	
Longitude:	

Site: ***VICTOR'S MOTORS***
MAIN STREET BUFFALO NY

NY SPILLS

Spill No:	9300772	***UST Trust:***	False
Site ID:	263253	***Spill Date:***	1993-04-01 12:00:00
DER Facility ID:	282665	***Received Date:***	1993-04-14 12:00:00
CID:		***CAC Date:***	1993-04-21 00:00:00
Program Type:	ER	***Insp Date:***	1993-04-21 00:00:00
SWIS Code:	1502	***Close Date:***	1993-04-21 00:00:00
Water Body:		***Create Date:***	1993-04-20 00:00:00
Class:	D3	***Update Date:***	1997-03-28 00:00:00
Meets Std:	True	***DEC Region:***	9
Penalty:	False	***Lead DEC:***	COOKE
REM Phase:	0	***After Hours:***	False
County:	Erie		
Contributing Factor:	Housekeeping		
Reported by:	Citizen		
Referred to:			
Source:	Commercial/Industrial		
Source File:	NYSDEC - Environmental Remediation Data Files - Spill Data		

Caller Remark:

"VICTOR'S MOTORS IS DUMPING OIL & BATTERY ACID ON PROPERTY."

DEC Remark:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was JDC 04/21/93: JDC/VICTOR LORENZO, OWNER/SITE - NO EVIDENCE OF DELIBERATE SPILLAGE OF OIL AND/OR BATTERY ACID. WASTE OIL STORED IN AG STORAGE TANK. OFFERED SOME HANDLING RECOMMENDATIONS. NO FURTHER ACTION REQUIRED. "

Material Information

OP Unit ID:	979380	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	401515	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Petroleum	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0022		
Material Name:	waste oil/used oil		

OP Unit ID:	979380	***Med Ind Air:***	False
OU:	01	***Med GW:***	False
Material ID:	401516	***Med SW:***	False
CAS No:		***Med DW:***	False
Material Family:	Other	***Med Sewer:***	False
Quantity:	.00	***Med Surf:***	False
Units:	L	***Med Subway:***	False
Recovered:	.00	***Med Utility:***	False
Med Soil:	True	***Oxygenate:***	
Med Air:	False		
Material Code:	0044A		
Material Name:	battery acid		

Spiller Information

Spiller Name:	
Spiller Company:	NONE
Spiller Address:	
Spiller City:	
Spiller State:	NY
Spiller Zip:	
Spiller Country:	999
Contact Name:	
Contact Phone:	
Contact Ext:	
Latitude:	42.943809993
Longitude:	-78.839240022

Site: ***BUFFALO CITY OF MICHIGAN ST LIFT BRIDGE***
MICHIGAN ST LAT N42 52 20 LONG E78 52 20 BUFFALO NY 14202

RCRA NON GEN

EPA Handler ID:	NYR000018754
Gen Status Universe:	No Report
Contact Name:	DON POLETO
Contact Address:	502, CITY HALL, BUFFALO, NY, 14202, US
Contact Phone No and Ext:	716-851-5359
Contact Email:	
Contact Country:	US
County Name:	ERIE
EPA Region:	02
Land Type:	Municipal
Receive Date:	20070101
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2022, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20070101
Handler Name: BUFFALO CITY OF MICHIGAN ST LIFT BRIDGE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060101
Handler Name: BUFFALO CITY OF MICHIGAN ST LIFT BRIDGE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960118
Handler Name: BUFFALO CITY OF MICHIGAN ST LIFT BRIDGE
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Waste Code Details

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Municipal
Name: CITY OF BUFFALO
Date Became Current:
Date Ended Current:
Phone: 716-851-5359
Source Type: Notification
Street No:
Street 1: 502 CITY HALL
Street 2:
City: BUFFALO
State: NY
Country:
Zip Code: 14202

Owner/Operator Ind: Current Owner
Type: Municipal
Name: CITY OF BUFFALO
Date Became Current:
Date Ended Current:
Phone: 716-851-5359
Source Type: Implementer
Street No:
Street 1: 502 CITY HALL
Street 2:
City: BUFFALO
State: NY
Country: US
Zip Code: 14202

Owner/Operator Ind: Current Operator
Street No:

Type:	Municipal	***Street 1:***	502 CITY HALL
Name:	CITY OF BUFFALO	***Street 2:***	
Date Became Current:		***City:***	BUFFALO
Date Ended Current:		***State:***	NY
Phone:	716-851-5359	***Country:***	US
Source Type:	Implementer	***Zip Code:***	14202

Historical Handler Details

Receive Dt:	19960118
Generator Code Description:	Not a Generator, Verified
Handler Name:	BUFFALO CITY OF MICHIGAN ST LIFT BRIDGE

Receive Dt:	20060101
Generator Code Description:	Not a Generator, Verified
Handler Name:	BUFFALO CITY OF MICHIGAN ST LIFT BRIDGE

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

Formerly Utilized Sites Remedial Action Program: DOE FUSRAP

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

National Priority List: NPL

Sites on the United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. The NPL, which EPA is required to update at least once a year, is based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Nov 3, 2022

National Priority List - Proposed: PROPOSED NPL

Sites proposed by the United States Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Nov 3, 2022

Deleted NPL: DELETED NPL

Sites deleted from the United States Environmental Protection Agency (EPA)'s National Priorities List. The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites are represented by boundaries where available in the EPA Superfund Site Boundaries maintained by the Shared Enterprise Geodata and Services (SEGS). Site boundaries represent the footprint of a whole site, the sum of all of the Operable Units and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Nov 3, 2022

SEMS List 8R Active Site Inventory: SEMS

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the SEMS GIS/REST file layer obtained from EPA's Facility Registry Service.

Government Publication Date: Nov 23, 2022

SEMS List 8R Archive Sites: SEMS ARCHIVE

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file.

Government Publication Date: Nov 23, 2022

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Nov 7, 2022

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites listed as treatment, storage and/or disposal facilities of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Government Publication Date: Nov 7, 2022

RCRA Generator List: RCRA LQG

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Nov 7, 2022

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Nov 7, 2022

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Nov 7, 2022

RCRA Non-Generators: RCRA NON GEN

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Nov 7, 2022

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Nov 7, 2022

Federal Engineering Controls-ECs: FED ENG

This list of Engineering controls (ECs) is provided by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents issued in fiscal years 1982-2020 for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Dec 22, 2022

Federal Institutional Controls- ICs: FED INST

This list of Institutional controls (ICs) is provided by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents issued in fiscal years 1982-2020 for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Dec 22, 2022

Land Use Control Information System: LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Institutional Control Boundaries at NPL sites: NPL IC

Boundaries of Institutional Control areas at sites on the United States Environmental Protection Agency (EPA)'s National Priorities List, or Proposed or Deleted, made available by the EPA's Shared Enterprise Geodata and Services (SEGS). United States Environmental Protection Agency (EPA)'s National Priorities List of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy.

Government Publication Date: Nov 3, 2022

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Nov 6, 2022

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Sep 13, 2022

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

List of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 31, 2021

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

List of petroleum refineries from the U.S. Energy Information Administration (EIA) Refinery Capacity Report. Includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year located in the 50 States, the District of Columbia, Puerto Rico, the Virgin Islands, Guam, and other U.S. possessions. Survey locations adjusted using public data.

Government Publication Date: Aug 30, 2022

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

List of petroleum product and crude oil rail terminals made available by the U.S. Energy Information Administration (EIA). Includes operable bulk petroleum product terminals located in the 50 States and the District of Columbia with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil that were active between 2017 and 2018. Petroleum product terminals comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings. Survey locations adjusted using public data.

Government Publication Date: Jun 29, 2022

LIEN on Property: SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Nov 23, 2022

Superfund Decision Documents: SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Dec 22, 2022

State

Registry of Inactive Hazardous Waste Disposal Sites in New York State: SHWS

State-and tribal- equivalent CERCLIS. State Superfund Program (Inactive Hazardous Waste Disposal Site Remedial Program) (IHWDS) - Oversees the identification, investigation and cleanup of sites where consequential amounts of hazardous waste exist. These sites go through a process of investigation, evaluation, cleanup and monitoring that has several distinct stages. This list is made available by New York State Department of Environmental Conservation's State Superfund Program.

Government Publication Date: Jan 3, 2023

Delisted Registry of Inactive Hazardous Waste Disposal Sites in New York: DELISTED SHWS

This database contains a Registry of Inactive Hazardous Waste Disposal sites which have been removed from New York Department of Environmental Conservation's Environmental Site Remediation database.

Government Publication Date: Jan 3, 2023

Hazardous Substance Waste Disposal Sites: HSWDS

A list of sites included in Hazardous Substance Waste Disposal Site Study reports made available by the New York Department of Environmental Conservation Division of Hazardous Waste Remediation. Provides information regarding the evolving status of hazardous substance waste disposal sites in New York.

Government Publication Date: Oct 24, 2003

Vapor Intrusion Legacy Site List: VAPOR

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion. This list is made available by Department of Environmental Conservation's Vapor Intrusion Legacy Site List. This database is state equivalent CERCLIS.

Government Publication Date: Dec 29, 2022

Solid Waste Facilities and Landfills: SWF/LF

Solid Waste Information Management System (SWIMS) is an inventory containing active and inactive facilities throughout the state. This list is made available by Department of Environmental Conservation's Solid Waste Information Management System (SWIMS).

Government Publication Date: Dec 22, 2021

Inactive Landfill Facilities: LANDFILL INACTIVE

List of inactive landfills in the State of New York. This data is made available by the New York State Department of Environmental Conservation (DEC). DEC notes that these are preliminary data and should not be regarded as a complete inventory of all landfills in the State, and also that site locations and attributes are preliminary and should not be relied upon without independent verification.

Government Publication Date: Sep 21, 2022

Waste Tire Facilities: WASTE TIRE

This list of active Waste Tire Facilities is maintained by the New York State Department of Environmental Conservation. Waste tire storage facilities (WTSF) store waste tires or portions of waste tires. Most of these facilities require Part 360 permits, but under certain conditions a registration maybe available.

Government Publication Date: Apr 7, 2022

Recycling Facilities: RECYCLING

The Department of Environmental Conservation (DEC), Division of Materials Management (DMM), Bureau of Permitting and Planning regulates solid waste management facilities in accordance with 6 NYCRR Part 360. Information pertaining to those facilities is maintained with the Division's Solid Waste Information Management System (SWIMS) database. The Facility List is a dataset related to solid waste management facilities operating in the state, and includes such information as facility location, contact names and associated information, waste types managed, and regulatory information.

Government Publication Date: Apr 7, 2022

Leaking Storage Tanks: LST

This database contains records of chemical and petroleum spill incidents. They include leaking aboveground storage tanks or leaking underground storage tanks, with incidents of tank test failures, tank failures and tank overfill. This list is made available by New York State Department of Environmental Conservation's Spill Response Program.

Government Publication Date: Jan 6, 2023

Delisted Leaking Storage Tanks: DELISTED LST

List of Leaking Storage Tank sites which has been removed from New York Department of Environmental Conservation's Spill Response Program

Government Publication Date: Jan 6, 2023

Underground Storage Tanks- UST-Petroleum Bulk Storage (PBS): UST

Facilities within the Petroleum Bulk Storage (PBS) that have underground storage tanks. Underground petroleum storage facilities with a combined storage capacity over eleven hundred (1,100) gallons. This list is made available by NewYork Department of Environmental Conservation's Environmental Site Database Search.

Government Publication Date: Nov 21, 2022

The Bulk Storage Program Database - AST: AST

Facilities within the Petroleum Bulk Storage (PBS) that have aboveground storage tanks. Aboveground petroleum storage facilities with a combined storage capacity over eleven hundred (1,100) gallons. This list is made available by New York State Department of Environmental conservation's Petroleum Bulk Storage (PBS) program.

Government Publication Date: Nov 21, 2022

Petroleum Bulk Storage: TANKS

The Bulk Storage Program Database maintains the registrations of active and inactive bulk storage sites statewide. This database includes Petroleum Bulk Storage (PBS) tanks where no information is available on whether they are ASTs or USTs. This list is made available by Department of Environmental Conservation's Petroleum Bulk Storage (PBS) program.

Government Publication Date: Nov 21, 2022

Major Oil Storage Facilities (MOSF): MOSF

In 1977, the New York State Legislature passed the "Oil Spill Prevention, Control and Compensation Act" (Article 12 of the Navigation Law). This law regulates all oil terminals and transport vessels operating in the waters of the State which have a storage capacity of 400,000 gallons or more. (Terminals and vessels with a capacity of 400,000 gallons or more are commonly referred to as major oil storage facilities or MOSFs). This list is made available by Department of Environmental Conservation's Major Oil Storage Facility (MOSF) Program.

Government Publication Date: Nov 21, 2022

Chemical Bulk Storage (CBS): CBS

Facilities that store regulated hazardous substances in underground tanks . "Hazardous substance" means any substance listed as hazardous or acutely hazardous in 6 NYCRR Part 597 or a mixture thereof. This list is made available by Department of Environmental Conservation's Chemical Bulk Storage (CBS) Program.

Government Publication Date: Nov 21, 2022

Delisted Storage Tanks: DELISTED TANKS

List of Storage Tank sites which has been removed from New York Department of Environmental Conservation's Environmental Site Database.

Government Publication Date: Nov 21, 2022

Delisted County Records: DELISTED COUNTY

Records removed from county databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: Dec 5, 2022

Registry of Engineering Controls in New York State: ENG

Registry of Engineering Controls in New York State taken from the Environmental Site Remediation Database.

Government Publication Date: Jan 3, 2023

Registry of Institutional Controls in New York State: INST

Registry of Institutional Controls in New York State taken from the Environmental Site Remediation Database.

Government Publication Date: Jan 3, 2023

Voluntary Cleanup Agreements: VCP

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites. This list is made available by Department of Environmental Conservation's Voluntary Cleanup Program.

Government Publication Date: Jan 3, 2023

Environmental Restoration Program Listing: ERP

Environmental Restoration Program - Provides municipalities with financial assistance for site investigation and remediation at eligible brownfield sites. In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (Bond Act). Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. This list is made available by Department of Environmental Conservation's Environmental Restoration Program.

Government Publication Date: Jan 3, 2023

Brownfields Site List (Subset of Site Remediation): BROWNFIELDS

Brownfield Cleanup Program was developed to enhance private-sector cleanups of brownfields and to reduce development pressure on "Greenfields". A Brownfield site is real property, the redevelopment or reuse of which may be complicated by the presence or potential presence of a contaminant. Contaminants include hazardous waste and/or petroleum. This list is made available by Department of Environmental Conservation's Brownfield Cleanup Program.
Government Publication Date: Jan 3, 2023

Tribal

Leaking Underground Storage Tanks (LUSTs) on Tribal/Indian Lands: INDIAN LUST
This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 2, which includes New York, is made available by the United States Environmental Protection Agency (EPA).
Government Publication Date: Jan 28, 2016

Underground Storage Tanks (USTs) on Indian Lands: INDIAN UST
This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 2, which includes New York, is made available by the United States Environmental Protection Agency (EPA).
Government Publication Date: Apr 04, 2016

Delisted Tribal Leaking Storage Tanks: DELISTED INDIAN LST
Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).
Government Publication Date: Nov 23, 2022

Delisted Tribal Underground Storage Tanks: DELISTED INDIAN UST
Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).
Government Publication Date: Nov 23, 2022

County

No County databases were selected to be included in the search.

Additional Environmental Record Sources

Federal

Facility Registry Service/Facility Index: FINDS/FRS
The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the Environmental Protection Agency (US EPA).
Government Publication Date: Nov 2, 2020

Toxics Release Inventory (TRI) Program: TRIS
The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U. S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment.
Government Publication Date: Aug 24, 2021

Perfluorinated Alkyl Substances (PFAS) Releases: PFAS TRI
List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment.
Government Publication Date: Aug 24, 2021

Federal Agency Locations with Known or Suspected PFAS Detections: PFAS FED SITES

List of Federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS), made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data. EPA outlines that these data are gathered from several federal entities, such as the Federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration, Department of Transportation, and Department of Energy. Sites on this list do not necessarily reflect the source/s of contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: Jun 30, 2022

PFOA/PFOS Contaminated Sites: PFAS NPL

List of National Priorities List (NPL) and related Superfund Alternative Agreement (SAA) sites where PFOA or PFOS contaminants have been found in water and/or soil. The site listing is provided by the Federal Environmental Protection Agency (EPA).

Government Publication Date: Oct 4, 2022

Perfluorinated Alkyl Substances (PFAS) Water Quality: PFAS WATER

The Water Quality Portal (WQP) is a cooperative service sponsored by the United States Geological Survey (USGS), the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC). This listing includes records from the Water Quality Portal where the characteristic (environmental measurement) is in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances.

Government Publication Date: Jul 20, 2020

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents, and this is cited in the tracker. Disclaimer: The source conveys this database undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Limited location details are available with this data. Access the following for the most current informations https://pfasproject.com/pfas-contamination-site-tr acker/

Government Publication Date: Dec 12, 2019

National Response Center PFAS Spills: ERNS PFAS

National Response Center (NRC) calls from 1990 to the most recent complete calendar year where there is indication of Aqueous Film Forming Foam (AFFF) usage. NRC calls may reference AFFF usage in the "Material Involved" or "Incident Description" fields. Data made available by the US Environmental Protection Agency (EPA). Disclaimer: dataset may include initial or misidentified incident data not yet validated or investigated by a federal/state response agency.

Government Publication Date: Feb 23, 2022

Hazardous Materials Information Reporting System: HMIRS

US DOT - Department of Transportation Pipeline and Hazardous Materials Safety Administration (PHMSA) Incidents Reports Database taken from Hazmat Intelligence Portal, U.S. Department of Transportation.

Government Publication Date: Sep 1, 2020

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Aug 30, 2022

Toxic Substances Control Act: TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI).
Government Publication Date: Apr 11, 2019

Hist TSCA: HIST TSCA
The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.
Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN
An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.
Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP
An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.
Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP
Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).
Government Publication Date: Nov 23, 2022

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER
The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.
Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS
The U.S. Environmental Protection Agency's Enforcement and Compliance History Online system incorporates data from the Integrated Compliance Information System - National Pollutant Discharge Elimination System (ICIS-NPDES). ICIS-NPDES is an information management system maintained by the Office of Compliance to track permit compliance and enforcement status of facilities regulated by the NPDES under the Clean Water Act. This data includes permit, inspection, violation and enforcement action information for applicable ICIS records.
Government Publication Date: Oct 15, 2022

Drycleaner Facilities: FED DRYCLEANERS
A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) online search. The Environmental Protection Agency (EPA) tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.
Government Publication Date: Jun 25, 2022

Delisted Drycleaner Facilities: DELISTED FED DRY
List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).
Government Publication Date: Jun 25, 2022

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset.

Government Publication Date: Jul 12, 2022

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

A list of flagged pipeline incidents made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types.

Government Publication Date: Mar 31, 2021

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United State Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Aug 3, 2022

Surface Mining Control and Reclamation Act Sites: SMCRA

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by the Office of Surface Mining Reclamation and Enforcement (OSMRE) to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of Abandoned Mine Land (AML) impacts, as well as information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Government Publication Date: Aug 18, 2022

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites: LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Tile II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Dec 1, 2022

Alternative Fueling Stations: ALT FUELS

This list of alternative fueling stations is sourced from the Alternative Fuels Data Center (AFDC). The U.S. Department of Energy's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG) fuel type locations.

Government Publication Date: Jan 3, 2023

Superfunds Consent Decrees: CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS) since 2010. CMS may not reflect the latest developments in a case nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Jan 11, 2023

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

List of active EPA-registered foreign and domestic pesticide-producing and device-producing establishments based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that facilities producing pesticides, active ingredients, or devices be registered. The list of establishments is made available by the EPA.

Government Publication Date: Mar 30, 2022

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: Nov 3, 2022

State

Underground Injection Control Wells: UIC

A well permit is required from the Division of Mineral Resources for any brine disposal well deeper than 500 feet. This includes any operation to drill, deepen, plug back or convert a well. Regardless of well depth, the NYSDEC Division of Water must be contacted for a determination of whether a SPDES permit is necessary to operate any brine disposal well.

Government Publication Date: Aug 6, 2018

Manufactured Gas Plants: MGP

A list of former Manufactured Gas Plants (MGP) made available by the New York Department of Environmental Conservation (NYSDEC). From the late 1800's to the mid 1900's, hundreds of manufactured gas plants across New York State supplied homes and industry with fuel. Former MGP structures such as gas holders, tar separators, wells, and tanks were often susceptible to spills and leaks. As a result, these structures were a significant source of contamination from the release of tar and other toxic by-products.

Government Publication Date: Jan 9, 2023

Spill Incidents Database: NY SPILLS

Spill Incidents Database has records dating back to 1978. This database contains records of chemical and petroleum spill incidents. The DEC Spill Response program receives and compiles reports of hazardous material spills occurring anywhere in New York State. These reports are submitted through the Spill Hotline and other mechanisms, and entered by DEC spill response staff into the state's official data base of Spill Incidents Reports. This list is made available by New York State Department of Environmental Conservation's Spill Response Program.

Government Publication Date: Jan 6, 2023

PFAS Remedial Sites: PFAS CONTAM

List of sites being addressed under one of the New York Department of Environmental Conservation (DEC) Division of Environmental Remediation (DER)'s remedial programs, where the waste or contaminant of concern is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances.

Government Publication Date: Jan 3, 2023

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

A list of sites surveyed by the New York Department of Environmental Conservation to determine locations that manufacture, use, store, or release into the environment materials containing Per- and Polyfluoroalkyl Substances (PFAS). Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Some PFAS are difficult to break down and persist in the environment that may cause harm to the public. This list is made available by the Department of Environmental Conservation of New York State.

Government Publication Date: Jan 16, 2019

Landfill Investigations PFAS Sampling Results: PFAS LANDFILL

A list of inactive landfill sites that have been investigated for Per- and Polyfluoroalkyl Substances (PFAS) in the state of New York made available by the New York State Department of Environmental Conservation.

Government Publication Date: Jun 30, 2020

Registed Dry Cleaner Facilities: DRYCLEANERS

The Division of Air Resources of the Department of Environmental Conservation (DEC) tracks all registered dry cleaner facilities.

Government Publication Date: Feb 8, 2023

Delisted Dry Cleaner Facilities: DELISTED DRYCLEANERS

Sites removed from the list of dry cleaner facilities registered with the Department of Environmental Conservation (DEC)'s Division of Air Resources.

Government Publication Date: Feb 8, 2023

Hazardous Waste Manifest - Facilities: NY MANIFEST

List of facilities located in New York that are included in the Hazardous Waste Manifest Data Downloads Location Address data file made available by the New York Department of Environmental Conservation (DEC), with which no manifests are associated. The Hazardous Waste Manifest Data made available by the NY DEC is compiled from hazardous waste manifest shipments to, from, or within New York State. The Bureau of Program Management, in the Division of Environmental Remediation, is responsible for maintaining hazardous waste manifest records.

Government Publication Date: Dec 15, 2022

Receivers from Hazardous Waste Manifests: REC MANIFEST

List of receiver facilities located in New York that are included in the Hazardous Waste Manifest Data Downloads Location Address data file made available by the New York Department of Environmental Conservation (DEC), which are identified as a receiver in associated manifests. The Hazardous Waste Manifest Data made available by the NY DEC is compiled from hazardous waste manifest shipments to, from, or within New York State. The Bureau of Program Management, in the Division of Environmental Remediation, is responsible for maintaining hazardous waste manifest records. Hazardous Waste Code Descriptions are from NY Part 371.4 (6 CRR-NY 371.4) Identification and Listings of Hazardous Waste, unless otherwise noted.

Government Publication Date: Dec 15, 2022

Generators from Hazardous Waste Manifests: GEN MANIFEST

List of generator facilities located in New York that are included in the Hazardous Waste Manifest Data Downloads Location Address data file made available by the New York Department of Environmental Conservation (DEC), which are identified as a generator in associated manifests. The Hazardous Waste Manifest Data made available by the NY DEC is compiled from hazardous waste manifest shipments to, from, or within New York State. The Bureau of Program Management, in the Division of Environmental Remediation, is responsible for maintaining hazardous waste manifest records. Hazardous Waste Code Descriptions are from NY Part 371.4 (6 CRR-NY 371.4) Identification and Listings of Hazardous Waste, unless otherwise noted.

Government Publication Date: Dec 15, 2022

New York City E-Designated Sites: E DESIGNATION

A list of sites with an (E) Designation, described as a New York City (NYC) zoning map designation that indicates the presence of an environmental requirement pertaining to potential hazardous materials contamination, window/wall noise attenuation, or air quality impacts on a particular tax lot. The NYC Office of Environmental Remediation administers the E-Designation Environmental Review Program to avoid significant adverse impacts to human health or the environment through exposure to these hazards. The data is provided by the NYC Department of City Planning (DCP).

Government Publication Date: Jul 1, 2022

Registered Cooling Towers: COOLING TOWERS

Locations of cooling towers registered with New York State, made available by the Center for Environmental Health. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State. These data are self-reported by owners and/or property managers of cooling towers in service in New York State.

Government Publication Date: Aug 2, 2022

Tier 2 Report: TIER 2

A list of Tier 2 facilities in the state of New York. This is a list of facilities which have reported hazardous substances provided by Homeland Security and Emergency Services.

Government Publication Date: Sep 28, 2022

NY DEC Projects of Interest: PROJECTS

A list of permits for notable projects - permit applications that have received a lot of public attention - made available by the New York Department of Environmental Conservation (DEC).

Government Publication Date: Nov 26, 2021

Air Permitted Facilities: AIR PERMITS

This list of issued state facility air permits is maintained by the New York State Department of Environmental Conservation (NYDEC). The listing includes Air State Facility Permits (ASF) and Air Title V Facility Permits (ATV). ASF permits may be required by medium-sized commercial or industrial facilities or larger facilities that have agreed to limit emissions. ATV permits may be required at the largest facilities statewide, or at facilities located in those areas where state implementation plans are in place to improve air quality. Please note: An Issued permit is valid for a stated period of time. Modifications may be made to an issued permit for the remainder of the active permit.

Government Publication Date: Dec 30, 2022

Liens Listing: LIEN

New York Environmental Protection and Spill Compensation Fund (Oil Spill Fund) places liens on properties that are sites of oil spills when the owners are responsible parties and fail to pay for cleanup. The Office of the State Comptroller provides this listing of liens information from the Oil Spill Fund.

Government Publication Date: Oct 5, 2021

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

LaBella
Powered by partnership.

Qualifications

CHRISTOPHER FINN

Environmental Analyst

Chris is an Environmental Analyst working with the Due Diligence Program of LaBella's Environmental Division. Chris is responsible for preparing Phase I Environmental Site Assessments (ESAs), Transaction Screen ESAs, and other due diligence reports.

EDUCATION

University at Buffalo:
Environmental Geosciences, BS

Erie Community College:
Construction Management Engineering Technology, AAS

Chris has completed numerous Environmental Site Assessments. Site assessments include evaluation of environmental liability associated with properties such as industrial facilities, commercial properties, gasoline stations, automotive/ collision repair, warehouses, and residential homes. Chris provides efficient analysis and has completed environmental assessments for the following groups:

Financial Institutions

- Alden State Bank
- Bank on Buffalo
- The Community Preservation Corporation
- Citizens Bank
- Cattaraugus County Bank
- Community Bank
- Evans Bank
- First National Bank of Pennsylvania
- Five Star bank
- Key Bank
- Lake Shore Savings Bank
- M&T Bank
- Northwest Bank
- TowneBank
- United Midwest Savings Bank

Municipal & Government Clients

- Belmont Housing Resources for WNY Inc.
- CDS Housing LLC
- Chautauqua County Land Bank
- Hamburg Redevelopment Corporation
- Niagara County Department of Economic Development
- Home Leasing

Developers, Schools, Construction Companies, etc.

- BQ Energy Development LLC
- Canisius College
- Covanta Energy Solutions
- DePaul Properties Inc
- Passero Associates
- Intersection Realty Group
- WF Acquisitions
- Worksport Limited

LaBella
Powered by partnership.

Phase I ESAs

Phase I ESA at 55 Main Street Lockport, NY for Niagara County Department of Economic Development

To determine environmental conditions at the site Chris completed a Phase I ESA on a former hydroelectric power plant and transformer house. Historical records indicated the site was formerly occupied by blacksmithing shops, a furnishing company, Niagara Gazette, and a dry cleaning facility. Chris was the Environmental Analyst assisting the client in assessing the environmental risk associated with the site and LaBella recommended a subsurface investigation be completed at the site.

Elk Street Buffalo, NY for BQ Energy Development LLC

As part of a future solar development project, Chris conducted a Phase I Investigation on an NYSDEC Brownfield site. The site was formerly utilized as an oil refinery and petroleum bulk storage terminal circa 1880 through the 2000s. Chris reviewed previous subsurface investigation reports, Site Management Plan, and a completion report as part of the project.

Phase I ESA at 33 Scott Street Hamburg, NY for Hamburg Redevelopment Corporation

As part of future purchase, acting as the Environmental Analyst, Chris helped evaluate the environmental conditions at the site by completing a Phase I ESA. Historical records indicated the site was formerly used as a foundry and upholstery spring manufacturer and an electroplating facility for over 100 years. Chris reviewed a previous Phase II investigation and NYSDEC spill records for adjacent properties. LaBella recommended a subsurface be completed at the site.

Phase I ESA at 70-78 & 80-88 Boices Lane Kingston, NY for M&T Bank

Completion of a Phase I ESA for two parcels on a large NYSDEC brownfield site. Historical records indicated the site was part of a former IBM manufacturing facility. Chris reviewed the remedial investigation, groundwater monitoring, emergent contaminant, and record of decision reports as part of the Phase I ESA. Based on the results of the previous investigations no additional investigation was warranted at the time.

Phase II ESAs & Additional Reports

33 Scott Street Hamburg, NY Phase II for Hamburg Redevelopment Corporation

A site-wide investigation was completed at the property to assess subsurface soil and groundwater conditions prior to the acquisition of the property. Chris assisted with the screening of soil borings using olfactory methods and a PID and, with the sampling of groundwater monitoring wells.

Commercial Plaza on Buffalo Road Orchard Park, NY Phase II for Evans Bank

A subsurface investigation and vapor intrusion assessment of a commercial plaza that historically contained dry cleaning operations. Included the collection of soil and groundwater samples, and of sub-slab vapor and indoor air samples. Based on laboratory sampling results LaBella recommended the installation of mitigation system.

Environmental Management Plan for DePaul Properties Inc.

As part of an affordable housing development project, Chris was responsible for the development of the Environmental Management Plan to ensure proper handling of NYSDEC-regulated materials including cinders and ash during intrusive site development activities.

Landfills

Allegany County: Allegany County Landfill Environmental Monitoring - Allegany, NY

Responsible for groundwater, storm water, sediment, and leachate sampling; and gas vent monitoring on a quarterly basis.

Ischua Landfill: Water Quality Monitoring Program - City of Olean, NY

Assisted with the semi-annual water quality monitoring of the Ischua Landfill. The semi-annual monitoring includes the collection of groundwater and surface water samples

Unity Island Landfill: Water Quality Monitoring Program – City of Buffalo, NY

Assisted with the water quality monitoring of the Unity Island Landfill. The bi-annual monitoring includes the collection of groundwater and surface water samples and gas vent monitoring.

JACQUELYN BRAYER

Phase I Technical Reviewer

Jackie is a technical reviewer for LaBella's Phase I Environmental Due Diligence department and is involved with the overall quality assurance/quality control of Phase I Environment Site Assessments (ESAs), Transactions Screens, and Records Search with Risk Assessment (RSRA) due diligence reports. Her duties include conducting senior reviews of due diligence reports and assisting the Phase I Program Manager with the oversight, training, and professional development of analysts. With over 11 years of experience in Environmental Due Diligence, Jackie has been involved with several thousands due diligence projects on commercial, residential, and industrial properties completed for commercial lenders, developers, private entities/individuals, attorneys, and municipalities. Jackie's experience also includes conducting technical reviews of other consultant's Transaction Screen and Phase I ESA reports and former management/oversight of a previous Environmental Due Diligence Department consisting of 5-10 technical writers/analysts.

EDUCATION

SUNY Fredonia: B.S. in Environmental Science, Minor in Geology

CERTIFICATIONS

Environmental Professional

Stone Quarries/Asphalt Plants Portfolios: Transaction Screens and Phase I ESAs—NY, PA

Oversight and completion of multiple project portfolios for various large-scale stone and asphalt companies. These portfolios included extensive site visits of the facilities which consisted of several hundred acres of land, numerous production/plant buildings, various bulk ASTs/silos, and truck service/fueling operations. Extensive review of historical and regulatory records and previous investigation reports was also completed to identify environmental concerns and evaluate environmental risks, providing the clients with thorough findings and recommendations relative each project.

Formerly Used Defense Sites: Phase I ESAs—NY, MD

Completed numerous Phase I ESA reports on formerly used defense sites which were undergoing remediation activities or had remedial activities completed under the direction and supervision of the USEPA, US Army Corps of Engineers, NYSDEC, MDE, and various other state and federal agencies. These projects were assessed through extensive review of numerous historical records and regulatory records, including various state and federal-completed site investigation and remedial action reports.

Gasoline Station and Automobile Dealership Portfolios: Transaction Screens and Phase I ESAs—Northeastern US

Oversight and completion of multiple project portfolios for various petroleum companies and automobile dealerships.

LaBella
Powered by partnership.

These portfolios included extensive review of various fuel storage tank inventory, registration, testing, and closure reports and review of subsurface investigation/remedial reports, including former aboveground and underground storage tanks, fueling systems, in-ground vehicle lifts, and oil-water separators.

Environmental Due Diligence Reports—Various Locations

In addition, Jackie has also completed several thousand due diligence reports on various properties including automobile repair facilities, apartment buildings/complexes, assisted living facilities, hotels, office complexes, commercial shopping plazas, dry cleaners, educational facilities/campuses, landfills, several hundred-acre vacant land properties, petroleum bulk storage terminals, warehouses, and various large-scale industrial facilities in over 20 states across the U.S.