

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Materials Management

625 Broadway, Albany, New York 12233-7250

P: (518) 402-8651 | F: (518) 402-9024

www.dec.ny.gov

December 31, 2019

Mr. Stephen Fleming, P.E.
Senior Remediation Manager
Safety-Kleen Systems, Inc.
2858 U.S. Route 322
Logan Township, NJ 08085

RE: Safety-Kleen Amityville

Dear Mr. Fleming:

The New York State Department of Environmental Conservation (the "Department") has reviewed Safety-Kleen's "Groundwater Monitoring Program Report". The report provides the results of the September 2019 groundwater sampling event and provides an evaluation of long-term groundwater trends at the Amityville facility.

Upon review, the Department has the following comments:

Groundwater conditions continue to improve in response to remedial efforts. Mineral Spirits Range Organics (MSRO) have not been detected in site groundwater in the past year and have exhibited a declining trend subsequent to the subsurface injection program conducted in the fall in 2014.

Upon review of historical facility groundwater data, the Department has determined that an addition two (2) rounds of semi-annual sampling will be necessary to confirm that site groundwater has achieved the remedial goals required for a determination of "no further action".

If you have any questions on this matter, please contact me at (518) 402-9813.

Sincerely,



Kent D. Johnson, P.G.
Professional Geologist 1
Division of Materials Management



Department of
Environmental
Conservation

ec: A. Everett, USEPA, Region 2
S. Rahman, Region 1
L. Winterberger