Amphenol

Amphenol Corporation

Aerospace Operations 40-60 Delaware Avenue Sidney, NY 13838-1395 Telephone (607) 563-5940


September 7, 2007

Ms. Young S. Chang – Remedial Project Manager Central New York Remediation Section New York Remediation Branch Emergency and Remedial Response Branch U.S. Environmental Protection Agency (USEPA), Region II 290 Broadway, 20th Floor New York, NY 10007-1866

RE: Richardson Hill Road Landfill (RHRL)
Final Interim Remedial Action Report for Remedial Action Work Element I Remedial Excavation and Capping

Dear Ms. Chang:

Pursuant to Section XI.C. of the Statement of Work, please find attached three paper copies and two cd copies of the report entitled "Final Interim Remedial Action Report for Remedial Work Element I – Remedial Excavation and Capping, Richardson Hill Road Landfill Site." Also attached are copies of the associated record drawings for Remedial Work Element I. The construction of Remedial Work Element II (Groundwater Collection and Treatment) is presented in a separate Interim Remedial Action Report.



cc: G. Burke, NYS DEC (w/ 1 paper copy and 1 cd copy)

- A. Belensz, NYS OAG (w/ 1 paper copy)
- J. Damrath, NYC DEP (w/ 1 paper copy)
- J. Kaczor, Earthtech (w/ 1 cd copy)
- J. Bianchi, Amphenol (w/ 2 paper and 2 cd copies)
- S. Waldo, Amphenol (w/ 1 paper and 1 cd copy)
- R. Galloway, Honeywell (w/ 1 paper and 1 cd copy)
- J. Mojka, Honeywell (w/ 1 paper and 1 cd copy)
- J. Mickam, JTM Associates (w/ 1 paper and 1 cd copy)
- J. O'Loughlin, Parsons (w/ 1 paper and 1 cd copy)
- R. D'Hollander, Parsons (w 1 paper and 1 cd copy)