


Table of Contents

1.0	Introduction	4
1.1	Purpose	4
1.2	Background	4
2.0	Corrective Measures Addressing Contaminated Soils	5
2.1	PCB Soils	5
	1.1 Remedial Criteria	5
	1.2 Disposal Criteria	5
	1.3 Excavation Procedures	5
	1.4 Verification Procedures	7
	1.5 Stockpile Procedures	8
	1.6 Stockpile Characterization Procedures	8
	1.7 Disposal Procedures	8
	1.8 Equipment Decontamination	8
	1.9 Institutional Controls	8
	1.10 Post-Remediation Requirements	9
	Phenol Recovery Area (PRA) Soil	9
	2.1 Remedial Criteria	9
	2.2 Disposal Criteria	9
	2.3 Excavation Procedures 2.4 Verification Procedures	9
		10
	2.5 Stockpile Procedures2.6 Stockpile Characterization Procedures	10
	2.7 Disposal Procedures	10
	2.8 Equipment Decontamination	10 10
	2.9 Institutional Controls	10
	2.10 Post-Remediation Requirements	11
3.0	Corrective Measures Addressing Contaminated Sewers	12
3.		12
3.		12
3.		12
3.		13
3.		14
3.		14
3.		14
3.		14
3.		15
3.	10 Post-Remediation Requirements	15
1.0	Corrective Measures Addressing Contaminated Groundwater	16
4.1	Conceptual Design	16
4.2	Pilot Air Sparging Test	16
	2.1 Pilot Test Design	16
	2.2 Short-term Pilot Test	17
	2.3 Long-term Pilot Test	18
4.3	Continued Operation of IRM Pump-and-Treat	18
4.4	Submission of Full-Scale Design	18
	Start-up Monitoring Plan	19
5.1	Pre-pilot test monitoring	19
5.2	Short-term Pilot Test Monitoring	19
5.3	Long-term Pilot Test Monitoring	19
5.4	Phenol Recovery Area Groundwater Monitoring	19
	Schedule VI Control of the Pilot of the Pilo	20
	Health and Safety Plan	21
3.0	References	22



	orden Resin Facility - Bainbrid	ge, Ne	w York	<												
Figure 18																
Implement	tation Schedule															
Section	Task Secure soil/sediment disposal facilities	Apr-99	May-99	Jun-99	Jul-99	Aug-99	<u>Sep-99</u>	Oct-99	Nov-99	<u>Dec-99</u>	<u>Jan-00</u>	Feb-00	Mar-00	<u>Apr-00</u>	May-00	Jun-00
	Groundwater Corrective Measures															
5.1	Pre-pilot monitoring									3 1						
4.2.2	Short-term pilot test														A SECTION OF	
4.2.3	Long-term pilot test															
5.3, 5.4	Groundwater monitoring			X			X			X			X			
4.4	Full-scale design															X
	Sewer Corrective Measures			D COLORED												
3.0	Trace and map sewers, Install temporary manholes															
3.1.3, 3.1.4	Clean sewers, scope, video															
3.1.7	Dispose of solids							Mark.								
3.1.7	Treat and dispose of liquids															
3.1.9	Final equipment decontamination							X								
3.1.10	Remove sewer segment,															
	close manholes															
2.1.3, 2.2.3	Soil Corrective Measures Excavation preparations/de-watering				Dec.											
2.1.3, 2.2.3	Soil excavation															
2.1.4, 2.2.4	Verification sampling															
2.1.7, 2.2.7	Soil disposal															
2.1.10, 2.2.10	Final decon/regrade/backfill															





LAW PROJEC	T NO: 50700.8.0985	File Location: G:\Projects\Cincinnati\Cherokee\Boinbridge\rem desg figs					
Date: 2/1/99	Source: T.M. Gates, Inc.	PCB Area Water Treatment System					
Figu	re B1	Former Borden Resin Facility - Bainbridge, New York					



LAWGIBB Group Member

801 Washington Avenue, Sts. 330 (606) 581-6031 Newport, Kentucky 41071 FAX (806) 581-8036

DISPOSAL

Depending upon what materials are adsorbed on the carbon, the storage, transportation and disposal of the spent carbon may be subject to federal, state and local regulations as a hazardous material.

TRANSPORTING ADSORBER MATERIALS

DISPOSORB adsorber units may be easily moved by sling or forklift.

Shipping weight for the 350 gallon DISPOSORB units containing granular activated carbon is approximately 2500 pounds. Spent units can be expected to weigh about 2500 pounds after water is drained via siphon on the effluent line or 1 psi air pressure connected to the influent line.

For 350 gallon DISPOSORB units which contain Klensorb 100, shipping

weight is approximately 2800 pounds.

Shipping weight for the 55 gallon DISPOSORB units containing granular activated carbon is approximately 350 pounds. Spent units can be expected to weigh approximately 350 pounds after water drain.

For 55 gallon DISPOSORB units which contain Klensorb 100, shipping weight is approximately 400 pounds.

PRECAUTIONS

Wet activated carbon preferentially removes oxygen from air. In closed or partially closed containers and vessels, oxygen depletion may reach hazardous levels. If workers are to enter a vessel containing carbon, appropriate sampling and work procedures for potentially low-oxygen spaces should be followed, including all applicable federal and state requirements.

WARRANTY

There are no warranties either expressed or implied or any warranty of merchantability or fitness for a particular purpose associated with the sale of this product.

For information regarding incidents involving human and environmental exposure, call (412) 787-6700 and usk for the Regulatory and Trade Affairs Department.

For further information, phone (412) 787-6700, or contact: Calgon Carbon Corporation, P.O. Box 717, Pittsburgh, PA 15230-0717

