



Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 98.10.01

Site Name: Leica, Inc.		Class: 4	Number: 915156
O&M Funding Source: <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
O&M Information:		O&M Start: Feb. 2000	End: Annual Cost: \$unknown <input type="checkbox"/> Estimated
Interim Remedial Measures/Operable Units In O&M Phase:			
<input type="checkbox"/> Drum Removal <input type="checkbox"/> Soil Removal <input type="checkbox"/> Tank Removal <input type="checkbox"/> Cap/Cover <input type="checkbox"/> Containment Structure <input type="checkbox"/> Fence/Security <input checked="" type="checkbox"/> Groundwater Recovery/Treatment <input type="checkbox"/> Leachate Collection/Treatment <input checked="" type="checkbox"/> Vapor Extraction/Treatment <input checked="" type="checkbox"/> Air Sparging/Stripper System <input type="checkbox"/> Treatment/Filtration Plant/System <input type="checkbox"/> Potable Water Supply/System <input type="checkbox"/> Other:			
Institutional Controls: <input checked="" type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input checked="" type="checkbox"/> Other: Sewer discharge permit			
O&M Review Information:			
Reports: <u>O&amp;M plan &amp; Final Remediation Summary Report approved August 9, 2001. Rec'd August 2002 Supplemental Soil Removal Action WP for review.</u>			
Inspection: <u>Inspection performed 08/29/02. SVE/Air sparging system operating satisfactory. High groundwater levels within system area still causing problems with system. Has been ok due to dry summer. Scientech proposing complete excavation and off-site disposal of all remaining soils to address problem.</u>			
<u>Groundwater extraction system appears to running with little problem. Deep wells showing GW depression within well design influence.</u>			
<u>Data submission to DEC acceptable and on-time</u>			
<u>DEC approved (July 30, 2002) discontinuation of treatment in areas A &amp; B because sampling showed RAOs met</u>			
Sampling: <u>NYSDEC did not collect samples at time of inspection.</u>			
Other:			
Conclusions:			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: explain: _____			
ROD Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: explain: _____			
Consent Order Compliance? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: explain: _____			
Other:			
Recommendations: <u>Continue review of August 2002 proposal to complete overburden soil remediation through excavation.</u>			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above) Reclassify the Site? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes → Class:			
Comments: <u>No other comments applicable.</u>			
Project Manager:		Reviewer:	
 Signature August 30, 2002 Date Gregory Sutton, P.E. Region 9 (716)851-7220 Name Region or Bureau Telephone		 Signature 9/3/02 Date Martin Doster, P.E. Region 9 (716)851-7220 Name Region or Bureau Telephone	

