

NYSDEC SPILL REPORT FORM



DEC REGION:	ON : 9			SPILL NUMBER:		080347	0803478	
SPILL NAME:	L NAME: NIAGARA FALLS ARMY RESERVE				DEC LEAD:		nd	_
CALLER NAME: INGRID WEGAND				NOTIFIER'S NAME:		INGRID \	INGRID WEGAND	
CLR'S AGENCY: US ARMY RESERVE				NOTIFIER'S AGENCY:		Y: US ARM	US ARMY RESERVE	
CALLER'S PHONE: (347) 219-9834					R'S PHONE	: (347) 219	(347) 219-9834	
SPILL DATE:		06/24/2008	_ SPILL TI	ME:	9:00 am		DISPATCHER:	
CALL RECEIV	06/24/2008	_ RECEIVI	ED TIME:	10:10 am			_	
SPILL LOCATION								
PLACE:	NIAGARA FALLS ARMY RESERVE			COUNTY:		Niagara	Niagara	
STREET:	STREET: 9400 PORTER ROAD			TOWN/CITY:			Niagara Falls (c)	
				COMMUNITY:		NIAGAR	A FALLS	_
CONTACT:	: INGRID WEGAND				CONTACT PHONE:		(347) 219-9834	
CONT. FACTOR: Other SPILL REPORTED BY: Federal Government								
FACILITY TY	tional, Educational, G	ational, Gov., Othe WATERBODY :						
CALLER REMARKS: ABOUT 10 YEARS AGO WERE TRANSFORMERS ON SITE AND WAS ALL CLEANED UP: THINK IT MAY BE COMING UP FROM FORMER SPILL AND FOUND DURING OUTFALL INSPECTIONS FOUND A BLOCKED PIPE AND A UNDOING IT A SMALL POOL WAS REALEASED AND MAYBE THE PIPE WAS HOLDING OIL AND THEY WILL CAP IT SO NOTHING ELES CAN BE RELEASED> AND CREW ON SITE								
MATERIAL PCB OIL		CLASS Petrolet		SPILLED 0.00 G		COVERED 00 G	RESOURCES AFFECTE Soil,	Ē

POTENTIAL SPILLERS

COMPANY ADDRESS CONTACT

US ARMY RESERVE 9400 PORTER ROAD NIAGARA FALLS NY INGRID WEGAND

(347) 219-9834

Tank No. Tank Size Material Cause Source Test Method Leak Rate Gross Failure

DEC REMARKS:

6/24/08:SAC TELECON INGRID WEGAND - US ARMY RESERVE. MS. WEGAND SAID THEY HAVE BEEN INVESTIGATING A WHITE MILKY DISCHARGE FROM THEIR NUMBER 5 OUTFALL WHICH THEY SUSPECTED TO BE A PAINT. THEY PUT A CAMERA UP THE PIPE UNTIL THEY RAN INTO THE PIPE INVERT. WHEN THEY EXCAVATED AROUND THE INVERT THEY OBSERVED A REDDISH-BROWN PRODUCT BUBBLE UP IN THE TRENCH WHICH ONE OF THE WORKERS BELIEVED WAS PCB OIL. LESS THAN 4 FLUID OUNCES OF PRODUCT COLLECTED. THEY TOOK A SAMPLE TO HAVE IT ANALYZED. THEY INSTALLED A BALL VALVE IN THE LINE TO PREVENT ANY POTENTIAL DISCHARGE OF THE PRODUCT. SHE IS UNSURE WHETHER EXCAVATION HAS BEEN BACKFILLED. CHRISTINE ALBA FROM HER DEPT IS ON-SITE. WILL ARRANGE MEETING/INSPECTION ON-SITE TOMORROW.

6/24/08:SAC TELECON CHRISTINE ALBA. MS. ALBA SAID THAT EXCAVATION HAS BEEN BACKFILLED DUE TO SAFETY CONCERNS. WILL MEET TO TOMORROW ON-SITE.

Created On: 06/24/2008

Date Printed: 10/19/2010 Last Updated: 09/15/2010