

NYSDEC SPILL REPORT FORM



DEC REGION: 3			SPILL NUMBER: DEC LEAD:		0905232				
SPILL NAME: BROWNFIELD SITE: B00190					VPMCCABE				
CALLER NAME: AARON HOLLENBECK				NOTIFIER'S NAME:		AARON HOLLENBECK			
CLR'S AGENCY: STAMFORD RECKING COMPANY				NOTIFIE	R'S AGENCY:	STAMFORD RECKING COMPAN_			
CALLER'S PHONE: (607) 765-5042					NOTIFIER'S PHONE: (607) 765-5042				
SPILL DATE:		08/03/2009	SPILL T	IME:	10:00 am		DISPATCHER:		
CALL RECEIV	/ED DATE:	08/05/2009	RECEIV	ED TIME:	10:20 am		CRBARRY		
SPILL LOCATION									
PLACE:	BROWNFIELD SITE: B00190			COUNTY:		Dutchess			
STREET:	204 RINALDI I	IALDI BLVD		TOWN/CITY: COMMUNITY:		Poughkeepsie (c)			
						POUGH	KEEPSIE		
CONTACT:	JOSH COOK			CONT	ACT PHONE:	(518) 40	02-9652		
CONT. FACTOR: Other				SPILL REPORTED BY: Other					
FACILITY TYPE: Comme		ercial/Industrial		WATERBODY:					
CALLER RE removing of Albany to	contaminated so	oil from brownfield site,	discovered	d more conf	taminated soil,	was asked	d by Josh Cook of DEC	in	
MATERIAL JNKNOWN PET	ROLEUM	CLASS Petroleum	l	SPILLED	REC	OVERED	RESOURCES AFFECT Soil,	TED	
		<u>POT</u>	ENTIAL	SPILLEF	<u>RS</u>				
COMPANY BROWNFIELD SITE		ADDRESS NY			CONTACT JOSH COOK				
						(518	8) 402-9652		

Tank No. Tank Size Material Cause Source **Test Method** Leak Rate Gross Failure

DEC REMARKS:

Spill is at ERP Site (ID B00190). This area of historic contamination was not identified during RI. Area was distinct from other areas of petroluem contamination previously identified (See also Spills 0010139 & 0404948).

Consultant reports that contamination was identified in vicinity of newly installed manhole on east side of site. Contamination was encountered at groundwater table and appeared to extend off-site to the east, under the retaining wall for Metro North RR. - jpc 08/05/09

PIN T & A COST CENTER

CLASS: C3 **CLOSE DATE:** 08/05/2009 **MEETS STANDARDS:** False

Created On: 08/05/2009

Date Printed: 4/8/2010 Last Updated: 08/05/2009