

APPENDIX Y

Hazardous Solid Waste
Disposal Manifests

142841

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NY D001495274	2. Page 1 of 1	3. Emergency Response Phone 927 685107	4. Manifest Tracking Number 008275116 FLE		
5. Generator's Name and Mailing Address VERNON 4540 Reality LLC 45-40 VERNON BLVD LIC NY 1101		Generator's Site Address (if different than mailing address) VERNON 4540 5-49 46TH AVENUE LIC NY 1101					
6. Transporter 1 Company Name IWT TRANSPORT INC.		U.S. EPA ID Number NJR988628162					
7. Transporter 2 Company Name		U.S. EPA ID Number					
8. Designated Facility Name and Site Address CLEAN EARTH OF NORTH JERSEY 105 JACOBUS AVENUE SOUTH KEARNY NJ 07032 Facility's Phone: 073-344-4004		U.S. EPA ID Number NJD991291105					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit WL/Vol.	13. Waste Codes
	X	1. RQ NA3077, Hazardous waste, solid, n.o.s. (CONTAINS LEAD COMPOUNDS) 9, PGM	4	DM	2000	P	D008
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information Arrived 115 P DOWLOADING 315P BE Profile 163080429 - ORDER 142841 - Note							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Officer's Printed/Typed Name Steve Carrier		Signature 		Month Day Year 4/8/16			
INTL	16. International Shipments ☐ Import to U.S. ☐ Export from U.S.		Port of entry/exit: Date leaving U.S.:				
	Transporter signature (for exports only):						
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials		Signature		Month Day Year		
	Transporter 1 Printed/Typed Name Chris Cifelli				4/8/16		
DESIGNATED FACILITY	Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy							
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection							
Manifest Reference Number:							
18b. Alternate Facility (or Generator)		U.S. EPA ID Number					
Facility's Phone:							
18c. Signature of Alternate Facility (or Generator)		Month Day Year					
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H110		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in item 18a							
Printed/Typed Name Doug McKinnis		Signature 		Month Day Year 4/11/16			