

Weekly Construction Progress Report

Work Period: 7/6/21 thru 7/9/21

**Northrop Grumman
Operable Unit 3
RW-21 Project Area
Bldg. 109 Treatment System
Bethpage, New York**

Project Work Performed:

- Performed Community Air Monitoring with no reportable exceedances.
- Performed noise monitoring with no sustained exceedances.
- Influent Pipe (Near Building):**
 - Continued installation and compaction of backfill within the influent pipe trench.
- Effluent Pipe (Near Building):**
 - Continued installation and compaction of backfill within the effluent pipe trench.
 - Placed cement around effluent pipe to seal opening in Control Structure B.



Effluent Pipe Connection to Control Structure B

Work Projected Next Period:

- Continue Community Air Monitoring.
- Continue noise monitoring.
- Complete installation and compaction of backfill within the influent and effluent pipe trenches.



Backfilled Influent Pipeline



Backfilling Effluent Pipe Trench

Site Visitors:

- None.