

Weekly Construction Progress Report

Work Period: 7/12/21 thru 7/16/21

**Northrop Grumman
Operable Unit 3
RW-21 Project Area
Bldg. 109 Treatment System
Bethpage, New York**

Project Work Performed:

- Performed Community Air Monitoring with no reportable exceedances.
 - Performed noise monitoring with no sustained exceedances.
 - Delivered potable water pipe to site.
- Influent Pipe (Near Building):
- Completed backfilling and compaction of influent pipe trench.
- Effluent Pipe (Near Building):
- Completed backfilling and compaction of effluent pipe trench.



Backfilled Influent and Effluent Pipe Trenches

Work Projected Next Period:

- Continue Community Air Monitoring.
- Continue noise monitoring.
- Begin installing storm sewer piping and structures.



Backfilled Influent Pipe Trench

Site Visitors:

- None.



Delivery of Potable Water Pipe