

New York State Department of Environmental Conservation
Division of Environmental Remediation
Central Office



DAILY INSPECTION REPORT

Site Code #: 1-30-009	Date: 03/02/2014	Report #: 60
------------------------------	-------------------------	---------------------

Site Name: Photo Circuits Site – Waste Characterization, Transportation & Disposal

Location: Glen Cove, Nassau County

DEC Proj. Mgr.: Michael Mason

Call Out Contractor: Environmental Assessment & Remediation (EAR)

Call Out Contractor Proj. Mgr.: Ian Hofmann

	AM	PM
Weather	Cloudy	
Temperature	20	
Wind Direction	West	

Description of work performed by contractor this report period:

EAR (Prime), PSC Environmental Services (Sub):

- The last remaining drummed waste chemicals were removed from the Chemical Storage Building and shipped to Northland Environmental, Providence, RI. for disposal.

Discussions/comments regarding visitors, contractor and/or engineer:

- EAR plowed snow to gain access to the site

Change Orders:

Sampling and Analyses:

Major Issues	Description & Reason

Health & Safety:

Level of protection: D

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? Yes

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from: 7:00am – 12:00pm (Estimate)


Subcontractor	Activity	Hours Worked
(1) PSC	Chemical Disposal	5

Equipment	P	1	2	3	4	Personnel	P	1	2	3	4
Pick up/Ford F150	1					Super	1				
Pick Up/Ford Ranger						(3)Laborers					
Decon Trailer	1					Chemists	1				
Generator						Laborer					
Utility Trailer	1					Technician		1			
Tractor Trailer											
Pick up/Ford F250											
Box Truck		1									
Sampling Van											
Fork Lift/Doosan	1										

Site Representative: Kristopher Keenan**Date: 03/02/2014****Representative's Signature:**

Photo Log

None



Currently occupied by Ted Dubilly North Shore Contracting (516-676-2772)