


330 Crossways Park Drive, Woodbury, New York, 11797-2015 516-364-9890 • 718-460-3634 • Fax: 516-364-9045 e-mail: findingsolutions@db-eng.com



Principals

Nicholas J. Bartilucci, P.E.

Henry J. Chlupsa, P.E. Executive Vice President

Steven A. Fangmann, P.E. Senior Vice President

Richard M. Walka Senior Vice President

John A. Mirando, P.E. Vice President

Anthony O. Conetta, P.E. Vice President

Dennis F. Koehler, P.E. Vice President

Joseph H. Marturano Vice President

Kenneth J. Pritchard, P.E Vice President

Theodore S. Pytlar, Jr. Vice President

Brian M. Veith, P.E. Vice President

Senior Associates

Garrett M. Byrnes, P.E.

Thomas P. Fox, P.G

William D. Merklin, P.E.

Michael Neuberger, P.E.

Kenneth P. Wenz, Jr., C.P.G.

Associates

Joseph F. Baader

Steven M. Cabrera

Rudolph F. Cannavale

Christopher M. Clement

Stefanos J. Eapen, R.A. Joseph A. Fioraliso, P.E.

Christopher W. Francis

Robert L. Haynie, P.E.

Michael R. Hofgren

Sean Pepling, P.G.

Edward J. Reilly
Daniel Shabat, P.E.

Charles J. Wachsmuth, P.E.

March 28, 2006

Heide-Marie Dudek, P.E. Environmental Engineer I New York State Department of Environmental Conservation Bureau of Eastern Remedial Action Division of Environmental Remediation Remedial Bureau A, 11th Floor 625 Broadway Albany, New York 12233-7015

Re: Fumex Sanitation Site No. 1-30-041

Project Management Work Plan

D&B 2475

Dear Ms. Dudek:

Please find enclosed seven revised copies of the Project Management Work Plan for the Fumex Sanitation Site. We have addressed your comments as follows:

Comment No. 1

<u>Section 3.2.2 - Off-Site Soil Sampling</u> - Please remove the sentence "As requested by the NYSDEC, area currently covered with asphalt pavement or concrete will not be sampled as potential exposure of site occupants to any underlying contamination would be highly unlikely in these areas due to isolation."

Response to Comment No. 1

Comment acknowledged and the statement was removed from the text.

Dvirka and Bartilucci

CONSULTING ENGINEERS

Heide-Marie Dudek, P.E. Environmental Engineer I New York State Department of Environmental Conservation Bureau of Eastern Remedial Action Division of Environmental Remediation March 28, 2006 Page Two

Comment No. 2

<u>Section 3.2 - Task 2 - Pre-design Investigation</u> - Please include one round of groundwater monitoring well sampling to establish a baseline.

Response to Comment No. 2

One round of groundwater monitoring well sampling has been added to the work plan.

Comment No. 3

<u>Section 3.3.4 - Project Cost Estimate</u> - The Engineer's cost estimate will be sealed and signed by a Professional Engineer licensed to practice in New York State.

Response to Comment No. 3

The Engineer's cost estimate will be sealed and signed by a Professional Engineer licensed to practice in New York State.

Comment No. 4

<u>Section 2.1 - Site Location and Description</u> - Please change the last sentence to read, "The site was historically occupied by Fumex Sanitation, Inc., a commercial termite extermination business."

Response to Comment No. 4

This statement has been added to Section 2.1 as requested.

Comment No. 5

<u>Section 2.2 - Site History, Page 2-4</u> - When referencing the residential samples, please use sample location names.

Response to Comment No. 5

The sample references on Page 2-4 have been revised to use the sample location names.

Dvirka and Bartilucci

CONSULTING ENGINEERS

Heide-Marie Dudek, P.E. Environmental Engineer I New York State Department of Environmental Conservation Bureau of Eastern Remedial Action Division of Environmental Remediation March 28, 2006 Page Three

If you have any additional comments or questions, please do not hesitate to contact me at (516) 3364-9890.

Very truly yours,

Frank DeVita Project Manager

FD/MDWt/jmy

cc:

J. Yavonditte (NYSDEC)

R. Walka (D&B)

B. Veith (D&B)

K. Wenz (D&B)

◆2475\FD06LTR.DOC-01(R01)