

County of Richmond

ORIGINAL TO COMMISSION

State of New York
Department of Conservation
Division of Water Power and Control

Well No. N 4154
(See publication report)

LOG

Ground Surf., 21 ft. above sea

COMPLETION REPORT—LONG ISLAND WELL

Owner Mrs. R. G. Allen

Address R. 21 Box West

Location of well John's Creek, Twp. 1, R. 21

Depth below surface 101 feet

Depth to water: Ground water 79 ft.; Finished well 101 ft.

CASINGS:

Diameter 4" in.

Length 91 ft.

Sealing *

Casings removed 2'

SCREENS: Make Clayton in. 1/2 openings 4/15

Diameter 2 in.

Length 98 ft.

Depth to top from top of casing 98 ft.

PUMPING TEST: Date April 21/53 Test on permanent pump?

Duration of Test 3 days 3 hours

Maximum Discharge 4 gallons per minute

Static Level Prior to Test 79 ft. in. below top of casing

Level during Max. Pumping 79 ft. in. below top of casing

Maximum Drawdown 98 ft.

Approx. time of return to normal level after cessation of pumping 101 minutes

PUMP INSTALLED:

Type Electric Make General Model No. 16A

Motive power Electric Make Westinghouse H.P. 3/4

Capacity 4 g.p.m. against 40 ft. of discharge head

No. bowls or stages 1 ft. of total head

DROP LINE:

Diameter 2 1/2 in.

Length 28 ft.

SUCTION LINE:

Use of water

Work started April 16/53 Completed April 24/53

Date June 17/53 Driller Paul H. H. H.


License No. 208

Notes: Show log of well materials encountered, with depth below ground surface, water-bearing beds and water levels in each, casings, screens, pump, additional pumping tests and other matters of interest. Describe repair job.

See Instructions as to Well Drillers' Licenses and Reports—pp. 5-7.

STATE OF NEW YORK
WATER POWER AND
CONTROL COMMISSION
RECEIVED
JUN 17 1953

SKETCH OF LOCATION



Locate well with respect to at least two streets or roads, showing distance from corner and front of lot.

Show North Point