

DUPLICATE RETAIN

Well No. N 6373
(on preliminary report)
LOG
 Ground Surf., El. 11 ft. above sea
11 ft.
 Top of Well

State of New York
 Department of Conservation
 Division of Water Power and Control
 COMPLETION REPORT - LONG ISLAND WELL

Owner ADAMUS PROPERTY, INC.

Address 121 E. 12th St., New York, N.Y.

Location of well Swan

Depth of well below surface 55' 10" feet

Depth to ground water from surface 16 feet

CASINGS:

Diameter 4 in. in. in. in.

Length 50' 10" ft. ft. ft. ft.

Sealing

Casings removed

SCREENS: Make Johnson SRR Openings 30

Diameter 1 in. in. in. in.

Length 5' 9" ft. ft. ft. ft.

Depth to top from top of casing 51' 8" ft.

PUMPING TEST: Date 1-26-55 Test or permanent pump? P

Duration of Test 2 hours

Maximum Discharge 15 gallons per minute

Static level prior to test 16 ft. in. below top of casing

Level during Max. Pumping 18 ft. in. below top of casing

Maximum Drawdown 2 ft.

Approx. time of return to normal level after cessation
 of pumping hours minutes

PUMP INSTALLED:

Type SWT Make JACOZZI Model No. 3 SPS

Motive power ELCO Make JACOZZI H.P. 3

Capacity 30 g.p.m. against 150 ft. of discharge head

No. bowls or stages 3 190 ft. of total head

DROP LINE:

Diameter in.

Length ft.

SUCTION LINE:

Diameter 2 in.

Length ft.

Use of water Washing

Work started 5-11-55 Completed 5-26-55

Date 6-10-55 Driller G.W. Lauman & Co., Inc

License No. 13

NOTE: Show log of well—materials encountered, with depth below ground surface, water bearing beds and water levels in each, casings, screens, pump, additional pumping tests and other matters of interest. Describe repair job.
 See Instructions as to Well Drillers' Licenses and Reports—pp. 5-7.

STATE OF NEW YORK
 WATER POWER AND
 CONTROL COMMISSION
 JUN 14 1955 ✓

