

## ORIGINAL--TO COMMISSION

Capacity. 100 gpm

State of New York

Department of Conservation

Division of Water Power and Control

## COMPLETION REPORT—LONG ISLAND WELL

Well No. N-6617

(on preliminary report)

## LOG

Ground Surf., El.....ft. above sea

.....ft.

Top of Well

Owner \_\_\_\_\_

Address \_\_\_\_\_

Location of well at \_\_\_\_\_

Depth of well below surface .....feet

Depth to ground water from surface.....55.....feet

## CASINGS:

Diameter.....in. ....in. ....in. ....in. ....in.

Length.....ft. ....ft. ....ft. ....ft. ....ft.

Sealing .....

Casings removed .....

SCREENS: Make. ....in. ....Openings. ....in. ....in.

Diameter.....in. ....in. ....in. ....in. ....in.

Length.....ft. ....ft. ....ft. ....ft. ....ft.

Depth to top from top of casing.....ft. ....ft.

PUMPING TEST: Date. 1/24/51 Test for permanent pump?.....

Duration of Test.....days.....hours.....

Maximum Discharge.....gallons per minute

Static level prior to test.....ft. ....in. below top of casing

Level during Max. Pumping.....ft. ....in. above top of casing

Maximum Drawdown.....ft. ....ft.

Approx. time of return to normal level after cessation  
of pumping.....hours.....minutes

## PUMP INSTALLED:

Type. ....Make. ....Model No. ....

Motive power. ....Make. ....H.P. ....

Capacity. ....g.p.m. against } ....ft. of discharge head

No. bowls or stages. ....} ....ft. of total head

## DROP LINE:

## SUCTION LINE:

Diameter .....in. ....in. ....in.

Length .....ft. ....ft. ....ft.

Use of water. ....

Work started.....Completed.....


Date. 1/24/51 Driller. ....

License No. ....

Note: Show log of well—materials encountered, with depth below ground surface, water bearing beds and water levels in each, casings, screens, pump, additional pumping tests and other matters of interest. Describe repair job.

See Instructions as to Well Drillers' Licenses and Reports—pp. 5-7.

**SKETCH OF LOCATION**



Locate well with respect to at least two streets or roads, showing distance from corner and front of lot.

Show North Point

Report

1/3/65 Diamond - Pump off grid. well surgeyed.