


CARICH
ENVIRONMENTAL SPECIALISTS

e-mail: eweinstock@carichinc.com



April 1, 2008

NYSDEC

Division of Hazardous Waste Remediation
625 Broadway
Albany, New York 12233-7015

Attention: Joe Jones

Re: **On-Site Air Sparging/Soil Vapor Extraction System
Revised Partial Decommissioning Report
Tishcon Corporation, Site No.: 130043E
30 New York Avenue, Westbury, NY
Agreement Index No.: W1-0758-95-05; Tishcon file #74**

Dear Mr. Jones:

As a follow up to our July 7, 2007 AS/SVE Closure Report for the Tishcon Site at 30 New York Avenue and in accordance with our Site Management Plan (Ref. 1), we are pleased to provide you with the following information regarding the partial decommissioning of the on-site AS/SVE system. Tishcon is in the process of adding an extension to the rear portion of their building. To accommodate the construction of the addition, the following actions were performed.

- On September 24, 2007, SVE well V-3 and air sparge point S-6 were properly abandoned by the drilling company ADT using clean sand in the screen zones and a mixture of Portland cement and bentonite above the screen zones.
- On March 14, 2008, SVE wells V-4 (Deep), V-4 (Shallow) and air sparge points S-4, S-5, S-7, S-8, S-9, S-10, and S-11 were properly abandoned by the construction company Practice Group International Inc. using clean sand in the screen zone and a mixture of Portland cement and bentonite above the screen zones.

The off-site extension of the AS/SVE system remains in operation. Once the off-site compliance wells meet their termination criteria, we will contact you regarding the decommissioning of the remaining system components.

If you have any questions regarding this report, please do not hesitate to call our Office.

Sincerely,

CARICH CONSULTANTS, INC.

Paul S. Loor
Project Environmental Scientist

Ca RICH Environmental Specialists

References


1. CA RICH, April, 2008, Site Management Plan, Tishcon Corporation, 30 - 36 New York Avenue and 31 - 33 Brooklyn Avenue, Westbury, New York

EW/PL

cc: Joe Elbaz, Tishcon
Carl Hoffman, NYSDEC (Albany)



NT Server\Files\Users\Eric\Docs\Tishcon\On-site closure\AS-SVE 2008 closure report

Figures



LEGEND

- ⊙ ACTIVE SVE WELL
- ⊖ ACTIVE SPARGE WELL
- ⊕ ACTIVE COMBINED SVE/SPARGE
- ⊗ ABANDONED SPARGE POINT
- ⊗ ABANDONED SOIL VAPOR EXTRACTION WELL



CA RICH CONSULTANTS, INC.	
Certified Groundwater and Environmental Specialists 17 Dupont Street, Plainview, New York 11803	
TITLE	ACTIVE AND ABANDONED REMEDIATION WELL LOCATION MAP
DATE	4/2/08
SCALE	1" = 60'
DRAWN BY	J.T.C.
CHECKED BY	E.A.W.
FIGURE	1
TREATING NO.	2008-2A