
VOLUME I FINAL REPORT

# Soil Vapor Extraction System Evaluation Lockheed Martin Corporation Great Neck, New York





Michael A. Hansen, P.E. Senior Engineer

Hansel SSS

Frank C. Lenzo, P.E.

Associate

## **SVE System Evaluation Report** and Pilot Study Workplan

Former Lockheed Martin Facility Great Neck, New York

Prepared by: ARCADIS Geraghty & Miller, Inc. and GM Consulting Engineers, PC.

Our Ref.: NY0001227.0001

Date: March 4, 1999

This document is intended only for the use of the individual or entity for which it was prepared and may contain information that is privileged, confidential, and exempt from disclosure under applicable law. Any dissemination, distribution, or copying of this document is strictly prohibited.

#### DISCLOSURE STATEMENT

The laws of New York State require that corporations which render engineering services in New York be owned by individuals licensed to practice engineering in the state. ARCADIS Geraghty & Miller, Inc. cannot meet that requirement. Therefore, all engineering services rendered to Lockheed Martin Corporation in New York are being performed by GM Consulting Engineers, P.C., a New York professional corporation qualified to render professional engineering services in New York. There is no surcharge or extra expense associated with the rendering of professional services by GM Consulting Engineers, P.C.

ARCADIS Geraghty & Miller is performing all those services which do not constitute professional engineering and is providing administrative and personnel support to GM Consulting Engineers, P.C. All matters relating to the administration of the contract with Lockheed Martin Corporation are being performed by ARCADIS Geraghty & Miller pursuant to its amended and restated services agreement with GM Consulting Engineers, P.C. All communications should be referred to the designated Project Manager at ARCADIS Geraghty & Miller.

## **Table of Contents**

## **ARCADIS** GERAGHTY& MILLER

1.	Introduction	1
2.	SVE System Evaluation	2
	2.1 Review and Summary of SVE Evaluation Report Prepared by Tetra Tech	2
	2.2 Conclusions from SVE Evaluation Report - Tetra Tech	3
	2.3 ARCADIS Geraghty & Miller Evaluation and Proposed Modifications	3
3.	Pilot Study Workplan	5
	3.1 Pilot Study Location	6
	3.2 Pilot Study Wells	6
	3.3 Pilot Study Methodology	6
	3.4 Pilot Study Performance Monitoring, Evaluation, and Reporting	7
	3.5 Modified System Operation and Shut-down Criteria	8
4.	References	9

## **Tables**

3-1 Summary of Data Collection for SVE Pilot Study, Former Lockheed Martin Corporation Facility, Great Neck, New York.

## **Figures**

3-1 SVE Pilot Study Equipment Setup, Former Lockheed Martin Corporation Facility, Great Neck, New York.

## **Attachments**

A Soil Vapor Extraction System Evaluation Volumes I, II, III, Lockheed Martin Corporation Great Neck, New York, prepared by Tetra Tech, March 5, 1999.

#### 1. Introduction

ARCADIS Geraghty & Miller, Inc. and its engineering subcontractor, GM Consulting Engineers, P.C. has prepared the following Soil Vapor Extraction (SVE) System Evaluation Report and Pilot Study Workplan for the existing SVE system located at the Former Lockheed Martin facility (site) located in Great Neck, New York. The SVE system was implemented at the site in 1994 in order to remove volatile organic compounds (VOCs) identified in the vadose zone in the former dry well area located to the southeast of the main site building. Removal of the VOCs was intended to remove a possible source of additional groundwater impacts at the site.

Review of the SVE system operating data since system start-up in 1994 indicates that the mass removal rates from the system are currently lower than expected and have declined significantly since operation began in 1994. Although more than 30,000 pounds of VOCs have been recovered by the system to date, an estimated additional 36,000 pounds of VOCs are still assumed to be present in the subsurface (see Attachment A). In addition, the concentrations of these VOCs in soils are in excess of the clean-up goals specified by the Record of Decision (ROD) for the site. Finally, in June of 1998, the three drywells along with approximately 800 tons of surrounding soil were removed by excavation to a depth of approximately 30 feet, thus eliminating another potential source of VOC mass.

Based on these factors it was determined that an evaluation of the SVE system design and performance was required. The goal of this evaluation was to determine if SVE system operation could be enhanced, optimized, and/or modified to provide more efficient and timely VOC recovery from the drywell source area.

This report is organized into four sections. Section 1.0 provides a brief introduction to the report. A discussion of the results of the SVE Evaluation performed by Tetra Tech (Attachment A) as well as a summary of the results and proposed strategy to enhance the SVE system performance is presented in Section 2.0 A workplan outlining a proposed pilot study is presented in Section 3.0. References are provided in Section 4.0.

1

## 2. SVE System Evaluation

#### 2.1 Review and Summary of SVE Evaluation Report prepared by Tetra Tech

In early 1998, Lockheed Martin contracted Tetra Tech Inc. (Tetra Tech) of Pasadena, California, to perform an evaluation of the SVE system, as outlined in Section 1.0. An SVE Evaluation Workplan was initially submitted to the NYSDEC in March of 1998. Following workplan approval, Tetra Tech initiated the evaluation. The results of the SVE System Evaluation performed by Tetra Tech are included as Attachment A.

As outlined in Attachment A, and in the SVE Evaluation Workplan (Tetra Tech - 1998) the SVE system has been in operation in the former dry well area at the site since 1994. This system was implemented in order to remove the residual VOCs identified in the subsurface soils in the dry well area during various investigatory programs conducted at the site. SVE system operation in the period between January 1994 and the middle of 1998 has reportedly resulted in recovery of approximately 37,000 pounds of VOCs in the vapor phase. The SVE system, which is currently operating, is now recovering VOCs at a removal rate on the order of less than 50 pounds per month of total VOCs.

As part of the SVE system evaluation, detailed in Attachment A, Tetra Tech has estimated that approximately 36,000 pounds of VOCs likely remain in the area of interest. Therefore, given the fairly low extraction rate currently being achieved, timeframes for removal of a significant portion of the residual VOCs are extensive, estimated by Tetra Tech to be at least 28 years.

Additional relevant items from the evaluation performed by Tetra Tech include the following:

■ Review of the lithologic sampling logs for the soil borings installed as part of the evaluation, as well as review of past soil boring data (H<sub>2</sub>M - 1997) indicated that a zone of lower permeability soils are present in the subsurface in the dry well area. These lower permeability soils are described as silty sand/clayey sand, where as the balance of the unsaturated zone in the dry well area is made up of gravely sand and/or sandy gravel. The lower permeability soils are reported to extend from between 34 and 50 feet below land surface (bls) with the thickness of the layer varying between 4 and 7 feet. Additional details regarding these observations, including geologic cross-sections for the area of interest are provided in the SVE System Evaluation Report in Attachment A.

- Review of the Tetra Tech lithologic logs and other soil boring data also indicated that a localized zone of perched water is encountered in the dry well area at depths of between 35 and 40 feet bls. This perched water is apparently present in and above the layer of low permeability soils.
- Based on soil analytical data collected by Tetra Tech (Attachment A), it is assumed that 95% of the remaining VOC mass is present in the area where the fine-grained or low permeability soils are present.

#### 2.2 Conclusions from SVE Evaluation Report - Tetra Tech

Following collection of the additional geologic and VOC analytical data, Tetra Tech constructed a numerical airflow and vapor transport model for the dry well area. These models were intended to simulate air flow and VOC migration in the subsurface under both the existing and possible proposed extraction scenarios. Based on this modeling, Tetra Tech estimated that by operating only the existing SVE system, 28 years of operation would be required to recover 90 % of the remaining VOCs and achieve clean-up goals.

#### 2.3 ARCADIS Geraghty & Miller Evaluation and Proposed Modifications

The newly collected soil analytical data reported in Attachment A, combined with the past mass removal from the operating SVE system clearly illustrate the system is not performing as efficiently as needed for timely remediation of the residual VOCs. Given the fairly large mass of residual VOCs present in the subsurface, it would be expected that mass removal rates from the system would be much higher than they are currently.

Based on a review of the SVE Evaluation Report, as well as the other sources of information available, the most likely cause for the poor mass removal rates is that the SVE system is not generating airflow sufficient for timely remediation in the lower permeability soils. This is significant since these soils apparently contain the majority of the remaining VOCs, and that the most important factor is providing efficient mass removal using SVE technology is the generation of significant airflow across the soils impacted by the VOCs.

The absence of airflow in the low permeability soil is likely due to two related factors;

- The four existing SVE wells are all completed with long screened intervals (between 20 and 40 feet long) and these intervals generally cross both the lower and higher permeability portions of the vadose zone soils. Given the nature of subsurface airflow, it is expected that almost all of the airflow from the SVE wells will be generated from the potion of the screened interval completed in the higher permeability soils. Therefore, airflow is not being generated in the lower permeability sediments and the only mass removal from these zones (which contain the majority of the residual VOCs) is via diffusion from these areas. Diffusion provides a very poor mass removal efficiency compared to that of generating airflow directly across the impacted soils.
- The presence of the perched water in and above the lower permeability soil will completely block airflow in this zone. In this scenario all mass removal from the zone containing the perched water (the zone of low permeability soils containing the majority of the residual VOCs) will be via diffusion, which once again is very inefficient.

Based on this evaluation , ARCADIS Geraghty & Miller is proposing a modification to the SVE system. This proposed system modification will employ additional SVE wells, focused in the area of greatest levels of residual VOCs. These new wells will have small, discrete screened intervals corresponding to the zones of variable permeability. In addition, we propose to recover the perched water present in the low permeability unit. The combination of the perched water removal, along with the focused screened intervals of the new extraction wells - located in the areas of higher VOC impact - should provide for maximizing airflow across the most impacted soils, thus providing the most efficient VOC removal possible. It is assumed that the revised system will also employ individual vacuum blowers for each permeability horizon in which one or more SVE wells is completed. This will further limit the possibility for preferential air flow from only one zone.

The actual design and requirements for the proposed modified system will be determined following pilot testing (see Section 3.0). However, conceptually it is assumed that 2 to 3 new SVE wells will be completed with well screens located in the few feet above the low permeability zone, and an additional 2 to 3 wells will be completed with screens only within the low permeability zone. One of the existing system wells, VW-13, completed below the low permeability zone will also likely be included in the system. Assuming this well arrangement, three vacuum blowers will

be provided, one for each zone. The SVE wells located within the low permeability zone will also be used for recovery of the perched water, either via air-lift pumping or via down-hole pumps deployed within the wells. Given the relatively small extent of the perched water zone, it is expected the volume of water to be recovered will be relatively small. The recovered water will be contained in a storage tank and periodically transported to the IRM groundwater treatment system for treatment and disposal. It is assumed the existing off-gas treatment system will be used for the modified SVE system. However, alternate treatment for some or all of the off-gas may be proposed based on the pilot test results.

Based on this proposed approach and the anticipated modifications, ARCADIS Geraghty & Miller expects the upgraded SVE system to operate for a period of 6 to 18 months. System operation will be terminated based on achieving asymptotic recovery of soil vapors.

## 3. Pilot Study Workplan

As discussed above, implementation of a pilot study will be necessary to determine if the proposed modifications can be successfully applied, and to allow for confirmation of engineering design criteria for full-scale operation of the modified system. The goal of the proposed modifications is to maximize VOC mass removal in the short term to minimize the possible source of shallow groundwater impacts.

This workplan provides a description of the proposed pilot study location, layout, and methodology, including the proposed monitoring program, as well as data evaluation, and reporting plans. Specific objectives for the pilot study include the following:

- gathering data on the amount of perched water present in the dry well area, and the potential recovery rates;
- determining the required well construction and air flow characteristics (i.e., applied vacuum level and extraction airflow rate) necessary to insure reasonable mass removal rates;
- determining the VOC removal efficiency and the overall mass removal from the soil provided with various operating methodologies (i.e., air removal rates and pressures) - this data will also be used to determine possible modifications required for off-gas treatment;
- determination of process information necessary to size, select, and specify any new mechanical and electrical equipment needed for the modified system; and,

 determination of the geometry of the area of influence created by the SVE well operation - this data will be used to determine the total number of new wells required for the full-scale system (currently estimated at 4 to 6 - see Section 2.3).

#### 3.1 Pilot Study Location

The pilot study will be performed in the area of Tetra Tech Soil Borings TT-4 and TT-5. This area was selected based on residual VOC concentrations detected in soil samples collected by Tetra Tech as part of their Evaluation (Attachment A) as well as the presence of a lower permeability silty sand/clayey sand unit from approximately 40 to 50 feet below land surface (bls) in this location. Based on the vertical soil delineation completed by Tetra Tech, the silty sand/clayey sand unit and the zone directly above it (saturated/perched groundwater) appear to contain the highest concentrations of residual VOCs.

#### 3.2 Pilot Study Wells

Two new SVE wells will be installed for use during the pilot study. The new SVE wells will be installed adjacent to the locations of Tetra-Tech borings TT-4 and TT-5, respectively. Both wells will be constructed of 4-inch diameter PVC well materials with a stick-up casing. No well development will be required. One of the new wells will be completed to the top of the lower permeability unit, in the zone of perched water (total depth approximately 45 feet) with approximately 5 to 10 feet of well screen. The second new well will be completed to the bottom of the lower permeability unit (total depth approximately 50 feet) with approximately 5 feet of screen. The specific well completion details (total depth, screen interval, etc.) will be field determined based on the results of additional lithologic samples collected during installation of the well borings. Both wells will be equipped with a 5-foot long section of blank casing at their base to serve as a sump for collection of the perched water in and above the low permeability zone.

#### 3.3 Pilot Study Methodology

It is anticipated the pilot study will be performed over a period of three to five days. Prior to initiating the test, the existing SVE wells and vapor monitoring points will be gauged to determine where perched and/or shallow groundwater is present. In addition, perched water and/or shallow groundwater samples may be collected, if present, and analyzed for VOCs. The purpose of these analyses to evaluate VOC concentrations in the perched water in the SVE area.

Following the pre-pilot activities, the two new SVE wells will be installed as outlined above. At the completion of well installation the method for removing the perched groundwater will be selected.

Prior to start-up of the SVE pilot testing, the perched water will begin to be recovered. Because the volume of perched groundwater to be extracted is expected to be limited, it will be stored in a temporary holding tank, and periodically transferred to the IRM groundwater treatment system for treatment and disposal. It is anticipated that perched water recovery will be performed for one to two days.

Once the perched groundwater has been removed from the test location, each new SVE well will be tested individually by connecting it to one of the existing blowers and/or a portable blower to apply vacuum for the pilot study. The portable blower will be capable of developing a vacuum of at least 15 inches of mercury, in order to be able to generate sufficient airflow in the lower permeability soils. Vacuum application to each well is anticipated to be between 8 and 24 hours at each location. During testing, a minimum of three different applied vacuum levels will be evaluated for each SVE test well and data will be collected during each of the corresponding flow regimes.

The pilot study equipment setup will include an air dilution valve on the suction side of the blower to control the vacuum to the SVE test well. The extracted soil vapor will be treated using a temporary vapor phase carbon vessel prior to discharge to the atmosphere. The soil vapor extraction line will be equipped with a sampling port for the collection of air samples and to measure vacuum applied to the SVE wells. Airflow measurements will be collected from the discharge stack using an anemometer. The anticipated SVE pilot study equipment setup is shown on Figure 3-1.

#### 3.4 Pilot Study Performance Monitoring, Evaluation, and Reporting

During the testing at each well, the following system performance data will be collected;

- Vacuum and airflow rates from the extraction well;
- Perched water recovery rates;
- Induced vacuum levels at existing vapor monitoring points (for collection of spatial SVE system performance data);
- VOC concentrations in the extracted soil vapor; and

## • VOC concentrations in the treated off-gas.

At each well, the maximum vacuum that can be developed by the blower will be applied initially. Samples of the extracted soil vapor will be collected for laboratory analysis of VOCs at the start-up of each test phase, midway through each test phase, and at the end of each test phase. During and between collection of laboratory samples additional vapor samples will be collected for field analysis with a photo-ionization detector (PID) along with field measurements of the remaining performance monitoring parameters. At the end of the test run, the vacuum applied at the well will then be stepped down, twice, with field measurements collected at each interval to evaluate the change in airflow and observed subsurface vacuum with changing applied vacuum levels. The attached Table 3-1 contains a summary of the proposed data to be collected and the frequency of collection for the pilot study.

After the field study has been completed, ARCADIS Geraghty & Miller will evaluate the results to determine the feasibility of possible system modifications for the SVE system. If it is determined that modifications sufficient to provide a reasonable increase in VOC recovery, specific design criteria for such system modifications will also be determined. A pilot study summary report, for NYSDEC review, will then be prepared. This report will include the baseline and performance monitoring results, along with a conceptual design of the full-scale system.

Following implementation of the modified system, a design report including system specifications and as-built plans will be provided.

#### 3.5 Modified System Operation and Shut-down Criteria

Following modifications, the system will be restarted and resume continuous operation. It is assumed that operating data for the modified system will be collected and reported per the existing approved IRM workplan.

In accordance with the ROD, a request will be made to the NYSDEC to terminate operation of the SVE system when either soil concentrations meet the site specific soil clean-up objectives, or when the SVE system is no longer effective in removing VOC mass. Based on the anticipated response to the system modifications, it is anticipated that the period of additional operation will be between 6 and 18 months.

## 4. References

Tetra Tech, Inc. 1998. Final Workplan for Soil Vapor Extraction System Evaluation. Former Lockheed Martin Facility, 365 Lakeville Road, Great Neck, New York. March 1998.

H<sub>2</sub>M Associate, Inc. 1997. Scope of Work for Soil Vapor Extraction System
 Evaluation. Lockheed Martin Tactical Defense Systems, 365 Lakeville Road,
 Great Neck, New York. July 1997.

g:\aproject\lmc\_grip\grt\_neck\SVE system\SVE report and pilot workplan






Table 3-1. Summary of Data Collection for SVE Pilot Study,
Former Lockheed Martin Corporation Facility, Great Neck, New York.

Phase	Data Collected	Frequency
Baseline	Depth to water measurements from existing SVE wells and monitoring points	One time
(prior to test)	Groundwater samples from existing SVE wells and observation points (analyzed for VOCs)	
		One time
During test	Vacuum and air extraction rates at extraction wellhead	Hourly during test
(to be duplicated at each test well)	Induced vacuum at observation points	Hourly during test
	Effluent soil vapor sample from extraction line (for laboratory analysis)	Three times during maximum vacuum development (start, middle, end of run)
	Effluent vapor sample from extraction line (to be field screened with PID/FID)	Hourly during test and between laboratory sampling
	Off-gas sample from vapor treatment (to be field screened with PID/FID)	Hourly during test

#### Notes:

PID Photo Ionization Detector
FID Flame Ionization Detector





Attachment A

Soil Vapor Extraction System Evaluation

## Lockheed Martin Corporation Soil Vapor Extraction System Evaluation Report

Prepared for: Lockheed Martin Corporation

Prepared by: Tetra Tech, Inc.

Dan Batrack Program Manager

Nisha Bansal Project Manager

Jia-Ling Wur, P.E. PhD Project Engineer

Phil Skorge Project Geologist

## **TABLE OF CONTENTS**

Sec	ction				Page
1	INTE	RODUCTION	ON		1-1
2	SITE	HISTOR	Υ		2-1
	2.1	Site Lo	cation and De	scription	2-1
	2.2			ns at the Dry Well Area	
	2.3			on	
	2.4			Calculations	
		2.4.1	VOC Mas	ss Estimate by Unisys Corporation	2-8
		2.4.2	VOC Mas	ss Estimate by H2M	2-8
	2.5	Site Ge	ology and Hy	drogeology	2-10
3	DAT	A COLLE	CTION FOR	SVE EVALUATION	3-1
	3.1	Data Ga	aps		3-1
	3.2	Soil Bo	ring Location	s	3-2
	3.3			Ţ	
		3.3.1		ix Sample Collection Procedures	
		3.3.2		ical Data	
		3.3.3		Data	
	3.4				
		3.4.1		or Sample Collection Procedures	
		3.4.2		or Data	
	3.5	Extent of	of VOC Plume	e	3-19
4	CUR	RENT VC	OC MASS ES	STIMATION	4-1
	4.1			ons	
	4.2			Distribution	
	4.3	Assump	otions of VOC	Mass Estimate	4-12
5	ASS	ESSMEN <sup>.</sup>	T OF CURR	ENT SVE SYSTEM	5-1
	5.1				
	5.2	_		nt SVE System	
	5.3			······································	
		5.3.1		omain	
		5.3.2	5.3.2.1	libration	
			5.3.2.1	Air Filled Soil Porosity	
		5.3.3		ee Air Flow Simulation Results	
		ر.ر.	5.3.3.1	Case 1	
			5.3.3.2	Case 2	
			5.3.3.3	Case 3	
			5.3.3.4	Case 4	
		5.3.4		n of Air Flow Simulation Data	

# TABLE OF CONTENTS (Continued)

Secti	on			Page
	5.4	VOC M	ass Transport Model Results	5-12
		5.4.1	Model Domain	5-12
		5.4.2	Physical and Chemical Parameters	5-12
		5.4.3	VOC Mass Transport Simulation Results	5-13
		5.4.4	Evaluation of VOC Transport Data	5-13
٠	5.5	Conclus	ions	5-15
6	REF	ERENCES	<b>3</b>	6-1
			LIST OF FIGURES	
2-1	Site L	ocation Ma	ap	2-2
2-2	Site C	verview		2-3
3-1	Soil E	Boring Loca	ations	3-2
3-2			il Gas Sampling Train	
3-3	Estim	ated Latera	ll Extent of VOC Impacted Soil	3-20
3-4			·A'	
3-5			B'	
4-1			n Areas	
4-2	Mass	Distribution	n of Remaining VOCs in the Dry Well Area	4-11
5-1	Overv	iew of Exis	sting Extraction Wells	5-4
5-2	Soil V	Japor Extra	ction System Schematic	5-5
5-3	AIR3		lane Grids	
5-4 to :	5-23	AlR3D I	Modeling Results: Pressure Distribution, Cases 1 to 4	5-17 to 5-36
5-24	VT3E	) Model Pla	ane Grids	5-37
5-25 to	5-28	VT3D M	Modeling Results for Case 4	5-38 to 5-42

# TABLE OF CONTENTS (Continued)

## **LIST OF TABLES**

		Page
2-1	NWSDEC Recommended Soil Cleanup Objectives, Dry Well Area	2-7
2-2	H2M Volume and Mass Calculations	
3-6	Soil Boring Locations	3-2
3-7	Summary of Geotechnical Data	
3-8	Soil Sampling Locations and Depths	
3-9	Summary of VOCs Detected in Soil Samples	
3-10	Soil Vapor Sampling Locations and Depths	
3-11	Target Volatile Organic Compound List	3-17
3-12	Summary of VOCs Detected in Soil Vapor Samples	3-18
4-1	VOCs Mass Estimate for Area 1	
4-2	VOCs Mass Estimate for Area 2	4-4
4-3	VOCs Mass Estimate for Area 3	4-5
4-4	VOCs Mass Estimate for Area 4	4-6
4-5	Summary of VOC Mass Estimate	4-8
4-6	Summary of Vertical Mass Profiles for Total VOCs	4-10
5-1	Summary of Existing Extraction Wells	5-2
5-2	Summary of Existing Vapor Monitoring Wells	5-2
5-3	Summary of Soil Parameters Used in Modeling Simulations	
5-4	Calibrated Soil Air Permeability Values	5-8
5-5	SVE Operation Data for AIR3D Model Calibration	5-9
5-6	Air Flow Model Case Scenarios	
5-7	VT3DModeling Simulation Results for Case 4	5-14
	APPENDICES	
Α	Previous Mass Estimates	
В	Soil Boring Logs	
C	Geotechnical Data	
D	Soil Vapor Probe Construction Diagrams	
E	Soil Vapor Laboratory Analytical Data	
F	Soil Matrix Laboratory Analytical Data	

## Section 1

## Introduction

On behalf of Lockheed Martin Corporation (Lockheed Martin), Tetra Tech, Inc. has prepared the following report evaluating the soil vapor extraction (SVE) system located at the Lockheed Martin Great Neck facility. The SVE system was installed to reduce concentrations of volatile organic compounds (VOCs) within a former dry well area located at the southeast corner of the facility. The Lockheed Martin facility (New York State Department of Environmental Conservation (NYSDEC) Site ID# 130045) is located at 365 Lakeville Road in Great Neck, New York.

The objective of this evaluation is to determine whether the existing system is capable of reducing volatile organic compound (VOC) concentrations as established in NYSDEC's Record of Decision (ROD), dated July 1997. Subsurface soil sampling was conducted to obtain current chemical data around the dry well area where the SVE system is operating. The data was used to estimate the current lateral and vertical extent of VOC impacted soil, and to determine the total current VOC mass in the subsurface. Air flow and VOC transport modeling was conducted to determine if the existing SVE system is capable of attaining the cleanup goals as presented in the ROD.

This report is organized into the following sections:

- <u>Section 2</u> Site History, presenting a brief description of site location, previous investigations, previous VOC mass estimates, and site geology;
- <u>Section 3</u> Data Collection for SVE Evaluation, presenting the rationale and results for collection of geotechnical, soil matrix, and soil vapor data;
- <u>Section 4</u> Current VOC Mass Estimation, presenting the VOC mass calculation and distribution of chemicals;
- <u>Section 5</u> Assessment of SVE System, presenting the results of the air flow and VOC mass transport models;
- <u>Section 6</u> References.

## Section 2

# **Site History**

Investigations conducted at the Lockheed Martin facility in 1990 detected VOCs in the subsurface soil near the dry well area (H2M, July 1997). Further assessment of the area detected VOCs from the near surface to groundwater. As required by NYSDEC in the ROD, a SVE system was installed to recover VOCs from the soil around the dry well area. The existing SVE system operated at the site from January 1994 through June 1998.


This section presents the site location and description, the previous investigations conducted at the dry well areas, previous VOC mass estimates, and site geology and hydrogeology.

## 2.1 SITE LOCATION AND DESCRIPTION

The Lockheed Martin facility consists of approximately 94 acres and is located at 365 Lakeville Road in Great Neck, New York - see Figure 2-1. The facility was constructed in 1941 and formerly consisted of manufacturing operations for the design and production of a wide range of defense related equipment, navigational systems, and radar tracking systems. The facility is currently undergoing decommissioning and closure.


Three dry wells were formerly located at the southeast corner of the main manufacturing building. Various chemicals, including chlorinated solvents and other organic compounds, were detected in the soils beneath the dry wells. Figure 2-2 shows the locations of the former dry wells at the facility.

## FIGURE 2-1 SITE LOCATION MAP





## FIGURE 2-2 SITE OVERVIEW



PAGE 2-3

## 2.2 PREVIOUS INVESTIGATIONS AT THE DRY WELL AREA

Previous subsurface investigations at the dry well area were conducted in 1988, 1990, 1993, 1996, and 1997 (H2M, July 1997). Data obtained from these previous investigations were used to delineate the extent and estimate the mass of VOCs in the subsurface soils in the dry well area. A summary of the investigations is presented below.

#### 1988 Investigation

In 1988, a total of fourteen soil borings (B-1 through B-14) were drilled at the dry well area. Samples were collected at depths ranging from 5 to 32 feet below ground surface (bgs) and analyzed for VOCs and petroleum hydrocarbon compounds (PHC). No analytical data was available from borings B-2 through B-5. VOCs were not detected in samples collected from borings B-1 and B-6 through B-14. PHCs were detected at a maximum concentration of 41 parts per million (ppm) in boring B-10 (H2M, 1997).

## 1990 Investigation

In 1990 and 1991, eighteen soil borings (SVB1 through SVB18) were drilled to depths of 25 to 90 feet below ground surface (bgs) in the area of the southeast corner of the main building. Soil samples were collected at selected intervals to evaluate the vertical and horizontal extent of impacted soil. VOC impacted soil extended to the groundwater table, approximately 80 feet bgs. Total VOCs ranged from non-detectable concentrations to 2,200 ppm. The highest concentrations of VOCs were detected in soil samples collected in the vicinity immediately around the dry wells. The maximum concentrations of total VOCs were detected in boring SVB-17 at the 20 to 22 foot depth. The primary VOCs detected included tetrachloroethene (PCE), trichloroethene (TCE), toluene, ethylbenzene, xylenes, and 1,2-dichloroethene (H2M, July 1997).

Four of the borings were converted into vapor extraction wells (VW-1, VW-2, VW-13 and VW-14). Ten borings were converted into vapor monitoring wells (VW-3 through VW-12). Well construction details are presented in Section 5.2 of this report. Further discussion of the 1990 investigation is presented in the Scope of Work for Soil Vapor Extraction System Evaluation, (H2M, July 1997).

## 1993 Remedial Investigation

As part of a remedial investigation conducted in November 1993, five soil borings (B-15 through B-19) were conducted to a depth of 20 feet bgs near the southeast corner of the main building. The VOCs detected were PCE with a maximum concentration of 18,000 ppm, TCE (7,800 ppm), toluene (280 ppm), and xylenes (440 ppm). VOCs were detected at the highest concentrations in borings B-18 and B-19 at the 6 to 8 foot depth interval. Further discussion of the 1993 remedial investigation is presented in the Scope of Work for Soil Vapor Extraction System Evaluation (H2M, July 1997).

## 1996 Supplemental Remedial Investigation

A supplemental remedial investigation was conducted in November 1996, consisting of eight additional borings completed to a depth of 30 feet bgs. Three soil borings (SB-1, SB-5, and SB-6) were drilled through the center of each of the three dry wells and the remaining five borings were drilled in the area surrounding the dry wells. The highest concentrations of VOCs were detected in the three dry well borings. Primary VOCs detected included cis-1,2-dichloroethene at a maximum concentration of 3.3 ppm, PCE (4,400 ppm), and TCE (1,600 ppm). Further discussion of the 1996 supplemental remedial investigation is presented in the Scope of Work for Soil Vapor Extraction System Evaluation (H2M, July 1997).

## 1997 Investigation

In June 1997, three borings (D1, D2, and D3) were conducted through the center of each of the three dry wells at the same locations as in 1996. The three borings were drilled to a depth of 85 feet bgs. A total of 18 soil samples were collected at 40, 50, 60, 70, 78, and 85 feet bgs. The primary VOCs detected were PCE, TCE, toluene, ethylbenzene, and xylenes. Maximum concentrations (PCE at 610 ppm, TCE at 400 ppm, toluene at 28 ppm, ethylbenzene at 29 ppm, and xylenes at 180 ppm) were detected from boring D1 at the 50 foot depth. Further discussion of the 1997 investigation is presented in the Scope of Work for Soil Vapor Extraction System Evaluation (H2M, July 1997).

#### Dry Well Excavations

In June 1998, H2M excavated the three dry wells from the southeast portion of the site. The excavations extended to a depth of approximately 30 feet. A total of 833 tons of soil was removed from the dry wells (H2M, January 1999).

## 2.3 SVE SYSTEM OPERATION

In the ROD, NYSDEC established soil cleanup levels for the VOCs detected in the dry well area. A summary of the NYSDEC recommended soil cleanup objectives (RSCOs) established in the ROD is presented in Table 2-1.

In accordance with the ROD, a request will be made to the NYSDEC to terminate operation of the SVE system when either soil concentrations meet the site specific soil cleanup objectives, or when the SVE system is no longer effective in removing VOC mass. The system would be shutdown, allowed to equilibrate, and restarted to determine if additional VOCs could be removed. At such time, soil sampling will be conducted and compared to the RSCOs to assess the adequacy of the source area remediation.

Table 2-1

NYSDEC Recommended Soil Cleanup Objectives

Dry Well Area

Analyte of Concern	NYSDEC RSCO (ug/kg)
1,2-Dichloroethene (total)	885
Chlorobenzene	4,950
1,2-Dichlorobenzene	23,970
Ethylbenzene	16,500
Tetrachloroethene	4,155
Toluene	4,500
Trichlorofluoroethane (Freon 113)	18,450
1,1,1-Trichloroethane	2,280
Trichloroethene	1,890
Xylenes (total)	3,600

Note: NYSDEC Recommended Soil Cleanup Objectives and Cleanup Levels
Division of Hazardous Waste Remediation - Technical and Administrative
Guidance Memorandum (NYSDEC TAGM No. 92-4046, revised 4/95).
Site-specific Total Organic Carbon concentration of 30,000 mg/kg was used to calculate the site-specific RSCOs.

To reduce VOC concentrations to below NYSDEC RSCO levels, an SVE system was installed in January 1994 in the dry well area. The system consists of two vacuum blowers, four vapor extraction wells, a piping network, and catalytic oxidizer with a wet scrubber for emission control. Ten vapor wells for monitoring are located in the vicinity of the SVE system. Since operation of the SVE system from January 1994 to June 1998, approximately 37,723 pounds of VOCs have been removed and treated (H2M, June 1998). The existing SVE system has been operating at the site from January 1994 through June 15, 1998. Further details of the current SVE system are provided in Section 5.2.

## 2.4 PREVIOUS VOC MASS CALCULATIONS

The total mass of VOCs present in the soil at the dry well area prior to SVE operation was calculated by Unisys Corporation (Unisys) in approximately 1993 and by H2M Group (H2M) in 1996. A theoretical mass estimate using limited data was performed in approximately 1993

by Unisys - see Section 2.4.1. A second mass estimate was performed in 1996 by H2M using soil mass and average VOC concentration calculations - see Section 2.4.2.

## 2.4.1 VOC Mass Estimate by Unisys Corporation

In October and November 1991, Unisys conducted a pilot test to assess the feasibility of the SVE system to treat VOC impacted soils within the dry well area. One of the objectives of the pilot test was to collect analytical data for VOC mass estimation. A single VOC concentration data point was used by Unisys to extrapolate a theoretical exponential concentration curve to calculate a VOC mass of 200,000 pounds – *see Appendix A*.

Unisys applied a "standard chemical concentration reduction curve" to a single VOC concentration measured during the initial SVE pilot test. Based on the application of a theoretical VOC reduction rate applied over an assumed 450-day time period, Unisys estimated that 200,000 pounds of VOCs were present in the dry well area. Both the VOC removal rate and the period of anticipated SVE operation were estimated by Unisys based on data observed on other SVE projects. It should be noted that Unisys did not use the soil chemical analytical data available from the soil borings drilled from 1988 to 1991 to estimate the total VOC mass.

## 2.4.2 VOC Mass Estimate by H2M

In 1996, H2M calculated the mass of VOCs in the dry well area using data from soil samples collected in 1988, 1990, and 1991. H2M plotted the total VOC soil analytical results on a geologic cross section to estimate the volume of soil impacted by VOCs. H2M performed volume and mass estimates based on the following assumptions:

- 1) The extent of impacted soil was cylindrical in shape and encompassed two areas:
  - Area 1 contained high VOC concentrations in the immediate vicinity of the dry wells and encompassed a diameter of 125 feet with a depth of 30 feet.
  - Area 2 contained lower VOC concentrations surrounding Area 1 and encompassed a diameter of 225 feet with a depth of 90 feet.
- 2) The area of impacted soil did not extend greater than 10 feet below the groundwater table.
- 3) The analytical data was representative of average soil conditions.

Based on the volume estimates, mass calculations were performed for each area using the following calculation:

Total VOC mass = (soil volume) x (soil density) x (average total VOC concentration)

A summary of H2M's volume and mass estimates are presented in Table 2-2 as follows:

Table 2-2
H2M Volume and Mass Calculations

Area	Soil Volume (yd³)	Soil Mass (lbs.)	Total VOC Mass (lbs.)
1	13,900	41 x 10 <sup>6</sup>	52,000
2	120,000	3.56 x 10 <sup>8</sup>	18,000
Totals	133,900	3.97 x 10 <sup>8</sup>	70,000

Based on the sum of Areas 1 and 2, H2M estimated a total VOC mass of 70,000 pounds in the soil underlying the dry well area. Further details on H2M's mass calculations are provided in Appendix A.

## 2.5 SITE GEOLOGY AND HYDROGEOLOGY

Based on boring logs completed at the site, the uppermost subsurface soils at the dry well area consist of Upper Pleistocene glacial deposits. Subsurface soils to a depth of 80 feet bgs consist primarily of gravelly sand, sandy gravel, cobbles, and boulders. Borings completed west of the dry well area contained thick cobble and boulder layers. Thin fine-grained soil zones (clay, sandy clay, and silty sand) are present at a depth of approximately 30 to 50 feet below ground surface (bgs). Thickness of the fine-grained zones is approximately 15 feet.

Based on measurements collected from on-site monitoring wells, the depth to the first aquifer at the dry well area varies between 80 and 85 feet bgs. Groundwater is present within a gravelly sand / sandy gravel matrix.

A localized perched water lens exists in the immediate vicinity of the dry well area (around vent wells VW-13 and VW-14) at a depth between 35 and 40 feet bgs. Based on the absence of perched water in borings completed outside the immediate dry well area, the perched water appears to be no larger than approximately 50 feet in diameter. Perched water is likely to have been caused by surface infiltration located near the dry well area. Water appears to have pooled within fine-grained sediments at the 35 to 40 foot depth interval.

## Section 3

# Data Collection for SVE Evaluation

This section describes the data collected for the SVE evaluation. Current geotechnical and chemical data were required for a current assessment of site conditions, including soil VOC chemical data, soil vapor concentrations, soil moisture content and geotechnical parameters. This section discusses data gaps, field methods and the analytical results.

## 3.1 DATA GAPS

Geotechnical and chemical data were collected at the dry well area to evaluate the SVE system. Additional data were needed to determine lithology and geotechnical properties; assess the current lateral and vertical extent of the VOC plume; and estimate the current mass of VOCs in the subsurface soils.

Eight soil borings were completed in the dry well area for data collection. Soil matrix and soil gas samples were collected from the borings to obtain the data needed for the SVE evaluation. Soil matrix samples were collected to characterize site geology, estimate geotechnical parameters, and to obtain soil VOC analytical data. Multi-depth, nested soil vapor monitoring probes were installed in six of the borings to allow collection of soil vapor samples in various soil horizons. The following sections describe the data collection methods and present the results.


## 3.2 SOIL BORING LOCATIONS

To obtain geotechnical and chemical data for the SVE system evaluation, eight soil borings were drilled at the Lockheed Martin Great Neck facility. Soil borings were placed adjacent to previous investigation areas to provide direct correlation with data collected during the previous site investigations. Five of the eight soil borings were completed adjacent to locations where soil borings previously detected the highest VOC concentrations. To confirm delineation of the plume, the remaining three borings were completed at locations where previous soil borings reported low or non-detectable VOC concentrations. Figure 3-1 shows the locations of the soil borings. A summary of the borings is presented in Table 3-1.

Table 3-1
Soil Boring Locations

Tetra Tech Soil Boring	Soil Boring Location	Purpose of Soil Boring
TT-1	west of VOC plume, adjacent to VW-4	Obtain current data in area of previously detected high VOCs
TT-2	southwest of dry well #1, adjacent to VW-1	Obtain current data in area of previously detected high VOCs
TT-3	south of VOC plume, adjacent to VW-5	Obtain current data at southern edge of the VOC plume
TT-4	south of dry well #1, between B-16 and B-17	Obtain current data in area of previously detected high VOCs
TT-5	east of dry well #1, adjacent to VW-14	Obtain current data in area of previously detected high VOCs
TT-6	adjacent to dry well #1 and VW-13	Obtain current data in area of previously detected high VOCs
TT-7	north of VOC plume, adjacent to VW-6	Obtain current data at northern edge of the VOC plume
TT-8	east of VOC plume, adjacent to VW-3	Obtain current data at eastern edge of the VOC plume

## FIGURE 3-1 SOIL BORING LOCATIONS



## 3.3 SOIL MATRIX SAMPLING

Based on groundwater depth, the eight soil borings were extended to approximately 80 feet bgs. The intent was to determine the extent of VOCs to the depth of first groundwater. Continuous coring was conducted in selected borings to characterize lithology. Soil samples were collected for both geotechnical and chemical analyses. In accordance with the Soil Vapor Extraction System Evaluation Work Plan (Tetra Tech, July 1998), soil samples for chemical analyses were collected at 10-foot intervals beginning at 10 feet bgs, and at each major change in lithology.

Sludge materials were encountered at approximately 42 feet bgs in boring TT-5. In accordance with the Work Plan, a sample was collected from the sludge materials for further chemical analyses and characterization.

Soil matrix sample collection procedures are presented in Section 3.3.1. Geotechnical data are presented in Section 3.3.2, and chemical data are presented in Section 3.3.3.

## 3.3.1 Soil Matrix Sample Collection Procedures

## **Drilling** and Sample Collection

To complete the soil borings, Tetra Tech utilized hollow stem drilling methods to reach the desired boring depths. In areas of previously undefined lithology, continuous coring was conducted to provide a detailed evaluation of lithology. A split spoon sampler fitted with sampling sleeves was used for the collection of discrete undisturbed soil samples.

The sampler was loaded with clean stainless steel sample liners. All sample liners were washed prior to use. Advancement of the hollow stem auger continued to the sampling depth. The split spoon sampler was then driven into the soil for sample collection.

One sample liner with 100% recovery (completely filled with soil so that there was little void space) was delivered to the laboratory for analysis. The second sample liner was used for onsite head-space analysis. A third sample liner was used to log lithology.

## Sample Handling

Soil samples collected for chemical analysis were immediately capped and placed in a cooler with blue-ice pending delivery to the analytical laboratory. Each sample liner was covered with plastic end caps over teflon sheets. A label was placed on the sample liner that included a unique sample number, date and time that the sample was collected, name of the person handling the sample, and the specific analyses being requested from the laboratory. The sample liner used for headspace analysis was emptied into a sealable zip-lock plastic bag.

All soil samples for chemical analysis were placed in a cooler on blue ice pending shipment to a certified New York State Department of Health approved analytical laboratory. A Chain-of-Custody form was completed to record sample identification numbers, date and time of collection, and analyses requested. Copies of the Chain-of-Custody forms are presented in Appendix F.

## Headspace Analysis

Headspace analyses were performed as a field screening technique using calibrated organic vapor detectors. After being left at ambient temperature for approximately 10 minutes, the head-space in the bag was analyzed using a Photovac Microtip photoionization detector (PID). The PID instrument registers the concentration of total organic vapors in the headspace which is an indication of the presence of volatile organic compounds in the soil. The PID measures the concentration of airborne ionizable gases and vapors in the C<sub>2</sub> to C<sub>12</sub> range.

## Lithological Logging

A field geologist logged all boreholes using ASTM procedures and techniques. Each soil sample collected was inspected for color, moisture, sorting, grain size, and any other pertinent soil characteristics observed. The soil was classified using the Unified Soil Classification System, and all information was documented on the boring log form. Copies of the boring logs are presented in Appendix B.

## Equipment Decontamination

During sampling, a restricted work zone was established. Only authorized team members were permitted to enter this zone. A decontamination area and a clean zone were established at the perimeter of the restricted work zone for preparation and breakdown of sampling appurtenances. The decontamination area was established to contain decontamination rinsate solution for subsequent disposal. The decontamination staging area included buckets for decontamination of equipment.

Equipment used for sampling which was in direct contact with the soil media, underwent the following decontamination process:

- ✓ Loose dirt was brushed off with a steel-bristle brush in the decontamination area;
- ✓ Equipment was washed in a non-phosphate detergent solution using plastic scrub brushes;
- ✓ Following the detergent wash, equipment was rinsed with tap water; and
- ✓ As a final step, equipment was rinsed with distilled water and allowed to air dry.
- ✓ The clean equipment was transferred to the clean zone.
- ✓ Decontamination solutions were transferred to 55-gallon drums for storage prior to disposal.
- ✓ Hollow-stem augers were decontaminated using an on-site steam cleaner.

#### Borehole Abandonment

Borings TT-2 and TT-4 were backfilled with bentonite grout. The other six borings were converted into nested soil gas probes - see Section 3.4.

#### Waste Management

Equipment rinse water and drill cuttings were generated during the sampling program. The wastes were contained in Department of Transportation (DOT) approved 55-gallon drums and stored at a designated staging area. All drums were appropriately labeled and logged on a drum inventory form. All drill cuttings and associated waste were characterized and disposed of in accordance with the NYSDEC Final Division Technical and Administrative Guidance Memorandum - Disposal of Drill Cuttings. Equipment rinse water was transported to the onsite groundwater Interim Remedial Measures (IRM) system for treatment.

## 3.3.2 Geotechnical Data

Ten soil samples were collected for geotechnical analyses. The soil samples were analyzed for total organic carbon, bulk density, moisture content, and soil porosity. The geotechnical data are summarized in Table 3-2. Copies of the laboratory reports are presented in Appendix C.

Table 3-2
Summary of Geotechnical Data

Sample No.	Total Organic Carbon	Bulk Density	Moisture Content	Soil Porosity
TT2-40	0.100U %	121.03 pcf	11.35%	0.2795
TT2-52	0.100U %	110.42 pcf	11.39%	0.3413
TT2-62	0.43%	109.08 pcf	10.95%	0.3644
TT2-72	0.24%	114.75 pcf	13.37%	0.3084
TT2-82	0.19%	115.21 pcf	14.02%	0.3038
TT4-50	0.30%	113.28 pcf	15.19%	0.3177
TT4-60	0.36%	107.78 pcf	13.73%	0.3418
TT4-70	0.64%	113.01 pcf	17.06%	0.309
TT6-30	0.98%	127.67 pcf	11.72%	0.245
TT6-40	0.22%	131.34 pcf	11.14%	0.2181

Note: pcf = pounds / cubic foot

## 3.3.3 Chemical Data

A total of 61 soil samples were collected for chemical analysis. All soil samples were analyzed for VOCs. As requested by NYSDEC, one sample collected from sludge materials was further analyzed for semivolatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), and metals. A summary of the sampling locations and depths is presented in Table 3-3.

Table 3-3
Soil Sampling Locations and Depths

Boring Number	No. of Soil Samples	Sampling Depths	Chemical Analyses
TT1	7	14', 22', 42', 52', 62',	VOCs
		72', 80'	
TT2	8	10', 22', 34', 40', 52',	VOCs
		62', 72', 82'	
TT3	8	12', 22', 37', 42', 52',	VOCs
		62', 72', 83'	
TT4	8	10', 18', 30', 36', 50',	VOCs
		60', 70', 80'	
TT5	6	32', 42', 52', 62', 72',	VOCs
		82'	
TT6	9	10', 20', 30', 35', 40',	VOCs
		50', 60', 70', 80'	
TT7	7	10', 22', 28', 42', 52',	VOCs
		62', 82'	
TT8	8	12', 22', 34', 42', 52',	VOCs
		62', 72', 82'	

Note: The sample collected at the 42-foot depth from soil boring TT-5 was also analyzed for SVOCs, PCBs and metals

#### Chemical Analysis Methods

All soil samples collected were analyzed for Target Compound List (TCL) VOCs + Freon-113 using NYSDEC Method 95-1. The sludge material sample was analyzed for TCL VOCs, TCL SVOCs, TAL Metals, and TCL PCBs (report only format).

Laboratory performance quality control (QC) was conducted to ensure the laboratory systems (instrumentation, sample preparation, analysis, data reduction, etc.) are operating within acceptable QC guidelines during data generation. Laboratory QC samples consisted of method blanks, laboratory control samples, and calibration verification samples. In addition, matrix-specific QC which includes matrix spikes, matrix spike duplicates, sample duplicates, and the use of surrogate compounds were utilized to determine the effect of the sample matrix on the data being generated – see Appendix F for copies of the laboratory QC reports.

## Chemical Data Results

Eighteen VOCs were detected in the soil around the dry well area. Tetrachloroethene (PCE) and trichloroethene (TCE) were detected most frequently and at the highest concentrations, followed by ethyl benzene, toluene and xylenes. Other VOCs detected include acetone, benzene, 2-butanone, chloroform, 1,2-dichloroethane, 1,2-dichloroethene, 2-hexanone, 4-methyl-2-pentanone, methylene chloride, 1,1,1-trichloroethane, 1,1,2-trichloroethane, 1,1,2-trichloroethan

The chemical analysis results are summarized in Table 3-4. Copies of the laboratory data reports are presented in Appendix F.

Table 3-4
Summary of VOCs Detected in Soil Samples

Sample		_						Concentra	tion of VOC	s Detect	ed in	Soil	(μ <b>g/kg</b> )	<u>,</u>	144		<del></del>		
No.	Acetone	Benzene	2-Butanone	Chloro	1,2-	1,2-DCE	Ethyl	2-Hexanone	4-Methyl-	Methylene	1,1,1-	1,1,2-	TCE	PCE	1,1,2,2-	Toluene	Xylenes	Freon	Total
				form	DCA	(total)	benzene		2-pentanone	Chloride	TCA	TCA		for s	PCA		(total)	113	VOCs
TT1-14	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT1-22	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	3 J	ND	ND	ND	ND	3
TT1-42	10 J	ND	3 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	3 J	ND	ND	ND	ND	16
TT1-52	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT1-62	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	320 J	390 J	ND	ND	ND	ND	710
TT1-72	47 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	26 J	ND	ND	ND :	ND	73
TT1-80	ND	ND	ND	ND	ND	ИD	ND	ND	ND	ND	ND	ND	ND	170 J	ND	ND	ND	ND	170
TT2-10	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT2-22	130	ND	52	ND	ND	ND	ND	14	2 J	ND	ND	ND	1 J	18	ND	ND	ND	ND	217
TT2-34	ND	, <b>N</b> D	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT2-40	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT2-52	7 J	ND	ND	ND	ND	8 J	ND	ND	ND	ND	ND	ND	2 J	4 J	ND	ND	ND	ND	21
TT2-62	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	11 J	ND	ND	ND	ND	11
TT2-72	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT2-82	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT3-12	ND	ND	. ND	ND	ND	ND	ND	ND	ND .	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT3-22	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT3-37	ND	ND	ND	ND	ND	37	ND	ND	ND	ND	ND	ND	9 J	22	ND	ND	ND	ND	68
TT3-42	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	2 J	13	ND	ND	ND	ND	15
TT3-52	ND	ND	ND	ND	ND	ND	ИD	ND	ND	ND	ND	ND	ND	570 J	ND	ND	ND	ND	570
TT3-62	21	ND	6 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	1 J	8 J	ND	ND	ND	ND	36
TT3-72	18	ND	4 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	2 J	ND	ND	ND	ND	24
TT3-83	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT4-10	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT4-18	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	22	180	ND	ND	2 J	ND	204
TT4-30	ND	ND -	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	1900	<b>57000</b> D	ND	180 J	240 J	ND	59320
TT4-36	ND	ND	ND	ND	ND	ND	26000 J	ND	ND	ND	ND	ND	160000	2800000	ND	68000 J	120000 J	ND	3174000
TT4-50	פא	ND	ND	ND	ND	ND	260 J	ND	ND	ND	ND	ND	920 J	15000	ND	450 J	1500	ND	18130

Table 3-4 (Continued)
Summary of VOCs Detected in Soil Samples

Sample			<del></del>				(	Concentra	ion of VOC	s Detect	ed in	Soil	(μ <b>g/kg</b> )	<del></del>					
No.	Acetone	Benzene	2-Butanone	Chloro	1,2-	1,2-DCE	Ethyl	2-Hexanone	4-Methyl-	Methylene	1,1,1-	1,1,2-	TCE	PCE	1,1,2,2-	Toluene	Xylenes	Freon	Total
				form	DCA	(total)	benzene		2-pentanone	Chloride	TCA	TCA	3		PCA	1 4 4 A	(total)	113	VOCs
TT4-60	ND	ND	ND	ND	ND	ND	210 J	ND	ND _	ND	ND	ND	320 J	15000	ND	220 J	1100 J	ND	16850
TT4-70	ND	ND	ND	ND	ND	ND	960 J	ND	ND	ND	ND	ND	2300	84000 D	ND	1300 J	5500	ND	94060
TT4-80	ND	ND	ND	ND	ND	ND	2000 J	ND	ND	ND	ND	ND	6800 J	180000	ND	3400 J	11000 J	ND	203200
TT5-32	ND	ND	ND	ND	ND	3800 J	3900 J	ND	ND	ND	ND	ND	39000	430000	ND	6100 J	14000 J	ND	496800
TT5-42*	ND	ND	ND	ND	ND	ND	190000 J	ND	ND	ND	ND	ND	4600000	5600000	ND	2300000	1100000	960000	14750000
TT5-52	ND	ND	ND	ND	ND	2900 J	10000 J	ND	ND	ND	ND	ND	240000	410000	ND	120000	57000	39000	878900
TT5-62	15	ND	4 J	ND	ND	9 J	4 J	ND	ND	ND	2 J	ND	220	140	ND	79	18	24	515
TT5-72	ND	ND	ND	ND	ND	ND	2 J	ND	ND	ND	ND	ND	26	56	ND	18	8 J	ND	110
TT5-82	ND	ND	ND	ND	ND	ND	2100 J	ND	ND	ND	ND	ND	14000	83000	ND	11000	13000	2600 J	125700
TT6-10	ND	ND	ND	8 J	ND	ND	ND	ND	ND	_ND	ND	ND	15 J	520	ND	ND	ND	ND	543
TT6-20	71	ND_	17 J	ND	ND	17 J	12 J	ND	8J	ND	ND	ND	740	390	ND	290	92	24 J	1661
TT6-30	38000 J	ND	17 J	ND	ND	68000 J	65000 J	ND	ND	ND	ND	ND	820000	3700000 D	ND	400000	370000	28000 J	5489017
TT6-35	23	6 J	7 J	<b>4</b> J	2 J	33	21	ND	6 J	13	ND	13	91 D	ND	4J	ND	140	56	419
TT6-40	17	ND	5 J	ND	ND	ND	2 J	3 J	4 J	ND	ND	ND	32	180	ND	13	22	ND	278
TT6-50	66	ND	ND	ND	ND	220	12 J	ND	ND	ND	ND	10 J	490JD	2400D	ND	150	70	6 J	3424
TT6-60	ND	ND	ND	ND	ND	ND	570 J	ND	ND	ND	ND	ND	7700	23000	ND	4600	3400	330 J	39600
TT6-70	11	ND	ND	ND	ND	ND	31	ND	ND .	ND	ND	ND	16	100	ND	18	15	ND	163
TT6-80	ND	ND	ND	ND	ND	ND	1100 J	ND	ND	ND	ND	ND	180 J	320 J	ND	200 J	470 J	ND	2270
TT7-10	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT7-22	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT7-28	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	1 J	ND	ND	ND	ND	ND	1
TT7-42	ND	ND	ND	ND	ND	מא	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND_	ND	ND	0
П7-52	МD	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT7-62	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT7-82	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0
TT8-12	ND	ND_	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	0_
TT8-22	13	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	13
TT8-34	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND_	ND	NO	ND	ND	ND	0

# Table 3-4 (Continued) Summary of VOCs Detected in Soil Samples

Sample		11 444	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	į,		1.		Concentrat	ion of VOC	s Detect	ed in	Soil	(μ <b>g/kg</b> )						
No.	Acetone	Benzene	2-Butanone	Chloro	1,2- DCA	1,2-DCE (total)	Ethyl benzene	2-Hexanone	4-Methyl- 2-pentanone	Methylene Chloride	1.5	1,1,2- TCA	TCE	PCE	1,1,2,2- PCA	Toluene	Xylenes (total)	Freon 113	Total VOCs
		1 F W **		101111	סקר	tour	001120110	,	2 pontanono	- Omorida	107.	1 4/.		TAME	105		_ (total)		¥005 ×
TT8-42	ND	ND	720 J	ND	ND	ND	ND	ND -	ND	ND	ND	ND	2000	7600	ND	ND	ND	ND	10320
TT8-52	ND	ND	1 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	<b>3</b> J	79	ND	ND	5 J	ND	88
TT8-62	7 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	7
TT8-72	13	ND	2 J	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	3 J	ND	ND	ND	ND	18
TT8-82	8 J	ND	ND	ND	ND	ND	ND	· ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	8

ND = Not Detected Above Sample Quantitation Limit

DCA = Dichloroethane; DCE = Dichloroethene; TCA = Trichloroethane; TCE = Trichloroethene; PCE = Tetrachloroethene; PCA = Tetrachloroethene

J = Compound meets the identification criteria, but the result is less than the sample quantititation limit and greater than zero

D = Compound identified in an analysis at a secondary dilution factor

<sup>\*</sup> Sample was also analyzed for SVOCs, PCBs and metals Results are presented in Appendix f

## 3.4 SOIL VAPOR SAMPLING

To allow future VOC vapor monitoring and sampling, nested soil vapor monitoring probes were installed in six of the eight soil borings. Monitoring probes were installed in borings TT-1, TT-3, TT-5, TT-6, TT-7 and TT-8 - see Figure 3-1 for boring locations. Depths of the monitoring probes were determined during the field program and were based on VOC field screening results and lithology. Probes were targeted at depths where high concentrations of VOCs were detected, and where fine-grained soil materials were identified. The soil vapor samples were analyzed using a method similar to EPA Method 8260. A summary of the soil vapor sampling locations and depths is presented in Table 3-5.

Table 3-5
Soil Vapor Sampling Locations and Depths

Boring Number	Soil Vapor Sampling Depths	Chemical Analyses
TT1	62', 72'	VOCs
TT3	52', 62', 72'	VOCs
TT5	37', 62', 73'	VOCs
TT6	29', 38', 60', 70'	VOCs
TT7	34', 60'	VOCs
TT8	42', 62'	VOCs

Soil vapor sample collection procedures are presented in Section 3.4.1, with the soil vapor data presented in Section 3.4.2.

## 3.4.1 Soil Vapor Sample Collection Procedures

## Installation of Soil Vapor Probes

Each soil vapor probe consisted of 1/4" polyethylene tubing with a soil vapor inlet located at the down-hole end of the tubing and a sample collection port at the surface end. The construction procedure for each of the nested soil vapor probes were as follows:

- 1. Bentonite chips were poured through the center of the drill pipe to seal off the saturated zone and the vadose zone below the deepest probe location;
- 2. The soil vapor probe was installed into the borehole. Each probe was set within a 2-foot thick filter pack consisting of #3 coarse sand. The filter pack allows free migration of vapors from the surrounding formations into the probe inlets. Three inches of #00 fine-grained sand, that serves as a transition sand, were placed above and below the filter pack.
- 3. One foot of granular bentonite was placed above the #00 fine sand. Bentonite chips were then added up to the next soil vapor probe location and hydrated;
- 4. The drill casing was pulled to the next probe interval. Procedures 2 through 4 were repeated for each soil vapor probe depth location.
- 5. Following installation of the final soil vapor probe, all probes were capped, labeled and secured within a well box. The well box was set within a concrete pad and locked.

Soil vapor probe construction diagrams are presented in Appendix D.

#### Soil Vapor Sampling

Soil gas sampling and analysis was conducted approximately two days after installation of the probes. Prior to sample collection, a purge test was performed to evaluate the appropriate volume of gas to be purged. The purge test consisted of extracting 1, 2, 4, 6, 8 and 10 times the polyethylene tubing and sample probe volume prior to analysis. Analytical results associated with each purge volume was plotted to determine the optimum purge volume for the


remaining samples of each location. Based on the results of the purge tests, seven to ten purge volumes were used as the optimum purge volume for all subsequent tests.

Soil vapor samples were collected using a soil vapor sampling system shown in Figure 3-2. Soil vapor samples were collected in a glass sampling bulb fitted with Teflon stopcocks and a viton rubber sampling port. The bulb was connected to a vacuum gauge, flowmeter and portable sampling pump. During the sampling, a pentane-soaked kimwipe was exposed to the sampling train. The detection of any pentane in the sample would have indicated the intrusion of ambient air into the sampling train, thus invalidating the results of that sample. Once the sampling system was determined to be leak-tight, the bulb was opened, and flow was maintained for seven to ten purge volumes. The stopcocks were then closed and the sample was retained within the container.

As an additional quality control measure, five isotopically-labeled surrogate compounds were added through the septum into the sampling bulb. The recovery of more than 75% of these compounds demonstrates that the bulbs have remained leak-tight up to the actual analysis. All surrogate recoveries exceeded 75% for this project.

Soil vapor samples were analyzed using a Hewlett Packard model 5890 Gas Chromatograph (GC) interfaced with a Hewlett Packard model 5972 mass spectrometer. These detectors were used to analyze soil vapor samples for VOCs using a method similar to EPA Method 8240. The practical quantitation limits (PQLs) for the VOCs were one microgram per liter ( $\mu$ g/L). Instrument detection limits were about 0.1  $\mu$ g/L. The targeted VOCs are listed in Table 3-6.

## FIGURE 3-2 SCHEMATIC OF SOIL GAS SAMPLING TRAIN



NOT TO SCALE

Table 3-6
Target Volatile Organic Compound List

Vinyl Chloride	1,2-Dichloroethane	trans-1,3-dichloropropene
Bromomethane	1,1,1-Trichloroethane	1,1,2-Trichloroethane
Chloroethane	Carbon Tetrachloride	Dibromochloromethane
1,1-Dichloroethene	Benzene	Bromoform
Methylene Chloride	Trichloroethene	Toluene
1,2-Dichloroethene	1,2-Dichloropropane	Tetrachloroethene
1,1-Dichloroethane	Bromodichoromethane	Chlorobenzene
Chloroform	cis-1,3-dichloropropene	Ethylbenzene
Total Xylenes	Styrene	1,1,1,2-Tetrachloroethane
1,1,2,2-Tetrachloroethane	Freon-11	Freon-12
Freon-113		

Two rounds of soil vapor sampling was conducted at selected vapor probes to ensure that VOC concentrations detected were representative of equilibrium subsurface conditions. Two rounds of sampling were conducted at all vapor probes from boring TT6 (vapor probes TT6-29, TT6-38, TT6-60, and TT-70). The second round of sampling was conducted approximately 6 days after the first round of sampling.

## 3.4.2 Soil Vapor Data

Seventeen VOCs were detected in the soil vapor around the dry well area. Similar to the soil sampling data, tetrachloroethene (PCE) and trichloroethene (TCE) were detected most frequently and at the highest concentrations. Other VOCs detected include 1,2-DCE, toluene, benzene, chloroform, 1,1-dichloroethane, 1,1-dichloroethene, ethylbenzene, methylene chloride, 1,1,1-trichloroethane, 1,1,1,2-tetrachloroethane, xylenes, vinyl chloride, Freon-11, Freon-12, and Freon-113.

The soil vapor analysis data are summarized in Table 3-7. Copies of the laboratory data reports are presented in Appendix E.

Table 3-7
Summary of VOCs Detected in Soil Vapor Samples

			T.			Cor	ncentration	of VO	Cs Det	ected in	Soil V	apor (μ	g/L)		New A			
Sample No.	Benzene	Chloro form	DCA	1,1-DCE	1,2-DCE (total)	Ethyl benzene	Methylene Chloride	TCA	TCE	PCE	PCA	Toluene	Xylenes (total)	Vinyl Chloride	Freon 11	Freon 12	Freon 113	Total VOCs
TT1-62	ND	ND	ND	ND	4.2	ND	ND	ND	6.3	6.5	ND	1.9	ND	0.6	ND	ND	6.6	26.1
TT1-72	ND	ND	ND	ND	15	ND	ND	ND	1.8	2.3	ND	ND	ND	4.3	ND	ND	12	35.4
TT3-52	ND	ND	ND	ND	4.4	ND	ND	ND	2.5	4.7	ND	1	ND	ND	ND	ND	2.3	14.9
TT3-62	ND	ND	ND	ND	ND	ND	ND	ND	1	2.5	ND	ND	ND	ND	ND	ND	ND	3.5
TT3-72	ND	ND	ND	ND	ND	ND	ND	ND	1	1.6	ND	0.6	ND	ND	ND	ND	1.1	4.3
TT5-37	6.8	1.9	ND	72	1849	24	ND	145	11214	3410.1	1.3	1673	52	4.9	6.8	62.2	5693	24216
TT5-62	4.5	ND	ND	2.5	166	ND	ND	13	6296	2937.7	ND	1498	ND	ND	ND	ND	104	11021.7
TT5-73	0.9	ND	ND	ND	32	24	ND	2.1	1678	1685.2	ND	615	61	ND	ND	ND	25	4123.2
TT6-29	1.8	0.5	ND	52	1911	2.6	0.5	5.3	778	592	ND	132	ND	9.6	ND	ND	361	3846.3
TT6-29r	1.6	ND	ND	63	2744	6.1	0.6	4	886	923	ND	150	ND	8.4	ND	ND	311	5097.7
TT6-38	10	7.8	8.7	54	468	3.9	41.9	23	3064	720	ND	351	1.8	9.7	5.1	ND	2714	7482.9
TT6-38r	9.8	6.6	8.1	ND	404	3.2	27.5	26	3643	544	ND	168	ND	7.1	ND	ND	3492	8339.3
TT6-60	ND	ND	ND	0.6	19	27	ND	ND	141	33	ND	ND	ND	ND	ND	ND	16	236.6
TT6-60r	0.6	ND	ND	ND	49	3.4	ND	0.7	663	399	ND	125	ND	ND	ND	ND	ND	1240.7
TT6-70	ND	ND	ND	ND	45	ND	ND	ND	91	33	ND	16	ND	ND	ND	ND	13	198
TT6-70r	0.5	ND	ND	ND_	23	ND	ND	ND	388	85	ND	41	ND	ND	ND	ND	3.5	541
TT7-34	ND	ND	ND	ND	ND	ND	ND	ND	2.7	2.4	ND	1.1	ND	ND	ND	ND	ND	6.2
TT7-60	ND	ND	ND	ND	ND	ND	ND	ND	3.3	3.3	ND	1.1	ND	ND	ND	ND	0.8	8.5
TT8-42	ND	ND	ND	ND	449	ND	ND	1.2	447	127	ND	ND	ND	2.6	ND	ND	86	1112.8
TT8-42d	ND	ND	ND	ND	368	ND	ND	1	325	66	ND	ND	ND	2.1	ND	ND	72	834.1
TT8-62	ND	ND	ND	ND	0.9	ND	ND	ND	1.2	0.9	ND	ND	ND	ND	ND	ND	0.7	3.7
TT8-62d	ND	ND	ND	ND	0.6	ND	ND	ND	1.2	1	ND	ND	ND	ND	ND	ND	0.8	3.6

ND = Not Detected Above Reporting Limit of 0.5  $\mu$ g/L

DCA = 1,1-Dicholorethane; DCE = Dichloroethene; TCA = 1,1,1-Trichloroethane; TCE = Trichloroethene; PCA = 1,1,1,2-Tetrachloroethane; PCE = Tetrachloroethene

r = rebound


d = duplicate

## 3.5 EXTENT OF VOC PLUME


The soil matrix and soil gas data indicate that the highest concentrations of total VOCs were in borings TT-4, TT-5, and TT-6, located in the immediate vicinity of the dry wells. VOC concentrations in the soil decrease in each direction away from the dry well area. The estimated lateral extent of the VOC plume is shown in Figure 3-3.

VOCs were detected in the dry well area from the near surface to first groundwater at 80 feet bgs. The highest VOCs in these borings were detected in silty sands and clayey sands located between 30 and 40 feet bgs. Figures 3-4 and 3-5 are cross-sections that illustrate the subsurface geology in the dry well area.


## FIGURE 3-3 ESTIMATED LATERAL EXTENT OF VOC IMPACTED SOIL



## FIGURE 3-4 CROSS SECTION A-A'



## FIGURE 3-5 CROSS SECTION B-B'



## **Section 4**


## **Current VOC Mass Estimation**

The current mass of VOCs present in the subsurface soils was calculated using the analytical results of soil samples collected in August 1998. As presented in Section 3, eight soil borings (TT-1 through TT-8) were drilled and sampled to obtain current analytical data for estimation of VOC mass. A total of 61 soil samples were collected and analyzed for VOCs as summarized in Table 3-2 - see Section 3. Analytical results of soil samples collected from the borings indicate that the highest concentrations of VOCs are limited to the immediate vicinity of the dry wells.

## 4.1 VOC MASS CALCULATIONS

The current mass of VOCs present in the subsurface soils was determined by calculating the average concentration of each compound (i.e., PCE, TCE, 1,2-DCE, etc.) present in the area surrounding the former dry wells. The average concentration of each compound was calculated for each 5-foot depth interval from the surface to groundwater. Further, the lateral distribution of chemicals was also calculated based on the spatial distance from the former dry wells using the August 1998 chemical data. Overall, the average concentration of each chemical compound was calculated for 17 vertical layers in four lateral sections surrounding the former dry wells. The division of the four lateral sections of varying VOC concentrations is shown in Figure 4-1. The calculated average chemical concentration for each 5-foot depth interval within each lateral area is presented in Tables 4-1 through 4-4.

Figure 4-1
Mass Distribution Areas



## LEGEND

- x Existing extraction well
- ⊕ Soil boring installed by Tetra Tech
- O Dry Well

Table 4-1 VOCs Mass Estimate for Area 1

						-		UCS Mas	3 L3(III	iate ioi	Aicu i							
	pth (ft) bgs.	Soil USC	PCE <sup>(1)</sup> (ug/kg)	TCE <sup>[1]</sup> (ug/kg)	1,2-DCE <sup>[1]</sup> (ug/kg)	Toluene <sup>[1]</sup> (ug/kg)	Ethyl Benzene <sup>(1)</sup> (ug/kg)	Xylenes <sup>[1]</sup> (ug/kg)	Bulk Density (pcf)	Area (ft²)	Soil Volume (ft³)	Soil Dry Weight (lbs.)	PCE Mass (lbs.)	TCE Mass (lbs.)	1,2-DCE Mass (lbs.)	Toluene Mass (lbs.)	Ethyl Benzene Mass (lbs.)	Xylenes Mass (lbs.)
1	0-5	sw	520	15	0	О	0	0	111 4	1,116	6.E+03	6 22E+05	0.3	0 01	0.0	0.0	0.0	0.0
(	6-10	sw	520	15	0	0	0	0	111.4	1,116	6 E+03	6.22E+05	0.3	0 01	0.0	0.0	0.0	0.0
1	1-15	sw	630	203	5	145	6	46	111 4	1,116	6 E+03	6 22E+05	0.4	0.13	0.0	, 0 1	0.0	0.0
1	6-20	GW	740	390	17	290	12	92	111 4	1,116	6 E+03	6.22E+05	0.5	0 24	0.0	02	0.0	0 1
2	1-25	sw	1,850,370	410,195	34,009	245,145	32,596	185,046	111 4	1,116	6 E+03	6 22E+05	1150 2	254.98	21 1	152 4	20 3	115 0
	6-30	sw/sc	3,700,000	820,000	68,000	490,000	65,000	370,000	1119	1,116	6 E+03	6 24E+05	<i>)</i> 2310.3	512 01	425	306 0	40 6	231 0
_	1-35	SC	1,850,090	410,016	34,017	245,007	32,511	185,070	126 7	1,116	6.E+03	7.07E+05	1308.0	289 88	240	173 2	23 0	130 8
3	6-40	CL	180	32	33	13	21	140	126 7	1,116	6 E+03	7 07E+05	0 1	0.02	0.0	00	0.0	0 1
4	1-45	SC	1,290	261	0	82	17	105	126.7	1,116	6 E+03	7.07E+05	0.9	0.18	0.0	01	0.0	0 1
4	6-50	sw/sc	2,400	490	220	150	12	70	111 9	1,116	6 E+03	6 24E+05	15	0 31	0 1	01	0.0	0 0
5	1-55	sw/sc	12,700	4,095	0	2,375	291	1,735	111.9	1,116	6 E+03	6 24E+05	7.9	2 56	0.0	15	0 2	1 1
5	6-60	sw	23,000	7,700	0	4,600	570	3,400	108 4	1,116	6. <b>E</b> +03	6 05E+05	13 9	4 66	0.0	28	03	2 1
6	1-65	sw	11,550	3,858	0	2,309	287	1,708	108 4	1,116	6 E+03	6 05E+05	70	2 33	0.0	1 4	0 2	10
6	6-70	sw	100	16	0	18	3	15	113.9	1,116	6 E+03	6 36E+05	0 1	0 01	0.0	0.0	0.0	0.0
7	1-75	sw	210	98	0	109	552	243	113.9	1,116	6.E+03	6.36E+05	0.1	0 06	00	01	0.4	0 2
7	6-80	sw	320	180	0	200	1,100	470	113 9	1,116	6.E+03	6.36E+05	0.2	0 11	00	0 1	07	03
8	1-85	sw	320	180	0	200	1,100	470	113.9	1,116	6.E+03	6.36E+05	0.2	0 11	0.0	0 1	07	03
											Total	1.09E+07	4,802	1,068	88	638	86	482

Numbers in bold are actual sampling results, others are estimated

Total VOCs = 7,164 lbs

Table 4-2

**VOCs Mass Estimate for Area 2** 

								VOC3 IVIG			, ou =							
	epth (ft) bgs.	Soil USC	PCE <sup>(1)</sup> (ug/kg)	TCE <sup>(1)</sup> (ug/kg)	1,2-DCE <sup>[1]</sup> (ug/kg)	Toluene <sup>[1]</sup> (ug/kg)	Ethyl Benzene <sup>[1]</sup> (ug/kg)	Xylenes <sup>[1]</sup> (ug/kg)	Bulk Density (pcf)	Area (ft²)	Soil Volume (ft³)	Soil Dry Weight (lbs.)	PCE Mass (lbs.)	TCE Mass (lbs.)	1,2-DCE Mass (lbs.)	Toluene Mass (lbs.)	Ethyl Benzene Mass (Ibs.)	Xylenes Mass (lbs.)
	0-5	sw	500	20	5	5	5	10	111 4	977	5 E+03	5 44E+05	03	D 01	0.0	0.0	0.0	0 0
-	6-10	sw	700	50	10	10	10	20	111 4	977	5 E+03	5 44E+05	0 4	0 03	0.0	0.0	0.0	0 0
-	11-15	SW	1,000	100	20	20	20	50	111.4	977	5 E+03	5 44E+05	0 5	0 05	00	0.0	0.0	0.0
-	16-20	GW	1,500	150	35	35	35	75	111 4	977	5 E+03	5.44E+05	0.8	0 08	0.0	0.0	0.0	0.0
-	21-25	sw	2,000	200	50	50	50	100	111 4	977	5 E+03	5 44E+05	1 1	0 11	0.0	0.0	0.0	0 1
1	26-30	SW/SC	216,000	19 600	1,925	3,075	1,975	7,050	1119	977	5 E+03	5 47E+05	118 1	10 71	1.1	17	11	3 9
	31-35	SC	430,000	39,000	3,800	6,100	3,900	14,000	126 7	977	5 E+03	6 19E+05	( 266 1	24 14	2 4	38	2 4	8 7
-	36-40	CL	3 015.000	2,319,500	3,575	1,153,050	96,950	557,000	126 7	977	5 E+03	6.19E+05	1866.1	1435 61	<b>2</b> 2	713 7	60 0	344 7
_	41-45	sc	5,600,000	4,600,000	3,350	2,300,000	190,000	1,100,000	126.7	977	5 E+03	6 19E+05	3466 0	2847 08	2 <b>1</b>	1423 5	117 6	680 8
	46-50	<b>SW</b> /SC	3,005,000	2,420,000	3,125	1,210,000	100,000	578,500	111.9	977	5.E+03	5.47E+05	1642 6	1322 85	1 7	661 4	54 7	316 2
-	51-55	SW/SC	410,000	240,000	2,900	120,000	10,000	57,000	1119	977	5 E+03	5 47E+05	224 1	131 19	16	65 6	5 5	31 2
1	56-60	sw	205.070	120,110	1,455	60,040	5,002	28,509	108 4	977	5 E+03	5.30E+05	108 6	63 60	0.8	31 8	26	15 1
	61-65	SW	140	220	9	79	4	18	108 4	977	5 E+03	5 30E+05	0 1	0 12	0.0	,00	0.0	0 0
	66-70	SW	98	123	5	49	3	13	113 9	977	5 E+03	5.56E+05	0 1	0 07	0 0	0 0	0.0	0 0
	71-75	SW	56	26	0	18	2	8	113.9	977	5 E+03	5 56E+05	0 0	0 01	0.0	0 0	0.0	0 0
1	76-80	SW	41.528	7,013	0	5,509	1,052	6,504	1139	977	5.E+03	5 56E+05	23 1	3 90	0 0	3 1	0.6	3 6
_L	81-85	sw	83,000	14,000	0	11,000	2,100	13,000	113.9	977	5.E+03	5.56E+05	46.2	7.79	0.0	6.1	12	7 2
										1	Total	9.50E+06	7,764	5,847	12	2,911	246	1,412

Numbers in bold are actual sampling results, others are estimated

Total VOCs = 18,191 lbs

Table 4-3
VOCs Mass Estimate for Area 3

								33 E3UII									
Depth (ft) bgs.	Soil USC_	PCE <sup>III</sup> (ug/kg)	TCE <sup>(1)</sup> (ug/kg)	1,2-DCE <sup>[1]</sup> (ug/kg)	Toluene <sup>[1]</sup> (ug/kg)	Ethyl Benzene <sup>[1]</sup> (ug/kg)	Xylenes <sup>[1]</sup> (ug/kg)	Bulk Density (pcf)	Area (ft²)	Soil Volume (ft³)	Soil Dry Weight (lbs.)	PCE Mass (lbs.)	TCE Mass (lbs.)	1,2-DCE Mass (lbs.)	Toluene Mass (lbs.)	Ethyl Benzene Mass (lbs.)	Xylenes Mass (lbs.)
0-5	sw	500	<b>2</b> 0	20	20	20	20	111 4	1,814	9.E+03	1.01E+06	0.5	0.02	0.0	0.0	0.0	0.0
6-10	sw	700	50	50	50	50	50	111,4	1,814	9.E+03	1.01E+06	0.7	0.05	0.1	0.1	0.1	0.1
11-15	sw	1,000	100	100	100	100	100	111.4	1,814	9.E+03	1.01E+06	1.0	0.10	0.1	0.1	0.1	0.1
16-20	GW	1,500	150	150	150	150	300	111.4	1,814	9.E+03	1.01E+06	1.5	0 15	0.2	0.2	0.2	0.3
21-25	sw	2.000	200	200	200	200	500	111.4	1,814	9.E+03	1.01E+06	2.0	0.20	0.2	0.2	0.2	0 5
26-30	sw/sc	2,500	3.600	1,000	2.500	1,000	2,500	111.9	1,814	9.E+03	1.01E+06	2.5	3.65	1.0	2.5	1.0	2.5
31-35	sc	712,500	41,800	18,909	125,553	18,205	99,535	126.7	1,814	9.E+03	1.15E+06	818.8	48.04	21.7	144.3	20.9	114.4
36-40	CL	1,400,000	80,000	16.455	69,777	16,103	56,768	126.7	1,814	9.E+03	1.15E+06	1608.8	91.93	18 9	80.2	18.5	65.2
41-45	sc	52,000	14,000	14,000	14,000	14,000	14,000	126.7	1,814	9.E+03	1.15E+06	59.8	16.09	16 1	16.1	16 1	16.1
46-50	sw/sc	26,270	7,028	7,028	7,028	7,038	7,140	111.9	1,814	9.E+03	1.01E+06	26.7	7.13	7,1	7.1	7.1	7 2
51-55	sw/sc	540	55	55	55	76	280	111.9	1,814	9.E+03	1.01E+06	0.5	0.06	0.1	0.1	0.1	03
56-60	sw	390	108	53	60	64	180	108.4	1,814	9.E+03	9.83E+05	0.4	0.11	0.1	0 1	0.1	0.2
61-65	sw	240	160	52	64	52	80	108.4	1,814	9.E+03	9.83E+05	0.2	0.16	0 1	0.1	0 1	0 1
66-70	sw	190	107	52	58	52	67	113.9	1,814	9.E+03	1.03E+06	0.2	0.11	0 1	0.1	0.1	0 1
71-75	sw	140	53	53	53	53	53	113.9	1,814	9.E+03	1.03E+06	0.1	0.05	0 1	01	01	0 1
76-80	sw	200	51	51	51	51	58	113,9	1,814	9.E+03	1.03E+06	0.2	0.05	0.1	0.1	0.1	0.1
81-85	sw	120	51	51	51	51	58	113,9	1,814	9.E+03	1.03E+06	0.1	0.05	0 1	0.1	0.1	0.1
									l	Total	1.76E+07	2,524	168	66	251	65	207

<sup>[1]</sup> Numbers in bold are actual sampling results, others are estimated.

Total VOCs = 3,281 lbs

Table 4-4
VOCs Mass Estimate for Area 4

	th (ft) gs.	Soil USC	PCE <sup>[1]</sup> (ug/kg)	TCE <sup>(1)</sup> (ug/kg)	1,2-DCE <sup>(1)</sup> (ug/kg)	Toluene <sup>(1)</sup> (ug/kg)	Ethyl Benzene <sup>(1)</sup> (ug/kg)	Xylenes <sup>[1]</sup> (ug/kg)	Bulk Density (pcf)	Area (ft²)	Soll Volume (ft³)	Soll Dry Weight (lbs.)	PCE Mass (lbs.)	TCE Mass (lbs.)	1,2-DCE Mass (lbs.)	Toluene Mass (lbs.)	Ethyl Benzene Mass (lbs.)	Xylenes Mass (lbs.)
	-5	sw	180	22	О	0	0	0	1114	1,116	6.E+03	6.22E+05	0 1	0 01	0.0	0.0	0.0	0 0
6	10	sw	180	22	0	0	0	0	111 4	1,116	6 E+03	6 22E+05	0 1	0 01	00	0.0	0.0	0 0
11	-15	sw	180	22	0	o	0	0	1114	1,116	6 E+03	6 22E+05	0 1	0 01	0.0	0.0	0.0	<b>0</b> 0
16	-20	GW	180	22	0	0	9	a	1114	1,116	6.E+03	6 22E+05	0 1	0.01	0.0	0.0	0.0	0.0
21	-25	sw	28,590	961	c	0	О	0	111 4	1,116	6.E+03	6 22E+05	178	0 60	0.0	. 00	0.0	0.0
26	-30	sw/sc	57,000	1,900	0	180	0	240	1119	1,116	6 E+03	6 24E+05	35 6	1 19	0.0	0.1	0.0	0 1
31	-35	sc	1,428.500	80.950	0	34.090	13,000	60,120	126.7	1,116	6 E+03	7.07E+05	/ 1009 9	57.23	0 0	24 1	92	42 5
. 36	-40	CL	2,800,000	160,000	0	68,000	26,000	120,000	126 7	1,116	6 E+03	7.07E+05	( 1979 6	113.12	0.0	48 1	18 4	84 8
_ 41	-45	sc	1,407,500	80,460	О	34,225	13,130	60,750	126 7	1,116	6 E+03	7.07E+05	995 1	56 88	0.0	24 2	93	42 9
46	-50	sw/sc	15,000	920	0	450	260	1,500	1119	1,116	6 E+03	6.24E+05	94	0 57	0.0	03	0 2	0 9
51	-55	sw/sc	15,000	620	0	335	235	1,300	1119	1,116	6 E+03	6 24E+05	94	0 39	٥٥	0 2	0 1	0.8
56	-60	sw	15,000	320	0	220	210	1,100	108 4	1,116	6 E+03	6.05E+05	9 1	0 19	0.0	0 1	0 1	0 7
61	-65	sw	49,500	1,310	0	760	585	3,300	108 4	1,116	6 <b>E</b> +03	6 05E+05	29 9	0 79	0.0	0.5	0.4	2 0
66	-70	sw	84,000	2,300	0	1,300	960	5,500	113.9	1,116	6 <b>E</b> +03	6.36E+05	53.4	1.46	00	0.8	0.6	3 5
71	-75	SW	132,000	4,550	0	2,350	1,480	8,250	113'9	1,116	6.E+03	6.36E+05	83 9	2.89	0.0	15	09	5 2
76	-80	sw	180,000	6,800	0	3,400	2,000	11,000	113.9	1,116	6.E+03	6 36E+05	114 4	4 32	0.0	2 2	13	70
81	- <b>8</b> 5	sw	180,000	6,800	0	3,400	2,000	1,100	113.9	1,116	6.E+03	6.36E+05	114.4	4 32	0.0	22	13	0 7
											Total	1.09 <u>E+</u> 07	4,462	244	0	104	42	191

<sup>[1]</sup> Numbers in bold are actual sampling results, others are estimated

Total VOCs = 5,043 lbs

In order to quantify and calculate the mass of VOCs, the following assumptions were made:

- 1. The soil impacted with VOCs is cylindrical in shape encompassing a diameter of 80 feet with the center at extraction well VW-14 see Figure 4-1;
- 2. The dry well vicinity was divided into 4 areas for the purpose of VOC mass estimation. The four areas are shown in Figure 4-1. The vertical soil concentration profiles of each area can be represented by specific analytical results:
  - Area I Estimation based on soil data collected from boring TT-6,
  - Area 2 Estimation based on soil data collected from boring TT-5,
  - Area 3 Estimation based on an approximation of soil data collected from borings TT-4, TT-5, and TT-6 for soils greater than 40 feet bgs, in addition to data collected from Dry Well 3 in June 1997 for soils less than 40 feet bgs,
  - Area 4 Estimation based on soil data collected from boring TT-4;
- 3. The vadose zone depth of 85 feet bgs was used for estimating the mass of VOCs.

After determining the average VOC concentration (C) for each compound, the total VOC mass was calculated by applying (C) to the corresponding soil volume and associated soil bulk density. The equation for soil VOC mass calculation is as follows:

$$VOC\ Mass = 10^{-9}\ CV\rho_h$$

#### Parameters:

 $C = Soil VOC Concentration (\mu g/kg)$ 

 $V = Soil Volume (ft^3)$ 

 $\rho_b$  = Soil Bulk Density (lbs/ft<sup>3</sup>)

## 4.2 CURRENT VOC MASS DISTRIBUTION

Based on chemical data, mass calculations of VOCs were conducted and summarized for each of the four areas in Tables 4-1 through 4-4. Table 4-5 presents a summary of total mass estimates of VOCs for each area. The current distribution of VOC mass for each of the four areas is summarized below.

## <u>Area 1</u>

The mass of VOCs for Area 1 surrounding dry well #1 is approximately 7,200 lbs. The mass of 99% of the VOCs is located from 20 to 35 feet bgs. Note that the nearest extraction well VW-13 has a screen interval from 45 to 85 feet bgs.

#### Area 2

The mass of VOCs for Area 2 surrounding dry well #2 is approximately 18,000 lbs, and represents more than half of the total remaining mass. The mass of 96% of the VOCs is located from 31 to 55 feet bgs. There is no active extraction well within this area.

Table 4-5
Summary of VOC Mass Estimate

Mass of VOC Compound in pounds (lbs.)					VOC Mass		
Area	PCE	TCE	1,2- DCE	Toluene	Ethyl benzene	Xylenes	Subtotal by Area (lbs.)
1	4,800	1,100	88	640	90	480	7,200
2	7,800	5,800	12	2,900	250	1,400	18,000
3	2,500	170	66	250	65	210	3,300
4	4,500	240	0	100	42	190	5,100
VOC Mass Subtotal by Compound (lbs.)	20,000	7,300	170	3,900	450	2,300	34,000 lbs. Total VOC Mass

## Area 3

The mass of VOCs for Area 3 surrounding dry well #3 is approximately 3,300 lbs.

#### Area 4

The mass of VOCs for Area 4 is approximately 5,100 lbs. The mass of 90% of the VOCs is located from 31 to 45 feet bgs. Additionally, there is no active extraction well within this area.

## Total VOC Mass

As presented in Table 4-5, the total estimated mass of VOCs currently remaining in the soils located in the immediate vicinity of the dry wells is 34,000 lbs. The VOC mass remaining includes approximately 20,000 lbs of PCE, 7,300 lbs of TCE, 170 lbs of 1,2-DCE, 3,900 lbs of toluene, 440 lbs of ethylbenzene, and 2,300 lbs of xylenes.

In addition to the current VOC mass, a calculation of the VOC mass extracted by the SVE system from 1991 through 1998 was also determined. The total VOC mass extracted was determined by reviewing all historical operation and monitoring records. Based on the concentrations of VOCs in the airstream and volume of air extracted, an estimated 38,000 lbs of VOCs were removed from 1991 through 1998.

Based on the calculated extraction of 38,000 lbs of VOCs from 1991 through 1998 and an additional 34,000 lbs of VOCs that currently remain in place, an estimated total of 71,000 lbs of VOCs are estimated to have been in the subsurface soil prior to operation of the SVE system.

## Vertical Distribution of VOC Mass


To determine the vertical distribution of VOC mass, total VOC concentrations at the site were estimated in 5-foot depth intervals for each of the four areas (Areas 1, 2, 3, and 4). Vertical concentration profile data was calculated based on VOC analytical data collected in August 1998. A summary of total VOC vertical profile concentrations at each depth interval for the four areas are presented in Table 4-6.

As shown in Table 4-6, most of the remaining VOC mass is located between 26 and 50 feet bgs. Based on site geology, the VOC mass appears to be located primarily within fine-grained soil zones. Figure 4-2 presents a three-dimensional (3-D) plot of the current VOC mass distribution in the soil.

Table 4-6
Summary of Vertical Mass Profiles for Total VOCs

Depth	Vertical Mass Profiles of Total VOCs by Area (lbs.)					
(ft)	Area 1	Area 2	Area 3	Area 4		
0-5	0.3	0.3	0.5	0.1		
6-10	0.3	0.4	1.2	0.1		
11-15	0.6	0.6	1.5	0.1		
16-20	1.0	0.9	2.6	0.1		
21-25	1700	1.3	3.3	18		
26-30	3400	137	13	37		
31-35	1900	310	1200	1100		
36-40	0.22	4400	1900	2200		
41-45	1.3	8500	140	1100		
46-50	2.0	4000	62	11		
51-55	13	460	1.2	11		
56-60	24	220	1.0	10		
61-65	12	0.2	0.8	34		
66-70	0.1	0.2	0.7	60		
71-75	0.9	0.0	0.6	94		
76-80	1.4	34	0.7	130		
81-85	1.4	68	0.6	123		
Total VOC Mass by Area (lbs.)	7100	18000	3300	4900		

Figure 4-2 Mass Distribution of Remaining VOC In The Dry Well Area



## 4.3 ASSUMPTIONS OF VOC MASS ESTIMATE

The VOC mass estimate for each area was based on limited data and the assumptions used in the calculations. The assumptions included an estimate the size of the area impacted with VOCs. In order to provide a conservative estimate of the current VOC mass, the following two items were assumed:

- 1. The VOC plume is contained within a circular area with a diameter of 80 feet, where high VOC concentrations are present.
- 2. The soil concentrations in the each of the 4 areas were assumed to be uniform for each depth interval. The concentrations in each interval were represented by a high concentration profile at the dry wells.

Based on the analytical data, the amount of VOC mass represents a conservative estimate. Further, if the circular area was assumed to have a diameter of 60 feet (instead of 80 feet), the estimate of remaining VOCs would be 20,000 lbs or 40% less.

## Section 5

# Assessment of Current SVE System

## 5.1 TECHNICAL APPROACH

The objective of this evaluation is to determine whether the existing SVE system is capable of reducing volatile organic compound (VOC) concentrations to below soil cleanup levels established by NYSDEC in the Record of Decision (ROD).

The existing configuration of the SVE system was evaluated to determine if RSCOs can be attained without modifications to the system (i.e., without adding new wells or equipment). Air flow was modeled using the AIR3D numerical model developed by the United States Geological Survey (USGS). Data from the air flow model was then input into the VT3D numerical model to calculate VOC mass transport. The VOC mass transport model was used to predict VOC removal rates and the total mass of VOCs that will be removed using the existing system. A description of the existing SVE system and its standard operating parameters is presented in Section 5.2. The air flow modeling results are discussed in Section 5.3, and the VOC mass transport modeling results are presented in Section 5.4.

## 5.2 DESCRIPTION OF CURRENT SVE SYSTEM

The SVE system is located at the southeast corner of the Great Neck facility's main building and operated from January 1994 until June 15, 1998. During this period, approximately 37,723 pounds of VOCs were recovered from wells VW-1, VW-2, VW-13 and VW-14. The depths and screened intervals for the four wells are summarized in Table 5-1.

Table 5-1
Summary of Existing Extraction Wells

Extraction Well	Well Depth (feet)	Screened Interval (feet)
VW1	91	51 - 91
VW2	45	24 - 45
VW13	85	45 - 85
VW14	40	20 - 40

In addition to the extraction wells, ten vapor wells were used for monitoring VOC concentrations in soil vapor. The depths and screened intervals for the vapor monitoring wells are summarized in Table 5-2.

Table 5-2
Summary of Existing Vapor Monitoring Wells

Vapor Monitoring Well	Well Depth (feet)	Screened Interval (feet)
VW3	93	73 - 93
VW4	90	60 – 90
VW5	93	63 – 93
VW6	90	70 - 90
VW7	47	37 – 47
VW8	87	67 – 87
VW9	90	70 – 90
VW10	90	70 – 90
VW11	90	70 - 90
VW12	90	70 – 90

Figure 5-1 presents an overview of the extraction wells, monitoring wells and the current lateral extent of the VOC plume.

Each of the four extraction wells are connected to a common manifold via 4-inch diameter, Schedule 40 PVC piping. From the manifold, the piping is connected in parallel to two centrifugal blowers. VOC vapors are treated using a catalytic oxidizer with a wet scrubber for emission control. Figure 5-2 shows a schematic of the SVE system currently installed at the site.

Prior to shutdown, the SVE system was operating at the following parameters:

- Soil vapor flow rate\*: 150 to 300 scfm
- Vacuum on suction side of blower: 20 to 25 inches of water
- Continuous operation with ability to take individual vent wells on and off-line
- Influent air temperature: 70°F to 74°F
- Effluent air temperature: 120°F to 140°F at blower
- Total organic vapor concentration: Up to 10,000 ppm of total VOCs


## 5.3 AIR FLOW MODELING

To determine whether the existing system will meet the remedial goals established by the ROD, the air flow and vacuum distribution were evaluated across the dry well area. The AIR3D numerical air flow code was utilized to simulate the effectiveness of the existing vapor extraction system under different system configurations.

The locations, depths, screened intervals of the existing wells, and the extraction flow rates, were input into AIR3D to model the VOC capture zone and soil air flushing frequency. Actual operating data obtained during the SVE pilot test and system operation was used to calibrate the model and verify calculated flow rates and area of influence.

<sup>\*</sup> The design capacity of the existing SVE system is 400-500 scfm, as outlined in the SVE IRM work plan

# FIGURE 5-1 OVERVIEW OF EXISTING EXTRACTION WELLS



## 5.3.1 Model Domain

The model domain covers an area of 36,000,000 square feet (6000 by 6000 feet) and is centered at extraction well VW-14. A fine grid, with a cell size of 2 feet by 2 feet, was used to cover the central dry well area. As shown on Figure 5-3 at the end of this section, the central area measured 100 feet by 100 feet and is covered by 2500 cells (50 x 50) using the fine grid. The cell size was gradually increased toward the model side boundaries.

Vertically, the 85-foot-thick unsaturated zone was divided into seventeen 5-foot thick layers. A large plane area model domain for air flow was adequate for a constant boundary condition in this type of application.

## 5.3.2 Model Calibration

The AIR3D model was calibrated to ensure that the simulated volumetric flow rates agreed with field values observed during the historical SVE operation. Model calibration included inputting average values for air filled soil porosity and assumed values for soil air permeability. The soil parameters used for this model were based on lithological and geotechnical data obtained from soil samples collected in August 1998.

# 5.3.2.1 Air Filled Soil Porosity

Air filled soil porosity was calculated by subtracting water filled soil porosity (water moisture content by volume) from total soil porosity. The soil porosity parameters are summarized in Table 5-3. The average values of air filled soil porosity listed in the table were applied in the model.

Table 5-3

**Summary of Soil Parameters Used in Modeling Simulations** 

			Average Soil Bulk Average Moisture Density Content (%)		Average Average		Average Total	Distribution Coefficient		
Depth bgs.	Soil USC	Soil Samples	(pcf)_	(g/cm³)	By Weight		Soil Porosity	Air Fill Porosity	Organic Carbon Content (TOC)	Kd=Koc*TOC (I/mg)
0 to 25 ft	sw	TT2-62, TT4-60, TT2-72, TT4-70, TT2-82	112.5	1.803	15.69	25.02	0.3219	0.0717	0.342%	1.7
26 to 30 ft	swisc	TT2-52,TT4-50	111.9	1.793	13.29	23.87	0.3295	0.0908	0.200%	1.0
31 to 45 ft	SC/CL	TT2-40, TT6-30, TT6-40	126.7	2.030	11.40	23.14	0.2475	0.0161	0.433%	2.2
46 to 55 ft	swisc	TT2-52, TT4-50	111.9	1.793	13.29	23.87	0.3295	0.0908	0.200%	1.0
56 to 65 ft	sw	TT2-62, TT4-60	108.4	1.737	17.82	21.43	0.3531	0.1388	0.395%	2.0
66 to 75 ft	sw	TT2-72, TT4-70	113.9	1.825	15.22	27.74	0.3087	0.0313	.0.440%	2.2
76 to 85 ft	sw	TT2-82	115.2	1.846	14.02	25.89	0.3038	0.0449	0.190%	1.0

## 5.3.2.2 Soil Air Permeability

Soil air permeability values correlate with soil types. For the site, a layer cake model was assumed, such that a homogeneous air permeability field was used for each layer. For layers with similar soil types, equivalent air permeability values were assumed. A review of the site geology shows that the subsurface can be divided into three general soil types: (1) clayey sands and clays, located at 30 to 45 feet bgs; (2) sands and clayey sands, located at 26 to 30 feet bgs, and 45 to 55 feet bgs; and (3) sands and gravels, located at 0 to 25 feet bgs, and 55 to 85 feet bgs. The soil layers and corresponding soil air permeability values are listed in Table 5-4.

Table 5-4
Calibrated Soil Air Permeability Values

Depth Range (feet bgs)	Soil Type <sup>(l)</sup>	Soil Air Permeability (2) (darcys)
0 - 25	Sands and Gravels (SW/GW)	74
26 - 30	Sands and Clayey Sands (SW/SC)	7.4
30 - 45	Clayey Sands and Clays (SC/CL)	2
45 – 50	Sands and Clayey Sands (SW/SC)	7.4
55 - 85	Sands and Gravels (SW/GW)	74

<sup>(1)</sup> Unified Soil Classification System (USCS) codes are shown in parentheses

The actual soil air permeability values were calibrated by using the field SVE operational data. The model assumed that the soil column from the surface to 80 feet bgs was unsaturated. The field pneumatic data from the SVE pilot test conducted for well VW01 in November 1991 by Unisys Corporation were used initially to estimate the soil air permeability for the sand and gravel soil group (SW/GW), as cross correlated to the well screen interval of 51 to 91 feet

<sup>(2)</sup> An anisotropy ratio, (horizontal - vertical ratio of soil air permeability) of 5:1 was assumed for all soil types

bgs. The field SVE data from four operational cases were also used for the calibrations of soil air permeability. The vacuums were specified for each well as the operation condition. Flow rates from the model simulations were compared to the actual extraction flow rates for each trial run. The air permeability values were modified, as necessary, to allow the best match of model simulated flow rates to actual operation flow rates for each well. The results are summarized in Table 5-5. Based on the calibration results, the soil air permeability values are 2, 7.4 and 74 darcys for the three soil types, as shown in Table 5-4.

Table 5-5
SVE Operation Data for AIR3D Model Calibration

SVE Operating	SVE	Vacuum Readings (inch H2O)				Reported Total	Total Volumetric Flow	
Cases	Operation Date	VW01 VW02		VW13	VW14	Volumetric Flow Rate (scfm)	Rate (scfm) Simulated by AIR3D	
Pilot Test Data	Oct-91	20	-	-	-	350	334	
Pilot Test Data	Oct-91	14	-	-	-	262	232	
Case 1	Apr-95	-	38	-	35	219	205	
Case 2	Apr-97	10	15	11	12	263	309	
Case 3	Feb-98	12	-	12	-	265	271	
Case 4	May-98	10	_	12	10	268	312	

#### 5.3.3 Subsurface Air Flow Simulation Results

To evaluate the air pressure distribution within the subsurface, four different SVE scenarios were modeled using the existing extraction wells (hereinafter referred to as Cases #1 to #4). The case scenarios varied in terms of extraction flow rate, vacuum and the wells used for extraction. A summary of the four case scenarios is presented in Table 5-6.

Table 5-6
Air Flow Model Case Scenarios

Case Scenario	Extraction Wells	Total Extraction	Vacuum		
		Flow Rate (scfm)	(inches of water)		
1	VW2 and VW14	205	38 in VW2		
			35 in VW14		
2	VW1, VW2, VW13	309	10 in VW1		
	and VW14		15 in VW2		
			11 in VW13		
			12 in VW14		
3	VW1 and VW13	271	12 in VW2		
			12 in VW14		
4	VW1, VW13 and	312	10 in VW1		
	VW14		12 in VW13		
	_		10 in <u>VW14</u>		

For each case scenario, pressure distributions were evaluated at five discrete soil layers, at 5-foot thicknesses. Individual simulations were run at 10 to 15 feet, 25 to 30 feet, 35 to 40 feet, 45 to 50 feet, and 65 to 70 feet. A total of 20 different simulations were run to assess the air flow parameters of the current SVE system.

The model outputs, which show the spatial air pressure distributions in the subsurface around the dry well area for each model simulation, are shown as Figures 5-4 through 5-23 and are presented at the end of this section. The figures are depicted in two-dimensional (2-D) plane view. The cutoff vacuum used to determine the area of influence was assumed to be 0.5 inches of water. The results of the four case models are further discussed in the following subsections.

#### 5.3.3.1 Case #1

In Case #1, extraction was conducted from shallow wells VW2 and VW14. The pressure fields created by the SVE indicate that the vacuum area of influence covered the dry well area only at the depth interval of 25 to 40 ft bgs. The pressure distributions are shown in Figures 5-4 through 5-8.

## 5.3.3.2 Case #2

In Case #2, extraction was conducted from VW2 and VW14, and two deep vapor extraction wells VW1 and VW13. The vacuum area of influence appears to be adequate for the vadose zone except at the depth interval of 0 to 15 ft bgs. The pressure distributions are shown in Figures 5-9 through 5-13.

#### 5.3.3.3 Case #3

In Case #3, extraction was conducted only from the two deep wells VW1 and VW13. The shallow vadose zone from ground surface to 35 feet bgs had very low vacuum influence. A stronger vacuum area of influence was observed at depths below 35 feet bgs. The pressure distributions are shown in Figures 5-14 through 5-18.

#### 5.3.3.4 Case #4

In Case #4, extraction was conducted from VW1, VW13 and VW14, which was the most recent SVE well configuration operated at the site. The shallow vadose zone from ground surface to 25 feet bgs had low vacuum influence. A stronger vacuum area of influence was observed at depths below 25 feet bgs. The pressure distributions are shown in Figures 5-19 through 5-23.

#### 5.3.4 Evaluation of Air Flow Simulation Data

The air flow model simulations indicate that the vadose zone in the dry well area has adequate vacuum area of influence for an effective SVE operation. However, approximately 33,680 lbs of VOCs still remain in the vadose zone, mostly in the finer grained, low-permeability soils. The existing SVE system has not been capable of removing VOCs more rapidly, due to the extraction wells being screened across different soil types. For wells screened across both

high and low-permeability soils, air will flow preferentially through the high-permeability soils. As a result, VOCs are removed more readily from high-permeability soils than low-permeability soils under the same vacuum conditions. Furthermore, based on the modeling results, vacuums of less than 0.5 inches of water are not sufficient to induce air flow in low-permeability soils at the site. To further evaluate the SVE system, VOC mass transport modeling studies were conducted – see Section 5.4.

#### 5.4 VOC MASS TRANSPORT MODELING

Estimation of the VOC mass removal rate at the site was performed utilizing the VT3D model. The VT3D model uses input from the AIR3D to calculate the rate of removal and estimated time to complete remediation of the site. Total VOC mass and compound specific vapor pressures, together with air flow rates, were used to calculate VOC removal rates.

#### 5.4.1 Model Domain

The VOC mass transport model domain covers the dry well area and is centered at extraction well VW-14. A fine grid, with a cell size of 4 feet by 4 feet, was used to cover the dry well area. As shown on Figure 5-24 at the end of this section, the central area measured 100 feet by 100 feet and is covered by 1250 cells (25 x 25 cells). Vertically, the 85-foot-thick unsaturated zone was divided into seventeen 5-foot thick layers. The model has total grids of 25x25x17. This model domain in plane was much smaller than the flow model domain, because there are no boundary condition problems in the mass transport model. The air flow results from the central dry well area were extracted from the flow model outputs and input into the VT3D model.

# 5.4.2 Physical and Chemical Parameters

Soil physical and chemical parameters used in the VOC mass transport model, including bulk density, total organic carbon, and the distribution coefficient are listed in Table 5-3. The

VOC molecular weight of 145 grams/mole was used, which was weighted by mass percentages of each VOC with their molecular weights. Similar calculations were performed for total VOC solubility in water (397 mg/l) and density of total VOC liquids (1439 g/l).

## 5.4.3 VOC Mass Transport Simulation Results

VOC mass transport was simulated using the Case #4 well configuration, because it was the configuration used most recently during full-scale SVE operation. In Case #4, extraction was conducted from VW1, VW13 and VW14. Based on the modeling results, approximately 5,500 lbs, or only 17% of the remaining VOCs, will be recovered from the vadose zone in a three-year period using the current SVE system.

Table 5-7 summarizes the VT3D modeling results. Figures 5-25 through 5-28 present the calculated VOC vapor concentrations and the cumulative anticipated VOC mass recovered (from each well individually, and combined).

# 5.4.4 Evaluation of VOC Transport Data

The VT3D modeling results show that the current SVE system will remove less than 17% of the total remaining VOC mass in the vadose zone within three years. As shown in Figure 5-28b, the transport model projects that operation of the existing SVE system, as currently configured, would require at least 28 years to remove 93% of the remaining VOCs at the site.

Table 5-7 VT3D Modeling Simulation Results for Case 4:

VOC Vapor Concentrations and Recovering VOC Mass From Extraction Wells

	VW	)1	VW13		VW14				
Time (month)	VOC Vapor Concentration (ug/l)	Recovering VOC Mass (lbs)	VOC Vapor Concentration (ug/l)	Recovering VOC Mass (lbs)	VOC Vapor Concentration (ug/l)	Recovering VOC Mass (lbs)	Combined VOC Vapor Concentration (ug/l)	Monthly Recovering VOC Mass (lbs)	Total Cumulative VOC Mass (lbs)
1	272	70.6	364	157.9	1258	199.5	502	428 0	428 0
2	130	33.8	400	173.6	1225	194.3	471	401.7	829 7
3	87	22.7	379	164.5	1082	171.6	421	358 8	1188 5
4	56	14.5	333	144.4	1058	167.7	383	326 7	1515 1
5	33	8.7	272	118.2	1023	162.2	339	289.0	1804.2
6	19	5.0	214	92.9	946	150.0	291	247.9	2052.0
7	11	3.0	169	73.1	890	141.2	255	217 3	2269.3
8	7	1.9	138	59.7	866	137.4	233	199.0	2468.3
9	6	1 4	119	51.5	838	132.8	218	185.7	2654.0
10	5	1.2	109	47.1	812	128.8	208	177 1	2831 1
11	4	1.2	104	45.0	784	124.4	200	170.5	3001.6
12	4	1.1	102	44.1	752	119.2	193	164 5	3166.1
13	4	1.1	101	43.8	725	115.0	188	160.0	3326.0
14	4	1.2	101	43.8	698	110.6	183	155.6	3481.7
15	5	1.2	101	43.9	643	101.9	172	147.0	3628.6
16	5	1.2	102	44.1	534	84.7	152	129.9	3758.5
17	5	1.2	102	44.2	425	67.4	132	112.8	3871.3
18	5	1.2	102	44.1	357	56.6	120	102.0	3973.3
19	5	1.2	100	43.3	323	51.3	112	95.8	4069.1
20	5	1.3	98	42.4	308	48.8	108	92 4	4161.5
21	5	1 3	97	41.9	300	47.5	106	90.7	4252.2
22	5	1.3	96	41.7	295	46.8	105	89.9	4342.1
23	5	1.3	96	41.7	293	46.4	105	89.3	4431.4
24	5	1.3	96	41.6	291	46.1	104	89.0	4520.4
25	5	1.3	96	41.5	289	45.8	104	88.6	4609.0
26	5	1.3	94	41.0	287	45.6	103	87.9	4696.9
27	5	1.3	90	39.3	286	45.4	101	85.9	4782.8
28	5	1.3	88	38.3	285	45.2	99	84.8	4867.6
29	5	1.3	87	37.9	284	45.0	99	84.2	4951.8
30	5	1,3	87	37.7	283	44.8	98	83.8	5035.6
31	5	1.3	86	37.5	282	44.6	98	83.4	5119.0
32 33	5 5	1.3	86	37.3	281	44.5	98	83.1	5202.1
33		1 3	86	37.1	280	44.3	97	82.8	5284.9
35	5	1.3	85	36.9	279	44.2	97	82.4	5367.3
36	5 5	1.3 1.3	84	36.7	278	44.0	96) 95	82.0	5449.3
Total	<u> </u>	195.8	84	36.2 2145.7		43.7 3189.0	95	81.2 5530.5	5530.5


## 5.5 CONCLUSIONS

Based on current soil analytical data and the modeling results, the following conclusions can be drawn regarding operation of the current SVE system:

- The total VOC mass that may still remain in the vadose zone of the dry well area is conservatively estimated at approximately 34,000 pounds;
- More than 95% of the total remaining VOC mass is likely located in soils possessing lower permeability;
- The existing extraction wells are not located nor screened appropriately to remove VOCs from the low-permeability soils due to likely preferential air flow through portions of the well screen present within the high-permeability soils;
- Under the current well configuration, the model projects that approximately 28 years would be required to remove 93% of the total VOC mass at the site.

Modifications to the existing well configuration are required to enhance system performance in order to optimize mass removal from the impacted soils in the former dry well area and achieve practicable maximum treatment levels.

# Figure 5-3 AIR3D Model Plane Grids



#### **LEGEND**

- X Existing extraction well
- Soil boring installed by Tetra Tech
- O Dry Well
- $\square$  Cell Size = 2 x 2 feet

Figure 5-4 AIR3D Modeling Results: Pressure Distribution

Case 1: 2 Extraction Wells -- VW02 and VW14
Total Extraction Flow Rate = 205 scfm

Vacuum: VW02 = 38 inch H2O, VW14 = 35 inch H2O

Layer 3: Depth = 10 to 15 ft bgs




Figure 5-5 AIR3D Modeling Results: Pressure Distribution

Case 1: 2 Extraction Wells - VW02 and VW14
Total Extraction Flow Rate = 205 scfm
Vacuum: VW02 = 38 inch H2O, VW14 = 35 inch H2O
Layer 6: Depth = 25 to 30 ft bgs




Figure 5-6 AIR3D Modeling Results: Pressure Distribution

Case 1: 2 Extraction Wells – VW02 and VW14 Total Extraction Flow Rate = 205 scfm

Vacuum: VW02 = 38 inch H2O, VW14 = 35 inch H2O

Layer 8: Depth = 35 to 40 ft bgs




Figure 5-7 AIR3D Modeling Results: Pressure Distribution

Case 1: 2 Extraction Wells - VW02 and VW14
Total Extraction Flow Rate = 205 scfm
Vacuum: VW02 = 38 inch H2O, VW14 = 35 inch H2O

Layer 10: Depth = 45 to 50 ft bgs




Figure 5-8 AIR3D Modeling Results: Pressure Distribution

Case 1: 2 Extraction Wells - VW02 and VW14
Total Extraction Flow Rate = 205 scfm

Vacuum: VW02 = 38 inch H2O, VW14 = 35 inch H2O

Layer 14: Depth = 65 to 70 ft bgs




Figure 5-9 AIR3D Modeling Results: Pressure Distribution

Case 2: 4 Extraction Wells - VW01, VW02, VW13 and VW14

Total Extraction Flow Rate = 309 scfm

Vacuum: VW01 = 10 inch H2O, VW02 = 15 inch H2O

VW13 = 11 inch H2O, VW14 = 12 inch H2O

Layer 3: Depth = 10 to 15 ft bgs




Figure 5-10 AIR3D Modeling Results: Pressure Distribution

Case 2: 4 Extraction Wells – VW01, VW02, VW13 and VW14 Total Extraction Flow Rate = 309 scfm

Vacuum: VW01 = 10 inch H2O, VW02 = 15 inch H2O

VW13 = 11 inch H2O, VW14 = 12 inch H2O

Layer 6: Depth = 25 to 30 ft bgs




Figure 5-11 AIR3D Modeling Results: Pressure Distribution

Case 2: 4 Extraction Wells - VW01, VW02, VW13 and VW14

Total Extraction Flow Rate = 309 scfm

Vacuum: VW01 = 10 inch H2O, VW02 = 15 inch H2O

VW13 = 11 inch H2O, VW14 = 12 inch H2O

Layer 8: Depth = 35 to 40 ft bgs




Figure 5-12 AIR3D Modeling Results: Pressure Distribution




Figure 5-13 AIR3D Modeling Results: Pressure Distribution

Case 2: 4 Extraction Wells - VW01, VW02, VW13 and VW14 Total Extraction Flow Rate = 309 scfm

Vacuum: VW01 = 10 inch H2O, VW02 = 15 inch H2O

VW13 = 11 inch H2O, VW14 = 12 inch H2O

Layer 14: Depth = 65 to 70 ft bgs




Figure 5-14 AIR3D Modeling Results: Pressure Distribution

Case 3: 2 Extraction Wells -- VW01 and VW13 Total Extraction Flow Rate = 271 scfm

Vacuum: VW01 = 12 inch H2O, VW13 = 12 inch H2O

Layer 3: Depth = 10 to 15 ft bgs




Figure 5-15 AIR3D Modeling Results: Pressure Distribution

Case 3: 2 Extraction Wells - VW01 and VW13 Total Extraction Flow Rate = 271 scfm Vacuum: VW01 = 12 inch H2O, VW13 = 12 inch H2O Layer 6: Depth = 25 to 35 ft bgs




Figure 5-16 AIR3D Modeling Results: Pressure Distribution

Case 3: 2 Extraction Wells – VW01 and VW13
Total Extraction Flow Rate = 271 scfm

Vacuum: VW01 = 12 inch H2O, VW13 = 12 inch H2O

Layer 8: Depth = 35 to 40 ft bgs




Figure 5-17 AIR3D Modeling Results: Pressure Distribution

Case 3: 2 Extraction Wells - VW01 and VW13 Total Extraction Flow Rate = 271 scfm

Vacuum: VW01 = 12 inch H2O, VW13 = 12 inch H2O

Layer 10: Depth = 45 to 50 ft bgs




Figure 5-18 AIR3D Modeling Results: Pressure Distribution

Case 3: 2 Extraction Wells - VW01 and VW13
Total Extraction Flow Rate = 271 scfm

Vacuum: VW01 = 12 inch H2O, VW13 = 12 inch H2O

Layer 14: Depth = 65 to 70 ft bgs




Figure 5-19 AIR3D Modeling Results: Pressure Distribution

Case 4: 3 Extraction Wells - VW01, VW13 and VW14

Total Extraction Flow Rate = 312 scfm

Vacuum: VW01 = 10 inch H2O, VW13 = 12 inch H2O

VW14 = 10 inch H2O

Layer 3: Depth = 10 to 15 ft bgs




Figure 5-20 AIR3D Modeling Results: Pressure Distribution

Case 4: 3 Extraction Wells -- VW01, VW13 and VW14

Total Extraction Flow Rate = 312 scfm

Vacuum: VW01 = 10 inch H2O, VW13 = 12 inch H2O

VW14 = 10 inch H2O

Layer 6: Depth = 25 to 30 ft bgs




Figure 5-21 AIR3D Modeling Results: Pressure Distribution

Case 4: 3 Extraction Wells - VW01, VW13 and VW14

Total Extraction Flow Rate = 312 scfm

Vacuum: VW01 = 10 inch H2O, VW13 = 12 inch H2O

VW14 = 10 inch H2O

Layer 8: Depth = 35 to 40 ft bgs




Figure 5-22 AIR3D Modeling Results: Pressure Distribution

Case 4: 3 Extraction Wells -- VW01, VW13 and VW14 Total Extraction Flow Rate = 312 scfm

Vacuum: VW01 = 10 inch H2O, VW13 = 12 inch H2O

VW14 = 10 inch H2O Layer 10: Depth = 45 to 50 ft bgs





Figure 5-23 AIR3D Modeling Results: Pressure Distribution

Case 4: 3 Extraction Wells -- VW01, VW13 and VW14 Total Extraction Flow Rate = 312 scfm


Vacuum: VW01 = 10 inch H2O, VW13 = 12 inch H2O

VW14 = 10 inch H2O

Layer 14: Depth = 65 to 70 ft bgs




# Figure 5-24 VT3D Model Plane Grids



#### **LEGEND**

- X Existing extraction well
- ⊕ Soil boring installed by Tetra Tech
- O Dry Well
- Cell Size = 4 x 4 feet

Figure 5-25 VT3D Modeling Results for Case 4 VOC Vapor Concentrations and Cumulative VOC Mass Recovered from VW01



FAGE 3-3

Figure 5-26 VT3D Modeling Results for Case 4 VOC Vapor Concentrations and Cumulative Mass Recovered from VW13





Figure 5-27 VT3D Modeling Results for Case 4 VOC Vapor Concentrations and Cumulative Mass Recovered from VW14



PAGE 5-4

Figure 5-28a VT3D Modeling Results for Case 4
Combined VOC Vapor Concentrations and Cumulative Recovering VOC Mass





Figure 5-28b VT3D Modeling Results for Case 4 Cumulative Recovery of 93% of Total VOC Mass




#### Section 6


## References

- Final Division Technical and Administrative Guidance Memorandum (TAGM) -Disposal of Drill Cuttings New York State Department of Environmental Conservation, November 21, 1989
- Record of Decision
   Great Neck, New York
   New York State Department of Environmental Conservation, March 1997
- 3. Interim Remedial Measure Operable Unit II Soil Remediation Work Plan Great Neck, New York Unisys Corporation, November 15, 1993
- Start Up Report May 1994
   IRM Operable Unit II SVE System
   Great Neck, New York
   Unisys Corporate Environmental Affairs, June 6, 1994
- June 1994 through May 1995 Monthly Reports IRM Operable Unit II – SVE System Great Neck, New York Unisys Corporate Environmental Affairs
- June 1995 through February 1996 Monthly Reports IRM Operable Unit II - SVE System Great Neck, New York Loral Environmental
- 7. March 1996 through June 1998 Monthly Reports IRM Operable Unit II SVE System Great Neck, New York H2M Associates, Inc.

- 8. Feasibility Study Report Operable Unit I Great Neck, New York H2M Associates, Inc., January 1997
- 9. Phase I Environmental Assessment Report Lockheed Martin Tactical Defense Systems H2M Associates, Inc., April 1997
- Scope of Work for Soil Vapor Extraction System Evaluation Lockheed Martin Tactical Defense Systems H2M Associates, Inc., July 1997
- Soil Vapor Extraction System Evaluation Work Plan Lockheed Martin Corporation Great Neck, New York Tetra Tech, Inc., July 14, 1998
- 12. Fax transmittal of dry well excavation information from Sui Leong of H2M Group to Nisha Bansal of Tetra Tech, Inc. January 21, 1999



# UNISYS CORPORATION THEORETICAL VOC EXTRACTION CURVE



## H2M CORPORATION VOC MASS CALCULATIONS

#### FEASIBILITY STUDY REPORT

#### **OPERABLE UNIT I**

## LOCKHEED MARTIN TACTICAL DEFENSE SYSTEMS DIVISION (Former Unisys Corp. Site)

Great Neck, New York NYSDEC Site No.130045

Prepared for:

New York State
Department of Environmental Conservation

On behalf of:

Lockheed Martin Tactical Defense Systems Division of Lockheed Martin Tactical Systems, Inc.

**JANUARY 1997** 

Prepared by:



#### VOC MASS CALCULATION FOR SOIL

Available data was used to estimate the mass of VOCs adsorbed to impacted soils located in the vicinity of the former dry wells. Data utilized included soil samples collected prior to the RI in 1988, 1990, and 1991 and soil samples collected during the RI. Total VOC (TVOC) analytical results were plotted on a cross section in order to estimate the volume of soil impacted by VOCs. Review of the plotted data indicated an area of relatively high VOCs in the immediate vicinity of the dry wells (area 1) and a much larger area (area 2) with lower VOC concentrations surrounding area 1. Results of the VOC mass estimation are summarized below.

Агеа	Soil Volume (yd³)	Soil Mass (lb)	TVOC Mass (lb)
1	13,900	41 x 10°	52,000
2	120,000	3.56 x 10°	18,000
Total	133,900	3.97 x 10°	70,000

The quantities given above are only estimates and several assumptions were made in order to calculate the mass of TVOCs. These assumptions include the area of impacted soil is cylindrical in shape with a diameter of 125 feet in Area 1 and 225 feet in Area 2; the analytical data is representative of average current soil conditions, and the zone of impacted soil does not extend more than 10 feet below the groundwater table. These quantities will be reevaluated as more data becomes available.

#### Area 1

Soil volume = 
$$\pi (63 \text{ ft})^2 (30 \text{ ft})$$
  
= 374,069 ft<sup>3</sup>  
= 13,900 yd<sup>3</sup>  
Soil mass = 374,069 ft<sup>3</sup> x 110 lb/ft<sup>3</sup> x 1 lb/2.2 kg  
= 18.7 x 10<sup>6</sup> kg  
= 41 x 10<sup>6</sup> lb  
TVOC mass = 18.7 x 10<sup>6</sup> kg x 10<sup>-6</sup> kg/mg x 1,250 mg/kg  
= 23,400 kg  
= 52,000 lb



Soil volume = 
$$[\pi(113 \text{ ft})^2 (90 \text{ ft})] - 374,100 \text{ ft}^3$$
  
= 3.24 x 10<sup>6</sup> ft<sup>3</sup>  
= 120,000 yd<sup>3</sup>  
Soil mass = 3.24 x 10<sup>6</sup> ft<sup>3</sup> x 110 lb/ft<sup>3</sup> x 1 lb/2.2 kg  
= 1.62 x 10<sup>8</sup> kg  
= 3.56 x 10<sup>8</sup> lb  
TVOC mass = 1.62 x 10<sup>8</sup> kg x 10<sup>-6</sup> kg/mg x 45 mg/kg  
= 7,200 kg  
= 18,000 lb

Estimated Total VOCs in Soil = Approximately 70,000 lb

### Pre RI Soil Sampling Data

Great Neck, NY

	Vapor	Boring			Sample	PHC	Total	Total	Total	
Boring	Well	Depth (ft.)	Date Drilled	Sample Number	Depth (ft)	(ppm)	VOCs	SVOCs	Pest./PCBs	Parameters
B-1	no _	4	1/13/88	B-1	1012	ND	ND			vocs, phc, metals
B-2	<u>no</u>	20	3/31/88	B-2	1012	+	+			vocs, phc, metals
B-3	no	29	3/31/88	B-3	2527	+	+			vocs, phc, metals
B-4	no	35	4/5/88	B-4	2022	+	+			vocs, phc, metals
B-4	no	35	4/5/88	B-4	3032	+	+			vocs, phc, metals
B-4	no	_35	4/5/88	B-4	3537	+	+			vocs, phc, metals
B-5	no	18	4/5/88	B-5	1517	+	+			vocs, phc, metals
B-6	no	30	4/11/88	B-6	2527	ND	ND			vocs, phc, metals
B-7	no	30	4/11/88	B-7	30-32	16	ND		,	vocs, phc, metals
B-8	no	30	4/11/88	B-8	3032	ND	ND			vocs, phc, metals
B-9	no	32	4/12/88	B-9	3032	ND	ND			vocs, phc, metals
B-10	no	12	4/12/88	B-10	57	41	ND	-		vocs, phc, metals
B-11	no	30	3/31/88	B-11	30-32	ND	ND			vocs, phc, metals
B-12	no	30	3/31/88	B-12	30-32	ND	ND			vocs, phc, metals
B-13	no	30	3/31/88	B-13	2527	ND	ND			vocs, phc, metals
B-14	no	30	4/12/88	B-14	2527	ND	ND			vocs, phc, metals
SVB1	no	50	6/12/90							not sampled
SVB2	VW1	91	6/14/90	SVB2-50-51.5	50-51.5		18			vocs
SVB2	11	91	6/14/90	SBVB2-85-86.5	85-86.5		94,000			vocs
SVB3	VW2	45	6/18/90							not sampled
SVB4	VW3	93	6/18/90	SVB4-80-81.5	80-81.5		ND			vocs
SVB5	VW4	80	6/21/90	SVB5-60-61.5	6061.5					vocs
SVB5	10	80	6/21/90	SBV5-50-51.5	5051.5		6300			vocs
SVB5	"	80	6/21/90	SVB5-12	12		*			vocs
SVB5	"	80	6/21/90	SVB5-70-71.5	70-71.5		*		-+	vocs
SVB5	"	80	6/21/90	SVB5-80-81.5	80-81.5		8400			vocs
SVB6	no	37	6/21/90	SVB6-12	12				~ *	#2 fuel oil (ND)
SVB7	VW5	93								NA
SVB8	no	25	6/25/90							NA

note: all results in ppb unless otherwise noted, -- not analyzed, \* detected in blank or below mdl, ND not detested, + data not available.

#### Pre RI Soil Sampling Data

Great Neck, NY


	Vapor	Boring			Sample	PHC	Total	Total	Total	And the second
Boring	Well	Depth (ft.)	Date Drilled	Sample Number	Depth (ft)	(ppm)	VOCs	SVOCs	Pest./PCBs	Parameters
SVB9	VW6	90								NA
SVB10	VW7	48	7/30/91	SVB102022	2022		*			tcl vocs
SVB10	u	48	33449	SVB104042	4042		5			tcl vocs
SVB11	VW8	90	7/24/91	SVB112022	2022		ND			tcl vocs
SVB11	**	90	7/24/91	SVB114042	4042		59			tcl vocs
SVB11	"	-90	7/24/91	SVB116062	6062		ND			tcl vocs
SVB11		90	7/24/91	SVB118082	8082		27			tcl vocs
SVB12	no	3	7/25/90							not sampled
SVB13	VW9	90	7/26/91	SVB132022	2022		*			tcl vocs
SVB13	"	90	7/26/91	SVB134042	4042		*			tcl vocs
SVB13		90	7/26/91	SVB136062	6062		*			tcl vocs
SVB13		90	7/26/91	SVB138082	8082		65			tcl vocs
SVB14	VW10	90	8/16/91	SVB142022	2022		•			tcl vocs
SVB14	11	90	8/16/91	SVB144042	4042		*			tcl vocs
SVB14	11	90	8/16/91	SVB146062	6062		*			tcl vocs
SVB14		90	8/16/91	SVB148082	8082		15			tcl vocs
SVB15	VW11	90	8/6/91	SVB152022	2022		*			tcl vocs
SVB15		90	8/6/91	SVB154042	4042		•			tcl vocs
SVB15		90	8/6/91	SVB156062	6062		•			tcl vocs
SVB15	"	90	8/6/91	SVB158082	8082		ND			tcl vocs
SVB16	VW12	90	8/14/91	SVB162022	2022		7		••	tcl vocs
SVB16	"	90	8/14/91	SVB164042	4042		6			tcl vocs
SVB16	"	90	8/14/91	SVB166062	6062		6			tcl vocs
SVB16	**	90	8/14/91	SVB168082	8082		30			tcl vocs
SVB17	VW13	90	8/22/91	SVB17	2022		1,330,000			tcl vocs
SVB17	"	90	8/22/91	SVB-17	60-62		308,000			tcl vocs
SVB17	"	90	8/22/91	SVB-17	40-42		*			tcl vocs
SVB17	"	90	8/22/91	SVB-17	80-82		130,000			tcl vocs
SVB17	"	90	8/22/91	SVB-17B	20-22		1,899,000			tcl vocs

note: all results in ppb unless otherwise noted, -- not analyzed, \* detected in blank or below mdl, ND not detested, + data not available.

#### Pre RI Soil Sampling Data

Great Neck, NY


	Vapor	Boring			Sample	PHC	Total	Total	Total	
Boring	Well	Depth (ft.)	Date Drilled	Sample Number	Depth (ft)	(ppm)	VOCs	SVOCs	Pest./PCBs	Parameters
SVB17	"	90	8/22/91	SVB-17 011	40-42					tcl vocs
SVB17	и	90	8/22/91	SVB-17 RE	60-62		348,000			tcl vocs
SVB17	8	90	8/22/91	SVB-17 RE	80-82		130,000			tcl vocs
SVB17	н	90	8/22/91	SVB-17B RE	20-22		2,200,000			tcl vocs
SVB17	"	90	8/22/91	SVB-17 002 RE	40-42		15.5			tcl vocs
SVB17	11	90	8/22/91	SVB-17 011 RE	40-42		*			tcl vocs
SVB17	.,	90	8/22/91	SVB-17	20-Dec	<b></b>		1140	48/890	tcl sem-voc,pest/PCB
SVB17	.,	90	8/22/91	SVB-17 RE	20-Dec			1640		tci semi-vois
SVB17		90	8/22/91	SVB-17	30-40			ND	ND/ND	tcl sem-voc,pest/PCB
SVB17	н	90	8/22/91	SVB-17	50-60			6270		tcl sem-voc
SVB17	31	90	8/22/91	SVB-17	70-80			5370	ND/2730	tcl sem-voc,pest/PCB
SVB17		90	8/22/91	SVB-17	20-Dec					tcl pest/PCB
SVB17	и.	90	8/22/91	SVB-17	30-40					tcl pest/PCB
SVB-17			SVB-18	50-60					tcl pest/PCB	LBG
SVB17		90	8/22/91	SVB-17	70-80					tcl pest/PCB
SVB17	"	90	8/22/91	SVB-17	20-Dec	<b></b>				tal metals plus cyanide
SVB17	11	90	8/22/91	SVB-17	30-40					tal metals plus cyanide
SVB17	n	90	8/22/91	SVB-17	50-60					tal metals plus cyanide
SVB17	10	90	8/22/91	SVB-17	70-80	<b></b>				tal metals plus cyanide
SVB18	VW14	42	8/23/91				••	***	88/3060	tcl pest/PCB




ALL CONCENTRATIONS TOTAL VOLATILE ORGANIC COMPOUNDS IN Mg / Kg

	S-SECTION A-A'
MAN BY DAP. SOIL C	NALITY
ORC BE F.JF.	noute
PROJ. MOR. F.1F.	(
PROJ. MG: 07041	.l. 1
दवस्कः १	· <b></b>   '

E HAME O /CEY/DROM/BLOHI/B1041-34







BORING I.D. NO. TT-1

Page 1 of 1

CLIEN	T	KHEED	MAF	RTIN_	T.C.	1768-05	LOCATION	GREAT NECK	. DATE <u>8/25/98</u>										
,	METHOD	H	SA			AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST	Phil Skorge										
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	nscs		GEOLOGI	C DESCRIPTION											
					SW														
- 5 -	5/5 4/5	ND	×			SAND - Yellowish moist.  Cobbles @ 7.0 fee		orted fine to coarse sand	d, trace gravel, loose,										
- 10 -	10/12 12/18 11/18 18/28		X	00000	GW	sand, fine to coar:	se gravel, moist.	covery for lab sample. Rock stuck in shoe. Soppm P.I.D. readings.	Yellowish Brown 30% ome dark gray to										
- 15 -	50=6"		X	0000	SW	No recovery. Cob recovery.	bles. Cuttings 6	aboratory analysis. ? 15.0 feet measured up f 20% gravel, poorly sorte											
- 20 -	13/19 23/25 24/31	8.0	$\times$		3n	sand, moist. 210pp	om in soil cutting	S.	ed fille to coarse										
- 25 -	36/40	0.0	$\bigvee$	5000 0000	GW			wish Brown, 30% sand, fin	e to medium gavel.										
20	32/38 44/50		$\bigcirc$	0000	,	No recovery. Cob													
- 30 -	40/38 42/42		X	000000		Cobbles, 5% recov	ery. 5ppm in so	il cuttings.											
- 35 -	24/31 35/38		X	000000		Cobbles, <5% reco	very.												
- 40 -	32/34 38/41	4.0	X	0000		cobbles. Refusal (	@ 42.0 feet, bou 												
45						Total Depth 42.0 t grout.	feet. Terminate	d per soil refusal. Backf	ill with bentonite										
REVIE	WING GE	OLOGIS	τ_	Rich B	aldwin	SIGNATURE			REVIEWING GEOLOGIST Rich Baldwin SIGNATURE REG. NO.										



BORING I.D. NO. <u>TT-1a</u>

Page 2 of 2

CLIEN	T	CKHEED	MAI	RTIN	T.C	. <u>1768-05</u>	LOCATION	GREAT NECK	_ DATE <u>8/25/98</u> _		
DRILL	METHOD	)H:	SA			AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST	Phil Skorge		
OEPTH (feet)	BLOW	0VA (ppm)	SAMPLE	GRAPHIC	SOSO	GEOLOGIC DESCRIPTION					
						Continued from ref	usal of boring 1	T – 1.			
- 50 -	30/20 18/18	ND	: ×	• • •	SW	SAND - Light Yello to medium), moist,		orly sorted fine to coars	e sand, (mostly fine		
- 55 -			X	0000	GW	SANDY GRAVEL - gravel, moist, no o No recovery.	Light Gray to Y dor.	ellowish Brown, 40% sand	d, fine to medium		
	34/29 35/38	34.0				He recovery.					
	25/38 48/50	20.0			SW	GRAVELLY SAND - moist.	Light Yellowish	Brown, 30% gravel, fine	to coarse sand,		
- 60 -	15/19 21/33	41.0				No gravel, fine to	coarse sand (m	ainly fine to medium).			
	15/22 37/39 15/18 20/24	212.0 120.0				Solvent odor @ 62	.0 feet.				
- 65 -	12/15 17/21	145.0	\/	• • •		20% gravel, mainly	coarse sand.				
			X			No recovery.					
- 70 -	13/18 18/19	68.0				Trace gravel, main	ly medium to co	arse sand.			
	15/17 17/17	144.0	X			20% gravel, mainly	fine to medium	sand.			
- 75 -	18/23 27/32	150.0		• • •		Mainly coarse sand	d, 30% gravel.				
	16/24 27/31	204.0	$\times$			<5% recovery, cob					
- 80 -	18/24 29/34	282.0	\ /		SP	coarse sand.  SAND - Light Yello		ine grained sand, laminat  derately sorted fine to m			
			X			heavy odor. <b>T</b> : Groundwater en	countered @ 82	.5 feet.			
- 85 -						<u> </u>	feet. Terminate	d boring. Groundwater e	ncountered @ 82.5		
90					<b>3</b> -44 :		_				
REVIE	WING GE	OLOGIS	т _	Rich E	Baldwin	SIGNATURE	·		_ REG. NO		



BORING I.D. NO. TT-2

Page 1 of 2

REG. NO.\_\_\_

CLIEN	T	CKHEED	MAF	RTIN	T.C.	<i>1768-05</i>	LOCATION	GREAT NECK	DATE <u>8/19/98</u>
	METHOD	<u>H</u> .	SA			. AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST	Phil Skorge
DEPTH (feet)	BLOW	0VA (ppm)	SAMPLE	GRAPHIC	SOSO		GEOLOGI	C DESCRIPTION	
- 5 -	5/8 11/13 7/5 5/5 2/2 3/3	2.0	X		SW	GRAVELLY SAND (mostly fine), 20% Cobble/Boulder @	gravel, moist.	% fines, poorly sorted fil	ne to coarse sand
- 10 -	4/4 5/6 4/6 7/7	3.0 1.5 4.0	$\times \times \times$						
- 15 -	7/11 12/14 9/17 26/29 10/17 21/26	4.0 4.0 II.0	X			SAND - Yellowish moist. 30% gravel/cobble Cobbles/Boulders	es, faint odor, m		sand. trace gravel,
- 20 - - 25 -	6/12 14/17 6/13 14/16	3.0 2.5	×			30% gravel/cobble 5% gravel.	es, poorly sorted	d sand, faint odor.	
- 30 -	7/12 15/19 8/12 19/20	3.0	$\times$			No recovery, cobt		oarse sand, no odor.	
- 35 -	6/11 13/12 6/10 13/18 6/7 9/12	1.0 3.5 4.0	$\times$		SC	gravel, moist.		t, fine to coarse sand (m	
40	6/9 11/13 8/14	2.0 4.0	X	• • •	SW	moist.  SAND - 5% fines,	poorly sorted fil	poorly sorted fine to coanne to coarse sand, 5% gr	
45	18/21 11/16 19/23 8/11 12/15	2.5 5.0	$\times$	• • •	SW	moist.	– Dark Brown, po	no gravel.  poorly sorted fine to coar  3" silty sand zone.	se sand, 5% gravel.
			$\angle$						

REVIEWING GEOLOGIST Rich Baldwin SIGNATURE



BORING I.D. NO. TT-2

Page 2 of 2

	CLIEN	т <i></i>	KHEED	MAI	RTIN	T.C.	<u> 1768-05</u>	LOCATION	GREAT NECK	DATE 8/19/98
_		METHOD		SA			AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST _	Phil Skorge
1	DIVICE	ME THOS					- ACCENTIANTE VEN			
	ОЕРТН (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	SOSU		GEOLOGI	C DESCRIPTION	
		7/10	1.5	×	• • •	S₩	Yellowish Brown, I	J% gravel.		-
		14/19				SM	SILTY SAND - Lig	ht Brown, 30% f	ines, fine to coarse sand	, moist.
		NR	5.0	$\times$		SW	SAND - Light Bro	wn, 5% fines, poo	orly sorted fine to coarse	e sand, moist.
	- 50 -	10/17 2/24	7.0	$\times$	• • •		Yellowish Brown, w	with laminations, s	5% gravel, trace fines.	
		11/19 25/ <b>2</b> 8	3.0	$\simeq$	• • •		Yellowish Brown, n	io laminations.		
		8/17 19/22	5.0	$\checkmark$			10% gravel.			
	- 55 -	9/14 17/24	5.0	$\stackrel{\frown}{\times}$			Orange Brown, ma	inly coarse sand	I.	
		8/11 17/21	7.0	$\times$	• • •		Light Brown, with I	aminations, no g	ravel.	
	- 60 -	7/10 14/15	52.0	×			Fine to coarse sa	nd, no lamination	ns, 3" gray layer, solvent	odor.
		12/19 24/29	58.0		• • •					
		6/13 20/26	234.0	$\sim$	• • •		Solvent odor.			
	- 65 -	11/17 23/29	253.0	×			Fine to coarse sa	nd, solvent odor		
		8/11 14/19	225.0				Light Gray, fine to	coarse sand, s	trong odor.	
	- 70 -	9/12 18/23	165.0		• • •					
		7/10 14/18	476.0							
		9/ <b>18</b> 21/25	206.0		• • •		5		ahawa	
	- 75 -	10/11	86.0				5% gravel, more c			
		14/17		$\times$	• • •		10% gravel, more o	coarse sand thar	n above.	
		7/10 12/15	85.0	$\checkmark$	• • •		No gravel, less co	arse sand than	above.	
	- 80 -	9/12 18/25	130.0		• • •		- 0			and Carried order
		7/14 17/19	200.0	×	• • •		t: Gray, moderate encountered € 80		o medium sand, heavy odd	or, wet. Groundwater
		פוזיו					Total Depth 82.0 Groundwater enco	feet. Terminate ountered @ 80.0	d boring. Backfill with be feet.	entonite grout.
	- 85 -									
	90									



BORING I.D. NO. TT-3

Page 1 of 2

CLIEN	T	<u>CKHEED</u>	MARTIN	T.C.		LOCATION	GREAT NECK	_ DATE <u>8/28/98</u>		
DRILL	METHOD	H	SA		. AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST .	Phil Skorge		
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE GRAPHIC COLUMN	nscs		GE OL OGI	C DESCRIPTION			
			000	G₩						
			000							
- 5 -			$\times$							
	22/15 19/25	0.0			SANDY GRAVEL - medium gravel, mois	Dark Brown, 30% st.	spoorly sorted fine to c	oarse sand, fine to		
10			• • •	SW				<del>-</del>		
- 10 -	12/15 12/12	0.0	$\boxtimes$ •• $ $		GRAVELLY SAND -	· Dark Brown, 15:	% gravel, poorly sorted t	ine to coarse sand,		
	12712				morst.					
- 15 -					20% gravel.					
	12/10 10/11	0.0			Yellowish Brown, 59	% gravel.				
- 20 -										
	14/15 14/14	0.0			No gravel.					
	8/9 9/10	0.0			Trace gravel (<5%	5).				
- 25 -	9/10 9/11	0.0	•••							
	9/12 15/28	0.0	• • •		10% fines, cobble in	n shoe.				
- 30 -					No recovery, cobb	les.				
			X.:.		No recovery, cobb	les.				
			•••	CL -	SANDY CLAY - Day	rk Brown, non-pl	astic fines, 20% sand (r	nainly fine sand),		
- 35 -	9/12	0.0			moist.					
	15/16									
- 40 -			×		Cobbles.					
	15/17 18/18	0.0	×	SM	<u>SILTY SAND</u> - Dar gravel, moist.	k Brown, 30% fin	es, fine to coarse (mair	nly fine sand), Trace		
45	9/12 28/29	0.0			20% fines, mainly m	edium to coarse	sand.			
	EVIEWING GEOLOGIST Rich Baldwin SIGNATURE REG. NO.									



BORING I.D. NO. TT-3

Page 2 of 2

REG. NO.\_\_

CLIEN	T	KHEED	MAF	RTIN	т.с	1768-05	L	OCATION	GREAT NECK	_ DATE <u>8/28/98</u>
	METHOD	H	SA	_		_ AUGER DIAME	TER _	8.00" OD	FIELD GEOLOGIST .	Phil Skorge
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	nscs			GEOLOGI	C DESCRIPTION	
	10/14	2.0			SM					
	17/19 8/15	21.0	X			•				
	17/22		$\times$							
50 -	15/17 17/22	8.0	$\times$							
	18/20 22/28	72.0								
-	35/33 25/28	0.0	×		SW	GRAVELLY Sa to coarse sa	AND - 0 nd, mois	Grey Brown to it.	Yellow Brown, 20% grave	el, poorly sorted fine
- 55 -	24/26 28/31	13.0	×			Trace gravel	(<5%).			
	32/37 40/44	70.0				With laminatio	ns, odo	r.		
- 60 -	25/29 30/30	38.0	><	•		No odor.				
	22/26 27/29	206.0	X							
- 65 -	24/26 29/32	12.0	X	• • •		20% gravel, s	ome col	bbles from 60	' to 65'.	
	17/20 21/24	18.0	X	• • •		30% gravel, c	obble in	n shoe.		
	19/22 22/26	28.0	$\times$	• • •						
- 70 -				• • •						
-	15/19 22/25	3.0				10% gravel.				
				• • •						
- 75 -			$\nabla$		1	No recovery,	a abbia			
			$\triangle$	• • •		No recovery,	CODDIE	5.		
				• • •		•				
- 80				• • •						
	21/22 24/25	240.0	-=-	• • •		sand, (mostly	y coarse	e), wet. Grour	ın, 20% gravel, poorly so ndwater encountered @ 8	rted fine to coarse 31.5 feet, odor.
	19/19 20/21	1904.0							udge), heavy odor.	ancountered @ 815
- 85 -						feet. Soil ga	is probe	es set @ 52', 6	d boring. Groundwater e 2' and 72'.	TICOUITETED & OLO
90										

REVIEWING GEOLOGIST Rich Baldwin SIGNATURE



BORING I.D. NO. TT-4

Page 1 of 2

REG. NO.\_\_\_\_\_

CLIEN	T	KHEED	MARTIN	т.с	c. <u>1768-05</u>	LOCATION	GREAT NECK	DATE <u>8/24/98</u>
	METHOD	H	SA		_ AUGER DIAMETER	8.00" OD	_ FIELD GEOLOGIST _	Phil Skorge
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE GRAPHIC COLUMN	SOSN		GEOLOG1	IC DESCRIPTION	
- 5 -			X	SW	<u>GRAVELLY SAND</u> - moist.	- Dark Brown, p	oorly sorted fine to coar	se sand, 20% gravel,
- 15 -	NR	0.0			Cobbles/boulders			
- 20 -	8/6 7/7	19.0			Yellowish Brown, n	o gravel.		
- 25 -	4/7 10/11	80.0			10% fines.			
	5/8 9/12	361.0	<b>≥•••</b>				and 10% fines, solvent od	
- 35 -		2500+	×	SM	(perched water),	strong odor.	ines, poorly sorted fine t	
45	5/10 12/13 7/10 12/14	1012.0 2500+	ו••	SW	<u>SAND</u> - Gray Brov odor. 5% gravel.	wn, poorly sorte	d fine to coarse sand, 10	% gravel, wet, strong

SIGNATURE \_\_\_\_\_

REVIEWING GEOLOGIST Rich Baldwin



BORING I.D. NO. TT-4

Page 2 of 2

REG. NO.\_\_\_

CLIEN	1T	KHEED	MAF	RTIN	T.C.	<u>1768-05</u>	LOCATION	GREAT NECK	DATE <u>8/24/98</u>						
_	METHOD	H:	SA			AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST	Phil Skorge						
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	nscs	GEOLOGIC DESCRIPTION									
- 50 -	6/11 14/16 8/12 19/24	2500+ 556.0	X		SW		Mainly fine to medium sand.  Fine to coarse sand, poorly sorted.								
- 55 -	6/10 13/17	201.0	X			Yellowish Brown.  Fine to medium sand, moderately sorted.									
- 60 -	10/1 <b>4</b> 16/19	293.0													
65 -	7/8 10/12	30.0	X												
- 70 -	6/12 13/15		X			Mainly medium to c	coarse sand.								
- 75	9/16 - 23/30			00°0°	GW	SANDY GRAVEL -	Gray Orange, 40	0% fine to coarse sand,	fine to medium gravel.						
- 80	8/12 14/17		***	00°00		▼: Groundwater Er Total Depth 80.0 Groundwater enco	feet. Terminate	d boring. Backfill with b	entonite grout.						
	- - -					Groundwater enco	טווופופט פ 20.0 .								
- 85 															
90	-														

REVIEWING GEOLOGIST \_\_\_\_\_ Rich Baldwin \_\_\_\_ SIGNATURE \_\_\_\_\_



BORING I.D. NO. TT-5

Page 1 of 2

REG. NO.\_\_\_\_\_

	CLIEN	T	KHEED	MAF	RTIN	T.C.	<u> 1768-05</u>	LOCATION	GREAT NECK	DATE 8/26/98
	DRILL	METHOD	Н	SA			AUGER DIAMETER	8.00"_ <u>OD</u>	FIELD GEOLOGIST _	Phil Skorge
	ОЕРТН (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	SOSA		GE OLOGI	C DESCRIPTION	
	- 5 -	4/6 9/11	0.0	X	1 - 4) - 4) - 4) - 4) - 4) - 4) - 4) - 4	FILL	<u>SAND</u> - Light yell moist.	owish Brown, poo	rly sorted fine to coarse	e sand, trace gravel,
	- 10 -	<b>4/</b> 7 7/9	0.0	×	~ \~ \~ \~ \~ \~ \~ \~ \~ \~ \~ \~ \~ \~		Dark Brown, 10% g	ravel.		
	- 15 -	5/8 9/11	0.0	X	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		20% gravel.			•
	- 20 -	<b>4</b> /6 7/6	0.0	X	w) w) w) w) W w) w) w) w) w		Light Yellowish Bri	own.		
	- 25 -	6/7 9/9	0.0	X	w w w w w w					
	- 30 -	6/8 II/I3	8.0	X	0000	GW	SANDY GRAVEL - damp, (native).	Dark Gray, 20%	sand, fine to medium gra	vel, heavy odor,
	- 35 -	6/8 10/11	2500+	X	0000000 000000000000000000000000000000		Damp to wet, (pe	rched water), he	avy odor.	
-	45	11/13 14/18	674.0	×	000	SC	<u>CLAYEY SAND</u> — [ Black @ bottom 6'	Dark Brown, 30% of sample, heav	fines, mainly fine sand, 10 y odor, wet.	D% gravel, odor.

REVIEWING GEOLOGIST Rich Baldwin SIGNATURE \_\_\_\_\_



REVIEWING GEOLOGIST Rich Baldwin

#### **TETRA TECH BORING LOG**

BORING I.D. NO. TT-5

Page 2 of 2

REG. NO.\_\_\_\_

CLIENT LOCKHEED MARTIN T.C. 1768-05 LOCATION GREAT NECK DATE 8/26/98 **HSA** \_ AUGER DIAMETER <u>8.00" OD</u> FIELD GEOLOGIST \_ Phil Skorge DRILL METHOD . SAMPLE DEPTH (feet) nscs BLOW COUNT OVA (ppm) GEOLOGIC DESCRIPTION SC 2500+ 6/9 11/15  $\underline{\sf SAND}$  - Light Brown, poorly sorted fine to coarse sand, (mainly fine to medium), moist. Some black soil in sample. SW 13/27 528.0 50/6 50 2500+ 8/12 14/17 55 326.0 7/10 Gray Brown, mainly medium to coarse sand, 10% gravel. 11/16 60 6/12 75.0 No gravel, moist. 19/26 65 6/11 11.0 10% fine gravel. 12/15 70 6/8 31.0 Orange Brown. 12/15 75 6/11 38.0 14/14 80 6/12 380.0 ▼: Groundwater Encountered @ 81', 13/12 Total Depth 82.0 feet. Terminated boring. Groundwater encountered @ 81.0'. Soil gas probes set @ 37', 50', 62' and 72'. 85 90

SIGNATURE \_\_\_\_



BORING I.D. NO. <u>TT-6</u>

Page 1 of 2

\_\_\_\_ REG. NO.\_\_\_

CLIEN	T	CKHEED	MAI	RTIN	T.C.	1768-05	LOCATION	GREAT NECK	DATE 8/24/98						
DRILL	METHOD	H	SA			AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST	Phil Skorge						
DEРТН (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	SJSN		GEOLOGI	C DESCRIPTION							
- 5 -	2/2 3/5	0.0	$\nabla$		SW										
- 10 -	8/9	0.0				SAND - Orange Brown, poorly sorted fine to coarse sand, 10% gravel, moist.									
	9/16	0.0	×	V ou	GW	Cobbles from 7' to									
- 15 -	9/17 20/22	150.0	X	0000		SANDY GRAVEL - medium gravel, fain	it odor, moist.	30% poorly sorted fine t							
- 20 -	8/9 8/8	91.0	X		SW	<u>GRAVELLY SAND</u> - gravel, faint odor,	·Yellowish Browi moist.	n, poorly sorted fine to	coarse sand 20%						
- 25 -	6/9 10/13		X	• • •		No recovery.		·							
- 30 -	4/7 8/10	2100			SC	<u>CLAYEY SAND</u> - G	ray, 40% fines, i	fine to medium sand, odd	or, damp.						
- 35 -	4/6 9/11	102.0			CL	SANDY SILTY CLA moist.	<u>Y</u> - Brown Gray,	non-plastic fines, 20%	fine sand, faint odor,						
45	7/9 12/13	820.0				Gray Black and Grawet, (perched wat	ay Green, trace er).	gravel, 40% fine to coa	rse sand, strong odor,						

REVIEWING GEOLOGIST Rich Baldwin SIGNATURE



BORING I.D. NO. TT-6

Page 2 of 2

\_\_\_\_\_ REG. NO.\_\_\_

CLIEN	T	CKHEED	MAI	NITR	т.с	1768-05	LOCATION	GREAT NECK	DATE <u>8/24/98</u>
DRILL	METHOD	H	SA			AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST	Phil Skorge
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	SOSO	_	GEOLOGI	C DESCRIPTION	
	4/7 7/7	2500+			CL		_		
- 50 -	7/13 19/22	23.0	×		SW	<u>SAND</u> – Gray Brow	n, poorly sorted	d fine to coarse sand, tr	ace gravel, damp.
- 55 -	9/11 14/26 7/10 16/23	35.0	X						
- 60 -	<b>4/</b> 5 8/8	141.0	X	• • •		Mainly fine to medi	um sand.		
- 65 -	4/6 7/5	34.0	X			Mainly coarse sand	l, 20% gravel.		
- 70 -	2/2 4/4	10.0	$\times$						
- 75 -	2/4 4/5	40.0	X						
- 80 -	2/2 <b>3/</b> 5	17.0	X	• • •		▼: Groundwater end Black sand @ 81.0 f		O feet.	
- 85 -						Total Depth 82.0 f Groundwater encou 70°.	eet. Terminated Intered @ 80.0 f	d boring. Backfill with be eet. Soil gas probes se	entonite chips. t at 30', 45', 60' and

REVIEWING GEOLOGIST Rich Baldwin SIGNATURE



BORING I.D. NO. TT-7

Page 1 of 2

CLIENT LOCKHEED MARTIN				T.C.	<u>1768</u> -05	LOCATION	GREAT NECK	DATE 8/28/98
DRILL	METHOD	<i>H</i>	'SA		AUGER DIAMETER	R <u>8.00" OD</u>	FIELD GEOLOGIST	Phil Skorge
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE GRAPHIC COLUMN	SOSO		GEOLOGI	C DESCRIPTION	_
			500	G₩				
			000			•		
			000					
- 5 -			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					
	4/6 9/11	0.0	<b>₽</b> 000					
			1 6 8					
- 10 -			2003					
	6/8 11/1 <b>4</b>	0.0		1	<u>SANDY GRAVEL</u> - moist.	- Dark Brown, 20%	fine to coarse sand, fir	ne to medium gravel,
		•	000					
- 15 -								
	6/9	0.0			40% sand.			
	11/12							
- 20 -			• • •	SW	GRAVELLY SAND (mostly fine to m	- Gray Brown, 101 edium), moist.	% gravel, poorly sorted t	fine to coarse sand,
20 -	8/10	0.0						
	11/14	0.0	$\boxtimes$ •••					
_	7/11 15/19	0.0			30% fines, trace (	gravel.		
- 25 -	6/13 15/20	0.0			10% fines, 10% gra	ivel.		
$\vdash$	6/9	0.0	• • •	-				
	10/12 5/6	0.0		SM	<u>SILTY SAND</u> - 40	)% fines, fine to c	oarse sand, mainly fine	sand, moist.
- 30 -	9/10	-	X					
	6/10 11/13	0.0	<b></b>					
	8/11 16/17	0.0		CL	SANDY CLAY - DO	ark Brown, non-pi	astic fines, 30% sand, m	ainly fine sand,
- 35 -	11/19 27/37	0.0		·SW	moist.			
	10/14	0.0	• • •	· 3#	<u> 28Mñ</u> - natk Rtoi	wn, poorly sorted	fine to coarse sand, 109	ե gravei, moist.
	19/23							
- 40 -	6/15 17/19	0.0						
<u> </u>	7/10 11/14	0.0						
$\vdash$	8/11 15/17	0.0			No recovery.			
45								
REVIE	WING GE	OLOGIST	r <u>Rich Ba</u>	aldwin	SIGNATURE	E		REG. NO



BORING I.D. NO. <u>TT-7</u>

Page 2 of 2

CLIEN	T	CKHEED_	MAF	RTIN	T.C.	<u> 1768-05</u>	LOCATION	GREAT NECK	_ DATE <u>8/28/98</u>						
	METHOD	<u> </u>	SA			AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST .	Phil Skorge						
DEРТН (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	SOSO	GEOLOGIC DESCRIPTION									
	6/9 11/14	0.0	$\searrow$	• • •	SW	10% fines, moderately sorted fine sand, trace gravel.									
	7/10 13/14	0.0		• • •		Light Brown, poorly	y sorted fine to	coarse sand.							
- 50 -	6/10 11/12	0.0		• • •											
	7/12 14/17	0.0				No fines.									
	8/10 11/14	0.0		•											
- 55 -	6/11 15/18	0.0													
	11/14 19/21	0.0		• • •											
- 60 -	10/14 17/23	0.0		• • •											
	8/10 11/15	0.3		• • •											
	7/14 12/14 7/9		X	• • •		No recovery.									
- 65 -	11/10 6/9	0.0	X	• • •											
	10/12 6/8	0.0	X	• • •											
- 70 -	11/14 9/15	0.0	X	• • •		No recovery.									
	17/21		X	• • •											
	NR	0.0		• • •		Not enough for lab	oratory sample	•							
- 75 -			$\times$												
	6/8 11/15			• • •		Mainly medium to c	oarse sand.								
- 80 -	2.44			• • •											
	6/11 12/14		$\times$	• • •											
						Total Depth 82.0 f	eet. Terminate	d boring. Set soil gas pr	obes at 34' and 60'.						
- 85 -									,						
90															
	WING GE	OLOGIS	T _	Rich B	Baldwin	SIGNATURE			REG. NO						



BORING I.D. NO. <u>TT-8</u>

Page 1 of 2

CLIEN'	T	KHEED	MAF	RTIN	т.с.	1768-05	LOCATION	GREAT NECK	DATE 8/31/98				
	METHOD	H	5 <u>A</u>			. AUGER DIAMETER	8.00" OD	FIELD GEOLOGIST	Phil Skorge				
ОЕРТН (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	SOSO		GEOLOGIC DESCRIPTION						
- 5 -			X	000000000000000000000000000000000000000	GW CN	Cobbles and grav No recov <b>e</b> ry.	el.						
- 15 -	8/27 29/30	0.0	X		SW	<u>SAND</u> – Dark Bro gravel, moist.	wn, poorly sorted	fine to coarse sand (m	ainly fine sand), 10%				
- 20 -	7/8 11/13	0.0	X			Yellowish Brown, r	nainly medium to c	coarse sand.					
	6/7 10/12 6/9 11/14	0.00	X			No gravel, even d	listribution of fine	, medium, and coarse sa	nd.				
- 25 -	5/7 6/10 7/8 11/14	0.0	$\times$										
- 30 -	7/9 10/13 6/11 15/17	1.0				Orange Brown 10% gravel, 10% fir	nes.						
- 35 -	11/14 17/18 6/19 27/29	0.0	X	• • •		No gravel							
- 40 -	8/14 15/18 8/11 15/17	0.0	X			30% gravel.							
45	7/11 12/15 9/15 21/22	32.0 5.0	Ŷ X		SC	CLAYEY SAND - sand, 10% gravel,	moist.	fines (non-plastic fines	), fine to medium				

REVIEWING GEOLOGIST Rich Baldwin

SIGNATURE \_\_

REG. NO.\_\_\_\_



BORING I.D. NO. TT-8

Page 2 of 2

REG. NO.\_\_\_\_

CLIEN	IT	CKHEED	MAI	RTIN	т.с.	<u> 1768-05</u>	LOCATION	GREAT NECK	_ DATE <u>8/31/98</u>
	METHOD		SA			AUGER DIAMETER	8.00 <u>" OD</u>	FIELD GEOLOGIST	Phil Skorge
DEPTH (feet)	BLOW	OVA (ppm)	SAMPLE	GRAPHIC	nscs		GE OL OG1	C DESCRIPTION	
	6/10	9.0			SC				100
	11/13 6/10	10.0	X		SW	<u>SAND</u> - Orange Br	rown, poorly sor	ted fine to coarse sand,	10% grave
	12/13		$\times$						
- 50 -	9/10 11/13	1.0	$\times$	•••					
	7/10 12/13	1.0	X						
	6/11	1.0							
- 55 -	12/15 7/10 12/14	0.0	X	• • •	•				
			$\times$	• • •					
	7/8 11/13	0.0	$\times$						
- 60 -	9/11 12/16	0.0	$\times$	• • •					
	6/10 11/14	0.0		•••		Dark Brown, mainly	/ coarse sand.		
	9/11	0.0		• • •		No gravel.			
- 65 -	11/14 4/5	0.0	Ž	• • •					
	7/7 5/7	0.0	$\times$			Orange Brown.			
	9/10	0.0	$\bigvee$	• • •		Orange brown.			
- 70 -			$\Diamond$						
	8/11 12/15	0.0							
				• • •					
- 75 -			$\times$	• • •					
	7/12 13/16	0.0							
	10,10			• • • ]					
- 80 -			$\times$						
	6/9 10/13	0.0				Ţ: Groundwater er		31.0 feet. ed boring. Groundwater e	ancountered 6 ~810
	1					feet. No odors. S	Soil gas probes	set @ 42' and 62'.	incountered & Folio
- 85 -		ı							
90									

REVIEWING GEOLOGIST Rich Baldwin SIGNATURE



CAS - LOCKHEAD MARTIN/GREAT NECK Project: Proj. No.

> Diameter (Inches)

> > 1.410

1.410

1.410

1.410

1.410

01880.001.009

Tested by:

K.H. K.H.

Sample:

TT2-40'

Length

(Inches)

5.985

5.985

5.985

5.985

5.985

1.

2.

3.

4.

5.

Date:

9-3-98

Entered by: Checked by:

R.S.A.

Remarks:

Dimensions of Specimen:

1. 2.

3.

4.

5.

Weight of Specimen:

Initial Weigh

330.6 Grams

Dry Weight

296.9 Grams

0.654 Lbs.

0.728 Lbs.

Moisture

Content:

11.35 %

Density, Wet Initial

134.77 pcf

5.985 In Avg.

1.410 In Ave.

Density, Dry

121.03 pcf

15.202 CM

1.561 In

10.074 CM

3.581 CM

Volume

9.3452768 In

0.0054081 Cfl.

Remarks:

1. Soil Description:

Yellowish Brown cmf SAND, little Silt, little mf Gravel

(visual)

2. Specific Gravity:

2.6909

## **DENSITY TEST**

CAS - LOCKHEAD MARTIN/GREAT NECK Project:

Proj. No.

01880.001.009

Tested by:

K.H. K.H.

Sample:

TT2-52'

Date:

9-3-98

Entered by: Checked by: R.S.A.

Remarks:

Dimensions of Specimen:

Dimensio	ons oi	Specimen:			<b>.</b>			•	Weight of Specimen:					
	_	Length (Inches)			Diameter (Inches)				Initial Weigh	<u>292.4</u>	Grams	;		
	1.	5.800		1.	1.410					<u>0.644</u>	Lbs.			
	2.	5.800		2.	1.410				Dry Weight	<u>262.5</u>	Gram	ì		
	3.	5.800		3.	1.410					<u>0.578</u>	Lbs.			
	4.	5.800		4.	1.410				Moisture Content:	11.39	%			
	<b>5</b> .	5.800		5.	1.410				COMMA.	11.07	~			
									Density, Wet Initial			<u>123.00</u>	pcf	
Avg.		<u>5.800</u>	In		Ave.	1.410	In		Density, Dry			<u>110.42</u>	pcf	
		<u>14.732</u>	СМ			<u>3.581</u>	СМ							
Area		<u>1.561</u>	In	2		10.074	CM <sup>2</sup>							
Volume		9.0564086	In		0.0052410 Cft.									

Remarks:

1. Soil Description:

Yellowish Brown cmf SAND, little Silt, little mf Gravel

(visual)

2. Specific Gravity:

2.6852

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

ı.

2.

3.

4.

Proj. No.

01880.001.009

Tested by:

K.H. K.H.

Sample:

TT2-62'

Length

(Inches)

5.985

5.985

5.985

5.985

5.985

5.985 In

Date:

9-3-98

Entered by: Checked by:

R.S.A.

Remarks:

Dimensions of Specimen:

ı.

2.

3.

4.

5.

Weight of Specimen:

Initial Weigh

296.9 Grams

0.654 Lbs.

Dry Weight

267.6 Grams 0.589 Lbs.

Moisture

Content:

10.95 %

Density, Dry

Density, Wet Initial

Diameter

(Inches)

1.410

1.410

1.410

1.410

1.410

Ave.

121.03 pcf 109.08 pcf

15.202 CM

3.581 CM

1.410 In

Area

Avg.

2 1.561 In

10.074 CM

Volume

9.3452768 In

2

0.0054081 Cft.

Remarks:

1. Soil Description:

Yellowish Brown cmf SAND, trace Silt, trace mf Gravel

(visual)

2. Specific Gravity:

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

Proj. No.

01880.001.009

Tested by:

K.H. K.H.

Sample:

TT2-72'

Date:

9-3-98

Entered by: Checked by:

R.S.A.

Remarks:

Dimensions of Specimen:

Length Diameter (Inches) (Inches) 1. 1.410 1. 5.800 2. 5.810 1.410 1.410 3. 5.800 3. 4. 5.800 4. 1.410 5. 5.800 5. 1.410

2

Weight of Specimen:

 Initial Weigh
 309.4
 Grams

 0.681
 Lbs.

Dry Weight 272.9 Grams

<u>0.601</u> Lbs.

Moisture

Density, Wet Initial

Density, Dry

Content: <u>13.37</u> %

130.10 pcf

114.75 pcf

5.802 In Ave. 1.410 In

3.581 CM

<u>14.737</u> CM

10.074 CM

Area <u>1.561</u> In

0.0052428 Cft.

Remarks:

Volume

Avg.

1. Soil Description:

9.0595315 In

Brown cmf SAND, trace Silt, trace mf Gravel

(visual)

2. Specific Gravity:

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

1.

2.

3.

5.

Proj. No.

01880.001.009

Tested by:

K.H. K.H.

Sample:

TT2-82'

Length

(Inches)

5.800

5.800

5.800

5.800

5.800

Date:

9-3-98

Entered by: Checked by: R.S.A.

Remarks:

Dimensions of Specimen:

1.

2.

3.

4.

5.

Weight of Specimen:

Initial Weigh

312.3 Grams

0.688 Lbs.

0.603 Lbs.

Dry Weight

273.9 Grams

Moisture

Content:

<u>14.02</u> %

Density, Wet Initial

131.37 pcf

5.800 In Avg.

1.410 In

Density, Dry

115.21 pcf

14.732 CM

3.581 CM

2 1.561 In

10.074 CM

Volume

9.0564086 In

0.0052410 Cft.

Diameter

(Inches)

1.410

1.410

1.410

1.410

1.410

Ave.

Remarks:

1. Soil Description:

Brown cmf SAND, trace Silt, trace mf Gravel

(visual)

2. Specific Gravity:

CHAIN OF CUSTODY/LABORATORY ANALYSIS REQUEST FORM

1 Mustard S., Suite 250, P.O. Box 90859, Rochester, NY 14609-0859 (716) 288-5380 • FAX (716) 288-8475

(800) 695-7222

	_/ / _		
DATE	8/24/98	PAGE A	) OF /

PROJECT NAME														NAL				EST	ED							
PROJECT MANA 3ER/CONTA	ACT //	nork	111:1501							_		<b>"</b>	و	S i										PRES	ERVA	MOITA
						ર્			GC VOA's		VOA's	SVOA's	H D	WASTE CHARACTERIZATION  ☐ React ☐ Corros. ☐ Ignit.												
Mustar LL.	$\mathcal{K}$	och.	NY- 1460	9		INE	4	52	9	CB's	221 721	270 ICLF	ALS VOA	STOS	ر ہا	SOLV			}							
TEL ( )		_ FAX (	)	_=		OF CONTAINERS	GC/MS VOA's □ 8260 □ 624	ĕ¤	020	DES/F	IST 8	IST 8	MET	AAR CAR	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	DISS LOW)		l		}						<u> </u>
SAMPLER'S SIGNATURE						آ ا	MS V 260	MS S 270A	VOA:	3TICIE	R'S L OTAL	R'S L	P. P. □	STE C	TALS.	TALS,		ļ	}	}				< 2.0	> 12	ĕ
SAMPLE I.D.	DATE	TIME	LAB I.D.	SA M/	MPLE	10	Ç   0   0   0   0   0   0   0   0   0   0	\0 0 0 0 0 0 0	ပ္ပဋ	PES C	STA	STA	[달合	×□	RES	RES EIS		ļ		 				됩	표	Other
TT2-40' 8	6148		234243		il	1												-								
TT2-52'			234244			1	<u> </u>							<u> </u>				<u> </u>	<u> </u>							
772 -62' 772 - 72'			234295		<u> </u>	1						<u> </u>		L			<u>_</u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>					
TT2 - 72'	_		234296		L	Ш									<u> </u>		<u> </u>		<u> </u>	<u> </u>	<u> </u>					
TT2-82'	V		234297			j																				
·																				<u> </u>						
RELINQUI SHED BY:			RECEIVED BY:	_	TURN	AROU	ID REC	UIREN	ENTS		PORT		REMEI	NTS		INVO	CE IN	FORMA	ATION:			SA	MPLE	RECEI	PT:	$\overline{}$
Tom Hastings		Signature			_ 24	hr	48 hr.	5	day		Rouline Rouline		CASE		P.O. #	:					Shinni	na Via	UF	25 7	el	' I
Printed Hastings		Printed Nam	B		-   Sta	ndard (1	0-15 wo	rking da	ys)		Narrativ EPA Lev					· ·										
8/24/98 16:00	<del>5</del>	Firm			_ Pro	vide Ver	bal Preli	minary F	Results	_	Validata		kage		l —		_					-				
Date/Time		Date/Time			Pro	vide FA	( Prelimi	inary Re	sults		N.J. Red Delivera				l —						l					[
RELINQUISHED BY:	l,		RECEIVED BY:		Reques	ited Rep	ort Date		]	5.	NY ASP Site spe	/CLP D	eliverab	les							Submi	ssion No	o: _ <b>&amp;</b>	? <b>-3</b>	//_	
Signature		Signature			<del> </del>						<u> </u>		<u>.                                    </u>		<u> </u>						<u> </u>					
Printed Name		Printed Nam	е		SPE	CIAL	NSTR	UCTR	ONS/C	ОММ	ENTS	:														
Firm		Firm			MET	ALS																				[
Date/Time  RELINQUISHED BY:		Date/Time	RECEIVED BY:		ORG	ANIC	s:_ 🗆	TCL	□ Pf	PL [	] AE	Only	□в	N Onl	<u>у</u> 🗆	Speci	al List	t								
Signature		Signature			-						_															
Printed Name	l	Printed Nam	e		-   ̄																					}
Firm	—— <b> </b>	Firm	<del>-</del>		65 F	AMA	PO V	ALLF	Y RO	ΑŊ	·		201-5	12-3	292	309	WES	T RID	LEY	AVE				6′ 5	21-3	083
Date/Time		Date/Time					i, NJ			1		FAX:	201-5	12-3	362				, PA				FAX	<u>(</u>	21-4	589

# **DENSITY TEST**

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

Proj. No.

01880.001.009

Tested by: Entered by:

K.H. K.H.

Sample:

TT4-50'

Date:

9-3-98

Checked by: R.S.A.

Remarks:

Dimensions of Specimen:

_	Length (Inches)	_	Diameter (Inches)
1.	5.980	1.	1.410
2.	5.982	2.	1.410
3.	5.983	3.	1.410
4.	5.984	4.	1.410
5.	5.985	5.	1.410

2

Weight of Specimen:

Initial Weigh 320.0 Grams 0.705 Lbs. Dry Weight 277.8 Grams 0.612 Lbs. Moisture

Content:

Density, Dry

<u>15.19</u> %

Density, Wet Initial

130.49 pcf 113.28 pcf

<u>5.983</u> In

3.581 CM

15.196 CM

1.410 In

1.561 In Area

10.074 CM

Volume

Avg.

9.3418416 In

0.0054062 Cft.

Ave.

Remarks:

1. Soil Description:

Brown cmf SAND, little Silt, little mf Gravel

(visual)

2. Specific Gravity:

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

1.

2.

Proj. No. 01880.001.009

K.H.Tested by:

Sample:

TT4-60'

Date:

9-3-98

Entered by: Checked by: R.S.A.

KH

Remarks:

Dimensions of Specimen:

ı.

2.

5.

Weight of Specimen: Initial Weigh

Diameter (Inches) 1.410

300.7 Grams

5.985 5.985

5.985

Length

(Inches)

0.662 Lbs.

3. 5.985 Dry Weight

264.4 Grams

1.410

1.410

0.582 Lbs.

5.985 4.

1.410 1.410

Moisture Content:

13.73 %

Density, Wet Initial

122.58 pcf

Avg. 5.985 In Ave. 1.410 In Density, Dry

107.78 pcf

15.202 CM

3.581 CM

Area

2 1.561 In

2 10.074 CM

Volume

9.3452768 In

0.0054081 Cft.

Remarks:

1. Soil Description:

Brown cm+f SAND, trace (+) Silt

(visual)

2. Specific Gravity:

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

Proj. No.

01880.001.009

Tested by:

K.H. K.H.

Sample:

TT4-70'

Date:

9-3-98

Entered by: Checked by: R.S.A.

Remarks:

Dimensions of Specimen:

Weight of Specimen:

Density, Wet Initial

Density, Dry

Diameter Length (Inches) (Inches) 1. 5.985 ı. 1.410 2. 5.988 2. 1.410 3. 5.985 3. 1.410 4. 5.989 4. 1.410 5.985 5. 1.410 5.

Initial Weigh 324.6 Grams 0.715 Lbs. Dry Weight 277.3 Grams 0.611 Lbs. Moisture <u>17.06</u> % Content:

1.410 in

132.29 pcf

113.01 pcf

15.205 CM

5.986 In

3.581 CM

2 <u>1.561</u> In Area 3

2 10.074 CM

Volume

Avg.

9.3474629 In

0.0054094 Cft.

Ave.

Remarks:

1. Soil Description:

Brown cmf SAND, trace Silt, trace mf Gravel

(visual)

2. Specific Gravity:

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

Proj. No. 01880.001.009 Tested by:

KН K.H.

Sample:

TT6-30'

Length

Date:

9-3-98

Entered by: Checked by: R.S.A.

Remarks:

Dimensions of Specimen:

2.

Weight of Specimen:

(Inches) (Inches) 5.985 1. 1. 1.410

5.985 2. 1.410

3. 5.985 1.410

5.985 1.410 4.

1.410 5.985

Initial Weigh 349.9 Grams

0.771 Lbs.

Dry Weight

313.2 Grams

0.690 Lbs.

Moisture

Content:

11.72 %

Density, Wet Initial

Density, Dry

142.63 pcf

127.67 pcf

15.202 CM 3.581 CM

2 1.561 In

10.074 CM

Volume

Avg.

9.3452768 In

5.985 In

0.0054081 Cft.

Ave.

Diameter

Remarks:

1. Soil Description:

Brown cmf SAND, trace Silt, trace mf Gravel

1.410 in

(visual)

odorous

2. Specific Gravity:

# COLJI. IA ANALYTICAL SERVICES, INC.

1 N ustard St., Suite 250, Rochester, NY 14609-6925 (716) 288-5380 • FAX (716) 288-8475

# CHAIN OF JSTODY/LABORATORY ANALYSIS REQUE? FORM

(800) 695-7222

DATE 8/25 /98 PAGE / OF /

PROJECT NAM.:						Γ										RE	QUI	EST	ED							
PROJECT MANAGER/CO	ONTACT A	Mark	Wilson									s	٩	SE										PRES	ERVA	NOIT
						S	95-1	95-2		95-3	)A's	VOA	E E	ZATI Pos		۵					1 1					
COMPANY/ADDITESS	! A-	och.	NY 1460	19		CONTAINERS	4	2	1/602	CB's	STAR'S LIST 8021 VOA'S	270 SI ICLP	ALS /OA's	CTER orros.	 ا بر	DISSOLVED										
TEL( )		FAX (	)			A F	)A's □ 62	0A9	09 🗆	ES/P	ST 8	ST 8	MET.	AR C	TOTAL LOW)	OISS OW)								<u> </u>		
SAMPLER'S SIGNATURE						8	\$ V C	18 S/	0A's	FICID 1	T'S LI	TS LI	.×.□	로 로 로 로	METALS, 7 (LIST BEL	METALS, ( (LIST BEL					} }			2.0	12	_
SAMPLE I.D.	DATE	TIME	FOR OFFICE USE ONLY LAB 1,D,	SA M/	MPLE	# P	GCA B2A	6C 82 82 0	၁၉	PES BO	STAF	STAF		WAS	MET, (LIST	MET,								Ρ̈́Α	v Hd	Other
714-50'	8/x/A	-	234780	Se	ī.l	1																				
			234781			1																				
TT4-60'			234782			1																				
776-301	<b>↓</b>		234789	7		ر																				
															_	_										
																						_				
																				-						_
RELINQUISHED B	Y:		RECEIVED BY:		TURN						PORT I		REMEN	ITS		INVO	CE INF	ORMA	TION:			SA	MPLE I	RECEIP	Τ:	
Signatura Hasting		Signature			1		48 hr.			2.	Routine Routine	Rep. w/	CASE		PO. #	:					Shippin	ng Via:	ups	-Pa	<u> </u>	
Partied dame		Printed Nam	8		ł	-	0-15 wor bal Prelir	-		3.	Narralivi EPA Lev	el III			Bill To:						Shippin	ng#: _				[
Date/Time	00	Firm Date/Time			J		( Prelimi	•			Validatai N.J. Red		kage							_	Tempe	rature: _				
RELIN JUISHED B	Y:		RECEIVED BY:		Requesi	led Rep	ort Date	<u> </u>	_	5.	Delivera Ny ASP	/CLP De	eliverable	es							Submis	ssion No	8	<sup>3</sup> -3	//	_
Signature		Signature									Site spe															[
Printed Name		Printed Nami	e				NSTR	UCTIC	)NS/C	OMM	ENTS:	•														ĺ
Date/Time		Date/Time			META	ALS																				_
RELINQUISHED B	Y:		RECEIVED BY:		ORG.	ANICS	S: []	TCL	☐ Pf	<u> PL [</u>	AE (	Only		N Only		Specia	l List									_
Signature		Signature	<del></del>																							_
Printed Name		Printed Name	e				_										_								_	
Pate/Time		Firm Date/Time							1	\																
DAIGHTHIU		Date: Hille			Ь——				- )	<del>-</del> -													_	<b>)</b> —		

# **DENSITY TEST**

Project:

CAS - LOCKHEAD MARTIN/GREAT NECK

1.

2.

3.

4.

5.

01880.001.009 Proj. No.

Tested by:

K.H.

Sample:

TT6-40'

Length

(Inches)

5.985

5.985

5.985

5.990

5.989

5.987 In

Date:

9-3-98

Entered by: Checked by: R.S.A.

K.H.

Remarks:

Dimensions of Specimen:

1.

2.

3.

4.

5.

Weight of Specimen:

Initial Weigh

358.2 Grams

0.789 Lbs.

Dry Weight

322.3 Grams 0.710 Lbs.

Moisture

Content:

11.14 %

Density, Wet Initial

Density, Dry

145.97 pcf

131.34 pcf

15.206 CM

1.410 In 3.581 CM

Area

10.074 CM

1.561 In 9.3480874 In Volume

0.0054098 Cft.

Diameter

(Inches)

1.410

1.410

1.410

1.410

1.410

Ave.

Remarks:

Avg.

1. Soil Description:

Brown cmf SAND, some clayey Silt, little mf Gravel

(visual)

2. Specific Gravity:

## CO. ""BIA ANALYTICAL SERVICES, INC.

ard St., Suite 250, Rochester, NY 14609-6925 (716) 288-5380 • FAX (716) 288-8475

# CHAIN O' CUSTODY/LABORATORY ANALYSIS REQU

(800) 695-7222

DATE 8/25-198 PAGE 1 OF 1

PROJECT NAME PROJECT MAIAGER/CONTACT Mark Willam COMPANY/AC DRESS CAS I MULTIA St. Rock N.Y. 14609 TEL( ) FAX( ) SAMPLERIS S GNATURE  SAMPLERIS S GNATURE  SAMPLE I.D. DATE TIME FOR OFFICE UNITY MAIR ST. DATE TO BE SET OF SAMPLE LABID.  SAMPLE I.D. DATE TIME FOR OFFICE UNITY MAIR ST. DATE MAIR ST	
CONTACT   CONT	ATION
CONTACT   CONT	
	Other
	$\Box$
	$t^-$
	╁
	╁—
	<u> </u>
	<b>!</b> .
RELINC. JISHED BY:  RECEIVED BY:  TURNAROUND REQUIREMENTS  REPORT REQUIREMENTS  INVOICE INFORMATION:  SAMPLE RECEIPT:  1. Routine Report  2. Routine Report  2. Routine Report  2. Routine Report  2. Routine Report  3. Routine Report  4. Routine Report  4. Routine Report  4. Routine Report  5. Routine Report  6. Routine Report  7. Routine Report  8. Routine Report  9. Routine Report  1. Routine Report  2. Routine Report  3. Routine Report  4. Routine Report  4. Routine Report  5. Routine Report  6. Routine Report  6. Routine Report  7. Routine Report  8. Routine Report  9. Routine Report  1. Routine Report  2. Routine Report  3. Routine Report  4. Routine Report  4. Routine Report  5. Routine Report  6. Routine Report  7. Routine Report  8. Routine Report  9. Routine Report  1. Routi	<u></u>
Shipping Via: Warraine Shipping Via: W73 12X	
Printed Name Printed Name Provide Verbal Preliminary Results Provide Verbal Preliminary Results  Bill To:	
Firm	
RELINQ JISHED BY:  REQUESTED Requested Report Date  Deliverables Level IV	<u></u>
Signature Signature Signature Signature Signature Special INSTRUCTIONS/COMMENTS:	
Firm Firm	
Date/Time Dete/Time METALS	
RELING JISHED BY:  RECEIVED BY:  ORGANICS: ☐ TCL ☐ PPL ☐ AE Only ☐ BN Only ☐ Special List	
Signature Signature —	
Printed Name Printed Name	
Date/Time Firm Date/Time	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID :TT2-10'

Date Sampled: 08/20/98 Date Received: 08/22/98		#:234290 #:9808000311		Sample Matrix:SOIL/SEDIMEN				
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION			
PERCENT SOLIDS	1.0	94.1	8	09/03/98	1.0			

Reported: 09/28/98

Tetra Tech Inc.
Project Reference: GREAT NECK PLUME
Client Sample ID : TT2-22'

Date Sampled: 08/20/98 Date Received: 08/22/98		#:234291 #:9808000311		Sample Matrix:SOIL/SEDIMENT				
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION			
PERCENT SOLIDS	1.0	96.4	8	09/03/98	1.0			

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME

Client Sample ID :TT2-34'

Date Sampled: 08/21/98 Date Received: 08/22/98		#:234292 #:9808000311		Sample Matrix:SOIL/SE						
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION					
PERCENT SOLIDS	1.0	90.5	8	09/03/98	1.0					

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT2-40'

Date Sampled: 08/21/98 Date Received: 08/22/98		#:234293 #:9808000311		Sample Matrix:SOIL/SEDIMENT					
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION				
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0	95.8 0.100 U	8	09/03/98 09/09/98	1.0				

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID : TT2-52'

Date Sampled: 08/21/98 Date Received: 08/22/98		#:234294 #:9808000311		Sample Matrix:SOIL/SEDIMENT				
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION			
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0	86.7 0.100 U	<b>%</b>	09/03/98 09/09/98	1.0			

Reported: 09/28/98

Tetra Tech Inc.
Project Reference: GREAT NECK PLUME
Client Sample ID : TT2-62'

Date Sampled: 08/21/98 Date Received: 08/22/98		#:234295 #:9808000311		Sample Matrix:SOIL/SEDIMENT				
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION			
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0 0.10	94.7 0.43	8	09/03/98 09/0 <b>9</b> /98	1.0			

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT2-72'

Date Sampled:08/21/98 Date Received:08/22/98		#:234296 #:9808000311		Sample Matrix:SOIL/					
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION				
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0 0.10	95.4 0.24	<b>%</b>	09/03/98 09/09/98	1.0				

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT2-82'

Date Sampled: 08/21/98 Date Received: 08/22/98	_	Order #:234297 Submission #:9808000311		Sample Matrix:SOIL/SEDIMEN		
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0 0.10	91.5 0.19	g g	09/03/98 09/09/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT4-10'

Date Sampled: 08/24/98 Date Received: 08/25/98	_	Order #1234774 Submission #:9808000311		Sample Matrix: SOIL/SEDIMENT		
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS	1.0	88.9	8	09/15/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID : TT4-18'

Date Sampled: 08/24/98 Date Received: 08/25/98 ANALYTE		der #:234776 ion #:98080003	11	Sample Matrix: SOIL/SEDIMENT		
	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS	1.0	95.0	8	09/15/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT4-30'

Date Sampled: 08/24/98 Date Received: 08/25/98 ANALYTE	Order #:234777 Submission #:9808000311		11	Sample Matrix:SOIL/SEDIMENT		
	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS	1.0	87.7	8	09/15/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.
Project Reference: GREAT NECK PLUME
Client Sample ID : TT4-36'

Date Sampled: 08/24/98 Date Received: 08/25/98  ANALYTE		er #:234779 on #:98080003	11	Sample Matrix:SOIL/SEDIMEN		
	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS	1.0	90.9	8	09/15/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT4-50'

Date Sampled: 08/24/98 Date Received: 08/25/98		Order #:234780 Submission #:9808000311		Sample Matrix:SOIL/SEDIMEN		
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0 0.10	94.0 0.30	<b>%</b>	09/09/98 09/09/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID :TT4-60'

Date Sampled:08/24/98 Date Received:08/25/98		er #:234781 on #:9808000311		Sample Matrix:SOIL/SEDIMEN		
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0	95.7 0.36	8	09/09/98 09/09/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.
Project Reference: GREAT NECK PLUME
Client Sample ID : TT4-70'

Date Sampled: 08/24/98 Date Received: 08/25/98		Order #:234782 Submission #:9808000311		Sample Matrix:SOIL/SEDIMEN		
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0	92.3 0.64	8	09/09/98 09/09/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.
Project Reference: GREAT NECK PLUME
Client Sample ID : TT4-80'

Date Sampled:08/24/98 Date Received:08/25/98  ANALYTE	Order #:234783 Submission #:9808000311		11	Sample Matrix: SOIL/SEDIMENT		
	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS	1.0	90.4	&	09/15/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT6-10'

Date Sampled: 08/24/98 Date Received: 08/25/98	Order #:234787 Submission #:9808000311			Sample Matrix: SOIL/SEDIMENT		
ANALYTE	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS	1.0	94.7	8	09/15/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.
Project Reference: GREAT NECK PLUME
Client Sample ID : TT6-20'

Date Sampled: 08/24/98 Date Received: 08/25/98  ANALYTE		der #:234788 ion #:98080003	11	Sample Matrix: SOIL/SEDIMEN		
	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS	1.0	92.5	8	09/15/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.
Project Reference: GREAT NECK PLUME
Client Sample ID: TT6-30'

Date Sampled: 08/24/98 Date Received: 08/25/98  ANALYTE	•	Order #:234789 Submission #:9808000311		Sample Matrix:SOIL/SEDIMEN		
	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION	
PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0	91.7 0.98	8	09/09/98 09/09/98	1.0	

Reported: 09/28/98

Tetra Tech Inc.

Project Reference: GREAT NECK PLUME Client Sample ID: TT6-35'

Date Sampled: 08/24/98 Date Received: 08/25/98  ANALYTE		#:234790 #:9808000311	Sample Matrix: SOIL/SEDIMENT		
	PQL	RESULT	UNITS	DATE ANALYZED	ANALYTICAL DILUTION
PERCENT SOLIDS	1.0	90.0	8	09/15/98	1.0

Reported: 10/06/98


Tetra Tech Inc.

Project Reference: GREAT NECK PLUME


Client Sample ID :TT6-40'

Date Sampled : 08/24/98 Date Received: 08/25/98 Order #: 234791 Submission #:9808000351 Sample Matrix: SOIL/SEDIMENT


ANALYTE	PQL	RESULT	DRY WEIGHT DATE UNITS ANALYZED	ANALYTICAL DILUTION	
WET CHEMISTRY PERCENT SOLIDS TOTAL ORGANIC CARBON	1.0	89.7 0.220	ት 09/09/98 ት 09/09/98	1.0	




# **SOIL VAPOR PROBE SCHEMATIC TT-1**




# **SOIL VAPOR PROBE SCHEMATIC TT-3**




# **SOIL VAPOR PROBE SCHEMATIC TT-5**




#### SOIL VAPOR PROBE SCHEMATIC TT-6



#### **SOIL VAPOR PROBE SCHEMATIC TT-7**



#### **SOIL VAPOR PROBE SCHEMATIC TT-8**





### On Site Soil • Soil Vapor • GH<sub>2</sub>0 Sampling and GCMS Analysis



October 1, 1998

Nisha Bansal TetraTech 670 N. Rosemead Pasadena, CA 91107-2160

Dear Nisha:

Enclosed please find the report on the soil vapor sampling/analysis performed at the Lockheed-Martin facility in Great Neck, N.Y. between August 27 and September 4, 1998. You will find one bound and one unbound copy with the following sections:

i. Technical approach with results and discussion.

ii. Spreadsheets of results.

iii. Raw data in LARWQCB format.

iv. QA/QC section in LARWQCB format.

v. Chromatograms (unbound copy only).

If you have any questions or additional requirements, please do not hesitate to call. It was a pleasure working with you, and I look forward to future projects.

Sincerely,

Raphe Pavlick

Director



#### SOIL VAPOR TECHNICAL APPROACH

Nested soil vapor probes were installed using an auger rig as follows: after maximum depth was reached, a one-quarter inch polyethylene probe was dropped to the bottom, surrounded by approximately 1 foot of #3 sand, the grouted to the next depth where another probe was dropped and the procedure repeated until all the probes were installed. The probes were allowed to sit at least one day to reach equilibrium conditions in the subsurface. Sampling is done as follows: The tubing exiting the surface of the ground is connected to a glass sampling bulb fitted with Teflon stopcocks and a viton rubber sampling port. This bulb is connected in turn to a vacuum gauge, flowmeter, and portable sampling pump. Initially both stopcocks are closed, and the absence of flow and the presence of a slight vacuum is noted. This demonstrates that the sampling train on the far end of the bulb is leak-tight. Then the first stopcock (pump end) is opened; the absence of flow demonstrates that the sampling bulb itself is leaktight. The ground end of the bulb is then opened, and a flow of 0.6 cfm is maintained for seven to ten purge volumes. During the sampling an open container containing a pentane-soaked kimwipe is exposed to the sampling train. Any trace of pentane detected in the sample indicates the intrusion of ambient air into the sampling train, invalidating the results of that sample. No such leaks were detected with any of the samples. The stopcocks were then closed (pump end first), and the sample retained in the container. Approximately 25 NG each of deutero-chloroform, deuteroacetone, deuterated-methylene chloride, deuterated-toluene and deutero-benzene were added through the septum into the bulb. The recovery of these isotopically-labeled surrogate compounds demonstrates that the bulbs have remained leak-free up until the actual analysis. A recovery of 90% is desirable; a recovery of less than 75% invalidates the sample results. These bulbs were then delivered to the mobile laboratory for analysis by GCMS.

The <u>analyses</u> of the soil vapor samples proceeded as follows. A 1 ml aliquot of soil vapor was withdrawn from each bulb and injected into a Hewlett-Packard model 5890 gas chromatograph interfaced to a Hewlett-Packard model 5972 mass spectrometer. Chromatography was performed in such a way that the combination of retention times and mass fragmentation allowed for the complete separation of all the target compounds. The mass spec was operated in *full scan* mode between 35 and 350 amu. This allows for the identification of any volatile organic species that may be present in the soil vapor.

The following laboratory QA/QC was performed. An initial five-point calibration was run on July 10, 1998. A laboratory control standard (LCS) from Absolute Standards Volatiles Mix was run at the end of the same day and at the end of the sampling days. The daily standard, run on the sampling days, was made from Supelco certified Custom 1 mix. The initial calibration was also run on this standard stock. The surrogate calibration curve was run on Aldrich certified material. All results were within the LAWQCB and HGS requirements.

Two notable additions to the LAWQCB requirements were deemed necessary:

- i. Five isotopically-labeled surrogates, D6-Benzene, D2-Methylene Chloride, D8-Toluene, D6-Acetone and D-Chloroform, were added to the collection vessel, a 125-ml glass bulb fitted with Teflon stopcocks and a viton rubber septum, to measure recovery percentages. The benzene, toluene, methylene chloride and chloroform surrogates are used to verify the recovery of the BTEX and chlorinated hydrocarbons respectively; a recovery of at least 90% is desired. The deuterated acetone is a measure of the possible presence of water vapor in the sample and general condition of the chromatographic system in terms of hydration; a recovery of 75% indicates acceptability of the complete sampling and analysis procedure; below this level, water vapor presence in the sampling line should be investigated or chromatographic dehydration procedures should be considered.
- ii. Isopentane vapor was used to surround the sampling train at the surface to identify possible ambient intrusion into the sampling train or down the outside surface of the sampling tubing connected to the subsurface.

#### RESULTS AND DISCUSSION

Only one sample failed surrogate recovery requirements, TT1-72; this sample was retaken and analyzed again with good surrogate recovery.

Two different purge volume tests were performed to verify the slightly lower number of purge volumes that were required as well as the narrower range of acceptability. This probably had to do with the soil types or amounts of moisture in the soils.

The rebounds in general showed increases with time, mainly with the "heavier" compounds such as PCE and, to a lesser degree, PCE. The rebounds were taken approximately six days after installation, whereas the normal samples were taken two days after installation.

Two duplicates were taken on the same day, and these results were within acceptable range. It should be noted that small differences exist in rounding of numbers between the LARWQCB forms and the EXCEL spreadsheet; the differences are insignificant, generally having to do with decimal points, and should be of no concern.

All QA/QC requirements of both HydroGeoSpectrum (HGS) and LARWQCB were met.

LOCATION-	VC	1,1-DCE	1,2-DCE	1,1,1-TCA	TCE	PCE	BTEX	нс	Freon-113	OTHER			
DEPTH(ft)	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L			
TT1-62	0.6	N	4.2	N	6.3	6.5	N/1.9/N/N	N.	6.6	N			
TT1-72 low surr	1.1	<b>N</b>	9.6	N	5.2	6.3	N/1.4/N/N	N	6.4	N N	]		
TT1-72	4.3	N	15	N	1.8	2.3	N	N	12	N	1		
TT3-52	N	N	4.4	Ñ	2.5	4.7	N/1/N/N	N	2.3	N			
TT3-62	N	Ň	N	Ñ	1	2.5	N	N	N	N			
TT3-72	N	N	Ñ	Ň	1	1.6	N/0.6/N/N	N	1.1	N			
TT5-37	4.9	72	1849	145	11214	3410	6.8/1673/24/52	1000	5693	PCA,Fr11,I	12,PC	A, Chlorof	orm
TT5-62	N	2.5	166	13	6296	2938	4.5/1498/N/N	90	104	N			
TT5-73	N	N	32	2.1	1678	1685	0.9/615/24/61	N	25	N			
TT6-29	9.6	52	1911	5.3	778	592	1.8/132/2.6/N	N	361	DCM,Chlorofe	orm		
TT6-29rebound	8.4	63	2744	4	886	923	1.6/150/6.1/N	210	311	DCM			
TT6-38	9.7	54	468	23 26	3064	720	10/351/3.9/1.8	400	2714	DCM,DCA,Fr	11		
TT6-38 rebound	7.1	Ň	404	26	3643	544	9.8/168/3,2/N	300	3492	DCM,DCA,Ch	loroform.		
TT6-60	N	0.6		N	141	33	N/27/N/N	N	16	N	1		
TT6-60rebound	N	Ň	19 49	0.7	663	399	0.6/125/3.4/N	N	N	N			
TT6-70	N	N	45	N	91	33	N/16/N/N	N	13	N	ļ		
TT6-70 rebound	N	Ñ	23	Ñ	388	85	0.5/41/N/N	N	3.5	N	!		
TT7-34	N	Ń	23 N	N	2.7	2.4	N/1.1/N/N	N	N	N	ļ		
TT7-60	N	N	N I	N	3.3	3.3	N/1.1/N/N	N	0.8	N	1		
TT8-42	2.6	N	449	1.2	447	127	N/0.4/N/N	30	86	N			
TT8-42 dup	2.1	N	368	1	325	66	N	20	72	N			
TT8-62	N	N	0.9	N	1.2	0.9	N	N	0.7	N			
TT8-62 dup	N	N	0.6	N	1.2	1	N	N	0.8	N		1	

VC = Vinyl Chloride

DCE = Dichloroethylene

TCA = Trichloroethane

TCE = Trichloproethylene

PCE = Tetrachloroethylene BTEX = Benz/Tol/ EthylBenz/Xylenes HC = Hydrocarbons DCA = Dichloroethane
PCA = Tetrachloroethane
DCM = Methylene Chloride

# DATA

MINDISI. Kapite Favilek				CODDLCTOR.		Rodney brot			THOTROHEM	I ID.	ZTIJNUZ	01	
NORMAL INJECTION VOLUME		1 ml											
Sample ID:			TT6			тт6			ттє			TT6	
		V	OB8281-09	032	V	OB8282-0903	33	1	OB8283-09	034	V	OB8283D-09	9034
Sampling Depth (ft)			29			70			38			38 df	i i
Purge Volume (ml)			3075			5125			3525			3525	
Vacuum			NO			NO			ио			NO	
Sampling Time			27Aug			27Aug			27Aug			27Aug	
Injection Time			1149			129			1227			1459	
Injection Volume			1ml			1ml			1ml			0.2ml	
Dilution Factor			1			1			1			5	
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	RТ	AREA	CONC
Vinyl Chloride	MS	1.85	9817	9.5				1.78	9931	9.6			
1,1-Dichloroethene	MS	4.26	101804	52:0				4.21	106206	54.3	4.14	20345	52.0
Methylene Chloride	MS	3.10	1130	0.5	3.07	961	0.4	3.05	94106	41.9	2.98	18159	40.4
1,2-Dichloroethene (total)	MS	5.03	9043340	1911.2	5.01	211694	44.7	5.00	2214427	468.0	4.95	442514	467.6
1,1-Dichloroethane	MS							4.77	37195	8.7			
Chloroform	MS	5.31	2021	0.5				5.27	31829	7.8			
1,1,1-Trichloroethane	MS	6.27	18123	5.3				6.26	76598	22.5			
Benzene	MS	7.74	12787	1.7				7.74	72894	10.1			
Trichloroethene	MS	7.48	2498548	777.5	7.47	291616	90.7	7.47	8837211	2750.2	7.42	1969022	3063.9
Toluene	MS	10.73	634100	132.3	10.71	77440	16.1	10.72	1682390	351.0	10.67	335861	350.4
Tetrachloroethene	MS	9.96	1481638	591.6	9.95	81567	32.5	9.94	1803930	720.3	9.90	382620	763.9
Ethylbenzene	MS	13.12	7950	2.6				13.15	11811	3.9			
Xylene (total)	MS							16.70	26606	1.8			
FREON-11	MS							3.99	22142	5.1			
FREON-113	MS	5.57	1592382	361.0	5.54	57334	13.0	5.54	11363258	2576.1	5.49	2394744	2714.5
Deutero-chloroform	MS	5.28	51827	81%	5.27	55682	87%	5.25	64095	101%	5.19	12476	98%
D6-BENZENE	MS	7.67	118390	83%	7.66	127198	89%	7.65	130998	918	7.61	26495	92%
D6-ACETONE	MS	3.26	71664	93%	3.22	69678	90%	3.20	75248	98%	3.12	14676	95%
D2-Dichloromethane	MS	3.08	43888	91%	3.06	43614	90%	3.05	46640	968	2.96	9785	10]%
D8-TOLUENE	MS	10.63	56857	81%	10.61	61432	87%	10.58	61207	87%	10.55	13724	48%

Total Number of Peaks by GCMS: 12 + Surrogates 6 + Surrogates 15 + Surrogates 7 + Surrogates

SITE NAME: GreatNeck/Tt			LAB NAME	: Hy	ydroGeoSj	pectrum (H	GS)	1	DATE:	29 AUG 19	98		
ANALYST: Raphe Pavlick			C	OLLECTOR:	1	Rodney Bro	tt	II	NSTRUMENT	ID:	2415A8201		
NORMAL INJECTION VOLUME		1 ml											
Sample ID:			TT6			ттє			TT6				
		V	OB8284-090	35	V	OB8285-090	36	V	OB8286-09	037			
Sampling Depth (ft)			60 pur	g		60 pur	g		60 pu	ırg			
Purge Volume (ml)			564			1692			2820				
Vacuum			NO			NO			NO				
Sampling Time			27Aug			27Aug			27Aug	Ī			
Injection Time			1249			1305			1323				
Injection Volume			1ml			1ml			1ml				
Dilution Factor			1			1			1	,			
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC
1,1-Dichloroethene	MS	4.24	1377	0.7	4.21	1262	0.6	4.25	1494	0.7			
1,2-Dichloroethene (total)	MS	5.02	81244	17.1	4.99	91841	19.4	5.01	72186	15.2			
Trichloroethene	MS	7.46	417267	129.8	7.44	452025	140.6	7.45	313058	97.4			
Toluene	MS	10.68	76735	16.0	10.68	130485	27.2	10.68	100053	20.8			
Tetrachloroethene	MS	9.93	35184	14.0	9.92	81622	32.5	9.92	75971	30.3			
FREON-113	MS	5.56	46317	10.5	5.52	71137	16.1	5.54	59244	13.4			
Deutero-chloroform	MS	5.25	57353	90%	5.23	63697	100%	5.25	57177	90%			
D6-BENZENE	MS	7.64	125928	88%	7.64	141492	99%	7.62	128118	89%			
D6-ACETONE	MS	3.25	68840	89%	3.20	81238	105%	3.25	68845	89%			
D2-Dichloromethane	MS	3.08	44564	92%	3.01	50268	104%	3.09	44616	92%			
D8-TOLUENE	MS	10.58	61208	87%	10.56	68218	97%	10.55	64263	91%			

6 + Surrogates

6 + Surrogates

Unidentified peaks and/or other analytical remarks: UNITS: mcg/L

6 + Surrogates

Total Number of Peaks by GCMS:

						SMILTE KEDC							
SITE NAME: GreatNeck/Tt			LAB NAME:	: Hy	ydroGeoSj	pectrum (HG	S)	I	DATE: 2	29 AUG 19	98		
ANALYST: Raphe Pavlick			C	OLLECTOR:	1	Rodney Brot	t	11	NSTRUMENT	ID:	2415A8201		
NORMAL INJECTION VOLUME		1 ml											
Sample ID:			TT6			TT6			Blank				
		V	OB8287-0903	38	V	OB8288-0903	9	V	DB8280-090	31			
Sampling Depth (ft)			60 purg	3		60 purg	Í		BLANK				
Purge Volume (ml)			3948			7050			N.A	A			
Vacuum			ИО			NO			NO				
Sampling Time			27Aug			27Aug			27Aug				
Injection Time			1339			1354			1055				
Injection Volume			1ml			1ml			1ml				
Dilution Factor			1			1			1				
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC
1,1-Dichloroethene	MS	4.20	1116	0.5	4.19	876	0.4	NONE DE	rected .				
1,2-Dichloroethene (total)	MS	4.99	71640	15.1	4.98	69907	14.7						
Trichloroethene	MS	7.45	296837	92.3	7.44	247195	76.9						
Toluene	MS	10.68	98884	20.6	10.66	87582	18.2						
Tetrachloroethene	MS	9.90	78389	31.3	9.91	73354	29,2						
FREON-113	MS	5.53	58061	13.1	5.51	56983	12.9						
Deutero-chloroform	MS	5.22	56704	89%	5.22	51338	81%	5.28	63842	100%			
D6-BENZENE	MS	7.62	129644	90%	7.62	120015	84%	7.67	144669	101%			
D6-ACETONE	MS	3.19	69164	90%	3.19	63069	82%	3.27	79826	1038			
D2-Dichloromethane	MS	3.03	39377	81%	3.03	39096	81%	3.08	48968	101%			
D8-TOLUENE	MS	10.57	65039	93%	10.56	55117	78%	10.64	66334	94%			

6 + Surrogates 0 + Surrogates

Unidentified peaks and/or other analytical remarks: UNITS: mcg/L

Total Number of Peaks by GCMS: 6 + Surrogates

SITE NAME: GreatNeck/Tt			LAB NAME:	H	ydroGeoSp	ectrum (HC	SS)	1	DATE:	2 SEP 19	98		
ANALYST: Raphe Pavlick			CC	LLECTOR:	R	odney Brot	:t	11	NSTRUMENT	ID:	2415A8201		
NORMAL INJECTION VOLUME		1 ml											
Sample ID:			TT1			TT1		i	AMBIENT BI	ANK			
		V	OB8331-0907	77	VO	B8330-090	76		VOB8327				
Sampling Depth (ft)			62			73							
Purge Volume (ml)			3000			3300			NA.	4			
Vacuum			NO			ИО			NO				
Sampling Time			01Sep			01Sep			0932				
Injection Time			1245			1220			0932				
Injection Volume			1ml			1ml			1ml				
Dilution Factor			1			1			1				
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC
Vinyl Chloride	MS	1.91	633	0.6	1.71	1105	1.0	NONE DE	TECTED				
1,2-Dichloroethene (total)	MS	5.07	19989	4.2	4.97	45552	9.6						
Trichloroethene	MS	7.47	20335	6.3	7.43	16587	5.1						
Toluene	MS	10.68	9282	1.9	10.70	6593	1.3						
Tetrachloroethene	MS	9.92	16224	6.4	9.92	15772	6.3						
FREON-113	MS	5.57	29238	6.6	5.50	28131	6.3						
Deutero-chloroform	MS	5.29	59328	93%	5.22	38655	61%	5.30	93346	106%			
D6-BENZENE	MS	7.65	140704	98%	7.63	89400	62%	7.66	173554	95%			
D6-ACETONE	MS	3.31	71645	93%	3.15	44937	58%	3.31	88475	93%			
D2-Dichloromethane	MS	3.13	43931	91%	2.97	29376	61%	3.16	49308	101%			
D8-TOLUENE	MS	10.58	72153	103%	10.59	37012	53%	10.60	103762	94%			

6 + Surrogates 0 + Surrogates

Unidentified peaks and/or other analytical remarks: UNITS: mcg/L

Total Number of Peaks by GCMS: 6 + Surrogates

SITE NAME: GreatNeck/Tt			LAB NAME:	: Н	ydroGeoS	pectrum (HC	GS)		DATE:	2 SEP 19	98		
ANALYST: Raphe Pavlick			CC	OLLECTOR:	1	Rodney Brot	t		INSTRUMEN	T ID:	2415A8201	L	
NORMAL INJECTION VOLUME		1 ml											
Sample ID:			TT7			TT7							
		V	OB8328-0907	74	V	OB8329-090°	75						
Sampling Depth (ft)			34	,		60							
Purge Volume (ml)			2250	***		2850							
Vacuum			NO			NO			•				
Sampling Time			01Sep			01Sep							
Injection Time			1150			125							
Injection Volume			1ml			1m1							
Dilution Factor			1			1							
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	· CONC	RT	AREA	CONC
Trichloroethene	MS	7.47	8640	2.6	7.46	10507	3.2	10.1	7111271	conc	10.1	711(3)1	conc
Toluene	MS	10.69	5187	1.0	10.76	5233	1.0						
Tetrachloroethene	MS	9.92	5900	2.3	9.92	8288	3.3						
FREON-113	MS				5.56	3407	0.7						
Deutero-chloroform	MS	5.29	53100	83%	5.25	60888	95%						
D6-BENZENE	MS	7.66	112866	79%	7.65	140783	98%						
D6-ACETONE	MS	3.31	58615	76%	3.22	74534	978						
D2-Dichloromethane	MS	3.15	44553	92%	3.06	43629	90%						

Total Number of Peaks by GCMS:

D8-TOLUENE

3 + Surrogates

34684

4 + Surrogates

71824

102%

10.59

Unidentified peaks and/or other analytical remarks: UNITS: mcg/L

10.58

MS

		LAB NAME	E: H	ydroGeoS	pectrum (H	GS)	]	DATE:	2 SEP 19	98		•
		C	COLLECTOR:		Rodney Bro	tt	II	NSTRUMENT	ID:	2415A8201		
	1 ml											
		TT6			TT6							
	V	OB8332-090	77	V	OB8334-090	80						
		60			70							
		2850			3300			•				
		NO			NO							
		01Sep			01Sep							
		1302			1337							
		1ml	•		1ml							
		1			1							
	RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC
MS	5.04	230415	48.7	5.01	106633	22.5						
MS	6.26	2386	0.7									
MS	7.72	4411	0.6	7.68	3893	0.5						
MS	7.46	2128784	662.5	7.43	1248286	388.4						
MS	10.69	597874	124.7	10.65	196264	40.9						
MS	9.93	999918	399.2	9.90	212084	84.6						
MS	13.10	10110	3.3									
MS				5.55	15364	3.4						
MS	5.28	51405	81%	5.26	66463	104%						
MS	7.66	114743	80%	7.63	149128	104%						
MS	3.29	60783	79%	3.27	77661	101%						
MS	3.11	37696	78%	3.10	47637	98%						
MS	10.58	57148	81%	10.54	70368	100%						
	MS	RT MS 5.04 MS 6.26 MS 7.72 MS 7.46 MS 10.69 MS 9.93 MS 13.10 MS  MS 5.28 MS 7.66 MS 3.29 MS 3.11	1 ml  TT6  VOB8332-090 60 2850 NO 01Sep 1302 1ml 1  RT AREA MS 5.04 230415 MS 6.26 2386 MS 7.72 4411 MS 7.46 2128784 MS 10.69 597874 MS 9.93 999918 MS 13.10 10110 MS  MS 5.28 51405 MS 7.66 114743 MS 3.29 60783 MS 3.11 37696	COLLECTOR:  1 ml  TT6  VOB8332-09077  60 2850 NO 01Sep 1302 1ml 1  RT AREA CONC  MS 5.04 230415 48.7 MS 6.26 2386 0.7 MS 7.72 4411 0.6 MS 7.46 2128784 662.5 MS 10.69 597874 124.7 MS 9.93 999918 399.2 MS 13.10 10110 3.3 MS  MS 5.28 51405 81% MS 7.66 114743 80% MS 7.66 114743 80% MS 3.29 60783 79% MS 3.11 37696 78%	COLLECTOR:  1 ml  TT6  VOB8332-09077 60 2850 NO 01Sep 1302 1ml 1  RT AREA CONC RT MS 5.04 230415 48.7 5.01 MS 6.26 2386 0.7 MS 7.72 4411 0.6 7.68 MS 7.46 2128784 662.5 7.43 MS 10.69 597874 124.7 10.65 MS 9.93 999918 399.2 9.90 MS 13.10 10110 3.3 MS  S 5.28 51405 81% 5.26 MS 7.66 114743 80% 7.63 MS 3.29 60783 79% 3.27 MS 3.11 37696 78% 3.10	COLLECTOR: Rodney Bro  1 ml  TT6  VOB8332-09077  FOO  60  70  2850  NO  NO  01Sep  1302  1337  1ml  1ml  1  1  RT  AREA  CONC  RT  AREA  MS  5.04  230415  48.7  5.01  106633  MS  6.26  2386  0.7  MS  7.72  4411  0.6  7.68  3893  MS  7.46  2128784  662.5  7.43  1248286  MS  10.69  597874  124.7  10.65  196264  MS  9.93  999918  399.2  9.90  212084  MS  13.10  10110  3.3  MS  5.28  51405  81%  5.26  66463  MS  7.66  114743  80%  7.63  149128  MS  3.29  60783  79%  3.27  77661  MS  3.11  37696  78%  3.10  47637	COLLECTOR:   Rodney Brott   1 ml   TT6	TT6	COLLECTOR: Rodney Brott   INSTRUMENT	COLLECTOR:   Rodney Brott   INSTRUMENT   ID:	TT6	TICHENT   TICH

6 + Surrogates

Unidentified peaks and/or other analytical remarks: UNITS: mcg/L

Total Number of Peaks by GCMS: 7 + Surrogates

HydroGeoSpectrum (HGS) SITE NAME: GreatNeck/Tt LAB NAME: DATE: 2 SEP 1998 Rodney Brott ANALYST: Raphe Pavlick COLLECTOR: INSTRUMENT ID: 2415A8201 NORMAL INJECTION VOLUME 1 ml Sample ID: TT5 TT5 TT5 **TT5** VOB8335-09081 VOB8335D-09081 VOB8341-09087 VOB8341D-09087 Sampling Depth (ft) 37 PURG 37 DF10 37 PURG 37 PURG E40 - 40 0640

Purge Volume (ml)			540			540			8640			8640	
Vacuum			NO			NO			NO			NO	
Sampling Time			01Sep			01Sep			01Sep			01Sep	
Injection Time			1353			1506			1627			1650	
Injection Volume			1ml			0.1ml			1ml			0.1ml	
Dilution Factor			1			10			1			10	
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	ŘТ	AREA	CONC	RT	AREA	CONC
Vinyl Chloride	MS	1.85	3741	3.6				1.75	5007	4.8			
1,1-Dichloroethene	MS	4.22	95386	48.8				4.18	140409	71.8			
1,2-Dichloroethene (total)	MS	5.00	4709300	995.2	5.02	450627	952.3	4.96	8749639	1849.1	5.03	882907	1865.9
Chloroform	MS	5.26	6299	1.5				5.22	8073	1.9			
1,1,1-Trichloroethane	MS	6.24	394780	116.0	6.25	39295	115.4	6.22	494596	145.3			
Benzene	MS	7.68	36076	5.0				7.68	48921	6.8			
Trichloroethene	MS	7.43	14757130	4592.6	7.43	1944141	6050.4	7.42	20173584	6278.3	7.44	3603306	11214.
Toluene	MS	10.64	3587101	748.5	10.67	361627	754.6	10.67	8019286	1673.4	10.68	808002	1686.1
Tetrachloroethene	MS	9.89	4269118	1704.7	9.90	429869	1716.5	9.90	7656217	3057.3	9.90	853972	3410.1
Ethylbenzene	MS	13.07	41010	13.5				13.05	72912	24.1			
Xylene (total)	MS							16.61	254903	52.3			
1,1,1,2-Tetrachloroethane	MS	9.03	5989	2.1				9.04	3818	1.3			
FREON-11	MS	4.00	31145	7.2				3.93	29324	6.8			
FREON-12	MS	2.05	64470	172.0				1.96	23329	62.2			
FREON-113	MS	5.54	20281172	4597.9	5.54	2697425	6115.2	5.51	18743008	4249.2	5.56	2511284	5693.2
Deutero-chloroform	MS	5.25	62951	99%	5.26	6836	107%	5.21	60972	96%	5. <b>27</b>	5780	91%
D6-BENZENE	MS	7.61	135867	95%	7.63	15048	105%	7.61	129155	90%	7.63	13452	948
D6-ACETONE	MS	3.26	75299	98%	3.27	7908	102%	3.15	70006	91%	3.29	6998	91%
D2-Dichloromethane	MS	3.08	50861	105%	3.09	4383	91%	2.99	43678	90%	3.10	5 <b>502</b>	114%
D8-TOLUENE	MS	10.54	67679	96%	10.54	6954	99%	10.56	69946	100%	10.56	<b>7</b> 555	108%

Total Number of Peaks by GCMS:

14 + Surrogates

6 + Surrogates

15 + Surrogates

5 + Surrogates

SITE NAME: GreatNeck/Tt			LAB NAM	E: H	ydroGeoS	pectrum (F	HGS)		DATE:	2 SEP 19	998		
ANALYST: Raphe Pavlick			•	COLLECTOR:		Rodney Bro	ott	I	NSTRUMENT	ID:	2415A820	1	
NORMAL INJECTION VOLUME		1 ml											
Sample ID:			T <b>T6</b>			TT6			TT6			ТТ6	
		,	VOB8336 - 09	082	v	OB8336D-09	9082	V	OB8338-09	084	v	OB8338D-0	9084
Sampling Depth (ft)			29			29			38			38 DF	5
Purge Volume (ml)			1950			1950			2250			2250	
Vacuum			NO			NO			NO			NO	
Sampling Time			01Sep			01Sep			01Sep			01Sep	98
Injection Time			1412			2020			1733			1753	
Injection Volume			1ml			0.2ml			1ml			0.2ml	
Dilution Factor			1			5			1	,		5	
COMPOUND		RT	AREA	CONC	RТ	AREA	CONC	RТ	AREA	CONC	RТ	AREA	CONC
Vinyl Chloride	MS	1.86	8623	8.3				1.91	7259	7.0			
1,1-Dichloroethene	MS	4.25	123616	63.2									
Methylene Chloride	MS	3.14	1362	0.6				3.16	61838	27.5			
1,2-Dichloroethene (total)	MS	5.02	12057678	2548.2	5.01	2596639	2743.8	5.05	1911009	403.8	4.98	393525	415.8
1,1-Dichloroethane	MS							4.84	34583	8.1			
Chloroform	MS							5.29	27116	6.6			
1,1,1-Trichloroethane	MS	6.25	13579	3.9				6.27	86849	25.5			
Benzene	MS	7.67	11342	1.5				7.70	70156	9.8			
Trichloroethene	MS	7.44	2845641	885.6	7.47	582547	906.4	7.45	9590205	2984.6	7.43	2341424	3643.4
Toluene	MS	10.66	719611	150.1	10.74	148347	154.7	10.67	804288	167.8	10.68	172181	179.6
Tetrachloroethene	MS	9.90	2310449	922.6	9.95	492672	983.6	9.91	1361748	543.7	9.91	293095	585.2
Ethylbenzene	MS	16.62	18385	6.0				16.63	9717	3.2			
FREON-113	MS	5.56	1373775	311.4				5.57	12275586	2782.9	5.51	3080971	3492.4
Deutero-chloroform	MS	5.26	63774	100	5.25	13954	79%	5.28	63155	99%	5.22	12294	96%
D6-BENZENE	MS	7.63	147782	103	7.67	32969	91%	7.64	134573	94%	7.61	31223	109%
D6-ACETONE	MS	3.26	74416	96	3.22	16486	87%	3.31	75133	97₺	3.16	14276	92%
D2-Dichloromethane	MS	3.11	49145	102	3.04	10185	105%	3.15	45380	94%	2.99	11155	115%
D8-TOLUENE	MS	10.54	73539	105	10.65	18842	85%	10.56	72572	103%	10.56	14925	106%
Total Number of Peaks by GO	CMS:	11	+ Surrogat	ces	4	+ Surrogat	es	12	+ Surrogat	tes	5	+ Surroga	tes

SITE NAME: GreatNeck/Tt			LAB NAM	E: Hy	ydroGeoS	Spectrum (i	HGS)		DATE:	2 SEP 19	98		
ANALYST: Raphe Pavlick				COLLECTOR:		Rodney Bro	ott	I	NSTRUMENT	ID:	2415A8201		
NORMAL INJECTION VOLUME		1 ml											
Sample ID:			TT5			TT5			TT5				
		•	VOB8337-09	083	V	OB8337D-0	9083	v	OB8339-09	085			
Sampling Depth (ft)			62			62 DF:	10		73				
Purge Volume (ml)			3000			3000			3300				
Vacuum			NO			NO			NO				
Sampling Time			01Sep			01Sep			01Sep				
Injection Time			1433			1448			1522				
Injection Volume			1ml			0.1ml			1ml				
Dilution Factor			1			10			1				
				aora			2012			gog			20112
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC
1,1-Dichloroethene	MS	4.23		2.5									
1,2-Dichloroethene (total)	MS	5.00		166.1	4.92	75796	160.1	5.02	149891	31.6			
1,1,1-Trichloroethane	MS	6.24		13.4				6.24	7188	2.1			
Benzene	MS	7.67		4.5				7.68	6456	0.9			
Trichloroethene	MS		16132098	5020.5	7.42	2023019	6295.9	7.44	5392215	1678.1			
Toluene	MS	10.66		1498.3	10.66	655370	1367.6	10.66	2945055	614.5			
Tetrachloroethene	MS	9.89	7334732	2928.9	9.88	735677	2937.7	9.89	4220292	1685.2			
Ethylbenzene	MS							13.08	71875	23.8			
Xylene (total)	MS							16.60	298874	61.1			
FREON-113	MS	5.54	459895	104.2				5.54	112259	25.4			
Deutero-chloroform	MS	5.25	69795	109%	5.16	6659	104%	5.27	65916	103%			
D6-BENZENE	MS	7.62		93%	7.59	15592	109%	7.63	143530	100%			
D6-ACETONE	MS	3.22		103%	3.08	8098	105%	3.27	74446	96%			
D2-Dichloromethane	MS	3.07		101%	2.91	4731	98%	3.09	46775	97%			
D8-TOLUENE	MS	10.54	69746	99%	10.57	6883	98%	10.56	68210	97%			
Total Number of Peaks by GO	'MG	Ω	+ Surroga	tes	Δ	+ Surrogat	- Ac	۵	+ Surroga	tes			
TOTAL HUMBEL OF LEAKS BY GO		0	, surroga		- 1	, builoga		,	Julioga	CCB			

				SC	IL GAS	SAMPLE RE	SULIS						
SITE NAME: GreatNeck/Tt			LAB NAM	E: Hy	droGeoS	Spectrum (I	HGS)	1	DATE:	2 SEP 19	998		
ANALYST: Raphe Pavlick				COLLECTOR:		Rodney Bro	ott	II	NSTRUMENT	ID:	2415A8201		
NORMAL INJECTION VOLUME		1 ml		•									
Sample ID:			TT5			TT5			BLANK				
•		•	VOB8340-09	086	V	OB8340D-0	9086	V	DB8333-090	079			
Sampling Depth (ft)			37 PU	RG		37 PU	RG						
Purge Volume (ml)			8640			8640			N	A			
Vacuum			NO			NO			NO				
Sampling Time			01Sep			01Sep			01Sep				
Injection Time			1544			1606			1322				
Injection Volume			1ml			0.1ml			1ml				
Dilution Factor			1			10			1				
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	ŔŤ	AREA	CONC
Vinyl Chloride	MS	1.90	4346	4.2				NONE DE	TECTED				
1,1-Dichloroethene	MS	4.26	167962	85.9									
1,2-Dichloroethene (total)	MS	5.02	11602548	2452.1	4.97	1138710	2406.5						
Chloroform	MS	5.26	7792	1.9									
1,1,1-Trichloroethane	MS	6.25	484757	142.4									
Benzene	MS	7.68	52659	7.3									
Trichloroethene	MS	7.43	22141461	6890.7	7.42	3859526	12011.						
Toluene	MS	10.65	11790035	2460.3	10.65	1117789	2332.6						
Tetrachloroethene	MS	9.89	13481024	5383.3	9.90	1557485	6219.4						
Ethylbenzene	MS	13.07	164172	54.4									
Xylene (total)	MS	16.54	620424	42.4									
1,1,1,2-Tetrachloroethane	MS	9.02	2771	0.9									
FREON-11	MS	4.04	28703	6.6									
FREON-113	MS	5.55	18960041	4298.4	5.50	2441493	5535.0						
Deutero-chloroform	MS	5.26	59233	93%	5.21	6500	102%	5.25	70292	110%			
D6-BENZENE	MS	7.62	148665	104%	7.61	15068	105%	7.63	158222	110%			
D6-ACETONE	MS	3.28	75238	97%	3.18	7041	91%	3.29	77273	100%			
D2-Dichloromethane	MS	3.12	44639	9 <b>2</b> %	2.98	4447	92%	3.11	46813	9 <b>7</b> %			
D8-TOLUENE	MS	10.54	71777	102%	10.53	6815	97%	10.54	73944	105%			
Total Number of Peaks by GC	CMS:	14	+ Surroga	tes	5	+ Surrogal	tes	0	+ Surroga	tes			

SITE NAME: GreatNeck/Tt LAB NAME: HydroGeoSpectrum (HGS)

ANALYST: Raphe Pavlick COLLECTOR: Rodney Brott INSTRUMENT ID: 2415A8201

NORMAL INJECTION VOLUME 1 ml

NORMAL INJECTION VOLUME		1 ml											
Sample ID:			TT3	•		TT3			TT3			BLANK	
		V	DB8353-090	96	V	DB8354-090	97	V	DB8355-090	98	VC	DB8356-090	99
Sampling Depth (ft)			62			52			72				
Purge Volume (ml)			3000			2700			3300			N.	A
Vacuum			NO			NO			NO			NO	
Sampling Time			02Sep			02Sep			02Sep			P98) N	
Injection Time			1142			1157			1346			1401	
Injection Volume			1m1			1ml			1ml			1ml	
Dilution Factor			1			1			1			1	
COMPOUND		RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC	RT	AREA	CONC
1,2-Dichloroethene (total)	MS				5.02	20607	4.3				NONE DET	<b>FECTED</b>	
Trichloroethene	MS	7.45	3386	1.0	7.44	8137	2.5	7.46	3337	1.0			
Toluene	MS				10.69	4569	0.9	10.69	2813	0.5			
Tetrachloroethene	MS	9.92	6161	2.4	9.91	11826	4.7	9.92	3946	1.5			
FREON-113	MS				5.54	10020	2.2	5.59	4699	1.0			
Deutero-chloroform	MS	5.27	64021	100%	5.27	67799	106%	5.28	58244	91%	5.28	64656	101%
D6-BENZENE	MS	7.64	152543	106%	7.64	150157	105%	7.64	138848	97%	7.64	152375	106%
D6-ACETONE	MS	3.30	77410	100%	3.28	69224	90%	3.31	65622	85%	3.25	78218	101%
D2-Dichloromethane	MS	3.14	48727	101%	3.13	47539	98%	3.14	44504	92%	3.10	48018	998

Total Number of Peaks by GCMS: 2 + Surrogates 5 + Surrogates 4 + Surrogates 0 + Surrogates

73715

105%

10.59

69112

98%

10.57

75777

108%

10.57

Unidentified peaks and/or other analytical remarks: UNITS: mcg/L

10.57

74526

106%

MS

D8-TOLUENE

SITE NAME: GreatNeck/Tt LAB NAME: HydroGeoSpectrum (HGS) DATE: 4 SEP 1998 ANALYST: Raphe Pavlick COLLECTOR: Rodney Brott INSTRUMENT ID: 2415A8201 NORMAL INJECTION VOLUME 1 ml TT8 TT8 TT8 8TT Sample ID: VOB8393-09133 VOB8395-09135 VOB8394-09134 VOB8397-09137 42 42 62 Sampling Depth (ft) 62 2250 2250 3000 -3000 Purge Volume (ml) NO NO NO NO Vacuum Sampling Time 03Sep 03Sep 03Sep 03Sep Injection Time 1020 1249 1035 1321 1 m l 1ml 1ml 1ml Injection Volume Dilution Factor 1 1 1 1 COMPOUND CONC CONC AREA CONC AREA CONC RT AREA RTAREA RT RT Vinyl Chloride MS 1.90 2753 2.6 1.89 2211 2.1 1,2-Dichloroethene (total) 5.05 2123754 448.8 5.05 1743051 368.3 5.04 4652 0.9 5.06 2978 0.6 MS 1,1,1-Trichloroethane MS 6.29 4328 1.2 6.29 3465 1.0 Trichloroethene MS 447.5 325.6 7.45 1.1 7.48 1437993 7.48 1046448 7.46 3847 1.2 3648 Toluene MS 10.75 2006 0.4 Tetrachloroethene MS 9.94 318949 127.3 9.95 164952 65.8 9.92 2390 0.9 9.97 2668 1.0 FREON-113 5.58 0.8 MS 5.58 377278 85.5 5.59 317715 72.0 5.57 3506 0.7 3451 Deutero-chloroform MS 5.30 56562 898 5.30 59004 93% 5.28 61491 96% 5.30 64450 101% 108% D6-BENZENE MS 7.67 133467 93% 7.67 136394 95% 7.65 135944 95% 7.65 154236 D6-ACETONE MS 69486 90% 3.27 71472 93% 3.30 76197 99% 3.31 69841 91% 3.31 D2-Dichloromethane MS 3.15 41418 86% 3.14 43009 898 3.10 44249 91% 3.14 50217 104% D8-TOLUENE MS 10.60 69359 998 10.61 75412 107% 10.59 63018 90% 10.60 57234 81%

Total Number of Peaks by GCMS: 7 + Surrogates 6 + Surrogates 4 + Surrogates 4 + Surrogates

SITE NAME: GreatNeck/Tt LAB NAME: HydroGeoSpectrum (HGS) DATE: 4 SEP 1998 ANALYST: Raphe Pavlick Rodney Brott COLLECTOR: INSTRUMENT ID: 2415A8201 NORMAL INJECTION VOLUME 1 ml Sample ID: TT1 VOB8396-09136 Sampling Depth (ft) 72 resample Purge Volume (ml) 3300 NO Vacuum Sampling Time 03Sep Injection Time 1304 Injection Volume 1 m l Dilution Factor 1 COMPOUND RTAREA CONC RT AREA CONC RTCONC AREA CONC AREA RT Vinyl Chloride 4391 4.2 MS 1.88 1,2-Dichloroethene (total) MS 72452 5.05 15.3 Trichloroethene MS 7.49 5**817** 1.8 Tetrachloroethene MS 9.95 5696 2.2 FREON-113 MS 51965 5.57 11.7 Deutero-chloroform MS 5.28 134575 211% D6-BENZENE 7.65 301983 211% MS

Total Number of Peaks by GCMS:

D6-ACETONE

D8-TOLUENE

D2-Dichloromethane

5 + Surrogates

158867

103333

137362

206%

214%

196%

Unidentified peaks and/or other analytical remarks: UNITS: mcg/L

MS

MS

MS

3.27

3.10

10.60

NOTE: Twice amount surrogates added to sample.

QA/QC

	LABORAT			BY FULL SCAN MASS SPEC		
1 ng Detection Limit Check						
SITE NAME:	Initial		HydroGeoSpectrum	DATE: 10July98		
-		STD LOT#:		TIME: 14:54		
ANALYST: R	aphe Pavli	INSTRUMEN	IT ID: 2415A8201			
F	Rt	Response	Conc µg/L AccRge			
Vinyl Chlori	1.75	1142	1.1104 1 ± 50%			
Bromometh	1.39	331				
Chloroetha	2.28	1238	$0.9258 1 \pm 50\%$			
1,1-Dichlor	4.18	1964	$1.005 1 \pm 50\%$			
Methylene	3.1	2532	1.1284 1±50%			
1,2-Dichlor	4.99	5099	1.0776 1 ± 50%			
1,1-Dichlor	4.73	4673	1.0961 1 ± 50%			
Chloroform	5.23	4735	1.16 1 ± 50%			
1,2-Dichlor	5.57	2468	1.0414 1 ± 50%			
2-Butanone	5.52	13102	1.2034 1 ± 50%			
1,1,1-Trichl	6.21	3927	1.1542 1 ± 50%			
Carbon Tet	6.37	3062	0.9677 1 ± 50%			
Benzene	7.66	8171	1.1415 1 ± 50%			
Trichloroet	7.43	3792	1.1801 1 ± 50%			
1,2-Dichlor	7.12	2692	0.9637 1 ± 50%			
Bromodichl	6.49	4123	1.093 1 ± 50%			
cis-1,3-Dic	7.22	4723	1.075 1 ± 50%			
trans-1,3-D	7.81	3571	1.2078 1 ± 50%			
1,1,2-Trichl	7.73	2620	1.0679 1 ± 50%			
Dibromochl	7.73	3359	0.9917 1 ± 50%			
Bromoform	8.86	2900	0.9266 1 ± 50%	1		
4-Methyl-2-	9.75	14186	1.2638 1 ± 50%			
Toluene	10.66	5700	1.1895   1 ± 50%	4		
Tetrachloro	9.89	2657	1.061 1 ± 50%			
2-Hexanon	9.75	13997	1.2593 1 ± 50%			
Chlorobenz	11.43	6180	1.0762 1 ± 50%			
Ethylbenze	13.1	2796	0.9266 1 ± 50%			
Xylene (tot	17.35	15190	1.04 1 ± 50%	i i		
Styrene	16.36	7407	1.2558 1 ± 50%			
1,1,1,2-Tet	9.01	2611	0.9674 1 ± 50%			
1,1,2,2-Tet	9.88	5756	1.1995 1 ± 50%			
FREON-11	3.96	4980	1.1541 1±50%			
FREON-12	1.69	335	0.8938 1 ± 50%			
FREON-11	5.47	5004				
Freon-22	1.42	525				
Freon-141B	4.01	5767	1.0108 1 ± 50%			

Laboratory Control Standard (LCS)

Data File: E:\VOB7743.D Vial: 1

Acq On : 10 Jul 1998 4:54 pm Operator: Raphe HGS

Sample : LCS 50NG Inst : GC/MS #1

Misc : 10JULY98 Multiplr: 1.00

MS Integration Params: rteint.p GC Integration Params: rteint2.p

Method : C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator)

Title : FULL SCAN

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev: 15% Max. Rel. Area: 150%

Com	pound i	AvgRF	CCRF		%Dev	AccRge		Dev(min)
				·				
1		1028.435					25_	-0.01
2	Brom	313.657		0.09	1.1		25	-0.03
3	Chlor	1.337	1.355	E3	-1.4	<u> </u>	25	0.03
4	1,1-D	1.954	2.183	E3	-11.7		15	0
6	Meth	2.244	2.471	E3	-10.1	•	15	-0.03
7	1,2-D	4.732	4.936	E3	-4.3		15	-0.02
8	1,1-D	4.263	4.427	E3	-3.8		15	-0.02
9	Chlor	4.082	4.245	E3	-4		15	0
10	1,2-	2.37	2.452	E3	-3.5		15.	-0.02
12	1,1,	3.402	3.517	E3	-3.4		15	0
13	Carb	3.164	3.128	E3	1.1	-	15	0
14	Ben	7.158	7.746	E3	-8.2		15	0
15	Tric	3.213	3.527	E3	-9.8		15.	-0.02
16	1,2-	2.793	3.046	E3	-9.1		15	0
17	Bro	3.772	4.149	E3	-10		15	0
18	cis-	4.394	4.228	E3	3.8		15	0
19	tran	2.957	3.153	E3	-6.6	-	15	-0.07
20	1,1,	2.453	2.596	E3	-5.8		15	0
21	Dibr	3.387	3.680	E3	-8.7		15	-0.02
22	Bro	3.13	3.301	E3	-5.5		15	-0.02
24	Tolu	4.792	5.237	E3	-9.3		15	0
25	Tetr	2.504	2.704	E3	-8		15	-0.02
27	Chlo	5.742	6.319	E3	-10		15	0
28	Ethy		3.308		-9.6		15	
29	Xyle	14.606	14.92	2 E3	-2.2		15	-0.02
30	Styr	5.898			-3.6		15	
31	1,1,	2.842	2.989	E3	-5.2		15	0:
32	1,1,	4.342	4.891	E3	-12.6		15 <sup>-</sup>	0
33	FRE	4.315	4.374	E3	-1.4		20	-0.02
35	FRE	374.788	38	2.38	-2		20	-0.06
36	FRE	4.411	4.532	E3	-2.7		20	0

#### Evaluate Continuing Calibration Report

Data File : C:\HPCHEM\1\DATA\VOB8275.D Vial: 1

Acq On : 29 Aug 1998 8:01 am Sample : STANDARD 50ng 'isc : 29AUG98 Operator: Raphe HGS Inst : GC/MS Ins

Multiplr: 1.00

S Integration Params: rteint.p

Method : C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator)
Title : FULL SCAN

Response via: Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev: 15% Max. Rel. Area: 150%

	Compound	AvgRF	CCRF		%Dev Ac	cRge	Dev(min)
1	Vinyl Chloride	1028.435	5 1102.26	0	-7.2	20	-0.35
2	Bromomethane	313.657			2.1	20	-0.31
3	Chloroethane	1.337	1.098	E3	17.9	20	-0.36
4	1,1-Dichloroethene	1.954	1.965	E3	-0.6	15	-0.06
5	Acetone	5.745	5.854	<b>E</b> 3	-1.9	15	-0.24
6	Methylene Chloride	2.244	2.271	E3	-1.2	15	-0.30
7	1,2-Dichloroethene (total)	4.732	4.930	E3	-4.2	15	-0.03
8	1,1-Dichloroethane	4.263	4.083	E3	4.2	15	-0.05
9	Chloroform	4.082	4.114	E3	-0.8	15	-0.01
10	1,2-Dichloroethane	2.370	2.120	E3	10.5	15	-0.03
11	2-Butanone	10.888	11.608	E3	-6.6	15	-0.05
12	1,1,1-Trichloroethane	3.402	3.251	E3	4.4	15	0.02
13	Carbon Tetrachloride	3.164	3.085	E3	2.5	15	0.02
14	Benzene	7.158	7.163	E3	-0.1	15	0.05
	Trichloroethene	3.213	3.162	E3	1.6	15	0.02
	1,2-Dichloropropane	2.793		<b>E</b> 3	-6.2	15	0.01
17	Bromodichloromethane	3.772		<b>E</b> 3	-1.1	15	0.00
18	cis-1,3-Dichloropropene	4.394		E3	2.8	15	0.02
19	trans-1,3-Dichloropropene			E3	-0.4	15	-0.03
20	1,1,2-Trichloroethane	2.453	2.747	E3	-12.0	15	0.04
21	Dibromochloromethane	3.387	3.374	E3	0.4	15	0.01
22	Bromoform	3.130	2.981	E3	4.8	15	0.02
23 .	4-Methyl-2-Pentanone	11.225		E3	-4.3	15	0.06
24	Toluene	4.792	4.894	E3	-2.1	15	0.09
25	Tetrachloroethene	2.504	2.657	E3	-6.1	15	0.04
26	2-Hexanone	11.115	11.712	E3	-5.4	15	0.06
27	Chlorobenzene	5.742	6.244	E3	-8.7	15	0.12
28	Ethylbenzene	3.018	3.209	E3	-6.3	15	0.14
29	Xylene (total)	14.606		E3	-1.2	15	0.19
30	Styrene	5.898		<b>E</b> 3	2.5	15	0.26
31 T	1,1,1,2-Tetrachloroethane			E3	-1.0	15	0.05
32	1,1,2,2-Tetrachloroethane	4.342		E3	-3.2	15	0.06
33	FREON-11	4.315	3.479	<b>E</b> 3	19.4	20	-0.21
35	FREON-12	374.788			-8.6	20	-0.39
36	FREON-113	4.411	3.959	E3	10.2	20	0.02
43	Freon-22		443.560		19.3	20	-0.08
44	Freon-141B	5.705	4.749	E3	16.8	20	-0.08

#### Evaluate Laboratory Control Standard Report

Data File : D:\VOB8302.D Vial: 1

Acq On : 29 Aug 98 6:44 pm Operator: Raphe HGS Sample : LCS 50NG Inst : GC/MS Ins

Sample : LCS 50NG Inst : GC/MS 1isc : ACTA/TT 29AUG98 Multiplr: 1.00

MS Integration Params: rteint.p

Method : C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator)

Title : FULL SCAN

Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev : 15% Max. Rel. Area : 150%

	Compound	AvgRF	CCRF		%Dev	AccRge	Dev(min)
1	Vinyl Chloride	1028.435	1124.270	)	-9	25	-0.11
2	Bromomethane	313.657	323.610		-3	25	-0.11
3	Chloroethane	1.337	1.177		12	25	-0.10
4	1,1-Dichloroethene	1.954	2.019	E3	-3.3	20	-0.05
6	Methylene Chloride	2.244	2.130	E3	5.1	20	-0.10
7	1,2-Dichloroethene (total)	4.732	4.879	E3	-3.1	20	-0.02
8	1,1-Dichloroethane	4.263	3.858	<b>E</b> 3	9.5	20	-0.03
9	Chloroform	4.082	3.863	E3	5.4	20	0.03
10	1,2-Dichloroethane	2.370	1.987	E3	16.2	20	0.00
٦	1,1,1-Trichloroethane	3.402	3.242	E3	4.7	20	0.03
<b>-2</b> 3	Carbon Tetrachloride	3.164	2.702	E3	14.6	20	0.04
14	Benzene	7.158	6.747	E3	5.7	20	0.05
15	Trichloroethene	3.213	3.042	E3	5.3	20	0.03
16	1,2-Dichloropropane	2.793	2.738	E3	2.0	20	0.03
17	Bromodichloromethane	3.772	3.653	E3	3.2	20	0.03
18	cis-1,3-Dichloropropene	4.394	3.809	E3	13.3	20	0.04
19	trans-1,3-Dichloropropene	2.957	3.167	E3	-7.1	20	0.00
20	1,1,2-Trichloroethane	2.453	2.778	E3	-13.2	20	0.05
21	Dibromochloromethane	3.387	3.400	E3	-0.4	20	0.03
22	Bromoform	3.130	3.073	EЗ	1.8	20	0.04
24	Toluene	4.792	4.635	E3	3.3	20	0.09
25	Tetrachloroethene	2.504	2.642	E3	-5.5	20	0.05
27	Chlorobenzene	5.742	6.084	E3	-6.0	20	0.10
28	Ethylbenzene	3.018	3.121	E3	-3.4	20	0.12
29	Xylene (total)	14.606	14.920	E3	-2.1	20	0.12
30	Styrene	5.898	5.997	E3	-1.7	20	0.17
31 T	1,1,1,2-Tetrachloroethane	2.842	2.760	<b>E</b> 3	2.9	20	0.07
32	1,1,2,2-Tetrachloroethane	4.342	4.800	E3	-10.5	20	0.05
33	FREON-11	4.315	3.452	E3	20.0	25	-0.05
35	FREON-12	374.788	410.920		-9.6	25	-0.14
75	FREON-113	4.411	3.797	E3	13.9	25	0.00

#### Evaluate Continuing Calibration Report

Data File : C:\HPCHEM\1\DATA\VOB8326.D Vial: 1

Acq On : 2 Sep 1998 8:16 am Operator: Raphe HGS Sample : STANDARD 50NG Tisc : 02SEP98 Inst : GC/MS Ins

Multiplr: 1.00

.S Integration Params: rteint.p

Method : C:\HPCHEM\1\METHODS\10JUL98T.M (RTE Integrator)
Title : FULL SCAN

Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min Max. RRF Dev : 15% Max. Rel. Area : 150%

	Compound	AvgRF	CCRF		%Dev .	AccRge	Dev(min)
1	Vinyl Chloride Bromomethane Chloroethane			0	-2.0	20	-0.01
2	Bromomethane	313.657	361.660		-15.3	20	-0.01
3	Chloroethane	1.337	1.306	E3	2.3	20	0.00
4	1,1-Dichloroethene	1.954	2.057			15	0.02
5	Acetone	5.745	6.555		-14.1		0.00
6	Methylene Chloride		2.460	E3	-9.6		0.00
7	1,2-Dichloroethene (total)				-12.4		0.02
8	1,1-Dichloroethane	4.263		E3	-0.6		0.02
9	Chloroform	4.082		E3	-5.0		0.04
10	1,2-Dichloroethane	2.370		E3	3.1		0.02
11	2-Butanone	10.888		E3	-1.9	15	0.04
12	1.1.1-Trichloroethane	3.402	3.538	E3	-4.0		0.03
13	Carbon Tetrachloride	3.164	2.901	E3	8.3	15	0.04
14	Benzene	7.158	7.514	E3	-5.0	15	0.06
	Trichloroethene	3.213	3.364	E3	-4.7	15	0.04
<b>-</b> 70	1,2-Dichloropropane			E3	-9.6	15	0.06
17	Bromodichloromethane	3.772	3.869	E3	-2.6	15	0.07
18	cis-1,3-Dichloropropene	4.394	4.465	E3	-1.6	15	0.07
19	trans-1,3-Dichloropropene	2.957	3.071	E3	-3.9	15	0.00
20	1,1,2-Trichloroethane Dibromochloromethane Bromoform	2.453	2.606	E3	-6.2	15	0.08
21	Dibromochloromethane	3.387	3.572	E3	-5.5	15	0.04
22	Bromoform	3.130	3.215	E3	-2.7	15	0.06
23	4-Methyl-2-Pentanone	11.225	11.103	E3	1.1	15	0.09
24	Toluene	4./24	J.001	E3	-6.0	15	0.11
25	Tetrachloroethene	2.504	2.842	E3	-13.5	15	0.06
26	2-Hexanone Chlorobenzene Ethylbenzene Xylene (total) Styrene	11.115	11.103	E3	0.1		0.09
27	Chlorobenzene	5.742	6.464		-12.6		0.11
28	Ethylbenzene	3.018	3.287	E3	-8.9		0.14
29	Xylene (total)	14.606	15.238	E3	-4.3		0.21
30				E3	0.7		0.24
31 T	1,1,1,2-Tetrachloroethane	2.842	2.949	E3	-3.8		0.08
32		4.342		E3			0.08
33	FREON-11	4.315		E3	13.2		0.03
35	FREON-12		310.200		17.2		-0.05
36	FREON-113	4.411	4.225	E3	4.2		0.04
43	Freon-22	549.764			-9.7		0.09
44	Freon-141B	5 <b>.7</b> 05	5.098	E3	10.6	20	0.03

#### Evaluate Laboratory Control Standard Report

Vial: 1

Data File : C:\HPCHEM\1\DATA\VOB8350.D

Acq On : 2 Sep 1998 9:21 pm Sample : LCS 50NG 'isc : 02SEP98 Operator: Raphe HGS Inst : GC/MS Ins

Multiplr: 1.00

\_ S Integration Params: rteint.p

Method : C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator)
Title : FULL SCAN

Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev : 15% Max. Rel. Area : 150%

	Compound	AvgRF	CCRF		%Dev	AccRge	Dev(min)
1 2 3 4 6 7 8 9 10 12	Vinyl Chloride Bromomethane Chloroethane 1,1-Dichloroethene Methylene Chloride 1,2-Dichloroethene (total) 1,1-Dichloroethane Chloroform 1,2-Dichloroethane 1,1,1-Trichloroethane Carbon Tetrachloride	313.657 1.337 1.954 2.244 4.732 4.263 4.082 2.370 3.402 3.164	1.146 1.941 2.159 4.638 3.786 3.720 1.951 3.097 2.598	E3 E3 E3 E3 E3 E3 E3 E3	-10 4 14 0.7 3.8 2.0 11.2 8.9 17.7 9.0	20 20 20 20 20 20 20 20	-0.16 -0.15 -0.17 -0.11 -0.17 -0.03 -0.04 0.00 0.00 0.03 0.04
14 15 16	Benzene Trichloroethene 1,2-Dichloropropane Bromodichloromethane cis-1,3-Dichloropropene	7.158 3.213 2.793 3.772 4.394	6.585 2.980 2.614 3.504 3.861	E3 E3 E3 E3	8.0 7.3 6.4 7.1 12.1	20 20 20	0.04 0.03 0.04 0.03 0.04
19 20 21 22 24 25 27 28 29 30 31 32 33 35 36	trans-1,3-Dichloropropene 1,1,2-Trichloroethane Dibromochloromethane Bromoform Toluene Tetrachloroethene Chlorobenzene Ethylbenzene Xylene (total) Styrene 1,1,1,2-Tetrachloroethane 1,1,2,2-Tetrachloroethane FREON-11 FREON-12 FREON-13	2.957 2.453 3.387 3.130 4.792 2.504 5.742 3.018 14.606 5.898 2.842 4.342 4.315 374.788 4.411	4.876 3.476	E3333333333333333333333333333333333333	-12.2 -9.8 4.3 5.7 6.2 -0.8 -2.7 0.1 0.9 8.9 7.4 -12.3 19.4 1.7 15.2	20 20 20 20 20 20 20 20 20 20 25 25	0.00 0.07 0.04 0.03 0.11 0.06 0.11 0.13 0.16 0.25 0.08 0.07 -0.12 -0.21 -0.01

#### Evaluate Continuing Calibration Report

Data File : C:\HPCHEM\1\DATA\VOB8351.D Vial: 1

Acq On : 3 Sep 1998 7:12 am Sample : STANDARD 50NG Misc : 03SEP98 Operator: Raphe HGS Inst : GC/MS Ins

Multiplr: 1.00

IS Integration Params: rteint.p

: C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator) Method

Title : FULL SCAN

Response via : Multiple Level Calibration

: 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min Min. RRF

Max. RRF Dev : 15% Max. Rel. Area : 150%

	Compound	AvgRF	CCRF		%Dev Ac	cRge	Dev(min)
1	Vinyl Chloride	1028.435	5 1008.86	0	1.9	20	0.00
2	Bromomethane	313.657	334.700		-6.7	20	-0.02
3	Chloroethane	1.337	1.226	<b>E</b> 3	8.3	20	0.01
4	1,1-Dichloroethene	1.954	1.915	E3	2.0	15	0.05
5	Acetone	5.745	5.9 <b>7</b> 7	<b>E</b> 3	-4.0	15	0.02
6	Methylene Chloride	2.244	2.238	E3	0.3	15	0.01
7	1,2-Dichloroethene (total)	4.732	4.897	E3	-3.5	15	0.04
8	1,1-Dichloroethane	4.263	4.040	<b>E</b> 3	5.2	15	0.04
9	Chloroform	4.082	4.021	<b>E</b> 3	1.5	15	0.06
10	1,2-Dichloroethane	2.370	2.052	E3	13.4	15	0.05
11	2-Butanone	10.888	10.681	<b>E</b> 3	1.9	15	0.05
12	1,1,1-Trichloroethane	3.402	3.315	E3	2.6	15	0.06
13	Carbon Tetrachloride	3.164	2.788	E3	11.9	15	0.05
14	Benzene	7.158	7.034	E3	1.7	15	0.07
יק	Trichloroethene	3.213	3.166	E3	1.5	15	0.05
	1,2-Dichloropropane	2.793		E3	-0.3	15	0.07
<u> </u>	Bromodichloromethane	3. <b>77</b> 2	3.728	<b>E</b> 3	1.2	15	0.07
18	cis-1,3-Dichloropropene	4.394	4.167	E3	5.2	15	0.07
19	trans-1,3-Dichloropropene	2.957		E3	-3.1	15	0.01
20	1,1,2-Trichloroethane	2.453	2.613	E3	-6.5	15	0.08
21	Dibromochloromethane	3.387	3.359	<b>E</b> 3	0.8	15	0.06
22	Bromoform	3.130	3.007	<b>E</b> 3	3.9	15	0.06
23	4-Methyl-2-Pentanone	11.225	10.600	E3	5.6	15	0.11
24	Toluene	4.792	4.782	E3	0.2	15	0.13
25	Tetrachloroethene	2.504	2.714	<b>E</b> 3	-8.4	15	0.08
26	2-Hexanone	11.115	10.600	<b>E</b> 3	4.6	15	0.11
27	Chlorobenzene	5,742	6.222	E3	-8.4	15	0.15
28	Ethylbenzene	3.018	3.109	E3	-3.0	15	0.17
29	Xylene (total)	14.606		E3	-4.0	15	0.26
30	Styrene	5.898	5.861	E3	0.6	15	0.25
31	1,1,1,2-Tetrachloroethane	2.842		E3	2.7	15	0.10
32	1,1,2,2-Tetrachloroethane	4.342		E3	-5.8	15	0.07
33	FREON-11	4.315	3.551	E3	17.7	20	0.04
35	FREON-12		380.160	m^	-1.4	20	-0.04
36	FREON-113	4.411	3.959	E3	10.2	20	0.05
43	Freon-22		527.400	-	4.1	20	0.10
44	Freon-141B	5.705	4.703	<b>E</b> 3	17.6	20	0.04

#### Evaluate Lab Control Standard Report

Data File : C:\HPCHEM\1\DATA\VOB8390.D Vial: 1

Acq On : 3 Sep 1998 11:05 pm Operator: Raphe HGS Sample : LCS 50NG Misc : 03SEP98 Inst : GC/MS Ins

Multiplr: 1.00

3 Integration Params: rteint.p

: C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator) Method : C:\HPCHEMY
Title : FULL SCAN

Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev: 15% Max. Rel. Area: 150%

	Compound	AvgRF	CCRF		%Dev	AccRge	Dev(min)
1	Vinyl Chloride	1028.435	1017 34		1.1	25	0.03
2	Bromomethane	313.657	331.54		-5.7		0.02
3	Chloroethane	1.337	1,316		1.6	25	0.03
4	1,1-Dichloroethene	1.954	2.119	E3	-8.4		0.03
6	Methylene Chloride	2.244	2.602	E3	-16.0		0.03
7	1,2-Dichloroethene (total)	4.732	5.459	E3	-15.4		0.00
8	1,1-Dichloroethane	4.263	4.402	E3	-3.3		0.02
9	Chloroform	4.082	4.435	E3	-8.6		0.04
10	1,2-Dichloroethane	2.370	2.289	<b>E</b> 3	3.4		0.02
12	1,1,1-Trichloroethane	3.402	3,545	E3	-4.2		0.02
13	Carbon Tetrachloride	3.164	3.053	E3	3.5		0.03
14	Benzene	7.158	7.652	E3	-6.9		0.03
15	Trichloroethene	3.213	3.469	<b>E</b> 3	-8.0		0.02
16	1,2-Dichloropropane	2.793	3.118	E3			0.04
	Bromodichloromethane	3.772	4.038	E3	-7.1		0.04
	cis-1,3-Dichloropropene	4.394	4.128	<b>E</b> 3	6.1		0.04
19	trans-1,3-Dichloropropene	2.957	3.428	EЗ	-15.9		-0.01
21	Dibromochloromethane	3.387	3.745	<b>E</b> 3	-10.6	20	0.03
22	Bromoform	3.130	3.385	<b>E</b> 3	-8.1	. 20	0.03
24	Toluene	4.792	5.194	<b>E</b> 3	-8.4	20	0.09
25	Tetrachloroethene	2.504	2.936	E3	-17.3	20	0.03
27	Chlorobenzene	5.742	6.690	<b>E</b> 3	-16.5	20	0.10
28	Ethylbenzene	3.018	3.407	<b>E</b> 3	-12.9	20	0.08
29	Xylene (total)	14.606	15.243	<b>E</b> 3	-4.4	20	0.15
<b>3</b> 0	Styrene	5.898	6.D96	<b>E3</b>	-3.4	20	0.18
31 T	1,1,1,2-Tetrachloroethane	2.842	3.039	E3	-6.9	20	0.06
32	1,1,2,2-Tetrachloroethane	4.342	4.970	<b>E</b> 3	-14.5	20	0.06
33	FREON-11	4.315	3.905	E3	9.5		0.03
35	FREON-12	374.788			16.8		-0.01
36	FREON-113	4.411	4.309	E3	2.3	25	0.03

#### Evaluate Continuing Calibration Report

Data File : C:\HPCHEM\1\DATA\VOB8391.D

Vial: 1 Acq On : 4 Sep 1998 9:49 am Sample : STANDARD 50NG 'isc : 04SEP98 Operator: Raphe HGS Inst : GC/MS Ins

Multiplr: 1.00

\_\_\_.iS Integration Params: rteint.p

Method : C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator)
Title : FULL SCAN

Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev: 15% Max. Rel. Area: 150%

	Compound	AvgRF	CÇRF		%Dev	AccRge	Dev(min)
1	Vinyl Chloride	1028.43	5 1020.52	20	0.8	20	0.00
2	Bromomethane	313.657	356.600		-13.7	20	-0.01
3	Chloroethane	1.337	1.245	E3	6.9	20	0.01
4	1,1-Dichloroethene	1.954	1.984	E3	-1.5	15	0.03
5	Acetone	5.745	5.961	E3	-3.8	15	0.01
6	Methylene Chloride	2.244	2.369	E3	-5.6	15	0.01
7	1,2-Dichloroethene (total)	4.732	5.163	E3	-9.1	15	0.03
8	1,1-Dichloroethane	4.263	4.131	E3	3.1	15	0.03
9	Chloroform	4.082	4.148	E3	-1.6	15	0.05
10	1,2-Dichloroethane	2.370	2.195	E3	7.4	15	0.03
11	2-Butanone	10.888	11.506	E3	-5.7	15	0.05
12	1,1,1-Trichloroethane	3.402	3.363	E3	1.1	15	0.05
13	Carbon Tetrachloride	3.164	2.808	E3	11.3	15	0.03
٦ 4	Benzene	7.158	7.420	E3	-3.7	15	0.05
	Trichloroethene	3.213	3.295	E3	-2.6	15	0.03
6	1,2-Dichloropropane	2.793	2.944	E3	-5.4	15	0.06
17	Bromodichloromethane	3.772	3.829	E3	-1.5	15	0.06
18	cis-1,3-Dichloropropene	4.394	4.393	E3	0.0		0.07
19	trans-1,3-Dichloropropene	2.957		E3	-8.3		0.00
20	1,1,2-Trichloroethane	2.453	2.663	E3	-8.6	15	0.07
21	Dibromochloromethane	3.387	3.510	<b>E</b> 3	-3.6		0.05
22	Bromoform	3.130	3.100	E3	1.0		0.05
23	4-Methyl-2-Pentanone	11.225	11.445	E3	-2.0		0.08
24	Toluene	4.792	5.004	E3	-4.4		0.09
25	Tetrachloroethene	2.504	2.780	E3	-11.0		0.05
26	2-Hexanone	11.115	11.445	E3	-3.0		0.08
27	Chlorobenzene	5.742	6.459	E3	-12.5		0.13
29	Xylene (total)	14.606	15.064	E3	-3.1		0.17
30	Styrene	5.898		E3	2.1		0.23
31 T	1,1,1,2-Tetrachloroethane	2.842		E3	-4.5		0.08
32	1,1,2,2-Tetrachloroethane	4.342		E3	-11.9		0.06
33	FREON-11	4.315	3.648	E3	15.5		0.03
35	FREON-12	374.788			3.7		-0.05
36	FREON-113	4.411	4.123	<b>E</b> 3	6.5		0.06
43	Freon-22	549.764			16.3		0.11
44	Freon-141B	5.705	4.925	<b>E</b> 3	13.7	20	0.03

#### Evaluate Lab Control Standard Report

Data File : C:\HPCHEM\1\DATA\VOB8418.D Vial: 1

Acq On : 4 Sep 1998 7:15 pm Operator: Raphe HGS Sample : LCS 50NG
Misc : Heather 04SEP98 Inst : GC/MS Ins

Multiplr: 1.00

\_ iS Integration Params: rteint.p

Method : C:\HPCHEM\1\METHODS\10JUL98.M (RTE Integrator)
Title : FULL SCAN

Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min Max. RRF Dev : 15% Max. Rel. Area : 150%

	Compound	AvgRF	CCRF		%Dev	AccRge	Dev(min)
1 2 3 4 6	Vinyl Chloride Bromomethane Chloroethane 1,1-Dichloroethene Methylene Chloride 1,2-Dichloroethene (total)	313.657 1.337 1.954 2.244	1.179 2.076 2.311	E3 E3 E3	-11 -5.4 11 -6.2 -3.0	20	0.00 0.00 0.02 0.00 0.00 0.00
8 9 10	1,1-Dichloroethane Chloroform 1,2-Dichloroethane	4.263 4.082 2.370 3.402	4.138 4.055	E3 E3	2.9 0.7 10.0 3.3	20 20 20	0.02 0.04 0.03
12 13 14 15	1,1,1-Trichloroethane Carbon Tetrachloride Benzene Trichloroethene	3.402 3.164 7.158 3.213	2.767 7.161 3.116	E3 E3 E3	12.5 -0.0 3.0	20 20	0.04 0.04 0.05 0.04
16	1,2-Dichloropropane Bromodichloromethane cis-1,3-Dichloropropene	2.793 3.772 4.394	2.894 3.806 3.721	E3 E3	-3.6 -0.9 15.3	20 20	0.05 0.05 0.05
19 20 21 22	trans-1,3-Dichloropropene 1,1,2-Trichloroethane Dibromochloromethane Bromoform	2.957 2.453 3.387 3.130	3.333 2.796 3.368 2.982	E3 E3 E3	-12.7 -14.0 0.6 4.7	20 20	0.00 0.07 0.05 0.05
24 25 27	Toluene Tetrachloroethene Chlorobenzene	4.792 2.504 5.742	4.841 2.640 6.049	E3 E3	-1.0 -5.4 -5.3	20 20 20	0.10 0.04 0.12
28 29 30 31	Ethylbenzene Xylene (total) Styrene 1,1,1,2-Tetrachloroethane		3.055 13.969 5.586 2.747	E3 E3 E3	-1.2 4.4 5.3 3.3	20 20 20	0.10 0.17 0.23 0.08
32 <b>3</b> 3 35 36	1,1,2,2-Tetrachloroethane FREON-11 FREON-12 FREON-113	4.342 4.315 374.788 4.411	4.872 3.496 305.300 3.948	E3 E3	-12.2 19.0 18.5 10.5	25	0.08 0.02 -0.02 0.03

## CHROMATOGRAMS

File : C:\HPCHEM\1\DATA\VOB8280.D

Operator : Raphe HGS

Acquired : 29 Aug 1998 10:55 am using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: B-09031-BLANK

Misc Info : GREAT NECK/TT 29AUG98 1836/8-27-98 B3

Vial Number: 1

File : C:\HPCHEM\1\DATA\VOB8281.D

Operator : Raphe HGS

Acquired : 29 Aug 1998 11:49 am using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT6-09032-29

Misc Info : GREAT NECK/TT 29AUG98 1820/8-27-98 R6

Abundance		1 '	TIC: VC	B8281.D		-	
5800000		ł					
5600000							
5400000							
5200000							
5000000							
4800000							
4600000							
4400000							
4200000		1					
4000000							
3800000							
3600000							
3400000							
3200000							
3000000							
2800000							
2600000							
2400000							
2200000							
2000000							
1800000							
1600000							
1400000				•			
1200000							
1000000							
800000							
600000				**			
400000							
200000					11 1		
0 Time> 1.00 2.00	3.00 4.00	5.00 6.00	7.00 8.00	9.00 10.00	11.00 12.00	13.00 14	.00 15.00


File : C:\HPCHEM\1\DATA\VOB8282.D

Operator : Raphe HGS

Acquired : 29 Aug 1998 12:09 pm using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: TT6-09033-70

Misc Info : GREAT NECK/TT 29AUG98 1751/8-27-98 L6



File : C:\HPCHEM\1\DATA\VOB8283.D

Operator : Raphe HGS

Acquired : 29 Aug 1998 12:27 pm using AcqMethod 10JUL98

GC/MS Ins Instrument : Sample Name: TT6-09034-38

Misc Info : GREAT NECK/TT 29AUG98 1803/8-27-98 E4

Vial Number: 1

2.00 3.00 4.00 9.00 10.00 11.00 12.00 13.00 14.00 15.00 16.00 17.00 5.00 6.00 7.00 8.00

File : C:\HPCHEM\1\DATA\VOB8283D.D
Operator : Raphe HGS
Acquired : 29 Aug 1998 2:59 pm using 2:59 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT6-09034-38 df5

Misc Info : GREATNECKTT 29AUG98 1803/8-27-98 E4 Vial Number: 1

Abundance					1		Т	IC: VO	38283D	.D						
1900000																
1800000							l									
1700000							-									
1600000																
1500000																
1400000							·									
1300000																
1200000																
1100000																
1000000																
900000																
800000																
700000																
600000																
500000																
400000																
300000				}												
200000									; ; ;	1						
100000								ž.								
0			<u> </u>	<u>الحوالين</u>	البامرين يب	رسيدي		<u>_/</u> '	سداً س	سال	<u> </u>		·	ما . ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ ـ	٠	
Time> 1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.00	11.00	12.00	13.00	14.00	15.00	16.00	17.00

File : C:\HPCHEM\1\DATA\VOB8284.D

Operator : Raphe HGS Acquired : 29 Aug 1998 12:49 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT6-09035-60 purge 5'
Misc Info : GREAT NECK/TT 29AUG98 1635/8-27-98 Y2
Vial Number: 1

Abundance						TIC: V	OB8284.D							
								1						
360000														
340000														
320000														
300000														
280000														
260000														
240000														
240000														
220000														
200000														
180000														
160000														
140000														
120000														
100000								1						
100000														
80000														
60000					ı									
60000								1 1			1	•		
40000						•								
					•					J	santi J.	محمد ا	We comme	العاكوة ويواوي والان
20000	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	1	· I I	ميار المحمور الرار منعاط	. N	W-4-20/2-1914 V-1-1914	ui munun	j Num	MAN JOHN JOHN	N. A. Mary	1	M. Sc S.	,	
Time>	2.00	3.00	4.0	0	5.00	6.00	7.00	8.0	00	9.00	10.	00	11.00	


File : C:\HPCHEM\1\DATA\VOB8285.D

Operator : Raphe HGS

1:05 pm using AcqMethod 10JUL98 Acquired : 29 Aug 1998

Instrument : GC/MS Ins

Sample Name: TT6-09036-60 purge 14'
Misc Info : GREAT NECK/TT 29AUG98 1644/8-27-98 B2



File : C:\HPCHEM\1\DATA\VOB8286.D

Operator : Raphe HGS

Acquired : 29 Aug 1998 1:23 pm using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: TT6-09037-60 purge 24' Misc Info : GREAT NECK/TT 29AUG98 1654/8-27-98 N11

				•			)				
280000							!				
270000											
260000											
250000											
240000											
230000											
220000											
210000											
200000											
190000											
180000											
170000											
160000											
150000											
140000											
130000											
120000											
110000											
100000											
90000									•		
80000											
70000										1	
60000							. 1				
50000					1		. !				•
40000							. ' <sup>1</sup>				
30000											,
20000		. 1					My Mark	make shape toward	"Propos" Storyan	A COND	ika Minara ana
10000	and the second of	Malpa	ر المعلى المراجع المواجع الموا المواجع المواجع المواج	La en para de la	mary hydron	mga-NMWinneshin	دياً هاد. <u>۾</u>	<u> </u>			_
Time>	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.00	11.00	

File : C:\HPCHEM\1\DATA\VOB8287.D
Operator : Raphe HGS

Acquired : 29 Aug 1998 1:39 pm using AcqMethod 10JUL98 Instrument : GC/MS Ins

Sample Name: TT6-09038-60 purge 30'
Misc Info : GREAT NECK/TT 29AUG98 1703/8-27-98 A9

bundance	रा	C: VOB8287.D	
260000			
250000			
240000			
230000			
220000			
210000			
200000			
190000			
180000		•	
170000			
160000		•	
150000			
140000			
130000			
120000			
110000			
100000			
90000			
80000			
70000			
60000			
50000		1 1 <sup>9</sup> 1	
40000		1	
30000		<u> </u>	!, .
20000			and the state of the
10000	entransaminen (h. 1907), eta errakia eta errakia eta eta eta eta eta eta eta eta eta et	most of minute to the on	in a

File : C:\HPCHEM\1\DATA\VOB8288.D


Operator : Raphe HGS

Acquired : 29 Aug 1998 1:54 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT6-09039-60 purge 47'

Misc Info : GREAT NECK/TT 29AUG98 1717/8-27-98 N1



File : C:\HPCHEM\1\DATA\VOB8328.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 11:50 am using AcqMethod 10JUL98

Instrument : GC/MS Ins Sample Name: TT7-09074-34

Misc Info : Great Neck/TT 02SEP98 1836(01SEP98) S1 Vial Number: 1

Abundance 440000	_				TIC:	VOB8328.D					
420000											
400000											
380000											
360000											
340000											
320000											
300000											
280000											
260000											
240000											
220000											
200000											
180000											
160000											
140000											
120000											
100000											
80000 60000											
40000							ţ.				
20000						! !	I was	and the same of th	أرادام معين براء مالك معلمة	A) Markenine	ar Sign
Time>	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.00	11.00	

File : C:\HPCHEM\1\DATA\VOB8329.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 12:05 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT7-09075-60

Misc Info : Great Neck/TT 02SEP98 1841(01SEP98) A5 Vial Number: 1

Abundance 440000						•			TIC:	VOB8	329.D								
420000																			
400000																			
380000																			
360000																			
340000																			
320000																			
300000																			
280000																			
260000																			
240000																			
220000																			
200000																			
180000																			
160000																			
140000																			
120000																			
100000																			
80000																			
60000												,				,÷	gerd <sup>er</sup> .	, .	
40000												1.				.'		`. '.	,
20000	* ~ .	!		**************************************	مارست من المارست -	وجاح المحموسين	١٧ إمة كما إساستان	ا راسین.	- 4	on the second	معصبها برمب	√\	Mumman	mm	معمدار كور	~ ¹ ´			il Kalindan
Time>	2.00	2.50	3.00	3.50	4.00	4.50	5.00	5.50	6.00	6.50	7.00	7.50	8.00	8.50	9.00	9.50	10.00	10.50	11.00


File : C:\HPCHEM\1\DATA\VOB8330.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 12:20 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins
Sample Name: TT1-09076-73

Misc Info : Great Neck/TT 02SEP98 1738(01SEP98) R2



File : C:\HPCHEM\1\DATA\VOB8331.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 12:45 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins
Sample Name: TT1-09077-62

Misc Info : Great Neck/TT 02SEP98 1736(01SEP98) Y6

Vial Number: 1

File : C:\HPCHEM\1\DATA\VOB8332.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 1:02 pm using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: TT1-09077-62

3.00

4.00

5.00

6.00

7.00

8.00

9.00

10.00

11.00

12.00

13.00 14.00

Misc Info : Great Neck/TT 02SEP98 1656(01SEP98) E2

Vial Number: 1

File : C:\HPCHEM\1\DATA\VOB8333.D
Operator : Raphe HGS
Acquired : 2 Sep 1998 1:22 pm using
Instrument : GC/MS Ins 1:22 pm using AcqMethod 10JUL98

Sample Name: BLANK-09079

Misc Info : Great Neck/TT 02SEP98 1621(01SEP98) GN9 Vial Number: 1

Abundance								-	TIC: V	OB833:	3.D								
440000																	,		
420000											•								
400000																			
380000																			
360000																			
340000																			
320000																			
300000																			
280000																			
260000																			
240000																			
220000																			
200000																			
180000					•														
160000																			
140000																			
120000																			
100000																			
80000												,							
60000																			
40000			,												ı	ŀ	أس. أأنجير	10 ~	يواد ومومات
20000	A	والمن المال ا		ا د مرودد	en e	, share-ran	، ريعسيس شاليا	المرابع معراضها	u pamba	~~~~	Japan and	~	- with the subsection	grand a	گعمه مرز	ما مير د ۱۳۸۰ ۲۰۰	•		i
Time>	2.00	2.50	3.00	3.50				5.50	6.00	6.50	7.00	7.50	8.00	8.50	9.00	9.50	10.00	10.5	 O

File : C:\HPCHEM\1\DATA\VOB8334.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 1:37 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT6-09080-70

Misc Info : Great Neck/TT 02SEP98 1604(01SEP98) GN6 Vial Number: 1

Abundanse					-	TIC: VOB83	34.D				
1050000							,				
1000000											
950000											
900000											
850000											
800000											
750000											
700000											
650000											
600000											
550000											
500000					•						
450000											
400000											
350000											
300000											
250000											
200000											
150000											,
100000								ı. LA			
50000	84.7	~ unu= %			and Salah Kingdon	New Committee of the Co		T).		ا مسم سر سدید	
0 Time>	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.00	11.00

File : C:\HPCHEM\1\DATA\VOB8335.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 1:53 pm using AcqMethod 10JUL98

Instrument: GC/MS Ins
Sample Name: TT5-09081-37 PURGE 3.6'
Misc Info: Great Neck/TT 02SEP98 1431(01SEP98) GN1

Abundance	TIC: VOB8335.D	
1.35e+07	ļ	
1.3e+07		
1.25e+07		
1.2e+07	$\{\cdot\}$	
1.15e+07		
1.1e+07		
1.05e+07		
1e+07		
9500000		
9000000		
8500000		
8000000		
7500000		
7000000		
6500000		
6000000		
5500000		
5000000		
4500000		
4000000	ı	
3500000		
3000000		
2500000		
2000000		
1500000		
1000000		
500000	7 1	
_ 0	<u> </u>	
Time> 1.0	00 2.00 <u>3.00</u> 4.00 5.00 6.00 7.00 8.00 9.00 10.00 11.0	0 12.00 13.00 14.00

File : C:\HPCHEM\1\DATA\VOB8335D.D
Operator : Raphe HGS
Acquired : 2 Sep 1998 3:06 pm using

3:06 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT5-09081-37 DF10

Misc Info : Great Neck/TT 02SEP98 1431(01SEP98) GN1

Abundanse	•		TIC: VOB8335E	۵.0	
2100000					
2000000					
1900000					
1800000					
1700000				I	
1600000					
1500000					
1400000					
1300000					
1200000					
1100000					
1000000					
900000					
800000					
700000					
600000					
500000					
400000					
300000			1		1
200000				•	
100000			,		j Johanna
0 Time>	1.00 2.00 3.00	4.00	5.00 6.00	7.00 8.00	9.00 10.00

File : C:\HPCHEM\1\DATA\VOB8336.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 2:12 pm using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: TT6-09082-29

Misc Info : Great Neck/TT 02SEP98 1618(01SEP98) GN8

Vial Number: 1

Abundance TIC: VOB8336.D
8000000
7500000
6500000
6000000

5500000

5000000

4500000

4000000

3500000

3000000

2500000

2000000

1500000

1000000

500000

Time--> 1.00 2.00 3.00 4.00 5.00 6.00 7.00 8.00 9.00 10.00 11.00 12.00 13.00 14.00 15.00 16.00

File : C:\HPCHEM\1\DATA\VOB8337.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 2:33 pm using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: TT5-09083-62

2.00

3.00

4.00

5.00

6.00

7.00

8.00

9.00

10.00

Misc Info : Great Neck/TT 02SEP98 1545(01SEP98) GN5

Vial Number: 1

File : C:\HPCHEM\1\DATA\VOB8337D.D

Operator : Raphe HGS Acquired : 2 Sep 1998 2:48 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT5-09083-62 DF10

Misc Info : Great Neck/TT 02SEP98 1545(01SEP98) GN5 Vial Number: 1

Abundance	TIC: VOB8337D.D
1800000	
1700000	
1600000	
1500000	
1400000	
1300000	
1200000	
1100000	
1000000	
900000	
800000	
700000	;
600000	
500000	
400000	
300000	
200000	
100000	· 1.
1	

1.00 2.00 3.00 4.00 5.00 6.00 7.00 8.00 9.00 10.00 11.00 12.00 File : C:\HPCHEM\1\DATA\VOB8338.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 5:33 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins Sample Name: TT6-09084-38

Misc Info : GreatNeck/TT 02SEP98 1607(01SEP98) GN7

Vial Number: 1

TIC: VOB8338.D Abundance 9000000 8500000 8000000 7500000 7000000 6500000 6000000

5500000 5000000

4500000

4000000

3500000

3000000

2500000

2000000

1500000

1000000

500000

<u>10.00</u> 11.00 <u>12.00</u> 13.00 14.00 15.00 16.00 2.00 3.00

File : C:\HPCHEM\1\DATA\VOB8338D.D
Operator : Raphe HGS
Acquired : 2 Sep 1998 5:53 pm using 5:53 pm using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: TT6-09084-38 DF5

Misc Info : GreatNeck/TT 02SEP98 1607(01SEP98) GN7 Vial Number: 1

Abundance			·		TIC: VO	B8338D.	D			-		
2200000			1									
2100000					1							
2000000					ļ							
1900000			1									
1800000		•										
1700000					1							
1600000					1,							
1500000												
1400000												
1300000				,								
1200000												
1100000												
1000000												
900000												
800000												
700000												
600000												
500000												
400000												
300000			•					į				
200000								1 1 1				
100000						٠.	$\int_{\Sigma}$	الر	$\bigwedge$			
0 Time> 1.00	2.00 3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.00	11.00	12.00	13.00	14.00

File : C:\HPCHEM\1\DATA\VOB8336D.D

Operator : Raphe HGS
Acquired : 2 Sep 1998 8:20 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins Sample Name: TT6-09082-29

Misc Info : GreatNeck/TT 02SEP98 1618(01SEP98) GN8 Vial Number: 1

Time--> 0 1.00

2.00 3.00

Abundance	TIC: VOB	8336D.D	
1800000	İ		
1700000			
1600000			
1500000			
1400000			
1300000			
1200000			
1100000			
1000000			
900000	·		
800000			
700000			
600000		ŀ	
500000			
400000			
300000			
200000			
100000		1 ! 1 } 1 }	t.
		1. 1	j

5.00

4.00

6.00

7.00

8.00

9.00

10.00

File : C:\HPCHEM\1\DATA\VOB8340D.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 4:06 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT5-09086-37 PURGE 58' DF10

Misc Info : Great Neck/TT 02SEP98 1525(01SEP98) GN3

Vial Number: 1

Abundance TIC: VOB8340D.D 3400000

Time--> 1.00 2.00 3.00 4.00 5.00 6.00 7.00 8.00 9.00 10.00 11.00 12.00 13.00 14.00 15.00 16.00 17.00

File : C:\HPCHEM\1\DATA\VOB8341.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 4:27 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT5-09087-37 PURGE 14'

Misc Info : Great Neck/TT 02SEP98 1442(01SEP98) GN2

Vial Number: 1

TIC: VOB8341.D Abundance 1.5e+07 1.45e+07 1.4e+07 1.35e+07 1.3e+07 1.25e+07 1.2e+07 1.15e+07 1.1e+07 1.05e+07 1e+07 9500000 9000000 8500000 8000000 7500000 7000000 6500000 6000000 5500000 5000000 4500000 4000000 3500000 3000000 2500000 2000000 1500000 1000000 500000

9.00 10.00 11.00 12.00 13.00 14.00 15.00 16.00 17.00

2.00 3.00 4.00 5.00 6.00 7.00 8.00

File : C:\HPCHEM\1\DATA\VOB8341D.D

Operator : Raphe HGS

Acquired : 2 Sep 1998 4:50 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT5-09087-37 PURGE 14' DF10

Misc Info : Great Neck/TT 02SEP98 1442(01SEP98) GN2

Vial Number: 1


File : C:\HPCHEM\1\DATA\VOB8353.D

Operator : Raphe HGS

11:42 am using AcqMethod 10JUL98 Acquired : 3 Sep 1998

Instrument : GC/MS Ins Sample Name: TT3-09096-62

Misc Info : 03SEP98 1340(02SEP98) L4



File : C:\HPCHEM\1\DATA\VOB8354.D

Operator : Raphe HGS

Acquired : 3 Sep 1998 11:57 am using AcqMethod 10JUL98

Instrument : GC/MS Ins Sample Name: TT3-09097-52

Misc Info : 03SEP98 1338(02SEP98) N6 Vial Number: 1

Abundance 440000			TIC: VOB8354.D		
420000 -				·	
400000					
380000 -					
360000					
340000					
320000					
300000					
280000					
260000					
240000					
220000					
200000					
180000					
160000					
140000					
120000					
100000					
80000					
60000			† 		
40000					
20000	·	, , , , , , , , , , , , , , , , , , ,	1.	My Jayman Managar	Marine Carlo

File : C:\HPCHEM\1\DATA\VOB8355.D

Operator : Raphe HGS

Acquired : 3 Sep 1998 1:46 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins Sample Name: TT3-09098-72

Misc Info : 03SEP98 1348(02SEP98) S2 Vial Number: 1

Abundance		TIC: VOE	18355.D	
440000 -				
420000				
400000				
380000				
360000 -				
340000				
320000				
300000				
280000				
260000				
240000				
220000				
200000				
180000				
160000				
140000				
120000				
100000				
80000				
60000			,	,
40000		,		Ç.
20000	The second of th			a company of Manager and I want to be a fact of

File : C:\HPCHEM\1\DATA\VOB8356.D

Operator : Raphe HGS

Acquired : 3 Sep 1998 2:01 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins Sample Name: BLANK-09099

Misc Info : 03SEP98 1350(02SEP98) N12 Vial Number: 1

Abundance 440000						TIC: VOB8356	5.D				
420000											
400000											
380000											
360000											
340000											
320000											
300000											
280000											
260000											
240000											
220000											
200000											
180000											
160000											
140000											
120000											
100000											
80000											
60000							4				
40000		٠								-	
20000						and the same of	production of the contraction of	بسريارا	ng gapata dinanganasi si si	•	A Minerally in a
Time>	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.00	11.00	

File : C:\HPCHEM\1\DATA\VOB8393.D

Operator : Raphe HGS

Acquired : 4 Sep 1998 10:20 am using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT8-09133-42

Misc Info : GreatNeck/TT 04SEP98 1825(03sep98) E6

Abundance 1400000	_			TIC	: VOB8393	.D		- =		
1350000										
1300000										
1250000						1				
1200000										
1150000										
1100000										
1050000										
1000000										
950000						•				
900000										
850000										
800000										
750000										
700000										
650000										
600000										
550000										
500000										
450000						,				
400000										
350000										
300000									1	
250000										
200000										
150000						1			1	
100000									. 1	
50000			1			,		,		-
0	2.00	· · · · · · · · · · · · · · · · · · ·	4.00	E 00	6.00	7.00	9.00		40.00	
Time> 1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.00	11.00


File : C:\HPCHEM\1\DATA\VOB8394.D

Operator : Raphe HGS

Acquired : 4 Sep 1998 10:35 am using AcqMethod 10JUL98

Instrument: GC/MS Ins Sample Name: TT8-09134-62

Misc Info : GreatNeck/TT 04SEP98 1832(03sep98)Y2



File : C:\HPCHEM\1\DATA\VOB8395.D

Operator : Raphe HGS

Acquired : 4 Sep 1998 12:49 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT8-09135-42

Misc Info : GreatNeck/TT 04SEP98 1610(03sep98)L6 Vial Number: 1

bundance				TIC	VOB8395.E	)		
1150000				}				
1100000								
1050000								
1000000								
950000								
900000						٠		
850000								
800000				11				
750000								
700000								
650000								
600000								
550000								
500000								
450000								
400000						1		
350000						0 -		
300000						· ·		
250000						:		
200000								
150000						. 		•
100000				:		:		
50000				1		: <u> </u>		
0 ne> 1.00	2.00	3.00	- <u> </u>		والمستوارية المستورد		سيداء المراد ويتعالم والمستعدد المستعدد	

File : C:\HPCHEM\1\DATA\VOB8396.D

Operator : Raphe HGS

Acquired : 4 Sep 1998 1:04 pm using AcqMethod 10JUL98

Instrument : GC/MS Ins

Sample Name: TT1-09136-72 RESAMPLE

Misc Info : GreatNeck/TT 04SEP98 1643(03sep98)L3 Vial Number: 1

Abundance					TIC: V	OB8396.D						
440000												
420000												
400000												
380000 -												
360000												
340000												
320000												
300000												
280000												
260000												
240000												
220000												
200000												
180000												
160000												
140000												
120000												
100000							6 11					
80000							j.					
60000				,						Ī		
40000				• .						1		
20000	·	tie.					~ ^ \	بالمسترسية	أ للعدم مريد ومحمد معام	race the company	المراهدين المتم	•
Time>	2.00 2.50	3.00 3.50	4.00 4.5	0 5.00	5.50 6.00	6.50 7.00	7.50	8.00 8.	50 9.00	9.50 1	0.00 10.5	0

File : C:\HPCHEM\1\DATA\VOB8397.D
Operator : Raphe HGS
Acquired : 4 Sep 1998 1:21 pm using AcqMethod 10JUL98
Instrument : GC/MS Ins
Sample Name: TT8-09137-62
Misc Info : GreatNeck/TT 04SEP98 1615(03sep98)F9
Vial Number: 1

Abundance			TIC:	VOB8397.D			
440000							
420000							
400000							
380000							
360000							
340000							
320000							
300000							
280000							
260000							
240000							
220000							
200000							
180000							
160000	•						
140000							
120000							
100000							
80000							
60000							
40000					ı	<i>J</i>	
20000				and the second	Makeus and Milleryan 1984.	and water to	All the second of the second o
	A manager of the contract of t	ه هجر بروند و موسد می امو و بروند. 		And the Control of th			
Time>	2.00 3.00	4.00 5.00	6.00	7.00 8.0	0 9.00	10.00 1	1.00

## Chains of Custody

PROJECT Great Neck Plume Verificat a CLIENT Lockheed Martin DATE 4-27-98

SAMPLE ID-Depth(ft)	INSTALLED	SAMPLED	BULB ID	FLOW ml/min	TIME min	Purge Vol	MISC Leak Check
TT-6-60', 8 pu	8-25-98	1630 -> 1635 45-27-98	42	150	5	564ml	PED 800 PPM
11 2.4ev	/	( -> 1644	B2	1	الر	1692ml	
11 4/00		7 1654	71		24	2820	
11 5.600		1703	A 9			39 48ml	1
ال ج	\ _	1717	2		47	7050ml	
TT-6-70		1717 - 1751 1-27-92	26		34	5125W	PIN 10 ppm
TT-6-38'		1739 -> 1803	ELI		24	3525M	PID 141 ppm
TT-6-29'	8-25.98	7-27-99	R 6	150		1	DID 2100 ppm
BLANK		8-27-98 1836	B3				
					-		
			_				
					-		

SURROGATES: D6-Benzene D8-Toluene D-Chlorof	form D6-DMK D-DCM		
RELINQUISHED BY:	_RECEIVED BYFeeler	DATE/TIME <u>8:27-98 / 193</u> 0	
RELINQUISHED BY Fell	_ RECEIVED BY Mark	1_DATE/TIME_ 8-29-18	

PROJECTGISCH Neck Plane Verification CLIENT Lockheed Martin DATES 1-98RB

SAMPLE ID-Depth(ft)	INSTALLED	SAMPLED	BULB ID	FLOW ml/min	TIME min	Purge Vol	MISC Leak Check
TT-6-37'-1	8-26.98	9-1-98/1431	61NI	150	3.6		1/4
TI-5-37'-2	8-26.98	9-1-98/1442	GH2	150	14.4		Mormal
TT-5-37'-3		9-1-98/1525		150	57.6		4x
11-5-73		9-1-98/1523			22		
TT-5-62	1	9-1-98/1545			28		,
TT-6-70		9-1-98/1604		_	21		Rosample
TT-6-38	8-25-98	9-1-98/1607	6N7	150	15		Resumple
TT.6-29	8-25-98	9-1-98/1618	5N8	150	13		Resumply
BLANK		9-1-98/1621					·
TT-6-60	8-25-98	9-1-98/1656	Ea	150	19		Resample
M-1-73	8-27-98	9-1-98/1738	R2	150	22		
TT-1-62	8-27-98	9-1-98/1736	76	150	20		
TT-7-34		9-1-98/1836		150	15		
TT-7-60		9-1-981841		150	19		

SURROGATES: <u>D</u> 6-Benzene	_ D8-Toluene I	D-Chloroform	D6-DMK			<u> </u>		
DEI INTITIONE	DBY: Bdny P	S. L. L. DEC	TEIVED BY TE	DEV	DATE/TIME	9-1-98	1937	
RELINQUISHE	DBI: VOOVE	JYSPF REC			_			
RELINQUISHE	DBY Feder	REC	CEIVED BY <u>/</u>	Hould	_DATE/TIME_	9-2-98	<u> </u>	

PROJECT Great Nack Plume Veriliation Client Lockhad Martin DATE 9-2-98

SAMPLE ID-Depth(ft)	INSTALLED	SAMPLED	BULB ID	FLOW ml/min	TIME min	Purge Vol	MISC Leak Check
TT3-52	8-31-98	9-2-98/1338	76	150			
TF3-62	8-31-98	9-2-98/1340	4	150			
TT3-72	1	9-2-98/1348	52	150			
		,					
				-			
				-			
		-					
				-			
	· · · · · · · · · · · · · · · · · · ·						
		-			_		
						<u> </u>	

SURROGATES: D6-Benzene	D8-Toluene1	D-Chloroform	D6-DMK	<i>D-DCM</i>		
RELINQUISHED	ву.4-7-3-	RECEI	VED BY FED	DEX	date/time <u>9-2-98-</u>	<u>173</u> 0
RELINQUISHED	BY	RECE	IVED BY		_DATE/TIME	

PROJECT Gyreat Hak Thum Varidicustra Tuja GLIENT Lockhus Marsin DATE 9-3-98

SAMPLE ID-Depth(ft)	INSTALLED	SAMPLED	BULB ID	FLOW ml/min	TIME min	Purge Vol	MISC Leak Check
77-8-42	8-31-98	9-3-98/1610	16	150	15		
77-8-42 TT-8-62	8-31-98	7-3-48/1615	F9	150	23		
TI-1-72	8-27-98	9-3-98/1643	43	150	22	`	Resamply
Tr.8- 42	8-31-98	9-3-98 /1825	E6	150	15		Resamply Dup
TT-8-62	_	9-3-96/1830	72	150	20		Dan
Blank		9-3-48/1835	54				
		, ,					
				· 			
				,			
				ı	-		

SURROGATES: D6-Benzene	_ D8-Toluene	_ D-Chloroform	D6-DMK	D-DCM			
	$Z_{I}$ :	Z n =					$\Gamma = 1$
RELINQUISH	ED BYCLEY	REC	EIVED BY Tu	dex	DATE/TIME	9-3-58/	<u>19</u> 30
	70			2000	,	2 /	
RELINQUISH	ED BY FEEL	<u></u>	CEIVED BY <u>//</u>	Hanhal	_DATE/TIME;	<u> </u>	