

Monthly Inspection Photograph Log

Client: NYSDEC

Project Number: 3616206123

Site Name: Franklin Cleaners

Site Location: Rockville Centre, New York

Photographer:

Mike Bates

Date:

May 13, 2022

Photograph: 1

Direction:

Not applicable

Description:

Fire extinguisher tag documenting monthly inspection.



Photographer:

Mike Bates

Date:

May 13, 2022

Photograph: 2

Direction:

Northeast

Description:

Fire extinguisher.



Monthly Inspection Photograph Log

Client: NYSDEC

Project Number: 3616206123

Site Name: Franklin Cleaners

Site Location: Rockville Centre, New York

Photographer:

Mike Bates

Date:

May 13, 2022

Photograph: 3

Direction:

Northeast

Description:

Lawn surrounding treatment building.



Photographer:

Mike Bates

Date:

May 13, 2022

Photograph: 4

Direction:

Southeast

Description:

Lawn surrounding treatment building.



Monthly Inspection Photograph Log

Client: NYSDEC

Project Number: 3616206123

Site Name: Franklin Cleaners

Site Location: Rockville Centre, New York

Photographer:

Mike Bates

Date:

May 13, 2022

Photograph: 5

Direction:

West

Description:

Lawn surrounding treatment building.



Photographer:

Mike Bates

Date:

May 13, 2022

Photograph: 6

Direction:

Northwest

Description:

Lawn surrounding treatment building.

