

Monthly Inspection Photograph Log

Client: NYSDEC

Project Number: 3616206123

Site Name: Franklin Cleaners

Site Location: Rockville Centre, New York

Photographer:

Mike Bates

Date:

July 26, 2022

Photograph: 1

Direction:

Not applicable

Description:

Fire extinguisher tag documenting monthly inspection.



Photographer:

Mike Bates

Date:

July 26, 2022

Photograph: 2

Direction:

North-northeast

Description:

View of fire extinguisher gauge and pin.



Monthly Inspection Photograph Log

Client: NYSDEC

Project Number: 3616206123

Site Name: Franklin Cleaners

Site Location: Rockville Centre, New York

Photographer:

Mike Bates

Date:

July 26, 2022

Photograph: 3

Direction:

North-northwest

Description:

General view of fire extinguisher.



Photographer:

Mike Bates

Date:

July 26, 2022

Photograph: 4

Direction:

West

Description:

View of vegetative growth and treatment building.



Monthly Inspection Photograph Log

Client: NYSDEC

Project Number: 3616206123

Site Name: Franklin Cleaners

Site Location: Rockville Centre, New York

Photographer:

Mike Bates

Date:

July 26, 2022

Photograph: 5

Direction:

West-southwest

Description:

View of vegetative growth within fenced area around treatment building.



Photographer:

Mike Bates

Date:

July 26, 2022

Photograph: 6

Direction:

Southeast

Description:

View of vegetative growth within fenced area around treatment building.

