



**Department of
Environmental
Conservation**

**Division of Environmental Remediation
Central Office**

DAILY INSPECTION REPORT

Site Code #: 1-30-053A	Date: 03/23/2015	Report #: 1
-------------------------------	-------------------------	--------------------

Site Name: Pass and Seymour – Waste Characterization, Transportation & Disposal

Location: Glen Cove, Nassau County

DEC Proj. Mgr.: Michael Mason

Contractor: Environmental Assessment & Remediation (EAR)

	AM	PM
Weather	Clear	Clear
Temperature	20	35
Wind Direction	West	West

Description of work performed by contractor this report period:

EAR (Prime):

- Waste chemicals recovered from Building 7 were staged at the west end of the building near the loading dock.
- Contractor entered Building 45B to document and recover waste chemicals remaining in the building.

Discussions/comments regarding visitors, contractor and/or engineer:

Summary of samples collected this report period:

Sample Number	Date Collected	Sample Type	Location	Parameter	Method Number	Turn Around

Health & Safety:

Level of protection: C when entering buildings

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? Yes

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from: 6:30am – 3:00pm

Subcontractor	Activity	Hours Worked
(1) PSC	Chemical Disposal	

Equipment	P	1	2	3	4	Personnel	P	1	2	3	4
Pick up/Ford F150						Super	1				
Pick Up/Ford Ranger	1					Laborers	3				
Decon Trailer	1					Chemists	1				
Generator	1					Laborer					
Utility Trailer	1					Technician					
Tractor Trailer											
Pick up/Ford F250	1										
Box Truck											
Sampling Van	1										
Fork Lift/Doosan											

Site Representative: Kristopher Keenan

Date: 03/23/2015

Representative's Signature:




Photo Log



Waste chemicals staged at west end of Building 7



Building 7. Unknown substance on floor



DATE: 8/24/94
 DRAWN BY: J. J. BARTON
 PROJECT: 643003

Barton
Reguidice, P.C.
 Engineers - Environmental Scientists - Planners - Landscape Architects

PHOTO CIRCUITS CORPORATION
 LOCATION OF HAZARDOUS
 WASTE STORAGE AREAS
 GLEN COVE NEW YORK

Figure
 1
 Project No.
 643 003

Currently occupied by Ted Dubik North Shore Contracting (516-676-2772)

155