



**Department of
Environmental
Conservation**

**Division of Environmental Remediation
Central Office**

DAILY INSPECTION REPORT

Site Code #: 1-30-053A	Date: 04/16/2015	Report #: 03
-------------------------------	-------------------------	---------------------

Site Name: Pass and Seymour – Waste Characterization, Transportation & Disposal

Location: Glen Cove, Nassau County

DEC Proj. Mgr.: Michael Mason

Contractor: Environmental Assessment & Remediation (EAR)

	AM	PM
Weather	Cloudy	Cloudy
Temperature	45	55
Wind Direction	South	South

Description of work performed by contractor this report period:

EAR (Prime):

- Carbon was removed from two 2000lb carbon vessels that were part of a water treatment system between Building 45A and Building 7. Carbon was vacced out and containerized in 55 gallon drums.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling this report period:

Health & Safety:

Level of protection: C

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? Yes

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from: 6:30am – 3:00pm

Subcontractor	Activity	Hours Worked
(1) PSC	Chemical Disposal	

Equipment	P	1	2	3	4	Personnel	P	1	2	3	4
Pick up/Ford F150	1					Super	1				
Pick Up/Ford Ranger	1					Laborers	2				
Decon Trailer	1					Chemists	1				
Generator	1					Technician					
Utility Trailer	1										
20ft Storage Container	1										
Pick up/Ford F250	1										
Box Truck											
Sampling Van	1										
Fork Lift/Doosan											

Site Representative: Kristopher Keenan


Date: 04/16/2015

Representative's Signature:



Photo Log

No photos



Currently occupied by Ted Dubilly North Shore Contracting (516-676-2772)