



Photo 1: Bomb Shelter doorway, facing west.



Photo 2: Drain observed in bomb shelter floor.



Photo 3: Opened metal drain plate with drain cap in bomb shelter.



Photo 4: 2" diameter drain pipe.



Photo 5: View of illuminated dry well beneath bomb shelter floor.




Photo 6: Bomb shelter doorway with holes in wall, facing east.



Photo 7: Blocked entrance to bilco doors in basement western foundation wall.



Photo 8: Approximate location of bomb shelter and drainpipe/drywell beneath parking lot/sidewalk, facing east.