

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Site Name: Tamco Industries Inc Class: 2 Number: 1-52-006

O&M Funding Source: ☐ State Superfund ☐ Federal Superfund ☐ Municipal ☒ Responsible P:

O&M Information: O&M Start: 12/97 End: _____ Annual Cost: \$ _____ ☐ Est:

Interim Remedial Measures/Operable Units in O&M Phase:

☐ Drum Removal ☐ Soil Removal ☐ Tank Removal
☐ Cap/Cover ☐ Containment Structure ☐ Fence/Security
☐ Groundwater Recovery/Treatment ☐ Leachate Collection/Treatment ☒ Vapor Extraction/Treatment
☐ Air Sparging/Stripper System ☐ Treatment/Filtration Plant/System ☐ Potable Water Supply/System
☐ Other: _____

Institutional Controls: ☐ Deed Restriction ☐ Discharge Permit ☐ Department of Health Sample
☒ Other: Permissible air emission levels imposed by DOAR

O&M Review Information:

Reports: _____

Inspection: _____

Sampling: Monthly air monitoring with PID and Carbon Sorbent Method

Other: _____

Conclusions:

Remedy Effective? ☒ Yes ☐ No: Effluent air monitoring has been consistently below the air emission levels imposed by DOAR.

ROD Compliance? ☐ Yes ☐ No: _____

Consent Order Compliance? ☐ Yes ☐ No: _____

Other: _____

Recommendations: Continue operating and monitoring the system.

ROD/Consent Order Modifications? ☐ No ☐ Yes (per above) Reclassify the Site? ☐ No ☐ Yes → Class: _____

Comments: _____

Project Manager: Jamie Ascher 8/7/98
Signature Date
Jamie Ascher Reg 1 516 444 0246
Name Region or Bureau Telephone

Reviewer: Bob Becker 8/7/98
Signature Date
Bob Becker, DER 516 444 0291
Name Region or Bureau Telephone