
SMS Instruments 152026

DER Site Management, 03/02/2011. Report by Will Welling, NYSDEC.

Photos with Notes

Photo

Description



Day 2, 3/2/2011. This day we scoped out air sampling locations in Marble.com. This view is looking towards the stone place from the southwest corner of SMS Instruments.



Inside the brick stone warehouse and cutting shop



Inside the stone warehouse, all is neat and orderly.



This is the cutting area. I believe cutting is done with water. The area is dry and it looks like Marble.com is not yet set up to cut.



This is the cutting area.



Large stone slabs



Tile and concrete cover or make up the floor. We were looking for an un-tiled location but there were none.



A sampling location: there is tile here too.



More drilling in approximately the same area as yesterday's drilling.



Large capacity lift truck handling stone in the yard next door



Parting shot looking down the driveway back towards Marcus Blvd.

