

Project: Spectrum Finishing - Remedial Action  
 Contractor: EnviroTrac Environmental Services  
 CDM Job No: D-006956 Site No. 1-52-029  
 CDM Project Manager: John Blaum

CDM  
 100 Crossways Park West  
 Woodbury, NY 11797  
 Telephone: 516.496.8400  
 Fax: 516.496.8864

### DAILY REPORT

Day: 

S	<b>M</b>	T	W	TH	F	S
---	----------	---	---	----	---	---

  
 Date: 16-Mar-09  
 REPORT No. 100  
 PAGE No. 1

<b>WEATHER</b>	Clear	<b>Partly Cloudy</b>	Overcast	Rain	Snow
<b>TEMP L/H</b>		<b>32/49</b>			
<b>HUMIDITY</b>	Dry	<b>Moderate</b>	High		
<b>WIND</b>	Calm	<b>Light</b>	Moderate	High	
<b>WIND DIR</b>	N	E	S	W	
	<b>NE</b>	SE	SW	NW	

PREPARED BY: F.Robinson TITLE: Inspector

#### **AVERAGE FIELD FORCE**

Name of Contractor	Title	Hours Worked	Remarks
EnviroTrac	Construction Manager	1x4 hrs	J. Szymanski'
YEC Inc.	Surveyor	2x2 hrs	D.Stedge P.Webster

#### **EQUIPMENT AT THE SITE**

I = Idle      W = Working

20" Storage Container - W	
Case CX130 Excavator - I	
Case 621D Front End Loader - I	
Daewoo 450 skidder - I	

#### **HEALTH AND SAFETY**

Name	Time (From - To)	Task/Level of PPE
All workers onsite were in level D-PPE		

#### **CONSTRUCTION ACTIVITIES**

<b>Site Representative:</b> Frank Robinson - CDM
<b>Health and Safety Site Officer:</b> N/A
<b>DESCRIPTION OF WORK PERFORMED AND OBSERVED</b>
1-YEC surveyors on site to survey the additional east and west alleyway excavations and sample locations.



x - Designates report is continued on additional pages

CDM Site Representative: F. Robinson

Project Manager: John Blaum

**PHOTOGRAPHIC LOG**

**Date: 03/16/09**

**CDM Job No. D-006956**

**Spectrum Finishing Remedial Action**

**SITE No. 1-52-029**

<b>PHOTO</b>	<b>DATE</b>	<b>TIME</b>	<b>DESCRIPTION</b>
100_0125.jpg	3/16/2009	PM	YEC surveyors surveying east alleyway

# PHOTOS 3-16-09



100\_00125.jpg - YEC Surveyors surveying east alleyway.

