

Project: Spectrum Finishing - Remedial Action
 Contractor: EnviroTrac Environmental Services
 CDM Job No: D-006956 Site No. 1-52-029
 CDM Project Manager: John Blaum

CDM
 100 Crossways Park West
 Woodbury, NY 11797
 Telephone: 516.496.8400
 Fax: 516.496.8864

DAILY REPORT

Day:

S	M	T	W	TH	F	S
---	---	---	---	----	---	---

 Date: 29-Apr-09
 REPORT No. 132
 PAGE No. 1

WEATHER	Clear	Partly Cloudy	Overcast	Light Rain	Snow
TEMP L/H		51/61			
HUMIDITY	Dry	Moderate	High		
WIND	Calm	Light	Moderate	High	
WIND DIR	N	E	S	W	
	NE	SE	SW	NW	

PREPARED BY: F.Robinson TITLE: Inspector

AVERAGE FIELD FORCE

Name of Contractor	Title	Hours Worked	Remarks
EnviroTrac	Construction Manager	1x8 hrs	M. Rose
EnviroTrac	Operator	2x8 hrs	B.Gimbel, J. Byrnes
EnviroTrac	Technician	2x8 hrs	R.Maletta, K.Davies

EQUIPMENT AT THE SITE I = Idle W = Working

20" Storage Container - W	Sakai Paving Pro 270 Roller Compactor - W
Case CX130 Excavator - W	
Case 621D Front End Loader - W	
Daewoo 450 skidder - W	

HEALTH AND SAFETY

Name	Time (From - To)	Task/Level of PPE
		All workers onsite were in level D-PPE

CONSTRUCTION ACTIVITIES

Site Representative: Frank Robinson - CDM
Health and Safety Site Officer: N/A
DESCRIPTION OF WORK PERFORMED AND OBSERVED
1-Tailgate H&S meeting performed before the start of the work day.
2-EnviroTrac continued to install and compact recycled concrete aggregate (RCA) in the excavation area.

x - Designates report is continued on additional pages

CDM Site Representative: F. Robinson Project Manager: John Blaum

PHOTOGRAPHIC LOG
29-Apr-09
CDM Job No. D-006956
Spectrum Finishing Remedial Action
SITE No. 1-52-029

PHOTO	DATE	TIME	DESCRIPTION
100_00524.jpg	4/29/2009	PM	East alleyway at the end of the day, looking west
100_00525.jpg	4/29/2009	PM	South alleyway at the end of the day, looking south
100_00526.jpg	4/29/2009	PM	Excavation at the end of the day, looking east
100_00527.jpg	4/29/2009	PM	Excavation at the end of the day, looking east

PHOTOS 4/29/09



100_00524.jpg - East alleyway at the end of the day,




100_00525.jpg - South alleyway at the end of the day, looking south



100_00526.jpg - Excavation at the end of the day, looking east



100_00527.jpg - Excavation at the end of the day, looking east



PLAN
1" = 20'

Work Areas

4/20/09

East Alleyway

South Alleyway

West Alleyway

Utility Pole

STORAGE CONTAINER

Sump 1
Sump 2
Sump 3
Sump 2A

61 CABOT ST.
1 STY. BRICK WAREHOUSE

60 DALE ST.
(SPECTRUM)
1 STY. BRICK WAREHOUSE

51 CABOT ST.
(UNIQUE DOOR GALLERY)
1 STY. BRICK WAREHOUSE

45 CABOT ST.
1 STY. BRICK WAREHOUSE

40 DALE ST.
1 STY. BRICK WAREHOUSE

50 DALE ST.
(SPECTRUM)
1 STY. BRICK WAREHOUSE

DALE

STREET