

**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**1**

**Date:**  
4/21/22

**Description:**

Condition of front gate when we arrived to the site



**Photo No.**  
**2**

**Date:**  
4/21/22

**Description:**

View of front of site when we arrived



**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**3**

**Date:**  
4/21/22

**Description:**

Canister SV-1 after  
installed and started



**Photo No.**  
**4**

**Date:**  
4/21/22

**Description:**

Close up of canister SV-1





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**5**

**Date:**  
4/21/22

**Description:**

Another close up view of SV-1



**Photo No.**  
**6**

**Date:**  
4/21/22

**Description:**

View of SV-2 with duplicate SV-2X and ID-1 some 7' to the left





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**7**

**Date:**  
4/21/22

**Description:**

Canisters SV-2 and SV-2X in the middle of the room




SerAll. Bayshore, L.I. New York  
SV-2  
Apr 21, 2022 11:33:16 AM

**Photo No.**  
**8**

**Date:**  
4/21/22

**Description:**

The back of the building and OD-1 barely visible against the wall under the window



SerAll. Bayshore, L.I. New York  
OD-1  
Apr 21, 2022 11:35:55 AM



**Client Name:**  
NYSDEC


**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**9**

**Date:**  
4/21/22

**Description:**

A better view of OD-1 with a long tubing extending out through an opening in the window so it can collect air from outside




**Photo No.**  
**10**

**Date:**  
4/21/22

**Description:**

Close up of OD-1 sitting on the floor near the wall





**Client Name:**

NYSDEC

**Site Location:**


8 Drayton Avenue, Bayshore, NY

**Photo No.****11****Date:**

4/21/22

**Description:**

Tubing coming out of OD-1 and going through the window to the back parking lot

**Photo No.****12****Date:**

4/21/22

**Description:**

Tubing from OD-1 coming out into the parking lot and secured in place with tape





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**13**

**Date:**  
4/21/22

**Description:**

AECOM placed some items in front of the canister so they would be less visible in case someone breaks into the building overnight



**Photo No.**  
**14**

**Date:**  
4/21/22

**Description:**

Wall between the two buildings



**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**15**

**Date:**  
4/21/22

**Description:**

Plastic drum placed in front of SV-1 to block its view from the front of building



**Photo No.**  
**16**

**Date:**  
4/21/22

**Description:**

View of the back of the building





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**17**

**Date:**  
4/21/22

**Description:**

Trench in the middle of the building probably used for draining



**Photo No.**  
**18**

**Date:**  
4/21/22

**Description:**

A large sump in the middle of the room attached to the trench





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**1**

**Date:**  
4/21/22

**Description:**

View of inside the sump in the middle of the building and attached to the trench




**Photo No.**  
**2**

**Date:**  
4/21/22

**Description:**

A box was placed on top of OD-1 to make it less visible





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**3**

**Date:**  
4/21/22

**Description:**

SV-2 covered with a shirt found on the floor to make it less visible



**Photo No.**  
**4**

**Date:**  
4/21/22

**Description:**

SV-1 was covered to make it less visible in case someone breaks into the building overnight





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**5**

**Date:**  
4/21/22

**Description:**

View of the empty lot to the West of the site



**Photo No.**  
**6**

**Date:**  
4/21/22

**Description:**

The parking lot in the back of the building.  
Photo facing East





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**7**

**Date:**  
4/21/22

**Description:**

The bakery located to the East of the site



**Photo No.**  
**8**

**Date:**  
4/21/22

**Description:**

Several cars were parked in front of the site seen in the background





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**9**

**Date:**  
4/21/22

**Description:**

Alley way between the site and the bakery to the East



**Photo No.**  
**10**

**Date:**  
4/21/22

**Description:**

View of the front of the site as we completed the work on the first day





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**11**

**Date:**  
4/21/22

**Description:**

With the help from the bakery's manager AECOM was able to lift the plywood covering the front and set it so it would not fall



**Photo No.**  
**12**

**Date:**  
4/21/22

**Description:**

Another view of the front of the building at the end of the day





**Client Name:**

NYSDEC

**Site Location:**

8 Drayton Avenue, Bayshore, NY

**Photo No.**


1

**Date:**

4/22/22

**Description:**

View of the area where SV-2 and SV-2X were set up after the test ended, the tubing was pulled and the hole patched



**Photo No.**

2

**Date:**

4/22/22

**Description:**

The area where SV-1 was set up after the test ended, the tubing was pulled and the hole patched





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**3**

**Date:**  
4/22/22

**Description:**

The back of the building  
after the tests ended.



**Photo No.**  
**4**

**Date:**  
4/22/22

**Description:**

The building attached to  
the site had no electricity  
and was full of debris





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**5**

**Date:**  
4/22/22

**Description:**

Debris seen in the building attached to the site. The floor was generally covered with debris



SerAll. Bayshore, L.I. New York  
Apr 22, 2022 11:29:03 AM

**Photo No.**  
**6**

**Date:**  
4/22/22

**Description:**

The front of the building after the tests were completed and the plywood covering the gate on the left was raised and placed in such a way as it would not easily get blown down by the wind



SerAll. Bayshore, L.I. New York  
Apr 22, 2022 11:45:22 AM



**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**7**

**Date:**  
4/22/22

**Description:**

Church located North and across the street from the site



**Photo No.**  
**8**

**Date:**  
4/22/22

**Description:**

View of the bakery to the East of the site





**Client Name:**  
NYSDEC

**Site Location:**  
8 Drayton Avenue, Bayshore, NY

**Photo No.**  
**9**

**Date:**  
4/22/22

**Description:**

Alley way between the site and the bakery to the East



**Photo No.**  
**10**

**Date:**  
4/22/22

**Description:**

BLANK