

Photolog of Remedial Activities
June 7, 2022
Liberty Industrial Finishing Site
500-550 Suffolk Avenue, Brentwood, NY

Below: View of former impacted soil stockpile area. Eight dump truck loads of this soil were removed on 6/7/22 and transported for disposal at the ACUA landfill, which completely removed the stockpile.



Below: View of concrete chunks removed from the permanently-capped area. This concrete was reported to originate from a platform and stairs at the rear of the former building, which were demolished at the time that the tank remediation and abandonment were conducted.



Below: Former temporarily-capped area after removal of additional soil from the north and south ends . This area is now approximately 20 feet wide, 35 feet long, and between 3 and 5 feet deep. View is looking south at the former foundation adjoining the abandoned tank area. Confirmatory samples were collected from the floor and north wall of the enlarged excavation.



Below: View looking north at the enlarged excavation.

