

Project: National Heatsheet Printing Site - Off-Site - Site Management
 Contractors: AECOM and Preferred Environmental Services
 AECOM Job No: 60135649
 Site No: 1-52-140
 AECOM Project Manager: Walt Howard

AECOM
 40 British American Boulevard
 Airport Park
 Latham, NY 12110
 Telephone: 518.7951.2242

DAILY REPORT

Day:

S	M	T	W	TH	F	S
---	---	---	----------	----	---	---

 Date: 27-Mar-13
 REPORT No. _____
 PAGE No. 1
 PREPARED BY: Thomas Fitzpatrick TITLE: Site Rep.

WEATHER	Bright Sun	Partly Cloudy	Overcast	Rain	Clear
TEMP	To 32	32-50	50-70	70-85	85 and up
WIND	Light	Moderate	High		
HUMIDITY	Dry	Moderate	Humid		
WIND DIR	NE	NW	SE	SW	
	N	S	E	W	

AVERAGE FIELD FORCE

Name of Contractor	Title	Hours Worked	Remarks
Thomas Fitzpatrick	Technician	14:18 - 17:00	Preferred
Marc Morgenstern	Technician	14:40 - 15:10	Preferred

VISITORS

Name	Time (From - To)	Representing	Remarks
NA	NA	NA	NA

EQUIPMENT AT THE SITE

I = Idle W = Working

1. Camera - W	3. Pressure Gauges - W	5. Vacuum Pump - W	7. VelociCalc - TSI 9555/9 -W
2. PID - W	4. Interface Probe - W	6. Four Gas Meter - W	

OPERATION & MAINTENANCE ACTIVITIES

AECOM/Preferred Site Representative: Thomas Fitzpatrick - Preferred
DESCRIPTION OF WORK PERFORMED AND OBSERVED
14:18 - Preferred arrived on-site. Both systems are up with three (3) alarms triggered:
3/20/2013 14:06 W8: Well DDC-5 Low Differential Pressure
3/20/2013 14:31 W13: Well DDC-6 Low Differential Pressure
3/20/2013 14:06 W12: Well DDC-7 Low Differential Pressure
14:21 - Weekly O&M started.
14:40 - Marc Morgenstern on-site to assist in the gauging of the DDC wells along Benjoe Drive.
15:10 - Marc Morgenstern off-site.
16:55 - O&M completed.
17:00 - Preferred locked both sheds and all parties off-site. All alarms were reset, with blowers B-501 & B-502 up upon departure.

- Designates report is continued on additional pages

AECOM/Preferred Site Representative: Thomas Fitzpatrick (Preferred)

Project Manager: W. Howard

O&M DATA SHEET - NATIONAL HEATSET - OFF-SITE SYSTEM

Date: 3/27/2013

Time: 14:25

Weather: 48° F - Partly Cloudy- Dry

B-501 Status on Arrival: **Up** / Down / Off

B-502 Status on Arrival: **Up** / Down / Off

Alarm Light Status on Arrival: **ON** / OFF

Alarm Light Reset on Arrival: YES / **NO**

SYSTEM OPERATING DATA

ID	B-501	TP-211	B-502	TP-212	B-503	TP-213	Time
Hours	6,615.9	0.1	6,891.9	0.3	0	0	@ 14:22
Hz	27	Hz	27		Separator ID	Water Level (IN)	Drained
PI-511	5.9	PI-512	7.2		ST-201	0	YES / NO
TSH-511	110	TSH-512	155		ST-202	0	YES / NO
VI-201	-2.5	IWC	VI-202		-2.0	IWC	
TI-201	58	°F	TI-202	61	°F		
DPT-201	0.39	IWC (6" Pipe)	DPT-202	0.42	IWC (6" Pipe)		
V-DLH5-6	Open / Closed		V-DLH5-6	Open / Closed			
VI-401	-4.0	IWC	VI-402	-4.0	IWC		
TI-401	58	°F	TI-402	59	°F		
VI-401B	-5.0	IWC	VI-402A	-17	IWC		
SP-401B	0.0	ppb / <u>ppm</u>	SP-402A	0.0	ppb / <u>ppm</u>		
VI-401A	-18	IWC	VI-402B	-6.0	IWC		
SP-401A	0.0	ppb / ppm	SP-402B	0.7	ppb / <u>ppm</u>		
VI-403B	-13	IWC	VI-403A	-13	IWC		
SP-403B	0.0	ppb / <u>ppm</u>	SP-403A	0.0	ppb / <u>ppm</u>		
VI-501	-24	IWC	VI-502	-22	IWC		
SP-501	0.0	ppb / <u>ppm</u>	SP-502	0.0	ppb / <u>ppm</u>		
TI-501	64	°F	TI-502	64	°F		
VI-501A	-24	IWC	VI-502A	-23	IWC		
DPT-301	0.33	IWC (6" Pipe)	DPT-302	0.32	IWC (6" Pipe)		
PI-301	6.3	PSI	PI-302	6.8	PSI		
TI-301	100	°F	TI-302	110	°F		
FM-601	82.7 gal	Electric Meter Reading:		6,282 kW/h @	1:40 AM		

B-501 Status on Departure: **UP** / DOWN / OFF

B-502 Status on Departure: **UP** / DOWN / OFF

Alarm Light Status on Departure: ON / **OFF**

Alarm Light Reset on Departure: **YES** / NO

O&M DATA SHEET - NATIONAL HEATSET - OFF-SITE SYSTEM

 Date: 03/27/13

 Time: 14:30

Weather:

48° F - Partly Cloudy

INJECTION & EXTRACTION MANIFOLD OPERATING DATA

Well ID	4" - INJECTION			6" - EXTRACTION			
	Δ Pressure (IWC)	Temp (°F)	Pressure (PSI)	Vacuum (IWC)	Temp (°F)	Velocity (ft/min)	VOCs (ppb or ppm)
DDC-05	-0.13	90	4.5	0.970	58	756	0.0
DDC-10	0.97	88	5.1	0.902	60	496	0.0
DDC-09	0.20	85	5.6	0.999	60	833	0.0
DDC-08	0.22	88	4.9	1.688	60	947	1.4
DDC-07	0.02	85	5.5	1.455	60	519	0.0
DDC-06	0.20	90	5.4	1.596	58	700	0.0

DDC WELLHEAD OPERATING DATA

WELL ID	PZ SHALLOW (FT)	PZ DEEP (FT)	Air Space (FT)	COMMENTS	MW ID	DTW (FT)
DDC-05	8.68	14.36	5.0'	---	NA	NA
DDC-10	8.62	12.15	1.5'	---	NA	NA
DDC-09	8.40	13.47	1.0'	1-foot of pooled water within vault	NA	NA
DDC-08	7.82	12.59	0.5'	2-feet of pooled water within vault	NA	NA
DDC-07	8.02	10.31	1.5'	---	NA	NA
DDC-06	7.96	8.10	2.5'	(1) Drained condensate valve	NA	NA

AIR SAMPLING DATA

B-501			B-502		
Sample Port Position	SAMPLE PORT ID	VOC Reading (ppb / ppm)	Sample Port Position	SAMPLE PORT ID	VOC Reading (ppb / ppm)
Influent	SP-401B	0.0	Influent	SP-402B	0.7
Intermediate #1	SP-403B	0.0	Intermediate #1	SP-403A	0.0
Intermediate #2	SP-401A	0.0	Intermediate #2	SP-402A	0.0
Effluent	SP-501	0.0	Effluent	SP-502	0.0

CHILLER

TECHNICIAN COMMENTS/NOTES:

Set Temp. (°F)	75	
Actual Temp. (°F)	72	
Pump Pressure (PSI)	25	1 - DDC-6's condensate valve was drained for 1 minute, from which a less than a quarter gallon of water was produced. DDC-6 produced mostly air from the initial release of the valve.
Freon High Pres. (PSI)	150	
Freon Low Pres. (PSI)	112	

PHOTOGRAPHIC LOG

Date: 3-27-13

AECOM Job No.

National Heatset Printing Site - Off-Site

PHOTO	DATE	TIME	DESCRIPTION	COMMENTS
Picture 3573	3/27/2013	13:21	System was up upon arrival with three (3) alarms triggered.	
Picture 3578	3/27/2013	13:30	Differential pressure gauge, DPT-301, read .33 IWC.	

Photos (3.27.13)



Picture 3573- System was up upon arrival with three (3) alarms triggered.



Picture 3578- Differential pressure gauge, DPT-301, read .33 IWC.