National Heatset Printing Co. (Site No. 152140) Town of Babylon, Suffolk County

Remedial Site Optimization Planning Meeting

Prepared for: NYSDEC



Prepared by:




Agenda

- Overview
- Remedial Site Optimization Strategy
 - Onsite
 - Limited existing information due to presence of structure
 - Groundwater concentrations
 - Stratigraphy
 - Data gaps
 - Areas of proposed investigation
 - Investigation methods
 - Downgradient Area
 - Receptors Investigation
 - Downgradient private well survey update
 - Water supply production well details
 - Surface water bodies



Site Overview

- Location: Babylon, New York
- History: Former tri-color printing operation, chemical inventory of organic solvents was dumped into onsite soils and former leaching pool.
- COCs: CVOCs, specifically: PCE, TCE, and DCE in soil and groundwater
- Soil: Contaminated soils in source area excavated to 15 ft bgs and backfilled with clean material prior to RI.
- 1999: Record of Decision
- Permanganate Injection in Source Area 2005
- Onsite SVE System 2002/2016
- Groundwater treatment using in situ density driven convection (DDC) 2006-2021
 - DDC systems shut down due to operational issues associated with high groundwater elevation and failure of systems to effectively remove contamination
- Remedial Site Optimization







Remedial Site Optimization Strategy


- Onsite Continuing Source Investigation due to remaining high concentrations in groundwater samples collected just south and southeast of the site building
 - Will inform selection of alternative treatment technology
 - ISCO
 - ISCR
 - Enhanced Bioremediation

- Downgradient Receptors Investigation
 - Will determine whether further measures are needed downgradient to protect human health and the environment






Recent Onsite Groundwater Conditions







Site Stratigraphy





Data Gaps

Horizontal Bounds of Contamination:


- Contamination is unbound horizontally
 - Northeast
 - Southwest
 - Northwest


Vertical Bounds of Contamination:

- 80 ft down to confining layer
- Depth to water approx. 12-15 ft.
- Average 65 ft thickness of water column to confining layer
- Most well locations have a shallow and deep interval, separated by 40 ft

Stratigraphy:

- Only one fully characterized boring (DDC-TB)
- MW-5D also logged, but not with the same level of detail as DDC-TB










Proposed Sampling Locations

Monitoring Wells

- 8 points within building footprint
- 1 point east of building
- 1 point north of building in source area








Drilling Methodology

Phased Approach

- Geoprobe with Hydraulic Profiling Tool (HPT) at four locations (Shown in green)
 - Relative conductivity
 - ◆ 24-hr VOC data
- Collect in situ water samples from four HPT locations for lab analysis to determine vertical thickness of the plume
- Following receipt of results, install 10 CMT wells
- Geoprobe with continuous logging at all locations








Continuous Multichannel Tubing Wells

- Propose to use CMT multilevel system
- Allows up to 7 groundwater sample intervals in one boring.
- Depths of intervals to be determined during drilling
- Will help refine contaminant mass calculations, likely reducing target volume for treatment
- Sample CMT wells for VOCs,
 MNA parameters, microbial analysis









Downgradient Area

June 2016 PCE Plume



Downgradient Area

- Receptors Investigation
 - Downgradient private well survey was conducted following issuance of ROD (1999)- update and verify no changes
 - Water supply production well details
 - Request details from Suffolk County
 - Review historic data
 - Surface water bodies







Objectives

Following proposed activities, information will be used to:

- Develop Conceptual Site Model
- Define Target Treatment Objective
- Evaluate recommended remedial technologies
 - + ISCO
 - + ISCR
 - In Situ Bioremediation



Thank You!

Megan Miller
Project Manager
mmiller@eaest.com

