

SITE CAP INSPECTION FORM
Halesite Former Manufactured Gas Plant
New York Avenue, Halesite, Suffolk County, NY

Inspector: Christopher Morris

Date: June 27, 2022

1. Landscaped Areas

Adequate top soil cover present?

Yes

Signs of erosion?

None

Recommended corrective action:

None

2. Concrete/Asphalt Paving

Note any signs of cracking or other damage:

None

Note any areas where greater than 25% of surface is cracked/damaged:

None

Recommended corrective action:

None

3. Gravel Access Road:

Adequate gravel cover present?

Yes

Signs of erosion?

Minimal

Recommended corrective action:

None

9. Comments

(attach photos/sketches to illustrate any damage noted)

SITE WIDE INSPECTION FORM
Halesite Former Manufactured Gas Plant
New York Avenue, Halesite, Suffolk County, NY

Inspector: Christopher Morris

Date: June 27, 2022

1. Site Use Restrictions

No on-site vegetable gardens?

None

No groundwater withdrawal for potable/non-potable use?

None

Restricted industrial use maintained?

Yes

2. Site Cap

Note the date that the annual site cap inspection was performed: 6/27/22

Repairs made as noted during inspection?

None Required

3. Soil Management

Note the date(s) of any soil disturbance activities conducted during the past year: N/A

Proper soil management procedures implemented (cite appropriate close out reports)?

N/A

4. Groundwater Monitoring

Monitoring being conducted in accordance with SMP and OM&M Plan (note the dates of sampling conducted)?

Monitoring conducted semi-annually during the reporting period.

All monitoring wells in working condition (note any repairs/replacement)?

None

5. Soil Vapor Monitoring

Monitoring being conducted in accordance with SMP and OM&M Plan (note the dates of sampling conducted)?

None Required

SITE WIDE INSPECTION FORM
Halesite Former Manufactured Gas Plant
New York Avenue, Halesite, Suffolk County, NY

All vapor monitoring points in working condition (note any repairs/replacement)?

NA

6. NAPL Monitoring

Monitoring being conducted in accordance with SMP and OM&M Plan (note the dates of sampling conducted)?

Monitoring conducted quarterly during the reporting period.

All recovery wells in working condition (note any repairs/replacement)?

None

7. O2 Injection System O&M

Are routine system inspections being completed as specified in the SMP and OM&M Plan?

Yes

Is system maintenance being conducted as specified in the SMP and OM&M Plan?

Yes

8. Recordkeeping

Check that the following records/reports are being maintained/completed (note report/log dates as appropriate):

1) Annual site cap inspection log ✓

2) Close-out report(s) for soil disturbance activities (including manifests for soil disposal) Not Applicable

3) Annual groundwater monitoring reports (including laboratory analytical data reports/groundwater contours) ✓

4) Annual O2 System OM&M reports ✓

9. Comments

(Note any deficiencies and recommendations for corrective actions.)

None

SITE CAP INSPECTION FORM
Halesite Former Manufactured Gas Plant
New York Avenue, Halesite, Suffolk County, NY



1. Oxygen Injection System.



2. Adjacent to east side of substation.



3. Western portion of Site along New York Avenue.



4. Northern Portion of Lowland Area.



5. Southern side of Site and substation driveway.



6. Downgradient Off-Site Conditions.