
APPENDIX B

Photographic Documentation

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site entrance looking south.



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of eastern Site boundary looking south.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site access road looking north towards West Main Street.



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site looking south/southeast.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site looking east.



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site looking south/southwest.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site looking north.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site looking north/northeast.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site looking south.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.

View of stores fronting West Main Street in commercial building located directly north of Site.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Site access road looking south from West Main Street.

Photographic Documentation



LOCATION: Former Patchogue MGP Site, Site Reconnaissance.
View of Swezeys Department Store (former Site of a Lace Mill) located north of the Site across West Main Street.

Photographic Documentation



LOCATION: GP-05

Artesian flow at GP-05 prior to fixing with PVC stick-up.



LOCATION: GP-03

Looking north.

Photographic Documentation



LOCATION: SB-08

Hand hammer direct push.



LOCATION: GP-04

Looking north.

Photographic Documentation



LOCATION: GP-06

Looking north.



LOCATION: GP-06

Looking north.

Photographic Documentation



LOCATION: SB-04

Looking north.



LOCATION: C'

Excavation looking south.

Photographic Documentation



LOCATION: C' + 17'N

Pipe from excavation on pile.



LOCATION: C' + 27'N

Tar seam.

Photographic Documentation



LOCATION: C' +
Looking south.



LOCATION: C' + 120'N
Looking northwest.

Photographic Documentation



LOCATION: B'
Blue and Black stained soil.



LOCATION: A' + 85E
Looking north.

Photographic Documentation



LOCATION: A' + 100'E
Looking north.