



Photo 1: Open canopy area of Patchogue Creek (by MW-4) with submerged aquatic vegetation (SAV).



Photo 2: Close up view in Photo 1 of SAV in Patchogue Creek. Eurasian milfoil (dominant), starwort (abundant) and water celery (sparse).



Photo 3: Riparian vegetation along Patchogue Creek bank by MW-4.



Photo 4: Iron floc and staining of creek sediments (coarse sand and pebble) on the downstream side of West Main Street overpass.



Photo 5: Channel of Patchogue Creek on downstream side of West Main St. overpass with dense stand of clasp leaf pondweed, musty odor also present.



Photo 6: Patchogue Creek upstream from West Main St. overpass, note large discharge pipe from Great Patchogue Lake in background.



Photo 7: View of left bank (facing upstream) showing iron staining of coarse sand substrate.



Photo 8: View of right side of bank showing bulkhead with significant ironing staining. Creek substrate consists of coarse sand, pebbles with Asian clam shells.



Photo 9: Norway maple and Catalupa stand along perimeter of concrete pad present.



Photo 10: Buried whelk shells with household trash against fence line in Norway maple stand north of small concrete pad.



Photo 11: Broad-leaf cat-tail/common rush wetland area along east to west fence line.



Photo 12: Open field area present in center of property looking NW from Lot 6.4.



Photo 13: Open field area looking NNW across open field area from Lot 6.4 concrete pad southern perimeter..