

# DAILY OBSERVATION REPORT

Report No.: NG061812

Date: June 18, 2012

**NYSDEC**

**DER - Remedial Bureau C**

**Inspection Unit**

**NG Patchogue MGP Site  
Pre-Design Investigation  
Site Number 152182**

**NG PM: Bill Ryan**

**NYSDEC PM: Liz Lukowski**

**Construction Manager: Brown and Caldwell**

**Project Engineers: Brown and Caldwell**

**Remedial Contractor: Viasant**

**Air Monitoring: Brown and Caldwell**

**Health & Safety: NA**

***Weather Conditions***

<i>General Description</i>	<i>P. Sunny</i>	<i>am</i>	<i>P. Sunny</i>	<i>pm</i>
<i>Temperature</i>	<i>60 F</i>	<i>am</i>	<i>75 F</i>	<i>pm</i>
<i>Wind Direction</i>	<i>None</i>	<i>am</i>	<i>None</i>	<i>pm</i>

**HEALTH & SAFETY:**

*(\*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report).*

<b>Were there any changes to the Health &amp; Safety Plan?</b>		<b>*Yes ( )</b>	<b>No (X)</b>	<b>NA ( )</b>
<b>Were there any exceedances at the perimeter action level reported on this date?</b>	<b>Air:</b>	<b>*Yes ( )</b>	<b>No (X)</b>	<b>NA ( )</b>
<b>Were there any Noise /Vibration exceedances reported on this date?</b>	<b>Noise:</b>	<b>*Yes ( )</b>	<b>No ( )</b>	<b>NA (X)</b>
	<b>Vibration:</b>	<b>*Yes ( )</b>	<b>No ( )</b>	<b>NA (X)</b>
<b>Were there any breaches to the silt fence reported/observed on this date?</b>		<b>*Yes ( )</b>	<b>No (X)</b>	<b>NA ( )</b>
<b>Were there any dust/odor issues reported or observed on this date?</b>		<b>*Yes ( )</b>	<b>No (X)</b>	<b>NA ( )</b>

**WASTE HAULING :**

*(\*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report).*

<b>Were there any vehicles which did not display proper D.O.T numbers and placards?</b>	<b>*Yes ( )</b>	<b>No (X)</b>	<b>NA ( )</b>
<b>Were there any vehicles which were not lined or tarped?</b>	<b>*Yes ( )</b>	<b>No (X)</b>	<b>NA ( )</b>
<b>Were there any vehicles which were not decontaminated prior to exiting the work site?</b>	<b>* Yes ( )</b>	<b>No (X)</b>	<b>NA ( )</b>

# DAILY OBSERVATION REPORT

Report No.: NG061812

Date: June 18, 2012

## Materials Removed From Site: N/A

Disposal Facility's: Bayshore Recycling, Keansby, NJ

Trucking Company: AVF Trucking, Hillsdale, NJ

Total Loads: (on this date) 10

Total Daily Weight: (est.) 250 tons

Total Loads: (to date) 10

Total Weight: (\*approx.) 250 tons

\*Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.

### Summary of Events:

- AOS 1300. Greg, Dustin (B&C); G. Gaydosh (Viasant), Viasant crew on site.
- Viasant sent off 10 loads to Bayshore Recycling, Keansby, NJ.
- Viasant began the 2-foot cut, starting from the south end working to the north. Completed approximately 40% of the excavation.
- Viasant completely removed the concrete pad in the northwest corner of the site. During the excavation of the 10 foot cut, a concrete obstruction was found at bottom 5 feet of the southwest corner of the proposed excavation, and extends 4-5 feet to the east. Appears to extend 5-6 feet to the south into the 2-foot cut area. Operator was able to find the top edge on the western side, but unable to determine the thickness.

### VISITORS TO SITE:

NAME	Representing	Entered Exclusion/CRZ Zone	
B. Ryan	NG	Yes (X)	No ( )
		Yes ( )	No ( )
		Yes ( )	No ( )
		Yes ( )	No ( )

### PROJECT SCHEDULE:

- Determine extent of concrete obstruction, complete both 5 and 10-foot cut.

### ISSUES PENDING:

### ITEMS OF CONCERN:

- None

SITE REPRESENTATIVE  
CONSTRUCTION INSPECTOR:

R. Scott Deyette

Name: (*signature*)

Date: 06/18/12