Report No.: NG062112

June 21, 2012

Date:

**NYSDEC** NG PM: Bill Ryan **DER - Remedial Bureau C** NYSDEC PM: Liz Lukowski **Inspection Unit Construction Manager: Brown and Caldwell Project Engineers: Brown and Caldwell NG Patchogue MGP Site Pre-Design Investigation** Remedial Contractor: Viasant Site Number 152182 Air Monitoring: Brown and Caldwell Health & Safety: NA Weather Conditions General Description pm Sunny am Sunny **Temperature** 75 F 95 F am pm Wind Direction None am None pm **HEALTH & SAFETY:** (\*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report). Were there any changes to the Health & Safety Plan? \*Yes ( ) No (X) NA () Were there any exceedances at the perimeter Air: \*Yes ( ) No (X) NA () action level reported on this date? Noise: \*Yes ( ) NA (X) Were there any Noise /Vibration exceedances No () Vibration: \*Yes ( ) No () NA (X) reported on this date? Were there any breaches to the silt fence reported/observed on this date? \*Yes ( ) No (X) NA () Were there any dust/odor issues reported or \*Yes ( ) No (X) NA () observed on this date? **WASTE HAULING:** (\*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report). Were there any vehicles which did not display proper D.O.T \*Yes ( ) () No (X) NA numbers and placards? Were there any vehicles which were not lined or tarped? \*Yes ( ) No (X) NA () NA () Were there any vehicles which were not decontaminated \* Yes ( ) No (X) prior to exiting the work site?

Report No.: NG062112 Date: June 21, 2012

## Materials Removed From Site: N/A

Disposal Facility's: Bayshore Recycling, Keansby, NJ

Trucking Company: AVF Trucking, Hillsdale, NJ

Total Loads: (on this date) 4

Total Daily Weight: (est.) 100 tons

Total Loads: (to date) 23

Total Weight: (\*approx.) 575 tons

## **Summary of Events:**

- AOS 0700. Greg, Desmond (B&C); G. Gaydosh (Viasant), Viasant crew on site.
- Viasant continued to remove soil from the 2-foot excavation to a stockpile.
- Viasant sent off 4 loads of material to Bayshore Recycling from stockpiled soil. Calciment was added to reduce water content of soil.
- Viasant removed approximately 1 foot of soil along the west and north slopes adjacent to the deeper excavations.
- Based on survey results, Viasant removed high spots within the 2-foot excavation area.

VISITORS TO SITE:					
NAME	Representing	Entered Exclusion/CRZ Zone			
		Yes ()	No ()		
		Yes ()	No ()		
		Yes ()	No ()		
		Yes ()	No ()		

## **PROJECT SCHEDULE:**

Clean-up the 2-foot cut excavations, send off remaining stockpiled soils, place demarcation barrier and backfill excavations.

## **ISSUES PENDING:**

ITEMS OF CONCERN:			
•			
SITE REPRESENTATIVE CONSTRUCTION INSPECTOR:	R. Scott Deyette		
Name: (signature)		Data: 06/21/12	

Date: 06/21/12

<sup>\*</sup>Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.