




MAP SOURCE:
THIS MAP WAS PRINTED FROM GOOGLE MAPS 8/2020.



AECOM

125 BROAD STREET
NEW YORK, NEW YORK 10004
WWW.AECOM.COM

AMERICANA LAUNDROMAT
& DRY CLEANERS
1572 NORTH 5TH AVENUE
BAY SHORE, NEW YORK


REMEDIAL INVESTIGATION REPORT

FIGURE 1

SITE LOCATION MAP

DATE 2020.08.13

PROJECT NUMBER 60586831




HUBBARD SAND AND GRAVEL
1612 5th Avenue
0500223000200057001

PRIMERA IGLESIA BAUTISTA
HISPANA de BAYSHORE CHURCH
1564 5th Avenue
Tax Map No. 0500245000100004000

LEGEND:
MW-# MONITORING WELL LOCATION

NOTES:
1. DRAWING BASED ON SURVEY FROM ADVANCE GEOLOGICAL SURVEY (AGS),
JANUARY 9, 2019 .



DATE
2020.08.10

PROJECT NUMBER
60586831

FIGURE TITLE
SAMPLE LOCATION MAP -
SITE

FIGURE 3

PROJECT

REMEDIAL
INVESTIGATION
REPORT

AMERICANA LAUNDROMAT
& DRY CLEANERS
1572 NORTH 5TH AVENUE
BAY SHORE, NEW YORK

PREPARED FOR


NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
625 BROADWAY
ALBANY, NEW YORK 12233

PREPARED BY

AECOM
125 BROAD STREET
NEW YORK, NEW YORK 10004
WWW.AECOM.COM

Project Management Initials: _____ Designer: _____ Checked: _____ Approved: _____

NAD 83 (2011) NYL (3104)



- LEGEND:
- SSA-# VAPOR INTRUSION SAMPLE LOCATION (INDOOR AIR)
 - OA-1 OUTDOOR AIR SAMPLE LOCATION
 - MW-# MONITORING WELL LOCATION
 - SB-# SOIL BORING SAMPLE LOCATION
 - HP-# HYDROPUNCH SAMPLE LOCATION
 - SGA-# SOIL GAS SAMPLE LOCATION

- NOTES:
- DRAWING BASED ON SURVEY FROM ADVANCE GEOLOGICAL SURVEY (AGS), JANUARY 9, 2019 .



DATE

2020.08.10

PROJECT NUMBER

60586831

FIGURE TITLE

SAMPLE LOCATION MAP -
OFF-SITE

FIGURE 4

PROJECT

REMEDIAL
INVESTIGATION
REPORT

AMERICANA LAUNDROMAT
& DRY CLEANERS
1572 NORTH 5TH AVENUE
BAY SHORE, NEW YORK

PREPARED FOR

NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
625 BROADWAY
ALBANY, NEW YORK 12233

PREPARED BY

AECOM
125 BROAD STREET
NEW YORK, NEW YORK 10004
WWW.AECOM.COM

DATE

2020.08.10


PROJECT NUMBER


60586831


FIGURE TITLE

GROUNDWATER ELEVATION
CONTOURS

FIGURE 5







PROJECT

REMEDIAL
INVESTIGATION
REPORT

AMERICANA LAUNDROMAT
& DRY CLEANERS
1572 NORTH 5TH AVENUE
BAY SHORE, NEW YORK

PREPARED FOR

NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
625 BROADWAY
ALBANY, NEW YORK 12233

PREPARED BY

AECOM
125 BROAD STREET
NEW YORK, NEW YORK 10004
WWW.AECOM.COM

DATE

2020.08.10


PROJECT NUMBER

60586831

FIGURE TITLE

SOIL VAPOR SAMPLING
RESULTS - SITE

FIGURE 8



Project Management Initials: _____ Designer: _____ Checked: _____ Approved: _____

Last saved by: THIBODM(2020-08-24) Last Plotted: 2020-08-24
Filename: P:\0036831-AME\3SHEET\SITE PLAN.DWG

PROJECT

REMEDIAL
INVESTIGATION
REPORT


AMERICANA LAUNDROMAT
& DRY CLEANERS
1572 NORTH 5TH AVENUE
BAY SHORE, NEW YORK

PREPARED FOR

NEW YORK STATE DEPARTMENT OF
ENVIRONMENTAL CONSERVATION
625 BROADWAY
ALBANY, NEW YORK 12233

PREPARED BY

AECOM
125 BROAD STREET
NEW YORK, NEW YORK 10004
WWW.AECOM.COM




LEGEND:

- SSA-# SUB-SLAB SOIL VAPOR SAMPLE LOCATION
- OA-1 SAMPLE LOCATION

NOTES:

- DRAWING BASED ON SURVEY FROM ADVANCE GEOLOGICAL SURVEY (AGS), JANUARY 9, 2019 .
- RESULTS SHOWN FOR AIR LOCATIONS WITH EXCEEDANCES ABOVE STANDARDS IN TABLES.
- RED AND BOLDED TEXT ARE EXCEEDANCES OF NYSDOH AIR ACTION LEVELS PER RESPECTIVE MATRIX. BOLDED TEXT IS FOR DETECTED COMPOUNDS. ALL AIR CONCENTRATIONS ARE REPORTED IN UG/M3
NE = NO EXCEEDANCE
SS = SUB SLAB
IA = INDOOR AIR LOCATION



DATE

2020.08.10

PROJECT NUMBER

60586831

FIGURE TITLE

INDOOR AIR INVESTIGATION
RESULTS - OFF-SITE

FIGURE 9