NEW YORK STATE DEPARTMENT OF **ENVIRONMENTAL** CONSERVATION Division of Environmental **Remediation**

Inactive Hazardous Waste Site **Operations** and Maintenance Review Report

| <u> </u> | Form Date 96.10.0 |
|--|---|
| Site Name: Pennsylvense- Aire Las | Number: ZZ4002 |
| | Federal Superfund K Municipal Responsible Party |
| O&M Information: O&M Start:- E | nd: Annual Cost: \$ /5 000 🗩 Estimated |
| Interim Remedial Measures/Operable Units in O&M Pha | ase: |
| □ Drum Removal □ Soil Remov | |
| □ Cap/Cover □ Containme | |
| • | ollection/Treatment |
| ☐ Air Sparging/Stripper System ☐ Treatment/☐ Other: | Filtration Plant/System |
| Institutional Controls: Deed Restriction Other: | Discharge Permit |
| O&M Review Information: | 1 " |
| O&M Review Information: Reports: Trensh Action Report | <u>{</u> |
| Inspection: | |
| Sampling: | |
| Other: | |
| Conclusions: | 1 1 1 1 |
| Remedy Effective? | 1 recovery trench is not us-king in |
| ROD Compliance? X Yes \(\square\) No: | |
| Consent Order Compliance? 🙇 Yes 🗆 No: | |
| Other: | |
| | |
| Recommendations: Trench will be redesqued and reconstructed to | |
| collect oil and leachate in accordance with the ROD. | |
| It will be activated and lengthenes and deepened. | |
| | |
| | |
| | |
| | |
| | |
| | |
| ROD/Consent Order Modifications? ☑ No ☐ Yes (per | above) Reclassify the Site? No □ Yes → Class: |
| Comments: Next veriew due 9805 | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| Project Manager! - | Reviewer: |
| Signature // Date | Signature Date |
| George Hetrium BERA 7-339 | 7 |
| Nante Region or Bureau Telephone | Name Region or Bureau Telephone |