

**Inactive Hazardous Waste Site Operations and Maintenance Review Report**

Form Date 96.10.01

<b>Site Name:</b> Naval Station - Brooklyn Transformer Area		<b>Class:</b> 4	<b>Number:</b> 224018A
<b>O&amp;M Funding Source:</b> <input type="checkbox"/> State Superfund <input type="checkbox"/> Federal Superfund <input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Responsible Party			
<b>O&amp;M Information:</b> O&M Start: 9603    End: _____		Annual Cost: _____ <input type="checkbox"/> Estimated	
<b>Interim Remedial Measures/Operable Units in O&amp;M Phase:</b>			
<input type="checkbox"/> Drum Removal	<input checked="" type="checkbox"/> Soil Removal	<input type="checkbox"/> Tank Removal	
<input type="checkbox"/> Cap/Cover	<input type="checkbox"/> Containment Structure	<input type="checkbox"/> Fence/Security	
<input type="checkbox"/> Groundwater Recovery/Treatment	<input type="checkbox"/> Leachate Collection/Treatment	<input type="checkbox"/> Vapor Extraction/Treatment	
<input type="checkbox"/> Air Sparging/Stripper System	<input type="checkbox"/> Treatment/Filtration Plant/System	<input type="checkbox"/> Potable Water Supply/System	
<input type="checkbox"/> Other: _____			
<b>Institutional Controls:</b> <input type="checkbox"/> Deed Restriction <input type="checkbox"/> Discharge Permit <input type="checkbox"/> Department of Health Sampling			
<input type="checkbox"/> Other: _____			
<b>O&amp;M Review Information:</b>			
Reports: <u>Rounds 1, 2 &amp; 3 Groundwater Monitoring Reports</u>			
Inspection: _____			
Sampling: _____			
Other: _____			
<b>Conclusions:</b>			
Remedy Effective? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: <u>Based on an examination of the analytical results for samples collected on 9120196, 12120196 and 3110197 which revealed that all samples were "non-detect" for PCBs. no further monitoring is required for Building 7.</u>			
ROD Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>There is no ROD</u>			
Consent Order Compliance? <input type="checkbox"/> Yes <input type="checkbox"/> No: <u>There is no Consent Order</u>			
Other: _____			
<b>Recommendations:</b> <u>A majority of the PCB-contaminated soil was removed. Additional contaminated/stained soil could not be removed without the risk of undermining the structural integrity of Building No. 7. Post-excavation soil sampling did reveal the presence of PCB-contaminated soil remaining on-site. As stated above, no further groundwater monitoring is required, therefore it has been recommended to reclassify this site from a Class 4 to a Class 5.</u>			
<u>No further annual reviews are necessary.</u>			
ROD/Consent Order Modifications? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (per above)    Reclassify the Site? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes → Class: 5			
<b>Comments:</b>			
<b>Project Manager:</b> <u>Ronnie Lee</u> Signature		<b>Reviewer:</b> <u>Gerald J. Rider, Jr.</u> Signature	
Date: <u>7</u>		Date: <u>7/7/98</u>	
Name: <u>Ronnie Lee</u> , <u>BHSC</u>		Name: <u>Gerald J. Rider, Jr.</u> , <u>BHSC</u>	
Region or Bureau: _____		Region or Bureau: _____	
Telephone: <u>518-457-0927</u>		Telephone: <u>(518) 457-0927</u>	