

PROJECT:	Former Fulton MGP – Parcels III and IV (Site No.: 224051)
ADDRESS:	545 Sackett St., Brooklyn, NY
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	February 2, 2024
WEATHER:	Temp: 35-43°F, Overcast, RH: 96% Pressure: 29.84" in Hg Wind: SSW @ 2 mph
TIME:	07:00 – 15:30

Project TeamGeneral Contractor and Subcontractors:

- Mega Contracting Group, LLC (Mega)
- Creamer Environmental, Inc. (CEI)

Engineers and Consultants:

- Roux Environmental Engineering and Geology, D.P.C. (Roux)
- GZA GeoEnvironmental Inc. of New York (GZANY)
- WSP USA (WSP)

Remedial Action Work SummaryWork Activities Performed Onsite:

- Import and backfill material in waste characterization grids WC-2 and WC-3.
- Installation of support of excavation (SOE) in Gas Holder 3 excavation area.

Contractor Work Performed Onsite:

Creamer Environmental, Inc. (CEI) imported 25 trucks (~627.84 tons) of general fill from Vulcan Wantage Quarry to be used as the 1' thick backfill cap in waste characterization grids WC-2 and WC-3. CEI began cleanup in Gas Holder 3 following completion of support SOE welding to prepare for future loadout.

The vapor management system (VMS) associated with the tension fabric structure (TFS) was operated throughout the day. Dust and odor control measures (wetting, tarping, limiting vehicle speeds, etc.) were performed as needed, to ensure there were no impacts to the neighborhood. All truck tires were cleaned before leaving the Site, to ensure no material was tracked onto the surrounding streets. Exposed soils were covered with Atmos odor suppressing foam and/or poly sheeting at the end of the day.

Air Monitoring:

- No VOC or dust exceedances were observed from the community air monitoring program (CAMP).
- GZANY to provide a summary report of CAMP activities separately.

Erosion and Sediment Control:

- None.

Sampling Conducted:

- None.

Other Items of Note:

- Construction activities were observed as part of the ongoing combined sewer overflow (CSO) project west of Nevins Street.

**DAILY STATUS REPORT**

PROJECT:	Former Fulton MGP – Parcels III and IV (Site No.: 224051)
ADDRESS:	545 Sackett St., Brooklyn, NY
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	February 2, 2024
WEATHER:	Temp: 35-43°F, Overcast, RH: 96% Pressure: 29.84" in Hg Wind: SSW @ 2 mph
TIME:	07:00 – 15:30

Imported Material

Name - Location	Source	During This Reporting Period		Total	
		Loads	Tons	Loads	Tons
Vulcan ASTM #3 (1 ½" Stone)	Vulcan Hamburg Quarry			10	255.36
Vulcan ASTM #57 (3/4" Stone)	Vulcan Hamburg Quarry			5	126.76
Vulcan General Fill	Vulcan Wantage Quarry	25	627.84	680	16,146.26

Exported Material

Material	Facility	During This Reporting Period		Total	
		Loads	Tons	Loads	Tons
TCE Impacted Haz Hot Spots	CWM Emelle			7	161.72
Cd Impacted Haz Material from WC-5	CWM Emelle			3	49.45
Pb Impacted Haz from Parcel IV Hot Spot	CWM Emelle			25	536.72
Cd Impacted Haz Material from WC-5	Clean Earth NJ			16	397.75
Concrete for Recycling	Bayshore			25	~465.87
Concrete for Landfill	WM Fairless			63	~1,415.93
Urban Fill for CVOC Orange Zone (Lot 17)	WM Fairless Urban Fill-OZ			47	~1034
Urban Fill for CVOC Orange Zone (Lot 49)	WM Fairless Urban Fill-OZ			24	~528
Non-Haz Urban Fill (Lot 17)	Clean Earth Carteret			42	~924
Non-Haz Urban Fill (Lot 49)	Clean Earth Carteret			73	~1,606
MGP soil with TCE>25 ppm	Clean Earth ESMI			181	~3,906
	CE Southeast Pennsylvania			8	~176
Non-Haz MGP Impacted (TCLP Benzene > 0.5)	CE Southeast Pennsylvania			8	~237.97
Non-Haz MGP Impacted (TCLP Benzene < 0.5)	CE Southeast Pennsylvania			58	~1,276
Non-Haz Contaminated Urban Fill	WM Fairless			323	~6,946.69
Non-Haz Urban Fill	Clean Earth Carteret -BZ			45	~967
Non-Haz MGP Impacted	Clean Earth of New Castle			35	~770
MGP Impacted (TCLP Benzene 0.2<x<0.5 mg/l)	CE Southeast Pennsylvania			5	~110

Exported Material Truck Log

Number	Excavation Grid	Disposal Facility	Disposal Profile	Manifest Number	Trucking Company	Truck License Plate
None.						

Dewatering

Time	Totalizer Reading
7:00	40,131,200
15:30	40,131,200
Water treated and discharged since last report:	0 gallons

**DAILY STATUS REPORT**


PROJECT:	Former Fulton MGP – Parcels III and IV (Site No.: 224051)
ADDRESS:	545 Sackett St., Brooklyn, NY
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	February 2, 2024
WEATHER:	Temp: 35-43°F, Overcast, RH: 96% Pressure: 29.84" in Hg Wind: SSW @ 2 mph
TIME:	07:00 – 15:30

Anticipated Upcoming Work Activities

Prepare for future material load out from Gas Holder 3 excavation area.


PROJECT:	Former Fulton MGP – Parcels III and IV (Site No.: 224051)
ADDRESS:	545 Sackett St., Brooklyn, NY
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	February 2, 2024
WEATHER:	Temp: 35-43°F, Overcast, RH: 96% Pressure: 29.84" in Hg Wind: SSW @ 2 mph
TIME:	07:00 – 15:30

Site Layout



PROJECT:	Former Fulton MGP – Parcels III and IV (Site No.: 224051)
ADDRESS:	545 Sackett St., Brooklyn, NY
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	February 2, 2024
WEATHER:	Temp: 35-43°F, Overcast, RH: 96% Pressure: 29.84" in Hg Wind: SSW @ 2 mph
TIME:	07:00 – 15:30

Excavation Diagram



PROJECT:	Former Fulton MGP – Parcels III and IV (Site No.: 224051)
ADDRESS:	545 Sackett St., Brooklyn, NY
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	February 2, 2024
WEATHER:	Temp: 35-43°F, Overcast, RH: 96% Pressure: 29.84" in Hg Wind: SSW @ 2 mph
TIME:	07:00 – 15:30



Photo 1:

Looking south, view of a truck off loading imported general fill into completed excavation in waste characterization grid WC-3.



Photo 2:

Looking west, view of CEI placing and compacting 1' thick of general fill in former excavation areas in WC-2 and WC-3.