

**NATIONAL GRID  
FORMER SCHOLES STREET HOLDER STATION SITE  
BROOKLYN, NEW YORK  
SITE NO. 224067**

**SITE-WIDE INSPECTION FORM**

Site Addresses: 154 Bogart Street (Lot 1), 338 Scholes Street (Lot 7), and 350 Scholes Street (Lot 11), Brooklyn,  
Kings County, New York.

Date and Time of Inspection: March 6, 2024 - 8:00 AM to 10:00 AM; April 11, 2024 - 7:00 AM to 8:00 AM

Inspector (Name and Affiliation): Salvatore Tedesco; Arcadis of New York, Inc.

Weather Conditions: Overcast, mid-50s° F

Describe repairs, maintenance, or corrective actions implemented since previous inspection: Not applicable. This is  
the initial annual site-wide inspection.

**ATTACH PHOTOGRAPHS OF AREAS OR ITEMS INSTALLED, REPAIRED, OR REPLACED**

**General Site Conditions:** Site inspection was performed from the exterior of the properties (see Attachment A –  
Photograph Log and attached Figure 3 from the NYSDEC-accepted September 2022 Interim Site Management Plan  
[ISMP] for the Site). None of the three lots comprising the Site are owned by National Grid and there is no current  
access agreement between National Grid and the property owners, and thus Site conditions within the three  
properties could not be observed during the inspection. As identified in the ISMP, the Site cover system is comprised  
of paved and concrete-covered ground surfaces and building slabs. The small exterior pavement areas on the north  
and south sides of Lot 11 appeared to be in acceptable condition based on observations from the exterior of the  
property. The footprint of the existing buildings generally extends to the approximate Site boundary (except for  
Lot 11; see attached figure) and based on observations from the exterior of the properties the buildings  
appeared to be in acceptable condition.

	<u>Acceptable</u>	<u>Unacceptable</u>
Pavement	<u>  X  </u>	<u>      </u>
Buildings	<u>  X  </u>	<u>      </u>

**Site Cover System:**

Any signs/evidence of ground-intrusive activities (e.g., excavating, trenching, etc.), soil disturbance regardless of quantity/extent, erosion, settlement, or if applicable, bare or sparsely-vegetated areas?

No  Yes; describe: Based on observations from the exterior of the three properties there was no evidence of ground-intrusive activities in the public right-of-way (see Attachment A – Photograph Log). The Site cover system could not be observed.

---

---

---

ATTACH PHOTOGRAPHS OF AREAS OF DISTURBANCE

Any signs/evidence of use of the Site in a manner inconsistent with the previous Site uses?

No  Yes; describe: Not applicable. This is the initial annual site-wide inspection.

---

---

---

---

---

ATTACH PHOTOGRAPHS OF AREAS OF NON-COMPLIANCE

Describe any repairs, maintenance, or corrective actions required to correct observed deficiencies: No deficiencies, if any, could be observed based on observations from the exterior of the three properties.

---

---

---

---

ATTACH PHOTOGRAPHS OF DEFICIENT AREAS OR ITEMS OBSERVED DURING THE INSPECTION

Inspector's Signature:

Signature:  Date: 5/30/2024

**Figure**



# Attachment A

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 1**

**Description: Looking South at Lot 11**

**Date: 3/6/2024**



**Photograph: 2**

**Description: Looking Southwest at Lot 7**

**Date: 3/6/2024**

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 3**

**Description: Looking South/Southeast at Lot 7**

**Date: 3/6/2024**



**Photograph: 4**

**Description: Looking Southeast at Lot 7**

**Date: 3/6/2024**

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 5**

**Description: Looking East/Northeast at Lot 7**

**Date: 3/6/2024**



**Photograph: 6**

**Description: Looking Southeast at Lot 1**

**Date: 3/6/2024**

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 7**

**Description: Looking North/Northeast at Lot 1**

**Date: 3/6/2024**



**Photograph: 8**

**Description: Looking Northeast at Lot 1**

**Date: 3/6/2024**

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 9**

**Description: Looking Northwest at Lot 1**

**Date: 4/11/2024**



**Photograph: 10**

**Description: Looking North at Lot 11**

**Date: 4/11/2024**

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 11**

**Description: Looking  
Northeast/East along  
Lot 7 on Scholes  
Street**

**Date: 3/6/2024**

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 12**

**Description: Looking Northwest along Lot 1 on Bogart Street**

**Date: 3/6/2024**

# Photograph Log

National Grid  
Former Scholes Street Holder Station Site  
Brooklyn, New York



**Photograph: 13**

**Description: Looking  
Northeast/East along  
Lot 1 on Meserole  
Street**

**Date: 3/6/2024**