

December 27, 2017

Mr. R. Scott Deyette
New York State Department of Environmental Conservation
Division of Environmental Remediation
Remedial Bureau C, 11th Floor
625 Broadway
Albany, New York 12233-7014

RE: Annual Site Inspection Form Wythe Ave. Site Brooklyn, New York Site No. 224069 Index No. A2-0552-0606

anabell

Dear Mr. Deyette:

Enclosed, as required by the draft Interim Site Management Plan Revision 1, dated June 2017, for the subject site, please find the Site Inspection Form for the annual site-wide inspection. The inspection was conducted by GEI Consultants, Inc. P.C. on July 24, 2017. The draft Interim Site Management Plan Revision 1 was revised in September 2017 and approved by New York State Department of Environmental Conservation on October 2, 2017. The Annual Site Inspection requirements remained the same in the draft and final versions.

If you have any questions or comments, please contact me at (718) 963-5453.

Sincerely,

Donald P. Campbell Project Manager

Enclosure

ec: M. Felter, GEI

SITE INSPECTION FORM Wythe Ave. Station Site

SITE INSPECTION DATE:	7/24/17	TIME OF ARRIVAL:	0800
		DEPARTURE:	1630
National Grid SIR Represent	ative(s): NoT	Present	**************************************
	<u> </u>	7	
INSPECTION TYPE:	Annua	I Inspection or Emergen	cy Inspection
(if emergency indicate event the	nat required an ins	pection):	
Are the Institutional Controls	s in place, perfor	ming properly, and rema	in effective?
Site Signage in Place?			Yes /(No)
	NA		
Hazard Communication Docur	nents Present?		Yes / (No)
	NA		
	, ,		
Has ownership of the property	changed since the	e last inspection?	Yes /No
(Verify with Real Estate and So	urvey Departments	s)	
		•	
First annual	inspection	No changes since	e ISMP W-S
35 ved	, ,	0	
		8:	

SITE INSPECTION FORM Wythe Ave. Station Site

Are the Engineering Controls in place, per	forming properly, and remain effective?
Surface Cover Intact (ie no evidence of erosio	on, excavations)?
Pe Site building	s are intact
	The state of the s
GENERAL SITE OBSERVATIONS:	
Has there been any changes to the property s	
(i.e. new equipment or facilities, changes in si	te topography, erosion, etc.)
The hotel and s	Shopping area bildings have been
	")
· · · · · · · · · · · · · · · · · · ·	
in .	
	T
COMPLETED BY: How's Koura (SK)	REVIEWED BY: Melissa Fetter
SIGNATURE Hall Mile	SIGNATURE: Milise Helt
SIGNATURE: Style 1992	SIGNATURE: ///