

SITE INSPECTION FORM

Wythe Ave. Station Site

SITE INSPECTION DATE: 7/13/2022

TIME OF ARRIVAL: 0655 TIME OF DEPARTURE: 1640

National Grid SIR Representative(s): Jessica Phillips stopped by the site to check in on the field work and conducted a brief health and safety tailgate discussing heat stress awareness and traffic safety (working along busy streets).

INSPECTION TYPE: Annual Inspection ☒ OR Emergency Inspection ☐

(if emergency, indicate event that required an inspection: Annual Inspection of Site and Site Boundaries)

Are the Institutional Controls in place, performing properly, and remain effective?

Site signage in place: Yes ☐ OR No ☒

Not Applicable

Hazard Communication Documents Present? Yes ☐ OR No ☒

On file with National Grid, property owners were not asked if they have copies.

Has ownership of the property changed since the last inspection? Yes ☐ OR No ☒
(Verify with Real Estate and Survey Departments)

NYC online records indicate property ownership has not changed since last inspection.

Property owners are Wythe Berry LLC (since May 2014) and Mihata Corp (since April 1994)

Are the Engineering Controls in place, performing properly, and remain effective?

Surface Cover Intact (i.e. no evidence of erosion, excavations)? Yes ☒ OR No ☐

Site buildings, sidewalks, and hardscape are intact (see photographs attached).

GENERAL SITE OBSERVATIONS:

Have there been any changes to the property since the last inspection? Yes ☐ OR No ☒

(i.e. new equipment or facilities, changes in site topography, erosion, etc.)

No changes in activities, use, or operations was observed on the Site. The site continues to be improved by a hotel and a warehouse.

COMPLETED BY: Mackenzie Fannon

REVIEWED BY: Melissa Felter

SIGNATURE:

Mackenzie Fannon

SIGNATURE:

Melissa Felter

GEI Consultants, Inc.

PHOTOGRAPHIC RECORD

Project: Wythe Avenue Former Holder Station
Annual Site Inspection
Location: Brooklyn, New York



Photographer: R. Perryman
Date: 7/13/22
Photo No.: 1
Direction: NE

Comments: Photo of sidewalk adjacent to Site on Wythe Avenue looking toward N. 13th Street. Gas system construction activity is shown along 12th Street.



Photographer: M. Fannon
Date: 7/13/22
Photo No.: 2
Direction: N

Comments: Photo of sidewalk and Site adjacent to Site along Berry Street.



Photographer: R. Perryman
 Date: 7/13/22
 Photo No.: 3
 Direction: E

Comments: Photo of Site adjacent to 13th Street and Wythe Avenue. Some construction activity/staging observed along 13th Street



Photographer: R. Perryman
 Date: 7/13/22
 Photo No.: 4
 Direction: E

Comments: Photo of Mirtex warehouse at the Site along 13th Street looking west.