




LEGEND

- DESTROYED MONITORING WELLS
- INTERIOR MONITORING WELL (INSIDE THE BUILDING)
- DEEP/SHALLOW MONITORING WELL CLUSTER
- SHALLOW MONITORING WELL
- INTERIOR SUMP
- FENCE LINE
- APPROXIMATE LOCATION OF DRAIN SPOUT
- APPROXIMATE VICINITY OF PREVIOUS EXCAVATED & STOCKPILED SOILS
- RIGHT OF WAY
- SEWER MANHOLE (APPROX 12' DEEP)
- UNDERGROUND STORM SEWER
- TOC
- DTW
- GW EL
- WNS
- GROUNDWATER CONTOUR LINE (feet)

DRAFTED BY:
W.G.S.
(N.J.)

CHECKED BY:

REVIEWED BY:

NORTH

SITE GROUNDWATER CONTOUR MAP
SHALLOW MONITORING WELLS
JULY 28, 2003

COMPREHENSIVE REMEDIAL INVESTIGATION REPORT
STANDARD MOTOR PRODUCTS, INC. SITE
LONG ISLAND CITY, NEW YORK

CDM

SCALE IN FEET
0 50

FIGURE
3-15

DATE
1-29-04