


M:\Graphics\0300-Wall\Misc\Standard Motor Products\Queens\Standard Motor Products SM.dwg, 01/29/2004 02:18:25 PM, WShea, Acrobat PDFWriter



LEGEND

- DESTROYED MONITORING WELLS
- INTERIOR MONITORING WELL (INSIDE THE BUILDING)
- DEEP/SHALLOW MONITORING WELL CLUSTER
- SHALLOW MONITORING WELL
- INTERIOR SUMP
- FENCE LINE
- APPROXIMATE LOCATION OF DRAIN SPOUT
- APPROXIMATE VICINITY OF PREVIOUS EXCAVATED & STOCKPILED SOILS
- ROW
- SEWER MANHOLE (APPROX 12' DEEP)
- UNDERGROUND STORM SEWER
- ANGLED DIRECT PUSH LOCATION (SOIL AND GROUNDWATER SAMPLES)
- DEEP DIRECT PUSH LOCATION (GROUNDWATER SAMPLES)
- DEEP DIRECT PUSH LOCATION (SOIL AND GROUNDWATER SAMPLES)
- VOC
- VOLATILE ORGANIC COMPOUND

SAMPLE IDENTIFICATION	MW09D	33	VINYL CHLORIDE	4	J
DEPTH (feet)					
COMPOUND					
CONCENTRATION (µg/L)					
DATA QUALIFIER					

NOTE:

ANALYTICAL DATA FROM JULY 2003 IS PRESENTED IN MICROGRAMS PER LITER (µg/L)

DRAFTED BY: W.G.S. (N.J.)	MONITORING WELL CHLORINATED VOC EXCEEDANCES		
CHECKED BY:	REMEDIAL INVESTIGATION REPORT		
REVIEWED BY:	REMEDIAL INVESTIGATION/FEASIBILITY STUDY		
	STANDARD MOTOR PRODUCTS, Inc.		
	LONG ISLAND CITY, NEW YORK		
	Groundwater & Environmental Services, Inc.		
	1340 CAMPUS PARKWAY, NEPTUNE, NJ 07753		
	SCALE IN FEET	DATE	FIGURE
	0 50	1-29-04	4-4