# Environmental Situation Report

## General Information

**Facility**
Latham, NY Hauling

**Type of Situation**
Spill

**Reported By**
Shannon Schaefer

**Date Situation Occurred**
03/25/2026

**Time Situation Occurred**
07:00 AM

**Date Situation Reported**
03/25/2026

**Time Situation Reported**
07:00 AM

## Situation Details

**Spill Class**
Oil/Petroleum

**Oil/Petroleum Subclass**
Hydraulic Oil

**Spill Location**
Offsite

**Offsite Spill Address (if applicable)**
325 Northern Blvd.
Albany, NY

**Spill Quantity**
15.000

**Unit**
Gallons

**Did the spill impact private property?**
Yes

**Was the spill contained?**
No

**Is this a State reportable quantity/event?**
Yes

**Was the spill cleaned up within 2 hours?**
Yes

**Spill Report Number (if applicable)**
2510057

**Summary of Situation: Brief Description**
Hydraulic Main Line Release

**Situation Details: Communications/Reporting & Corrective Actions**
Due to equipment failure of the hydraulic oil main line on unit 618, approximately 10 -15 gallons released to asphalt. MM alerted SS of the release at approximately 9:55am, indicating that proper notification to the NYSDEC spill hotline was complete and provided a spill number for our records. Spill remediation consisted of addressing the source, isolating the release, and applying spill absorbent material to the impacted area. The speedy dry was swept up and disposed internally.

**Resolution: Describe Resolution or Additional Actions Required**

# Environmental Situation Report

Spill remediation consisted of addressing the sources, isolating the release, and applying spill absorbent material to the impacted area. The speedy dry was swept up and disposed internally. No photos attached to the ESR.