## NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION DIVISION OF HAZARDOUS WASTE REMEDIATION

Original-BHSC Copy-REGION Copy-DEE

## REGISTRY SITE CLASSIFICATION DECISION

Copy-DOH Copy-PREPARER

1. SITE NAME		2. SITE NUMBER	3. TOWN/CITY/VILLAGE	4. COUNTY
FORMER HOPEWELL PRECISION		314052	EAST FISHKILL	DUTCHESS
5. REGION	6. CLASSIFICAT			
3		CURRENT		MODIFY
7. LOCATION OF	SITE (Attach U.S.	G.S. Topographic M	Iap showing site location)	162 20"
a. Quadrangle: Hopewell Junction b. Site Latitude 36° 39' 55" Site Longitude 73° 46' 30"				
c. Tax Map Number:				
8. BRIEFLY DESCRIBE THE SITE (Attach site plan showing disposal/sampling locations)  The site is approximately a 1 acre lot that is presently used by the owner, Nicholas Brothers Moving Co., for storage. Hopewell Precision operated a machine shop at the site until 1981, when they moved next door to a new facility. See Attachment II for a site sketch. Attachment III is a copy of the USGS Quad for Hopewell Junction. DEC performed both a Phase I and II at the site during the 1980's. During the Phase II, three monitoring wells were installed. At the time only one was found to contain TCE.  In 1993 the PRP and the DEC took samples at the site of the wells and the tap water. Nothing was detected.				
a. Area 1 acres b. EPA ID Number NYD066813064 c. Completed (X)Phase I (X)Phase II () PSA ()RI/FS ()PA/SI (X)Other-				
2 XX 1 Wests Disposed (Include EDA Hazardons Waste Numbers)				
9. Hazardous Waste Disposed (Include EPA Hazardous Waste Numbers)				
10. ANALYTICAL DATA AVAILABLE				
a. ()Air (X)Groundwater ()Surface Water ()Sediment ()Soil ()Waste ()Leachate ()EP10X				
()TCLP b. Contravention of Standards or Guidance Values				
Three onsite wells, two drinking water wells, and a storm drain were sampled in April 1993.  DEC split samples - Non Detect PRP Results 2ppb TCE in a monitoring well				
DEC split samples - Non Detect PRP Results 2ppb TCE in a monitoring well				
See Attachment IV for DEC results and Attachment V for PRP results.				
11. JUSTIFICATION FOR CLASSIFICATION DECISION				
Although low levels were detected in the well during the mid 80's, the latest round of sampling revealed levels less than 2 ppb of TCE. The site has not been used as a machine shop for over twelve years. The hazardous waste allegedly disposed has never been located nor any evidence of it found, therefore the site should be delisted from a 2A to D1.				
12. SITE IMPACT DATA  Negret Symbols Water: Distance: 100ft Direction: South West Classification: NA				
a. Nearest Surface water. Distance. Took				
b. Nearest Groundwater:Depth:10ft Flow Direction: SW ()Sole Source ()Primary ()Principal c. Nearest Water Supply: Distance 0 Direction On site Active (X)Yes ()No				
d. Nearest Building: Distance 0 ft. Direction On site Use: Storage, Commercial				
e. In State Economi	c Development Zone	()Y (X)	l	(X)Y ()N
f. Crops or livestock on site? ()Y (X)N J. Exposed nazardous waste? ()1 (A)N				
g. Documented fish or wildlife mortality?  ()Y (X)N k. HRS Score N/A  h. Impact on special status fish or wildlife ()Y (X)N l. For Class 2: Priority				
h. Impact on special resource?	l status fish or wildlin	Fe ()Y (X)	Category N/A	
13. SITE OWNER'S NAME		14. ADDRESS		15.
John DeNicholas, Sr.		Ryan Road,	Hopewell Jucntion 914/ 221 - 0430	
16. PREPARER October 7, 1993 October 7, 1993 October 7, 1993				
	/	October 7, 1993	Signatura	
Signature Pagion 3		Date	Signature ( ) A A Bate Ramanand Pergadia, RHWRF Region 3	
Daniel Bendell, DHWR - Region 3  Name, Title, Organization  Name, Title, Organization  Name, Title, Organization				
hpregl				