numbers and placards?

prior to exiting the work site?

Were there any vehicles which were not lined or tarped?

Were there any vehicles which were not decontaminated

NYSDEC Contractor PM: Paths Construction NYSDEC PM: Sarah Saucier Remedial Bureau C Construction Manager: Jesus (Leo) Montoya **Division of Environmental Remediation** Project Engineers: Paths construction Site: Bayeaux St , 135 Main St Poughkeepsie Remedial Contractor: C2G Josh Bendell Phase: Spill Site No.: Spill# 2500910 Air Monitoring: Hillman Dominic Health & Safety: Paths Construction Weather Conditions **General Description Mostly sunny Mostly sunny** pm am **Temperature** 80 80 pm am Wind Direction south am south pm **HEALTH & SAFETY:** (*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report). *Yes () No (X) NA () Were there any changes to the Health & Safety Plan? Were there any exceedances at the perimeter *Yes () No (X) Air: NA () action level reported on this date? Were there any Noise /Vibration exceedances Noise: *Yes () No (x) NA Vibration: *Yes () reported on this date? No (x)NA Were there any breaches to the tent structure or silt fence reported/observed on this date? *Yes () No () NA (X) Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA () **WASTE HAULING:** (*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report). Were there any vehicles which did not display proper D.O.T

*Yes ()

*Yes ()

* Yes ()

No (X)

No (X)

No (X)

NA

NA

NA

()

()

()

	V	lateri	als	Remo	ved F	rom	Site
--	---	--------	-----	------	-------	-----	------

Disposal Facility's:

Total Loads: (on this date) 0

Total Loads: (to date)

Total Daily Weight: (est.) 0

Total Weight: (*approx.)

Summary of Events:

C2G removing base of holder structure and contaminated soil. Dewatering of holder area ongoing. Dewatering pumped to vac truck and trucked offsite. Blebs and stringers of NAPL evident in water during dewatering. Ebullitions of coal tar from bedrock is occurring.

DEC observed Hillman representative take end point samples. VOC,SVOCs,Tal Metals, Cyanide. Samples collected and properly stored in cooler with ice.

Slight odors from vac truck. No odors at property boundary.

VISITORS TO SITE:				
NAME	Representing	Entered Exclusion/CRZ Zone		
		Yes ()	No ()	
		Yes ()	No ()	
		Yes ()	No ()	
		Yes ()	No ()	
PROJECT SCHEDULE:				
•				
ISSUES PENDING:				
•				

ITEMS OF CONCERN:

SITE REPRESENTATIVE / CONSTRUCTION INSPECTOR: Gerry Pratt

Name: (signature)

Hull hatti
Date: 7-18-25

^{*}Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.



C2G dewatering former holder excavation. Coal Tar blebs and stringers évident in water.



East Wall Two orange painted areas marked for end point sampling locations. Third (middle) location not sampled.



Former holder excavation bottom, coal tar blebs and stringers eveident during dewatering.



Former holder excavation, coal tar ebullation occuring.



North wall of excavation in background. Second holder foundation on top of bedrock



South wall of excavation. Two end point sampling locations marked with orange paint.

