Were there any vehicles which were not lined or tarped?

Were there any vehicles which were not decontaminated

prior to exiting the work site?

()

()

NA

NA

NYSDEC Contractor PM: Paths Construction NYSDEC PM: Sarah Saucier Remedial Bureau C Construction Manager: Jesus (Leo) Montoya **Division of Environmental Remediation** Project Engineers: Paths construction Site: Bayeaux St , 135 Main St Poughkeepsie Remedial Contractor: C2G Josh Bendell Phase: Spill Site No.: Spill# 2500910 Air Monitoring: Hillman Dominic Health & Safety: Paths Construction Weather Conditions **General Description Mostly sunny Mostly sunny** pm am **Temperature** 80 80 pm am Wind Direction south am south pm **HEALTH & SAFETY:** (*If any box(s) below are checked "Yes", list the deviation under the "Items for Concern" section of this report). *Yes () No (X) NA () Were there any changes to the Health & Safety Plan? Were there any exceedances at the perimeter *Yes () No (X) Air: NA () action level reported on this date? Were there any Noise /Vibration exceedances Noise: *Yes () No (x) NA Vibration: *Yes () reported on this date? No (x)NA Were there any breaches to the tent structure or silt fence reported/observed on this date? *Yes () No () NA (X) Were there any dust/odor issues reported or observed on this date? *Yes () No (X) NA () **WASTE HAULING:** (*If any box(s) below are checked "Yes", list the deviation under the "Items of Concern" section of this report). Were there any vehicles which did not display proper D.O.T *Yes () numbers and placards? No (X) NA ()

*Yes ()

* Yes ()

No (X)

No (X)

DAILY OBSERVATION REPORT **Materials Removed From Site:**

Disposal Facility's:

Total Loads: (on this date) 0

Total Loads: (to date)

Total Daily Weight: (est.) 0

Total Weight: (*approx.)

Summary of Events:

C2G dewatered excavation into two frac tanks ~ 25,000 gallons. Slight odors in immediate vicinity of frac tanks. No odors at property boundary . Frac tanks to be emptied Tuesday 7-22-25 Blebs and stringers of NAPL evident in water during dewatering. Ebullitions of coal tar from bedrock is occurring.

VISITORS TO SITE:			
NAME	Representing	Entered Exclusion/CRZ Zone	
		Yes ()	No ()
		Yes ()	No ()
		Yes ()	No ()
		Yes ()	No ()
PROJECT SCHEDULE:			
•			
ISSUES PENDING:			
•			
ITEMS OF CONCERN:			
SITE REPRESENTATIVE /			
CONSTRUCTION INSPECTOR:			
CONSTRUCTION INSPECTOR.			

Name: (signature)

Gerry Pratt

Genell Pratto 7-21-25 Date:

^{*}Actual (total weight) adjusted periodically based on weight tickets submitted by the disposal facilities.



Former holder excavation dewatered. Coal tar blebs and stringers évident following dewatering operations. North wall of excavation in background.

DAILY OBSERVATION REPORT



Blebs and stringers in groundwater within former holder excavation.